

Available from

NRC/GPO Sales Program

Superintendent of Documents
Government Printing Office
Washington, D. C. 20402

A year's subscription consists of 12 issues for
this publication.

Single copies of this publication
are available from National Technical
Information Service, Springfield, VA 22161

Microfiche of single copies are
available from NRC/GPO Sales Program
Washington, D. C. 20555

Title List of Documents Made Publicly Available

December 1-31, 1982

Division of Technical Information and Document Control
Office of Administration
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555



CONTENTS

Preface	v
Arrangement of Items by Docket Number	ix
Alphabetic Arrangement of Docket Items by Facility Name	xv
Docketed Items	
Low Level Radwaste Disposal Sites — Docket 27	1
Domestic Licensing of Source Material — Docket 40	1
Domestic Licensing of Production and Utilization Facilities — Docket 50	8
Domestic Licensing of Special Nuclear Material — Docket 70	363
Packaging of Radioactive Material for Transport and Transportation of	
Radioactive Material Under Certain Conditions — Docket 71	371
Licensing of Independent Spent Fuel Storage — Docket 72	375
Nondocketed Items	
10 CFR — Commission Meeting Records	377
ACRS — Advisory Committee on Reactor Safeguards	377
COMMISSION — NRC Commissioners	378
CONTRACT — NRC Contracts and Modifications	379
FOIA — Freedom of Information Act Requests and Releases	384
GEN TECH IS — Generic Technical Issues	396
I&E — Inspection and Enforcement	397
MISC — Public Document Room Miscellaneous	398
NUREG — NUREG Reports and Related Correspondence	398
ORG — Correspondence with Other Organizations	403
PR — Proposed Rule	404
PRM — Petition for Rulemaking	405
PROJ — Projects - Predocket Licensing	406
PT 21 — Noncompliance Reports and Related Correspondence	406
QA999 — Quality Assurance Inspections	406
REGGD — Regulatory Guides	408
RES — Research and Technical Assistance Reports	408
REVIEW GROUP — NRC Research Review Groups	411
SECY — Position Papers Before the Commission	411
STATE PROG — State Programs	412
TOPREP — Vendor Reports and Related Correspondence	412
WASTE MGT — Nuclear Waste Management	414
XPORTLIC — Export and Import Licenses	418
Personal Author Index	423
Corporate Source Index	453
Report Number Index	483
Cross Reference of Enclosures to Principal Documents	485
Appendix A — Definitions of Docket 50 Categories	A-1
Appendix B — Definitions of Nondocketed Categories	B-1

PREFACE

The *Title List of Documents Made Publicly Available* is a monthly publication. It contains descriptions of the information received and generated by the U.S. Nuclear Regulatory Commission (NRC). This information includes (1) docketed material associated with civilian nuclear power plants and other uses of radioactive materials and (2) nondocketed material received and generated by NRC pertinent to its role as a regulatory agency. As used here, *docketed* does not refer to Court dockets; it refers to the system by which NRC maintains its regulatory records. This series of documents is indexed by a Personal Author Index, a Corporate Source Index, and a Report Number Index.

The docketed information contained in the *Title List* includes the information formerly issued through the Department of Energy publication *Power Reactor Docket Information*, last published in January 1979. Microfiche of the docketed information listed in the *Title List* is available for sale on a subscription basis from the National Technical Information Service (NTIS). See NOTES at the end of the Preface for the complete NTIS address.

We encourage your comments, criticisms, and suggestions. In particular, if there are title descriptions that are not meaningful, please let us know so that we can correct the data base. In so far as possible, we would like this document to be a valuable part of your reference material.

DOCKETED ITEMS


The listings within Docket 50 are divided into the categories used for filing and searching in the NRC Public Document Room. Those categories are:

- A. Application/construction stage documents and correspondence
- B. Utility Preliminary Safety Analysis Report (PSAR), amendments
- C. Utility Environmental Report (ER), amendments and correspondence
- D. NRC Draft and Final Environmental (Impact) Statements (DES and FES), and correspondence
- E. NRC Safety Evaluation Report (SER), supplements and correspondence
- F. Security, medical, emergency and fire-protection plans
- G. Adjudicatory correspondence
- H. General correspondence
- I. Financial information
- J. Insurance and indemnity information
- K. Utility Final Safety Analysis Report (FSAR) and amendments
- L. Limited work authorization and related correspondence
- M. Antitrust correspondence
- N. Antitrust hearing transcripts
- O. Advisory Committee on Reactor Safeguards (ACRS) reports and correspondence
- P. Operating license stage documents and correspondence
- Q. Inspection reports, IE Bulletins and correspondence
- R. Periodic operating reports and related correspondence
- S. Reportable occurrences, LERs and related correspondence
- T. Hearing transcripts on non-antitrust matters
- U. Congressional/executive correspondence
- V. Licensing operators and related correspondence

I&E — Inspection and Enforcement
 MISC — Public Document Room Miscellaneous
 NUREG — NUREG Reports and Related Correspondence
 ORG — Correspondence with Other Organizations
 PR — Proposed Rule
 PRM — Petition for Rulemaking
 PROJ — Projects—Predocket Licensing
 PT21 — Noncompliance Reports and Related Correspondence
 QA999 — Quality Assurance Inspections
 REGGD — Regulatory Guides
 RES — Research and Technical Assistance Reports
 REVIEW GRP — NRC Research Review Groups
 RM — Rulemakings
 SECY — Position Papers Before the Commission
 STATE PROG — State Programs
 TOPREP — Vendor Reports and Related Correspondence
 WASH — Regulatory Publications—Pre-NUREG Series
 WASTE MGT — Nuclear Waste Management
 XPORTLIC — Export and Import Licenses

Appendix B sets forth these categories and describes the material available in each. Omission of a category in the listing for a docket indicates that no documents in that category were filed in the time period of the report.

The principal elements of the nondocketed items are:



1. Nondocketed category
2. NRC Accession Number (year, month, day, and sequence number of item)
3. NRC Report Number
4. Title and description of information contained in the document
5. Personal author(s). An asterisk in this position indicates that there is no personal author.
6. Corporate, agency or other nonindividual source.
7. Contract or financial (FIN) number (if any). If the document has a secondary report number, it will appear following this entry.
8. Secondary report number assigned by originator.
9. Date of document described.
10. NRC organizational recipient.
11. Pages in document.
12. All NUREG-series documents are available for purchase at NRC. Information on ordering documents is given below. All NUREG-series documents are also available at NTIS. Information on ordering from NTIS is also given below.
13. Price for which NRC sells the document.

14. The NRC 48X microfiche designation for this document. This five-digit portion of this entry is the number of the microfiche copy of this document that is available to NRC staff who have access to 48X microfiche files.
15. This three-digit portion of this entry is the number of the frame on which this document starts.

The Nondocketed Items list is arranged sequentially by Accession Number within category. Indented items preceded by a dash are enclosures to unindented items.

NOTES:

1. The address for NRC is:

Director
Division of Technical Information and Document Control
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

To place orders, send check or money order, payable to the Superintendent of Documents. GPO Deposit Account holders may charge their orders by calling (301) 492-9530.

2. The address for NTIS is:

National Technical Information Service
Springfield, Virginia 22161

To place orders for or to obtain price information about NRC publications at NTIS, either write to NTIS or call the Sales Desk at (703) 557-4650. Specify the NRC report number and title when you place your order. Publications can be charged to American Express credit cards; supply the chargecard number when placing your order

3. The address for the PDR is

1717 H Street, N.W.
Washington, D.C. 20555

To place orders, either write to the NRC PDR or call (202) 634-3274. When ordering documents listed in this publication, please identify the Document Accession Number for each citation.

Paper copy and microfiche of the documents listed in this title list may be purchased. Reproduction charges for duplication are as follows: (1) paper to paper is \$0.05 per page except for oversized documents and engineering drawings, which vary from \$0.50 to \$1.00 per square foot; (2) microform to paper is \$0.05 a page for pages on microfiche and is \$0.20 a square foot for a full-size print or \$0.25 for a reduced-size print (18" x 24") of a drawing on an aperture card; and (3) microform to microform is \$0.10 per microfiche and \$0.20 per aperture card. Orders completed for mailing or for a special delivery service will have an additional fee for the actual mailing, shipping, or delivery service rate. Unless a user requests special packing materials, there is no additional charge by the contractor for handling and wrapping materials.

Please acknowledge a willingness to assume charges for all orders but do not send payments. Orders will be processed and mailed with a bill from Literature Research Company. An account may be established with the Literature Research Company by calling (703)-941-8018.

ARRANGEMENT OF ITEMS BY DOCKET NUMBER

Docket	Name	Page	Docket	Name	Page
Low Level Radwaste Disposal Sites — Docket 27			40-8102	Exxon Co USA, Houston, TX	6
27-039	Sheffield, IL, U.S. Ecology, Inc	1	40-8135	Minnesota Mining & Manufacturing, St. Paul, MN	6
27-047	Barnwell, SC, Chem-Nuclear Systems, Inc	1	40-8200	Cleveland-Cliffs Iron Co , Casper, WY	6
27-048	Richland, WA, U S Ecology, Inc	1	40-8348	Minerals Exploration Co., Los Angeles, CA	6
Domestic Licensing of Source Material — Docket 40			40-8355	Amax Speciality Metals Corp., Parkersburg, WV	6
40-0017	Dow Chemical Co., Midland, MI	1	40-8380	Rocky Mountain Energy Co , Broomfield, CO	6
40-0086	W. R. Grace & Co., Pompton Plains, NJ	1	40-8452	Bear Creek Uranium Co , Casper, WY	6
40-0299	Union Carbide Corp , Grand Junction, CO	1	40-8511	Cotter Corp., Golden, CO	6
40-1162	Western Nuclear Corp., Jeffrey City, WY	1	40-8584	Minerals Exploration Co , Los Angeles, CA	6
40-1341	Tennessee Valley Authority, Chattanooga, TN	2	40-8602	Silver King Mines, Inc , Casper, WY	7
40-1478	Spencer Chemical Co , Kansas City, MO	2	40-8610	Stepan Chemical Co , Maywood, NJ	7
40-1606	Vitro Engineering Co.	2	40-8681	Energy Fuels Nuclear, Inc , Denver, CO	7
40-2061	Kerr-McGee Chemical Corp., Oklahoma City, OK	2	40-8697	Rocky Mountain Energy Co , Denver, CO	7
40-2116	Vitro Engineering Co.	2	40-8698	Plateau Resources, Ltd., Grand Junction, CO	7
40-2259	Pathfinder Mines Corp., Riverton, WY	2	40-8728	Teton Exploration Drilling Co., Inc., Casper, WY	7
40-3265	Vitro Engineering Co.	3	40-8743	Conoco, Inc , Denver, CO	7
40-3392	Allied Chemical Corp., Morristown, NJ	3	40-8745	Ogle Petroleum, Inc , Casper, WY	8
40-3453	Atlas Mineral, Inc., Denver, CO	3	40-8752	Pinal Minerals & Mining, Ltd., Miami, AZ	8
40-4492	Federal-American Partners, Riverton, WY	3	40-8768	Kerr-McGee Nuclear Corp., Oklahoma City, OK	8
40-6500	Energy, Dept. of, Canonsburg, PA	3	40-8771	Melapai Resources Co , Phoenix, AZ	8
40-6622	Pathfinder Mines Corp., Shirley Basin, WY	5	40-8781	Teton Exploration Drilling Co., Inc. Casper, WY	8
40-6659	Getty Oil Co. - Petrochemicals Co., Shirley Basin, WY	5	40-8783	Uranerz USA, Inc., Casper, WY	8
40-6940	Kawecki Berylo Industries, Inc., Boyertown, PA	5	40-8786	Uranium Resources, Inc., Richardson, TX	8
40-7086	Army, Dept. of, White Sands, NM	5	Domestic Licensing of Production and Utilization Facilities — Docket 50		
40-8006	Kerr-McGee Corp., Oklahoma City, OK	5	50-3	Indian Point Station, Unit 1	8
40-8027	Kerr-McGee Nuclear Corp., Oklahoma City, OK	5	50-5	Pennsylvania State Univ. Research Reactor	10
40-8064	Exxon Minerals Co. USA, Houston, TX	5	50-10	Dresden Nuclear Power Station, Unit 1	10
40-8084	Rio Algom Corp., Moab, UT	5			

Docket	Name	Page	Docket	Name	Page
50-13	Babcock & Wilcox Co., Critical Facility	11	50-237	Dresden Nuclear Power Station, Unit 2	32
50-20	Massachusetts Institute of Technology Research Reactor	12	50-243	Oregon State Univ Research Reactor	37
50-25	Dow Chemical Co. TRIGA Reactor	12	50-244	Robert Emmet Ginna Nuclear Plant, Unit 1	37
50-27	Washington State Univ. Research Reactor	12	50-245	Millstone Nuclear Power Station, Unit 1	39
50-29	Yankee-Rowe Nuclear Power Station	12	50-246	Advanced Critical Reactor Experiment	41
50-54	Union Carbide Research Reactor	14	50-247	Indian Point Station, Unit 2	41
50-70	General Electric Test Reactor	14	50-249	Dresden Nuclear Power Station, Unit 3	48
50-83	Univ of Florida Training Reactor	14	50-250	Turkey Point Plant, Unit 3	51
50-89	General Atomic Co	14	50-251	Turkey Point Plant, Unit 4	54
50-97	Cornell Univ. Zero Power Reactor	15	50-254	Quad-Cities Station, Unit 1	56
50-111	North Carolina State Univ. Research Reactor	15	50-255	Palisades Nuclear Plant	59
50-112	Univ. of Oklahoma Research Reactor	15	50-259	Browns Ferry Nuclear Power Station, Unit 1	62
50-124	Virginia Polytech Institute Training Reactor	15	50-260	Browns Ferry Nuclear Power Station, Unit 2	65
50-128	Texas A&M Univ. Research Reactor	16	50-261	H. B Robinson Plant, Unit 2	68
50-129	West Virginia Univ. Research Reactor	16	50-262	Brigham Young Univ Research Reactor	70
50-133	Humboldt Bay Power Plant, Unit 3	16	50-263	Monticello Nuclear Generating Plant	70
50-142	UCLA Training Reactor	16	50-265	Quad-Cities Station, Unit 2	72
50-148	Univ. of Kansas Research Reactor	16	50-266	Point Beach Nuclear Plant, Unit 1	75
50-150	Ohio State Univ Research Reactor	16	50-267	Fort St Vrain Nuclear Generating Station	77
50-151	Univ of Illinois Research Reactor	17	50-269	Oconee Nuclear Station, Unit 1	80
50-155	Big Rock Point Nuclear Plant	17	50-270	Oconee Nuclear Station, Unit 2	82
50-156	Univ. of Wisconsin Research Reactor	20	50-271	Vermont Yankee Nuclear Power Station	83
50-157	Cornell Univ. Research Reactor	20	50-272	Salem Nuclear Generating Station, Unit 1	85
50-163	General Atomic Co	20	50-275	Diablo Canyon Nuclear Power Plant, Unit 1	87
50-170	National Naval Medical Center	20	50-277	Peach Bottom Atomic Power Station, Unit 2	92
50-182	Purdue Univ. Research Reactor	21	50-278	Peach Bottom Atomic Power Station, Unit 3	95
50-184	National Bureau of Standards Reactor	21	50-280	Surry Power Station, Unit 1	98
50-186	Univ. of Missouri Research Reactor	21	50-281	Surry Power Station, Unit 2	101
50-187	Space Radiation Research Reactor	21	50-282	Prairie Island Nuclear Station, Unit 1	105
50-193	Rhode Island & Providence Plantations AEC	21	50-285	Fort Calhoun Station, Unit 1	106
50-201	West Valley Reprocessing Plant	21	50-286	Indian Point Station, Unit 3	109
50-206	San Onofre Nuclear Station, Unit 1	21	50-287	Oconee Nuclear Station, Unit 3	114
50-213	Haddam Neck Plant	25	50-289	Three Mile Island Nuclear Station, Unit 1	116
50-219	Oyster Creek Nuclear Power Plant	27	50-293	Pilgrim Nuclear Power Station, Unit 1	121
50-220	Nine Mile Point Nuclear Station, Unit 1	31	50-295	Zion Nuclear Power Station, Unit 1	122
50-225	RPI Critical Experiment	32	50-296	Browns Ferry Nuclear Power Station, Unit 3	126

Docket	Name	Page	Docket	Name	Page
50-298	Cooper Nuclear Station	129	50-352	Limerick Generating Station, Unit 1	217
50-301	Point Beach Nuclear Plant, Unit 2	131	50-353	Limerick Generating Station, Unit 2	220
50-302	Crystal River Nuclear Plant, Unit 3	133	50-354	Hope Creek Nuclear Station, Unit 1	223
50-304	Zion Nuclear Power Station, Unit 2	135	50-355	Hope Creek Nuclear Station, Unit 2	224
50-305	Kewaunee Nuclear Power Plant	138	50-356	Univ of Illinois LOPRA Research Reactor	224
50-306	Prairie Island Nuclear Station, Unit 2	140	50-358	William H Zimmer Nuclear Station, Unit 1	224
50-309	Maine Yankee Atomic Power Plant	141	50-361	San Onofre Nuclear Station, Unit 2	228
50-311	Salem Nuclear Generating Station, Unit 2	144	50-362	San Onofre Nuclear Station, Unit 3	232
50-312	Rancho Seco Nuclear Generating Station	146	50-364	Joseph M Farley Nuclear Plant, Unit 2	235
50-313	Arkansas Nuclear One, Unit 1	149	50-366	Edwin I Hatch Nuclear Plant, Unit 2	237
50-315	Donald C. Cook Nuclear Power Plant, Unit 1	152	50-367	Bailly Generating Station	240
50-316	Donald C. Cook Nuclear Power Plant, Unit 2	155	50-368	Arkansas Nuclear One, Unit 2	240
50-317	Calvert Cliffs Nuclear Power Plant, Unit 1	157	50-369	William B. McGuire Nuclear Station, Unit 1	243
50-318	Calvert Cliffs Nuclear Power Plant, Unit 2	160	50-370	William B McGuire Nuclear Station, Unit 2	245
50-320	Three Mile Island Nuclear Station, Unit 2	162	50-373	LaSalle County Station, Unit 1	246
50-321	Edwin I. Hatch Nuclear Plant, Unit 1	165	50-374	LaSalle County Station, Unit 2	250
50-322	Shoreham Nuclear Power Station	168	50-375	Nuclear Examination Reactor	252
50-323	Diablo Canyon Nuclear Power Plant, Unit 2	171	50-382	Waterford Generating Station, Unit 3	252
50-324	Brunswick Steam Electric Plant, Unit 2	173	50-387	Susquehanna Steam Electric Station, Unit 1	256
50-325	Brunswick Steam Electric Plant, Unit 1	176	50-388	Susquehanna Steam Electric Station, Unit 2	259
50-327	Sequoyah Nuclear Plant, Unit 1	179	50-389	St. Lucie Plant, Unit 2	261
50-328	Sequoyah Nuclear Plant, Unit 2	182	50-390	Watts Bar Nuclear Plant, Unit 1	263
50-329	Midland Plant, Unit 1	184	50-391	Watts Bar Nuclear Plant, Unit 2	266
50-330	Midland Plant, Unit 2	188	50-395	Virgil C. Summer Nuclear Station, Unit 1	268
50-331	Duane Arnold Energy Center	191	50-396	Univ. of Virginia Cavalier Reactor	273
50-332	Barnwell Reprocessing Plant	194	50-397	WPPSS Nuclear Project, Unit 2	273
50-333	James A. Fitzpatrick Nuclear Power Plant	194	50-400	Shearon Harris Nuclear Power Plant, Unit 1	275
50-334	Beaver Valley Power Station, Unit 1	195	50-401	Shearon Harris Nuclear Power Plant, Unit 2	277
50-335	St. Lucie Plant, Unit 1	198	50-404	North Anna Power Station, Unit 3	278
50-336	Millstone Nuclear Power Station, Unit 2	201	50-409	La Crosse Boiling Water Reactor	278
50-338	North Anna Power Station, Unit 1	202	50-410	Nine Mile Point Nuclear Station, Unit 2	281
50-339	North Anna Power Station, Unit 2	206	50-412	Beaver Valley Power Station, Unit 2	282
50-341	Enrico Fermi Atomic Power Plant, Unit 2	209	50-413	Catawba Nuclear Station, Unit 1	282
50-344	Trojan Nuclear Plant	211	50-414	Catawba Nuclear Station, Unit 2	285
50-346	Davis-Besse Nuclear Power Station, Unit 1	213	50-416	Grand Gulf Nuclear Station, Unit 1	288
50-348	Joseph M. Farley Nuclear Plant, Unit 1	217	50-417	Grand Gulf Nuclear Station, Unit 2	293

Docket	Name	Page	Docket	Name	Page
50-423	Millstone Nuclear Power Station, Unit 3	294	STN-50-509	WPPSS Nuclear Project, Unit 5	342
50-424	Alvin W. Vogtle Nuclear Plant, Unit 1	295	50-513	WPPSS Nuclear Project, Unit 4	342
50-425	Alvin W. Vogtle Nuclear Plant, Unit 2	296	50-514	Pebble Springs Nuclear Plant, Unit 1	343
STN-50-437	Floating Nuclear Plant	296	50-515	Pebble Springs Nuclear Plant, Unit 2	343
50-438	Bellefonte Nuclear Plant, Unit 1	297	STN-50-518	Hartsville Nuclear Plant, Unit 1	343
50-439	Bellefonte Nuclear Plant, Unit 2	299	STN-50-519	Hartsville Nuclear Plant, Unit 2	344
50-440	Perry Nuclear Power Plant, Unit 1	301	STN-50-520	Hartsville Nuclear Plant, Unit 3	345
50-441	Perry Nuclear Power Plant, Unit 2	305	STN-50-521	Hartsville Nuclear Plant, Unit 4	345
50-443	Seabrook Nuclear Station, Unit 1	309	50-522	Skagit Nuclear Power Project, Unit 1	346
50-444	Seabrook Nuclear Station, Unit 2	312	50-523	Skagit Nuclear Power Project, Unit 2	347
50-445	Comanche Peak Steam Electric Station, Unit 1	316	STN-50-528	Palo Verde Nuclear Station, Unit 1	348
50-446	Comanche Peak Steam Electric Station, Unit 2	317	STN-50-529	Palo Verde Nuclear Station, Unit 2	351
STN-50-447	GESSAR-238	319	STN-50-530	Palo Verde Nuclear Station, Unit 3	353
STN-50-454	Byron Station, Unit 1	320	50-537	Clinch River Breeder Reactor	355
STN-50-455	Byron Station, Unit 2	322	STN-50-546	Marble Hill Nuclear Station, Unit 1	358
STN-50-456	Braidwood Station, Unit 1	324	STN-50-547	Marble Hill Nuclear Station, Unit 2	359
STN-50-457	Braidwood Station, Unit 2	325	STN-50-553	Phipps Bend Nuclear Station, Unit 1	361
50-458	River Bend Station, Unit 1	326	STN-50-554	Phipps Bend Nuclear Station, Unit 2	361
50-459	River Bend Station, Unit 2	328	STN-50-556	Black Fox Station, Unit 1	362
50-460	WPPSS Nuclear Project, Unit 1	328	STN-50-557	Black Fox Station, Unit 2	362
50-461	Clinton Power Station, Unit 1	329	STN-50-566	Yellow Creek Nuclear Plant, Unit 1	362
50-462	Clinton Power Station, Unit 2	332	STN-50-567	Yellow Creek Nuclear Plant, Unit 2	363
50-466	Allens Creek Nuclear Station, Unit 1	332	Domestic Licensing of Special Nuclear Material — Docket 70		
STN-50-482	Wolf Creek Generating Station	333	70-0025	Rockwell International Corp , Canoga Park, CA	363
STN-50-483	Callaway Plant, Unit 1	334	70-0027	Babcock & Wilcox Co , Lynchburg, VA	364
STN-50-485	Sterling Power Nuclear Project, Unit 1	336	70-0033	Texas Instruments, Inc., Attleboro, MA	364
STN-50-486	Callaway Plant, Unit 2	336	70-0036	Combustion Engineering, Inc , Windsor, CT	364
STN-50-488	Perkins Nuclear Station, Unit 1	336	70-0135	Babcock & Wilcox Co., Apollo, PA	364
STN-50-489	Perkins Nuclear Station, Unit 2	336	70-0143	Nuclear Fuel Services, Inc., Erwin, TN	364
STN-50-490	Perkins Nuclear Station, Unit 3	337	70-0146	Spencer Chemical Co., Kansas City, MO	366
STN-50-491	Cherokee Nuclear Station, Unit 1	337	70-0258	Illinois, Univ. of, Urbana, IL	366
STN-50-492	Cherokee Nuclear Station, Unit 2	337	70-0340	Spencer Chemical Co., Kansas City, MO	367
STN-50-493	Cherokee Nuclear Station, Unit 3	338	70-0371	UNC Naval Products, Inc , Uncasville, CT	367
STN-50-498	South Texas Project, Unit 1	338	70-0687	Union Carbide Corp., Tuxedo, NY	367
STN-50-499	South Texas Project, Unit 2	339	70-0698	Westinghouse Electric Corp., Pittsburgh, PA	367
STN-50-508	WPPSS Nuclear Project, Unit 3	341			

Docket	Name	Page	Docket	Name	Page
70-0734	GA Technologies, Inc , San Diego, CA	367	Packaging of Radioactive Material for Transport and Transportation of Radioactive Material Under Certain Conditions — Docket 71		
70-0754	General Electric Co , Pleasanton, CA	367			
70-0820	United Nuclear Corp., Wood River Junction, RI	367	71-0170	General Electric Co	371
70-0824	Babcock & Wilcox Co., Lynchburg, VA	368	71-0206	Pryor Foundry, Inc.	371
70-1100	Combustion Engineering, Inc , Windsor, CT	368	71-0370	Amersham Corp.	371
70-1113	General Electric Co , Wilmington, NC	368	71-0394	Nuclear Sources & Services, Inc.	371
70-1143	Westinghouse Electric Corp., Pittsburgh, PA	368	71-0454	Atomic Energy of Canada, Ltd.	371
70-1151	Westinghouse Electric Corp., Pittsburgh, PA	369	71-0474	Navy, Dept. of	371
70-1193	Kerr-McGee Nuclear Corp , Oklahoma City, OK	369	71-0483	Fairchild Weston Systems, Inc	371
70-1201	Babcock & Wilcox Co , Lynchburg, VA	369	71-0484	Nebraska Public Power District	371
70-1257	Exxon Nuclear Co , Inc , Richland, WA	369	71-0486	INTEC Inspection, Inc.	371
70-1308	General Electric Co., San Jose, CA	369	71-0487	Army, Dept of	371
70-1334	AVCO Everett Research Laboratory, Inc , Everett, MA	369	71-0488	Ramsey Construction & Fabricating Co., Inc.	371
70-1359	IRT Corp , San Diego, CA	369	71-0489	Sacramento Municipal Utility District	372
70-1430	Mt Sinai Hospital Medical Center, Chicago, IL	369	71-0490	Inspection Services Corp.	372
70-1621	Duquesne Light Co., Pittsburgh, PA	370	71-4909	Model GE 21PF-1, General Electric Co	372
70-2487	St Clare's Hospital, Denville, NJ	370	71-5086	Model UNC-2600, United Nuclear Corp	372
70-2792	Lower Bucks Hospital, Bristol, PA	370	71-5461	Model: ORNL TRU, Energy, Dept. of	372
70-2872	RS Holding, Inc , Cleveland, OH	370	71-5469	Model: HNPF Spent Fuel Shipping Cask, Energy, Dept. of	372
70-2895	Spectro Chem Laboratories, Inc , Franklin Lakes, NJ	370	71-5740	Model: ORNL TRU Calif., Energy, Dept. of	372
70-2926	Detroit Edison Co., Detroit, MI	370	71-5796	Model: 181375, 181361, Advanced Medical Systems, Inc.	372
70-2928	Tennessee Valley Authority	370	71-5814	Model: NRBK-41, -42 & -43, Energy, Dept of	372
70-2941	Tennessee Valley Authority, Chattanooga, TN	370	71-5907	Model: ORNL In Pile Capsule, Energy, Dept of	372
70-2949	Arizona Public Service Co., Phoenix, AZ	370	71-5939	Model GE-1500, General Electric Co.	372
70-2955	Edlow International Co., Washington, DC	370	71-5942	Model: GE-700, General Electric Co.	372
70-2957	Florida Power & Light Co., Miami, FL	370	71-5957	Model: BMI-1, Battelle Columbus Laboratory	372
70-2960	Kansas Gas & Electric Co., Wichita, KS	370	71-5971	Model: GE-200, General Electric Co.	373
70-2964	Consumers Power Co., Jackson, MI	370	71-6003	Model M-130, Energy, Dept. of	373
70-2965	Consumers Power Co., Jackson, MI	371	71-6144	Model: B-2, U.S Ecology	373
70-2968	Cleveland Electric Illuminating Co., Cleveland, OH	371	71-6347	Model: FSV-3, General Atomic Co.	373
			71-6495	Model: PADUCAH Demonstration Cask, Energy, Dept. of	373

Docket	Name	Page	Docket	Name	Page
71-6574	Model: HN-200, Hittman Nuclear & Development Corp.	373	71-9096	Model: CNS 21-300, Chem-Nuclear Systems, Inc.	374
71-6601	Model. CNS 8-120, Chem-Nuclear Systems, Inc.	373	71-9099	Model. ATR, Exxon Nuclear Idaho Co.	374
71-6717	Model 6717-B, Gamma Industries	373	71-9111	Model. CNS 6-80-2, Chem-Nuclear Systems, Inc	374
71-9001	Model. IF-300, General Electric Co.	373	71-9126	Model: 20, 20A, 50, 50A, Gamma Industries	374
71-9006	Model: 500-SU, Automation Industries, Inc	373	71-9127	Model: 100, 100A, 200, 200A, Gamma Industries	374
71-9010	Model: NLI-1/2, NL Industries, Inc	373	71-9128	Model. C-8, Gamma Industries	374
71-9015	Model. TN-8, -8L, No Users	373	71-9132	Model T-3, Energy, Dept of	374
71-9032	Model. 650, Technical Operations, Inc	373	71-9150	Model PAT-2, Energy, Dept. of	375
71-9033	Model: 660 & 660E, Technical Operations, Inc.	374	71-9151	Model: HN-100, Series 3, Hittman Nuclear & Development Corp.	375
71-9044	Model: GE-1600, General Electric Co	374	71-9156	Model. IR-50, Industrial Nuclear Co.	375
71-9073	Model. OH-142, Nuclear Packaging, Inc.	374	71-9157	Model IR-100, Industrial Nuclear Co	375
71-9079	Model. HN-100, Series 2 & 2A, Hittman Nuclear & Development Corp.	374	71-9167	Model Type B, Amersham Corp	375
71-9081	Model CNS-1600, Chem-Nuclear Systems, Inc.	374	71-9852	Model DT-14, Energy, Dept of	375
71-9086	Model. HN-100, Series 1, Hittman Nuclear & Development Corp	374	Licensing of Independent Spent Fuel Storage — Docket 72		
71-9089	Model. HN-100S, Hittman Nuclear & Development Corp.	374	72-0001	Morris Operations, General Electric Co.	375
71-9094	Model. CNS 14-195-H, Chem-Nuclear Systems, Inc.	374	72-0002	Virginia Electric & Power Co.	375

ALPHABETIC ARRANGEMENT OF DOCKET ITEMS BY FACILITY NAME

Name	Docket	Page	Name	Docket	Page
Low Level Radwaste Disposal Sites — Docket 27			Minnesota Mining & Manufacturing, St. Paul, MN	40-8135	6
Barnwell, SC, Chem-Nuclear Systems, Inc.	27-047	1	Ogle Petroleum, Inc., Casper, WY	40-8745	8
Richland, WA, U.S. Ecology, Inc.	27-048	1	Pathfinder Mines Corp., Riverton, WY	40-2259	2
Sheffield, IL, U.S. Ecology, Inc.	27-039	1	Pathfinder Mines Corp., Shirley Basin, WY	40-6622	5
Domestic Licensing of Source Material — Docket 40			Pinal Minerals & Mining, Ltd., Miami, AZ	40-8752	8
Allied Chemical Corp., Morristown, NJ	40-3392	3	Plateau Resources, Ltd., Grand Junction, CO	40-8698	7
Amax Speciality Metals Corp., Parkersburg, WV	40-8355	6	Rio Algom Corp., Moab, UT	40-8084	5
Army, Dept. of, White Sands, NM	40-7086	5	Rocky Mountain Energy Co , Broomfield, CO	40-8380	6
Atlas Mineral, Inc., Denver, CO	40-3453	3	Rocky Mountain Energy Co., Denver, CO	40-8697	7
Bear Creek Uranium Co., Casper, WY	40-8452	6	Silver King Mines, Inc , Casper, WY	40-8602	7
Cleveland-Cliffs Iron Co., Casper, WY	40-8200	6	Spencer Chemical Co., Kansas City, MO	40-1478	2
Conoco, Inc., Denver, CO	40-8743	7	Stepan Chemical Co , Maywood, NJ	40-8610	7
Cotter Corp., Golden, CO	40-8511	6	Tennessee Valley Authority, Chattanooga, TN	40-1341	2
Dow Chemical Co., Midland, MI	40-0017	1	Teton Exploration Drilling Co., Inc , Casper, WY	40-8728	7
Energy Fuels Nuclear, Inc., Denver, CO	40-8681	7	Teton Exploration Drilling Co., Inc., Casper, WY	40-8781	8
Energy, Dept. of, Canonsburg, PA	40-6500	3	Union Carbide Corp., Grand Junction, CO	40-0299	1
Exxon Co. USA, Houston, TX	40-8102	6	Uranerz USA, Inc., Casper, WY	40-8783	8
Exxon Minerals Co. USA, Houston, TX	40-8064	5	Uranium Resources, Inc., Richardson, TX	40-8786	8
Federal-American Partners, Riverton, WY	40-4492	3	Vitro Engineering Co.	40-1606	2
Getty Oil Co. — Petrochemicals Co., Shirley Basin, WY	40-6659	5	Vitro Engineering Co.	40-2116	2
Kawecki Beryllco Industries, Inc., Boyertown, PA	40-6940	5	Vitro Engineering Co.	40-3265	3
Kerr-McGee Chemical Corp., Oklahoma City, OK	40-2061	2	W. R. Grace & Co., Pompton Plains, NJ	40-0086	1
Kerr-McGee Corp., Oklahoma City, OK	40-8006	5	Western Nuclear Corp., Jeffrey City, WY	40-1162	1
Kerr-McGee Nuclear Corp., Oklahoma City, OK	40-8027	5	Domestic Licensing of Production and Utilization Facilities — Docket 50		
Kerr-McGee Nuclear Corp., Oklahoma City, OK	40-8768	8	Advanced Critical Reactor Experiment	50-246	41
Melapai Resources Co., Phoenix, AZ	40-8771	8	Allens Creek Nuclear Station, Unit 1	50-466	332
Minerals Exploration Co., Los Angeles, CA	40-8348	6	Alvin W. Vogtle Nuclear Plant, Unit 1	50-424	295
Minerals Exploration Co., Los Angeles, CA	40-8584	6	Alvin W. Vogtle Nuclear Plant, Unit 2	50-425	296

Name	Docket	Page	Name	Docket	Page
Arkansas Nuclear One, Unit 1	50-313	149	Cooper Nuclear Station	50-298	129
Arkansas Nuclear One, Unit 2	50-368	240	Cornell Univ Research Reactor	50-157	20
Babcock & Wilcox Co. Critical Facility	50-13	11	Cornell Univ Zero Power Reactor	50-97	15
Bailly Generating Station	50-367	240	Crystal River Nuclear Plant, Unit 3	50-302	133
Barnwell Reprocessing Plant	50-332	194	Davis-Besse Nuclear Power Station, Unit 1	50-346	213
Beaver Valley Power Station, Unit 1	50-334	195	Diablo Canyon Nuclear Power Plant, Unit 1	50-275	87
Beaver Valley Power Station, Unit 2	50-412	282	Diablo Canyon Nuclear Power Plant, Unit 2	50-323	171
Bellefonte Nuclear Plant, Unit 1	50-438	297	Donald C Cook Nuclear Power Plant, Unit 1	50-315	152
Bellefonte Nuclear Plant, Unit 2	50-439	299	Donald C. Cook Nuclear Power Plant, Unit 2	50-316	155
Big Rock Point Nuclear Plant	50-155	17	Dow Chemical Co TRIGA Reactor	50-25	12
Black Fox Station, Unit 1	STN-50-556	362	Dresden Nuclear Power Station, Unit 1	50-10	10
Black Fox Station, Unit 2	STN-50-557	362	Dresden Nuclear Power Station, Unit 2	50-237	32
Braidwood Station, Unit 1	STN-50-456	324	Dresden Nuclear Power Station, Unit 3	50-249	48
Braidwood Station, Unit 2	STN-50-457	325	Duane Arnold Energy Center	50-331	191
Brigham Young Univ. Research Reactor	50-262	70	Edwin I Hatch Nuclear Plant, Unit 1	50-321	165
Browns Ferry Nuclear Power Station, Unit 1	50-259	62	Edwin I Hatch Nuclear Plant, Unit 2	50-366	237
Browns Ferry Nuclear Power Station, Unit 2	50-260	65	Enrico Fermi Atomic Power Plant, Unit 2	50-341	209
Browns Ferry Nuclear Power Station, Unit 3	50-296	126	Floating Nuclear Plant	STN-50-437	296
Brunswick Steam Electric Plant, Unit 1	50-325	176	Fort Calhoun Station, Unit 1	50-285	106
Brunswick Steam Electric Plant, Unit 2	50-324	173	Fort St. Vrain Nuclear Generating Station	50-267	77
Byron Station, Unit 1	STN-50-454	320	General Atomic Co	50-89	14
Byron Station, Unit 2	STN-50-455	322	General Atomic Co	50-163	20
Callaway Plant, Unit 1	STN-50-483	334	General Electric Test Reactor	50-70	14
Callaway Plant, Unit 2	STN-50-486	336	GESSAR-238	STN-50-447	319
Calvert Cliffs Nuclear Power Plant, Unit 1	50-317	157	Grand Gulf Nuclear Station, Unit 1	50-416	288
Calvert Cliffs Nuclear Power Plant, Unit 2	50-318	160	Grand Gulf Nuclear Station, Unit 2	50-417	293
Catawba Nuclear Station, Unit 1	50-413	282	H.B. Robinson Plant, Unit 2	50-261	68
Catawba Nuclear Station, Unit 2	50-414	285	Haddam Neck Plant	50-213	25
Cherokee Nuclear Station, Unit 1	STN-50-491	337	Hartsville Nuclear Plant, Unit 1	STN-50-518	343
Cherokee Nuclear Station, Unit 2	STN-50-492	337	Hartsville Nuclear Plant, Unit 2	STN-50-519	344
Cherokee Nuclear Station, Unit 3	STN-50-493	338	Hartsville Nuclear Plant, Unit 3	STN-50-520	345
Clinch River Breeder Reactor	50-537	355	Hartsville Nuclear Plant, Unit 4	STN-50-521	345
Clinton Power Station, Unit 1	50-461	329	Hope Creek Nuclear Station, Unit 1	50-354	223
Clinton Power Station, Unit 2	50-462	332	Hope Creek Nuclear Station, Unit 2	50-355	224
Comanche Peak Steam Electric Station, Unit 1	50-445	316	Humboldt Bay Power Plant, Unit 3	50-133	16
Comanche Peak Steam Electric Station, Unit 2	50-446	317	Indian Point Station, Unit 1	50-3	8

Name	Docket	Page	Name	Docket	Page
Indian Point Station, Unit 2	50-247	41	Oyster Creek Nuclear Power Plant	50-219	27
Indian Point Station, Unit 3	50-286	109	Palisades Nuclear Plant	50-255	59
James A. Fitzpatrick Nuclear Power Plant	50-333	194	Palo Verde Nuclear Station, Unit 1	STN-50-528	348
Joseph M. Farley Nuclear Plant, Unit 1	50-348	217	Palo Verde Nuclear Station, Unit 2	STN-50-529	351
Joseph M. Farley Nuclear Plant, Unit 2	50-364	235	Palo Verde Nuclear Station, Unit 3	STN-50-530	353
Kewaunee Nuclear Power Plant	50-305	138	Peach Bottom Atomic Power Station, Unit 2	50-277	92
La Crosse Boiling Water Reactor	50-409	278	Peach Bottom Atomic Power Station, Unit 3	50-278	95
LaSalle County Station, Unit 1	50-373	246	Pebble Springs Nuclear Plant, Unit 1	50-514	343
LaSalle County Station, Unit 2	50-374	250	Pebble Springs Nuclear Plant, Unit 2	50-515	343
Limerick Generating Station, Unit 1	50-352	217	Pennsylvania State Univ. Research Reactor	50-5	10
Limerick Generating Station, Unit 2	50-353	220	Perkins Nuclear Station, Unit 1	STN-50-488	336
Maine Yankee Atomic Power Plant	50-309	141	Perkins Nuclear Station, Unit 2	STN-50-489	336
Marble Hill Nuclear Station, Unit 1	STN-50-546	358	Perkins Nuclear Station, Unit 3	STN-50-490	337
Marble Hill Nuclear Station, Unit 2	STN-50-547	359	Perry Nuclear Power Plant, Unit 1	50-440	301
Massachusetts Institute of Technology Research Reactor	50-20	12	Perry Nuclear Power Plant, Unit 2	50-441	305
Midland Plant, Unit 1	50-329	184	Phipps Bend Nuclear Station, Unit 1	STN-50-553	361
Midland Plant, Unit 2	50-330	188	Phipps Bend Nuclear Station, Unit 2	STN-50-554	361
Millstone Nuclear Power Station, Unit 1	50-245	39	Pilgrim Nuclear Power Station, Unit 1	50-293	121
Millstone Nuclear Power Station, Unit 2	50-336	201	Point Beach Nuclear Plant, Unit 1	50-266	75
Millstone Nuclear Power Station, Unit 3	50-423	294	Point Beach Nuclear Plant, Unit 2	50-301	131
Monticello Nuclear Generating Plant	50-263	70	Prairie Island Nuclear Station, Unit 1	50-282	105
National Bureau of Standards Reactor	50-184	21	Prairie Island Nuclear Station, Unit 2	50-306	140
National Naval Medical Center	50-170	20	Purdue Univ. Research Reactor	50-182	21
Nine Mile Point Nuclear Station, Unit 1	50-220	31	Quad-Cities Station, Unit 1	50-254	56
Nine Mile Point Nuclear Station, Unit 2	50-410	281	Quad-Cities Station, Unit 2	50-265	72
North Anna Power Station, Unit 1	50-338	202	Rancho Seco Nuclear Generating Station	50-312	146
North Anna Power Station, Unit 2	50-339	206	Rhode Island & Providence Plantations AEC	50-193	21
North Anna Power Station, Unit 3	50-404	278	River Bend Station, Unit 1	50-458	326
North Carolina State Univ. Research Reactor	50-111	15	River Bend Station, Unit 2	50-459	328
Nuclear Examination Reactor	50-375	252	Robert Emmet Ginna Nuclear Plant, Unit 1	50-244	37
Oconee Nuclear Station, Unit 1	50-269	80	RPI Critical Experiment	50-225	32
Oconee Nuclear Station, Unit 2	50-270	82	Salem Nuclear Generating Station, Unit 1	50-272	85
Oconee Nuclear Station, Unit 3	50-287	114	Salem Nuclear Generating Station, Unit 2	50-311	144
Ohio State Univ. Research Reactor	50-150	16	San Onofre Nuclear Station, Unit 1	50-206	21
Oregon State Univ. Research Reactor	50-243	37	San Onofre Nuclear Station, Unit 2	50-361	228

Name	Docket	Page	Name	Docket	Page
San Onofre Nuclear Station, Unit 3	50-362	232	Vermont Yankee Nuclear Power Station	50-271	83
Seabrook Nuclear Station, Unit 1	50-443	309	Virgil C. Summer Nuclear Station, Unit 1	50-395	268
Seabrook Nuclear Station, Unit 2	50-444	312	Virginia Polytech Institute Training Reactor	50-124	15
Sequoyah Nuclear Plant, Unit 1	50-327	179	Washington State Univ. Research Reactor	50-27	12
Sequoyah Nuclear Plant, Unit 2	50-328	182	Waterford Generating Station, Unit 3	50-382	252
Shearon Harris Nuclear Power Plant, Unit 1	50-400	275	Watts Bar Nuclear Plant, Unit 1	50-390	263
Shearon Harris Nuclear Power Plant, Unit 2	50-401	277	Watts Bar Nuclear Plant, Unit 2	50-391	266
Shoreham Nuclear Power Station	50-322	168	West Valley Reprocessing Plant	50-201	21
Skagit Nuclear Power Project, Unit 1	50-522	346	West Virginia Univ. Research Reactor	50-129	16
Skagit Nuclear Power Project, Unit 2	50-523	347	William B. McGuire Nuclear Station, Unit 1	50-369	243
South Texas Project, Unit 1	STN-50-498	338	William B. McGuire Nuclear Station, Unit 2	50-370	245
South Texas Project, Unit 2	STN-50-499	339	William H. Zimmer Nuclear Station, Unit 1	50-358	224
Space Radiation Research Reactor	50-187	21	Wolf Creek Generating Station	STN-50-482	333
St. Lucie Plant, Unit 1	50-335	198	WPPSS Nuclear Project, Unit 1	50-460	328
St. Lucie Plant, Unit 2	50-389	261	WPPSS Nuclear Project, Unit 2	50-397	273
Sterling Power Nuclear Project, Unit 1	STN-50-485	336	WPPSS Nuclear Project, Unit 3	STN-50-508	341
Surry Power Station, Unit 1	50-280	98	WPPSS Nuclear Project, Unit 4	50-513	342
Surry Power Station, Unit 2	50-281	101	WPPSS Nuclear Project, Unit 5	STN-50-509	342
Susquehanna Steam Electric Station, Unit 1	50-387	256	Yankee-Rowe Nuclear Power Station	50-29	12
Susquehanna Steam Electric Station, Unit 2	50-388	259	Yellow Creek Nuclear Plant, Unit 1	STN-50-566	362
Texas A&M Univ. Research Reactor	50-128	16	Yellow Creek Nuclear Plant, Unit 2	STN-50-567	363
Three Mile Island Nuclear Station, Unit 1	50-289	116	Zion Nuclear Power Station, Unit 1	50-295	122
Three Mile Island Nuclear Station, Unit 2	50-320	162	Zion Nuclear Power Station, Unit 2	50-304	135
Trojan Nuclear Plant	50-344	211	Domestic Licensing of Special Nuclear Material — Docket 70		
Turkey Point Plant, Unit 3	50-250	51	Arizona Public Service Co., Phoenix, AZ	70-2949	370
Turkey Point Plant, Unit 4	50-251	54	AVCO Everett Research Laboratory, Inc., Everett, MA	70-1334	369
UCLA Training Reactor	50-142	16	Babcock & Wilcox Co., Apollo, PA	70-0135	364
Union Carbide Research Reactor	50-54	14	Babcock & Wilcox Co., Lynchburg, VA	70-0027	364
Univ. of Florida Training Reactor	50-83	14	Babcock & Wilcox Co., Lynchburg, VA	70-0824	368
Univ. of Illinois LOPRA Research Reactor	50-356	224	Babcock & Wilcox Co., Lynchburg, VA	70-1201	369
Univ. of Illinois Research Reactor	50-151	17	Cleveland Electric Illuminating Co., Cleveland, OH	70-2968	371
Univ. of Kansas Research Reactor	50-148	16	Combustion Engineering, Inc., Windsor, CT	70-1100	368
Univ. of Missouri Research Reactor	50-186	21	Combustion Engineering, Inc., Windsor, CT	70-0036	364
Univ. of Oklahoma Research Reactor	50-112	15	Consumers Power Co., Jackson, MI	70-2965	371
Univ. of Virginia Cavalier Reactor	50-396	273	Consumers Power Co., Jackson, MI	70-2964	370
Univ. of Wisconsin Research Reactor	50-156	20			

Name	Docket	Page	Name	Docket	Page
Detroit Edison Co , Detroit, MI	70-2926	370	Atomic Energy of Canada, Ltd	71-0454	371
Duquesne Light Co., Pittsburgh, PA	70-1621	370	Fairchild Weston Systems, Inc.	71-0483	371
Edlow International Co , Washington, DC	70-2955	370	General Electric Co.	71-0170	371
Exxon Nuclear Co , Inc , Richland, WA	70-1257	369	Inspection Services Corp	71-0490	372
Florida Power & Light Co., Miami, FL	70-2957	370	INTEC Inspection, Inc.	71-0486	371
GA Technologies, Inc , San Diego, CA	70-0734	367	Model. 100, 100A, 200, 200A, Gamma Industries	71-9127	374
General Electric Co , Pleasanton, CA	70-0754	367	Model 181375, 181361, Advanced Medical Systems, Inc	71-5796	372
General Electric Co., San Jose, CA	70-1308	369	Model. 20, 20A, 50, 50A, Gamma Industries	71-9126	374
General Electric Co , Wilmington, NC	70-1113	368	Model. 500-SU, Automation Industries, Inc	71-9006	373
Illinois Univ. of, Urbana, IL	70-0258	366	Model. 650, Technical Operations, Inc.	71-9032	373
IRT Corp., San Diego, CA	70-1359	369	Model. 660 & 660E, Technical Operations, Inc.	71-9033	374
Kansas Gas & Electric Co., Wichita, KS	70-2960	370	Model: 6717-B, Gamma Industries	71-6717	373
Kerr-McGee Nuclear Corp., Oklahoma City, OK	70-1193	369	Model ATR, Exxon Nuclear Idaho Co.	71-9099	374
Lower Bucks Hospital, Bristol, PA	70-2792	370	Model. B-2, U S Ecology	71-6144	373
Mt. Sinai Hospital Medical Center, Chicago, IL	70-1430	369	Model: BMI-1, Battelle Columbus Laboratory	71-5957	372
Nuclear Fuel Services, Inc., Erwin, TN	70-0143	364	Model C-8, Gamma Industries	71-9128	374
Rockwell International Corp., Canoga Park, CA	70-0025	363	Model: CNS 14-195-H, Chem-Nuclear Systems, Inc	71-9094	374
RS Holding, Inc., Cleveland, OH	70-2872	370	Model: CNS 21-300, Chem-Nuclear Systems, Inc.	71-9096	374
Spectro Chem Laboratories, Inc., Franklin Lakes, NJ	70-2895	370	Model: CNS 6-80-2, Chem-Nuclear Systems, Inc.	71-9111	374
Spencer Chemical Co., Kansas City, MO	70-0146	366	Model CNS 8-120, Chem-Nuclear Systems, Inc.	71-6601	373
Spencer Chemical Co , Kansas City, MO	70-0340	367	Model: CNS-1600, Chem-Nuclear Systems, Inc	71-9081	374
St. Clare's Hospital, Denville, NJ	70-2487	370	Model: DT-14, Energy, Dept. of	71-9852	375
Tennessee Valley Authority	70-2928	370	Model: FSV-3, General Atomic Co	71-6347	373
Tennessee Valley Authority, Chattanooga, TN	70-2941	370	Model: GE 21PF-1, General Electric Co	71-4909	372
Texas Instruments, Inc., Attleboro, MA	70-0033	364	Model: GE-1500, General Electric Co	71-5939	372
UNC Naval Products, Inc , Uncasville, CT	70-0371	367	Model: GE-1600, General Electric Co	71-9044	374
Union Carbide Corp., Tuxedo, NY	70-0687	367	Model. GE-200, General Electric Co.	71-5971	373
United Nuclear Corp , Wood River Junction, RI	70-0820	367	Model: GE-700, General Electric Co.	71-5942	372
Westinghouse Electric Corp., Pittsburgh, PA	70-0698	367	Model: HN-100, Series 1, Hittman Nuclear & Development Corp.	71-9086	374
Westinghouse Electric Corp., Pittsburgh, PA	70-1143	368	Model HN-100, Series 2 & 2A, Hittman Nuclear & Development Corp.	71-9079	374
Westinghouse Electric Corp , Pittsburgh, PA	70-1151	369	Model: HN-100, Series 3, Hittman Nuclear & Development Corp.	71-9151	375
Packaging of Radioactive Material for Transport and Transportation of Radioactive Material Under Certain Conditions — Docket 71			Model: HN-100S, Hittman Nuclear & Development Corp.	71-9089	374
Amersham Corp.	71-0370	371	Model HN-200, Hittman Nuclear & Development Corp	71-6574	373
Army, Dept. of	71-0487	371			

Name	Docket	Page	Name	Docket	Page
Model: HNPF Spent Fuel Shipping Cask, Energy, Dept. of	71-5469	372	Model. T-3, Energy, Dept. of	71-9132	374
Model: IF-300, General Electric Co.	71-9001	373	Model: TN-8, -8L, No Users	71-9015	373
Model: IR-100, Industrial Nuclear Co.	71-9157	375	Model: Type B, Amersham Corp.	71-9167	375
Model: IR-50, Industrial Nuclear Co.	71-9156	375	Model: UNC-2600, United Nuclear Corp	71-5086	372
Model: M-130, Energy, Dept. of	71-6003	373	Navy, Dept. of	71-0474	371
Model NLI-1/2, NL Industries, Inc.	71-9010	373	Nebraska Public Power District	71-0484	371
Model: NRBK-41, -42 & -43, Energy, Dept. of	71-5814	372	Nuclear Sources & Services, Inc.	71-0394	371
Model: OH-142, Nuclear Packaging, Inc.	71-9073	374	Pryor Foundry, Inc.	71-0206	371
Model: ORNL In Pile Capsule, Energy, Dept of	71-5907	372	Ramsey Construction & Fabricating Co., Inc.	71-0488	371
Model: ORNL TRU Calif., Energy, Dept. of	71-5740	372	Sacramento Municipal Utility District	71-0489	372
Model. ORNL TRU, Energy, Dept. of	71-5461	372			
Model PADUCAH Demonstration Cask, Energy, Dept. of	71-6495	373	Licensing of Independent Spent Fuel Storage — Docket 72		
Model. PAT-2, Energy, Dept of	71-9150	375	Morris Operations, General Electric Co.	72-0001	375
			Virginia Electric & Power Co	72-0002	375

DOCKETED ITEMS

LOW LEVEL RADWASTE DISPOSAL SITES

DOCKET 27-039 SHEFFIELD, IL, U S ECOLOGY, INC

B212010476 Forwards "Tritium Migration Investigation Status Rept "
GAYNOR, R K US Ecology, Inc (Formerly Nuclear Engineering)
82/11/11 US Ecology, Inc (Formerly Nuclear Engineering) 1p
16270 210

- B212010477 "Tritium Migration Investigation Status Rept "
* US Ecology, Inc (Formerly Nuclear Engineering) 82/11/10 4pp
16270 211

DOCKET 27-047 BARNWELL, SC, CHEM-NUCLEAR SYSTEMS, INC

B212290005 Application for amends to Licenses 46-13536-01 &
46-19524-01, to reflect merger of Chem-Nuclear Sys, Inc into
Waste Mgt, Inc
HUIZENGA, H W Waste Management, Inc HUIZENGA, H W Chem-Nuclear
Systems, Inc 82/10/29 DAVIS, J O Division of Fuel Cycle &
Material Safety 1p 16607 234

B212280541 Forwards Waste Mgt, Inc & Chem-Nuclear Sys, Inc 821029 1tr
requesting amends to Licenses 46-13536-01 & 46-19524-01, to
reflect change in licensee name
REIS, H F Lowenstein, Newman, Reis, Axelrad & Toll REIS, H F Waste
Management, Inc REIS, H F Chem-Nuclear Systems, Inc 82/11/01
DAVIS, J O Office of Nuclear Material Safety & Safeguards, Director
1p 16593 049

B212230383 Forwards Amend 22 reflecting change in corporate address
effected by merger w/HMI Holdings, Inc per 821029 request
License 46-13536-01 changed to 12-13536-01
SCARAND, R A Low Level Waste Licensing Branch 82/11/23
HUIZENGA, H W Chem-Nuclear Systems, Inc 2pp 16540 248

DOCKET 27-048 RICHLAND, WA, U S ECOLOGY, INC

B212290010 Forwards revised SNM license acceptable to licensee,
providing sound basis for settlement of outstanding license
issue
SCOVILLE, J J US Ecology, Inc (Formerly Nuclear Engineering)
82/09/27 MARTIN, J Division of Waste Management 17pp
16607 216

B212230162 Amend 15 to Radioactive Matls License WN-I019-2 for US
Ecology, Inc, authorizing use of 60,000 Ci of any radioactive
matl & 36,000 kg source matl
* Washington, State of 82/10/11 26pp 16544 013

B212280538 Proposes language to be included in SNM license to insure
licensee is cognizant of continuing authority of State of
WA over licensee activities
HANBEY, M Washington, State of 82/11/30 FOMNER, R Regulations
Division 2pp 16593 050

DOMESTIC LICENSING OF SOURCE MATERIAL

DOCKET 40-0017 DOW CHEMICAL CO , MIDLAND, MI

B212020034 Forwards plan for decommissioning Midland, MI thorium slag
storage site for License STB-527
OLSON, R A Dow Chemical Co 82/10/21 PAGE, R O Division of Fuel
Cycle & Material Safety 7pp 16308 334

B212100183 Responds to 821102 1tr re movement of soil contaminated
w/thorium residues from Dow Chemical Co to Bay City site
Dow proposal requesting authorization to consolidate
contaminated soil being reviewed
DAVIS, J O Office of Nuclear Material Safety & Safeguards, Director
82/11/26 WALKER, B Michigan, State of, Dept of Public Health
3pp 16399 001

DOCKET 40-0086 W R GRACE & CO , POMPTON PLAINS, NJ

B212060509 Responds to 821108 1tr re constituent concern over thorium
contamination in Haynes, NJ "Radiological Survey of
Sheffield Brook" encl for info W/o encl
DIRCKS, W J Office of the Executive Director for Operations
82/11/26 BRADY, N F Senate 4pp 16348 006

--B212060511 Requests info re constituent M Casson 821014 1tr expressing
concern about thorium contamination in Wayne, NJ
BRADY, N F Senate 82/11/08 HAMMERER, C C Office of
Congressional Affairs 2pp 16348 010

DOCKET 40-0299 UNION CARBIDE CORP , GRAND JUNCTION, CO

B212030252 Documents 821025 telcon w/Union Carbide Corp re 1981
evaporation pond insp rept Evaporation pond erosion
protection restored w/2 ft of cobbles No further action
required
FLEMING, T E Region 4, Office of Director 82/11/23 Region 4,
Office of Director 1p 16316 359

B212060513 Requests extension until 830107 for response re GA program,
per NRC 821021 request Delay due to preparation of quarterly
repts & holidays
WONG, T Union Carbide Corp 82/11/23 WOOLSEY, R T Uranium
Recovery Licensing Branch 1p 16348 005

B212230185 Advises that 10CFR40 65 quarterly rept for third quarter
1982 will be submitted by due date but w/o info for 40CFR190
monitoring Extension for submittal of matl requested
WONG, T Union Carbide Corp 82/11/23 PETTENGILL, H Uranium
Recovery Licensing Branch 1p 16543 278

B212270074 Forwards "Reporting Requirements for Union Carbide Corp,
Third Quarter, 1982 "
WONG, T Union Carbide Corp 82/11/24 BROWN, Q D Region 4, Office
of Director 2pp 16573 001

--B212270083 "Reporting Requirements for Union Carbide Corp, Third
Quarter, 1982 "
* Union Carbide Corp 82/11/24 290pp 16573 003

B212270063 Submits review of dose calculation & compliance evaluation
of environ monitoring data for First & Second Quarters 1982,
submitted 820803 & 1007 Licensee in compliance w/ 40CFR190
SOLLEBERGER, D Low Level Waste Licensing Branch 82/12/09 Low
Level Waste Licensing Branch 4pp 16531 350

DOCKET 40-1162 WESTERN NUCLEAR CORP , JEFFREY CITY, WY

B212130105 Provides info in response to 821015 1tr Wells 17 & 25
cleaned 24-h before sampling & again on 821005 Addl cleaning
showed improvement in water quality data Disposal of spent
acid discontinued in 1977
BODDEN, O Western Nuclear, Inc (subs of Phelps Dodge Corp)
82/11/10 GARCIA, P Uranium Recovery Licensing Branch 1p
16417 257

DOCKETED ITEMS

B212030255 Discusses major findings of IE insp of tailings mgt practices at Split Rock Mill on B20901 Measures taken by licensee to control migration of tailings effective No further action required
GARCIA, P J , PETTENGILL, H J Region 4, Office of Director
B2/11/19 Region 4, Office of Director 2pp 16316 360

B212070052 Advises that sampling & analysis re environ monitoring data for Jan-June 1982 acceptable
GARCIA, P J Region 4, Office of Director B2/11/26 Region 4, Office of Director 3pp 16356 277

DOCKET 40-1341 TENNESSEE VALLEY AUTHORITY, CHATTANOOGA, TN

B212300023 Discusses monitoring program of Edgemont seep area addressing unresolved item & including chemical & radiological sampling of seep area & similar control areas Access to uninhabited area should be restricted
JOHNSON, T L Region 4, Office of Director B2/12/17 Region 4, Office of Director 3pp 16624 283

DOCKET 40-147B SPENCER CHEMICAL CO , KANSAS CITY, MO

B212380009 Addl response to FOIA request for six categories of documents re Spencer Chemical Co Forwards documents listed in App A
FELTON, J M Division of Rules and Records B2/11/29 BARNES, C Affiliation Unknown 2pp 16590 141

--B212280012 Requests correspondence re Spencer Chemical Co be sent to listed address
COBB, G H Kerr-McGee Corp B2/09/06 JOHNSON, L Atomic Energy Commission 1p 16590 144

DOCKET 40-1604 VITRO ENGINEERING CO

B212160080 Addl response to FOIA request for records re receipt, processing, storage or removal of source matl at Canonsburg, PA; Vitro Mfg Co & Vitro Rare Metals Co Forwards documents listed in App A Remaining info under review
FELTON, J M Division of Rules and Records B2/09/30 BLACK, A E Buchanan, Ingersoll, Rodewald, Kyle & Buerger 7pp 16447 312

--B212160934 Source Matl License C-3820 for Vitro Corp of America, authorizing use of 300 lbs thorium-bearing residues containing 13 lbs thorium
DELANEY, J C Atomic Energy Commission 5/7/09/09 1p 16449 015

DOCKET 40-2061 KERR-MCGEE CHEMICAL CORP , OKLAHOMA CITY, OK

B212210512 Forwards corrected paragraphs to health physics manual per telcon request
SHELLEY, W J Kerr-McGee Corp B2/11/04 NIXON, W A Uranium Fuel Licensing Branch 1p 16502 349

--B212210515 Corrected paragraphs to health physics manual
* Kerr-McGee Corp B2/10/28 2pp 16502 350

B212130432 Forwards applications to City of West Chicago & State of IL for permit to construct incinerator sys
DENNY, I L Kerr-McGee Chemical Corp (subs of Kerr-McGee Corp) B2/11/10 NIXON, W A Division of Fuel Cycle & Material Safety 23pp 16415 021

B212010487 Responds to B21015 ltr re Kerr-McGee installation of incinerator at Rare Earths Facility Action valid per Amend 2 to License STA-583 Impact on public limited to exhaust gas cleanup sys
PAGE, R O Uranium Recovery Licensing Branch B2/11/18 SPELMAN, H J West Chicago, IL 1p 16270 255

B212070474 Discusses B21116 telcon re D Mausshardt request to tour West Chicago Rare Earths facility on B21117
NIXON, W A Division of Fuel Cycle & Material Safety. B2/11/24 Division of Fuel Cycle & Material Safety 1p 16355 264

B212130237 Responds to questions re amend application raised in B21116 telcon Hood stored in Bldg 2 will be kept on factory site & protected from weather until incinerated Bldgs 10, 11, 14 & 16 surveyed Contamination minor
SHELLEY, W J Kerr-McGee Corp B2/11/29 NIXON, W A Uranium Fuel Licensing Branch 3pp 16410 332

B212270478 Objections to Amends 5 & 6 to License STA-583 Informal hearing on amends protested Assurance that new amends will employ control procedures permitted under Amend 1 & 3 requested
SPELMAN, H J West Chicago, IL SPELMAN, H J Harold J Spelman & Associates B2/11/29 MAUSSHARDT, D B Division of Fuel Cycle & Material Safety 8pp 16551 067

B212100174 Trip rept of B21117 site visit to Kerr-McGee facility at West Chicago, IL re proceeding to be followed in resolution of dispute over License Amends 5 & 6
MAUSSHARDT, D B NRC - No Detailed Affiliation Given B2/11/30 NRC - No Detailed Affiliation Given 3pp 16398 349

B212140359 Requests permission for Oak Ridge Associated Univs to perform radiological surveys on property Property may have low levels of radioactive contamination from Kerr-McGee Rare Earth Facility Soil samples taken along Kress Creek
KEPPLER, J O Region 3, Office of Director B2/11/30 Nichiren Shoshu Temple 3pp 16401 038

B212130167 Comments on Kerr-McGee B21011 proposal to extend License STA-583 for 25 yrs Kerr-McGee should remain responsible for contaminated matl while matl on site Proposal potentially conflicts w/termination requirements
SPELMAN, H J Harold J Spelman & Associates SPELMAN, H J West Chicago, IL B2/12/01 CUNNINGHAM, R E Division of Fuel Cycle & Material Safety 4pp 16414 055

B212140470 Forwards list of documents for initial record in NRC hearing re Amends 5 & 6 to license Relevant documents will be added to list w/o encl
RHINELANDER, J J Shaw, Pittman, Potts & Troubridge B2/12/01 MAUSSHARDT, D B Office of Nuclear Material Safety & Safeguards, Director 2pp 16431 319

B212270469 Comments, on behalf of Kerr-McGee, re B21011 proposal to extend license for 25-yr City of West Chicago assumes that proposal amends application for stabilization plan approval Hearing on proposed amend requested
SPELMAN, H J Harold J Spelman & Associates SPELMAN, H J West Chicago, IL B2/12/01 CUNNINGHAM, R E Division of Fuel Cycle & Material Safety 4pp 16568 354

B212100496 Ack receipt of documents designated as initial record in NRC Hearing 2 re Amends 5 & 6 to License SUA-583 Addl documents will be sent as generated
MAUSSHARDT, D B Office of Nuclear Material Safety & Safeguards, Director B2/12/02 RHINELANDER, J J Shaw, Pittman, Potts & Troubridge 1p 16389 055

DOCKET 40-2116 VITRO ENGINEERING CO

B212160080 Addl response to FOIA request for records re receipt, processing, storage or removal of source matl at Canonsburg, PA; Vitro Mfg Co & Vitro Rare Metals Co Forwards documents listed in App A Remaining info under review
FELTON, J M Division of Rules and Records B2/09/30 BLACK, A E Buchanan, Ingersoll, Rodewald, Kyle & Buerger 7pp 16447 312

--B212160505 Source Matl License C-4625 for Vitro Corp of America, authorizing use of 25,000 lbs of sludge containing U for processing
DELANEY, J C Atomic Energy Commission 5/7/03/16 Vitro Engineering Co 1p 16449 010

--B212160510 Requests that term of License C-3948 be extended to 600131 or new license be issued Effective date of renewal or new license requested by 590302
LITTEL, E G Vitro Engineering Co 5/7/02/27 DELANEY, J C Atomic Energy Commission 1p 16449 011

--B212160513 Source Matl License C-3948 for Vitro Corp of America, authorizing use of 25,000 lbs sludge containing natural U for processing
DELANEY, J C Atomic Energy Commission 5/8/01/08 LITTEL, E G Vitro Engineering Co 1p 16449 012

--B212160525 Application for source matl license to receive various quantities of sludge containing natural U concentrations of 40%-70% by weight, from Westinghouse
LITTEL, E G Vitro Engineering Co 5/7/12/26 2pp 16449 013

DOCKET 40-2259 PATHFINDER MINES CORP , RIVERTON, WY

B212070063 Advises that environ monitoring data submitted on B20831 acceptable
SOLLENGER, D Low Level Waste Licensing Branch B2/11/26 Low Level Waste Licensing Branch 4pp 16356 267

DOCKETED ITEMS

3

B212230155 Forwards "Quarterly Effluent Monitoring Rept, Jul - Sept 1982," per 10CFR40 & License Condition 54
POYSER, R W Pathfinder Mines Corp 82/11/30 SOLLENBERGER, D
Uranium Recovery Licensing Branch 1p 16544 040

--B212230163 "Quarterly Effluent Monitoring Rept, Jul - Sept 1982"
* Pathfinder Mines Corp 82/11/30 10pp 16544 041

DOCKET 40-3265 VITRO ENGINEERING CO

B212160080 Addl response to FOIA request for records re receipt, processing, storage or removal of source matl at Canonsburg, PA, Vitro Mfg Co & Vitro Rare Metals Co Forwards documents listed in App A Remaining info under review
FELTON, J M Division of Rules and Records 82/09/30 BLACK, A E
Buchanan, Ingersoll, Rodewald, Kyle & Buerger 7pp 16447 312

--B212160337 Authorizes receipt & transfer of U &/or thorium source matl
Specific license must be obtained by 610514
JOHNSON, L Atomic Energy Commission 61/04/06 Vitro
Engineering Co 1p 16448 067

--B212160341 Authorizes license to receive & possess 1 lb source matl during term of license for fabrication
DELANEY, J C Atomic Energy Commission 58/09/08 Vitro
Engineering Co 1p 16448 068

--B212160350 Application for license to receive thorium oxide from Heavy Minerals Co Requests that license authorize shipment of coated rod to Atlantic Research Corp for testing
LITTLE, E O Vitro Engineering Co 58/09/05 2pp 16448 069

DOCKET 40-3392 ALLIED CHEMICAL CORP, MORRISTOWN, NJ

B212160060 Application for Amend 5 to License SUB-926, increasing possession limit of natural U from 50 million lb to 75 million lb
CIPOLLA, A J Allied Chemical Corp 82/10/29 NIXON, W A Uranium
Fuel Licensing Branch 5pp 16447 253

--B212160067 Requests remittance of minor amend fee for review of B21029 application to amend License SUB-926
WEISS, D License Fee Management Branch 82/11/16 CIPOLLA, A J
Allied Chemical Corp 1p 16447 258

DOCKET 40-3453 ATLAS MINERAL, INC, DENVER, CO

B212030281 Forwards Securities & Exchange Commission 10-K Rept & Annual Financial Rept for FY82, supplementing B21029 submittal re surety agreement w/UT Board of Oil, Gas & Mining
BLUBAUGH, R E Atlas Minerals 82/11/09 SMITH, R D Uranium
Recovery Licensing Branch 21pp 16322 266

--B212030282 Annual Financial Rept, 1982
FARLEY, E R Atlas Minerals 82/09/14 45pp 16322 288

B212270401 Forwards "Gamma Survey of Tailings Pond & Perimeter, Third Quarter 1982"
EDWARDS, D L Atlas Minerals 82/11/22 SMITH, R D Uranium
Recovery Licensing Branch 1p 16590 003

--B212270405 "Gamma Survey of Tailings Pond & Perimeter, Third Quarter 1982"
* Atlas Minerals 82/11/22 73pp 16590 004

B212290123 Responds to B21104 ltr re location for background air particulate monitoring site Location of Site 5 satisfactory provided NRC objective is to determine radionuclide concentrations representative of source
BLUBAUGH, R E Atlas Minerals 82/12/02 PETTINGILL, H Region 4,
Office of Director 2pp 16606 332

DOCKET 40-4492 FEDERAL-AMERICAN PARTNERS, RIVERTON, WY

B212070407 Forwards chemical data for water samples omitted from semiannual rept for Jan-June 1982
ANDRUS, N J Federal American Partners 82/11/08 GILLEN, D Office
of Nuclear Material Safety & Safeguards, Director 30pp 16356 197.

B212010295 Submits review of second half of 1981 environ monitoring rept & air sampling data omitted from first half rept
Control TLD should be added TLDs at old camp may be deleted
Map showing monitoring locations should be updated
GILLEN, D M Region 4, Office of Director 82/11/22 Region 4,
Office of Director 5pp 16271 272

B212230170 Lists info which would suppl record & facilitate more knowledgeable final decision on approval/disapproval of proposed in-pit tailings disposal plan
ACKERMAN, W C Wyoming, State of 82/11/24 ANDRUS, N Federal
American Partners 4pp 16544 009

DOCKET 40-6500 ENERGY, DEPT OF, CANONSBURG, PA

B212170405 Forwards DEB, "Remedial Actions at Former Vitro Rare Metals Plant Site, Canonsburg, WA County, PA"
CAMPBELL, R H Energy, Dept of 82/12/03 NIXON, W A Uranium Fuel
Licensing Branch 5pp 16481 001

--B212170409 "Remedial Actions at Former Vitro Rare Metals Plant Site, Canonsburg, WA County, PA"
* Energy, Dept of DOE/EIS-0096-0 82/11/30 574pp
16481 009

B212160080 Addl response to FOIA request for records re receipt, processing, storage or removal of source matl at Canonsburg, PA, Vitro Mfg Co & Vitro Rare Metals Co Forwards documents listed in App A Remaining info under review
FELTON, J M Division of Rules and Records 82/09/30 BLACK, A E
Buchanan, Ingersoll, Rodewald, Kyle & Buerger 7pp 16447 312

--B212160082 Forwards recent correspondence re facility
DUBINSKI, L Atomic Energy Commission 63/11/08 KIRKMAN, R W
Atomic Energy Commission 1p 16448 245

--B212160097 Forwards 630715 ltr to AEC from Vitro describing proposal for temporary storage of tailings & for decontamination of bldgs & equipment at facility Ltr dtd 630814 amending license & decontamination limits encl
NUSSBAUMER, D A Atomic Energy Commission 63/11/08 GERUSKY, T
Pennsylvania, State of 2pp 16448 247

--B212160105 Forwards followup insp rept for License SUC-315 on 621220 Noncompliance noted failure to decontaminate bldgs & unauthorized entry into facility
CLEVELAND, R S Atomic Energy Commission 63/10/25 PRICE, E R
Atomic Energy Commission 3pp 16448 248

--B212160123 Advises that insp rept of License SUC-315 should be completed immediately despite lack of results on analytical samples
DUBINSKI, L Atomic Energy Commission 63/10/23 KIRKMAN, R W
Atomic Energy Commission 1p 16448 264

--B212160131 Provides results of resurvey of Bldgs 14 & 16 Bldg 14 had U tailings Tailings removed & properly packaged for disposal Bldg 16 radiation level unchanged
MURPHY, J D Allied-Crossroads Nuclear Corp 66/01/11 RUDER, R T
Vitro Engineering Co 1p 16447 358

--B212160140 Forwards 31 soil, sludge, water & vegetation samples for analysis
KIRKMAN, R W Atomic Energy Commission 63/10/17 SILL, C W
Atomic Energy Commission 1p 16448 269

--B212160144 Thirty-one soil, sludge, water & vegetation samples
* Atomic Energy Commission 65/10/11 3pp

--B212160161 Provides results of close-out survey at facility, including lagoon area, plant area & Bldgs 14 & 16 Related info encl
NELSON, P R Atomic Energy Commission 63/11/07 Atomic Energy
Commission 9pp 16448 030

--B212160168 Confirms ER Resner of AEC 631007 visit to facility to collect grab samples, per telcon
CURRAN, J E Vitro Engineering Co 63/10/03 BUCKLEY, F J
Buckley Insurance Agency 1p 16448 274

--B212160182 Requests final close-out facility insp as soon as practicable Final survey results supplied by
Allied-Crossroads Nuclear Corp forwarded to Region 1 on 631005
BROCKETT, T W Atomic Energy Commission 65/10/07 NELSON, R
Atomic Energy Commission 1p 16448 039

DOCKETED ITEMS

- B212160191 Confirms that licensee 630717 & 26 ltrs in response to 630628 followup ltr completes enforcement action re insp of License SUC-315 on 621220. 630103 & 0218 Followup Insp should be conducted to determine progress
PAGE, R O Atomic Energy Commission 63/09/18 DUBINSKI, L Atomic Energy Commission 1p 16448 277
- B212160193 Forwards Allied-Crossroads health physics survey rept re facility Related info encl
MURPHY, J D Allied-Crossroads Nuclear Corp 65/09/30
NUSSBAUMER, D A Atomic Energy Commission 3pp 16448 041
- B212160197 Requests that during followup facility insp representative samples be obtained from specific locations & analyzed for natural U & thorium. Th-230 & Ra-226
NUSSBAUMER, D A Atomic Energy Commission 63/09/12 PAGE, R O Atomic Energy Commission 1p 16448 278
- B212160214 Advises that AEC license required for possession of stored U residues contained by weight more than 0.05% AEC authorization required to dispose of or transfer matl by methods not specified by 10CFR20
NUSSBAUMER, D A Atomic Energy Commission 63/09/13 TERRELL, J O Health & Human Services, Dept of, 1p 16448 279
- B212160243 Discusses 630812 meeting w/ JE Van Zandt re current status of problems associated w/ Vitro Corp of America in Canonsburg, PA. Licensee responsible for control of tailings until adequate disposal method determined
LOHL, D Atomic Energy Commission 63/08/12 DUBINSKI, L Atomic Energy Commission 2pp 16448 282
- B212160240 Amends Condition B of License SUA-315 for storage & decontamination only at facility. Results of analyses & surveys after decontamination showing that conditions specified in 630502 ltr have been met requested
NUSSBAUMER, D A Atomic Energy Commission 63/08/14 1p 16448 057
- B212160244 Health physics survey conducted at Vitro Rare Metals Plant in Canonsburg, PA. Related info encl
MURPHY, J D Vitro Engineering Co 63/07/24 8pp 16448 290
- B212160273 Source Matl License SUA-315 for Vitro Corp of America to store 23 tons of U contained in 4.45B tons of milling by-product residual matl only at facility in accordance w/ procedures of 610521 application
NUSSBAUMER, D A Atomic Energy Commission 61/06/23 1p 16448 058
- B212160284 Forwards 630607 memo from Region 1 requesting that licensee be contacted in order to determine status of property w/ respect to ownership & possession
DUBINSKI, L Atomic Energy Commission 63/06/11 PRICE, E R Atomic Energy Commission 1p 16448 300
- B212160307 Requests addl info re description of storage area including procedures & facilities used to prevent unauthorized persons from entering area & procedures for preventing spread of airborne radioactive contamination while in storage
NUSSBAUMER, D A Atomic Energy Commission 61/05/29 LITTEL, E G Vitro Engineering Co 1p 16448 061
- B212160315 Forwards application for source matl license to cover possession of stockpiles of residu still on hand. Pending completion of disposal arrangement, negotiations re proposed new source matl license should be issued
LITTEL, E G Vitro Engineering Co 61/05/12 Atomic Energy Commission 2pp 16448 062
- B212160352 Source Matl License R-179 for Vitro Corp of America, authorizing use of 48,000 tons of milling byproduct residue matl containing 0.5% U-238 on dry basis through import from Canada
JOHNSON, L Atomic Energy Commission 56/08/16 1p 16448 319
- B212160362 Discusses burial of U bearing residues at facility. Licensee covered by timely application until burial operation & facility satisfactorily completed
BROCKETT, T W Atomic Energy Commission 65/08/03 Atomic Energy Commission 2pp 16448 071
- B212160370 Confirms 650615 telcon re burial of U bearing residues at facility. Removal of U residues not begun but state has given permission. Effort may not be completed until Sept, 1965
BROCKETT, T W Atomic Energy Commission 65/06/15 KIRKMAN, R W, DAVIS, J G, HAGEMAN, R C Atomic Energy Commission 1p 16448 073
- B212160388 Discusses burial of U bearing residues at Canonsburg, PA by Vitro Corp of America. State must issue permit. Region 1 will make closeout check survey
DUBINSKI, L Atomic Energy Commission 65/03/10 KIRKMAN, R W, DAVIS, J G, HAGEMAN, R C Atomic Energy Commission 1p 16448 078
- B212160424 Discusses Div of Compliance insp of facility. Licensee wants to sell property & has prospective buyer. Residue stockpile must be disposed of first
BLARCOM, E C Atomic Energy Commission 63/03/13 Atomic Energy Commission 3pp 16448 328
- B212160432 Advises of 630212 insp of facility status of compliance w/ 10CFR30, "Licensing of Byproduct Matl," 10CFR40, "Control of Source Matl" & 10CFR20, "Stds for Protection Against Radiation." Records re regulations should be available
KIRKMAN, R W Atomic Energy Commission 63/02/11 DIBB, G Vitro Engineering Co 1p 16448 362
- B212160435 Application to renew License SUC-315, formerly operated by Vitro Rare Metals Co
LITTEL, E G Vitro Engineering Co 64/06/02 NUSSBAUMER, D A Atomic Energy Commission 3pp 16448 139
- B212160436 Advises of 630212 insp of records re status of compliance w/ 10CFR30, "Licensing of Byproduct Matl," 10CFR40, "Control of Source Matl" & 10CFR20, "Stds for Protection Against Radiation." Records re regulations should be available
KIRKMAN, R W Atomic Energy Commission 63/02/01 DIBB, G Vitro Engineering Co 1p 16449 001
- B212160459 Notifies that facility bldgs & grounds w/ exception of area fenced off around pile of radioactive contaminated soil & matl, are released for occupancy
LISBON, J Pennsylvania, State of 64/04/24 CURRAN, J Vitro Engineering Co 1p 16448 154
- B212160464 "Health Physics Survey of Vitro Former Rare Metals Plant, Canonsburg, PA."
MURPHY, J D Atomic Energy Commission 64/03/19 4pp 16448 162
- B212160466 Advises of 630103 insp re status of compliance w/ 10CFR30, "Licensing of Byproduct Matl," 10CFR40, "Control of Source Matl" & 10CFR20, "Stds for Protection Against Radiation." Records re regulation should be available
KIRKMAN, R W Atomic Energy Commission 62/12/27 BRANNAN, C D, CURRAN, J Vitro Engineering Co 1p 16449 002
- B212160471 Advises of 621220 insp of facility & status of compliance w/ 10CFR30, "Licensing of Byproduct Matl," 10CFR40, "Control of Source Matl" & 10CFR20, "Stds for Protection Against Radiation." Records should be available
KIRKMAN, R W Atomic Energy Commission 62/12/12 BRANNAN, C D, CURRAN, J Vitro Engineering Co 1p 16449 003
- B212160485 Analytical results of samples collected by Region 1 during followup insp on 631009
* Atomic Energy Commission 63/10/09 3pp 16448 168
- B212160506 Partial results of environ samples from facility area
* Atomic Energy Commission 63/11/20 6pp 16448 221
- B212160516 Forwards trip rept of meeting w/ PA State Health & Vitro Corp of America re facility
DUBINSKI, L Atomic Energy Commission 63/11/21 KIRKMAN, R W Atomic Energy Commission 1p 16448 228
- B212160527 Discusses insp of activities under License SUC-315 on 631009 at Canonsburg, PA & on 631016 in NY. Noncompliance noted. Failure to conduct survey of unrestricted areas outside fenced restricted area at facility
PRICE, E R Atomic Energy Commission 63/11/11 LITTEL, E G Vitro Engineering Co 3pp 16448 239
- B212160583 Forwards EC Van Blarcom 631105 memo re Div of Compliance insp of facility
DUBINSKI, L Atomic Energy Commission 63/11/08 KIRKMAN, R W Atomic Energy Commission 2pp 16448 242
- B212160587 Discusses reinsp of facility. Final disposition of old radium bearing tailings not resolved
VAN BLARCOM, E Atomic Energy Commission 63/11/05 Atomic Energy Commission 1p 16448 244
- 621220010 Forwards "Results of Radiological Survey at Canonsburg Bit# Vicinity Property CA 133," per 791221 ltr
NOTT, W E Energy, Dept of 82/10/26 SCARANO, R A Uranium Recovery Licensing Branch 1p 16529 103

DOCKETED ITEMS

5

--8212220013 "Results of Radiological Survey at Canonsburg Site Vicinity
Property CA 133 "
* Oak Ridge National Laboratory 82/09/30 49pp 16529 104

DOCKET 40-6622 PATHFINDER MINES CORP , SHIRLEY BASIN, WY

8212030270 Issues Amend 11 to License SUA-442, revising Condition 28 to delete ref to piezometer T-5 & to require installation of new piezometer in northern abutment section
SMITH, R D Region 4, Office of Director 82/11/19 Pathfinder Mines Corp 2pp 16316 309

--8212030272 Recommends issuance of amend to License SUA-442, revising Condition 28 to delete ref to piezometer T-5 & to require installation of new piezometer in northern abutment section
GARCIA, P J , PETTENGILL, H J Region 4, Office of Director 82/11/19 Region 4, Office of Director 4pp 16316 311

8212230079 Forwards analysis of samples taken from tailings pond wells on 820812 Tailings water quality monitoring data for 1982 requested to help determine if discrepancy between wells exists
LIDSTONE, C Wyoming, State of 82/12/02 PETTENGILL, H Uranium Recovery Licensing Branch 11pp 16344 327

8212300129 Forwards sample analyses performed by Camp Dresser & McKee on Pathfinder Shirley Basin tailing pond well samples
Trip rept dtd 820817 & C Schugarts 820927 ltr re corrected rept encl
LIDSTONE, C Wyoming, State of 82/12/02 PETTENGILL, H Uranium Recovery Licensing Branch 11pp 16624 232

8212290132 Forwards "Environ Monitoring Data W/Dose Calculations, Third Quarter 1982 "
SMITH, J C Pathfinder Mines Corp 82/12/09 SOLLENDERGER, D Uranium Recovery Licensing Branch 1p 16606 294

--8212290136 "Environ Monitoring Data W/Dose Calculations, Third Quarter 1982 "
* Pathfinder Mines Corp 82/12/09 27pp 16606 295

DOCKET 40-6659 GETTY OIL CO - PETROTONICS CO , SHIRLEY BASIN, WY

8212230084 Requests ruling on effect of proposed corporate mod on license Planned change would not affect property ownership of mine & mill facilities
YOUNG, O S Getty Oil Co (Petrotonics) 82/12/02 PETTENGILL, H Uranium Recovery Licensing Branch 1p 16544 325

8212270325 Informs that data necessary to complete 10CFR40 65 & 40CFR190 repts has not been received Repts should be submitted no later than 821221
PFAFF, S J Getty Oil Co (Petrotonics) 82/12/07 JONES, S Uranium Recovery Licensing Branch 1p 16585 324

DOCKET 40-6940 KAWECKI BERYLCO IND , INC , BOYERTOWN, PA

8212020122 Trip rept of 821118 visit to Boyertown & Reading, PA facilities & 821119 visit to Revere, PA facility re license renewal
WYNGARDEN, S D Office of Nuclear Material Safety & Safeguards, Director 82/11/24 CROW, W T Office of Nuclear Material Safety & Safeguards, Director 1p 16308 299

8212230389 Forwards list of environ questions requiring written response in order to complete review of environ info submitted on 820806 as part of renewal action for License 5HB-520
WYNGARDEN, S Uranium Fuel Licensing Branch 82/12/13 COYLE, F T Kaweck Berylco Industries, Inc 5pp 16540 234

DOCKET 40-7086 ARMY, DEPT OF, WHITE SANDS, NM

8212210412 IE Insp Findings & Licensee Ack dtd 821208-10 of License SUB-734 Insp findings no violations observed
SHOPPENN, N M Region 4, Office of Director 82/12/10 2pp 16493 086

DOCKET 40-8006 KERR-MCGEE CORP , OKLAHOMA CITY, OK

8212210184 IE Insp Findings & Licensee Ack dtd 821116 of License SUB-736 Insp findings no violations observed Steps taken to correct violations identified during last insp verified
SHOPPENN, N M Region 4, Office of Director 82/11/16 2pp 16484 336

DOCKET 40-8027 KERR-MCGEE NUCLEAR CORP , OKLAHOMA CITY, OK

8212230379 Forwards recent sampling data for new Monitor Well 2331 Well used for groundwater chemistry monitoring associated w/ injection well
SHELLEY, W J Kerr-McGee Corp 82/12/06 KOSLA, B M Uranium Fuel Licensing Branch 2pp 16529 356

--8212230380 Sampling data for new Monitor Well 2331
WIDMANN, R K Kerr-McGee Corp 82/11/29 2pp 16529 358

8212160659 Trip rept of 821129 visit to Univ of MO in Rolla, MO & 821201 & 02 site visit to Kerr-McGee facility in Gore, OK re vendor requests to amend License SUB-1010 in area of waste injection wells
KOSLA, B , WYNGARDEN, S D , RHODES, M Uranium Fuel Licensing Branch 82/12/09 CROW, W T NRC - No Detailed Affiliation Given 2pp 16464 188

8212270563 Revision to 820901 application to amend License SUB-1010 for const of sludge processing plant Facility changes & layout revised Revisions to App A included in Sequoyah 820924 license renewal application
SHELLEY, W J Kerr-McGee Corp 82/12/10 PAGE, R O Uranium Recovery Licensing Branch 42pp 16548 308

DOCKET 40-8064 EXXON MINERALS CO USA, HOUSTON, TX

8212210536 Forwards "Expanded R&D Pilot U Solution Mine Restoration & Post-Restoration Program," in accordance w/License Conditions 28 & 29 of License SUA-1064
GILCHRIST, J E Exxon Corp 82/09/17 LINEHAN, J J Uranium Recovery Licensing Branch 1p 16502 273

--8212210542 "Expanded R&D Pilot U Solution Mine Restoration & Post-Restoration Program "
* Exxon Corp 07151 82/09/17 14pp 16502 274

8212060456 Notification of 821020 meeting w/NRC in Cheyenne, WY to discuss restoration of acid patterns & Minerals Exploration restoration
BEACH, O Wyoming, State of 82/10/07 MARTIN, L , OGLE, K , SCHMITTDIEL, P Wyoming, State of 1p 16343 310

8212010056 Reviews second quarterly rept No actions necessary as result of review
KALMAN, K L , LINEHAN, J J Region 4, Office of Director 82/11/22 Region 4, Office of Director 2pp 16271 340

8212300017 Discusses 820628-0702 insp of Highland Operation area to examine activities conducted under Licenses SUA-1139 & 1064 re radiation safety Infraction found w/SUA-1064 License Condition 13, "Restoration Phase of Monitor Wells "
KALMAN, K L , LINEHAN, J J Region 4, Office of Director 82/12/17 SMITH, R D Region 4, Office of Director 3pp 16628 188

DOCKET 40-8084 RIO ALGOM CORP , MOAB, UT

8212030278 Requests assurance that license will be extended in event Reg Guide 3.5 renewal document delayed beyond 821130 filing deadline, per 821102 telcon
HARDY, B L Rio Algom, Ltd 82/11/09 GARCIA, P Uranium Recovery Licensing Branch 1p 16322 315

8212030274 Forwards data omitted from Second Quarter 1982 environ monitoring rept
HARDY, B L Rio Algom, Ltd 82/11/16 Office of Nuclear Material Safety & Safeguards, Director 13pp 16316 294

8212060004 Reviews Rio Algom Corp 820901 land use survey No change in land use occurred that would result in significant increased impact to public or environs
WOOLSEY, R T , PETTENGILL, H J Region 4, Office of Director 82/11/19 Region 4, Office of Director 1p 16325 336

DOCKETED ITEMS

B212230404 Forwards application for renewal of License SUA-1119, authorizing use of natural U for production of U oxide as yellowcake
LAHTON, M D Rio Algom, Ltd 82/11/22 Uranium Recovery Licensing Branch 1p 16541 001

--B212230411 Application for renewal of License SUA-1119, authorizing use of natural U for production of U oxide as yellowcake
W/one oversize figure Aperture card is available in PDR
LAHTON, M D Rio Algom, Ltd 82/12/31 384pp 16541 002

B212280376 Reviews repts submitted under 40CFR190 & 10CFR40 65 requirements for Second Quarter 1982 Licensee in compliance
WOOLSEY, R T Region 4, Office of Director 82/11/29 Region 4, Office of Director 4pp 16590 165

B212270331 Forwards corrected Th-230 air particulate analyses reported in B21116 addendum to Second Quarterly Rept. 1982
HARDY, B L Rio Algom, Ltd 82/12/02 NRC - No Detailed Affiliation Given 1p 16595 325

--B212270337 Corrected Th-230 air particulate analyses reported in B21116 addendum to Second Quarterly Rept. 1982
* Rio Algom, Ltd 82/08/23 3pp 16555 326

DOCKET 40-8102 EXXON CO USA, HOUSTON, TX

G212030285 Application for administrative amend to License SUA-1139 to recycle tailings solution from tailings basin to mill for use in milling process & for transport of mill tailings to tailings basin
SHANNON, J B Exxon Corp 82/11/05 PETTENGILL, H J Uranium Recovery Licensing Branch 3pp 16316 216

B212060496 Forwards review of environ monitoring data & 40CFR190 dose assessment for Second Quarter 1982
JONES S Z Region 4, Office of Director 82/11/26 Region 4, Office of Director 5pp 16348 015

B212230063 Requests confirmation of authorization to receive 60 55-gallon drums of unprocessed U ore & 20 drums of depleted U ore
YARNICK, T P Exxon Corp 82/12/06 PETTENGILL, H J Uranium Recovery Licensing Branch 1p 16544 361

DOCKET 40-8135 MINNESOTA MINING & MANUFACTURING, ST PAUL, MN

B212220262 IE Insp Findings & Licensee Ack dtd 821213 of License 5TB-1129 Insp findings no noncompliance noted
BURGIN, R E Division of Project & Resident Programs 82/12/13 1p 16518 330

DOCKET 40-8200 CLEVELAND-CLIFFS IRON CO, CASPER, WY

B212030306 Notifies that State of NY will not release Cleveland Cliffs Iron Co from responsibility until vegetation established, probably in Spring 1983 No source matl license will be issued until corrective actions taken
CHANCELLOR, R A Wyoming State of 82/11/16 SMITH, R D Region 4, Office of Director 1p 16316 336

DOCKET 40-8348 MINERALS EXPLORATION CO, LOS ANGELES, CA

B212170438 Informs of Dept of Environ Quality position re groundwater restoration based on Aug 1982 restoration status rept if samples taken from wells at end of month show geotechnical stability then wells can be plugged & reclamation begun
ENGELMAN, R Wyoming, State of 82/11/22 ABRAMO, J Union Oil Co of California 1p 16478 134

DOCKET 40-8395 AMAX SPECIALITY METALS CORP, PARKERSBURG, WV

B212090208 Responds to B21103 ltr expressing concern over toxicity of soil samples taken from LB Foster Co site Surveys revealed presence of buried zirconium/thorium residues from pilot plant operations Air sampling revealed low radioactivity
O'REILLY, J P Region 2, Office of Director 82/11/17 LOWE, J Affiliation Unknown 2pp 16362 344

DOCKET 40-8380 ROCKY MOUNTAIN ENERGY CO, BROOMFIELD, CO

B212060456 Notification of B21020 meeting w/NRC in Cheyenne, WY to discuss restoration of acid patterns & Minerals Exploration restoration
DEACH, O Wyoming, State of 82/10/07 MARTIN, L, OGLE, K, SCHMITTDIEL, P Wyoming, State of 1p 16343 310

B212030284 Forwards requested groundwater quality data for Patterns 1, 2 & 3 at Nine Mile Lake Project Data includes well sampling results for important water quality parameters from Feb-Sept 1982
NEUMANN, M R Rocky Mountain Energy Co 82/11/01 OGLE, K M Wyoming, State of 3pp 16316 219

--B212030295 Groundwater quality data for Feb-Sept 1982
* Rocky Mountain Energy Co 82/11/01 18pp 16316 222

B212230183 Forwards pH sample analyses for Monitor Wells M-16 & M-18 & analyses for Pattern 2 U concentrations during 1 yr of stabilization monitoring, per B21118 telcon request
NEUMANN, M R Rocky Mountain Energy Co 82/11/19 KALMAN, K Uranium Recovery Licensing Branch 28pp 16540 267

B212010059 Advises that Amend 3 for License Condition 37 required submittal of surety instrument & is exempt from fees
KALMAN, K L Low Level Waste Licensing Branch LINEHAN, J J Region 4, Office of Director 82/11/22 MILLER, W O License Fee Management Branch 1p 16271 339

B212030264 Reviews Rocky Mountain Energy Co second quarterly environ monitoring rept for Apr-June 1982
KALMAN, K L, LINEHAN, J J Region 4, Office of Director 82/11/23 Region 4, Office of Director 3pp 16316 320

DOCKET 40-8452 BEAR CREEK URANIUM CO, CASPER, WY

B212030254 Informs that U Recovery Field Ofc opened in Lakewood, CO on 821004 Licensing work will continue in Washington, DC through Apr 1983 to assure least disruption during transition period
SMITH, R D Region 4, Office of Director 82/11/04 YELICH, J Bear Creek Uranium Co 2pp 16316 342

B212280079 Submits compliance evaluation of B20915 dose calculations per 40CFR190 requirements for Second Quarter 1982 Mill in compliance w/requirements
GOLLENBERGER, D Low Level Waste Licensing Branch 82/11/24 Low Level Waste Licensing Branch 3pp 16590 170

B212290157 Forwards environ monitoring rept for Third Quarter 1982, per 10CFR40 65
BLOSSOM, J H Bear Creek Uranium Co 82/12/06 Uranium Recovery Licensing Branch 1p 16606 322

--B212290161 Environ monitoring rept for Third Quarter 1982
* Bear Creek Uranium Co 82/12/06 9pp 16606 323

DOCKET 40-8511 COTTER CORP, GOLDEN, CO

B212030258 Forwards addl info addressing NRC concerns re in-plant safety portion of renewal application in response to NRC 820707 ltr
MCCLUSKEY, J P Cotter Corp 82/11/03 PETTENGILL, H J Uranium Recovery Licensing Branch 17pp 16317 324

DOCKET 40-8584 MINERALS EXPLORATION CO, LOS ANGELES, CA

B212070456 Suggests complementary review of Minerals Exploration application for amend to License SUA-1350, modifying tailings disposal scheme
ACKERMAN, W C Wyoming, State of 82/11/12 SMITH, D Uranium Recovery Licensing Branch 1p 16355 263

B212210558 Advises that on 821105, airborne concentration of radioactive matl exceeded specified limit when yellowcake spilled during packaging operations No worker exposure believed to have occurred Device to prevent overfilling will be installed
SNYDER, H L Union 76 Minerals Exploration Co 82/11/17 Director's Office, Office of Inspection and Enforcement 3pp 16529 343

DOCKETED ITEMS

7

DOCKET 40-8502 SILVER KING MINES, INC., CASPER, WY

B212230391 Comments on review of B20827 preoperational environ monitoring rept for Jan-Jul 1982 for License SUA-1356 Except for high U area monitoring data rept shows background environ levels of radionuclides
SOLLENBERGER, D Low Level Waste Licensing Branch PETTENQILL, H J
Region 4, Office of Director B2/12/14 Low Level Waste Licensing Branch 3pp 16540 229

DOCKET 40-8610 STEPAN CHEMICAL CO., MAYWOOD, NJ

B212290368 Discusses IE Insp Rept 40-8610/B2-01 conducted on B20929 No noncompliance noted Issues which need to be resolved include schedule for amending license to include thorium & rationale for depth of different boreholes
MARTIN, T T Division of Engineering & Technical Programs B2/12/15
O'BRIEN, J Stepan Chemical Co 2pp 16586 162

DOCKET 40-8681 ENERGY FUELS NUCLEAR, INC., DENVER, CO

B212070509 Forwards data sheets for Monitor Wells 1-5 & 7-2 & culinary water well chemical analyses, omitted from Second Quarter 1982 effluent & monitoring rept
BAKER, C E Energy Fuels Nuclear, Inc B2/11/15 GILLEN, D Uranium Recovery Licensing Branch 10pp 16354 275

B212020001 Discusses results of annual land use survey covering White Mesa Mill operational period from Jul 1981-Jul 1982, submitted B20806 No addl review or licensing action required
GILLEN, D M, LINEHAN, J J Region 4, Office of Director B2/11/22
Region 4, Office of Director 1p 16308 302

B212030228 Reviews Energy Fuels Nuclear B20726 tailings retention sys annual insp summary for June 1981-June 1982 Tailings retention sys operating as designed w/no major problems or conditions that would lead to failure
GILLEN, D M, LINEHAN, J J Region 4, Office of Director B2/11/23
Region 4, Office of Director 2pp 16316 337

B212030238 Summary of B20913 meeting w/Energy Fuels Nuclear in Silver Spring, MD re tailings reclamation program, reclamation costs & proposed surety arrangements
GILLEN, D M, LINEHAN, J J Region 4, Office of Director B2/11/23
Region 4, Office of Director 7pp 16317 352

B212030244 Trip rept of B21012 meeting w/Energy Fuels Nuclear in Denver, CO re long-term stability aspects of revised White Mesa tailings reclamation plan & B21013 visit to Pinal Minerals & Mining Heap Leach Site near Globe, AZ
GILLEN, D M, LINEHAN, J J Region 4, Office of Director B2/11/23
Region 4, Office of Director 3pp 16316 339

B212030251 Reviews Energy Fuels Nuclear B20827 10CFR40.65 environ monitoring rept for Apr-June 1982 Reported data within applicable limits Chemical groundwater data will be sent as suppl to second quarter rept
GILLEN, D M, LINEHAN, J J Region 4, Office of Director B2/11/23
Region 4, Office of Director 4pp 16316 355

B212290012 Forwards "Effluent & Monitoring Rept, Jul - Sept 1982"
BAKER, C E Energy Fuels Nuclear, Inc B2/11/24 GILLEN, D Uranium Fuel Licensing Branch 1p 16607 183

--B212290013 "Effluent & Monitoring Rept, Jul - Sept 1982"
* Energy Fuels Nuclear, Inc B2/11/23 32pp, 16607 184

B212280048 Reviews dose evaluation & compliance evaluation forwarded in B20827 ltr re 40CFR190 compliance for Second Quarter 1982
SOLLENBERGER, D Low Level Waste Licensing Branch B2/12/01 Low Level Waste Licensing Branch 3pp 16591 355

DOCKET 40-8697 ROCKY MOUNTAIN ENERGY CO., DENVER, CO

B212060456 Notification of B21020 meeting w/NRC in Cheyenne, WY to discuss restoration of acid patterns & Minerals Exploration restoration
BEACH, O Wyoming, State of B2/10/07 MARTIN, L, OGLE, K, SCHMITZ, P Wyoming, State of 1p 16343 310

B212230183 Forwards pH sample analyses for Monitor Wells M-16 & M-18 & analyses for Pattern 2 U concentrations during 1 yr of stabilization monitoring, per B21118 telcon request
NEUMANN, M R Rocky Mountain Energy Co B2/11/19 KALMAN, K Uranium Recovery Licensing Branch 28pp 16540 267

DOCKET 40-8698 PLATEAU RESOURCES, LTD., GRAND JUNCTION, CO

B211020241 Forwards "Earthwork QC Overview & As-Built Drawings Const of Stage I Tailings Impoundment & Dam, Shooting Canyon U Project, Garfield County, UT," per License Conditions 42 & 43
GERDEMAN, F H Plateau Resources, Ltd B2/09/17 FLEMING, T E Uranium Recovery Licensing Branch 1p 15915 249

--B211020246 "Earthwork QC Overview & As-Built Drawings Const of Stage I Tailings Impoundment & Dam, Shooting Canyon U Project, Garfield County, UT"
GORDON, B B Woodward-Clyde Consultants, Inc B2/07/28 57pp 15915 250

--B211020252 "Embankment Foundation & Blush Grouting Photographs & Geologic Map " W/one oversize map & 39 photographs Aperture card is available in PDR
* Plateau Resources, Ltd B2/09/30 12pp 15915 307

B212070045 Advises that B20924 annual land use survey for mill acceptable
FLEMING, T E, PETTENQILL, H J Region 4, Office of Director B2/11/29 Region 4, Office of Director 2pp 16355 361

B212270319 Informs that addl data re tailings dam compaction rept will be delayed due to Mountain States Mineral Enterprises law suit
GERDEMAN, F H Plateau Resources, Ltd B2/11/30 FLEMING, T E NRC - No Detailed Affiliation Given 1p 16555 323

B212300120 Notifies that submittal of requested test result data re tailings dam compaction repts will be delayed due to use of data in Mountain States Mineral Enterprises suit, per NRC B21028 request
GERDEMAN, F H Plateau Resources, Ltd B2/11/30 FLEMING, T E NRC - No Detailed Affiliation Given 1p 16624 249

B212280053 Advises that UT Div of Wildlife Resources review of Plateau Resources Ltd proposed monitoring of wildlife not necessary Recommends annual samples of fauna & biota be taken from tailings impoundment area
FLEMING, T E Region 4, Office of Director B2/12/01 Region 4, Office of Director 2pp 16592 119

B212270340 Informs that due to recent resignation of DJ Allen, RJ Carr has been appointed environ & radiological health supervisor effective B21209
GERDEMAN, F H Plateau Resources, Ltd B2/12/08 FLEMING, T E NRC - No Detailed Affiliation Given 2pp 16555 351

DOCKET 40-8728 TETON EXPLORATION DRILLING CO., INC., CASPER, WY

B212170443 Issues Amend 7 to License SUA-1373, revising License Conditions 10, 23, 25, 29 & 30 to reduce environ & in-plant radiation safety monitoring requirements between conclusion of R&D activities & startup of proposed mining operations
SMITH, R D Region 4, Office of Director B2/11/26 Teton Exploration Drilling Co., Inc 2pp 16478 135

--B212170459 Safety evaluation recommending issuance of amend to License SUA-1373, revising License Conditions 10, 23, 25, 29 & 30 to reduce environ & in-plant radiation monitoring requirements between R&D activities & startup of mining operations
ROSS, F W, LINEHAN, J J Region 4, Office of Director B2/11/26 4pp 16478 137

DOCKET 40-8743 CONOCO, INC., DENVER, CO

B212130128 Reviews Conoco, Inc application for permit to mine U ore at Moore Ranch Mine & Sand Rock Mill Project in Campbell County, WY Approval recommended w/listed stipulations
LIDSTONE, C NRC - No Detailed Affiliation Given B2/11/01 NRC - No Detailed Affiliation Given 3pp 16417 152

B212060330 Forwards correspondence w/State of WY from B00812 to B10724 re air quality permit
GUILLEY, T W CONOCO, Inc (Continental Oil Co) B2/11/18 FLEMING, T NRC - No Detailed Affiliation Given 49pp 16325 119

DOCKETED ITEMS

--B212060336 "Study of Use of Porous Wind Fences to Reduce Fugitive Dust Transport at Mohave Generating Station"
RADWY, R L, MACCREADY, P J AeroVironment, Inc AV-R-9563R
8/07/73 68pp 16325 164

B212290145 Forwards responses to USGS, WY State Engineers ofc & EPA comments on Sand Rock Mill Project
QUIGLEY, T H CONOCO, Inc (Continental Oil Co) 82/12/08
FLEMING, T NRC - No Detailed Affiliation Given 10pp 16606 284

DOCKET 40-8745 OGLE PETROLEUM, INC., CASPER, WY

B212070461 Requests advice re fulfilling radiation safety officer specialized health physics training requirements, per Amend 3, by B21231 Licensee unable to find course of adequate duration
CATCHPOLE, O J Ogle Petroleum, Inc 82/10/04 LINEHAN, J J Uranium Recovery Licensing Branch 4pp 16354 285

B212100083 Submits final rept re B21010 leak in evaporation ponds at Bison Basin Mine Liquid detected in R&D pond stand pipe
Caused by 3-inch puncture in pond line Hole patched using manufacturer recommended procedures
CATCHPOLE, O J Ogle Petroleum, Inc 82/11/10 SMITH, D Uranium Recovery Licensing Branch FRANCIS, E Wyoming, State of 11pp 16399 360

B212170404 Forwards "Second Semiannual Rept for B20222-0824"
SAUNDERS, O A Ogle Petroleum, Inc 82/11/12 SMITH, D Uranium Recovery Licensing Branch 1p 16480 013

--B212170407 "Second Semiannual Rept for B20222-0824"
* Ogle Petroleum, Inc 82/11/12 264pp 16480 014

B212070480 Forwards check covering B21004 amend request Requests extension be revised from 6 to 12 months due to slow down in offering of radiation safety courses
CATCHPOLE, O J Ogle Petroleum, Inc 82/11/15 WEISS, D License Fee Management Branch 1p 16354 274

B212030235 Reviews Ogle Petroleum, Inc B20409 excursion notification of Monitor Well M-17 & B20721 quarterly excursion rept for Monitor Wells M-14, M-17 & M-72 Well M-72 not discussed as well was covered in previous memo
YOUNG, Y A, LINEHAN, J J Region 4, Office of Director 82/11/23 Region 4, Office of Director 4pp 16317 348

B212280045 Discusses semiannual rept for Jul-Dec 1981 submitted B20420 Rept meets requirements Environ & operational data meet max permissible concentrations
LINEHAN, J J Division of Resident, Reactor Project & Engineering Programs 82/12/01 Region 4, Office of Director 3pp 16393 008

B212230219 Notifies that B21005 Unit 2 Aquifer pumping test did not adequately demonstrate ore zone confinement Test not conducted as approved by NRC Positive finding on evaluation of new test using ratio method would allow authorization
SMITH, R D Uranium Recovery Licensing Branch 82/12/07 Ogle Petroleum, Inc 2pp 16540 354

DOCKET 40-8752 PINAL MINERALS & MINING, LTD., MIAMI, AZ

B212030244 Trip rept of B21012 meeting w/Energy Fuels Nuclear in Denver, CO re long-term stability aspects of revised White Mesa tailings reclamation plan & B21013 visit to Pinal Minerals & Mining Heap Leach Site near Globe, AZ
GILLEN, D M, LINEHAN, J J Region 4, Office of Director 82/11/23 Region 4, Office of Director 3pp 16316 339

DOCKET 40-8768 KERR-McGEE NUCLEAR CORP., OKLAHOMA CITY, OK

B212100403 Forwards second & third Quarter 1982 repts for A-Sand In-Situ U Recovery R&D Project
SHELLEY, W J Kerr-McGee Nuclear Corp 82/11/09 SCARANO, R A Division of Waste Management 1p 16389 082

--B212100407 "O-Sand In-Situ U Recovery R&D Project Second Quarterly Rept, Apr-June 1982,"
* Kerr-McGee Nuclear Corp. 82/11/09 55pp 16389 083

--B212100410 "O-Sand In-Situ U Recovery R&D Project Third Quarterly Rept, Jul-Sept 1982"
* Kerr-McGee Nuclear Corp 82/11/09 52pp 16389 138

B212290149 Responds to items in NRC B21103 ltr re environ monitoring repts for First & Second Quarter 1982
FREEMAN, M S Kerr-McGee Nuclear Corp 82/12/07 LINEHAN, J J Uranium Recovery Licensing Branch 2pp 16606 282

DOCKET 40-8771 MELAPAI RESOURCES CO., PHOENIX, AZ

B212230121 Notifies that cost data requested in B21115 ltr re License Condition 5B will be provided prior to injection of lixiviant
BECK, H Malapai Resources Co 82/12/01 LINEHAN, J J Uranium Recovery Licensing Branch 1p 16544 345

DOCKET 40-8781 TETON EXPLORATION DRILLING CO., INC., CASPER, WY

B212080042 Forwards addl info re DES requested as result of public comment & review Keep hole in Figure 2-5 clarified Solid waste will be transported to Exxon licensed tailing facility
APPEL, R R United Nuclear Corp 82/11/04 LINEHAN, J J Region 4, Office of Director 4pp 16367 142

DOCKET 40-8783 URANERZ USA, INC., CASPER, WY

B212280435 Forwards third quarter rept for 1982
SOMERVILLE, K O Uranerz USA, Inc 82/10/29 LINEHAN, J J Uranium Recovery Licensing Branch 1p 16590 194

--B212280439 Third quarter rept for 1982
* Uranerz USA, Inc 82/10/29 87pp 16590 195

B212270264 Forwards raw data used in calculating upper control limits
SCHMIDT, C Uranerz USA, Inc 82/11/19 YOUNG, Y Uranium Recovery Licensing Branch 8pp 16551 047

DOCKET 40-8786 URANIUM RESOURCES, INC., RICHARDSON, TX

B212030261 Forwards decommissioning plan for wellfield & process Facility Decommissioning will begin within 90 days
PELIZZI, M S Uranium Resources, Inc 82/10/14 LINEHAN, J J Uranium Recovery Licensing Branch 1p 16317 341

--B212030263 Decommissioning plan for wellfield & process facility
* Uranium Resources, Inc 82/10/14 5pp 16317 342

B212280041 Comments on review of Resources, Inc quarterly rept (Apr 15-Jul 15, 1982) Monitor well fluid level measurements do not indicate significant problem w/wellfield balance
WESTBROOK, K D Region 4, Office of Director 20661 82/12/03 Region 4, Office of Director 3pp 16593 003

DOMESTIC LICENSING OF PRODUCTION AND UTILIZATION FACILITIES

DOCKET 50-3 INDIAN POINT STATION, UNIT 1

F Security, medical, emergency & fire protection plans

B212140359 Advises that util will conduct annual onsite drill of emergency plan on B21208 Alternate drill dates are B21201 & 15
O'TOOLE, J D Consolidated Edison Co of New York, Inc 82/11/09 HAYNES, R C Region 1, Office of Director 1p 16401 025 24X Fiche 50-003, 82/11/09, B212140353

B212220006 Staff requirements memo re B21119 briefing by FEMA on status of emergency preparedness findings Conclusions re removal of deficiencies & overall adequacy of emergency plans will be submitted between B21203 & 17
CHILK, S J Office of the Secretary of the Commission 82/11/24 Office of the Secretary of the Commission 1p 16529 151 24X Fiche 50-003, 82/11/24, B212220006

B212030124 Responds to B20902 ltr describing corrective actions re significant deficiencies identified in FEMA B20730 rept, "Interim Findings on Adequacy of Radiological Emergency Response Preparation of State & Local Govts"
HAYNES, R C Region 1, Office of Director 82/11/26 O'TOOLE, J D Consolidated Edison Co of New York, Inc 2pp 16306 296 24X Fiche 50-003, 82/11/26, B212030124

DOCKETED ITEMS

9

--B212030248 Forwards description of activities planned or underway to correct deficiencies identified in FEMA interim findings on adequacy of radiological emergency response preparedness of state & local govts, per B20803 request
O'TOOLE, J D Consolidated Edison Co of New York, Inc 82/09/02
HAYNES, R C Region 1, Office of Director 11pp 16306 298 24X
Fiche 50-003, 82/11/26, B212030124

B212220037 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 82/12/13 Document
Management Branch 1p 16527 336 24X Fiche 50-003, 82/12/13,
B212220037

--B212220042 Forwards public version of revised emergency plan implementing procedures, including Procedures IP-1001 re mobilization of onsite emergency organization & IP-1039 re offsite contamination checks
O'TOOLE, J D Consolidated Edison Co of New York, Inc 82/12/01
HAYNES, R C Region 1, Office of Director 1p 16527 337 24X
Fiche 50-003, 82/12/13, B212220037

--B212220046 Public version of revised emergency plan implementing procedures, including Procedures IP-1001 re mobilization of onsite emergency organization & IP-1039 re offsite contamination checks
FINCH, O L Consolidated Edison Co of New York, Inc 82/11/08
43pp 16527 338 24X Fiche 50-003, 82/12/13, B212220037

B212210409 Forwards Event Notification Forms Part I & II to better prepare shift crews for questions NRC duty officer may ask during emergency notification
STAROSTECKI, R Division of Project & Resident Programs 82/12/16
O'TOOLE, J D Consolidated Edison Co of New York, Inc 6pp
16493 088 24X Fiche 50-003, 82/12/16, B212210409

B212290295 Releases public version of page changes to emergency procedures document
FELTON, J M Division of Rules and Records 82/12/20 Document
Management Branch 1p 16606 086 24X Fiche 50-003, 82/12/20,
B212290295

--B212290302 Forwards public version of page changes to emergency procedures document re determination of magnitude of release & effect on offsite personnel
O'TOOLE, J D Consolidated Edison Co of New York, Inc 82/12/08
HAYNES, R C Region 1, Office of Director 1p 16606 087 24X
Fiche 50-003, 82/12/20, B212290295

--B212290308 Public version of page changes to emergency procedures document re determination of magnitude of release & effect on offsite personnel One oversize drawing encl Aperture card is available in PDR
SMITH, M Consolidated Edison Co of New York, Inc 82/11/08
20pp 16606 088 24X Fiche 50-003, 82/12/20, B212290295

I General correspondence

B212270428 Responds to B21130 ltr forwarding constituent concern re temporary suspension of hearings Approx 10 wks of hearings beginning 830110 scheduled
DICKS, W J Office of the Executive Director for Operations
82/12/20 BRADLEY, B Senate 2pp 16568 339 24X
Fiche 50-003, 82/12/20, B212270428

--B212270431 Forwards DK & FL Cinquamenl B20730 ltr requesting resumption of hearings on safety of plants
BRADLEY, R Senate 82/11/30 Office of Congressional Affairs
5pp 16568 341 24X Fiche 50-003, 82/12/20, B212270428

P Operating license stage documents & correspondence

B212070285 Notifies that radiological effluent Tech Specs & offsite dose calculation manual will be submitted by 830201 & 0401, respectively
O'TOOLE, J D Consolidated Edison Co of New York, Inc 82/12/01
VAROA, S A Operating Reactors Branch 1 1p 16339, 113, 24X
Fiche 50-003, 82/12/01, B212070285

B208190263 Generic Ltr B2-32 to all PWR licensees re potential steam generator-related generic requirements Forwards Science Applications, Inc draft rept re subj requirements Comments requested within 30 days of ltr Svc list encl
EISENHUT, D O Division of Licensing 82/12/09 Consolidated
Edison Co of New York, Inc 29pp 16627 247 24X
Fiche 50-000, 82/12/09, B208190263

--B21220096 "Value-Impact Analysis of Recommendations re Steam Generator Tube Degradations & Rupture Events," final draft
MOREHOUSE, J H, LINER, R T, JOHNSON, B W Science Applications, Inc NRC-03-B2-131 82/09/23 Division of Licensing 296pp
16629 281 24X Fiche 50-003, 82/12/09, B208190263

B212270108 Forwards Amends 31 & 32 to Licenses DPR-5 & DPR-26, respectively, safety evaluation & notice of issuance & availability Amends modify facility organization structure & testing requirements on containment isolation valves
HANNON, J N Operating Reactors Branch 1 82/12/11 O'TOOLE, J D
Consolidated Edison Co of New York, Inc 4pp 16553 200 24X
Fiche 50-003, 82/12/11, B212270108

--B212270111 Amends 31 & 32 to Licenses DPR-5 & DPR-26, respectively, modifying facility organization structure for Units 1 & 2 & testing requirements on containment isolation valves & snubber Tech Specs for Unit 2
VAROA, S A Operating Reactors Branch 1 82/12/11 39pp
16593 204 24X Fiche 50-003, 82/12/11, B212270108

--B212270113 Safety evaluation supporting Amends 31 & 32 to Licenses DPR-5 & DPR-26, respectively
* Office of Nuclear Reactor Regulation, Director 82/12/11 4pp
16593 243 24X Fiche 50-003, 82/12/11, B212270108

--B212270117 Notice of issuance & availability of Amends 31 & 32 to Licenses DPR-5 & DPR-26, respectively
VAROA, S A Operating Reactors Branch 1 82/12/11 2pp
16553 247 24X Fiche 50-003, 82/12/11, B212270108

Q Inspection reports, IE Bulletins & correspondence

B208190240 IE Bulletin B2-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc
112pp 16462 163 24X Fiche 50-000, 82/10/28, B208190240

B208190245 IE Info Notice B2-42, "Defects Observed in Panasonic Model B01 & Model B02 Thermoluminescent Dosimeters " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards
82/11/05 Consolidated Edison Co of New York, Inc 110pp
16372 142 24X Fiche 50-000, 82/11/05, B208190245

B208190251 IE Info Notice B2-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18
Consolidated Edison Co of New York, Inc 109pp 16411 197 24X
Fiche 50-000, 82/11/18, B208190251

B208190256 IE Info Notice B2-46, "Defective & Obsolete Combination Padlocks " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc
127pp 16411 065 24X Fiche 50-000, 82/11/26, B208190256

B208190257 IE Info Notice B2-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards
82/11/30 Consolidated Edison Co of New York, Inc 356pp
16387 028 24X Fiche 50-000, 82/11/30, B208190257

B208190259 IE Bulletin B2-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc
113pp 16411 317 24X Fiche 50-000, 82/12/03, B208190259

B208190261 IE Info Notice B2-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03
Consolidated Edison Co of New York, Inc 110pp 16462 044 24X
Fiche 50-000, 82/12/03, B208190261

B208190267 IE Info Notice B2-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc
127pp 16628 191 24X Fiche 50-000, 82/12/16, B208190267

B212220366 Forwards list of topic areas for discussion at upcoming meeting on drug & alcohol abuse programs instituted per IE Info Notice B2-05 One util representative should be available to participate in entire meeting
STAROSTECKI, R Division of Project & Resident Programs 82/12/16
O'TOOLE, J D Consolidated Edison Co of New York, Inc 3pp
16517 173 24X Fiche 50-003, 82/12/16, B212220366

B208190268 IE Info Notice B2-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27 " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20
Consolidated Edison Co of New York, Inc 108pp 16628 293 24X
Fiche 50-000, 82/12/20, B208190268

DOCKETED ITEMS

I Hearing transcripts on non-antitrust matters

B212300235 Transcript of Commission 821221 meeting in Washington, DC re possible action concerning emergency preparedness at Facilities Supporting documentation & viewgraphs encl
* Commissioners 82/12/21 121pp 16624 037 24X
Fiche 50-003, 82/12/21, 8212300235

DOCKET 50-5 PENNSYLVANIA STATE UNIV RESEARCH REACTOR

P Operating license stage documents & correspondence

B212030010 Informs of method for leak testing non-TRIGA (PATR) fuel elements Fuel pellets will be loaded into separate aluminum tubes & sealed by arc welding to form fuel tube Record will verify integrity
LEVINE, S H Pennsylvania State Univ 82/11/30 CARTER, R E
Standardization & Special Projects Branch 3pp 16304 231 24X
Fiche 50-005, 82/11/30, 8212030010

DOCKET 50-10 DRESDEN NUCLEAR POWER STATION, UNIT 1

F Security, medical, emergency & fire protection plans

B212030283 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 82/11/30 Document
Management Branch 1p 16316 253 24X Fiche 50-010, 82/11/30, 8212030283

--B212030286 Forwards public version of revised emergency plan implementing procedures, including Procedure EPIP 100-2 re shift turnover w/technical support ctr & environ teams activated Receipt forms & procedure histories encl
SCOTT, D J Commonwealth Edison Co 82/11/19 DENTON, H R Office
of Nuclear Reactor Regulation, Director 7pp 16316 255 24X
Fiche 50-010, 82/11/30, 8212030283

--B212030287 Public version of revised emergency plan implementing procedures, including Procedure EPIP 100-2 re shift turnover w/technical support ctr & environ teams activated
* Commonwealth Edison Co 82/11/17 14pp 16316 262 24X
Fiche 50-010, 82/11/30, 8212030283

B212130017 Releases public version of Revision 1 to Emergency Plan Implementing Procedure EQ-2, "Pre-Established Onsite & Offsite Monitoring Locations (Maps)"
FELTON, J M Division of Rules and Records 82/12/07 Document
Management Branch 1p 16417 062 24X Fiche 50-000, 82/12/07, 8212130017

--B212130028 Forwards public version of Revision 1 to Emergency Plan Implementing Procedure EQ-2, "Pre-Established Onsite & Offsite Monitoring Locations (Maps)" Revised table of contents encl
PAJOWSKI, J Commonwealth Edison Co 82/11/01 DENTON, H R NRC -
No Detailed Affiliation Given 2pp 16417 063 24X
Fiche 50-000, 82/12/07, 8212130017

--B212130041 Public version of Revision 1 to Emergency Plan Implementing Procedure EQ-2, "Pre-Established Onsite & Offsite Monitoring Locations (Maps)"
PAJOWSKI, J E, LITERSKI, L A Commonwealth Edison Co 82/11/29
4pp 16417 065 24X Fiche 50-000, 82/12/07, 8212130017

B212140243 Advises of distribution of revisions to "Generating Station Emergency Plan" Braidwood annex not prepared
YRAHM, T R Commonwealth Edison Co 82/12/07 DENTON, H R Office
of Nuclear Reactor Regulation, Director 2pp 16409 302 24X
Fiche 50-000, 82/12/07, 8212140243

B212220175 Releases public version of revised generating station emergency plan implementing procedures
FELTON, J M Division of Rules and Records 82/12/10 Document
Management Branch 1p 16529 029 24X Fiche 50-000, 82/12/10, 8212220175

--B212220190 Forwards public version of revised generating station emergency plan implementing procedures, including Procedures ED-3 re demand polling of meteorological data & ED-20 re emergency forecast request
PAJOWSKI, J E Commonwealth Edison Co 82/11/15 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 16529 030
24X Fiche 50-000, 82/12/10, 8212220175

--B212220202 Public version of revised generating station emergency plan implementing procedures, including Procedures ED-3 re demand polling of meteorological data & ED-20 re emergency forecast request
LITERSKI, L A, PAJOWSKI, J E Commonwealth Edison Co 82/10/13
48pp 16529 031 24X Fiche 50-000, 82/12/10, 8212220175

B212230019 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 82/12/15 Document
Management Branch 1p 16545 350 24X Fiche 50-010, 82/12/15, 8212230019

--B212230028 Forwards public version of Revision 1 to Emergency Plan Implementing Procedure EPIP 500-1, "Quarterly Inventory of First Aid Supplies"
SCOTT, D J Commonwealth Edison Co 82/12/03 DENTON, H R Office
of Nuclear Reactor Regulation, Director 3pp 16545 351 24X
Fiche 50-010, 82/12/15, 8212230019

--B212230042 Public version of Revision 1 to Emergency Plan Implementing Procedure EPIP 500-1, "Quarterly Inventory of First Aid Supplies" Revised index encl
* Commonwealth Edison Co 82/11/22 6pp 16545 354 24X
Fiche 50-010, 82/12/15, 8212230019

B212220306 Discusses layout of communications equipment required in control room, onsite technical support ctr & near-site emergency operations facility
KEPPLER, J D Region 3, Office of Director 82/12/16
Commonwealth Edison Co 3pp 16503 351 24X Fiche 50-000 82/12/16, 8212220306

B212280214 Forwards IE Safeguards Insp Repts 50-010/82-20, 50-237/82-28 & 50-249/82-29 on 821115-19 Noncompliance noted failure to adequately control security-related key as required by security plan Details withheld (ref 10CFR73 21)
MILLER, J R Division of Engineering & Technical Programs 82/12/20
REED, C Commonwealth Edison Co 2pp 16562 120 24X
Fiche 50-010, 82/12/20, 8212280214

--B212280220 IE Safeguards Insp Rept 50-010/82-20, 50-237/82-28 & 50-249/82-29 on 821115-19 Noncompliance noted failure to adequately control security-related key as required by security plan Details withheld (ref 10CFR73 21)
CHRISTOFFER, G Division of Emergency Preparedness & Operational Support 82/12/15 2pp 16562 122 24X Fiche 50-010, 82/12/20, 8212280214

B212300167 Releases public version of revised generating station emergency plan telephone directory
FELTON, J M Division of Rules and Records 82/12/20 Document
Management Branch 1p 16612 215 24X Fiche 50-000, 82/12/20, 8212300167

--B212300179 Forwards public version of revised generating station emergency plan telephone directory
MOORE, R D Commonwealth Edison Co 82/12/02 DENTON, H R Office
of Nuclear Reactor Regulation, Director 1p 16612 216 24X
Fiche 50-000, 82/12/20, 8212300167

--B212300199 Public version of revised generating station emergency plan telephone directory
GALLE, D P Commonwealth Edison Co 82/11/05 60pp 16612 317
24X Fiche 50-000, 82/12/20, 8212300167

H General correspondence

B212280176 Notifies of change in mailing address for NRC licensing mail
WRIGHT, Q N Illinois, State of, Dept Nuc Safety (formerly Dept Public Health) 82/12/20 EISENHUT, D G Division of Licensing
1p 16556 135 24X Fiche 50-000, 82/12/20, 8212280176

P Operating license stage documents & correspondence

B212140001 Addl response to FOIA request for five categories of documents re SEP Forwards documents listed in App A No documents located sub j to Item 3 of request Review of remaining documents continuing Documents available in PDR
FELTON, J M Division of Rules and Records 82/11/03 GALLO, J
Isham, Lincoln & Beale 2pp 16433 354 24X Fiche 50-000, 82/11/03, 8212140001

--7908070435 Forwards individual plant summaries re seismic capability & recommended interim actions Older SEP plants have less inherent margins to withstand lateral dynamic loads
DAVIS, D K Systematic Evaluation Program Branch (Pre 791030)
79/06/18 VOLLMER, R H Assistant Director for Systematic Evaluation Program (Pre 791030) 5pp 16434 321 24X
Fiche 50-000, 82/11/03, 8212140001

DOCKETED ITEMS

11

--B009110797 Forwards excerpt from utility 680801, "Rept to Stockholders," re effect of 680515 tornadoes on utility 345 kV sys
DENTON, H R Atomic Energy Commission 68/08/14 TEDESCO, R L
Atomic Energy Commission 2pp 16434 254 24X
Fiche 50-000, 82/11/03, 8212140001

B212220212 Forwards Revision 22 to CE-1-A, "QA Program for Nuclear Generating Stations"
SWARTZ, E D Commonwealth Edison Co 82/12/14 HAASS, W P Quality Assurance Branch 1p 16518 007 24X Fiche 50-000, 82/12/14, 8212220212

--B212520231 "QA Program for Nuclear Generating Stations," Revision 22
* Commonwealth Edison Co CE-1-A R22 82/11/01 17pp
16518 007 24X Fiche 50-000, 82/12/14, 8212220212

Q Inspection reports, IE Bulletins & correspondence

B208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BHR Plants" Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240

G208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model B01 & Model 802 Thermoluminescent Dosimeters" Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000, 82/11/05, 8208190245

B208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements" Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 107pp 16411 199 24X Fiche 50-000, 82/11/18, 8208190251

B208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks" Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000, 82/11/26, 8208190256

B212060036 Ack receipt of 821028 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-010/82-13, 50-237/82-17 & 50-249/82-18
STREETEY, J F Region 3, Office of Director 82/11/26 REED, C Commonwealth Edison Co 1p 16313 284 24X Fiche 50-010, 82/11/26, 8212060036

--B212060045 Responds to NRC 820928 ltr re violations noted in IE Insp Repts 50-010/82-13, 50-237/82-17 & 50-249/82-18 Corrective actions involve leak test performed on water leg portion of torus level mod Training session scheduled
DELOERGE, L O Commonwealth Edison Co 82/10/28 KEPPLER, J O Region 3, Office of Director 3pp 16313 285 24X Fiche 50-010, 82/11/26, 8212060036

B212170300 Forwards IE Insp Repts 50-010/82-19, 50-237/82-26 & 50-249/82-26 on 821104-05 No noncompliance noted
LITTLE, W S Division of Engineering & Technical Programs 82/11/29 REED, C Commonwealth Edison Co 2pp 16483 206 24X Fiche 50-010, 82/11/29, 8212170300

--B212170306 IE Insp Repts 50-010/82-19, 50-237/82-26 & 50-249/82-26 on 821104-05 No noncompliance noted Major areas inspected licensee actions on previously identified items
REIMANN, F W, JACKLIN, I N Division of Engineering & Technical Programs 82/11/24 4pp 16493 208 24X Fiche 50-010, 82/11/29, 8212170306

B208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl" Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000, 82/11/30, 8208190257

B212030178 Forwards final SALP Repts 50-010/82-10, 50-237/82-14 & 50-249/82-15 for assessment period Jul 1980-Dec 1981, discussed at IE mgt meeting on 820602 Util 820618 comments on SALP rept addressed
KEPPLER, J O Region 3, Office of Director 82/12/01 REED, C Commonwealth Edison Co 3pp 16303 228, 24X Fiche 50-010, 82/12/01, 8212030178

--B212030185 SALP Repts 50-010/82-10, 50-237/82-14 & 50-249/82-15 for assessment period Jul 1980-Dec 1981 Mgt attention warranted in areas of plant operations, radiological controls & review committee activities
* Region 3, Office of Director 82/05/31 47pp 16303 231 24X Fiche 50-010, 82/12/01, 8212030178

B208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies" Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259

B208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets" Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X Fiche 50-000, 82/12/03, 8208190261

B212170196 Forwards IE Insp Repts 50-010/82-18, 50-237/82-25 & 50-249/82-25 on 821002-29 No noncompliance noted
STREETEY, J F Division of Project & Resident Programs 82/12/03 REED, C Commonwealth Edison Co 2pp 16450 153 24X Fiche 50-010, 82/12/03, 8212170196

--B212170201 IE Insp Repts 50-010/82-18, 50-237/82-25 & 50-249/82-25 on 821002-29 No noncompliance noted Major areas inspected headquarters & regional requests, operational safety verification, monthly maint observation & LERs
TONGUE, T M, STASCH, S, WALKER, R D Division of Project & Resident Programs 82/12/01 8pp 16450 155 24X Fiche 50-010, 82/12/03, 8212170196

B208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring" Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16, 8208190267

B208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27" Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X Fiche 50-000, 82/12/20, 8208190268

B212280214 Forwards IE Safeguards Insp Repts 50-010/82-20, 50-237/82-28 & 50-249/82-29 on 821115-19 Details & notice of violation withheld (ref 10CFR73 21)
MILLER, J R Division of Engineering & Technical Programs 82/12/20 REED, C Commonwealth Edison Co 2pp 16562 120 24X Fiche 50-010, 82/12/20, 8212280214

--B212280220 IE Safeguards Insp Repts 50-010/82-20, 50-237/82-28 & 50-249/82-29 on 821115-19 Noncompliance noted failure to adequately control security-related key as required by security plan Details withheld (ref 10CFR73 21)
CHRISTOFFER, O, KNICELEY, J R, CRCED, J R Division of Emergency Preparedness & Operational Support 82/12/15 2pp 16562 122 24X Fiche 50-010, 82/12/20, 8212280214

B212280070 Requests addition of RE Farrell to unescorted access list to vital & protected areas Individual possesses Q clearance
KEPPLER, J O Region 3, Office of Director 82/12/22 REED, C Commonwealth Edison Co 1p 16563 136 24X Fiche 50-010, 82/12/22, 8212280070

R Periodic operating reports & related correspondence

B212140077 "1982 Evaluation, Dresden Nuclear Power Station, Comm Ed Co"
* Institute of Nuclear Power Operations 82/11/30 39pp 16403 171 24X Fiche 50-010, 82/11/30, 8212140077

B212140112 Forwards monthly operating repts for Nov 1982
SCOTT, D J Commonwealth Edison Co 82/12/01 Director's Office, Office of Inspection and Enforcement 1p 16408 204 24X Fiche 50-010, 82/12/01, 8212140112

--B212140120 Monthly operating repts for Nov 1982
SCHROEDER, B A Commonwealth Edison Co 82/12/01 28pp 16408 205 24X Fiche 50-010, 82/12/01, 8212140112

DOCKET 50-13 BABCOCK & WILCOX CO CRITICAL FACILITY

P Operating license stage documents & correspondence

B212030262 Responds to 821029 memo re planned reorganization of McDermott, Inc Conditions imposed on QA Co during formation should apply to B&W
DENTON, H R Office of Nuclear Reactor Regulation, Director 82/11/19 CUNNINGHAM, O H Office of the Executive Legal Director, 1p 16314 349 24X Fiche 50-013, 82/11/19, 8212030262

DOCKETED ITEMS

DOCKET 50-20 MASSACHUSETTS INST OF TECH RES REACTOR

F Security, medical, emergency & fire protection plans

B212150211 Approves B21013 Revision 27 to SAR which affects physical security plan for reactor facility. Changes consistent w/provisions of 10CFR50.94(p) & do not decrease effectiveness of plan.
THOMAS, C D Standardization & Special Projects Branch 82/12/08
CLARK, L Massachusetts Institute of Technology 2pp 16447 063
24X Fiche 50-020, 82/12/08, B212150211

P Operating license stage documents & correspondence

B212280406 Application to amend License R-37, consisting of Tech Spec changes revising frequencies for surveillance testing of ECCS & charcoal filters in bldg pressure relief sys & Revision 28 to SAR revising testing frequency for ECCS.
CLARK, L Massachusetts Institute of Technology 82/12/22
THOMAS, C Standardization & Special Projects Branch 2pp 16560 042 24X Fiche 50-020, 82/12/22, B212280406

--B212280411 Proposed Tech Spec changes revising frequencies for surveillance testing of ECCS & charcoal filters in bldg pressure relief sys SAR Page 6 & re tests & surveillance encl
* Massachusetts Institute of Technology 82/12/22 6pp 16550 044 24X Fiche 50-020, 82/12/22, B212280406

DOCKET 50-25 DOW CHEMICAL CO TRIOA REACTOR

C Utility Environmental Report (ER), amends & correspondence

B212210246 IE Safeguards Insp Rept 70-0025/B2-10 on B21018-20 & 1101-05 No noncompliance noted. Major areas inspected: physical inventory & inventory verification & independent safeguards insp effort Details withheld (ref 10CFR2.790).
NELSON, G B, NORDERHAUG, L R Division of Radiological Safety & Safeguards Program 82/12/13 1p 16493 016 24X
Fiche 50-025, 82/12/14, B212210246

DOCKET 50-27 WASHINGTON STATE UNIV RESEARCH REACTOR

Q Inspection reports, IE Bulletins & correspondence

B212130269 Forwards IE Insp Rept 50-027/B2-03 on B21108-10 No noncompliance noted.
STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 82/11/24 NYMAN, C J Washington State Univ 2pp 16390 161 24X Fiche 50-027, 82/11/24, B212130269

--B212130270 IE Insp Rept 50-027/B2-03 on B21108-10 No noncompliance noted. Major areas inspected: organization, logs, records, reviews & audits, requalification training, procedures, surveillance & experiments.
JOHNSON, A D, TOTH, A D, DODDS, R T Division of Resident, Reactor Project & Engineering Programs 82/11/23 5pp 16390 163 24X
Fiche 50-027, 82/11/24, B212130269

DOCKET 50-29 YANKEE-ROWE NUCLEAR POWER STATION

F Security, medical, emergency & fire protection plans

B212140394 Forwards info re emergency operations facility (EOF) per B21201 telcon & Generic Ltr B1-10 Const of permanent primary, permanent backup & interim EOFs complete.
KAY, J A Yankee Atomic Electric Co 82/12/06 CRUTCHFIELD, D Operating Reactors Branch 5 2pp 16401 271 24X
Fiche 50-029, 82/12/06, B212140394

B212210149 Forwards addl info to prepare shift crews operating nuclear plants for types of questions NRC duty officer may ask via NRC emergency notification sys.
STAROSTECKI, R Division of Project & Resident Programs 82/12/16
HEIDER, L H Yankee Atomic Electric Co 5pp 16485 161 24X
Fiche 50-029, 82/12/16, B212210149

J Insurance & indemnity information

B212300333 Forwards Endorsement 102 to NELA Policy NF-76 & Endorsement 83 to MAELU Policy NF-26.
BINISI, J M Marsh & McLennan, Inc., M & M Nuclear Consultants, Inc Div 82/12/27 BALTZMAN, J D Assistant Director for State & License Relations 3pp 16594 072 24X Fiche 50-029, 82/12/27, B212300333

P Operating license stage documents & correspondence

B211080101 Forwards Amend 74 to License DPR-3 Amend revises administrative controls section of Tech Specs to modify organizational structure & to reflect changes in titles.
CRUTCHFIELD, D Operating Reactors Branch 5 82/11/02 KAY, J A Yankee Atomic Electric Co 2pp 15993 075 24X
Fiche 50-029, 82/11/02, B211080101

--B211080105 Amend 74 to License DPR-3, revising administrative controls section of Tech Specs to modify organizational structure & to reflect changes in titles.
CRUTCHFIELD, D Operating Reactors Branch 5 82/11/02 7pp 15993 077 24X Fiche 50-029, 82/11/02, B211080101

--B211080107 Safety evaluation supporting Amend 74 to License DPR-3.
CARUSO, R Office of Nuclear Reactor Regulation, Director 82/11/02 2pp 15993 084 24X Fiche 50-029, 82/11/02, B211080101

--B211080110 Notice of issuance & availability of Amend 74 to License DPR-3.
CRUTCHFIELD, D Operating Reactors Branch 5 82/11/02 2pp 15993 086 24X Fiche 50-029, 82/11/02, B211080101

B212140031 Addl response to FOIA request for five categories of documents re SEP. Forwards documents listed in App A. No documents located subj to Item 3 of request. Review of remaining documents continuing. Documents available in PDR.
FELTON, J M Division of Rules and Records 82/11/03 GALLO, J Isham, Lincoln & Beale 2pp 16433 354 24X Fiche 50-000, 82/11/03, B212140001

--/908090435 Forwards individual plant summaries re seismic capability & recommended interim actions. Older SEP plants have less inherent margins to withstand lateral dynamic loads.
DAVIS, D K Systematic Evaluation Program Branch (Pre 791030) 79/06/18 VOLLMER, R H Assistant Director for Systematic Evaluation Program (Pre 791030) 5pp 16434 321 24X
Fiche 50-000, 82/11/03, B212140001

--B203310670 Forwards SEP seismic completion plan to perform review parallel w/license efforts to complete SEP Topic III-6, seismic design considerations for Group II plants.
HERMANN, R Systematic Evaluation Program Branch 82/03/08
RUSSELL, W T Systematic Evaluation Program Branch 5pp 16434 276 24X Fiche 50-000, 82/11/03, B212140001

--B212140149 Discusses SEP site-specific spectra project. Project in final stages. Comments from Peer Review Group & all other comments should be received by 791130. Listing of references re site-specific spectra (SEP Topic III-6) encl.
LEVIN, H A Systematic Evaluation Program Branch 79/11/13
ISENHUT, D G Division of Operating Reactors 4pp 16436 300 24X Fiche 50-000, 82/11/03, B212140001

B212020356 Advises that draft safety evaluation input re SEP Topic VI-4, "Containment Isolation Sys" considered final input to integrated safety assessment.
CARUSO, R Operating Reactors Branch 5 82/11/24 KAY, J A Yankee Atomic Electric Co 2pp 16278 180 24X Fiche 50-029, 82/11/24, B212020356

B212020300 Application for Proposed Change 17B to License DPR-3, revising Tech Spec max allowable peak rod linear heat generation rate limits as determined by Core XVI LOCA analysis.
HEIDER, L H Yankee Atomic Electric Co 82/11/26 Office of Nuclear Reactor Regulation, Director 2pp 16277 339 24X
Fiche 50-029, 82/11/26, B212020300

--B212020304 Proposed Tech Spec Change 17B, revising max allowable peak rod linear heat generation rate limits as determined by Core XVI LOCA analysis.
* Yankee Atomic Electric Co 82/11/26 11pp 16277 341 24X
Fiche 50-029, 82/11/26, B212020300

B212060026 Submits info re steam generator tube integrity, per B21026 generic ltr. No appreciable problems in steam generator tube integrity area identified.
KAY, J A Yankee Atomic Electric Co 82/11/29 CRUTCHFIELD, D Operating Reactors Branch 5 2pp 16313 300 24X
Fiche 50-029, 82/11/29, B212060026

B212070040 Advises that util will submit operator procedures, design details for diesel generator load shedding & Tech Specs at least 3 months prior to placing protection scheme in svc. Installation scheduled for 1984 refueling outage.
KAY, J A Yankee Atomic Electric Co 82/11/30 CRUTCHFIELD, D Operating Reactors Branch 5 1p 16327 354 24X
Fiche 50-029, 82/11/30, B212070040

DOCKETED ITEMS

13

G212070047 Requests exemption from requirements of 10CFR50.44(c)(3)(ii) requiring containments w/purge/repressurization sys as primary means of hydrogen control be provided w/internal hydrogen recombiner or ability to install recombiner
KAY, J A Yankee Atomic Electric Co 82/12/01 CRUTCHFIELD, D
Operating Reactors Branch 5 4pp 16327 330 24X
Fiche 50-029, 82/12/01, 8212070047

G212130228 Forwards revised final evaluation of SEP Topic XV-16, "Radiological Consequences of Failure of Small Lines Carrying Primary Coolant Outside Containment." Does meet acceptance criteria
CARUSO, R Operating Reactors Branch 5 82/12/01 KAY, J A Yankee Atomic Electric Co 6pp 16390 123 24X Fiche 50-029, 82/12/01, 8212130228

G212080376 Forwards Amend 77 to License DPR-3, safety evaluation & notice of issuance & availability Amend incorporates provisions required for operation w/refueled Core XVI into Tech Specs
CRUTCHFIELD, D Operating Reactors Branch 5 82/12/03 KAY, J A Yankee Atomic Electric Co 2pp 16392 323 24X
Fiche 50-029, 82/12/03, 8212080376

--G212080389 Amend 77 to License DPR-3, incorporating provisions required for operation w/refueled Core XVI into Tech Specs
CRUTCHFIELD, D Operating Reactors Branch 5 82/12/03 49pp 16392 325 24X Fiche 50-029, 82/12/03, 8212080376

--G212080397 Safety evaluation supporting Amend 77 to License DPR-3
* Office of Nuclear Reactor Regulation, Director 82/12/03 21pp 16353 012 24X Fiche 50-029, 82/12/03, 8212080376

--G212080403 Notice of issuance & availability of Amend 77 to License DPR-3
CRUTCHFIELD, D Operating Reactors Branch 5 82/12/03 2pp 16353 033 24X Fiche 50-029, 82/12/03, 8212080376

G212130223 Forwards final revision to offsite dose calculation manual. Manual will be used for implementing requirements of proposed radiological effluent Tech Specs submitted in 820930 ltr
KAY, J A Yankee Atomic Electric Co 82/12/06 CRUTCHFIELD, D
Operating Reactors Branch 5 1p 16398 183 24X
Fiche 50-029, 82/12/06, 8212130223

--G212130227 Offsite dose calculation manual
HODDGM, A D, GILLINGS, W D Yankee Atomic Electric Co 82/12/01 123pp 16398 184 24X Fiche 50-029, 82/12/06, 8212130223

G208190263 Generic Ltr 82-32 to all PWR licensees re potential steam generator-related generic requirements Forwards Science Applications, Inc draft rept re subj requirements Comments requested within 30 days of ltr Svc list encl
EISENHUT, D O Division of Licensing 82/12/09 Consolidated
Edison Co of New York, Inc 29pp 16629 247 24X
Fiche 50-000, 82/12/09, 8208190263

G212140259 Advises that requirements of TMI Action Items I A 1 2 4, "Upgrading Reactor Operator & Senior Reactor Operator Training," & II B 4, "Training for Mitigating Core Damage," have been met SER & technical evaluation rept forwarded
CRUTCHFIELD, D Operating Reactors Branch 5 82/12/09 KAY, J A Yankee Atomic Electric Co 4pp 16401 312 24X
Fiche 50-029, 82/12/09, 8212140259

--G212140260 "Improvements in Training & Requalification Programs as Required by TMI Action Items I A 2 1 & II B 4," technical evaluation rept
* Science Applications, Inc NRC-03-82-076 SAI-186-029-14 82/08/17 NRC - No Detailed Affiliation Given 14pp 16401 316 24X Fiche 50-029, 82/12/09, 8212140259

G212140103 Generic Ltr 82-28 to all licensees of operating Westinghouse & C-E PWRs (except Arkansas Nuclear One, Unit 2 & San Onofre 2 & 3) re inadequate core cooling instrumentation sys Svc list encl
EISENHUT, D O Division of Licensing 82/12/10 Yankee Atomic Electric Co 27pp 16690 035 24X Fiche 50-000, 82/12/10, 8212140103

G212270365 Forwards SER & proprietary & nonproprietary "Review of Licensee Resolution of Outstanding Issues From NRC Equipment Environ Qualification SERs (F-11, B-60)," technical evaluation repts Proprietary rept withheld (ref 10CFR2.790)
CRUTCHFIELD, D Operating Reactors Branch 5 82/12/16 KAY, J A Yankee Atomic Electric Co 3pp 16332 247 24X
Fiche 50-029, 82/12/16, 8212270365

--8212270367 Safety evaluation re environ qualification of safety-related electric equipment info for items in NRC Categories I B, II A & II B justifying continued operation requested within 30 days
* Office of Nuclear Reactor Regulation, Director 82/12/16 4pp 16332 250 24X Fiche 50-029, 82/12/16, 8212270365

--8207010124 "Review of Licensee Resolution of Outstanding Issues From NRC Equipment Environ Qualification Safety Evaluation Repts (F-11, B-60), Yankee Atomic Electric Co, Yankee Rowe," technical evaluation rept
CRANE, C J Franklin Institute/Franklin Research Center NRC-03-79-118 TER-C5257-463 82/05/28 L E, N B, SHEMANSKI, P NRC - No Detailed Affiliation Given 422pp 16532 256 24X
Fiche 50-029, 82/12/16, 8212270365

G212230238 Forwards Amend 78 to License DPR-3, safety evaluation & notice of issuance & availability Amend revises max allowable peak rod linear heat generation rate limits
CRUTCHFIELD, D Operating Reactors Branch 5 82/12/17 KAY, J A Yankee Atomic Electric Co 2pp 16508 238 24X
Fiche 50-029, 82/12/17, 8212230238

--G212230243 Amend 78 to License DPR-3, revising max allowable peak rod linear heat generation rate limits as determined by revised Core XVI LOCA limits
CRUTCHFIELD, D Operating Reactors Branch 5 82/12/17 4pp 16508 240 24X Fiche 50-029, 82/12/17, 8212230238

--G21230248 Safety evaluation supporting Amend 78 to License DPR-3
LOIS, L, VOGLEWEDE, J, GILL, A Office of Nuclear Reactor Regulation, Director 82/12/17 5pp 16508 244 24X
Fiche 50-029, 82/12/17, 821230238

--G21230264 Notice of issuance & availability of Amend 78 to License DPR-3
WAMBACH, T V Operating Reactors Branch 5 82/12/17 2pp 16508 249 24X Fiche 50-029, 82/12/17, 821230238

G212280476 Forwards "Yankee SEP Integrated Assessment"
KAY, J A Yankee Atomic Electric Co 82/12/23 CRUTCHFIELD, D
Operating Reactors Branch 5 1p 16556 234 24X
Fiche 50-029, 82/12/23, 8212280476

--G212280480 "Yankee SEP Integrated Assessment"
* Yankee Atomic Electric Co 82/12/31 297pp 16556 235 24X
Fiche 50-029, 82/12/23, 8212280476

G Inspection reports, IE Bulletins & correspondence

G208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants." Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240

G208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters." Svc list encl
GOSB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000, 82/11/05, 8208190245

G208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements." Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/10 Consolidated Edison Co of New York, Inc 109pp 16411 179 24X
Fiche 50-000, 82/11/10, 8208190251

G208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks." Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000, 82/11/26, 8208190256

G208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl." Svc list encl
GOSB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000, 82/11/30, 8208190257

G208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies." Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259

DOCKETED ITEMS

B'08190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay
Lockets " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03
Consolidated Edison Co of New York, Inc 110pp 16462 064 24X
Fiche 50-000, 82/12/03, 8208190261

B'08190267 IE Info Notice 82-49, "Correction for Sample Conditions for
Air & Gas Monitoring " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and
Enforcement 82/12/16 Consolidated Edison Co of New York, Inc
127pp 16628 191 24X Fiche 50-000, 82/12/16, 8208190267

B'12220418 Informs of interviews to be conducted similar to NRC study
conducted in Mar 1982 re IE Info Notice 82-05, "Increasing
Frequency of Drug-Related Incidents " Util will be contacted
shortly to arrange interviews w/o stated NUREG
STAROSTECHKI, R Division of Project & Resident Programs 82/12/16
HEIDER, L H Yankee Atomic Electric Co 2pp 16503 268 24X
Fiche 50-029, 82/12/16, 8212220418

B'208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage
Relays Type ITE-27 " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20
Consolidated Edison Co of New York, Inc 108pp 16628 293 24X
Fiche 50-000, 82/12/20, 8208190268

K Periodic operating reports & related correspondence

B'12290126 Forwards monthly operating rept for Oct 1982
HEIDER, L H Yankee Atomic Electric Co 82/11/03 Office of
Resource Management, Director 1p 16583 220 24X
Fiche 50-029, 82/11/03, 8212290126

--8212290130 Monthly operating rept for Oct 1982
PHILLIPS, J Yankee Atomic Electric Co 82/11/03 5pp
16583 221 24X Fiche 50-029, 82/11/03, 8212290126

S Reportable occurrences, LERs & related correspondence

B'12140184 Forwards updated LER 82-034/01T-1
AUTIO, H A Yankee Atomic Electric Co 82/12/03 HAYNES, R C
Region 1, Office of Director 1p 16410 214 24X
Fiche 50-029, 82/12/03, 8212140184

--8212140187 Updated LER 82-034/01T-1 on 821009, leak detected on main
coolant pump l vent line Caused by incompatibility of
reducing insert w/main coolant sys Carbon steel components
replaced w/stainless steel
FRENCH, L D Yankee Atomic Electric Co 82/12/03 Region 1,
Office of Director 2pp 16410 215 24X Fiche 50-029, 82/12/03,
8212140184

B'12150155 Forwards LER 82-039/03L-0
AUTIO, H A Yankee Atomic Electric Co 82/12/06 HAYNES, R C
Region 1, Office of Director 1p 16430 183 24X
Fiche 50-029, 82/12/06, 8212150155

--8212150160 LER 82-039/03L-0 on 821106, emergency diesel generator 1
tripped, causing de-energization of emergency motor control
ctr Caused by failure of mechanical seal on low pressure
safety injection pump Seal replaced
FRENCH, L D Yankee Atomic Electric Co 82/12/06 Region 1,
Office of Director 1p 16430 184 24X Fiche 50-029, 82/12/06,
8212150155

B'12120278 Forwards LER 82-040/03L-0
AUTIO, H A Yankee Atomic Electric Co 82/12/10 HAYNES, R C
Region 1, Office of Director 1p 16483 033 24X
Fiche 50-029, 82/12/10, 8212120278

--8212120283 LER 82-040/03L-0 on 821112, in Mode 6, vital bus distribution
panel de-energized when circuit breaker 1CB inadvertently
opened Caused by length of electrical conduit striking
circuit breaker switch Personnel instructed to use caution
RICE, D A Yankee Atomic Electric Co 82/12/10 Region 1,
Office of Director 1p 16483 034 24X Fiche 50-029, 82/12/10,
8212120278

B'12290251 Forwards LER 82-041/03L-0
AUTIO, H A Yankee Atomic Electric Co 82/12/16 HAYNES, R C
Region 1, Office of Director 1p 16582 041 24X
Fiche 50-029, 82/12/16, 8212290251

--8212290258 LER 82-041/03L-0 on 821116, during Mode 6, while performing
main coolant sys pressure channel calibr procedure, Loop 1
channel initiation setpoint found out of Tech Spec limits
Caused by drift in main control board indicator
MAY, E L Yankee Atomic Electric Co 82/12/16 Region 1, Office
of Director 1p 16582 042 24X Fiche 50-029, 82/12/16,
8212290251

B'12290310 Forwards LER 82-042/03L-0
AUTIO, H A Yankee Atomic Electric Co 82/12/17 HAYNES, R C
Region 1, Office of Director 1p 16588 027 24X
Fiche 50-029, 82/12/17, 8212290310

--8212290316 LER 82-042/03L-0 on 821117, loop 2 low pressure scram
setpoint found out of Tech Spec limits Caused by drift in
main control board indicator Indicator recalibr
MAY, E L Yankee Atomic Electric Co 82/12/17 Region 1, Office
of Director 1p 16588 028 24X Fiche 50-029, 82/12/17,
8212290310

DDX KET 50-54 UNION CARBIDE RESEARCH REACTOR

P Operating license stage documents & correspondence

G'12070173 Forwards response to 821104 request for addl info & addl
Tech Spec changes re renewal fo License R-B1
VOTH, M H Union Carbide Corp 82/11/22 THOMAS, C O
Standardization & Special Projects Branch 14pp 16337 001 24X
Fiche 50-054, 82/11/22, 8212070173

--8212070162 Proposed Tech Spec changes re frequency of pool water
analysis & inclusion of radiation organization in
description of organizational structure
Union Carbide Corp 82/11/22 4pp 16337 015 24X
Fiche 50-054, 82/11/22, 8212070173

B'12030158 Suppl to 800523 amend to License R-B1 re renewal & Tech Spec
changes Footnote re Tech Spec 3 2 3 presently requiring that
ion chamber of third channel be operable prior to reactor
startup should be deleted Married-up Tech Specs encl
VOTH, M H Union Carbide Corp 82/11/29 BERNARD, H
Standardization & Special Projects Branch 2pp 16303 001 24X
Fiche 50-054, 82/11/29, 8212030158

DOCKET 50-70 GENERAL ELECTRIC TEST REACTOR

G Adjudicatory correspondence

B'12280276 Requests delay to respond to 821021, 1112 & 19 memoranda &
orders, due to inaccessability of documents needed for
complete response Partial response to GE 821123 requests
provided
TURK, J Affiliation Unknown 82/12/20 FRYE, J H, LINENBERGER, G,
FOREMAN, H Atomic Safety and Licensing Board Panel 2pp
16561 230 24X Fiche 50-070, 82/12/20, 8212280276

B'12300022 Grants J Turk petition for extension until 830105 to respond
to ASLB 821119 memorandum & order Other petitioners &
intervenor granted same extension NRC response due by
830117
FRYE, J H Atomic Safety and Licensing Board Panel 82/12/27
TURK, J Affiliation Unknown 1p 16598 310 24X
Fiche 50-070, 82/12/27, 8212300022

DOCKET 50-83 UNIV OF FLORIDA TRAINING REACTOR

R Periodic operating reports & related correspondence

B'12070004 Forwards "Annual Progress Rept of Univ of FL Training
Reactor," Sept 1981-Aug 1982
DIAZ, N J Florida, Univ of, Gainesville 82/11/30
Standardization & Special Projects Branch 1p 16327 244 24X
Fiche 50-083, 82/11/30, 8212070004

--8212070007 "Annual Progress Rept of Univ of FL Training Reactor,"
Sept 1981-Aug 1982
DIAZ, N J, VERNETSON, W G Florida, Univ of, Gainesville
82/11/30 26pp 16327 245 24X
Fiche 50-083, 82/11/30, 8212070004

DOCKET 50-89 GENERAL ATOMIC CO

J Insurance & indemnity information

B'12060142 Provides response to 821013 request for clarification re
Indemnity Agreement B-9 & corporate name
BENTON, H R Office of Nuclear Reactor Regulation, Director
82/11/22 MOWRY, W R GA Technologies, Inc /General Atomic Co 1p
16325 354 24X Fiche 50-089, 82/11/22, 8212060142

DOCKETED ITEMS

15

P Operating license stage documents & correspondence

G12060142 Provides response to B21013 request for clarification re Indemnity Agreement B-9 & corporate name
DENTON, H R Office of Nuclear Reactor Regulation, Director
02/11/22 MOWRY, W R GA Technologies, Inc /General Atomic Co 1p
16325 354 24X Fiche 50-089, B2/11/22, B212060142

DOCKET 50-97 CORNELL UNIV ZERO POWER REACTOR

P Operating license stage documents & correspondence

G12080598 Notification of B21207-09 meetings w/Cornell Univ & LASL in Cornell R to discuss review of reactor facilities for license renewal processing, questions sent to Cornell & LASL draft technical evaluation report
BERNARD, H Standardization & Special Projects Branch 02/11/23
THOMAS, C O Standardization & Special Projects Branch 3pp
16379 350 24X Fiche 50-097, B2/11/23, B212080598

R Periodic operating reports & related correspondence

G12140632 Forwards annual operating repts for Licenses R-80 & R-89 for two yrs ending B20630
ADERHOLD, H C Cornell Univ 02/12/06 Region 1, Office of Director 1p 16409 001 24X Fiche 50-097, B2/12/06, B212140632

G12140638 Annual operating repts for Licenses R-80 & R-89 for two yrs ending B20630
ADERHOLD, H C Cornell Univ 02/12/06 Region 1, Office of Director 3pp 16409 002 24X Fiche 50-097, B2/12/06, B212140638

G12140469 Forwards "Annual Operating Repts" for period ending June 1981 & June 1982 w/o encls
ADERHOLD, H C Cornell Univ 02/12/06 Director's Office, Office of Inspection and Enforcement 1p 16404 012 24X
Fiche 50-077, B2/12/06, B212140469

G12140146 "Annual Operating Rept: Jul 1980-June 1981"
ADERHOLD, H C Cornell Univ 02/12/14 Region 1, Office of Director 3pp 16408 173 24X Fiche 50-097, B2/12/14, B212140146

DOCKET 50-111 NORTH CAROLINA STATE UNIV RESEARCH REACTOR

W Decommissioning Stage Documents & Correspondence

G12070185 Advises that decommissioning will take longer than anticipated due to technical difficulty of breaking up heavily reinforced concrete. Number of demolition workers increased. Work will be complete by B30120
LOCKRELL, R G North Carolina State Univ 02/12/03 ERICKSON, P
Standardization & Special Projects Branch 1p 16335 258 24X
Fiche 50-111, B2/12/03, B212070185

DOCKET 50-112 UNIV OF OKLAHOMA RESEARCH REACTOR

F Security, medical, emergency & fire protection plans

G12010061 Releases public version of licensee info re status of emergency plan
FELTON, J M Division of Rules and Records 02/11/24 Document Management Branch 1p 16289 202 24X Fiche 50-112, B2/11/24, B212010061

--B212010066 Submits public version of status of emergency plan, due B21103 Plan submitted on B20420 complies w/requirements. No new plan need be developed or submitted
TERRILL, C W Oklahoma, Univ of 02/10/27 BATES, E F EP Licensing Branch 1p 16289 203 24X Fiche 50-112, B2/11/24, B212010061

G12150040 Forwards IE Safeguards Insp Repts 50-112/B2-02 & 70-1430/B2-02 on B21025-29 No noncompliance noted
MADSEN, G L Division of Resident, Reactor Project & Engineering Programs 02/12/09 UPTHEGROVE, W R Oklahoma, Univ of 2pp 16421 322 24X Fiche 50-112, B2/12/09, B212150040

--B212150049 IE Safeguards Insp Repts 50-112/B2-02 & 70-1430/B2-02 on B21025-29 No noncompliance noted. Major areas inspected nuclear mat'l control & accountability, including facility organization & operation Details withheld (ref 10CFR2 790)
CALDWELL, R A, KELLY, J A Division of Resident, Reactor Project & Engineering Programs 02/11/30 1p 16421 324 24X
Fiche 50-112, B2/12/09, B212150040

G Inspection reports, IE Bulletins & correspondence

G12070126 Forwards IE Insp Rept 50-112/B2-01 on B20913-15 & notice of violation
MADSEN, G L Division of Resident, Reactor Project & Engineering Programs 02/11/11 EGLE, D Oklahoma, Univ of 3pp 16327 054 24X Fiche 50-112, B2/11/11, B212070126

- B212070130 Notice of violation from insp on B20913-15
* Division of Resident, Reactor Project & Engineering Programs 02/11/11 2pp 16327 057 24X Fiche 50-112, B2/11/11, B212070126

--B212070133 IE Insp Rept 50-112/B2-01 on B20913-15 Noncompliance noted failure to perform audit, failure to properly conduct surveillance, lack of clear responsive method of keeping operating procedures up-to-date & technically correct
SCHUM, W S, MURPHY, M E, REDANO, R T Division of Resident, Reactor Project & Engineering Programs 02/11/05 10pp 16327 059 24X
Fiche 50-112, B2/11/11, B212070126

G12150040 Forwards IE Safeguards Insp Repts 50-112/B2-02 & 70-1430/B2-02 on B21025-29 No noncompliance noted
MADSEN, G L Division of Resident, Reactor Project & Engineering Programs 02/12/09 UPTHEGROVE, W R Oklahoma, Univ of 2pp 16421 322 24X Fiche 50-112, B2/12/09, B212150040

--B212150049 IE Safeguards Insp Repts 50-112/B2-02 & 70-1430/B2-02 on B21025-29 No noncompliance noted. Major areas inspected nuclear mat'l control & accountability, including facility organization & operation Details withheld (ref 10CFR2 790)
CALDWELL, R A, KELLY, J A Division of Resident, Reactor Project & Engineering Programs 02/11/30 1p 16421 324 24X
Fiche 50-112, B2/12/09, B212150040

V Operator Examinations

G12060226 Comments on proposed requalification program Region will interface w/NRR when listed items resolved
GAGLIARDO, J E Division of Resident, Reactor Project & Engineering Programs 02/12/01 TERRELL, C W Oklahoma, Univ of 1p 16312 170 24X Fiche 50-112, B2/12/01, B212060226

--B212060230 Forwards requalification program for Univ of OK, for approval
TERRELL, C W Oklahoma, Univ of 02/10/11 GAGLIARDO, J E Region 4, Office of Director 1p 16312 171 24X Fiche 50-112, B2/12/01, B212060226

--B212060233 Requalification program for Univ of OK
* Oklahoma, Univ of 02/10/11 6pp 16312 172 24X
Fiche 50-112, B2/12/01, B212060226

DOCKET 50-124 VIRGINIA POLYTECH INST TRAINING REACTOR

P Operating license stage documents & correspondence

G12280211 Forwards confirmation by Reactor Safety Committee chairman that proposal for Tech Spec change reviewed & approved
* Virginia Polytechnic Institute 02/12/22 Division of Licensing 1p 16562 279 24X Fiche 50-124, B2/12/22, B212280211

--B212280213 Forwards application to amend License R-62, revising Tech Specs to delete ultrasonic flow detector w/paddle wheel detector w/1% accuracy min
HOLIAN, P D Virginia Polytechnic Institute 02/12/16 THOMAS, C O Standardization & Special Projects Branch 1p 16562 280 24X Fiche 50-124, B2/12/22, B212280211

--B212280216 Application to amend License R-62, revising Tech Specs to delete ultrasonic flow detector w/paddle wheel detector w/1% accuracy min
HOLIAN, P D Virginia Polytechnic Institute 02/09/24 THOMAS, C O Standardization & Special Projects Branch 1p 16562 281 24X Fiche 50-124, B2/12/22, B212280211

--B212280217 Proposed Tech Specs deleting ultrasonic flow detector w/paddle wheel detector w/1% accuracy min
* Virginia Polytechnic Institute 02/09/24 4pp 16562 282 24X Fiche 50-124, B2/12/22, B212280211

DOCKETED ITEMS

DOCKET 50-128 TEXAS A&M UNIV RESEARCH REACTOR

G Reportable occurrences, LERs & related correspondence

B21200279 RD on B21019, power level indication dropped approx 15% on both safety channels On B21027, electromagnet current for shim safety 2 went to zero Causes not stated Electromagnet coil replaced
ROBBERS, D Texas A&M Univ, College Station, TX 82/10/29
MADSEN, G L Region 4, Office of Director 3pp 16376 299 24X
Fiche 50-128, 82/10/29, 8212100279

DOCKET 50-129 WEST VIRGINIA UNIV RESEARCH REACTOR

P Operating license stage documents & correspondence

B212030118 Informs that last fuel elements for AON-211 reactor sent to Univ or OK on B21119, completing disposal of all reactor components w/exception of Ra/Be startup source Plans to conduct radiation survey of former reactor site underway
BLACKSHAW, G L West Virginia Univ 82/11/29 CRUTCHFIELD, D
Operating Reactors Branch 5 2pp 16303 014 24X
Fiche 50-129, 82/11/29, 8212030118

DOCKET 50-133 HUMBOLDT DAY POWER PLANT, UNIT 3

Q Inspection reports, IE Bulletins & correspondence

B208190240 IE Bulletin B2-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240

B208190245 IE Info Notice B2-42, "Defects Observed in Panasonic Model B01 & Model B02 Thermoluminescent Dosimeters " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000, 82/11/05, 8208190245

B208190251 IE Info Notice B2-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X
Fiche 50-000, 82/11/18, 8208190251

B208190256 IE Info Notice B2-46, "Defective & Obsolete Combination Padlocks " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000, 82/11/26, 8208190256

B208190257 IE Info Notice B2-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000 82/11/30, 8208190257

B208190259 IE Bulletin B2-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259

B208190261 IE Info Notice B2-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X
Fiche 50-000, 82/12/03, 8208190261

B208190267 IE Info Notice B2-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16, 8208190267

B208190268 IE Info Notice B2-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27 " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X
Fiche 50-000, 82/12/20, 8208190268

R Periodic operating reports & related correspondence

B212290182 Forwards monthly operating rept for Oct 1982
WEEKS, E D Pacific Gas & Electric Co 82/11/02 Office of Resource Management, Director 1p 16580 091 24X
Fiche 50-133, 82/11/02, 8212290182

- B212290186 Monthly operating rept for Oct 1982
PERKINS, P S Pacific Gas & Electric Co 82/11/02 4pp 16580 091 24X Fiche 50-133, 82/11/02, 8212290182

DOCKET 50-142 UCLA TRAINING REACTOR

G Adjudicatory correspondence

B212060236 Memorandum & order memorializing B21124 & 1201 telcons & rulings on discovery re Contention XXI on emergency planning
LUEBKE, E A, PARIS, D H, FRYE, J H Atomic Safety and Licensing Board Panel 82/12/02 California Univ of Los Angeles 5pp 16312 274 24X Fiche 50-142, 82/12/02, 8212060236

B212070013 Forwards NRC opposing citations to Committee to Bridge the Gap (CBG) statement of matl fact attached to CBG motion for summary disposition of Contention XIII
WOODHEAD, C P Hearing Branch 1 82/12/03 FRYE, J H, PARIS, D H, LUEBKE, E A Atomic Safety and Licensing Board Panel 3pp 16327 240 24X Fiche 50-142, 82/12/03, 8212070013

B212140456 Answers to Interrogatories C(1), C(17), C(18), C(19), C(22) & C(24) Certificate of Svc encl
WOODHEAD, C P Hearing Branch 1 82/12/13 Committee to Bridge the Gap 16pp 16403 047 24X Fiche 50-142, 82/12/13, 8212140456

DOCKET 50-148 UNIV OF KANSAS RESEARCH REACTOR

H General correspondence

B212270379 FOIA request for documents re Univ of KS research reactor
BARNES, C Affiliation Unknown 82/11/09 Division of Technical Information & Document Control 1p 16568 346 24X
Fiche 50-148, 82/11/09, 8212270379

B212270386 Responds to FOIA request for documents re Univ of KS research reactor Request referred to PDR for processing
FELTON, J M Division of Rules and Records 82/11/18 BARNES, C Affiliation Unknown 1p 16568 347 24X Fiche 50-148, 82/11/18, 8212270386

P Operating license stage documents & correspondence

B212020211 Responds to B21006 & 13 questions re annual operating & decommissioning costs for facility NRC practice assumes state legislature will appropriate adequate funds for decommissioning state univ reactors
THOMAS, C O Standardization & Special Projects Branch 82/11/24 BARNES, C Kansas, Univ of 3pp 16302 321 24X
Fiche 50-148, 82/11/24, 8212020211

B212280524 FOIA request for documents in possession of licensee re receipt, use, disposal & storage of radioisotopes under License R-7B
BARNES, C Affiliation Unknown 82/11/25 Office of Administration 2pp 16593 030 24X Fiche 50-148, 82/11/25, 8212280524

B212280527 Responds to FOIA request for documents in possession of licensee re receipt, use, disposal & storage of radioisotopes under License R-7B Request not applicable to records in possession of licensee
FELTON, J M Division of Rules and Records 82/12/14 BARNES, C Affiliation Unknown 1p 16593 032 24X Fiche 50-148, 82/12/14, 8212280527

DOCKET 50-150 OHIO STATE UNIV RESEARCH REACTOR

F Security, medical, emergency & fire protection plans

B212010071 Releases public version of emergency preparedness plan
FELTON, J M Division of Rules and Records 82/11/24 Document Management Branch 1p 16289 281 24X Fiche 50-150, 82/11/24, 8212010071

--B212010074 Forwards public version of emergency preparedness plan
TALNAGI, J W Ohio State Univ 82/11/02 BATES, G EP Licensing Branch 1p 16289 282 24X Fiche 50-150, 82/11/24, 8212010074

DOCKETED ITEMS

17

8212010079 Public version of emergency preparedness plan
* Ohio State Univ 82/11/30 53pp 16289 283 24X
Fiche 50-150,82/11/24,8212010071

DOCKET 50-151 UNIV OF ILLINOIS RESEARCH REACTOR

Q Inspection reports IE Bulletins & correspondence

B212140396 Forwards IE Safeguards Insp Repts 50-151/82-01,50-356/82-02 & 70-0258/82-01 on 821117-19 & notice of violation Insp rept details withheld (ref 10CFR2 790)
MILLER, J R Division of Engineering & Technical Programs 82/12/09
MILLEY, G H Illinois, Univ of, Urbana-Champaign 2pp 16404 344
24X Fiche 50-151,82/12/09,8212140396

- 8212140399 Notice of violation from insp on 821117-19
MILLER, J R Division of Engineering & Technical Programs
82/12/09 1p 16404 346 24X Fiche 50-151,82/12/09,8212140396

8212140414 IE Safeguards Insp Repts 50-151/82-01,50-356/82-02 & 70-0258/82-01 on 821117-19 Noncompliance noted failure to include items containing SHM on annual inventory & to submit 742 forms Details withheld (ref 10CFR2 790)
MADEJA, T J, CREED, J R Division of Engineering & Technical Programs 82/12/06 1p 16404 347 24X Fiche 50-151,82/12/09,8212140396

DOCKET 50-155 BIO ROCK POINT NUCLEAR PLANT

F Security, medical, emergency & fire protection plans

8212070300 Documents 821202 telcon re emergency operations facility facilities for four plants completed Table encl
VANDENALLE, D J Consumers Power Co 82/12/03 CRUTCHFIELD, D
Operating Reactors Branch 5 2pp 16343 196 24X
Fiche 50-000,82/12/03,8212070300

B212090387 Forwards IE Safeguards Insp Rept 50-155/82-18 on 821025-29 No noncompliance noted
MILLER, J R Division of Engineering & Technical Programs 82/12/03
BEWITT, R B Consumers Power Co 2pp 16364 349 24X
Fiche 50-155,82/12/03,8212090387

--8212090396 IE Safeguards Insp Rept 50-155/82-18 on 821025-29 No noncompliance noted Major areas inspected security plan & implementing procedures,access controls & previous items of noncompliance Details withheld (ref 10CFR73 21)
CHRISTOFFER, O, BELANGER, J L, CREED, J R Region 3, Office of Director 82/12/02 1p 16364 351 24X Fiche 50-155,82/12/03,8212090387

8212100218 Responds to 821107 ltr re Revision 5 to security plan Modified screening program changes submitted as Revision 6 in 821105 ltr
VANDENALLE, D J Consumers Power Co 82/12/08 CRUTCHFIELD, D
Operating Reactors Branch 5 1p 16376 073 24X
Fiche 50-000,82/12/08,8212100218

8212100285 Advises that changes to security & suitability, training & qualification plans submitted 821105 do not decrease safeguards effectiveness NRC approval of changes in accordance w/10CFR50 54(p) not required
VANDENALLE, D J Consumers Power Co 82/12/08 CRUTCHFIELD, D
Operating Reactors Branch 5 1p 16377 145 24X
Fiche 50-000,82/12/08,8212100285

B212220306 Discusses layout of communications equipment required in control room,onsite technical support ctr & near-site emergency operations facility
KEPPLER, J O Region 3, Office of Director 82/12/16
Commonwealth Edison Co 3pp 16503 351 24X Fiche 50-000,82/12/16,8212220306

Q Adjudicatory correspondence

8212020361 Response opposing licensee request for immediate review of partial initial decision re criticality Piecemeal review unnecessary & would delay hearings Certificate of Svc encl
SEMEL, H Christa-Maria SEMEL, H Antioch School of Law, Washington, DC 82/11/29 Atomic Safety and Licensing Appeal Panel 9pp 16290 325 24X Fiche 50-155,82/11/29,8212020361

B212070127 Forwards util 821029 ltr to NRC transmitting info re NRC review of seismic stability of overhead crane inside containment info relevant to unlitigated portion of O'Neill Contention II C Related correspondence
GALLO, J Isham, Lincoln & Beale GALLO, J Consumers Power Co 82/12/02 BLOCH, P B, PARIS, O H, SHON, F J Atomic Safety and Licensing Board Panel 125pp 16326 099 24X Fiche 50-155,82/12/02,8212070127

8212070114 Order granting applicant motion to permit immediate appeal from ASLB 821029 partial initial decision since decision has likely immediate consequences Terms of ASLB 821004 order waived to allow appeal
SHOEMAKER, C J Atomic Safety and Licensing Appeal Panel 82/12/03
Consumers Power Co 5pp 16327 101 24X Fiche 50-155,82/12/03,8212070114

B212070247 Answer opposing licensee motion for stay of effectiveness of decision on criticality Licensee has had adequate time to prepare amended application Greater delays will result if stay granted Certificate of Svc encl
SEMEL, H Christa-Maria SEMEL, H Antioch School of Law, Washington, DC 82/12/03 Atomic Safety and Licensing Board Panel 2pp 16339 150 24X Fiche 50-155,82/12/03,8212070247

--8212070303 Response opposing licensee request for immediate review of partial initial decision re criticality Review unnecessary Delay in proceeding is licensee fault Need to maintain full core offload not demonstrated
SEMEL, H Christa-Maria SEMEL, H Antioch School of Law, Washington, DC 82/12/03 Atomic Safety and Licensing Appeal Panel 7pp 16339 192 24X Fiche 50-155,82/12/03,8212070247

B212070327 Partial response to ASLB 820914 order directing util to demonstrate certain evidentiary deficiencies in emergency planning have been remedied,are not serious or are being remedied through adequate interim compensatory actions
GALLO, J, COPELAND, V O Consumers Power Co GALLO, J Isham, Lincoln & Beale 82/12/03 14pp 16337 220 24X
Fiche 50-155,82/12/03,8212070327

--8212070330 Affidavit of JM Tyler re MI State Police, Emergency Mgt Div, training activities including radiological emergency planning & state & local official training
TYLER, J M Consumers Power Co TYLER, J M Michigan, State of 82/12/02 28pp 16337 234 24X Fiche 50-155,82/12/03,8212070327

--8212070337 Affidavit of E Muma re training of bus drivers for Charlevoix Public School District & program being developed for training & qualifying personnel of other support groups needed during radiological emergency
MUMA, E Consumers Power Co MUMA, E Charlevoix, MI 82/12/01 9pp 16337 262 24X Fiche 50-155,82/12/03,8212070327

--8212070340 Affidavit of WM Miller re annual training of support hosp emergency room staffs & ambulance crews around plant
MILLER, W H Consumers Power Co 82/12/01 4pp 16337 271 24X
Fiche 50-155,82/12/03,8212070327

--8212070345 Affidavit of OT Lasater showing adequate & current list of invalids, senior citizens & others needing transportation assistance in emergency planning zone is being maintained & plan for evacuation is in place
LASATER, O T Consumers Power Co LASATER, O T Charlevoix, MI 82/12/01 20pp 16337 275 24X Fiche 50-155,82/12/03,8212070327

--8212070349 Affidavit of A Saworski re number & availability of Charlevoix County Public Transit Bys buses for invalid evacuation from 5-mile emergency planning zone
SAWORSKI, A Consumers Power Co SAWORSKI, A Charlevoix, MI 82/12/01 4pp 16337 295 24X Fiche 50-155,82/12/03,8212070327

--8212070352 Motion for extension to respond to portions of ASLB 821021 order re Contentions 9(4) & 9(5) Certificate of Svc encl
GALLO, J, COPELAND, V O Consumers Power Co GALLO, J Isham, Lincoln & Beale 82/12/03 Atomic Safety and Licensing Board Panel 7pp 16337,299 24X Fiche 50-155,82/12/03,8212070327

8212080315 Memorandum & order denying util 821124 motion for stay of effectiveness of ASLB 821029 order Extension of time to comply w/order granted Util filing due within 60 days of issuance of ASLB decision on util exceptions to order
BLOCH, P B, PARIS, O H, SHON, F J Atomic Safety and Licensing Board Panel 82/12/07 Consumers Power Co 3pp 16353 347 24X
Fiche 50-155,82/12/07,8212080315

8212160223 Forwards application for subpoena directing HR Denton to appear for deposition
GALLO, J Isham, Lincoln & Beale GALLO, J Consumers Power Co 82/12/13 BLOCH, P B, PARIS, O H, SHON, F J Atomic Safety and Licensing Board Panel 1p 16446 088 24X Fiche 50-155,82/12/13,8212160223

--8212160227 Application for subpoena directing HR Denton to appear for deposition on 821230 in Washington, DC re Denton 820728 memo to ASLB Draft subpoena & Certificate of Svc encl
GALLO, J Consumers Power Co 82/12/13 Atomic Safety and Licensing Board Panel 11pp 16446 089 24X
Fiche 50-155,82/12/13,8212160223

DOCKETED ITEMS

B212160509 Memorandum & order denying until B21213 application for subpoena of HR Denton w/o prejudice ASLB lacks jurisdiction to reopen record on issue pending before ASLB
BLOCH, P B, PARIS, D H, SHON, F J Atomic Safety and Licensing Board Panel B2/12/14 Consumers Power Co 2pp 16442 120 24X
Fiche 50-155, B2/12/14, B212160509

B212110258 Brief in support of exceptions filed to ASLB B21203 order granting immediate appeal from B21029 partial initial decision on neutron multiplication factor O'Neill Contention III E-2 should be dismissed w/Certificate of Svc
GALLO, J, THORNTON, P Consumers Power Co GALLO, J Isham, Lincoln & Beale B2/12/16 Atomic Safety and Licensing Board Panel 30pp 16483 269 24X Fiche 50-155, B2/12/16, B212110258

B212210011 Advises of NRC/applicant agreement re NRC witness depositions Witnesses WL Brooks & DB Fieno will be available for depositions on B21229 in Bethesda, MD
GODDARD, R J Hearing Branch 3 B2/12/17 BLOCH, P B, SHON, F J, PARIS, D H Atomic Safety and Licensing Board Panel 2pp 16490 146 24X Fiche 50-155, B2/12/17, B212210011

B212210285 Further response to ASLB B20914 order re Subcontention 9(4) on evacuation of school children & Subcontention 9(5) on list of invalids Sufficient measures being taken to maintain current list of invalids & senior citizens
GALLO, J, COPELAND, V G Consumers Power Co GALLO, J Isham, Lincoln & Beale B2/12/17 12pp 16497 045 24X
Fiche 50-155, B2/12/17, B212210285

--B21210289 Affidavit of VR Olach explaining evacuation procedures & routes for school children
OLACH, V R Consumers Power Co OLACH, V R Charlevoix, MI B2/12/15 15pp 16497 057 24X Fiche 50-155, B2/12/17, B21210285

--B21210292 Affidavit of OT Lasater re results of recent updating of list of invalids & senior citizens to be evacuated during emergency
LASATER, O T Consumers Power Co LASATER, O T Charlevoix, MI B2/12/16 9pp 16497 072 24X Fiche 50-155, B2/12/17, B21210285

--B21210296 Affidavit of F Hooper re District Health Dept 3 cooperation w/Charlevoix County Sheriff to identify persons w/special care needs who would need assistance to evacuate Certificate of Svc encl
HOOPER, F Consumers Power Co HOOPER, F Charlevoix, MI B2/12/16 8pp 16497 081 24X Fiche 50-155, B2/12/17, B21210285

B212280292 Motion for protective order re deposition of H Denton on criticality issue Deposition must be delayed until all parties available, since intervenors have not received reasonable notice of deposition Certificate of Svc encl
SEMEL, H Christa-Maria SEMEL, H Antioch School of Law, Washington, DC B2/12/23 Atomic Safety and Licensing Board Panel 5pp 16561 356 24X Fiche 50-155, B2/12/23, B212280292

B212300015 Memorandum & order denying Sunflower Alliance B21223 motion for protective order re HR Denton deposition Matter beyond ASLB jurisdiction
BLOCH, P B Atomic Safety and Licensing Board Panel B2/12/27 Sunflower Alliance 1p 16598 308 24X Fiche 50-155, B2/12/27, B212300015

B212300176 Advises that NRC will make witnesses available for depositions on B30110, due to intervenor counsel inability to attend depositions originally scheduled for B21229
GODDARD, R J Hearing Branch 3 B2/12/29 BLOCH, P B, SHON, F J, PARIS, D H Atomic Safety and Licensing Board Panel 1p 16598 106 24X Fiche 50-155, B2/12/29, B212300176

P Operating license stage documents & correspondence

B212140001 Addl response to FOIA request for five categories of documents re SEP Forwards documents listed in App A No documents located sub; to Item 3 of request Review of remaining documents continuing Documents available in PDR
FELTON, J M Division of Rules and Records B2/11/03 GALLO, J Isham, Lincoln & Beale 2pp 16433 354 24X Fiche 50-000, B2/11/03, B212140001

--740890435 Forwards individual plant summaries re seismic capability & recommended interim actions Older SEP plants have less inherent margins to withstand lateral dynamic loads
BAYBIS, D K Systematic Evaluation Program Branch (Pre 791030) 79/06/18 VOLLMER, R H Assistant Director for Systematic Evaluation Program (Pre 791030) 5pp 16434 321 24X
Fiche 50-000, B2/11/03, B212140001

--B203310470 Forwards SEP seismic completion plan to perform review parallel w/license efforts to complete SEP Topic III-6, seismic design considerations for Group II plants
HERMANN, R Systematic Evaluation Program Branch B2/03/08
RUSSELL, W T Systematic Evaluation Program Branch 5pp 16434 276 24X Fiche 50-000, B2/11/03, B212140001

--B204010021 Forwards evaluation for SEP Topic VI-4, "Containment Isolation Sys." Outstanding items include insufficient isolation provisions in test, vent & drain lines & no isolation or leak detection provisions on ECOS subsystem
SPEIS, T P Assistant Director for Reactor Safety B2/03/24
LAJTHAS, G Assistant Director for Safety Assessment 34pp 16434 329 24X Fiche 50-000, B2/11/03, B212140001

--B207203474 Discusses problems w/completion of SER Topic III-6 re seismic design considerations by B20930 Actions required to attempt to meet schedule listed
HERRING, K S Systematic Evaluation Program Branch B2/07/12
RUSSELL, W T Systematic Evaluation Program Branch 3pp 16434 326 24X Fiche 50-000, B2/11/03, B212140001

--B212140149 Discusses SEP site-specific spectra project Project in final stages Comments from Peer Review Group & all other comments should be received by 791130 Listing of references re site-specific spectra (SEP Topic III-6) encl
LEVIN, H A Systematic Evaluation Program Branch 79/11/13
EISENHUT, D G Division of Operating Reactors 4pp 16436 300 24X Fiche 50-000, B2/11/03, B212140001

B212030137 Forwards evaluation of SEP Topic III-1, "Classification of Structures, Components & Sys (Seismic & Quality)" Intro re fracture toughness, full radiography requirements, valves & pipe cyclic loads on piping/fatigue analysis provided
TOKER, K A Consumers Power Co B2/11/23 CRUTCHFIELD, D Operating Reactors Branch 5 58pp 16306 041 24X Fiche 50-155, B2/11/23, B212030137

B212020255 Forwards safety evaluation of SEP Topic VI-1, "Organic Matter & Post-Accident Chemistry," based on licensee B20316 safety assessment rept Facility fails to meet current licensing criteria
CRUTCHFIELD, D Operating Reactors Branch 5 B2/11/24
VANDEWALLE, D J Consumers Power Co 8pp 16279 339 24X
Fiche 50-155, B2/11/24, B212020255

B212020266 Forwards final evaluation of SEP Topic III-4 A, "Tornado Missiles" Sys & components inadequately protected from tornado missiles Evaluation will be basic input to integrated safety assessment
CRUTCHFIELD, D Operating Reactors Branch 5 B2/11/29
VANDEWALLE, D J Consumers Power Co 20pp 16288 330 24X
Fiche 50-155, B2/11/29, B212020266

B212020332 Forwards evaluation of SEP Topic III-4 B, "Turbine Missiles" Turbine protection sys mod should be considered during integrated assessment Descriptions of sys need clarification
CRUTCHFIELD, D Operating Reactors Branch 5 B2/11/29
VANDEWALLE, D J Consumers Power Co 19pp 16279 212 24X
Fiche 50-155, B2/11/29, B212020332

B212020095 "Review of Big Rock Point Plant Request for Deferral of TMI Action Items Considered Nonessential," interim rept
POLASKI, J P, SULLIVAN, W H, GENTILLON, C D EG&O, Inc FIN A-6442
B212020095 B2/11/30 CHOW, E Division of Safety Technology 60pp 16309 080 24X Fiche 50-155, B2/11/30, B212020095

B212230322 Responds to comments on SEP Topics VI-2 D, "Mass & Energy Release for Possible Pipe Breaks Inside Containment" & VI-3 "Containment Pressure & Heat Removal Capability"
CRUTCHFIELD, D Operating Reactors Branch 5 B2/11/30
VANDEWALLE, D J Consumers Power Co 16pp 16507 293 24X
Fiche 50-155, B2/11/30, B212230322

B212070299 Forwards revised draft evaluation of SEP Topic III-3 A, "Effects of High Water Levels on Structures" Containment & turbine bldgs, core spray room & stack adequately designed to withstand effects of design basis flooding level
CRUTCHFIELD, D Operating Reactors Branch 5 B2/12/02
VANDEWALLE, D J Consumers Power Co 8pp 16339 116 24X
Fiche 50-155, B2/12/02, B212070299

B212090117 Notification of B21216 meeting w/util in Bethesda, MD to discuss status of seismic evaluation under SEP
EMCH, R Operating Reactors Branch 5 B2/12/08 CRUTCHFIELD, D Operating Reactors Branch 5 4pp 16357 268 24X
Fiche 50-155, B2/12/08, B212090117

DOCKETED ITEMS

19

0212150030 Forwards Containment Sys Branch final evaluation of SEP Topic VI-4 "Containment Isolation Sys." Isolation valves would be more appropriately located between containment & high pressure HX
CRUTCHFIELD, D Operating Reactors Branch 5 82/12/09
VANDEWALLE, D J Consumers Power Co 47pp 16421 276 24X
Fiche 50-155, 82/12/09, 8212150030

0212230354 Forwards technical evaluation rept of SEP Topic III 2, "Wind & Tornado Loadings, Big Rock Point Nuclear Plant"
CRUTCHFIELD, D Operating Reactors Branch 5 82/12/09
VANDEWALLE, D J Consumers Power Co 14pp 16511 266 24X
Fiche 50-155, 82/12/09, 8212230354

--8209230377 "Wind & Tornado Loadings, CPC, Big Rock Point Nuclear Plant," technical evaluation rept
BARRATT, D J, AGARWAL, R Franklin Institute/Franklin Research Center TER-C5257-405 82/09/21 PERSINKO, D NRC - No Detailed Affiliation Given 98pp 16511 280 24X Fiche 50-155, 82/12/09, 8212230354

0212170082 Submits response to NRC final SER on SEP Topic III-4 B, "Turbine Missiles" OE probabilistic analyses show very low probability of turbine sys failure even at runaway speeds
SEP topic complete
TONER, K A Consumers Power Co 82/12/13 CRUTCHFIELD, D Operating Reactors Branch 5 2pp 16450 352 24X Fiche 50-155, 82/12/13, 8212170082

0212220209 Forwards revised final safety evaluation on SEP Topics V-11 A, "Requirements for Isolation of High & Low Pressure Sys" & V-11 B, "RHR Interlock Requirements"
CRUTCHFIELD, D Operating Reactors Branch 5 82/12/15
VANDEWALLE, D J Consumers Power Co 6pp 16503 004 24X
Fiche 50-155, 82/12/15, 8212220209

0212220429 Forwards revised SER on SEP Topic VII-3, "Sys Required For Safe Shutdown" Design acceptable pending decision on Reg Guide 1.97, Revision 3 backfit
CRUTCHFIELD, D Operating Reactors Branch 5 82/12/17
VANDEWALLE, D J Consumers Power Co 5pp 16503 302 24X
Fiche 50-155, 82/12/17, 8212220429

0212230342 Application to amend License DPR-6, revising Tech Specs to replace min critical heat flux ratio w/min critical power ratio Tech Spec change request necessary to increase thermal power level Class III fee encl
VANDEWALLE, D J Consumers Power Co 82/12/20 CRUTCHFIELD, D Operating Reactors Branch 5 4pp 16505 185 24X
Fiche 50-155, 82/12/20, 8212230342

--0212230343 Proposed Tech Spec replacing min critical heat flux ratio w/min critical power ratio
* Consumers Power Co 82/12/20 2pp 16505 191 24X
Fiche 50-155, 82/12/20, 8212230342

0212280103 Forwards application to amend License DPR-6, changing Tech Specs to clarify existing requirements, to bring facility into closer agreement w/Midland Tech Specs & to achieve closer conformance w/STS
VANDEWALLE, D J Consumers Power Co 82/12/20 CRUTCHFIELD, D Operating Reactors Branch 5 2pp 16564 197 24X
Fiche 50-155, 82/12/20, 8212280103

--0212280107 Application to amend License DPR-6, changing Tech Specs to clarify existing requirements, to bring facility into closer agreement w/Midland Tech Specs & to achieve closer conformance w/STS
DEWITT, R B Consumers Power Co 82/12/17 4pp 16564 199 24X
Fiche 50-155, 82/12/20, 8212280103

--0212280113 Proposed changes to Tech Specs to clarify existing requirements, to bring facility into closer agreement w/Midland Tech Specs & to achieve closer conformance w/STS
* Consumers Power Co 82/12/17 16pp 16564 203 24X
Fiche 50-155, 82/12/20, 8212280103

0212290267 Forwards Amend 55 to License DPR-6, safety evaluation & notice of issuance & availability Amend changes Tech Specs by replacing shift technical advisor w/on-call technical advisor
CRUTCHFIELD, D Operating Reactors Branch 5 82/12/22
VANDEWALLE, D J Consumers Power Co 3pp 16581 048 24X
Fiche 50-155, 82/12/22, 8212290267

--8212290270 Amend 55 to License DPR-6, changing Tech Specs by replacing shift technical advisor w/on-call technical advisor
CRUTCHFIELD, D Operating Reactors Branch 5 82/12/22 5pp 16581 051 24X Fiche 50-155, 82/12/22, 8212290267

--8212290274 Safety evaluation supporting Amend 55 to License DPR-6
* Office of Nuclear Reactor Regulation, Director 82/12/22 3pp 16581 056 24X Fiche 50-155, 82/12/22, 8212290267

--8212290278 Notice of issuance & availability of Amend 55 to License DPR-6
CRUTCHFIELD, D Operating Reactors Branch 5 82/12/22 2pp 16581 059 24X Fiche 50-155, 82/12/22, 8212290267

0212300330 Provides explanation of start date for new inservice testing interval & submittal date for revised inservice testing program per 821209 conference telcon Revised inservice testing program expected in early Jan 1983
CRUTCHFIELD, D Operating Reactors Branch 5 82/12/22
VANDEWALLE, D J Consumers Power Co 4pp 16594 234 24X
Fiche 50-155, 82/12/22, 8212300330

0212170149 "1982 Evaluation of Big Rock Point Nuclear Plant, CPC"
* Institute of Nuclear Power Operations 82/12/31 37pp 16450 229 24X Fiche 50-155, 82/12/31, 8212170149

0 Inspection reports, IE Bulletins & correspondence

0208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants" Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240

0208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters" Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000, 82/11/05, 8208190245

0208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements" Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 197 24X Fiche 50-000, 82/11/18, 8208190251

0212080509 Forwards IE Insp Rept 50-155/82-17 on 820911-1022 & notice of violation
SPESSARD, R L Division of Project & Resident Programs 82/11/22
DEWITT, R B Consumers Power Co 2pp 16352 072 24X
Fiche 50-155, 82/11/22, 8212080509

--0212080515 Notice of violation from insp on 820911-1022
SPESSARD, R L Division of Project & Resident Programs 82/11/22 2pp 16352 074 24X Fiche 50-155, 82/11/22, 8212080509

--8212080522 IE Insp Rept 50-155/82-17 on 820911-1022 Noncompliance noted four control copy vols of facility prints containing discrepancies in changes issued
WRIGHT, O C, PARKER, M E, DOYD, D C Division of Project & Resident Programs 82/11/19 7pp 16352 076 24X Fiche 50-155, 82/11/22, 8212080509

0212030019 Forwards "Seismic Capacities of Masonry Walls at Big Rock Point Nuclear Generating Plant" per SEP Topic III-6, in response to NRC 820920 request for addl info on IE Bulletin 80-11, "Masonry Wall Design" Detailed responses discussed
BORDINE, T C Consumers Power Co 82/11/24 CRUTCHFIELD, D Operating Reactors Branch 5 10pp 16304 338 24X
Fiche 50-155, 82/11/24, 8212030019

--8212030025 "Seismic Capacities of Masonry Walls at Big Rock Point Nuclear Generating Plant"
WESLEY, D A, BANON, H Structural Mechanics Associates, BKA 13703 02 82/08/31 62pp 16304 348 24X Fiche 50-155, 82/11/24, 8212030019

0208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Radiolocks" Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000, 82/11/26, 8208190256

0208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl" Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards, 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000, 82/11/30, 8208190257

0208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies" Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259

DOCKETED ITEMS

B208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03
Consolidated Edison Co of New York, Inc 110pp 16462 064 24X
Fiche 50-000, 82/12/03, B208190261

B212090387 Forwards IE Safeguards Insp Rept 50-155/82-18 on 821025-29
No noncompliance noted
MILLER, J R Division of Engineering & Technical Programs 82/12/03
DEWITT, R B Consumers Power Co 2pp 16364 349 24X
Fiche 50-155, 82/12/03, B212090387

--B212090396 IE Safeguards Insp Rept 50-155/82-18 on 821025-29 No
noncompliance noted Major areas inspected security plan &
implementing procedures, access controls & previous items of
noncompliance Details withheld (ref JOCR73 21)
CHRISTOFFER, Q , BELANDER, J L , CREED, J R Region 3, Office of
Director 82/12/02 1p 16364 351 24X Fiche 50-155, 82/12/03,
8212090387

B212170148 Forwards IE Insp Rept 50-155/82-13 on 820816-19 & notice
of violation
LITTLE, W S Division of Engineering & Technical Programs 82/12/03
DEWITT, R B Consumers Power Co 2pp 16450 276 24X
Fiche 50-155, 82/12/03, B212170148

--B212170154 Notice of violation from insp on 820816-19
LITTLE, W S Division of Engineering & Technical Programs
82/12/03 2pp 16450 278 24X Fiche 50-155, 82/12/03, B212170148

--B212170162 IE Insp Rept 50-155/82-13 on 820816-19 Noncompliance noted
surveillance test for ventilation fire dampers or emergency
lighting units not performed & failure to adhere to
administrative procedures
RAMSEY, C , ULIE, J , WILLIAMS, C C Region 3, Office of Director
82/11/22 18pp 16450 280 24X Fiche 50-155, 82/12/03, B212170148

B212170145 Ack receipt of 821201 ltr informing NRC of steps taken to
correct violations noted in IE Insp Rept 50-155/82-09
NOBELIUS, C E Division of Engineering & Technical Programs
82/12/10 DEWITT, R B Consumers Power Co 1p 16450 266 24X
Fiche 50-155, 82/12/10, B212170145

--B212170150 Responds to NRC 820917 ltr re violations noted in IE Insp
Rept 50-155/82-09 Corrective actions nuclear operations
issued ltr requiring all evaluations be performed within 30
days or issuance of corrective action document
VANDEWALLE, D J Consumers Power Co 82/12/01 KEPLER, J G
Region 3, Office of Director 4pp 16450 267 24X
Fiche 50-155, 82/12/10, B212170145

B208190267 IE Info Notice 82-49, "Correction for Sample Conditions For
Air & Gas Monitoring " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and
Enforcement 82/12/15 Consolidated Edison Co of New York, Inc
127pp 16628 191 24X Fiche 50-000, 82/12/16, B208190267

B212280131 Forwards "Seismic Evaluation of Safety-Related Electrical
Equipment at Big Rock Point Nuclear Plant," in response to
IE Info Notice 80-21 re anchorage & support of
safety-related electrical equipment
BORDINE, T C Consumers Power Co 82/12/16 CRUTCHFIELD, D
Operating Reactors Branch 5 7pp 16563 144 24X
Fiche 50-155, 82/12/16, B212280131

--B212280134 "Seismic Evaluation of Safety-Related Electrical Equipment
at Big Rock Point Nuclear Plant "
+ URS Corp URS/JAB 8051 82/07/31 32pp 16563 151 24X
Fiche 50-155, 82/12/16, B212280131

B208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage
Relays Type ITE-27 " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20
Consolidated Edison Co of New York, Inc 108pp 16628 293 24X
Fiche 50-000, 82/12/20, B208190268

R Periodic operating reports & related correspondence

B212300332 Forwards monthly operating rept for Oct 1982
HOFFMAN, B P Consumers Power Co 82/11/03 Director's Office,
Office of Inspection and Enforcement 1p 16594 005 24X
Fiche 50-155, 82/11/03, B212300332

--B212300341 Monthly operating rept for Oct 1982
AHSTUTI, S R Consumers Power Co 82/11/03 4pp 16594 006 24X
Fiche 50-155, 82/11/03, B212300332

S Reportable occurrences, LERs & related correspondence

B212030114 PNO-111-82-128 chemistry lab sink drain discovered routed to
plant sewerage sys (onsite septic tank & leach field)
instead of radwaste sys Sludge from septic tank dumped in
municipal sanitary sewerage sys Drain capped
LOVENDALE, P C , OREGGER, L R Region 3, Office of Director 82/11/26
2pp 16306 101 24X Fiche 50-155, 82/11/26, B212030114

B212100304 Forwards LER 82-030/03L-0
BORDINE, T C Consumers Power Co 82/12/02 KEPLER, J G Region 3,
Office of Director 1p 16376 276 24X Fiche 50-155, 82/12/02,
B212100304

--B212100309 LER 82-030/03L-0 on 821105, audible alarm unit for fire
detection equipment in zones 1 & 2 of electrical equipment
room found inoperative Caused by loose wiring at panel
termination on Pyrotechnics Model FI U-6 Wire Reconnected
+ Consumers Power Co 82/12/02 Region 3, Office of Director
1p 16376 277 24X Fiche 50-155, 82/12/02, B212100304

DOCKET 50-156 UNIV OF WISCONSIN RESEARCH REACTOR

S Reportable occurrences, LERs & related correspondence

B212140195 RO during wk of 821128, proper operation of intrusion alarm
within interval specified in physical security plan not
verified Caused by employee oversight Alarm immediately
checked
CASHWELL, R J Wisconsin, Univ of Madison 82/12/08 Division
of Licensing 1p 16409 337 24X Fiche 50-156, 82/12/08, B212140195

DOCKET 50-157 CORNELL UNIV RESEARCH REACTOR

R Periodic operating reports & related correspondence

B212140232 Forwards annual operating repts for Licenses R-80 & R-89
For two yrs ending 820630
ADERHOLD, H C Cornell Univ 82/12/06 Region 1, Office of
Director 1p 16409 001 24X Fiche 50-097, 82/12/06, B212140232

--B212140238 Annual operating repts for Licenses R-80 & R-89 for two yrs
ending 820630
ADERHOLD, H C Cornell Univ 82/12/06 Region 1, Office of
Director 3pp 16409 002 24X Fiche 50-097, 82/12/06, B212140232

B212140469 Forwards "Annual Operating Repts" for period ending June
1981 & June 1982 w/o encls
ADERHOLD, H C Cornell Univ 82/12/06 Director's Office, Office
of Inspection and Enforcement 1p 16404 012 24X
Fiche 50-097, 82/12/06, B212140469

B212140146 "Annual Operating Rept, Jul 1980-June 1981 "
ADERHOLD, H C Cornell Univ 82/12/14 Region 1, Office of
Director 3pp 16408 173 24X Fiche 50-097, 82/12/14, B212140146

DOCKET 50-163 GENERAL ATOMIC CO

J Insurance & indemnity information

B212060142 Provides response to B21013 request for clarification re
Indemnity Agreement B-9 & corporate name
DENTON, H R Office of Nuclear Reactor Regulation, Director
82/11/22 MOWRY, W R GA Technologies, Inc /General Atomic Co 1p
16325 354 24X Fiche 50-089, 82/11/22, B212060142

P Operating license stage documents & correspondence

B212060142 Provides response to B21013 request for clarification re
Indemnity Agreement B-9 & corporate name
DENTON, H R Office of Nuclear Reactor Regulation, Director
82/11/22 MOWRY, W R GA Technologies, Inc /General Atomic Co 1p
16325 354 24X Fiche 50-089, 82/11/22, B212060142

DOCKET 50-170 NATIONAL NAVAL MEDICAL CENTER

G Adjudicatory correspondence

B212030223 Notice of I Stillman 821218 notice of deposition in
New York, NY re all issues upon which deponent has aided
Citizens for Nuclear Reactor Safety Certificate of Svc encl
BACHMANN, R G Hearing Branch 1 82/12/01 3pp 16306 288 24X
Fiche 50-170, 82/12/01, B212030223

1 Hearing transcripts on non-antitrust matters

8212030105 Corrected transcript of 821015 prehearing conference in Bethesda, MD. Pp 81-168 Supporting documentation encl
* Atomic Safety and Licensing Board Panel 82/10/15 93pp
16303 101 24X Fiche 50-170, 82/10/15, 8212030105

DOCKET 50-182 PURDUE UNIV RESEARCH REACTOR

1 Operating license stage documents & correspondence

8212130238 Application to amend License R-87, changing Tech Specs to bring surveillance intervals into agreement w/ANS 15.1 & revising min qualifications for radiological control officer
STANSBERRY, E R Purdue Univ 82/12/06 THOMAS, C O
Standardization & Special Projects Branch 1p 16390 129 24X
Fiche 50-182, 82/12/06, 8212130238

--8212130240 Proposed Tech Spec changes to bring surveillance intervals into agreement w/ANS 15.1 & revise min qualifications for radiological control officer
* Purdue Univ 82/12/06 6pp 16390 130 24X
Fiche 50-182, 82/12/06, 8212130238

DOCKET 50-184 NATIONAL BUREAU OF STANDARDS REACTOR

G Inspection reports, IE Bulletins & correspondence

8212290393 Ack receipt of 821104 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-184/82-02
STAROSTECKI, R Division of Project & Resident Programs 82/12/23
CARTER, R S Commerce, Dept of, National Bureau of Standards 2pp
16986 292 24X Fiche 50-184, 82/12/23, 8212290393

--8212290402 Responds to NRC 821008 ltr re violations noted in IE Insp Rept 50-184/82-02 Corrective actions subj individual checked out on pneumatic facility & was on approved list of users
CARTER, R S Commerce, Dept of, National Bureau of Standards
82/11/04 STAROSTECKI, R Division of Project & Resident Programs
2pp 16986 294 24X Fiche 50-184, 82/12/23, 8212290393

S Reportable occurrences, LERs & related correspondence

8212210411 RO on 821126, during routine refueling operations, fuel element 345 fell to upper grid in transfer from core position D-1 to D-7. Caused by operating difficulty in E-2 transfer arm. Element removed & seated
CARTER, R S Commerce, Dept of 82/12/06 STAROSTECKI, R Division of Project & Resident Programs 1p 16493 057 24X
Fiche 50-184, 82/12/06, 8212210411

DOCKET 50-186 UNIV OF MISSOURI RESEARCH REACTOR

F Operating license stage documents & correspondence

8212080331 Application for amend to License R-103, increasing inventory of irradiated fuel
MCKIBBEN, J C, ALGER, D M Missouri, Univ of, Columbia 82/12/03
Office of Nuclear Reactor Regulation, Director 2pp 16353 335
24X Fiche 50-186, 82/12/03, 8212080331

DOCKET 50-187 SPACE RADIATION RESEARCH REACTOR

F Security, medical, emergency & fire protection plans

8212130291 Forwards IE Safeguards Insp Rept 50-187/82-02 on 821013-15 & notice of violation
SPENCER, G S Division of Radiological Safety & Safeguards Program
82/11/24 CRANDALL, W Northrop Corp 2pp 16389 251 24X
Fiche 50-187, 82/11/24, 8212130291

--8212130294 Notice of violation from insp on 821013-15
WENSLAWSKI, F A Division of Radiological Safety & Safeguards Program
82/11/24 1p 16389 253 24X Fiche 50-187, 82/11/24, 8212130291

--8212130298 IE Safeguards Insp Rept 50-187/82-02 on 821013-15
Noncompliance noted annual calibr of area radiation & continuous air monitors not performed from 1980-82
CILLIS, M, WENSLAWSKI, F A, BOOK, H E Division of Radiological Safety & Safeguards Program
82/11/23 14pp 16389 254 24X
Fiche 50-187, 82/11/24, 8212130291

G Inspection reports, IE Bulletins & correspondence

8212130291 Forwards IE Safeguards Insp Rept 50-187/82-02 on 821013-15 & notice of violation
SPENCER, G S Division of Radiological Safety & Safeguards Program
82/11/24 CRANDALL, W Northrop Corp 2pp 16389 251 24X
Fiche 50-187, 82/11/24, 8212130291

--8212130294 Notice of violation from insp on 821013-15
WENSLAWSKI, F A Division of Radiological Safety & Safeguards Program
82/11/24 1p 16389 253 24X Fiche 50-187, 82/11/24, 8212130291

--8212130298 IE Safeguards Insp Rept 50-187/82-02 on 821013-15
Noncompliance noted annual calibr of area radiation & continuous air monitors not performed from 1980-82
CILLIS, M, WENSLAWSKI, F A, BOOK, H E Division of Radiological Safety & Safeguards Program
82/11/23 14pp 16389 254 24X
Fiche 50-187, 82/11/24, 8212130291

R Periodic operating reports & related correspondence

8212080194 Forwards "Natural Environ Radioactivity Survey for Period of Sept 1981-Aug 1982"
CRANDALL, W E Northrop Corp 82/10/29 Director's Office, Office of Inspection and Enforcement 1p 16354 045 24X
Fiche 50-187, 82/10/29, 8212080194

--8212080200 "Natural Environ Radioactivity Survey for Period of Sept 1981-Aug 1982"
AVANT, D, COZENS, G, WOODS, J Northrop Corp 82/10/29 7pp
16354 046 24X Fiche 50-187, 82/10/29, 8212080194

DOCKET 50-193 RHODE ISLAND & PROVIDENCE PLANTATIONS AEC

G Inspection reports, IE Bulletins & correspondence

8212290488 Forwards IE Insp Rept 50-193/82-02 on 821108-09 & notice of violation
STAROSTECKI, R Division of Project & Resident Programs 82/12/15
DIHEGLIO, A F Rhode Island, State of 2pp 16583 265 24X
Fiche 50-193, 82/12/15, 8212290488

--8212290490 Notice of violation from insp on 821108-09
* Division of Project & Resident Programs 82/12/15 1p
16583 267 24X Fiche 50-193, 82/12/15, 8212290488

--8212290492 IE Insp Rept 50-193/82-02 on 821108-09 Noncompliance noted failure to have monitoring sys & emergency procedures for criticality accident
KINNEY, W H, KEIMIG, R R Division of Project & Resident Programs
82/12/13 5pp 16583 268 24X Fiche 50-193, 82/12/15, 8212290488

DOCKET 50-201 WEST VALLEY REPROCESSING PLANT

F Operating license stage documents & correspondence

8212130430 Trip rept of 820813 site visit re completion of work involved in investigating physical characteristics of Rockwell waste tanks. Addl time & funding needed to complete work. Review of draft final rept would not affect schedule
CLARK, A T Advanced Fuel & Spent Fuel Licensing Branch 82/08/18
ROUSE, L C Advanced Fuel & Spent Fuel Licensing Branch 1p
16413 083 24X Fiche 50-201, 82/08/18, 8212130430

DOCKET 50-206 SAN ONOFRE NUCLEAR STATION, UNIT 1

F Security, medical, emergency & fire protection plans

8212070002 Notifies that SEP Topic IX-6, "Fire Protection," completed Request for exemption from implementation schedule under review
PAULSON, W Operating Reactors Branch 5 82/12/02 DIETCH, R
Southern California Edison Co 2pp 16327 235 24X
Fiche 50-206, 82/12/02, 8212070002

8212090532 Forwards IE Safeguards Insp Repts 50-206/82-29 & 50-361/82-29 on 821031-1105 & notice of violation Notice of violation 3 insp rept withheld (ref 10CFR2.790)
NORDERHAUG, L R Division of Radiological Safety & Safeguards Program
82/12/06 PAPAY, L T Southern California Edison Co 2pp
16366 106 24X Fiche 50-206, 82/12/06, 8212090532

DOCKETED ITEMS

8212140151 Responds to 821202 telcon request & documents 821122 & 23 conversations re emergency response facilities Facility declared operational on 821001
BASKIN, K P Southern California Edison Co 82/12/07
CRUTCHFIELD, D Operating Reactors Branch 5 2pp 16408 167 24X
Fiche 50-206, 82/12/07, 8212140151

8212170158 Informs of current revisions to schedules for availability of qualification documentation for electrical equipment, updating 820702 & 0907 schedules
KRIEGER, R H Southern California Edison Co 82/12/15
CRUTCHFIELD, D Operating Reactors Branch 5 2pp 16459 231 24X
Fiche 50-206, 82/12/15, 8212170158

8212170164 Forwards "Conceptual Study of Remote Shutdown Panel & Associated Circuits Evaluation re App R, Section III G 3 & NRC Request for Info," supplementing 820630 response to Generic Ltr 81-12, dtd 810220
BASKIN, K P Southern California Edison Co 82/12/15
CRUTCHFIELD, D Operating Reactors Branch 5 2pp 16459 233 24X
Fiche 50-206, 82/12/15, 8212170164

--8212170168 "Conceptual Study of Remote Shutdown Panel & Associated Circuits Evaluation re App R, Section III G 3 & NRC Request for Info"
* Southern California Edison Co * San Diego Gas & Electric Co
82/12/31 71pp 16459 235 24X Fiche 50-206, 82/12/15, 8212170164

J Insurance & indemnity information

9212270171 Forwards Endorsements 89 & 90 to NELIA Policy NF-146, Endorsements 77 - 79 to MAELU Policy NF-79, Endorsement 35 to NELIA Policy NF-282, Endorsement 1 to NELIA Binder EB-87 & Endorsement 1 to MAELU Binder XB-87
ROCCO, J Southern California Edison Co 82/12/20 DINI, I
Antitrust & Economic analysis Branch (Utility Finance) 19pp
16538 347 24X Fiche 50-206, 82/12/20, 8212270171

P Operating license stage documents & correspondence

8212140001 Addl response to FOIA request for five categories of documents re SEP Forwards documents listed in App A No documents located subg to Item 3 of request Review of remaining documents continuing Documents available in PDR
FELTON, J M Division of Rules and Records 82/11/03 GALLO, J
Isham, Lincoln & Beale 2pp 16433 354 24X Fiche 50-000, 82/11/03, 8212140001

--7908140421 Forwards, for review, summary & questions re seismic re-evaluation & RCS mod
MURRAY, R C Lawrence Livermore Laboratory 79/08/03 LEVIN, H A
Systematic Evaluation Program Branch (Pre 791030) 12pp
16433 001 24X Fiche 50-000, 82/11/03, 8212140001

--7912190426 Notifies of info required from applicant re independent confirmatory piping analysis
BOSNAK, R J Mechanical Engineering Branch 79/12/06
RUGENSTEIN, L Light Water Reactors Branch 4 2pp 16435 014
24X Fiche 50-000, 82/11/03, 8212140001

--8001180235 Comments on evaluation of ground motion modelling study Any choice of design evaluation should be sufficiently feasible to allow for changes in spectrum
REITER, L Geosciences Branch 80/01/03 JACKSON, R E
Geosciences Branch 3pp 16435 016 24X Fiche 50-000, 82/11/03, 8212140001

--8002130081 Discusses assessment impact of earthquake data upon facility modeling study, "Simulation of Earthquake Ground Motion"
Recommends that util provide program outline for assessing data impact upon calibr of slip function
JACKSON, R Geosciences Branch 80/01/21 CRUTCHFIELD, D
Systematic Evaluation Program Branch 2pp 16435 019 24X
Fiche 50-000, 82/11/03, 8212140001

--8002270255 Recommends that util be asked to submit outline of proposed scope, schedule & evaluation criteria for seismic re-evaluation program by 800401 Justification for continued operation until plan completed should be submitted
CRUTCHFIELD, D Systematic Evaluation Program Branch 80/02/05
EISENHUT, D Q Division of Operating Reactors 2pp 16434 256
24X Fiche 50-000, 82/11/03, 8212140001

--8003310092 Suggests review of existing high resolution seismic profiling to define possible Christiansitos-Offshore Deformation Zone USOC to assist
JACKSON, R E Geosciences Branch 80/03/18 KNIGHT, J P
Assistant Director for Engineering 1p 16434 258 24X
Fiche 50-000, 82/11/03, 8212140001

--8005050726 "Vertical Spectra from 1979 Imperial Earthquake"
* Southern California Edison Co 80/03/31 24pp 16435 021
24X Fiche 50-000, 82/11/03, 8212140001

--8006090164 Forwards proposed outline for responding to JL Smith 791114 petition re seismic data Adequate basis may exist for denying petition provided steps are taken by licensee to develop more complete program
CRUTCHFIELD, D Operating Reactors Branch 5 80/05/23 LAINAS, G
Assistant Director for Safety Assessment KNIGHT, J Assistant
Director for Components & Structures Engineering 5pp 16435 046
24X Fiche 50-000, 82/11/03, 8212140001

--8006090788 Forwards five items re ground motion modelling for facility w/o encls
REITER, L Geosciences Branch 80/04/14 SHERBURNE, R
California, State of 1p 16435 045 24X Fiche 50-000, 82/11/03, 8212140001

--8007180114 Forwards NRC formal question, requesting that util perform evaluation of estimated earthquake ground motion for Unit 1 based on deterministic modeling & ground motion for Units 2 & 3, based upon empirical evaluation
CARDONE, A T Geosciences Branch 80/06/11 DAVIS, J California, State of 1p 16434 259 24X Fiche 50-000, 82/11/03, 8212140001

--8007230260 Forwards transcripts of 800520-21 meetings w/ licensee re need for addl offshore seismic profiles w/o encl
CARDONE, A T Geosciences Branch 80/06/04 AMIMOTO, P
California, State of 1p 16435 052 24X Fiche 50-000, 82/11/03, 8212140001

--8009290433 Request for procurement NRR-7B-184 to execute mod to "Simulation of Earthquake Ground Motions for San Onofre Nuclear Generating Station Unit 1" Contractor K Aki
VOLLMER, R H Division of Engineering FIN B-6831 80/06/13
5pp 16435 053 24X Fiche 50-000, 82/11/03, 8212140001

--8010150236 Request for procurement NRR-80-143 to award sole source contract to JE Luco for "Followon to Simulation of Earthquake Ground Motion for San Onofre Nuclear Generating Station"
VOLLMER, R H Division of Engineering FIN B-6898-0 80/08/04
7pp 16435 057 24X Fiche 50-000, 82/11/03, 8212140001

--8010150242 Requests for procurement NRR-80-145 to award sole source contract to R Herrmann for "Followon to Simulation of Earthquake Ground Motions for San Onofre Nuclear Generating Station"
VOLLMER, R H Division of Engineering FIN B-6898-0 80/08/04
7pp 16435 065 24X Fiche 50-000, 82/11/03, 8212140001

--8010150246 Request for procurement NRR-80-144 to award sole source contract to K Aki for "Followon to Simulation of Earthquake Ground Motions for San Onofre Nuclear Generating Station"
VOLLMER, R H Division of Engineering FIN B-6898-0 80/08/04
7pp 16434 247 24X Fiche 50-000, 82/11/03, 8212140001

--8010170283 Forwards Div of Engineering 800904 memo re seismic rept related to SEP review for transmittal to appropriate hearing boards
EISENHUT, D Q Division of Licensing 80/09/23 NOVAK, T
Assistant Director for Operating Reactors TEDESCO, R Division of
Licensing 1p 16435 078 24X Fiche 50-000, 82/11/03, 8212140001

--8010170287 Provides outline of rept, "Simulation of Earthquake Ground Motions for San Onofre Nuclear Generating Station, Unit 1, Suppl III" Rept may be useful to hearing boards concerned w/near-field earthquake motion
VOLLMER, R H Division of Engineering 80/09/04 EISENHUT, D Q
Division of Licensing 1p 16435 079 24X Fiche 50-000, 82/11/03, 8212140001

--8110190952 Provides addl info supporting conclusion that three northern columns of turbine bldg cannot be modified per 810928 ltr due to limitations created by adjacent structures
BASKIN, K P Southern California Edison Co 81/10/06
CRUTCHFIELD, D Operating Reactors Branch 5 3pp 16435 080 24X
Fiche 50-000, 82/11/03, 8212140001

--8112110356 Discusses 811117, 18 & 19 telcons w/ licensee re need for extensive mods to preliminary seismic design of spent fuel bldg submitted in June 1981 (ref SEP Topic III-6) Details of new mods will be available after 820125
RUSSELL, H T Systematic Evaluation Program Branch 81/11/20
Systematic Evaluation Program Branch 2pp 16435 083 24X
Fiche 50-000, 82/11/03, 8212140001

- 8203310670 Forwards SEP seismic completion plan to perform review parallel w/ license efforts to complete SEP Topic III-6, seismic design considerations, for Group II plants
HERMANN, R Systematic Evaluation Program Branch 82/03/08
RUSSELL, W T Systematic Evaluation Program Branch 5pp 16434 276 24X Fiche 50-000, 82/11/03, 8212140001
- 8212140149 Discusses SEP site-specific spectra project Project in final stages Comments from Peer Review Group & all other comments should be received by 7/11/30 Listing of references re site-specific spectra (SEP Topic III-6) encl
LEVIN, H A Systematic Evaluation Program Branch 7/11/13
EISENHUT, D O Division of Operating Reactors 4pp 16436 300 24X Fiche 50-000, 82/11/03, 8212140001
- 8212010047 Forwards pages omitted from June 1980 LLL technical evaluation re overpressure mitigation sys encl in NRC
821028 ltr
PAULSON, W A Operating Reactors Branch 5 82/11/04 DIETCH, R
Southern California Edison Co 14pp 16260 319 24X
Fiche 50-206, 82/11/04, 8212010047
- 8212020252 Discusses util response to SEP Topic VIII-1 A, "Potential Equipment Failures Associated W/Degraded Grid Voltage " Topic complete for purposes of integrated assessment
PAULSON, W A Operating Reactors Branch 5 82/11/23 DIETCH, R
Southern California Edison Co 2pp 16279 335 24X
Fiche 50-206, 82/11/23, 8212020252
- 8212020197 Responds to 821004 ltr providing addl comments supporting position that fee not applicable to 820625 application
Fee position reassessed in light of addl info
No fee due for clarification of Tech Specs 82/11/24 BASKIN, K P
HILLER, W O License Fee Management Branch 1p 16308 287 24X
Southern California Edison Co 1p 16308 287 24X
Fiche 50-206, 82/11/24, 8212020197
- 8212140366 Forwards marked-up draft of radiological ETS annotated w/review comments from site visit Telcon suggested to discuss comments w/util, E&G & NRC representative
SERRANO, W E&G, Inc 82/11/24 KRIEGER, R Southern California Edison Co 9pp 16401 044 24X Fiche 50-206, 82/11/24, 8212140366
- 8212010023 Forwards summary of resolution for items discussed at 821110 meeting re SEP Topic III-6, "Seismic Design Considerations " Evaluations supporting NRC review also encl
PAULSON, W A Operating Reactors Branch 5 82/11/26 DIETCH, R
Southern California Edison Co 11pp 16260 139 24X
Fiche 50-206, 82/11/26, 8212010023
- 8212060403 Submits detailed comments on structural review of seismic re-evaluation Subcontractor rept submitted w/o critical review due to time constraints Uncertainty in soil structure interaction & concrete tensile strength discussed
NELSON, T A Lawrence Livermore Laboratory 82/10/15 HERMANN, R
Systematic Evaluation Program Branch 7pp 16260 151 24X
Fiche 50-206, 82/11/26, 8212010023
- 8212010036 "Review of Seismic Re-evaluation of Reactor Bldg & Balance of Plant Structures of San Onofre Nuclear Generating Station, Unit 1 "
TSAI, N C NCT Engineering, Inc 82/09/30 84pp 16260 155 24X
Fiche 50-206, 82/11/26, 8212010023
- 8212020250 Forwards comments re NRC 820914 evaluation of util response to SEP Topic IV-2, "Reactivity Control Sys "
KRIEGER, R W Southern California Edison Co 82/11/30
CRUTCHFIELD, D Operating Reactors Branch 5 2pp 16279 337 24X
Fiche 50-206, 82/11/30, 8212020250
- 8212020253 Advises that return to power date delayed beyond 821128
Precise date cannot be established at present Return to power dependent on NRC approval of acceptability of util response to SEP Topic III-6, "Schedule for Seismic Mods "
BASKIN, K P Southern California Edison Co 82/11/30
CRUTCHFIELD, D Operating Reactors Branch 5 2pp 16279 333 24X
Fiche 50-206, 82/11/30, 8212020253
- 8212060239 Summarizes status of open items identified at 820728-30 meeting w/NRC re SEP Topic III-6 concerning seismic design re-evaluation, supplementing util 820826 & 0915 responses
BASKIN, K P Southern California Edison Co 82/11/30
CRUTCHFIELD, D Operating Reactors Branch 5 2pp 16312 267 24X
Fiche 50-206, 82/11/30, 8212060239
- 8212020307 Requests addl info re SEP Topic II-4 F, "Settlement of Structures & Buried Equipment" per 811102 safety assessment
Response requested within 30 days of receipt of ltr
PAULSON, W A Operating Reactors Branch 5 82/12/01 DIETCH, R
Southern California Edison Co 16pp 16277 318 24X
Fiche 50-206, 82/12/01, 8212020307
- 8212060269 Forwards Revision 2 to "PWR Safety & Relief Valve Adequacy Rept for San Onofre, Unit 1 " Addl valve specific analyses will be submitted as suppl by 830601
BASKIN, K P Southern California Edison Co 82/12/02
CRUTCHFIELD, D Operating Reactors Branch 5 2pp 16311 088 24X
Fiche 50-206, 82/12/02, 8212060269
- 8212060276 Revision 2 to "PWR Safety & Relief Valve Adequacy Rept for San Onofre, Unit 1 " Safety valve discharge piping adequacy analysis encl W/four oversize drawings Aperture cards are available in PDR
KELLY, R E Westinghouse Electric Corp 82/11/30 90pp 16311 091 24X Fiche 50-206, 82/12/02, 8212060269
- 8212070266 Submits info for post-implementation review of NUREG-0737, Item II D 3, "Post-Accident Sampling Sys " W/six oversize drawings Aperture cards are available in PDR
BASKIN, K P Southern California Edison Co 82/12/03
CRUTCHFIELD, D Operating Reactors Branch 5 9pp 16336 352 24X
Fiche 50-206, 82/12/03, 8212070266
- 8212100009 Forwards revised safety evaluation re SEP Topic VIII-4, "Electrical Penetrations of Reactor Containment " Design of electrical protection circuits for containment penetrations does not meet licensing criteria Design changes recommended
PAULSON, W A Operating Reactors Branch 5 82/12/06 DIETCH, R
Southern California Edison Co 5pp 16379 149 24X
Fiche 50-206, 82/12/06, 8212100009
- 8212100020 Forwards revised SER of SEP Topic VI-4, "Containment Isolation Sys," based on addl info contained in KP Baskin 821122 ltr Design acceptable if visual display provided to show safety injection sys block status
PAULSON, W A Operating Reactors Branch 5 82/12/06 DIETCH, R
Southern California Edison Co 6pp 16379 126 24X
Fiche 50-206, 82/12/06, 8212100020
- 8212080283 Notification of 821217 meeting w/util in Bethesda, MD to appeal certain NRC positions re SEP Topic III-6, "Seismic Design Considerations "
PAULSON, W A Operating Reactors Branch 5 82/12/07 CRUTCHFIELD, D
Operating Reactors Branch 5 3pp 16354 183 24X
Fiche 50-206, 82/12/07, 8212080283
- 8212090103 Submits schedule for completion of draft safety assessments on SEP Topics III 5A & III 5B, per NRC 821112 ltr Topics for which evaluations have been received will be submitted by 830115
BASKIN, K P Southern California Edison Co 82/12/07
CRUTCHFIELD, D Operating Reactors Branch 5 2pp 16357 303 24X
Fiche 50-206, 82/12/07, 8212090103
- 8212130204 Forwards evaluation of SEP Topic IX-1, "Fuel Storage," based on 820429, 0901 & 1116 submittals Fuel storage facility acceptable Structural capability re seismic capacity will be reviewed in SEP Topic III-6 re tornado missiles
PAULSON, W A Operating Reactors Branch 5 82/12/07 DIETCH, R
Southern California Edison Co 13pp 16396 180 24X
Fiche 50-206, 82/12/07, 8212130204
- 8208190263 Generic Ltr 82-32 to all PWR licensees re potential steam generator-related generic requirements Forwards Science Applications, Inc draft rept re subj requirements Comments requested within 30 days of ltr Svc list encl
EISENHUT, D O Division of Licensing 82/12/09 Consolidated
Edison Co of New York, Inc 29pp 16629 247 24X
Fiche 50-000, 82/12/09, 8208190263
- 8212200063 Informs that proposed changes to Tech Spec will be provided approx 60 days prior to return to power from current outage, in response to 820920 Generic Ltr 82-16 & NUREG-0737
KRIEGER, R W Southern California Edison Co 82/12/09
CRUTCHFIELD, D Operating Reactors Branch 5 2pp 16474, 310 24X
Fiche 50-206, 82/12/09, 8212200063
- 8212140103 Generic Ltr 82-28 to all licensees of operating Westinghouse & C-E PWRs (except Arkansas Nuclear One, Unit 2 & San Onofre 2 & 3) re inadequate core cooling instrumentation sys Bvc list encl
EISENHUT, D O Division of Licensing 82/12/10 Yankee Atomic
Electric Co 27pp 16690 035 24X Fiche 50-000, 82/12/10, 8212140103
- 8212200028 Provides current schedule for completion of long-term emergency operating instruction effort re NUREG-0737, Item 1 C 1
BASKIN, K P Southern California Edison Co 82/12/13
CRUTCHFIELD, D Operating Reactors Branch 5 2pp 16474 271 24X
Fiche 50-206, 82/12/13, 8212200028

DOCKETED ITEMS

- B212210293 Summary of B21007 meeting w/util re status of guideline preparation for development of emergency operating instructions for facility, per TMI Action Item I C 1
PAULSON, W A Operating Reactors Branch 5 B2/12/13 Operating
Reactors Branch 5 10pp 16497 029 24X Fiche 50-206, B2/12/13, B212210293
- B212160018 Notification of B21216 meeting w/util in Bethesda, MD to discuss analysis criteria re seismic re-evaluation, SEP
Topic III-6
PAULSON, W A Operating Reactors Branch 5 B2/12/14 CRUTCHFIELD, D
Operating Reactors Branch 5 3pp 16446 123 24X
Fiche 50-206, B2/12/14, B212160018
- B212210001 Informs of addl action to be taken to verify adequacy of station electric distribution sys Study will be performed to optimize transformer tap settings Revised settings will be implemented prior to startup from current outage
BASKIN, K P Southern California Edison Co B2/12/14
CRUTCHFIELD, D Operating Reactors Branch 5 1p 16485 259 24X
Fiche 50-206, B2/12/14, B212210001
- B212170158 Informs of current revisions to schedules for availability of qualification documentation for electrical equipment, updating B20702 & 0907 schedules
KRUEGER, R W Southern California Edison Co B2/12/15
CRUTCHFIELD, D Operating Reactors Branch 5 2pp 16459 231 24X
Fiche 50-206, B2/12/15, B212170158
- B212220447 Forwards final evaluation of SEP Topic XV-2, "Spectrum of Sys Piping Failures Inside & Outside of Containment"
Qualification of main feedwater sys to function in required mode under accident conditions should be addressed
PAULSON, W A Operating Reactors Branch 5 B2/12/17 DETCH, R
Southern California Edison Co 10pp 16503 292 24X
Fiche 50-206, B2/12/17, B212220447
- B212220198 Forwards responses to NRC questions re seismic re-evaluation of fuel storage bldg, per SEP Topic III-6 Detailed model of structure & digitized time histories used in evaluation
encl
BASKIN, K P Southern California Edison Co B2/12/20
CRUTCHFIELD, D Operating Reactors Branch 5 576pp 16520 197 24X
Fiche 50-206, B2/12/20, B212220198
- 0 Inspection reports, IE Bulletins & correspondence
- B212290023 FOIA request for documents re EE Kent allegations concerning facilities
COHEN, E M, CARPENTER, T, JACOBSON, J Orange County Alliance for Survival B2/10/27 FELTON, J M Division of Rules and Records
1p 16607 055 24X Fiche 50-206, B2/10/27, B212290023
- B208190240 IE Bulletin B2-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants" Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement B2/10/28 Consolidated Edison Co of New York, Inc
112pp 16462 163 24X Fiche 50-000, B2/10/28, B208190240
- B208190245 IE Info Notice B2-42, "Defects Observed in Panasonic Model B01 & Model B02 Thermoluminescent Dosimeters" Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards
B2/11/05 Consolidated Edison Co of New York, Inc 110pp
16372 142 24X Fiche 50-000, B2/11/05, B208190245
- B208190251 IE Info Notice B2-44, "Clarification of Emergency Plan Exercise Requirements" Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance B2/11/18
Consolidated Edison Co of New York, Inc 109pp 16411 199 24X
Fiche 50-000, B2/11/18, B208190251
- B212060156 Forwards IE Insp Repts 50-206/B2-33 & 50-361/B2-33 on B21025-28 & notice of violation
BODK, H E Region 5, Office of Director B2/11/19 PAPAY, L T
Southern California Edison Co 4pp 16313 120 24X
Fiche 50-206, B2/11/19, B212060156
- B212060161 Notice of violation from insp on B21025-28
* Region 5, Office of Director B2/11/19 4pp 16313 122 24X
Fiche 50-206, B2/11/19, B212060156
- B212060168 IE Insp Repts 50-206/B2-33 & 50-361/B2-33 on B21025-28
Noncompliance noted failure to post notice to workers, described in 10CFR19.11, Paragraph 3
YUHAS, G P, WENSLAWSKI, F A, BODK, H E Division of Radiological Safety & Safeguards Program B2/11/18 9pp 16313 126 24X
Fiche 50-206, B2/11/19, B212060156
- B208190256 IE Info Notice B2-46, "Defective & Obsolete Combination Padlocks" Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement B2/11/26 Consolidated Edison Co of New York, Inc
127pp 16411 065 24X Fiche 50-000, B2/11/26, B208190256
- B208190257 IE Info Notice B2-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl" Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards
B2/11/30 Consolidated Edison Co of New York, Inc 356pp
16387 028 24X Fiche 50-000, B2/11/30, B208190257
- B212170369 Forwards IE Insp Repts 50-206/B2-31, 50-361/B2-31 & 50-362/B2-27 on B21015-1115 No noncompliance noted
HISHOP, T W Division of Resident, Reactor Project & Engineering Programs B2/11/30 PAPAY, L T Southern California Edison Co
4pp 16455 279 24X Fiche 50-206, B2/11/30, B212170369
- B212170376 IE Insp Repts 50-206/B2-31, 50-361/B2-31 & 50-362/B2-27 on B21015-1115 No noncompliance noted Major areas inspected
allegations re design inadequacies & deficiencies in implementation of welding codes & stds
HERNANDEZ, G, WAGNER, W J, KIRSCH, D F Division of Resident, Reactor Project & Engineering Programs B2/11/30 43pp
16455 283 24X Fiche 50-206, B2/11/30, B212170369
- B212170383 Requests notification if list of items to be submitted by B21103 re welding code requirements not correct
ENGELKEN, R H Region 5, Office of Director B2/10/29 PAPAY, L T
Southern California Edison Co 1p 16455 326 24X
Fiche 50-206, B2/11/30, B212170369
- B212170384 Responds to NRC B21029 ltr re allegations concerning const quality & welding code requirements
PAPAY, L T Southern California Edison Co B2/11/03
ENGELKEN, R H Region 5, Office of Director 11pp 16455 327 24X
Fiche 50-206, B2/11/30, B212170369
- B212170386 Forwards Bechtel B21029 response to allegations re const quality, per request made at B21103 site meeting
CURRAN, J M Southern California Edison Co B2/11/03 KIRSCH, D F
Region 5, Office of Director 37pp 16455 338 24X
Fiche 50-206, B2/11/30, B212170369
- B212080291 Transmits reply to B21029 request for technical assistance in evaluating EE Kent Allegation Items 2, 5, 6 & 8 Evaluation
concludes allegations unsubstantiated
EISENHUT, D G Division of Licensing B2/11/30 CREWS, J L
Division of Resident, Reactor Project & Engineering Programs 1P
16456 013 24X Fiche 50-206, B2/11/30, B212170369
- B212290023 Forwards safety evaluation of E Kent allegations re weldments at plants Allegations have no merit & no further action should be taken
JOHNSTON, W V Assistant Director for Materials & Qualifications
Engineering B2/11/17 NOVAK, T M Assistant Director for Licensing 14pp 16456 014 24X Fiche 50-206, B2/11/30, B212170369
- B208190259 IE Bulletin B2-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies" Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement B2/12/03 Consolidated Edison Co of New York, Inc
113pp 16411 317 24X Fiche 50-000, B2/12/03, B208190259
- B208190261 IE Info Notice B2-48, "Failures of Agastat CR 0095 Relay Baskets" Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance B2/12/03
Consolidated Edison Co of New York, Inc 110pp 16462 064 24X
Fiche 50-000, B2/12/03, B208190261
- B212290030 Partial response to FOIA request for documents re EE Kent allegations concerning facilities Forwards Documents 1, 2, 4, 7, 10, 15 & 16 listed in App A Remaining documents will be released when insp rpt issued Tapes available in PDR
FELTON, J M Division of Rules and Records B2/12/03 CARPENTER, T
Orange County Alliance for Survival 3pp 16607 056 24X
Fiche 50-206, B2/12/03, B212290030
- B212290035 Summarizes B21006 telcon w/J O'Dell (LA Times) re EE Kent allegations concerning welding practice at facilities
KIRSCH, D F Division of Resident, Reactor Project & Engineering Programs B2/10/06 Division of Resident, Reactor Project & Engineering Programs 2pp 16607 077 24X
Fiche 50-206, B2/12/03, B212290030
- B212290038 Forwards util/Bechtel QA audit package re EE Kent allegations concerning facilities
CURRAN, J M Southern California Edison Co B2/10/07 KIRSCH, D F
Region 5, Office of Director 48pp 16607 079 24X
Fiche 50-206, B2/12/03, B212290030

--B212290042 Lists EE Kent concerns re facilities, per B21022 discussions w/Kent
KIRSCH, D F Division of Resident, Reactor Project & Engineering Programs B2/10/22 CURRAN, J Southern California Edison Co 1p 16607 127 24X Fiche 50-206, B2/12/03, B212290030

--B212290049 Figure NB-4250-1, "Welding End Transitions - Max Envelope," w/annotation "Example of Approx Slopes Discovered B21025 at San Onofre Nuclear Generating Stations " Charts re welding & pipe support encl
KENT, E E Affiliation Unknown B2/11/12 3pp 16607 129 24X Fiche 50-206, B2/12/03, B212290030

B212090532 Forwards IE Safeguards Insp Repts 50-206/B2-29 & 50-361/B2-29 on B21031-1105 & notice of violation Notice of violation & insp rept withheld (ref 10CFR2 790)
NORDERHAUQ, L R Division of Radiological Safety & Safeguards Program B2/12/06 PAPAY, L J Southern California Edison Co 2pp 16366 105 24X Fiche 50-206, B2/12/06, B212090532

B212130329 Ack receipt of B21119 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-206/B2-26
BISHOP, T W Division of Resident, Reactor Project & Engineering Programs B2/12/09 PAPAY, L J Southern California Edison Co 1p 16367 285 24X Fiche 50-206, B2/12/09, B212130329

--B212130333 Responds to NRC B21021 ltr re violations noted in IE Insp Rept 50-206/B2-26 Corrective actions missing evaluations will be identified & corrected through B21119 Nuclear Audit & Review Committee evaluation will be completed by B20429
PAPAY, L T Southern California Edison Co B2/11/19 ENGELKEN, R H Region 5, Office of Director 3pp 16389 286 24X Fiche 50-206, B2/12/09, B212130329

B208190267 IE Info Notice B2-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement B2/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, B2/12/16, B208190267

B208190268 IE Info Notice B2-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27 " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance B2/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X Fiche 50-000, B2/12/20, B208190268

R Periodic operating reports & related correspondence

B212290102 Forwards monthly operating rept for Oct 1982
RAY, H B Southern California Edison Co B2/11/15 Office of Resource Management, Director 1p 16583 234 24X Fiche 50-206, B2/11/15, B212290102

--B212290106 Monthly operating rept for Oct 1982
SPEER, H J Southern California Edison Co B2/11/15 5pp 16583 235 24X Fiche 50-206, B2/11/15, B212290102

S Reportable occurrences, LERs & related correspondence

B212140360 Forwards LER B2-027/03L-0 Detailed event analysis submitted
RAY, H B Southern California Edison Co B2/12/02 ENGELKEN, R H Region 5, Office of Director 2pp 16401 041 24X Fiche 50-206, B2/12/02, B212140360

--B212140368 LER B2-027/03L-0 on B21103, letdown isolation ball valve CV-326 outside containment failed to remain in open position after two cycling attempts Caused by sticking latching arm in valve actuator Investigation continuing
RAY, H B Southern California Edison Co B2/12/02 Region 5, Office of Director 1p 16401 043 24X Fiche 50-206, B2/12/02, B212140360

DOCKET 50-213 HADDAM NECK PLANT

F Security, medical, emergency & fire protection plans

B212030165 Forwards IE Insp Rept 50-213/B2-18 on B20929-1001 No noncompliance noted
MARTIN, T T Division of Engineering & Technical Programs B2/11/17 COUNSIL, W G Connecticut Yankee Atomic Power Co 2pp 16306 105 24X Fiche 50-213, B2/11/17, B212030165

--B212030175 IE Insp Rept 50-213/B2-18 on B20929-1001 No noncompliance noted Major areas inspected security plan & implementing procedures, security organization, records, repts & training & qualification & contingency plans
MCKEOWN, L M, GODY, A T Region 1, Office of Director B2/11/10 5pp 16306 107 24X Fiche 50-213, B2/11/17, B212030165

B212150036 Forwards Revision 1 to suitability, training & qualification plan Revision withheld (ref 10CFR2 790(d) & 10CFR73 21)
COUNSIL, W G Connecticut Yankee Atomic Power Co B2/11/22 EISENHUT, D G Division of Licensing 1p 16421 235 24X Fiche 50-213, B2/11/22, B212150036

B212020299 Forwards Revision 3 to safeguards contingency plan Revision withheld (ref 10CFR2 790 & 10CFR73 21)
COUNSIL, W G, CAGNETTA, J P Connecticut Yankee Atomic Power Co B2/11/24 CRUTCHFIELD, D Operating Reactors Branch 5 2pp 16277 352 24X Fiche 50-213, B2/11/24, B212020299

B212140074 Forwards IE Insp Rept 50-213/B2-19 on B20927-1107 No noncompliance noted
STAROSTECKI, R Division of Project & Resident Programs B2/11/29 COUNSIL, W G Connecticut Yankee Atomic Power Co 2pp 16408 321 24X Fiche 50-213, B2/11/29, B212140074

--B212140084 IE Insp Rept 50-213/B2-19 on B20927-1107 No noncompliance noted Major areas inspected: review of periodic & special repts, TMI action plan items, by-product matl license, offsite emergency response & receipt of new fuel
HEBELOWSKI, T, BRIDGES, L, ELSSASSER, T C Division of Project & Resident Programs B2/11/17 11pp 16408 323 24X Fiche 50-213, B2/11/29, B212140074

B212020123 Notification of B21201 meeting w/util in Bethesda, MD to discuss licensee request for exemption from certain requirements of Section III G of App R re safe shutdown capability in event of fire
ERICKSON, P B Operating Reactors Branch 5 B2/11/30 CRUTCHFIELD, D Operating Reactors Branch 5 3pp 16272 040 24X Fiche 50-213, B2/11/30, B212020123

B212090114 Responds to Generic Ltr B2-25 re BNL request for assistance in field testing new measurement equipment & inventory techniques developed to aid in strengthening IAEA safeguards Addl info available should be sent expeditiously
COUNSIL, W G Connecticut Yankee Atomic Power Co COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) B2/11/30 EISENHUT, D G Division of Licensing 1p 16357 272 24X Fiche 50-000, B2/11/30, B212090114

B212140210 Summary of B21201 meeting w/util & Debevoise & Lieberman in Bethesda, MD re fire protection, App R safe shutdown requirements & exemption request
ERICKSON, P B Operating Reactors Branch 5 B2/12/09 Operating Reactors Branch 5 44pp 16406 263 24X Fiche 50-213, B2/12/09, B212140210

B212280119 Forwards info supporting 10CFR50 App R review, including safe shutdown fire zone analysis, PRA for proposed alternate shutdown sys & clarification of technical issues, intended for presentation during B21201 meeting w/NRC
COUNSIL, W G, FEE, W F Connecticut Yankee Atomic Power Co B2/12/15 EISENHUT, D G Division of Licensing 50pp 16564 074 24X Fiche 50-213, B2/12/15, B212280119

B212210303 Provides addl info to better prepare shift crews operating facility for questions asked by NRC duty officer during telephone notifications Encl event notification form should be disseminated
STAROSTECKI, R Division of Project & Resident Programs B2/12/16 COUNSIL, W G Connecticut Yankee Atomic Power Co 6pp 16497 101 24X Fiche 50-213, B2/12/16, B212210303

P Operating license stage documents & correspondence

B212140001 Addl response to FOIA request for five categories of documents re SEP Forwards documents listed in App A No documents located subj to Item 3 of request Review of remaining documents continuing Documents available in PDR
FELTON, J H Division of Rules and Records B2/11/03 GALL, J Lham, Lincoln & Beale 2pp 16433 354 24X Fiche 50-000, B2/11/03, B212140001

--B212160327 Forwards Structural Mechanics Associates B21208 comments re SEP Topic III-6 on seismic design considerations, for concurrence Marked-up summary document also encl
NELSON, T A Lawrence Livermore Laboratory B1/12/11 CHEN, P Y Systematic Evaluation Program Branch 8pp 16435 085 24X Fiche 50-000, B2/11/03, B212140001

--B203310670 Forwards SEP seismic completion plan to perform review parallel w/license efforts to complete SEP Topic III-6, seismic design considerations, for Group II plants
HERMANN, R Systematic Evaluation Program Branch B2/03/08 RUSSELL, W T Systematic Evaluation Program Branch 5pp 16434 276 24X Fiche 50-000, B2/11/03, B212140001

DOCKETED ITEMS

--8212140149 Discusses SEP site-specific spectra project Project in final stages Comments from Peer Review Group & all other comments should be received by 7/1/80 Listing of references re site-specific spectra (SEP Topic II-4) encl
LEVIN, H A Systematic Evaluation Program Branch 7/1/13
EISENHUT, D O Division of Operating Reactors 4pp 16436 300
24X Fiche 50-000, 82/11/03, 8212140001

8212070289 Summarizes analysis of flood level in response to SEP Topic III-3 A, "Effects of High Water Level on Structures"
Containment, primary auxiliary bldg, diesel generator bldg & safety-related tanks protected against flood at 30 ft
COUNSIL, W O, CAGNETTA, J P Connecticut Yankee Atomic Power Co
82/11/24 CRUTCHFIELD, D Operating Reactors Branch 5 2pp
16339 015 24X Fiche 50-213, 82/11/24, 8212070289

8212060157 Responds to Generic Ltr 82-22 re steam generators Haddam Neck steam generator performance excellent Max of 21 tubes replaced since 1979 Hillstone Unit 2 replaced max of 429
Radiation protection program established
COUNSIL, W O Connecticut Yankee Atomic Power Co COUNSIL, W O
Northeast Utilities 82/11/29 EISENHUT, D O Division of Licensing 3pp 16313 117 24X Fiche 50-000, 82/11/29, 8212060157

8212070102 Forwards final SER on SEP Topic VI-10 A, "Testing of Reactor Trip Sys & ESFs, Including Response Time Testing" Changes to Tech Specs for surveillance testing & hardware provisions recommended
CRUTCHFIELD, D Operating Reactors Branch 5, 82/12/03 COUNSIL, W O
Connecticut Yankee Atomic Power Co 14pp 16327 277 24X
Fiche 50-213, 82/12/03, 8212070102

8208190263 Generic Ltr 82-32 to all PWR licensees re potential steam generator-related generic requirements Forwards Science Applications, Inc draft rept re suby requirements Comments requested within 30 days of ltr Svc list encl
EISENHUT, D O Division of Licensing 82/12/09 Consolidated Edison Co of New York, Inc 29pp 16629 247 24X
Fiche 50-000, 82/12/09, 8208190263

8212140103 Generic Ltr 82-28 to all licensees of operating Westinghouse & C-E PWRs (except Arkansas Nuclear One, Unit 2 & San Onofre 2 & 3) re inadequate core cooling instrumentation sys Svc list encl
EISENHUT, D O Division of Licensing 82/12/10 Yankee Atomic Electric Co 27pp 16590 035 24X Fiche 50-000, 82/12/10, 8212140103

8212220377 Forwards evaluation of SEP Topic VI-4, "Containment Isolation Sys" Outstanding items include use of simple check valves outside containment as automatic isolation valve & lack of redundant sys for certain open sys
CRUTCHFIELD, D Operating Reactors Branch 5 82/12/13 COUNSIL, W O
Connecticut Yankee Atomic Power Co 33pp 16517 194 24X
Fiche 50-213, 82/12/13, 8212220377

8212230069 Forwards SER & proprietary & nonproprietary technical evaluation repts of environ qualification of safety-related equipment Four major qualification deficiencies listed
Proprietary rept withheld (ref 10CFR2 790)
CRUTCHFIELD, D Operating Reactors Branch 5, 82/12/13 COUNSIL, W O
Connecticut Yankee Atomic Power Co 3pp 16506 012 24X
Fiche 50-213, 82/12/13, 8212230069

--8212230096 SER of environ qualification of safety-related electric equipment Four major qualification deficiencies listed
* Office of Nuclear Reactor Regulation, Director 82/12/13 8pp
16506 015 24X Fiche 50-213, 82/12/13, 8212230096

--8212230110 Nonproprietary "Review of Licensee Resolution of Outstanding Issues From NRC Equipment Environ Qualification SERs (F-11, B-60), Haddam Neck Plant," technical evaluation rept
CRANE, C J Franklin Institute/Franklin Research Center
YER-C5257-460 82/06/07, LE, N B, BHEMANSKI, P NRC - No Detailed Affiliation Given 36pp 16506 021 24X Fiche 50-213, 82/12/13, 8212230089

8212210059 Application to amend License DPR-16, changing Tech Specs 3 17 & 3 18 to reduce peak linear heat generation rate limit & change power vs offset envelopes to reflect lowered linear heat generation rate
COUNSIL, W O Connecticut Yankee Atomic Power Co 82/12/14
CRUTCHFIELD, D Operating Reactors Branch 5 3pp 16492 253 24X
Fiche 50-213, 82/12/14, 8212210059

--8212210063 Proposed changes to Tech Specs 3 17 & 3 18, reducing peak linear heat generation rate limit & changing power vs offset envelopes to reflect lowered linear heat generation rate
* Connecticut Yankee Atomic Power Co 82/12/14 7pp 16492 256
24X Fiche 50-213, 82/12/14, 8212210059

8212210121 Submits results of discharge piping analyses in response to NUREG-0737, Item II D 1, "Performance Testing of PWR Relief & Safety Valves"
COUNSIL, W O Connecticut Yankee Atomic Power Co COUNSIL, W O
Northeast Nuclear Energy Co (subs of Northeast Utilities)
COUNSIL, W O Northeast Utilities 82/12/15 EISENHUT, D O
Division of Licensing 4pp 16485 084 24X Fiche 50-000, 82/12/15, 8212210121

8212210127 Forwards SER & technical evaluation rept advising of resolution of NUREG-0737, Items I A 2 1, "Upgraded Reactor Operator & Senior Reactor Operator Training" & II D 4, "Training for Mitigating Core Damage"
CRUTCHFIELD, D Operating Reactors Branch 5 82/12/15 COUNSIL, W O
Connecticut Yankee Atomic Power Co 5pp 16484 179 24X
Fiche 50-213, 82/12/15, 8212210127

--8209030343 "Improvements in Training & Requalification Programs as Required By TMI Action Items I A 2 1 & II B 4," technical evaluation rept
* Science Applications, Inc NRC-03-82-096 SAI-186-029-05
82/09/01 NRC - No Detailed Affiliation Given 18pp
16484 184 24X Fiche 50-213, 82/12/15, 8212210127

8212230257 Provides addl info re main steam line break w/continued feedwater addition in response to PRC 821027 ltr Increased flow rates will not adversely affect containment response
COUNSIL, W O, CAGNETTA, J P Connecticut Yankee Atomic Power Co
82/12/16 CRUTCHFIELD, D Operating Reactors Branch 5 5pp
16507 353 24X Fiche 50-213, 82/12/16, 8212230257

8212220457 Informs that draft SER for SEP Topics II-3 A, II-3 B, II-3 C & II-3 D considered final Quabbin Reservoir Dam issues will be addressed in SEP Topic II-4 E, "Dam Integrity"
CRUTCHFIELD, D Operating Reactors Branch 5 82/12/20 COUNSIL, W O
Connecticut Yankee Atomic Power Co 3pp 16503 220 24X
Fiche 50-213, 82/12/20, 8212220457

0 Inspection reports, IE Bulletins & correspondence

8208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants" Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240

8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters" Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards
82/11/05 Consolidated Edison Co of New York, Inc 110pp
16372 142 24X Fiche 50-000, 82/11/05, 8208190245

8212030165 Forwards IE Insp Rept 50-213/82-18 on 820929-1001 No noncompliance noted
MARTIN, T T Division of Engineering & Technical Programs 82/11/17
COUNSIL, W O Connecticut Yankee Atomic Power Co 2pp 16306 105
24X Fiche 50-213, 82/11/17, 8212030165

--8212030175 IE Insp Rept 50-213/82-18 on 820929-1001 No noncompliance noted Major areas inspected security plan & implementing procedures, security organization, records, repts & training & qualification & contingency plans
MCKEOWN, L H, GODY, A T Region 1, Office of Director 82/11/10
5pp 16306 107 24X Fiche 50-213, 82/11/17, 8212030165

8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements" Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18
Consolidated Edison Co of New York, Inc 109pp 16411 199 24X
Fiche 50-000, 82/11/18, 8208190251

8212060376 Informs that routine containment entries rescheduled from weekly to monthly or as required by unusual conditions within containment per IE Bulletin 80-24 Fewer entries result in reduced personnel radiation exposure
COUNSIL, W O Connecticut Yankee Atomic Power Co 82/11/24
HAYNES, R C Region 1, Office of Director 2pp 16311 079 24X
Fiche 50-213, 82/11/24, 8212060376

8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Radiolocks" Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000, 82/11/26, 8208190256

8212140074 Forwards IE Insp Rept 50-213/82-19 on 820927-1107 No noncompliance noted
STAROSTECKI, R Division of Project & Resident Programs 82/11/29
COUNSIL, W O Connecticut Yankee Atomic Power Co 2pp 16408 321
24X Fiche 50-213, 82/11/29, 8212140074

-8212140084 IE Insp Rept 50-213/82-19 on 820927-1107 No noncompliance noted Major areas inspected review of periodic & special repts, TMI action plan items, by-product matl license, offsite emergency response & receipt of new fuel
REBEL, LWSKI, T., BRIGGS, L., ELSASSER, T C Division of Project & Resident Programs 82/11/17 11pp 16408 323 24X
Fiche 50-213, 82/11/29, 8212140074

8208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards
82/11/30 Consolidated Edison Co of New York, Inc 356pp
16387 028 24X Fiche 50-000, 82/11/30, 8208190257

8208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc
113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259

8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X
Fiche 50-000, 82/12/03, 8208190261

8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc
127pp 16628 191 24X Fiche 50-000, 82/12/16, 8208190267

8212220361 Forwards list of topic areas for discussion at upcoming meeting on drug & alcohol abuse programs instituted per IE Info Notice 82-05 One util representative should be available to participate in entire meeting
STAROSTECKI, R Division of Project & Resident Programs 82/12/16
COUNSIL, W O Connecticut Yankee Atomic Power Co 3pp 16517 164 24X Fiche 50-213, 82/12/16, 8212220361

8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27 " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X
Fiche 50-000, 82/12/20, 8208190268

8212290239 Advises that relief from ASME Code Section XI re volumetric & visual exams of welds & internal surfaces of reactor coolant pumps granted for remainder of insp interval, through 871231 or until pump disassembled FR notice encl
CRUTCHFIELD, D Operating Reactors Branch 5 82/12/21 COUNSIL, W O Connecticut Yankee Atomic Power Co 5pp 16582 103 24X
Fiche 50-213, 82/12/21, 8212290239

--8212290242 Notice of granting of relief from certain requirements of ASME Code Section XI in service insp requirements
CRUTCHFIELD, D Operating Reactors Branch 5 82/12/21 2pp
16582 109 24X Fiche 50-213, 82/12/21, 8212290239

B Reportable occurrences, LERs & related correspondence

8212080449 Forwards LER 82-010/03L-0
GRAVES, R H Connecticut Yankee Atomic Power Co 82/12/02
HAYNES, R C Region 1, Office of Director 1p 16352 114 24X
Fiche 50-213, 82/12/02, 8212080449

--8212080459 LER 82-010/03L-0 on 821113, during preventive maint, operating linkage for containment air recirculation fan bypass damper failed Caused by mechanical failure of connecting linkage Linkage replaced
TEST, R 2 Connecticut Yankee Atomic Power Co 82/12/03 Region 1, Office of Director 1p 16352 115 24X Fiche 50-213, 82/12/02, 8212080449

DOCKET 50-219 OYSTER CREEK NUCLEAR POWER PLANT

B NRC Draft/Final Environmental Statements, supplis & correspondence

8212280218 Requests extension until 830315 to file response to NRC 821105 request for review of existing FER for significant changes to facility or environs
FIEDLER, P B General Public Utilities - GPU Service Corp 82/12/21
CRUTCHFIELD, D Operating Reactors Branch 5 2pp 16562 124 24X
Fiche 50-219, 82/12/21, 8212280218

F Security, medical, emergency & fire protection plans

8212100073 Forwards IE Safeguards Insp Rept 50-219/82-27 on 821020-22 No noncompliance noted
MARTIN, T T Division of Engineering & Technical Programs 82/11/24
FIEDLER, P B General Public Utilities - GPU Service Corp 2pp
16379 090 24X Fiche 50-219, 82/11/24, 8212100073

--8212100081 IE Safeguards Insp Rept 50-219/82-27 on 821020-22 No noncompliance noted Major areas inspected measurement & controls, shipping & receiving, storage & internal control, physical inventory, records & repts & mgt & matl control sys
DELLA RATTIA, A., GODY, A T Region 1, Office of Director 82/11/18
6pp 16379 092 24X Fiche 50-219, 82/11/24, 8212100073

8212210084 Forwards IE Insp Rept 50-219/82-25 on 821007-1111 (date differences throughout package noted) & notice of violation
STAROSTECKI, R Division of Project & Resident Programs 82/11/29
FIEDLER, P B General Public Utilities - GPU Service Corp 2pp
16493 020 24X Fiche 50-219, 82/11/29, 8212210084

--8212210089 IE Insp Rept 50-219/82-25 on 821007-1109 Noncompliance noted on 821028, visitor left protected area unescorted
Page 9 containing safeguards info deleted (ref 10CFR73 21)
COWILL, C., THOMAS, J., LAZARUS, W Division of Project & Resident Programs 82/11/19 13pp 16493 023 24X Fiche 50-219, 82/11/29, 8212210084

8212130306 Responds to NRC request for addl info re nearsite & farsite emergency operating facilities Util responded to Generic Ltr 81-11 on 820424, 810911 & 820401
FIEDLER, P B General Public Utilities - GPU Service Corp 82/12/07
CRUTCHFIELD, D Operating Reactors Branch 5 3pp 16389 321 24X
Fiche 50-219, 82/12/07, 8212130306

8212170050 Advises that Revision 13 to physical security plan, dtd 821019, acceptable
CRUTCHFIELD, D Operating Reactors Branch 5 82/12/09 FIEDLER, P B General Public Utilities - GPU Service Corp 1p 16480 363 24X
Fiche 50-219, 82/12/09, 8212170050

8212210550 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 82/12/13 Document Management Branch 1p 16542 318 24X Fiche 50-219, 82/12/13, 8212210550

--8212210555 Forwards public version of revised emergency plan implementing procedures, including Procedures EPIP-10 re emergency radiological surveys onsite & EPIP-25 re nearsite emergency operations facility (NEOF) Revised index encl
FIEDLER, P B General Public Utilities - GPU Service Corp 82/11/29 HAYNES, R C Region 1, Office of Director 4pp
16542 319 24X Fiche 50-219, 82/12/13, 8212210550

--8212210557 Public version of revised emergency plan implementing procedures, including Procedures EPIP-10 re emergency radiological surveys onsite & EPIP-25 re nearsite emergency operations facility (NEOF)
General Public Utilities - GPU Service Corp 82/09/23 39pp
16542 323 24X Fiche 50-219, 82/12/13, 8212210550

8212210453 Ack receipt of 820930 & 1129 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 50-219/82-18 Response to Item B of NRC 820830 ltr reviewed & violation rescinded Response withheld (ref 10CFR73 21)
STAROSTECKI, R Division of Project & Resident Programs 82/12/14
FIEDLER, P B General Public Utilities - GPU Service Corp 2pp
16489 202 24X Fiche 50-219, 82/12/14, 8212210453

--8212210460 Forwards revised response to NRC 820830 ltr re violations noted in IE Insp Rept 50-219/82-18 Safeguards markings revised to facilitate NRC handling
LAOGART, M W General Public Utilities - GPU Service Corp 82/11/29 STAROSTECKI, R Division of Project & Resident Programs
1p 16489 204 24X Fiche 50-219, 82/12/14, 8212210453

--8212210468 Forwards response to NRC 820830 ltr re violations noted in IE Insp Rept 50-219/82-18 Corrective actions instrument rack encls secured Equipment control procedure reviewed Safeguards info withheld (ref 10CFR2 790 & 10CFR73 21)
FIEDLER, P B General Public Utilities - GPU Service Corp 82/09/30 STAROSTECKI, R Division of Project & Resident Programs
4pp 16489 205 24X Fiche 50-219, 82/12/14, 8212210453

8212290477 Forwards IE Safeguards Insp Rept 50-219/82-26 on 821012-15 No noncompliance noted
MARTIN, T T Division of Engineering & Technical Programs 82/12/15
FIEDLER, P B General Public Utilities - GPU Service Corp 2pp
16583 258 24X Fiche 50-219, 82/12/15, 8212290477

--8212290477 IE Safeguards Insp Rept 50-219/82-26 on 821012-15 No noncompliance noted Major areas inspected security plan, implementing procedures, organization & program audit, records & repts, testing & maint & locks, keys & combinations
MADSEN, W. SMITH, G. GODDY, A. T. Division of Engineering & Technical Programs 82/11/24 3pp 16383 260 24X Fiche 50-219, 82/12/15, 8212290477

8212230299 Notifies that insufficient info prevents determination of tolling schedule requirements per 10CFR50 48(c) re 820630 request for exemption from 10CFR50 App R requirements
Schedules computed from 820630
EISENHUT, D. G. Division of Licensing 82/12/17 FIEDLER, P. B. General Public Utilities - GPU Service Corp 3pp 16508 283 24X Fiche 50-219, 82/12/17, 8212230299

8212290408 Responds to 821124 ltr re delay in submitting responses to Apps B & C of IE Emergency Preparedness Appraisal Rept 50-219/82-01 Submittal date of 821231 acceptable
MARTIN, T. T. Division of Engineering & Technical Programs 82/12/27 FIEDLER, P. B. General Public Utilities - GPU Service Corp 1p 16586 350 24X Fiche 50-219, 82/12/27, 8212290408

--8212290410 Informs of delay in submitting responses to Apps B & C of IE Emergency Preparedness Appraisal Rept 50-219/82-01 until 821231, due to elevated level of mgt attention needed to review revised emergency plan
FIEDLER, P. B. General Public Utilities - GPU Service Corp 82/11/24 SMITH, G. H. Division of Emergency Preparedness & Operational Support 1p 16586 351 24X Fiche 50-219, 82/12/27, 8212290410

G Adjudicatory correspondence

8212300174 Forwards complaint filed in connection w/traumatic back injury suffered by J. Bruschi at facility Complaint alleges injury resulted from unfit & unsafe working place & exposure to radioactive mists Investigation initiated
HARWARD, J. E. American Nuclear Insurers 82/12/27 SALTZMAN, J. Assistant Director for State & License Relations 10pp 16398 096 24X Fiche 50-219, 82/12/27, 8212300174

J Insurance & indemnity information

8212140362 Forwards Endorsement 65 to MAELU Policy MF-44 & Endorsement B4 to NELA Policy NF-164
MOREAU, W. N. General Public Utilities - GPU Service Corp 82/12/10 SALTZMAN, J. Antitrust & Economic Analysis Branch (Utility Finance) 3pp 16401 151 24X Fiche 50-219, 82/12/10, 8212140362

O Advisory Committee on Reactor Safeguards reports & correspondence

8212100074 Responds to ACRS 821109 comments on leakage detection in SEP integrated assessment rept Visual insp of emergency condenser steam line piping acceptable unless not supported by limiting leakage rate Draft NUREG-0822 will be revised
DENTON, H. R. Office of Nuclear Reactor Regulation, Director 82/12/02 SHEWMON, P. S. ACRS - Advisory Committee on Reactor Safeguards 7pp 16397 026 24X Fiche 50-219, 82/12/02, 8212100074

P Operating license stage documents & correspondence

8212060063 Informs that draft SERs re SEP Hydrology Topics II-3 A, II-3 B, II-3 C & III-3 C, transmitted by 820624 & 30 ltrs, considered final Evaluation will be basic input to integrated assessment
CRUTCHFIELD, D. Operating Reactors Branch 5 82/08/27 FIEDLER, P. B. General Public Utilities - GPU Service Corp 2pp 16314 020 24X Fiche 50-219, 82/08/27, 8212060063

8212140001 Addl response to FOIA request for Psva categories of documents re SEP Forwards documents listed in App A No documents located subj to item 3 of request Review of remaining documents continuing Documents available in PDR
FELTON, J. M. Division of Rules and Records 82/11/03 GALLO, J. Isham, Lincoln & Beale 2pp 16433 354, 24X Fiche 50-000, 82/11/03, 8212140001

--7908140784 Forwards "Tentative Plan for Seismic Reanalysis of Critical Structural Sys of Oyster Creek Unit 1"
MURRAY, R. C. Lawrence Livermore Laboratory 79/08/02 LEVIN, H. A. Systematic Evaluation Program Branch (Pre 791030) 1p 16435 093 24X Fiche 50-000, 82/11/03, 8212140001

--7908140789 "Tentative Plan for Seismic Reanalysis of Critical Structural Sys of Oyster Creek Unit 1"
H. A. S. M. EOXO, Inc 79/08/02 17pp 16435 094 24X Fiche 50-000, 82/11/03, 8212140001

--8002200995 Notifies that review & performance of audit calculations to be continued per contract & preliminary review work to be completed at LaCrosse Code used for reanalysis of piping sys requires benchmarking per code verification program
SHAO, L. C. Assistant Director for Engineering Programs 79/10/30 EISENHUT, D. G. Division of Operating Reactors 1p 16435 111 24X Fiche 50-000, 82/11/03, 8212140001

--8005280555 Forwards rept, "Role of Radiation Damping in Impedance Function Approach to Soil-Structure Interaction Analysis," prepared by NCT Engineering, Inc
MURRAY, R. C. Lawrence Livermore Laboratory 80/05/19 ALLISON, D. Systematic Evaluation Program Branch 1p 16435 112 24X Fiche 50-000, 82/11/03, 8212140001

--8005280561 "Role of Radiation Damping in Impedance Function Approach to Soil-Structure Interaction Analysis" Prepared for LLL
TSAL, T. NCT Engineering, Inc FIN A-0233 80/05/31 NRC - No Detailed Affiliation Given 30pp 16435 113 24X Fiche 50-000, 82/11/03, 8212140001

--8105110512 Forwards two consultant repts & list of open items re SEP Topics III-6 re seismic design consideration & III-11 re component integrity W/o consultant repts
CRUTCHFIELD, D. Operating Reactors Branch 5 81/03/20 FINFROCK, I. R. Public Service Electric & Gas Co. of New Jersey 3pp 16434 261 24X Fiche 50-000, 82/11/03, 8212140001

8211230056 Generic Ltr 82-27 to all BWR licensees of operating reactors except LACBWR, Big Rock Point, Dresden 1, Humboldt Bay, applicants for OL & holders of CP re transmittal of NUREG-0763 & NUREG-0783 Svc list encl W/o stated encl
EISENHUT, D. G. Division of Licensing 82/11/15 General Public Utilities - GPU Service Corp 22pp 16387 004 24X Fiche 50-000, 82/11/15, 8211230056

8212060247 Forwards schedules & resolutions for SEP Topics II-5 B, V-5, VII-3 B, V-12 A, XV-16, XV-18, II-4 A, VI-7 A, VI-10 A, II-3 B, II-3 C, II-3 C, III-1, III-2, III-3 A, III-3 C, II-4 A, II-4 B, II-4 D, III-5 A, III-5 B & III-6
CLARK, P. R. General Public Utilities - GPU Service Corp 82/11/29 CRUTCHFIELD, D. Operating Reactors Branch 5 17pp 16313 158 24X Fiche 50-219, 82/11/29, 8212060247

8212070097 Forwards SER & proprietary & nonproprietary technical evaluation repts re environ qualification of safety-related electric equipment Justification for continued operation must be reaffirmed & addl info submitted
CRUTCHFIELD, D. Operating Reactors Branch 5 82/11/30 FIEDLER, P. B. General Public Utilities - GPU Service Corp 3pp 16328 001 24X Fiche 50-219, 82/11/30, 8212070097

--8207150169 "Review of Licensee Resolution of Outstanding Issues From NRC Equipment Environ Qualification Safety Evaluation Repts," final technical evaluation rept
CRANE, C. J. Franklin Institute/Franklin Research Center NRC-03-79-118 TER-C5257-453 82/07/09 LE, N. B. NRC - No Detailed Affiliation Given 316pp 16328 010 24X Fiche 50-219, 82/11/30, 8212070097

8212080206 Forwards SER re radiological field operations training program Qualification criteria, per 821008 telcon, acceptable
CRUTCHFIELD, D. Operating Reactors Branch 5 82/12/03 FIEDLER, P. B. General Public Utilities - GPU Service Corp 2pp 16354 001 24X Fiche 50-219, 82/12/03, 8212080206

--8212080211 SER supporting proposed Tech Spec Section 6.3.2 re radiological field operations training program
* Office of Nuclear Reactor Regulation, Director 82/12/03 2pp 16354 003 24X Fiche 50-219, 82/12/03, 8212080206

8212210019 Tech Spec Change Request 100 for amend to License DPR-16, changing App A re inservice insp surveillance requirements for snubbers
FIEDLER, P. B. General Public Utilities - GPU Service Corp 82/12/10 * Office of Nuclear Reactor Regulation, Director 5pp 16490 164 24X Fiche 50-219, 82/12/10, 8212210019

--8212210020 Proposed Tech Specs re inservice insp surveillance requirements for snubbers
* General Public Utilities - GPU Service Corp 82/12/10 22pp 16490 169 24X Fiche 50-219, 82/12/10, 8212210019

8212280313 Application to amend License DPR-16, consisting of Tech Spec change limiting oxygen content to 4X Class III exemption fee encl
FIEDLER, P. B. General Public Utilities - GPU Service Corp 82/12/15 * Office of Nuclear Reactor Regulation, Director 7pp 16562 058 24X Fiche 50-219, 82/12/15, 8212280313

Q12230310 Forwards request for addl info re NUREG-0737, Item II D 1, "Safety/Relief Valve Testing." Info should be submitted within 90 days of ltr receipt
CRUTCHFIELD, D. Operating Reactors Branch 5 82/12/17 FIEDLER, P B
General Public Utilities - OPU Service Corp 3pp 16507 316 24X
Fiche 50-219, 82/12/17, 8212230310

Q Inspection Reports, IE Bulletins & correspondence

8208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at B&R Plants." Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240

8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters." Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000, 82/11/05, 8208190245

8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements." Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X Fiche 50-000, 82/11/18, 8208190251

8212030030 Forwards IE Insp Rept 50-219/82-23 on 820914-17 & notice of violation
MARTIN, T T Division of Engineering & Technical Programs 82/11/18 FIEDLER, P B General Public Utilities - OPU Service Corp 2pp 16305 061 24X Fiche 50-219, 82/11/18, 8212030030

--8212030033 Notice of violation from insp on 820914-17
* Division of Engineering & Technical Programs 82/11/18 2pp 16305 063 24X Fiche 50-219, 82/11/18, 8212030030

--8212030037 IE Insp Rept 50-219/82-23 on 820914-17 Noncompliance noted failure to follow air particulate sampling schedule & failure to calibrate thermal monitoring sys
JANO, J C, JACKSON, T J, BORES, R J Division of Engineering & Technical Programs 82/11/10 11pp 16305 065 24X Fiche 50-219, 82/11/18, 8212030030

8212100073 Forwards IE Safeguards Insp Rept 50-219/82-27 on 821020-22 No noncompliance noted
MARTIN, T T Division of Engineering & Technical Programs 82/11/24 FIEDLER, P B General Public Utilities - OPU Service Corp 2pp 16379 090 24X Fiche 50-219, 82/11/24, 8212100073

--8212100081 IE Safeguards Insp Rept 50-219/82-27 on 821020-22 No noncompliance noted Major areas inspected measurement & controls, shipping & receiving, storage & internal control, physical inventory, records & rpts & mgt & matl control sys
DELLA RATTA, A, GDDY, A T Region 1, Office of Director 82/11/18 6pp 16379 092 24X Fiche 50-219, 82/11/24, 8212100073

8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks." Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000, 82/11/26, 8208190256

8212040332 Informs of revision to routine insp interval for visual insp of sparger surfaces & ultrasonic test & dye penetrant exam of feedwater nozzles Future insps will be conducted per schedule outlined in Table 2 of NUREG-0419
FIEDLER, P B General Public Utilities - OPU Service Corp 82/11/29 CRUTCHFIELD, D Operating Reactors Branch 5 2pp 16312 079 24X Fiche 50-219, 82/11/29, 8212040332

8212100084 Forwards IE Insp Rept 50-219/82-25 on 821007-1111 (date differences throughout package noted) & notice of violation
STAROSTECKI, R Division of Project & Resident Programs 82/11/29 FIEDLER, P B General Public Utilities - OPU Service Corp 2pp 16493 020 24X Fiche 50-219, 82/11/29, 8212100084

--8212100087 Notice of violation from insp on 821007-1109
* Division of Project & Resident Programs 82/11/29 1p 16493 022 24X Fiche 50-219, 82/11/29, 8212100084

--8212100089 IE Insp Rept 50-219/82-25 on 821007-1109 Noncompliance noted on 821028, visitor left protected area unescorted
Page 9 containing safeguards info deleted (ref 10CFR73.21)
COWGILL, C, THOMAS, J, LAZARUS, W Division of Project & Resident Programs 82/11/19 13pp 16493 023 24X Fiche 50-219, 82/11/29, 8212100084

8208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl." Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 354pp 16387 028 24X Fiche 50-000, 82/11/30, 8208190257

8212070014 Discusses IE insp on 811103-820317 & forwards notice of violation & notice of proposed imposition of civil penalty
HAYNES, R C Region 1, Office of Director 82/11/30 FIEDLER, P B General Public Utilities - OPU Service Corp 5pp 16356 281 24X Fiche 50-219, 82/11/30, 8212070014

--8212070021 Notice of violation & notice of proposed imposition of civil penalty in amount of \$40,000 Noncompliance noted surveillance testing of A isolation condenser motor driven valve V-14-30 inadequate to demonstrate operability
HAYNES, R C Region 1, Office of Director 82/11/30 4pp 16356 286 24X Fiche 50-219, 82/11/30, 8212070014

8212080356 Responds to Questions 1 & 4 of IE Bulletin 82-03, Revision 1 re ultrasonic test methods detecting intergranular stress corrosion cracking in thick walled piping Response subj to change Related info encl
FIEDLER, P B General Public Utilities - OPU Service Corp 82/12/01 HAYNES, R C Region 1, Office of Director 24pp 16352 013 24X Fiche 50-219, 82/12/01, 8212080356

8208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies." Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259

8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets." Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X Fiche 50-000, 82/12/03, 8208190261

8212080347 Ack receipt of 821025 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-219/82-20
STAROSTECKI, R Division of Project & Resident Programs 82/12/03 FIEDLER, P B General Public Utilities - OPU Service Corp 1p 16353 325 24X Fiche 50-219, 82/12/03, 8212080347

--8212080354 Responds to NRC 820922 ltr re violations noted in IE Insp Rept 50-219/82-20 Corrective actions Diesel Generator 1 lube oil heater pump control switch returned to on position & revision to general drywell clearance issued
FIEDLER, P B General Public Utilities - OPU Service Corp 82/10/25 STAROSTECKI, R Division of Project & Resident Programs 3pp 16353 326 24X Fiche 50-219, 82/12/03, 8212080347

8212220466 Forwards IE Insp Rept 50-219/82-22 on 820908-1006 & notice of violation
STAROSTECKI, R Division of Project & Resident Programs 82/12/07 FIEDLER, P B General Public Utilities - OPU Service Corp 2pp 16504 021 24X Fiche 50-219, 82/12/07, 8212220466

--8212220468 Notice of violation from insp on 820908-1006
* Division of Project & Resident Programs 82/12/07 1p 16504 023 24X Fiche 50-219, 82/12/07, 8212220466

--8212220473 IE Insp Rept 50-219/82-22 on 820908-1006 Noncompliance noted failure to maintain fully operable isolation trip sys for isolation condensers during maint on isolation valves
COWGILL, C, THOMAS, J, TRIPP, L E Division of Project & Resident Programs 82/10/22 11pp 16504 024 24X Fiche 50-219, 82/12/07, 8212220466

821210019 Tech Spec Change Request 100 for amend to License DPR-16, changing App A re inservice insp surveillance requirements for snubbers
FIEDLER, P B General Public Utilities - OPU Service Corp, 82/12/10 Office of Nuclear Reactor Regulation, Director 3pp 16490 164 24X Fiche 50-219, 82/12/10, 821210019

--821210020 Proposed Tech Specs re inservice insp surveillance requirements for snubbers
* General Public Utilities - OPU Service Corp 82/12/10 22pp 16490 169 24X Fiche 50-219, 82/12/10, 821210019

821210453 Ack receipt of 820930 & 1129 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 50-219/82-18 Response to Item B of NRC 820830 ltr reviewed & violation rescinded Response withheld (ref 10CFR73.21)
STAROSTECKI, R Division of Project & Resident Programs, 82/12/14 FIEDLER, P B General Public Utilities - OPU Service Corp 2pp 16489 202 24X Fiche 50-219, 82/12/14, 821210453

DOCKETED ITEMS

--B212210460 Forwards revised response to NRC B20830 ltr re violations noted in IE Insp Rept 50-219/82-18 Safeguards markings revised to facilitate NRC handling
LAGGART, M W General Public Utilities - GPU Service Corp
B2/11/29 STAROSTECKI, R Division of Project & Resident Programs
lp 16489 204 24X Fiche 50-219, 82/12/14, B212210453

--B212210468 Forwards response to NRC B20830 ltr re violations noted in IE Insp Rept 50-219/82-18 Corrective actions instrument rack encls secured Equipment control procedure reviewed Safeguards info withheld (ref 10CFR2 790 & 10CFR73 21)
FIEDLER, P B General Public Utilities - GPU Service Corp
B2/09/30 STAROSTECKI, R Division of Project & Resident Programs
4pp 16489 205 24X Fiche 50-219, 82/12/14, B212210453

B212290477 Forwards IE Safeguards Insp Rept 50-219/82-26 on B21012-15 No noncompliance noted
MARTIN, T T Division of Engineering & Technical Programs B2/12/15
FIEDLER, P B General Public Utilities - GPU Service Corp 2pp
16583 258 24X Fiche 50-219, 82/12/15, B212290477

--B212290479 IE Safeguards Insp Rept 50-219/82-26 on B21012-15 No noncompliance noted Major areas inspected security plan, implementing procedures, organization & program audit, records & repts, testing & maint & locks, keys & combinations
MADDEN, W, SMITH, O, GODY, A T Division of Engineering & Technical Programs B2/11/24 3pp 16583 260 24X Fiche 50-219, 82/12/15, B212290477

B208190267 IE Info Notice B2-49, "Correction for Sample Conditions for Air & Gas Monitoring" Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement B2/12/16 Consolidated Edison Co of New York, Inc
127pp 16628 191 24X Fiche 50-000, 82/12/16, B208190267

B208190268 IE Info Notice B2-50, "Mod of Solid State AC Undervoltage Relays Type IIE-27" Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance B2/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X Fiche 50-000, 82/12/20, B208190268

B212290408 Responds to B21124 ltr re delay in submitting responses to Apps B & C of IE Emergency Preparedness Appraisal Rept 50-219/82-01 Submittal date of B21231 acceptable
MARTIN, T T Division of Engineering & Technical Programs B2/12/27
FIEDLER, P B General Public Utilities - GPU Service Corp lp 16586 350 24X Fiche 50-219, 82/12/27, B212290408

--B212290410 Informs of delay in submitting responses to Apps B & C of IE Emergency Preparedness Appraisal Rept 50-219/82-01 until B21231, due to elevated level of mgt attention needed to review revised emergency plan
FIEDLER, P B General Public Utilities - GPU Service Corp
B2/11/24 SMITH, O H Division of Emergency Preparedness & Operational Support lp 16586 391 24X Fiche 50-219, 82/12/27, B212290408

R Periodic operating reports & related correspondence

B212290127 Forwards monthly operating rept for Oct 1982
FIEDLER, P B General Public Utilities - GPU Service Corp B2/11/11
Office of Resource Management, Director 3pp 16583 210 24X Fiche 50-219, 82/11/11, B212290127

--B212290134 Monthly operating rept for Oct 1982
BARAN, R General Public Utilities - GPU Service Corp B2/11/03
7pp 16583 213 24X Fiche 50-219, 82/11/11, B212290127

B212210040 Forwards thirtieth quarterly rept, "Study of Woodborer Populations re Oyster Creek Generating Station, B20821-1120"
FIEDLER, P B General Public Utilities - GPU Service Corp B2/12/10
HAYNES, R C Region 1, Office of Director lp 16491 008 24X Fiche 50-219, 82/12/10, B212210040

--B212210044 "Study of Woodborer Populations re Oyster Creek Generating Station, B20821-1120," thirtieth quarterly rept
HILLMAN, R E., BELMORE, C J Battelle New England Marine Research Laboratory, B2/11/30 29pp, 16491 009 24X Fiche 50-219, 82/12/10, B212210040

S Reportable occurrences, LERs & related correspondence

B001140342 RO 50/219/80/1-lp on B00105, while performing electromechanical relief valve operability test, electromechanical relief valve D failed to open Cause undetermined Corrective action to be determined.
CARRDL, J T Jersey Central Power & Light Co B0/01/07 3pp
90017.245 24X Fiche 50-219, 80/01/07, B001140342

B212080511 Forwards LER B2-053/03L-0 Detailed event analysis encl
FIEDLER, P B General Public Utilities - GPU Service Corp B2/11/22
HAYNES, R C Region 1, Office of Director 3pp 16352 001 24X Fiche 50-219, 82/11/22, B212080511

--B212080525 LER B2-053/03L-0 on B21022, during brush change on recirculation pump D motor generator set, recirculation pump E tripped Caused by current overload on recirculation pump E Pump E restarted Worn brushes on motor generator replaced
HUTKO, K General Public Utilities - GPU Service Corp B2/11/22
Region 1, Office of Director lp 16352 004 24X Fiche 50-219, 82/11/22, B212080511

B212010158 EN-B2-036 notice of violation & proposed imposition of civil penalties will be issued to util approx B21130 Action based on inadequate surveillance testing to establish valve operability
HARBER, G, AXELRAD, J Director's Office, Office of Inspection and Enforcement B2/11/23 lp 16258 081 24X Fiche 50-219, 82/11/23, B212010158

B212060148 LER B2-056/01P on B21120, during insp of 24-volt dc battery charger A2, breaker found in tripped position Caused by setpoint drift for overvoltage relay on battery charger output breaker Output breaker reset & closed
FIEDLER, P B General Public Utilities - GPU Service Corp B2/11/23
HAYNES, R C Region 1, Office of Director 3pp 16313 149 24X Fiche 50-219, 82/11/23, B212060148

B212080240 Forwards LER B2-051/03L-0 Detailed event analysis encl
FIEDLER, P B General Public Utilities - GPU Service Corp B2/11/23
HAYNES, R C Region 1, Office of Director 4pp 16394 174 24X Fiche 50-219, 82/11/23, B212080240

--B212080263 LER B2-051/03L-0 on B20930, unmonitored release of radioactive liquid to soil around waste surge tank, pump & attached drain piping occurred Caused by severe pitting in bottom 10 ft of sidewall & bottom of tank
HAGAR, C General Public Utilities - GPU Service Corp B2/11/23
Region 1, Office of Director lp 16354 178 24X Fiche 50-219, 82/11/23, B212080240

B212080349 Forwards LER B2-055/01P-0
FIEDLER, P B General Public Utilities - GPU Service Corp B2/11/24
HAYNES, R C Region 1, Office of Director lp 16352 005 24X Fiche 50-219, 82/11/24, B212080349

--B212080359 LER B2-055/01P-0 on B21115, stack gas not monitored continuously due to breaker trip on stack gas sample pump B Cause under investigation Stack gas sample pump A put into svc Condition under review
General Public Utilities - GPU Service Corp B2/11/24
Region 1, Office of Director lp 16352 006 24X Fiche 50-219, 82/11/24, B212080349

B212080398 Forwards LER B2-054/03L-0 Detailed event analysis encl
FIEDLER, P B General Public Utilities - GPU Service Corp B2/11/24
HAYNES, R C Region 1, Office of Director 3pp 16352 280 24X Fiche 50-219, 82/11/24, B212080398

--B212080395 LER B2-054/03L-0 on B21105, after completing TIP trace, ball valve on TIP machine 3 failed to close Caused by moisture buildup around in-shield limit switch operating arm Arm cleaned & switch aligned
MURDOCK, R J General Public Utilities - GPU Service Corp B2/11/24
Region 1, Office of Director lp 16352 283 24X Fiche 50-219, 82/11/24, B212080398

B212140169 Forwards LER B2-052/01T-0 Detailed event analysis encl
FIEDLER, P B General Public Utilities - GPU Service Corp B2/12/02
HAYNES, R C Region 1, Office of Director 3pp 16409 357 24X Fiche 50-219, 82/12/02, B212140169

--B212140177 LER B2-052/01T-0 on B20828, environ release occurred w/ radwaste discharge monitor out of svc w/o performing second sample analysis Caused by personnel error Procedure change initiated requiring signed liquid release permit
HILLMAN, B General Public Utilities - GPU Service Corp B2/12/02
Region 1, Office of Director lp 16409 360 24X Fiche 50-219, 82/12/02, B212140169

B212210372 Forwards LER B2-056/01T-0 Detailed event analysis encl
FIEDLER, P B General Public Utilities - GPU Service Corp B2/12/08
HAYNES, R C Region 1, Office of Director 4pp 16494 305 24X Fiche 50-219, 82/12/08, B212210372

--B212210377 LER B2-056/01T-0 on B21120, output breaker for A2 24-volt dc battery charger tripped Caused by setpoint drift of overvoltage relay Breaker checked & closed & relay setpoint adjusted
CUSTODIO, D B General Public Utilities - GPU Service Corp B2/12/08
Region 1, Office of Director lp 16494 309 24X Fiche 50-219, 82/12/08, B212210372

B21240168 PHO-1-82-079 on B21209, reactor shutdown scheduled to correct increasing unidentified drywell leakage. Possibly caused by reactor recirculation pump seal degradation. Shutdown scheduled for 5 days.
THOMAS, J., LAZARUS, W., KEIMIO, R. Region 1, Office of Director
B2/12/09 1p 16410 210 24X Fiche 50-219, B2/12/09, B21240168

DOCKET 50-220 NINE MILE POINT NUCLEAR STATION, UNIT 1

F Security, medical, emergency & fire protection plans

B212030034 Ack receipt of B20903 ltr transmitting action plan progress rept for Apr-June 1982, in response to Health Physics Appraisal Rept 50-220/80-11
MARTIN, T. T. Division of Engineering & Technical Programs 82/11/08
RHODE, G. K. Niagara Mohawk Power Corp 2pp 16304 113 24X
Fiche 50-220, B2/11/08, B212030034

--B212030050 Submits action plan progress rept for Apr-June 1982, in response to Health Physics Appraisal Rept 50-220/80-11
Improvements made to radiation protection program
MANGAN, C. V. Niagara Mohawk Power Corp 82/09/03 HAYNES, R. C.
Region 1, Office of Director 7pp 16304 115 24X
Fiche 50-220, B2/11/08, B212030034

B212030018 Forwards IE Insp Rept 50-220/82-20 on B21126-29 No noncompliance noted
MARTIN, T. T. Division of Engineering & Technical Programs 82/11/17
RHODE, G. K. Niagara Mohawk Power Corp 2pp 16304 201 24X
Fiche 50-220, B2/11/17, B212030018

--B212030023 IE Insp Rept 50-220/82-20 on B21026-29 No noncompliance noted
Major areas inspected implementation of corrective actions for health physics appraisal, significant appraisal findings & licensee action on previous insp findings
NIMTZ, R. L., SHANBAKY, M. H. Region 1, Office of Director
B2/11/16 13pp 16304 303 24X Fiche 50-220, B2/11/17, B212030018

B212020302 Forwards TMI action item implementation schedule per B20416, 0607, 0820, 0930 & 1001 ltr items will be completed prior to startup from current recirculation piping replacement outage
MANGAN, C. V. Niagara Mohawk Power Corp 82/11/29 EISENHUT, D. G.
Division of Licensing 3pp 16277 336 24X Fiche 50-220, B2/11/29, B212020302

B212060204 Forwards response to B21103 request for addl info re alternate shutdown capability for postulated control room fire
MANGAN, C. V. Niagara Mohawk Power Corp 82/12/03 VASSALLO, D. B.
Operating Reactors Branch 3 36pp 16313 011 24X
Fiche 50-220, B2/12/03, B212060204

B212090106 Responds to request re emergency operations facilities per Generic Ltr B1-10 Info requested previously transmitted
MANGAN, C. V. Niagara Mohawk Power Corp 82/12/06 EISENHUT, D. G.
Division of Licensing 1p 16357 282 24X Fiche 50-220, B2/12/06, B212090106

B212210131 Forwards addl info to prepare shift crews operating nuclear plants for type of questions NRC duty officers may ask via NRC emergency notification sys
STAROSTECKI, R. Division of Project & Resident Programs 82/12/16
RHODE, G. K., SEIBERT, C. R. Niagara Mohawk Power Corp 6pp 16485 188 24X Fiche 50-220, B2/12/16, B212210131

F Operating license stage documents & correspondence

B211230056 Generic Ltr B2-27 to all BWR licensees of operating reactors except LACBWR, Big Rock Point, Dresden 1, Humboldt Bay, applicants for OL & holders of CP re transmittal of NUREG-0763 & NUREG-0783 Svc list encl W/o stated encl
EISENHUT, D. G. Division of Licensing 82/11/15 General Public
Utilities - OPU Service Corp 22pp 16387 004 24X
Fiche 50-000, B2/11/15, B211230056

B212020102 Advises that response to B20621 technical evaluation rept re comparison of effluent Tech Specs & offsite dose calculational manual will be submitted by B30301, not B21130 as stated in B21025 ltr Tech Specs & manual being revised
MANGAN, C. V. Niagara Mohawk Power Corp 82/11/24 VASSALLO, D. B.
Operating Reactors Branch 2 1p 16272 028 24X
Fiche 50-220, B2/11/24, B212020102

B212020302 Forwards TMI action item implementation schedule per B20416, 0607, 0820, 0930 & 1001 ltr items will be completed prior to startup from current recirculation piping replacement outage
MANGAN, C. V. Niagara Mohawk Power Corp 82/11/29 EISENHUT, D. G.
Division of Licensing 3pp 16277-336 24X Fiche 50-220, B2/11/29, B212020302

B212080199 Forwards design info re Class IE protection sys being installed on motor generator sets. Three oversize figures illustrating revised control, instrument on-line power & protective package encl Aperture cards are available in PDR
MANGAN, C. V. Niagara Mohawk Power Corp 82/12/01 VASSALLO, D. B.
Operating Reactors Branch 2 3pp 16354 241 24X
Fiche 50-220, B2/12/01, B212080199

B212130284 Forwards safety evaluation of response to NUREG-0737, Item 11 K 3 25, "Effect of Loss of AC Power on Pump Seals"
Present facility design acceptable. Demonstration of pump seal performance during loss of cooling water unnecessary
VASSALLO, D. B. Operating Reactors Branch 2 82/12/01 DISE, D. P.
Niagara Mohawk Power Corp 7pp 16418 244 24X
Fiche 50-220, B2/12/01, B212130284

B212090154 Forwards results of automatic depressurization sys logic studies & description of proposed mode studies included BWR small break LOCA accident outside primary containment, safe shutdown analysis & Mark I containment load mitigation
MANGAN, C. V. Niagara Mohawk Power Corp 82/12/03 EISENHUT, D. G.
Office of Nuclear Reactor Regulation, Director 4pp 16359 113 24X Fiche 50-220, B2/12/03, B212090154

B212170266 Advises that upon completion of current outage for replacement of safe-ends & recirculation piping, Cycle 7 operation will continue for approx 1 yr prior to refueling
Mod schedule encl
MANGAN, C. V. Niagara Mohawk Power Corp 82/12/15 VASSALLO, D. B.
Operating Reactors Branch 2 2pp 16457 175 24X
Fiche 50-220, B2/12/15, B212170266

B212270265 Responds to NRC B21108 request for info re implementation of NUREG-0313, Revision 1. Info will be provided by B30101
MANGAN, C. V. Niagara Mohawk Power Corp 82/12/20 VASSALLO, D. B.
Operating Reactors Branch 2 1p 16330 326 24X
Fiche 50-220, B2/12/20, B212270265

B212270353 Informs that schedule for providing info re NUREG-0737, Item 11 B 3 on post-accident sampling capability will not be provided until B21228, per B20726 request
MANGAN, C. V. Niagara Mohawk Power Corp 82/12/20 EISENHUT, D. G.
Division of Licensing 1p 16330 015 24X Fiche 50-220, B2/12/20, B212270353

G Inspection reports, IE Bulletins & correspondence

B208190240 IE Bulletin B2-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants" Svc list encl
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co. of New York, Inc
112pp 14462 163 24X Fiche 50-000, B2/10/28, B208190240

B208190245 IE Info Notice B2-42, "Defects Observed in Panasonic Model B01 & Model B02 Thermoluminescent Dosimeters" Svc list encl
COBB, L. T. Division of Fuel Facilities, Materials & Safeguards
B2/11/05 Consolidated Edison Co. of New York, Inc 110pp 16372 142 24X Fiche 50-000, B2/11/05, B208190245

B212030034 Ack receipt of B20903 ltr transmitting action plan progress rept for Apr-June 1982, in response to Health Physics Appraisal Rept 50-220/80-11
MARTIN, T. T. Division of Engineering & Technical Programs 82/11/08
RHODE, G. K. Niagara Mohawk Power Corp 2pp 16304 113 24X
Fiche 50-220, B2/11/08, B212030034

--B212030050 Submits action plan progress rept for Apr-June 1982, in response to Health Physics Appraisal Rept 50-220/80-11
Improvements made to radiation protection program
MANGAN, C. V. Niagara Mohawk Power Corp 82/09/03 HAYNES, R. C.
Region 1, Office of Director 7pp 16304 115 24X
Fiche 50-220, B2/11/08, B212030034

B212030018 Forwards IE Insp Rept 50-220/82-20 on B21126-29 No noncompliance noted
MARTIN, T. T. Division of Engineering & Technical Programs 82/11/17
RHODE, G. K. Niagara Mohawk Power Corp 2pp 16304 201 24X
Fiche 50-220, B2/11/17, B212030018

--B212030023 IE Insp Rept 50-220/82-20 on B21026-29 No noncompliance noted
Major areas inspected implementation of corrective actions for health physics appraisal, significant appraisal findings & licensee action on previous insp findings
NIMTZ, R. L., SHANBAKY, M. H. Region 1, Office of Director
B2/11/16 13pp, 16304 303 24X Fiche 50-220, B2/11/17, B212030018

B208190251 IE Info Notice B2-44, "Clarification of Emergency Plan Evertask Requirements" Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance 82/11/18
Consolidated Edison Co. of New York, Inc 109pp 16411 199 24X
Fiche 50-000, B2/11/18, B208190251

DOCKETED ITEMS

B208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Radiolocks " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000, 82/11/26, B208190256

B208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000, 82/11/30, B208190257

B208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, B208190259

B208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 054 24X Fiche 50-000, 82/12/03, B208190261

B212140397 Act receipt of B21022 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-220/82-14
STAROSTECKI, R Division of Project & Resident Programs 82/12/07 RHODE, O K Niagara Mohawk Power Corp 2pp 16404 018 24X Fiche 50-220, 82/12/07, B212140397

- B212140406 Responds to NRC B20922 ltr re violations noted in IE Insp Rept 50-220/82-14 Corrective actions radiation work permit procedure revised to provide reasonable & enforceable documentation requirement
LEMPGES, T E Niagara Mohawk Power Corp 82/10/22 STAROSTECKI, R Division of Project & Resident Programs 3pp 16404 020 24X Fiche 50-220, 82/12/07, B212140397

B212150207 Act receipt of B21119 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-220/82-17
STAROSTECKI, R Division of Project & Resident Programs 82/12/10 RHODE, O K Niagara Mohawk Power Corp 2pp 16430 264 24X Fiche 50-220, 82/12/10, B212150207

--B212150213 Responds to NRC B21019 ltr re violations noted in IE Insp Rept 50-220/82-17 Corrective actions six out of seven outstanding items re IE circulars closed out & IE Circular 80-22 will be closed by 830101
LEMPGES, T E Niagara Mohawk Power Corp 82/11/19 STAROSTECKI, R Division of Project & Resident Programs 2pp 16430 266 24X Fiche 50-220, 82/12/10, B212150207

B21220508 Requests written statement within 30 days of ltr re use or disposition of Raychem-Flamtril cables Generic qualification tests for cables no longer acceptable
JORDAN, E L Division of Engineering & Quality Assurance 82/12/10 RHODE, O K Niagara Mohawk Power Corp 3pp 16523 097 24X Fiche 50-220, 82/12/10, B21220508

B208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16, B208190267

B21220413 Advises of plans to conduct interviews w/util personnel re drug & alcohol abuse & rehabilitation programs, as result of IE Info Notice 82-05, "Increasing Frequency of Drug-Related Incidents " Topic areas encl
STAROSTECKI, R Division of Project & Resident Programs 82/12/16 RHODE, O K Niagara Mohawk Power Corp 2pp 16503 358 24X Fiche 50-220, 82/12/16, B21220413

B21220476 Act receipt of B21029 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-220/82-01
STAROSTECKI, R Division of Project & Resident Programs 82/12/16 RHODE, O K Niagara Mohawk Power Corp 2pp 16504 018 24X Fiche 50-220, 82/12/16, B21220476

--B21220479 Responds to NRC B20913 ltr re violations noted in IE Insp Rept 50-220/82-01 Corrective actions two phase operating procedure review program will be completed by 840101
LEMPGES, T E Niagara Mohawk Power Corp 82/10/29 STAROSTECKI, R Division of Project & Resident Programs 1p 16504 020 24X Fiche 50-220, 82/12/16, B21220476

B208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27 " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc. 108pp 16628 293 24X Fiche 50-000, 82/12/20, B208190268

R Periodic operating reports & related correspondence

B212140029 Forwards monthly operating rept for Nov 1982
LEMPGES, T E Niagara Mohawk Power Corp 82/12/07 Director's Office, Office of Inspection and Enforcement 1p 16409 286 24X Fiche 50-220, 82/12/07, B212140029

--B212140031 Monthly operating rept for Nov 1982
ROMAN, T W Niagara Mohawk Power Corp 82/12/03 4pp 16409 289 24X Fiche 50-220, 82/12/07, B212140029

5 Reportable occurrences, LERs & related correspondence

B212290416 Forwards LER B2-015/03L-0
LEMPGES, T E Niagara Mohawk Power Corp 82/12/16 HAYNES R C Region I, Office of Director 1p 16585 190 24X Fiche 50-220, 82/12/16, B212290416

--B212290430 LER B2-015/03L-0 on B21117 & 18, deluge valves 101N & 101S, protecting reserve power transformer, intentionally made inoperable to replace pressure switches to upgrade fire protection sys Deluge sys returned to svc after mod
RABY, J, NEILD, R Niagara Mohawk Power Corp 82/12/16 Region I, Office of Director 1p 16585 191 24X Fiche 50-220, 82/12/16, B212290416

DOCKET 50-225 RPI CRITICAL EXPERIMENT

P Operating license stage documents & correspondence

B212140103 Generic Ltr B2-28 to all licensees of operating Westinghouse & C-E PHRs (except Arkansas Nuclear One, Unit 2 & San Onofre 2 & 3) re inadequate core cooling instrumentation sys Svc list encl
LISENHUT, D G Division of Licensing 82/12/10 Yankee Atomic Electric Co 27pp 16690 035 24X Fiche 50-000, 82/12/10, B212140103

6 Inspection reports, IE Bulletins & correspondence

B208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27 " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X Fiche 50-000, 82/12/20, B208190268

DOCKET 50-237 DRESDEN NUCLEAR POWER STATION, UNIT 2

F Security, medical, emergency & fire protection plans

B212030283 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 82/11/30 Document Management Branch 1p 16316 253 24X Fiche 50-010, 82/11/30, B212030283

--B212030284 Forwards public version of revised emergency plan implementing procedures, including Procedure EPIP 100-2 re shift turnover w/technical support ctr & environ teams activated Receipt forms & procedure histories encl
SCOTT, D J Commonwealth Edison Co 82/11/19 DENTON, H R Office of Nuclear Reactor Regulation, Director 7pp 16316 255 24X Fiche 50-010, 82/11/30, B212030283

--B212030287 Public version of revised emergency plan implementing procedures, including Procedure EPIP 100-2 re shift turnover w/technical support ctr & environ teams activated
Commonwealth Edison Co 82/11/17 14pp 16316 262 24X Fiche 50-010, 82/11/30, B212030283

B212090383 Forwards info re emergency operations facilities per B21122 & 1202 requests info previously submitted by telcon Request for written response unnecessary burden on licensee
WELDON, L O Commonwealth Edison Co 82/12/03 EISENHUT, D G Division of Licensing 2pp 16365 051 24X Fiche 50-000, 82/12/03, B212090383

B212130017 Releases public version of Revision 1 to Emergency Plan Implementing Procedure EQ-2, "Pre-Established Onsite & Offsite Monitoring Locations (Maps) "
FELTON, J M Division of Rules and Records 82/12/07 Document Management Branch 1p 16417 062 24X Fiche 50-000, 82/12/07, B212130017

- B212130028 Forwards public version of Revision 1 to Emergency Plan Implementing Procedure EQ-2, "Pre-Established Onsite & Offsite Monitoring Locations (Maps)" Revised table of contents encl
PAJOWSKI, J Commonwealth Edison Co 82/11/01 DENTON, H R NRC -
No Detailed Affiliation Given 2pp 16417 063 24X
Fiche 50-000, 82/12/07, 8212130017
- B212130041 Public version of Revision 1 to Emergency Plan Implementing Procedure EQ-2, "Pre-Established Onsite & Offsite Monitoring Locations (Maps)"
PAJOWSKI, J E, LITERSKI, L A Commonwealth Edison Co 82/11/29
4pp 16417 065 24X Fiche 50-000, 82/12/07, 8212130017
- B212140243 Advises of distribution of revisions to "Generating Station Emergency Plan" Braidwood annex not prepared
TRAMM, T R Commonwealth Edison Co 82/12/07 DENTON, H R Office
of Nuclear Reactor Regulation, Director 2pp 16409 302 24X
Fiche 50-000, 82/12/07, 8212140243
- B212210118 Forwards IE Emergency Preparedness SERs 50-237/82-27 & 50-249/82-29 during Nov 1981 & June 1982, respectively No noncompliance noted
HEND, J A Division of Emergency Preparedness 82/12/10 REED, C
Commonwealth Edison Co 2pp 16485 088 24X Fiche 50-237, 82/12/10, 8212210118
- B212210124 IE Emergency Preparedness SERs 50-237/82-27 & 50-249/82-27 Major areas inspected emergency plan & site-specific annex dated Nov 1981 & June 1982, respectively Planning stds met
PHILLIPS, H P, AXELSON, H L, PAPERIELLO, C J Region 3, Office of Director 82/12/07 29pp 16485 091 24X Fiche 50-237, 82/12/10, 8212210118
- B212220175 Releases public version of revised generating station emergency plan implementing procedures
FELTON, J M Division of Rules and Records 82/12/10 Document
Management Branch 1p 16529 029 24X Fiche 50-000, 82/12/10, 8212220175
- B212220190 Forwards public version of revised generating station emergency plan implementing procedures, including Procedures ED-3 re demand polling of meteorological data & ED-20 re emergency forecast request
PAJOWSKI, J E Commonwealth Edison Co 82/11/15 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 16329 030
24X Fiche 50-000, 82/12/10, 8212220175
- B212220202 Public version of revised generating station emergency plan implementing procedures, including Procedures ED-3 re demand polling of meteorological data & ED-20 re emergency forecast request
LITERSKI, L A, PAJOWSKI, J E Commonwealth Edison Co 82/10/13
48pp 16529 031 24X Fiche 50-000, 82/12/10, 8212220175
- B212230014 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 82/12/15 Document
Management Branch 1p 16545 350 24X Fiche 50-010, 82/12/15, 8212230017
- B212230028 Forwards public version of Revision 1 to Emergency Plan Implementing Procedure EPIP 500-1, "Quarterly Inventory of First Aid Supplies"
SCOTT, D J Commonwealth Edison Co 82/12/03 DENTON, H R Office
of Nuclear Reactor Regulation, Director 3pp 16545 351 24X
Fiche 50-010, 82/12/15, 8212230017
- B212230042 Public version of Revision 1 to Emergency Plan Implementing Procedure EPIP 500-1, "Quarterly Inventory of First Aid Supplies" Revised index encl
Commonwealth Edison Co 82/11/22 6pp 16545 354 24X
Fiche 50-010, 82/12/15, 8212230017
- B212230306 Discusses layout of communications equipment required in control room, onsite technical support ctr & near-site emergency operations facility
KEPPLER, J G Region 3, Office of Director 82/12/16
Commonwealth Edison Co 3pp 16503 351 24X Fiche 50-000, 82/12/16, 8212230306
- B212280214 Forwards IE Safeguards Insp Repts 50-010/82-20, 50-237/82-28 & 50-249/82-29 on 821115-19 Details & notice of violation withheld (ref 10CFR73 21)
MILLER, J R Division of Engineering & Technical Programs 82/12/20
REED, C Commonwealth Edison Co 2pp 16562 120 24X
Fiche 50-010, 82/12/20, 8212280214
- B212280220 IE Safeguards Insp Rept 50-010/82-20, 50-237/82-28 & 50-249/82-29 on 821115-19 Noncompliance noted failure to adequately control security-related key as required by security plan Details withheld (ref 10CFR73 21)
CHRISTOFFER, O Division of Emergency Preparedness & Operational Support 82/12/15 2pp 16562 122 24X Fiche 50-010, 82/12/20, 8212280214
- B212300167 Releases public version of revised generating station emergency plan telephone directory
FELTON, J M Division of Rules and Records 82/12/20 Document
Management Branch 1p 16612 215 24X Fiche 50-000, 82/12/20, 8212300167
- B212300179 Forwards public version of revised generating station emergency plan telephone directory
MOORE, R D Commonwealth Edison Co 82/12/02 DENTON, H R Office
of Nuclear Reactor Regulation, Director 1p 16612 216 24X
Fiche 50-000, 82/12/20, 8212300167
- B212300199 Public version of revised generating station emergency plan telephone directory
GALLE, D P Commonwealth Edison Co 82/11/05 60pp 16612 21/24X Fiche 50-000, 82/12/20, 8212300167
- O Adjudicatory correspondence
- B212070160 Memorandum & order granting licensee 820818 request to dismiss proceeding w/o prejudice Util received authority to increase spent fuel pool storage capacity, making shipment of spent fuel between plants unnecessary
JOHNSON, E B, STODER, G J, MILHOLLIN, G L Atomic Safety and Licensing Board Panel 82/12/03 Commonwealth Edison Co 4pp 16336 320 24X Fiche 50-000, 82/12/03, 8212070160
- H General correspondence
- B212280176 Notices of change in mailing address for NRC licensing mail
WRIGHT, O N Illinois, State of, Dept Nuc Safety (formerly Dept Public Health) 82/12/20 FISENHUT, D G Division of Licensing 1p 16556 135 24X Fiche 50-000, 82/12/20, 8212280176
- D Advisory Committee on Reactor Safeguards reports & correspondence
- B212230277 Forwards, for info, ACRS 821213 ltr to NJ Palladino, consisting of ACRS rept on SEP review of plant
CRUTCHFIELD, D Operating Reactors Branch 5 82/12/16 DELGEORE, L
Commonwealth Edison Co 1p 16508 273 24X Fiche 50-237, 82/12/16, 8212230277
- B212220534 Summarizes ACRS 272nd meeting on 821209-11 re SEP review of facility Review of full term DL will be deferred until actions completed on remaining SEP topics, unresolved safety issues & THF action plan items
SHEWMON, P ACRS - Advisory Committee on Reactor Safeguards 82/12/13 PALLADINO, N J Commissioners 3pp 16508 274 24X
Fiche 50-237, 82/12/16, 8212230277
- P Operating license stage documents & correspondence
- B21170509 Forwards SERs referenced in NUREG-0823, App A, "Integrated Plant Safety Assessment Rept for Dresden Nuclear Power Station, Unit 2," for review
CRUTCHFIELD, D Operating Reactors Branch 5 82/10/27 SHEWMON, P B
ACRS - Advisory Committee on Reactor Safeguards 1p 16380 218
24X Fiche 50-237, 82/10/29, 821170509
- B21160015 Forwards, for review, draft integrated plant safety assessment rept (NUREG-0823) Rept will be on basis in considering issuance of full-term DL to replace provisional DL
MIRALIA, F Assistant Director for Safety Assessment 82/10/29
SHEWMON, P S ACRS - Advisory Committee on Reactor Safeguards 1p 16380 219 24X Fiche 50-237, 82/10/29, 821170509
- B212140001 Addl response to FOIA request for five categories of documents re SEP Forwards documents listed in App A No documents located subj to item 3 of request Review of remaining documents continuing Documents available in PDR
FELTON, J M Division of Rules and Records 82/11/03 GALLE, J
Isam, Lincoln & Beale 2pp 16433 354 24X Fiche 50-000, 82/11/03, 8212140001
- 790604022B Recommends EQ&O perform analyses of recirculation sys. LPC1 suction & seismic test example problem 1 in support of seismic evaluation rept
STEVENSON, J D Woodward-Clyde Consultants, Inc 79/05/25
JABBOUR, K N Division of Operating Reactors 10pp 16435 163
24X Fiche 50-000, 82/11/03, 8212140001

DOCKETED ITEMS

- 7907100659 Forwards proposed insertion to systematic evaluation program rept Section 2 re geology, seismicity & site conditions
HALL, W J N M Newark Consulting Engineering Services
NRC-03-78-150 79/07/05 LEVIN, H A , HOFMAYER, C Division of
Operating Reactors 3pp 16434 270 24X Fiche 50-000, 82/11/03,
8212140001
- 7907240319 Forwards replacement pages to SEP seismic review evaluation
HALL, W J N M Newark Consulting Engineering Services
NRC-03-78-150 79/07/02 LEVIN, H A Systematic Evaluation
Program Branch (Pre 791030) 3pp 16435 173 24X
Fiche 50-000, 82/11/03, 8212140001
- 7908080624 Forwards Section 4 to be added to Chapter 1 of SEP
seismic review evaluation
HALL, W J N M Newark Consulting Engineering Services
NRC-03-78-150 79/08/02 LEVIN, H A Systematic Evaluation
Program Branch (Pre 791030) 3pp 16435 178 24X
Fiche 50-000, 82/11/03, 8212140001
- 7909280656 Summary of 790802 telcon w/NM Newark & WJ Hall re seismic
evaluation rept
CHEN, P Y Systematic Evaluation Program Branch (Pre 791030)
79/08/21 KUD, P T Systematic Evaluation Program Branch (Pre
791030) 2pp 16435 176 24X Fiche 50-000, 82/11/03, 8212140001
- 791150252 Discusses issuance of SSRT rept Revised computation of
turbine design parameters submitted by consultant renders
rept inaccurate NRC should make final decision re issuance
NEWMARK, H M N M Newark Consulting Engineering Services
79/11/12 EISENHUT, D G Division of Operating Reactors 2pp
16435 181 24X Fiche 50-000, 82/11/03, 8212140001
- 8002200995 Notifies that review & performance of audit calculations to
be continued per contract & preliminary review work to be
completed at LaCrosse Code used for reanalysis of piping sys
requires benchmarking per code verification program
SHAD, L C Assistant Director for Engineering Programs 79/10/30
EISENHUT, D G Division of Operating Reactors 1p 16435 111
24X Fiche 50-000, 82/11/03, 8212140001
- 8004010318 Comments on "Seismic Analysis of Reactor Internals," Matl
supplied in rept useful in defining mass & stiffness
characteristics of vessel internals & supports but does not
answer design question in NUREG/CR-0891
STEVENS, T D Woodward-Clyde Consultants, Inc 80/03/25
JABBOUR, K M Systematic Evaluation Program Branch 1p
16434 273 24X Fiche 50-000, 82/11/03, 8212140001
- 8005070778 Forwards input to SEP Topics III-6 & III-11, consisting of
NUREG/CR-0891, "Seismic Review for SEP" & EGG-5045,
"Summary of Piping Calculations Performed for SEP" Repts
should be transmitted to licensee NUREG only encl
CRUTCHFIELD, D Systematic Evaluation Program Branch 80/04/14
ZIEHANN, D L Systematic Evaluation Program Branch 2pp
16435 183 24X Fiche 50-000, 82/11/03, 8212140001
- 8005070798 "Seismic Review for SEP"
NEWMARK, H M, HALL, W J, KENNEDY, R P Lawrence Livermore
Laboratory NUREG/CR-0891 79/07/31 198pp Available at NTIS
16435 185 24X Fiche 50-000, 82/11/03, 8212140001
- 8009110797 Forwards excerpt from utils 680801, "Rept to Stockholders,"
re effect of 680815 tornadoes on util 345 kV sys
DENTON, H R Atomic Energy Commission 68/08/14 TEDBEC, R L
Atomic Energy Commission 2pp 16434 254 24X
Fiche 50-000, 82/11/03, 8212140001
- 3/11230066 Generic Ltr 82-27 to all BWR licensees of operating reactors
except LACBWR, Big Rock Point, Dresden 1, Humboldt Bay,
applicants for OL & holders of CP re transmittal of
NUREG-0763 & NUREG-0783 Svc list encl w/o stated encl
EISENHUT, D G Division of Licensing 82/11/15 General Public
Utilities - OPU Service Corp 22pp 16387 004 24X
Fiche 50-000, 82/11/15, 8211230066
- 7/12030043 Forwards clarification of util position in areas
identified by NRC as not meeting current criteria, per SEP
Topic VI-4, "Containment Isolation Sys"
RAUSCH, T J Commonwealth Edison Co 82/11/18 O'CONNOR, P
Operating Reactors Branch 5 4pp 16304 106 24X
Fiche 50-237, 82/11/18, 8212030043
- 7/2060207 Submits addl info re SEP Topics III-2, "Wind & Tornado
Loadings" & III-7 B, "Design Loads, Design Criteria & Loading
Combinations."
RAUSCH, T J Commonwealth Edison Co 82/11/22 O'CONNOR, P
Operating Reactors Branch 5 5pp 16312 299 24X
Fiche 50-237, 82/11/22, 8212060207
- 8/12060267 Submits info re SEP Topic III-1, "Quality Group
Classification Components & Sys," in response to NRC 820309
ltr Operating temp ranges & thickness of matl illustrate
brittle fracture is of no concern
RAUSCH, T J Commonwealth Edison Co 82/11/22 O'CONNOR, P
Operating Reactors Branch 5 6pp 16312 310 24X
Fiche 50-237, 82/11/22, 8212060267
- 8/12090301 Advises that capacity discharge test demonstrates ability of
battery sys to deliver FSAR required loads & to meet
manufacturer rating, per SEP Topic VIII-3 A, "Station Battery
Capacity Test Requirements"
RAUSCH, T J Commonwealth Edison Co 82/12/03 O'CONNOR, P
Operating Reactors Branch 5 2pp 16364 361 24X
Fiche 50-237, 82/12/03, 8212090301
- 8/12140172 Provides outline re position on 34 open topics summarized
in Chapter 4 of integrated assessment
RAUSCH, T J Commonwealth Edison Co 82/12/06 O'CONNOR, P
Operating Reactors Branch 5 8pp 16410 197 24X
Fiche 50-237, 82/12/06, 8212140172
- 8/12160326 Forwards Revision 1 to "Second 10-Yr Inservice Insp &
Testing Program, Dresden Units 2 & 3" Response to NRC
questions & comments & procedures for reactor vessel 1,000
psi & ASME hydrostatic tests & quarterly valve timing encl
RAUSCH, T J Commonwealth Edison Co 82/12/10 EISENHUT, D G
Division of Licensing 44pp 16441 088 24X Fiche 50-237, 82/12/10,
8212160326
- 8212160334 Revision 1 to "Second 10-Yr Inservice Insp & Testing
Program, Dresden Units 2 & 3"
* Commonwealth Edison Co 82/12/31 268pp 16441 132 24X
Fiche 50-237, 82/12/10, 8212160334
- 8/12210036 Responds to NRC concerns re SEP Topic IX-5, "Ventilation
Sys" ESF ventilation sys adequate following loss of offsite
power event
RAUSCH, T J Commonwealth Edison Co 82/12/13 O'CONNOR, P
Operating Reactors Branch 5 7pp 16485 349 24X
Fiche 50-237, 82/12/13, 8212210036
- 8/12220212 Forwards Revision 22 to CE-1-A, "QA Program for Nuclear
Generating Stations"
SWARTZ, E D Commonwealth Edison Co 82/12/14 HAASS, W P Quality
Assurance Branch 1p 16518 007 24X Fiche 50-000, 82/12/14,
8212220212
- 8212220231 "QA Program for Nuclear Generating Stations," Revision 22
* Commonwealth Edison Co CE-1-A R22 82/11/01 17pp
16518 009 24X Fiche 50-000, 82/12/14, 8212220212
- 8/12230277 Forwards, for info, ACRS 821213 ltr to NJ Palladino,
consisting of ACRS rept on SEP review of plant
CRUTCHFIELD, D Operating Reactors Branch 5 82/12/16 DELGOURGF, L
Commonwealth Edison Co 1p 16508 273 24X Fiche 50-237, 82/12/16,
8212230277
- 8212220534 Summarizes ACRS 272nd meeting on 821209-11 re SEP review of
facility Review of full term QL will be deferred until
actions completed on remaining SEP topics, unresolved safety
issues & TMI action plan items
SHEIMON, P ACRS - Advisory Committee on Reactor Safeguards
82/12/13 PALLADINO, N J Commissioners 3pp 16508 274 24X
Fiche 50-237, 82/12/16, 8212220534
- 8/12280117 Forwards addl info re NUREG-0737, Item II F 1, "Addl Accident
Monitoring Instrumentation," per NRC 821109 request
Pressure monitoring sys provided w/separate loop for narrow
range monitoring
SWARTZ, E D Commonwealth Edison Co 82/12/20 EISENHUT, D G
Division of Licensing 9pp 16564 062 24X Fiche 50-000, 82/12/20,
8212280117
- 8/12280343 Forwards addl info re NUREG-0737, Items II F 1 4, 5 & 6
"Containment Pressure, Water Level & Hydrogen Monitoring,"
per Crutchfield 821109 ltr
SWARTZ, E D Commonwealth Edison Co 82/12/20 EISENHUT, D G
Division of Licensing 9pp 16561 053 24X Fiche 50-000, 82/12/20,
8212280343
- 8/12290190 Application to amend License DPR-25, revising Tech Specs to
allow use of fuel assemblies designed & mfg by Exxon Nuclear
Co for ensuing Cycle 9 reload & future reloads
RAUSCH, T J Commonwealth Edison Co 82/12/21 DENTON, H R Office
of Nuclear Reactor Regulation, Director 18pp 16581 223 24X
Fiche 50-237, 82/12/21, 8212290190
- 8212290193 Proposed Tech Specs allowing for use of Exxon Nuclear Co
fuel assemblies for ensuing Cycle 9 reload & future reloads
* Commonwealth Edison Co 82/12/21 58pp 16581 241 24X
Fiche 50-237, 82/12/21, 8212290190

- B212290199 Revision 1 to "Dresden Unit 2 LOCA Analysis Using EXEM/DWH Evaluation Model MAPLHGR Results"
BRAUN, D. J., JENSEN, S. E., KAYER, W. V. Exxon Nuclear Co., Inc (subs of Exxon Corp.) XN-NF-82-88 R01 82/12/02 20pp 16381 300
24X Fiche 50-237, 82/12/21, 8212290190
- B212290205 Nonproprietary version of Revision 1 to "Plant Transient Analysis for Dresden Unit 2, Cycle 9"
HELLEY, R. H., COOKE, G. C., STOUT, R. B. Exxon Nuclear Co., Inc (subs of Exxon Corp.) XN-NF-82-84(NP) R01 82/12/07 42pp
16581 321 24X Fiche 50-237, 82/12/21, 8212290190
- B212290215 Nonproprietary version of Revision 1 to "Dresden Unit 1, Cycle 9 Reload Analysis"
CHANDLER, J. C., STOUT, R. B., WILLIAMSON, H. E. Exxon Nuclear Co., Inc (subs of Exxon Corp.) XN-NF-82-77(NP) R01 82/12/06 33pp
16582 001 24X Fiche 50-237, 82/12/21, 8212290190
- B212280212 Forwards updated schedule for ongoing environ qualification testing programs, per 810528 commitment
SWARTZ, E. D. Commonwealth Edison Co 82/12/22 EISENHUT, D. O. Division of Licensing 18pp 16556 161 24X Fiche 50-000, 82/12/22, 8212280212
- B212280263 Clarifies position on classification of major mods to BWR Mark 1 Containment per 821216 ltr
RAUSCH, T. J. Commonwealth Edison Co 82/12/22 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 2pp 16561 307 24X
Fiche 50-000, 82/12/22, 8212280263
- G Inspection reports, IE Bulletins & correspondence
- B208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants" Svc list encl
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240
- B208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters" Svc list encl
COBB, L. I. Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000, 82/11/05, 8208190245
- B208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements" Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X
Fiche 50-000, 82/11/18, 8208190251
- B208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks" Svc list encl
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000, 82/11/26, 8208190256
- B212060036 Ack receipt of 821028 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-010/82-13, 50-237/82-17 & 50-249/82-18
STREETER, J. F. Region 3, Office of Director 82/11/26 REED, C. Commonwealth Edison Co 1p 16313 284 24X Fiche 50-010, 82/11/26, 8212060036
- B212060045 Responds to NRC B20928 ltr re violations noted in IE Insp Repts 50-010/82-13, 50-237/82-17 & 50-249/82-18 Corrective actions inservice leak test performed on water leg portion of torus level mod Training session scheduled
DEGEORGE, L. O. Commonwealth Edison Co 82/10/28 KEPLER, J. O. Region 3, Office of Director 3pp 16313 285 24X
Fiche 50-010, 82/11/26, 8212060036
- B212170330 Forwards IE Insp Repts 50-010/82-19, 50-237/82-24 & 50-249/82-26 on 821104-05 No noncompliance noted
LITTLE, W. S. Division of Engineering & Technical Programs 82/11/29 REED, C. Commonwealth Edison Co 2pp 16453 206 24X
Fiche 50-010, 82/11/29, 8212170330
- B212170306 IE Insp Repts 50-010/82-19, 50-237/82-26 & 50-249/82-26 on 821104-05 No noncompliance noted Major areas inspected
Licensee actions on previously identified items
REIMANN, F. W., JACKI, W. L. Division of Engineering & Technical Programs 82/11/24 4pp 16453 208 24X Fiche 50-010, 82/11/29, 8212170306
- B208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl" Svc list encl
COBB, L. I. Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp
16387 028 24X Fiche 50-000, 82/11/30, 8208190257
- B212030178 Forwards final SALP Repts 50-010/82-10, 50-237/82-14 & 50-249/82-15 for assessment period Jul 1980-Dec 1981, discussed at IE mgt meeting on 820602. Util 820618 comments on SALP rept addressed
KEPLER, J. O. Region 3, Office of Director 82/12/01 REED, C. Commonwealth Edison Co 3pp 16303 228 24X Fiche 50-010, 82/12/01, 8212030178
- B212030185 SALP Repts 50-010/82-10, 50-237/82-14 & 50-249/82-15 for assessment period Jul 1980-Dec 1981 Mgt attention warranted in areas of plant operations, radiological controls & review committee activities
* Region 3, Office of Director 82/03/31 47pp 16303 231 24X
Fiche 50-010, 82/12/01, 8212030178
- B212060029 Forwards response to IE Bulletin 82-03 re stress corrosion cracking in thick wall, large diameter stainless steel recirculation sys piping at BWRs Dresden response only addresses Item 4 Other info will be provided by startup
RAUSCH, T. J. Commonwealth Edison Co 82/12/01 KEPLER, J. O. Region 3, Office of Director 10pp 16313 288 24X Fiche 50-000, 82/12/01, 8212060029
- B212080537 Forwards response to Revision 1 to IE Bulletin 82-03 re stress corrosion cracking in thick-wall, large diameter stainless steel recirculation sys piping Addl info for Dresden 2 due prior to startup from Spring 1983 outage
RAUSCH, T. J. Commonwealth Edison Co 82/12/01 KEPLER, J. O. Region 3, Office of Director 10pp 16352 056 24X Fiche 50-000, 82/12/01, 8212080537
- B208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies" Svc list encl
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259
- B208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Buckets" Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X
Fiche 50-000, 82/12/03, 8208190261
- B212170196 Forwards IE Insp Repts 50-010/82-18, 50-237/82-25 & 50-249/82-25 on 821002-29 No noncompliance noted
STREETER, J. F. Division of Project & Resident Programs 82/12/03 REED, C. Commonwealth Edison Co 2pp 16450 153 24X
Fiche 50-010, 82/12/03, 8212170196
- B212170201 IE Insp Repts 50-010/82-18, 50-237/82-25 & 50-249/82-25 on 821002-29 No noncompliance noted Major areas inspected headquarters & regional requests, operational safety verification, monthly maint observation & LERs
TONQUE, T. H., STASEK, S., WALKER, R. D. Division of Project & Resident Programs 82/12/01 8pp 16450 155 24X Fiche 50-010, 82/12/03, 8212170196
- B212160326 Forwards Revision 1 to "Second 10-Yr Inservice Insp & Testing Program, Dresden Units 2 & 3" Response to NRC questions & comments & procedures for reactor vessel 1,000 psi & ASME hydrostatic tests & quarterly valve timing encl
RAUSCH, T. J. Commonwealth Edison Co 82/12/10 EISENHUT, D. O. Division of Licensing 44pp 16441 088 24X Fiche 50-237, 82/12/10, 8212160326
- B212160334 Revision 1 to "Second 10-Yr Inservice Insp & Testing Program, Dresden Units 2 & 3"
* Commonwealth Edison Co 82/12/31 268pp 16441 132 24X
Fiche 50-237, 82/12/10, 8212160326
- B212210118 Forwards IE Emergency Preparedness BERS 50-237/82-27 & 50-249/82-27 during Nov 1981 & June 1982, respectively No noncompliance noted
HIND, J. A. Division of Emergency Preparedness 82/12/10 REED, C. Commonwealth Edison Co 2pp 16485 088 24X Fiche 50-237, 82/12/10, 8212210118
- B212210124 IE Emergency Preparedness BERS 50-237/82-27 & 50-249/82-27 Major areas inspected emergency plan & site-specific annex dtd Nov 1981 & June 1982, respectively Planning stds met
PHILLIPS, H. P., AXELSON, W. L., PAPERIELLO, C. J. Region 3, Office of Director 82/12/07 29pp 16485 091 24X Fiche 50-237, 82/12/10, 8212210118
- B208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring" Svc list encl
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16, 8208190267

DOCKETED ITEMS

8212270295 Ack receipt of 821124 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-237/82-21, 50-249/82-22, 50-254/82-17 & 50-263/82-19 NORELIOUS, C E Division of Engineering & Technical Programs 82/12/16 REED, C Commonwealth Edison Co 2pp 16530 085 24X Fiche 50-000, 82/12/16, 8212270295

--8212270303 Responds to NRC 821026 ltr re violations noted in IE Insp Repts 50-237/82-21, 50-249/82-22, 50-254/82-17 & 50-263/82-19 Corrective actions annual audits of all active AE firms performing safety-related work required DELOECROE, L O Commonwealth Edison Co 82/11/24 KEPPLER, J G Region 3, Office of Director 4pp 16530 087 24X Fiche 50-000, 82/12/16, 8212270295

--8212270307 "EDS-NUTECH Interface Control Instructions," Revision 0 TSHUDDI, W F NUTECH (Nuclear Technology, Inc.) 82/09/30 22pp 16530 091 24X Fiche 50-000, 82/12/16, 8212270295

- 8212270313 "IE Bulletin 79-14 & YAP Piping Evaluation, Quad Cities Units 1 & 2 & Dresden Units 2 & 3," Revision 0 * NUTECH (Nuclear Technology, Inc.) 82/10/01 9pp 16530 113 24X Fiche 50-000, 82/12/16, 8212270295

8212280110 Provides final status rept of IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys." Complete & final listings of portions of sys failing to meet FSAR requirements under NUTECH responsibility encl RAUSCH, T J Commonwealth Edison Co 82/12/17 KEPPLER, J G Region 3, Office of Director 3pp 16564 191 24X Fiche 50-000, 82/12/17, 8212280110

8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type JTE-27" Svc list encl JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X Fiche 50-000, 82/12/20, 8208190268

8212280214 Forwards IE Safeguards Insp Repts 50-010/82-20, 50-237/82-28 & 50-249/82-29 on 821115-19 Details & notice of violation withheld (ref 10CFR73 21) MILLER, J R Division of Engineering & Technical Programs 82/12/20 REED, C Commonwealth Edison Co 2pp 16562 120 24X Fiche 50-010, 82/12/20, 8212280214

--8212280220 IE Safeguards Insp Repts 50-010/82-20, 50-237/82-28 & 50-249/82-29 on 821115-19 Noncompliance noted failure to adequately control security-related key as required by security plan. Details withheld (ref 10CFR73 21) CHRISTOFFER, O, KNICELEY, J R, CREED, J R Division of Emergency Preparedness & Operational Support 82/12/15 2pp 16562 122 24X Fiche 50-010, 82/12/20, 8212280214

8212280070 Requests addition of RE Farrell to unescorted access list to vital & protected areas individual possesses Q clearance KEPPLER, J G Region 3, Office of Director 82/12/22 REED, C Commonwealth Edison Co 1pp 16565 136 24X Fiche 50-010, 82/12/22, 8212280070

R Periodic operating reports & related correspondence

8212140077 "1982 Evaluation, Dresden Nuclear Power Station, Comm Ed Co" * Institute of Nuclear Power Operations 82/11/30 39pp 16403 171 24X Fiche 50-010, 82/11/30, 8212140077

8212140112 Forwards monthly operating repts for Nov 1982 SCOTT, D J Commonwealth Edison Co 82/12/01, Director's Office, Office of Inspection and Enforcement 1p 16408 204 24X Fiche 50-010, 82/12/01, 8212140112

--8212140120 Monthly operating repts for Nov 1982 SCHROEDER, B A Commonwealth Edison Co 82/12/01 28pp 16408 205 24X Fiche 50-010, 82/12/01, 8212140112

S Reportable occurrences, LERs & related correspondence

8212290344 Forwards updated LER 82-036/03X-1 SCOTT, D J Commonwealth Edison Co 82/11/16 KEPPLER, J G Region 3, Office of Director 1p 16586 217 24X Fiche 50-237, 82/11/16, 8212290344

--8212290345 Updated LER 82-036/03X-1 on 820723, during normal startup, gain adjustment factor for average power range monitors 2 & 3 exceeded 1.02 Caused by procedural deficiencies Average power range monitor gain adjusted SCHROEDER, B A Commonwealth Edison Co 82/11/16 Region 3, Office of Director 2pp 16586 218 24X Fiche 50-237, 82/11/16, 8212290344

8212290398 Forwards updated LER 82-037/03X-1 SCOTT, D J Commonwealth Edison Co 82/11/22 KEPPLER, J G Region 3, Office of Director 1p 16586 347 24X Fiche 50-237, 82/11/22, 8212290398

--8212290409 Updated LER 82-037/03X-1 on 820724, during final hours of 12-h xenon soak period, average power range monitor (APRM) gain adjustment factor for APRM 4 & 6 exceeded 1.02 Caused by procedural deficiencies Procedures will be modified SCHROEDER, B A Commonwealth Edison Co 82/11/22 Region 3, Office of Director 2pp 16586 348 24X Fiche 50-237, 82/11/22, 8212290398

8212020275 Forwards updated LER 82-042/01X-1 SCOTT, D J Commonwealth Edison Co 82/11/24 KEPPLER, J G Region 3, Office of Director 1p 16288 350 24X Fiche 50-237, 82/11/24, 8212020275

--8212020280 Updated LER 82-042/01X-1 on 821002, during normal operation, following torus hi/lo level alarm, sightglass isolation & vent valves reported open w/no indication of excess makeup Caused by operator error Valves locked closed HOLLAND, P Commonwealth Edison Co 82/11/24 Region 3, Office of Director 2pp 16288 351 24X Fiche 50-237, 82/11/24, 8212020275

8212100215 Forwards LER 82-046/03L-0 SCOTT, D J Commonwealth Edison Co 82/11/24 KEPPLER, J G Region 3, Office of Director 1p 16376 074 24X Fiche 50-237, 82/11/24, 8212100215

--8212100216 LER 82-046/03L-0 on 821109, during normal operation, high range boron test for standby liquid control, DCP 1100-4, revealed boron concentration below Tech Specs Caused by inadequate procedure for sys leakage Procedure revised COYLE, L Commonwealth Edison Co 82/11/24 Region 3, Office of Director 1p 16376 075 24X Fiche 50-237, 82/11/24, 8212100215

8212100312 Forwards LER 82-045/03L-0 SCOTT, D J Commonwealth Edison Co 82/12/01 KEPPLER, J G Region 3, Office of Director 1p 16376 274 24X Fiche 50-237, 82/12/01, 8212100312

- 8212100319 LER 82-045/03L-0 on 821106, during load reduction, all AGAF found greater than 1.02 Caused by substantial fraction of rated power change associated w/rapid changes in feedwater flow Gain adjustments made to average power range monitors BEVERLY, K Commonwealth Edison Co 82/12/02 Region 3, Office of Director 1p 16376 275 24X Fiche 50-237, 82/12/01, 8212100312

8212170122 Forwards LER 82-044/03L-0 SCOTT, D J Commonwealth Edison Co 82/12/03 KEPPLER, J G Region 3, Office of Director 1p 16453 001 24X Fiche 50-237, 82/12/03, 8212170122

--8212170130 LER 82-044/03L-0 on 821109, 2/3 diesel generator trouble alarm annunciated in control room due to lubricating oil pump being off & tripped breaker Caused by bad bearing in lubricating oil pump motor Deviation rept encl RHODE, B J Commonwealth Edison Co 82/12/03 Region 3, Office of Director 2pp 16453 002 24X Fiche 50-237, 82/12/03, 8212170122

8212090415 PNO-111-82-132 on 821203, licensee declared alert when level of flood-swollen IL River threatened svc water pumps & diesel fire pumps inside crib house Shutdown initiated Alert canceled on 821204 Units returned to power on 821205 WALKER, R, TONGUE, T, SPESARD, R Region 3, Office of Director 82/12/06 1p 16365 032 24X Fiche 50-237, 82/12/06, 8212090415

8212210157 Forwards LER 82-047/03L-0 SCOTT, D J Commonwealth Edison Co 82/12/06 KEPPLER, J G Region 3, Office of Director 1p 16484 313 24X Fiche 50-237, 82/12/06, 8212210157

--8212210160 LER 82-047/03L-0 on 821117, while performing DIS 5003, reactor vessel low water level ECCS initiation, LIS 263-72A found set at 111.6 inches delta P Caused by defective procedure LIS 263-72A reset & setpoints revised COYLE, L M Commonwealth Edison Co 82/12/06 Region 3, Office of Director 1p 16484 314 24X Fiche 50-237, 82/12/06, 8212210157

8212280472 Forwards LER 82-050/01T-0 SCOTT, D J Commonwealth Edison Co 82/12/13 KEPPLER, J G Region 3, Office of Director 1p 16556 023 24X Fiche 50-237, 82/12/13, 8212280472

--B212280479 LER 82-050/011-0 on B21203, during cribhouse insp, discovered intake water level at 509 ft 2 inches. Caused by rising river level from heavy rainfall. Water level rose to 509 ft 6 inches before receding.
CHRISTEL, B Commonwealth Edison Co 82/12/13 Region 3, Office of Director 2pp 16556 024 24X Fiche 50-237, 82/12/13, 8212280472

B212220207 PHD-111-B2-136 on B21216, male employee found dead on fourth level of reactor bldg. No radioactive contamination detected. Radiation levels measured less than 5 m/h. Investigation underway.
TODIGUE, T, WALKER, R, STREETER, J Region 3, Office of Director 82/12/16 1p 16518 331 24X Fiche 50-237, 82/12/16, 8212220207

1 Hearing transcripts on non-antitrust matters

B212020258 Transcript of ACRS Subcommittee on SEP 821130 meeting in Washington, DC. Pp 1-257. Supporting documentation encl.
* ACRS - Advisory Committee on Reactor Safeguards 82/11/30 359pp 16276 266 24X Fiche 50-000, 82/11/30, 8212020258

DOCKET 50-243 OREGON STATE UNIV RESEARCH REACTOR

F Security, medical, emergency & fire protection plans

B212150248 Releases public version of corrected pages to emergency response plan.
FELTON, J M Division of Rules and Records 82/12/07 Document Management Branch 1p 16446 292 24X Fiche 50-243, 82/12/07, 8212150248

--B212150252 Forwards public version of corrected pages to B21103 emergency response plan.
WANO, C H Ohio State Univ 82/11/29 Office of Nuclear Reactor Regulation, Director 1p 16446 295 24X Fiche 50-243, 82/12/07, 8212150248

--B212150257 Public version of corrected pages to B21103 emergency response plan.
* Ohio State Univ 82/11/29 6pp 16446 296 24X Fiche 50-243, 82/12/07, 8212150248

G Inspection reports, IE Bulletins & correspondence

B212060173 Forwards IE Insp Rept 50-243/82-03 on B21019-21. No noncompliance noted.
STERMBERG, D M Division of Resident, Reactor Project & Engineering Programs 82/11/12 WANO, C H Oregon State Univ 4pp 16313 078 24X Fiche 50-243, 82/11/12, 8212060173

--B212060178 IE Insp Rept 50-243/82-03 on B21019-21. No noncompliance noted. Major areas inspected: logs & records, review & audit procedures, requalification training, surveillance, experiments & miscellaneous independent insp effort.
WILLETT, D J, DODDS, R T Division of Resident, Reactor Project & Engineering Programs 82/11/10 9pp 16313 082 24X Fiche 50-243, 82/11/12, 8212060173

DOCKET 50-244 ROBERT EMMET CINNA NUCLEAR PLANT, UNIT 1

F Security, medical, emergency & fire protection plans

B212020291 Requests that next full-scale emergency exercise per 10CFR50 App E be held no later than 830630 due to prior commitments of NRC, FEMA & State of NY to support exercises at other facilities.
MAIER, J E Rochester Gas & Electric Corp 82/11/18 CRUTCHFIELD, D Operating Reactors Branch 5 1p 16288 250 24X Fiche 50-244, 82/11/18, 8212020291

B212030035 Forwards IE Safeguards Insp Rept 50-244/82-20 on 820927-30. No noncompliance noted.
MARTIN, T T Division of Engineering & Technical Programs 82/11/18 MAIER, J E Rochester Gas & Electric Corp 2pp 16304 122 24X Fiche 50-244, 82/11/18, 8212030035

--B212030038 IE Safeguards Insp Rept 50-244/82-20 on 820927-30. No noncompliance noted. Major areas inspected: security plan & procedure implementation, security organization & security sys power supply. Security info deleted (ref 10CFR73.21).
DUKLAP, J M, BAILEY, R J, GODY, A T Region 1, Office of Director 82/11/15 4pp 16304 124 24X Fiche 50-244, 82/11/18, 8212030035

B212070094 Forwards application for amend to License DPR-18 & proposed Tech Specs re audits of emergency plan & security plan.
MAIER, J E Rochester Gas & Electric Corp 82/12/01 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 16327 356 24X Fiche 50-244, 82/12/01, 8212070094

--B212070095 Application for amend to License DPR-18 re audits of emergency plan & security plan.
MAIER, J E Rochester Gas & Electric Corp 82/12/01 3pp 16327 357 24X Fiche 50-244, 82/12/01, 8212070094

--B212070098 Proposed Tech Spec Page 6 5-9 re audit of emergency & security plan audits. Safety evaluation encl.
* Rochester Gas & Electric Corp 82/12/01 2pp 16327 360 24X Fiche 50-244, 82/12/01, 8212070094

B212140240 Notifies that emergency operations facility located 18 miles from site. No backup facility required. No interim facility used before establishing permanent facilities.
MAIER, J E Rochester Gas & Electric Corp 82/12/07 CRUTCHFIELD, D Operating Reactors Branch 5 1p 16409 299 24X Fiche 50-244, 82/12/07, 8212140240

B212290375 Forwards IE Safeguards Insp Rept 50-244/82-23 on B21116-19 & notice of violation.
MARTIN, T T Division of Engineering & Technical Programs 82/12/13 MAIER, J E Rochester Gas & Electric Corp 2pp 16586 352 24X Fiche 50-244, 82/12/13, 8212290375

--B212290379 Notice of violation from insp on B21116-19.
* Division of Engineering & Technical Programs 82/12/13 1p 16586 354 24X Fiche 50-244, 82/12/13, 8212290375

--B212290383 IE Safeguards Insp Rept 50-244/82-23 on B21116-19. Noncompliance noted: failure to conduct physical inventories of SNM at less than 12-month intervals & failure to follow physical inventory instructions.
DELLA RATTIA, A, GODY, A T Region 1, Office of Director 82/12/08 6pp 16586 355 24X Fiche 50-244, 82/12/13, 8212290375

J Insurance & indemnity information

B212280258 Forwards Endorsements 1, 2 & 3 to NELIA Certificate N-14 & MAELU Certificate M-14.
SINISI, J M Marsh & McLennan, Inc, M & M Nuclear Consultants, Inc Div 82/12/21 SALTZMAN, J Assistant Director for State & Licensee Relations 19pp 16561 250 24X Fiche 50-244, 82/12/21, 8212280258

D Advisory Committee on Reactor Safeguards reports & correspondence

B212010502 Summary of 265th ACRS meeting on 820506-08 in Washington, DC re Ginna restart safety evaluation, Wolf Creek CL review, Palisades SEP review, emergency response capability of plants & safety-related equipment qualification program.
* ACRS - Advisory Committee on Reactor Safeguards 82/11/26 ACRS - Advisory Committee on Reactor Safeguards 605pp 16294 131 24X Fiche 50-000, 82/11/26, 8212010502

P Operating license stage documents & correspondence

B212140001 Addl response to FOIA request for five categories of documents re SEP. Forwards documents listed in App A. No documents located subj to Item 3 of request. Review of remaining documents continuing. Documents available in PDR.
FELTON, J M Division of Rules and Records 82/11/03 GALLO, J Isham, Lincoln & Beale 2pp 16433 354 24X Fiche 50-000, 82/11/03, 8212140001

--7909180332 Forward minutes of 790830 meeting w/util in Reading, PA re seismic analysis modeling.
NELSON, T A Lawrence Livermore Laboratory 79/09/12 LEVIN, H Systematic Evaluation Program Branch (Pre 791030) 4pp 16436 016 24X Fiche 50-000, 82/11/03, 8212140001

--8002200995 Notifies that review & performance of audit calculations to be continued per contract & preliminary review work to be completed at LaCrosse Code used for reanalysis of piping sys requires benchmarking per code verification program.
SHAO, L C Assistant Director for Engineering Programs 79/10/30 EISENHUT, D G Division of Operating Reactors 1p 16435 111 24X Fiche 50-000, 82/11/03, 8212140001

--8112270035 Summary of 810909 meeting w/util re SEP seismic review. List of attendees encl.
CHENG, T M Systematic Evaluation Program Branch 81/12/14 RUSSELL, W T Systematic Evaluation Program Branch 4pp 16436 020 24X Fiche 50-000, 82/11/03, 8212140001

--8205260070 Discusses integrated plant safety assessment rept for facility re SEP Topic III-6, seismic design considerations. Suggests that rept be modified to remove ambiguity re operability qualification of safety-related equipment.
BAOCHI, Q Equipment Qualification Branch 82/05/14 PAHLICKI, S B Assistant Director for Materials & Qualifications Engineering 1p 16436 024 24X Fiche 50-000, 82/11/03, 8212140001

DOCKETED ITEMS

B212070094 Forwards application for amend to License DPR-18 & proposed Tech Specs re audits of emergency plan & security plan
MAIER, J E Rochester Gas & Electric Corp 82/12/01 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 16327 356 24X
Fiche 50-244, 82/12/01, 8212070094

--B212070095 Application for amend to License DPR-18 re audits of emergency plan & security plan
MAIER, J E Rochester Gas & Electric Corp 82/12/01 3pp
16327 357 24X Fiche 50-244, 82/12/01, 8212070094

--B212070098 Proposed Tech Spec Page 6 5-9 re audit of emergency & security plan audits Safety evaluation encl
* Rochester Gas & Electric Corp 82/12/01 2pp 16327 360 24X
Fiche 50-244, 82/12/01, 8212070094

B212070282 Notifies that response to B21026 Generic Ltr 82-22, "Congressional Request for Info re Steam Generator Tube Integrity," will not be provided info necessary to respond to issue not readily available
MAIER, J E Rochester Gas & Electric Corp 82/12/01 CRUTCHFIELD, D
Operating Reactors Branch 5 1p 16343 194 24X
Fiche 50-244, 82/12/01, 8212070282

B212080384 Advises of expected completion dates for TMI Items II B 2 re radwaste remote control sys, II B 3 re post-accident sampling sys, II D 1 re safety & relief valve testing & III D 3 4 re control room HVAC mods
MAIER, J E Rochester Gas & Electric Corp 82/12/02 CRUTCHFIELD, D
Operating Reactors Branch 5 3pp 16392 286 24X
Fiche 50-244, 82/12/02, 8212080384

B212140404 Forwards application to amend License DPR-18, revising App A Tech Specs to clarify requirements for heatup & cooldown per analysis of reactor vessel surveillance capsule T Amend fee encl
MAIER, J E Rochester Gas & Electric Corp 82/12/08 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 16403 214 24X
Fiche 50-244, 82/12/08, 8212140404

--B212140409 Application to amend License DPR-18, clarifying & revising App A Tech Spec requirements for heatup & cooldown per analysis of reactor vessel surveillance capsule T
MAIER, J E Rochester Gas & Electric Corp 82/12/08 2pp
16403 215 24X Fiche 50-244, 82/12/08, 8212140404

--B212140413 Proposed App A Tech Spec changes to clarify requirements for heatup & cooldown requirements replacing Pages 3 1-5, 3 1-6, 3 1-7, 3 1-12, 3 1-13, 3 1-14 & 4 3-1
* Rochester Gas & Electric Corp 82/12/08 9pp 16403 218 24X
Fiche 50-244, 82/12/08, 8212140404

--B212140420 "Analysis of Capsule T From Rochester Gas & Electric Corp, RE Ginna Nuclear Plant, Reactor Vessel Radiation Surveillance Program"
YANICHKO, S E, ANDERSON, S L, SHOGAN, R P Westinghouse Electric Corp WCAP-10086 82/04/30 83p 16403 226 24X
Fiche 50-244, 82/12/08, 8212140404

B208190263 Generic Ltr 82-32 to all PWR licensees re potential steam generator-related generic requirements Forwards Science Applications, Inc draft re subj requirements Comments requested within 30 days of ltr Svc list encl
EISENHUT, D G Division of Licensing 82/12/09 Consolidated Edison Co of New York, Inc 29pp 16629 247 24X
Fiche 50-000, 82/12/09, 8208190263

B212140103 Generic Ltr 82-28 to all licensees of operating Westinghouse & C-E PWRs (except Arkansas Nuclear One, Unit 2 & San Onofre 2 & 3) re inadequate core cooling instrumentation sys Svc list encl
EISENHUT, D G Division of Licensing 82/12/10 Yankee Atomic Electric Co 27pp 16690 035 24X Fiche 50-000, 82/12/10, 8212140103

B212200008 Forwards SER & proprietary & nonproprietary technical evaluation repts re environ qualification of safety-related electrical equipment Plans for qualification or replacement of equipment in Categories I, B, II A & II B requested
CRUTCHFIELD, D Operating Reactors Branch 5 82/12/13 MAIER, J E
Rochester Gas & Electric Corp 3pp 24X Fiche 50-244, 82/12/13, 8212200008

--B212200013 SER re environ qualification of safety-related electrical equipment Addl info on qualification or replacement of equipment in Categories I, B, II A & II B required
* Office of Nuclear Reactor Regulation, Director 82/12/13 5pp
16476 044 24X Fiche 50-244, 82/12/13, 8212200008

--B207010149 "Review of Licensee Resolution of Outstanding Issues From NRC Equipment Environ Qualification SERs (F-11 & D-60)," technical evaluation repts
CRANE, C J Franklin Institute/Franklin Research Center
NRC 03-79-118 YER-C9257-454 82/05/28 L.E.N. II, SHEMANSKI, P
NRC - No Detailed Affiliation Given 475pp 16476 049 24X
Fiche 50-244, 82/12/13, 8212200008

B212210392 Forwards SER supporting resolution of NUREG-0737, Items 11 E 4 2 6, "Operable Valves or if Closed Must be Sealed Closed" & 11 E 4 2 7, "Primary Containment High Radiation to Close Vent & Purge Valves"
CRUTCHFIELD, D Operating Reactors Branch 5 82/12/15 MAIER, J E
Rochester Gas & Electric Corp 4pp 16474 294 24X
Fiche 50-244, 82/12/15, 8212210392

B212210456 Forwards "Reactor Containment Bldg Integrated Leak Rate Test, May 1982" Facility within Tech Spec limits
MAIER, J E Rochester Gas & Electric Corp 82/12/15 CRUTCHFIELD, D
Operating Reactors Branch 5 1p 16489 209 24X
Fiche 50-244, 82/12/15, 8212210456

--B212210461 "Reactor Containment Bldg Integrated Leak Rate Test, May 1982"
* Ojibert/Commonwealth Cos 82/12/15 75pp 16489 210 24X
Fiche 50-244, 82/12/15, 8212210456

B212220243 Advises that Exxon Nuclear Co repts re upper plenum injection will be submitted by mid-Feb 1983 Only Exxon fuel will be in reactor until Spring 1984 outage Westinghouse fuel response will be answered as part of 1984 fuel reload
MAIER, J E Rochester Gas & Electric Corp 82/12/15 CRUTCHFIELD, D
Operating Reactors Branch 5 1p 16518 328 24X
Fiche 50-244, 82/12/15, 8212220243

B212280388 Forwards Revision 3 to QA manual describing inservice pump & valve testing program for Jan 1981-Dec 1990 Revision provides clarification & changes re pump test frequency & performance parameters
MAIER, J E Rochester Gas & Electric Corp 82/12/21 CRUTCHFIELD, D
Operating Reactors Branch 5 2pp 16559 041 24X
Fiche 50-244, 82/12/21, 8212280388

--B212280391 Revision 3 to QA manual re inservice pump & valve testing program for Jan 1981-Dec 1990
ANDERSON, C R Rochester Gas & Electric Corp 82/12/21 35pp
16559 043 24X Fiche 50-244, 82/12/21, 8212280388

0 Inspection reports, IE Bulletins & correspondence

B208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants" Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc
112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240

B208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model B01 & Model B02 Thermoluminescent Dosimeters" Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp
16372 142 24X Fiche 50-000, 82/11/05, 8208190245

B208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements" Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X
Fiche 50-000, 82/11/18, 8208190251

B212030035 Forwards IE Safeguards Insp Rept 50-244/82-20 on 820927-30 No noncompliance noted
MARTIN, T T Division of Engineering & Technical Programs, 82/11/18 MAIER, J E Rochester Gas & Electric Corp 2pp 16304 122 24X
Fiche 50-244, 82/11/18, 8212030035

--B212030038 IE Safeguards Insp Rept 50-244/82-20 on 820927-30 No noncompliance noted Major areas inspected security plan & procedure implementation, security organization & security sys power supply Security info deleted (ref IOCFR73 21)
DUNLAP, J M, BAILEY, R J, GDDY, A T Region 1, Office of Director 82/11/15 4pp 16304 124 24X Fiche 50-244, 82/11/18, 8212030035

B208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks" Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc
127pp 16411 045 24X Fiche 50-000, 82/11/26, 8208190256

8208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards
82/11/30 Consolidated Edison Co of New York, Inc 356pp
16387 028 24X Fiche 50-000, 82/11/30, 8208190257

8208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259

8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X Fiche 50-000, 82/12/03, 8208190261

8212220350 Forwards IE Insp Rept 50-244/82-19 on 820927-1001 & notice of violation
MARTIN, T T Division of Engineering & Technical Programs 82/12/07 MAIER, J E Rochester Gas & Electric Corp 2pp 16517 153 24X Fiche 50-244, 82/12/07, 8212220350

--8212220354 Notice of violation from insp on 820927-1001
* Division of Engineering & Technical Programs 82/12/07 1p 16517 155 24X Fiche 50-244, 82/12/07, 8212220350

--8212220358 IE Insp Rept 50-244/82-19 on 820927-1001 Noncompliance noted failure to provide for egress from high radiation areas per 10CFR20.203(c)(5)
COLLINS, D J, SHANBAKY, M Region 1, Office of Director 82/12/06 8pp 16517 156 24X Fiche 50-244, 82/12/07, 8212220350

8212290375 Forwards IE Safeguards Insp Rept 50-244/82-23 on 821116-19 & notice of violation
MARTIN, T T Division of Engineering & Technical Programs 82/12/13 MAIER, J E Rochester Gas & Electric Corp 2pp 16586 352 24X Fiche 50-244, 82/12/13, 8212290375

--8212290379 Notice of violation from insp on 821116-19
* Division of Engineering & Technical Programs 82/12/13 1p 16586 354 24X Fiche 50-244, 82/12/13, 8212290375

--8212290383 IE Safeguards Insp Rept 50-244/82-23 on 821116-19 Noncompliance noted failure to conduct physical inventories of SNM at less than 12-month intervals & failure to follow physical inventory instructions
DELLA RATTA, A, GODY, A T Region 1, Office of Director 82/12/08 6pp 16586 355 24X Fiche 50-244, 82/12/13, 8212290375

8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16, 8208190267

8212220451 Forwards listing of topic areas for discussion at Region 1 / license meeting on drug & alcohol abuse programs per IE Info Notice 82-05 & NUREG-0903 W/o NUREG
STAROSTECKI, R Division of Project & Resident Programs 82/12/16 MAIER, J E Rochester Gas & Electric Corp 3pp 16504 277 24X Fiche 50-244, 82/12/16, 8212220451

8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27 " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X Fiche 50-000, 82/12/20, 8208190268

R Periodic operating reports & related correspondence

8212290163 Forwards monthly operating rept for Oct 1982
BNOV, B A Rochester Gas & Electric Corp 82/11/05 Office of Resource Management, Director 1p 16582 197 24X Fiche 50-244, 82/11/05, 8212290163

--8212290166 Monthly operating rept for Oct 1982
MCNAMARA, A E Rochester Gas & Electric Corp 82/11/05 5pp 16582 198 24X Fiche 50-244, 82/11/05, 8212290163

S Reportable occurrences, LERs & related correspondence

8212270066 FOIA request for SECY-82-58, "Media Attention to Preliminary Evaluation of Operator Actions During Ginna Event 1982 "
KING, A P United Kingdom 82/10/20 Office of Administration 1p 16553 160 24X Fiche 50-244, 82/10/20, 8212270066

8212290055 FOIA request for seven categories of info Documents will be used in PSC Case 28166 on behalf of Rochester Gas & Electric Corp ratepayers re 820125 accident at facility Waiver of Fees requested
SCHLISSEL, D A New York, State of 82/11/01 FELTON, J Division of Rules and Records 4pp 16607 235 24X Fiche 50-244, 82/11/01, 8212290055

8212060169 Forwards LER 82-026/03L-0
MAIER, J E Rochester Gas & Electric Corp 82/11/24 HAYNES, R C Region 1, Office of Director 1p 16313 088 24X Fiche 50-244, 82/11/24, 8212060169

--8212060175 LER 82-026/03L-0 on 821026, during performance of PT-3, containment spray sys periodic test, check valve B623 failed to close promptly Cause not stated Maint performed on valve & retest indicated acceptable performance
BODINE, J C Rochester Gas & Electric Corp 82/11/24 Region 1, Office of Director 1p 16313 089 24X Fiche 50-244, 82/11/24, 8212060169

8212270062 Responds to FOIA request for SECY-82-58, "Media Attention to Preliminary Evaluation of Operator Actions During Ginna Event 1982 " Documents available in PDR
FELTON, J M Division of Rules and Records 82/11/26 KING, A P United Kingdom 1p 16553 159 24X Fiche 50-244, 82/11/26, 8212270062

8212290060 Partial response to FOIA request for seven categories of info Forwards documents listed in App A Documents 1 & 2 already in PDR App B documents available in PDR LPDR profiles for Ginna & Indian Point 3 encl
FELTON, J M Division of Rules and Records 82/11/30 SCHLISSEL, D A New York, State of 7pp 16607 239 24X Fiche 50-000, 82/11/30, 8212290060

--8212290065 Forwards SER input (Task 82-05) re steam generator matl accountability controls at facility Matl accountability controls used during 1982 steam generator mods included major improvements over controls used in 1975
STAROSTECKI, R Division of Project & Resident Programs 82/05/19 EISENHUT, D G Division of Licensing 5pp 16607 257 24X Fiche 50-000, 82/11/30, 8212290060

DOCKET 50-245 MILLSTONE NUCLEAR POWER STATION, UNIT 1

F Security, medical, emergency & fire protection plans

8212070124 Forwards proposal for revision to modified amended security plan Proposal withheld (ref 10CFR73.21)
COUNSIL, W O, WERNER, R P Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL, W O Northeast Utilities 82/11/18 CLARK, R A Operating Reactors Branch 3 CRUTCHFIELD, D Operating Reactors Branch 5 2pp 16329 341 24X Fiche 50-245, 82/11/18, 8212070124

8212090114 Responds to Generic Ltr 82-23 re BNL request for assistance in field testing new measurement equipment & inventory techniques developed to aid in strengthening IAEA safeguards Addl info available should be sent expeditiously
COUNSIL, W O Connecticut Yankee Atomic Power Co COUNSIL, W O Northeast Nuclear Energy Co (subs of Northeast Utilities) 82/11/30 EISENHUT, D G Division of Licensing 1p 16357 272 24X Fiche 50-000, 82/11/30, 8212090114

821210576 Releases public version of revision to emergency plan
FELTON, J M Division of Rules and Records 82/12/10 Document Management Branch 1p 16543 014 24X Fiche 50-245, 82/12/10, 821210576

--821210579 Forwards public version of Revision 10 to emergency plan
ST PIERRE, M Northeast Nuclear Energy Co (subs of Northeast Utilities) 82/12/13 EISENHUT, D G Division of Licensing 1p 16543 015 24X Fiche 50-245, 82/12/10, 821210576

--821210581 Public version of Revision 10 to emergency plan
* Northeast Nuclear Energy Co (subs of Northeast Utilities) 82/11/24 200pp 16543 016 24X Fiche 50-245, 82/12/10, 821210576

J Insurance & indemnity information

8212280063 Forwards Endorsement 83 to NELIA Policy NF-173 & Endorsement 75 to MAELU Policy HF-52
BINI81, J M Marsh & McLennan Inc, M & M Nuclear Consultants, Inc Div 82/12/21 SALTZMAN, J D Assistant Director for State & Licensee Relations 3pp 16564 276 24X Fiche 50-245, 82/12/21, 8212280063

DOCKETED ITEMS

D Advisory Committee on Reactor Safeguards reports & correspondence

B212230287 Forwards P Sheumon B21213 ltr re ACRS rept on SEP Phase II review
CRUTCHFIELD, D Operating Reactors Branch 5 82/12/16 COUNCIL, W G
Northeast Nuclear Energy Co (subs of Northeast Utilities) 1p
16511 120 24X Fiche 50-245, 82/12/16, B212230287

--B212220544 Summarizes ACRS 272nd meeting on 82/12/09-11 re SEP review of facility
SHEUMON, P ACRS - Advisory Committee on Reactor Safeguards
82/12/13 PALLADINO, N J Commissioners 3pp 16511 121 24X
Fiche 50-245, 82/12/16, B212230287

P Operating license stage documents & correspondence

B211080257 Forwards four oversize drawings & info re reactor protection sys power monitoring sys design mod Proposed changes to Tech Specs will be submitted w/Cycle 9 reload package on 820901. Aperture cards are available in PDR
COUNCIL, W G, WERNER, R P Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNCIL, W G Northeast Utilities 82/08/18
CRUTCHFIELD, D Operating Reactors Branch 5 8pp 16002 217 24X
Fiche 50-245, 82/08/18, B211080257

B212140001 Addl response to FOIA request for five categories of documents re SEP Forwards documents listed in App A No documents located subj to Item 3 of request Review of remaining documents continuing Documents available in PDR
FELTON, J M Division of Rules and Records 82/11/03 GALLO, J
Isham, Lincoln & Beale 2pp 16433 354 24X Fiche 50-000, 82/11/03, B212140001

--B212200995 Notifies that review & performance of audit calculations to be continued per contract & preliminary review work to be completed at LaGrange Code used for reanalysis of piping sys requires benchmarking per code verification program
SHAO, L C Assistant Director for Engineering Programs 79/10/30
EISENHUT, D G Division of Operating Reactors 1p 16435 111 24X
Fiche 50-000, 82/11/03, B212140001

--B210220355 Forwards SEP info re slides for end-of-yr review of FY80 effort, info summarizing remaining SEP effort & preliminary structure spectra for facility
NELSON, T A Lawrence Livermore Laboratory 80/10/20 CHENG, T M
Systematic Evaluation Program Branch 28pp 16436 039 24X
Fiche 50-000, 82/11/03, B212140001

B212170321 Application to amend Licenses DPR-21 & DPR-65 by incorporating radiological effluent Tech Specs into safety Tech Specs
COUNCIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNCIL, W G Northeast Utilities 82/11/22
CLARK, R A Operating Reactors Branch 3 3pp 16453 280 24X
Fiche 50-245, 82/11/22, B212170321

--B212170322 Proposed radiological effluent Tech Specs for incorporation into safety Tech Specs
* Northeast Nuclear Energy Co (subs of Northeast Utilities)
82/11/30 11pp 16453 263 24X Fiche 50-245, 82/11/22, B212170321

--B212170323 Radiological effluent monitoring & offsite dose calculation manual
* Northeast Utilities 82/11/30 17pp 16454 037, 24X
Fiche 50-245, 82/11/22, B212170321

B212070286 Summarizes relative elevations of equipment in intake structure, in response to SEP Topic II-3 C, "Safety-Related Water Supply (UHS)" Sufficient redundancy would not preclude plant from achieving & maintaining safe shutdown
COUNCIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNCIL, W G Northeast Utilities 82/11/29
CRUTCHFIELD, D Operating Reactors Branch 5 3pp 16339 010 24X
Fiche 50-245, 82/11/29, B212070286

B212010100 INTEGRATED PLANT SAFETY ASSESSMENT SYSTEMATIC EVALUATION PROGRAM Millstone Nuclear Power Station, Unit 1 Docket No 50-245 (Northeast Nuclear Energy Company)
* Office of Nuclear Reactor Regulation, Director NUREG-0824 DRAFT
82/11/30 49pp 16292 001 24X Fiche 50-245, 82/11/30, B212010100

B212100277 Provides info to resolve concerns re ventilation stack failure to meet design basis criteria of SEP Topic III-2, "Wind & Tornado Loadings" Consequences of failure acceptable
COUNCIL, W G, CAGNETTA, J P, Northeast Nuclear Energy Co (subs of Northeast Utilities), COUNCIL, W G Northeast Utilities 82/12/03
CRUTCHFIELD, D Operating Reactors Branch 5 4pp 16377 097 24X
Fiche 50-245, 82/12/03, B212100277

B212170279 Forwards info re SEP Topics VI-7 A 3, "ECCS Actuation Sys" & IX-5, "Ventilation Sys" Supporting documentation of test procedures & results encl
COUNCIL, W G, CAGNETTA, J P Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNCIL, W G Northeast Utilities 82/12/03
CRUTCHFIELD, D Operating Reactors Branch 5 24pp 16461 158 24X
Fiche 50-245, 82/12/03, B212170279

B212170117 Discusses current status of segmented test rod bundle in light of GE rept of reconstitution activities at EDC-B, supplementing until 810520 & 821102 ltrs
COUNCIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 82/12/06 CRUTCHFIELD, D Operating Reactors Branch 5 3pp 16452 352 24X Fiche 50-245, 82/12/06, B212170117

B212150128 Forwards application for amend of Licenses DPR-21 & DPR-65, reflecting merger of CT Light & Power Co & Hartford Electric Co Class I & II fees encl
COUNCIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNCIL, W G Northeast Utilities 82/12/08
CLARK, R A Operating Reactors Branch 3 CRUTCHFIELD, D Operating Reactors Branch 5 2pp 16425 229 24X Fiche 50-245, 82/12/08, B212150128

--B212150142 Application for amend of Licenses DPR-21 & DPR-65, reflecting merger of CT Light & Power Co & Hartford Electric Co
* Northeast Nuclear Energy Co (subs of Northeast Utilities)
82/12/08 7pp 16425 231 24X Fiche 50-245, 82/12/08, B212150128

B212170199 Application to amend Licenses DPR-21 & DPR-65, reflecting merger of Hartford Electrical Light Co w/CT Light & Power Co
COUNCIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNCIL, W G Northeast Utilities 82/12/08
CLARK, R A Operating Reactors Branch 3 CRUTCHFIELD, D Operating Reactors Branch 5 9pp 16450 144 24X Fiche 50-245, 82/12/08, B212170199

B212200100 Forwards SER & nonproprietary & proprietary "Review of Licenses Resolution of Outstanding Issues From NRC Equipment Environ Qualification SERs (F-11, D-60)," Vols I & II, technical evaluation rept Proprietary rept withheld
CRUTCHFIELD, D Operating Reactors Branch 5 82/12/13 COUNCIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 11pp 16470 337 24X Fiche 50-245, 82/12/13, B212200100

--B207010396 "Review of Licensee Resolution of Outstanding Issues From NRC Equipment Environ Qualification Safety Evaluation Repts (F-11, D-60)," Vols I & II, technical evaluation rept
CRANE, C J Franklin Institute/Franklin Research Center NRC-03-79-118 TER-C5257-459 V01-02 82/05/28 LE, N B NRC - No Detailed Affiliation Given 779pp 16470 359 24X
Fiche 50-245, 82/12/13, B212200100

B212230287 Forwards P Sheumon B21213 ltr re ACRS rept on SEP Phase II review
CRUTCHFIELD, D Operating Reactors Branch 5 82/12/16 COUNCIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 1p 16511 120 24X Fiche 50-245, 82/12/16, B212230287

--B212220544 Summarizes ACRS 272nd meeting on 82/12/09-11 re SEP review of facility
SHEUMON, P ACRS - Advisory Committee on Reactor Safeguards
82/12/13 PALLADINO, N J Commissioners 3pp 16511 121 24X
Fiche 50-245, 82/12/16, B212230287

B212230305 Requests response to request for addl info re NUREG-0737, Item II D 1, "Safety Relief Valve Testing," within 90 days
CRUTCHFIELD, D Operating Reactors Branch 5 82/12/17 COUNCIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 3pp 16507 068 24X Fiche 50-245, 82/12/17, B212230305

B212270152 Notifies that mechanistic evaluation of discrete pipe break locations, in order to demonstrate Safety Factor 4 for normal operating load, will be completed in late 1983 w/mods implemented during 1984 outage
COUNCIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNCIL, W G Northeast Utilities 82/12/17
CRUTCHFIELD, D Operating Reactors Branch 5 1p 16538 342 24X
Fiche 50-245, 82/12/17, B212270152

B212290447 Forwards Teladyne Engineering Svcs "Mark I Containment Program Plant-Unique Analysis Rept of Torus Suppression Chamber for Millstone Point Unit 1," consisting of analysis summary & results & description of mods, per NUREG-0661
COUNCIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNCIL, W G Northeast Utilities 82/12/23
CRUTCHFIELD, D Operating Reactors Branch 5 1p 16584 328 24X
Fiche 50-245, 82/12/23, B212290447

DOCKETED ITEMS

41

--B212290452 "Mark I Containment Program Plant-Unique Analysis Rept of Torus Suppression Chamber for Millstone Point Unit 1," technical rept
* Teledyne Engineering Services TR-5318-1 R00 82/12/02
139pp 16584 330 24X Fiche 50-245, 82/12/23, 8212290447

G Inspection reports, IE Bulletins & correspondence

B208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 14662 163 24X Fiche 50-000, 82/10/28, 8208190240

G-08190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000, 82/11/05, 8208190245

B208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X Fiche 50-000, 82/11/18, 8208190251

B208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000, 82/11/26, 8208190256

B208190257 IE Info Notice 82-47, "Transportation of Type A Quantities or Non-Fissile Radioactive Matl " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000, 82/11/30, 8208190257

B212100071 Responds to 821028 IE Bulletin 82-03, Revision 1 re insp of large-diameter, stainless steel, recirculation sys piping
Action Item 4 re ultrasonic testing procedures addressed
Responses to Items 1-3 included w/821105 ltr Figures encl
COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL, W G Northeast Utilities 82/11/30
HAYNES, R C Region 1, Office of Director 13pp 16379 077 24X Fiche 50-245, 82/11/30, 8212100071

B208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259

D-08190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X Fiche 50-000, 82/12/03, 8208190261

G212140208 Ack receipt of 821119 ltr informing NRC of steps taken to re-examine nondestructive welds due to insp by unqualified technician
MARTIN, T T Division of Engineering & Technical Programs 82/12/09
COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 1p 16409 332 24X Fiche 50-245, 82/12/09, 8212140208

--G212140221 Responds to NRC 821102 ltr re resolution of nondestructive exam of welds All 13 welds re-examined w/no reportable indications
COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL, W G Northeast Utilities 82/11/19
HAYNES, R C Region 1, Office of Director 1p 16409 333 24X Fiche 50-245, 82/12/09, 8212140208

B208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16, 8208190267

B208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27 " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20, Consolidated Edison Co of New York, Inc 108pp 16628 293 24X Fiche 50-000, 82/12/20, 8208190268

R Periodic operating reports & related correspondence

B212290224 Forwards monthly operating rept for Oct 1982
MROCZKA, E J Northeast Nuclear Energy Co (subs of Northeast Utilities) MROCZKA, E J Northeast Utilities 82/11/09 Office of Resource Management, Director 1p 16578 057 24X Fiche 50-245, 82/11/09, 8212290224

--B212290229 Monthly operating rept for Oct 1982
HARRAN, O Northeast Nuclear Energy Co (subs of Northeast Utilities) 82/11/08 5pp 16578 058 24X Fiche 50-245, 82/11/09, 8212290224

S Reportable occurrences, LERs & related correspondence

G212030180 Forwards LER 82-029/031-0 Detailed event analysis encl
MROCZKA, E J Northeast Nuclear Energy Co (subs of Northeast Utilities) MROCZKA, E J Northeast Utilities 82/11/24
HAYNES, R C Region 1, Office of Director 2pp 16303 208 24X Fiche 50-245, 82/11/24, 8212030180

--B212030187 LER 82-025/031-0 on 821026, pressure switch 263-35C tripped above Tech Spec during reactor vessel high pressure functional & calibr test Caused by setpoint drift Switch reset & satisfactorily tested
THULL, T S Northeast Nuclear Energy Co (subs of Northeast Utilities) 82/11/24 Region 1, Office of Director 1p 16303 210 24X Fiche 50-245, 82/11/24, 8212030180

B212080445 Forwards LER 82-026/031-0 Detailed event analysis encl
MROCZKA, E J Northeast Nuclear Energy Co (subs of Northeast Utilities) MROCZKA, E J Northeast Utilities 82/12/03
HAYNES, R C Region 1, Office of Director 2pp 16352 168 24X Fiche 50-245, 82/12/03, 8212080445

--B212080453 LER 82-026/031-0 on 821104, steam tunnel temp switches 261-16A, 16B, 16D, 18B, 18C & 18D tripped above setpoint Caused by setpoint drift Switches adjusted to required setpoint
SCHWEIKERT-THUL Northeast Nuclear Energy Co (subs of Northeast Utilities) SCHWEIKERT-THUL Northeast Utilities 82/12/03
Region 1, Office of Director 1p 16352 170 24X Fiche 50-245, 82/12/03, 8212080445

B212160358 Forwards LER 82-027/031-0 Detailed event analysis encl
MROCZKA, E J Northeast Nuclear Energy Co (subs of Northeast Utilities) MROCZKA, E J Northeast Utilities 82/12/10
HAYNES, R C Region 1, Office of Director 3pp 16442 290 24X Fiche 50-245, 82/12/10, 8212160358

--B212160371 LER 82-027/031-0 on 821111, while performing automatic bleeddown logic test, automatic pressure relief relays timed out at 125-S & 123-B Caused by instrument setpoint drift due to high control room temp Setpoint reset & tested
THULL, T S Northeast Nuclear Energy Co (subs of Northeast Utilities) 82/12/10 Region 1, Office of Director 1p 16442 293 24X Fiche 50-245, 82/12/10, 8212160358

T Hearing transcripts on non-antitrust matters

B212020258 Transcript of ACRS Subcommittee on SEP 821130 meeting in Washington, DC Pp 1-297 Supporting documentation encl
* ACRS - Advisory Committee on Reactor Safeguards 82/11/30
359pp 16276 266 24X Fiche 50-000, 82/11/30, 8212020258

DOCKET 50-246 ADVANCED CRITICAL REACTOR EXPERIMENT

P Operating license stage documents & correspondence

B21230066 Generic Ltr 82-27 to all BWR licensees of operating reactors except LACBWR, Big Rock Point, Dresden 1, Humboldt Bay, applicants for DL & holders of CP re transmittal of NUREG-0763 & NUREG-0763 Svc list encl w/o stated encl
EISENHUT, D G Division of Licensing 82/11/15 General Public Utilities - GPU Service Corp 2rpp 16387 004 24X Fiche 50-000, 82/11/15, 821230066

DOCKET 50-247 INDIAN POINT STATION, UNIT 2

F Security, medical, emergency & fire protection plans

B210190499 Presents probabilistic safety study risk frequency & consequence data for proposed addition of seismic bumper for control bldg & transfer switches for alternate shutdown sys
O'TOOLE, J D Consolidated Edison Co of New York, Inc 82/10/08
VARONA, S A Operating Reactors Branch 1 12pp 15740 054 24X Fiche 50-247, 82/10/08, 8210190499

DOCKETED ITEMS

- 8210190510 "Indian Point Unit 2 Control Bldg Seismic Improvement Analysis"
NARVER, R B, WESLEY, D A Structural Mechanics Associates SMA
12701 03 82/08/31 80pp 15740 067 24X Fiche 50-247, 82/10/08.
8210190499
- 8212140353 Advises that util will conduct annual onsite drill of emergency plan on 821208 Alternate drill dates are 821201 & 15
O'TOOLE, J D Consolidated Edison Co of New York, Inc 82/11/09
HAYNES, R C Region 1, Office of Director 1p 16401 025 24X
Fiche 50-003, 82/11/09, 8212140353
- 8212030141 Forwards IE Safeguards Insp Rept 50-247/82-16 on 820726-30 & notice of violation Details & notice of violation withheld (ref 10CFR73 21)
MARTIN, T T Division of Engineering & Technical Programs 82/11/19
O'TOOLE, J D Consolidated Edison Co of New York, Inc 2pp
16306 021 24X Fiche 50-247, 82/11/19, 8212030141
- 8212030147 IE Safeguards Insp Rept 50-247/82-16 on 820726-30
Noncompliance noted failure to meet testing requirements for special purpose detectors & failure to meet security plan requirements Safeguards details withheld (ref 10CFR73 21)
BAILEY, R J, MADDEN, W, GODY, A T Region 1, Office of Director
82/11/19 7pp 16306 023 24X Fiche 50-247, 82/11/19, 8212030141
- 8212220006 Staff requirements memo re 821119 briefing by FEMA on status of emergency preparedness findings Conclusions re removal of deficiencies & overall adequacy of emergency plans will be submitted between 821203 & 17
CHILKIS, J Office of the Secretary of the Commission 82/11/24
Office of the Secretary of the Commission 1p 16529 151 24X
Fiche 50-003, 82/11/24, 8212220006
- 8212030124 Responds to 820902 ltr describing corrective actions re significant deficiencies identified in FEMA 820730 rept, "Interim Findings on Adequacy of Radiological Emergency Response Preparation of State & Local Govts"
HAYNES, R C Region 1, Office of Director 82/11/26 O'TOOLE, J D
Consolidated Edison Co of New York, Inc 2pp 16306 296 24X
Fiche 50-003, 82/11/26, 8212030124
- 8212030248 Forwards description of activities planned or underway to correct deficiencies identified in FEMA interim findings on adequacy of radiological emergency response preparedness of state & local govts, per 820803 request
O'TOOLE, J D Consolidated Edison Co of New York, Inc 82/09/02
HAYNES, R C Region 1, Office of Director 1pp 16306 298 24X
Fiche 50-003, 82/11/26, 8212030124
- 8212220037 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 82/12/13 Document
Management Branch 1p 16527 336 24X Fiche 50-003, 82/12/13, 8212220037
- 8212220042 Forwards public version of revised emergency plan implementing procedures, including Procedures IP-1001 re mobilization of onsite emergency organization & IP-1039 re offsite contamination checks
O'TOOLE, J D Consolidated Edison Co of New York, Inc 82/12/01
HAYNES, R C Region 1, Office of Director 1p 16527 337 24X
Fiche 50-003, 82/12/13, 8212220037
- 8212220046 Public version of revised emergency plan implementing procedures, including Procedures IP-1001 re mobilization of onsite emergency organization & IP-1039 re offsite contamination checks
FINCH, G L Consolidated Edison Co of New York, Inc 82/11/08
43pp 16527 338 24X Fiche 50-003, 82/12/13, 8212220037
- 8212270120 Forwards requested info re emergency operating facility (EDF) EDF located onsite in Buchanan svc ctr bldg approx: 2,000 ft from reactor bldg
O'TOOLE, J D Consolidated Edison Co of New York, Inc 82/12/15
VARGA, S A Operating Reactors Branch 1 3pp 16538 307 24X
Fiche 50-247, 82/12/15, 8212270120
- 8212210409 Forwards Event Notification Forms Part I & II to better prepare shift crews for questions NRC duty officer may ask during emergency notification
STAROSTECKI, R Division of Project & Resident Programs 82/12/16
O'TOOLE, J D Consolidated Edison Co of New York, Inc 6pp
16493 088 24X Fiche 50-003, 82/12/16, 8212210409
- 8212280084 Forwards FEMA 821217 ltr transmitting "Update Rept on Status of Remedial Actions Cited in 820730 Interim Findings on Adequacy of Radiological Emergency Response Preparation of State & Local Govts at Indian Point Nuclear Power Station"
HAYNES, R C Region 1, Office of Director 82/12/17 O'TOOLE, J D
Consolidated Edison Co of New York, Inc 2pp 16557 192 24X
Fiche 50-247, 82/12/17, 8212280084
- 8212280087 Forwards "Update Rept on Status of Remedial Actions Cited in 820730 Interim Findings on Adequacy of Radiological Emergency Response Preparation of State & Local Govts at Indian Point Nuclear Power Station"
THOMAS, L M Federal Emergency Management Agency 82/12/17
DIRCKS, W J Office of the Executive Director for Operations 3pp
16557 194 24X Fiche 50-247, 82/12/17, 8212280084
- 8212280092 "Update Rept on Status of Remedial Actions Cited in 820730 Interim Findings on Adequacy of Radiological Emergency Response Preparation of State & Local Govts at Indian Point Nuclear Power Station"
PETRONE, F P Federal Emergency Management Agency 82/12/16
52pp 16557 197 24X Fiche 50-247, 82/12/17, 8212280084
- 8212290295 Releases public version of page changes to emergency procedures document
FELTON, J M Division of Rules and Records 82/12/20 Document
Management Branch 1p 16606 086 24X Fiche 50-003, 82/12/20, 8212290295
- 8212290302 Forwards public version of page changes to emergency procedures document re determination of magnitude of release & effect on offsite personnel
O'TOOLE, J D Consolidated Edison Co of New York, Inc 82/12/08
HAYNES, R C Region 1, Office of Director 1p 16606 087 24X
Fiche 50-003, 82/12/20, 8212290295
- 8212290308 Public version of page changes to emergency procedures document re determination of magnitude of release & effect on offsite personnel One oversize drawing encl Aperture card is available in PDR
SMITH, H Consolidated Edison Co of New York, Inc 82/11/08
20pp 16606 089 24X Fiche 50-003, 82/12/20, 8212290295
- 8212270214 Decision CLI-82-38, ruling that no shutdown or enforcement action required re state of emergency planning FEMA determined that remedial action will be feasible Problems w/ local govts beyond licensee control
CHILKIS, J Office of the Secretary of the Commission 82/12/22
27pp 16537 128 24X Fiche 50-247, 82/12/22, 8212270214
- 0 Adjudicatory correspondence
- 8212070073 Forwards Director's Decision DD-82-12, denying 10CFR2 206 petition to suspend operation immediately until FEMA identified deficiencies corrected
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 WEISS, E R Public Interest Research Group, New York SHOLLY, S C Union of Concerned Scientists WEISS, E R
Harnon & Weiss 1p 16394 353 24X Fiche 50-247, 82/11/26, 8212070073
- 8212070081 Director's Decision DD-82-12, denying UCS & NY FIRC 820804 10CFR2 206 petition to suspend operation immediately until FEMA identified deficiencies corrected
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 8pp 16354 354 24X
Fiche 50-247, 82/11/26, 8212070073
- 8212020321 Order granting West Branch Conservation Assoc 821124 request for permission to file replies to licensee interrogatories on Contention 2 2a late Good cause shown
GLEASON, J P Atomic Safety and Licensing Board Panel 82/11/30
West Branch Conservation Association 2pp 16279 194 24X
Fiche 50-247, 82/11/30, 8212020321
- 8212070189 Motion for orders compelling discovery of utils re 820621 Interrogatories 1 - 11 & compelling NRC to produce documents on routine & unscheduled releases of radiation Certificate of Svc encl Related correspondence
RODRIGUEZ, P Parents Concerned About Indian Point 82/11/30
Atomic Safety and Licensing Board Panel 3pp 16335 128 24X
Fiche 50-247, 82/11/30, 8212070189
- 8212020318 Requests ASLB issue order modifying schedule in ASLB 821115 memorandum & order, rescheduling Westchester County testimony from 830103 to 830110 Time between filing of testimony & hearing commencement insufficient
MORGAN, C Power Authority of the State of New York BRANDENBURG, B
Consolidated Edison Co of New York, Inc MORGAN, C Morgan Associates 82/12/01. GLEASON, J P, SHON, F J, PARIS, D H Atomic Safety and Licensing Board Panel 2pp 16279 198 24X
Fiche 50-247, 82/12/01, 8212020318
- 8212060103 Motion to dismiss Contentions 2 (a) & (d) re filtered vented containments & separate containments respectively & 2 (b) re specific pressurized thermal shock responses W/Certificate of Svc
BRANDENBURG, B Consolidated Edison Co of New York, Inc MORGAN, C
Power Authority of the State of New York MORGAN, C Morgan Associates 82/12/01. Atomic Safety and Licensing Board Panel
10pp 16316 123 24X Fiche: 50-247, 82/12/01, 8212060103

DOCKETED ITEMS

43

B212060098 Response to interrogatories & document requests re Commission Questions 2 & 5 Related correspondence
SHOLLY, S C, BLUM, J M Union of Concerned Scientists BLUM, J M
New York Univ 82/12/02 Consolidated Edison Co of New York,
Inc 30pp 16316 133 24X Fiche 50-247, 82/12/02, 8212060098

B212060241 Memorandum & order granting Util 821201 request for postponement or hearing scheduled for wk of 830103 until wk of 830110 Parties presenting evidence concurring in request
GLEASON, J P Atomic Safety and Licensing Board Panel 82/12/02
Consolidated Edison Co of New York, Inc 2pp 16312 265 24X
Fiche 50-247, 82/12/02, 8212060241

B212060077 Response to 820716 first set of interrogatories & request for documents re Commission Questions 1 & 2
SHOLLY, S C, BLUM, J M Union of Concerned Scientists BLUM, J M
New York Univ 82/12/03 Office of the Executive Legal Director
14pp 16314 300 24X Fiche 50-247, 82/12/03, 8212060077

-B212060069 Notice of JF Meyer 821207 deposition in Bethesda, MD re filtered vented containment sys Certificate of Svc encl
BLUM, J M Union of Concerned Scientists BLUM, J M New York
Univ 82/12/03 5pp 16314 313 24X Fiche 50-247, 82/12/03,
8212060077

B212070246 Motion for mod of hearing schedule, delaying hearings until 820315 Hearing dates as scheduled conflict w/830308 emergency exercise Both NY State & Suffolk County witnesses will be engaged in exercise Certificate of Svc encl
FEINBERG, J D New York, State of, Energy Office 82/12/03
Atomic Safety and Licensing Board Panel 8pp 16329 284 24X
Fiche 50-247, 82/12/03, 8212070246

B212090087 Forwards three ads published in listed newspapers sponsored by utility informing of safe plant operation Info provided per ASLB oral directive at 820123 public hearing
BRANDENBURG, B Consolidated Edison Co of New York, Inc LEVIN, J J
Power Authority of the State of New York LEVIN, J J Morgan
Associates 82/12/03 GLEASON, J P, SHON, F J, PARIS, O H Atomic
Safety and Licensing Board Panel 5pp 16357 175 24X
Fiche 50-247, 82/12/03, 8212090087

B212230337 Urges that plants not return to svc until adequacy of emergency planning & preparedness guaranteed Worst case accident could result in many thousands of fatalities
RYAN, A B New York, NY 82/12/03 PALLADINO, N J, AHEARNE, J,
OILINSKY, V Commissioners 2pp 16305 132 24X
Fiche 50-247, 82/12/03, 8212230337

B212070209 Response in opposition to licensee 821201 motion to dismiss contentions Requirements arising under Contention 2 2(b) should be transferred to NRC & licensees Certificate of Svc encl
FLEISHER, Z S West Branch Conservation Association 82/12/04
Atomic Safety and Licensing Board Panel 3pp 16333 181 24X
Fiche 50-247, 82/12/04, 8212070209

B212070213 Motion to compel discovery of Con Ed re evaluation of hybrid closed cooling sys Matl requested for Contention 2 2(a)
Certificate of Svc encl Related correspondence
FLEISHER, Z S West Branch Conservation Association 82/12/04
Atomic Safety and Licensing Board Panel 2pp 16329 360 24X
Fiche 50-247, 82/12/04, 8212070213

B212080310 Supplemental response to first set of interrogatories & document requests on ASLB Questions 1, 2 & 3
COLARULLI, P F Power Authority of the State of New York
COLARULLI, P F Morgan Associates 82/12/06 Union of Concerned
Scientists 35pp 16354 010 24X Fiche 50-247, 82/12/06, 8212080310

B212090090 Adverse of attempted contact re W Fleisher deposition Utilis intend to take deposition next wk re Contention 2 2(a)
BRANDENBURG, B Consolidated Edison Co of New York, Inc
COLARULLI, P F Power Authority of the State of New York 82/12/06
FLEISHER, Z S West Branch Conservation Association 1p 16357 174
24X Fiche 50-247, 82/12/06, 8212090090

B212090101 Supplemental response to interrogatories on Commission Questions 1 & 2 Certificate of Svc encl
SHOLLY, S C, BLUM, J M Union of Concerned Scientists 82/12/07
Office of the Executive Legal Director 17pp 16357 284 24X
Fiche 50-247, 82/12/07, 8212090101

B212100103 Memorandum & order memorializing rulings of 821203 telcon Schedule for UCS, utilis & NRC modified as listed Deadline for notice of depositions of UCS witnesses for Question 1 to be negotiated
GLEASON, J P Atomic Safety and Licensing Board Panel 82/12/08
8pp 16379 105 24X Fiche 50-247, 82/12/08, 8212100103

B212140423 Responses opposing West Branch Conservation Assoc 821104 application for reinstatement of Contention 2 2(d) & Assoc 821104 objection to ASLB restatement of Contention 2 2(b)
Certificate of Svc encl
BRANDENBURG, B Consolidated Edison Co of New York, Inc MORGAN, C
Power Authority of the State of New York MORGAN, C Morgan
Associates 82/12/09 Atomic Safety and Licensing Board Panel
8pp 16404 199 24X Fiche 50-247, 82/12/09, 8212140423

B212150017 Answer objecting to State of NY motion for mod of hearing schedule Change in witness testimony schedule burdensome
Certificate of Svc encl
POSNER, P Parents Concerned About Indian Point 82/12/09 Atomic
Safety and Licensing Board Panel 1p 16421 180 24X
Fiche 50-247, 82/12/09, 8212150017

B212150022 Notice of concurrence w/Parents Concerned About Indian Point objection to State of NY motion to modify hearing schedule Further postponement of witness testimony unwarranted & burdensome to UCS/PIRO of NY & witnesses
HOLT, J Union of Concerned Scientists HOLT, J Public Interest
Research Group, New York 82/12/09 1p 16421 231 24X
Fiche 50-247, 82/12/09, 8212150022

B212130208 Order scheduling 830110 evidentiary hearing in White Plains, NY
GLEASON, J P Atomic Safety and Licensing Board Panel 82/12/10
1p 16397 015 24X Fiche 50-247, 82/12/10, 8212130208

B212130252 Forwards Westchester County 821205 ltr to Commissioner Palladino re offsite emergency preparedness to comply w/ex parte communications regulations
STUCKY, S W Docketing & Services Branch 82/12/10 Office of the
Executive Legal Director 1p 16396 230 24X Fiche 50-247,
82/12/10, 8212130252

--B212130254 Urges that facilities not be restarted until emergency response plans are fully workable & implementable State of emergency planning & preparedness in Westchester County still inadequate
DELBELLO, A B Westchester County, NY 82/12/05 PALLADINO, N J
Commissioners 12pp 16396 231 24X Fiche 50-247, 82/12/10,
8212130252

B212140242 Response in opposition to State of NY motion for mod of hearing schedule moving hearing commencement on Commission Questions 3 & 4 to 830315 Extension to 830314 for testimony on questions not opposed
KAPLAN, C New York, NY 82/12/10 Atomic Safety and Licensing
Board Panel 2pp 16409 304 24X Fiche 50-247, 82/12/10, 8212140242

B212140384 Notification of witnesses on Commission Question 2
BLUM, J M Union of Concerned Scientists 82/12/10 2pp
16404 320 24X Fiche 50-247, 82/12/10, 8212140384

--B212140393 Notice of deposition of NRC witnesses MR Denton, BH Hanauer, Rk Blond & FH Rowsome re testimony to be provided Denton & Hanauer will also be examined on decision criteria & process & CRAC & CRAC2 accident consequence codes
BLUM, J M Union of Concerned Scientists 82/12/10 2pp
16404 322 24X Fiche 50-247, 82/12/10, 8212140394

--B212140400 Notice of deposition of util witnesses DC Bley, BJ Garrick, B Kaplan & DC Richardson re probabilistic safety study
Certificate of Svc encl
BLUM, J M Union of Concerned Scientists 82/12/10 6pp
16404 323 24X Fiche 50-247, 82/12/10, 8212140384

B212140439 Motion for leave to file encl reply to West Branch Conservation Assoc 821204 reply to licensee 821201 motion to dismiss certain contentions If Assoc had participated in telcon, utilis would have orally replied
BRANDENBURG, B Consolidated Edison Co of New York, Inc LEVIN, J J
Power Authority of the State of New York LEVIN, J J Morgan
Associates 82/12/10 Atomic Safety and Licensing Board Panel
2pp 16405 249 24X Fiche 50-247, 82/12/10, 8212140439

-B212140446 Reply to West Branch Conservation Assoc 821204 reply to licensee 821201 motion to dismiss certain contentions Assoc misconstrues Commission intent in establishing proceeding Contention 2 2(b) should be struck w/Certificate of Svc
BRANDENBURG, B Consolidated Edison Co of New York, Inc
LEVIN, J J Power Authority of the State of New York LEVIN, J J
Morgan Associates 82/12/10 Atomic Safety and Licensing Board
Panel 7pp 16405 251 24X Fiche 50-247, 82/12/10, 8212140439

B212140451 Forwards Rockland County resolution calling for closing of plants for failure to remedy emergency planning deficiencies by expiration of 120-day clock
THORSEN, E O Rockland County, NY 82/12/10 PALLADINO, N J
Commissioners 3pp 16404 355 24X Fiche 50-247, 82/12/10,
8212140451

DOCKETED ITEMS

- 8212160289 Notice of I. Levi, D. Pisello & R. Piccioni 821229 depositions in NY, NY re testimony on Commission Question 1 Certificate of Svc encl Related correspondence
BRANDENBURG, B Consolidated Edison Co of New York, Inc MORGAN, C Power Authority of the State of New York MORGAN, C Morgan Associates 82/12/10 6pp 16446 068 24X Fiche 50-247, 82/12/10, 8212160289
- 8212150116 Response to licensee 821201 motion to dismiss Contentions 2 1(a), 2 1(d) & 2 2(b) Supports dismissal of Contention 2 2(b) West Branch Conservation Assoc filings show that Assoc will not pursue issue Certificate of Svc encl
MOORE, J E Hearing Branch 1 82/12/13 Atomic Safety and Licensing Board Panel 8pp 16427 351 24X Fiche 50-247, 82/12/13, 8212150116
- 8212200032 Qualifications statements for UCS/NY PIRQ witnesses on Commission Question 2 Prof qualifications & Certificate of Svc encl
BLUM, J M Union of Concerned Scientists 82/12/13 11pp 16473 391 24X Fiche 50-247, 82/12/13, 8212200032
- 8212170169 Advises that NRC does not intend to seek authorization to reply to West Branch Conservation Assoc 821224 objections to reinstatement of Contention 2 2(b) No new arguments raised
MOORE, J E Hearing Branch 1 82/12/14 OLEASON, J P, PARIS, O H, SHON, F J Atomic Safety and Licensing Board Panel 1p 16450 221 24X Fiche 50-247, 82/12/14, 8212170169
- 8212160375 Order requesting ASLB provide recommendations called for in CLT-81-23 no later than 830729
CHILK, S J Office of the Secretary of the Commission 82/12/15 Atomic Safety and Licensing Board Panel 1p 16442 341 24X Fiche 50-247, 82/12/15, 8212160375
- 8212170174 Response to Parents Concerned About Indian Point 821130 motion to compel discovery against utility & response opposing Parents request to file new document request on NRC Protective order requested Certificate of Svc encl
MCQUARRIE, H J Hearing Branch 1 82/12/15 Atomic Safety and Licensing Board Panel 5pp 16450 163 24X Fiche 50-247, 82/12/15, 8212170174
- 8212200097 Memorandum & order granting NRC motion for protective order re answer to UCS/NY PIRQ Interrogatory 5 NRC is not required to compile list of NRC criticisms of plant probabilistic safety study nor to formulate position
OLEASON, J P Atomic Safety and Licensing Board Panel 82/12/15 Office of the Executive Legal Director 2pp 16470 140 24X Fiche 50-247, 82/12/15, 8212200097
- 8212220293 Reply opposing licensee 821210 motion for leave to file reply to West Branch Conservation Assoc response to licensee 821201 motion Licensee is harassing Assoc Certificate of Svc encl
FLEISHER, Z S West Branch Conservation Association 82/12/15 Atomic Safety and Licensing Board Panel 3pp 16517 188 24X Fiche 50-247, 82/12/15, 8212220293
- 8212220220 Advises that M. Kaminski inadvertently omitted from amended witness lists Order of witnesses listed Related correspondence
VETERE, L A Westchester County, NY 82/12/16 OLEASON, J P, PARIS, O H, SHON, F J Atomic Safety and Licensing Board Panel 1p 16503 001 24X Fiche 50-247, 82/12/16, 8212220220
- 8212220226 Response to State of NY motion to modify hearing schedule Unnecessary to delay testimony of all other available witnesses until County & State witnesses available Certificate of Svc encl
VETERE, L A Westchester County, NY 82/12/16 Atomic Safety and Licensing Board Panel 2pp 16503 002 24X Fiche 50-247, 82/12/16, 8212220226
- 8212230261 Urges plants not be reopened until emergency preparedness plans adequate
BIALIK, E I New York, State of 82/12/16 PALLADINO, N Commissioners 1p 16508 188 24X Fiche 50-247, 82/12/16, 8212230261
- 8212230331 Forwards 821213 ltr inadvertently sent to J Hendrie Attendance at 830110 evidentiary hearing requested
MANTELL, A N Affiliation Unknown 82/12/16 PALLADINO, N Commissioners 1p 16505 157 24X Fiche 50-247, 82/12/16, 8212230331
- 8212230336 Ack receipt of 821210 invitation to attend evidentiary hearing in White Plains, NY Attendance certain unless accident postpones hearing
MANTELL, A N Affiliation Unknown 82/12/16 HENDRIE, J Atomic Safety and Licensing Board Panel 1p 16505 158 24X Fiche 50-247, 82/12/16, 8212230336
- 8212210235 Memorandum & order memorializing 821215 & 16 telcons & dismissing Parents Concerned About Indian Point & West Branch Conservation Assoc 821130 & 1204 discovery motions
PARIS, O H Atomic Safety and Licensing Board Panel 82/12/17 Parents Concerned About Indian Point 2pp 16484 234 24X Fiche 50-247, 82/12/17, 8212210235
- 8212210238 Supplementation of interrogatory response, naming Question 1 witnesses Certificate of Svc encl
BLUM, J M Union of Concerned Scientists 82/12/17 5pp 16484 236 24X Fiche 50-247, 82/12/17, 8212210238
- 8212210320 Forwards Congressman RL Ottinger 821201 ltr to utility seeking testimony before Congress re investigation Until 821203 response encl
LEVIN, J J Morgan Associates 82/12/17 PALLADINO, N J, AHEARNE, J F, GILINSKY, V Commissioners 6pp 16496 246 24X Fiche 50-247, 82/12/17, 8212210320
- 8212220246 Supplemental response to first set of interrogatories & document requests under Commission Question 1 Prof qualifications encl Related correspondence
HARTZMAN, R M Friends of the Earth HARTZMAN, R M New York City Audubon Society 82/12/17 Consolidated Edison Co of New York, Inc 2pp 16518 280 24X Fiche 50-247, 82/12/17, 8212220246
- 8212220271 Responses to interrogatories & document requests re Commission Question 6 Certificate of Svc encl
BRANDENBURG, B Consolidated Edison Co of New York, Inc PRATT, C M Power Authority of the State of New York PRATT, C M Morgan Associates 82/12/17 Parents Concerned About Indian Point 15pp 16517 280 24X Fiche 50-247, 82/12/17, 8212220271
- 8212230187 Response to motion to compel discovery re Commission Question & Certificate of Svc encl Related correspondence
BRANDENBURG, B Consolidated Edison Co of New York, Inc PRATT, C M Power Authority of the State of New York PRATT, C M Morgan Associates 82/12/17 Parents Concerned About Indian Point 14pp 16511 007 24X Fiche 50-247, 82/12/17, 8212230187
- 8212230235 Urges that units not be returned to svc until emergency planning concerns resolved
BRODSKY, R L Westchester County, NY DE MARCO, J W, HOCHBERG, A O Commissioners 82/12/17 PALLADINO, N J, AHEARNE, J F, GILINSKY, V Commissioners 3pp 16511 060 24X Fiche 50-247, 82/12/17, 8212230235
- 8212280014 Lists documents being withheld as privileged that were requested by SC Sholly (UCS) in UCS/NY PIRQ first set of interrogatories & document requests on Commission Questions 1, 2 & 5 NUREG/CR-2666 forthcoming
MCQUARRIE, H J Hearing Branch 1 82/12/17 BLUM, J M New York Univ 2pp 16564 290 24X Fiche 50-247, 82/12/17, 8212280014
- 8212280285 Response in opposition to State of NY motion for mod of hearing schedule Since motion relates to scheduling of testimony within allotted time frame, no further hearing delay necessary Certificate of Svc encl
MORGAN, C Power Authority of the State of New York MORGAN, C Morgan Associates 82/12/17 Atomic Safety and Licensing Board Panel 7pp 16561 327 24X Fiche 50-247, 82/12/17, 8212280285
- 8212210267 Response in support of State of NY 821203 motion for mod of schedule for hearing testimony on Commission Questions 3 & 4 Extension needed in order for witnesses to participate in emergency planning exercises Certificate of Svc encl
MOORE, J E Hearing Branch 1 82/12/20 Atomic Safety and Licensing Board Panel 5pp 16489 170 24X Fiche 50-247, 82/12/20, 8212210267
- 8212210332 Response opposing Con Ed 821215 mailgram requesting ASLB to grant previously filed motion to dismiss Contentions 2 1(a) & 2 1(d) Prejudice caused by UCS/NY PIRQ tardiness not equal to requested sanctions Certificate of Svc encl
MOORE, J E Hearing Branch 1 82/12/20 Atomic Safety and Licensing Board Panel 7pp 16497 013 24X Fiche 50-247, 82/12/20, 8212210332
- 8212220398 Memorandum supporting Con Ed 821215 renewed motion to dismiss UCS/NY PIRQ Contentions 2 1(a) & 2 1(d) UCS continues to act immune from orders of ASLB, notwithstanding Judge Paris admonition Certificate of Svc encl
MORGAN, C Power Authority of the State of New York MORGAN, C Morgan Associates 82/12/20 Atomic Safety and Licensing Board Panel 9pp 16503 223 24X Fiche 50-247, 82/12/20, 8212220398
- 8212230241 Strongly urges that units not be returned to svc until emergency planning concerns resolved
STEINGUT, R, STERN, H J, GREITZER, C New York, NY 82/12/20 PALLADINO, N J, AHEARNE, J F, GILINSKY, V Commissioners 11pp 16508 145 24X Fiche 50-247, 82/12/20, 8212230241

DOCKETED ITEMS

45

B212230270 Urges plants not be restarted until workable emergency plan implemented
FINN, S New York, NY 82/12/20 PALLADINO, N J Commissioners
2pp 16907 358 24X Fiche 50-247, 82/12/20, 8212230270

B212280293 Response in opposition to State of NY motion for mod of hearing schedule State did not meet heavy burden of persuasion required to extend hearings Certificate of Svc uncl
BRANDENBURG, B Consolidated Edison Co of New York, Inc 82/12/20
Atomic Safety and Licensing Board Panel 6pp 16562 067 24X
Fiche 50-247, 82/12/20, 8212280293

B212230181 Memorandum & order granting licensee B21210 motion to reply to West Branch Conservation Assoc (WBCA) reply to util
B21201 motion to dismiss contentions Util B21201 motion to dismiss also granted WBCA motion for reinstatement denied
GLEASON, J P, SHON, F J Atomic Safety and Licensing Board Panel
82/12/21 Consolidated Edison Co of New York, Inc 7pp
16510 230 24X Fiche 50-247, 82/12/21, 8212230181

B212230188 Memorandum & order granting Parents Concerned About Indian Point B21130 request to place specified documents issued by NRC prior to 1979 into LPDR
GLEASON, J P Atomic Safety and Licensing Board Panel 82/12/21
Parents Concerned About Indian Point 6pp 16511 106 24X
Fiche 50-247, 82/12/21, 8212230188

B212230358 Order extending time, until 821229, for Commission to decide whether to review IE Director B21126 denial of UCS request for action filed under 10CFR2 206
CHILK, S J Office of the Secretary of the Commission 82/12/21
1p 16511 161 24X Fiche 50-247, 82/12/21, 8212230358

B212230228 Urges FEMA update rept be given consideration in decision to reopen facilities Large number of emergency deficiencies still remain
WENZEL, J S Affiliation Unknown 82/12/22 PALLADINO, N J, AHEARNE, J F, ASSELSTINE, J K Commissioners 15pp 16511 032 24X
Fiche 50-247, 82/12/22, 8212230228

B212270214 Decision CLI-82-38, ruling that no shutdown or enforcement action required re state of emergency planning FEMA determined that remedial action will be feasible Problems w/ local govts beyond licensee control
CHILK, S J Office of the Secretary of the Commission 82/12/22
27pp 16537 128 24X Fiche 50-247, 82/12/22, 8212270214

B212280008 Forwards FEMA B21217 ltr to Ofc of Executive Director for Operations re current status of offsite emergency planning transmitting update rept w/o encl
HASSELL, D F Hearing Branch 1 82/12/22 GLEASON, J P, SHON, F J, PARIS, D H Atomic Safety and Licensing Board Panel 1p 16564 289
24X Fiche 50-247, 82/12/22, 8212280008

B212280011 Advises that invoice for copying documents requested by SC Shelly on 821214 forthcoming
MOORE, J E Hearing Branch 1 82/12/22 WEISS, E R Harmon & Weiss
1p 16565 144 24X Fiche 50-247, 82/12/22, 8212280011

B212270249 Order CLI-82-41, granting in part & denying in part, UCS B21008 motion to direct NRC to reschedule meeting All parties must be informed of scheduling of meetings
CHILK, S J Office of the Secretary of the Commission 82/12/23
Union of Concerned Scientists 3pp 16530 357 24X
Fiche 50-247, 82/12/23, 8212270249

B212300012 Memorandum & order dismissing West Branch Conservation Assoc B21215 motion to deny licensee motion for leave to reply licensee motion granted, rendering instant motion moot
GLEASON, J P Atomic Safety and Licensing Board Panel 82/12/23
West Branch Conservation Association 2pp 16598 227 24X
Fiche 50-247, 82/12/23, 8212300012

B212300014 Memorandum & order denying licensee B21201 motion & B21215 renewed motion to dismiss Contentions 2 1(a) & 2 1(d) UCS failure to meet B21210 deadline minor since delay did not prejudice parties
GLEASON, J P Atomic Safety and Licensing Board Panel 82/12/23
Consolidated Edison Co of New York, Inc 6pp 16598 218 24X
Fiche 50-247, 82/12/23, 8212300014

B212280326 Forwards revised Page 3 to NRC Order CLI-82-41 & separate view of Commissioner Roberts
STUCKY, S W Docketing & Services Branch 82/12/27 Power
Authority of the State of New York 1p 16562 084 24X
Fiche 50-247, 82/12/27, 8212280326

--B212280332 Corrected Page 3 to NRC Order CLI-82-41 & separate view of Commissioner Roberts
CHILK, S J Office of the Secretary of the Commission 82/12/23
Union of Concerned Scientists 2pp 16562 085 24X
Fiche 50-247, 82/12/27, 8212280332

B212300191 Ack receipt of summary of Steam Generator Owners Group B20729 meeting Request being filed for delay in delivering testimony on Question 2 2 1 in order to obtain previously inaccessible info
FLEISHER, Z S West Branch Conservation Association 82/12/27
MOORE, J Hearing Branch 1 1p 16598 023 24X
Fiche 50-247, 82/12/27, 8212300191

B212300197 Notice of continuation of Contentions 3 & 4
FLEISHER, Z S West Branch Conservation Association 82/12/27 1p
16598 024 24X Fiche 50-247, 82/12/27, 8212300197

--B212300201 Request for delay in filing testimony on Question 2 1 1 until 830112 in order to obtain addi info Certificate of Svc encl
FLEISHER, Z S West Branch Conservation Association 82/12/27
Atomic Safety and Licensing Board Panel 2pp 16598 025 24X
Fiche 50-247, 82/12/27, 8212300197

B212300230 Motion for expedited order compelling continuation of OR Thompson & SC Shelly depositions as witnesses on Contentions 2 1(a) & 2 1(d) Witness testimony incomplete Certificate of Svc encl
BRANDENBURG, B Consolidated Edison Co of New York, Inc
MORGAN, C M Power Authority of the State of New York MORGAN, C M Morgan Associates 82/12/28 Atomic Safety and Licensing Board Panel 14pp 16598 004 24X Fiche 50-247, 82/12/28, 8212300230

I General correspondence

B212230323 Forwards Rockland County Resolution 796 calling for closing of plants for Failure to remedy emergency planning deficiencies
SEIGERMAN, V K Rockland County, NY 82/12/13 PALLADINO, N Commissioners 2pp 16505 134 24X Fiche 50-247, 82/12/13, 8212230323

B212270428 Responds to B21130 ltr forwarding constituent concern re temporary suspension of hearings Approx 10 wks of hearings beginning 830110 scheduled
DIRKS, W J Office of the Executive Director for Operations 82/12/20 BRADLEY, B Senate 2pp 16568 339 24X
Fiche 50-003, 82/12/20, 8212270428

--B212270431 Forwards DK & FL Cinquemani B20730 ltr requesting resumption of hearings on safety of plants
BRADLEY, B Senate 82/11/30 Office of Congressional Affairs
5pp 16568 341 24X Fiche 50-003, 82/12/20, 8212270428

D Advisory Committee on Reactor Safeguards reports & correspondence

B212070077 Forwards "Review of Indian Point Probabilistic Safety Study"
AVERY, R Argonne National Laboratory 82/10/20 OKRENT, D ACRS - Advisory Committee on Reactor Safeguards OKRENT, D California, Univ of, Los Angeles 1p 16354 320 24X Fiche 50-247, 82/10/20, 8212070077

--B212070083 "Review of Indian Point Probabilistic Safety Study"
AVERY, R, CHO, D H, DEITRICH, L W Argonne National Laboratory 82/09/30 ACRS - Advisory Committee on Reactor Safeguards 30pp 16354 321 24X Fiche 50-247, 82/10/20, 8212070077

P Operating license stage documents & correspondence

B212030257 Forwards request for addi info to complete post-implementation review of NUREG-0737, Items II F 1 4, II F 1 5 & II F 1 6 re containment monitors Response within 30 days requested
VARGA, S A Operating Reactors Branch 1 82/11/18 O'TOOLE, J D Consolidated Edison Co of New York, Inc 10pp 16317 314 24X
Fiche 50-247, 82/11/18, 8212030257

B212090205 Forwards response to B21027 ltr re draft BNWL analysis of liquid pathway consequences due to basement penetration as presented in Indian Point probabilistic safety study
BAYNE, J P Power Authority of the State of New York O'TOOLE, J D Consolidated Edison Co of New York, Inc 82/11/29 VARGA, S A Operating Reactors Branch 1 14pp 16362 346 24X
Fiche 50-247, 82/11/29, 8212090205

B212070285 Notifies that radiological effluent Tech Specs & offsite dose calculation manual will be submitted by 830201 & 0401, respectively
O'TOOLE, J D Consolidated Edison Co of New York, Inc 82/12/01
VARGA, S A Operating Reactors Branch 1 1p 16339 113 24X
Fiche 50-003, 82/12/01, 8212070285

DOCKETED ITEMS

BP12080569 Advises that review of util evaluation of design differences per 800509 & 820527 ltr complete Design acceptable per 800211 confirmatory order Updated evaluation of differences between Units 2 & 3 encl
VARQA, S A Operating Reactors Branch 1 82/12/01 O'TOOLE, T D
Consolidated Edison Co of New York, Inc 13pp 16368 337 24X
Fiche 50-247, 82/12/01, 8212080569

BP12130030 Requests review of Unit 3 technical evaluation rept re seismic qualification of auxiliary feedwater sys Apparent discrepancies between Units 2 & 3 should be addressed
VARQA, S A Operating Reactors Branch 1 82/12/02 O'TOOLE, J D
Consolidated Edison Co of New York, Inc 2pp 16417 051 24X
Fiche 50-247, 82/12/02, 8212130030

BP12130232 Forwards analyses of control room ceilings w/fragility of ceiling structures & effects of failure on core melt frequency due to seismic events, in fulfillment of 821013 commitment re probabilistic safety study
YANKEE, J P Power Authority of the State of New York O'TOOLE, J D
Consolidated Edison Co of New York, Inc 82/12/06 Operating Reactors Branch 1 7pp 16390 134 24X Fiche 50-247, 82/12/06, 8212130232

BP12130288 Forwards further details re gas turbine operation Continued satisfactory gas turbine operation in future will confirm usefulness of gas turbine reliability improvements
O'TOOLE, J D Consolidated Edison Co of New York, Inc 82/12/06
VARQA, S A Operating Reactors Branch 1 3pp 16389 316 24X
Fiche 50-247, 82/12/06, 8212130288

BP208190263 Generic Ltr 82-32 to all PWR licensees re potential steam generator-related generic requirements Forwards Science Applications, Inc draft rept re subj requirements Comments requested within 30 days of ltr Svc list encl
EISENHUT, D O Division of Licensing 82/12/09 Consolidated Edison Co of New York, Inc 29pp 16629 247 24X
Fiche 50-000, 82/12/09, 8208190263

BP12140103 Generic Ltr 82-28 to all licensees of operating Westinghouse & G-E PWRs (except Arkansas Nuclear One, Unit 2 & San Onofre 2 & 3) re inadequate core cooling instrumentation sys Svc list encl
EISENHUT, D O Division of Licensing 82/12/10 Yankee Atomic Electric Co 27pp 16690 035 24X Fiche 50-000, 82/12/10, 8212140103

BP12270108 Forwards Amends 31 & 82 to Licenses DPR-5 & DPR-26, respectively, safety evaluation & notice of issuance & availability Amends modify facility organization structure & testing requirements on containment isolation valves
HANNOON, J N Operating Reactors Branch 1 82/12/11 O'TOOLE, J D
Consolidated Edison Co of New York, Inc 4pp 16593 200 24X
Fiche 50-003, 82/12/11, 8212270108

--BP12270111 Amends 31 & 82 to Licenses DPR-5 & DPR-26, respectively, modifying facility organization structure for Units 1 & 2 & testing requirements on containment isolation valves & snubber Tech Specs for Unit 2
VARQA, S A Operating Reactors Branch 1 82/12/11 39pp 16593 204 24X Fiche 50-003, 82/12/11, 8212270108

--BP12270113 Safety evaluation supporting Amends 31 & 82 to Licenses DPR-5 & DPR-26, respectively
Office of Nuclear Reactor Regulation, Director 82/12/11 4pp 16593 243 24X Fiche 50-003, 82/12/11, 8212270108

--BP12270117 Notice of issuance & availability of Amends 31 & 82 to Licenses DPR-5 & DPR-26, respectively
VARQA, S A Operating Reactors Branch 1 82/12/11 2pp 16593 247 24X Fiche 50-003, 82/12/11, 8212270108

BP12280364 Forwards current status of actions taken on probabilistic safety study Results of evaluation of soil/backfill containment bldg interaction expected in Spring 1983
O'TOOLE, J D Consolidated Edison Co of New York, Inc 82/12/14
VARQA, S A Operating Reactors Branch 1 2pp 16560 072 24X
Fiche 50-247, 82/12/14, 8212280364

BP12280237 Forwards application for amend to License DPR-26, adding Tech Specs 3 14 & 4 17 to establish limiting conditions for operation & surveillance requirements for severe hurricane condition Affidavit of Svc & Class III fee encl
O'TOOLE, J D Consolidated Edison Co of New York, Inc 82/12/17
VARQA, S A Operating Reactors Branch 1 2pp 16561 207 24X
Fiche 50-247, 82/12/17, 8212280237

--BP12280243 Application for amend to License DPR-26, adding Tech Specs 3 14 & 4 17 to establish limiting conditions for operation & surveillance requirements for severe hurricane condition
O'TOOLE, J D Consolidated Edison Co of New York, Inc 82/12/17 2pp 16561 209 24X Fiche 50-247, 82/12/17, 8212280237

--BP12280248 Proposed Tech Specs 3 14 & 4 17, establishing limiting conditions for operation & surveillance requirements for severe hurricane condition Safety assessment encl
Consolidated Edison Co of New York, Inc 82/12/31 6pp 16561 211 24X Fiche 50-247, 82/12/17, 8212280237

BP12300273 Forwards status of plant mods w/estimated date of completion, per NUREG-0737, Items II B 3, II F 1, III A 1 2 & III D 3 4 Administrative procedures revised per Generic Ltr 82-12
O'TOOLE, J D Consolidated Edison Co of New York, Inc 82/12/23
VARQA, S A Operating Reactors Branch 1 3pp 16595 247 24X
Fiche 50-247, 82/12/23, 8212300273

BP12300352 Responds to NRC 821118 ltr requesting addl info re NUREG-0737, Items II F 1 4, 5 & 6 re containment pressure, water level & hydrogen monitors, respectively Info to be submitted on or before 830501
O'TOOLE, J D Consolidated Edison Co of New York, Inc 82/12/23
VARQA, S A Operating Reactors Branch 1 1p 16594 222 24X
Fiche 50-247, 82/12/23, 8212300352

0 Inspection reports, IE Bulletins & correspondence

BP08190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel Recirculation Sys Piping at BWR Plants " Svc list encl
DEVOUNO, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 14462 163 24X Fiche 50-000, 82/10/28, 8208190240

BP08190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000, 82/11/05, 8208190245

BP08190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X
Fiche 50-000, 82/11/18, 8208190251

BP12030141 Forwards IE Safeguards Insp Rept 50-247/82-16 on 820726-30 & notice of violation Details & notice of violation withheld (ref 10CFR73 21)
MARTIN, T T Division of Engineering & Technical Programs 82/11/19
O'TOOLE, J D Consolidated Edison Co of New York, Inc 2pp 16305 021 24X Fiche 50-247, 82/11/19, 8212030141

--BP12030147 IE Safeguards Insp Rept 50-247/82-16 on 820726-30 Noncompliance noted failure to meet testing requirements for special purpose detectors & failure to meet security plan requirements Safeguards details withheld (ref 10CFR73 21)
BUTLEY, R J, MADDEN, W, GODY, A T Region I, Office of Director 82/11/19 7pp 16306 023 24X Fiche 50-247, 82/11/19, 8212030141

BP12060235 Forwards IE Insp Rept 50-247/82-22 on 821019-22 No noncompliance noted
MARTIN, T T Division of Engineering & Technical Programs 82/11/22
O'TOOLE, J D Consolidated Edison Co of New York, Inc 2pp 16312 180 24X Fiche 50-247, 82/11/22, 8212060235

--BP12060237 IE Insp Rept 50-247/82-22 on 821019-22 No noncompliance noted Major areas inspected inservice testing surveillance program for pumps & valves
REKUTO, W A, BETTENHAUSEN, L Division of Engineering & Technical Programs 82/11/17 8pp 16312 182 24X Fiche 50-247, 82/11/22, 8212060235

BP08190256 IE Info Notice 82-46, "Defective & Obsolete Combination Radiacks " Svc list encl
DEVOUNO, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000, 82/11/26, 8208190256

BP12070296 Forwards response to 821004 request for addl info re IE Bulletin 80-04, "PWR Main Steam Line Break W/Continued Feedwater Addition " No single failure will preclude main feedwater isolation under design basis steam line break
O'TOOLE, J D Consolidated Edison Co of New York, Inc 82/11/29
VARQA, S A Operating Reactors Branch 1 5pp 16339 066 24X
Fiche 50-247, 82/11/29, 8212070296

BP12140137 Forwards IE Insp Rept 50-247/82-20 on 821001-31 No noncompliance noted
STAROBTECKI, R Division of Project & Resident Programs 82/11/29
O'TOOLE, J D Consolidated Edison Co of New York, Inc 2pp 16408 181 24X Fiche 50-247, 82/11/29, 8212140137

--B212140140 IE Insp Rept 50-247/82-20 on B21001-31 No noncompliance noted Major areas inspected licensee actions on previous items, operational safety verification, plant tours, facility maint, surveillance observations & refueling activities
FOLEY, T., KOLTAJAY, P., REBELCWSKI, T. Division of Project & Resident Programs 82/11/24 16pp 16408 163 24X Fiche 50-247, 82/11/29, 8212140137

B-08190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl." Svc list encl
COBB, L. I. Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co. of New York, Inc 356pp 16387 028 24X Fiche 50-000, 82/11/30, 8208190257

B-08190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies." Svc list encl
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co. of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259

B-08190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets." Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co. of New York, Inc 110pp 16462 064 24X Fiche 50-000, 82/12/03, 8208190261

B-212170170 EN-82-039 on B21216, notice of violation & notice of proposed imposition of civil penalties to be issued Action based on alleged noncompliance re radiological surveys, degradation of security & operability of boron tank
ROSAND, R., FLACK, E., AXELRAD, J. Director's Office, Office of Inspection and Enforcement 82/12/13 1p 16450 140 24X Fiche 50-247, 82/12/13, 8212170170

B-08190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring." Svc list encl
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co. of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16, 8208190267

B212220366 Forwards list of topic areas for discussion at upcoming meeting on drug & alcohol abuse programs instituted per IE Info Notice 82-05 One util representative should be available to participate in entire meeting
STAROSTECKI, R. Division of Project & Resident Programs 82/12/16 O'TOOLE, J. D. Consolidated Edison Co. of New York, Inc 3pp 16517 173 24X Fiche 50-003, 82/12/16, 8212220366

B-08190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27." Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co. of New York, Inc 108pp 16628 293 24X Fiche 50-000, 82/12/20, 8208190268

B-212270358 Act receipt of B21018 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-247/82-18
STAROSTECKI, R. Division of Project & Resident Programs 82/12/20 O'TOOLE, J. D. Consolidated Edison Co. of New York, Inc 2pp 16530 049 24X Fiche 50-247, 82/12/20, 8212270358

- B212270361 Responds to NRC B20917 ltr re violations noted in IE Insp Rept 50-247/82-18 Corrective actions Temporary Procedure Change TPC-82-101 issued to resolve discrepancy between Procedure A-26 & Tech Spec Section 3.6A
O'TOOLE, J. D. Consolidated Edison Co. of New York, Inc 82/10/18 STAROSTECKI, R. Division of Project & Resident Programs 4pp 16530 091 24X Fiche 50-247, 82/12/20, 8212270358

R Periodic operating reports & related correspondence

B-12280219 Forwards monthly operating rept for Nov 1982 & update on refueling info per Hartfield 780118 request
O'TOOLE, J. D. Consolidated Edison Co. of New York, Inc 82/12/15 MCDONALD, W. O. Office of Resource Management, Director 1p 16562 126 24X Fiche 50-247, 82/12/15, 8212280219

--B212280221 Monthly operating rept for Nov 1982 Refueling info encl
EICH, E. Consolidated Edison Co. of New York, Inc 82/12/02 8pp 16562 127 24X Fiche 50-247, 82/12/15, 8212280219

S Reportable occurrences, LERs & related correspondence

B212060146 Forwards LER 82-045/01T-0
O'TOOLE, J. D. Consolidated Edison Co. of New York, Inc 82/11/22 HAYNES, R. C. Region 1, Office of Director 1p 16313 152 24X Fiche 50-247, 82/11/22, 8212060146

--B212060152 LER 82-045/01T-0 on B21108, upper end plug from one fuel rod within assembly F-44 separated from fuel tube Cause pending investigation Affected fuel assembly will be replaced
LIMOGES, C. Consolidated Edison Co. of New York, Inc 82/11/22 Region 1, Office of Director 2pp 16313 153 24X Fiche 50-247, 82/11/22, 8212060146

B-212080297 Forwards LER 82-044/03L-0
O'TOOLE, J. D. Consolidated Edison Co. of New York, Inc 82/11/28 HAYNES, R. C. Region 1, Office of Director 1p 16353 358 24X Fiche 50-247, 82/11/28, 8212080297

--B212080311 LER 82-044/03L-0 on B21029, three of first 10 snubbers tested did not meet acceptance criteria for lock-up rate & bleed Cause will be submitted following test completion Defective snubbers replaced
HINRICH, G. Consolidated Edison Co. of New York, Inc 82/11/28 Region 1, Office of Director 1p 16353 359 24X Fiche 50-247, 82/11/28, 8212080297

B-212150023 Forwards LER 82-046/03L-0
O'TOOLE, J. D. Consolidated Edison Co. of New York, Inc 82/11/29 HAYNES, R. C. Region 1, Office of Director 1p 16421 232 24X Fiche 50-247, 82/11/29, 8212150023

--B212150027 LER 82-046/03L-0 on B21030, during transfer of blended make-up, 15 gallon spill occurred through valve N336 Caused by defective diaphragm on closed valve 370 Valve bonnet for valve 336 & bonnet & diaphragm for valve 370 replaced
HINRICH, G. Consolidated Edison Co. of New York, Inc 82/11/29 Region 1, Office of Director 2pp 16421 233 24X Fiche 50-247, 82/11/29, 8212150023

B-212150080 Forwards LER 82-045/01T-0
O'TOOLE, J. D. Consolidated Edison Co. of New York, Inc 82/12/01 HAYNES, R. C. Region 1, Office of Director 1p 16430 162 24X Fiche 50-247, 82/12/01, 8212150080

--B212150084 LER 82-045/01T-0 on B21108, video tape insp revealed that upper end plug from fuel rod within assembly separated from fuel tube Cause not stated Assembly replaced
LIMOGES, C. Consolidated Edison Co. of New York, Inc 82/11/22 Region 1, Office of Director 2pp 16430 163 24X Fiche 50-247, 82/12/01, 8212150080

B-212210119 Forwards LER 82-047/03L-0
O'TOOLE, J. D. Consolidated Edison Co. of New York, Inc 82/12/04 HAYNES, R. C. Region 1, Office of Director 1p 16485 141 24X Fiche 50-247, 82/12/04, 8212210119

--B212210140 LER 82-047/03L-0 on B21104, during refueling/maint outage, pressurizer safety valves discovered outside tolerance Cause not stated Valves refurbished, readjusted & tested
HINRICH, G. Consolidated Edison Co. of New York, Inc 82/12/04 Region 1, Office of Director 2pp 16485 142 24X Fiche 50-247, 82/12/04, 8212210119

B-212210138 Forwards LER 82-048/03L-0
O'TOOLE, J. D. Consolidated Edison Co. of New York, Inc 82/12/05 HAYNES, R. C. Region 1, Office of Director 1p 16485 194 24X Fiche 50-247, 82/12/05, 8212210128

--B212210133 LER 82-048/03L-0 on B21105, air flow through reactor containment fan cooler unit 24 charcoal filter found 7% less than required by Tech Specs Cause under investigation Fresh charcoal placed in trays & sys retested
HINRICH, G. Consolidated Edison Co. of New York, Inc 82/12/05 Region 1, Office of Director 1p 16485 195 24X Fiche 50-247, 82/12/05, 8212210128

T Hearing transcripts on non-antitrust matters

B212070049 Transcript of B21203 telephone conference in Washington, DC
Pp 4, B56-4, B88
* Atomic Safety and Licensing Board Panel 82/12/03 33pp 16327 295 24X Fiche 50-247, 82/12/03, 8212070049

B-212150008 Forwards RL Goldfarb testimony & lists order of witnesses to testify Related correspondence
VETER, L. A. Westchester County, NY 82/12/09 OLEASON, J. P., PARIS, O. H., SHON, F. J. Atomic Safety and Licensing Board Panel 1p 16421 130 24X Fiche 50-247, 82/12/09, 8212150008

- B212150013 Testimony of RA Goldfarb re law enforcement concerns w/ emergency plan ASLB should consider effectiveness of emergency plan w/o adequate police communications sys Certificate of Svc encl
GOLDFARB, R. A. Westchester County, NY GOLDFARB, R. A. Ossining, NY 82/12/09 5pp 16421 131 24X Fiche 50-247, 82/12/09, 8212150008

DOCKETED ITEMS

8212300235 Transcript of Commission 821221 meeting in Washington, DC re possible action concerning emergency preparedness at facilities supporting documentation & viewgraphs encl
* Commissioners 82/12/21 121pp 16624 037 24X
Fiche 50-000, 82/12/21, 8212300235

U Congressional/Executive Correspondence

8212230341 Requests NRC statement of Commission basis for determination that reasonable assurance exists that public health & safety will be adequately protected in event of large nuclear accident
UDALL, M K House of Rep, Interior & Insular Affairs 82/12/15
FALLADINO, N J Commissioners 2pp 16511 126 24X
Fiche 50-247, 82/12/15, 8212230341

8212230276 Urges consideration of all info re adequacy of emergency plans & current state of emergency preparedness All steps must be taken to ensure adequacy of emergency planning
FISH, H, OILMAN, B, BINGHAM, J House of Rep 82/12/20
Commissioners 3pp 16508 277 24X Fiche 50-247, 82/12/20, 8212230276

DOCKET 50-249 DRESDEN NUCLEAR POWER STATION, UNIT 3

F Security, medical, emergency & fire protection plans

8212030283 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 82/11/30 Document
Management Branch 1p 16316 253 24X Fiche 50-010, 82/11/30, 8212030283

--8212030286 Forwards public version of revised emergency plan implementing procedures, including Procedure EPIP 100-2 re shift turnover w/technical support ctr & environ teams activated Receipt forms & procedure histories encl
SCOTT, D J Commonwealth Edison Co 82/11/19 DENTON, H R Office of Nuclear Reactor Regulation, Director 7pp 16316 255 24X
Fiche 50-010, 82/11/30, 8212030283

--8212030287 Public version of revised emergency plan implementing procedures, including Procedure EPIP 100-2 re shift turnover w/technical support ctr & environ teams activated
* Commonwealth Edison Co 82/11/17 14pp 16316 262 24X
Fiche 50-010, 82/11/30, 8212030283

8212090383 Forwards info re emergency operations facilities per 821122 & 1202 requests info previously submitted by telcon Request for written response unnecessary burden on licensee
DELGEOGE, L O Commonwealth Edison Co 82/12/03 EISENHUT, D Q Division of Licensing 2pp 16365 091 24X Fiche 50-000, 82/12/03, 8212090383

8212130017 Releases public version of Revision 1 to Emergency Plan Implementing Procedure EO-2, "Pre-Established Onsite & Offsite Monitoring Locations (Maps)"
FELTON, J M Division of Rules and Records 82/12/07 Document
Management Branch 1p 16417 062 24X Fiche 50-000, 82/12/07, 8212130017

--8212130028 Forwards public version of Revision 1 to Emergency Plan Implementing Procedure EO-2, "Pre-Established Onsite & Offsite Monitoring Locations (Maps)" Revised table of contents encl
PAJOWSKI, J Commonwealth Edison Co 82/11/01 DENTON, H R NRC --
No Detailed Affiliation Given 2pp 16417 063 24X
Fiche 50-000, 82/12/07, 8212130017

--8212130041 Public version of Revision 1 to Emergency Plan Implementing Procedure EO-2, "Pre-Established Onsite & Offsite Monitoring Locations (Maps)"
PAJOWSKI, J E, LITERSKI, L A Commonwealth Edison Co 82/11/29
4pp 16417 065 24X Fiche 50-000, 82/12/07, 8212130017

8212140243 Advises of distribution of revisions to "Generating Station Emergency Plan" Braidwood annex not prepared
TRAMIN, T R Commonwealth Edison Co 82/12/07 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 16409 302 24X
Fiche 50-000, 82/12/07, 8212140243

8212210118 Forwards IE Emergency Preparedness SERs 50-237/82-27 & 50-249/82-27 during Nov 1981 & June 1982, respectively No noncompliance noted
HIND, J A Division of Emergency Preparedness 82/12/10 REED, C Commonwealth Edison Co 2pp 16485 088, 24X Fiche 50-237, 82/12/10, 8212210118

--8212210124 IE Emergency Preparedness SERs 50-237/82-27 & 50-249/82-27 Major areas inspected emergency plan & site-specific annex dtd Nov 1981 & June 1982, respectively Planning stde met
PHILLIPS, M P Region 3, Office of Director 82/12/07 29pp
16485 091 24X Fiche 50-237, 82/12/10, 8212210118

8212220175 Releases public version of revised generating station emergency plan implementing procedures
FELTON, J M Division of Rules and Records 82/12/10 Document
Management Branch 1p 16529 029 24X Fiche 50-000, 82/12/10, 8212220175

--8212220190 Forwards public version of revised generating station emergency plan implementing procedures, including Procedures ED-3 re demand polling of meteorological data & ED-20 re emergency forecast request
PAJOWSKI, J E Commonwealth Edison Co 82/11/15 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 16529 030
24X Fiche 50-000, 82/12/10, 8212220175

--8212220202 Public version of revised generating station emergency plan implementing procedures, including Procedures ED-3 re demand polling of meteorological data & ED-20 re emergency forecast request
LITERSKI, L A, PAJOWSKI, J E Commonwealth Edison Co 82/10/13
48pp 16529 031 24X Fiche 50-000, 82/12/10, 8212220175

8212230019 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 82/12/15 Document
Management Branch 1p 16545 350 24X Fiche 50-010, 82/12/15, 8212230019

--8212230028 Forwards public version of Revision 1 to Emergency Plan Implementing Procedure EPIP 500-1, "Quarterly Inventory of First Aid Supplies"
SCOTT, D J Commonwealth Edison Co 82/12/03 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 16545 331 24X
Fiche 50-010, 82/12/15, 8212230019

--8212230042 Public version of Revision 1 to Emergency Plan Implementing Procedure EPIP 500-1, "Quarterly Inventory of First Aid Supplies" Revised index encl
* Commonwealth Edison Co 82/11/22 6pp 16545 354 24X
Fiche 50-010, 82/12/15, 8212230019

8212230306 Discusses layout of communications equipment required in control room, onsite technical support ctr & near-site emergency operations facility
KEPPLER, J O Region 3, Office of Director 82/12/16
Commonwealth Edison Co 3pp 16503 351 24X Fiche 50-000, 82/12/16, 8212230306

8212280214 Forwards IE Safeguards Insp Repts 50-010/82-20, 50-237/82-28 & 50-249/82-29 on 821115-19 Details & notice of violation withheld (ref IOCFR73 21)
MILLER, J R Division of Engineering & Technical Programs 82/12/20
REED, C Commonwealth Edison Co 2pp 16562 120 24X
Fiche 50-010, 82/12/20, 8212280214

--8212280220 IE Safeguards Insp Repts 50-010/82-20, 50-237/82-28 & 50-249/82-29 on 821115-19 Noncompliance noted failure to adequately control security-related key as required by security plan Details withheld (ref IOCFR73 21)
CHRISTOFFER, O Division of Emergency Preparedness & Operational Support 82/12/15 2pp 16562 122 24X Fiche 50-010, 82/12/20, 8212280214

8212300167 Releases public version of revised generating station emergency plan telephone directory
FELTON, J M Division of Rules and Records 82/12/20 Document
Management Branch 1p 16612 215 24X Fiche 50-000, 82/12/20, 8212300167

--8212300179 Forwards public version of revised generating station emergency plan telephone directory
MOORE, R D Commonwealth Edison Co 82/12/02 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 16612 216 24X
Fiche 50-000, 82/12/20, 8212300167

--8212300199 Public version of revised generating station emergency plan telephone directory
GALLE, D P Commonwealth Edison Co 82/11/05 60pp 16612 217
24X Fiche 50-000, 82/12/20, 8212300167

G Adjudicatory correspondence

GP12070160 Memorandum re order granting licensee B20818 request to dismiss proceeding w/o prejudice. Util received authority to increase spent fuel pool storage capacity, making shipment of spent fuel between plants unnecessary. JOHNSON, E B, STODER, G J, MILHOLLIN, Q L Atomic Safety and Licensing Board Panel 82/12/03 Commonwealth Edison Co 4pp 16336 320 24X Fiche 50-000, 82/12/03, B212070160

H General correspondence

B12280176 Notices of change in mailing address for NRC licensing mail. WRIGHT, Q N Illinois, State of, Dept Nuc Safety (formerly Dept Public Health) 82/12/20 EISENHUT, D G Division of Licensing 1p 16556 139 24X Fiche 50-000, 82/12/20, B212280176

P Operating license stage documents & correspondence

B212020110 "Analysis of Spectrum of Large-Break LOCAs in BWR/3 Using 1RAC-BD1," Vols 1 & 2, interim rept. JAVIS, C B EQ&G, Inc FIN A-6047 8212020110 82/10/31 ODAN, F Office of Nuclear Regulatory Research, Director 243pp 16310 039 24X Fiche 50-249, 82/10/31, B212020110

B12140001 Addl response to FOIA request for five categories of documents re SEP Forwards documents listed in App A No documents located subj to Item 3 of request. Review of remaining documents continuing Documents available in PDR. FELTON, J M Division of Rules and Records 82/11/03 QALLO, J Isham, Lincoln & Beale 2pp 16433 354 24X Fiche 50-000, 82/11/03, B212140001

-B009110797 Forwards excerpt from utility 680801, "Rept to Stockholders," re effect of 680515 tornadoes on util 345 kV sys. DENTON, H R Atomic Energy Commission 68/08/14 TEDESCO, R L Atomic Energy Commission 2pp 16434 254 24X Fiche 50-000, 82/11/03, B212140001

B1230066 Generic Ltr B2-27 to all BWR licensees of operating reactors except LACBWR, Big Rock Point, Dresden 1, Humboldt Bay, applicants for DL & holders of CP re transmittal of NUREG-0763 & NUREG-0783 Svc list encl W/o stated encl. EISENHUT, D G Division of Licensing 82/11/15 General Public Utilities - OPU Service Corp 2pp 16387 004 24X Fiche 50-000, 82/11/15, B211230066

B12160326 Forwards Revision 1 to "Second 10-Yr Inservice Insp & Testing Program, Dresden Units 2 & 3" Response to NRC questions & comments & procedures for reactor vessel 1,000 psi & ASME hydrostatic tests & quarterly valve timing encl. RAUSCH, T J Commonwealth Edison Co 82/12/10 EISENHUT, D G Division of Licensing 4pp 16441 088 24X Fiche 50-237, 82/12/10, B212160326

--B212160334 Revision 1 to "Second 10-Yr Inservice Insp & Testing Program, Dresden Units 2 & 3" Commonwealth Edison Co 82/12/31 250pp 16441 132 24X Fiche 50-237, 82/12/10, B212160334

B12220212 Forwards Revision 22 to CE-1-A, "QA Program for Nuclear Generating Stations." SWARTZ, E D Commonwealth Edison Co 82/12/14 HAASS, W P Quality Assurance Branch 1p 16318 007 24X Fiche 50-000, 82/12/14, B212220212

--B212220231 "QA Program for Nuclear Generating Stations," Revision 22 Commonwealth Edison Co CE-1-A R22 82/11/01 17pp 16518 009 24X Fiche 50-000, 82/12/14, B212220212

GP12280117 Forwards addl info re NUREG-0737, Item II F 1, "Addl Accident Monitoring Instrumentation," per NRC 821109 request. Pressure monitoring sys provided w/separate loop for narrow range monitoring. SWARTZ, E D Commonwealth Edison Co 82/12/20 EISENHUT, D G Division of Licensing 9pp 16564 062 24X Fiche 50-000, 82/12/20, B212280117

GP12280343 Forwards addl info re NUREG-0737, Items II F 1, 4.5 & 6 "Containment Pressure, Water Level & Hydrogen Monitoring," per Crutchfield 821109 ltr. SWARTZ, E D Commonwealth Edison Co 82/12/20 EISENHUT, D G Division of Licensing 9pp 16561 053 24X Fiche 50-000, 82/12/20, B212280343

B12280212 Forwards updated schedule for ongoing environ qualification testing programs, per 810528 commitment. SWARTZ, E D Commonwealth Edison Co 82/12/22 EISENHUT, D G Division of Licensing 18pp 16556, 161 24X Fiche 50-000, 82/12/22, B212280212

B212280263 Clarifies position on classification of major mods to BWR Mark I Containment per B21216 ltr. RAUSCH, T J Commonwealth Edison Co 82/12/22 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 16561 307 24X Fiche 50-000, 82/12/22, B212280263

Q Inspection reports, IE Bulletins & correspondence

B208190240 IE Bulletin B2-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants." Svc list encl. DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, B208190240

B208190245 IE Info Notice B2-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters." Svc list encl. COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000, 82/11/05, B208190245

B208190251 IE Info Notice B2-44, "Clarification of Emergency Plan Exercise Requirements." Svc list encl. JORDAN, E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X Fiche 50-000, 82/11/18, B208190251

B208190256 IE Info Notice B2-46, "Defective & Obsolete Combination Padlocks." Svc list encl. DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000, 82/11/26, B208190256

B212060036 Ack receipt of B21028 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-010/82-13, 50-237/82-17 & 50-249/82-18. STREETER, J F Region 3, Office of Director 82/11/26 REED, C Commonwealth Edison Co 1p 16313 284 24X Fiche 50-010, 82/11/26, B212060036

--B212060045 Responds to NRC B20728 ltr re violations noted in IE Insp Repts 50-010/82-13, 50-237/82-17 & 50-249/82-18. Corrective actions inservice leak test performed on water leg portion of torus level mod Training session scheduled. DELOERDE, L O Commonwealth Edison Co 82/10/28 KEPPLER, J O Region 3, Office of Director 3pp 16313 285 24X Fiche 50-010, 82/11/26, B212060036

B212170300 Forwards IE Insp Repts 50-010/82-19, 50-237/82-26 & 50-249/82-26 on B21104-05 No noncompliance noted. LITTLE, W S Division of Engineering & Technical Programs 82/11/29 REED, C Commonwealth Edison Co 2pp 16453 206 24X Fiche 50-010, 82/11/29, B212170300

--B212170306 IE Insp Repts 50-010/82-19, 50-237/82-26 & 50-249/82-26 on B21104-05 No noncompliance noted. Major areas inspected licensee actions on previously identified items. REIMANN, F W, JACKIH, I N Division of Engineering & Technical Programs 82/11/24 4pp 16453 208 24X Fiche 50-010, 82/11/29, B212170300

B208190257 IE Info Notice B2-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl." Svc list encl. COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000, 82/11/30, B208190257

B212030178 Forwards final BALP Repts 50-010/82-10, 50-237/82-14 & 50-249/82-15 for assessment period Jul 1980-Dec 1981, discussed at IE mgt meeting on 820602 Util 820618 comments on BALP rept addressed. KEPPLER, J O, Region 3, Office of Director 82/12/01 REED, C Commonwealth Edison Co 3pp 16303 228 24X Fiche 50-010, 82/12/01, B212030178

--B212030185 BALP Repts 50-010/82-10, 50-237/82-14 & 50-249/82-15 for assessment period Jul 1980-Dec 1981. Mgt attention warranted in areas of plant operations, radiological controls & review committee activities. Region 3, Office of Director 82/05/31 47pp 16303 231 24X Fiche 50-010, 82/12/01, B212030178

B208190259 IE Bulletin B2-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies." Svc list encl. DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, B208190259

DOCKETED ITEMS

B208190261 IE Info Notice B2-48, "Failures of Agastat CR 0095 Relay
Lockets " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance B2/12/03
Consolidated Edison Co of New York, Inc 110pp 16462 064 24X
Fiche 50-000, B2/12/03, B208190261

B212170196 Forwards IE Insp Repts 50-010/B2-18, 50-237/B2-25 &
50-249/B2-25 on B21002-29 No noncompliance noted
STREETER, J F Division of Project & Resident Programs B2/12/03
REED, C Commonwealth Edison Co 2pp 16450 153 24X
Fiche 50-010, B2/12/03, B212170196

--B212170201 IE Insp Repts 50-010/B2-18, 50-237/B2-25, 50-249/B2-25 on
B21002-29 No noncompliance noted Major areas inspected
headquarters & regional requests, operational safety
verification, monthly maint observation & LERS
TONDUVE, T M, STASEK, S, WALKER, R D Division of Project & Resident
Programs B2/12/01 8pp 16450 155 24X Fiche 50-010, B2/12/03,
B212170196

B212160326 Forwards Revision 1 to "Second 10-Yr Inservice Insp &
Testing Program, Dresden Units 2 & 3 " Response to NRC
questions & comments & procedures for reactor vessel 1,000
psi & ASME hydrostatic tests & quarterly valve timing encl
RAUSCH, T J Commonwealth Edison Co B2/12/10 EISENHUT, D G
Division of Licensing 4pp 16441 088 24X Fiche 50-237, B2/12/10,
B212160326

--B212160334 Revision 1 to "Second 10-Yr Inservice Insp & Testing
Program, Dresden Units 2 & 3 "
Commonwealth Edison Co B2/12/01 268pp 16441 132 24X
Fiche 50-237, B2/12/10, B212160326

B212210118 Forwards IE Emergency Preparedness SERs 50-237/B2-27 &
50-249/B2-27 during Nov 1981 & June 1982, respectively No
noncompliance noted
HIND, J A Division of Emergency Preparedness B2/12/10 REED, C
Commonwealth Edison Co 2pp 16483 088 24X Fiche 50-237, B2/12/10,
B212210118

--B212210124 IE Emergency Preparedness SERs 50-237/B2-27 & 50-249/B2-27
Major areas inspected emergency plan & site-specific annex
dtd Nov 1981 & June 1982, respectively Planning aids met
PHILLIPS, M P, AXELSON, W L, PAPERIELLO, C J Region 3, Office of
Director B2/12/07 29pp 16485 091 24X Fiche 50-237, B2/12/10,
B212210118

B208190267 IE Info Notice B2-49, "Correction for Sample Conditions for
Air & Gas Monitoring " Svc list encl
DEQUINO, R C Director's Office, Office of Inspection and
Enforcement B2/12/16 Consolidated Edison Co of New York, Inc
127pp 16628 191 24X Fiche 50-000, B2/12/16, B208190267

B212270295 Ack receipt of B21124 ltr informing NRC of steps taken to
correct violations noted in IE Insp Rept 50-237/B2-21,
50-249/B2-22, 50-254/B2-17 & 50-265/B2-19
MORELIUS, C E Division of Engineering & Technical Programs
B2/12/16 REED, C Commonwealth Edison Co 2pp 16530 083 24X
Fiche 50-000, B2/12/16, B212270295

--B212270303 Responds to NRC B21026 ltr re violations noted in IE Insp
Repts 50-237/B2-21, 50-249/B2-22, 50-254/B2-17 & 50-265/B2-19
Corrective actions annual audits of all active AE firms
performing safety-related work required
DELOERGE, L O Commonwealth Edison Co B2/11/24 KEPLER, J O
Region 3, Office of Director 4pp 16530 087 24X
Fiche 50-000, B2/12/16, B212270295

--B212270307 "EDS-NUTECH Interface Control Instructions," Revision 0
TSCHUDT, N F NUTECH (Nuclear Technology, Inc) B2/09/30 22pp
16530 091 24X Fiche 50-000, B2/12/16, B212270295

--B212270313 "IE Bulletin 79-14 & TAP Piping Evaluation, Quad Cities Units
1 & 2 & Dresden Units 2 & 3," Revision 0
NUTECH (Nuclear Technology, Inc) B2/10/01 9pp 16530 113
24X Fiche 50-000, B2/12/16, B212270295

B212280180 Provides final status rept of IE Bulletin 79-14, "Seismic
Analysis for As-Built Safety-Related Piping Sys " Complete
& final listings of portions of sys failing to meet FSAR
requirements under NUTECH responsibility encl
RAUSCH, T J Commonwealth Edison Co B2/12/17 KEPLER, J O Region
3, Office of Director 3pp 16564 191 24X Fiche 50-000, B2/12/17,
B212280180

B212290376 Forwards IE Insp Rept 50-249/B2-28 on B21109, 10 & 12 &
notice of violation
LITTLE, W S Division of Engineering & Technical Programs B2/12/17
REED, C Commonwealth Edison Co 2pp 16586 270 24X
Fiche 50-249, B2/12/17, B212290376

--B212290380 Notice of violation from insp on B21109, 10 & 12
LITTLE, W S Division of Engineering & Technical Programs
B2/12/17 1p 16586 272 24X Fiche 50-249, B2/12/17, B212290376

--B212290386 IE Insp Rept 50-249/B2-28 on B21109, 10 & 12 Noncompliance
noted Revision 3 to DTS B237 on calculation of core thermal
power - technical staff method reviewed & approved w/o
review & approval of associated computer program
ROBINSON, D L, JACKIN, I N Region 3, Office of Director
B2/12/10 6pp 16586 273 24X Fiche 50-249, B2/12/17, B212290376

B208190268 IE Info Notice B2-50, "Mod of Solid State AC Undervoltage
Relays Type ITE-27 " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance B2/12/03
Consolidated Edison Co of New York, Inc 108pp 16628 293 24X
Fiche 50-000, B2/12/20, B208190268

B212280214 Forwards IE Safeguards Insp Repts 50-010/B2-20, 50-237/B2-28
& 50-249/B2-29 on B21115-19 Details & notice of violation
withheld (ref 10CFR73 21)
MILLER, J R Division of Engineering & Technical Programs B2/12/20
REED, C Commonwealth Edison Co 2pp 16562 120 24X
Fiche 50-010, B2/12/20, B212280214

--B212280220 IE Safeguards Insp Repts 50-010/B2-20, 50-237/B2-28 &
50-249/B2-29 on B21115-19 Noncompliance noted failure to
adequately control security-related key as required by
security plan Details withheld (ref 10CFR73 21)
CHRISTOFFER, O, KNTICELEV, J R, CREED, J R Division of Emergency
Preparedness & Operational Support B2/12/15 2pp 16562 122
24X Fiche 50-010, B2/12/20, B212280214

B212280070 Requests addition of RE Farrell to unescorted access list
to vital & protected areas Individual possesses clearance
KEPLER, J O Region 3, Office of Director B2/12/22 REED, C
Commonwealth Edison Co 1p 16563 136 24X Fiche 50-010, B2/12/22,
B212280070

R Periodic operating reports & related correspondence

B212140077 "1982 Evaluation, Dresden Nuclear Power Station, Comm Ed Co "
Institute of Nuclear Power Operations B2/11/30 39pp
16403 171 24X Fiche 50-010, B2/11/30, B212140077

B212140112 Forwards monthly operating repts for Nov 1982
SCOTT, D J Commonwealth Edison Co B2/12/01 Director's Office,
Office of Inspection and Enforcement 1p 16408 204 24X
Fiche 50-010, B2/12/01, B212140112

--B212140120 Monthly operating repts for Nov 1982
SCHROEDER, D A Commonwealth Edison Co B2/12/01 28pp
16403 205 24X Fiche 50-010, B2/12/01, B212140112

S Reportable occurrences, LERS & related correspondence

B212080375 Forwards updated LER B2-008/03X-1
SCOTT, D J Commonwealth Edison Co B2/11/04 KEPLER, J O Region
3, Office of Director 1p 16353 310 24X Fiche 50-249, B2/11/04,
B212080375

--B212080381 Updated LER B2-008/03X-1 on B20126, while performing refuel
surveillance DFS 2300-7, calibr testing discovered HPCI temp
switches 2371A, 2372A, 2370C & 2370D above Tech Spec limit
Caused by vibration loosening set screws
ANANDAPPA, A Commonwealth Edison Co B2/11/04 Region 3,
Office of Director 2pp 16353 311 24X Fiche 50-249, B2/11/04,
B212080375

B212290472 Forwards updated LER B2-028/03X-1
SCOTT, D J Commonwealth Edison Co B2/11/08 KEPLER, J O Region
3, Office of Director 1p 16583 255 24X Fiche 50-249, B2/11/08,
B212290472

--B212290478 Updated LER B2-028/03X-1 on B20708, switch PS 1554 F tripped
above Tech Spec limit Caused by poor maint on HX
during bottom head removal allowing water to fall onto
instrument rack Rack covered & linkage tested
COYLE, L Commonwealth Edison Co B2/11/08 Region 3, Office of
Director 2pp 16583 256 24X Fiche 50-249, B2/11/08, B212290472

B212020337 Forwards LER B2-044/03C-0
SCOTT, D J Commonwealth Edison Co B2/11/13 KEPLER, J O Region
3, Office of Director 1p 16278 179 24X Fiche 50-249, B2/11/13,
B212020337

DOCKETED ITEMS

51

- 8212020357 LER 82-044/03L-0 on 821102, during routine surveillance, DIS-700-3, high trip (rod block) on source range monitor 24 found to trip above allowable limits Caused by setpoint drift on hi alarm potentiometer Setpoint reset
BEVERLY, K Commonwealth Edison Co 82/11/15 Region 3, Office of Director 1p 16278 176 24X Fiche 50-249, 82/11/15, 8212020337

8212170134 Forwards updated LER 82-038/03X-1
SCOTT, D J Commonwealth Edison Co 82/11/15 KEPPLER, J Q Region 3, Office of Director 1p 16459 166 24X Fiche 50-249, 82/11/15, 8212170134

--8212170139 Updated LER 82-038/03X-1 on 821001, during main steam line high radiation scram & isolation surveillance, radiation monitor 1705-2A tripped at 1.600 m/h Caused by instrument drift Setpoint adjusted to 1.460 m/h
RHEE, S Commonwealth Edison Co 82/11/15 Region 3, Office of Director 1p 16459 167 24X Fiche 50-249, 82/11/15, 8212170134

8212020239 Forwards LER 82-043/03L-0
SCOTT, D J Commonwealth Edison Co 82/11/16 KEPPLER, J Q Region 3, Office of Director 1p 16274 153 24X Fiche 50-249, 82/11/16, 8212020239

--8212020248 LER 82-043/03L-0 on 821028, magnetrol level switches B2D & B2F did not trip when tested Cause unknown Upper switch contact mechanisms installed on all failed switches
HALEN, R J Commonwealth Edison Co 82/11/16 Region 3, Office of Director 1p 16274 154 24X Fiche 50-249, 82/11/16, 8212020239

8212170218 Forwards LER 82-046/03L-0
SCOTT, D J Commonwealth Edison Co 82/12/03 KEPPLER, J Q Region 3, Office of Director 1p 16459 354 24X Fiche 50-249, 82/12/03, 8212170218

- 8212170225 LER 82-046/03L-0 on 821112, water discovered spraying from 1-inch drain line off bottom of feedwater regulator isolation valve 3A Caused by cracked weld at 1-inch chain line due to stresses from thermal effects
CHRISTEL, B Commonwealth Edison Co 82/12/03 Region 3, Office of Director 1p 16459 355 24X Fiche 50-249, 82/12/03, 8212170218

8212090415 PNO-111-82-132 on 821203, licensee declared alert when level of flood-swollen IL River threatened svc water pumps & diesel fire pumps inside crib house Shutdown initiated Alert canceled on 821204 Units returned to power on 821205
WALKER, R, TONGUE, T, SPESSARD, R Region 3, Office of Director 82/12/06 1p 16365 032 24X Fiche 50-237, 82/12/06, 8212090415

8212170097 Forwards LER 82-047/03L-0
SCOTT, D J Commonwealth Edison Co 82/12/06 KEPPLER, J Q Region 3, Office of Director 1p 16450 319 24X Fiche 50-249, 82/12/06, 8212170097

- 8212170102 LER 82-047/03L-0 on 821117, during normal operation, w/reactor vessel low water level ECOS initiation in progress, LIS 263-72-C found set at 111 D inches delta P Caused by defective procedure LIS 263-72-C reset
COYLE, L Commonwealth Edison Co 82/12/06 Region 3, Office of Director 1p 16450 320 24X Fiche 50-249, 82/12/06, 8212170097

8212290369 Forwards updated LER 82-037/03X-1
SCOTT, D J Commonwealth Edison Co 82/12/10 KEPPLER, J Q Region 3, Office of Director 1p 16986 361 24X Fiche 50-249, 82/12/10, 8212290369

--8212290385 Updated LER 82-037/03X-1 on 820922, during normal operation, TIP ball valve 2E would not automatically reclose using control switch Caused by possible hardened lubrication causing valve to drag Spring retensioned to overcome drag
MORGAN, W E Commonwealth Edison Co 82/12/10 Region 3, Office of Director 2pp 16986 362 24X Fiche 50-249, 82/12/10, 8212290369

8212290329 Forwards LER 82-048/03L-0
SCOTT, D J Commonwealth Edison Co 82/12/20 KEPPLER, J Q Region 3, Office of Director 1p 16586 231 24X Fiche 50-249, 82/12/20, 8212290329

--8212290333 LER 82-048/03L-0 on 821126, during normal operation, oxygen analyzer failed w/high oxygen alarm up in control room caused by failure of light bulb for light unit that activates photoelectric cell of analyzer Bulb replaced
ATA, H Commonwealth Edison Co 82/12/20 Region 3, Office of Director 2pp 16586 232 24X Fiche 50-249, 82/12/20, 8212290329

DOCKET 50-250 TURKEY POINT PLANT, UNIT 3

F Security, medical, emergency & fire protection plans

8212090529 Forwards IE Insp Repts 50-250/82-11 & 50-251/82-11 on 821004-10 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 82/10/29 UHR10, R E Florida Power & Light Co 2pp 16366 108 24X Fiche 50-250, 82/10/29, 8212090529

--8212090540 IE Insp Repts 50-250/82-11 & 50-251/82-11 on 821004-08 No noncompliance noted Major areas inspected followup on previous emergency preparedness findings & experience data on installation & operation of public notification sys
HUFFMAN, G M, JENKINS, G R Division of Emergency Preparedness & Operational Support 82/10/29 19pp 16366 110 24X Fiche 50-250, 82/10/29, 8212090529

8212290060 Partial response to FOIA request for seven categories of info Forwards documents listed in App A Documents 1 & 2 already in PDR App B documents available in PDR LPDR profiles for Ginn & Indian Point 3 encl
FELTON, J M Division of Rules and Records 82/11/30 SCHLESSEL, D A New York, State of 7pp 16607 239 24X Fiche 50-000, 82/11/30, 8212290060

--8212290094 Responds to NRC 750529 ltr re deviation noted in IE Insp Repts 50-250/75-07 & 50-251/75-07 Corrective actions fire stops installed in cable trays in Unit 4 control rod drive room & entrance to auxiliary bldg above main corridor doors
UHR10, R E Florida Power & Light Co 75/06/20 MOSELEY, N C Region 2, Atlanta, Office of the Director 2pp 16607 355 24X Fiche 50-000, 82/11/30, 8212290060

--8212290114 IE Insp Repts 50-250/75-07 & 50-251/75-07 on 750512-14 Deviation observed one tray of control cables in Unit 3 control rod drive room & cable trays exiting auxiliary bldg did not have fire stops installed
HARDIN, A K Region 2, Atlanta, Office of the Director 75/05/27 9pp 16607 360 24X Fiche 50-000, 82/11/30, 8212290060

J Insurance & indemnity information

8212020335 Forwards Endorsements 40 & 61 to NELIA Policy NF-185 & Endorsements 50 & 51 to MAELU Policy MF-55
FIELDER, J Marsh & McLennan, Inc, M & M Nuclear Consultants, Inc Div 82/11/18 SALTZMAN, J Assistant Director for State & License Relations 5pp 16279 151 24X Fiche 50-250, 82/11/18, 8212020335

8212300202 Forwards Endorsements 1, 2 & 3 to NELIA Certificates N-25 & N-26 & Endorsements 1, 2 & 3 to MAELU Certificates M-25 & M-26
DUCK, J R Marsh & McLennan, Inc, M & M Nuclear Consultants, Inc Div 82/12/27 SALTZMAN, J Assistant Director for State & License Relations 37pp 16598 050 24X Fiche 50-250, 82/12/27, 8212300202

8212300243 Forwards Endorsement 62 to NELIA Policy NF-185 & Endorsement 52 to MAELU Policy MF-55
DUCK, J R Marsh & McLennan, Inc, M & M Nuclear Consultants, Inc Div 82/12/27 SALTZMAN, J Assistant Director for State & License Relations 3pp 16595 273 24X Fiche 50-250, 82/12/27, 8212300243

D Advisory Committee on Reactor Safeguards reports & correspondence

8212070435 Discusses summary of ACRS Reactor Operations Subcommittee 820929 meeting re Turkey Point cold overpressure incident Tech Specs do not properly address situations in which availability of certain sys more vital to safe operation
BINFORD, F T Oak Ridge National Laboratory 82/10/19 MAJOR, R ACRS - Advisory Committee on Reactor Safeguards 1p 16355 336 24X Fiche 50-250, 82/10/19, 8212070435

P Operating license stage documents & correspondence

8212170273 Forwards "Turkey Point Unit 3 Containment Structure Post-Tensioning Sys Tenth-Yr Surveillance" & "Turkey Point Unit 4 Containment Structure Post-Tensioning Sys Tenth-Yr Surveillance" w/o rept for Unit 4
UHR10, R E Florida Power & Light Co 82/12/03 EISENHUT, D O Division of Licensing 2pp 16461 183 24X Fiche 50-250, 82/12/03, 8212170273

--8212170276 "Turkey Point Unit 3 Containment Structure Post-Tensioning Sys Tenth-Yr Surveillance"
GREEN, K, LEE, K Y Bechtel Corp 82/07/31 107pp 16461 185 24X Fiche 50-250, 82/12/03, 8212170273

DOCKETED ITEMS

8208190263 Generic Ltr 82-32 to all PWR licensees re potential steam generator-related generic requirements Forwards Science Applications, Inc draft rept re suby requirements Comments requested within 30 days of ltr Svc list encl
EISENHUT, D O Division of Licensing 82/12/09 Consolidated
Edison Co or New York, Inc 29pp 16629 247 24X
Fiche 50-000, 82/12/09, 8208190263

8212140103 Generic Ltr 82-28 to all licensees of operating Westinghouse & C-E PHRs (except Arkansas Nuclear One, Unit 2 & San Onofre 2 & 3) re inadequate core cooling instrumentation sys Svc list encl
EISENHUT, D O Division of Licensing 82/12/10 Yankee Atomic
Electric Co 27pp 16690 035 24X Fiche 50-000, 82/12/10,
8212140103

8212210190 Informs that util will utilize Westinghouse optimized fuel assemblies during Fall 1983 refueling
UHRIG, R E Florida Power & Light Co 82/12/13 EISENHUT, D O
Division of Licensing 1p 16484 353 24X Fiche 50-250, 82/12/13,
8212210190

8212290534 Forwards safety & technical evaluations for environ qualification of safety-related electrical equipment Reaffirmation of justification for continued operation & info re Categories I B, II A & II B requested
VARQA, S A Operating Reactors Branch 1 82/12/13 UHRIG, R E
Florida Power & Light Co 3pp 16608 061 24X
Fiche 50-250, 82/12/13, 8212290534

--8212290535 SER re environ qualification of safety-related electrical equipment
* Operating Reactors Branch 1 82/12/13 5pp 16608 054 24X
Fiche 50-250, 82/12/13, 8212290534

--8210070227 "Review of Licensees Resolution of Outstanding Issues From NRC Equipment Environ Qualification SERs (F-11 & D-60), Turkey Point Unit 4," Vols 1 & 2, technical evaluation rept
PANDEY, S Franklin Institute/Franklin Research Center
NRC-03-79-118 TER-C5257-480 82/09/30 LE, N D NRC - No Detailed Affiliation Given 778pp 16608 069 24X
Fiche 50-250, 82/12/13, 8212290534

--8212290536 "Review of Licensee Resolution of Outstanding Issues From NRC Equipment Environ Qualification SERs (F-11 & D-60)," Vols 1 & 2, technical evaluation rept
PANDEY, S Franklin Institute/Franklin Research Center
TER-C5257-479 82/09/30 LE, N D, SHEHANSKI, P NRC - No Detailed Affiliation Given 807pp 16610 128 24X Fiche 50-250, 82/12/13,
8212290534

8212300048 Forwards safety evaluation & technical evaluation rept supporting station electric distribution sys voltages
VARQA, S A Operating Reactors Branch 1 82/12/17 UHRIG, R E
Florida Power & Light Co 2pp 16624 213 24X
Fiche 50-250, 82/12/17, 8212300048

--8212300071 SER supporting station electric distribution sys voltages
* Operating Reactors Branch 1 82/12/27 5pp 16624 215 24X
Fiche 50-250, 82/12/17, 8212300048

--8209230424 "Adequacy of Station Electric Distribution Sys Voltages for Turkey Point Nuclear Generating Plant Units 3 & 4," technical evaluation rept
SELAN, J C Lawrence Livermore Laboratory FIN A-0250
UCID-19148 82/08/08 NRC - No Detailed Affiliation Given
13pp 16624 220 24X Fiche 50-250, 82/12/17, 8212300048

Q Inspection reports, IE Bulletins & correspondence

8208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Gas Piping at BWR Plants" Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc
112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240

8212090529 Forwards IE Insp Repts 50-250/82-11 & 50-251/82-11 on 821004-10 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 82/10/29 UHRIG, R E Florida Power & Light Co 2pp 16366 108 24X
Fiche 50-250, 82/10/29, 8212090529

--8212090540 IE Insp Repts 50-250/82-11 & 50-251/82-11 on 821004-08 No noncompliance noted Major areas inspected Followup on previous emergency preparedness findings & experience data on installation & operation of public notification sys
HUFFMAN, Q N, JENKINS, O R Division of Emergency Preparedness & Operational Support 82/10/29 19pp 16366 110 24X
Fiche 50-250, 82/10/29, 8212090529

8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters" Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp
16372 142 24X Fiche 50-000, 82/11/05, 8208190245

8212090490 Forwards IE Insp Repts 50-250/82-31 & 50-251/82-31 on 821018-22 No noncompliance noted
DANCE, H C Region 2, Office of Director 82/11/12 UHRIG, R E
Florida Power & Light Co 2pp 16365 344 24X
Fiche 50-250, 82/11/12, 8212090490

--8212090500 IE Insp Repts 50-250/82-31 & 50-251/82-31 on 821018-22 No noncompliance noted Major areas inspected radiation protection program including qualification of staff, training & radiological protection procedures
MOSELEY, N C, DEBS, B T, BARR, K P Division of Engineering & Technical Programs 82/11/12 10pp 16365 346 24X
Fiche 50-250, 82/11/12, 8212090490

8212090487 Ack receipt of 821029 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-250/82-29 & 50-251/82-29
DANCE, H C Division of Project & Resident Programs 82/11/16 UHRIG, R E Florida Power & Light Co 1p 16366 001 24X
Fiche 50-250, 82/11/16, 8212090487

--8212090503 Responds to NRC 820929 ltr re violations noted in IE Insp Repts 50-250/82-29 & 50-251/82-29 Corrective actions procedure revised to clarify policy for tagging motor operated valves
UHRIG, R E Florida Power & Light Co 82/10/29 O'REILLY, J P
Region 2, Office of Director 2pp 16366 002 24X
Fiche 50-250, 82/11/16, 8212090487

--8212090510 Forwards IE Insp Repts 50-250/82-29 & 50-251/82-29 on 820726-0826 & notice of violation
DANCE, H C Division of Project & Resident Programs 82/09/29 UHRIG, R E Florida Power & Light Co 2pp 16366 004 24X
Fiche 50-250, 82/11/16, 8212090487

--8212090518 Notice of violation from insp on 820726-0826
* Division of Project & Resident Programs 82/09/29 1p
16366 006 24X Fiche 50-250, 82/11/16, 8212090487

--8212090524 IE Insp Repts 50-250/82-29 & 50-251/82-29 on 820726-0826 Noncompliance noted failure to follow equipment clearance procedure for motor operated valve in safety injection sys
VOGT-LOWELL, R, JULIAN, C Division of Project & Resident Programs 82/09/24 6pp 16366 007 24X Fiche 50-250, 82/11/16, 8212090487

8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements" Svc list encl
JORDAN, C L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X
Fiche 50-000, 82/11/18, 8208190251

8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Radiolocks" Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc
127pp 16411 065 24X Fiche 50-000, 82/11/26, 8208190256

8208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl" Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp
16387 028 24X Fiche 50-000, 82/11/30, 8208190257

8212290060 Partial response to FOIA request for seven categories of info Forwards documents listed in App A Documents 1 & 2 already in PDR App B documents available in PDR LPDR profiles for Ginna & Indian Point 3 encl
FELTON, J M Division of Rules and Records 82/11/30 SCHLISSEL, D A New York, State of 7pp 16607 239 24X
Fiche 50-000, 82/11/30, 8212290060

--8212290064 Ack receipt of 750714 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-250/75-08 & 50-251/75-08
MOSELEY, N C Region 2, Atlanta, Office of the Director 75/08/01 UHRIG, R E Florida Power & Light Co 1p 16607 332 24X
Fiche 50-000, 82/11/30, 8212290060

--8212290068 Responds to NRC 750625 ltr re violation noted in IE Insp Repts 50-250/75-08 & 50-251/75-08 Corrective actions superseded procedures for surveillance testing removed & latest revision placed in control room on 750526
UHRIG, R E Florida Power & Light Co 75/07/14 MOSELEY, N C
Region 2, Atlanta, Office of the Director 3pp 16607 333 24X
Fiche 50-000, 82/11/30, 8212290060

--B212290073 Forwards IE Insp Repts 50-250/75-08 & 50-251/75-08 on 750527-30 Noncompliance noted
MOSELEY, N C Region 2, Atlanta, Office of the Director 75/06/25
UHRIO, R E Florida Power & Light Co 2pp 16607 336 24X
Fiche 50-000, 82/11/30, 8212290060

--B212290078 IE Insp Repts 50-250/75-08 & 50-251/75-08 on 750527-30 Noncompliance noted failure to use latest approved procedure in performance of surveillance test
HARDIN, A K, LONG, F J, WILDER, H A Region 2, Atlanta, Office of the Director 75/06/24 15pp 16607 338 24X
Fiche 50-000, 82/11/30, 8212290060

--B212290082 Forwards listed documents re IE Insp Repts 50-250/75-07 & 50-251/75-07 Documents filed in LPDR
MOSELEY, N C Region 2, Atlanta, Office of the Director 75/07/21
SUBER, F T Homestead, FL 1p 16607 353 24X
Fiche 50-000, 82/11/30, 8212290060

--B212290087 Forwards listed documents re IE Insp Repts 50-250/75-16 & 50-251/75-16 Documents filed in LPDR
MOSELEY, N C Region 2, Atlanta, Office of the Director 76/01/05
PEELER, E Florida International Univ 1p 16607 281 24X
Fiche 50-000, 82/11/30, 8212290060

--B212290090 Ack receipt of 750620 ltr informing NRC of steps taken to correct deviation noted in IE Insp Repts 50-250/75-07 & 50-251/75-07
MOSELEY, N C Region 2, Atlanta, Office of the Director 75/07/21
UHRIO, R E Florida Power & Light Co 1p 16607 354 24X
Fiche 50-000, 82/11/30, 8212290060

--B212290092 Ack receipt of 751229 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-250/75-16 & 50-251/75-16
LONG, F J Region 2, Atlanta, Reactor Operations Nuclear Support Branch 76/01/05 UHRIO, R E Florida Power & Light Co 1p 16607 282 24X Fiche 50-000, 82/11/30, 8212290060

--B212290094 Responds to NRC 750529 ltr re deviation noted in IE Insp Repts 50-250/75-07 & 50-251/75-07 Corrective actions fire stops installed in cable trays in Unit 4 control rod drive room & entrance to auxiliary bldg above main corridor doors
UHRIO, R E Florida Power & Light Co 75/06/20 MOSELEY, N C Region 2, Atlanta, Office of the Director 2pp 16607 355 24X
Fiche 50-000, 82/11/30, 8212290060

--B212290097 Responds to NRC 751209 ltr re violation noted in IE Insp Repts 50-250/75-16 & 50-251/75-16 Corrective actions overdue inservice insp rept transmitted to NRC on 751120 & procedure written to describe scheduling & preparation of repts
UHRIO, R E Florida Power & Light Co 75/12/29 MOSELEY, N C Region 2, Atlanta, Office of the Director 2pp 16607 283 24X
Fiche 50-000, 82/11/30, 8212290060

--B212290100 Forwards IE Insp Repts 50-250/75-07 & 50-251/75-07 on 750512-14 Deviation from FSAR commitment observed
MOSELEY, N C Region 2, Atlanta, Office of the Director 75/05/27
UHRIO, R E Florida Power & Light Co 2pp 16607 357 24X
Fiche 50-000, 82/11/30, 8212290060

--B212290101 Forwards IE Insp Repts 50-250/75-16 & 50-251/75-16 on 751105-21 Noncompliance noted
MOSELEY, N C Region 2, Atlanta, Office of the Director 75/12/07
UHRIO, R E Florida Power & Light Co 2pp 16607 285 24X
Fiche 50-000, 82/11/30, 8212290060

--B212290108 Forwards IE Insp Repts 50-250/75-07 & 50-251/75-07 on 750512-14 Deviation from FSAR commitment observed Licensee requested to inform NRC of plans for implementing FSAR commitment
LONG, F J Region 2, Atlanta, Office of the Director 75/05/27
SEYFRIT, V Office of Inspection & Enforcement, Office of the Director 1p 16607 359 24X Fiche 50-000, 82/11/30, 8212290060

--B212290109 IE Insp Repts 50-250/75-16 & 50-251/75-16 on 751105-21 Noncompliance noted failure to submit Unit 4 inservice insp rept to NRC within 90 days
HARDIN, A K, LEWIS, R C, HERDT, A R Region 2, Atlanta, Reactor Operations Nuclear Support Branch 75/12/05 17pp 16607 287 24X Fiche 50-000, 82/11/30, 8212290060

--B212290113 Forwards listed documents re IE Insp Repts 50-250/75-17 & 50-251/75-17 Documents filed in LPDR
MOSELEY, N C Region 2, Atlanta, Office of the Director 76/02/13
PEELER, E Florida International Univ 1p 16607 304 24X
Fiche 50-000, 82/11/30, 8212290060

--B212290114 IE Insp Repts 50-250/75-07 & 50-251/75-07 on 750512-14 Deviation observed one tray of control cables in Unit 3 control rod drive room & cable trays exiting auxiliary bldg did not have fire stops installed
HARDIN, A K, LONG, F J Region 2, Atlanta, Office of the Director 75/05/27 9pp 16607 360 24X Fiche 50-000, 82/11/30, 8212290060

--B212290118 Ack receipt of 760202 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-250/75-17 & 50-251/75-17
LONG, F J Region 2, Atlanta, Reactor Operations Nuclear Support Branch 76/02/13 UHRIO, R E Florida Power & Light Co 1p 16607 305 24X Fiche 50-000, 82/11/30, 8212290060

--B212290124 Responds to NRC 760113 ltr re violations noted in IE Insp Repts 50-250/75-17 & 50-251/75-17 Corrective actions drums of radwaste properly barricaded & all licensed operators will be brought up to date w/qualification quiz schedule
UHRIO, R E Florida Power & Light Co 76/02/02 MOSELEY, N C Region 2, Atlanta, Office of the Director 5pp 16607 306 24X
Fiche 50-000, 82/11/30, 8212290060

--B212290129 Forwards IE Insp Repts 50-250/75-17 & 50-251/75-17 on 751209-12 & 16-19 Noncompliance noted
LONG, F J Region 2, Atlanta, Reactor Operations Nuclear Support Branch 76/01/13 UHRIO, R E Florida Power & Light Co 2pp 16607 311 24X Fiche 50-000, 82/11/30, 8212290060

--B212290137 IE Insp Repts 50-250/75-17 & 50-251/75-17 on 751209-12 & 16-19 Noncompliance noted high radiation area improperly barricaded & licensed operator requalification program not fully performed per Administrative Procedure 0301
HARDIN, A K, LEWIS, R C, ROGERS, R F Region 2, Atlanta, Reactor Operations Nuclear Support Branch 76/01/12 18pp 16607 313 24X Fiche 50-000, 82/11/30, 8212290060

B208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies" Svc list encl
DEVOUNO, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259

B208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets" Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X
Fiche 50-000, 82/12/03, 8208190261

B208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring" Svc list encl
DEVOUNO, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16, 8208190267

B208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type TE-27" Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X
Fiche 50-000, 82/12/20, 8208190268

R Periodic operating reports & related correspondence

B212290153 Forwards monthly operating repts for Oct 1982
WILLIAMS, J H Florida Power & Light Co 82/11/15 Office of Resource Management, Director 1p 16582 226 24X
Fiche 50-000, 82/11/15, 8212290153

--B212290169 Monthly operating repts for Oct 1982
PAGE, P Florida Power & Light Co 82/11/15 12pp 16582 227 24X Fiche 50-000, 82/11/15, 8212290153

B21250180 Forwards "Groundwater Monitoring Program Summary Rept, Jul 1981-June 1982"
UHRIO, R E Florida Power & Light Co 82/12/03 O'REILLY, J P Region 2, Office of Director 1p 16427 196 24X
Fiche 50-250, 82/12/03, 821250180

- B21250183 "Groundwater Monitoring Program Summary Rept, Jul 1981-June 1982"
* Dames & Moore 82/07/27 126pp 16427 197 24X
Fiche 50-250, 82/12/03, 821250180

B Reportable occurrences, LERs & related correspondence

B212090356 Forwards updated LER B1-013/02X-2
WILLIAMS, J H Florida Power & Light Co 82/12/02 O'REILLY, J P Region 2, Office of Director 1p 16365 135 24X
Fiche 50-250, 82/12/02, 8212090356

DOCKETED ITEMS

--B212090371 Updated LER B1-013/02X-2 on 810710, small void in concrete found immediately below equipment hatch barrel Cause not stated Similar void confirmed on Unit 4 Voids repaired
BERRY, Z E Florida Power & Light Co 82/12/02 Region 2,
Office of Director 2pp 16365 136 24X Fiche 50-250, 82/12/02,
8212090356

B212100219 Forwards LER B2-015/03L-0
WILLIAMS, J H Florida Power & Light Co 82/12/03 O'REILLY, J P
Region 2, Office of Director 1p 16376 093 24X
Fiche 50-250, 82/12/03, 8212100219

--B212100220 LER B2-015/03L-0 on 821104, during normal operation, 3A high head safety injection pump failed to start from manual operation Cause undetermined Pump breaker racked out & back in Repairs made to breaker
BERRY, Z E Florida Power & Light Co 82/12/03 Region 2,
Office of Director 2pp 16376 094 24X Fiche 50-250, 82/12/03,
8212100219

B212210202 Forwards LER B2-018/01T-0
WILLIAMS, J H Florida Power & Light Co 82/12/15 O'REILLY, J P
Region 2, Office of Director 1p 16484 315 24X
Fiche 50-250, 82/12/15, 8212210202

--B212210207 LER B2-018/01T-0 on 821201, during full power operation, 3A load ctr de-energized following trip of 4-KV breaker 3AA08 Cause undetermined Breaker protective relays will be tested during next outage
BERRY, Z E Florida Power & Light Co 82/12/15 Region 2,
Office of Director 1p 16484 316 24X Fiche 50-250, 82/12/15,
8212210202

B212280164 Forwards LER B2-017/03L-0
WILLIAMS, J H Florida Power & Light Co 82/12/20 O'REILLY, J P
Region 2, Office of Director 1p 16563 220 24X
Fiche 50-250, 82/12/20, 8212280164

--B212280167 LER B2-017/03L-0 on 821119, during control room mods, two fire barrier penetrations disabled intentionally for longer than 7 days Action taken to implement approved design mods to control room
ARIAS, J Florida Power & Light Co 82/12/20 Region 2, Office of Director 1p 16563 221 24X Fiche 50-250, 82/12/20,
8212280164

B212280170 Forwards LER B2-016/03L-0
WILLIAMS, J H Florida Power & Light Co 82/12/20 O'REILLY, J P
Region 2, Office of Director 1p 16563 142 24X
Fiche 50-250, 82/12/20, 8212280170

--B212280173 LER B2-016/03L-0 on 821119, during insp of fire protection sys, fire barrier penetration (laundry room west doors) found nonfunctional New doors/parts ordered & will be installed upon receipt
ARIAS, J Florida Power & Light Co 82/12/20 Region 2, Office of Director 1p 16563 143 24X Fiche 50-250, 82/12/20,
8212280170

DOCKET 50-251 TURKEY POINT PLANT, UNIT 4

F Security, medical, emergency & fire protection plans

B212090529 Forwards IE Insp Repts 50-250/82-11 & 50-251/82-11 on B21004-10 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 82/10/29
UHRIG, R E Florida Power & Light Co 2pp 16366 108 24X
Fiche 50-250, 82/10/29, 8212090529

--B212090540 IE Insp Repts 50-250/82-11 & 50-251/82-11 on B21004-08 No noncompliance noted Major areas inspected followup on previous emergency preparedness findings & experience data on installation & operation of public notification sys
HUFFMAN, D N Division of Emergency Preparedness & Operational Support 82/10/29 19pp 16366 110 24X Fiche 50-250, 82/10/29,
8212090529

B212290060 Partial response to FOIA request for seven categories of info Forwards documents listed in App A Documents 1 & 2 already in PDR App B documents available in PDR LPDR profiles for Ginna & Indian Point 3 encl
FELTON, J H Division of Rules and Records 82/11/30
SCHLESSEL, D A New York, State of 7pp 16607 239 24X
Fiche 50-000, 82/11/30, 8212290060

--B212290094 Responds to NRC 750529 ltr re deviation noted in IE Insp Repts 50-250/75-07 & 50-251/75-07 Corrective actions fire steps installed in cable trays in Unit 4 control rod drive room & entrance to auxiliary bldg above main corridor doors
UHRIG, R E Florida Power & Light Co 75/06/20 MOSELEY, N C
Region 2, Atlanta, Office of the Director 2pp 16607 355 24X
Fiche 50-000, 82/11/30, 8212290060

--B212290114 IE Insp Repts 50-250/75-07 & 50-251/75-07 on 750512-14 Deviation observed one tray of control cables in Unit 3 control rod drive room & cable trays exiting auxiliary bldg did not have fire stops installed
HARBIN, A K Region 2, Atlanta, Office of the Director 75/05/27
9pp 16607 360 24X Fiche 50-000, 82/11/30, 8212290060

J Insurance & indemnity information

B212020335 Forwards Endorsements 60 & 61 to NELIA Policy NF-185 & Endorsements 50 & 51 to MAELU Policy MF-55
FIELDER, J Marsh & McLennan, Inc , M & M Nuclear Consultants, Inc
Div 82/11/18 SALTZMAN, J Assistant Director for State & Licensee Relations 5pp 16279 151 24X Fiche 50-250, 82/11/18, 8212020335

B212300202 Forwards Endorsements 1, 2 & 3 to NELIA Certificate N-25 & N-26 & Endorsements 1, 2 & 3 to MAELU Certificate M-25 & M-26
DUCK, J R Marsh & McLennan, Inc , M & M Nuclear Consultants, Inc
Div 82/12/27 SALTZMAN, J Assistant Director for State & Licensee Relations 37pp 16598 050 24X Fiche 50-250, 82/12/27, 8212300202

B212300243 Forwards Endorsement 62 to NELIA Policy NF-185 & Endorsement 52 to MAELU Policy MF-55
DUCK, J R Marsh & McLennan, Inc , M & M Nuclear Consultants, Inc
Div 82/12/27 SALTZMAN, J Assistant Director for State & Licensee Relations 3pp 16595 273 24X Fiche 50-250, 82/12/27, 8212300243

O Advisory Committee on Reactor Safeguards reports & correspondence

B212070435 Discusses summary of ACRS Reactor Operations Subcommittee 820929 meeting re Turkey Point cold overpressure incident Tech Specs do not properly address situations in which availability of certain sys more vital to safe operation
BINFORD, F T Oak Ridge National Laboratory 82/10/19 MAJOR, R
ACRS - Advisory Committee on Reactor Safeguards 1p 16359 336
24X Fiche 50-250, 82/10/19, 8212070435

P Operating license stage documents & correspondence

B208190263 Generic Ltr B2-32 to all PWR licensees re potential steam generator-related generic requirements Forwards Science Applications, Inc draft rept re subv requirements Comments requested within 30 days of ltr Svc list encl
EISENHUT, D G Division of Licensing 82/12/09 Consolidated
Edison Co of New York, Inc 29pp 16629 247 24X
Fiche 50-000, 82/12/09, 8208190263

B212140103 Generic Ltr B2-28 to all licensees of operating Westinghouse & C-E PWRs (except Arkansas Nuclear One, Unit 2 & San Onofre 2 & 3) re inadequate core cooling instrumentation sys Svc list encl
EISENHUT, D G Division of Licensing 82/12/10 Yankee Atomic
Electric Co 27pp 16690 035 24X Fiche 50-000, 82/12/10,
8212140103

B212210190 Informs that util will utilize Westinghouse optimized Fuel assemblies during Fall 1983 refueling
UHRIG, R E Florida Power & Light Co 82/12/13 EISENHUT, D G
Division of Licensing 1p 16484 353 24X Fiche 50-250, 82/12/13,
8212210190

B212290534 Forwards safety & technical evaluations for environ qualification of safety-related electrical equipment Reaffirmation of justification for continued operation & info re Categories I B, II A & II B requested
VARQA, S A Operating Reactors Branch 1 82/12/13 UHRIG, R E
Florida Power & Light Co 3pp 16608 061 24X
Fiche 50-250, 82/12/13, 8212290534

--B212290535 SER re environ qualification of safety-related electrical equipment
* Operating Reactors Branch 1 82/12/13 5pp 16608 064 24X
Fiche 50-250, 82/12/13, 8212290534

--B210070227 "Review of Licensees Resolution of Outstanding Issues From NRC Equipment Environ Qualification SERs (F-11 & B-60), Turkey Point Unit 4," Vols 1 & 2, technical evaluation rept
PANDEY, S Franklin Institute/Franklin Research Center
NRC-03-79-118 TER-C5257-480 82/09/30 LE, N B NRC - No Detailed Affiliation Given 778pp 16608 069 24X
Fiche 50-250, 82/12/13, 8212290534

--B212290536 "Review of Licensee Resolution of Outstanding Issues From NRC Equipment Environ Qualification SERs (F-11 & B-60)," Vols 1 & 2, technical evaluation rept
PANDEY, S Franklin Institute/Franklin Research Center
TER-C5257-479 82/09/30 LE, N B, GHAMANSKI, P NRC - No Detailed Affiliation Given 807pp 16610 128 24X Fiche 50-250, 82/12/13,
8212290534

82123006B Forwards safety evaluation & technical evaluation rept supporting station electric distribution sys voltages
VARGA, S A Operating Reactors Branch 1 82/12/17 UHRI0, R E
Florida Power & Light Co 2pp 16624 213 24X
Fiche 50-250, 82/12/17, 82123006B

--821230071 SER supporting station electric distribution sys voltages
* Operating Reactors Branch 1 82/12/27 3pp 16624 215 24X
Fiche 50-250, 82/12/17, 82123006B

--8209230424 "Adequacy of Station Electric Distribution Sys Voltages for Turkey Point Nuclear Generating Plant Units 3 & 4," technical evaluation rept
SELAN, J C Lawrence Livermore Laboratory FIN A-0250
UCID-1914B 82/08/08 NRC - No Detailed Affiliation Given
13pp 16624 220 24X Fiche 50-250, 82/12/17, 82123006B

Q Inspection reports, IE Bulletins & correspondence

82100190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel Recirculation Sys Piping at BWR Plants " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc
112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240

8212090529 Forwards IE Insp Repts 50-250/82-11 & 50-251/82-11 on 821004-10 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 82/10/29 UHRI0, R E Florida Power & Light Co 2pp 16366 108 24X
Fiche 50-250, 82/10/29, 8212090529

--8212090540 IE Insp Repts 50-250/82-11 & 50-251/82-11 on 821004-08 No noncompliance noted Major areas inspected followup on previous emergency preparedness findings & experience data on installation & operation of public notification system
HUFFMAN, G N, JEHKINS, G R Division of Emergency Preparedness & Operational Support 82/10/29 19pp 16366 110 24X
Fiche 50-250, 82/10/29, 8212090529

82108190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp
16372 142 24X Fiche 50-000, 82/11/05, 8208190245

8212090490 Forwards IE Insp Repts 50-250/82-31 & 50-251/82-31 on 821018-22 No noncompliance noted
DANCE, H C Region 2, Office of Director 82/11/12 UHRI0, R E Florida Power & Light Co 2pp 16365 344 24X
Fiche 50-250, 82/11/12, 8212090490

--8212090500 IE Insp Repts 50-250/82-31 & 50-251/82-31 on 821018-22 No noncompliance noted Major areas inspected radiation protection program, including qualification of staff, training & radiological protection procedures
MOSELEY, N C, DEBS, B T, BARR, K P Division of Engineering & Technical Programs 82/11/12 10pp 16365 346 24X
Fiche 50-250, 82/11/12, 8212090490

8212090487 Ack receipt of 821029 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-250/82-29 & 50-251/82-29
DANCE, H C Division of Project & Resident Programs 82/11/14 UHRI0, R E Florida Power & Light Co 1p 16366 001 24X
Fiche 50-250, 82/11/16, 8212090487

- 8212090503 Responds to NRC 820929 ltr re violations noted in IE Insp Repts 50-250/82-29 & 50-251/82-29 Corrective actions procedure revised to clarify policy for tagging motor operated valves
UHRI0, R E Florida Power & Light Co 82/10/29 O'REILLY, J P Region 2, Office of Director 2pp 16366 002 24X
Fiche 50-250, 82/11/16, 8212090487

--8212090510 Forwards IE Insp Repts 50-250/82-29 & 50-251/82-29 on 820726-0826 & notice of violation
DANCE, H C Division of Project & Resident Programs 82/09/29 UHRI0, R E Florida Power & Light Co 2pp 16366 004 24X
Fiche 50-250, 82/11/16, 8212090487

--8212090518 Notice of violation from insp on 820726-0826
* Division of Project & Resident Programs 82/09/29 1p 16366 006 24X Fiche 50-250, 82/11/16, 8212090487

--8212090524 IE Insp Repts 50-250/82-29 & 50-251/82-29 on 820726-0826 Noncompliance noted failure to follow equipment clearance procedure for motor operated valve in safety injection sys
VOOT-LOWELL, R, JULIAN, C Division of Project & Resident Programs 82/09/24 6pp 16366 007 24X Fiche 50-250, 82/11/16, 8212090487

82108190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 107pp 16411 199 24X
Fiche 50-000, 82/11/18, 8208190251

8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 045 24X Fiche 50-000, 82/11/26, 8208190256

8208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp
16387 028 24X Fiche 50-000, 82/11/30, 8208190257

8212290060 Partial response to FOIA request for seven categories of info Forwards documents listed in App A Documents 1 & 2 already in PDR App B documents available in PDR LPDR profiles for Ginna & Indian Point 3 encl
FELTON, J M Division of Rules and Records 82/11/30 SCHLISSEL, D A New York, State of 7pp 16607 239 24X
Fiche 50-000, 82/11/30, 8212290060

--8212290064 Ack receipt of 750714 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-250/75-08 & 50-251/75-08
MOSELEY, N C Region 2, Atlanta, Office of the Director 75/08/01 UHRI0, R E Florida Power & Light Co 1p 16607 332 24X
Fiche 50-000, 82/11/30, 8212290060

--8212290068 Responds to NRC 750625 ltr re violation noted in IE Insp Repts 50-250/75-08 & 50-251/75-08 Corrective actions superseded procedures for surveillance testing removed & latest revision placed in control room on 750526
UHRI0, R E Florida Power & Light Co 75/07/14 MOSELEY, N C Region 2, Atlanta, Office of the Director 3pp 16607 333 24X
Fiche 50-000, 82/11/30, 8212290060

--8212290073 Forwards IE Insp Repts 50-250/75-08 & 50-251/75-08 on 750527-30 Noncompliance noted
MOSELEY, N C Region 2, Atlanta, Office of the Director 75/06/25 UHRI0, R E Florida Power & Light Co 2pp 16607 336 24X
Fiche 50-000, 82/11/30, 8212290060

--8212290078 IE Insp Repts 50-250/75-08 & 50-251/75-08 on 750527-30 Noncompliance noted failure to use latest approved procedure in performance of surveillance test
HARDIN, A W, LONG, F J, WILBER, H A Region 2, Atlanta, Office of the Director 75/06/24 13pp 16607 338 24X
Fiche 50-000, 82/11/30, 8212290060

--8212290082 Forwards listed documents re IE Insp Repts 50-250/75-07 & 50-251/75-07 Documents filed in LPDR
MOSELEY, N C Region 2, Atlanta, Office of the Director 75/07/21 GUBER, F T Homestead, FL 1p 16607 353 24X
Fiche 50-000, 82/11/30, 8212290060

--8212290087 Forwards listed documents re IE Insp Repts 50-250/75-16 & 50-251/75-16 Documents filed in LPDR
MOSELEY, N C Region 2, Atlanta, Office of the Director 76/01/05 PEELER, E Florida International Univ 1p 16607 281 24X
Fiche 50-000, 82/11/30, 8212290060

--8212290090 Ack receipt of 750620 ltr informing NRC of steps taken to correct deviation noted in IE Insp Repts 50-250/75-07 & 50-251/75-07
MOSELEY, N C Region 2, Atlanta, Office of the Director 75/07/21 UHRI0, R E Florida Power & Light Co 1p 16607 354 24X
Fiche 50-000, 82/11/30, 8212290060

--8212290092 Ack receipt of 791229 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-250/75-16 & 50-251/75-16
LONG, F J Region 2, Atlanta, Reactor Operations Nuclear Support Branch 76/01/05 UHRI0, R E Florida Power & Light Co 1p 16607 282 24X Fiche 50-000, 82/11/30, 8212290060

--8212290094 Responds to NRC 750529 ltr re deviation noted in IE Insp Repts 50-250/75-07 & 50-251/75-07 Corrective actions fire stops installed in cable trays in Unit 4 control rod drive room & entrance to auxiliary bldg above main corridor doors
UHRI0, R E Florida Power & Light Co 75/06/20 MOSELEY, N C Region 2, Atlanta, Office of the Director 2pp 16607 355 24X
Fiche 50-000, 82/11/30, 8212290060

DOCKETED ITEMS

--B212290097 Responds to NRC 751209 ltr re violation noted in IE Insp Repts 50-250/75-16 & 50-251/75-16 Corrective actions overdue inservice insp rept transmitted to NRC on 751120 & procedure written to describe scheduling & preparation of repts
UHRIG, R E Florida Power & Light Co 75/12/29 MOSELEY, N C Region 2, Atlanta, Office of the Director 2pp 16607 283 24X
Fiche 50-000, 82/11/30, 8212290060

--B212290100 Forwards IE Insp Repts 50-250/75-07 & 50-251/75-07 on 750512-14 Deviation from FSAR commitment observed
MOSELEY, N C Region 2, Atlanta, Office of the Director 75/05/29, UHRIG, R E Florida Power & Light Co 2pp 16607 357 24X
Fiche 50-000, 82/11/30, 8212290060.

--B212290101 Forwards IE Insp Repts 50-250/75-16 & 50-251/75-16 on 751105-21 Noncompliance noted
MOSELEY, N C Region 2, Atlanta, Office of the Director 75/12/09 UHRIG, R E Florida Power & Light Co 2pp 16607 285 24X
Fiche 50-000, 82/11/30, 8212290060

--B212290108 Forwards IE Insp Repts 50-250/75-07 & 50-251/75-07 on 750512-14 Deviation from FSAR commitment observed Licensee requested to inform NRC of plans for implementing FSAR commitment
LONG, F J Region 2, Atlanta, Office of the Director 75/05/27 SEYFRIT, K V Office of Inspection & Enforcement, Office of the Director 1p 16607 359 24X Fiche 50-000, 82/11/30, 8212290060

--B212290109 IE Insp Repts 50-250/75-16 & 50-251/75-16 on 751105-21 Noncompliance noted failure to submit Unit 4 inservice insp rept to NRC within 90 days
HARDIN, A K, LEWIS, R C, HERDT, A R Region 2, Atlanta, Reactor Operations Nuclear Support Branch 75/12/05 17pp 16607 287 24X Fiche 50-000, 82/11/30, 8212290060

--B212290113 Forwards listed documents re IE Insp Repts 50-250/75-17 & 50-251/75-17 Documents filed in LPDR
MOSELEY, N C Region 2, Atlanta, Office of the Director 76/02/13 PEELER, E Florida International Univ 1p 16607 304 24X
Fiche 50-000, 82/11/30, 8212290060

--B212290114 IE Insp Repts 50-250/75-07 & 50-251/75-07 on 750512-14 Deviation observed one tray of control cables in Unit 3 control rod drive room & cable trays exiting auxiliary bldg did not have fire stops installed
HARDIN, A K, LONG, F J Region 2, Atlanta, Office of the Director 75/05/27 9pp 16607 360 24X Fiche 50-000, 82/11/30, 8212290060

--B212290118 Ack receipt of 760202 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-250/75-17 & 50-251/75-17
LONG, F J Region 2, Atlanta, Reactor Operations Nuclear Support Branch 76/02/13 UHRIG, R E Florida Power & Light Co 1p 16607 305 24X Fiche 50-000, 82/11/30, 8212290060

--B212290124 Responds to NRC 760113 ltr re violations noted in IE Insp Repts 50-250/75-17 & 50-251/75-17 Corrective actions drums of radwaste properly barricaded & all licensed operators will be brought up to date w/requalification quiz schedule
UHRIG, R E Florida Power & Light Co 76/02/02 MOSELEY, N C Region 2, Atlanta, Office of the Director 5pp 16607 306 24X
Fiche 50-000, 82/11/30, 8212290060

--B212290129 Forwards IE Insp Repts 50-250/75-17 & 50-251/75-17 on 751209-12 & 16-19 Noncompliance noted
LONG, F J Region 2, Atlanta, Reactor Operations Nuclear Support Branch 76/01/13 UHRIG, R E Florida Power & Light Co 2pp 16607 311 24X Fiche 50-000, 82/11/30, 8212290060

--B212290137 IE Insp Repts 50-250/75-17 & 50-251/75-17 on 751209-12 & 16-19 Noncompliance noted high radiation area improperly barricaded & licensed operator requalification program not fully performed per Administrative Procedure 0301
HARDIN, A K, LEWIS, R C, ROGERS, R F Region 2, Atlanta, Reactor Operations Nuclear Support Branch 76/01/12 18pp 16607 313, 24X Fiche 50-000, 82/11/30, 8212290060

B208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl
DEVOUNO, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp, 16411 317 24X Fiche 50-000, 82/12/03, 8208190259

B208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Baskets " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03, Consolidated Edison Co of New York, Inc 110pp 16462, 064 24X
Fiche 50-000, 82/12/03, 8208190261

B208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
DEVOUNO, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16428 191 24X Fiche 50-000, 82/12/16, 8208190267

B208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27 " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16428 293 24X
Fiche 50-000, 82/12/20, 8208190268

R Periodic operating reports & related correspondence

B212290153 Forwards monthly operating repts for Oct 1982
WILLIAMS, J W Florida Power & Light Co 82/11/15 Office of Resource Management, Director 1p 16582 226 24X
Fiche 50-000, 82/11/15, 8212290153

--B212290169 Monthly operating repts for Oct 1982
PACE, P Florida Power & Light Co 82/11/15 12pp 16582 227 24X Fiche 50-000, 82/11/15, 8212290153

B212150180 Forwards "Groundwater Monitoring Program Summary Rept, Jul 1981-June 1982 "
UHRIG, R E Florida Power & Light Co 82/12/03 O'REILLY, J P Region 2, Office of Director 1p 16427 196 24X
Fiche 50-250, 82/12/03, 8212150180

--B212150183 "Groundwater Monitoring Program Summary Rept, Jul 1981-June 1982 "
* Dames & Moore 82/07/27 126pp 16427 197 24X
Fiche 50-250, 82/12/03, 8212150180

DOCKET 50-254 QUAD-CITIES STATION, UNIT 1

F Security, medical, emergency & fire protection plans

B212030053 Ack receipt of B21108 ltr informing NRC of steps taken to resolve problems identified in IE Emergency Preparedness Appraisal Repts 50-254/82-14 & 50-265/82-16 Clarification re start & stop of 15-minute clock provided
KEPPLER, J O Region 3, Office of Director 82/11/30 REED, C Commonwealth Edison Co 1p 16304 143 24X Fiche 50-254, 82/11/30, 8212030053

--B212030056 Responds to NRC 820930 ltr re problems identified in Paragraph 5 of IE Emergency Preparedness Appraisal Repts 50-254/82-14 & 50-265/82-16 Addl corporate emergency planning positions budgeted for 1983
RAUSCH, T J Commonwealth Edison Co 82/11/08 KEPPLER, J O Region 3, Office of Director 3pp 16304 144 24X
Fiche 50-254, 82/11/30, 8212030053

B212030268 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 82/11/30 Document Management Branch 1p 16316 276 24X Fiche 50-254, 82/11/30, 8212030268

--B212030273 Forwards public version of revised emergency plan implementing procedures, including Procedures GEP 330-6 re air sampling under accident conditions & GEP 330-T9 re air radiation monitoring sys Receipt form encl
KOVACK, T J, GERNER, L Commonwealth Edison Co 82/10/18 DENTON, H R NRC - No Detailed Affiliation Given 1p 16316 278 24X Fiche 50-254, 82/11/30, 8212030268

--B212030279 Public version of revised emergency plan implementing procedures, including Procedures GEP 330-6 re air sampling under accident conditions & GEP 330-T9 re air radiation monitoring sys
* Commonwealth Edison Co 82/10/18 17pp 16316 279 24X
Fiche 50-254, 82/11/30, 8212030268

B212060172 Ack receipt of B21116 ltr informing NRC of steps taken to correct violations noted in NRC 821012 ltr re timeliness of emergency planning exercise submittals
HIND, J A Division of Emergency Preparedness & Operational Support 82/12/01 REED, C Commonwealth Edison Co 1p 16313 086 24X
Fiche 50-254, 82/12/01, 8212060172

--B212060181 Responds to NRC 821012 ltr re timeliness of scenario submittals to FEMA Region VII FEMA Region VII to be included in submittals & meetings associated w/future exercises
RAUSCH, T J Commonwealth Edison Co 82/11/16 KEPPLER, J O Region 3, Office of Director 1p 16313 087 24X
Fiche 50-254, 82/12/01, 8212060172

0212090329 Ack receipt of 821129 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Rpts 50-254/82-20 & 50-265/82-21
MILLER, J R Division of Engineering & Technical Programs 82/12/03
REED, C Commonwealth Edison Co 1p 16365 103 24X
Fiche 50-254, 82/12/03, 8212090325

-8212090338 Responds to NRC 821029 ltr re violations noted in IE Safeguards Insp Rpts 50-254/82-20 & 50-265/82-21 Corrective actions withheld (ref 10CFR73.21)
DELOEDROE, L O Commonwealth Edison Co 82/11/29 KEPLER, J O
Region 3, Office of Director 1p 16365 104 24X
Fiche 50-254, 82/12/03, 8212090325

8212090383 Forwards info re emergency operations facilities per 821122 & 1202 requests Info previously submitted by telcon Request for written response unnecessary burden on licensee
DELOEDROE, L O Commonwealth Edison Co 82/12/03 EISENHUT, D O
Division of Licensing 2pp 16365 051 24X Fiche 50-000, 82/12/03, 8212090383

8212140179 Responds to items re fire protection safe shutdown analysis, discussed in 820917 telephone conference Core can maintain water level above top of active fuel w/o initiation of RCIC flow for max of 14 minutes
RAUSCH, T J Commonwealth Edison Co 82/12/06 EISENHUT, D O
Division of Licensing 3pp 16410 205 24X Fiche 50-254, 82/12/06, 8212140179

8212160127 Ack receipt of 820621 ltr transmitting changes to security plan, Revision 1 Change consistent w/provisions of 10CFR50.54(p) & does not decrease effectiveness of plan
VASSALLO, D B Operating Reactors Branch 2 82/12/06
DELOEDROE, L O Commonwealth Edison Co 3pp 16447 206 24X
Fiche 50-254, 82/12/06, 8212160127

8212130017 Releases public version of Revision 1 to Emergency Plan implementing Procedure EG-2, "Pre-Established Onsite & Offsite Monitoring Locations (Maps)"
FELTON, J M Division of Rules and Records 82/12/07 Document
Management Branch 1p 16417 062 24X Fiche 50-000, 82/12/07, 8212130017

--8212130026 Forwards public version of Revision 1 to Emergency Plan implementing Procedure EG-2, "Pre-Established Onsite & Offsite Monitoring Locations (Maps)" Revised table of contents encl
PAJOWSKI, J Commonwealth Edison Co 82/11/01 DENTON, H R NRC --
No Detailed Affiliation Given 2pp 16417 063 24X
Fiche 50-000, 82/12/07, 8212130017

--8212130041 Public version of Revision 1 to Emergency Plan implementing Procedure EG-2, "Pre-Established Onsite & Offsite Monitoring Locations (Maps)"
PAJOWSKI, J E Commonwealth Edison Co 82/11/29 4pp 16417 065
24X Fiche 50-000, 82/12/07, 8212130017

8212140243 Advises of distribution of revisions to "Generating Station Emergency Plan" Braidwood annex not prepared
TRAUTMAN, T R Commonwealth Edison Co 82/12/07 DENTON, H R Office
of Nuclear Reactor Regulation, Director 2pp 16409 302 24X
Fiche 50-000, 82/12/07, 8212140243

8212220175 Releases public version of revised generating station emergency plan implementing procedures
FELTON, J M Division of Rules and Records 82/12/10 Document
Management Branch 1p 16529 029 24X Fiche 50-000, 82/12/10, 8212220175

--8212220190 Forwards public version of revised generating station emergency plan implementing procedures, including Procedures ED-3 re demand polling of meteorological data & ED-20 re emergency forecast request
PAJOWSKI, J E Commonwealth Edison Co 82/11/15 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 16529 030
24X Fiche 50-000, 82/12/10, 8212220175

--8212220202 Public version of revised generating station emergency plan implementing procedures, including Procedures ED-3 re demand polling of meteorological data & ED-20 re emergency forecast request
LITERBAK, L A Commonwealth Edison Co 82/10/13 48pp
16529 031 24X Fiche 50-000, 82/12/10, 8212220175

8212220306 Discusses layout of communications equipment required in control room, onsite technical support ctr & near-site emergency operations facility
KEPLER, J O Region 3, Office of Director 82/12/16
Commonwealth Edison Co 3pp 16503 351 24X Fiche 50-000, 82/12/16, 8212220306

8212300167 Releases public version of revised generating station emergency plan telephone directory
FELTON, J M Division of Rules and Records 82/12/20 Document
Management Branch 1p 16612 215 24X Fiche 50-000, 82/12/20, 8212300167

--8212300179 Forwards public version of revised generating station emergency plan telephone directory
MOORE, R D Commonwealth Edison Co 82/12/02 DENTON, H R Office
of Nuclear Reactor Regulation, Director 1p 16612 216 24X
Fiche 50-000, 82/12/20, 8212300167

--8212300199 Public version of revised generating station emergency plan telephone directory
GALLE, D P Commonwealth Edison Co 82/11/03 60pp 16612 217
24X Fiche 50-000, 82/12/20, 8212300167

8212300400 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 82/12/22 Document
Management Branch 1p 16613 203 24X Fiche 50-254, 82/12/22, 8212300400

- 8212300405 Forwards public version of revised emergency plan implementing procedures, including Procedures GEP 310-T3 re prioritized notification listing & GEP 360-3 re site evacuation Receipt form encl
* Commonwealth Edison Co 82/12/08 DENTON, H R NRC - No
Detailed Affiliation Given 2pp 16613 204 24X
Fiche 50-254, 82/12/22, 8212300400

--8212300409 Public version of revised emergency plan implementing procedures, including Procedures GEP 310-T3 re prioritized notification listing & GEP 360-3 re site evacuation
* Commonwealth Edison Co 82/12/08 12pp 16613 206 24X
Fiche 50-254, 82/12/22, 8212300400

G Adjudicatory correspondence

8212070160 Memorandum & order granting licensee 820818 request to dismiss proceeding w/o prejudice Util received authority to increase spent fuel pool storage capacity, making shipment of spent fuel between plants unnecessary
JOHNSON, E B, STODER, G J, MILHOLLIN, G L Atomic Safety and
Licensing Board Panel 82/12/03 Commonwealth Edison Co 4pp
16336 320 24X Fiche 50-000, 82/12/03, 8212070160

H General correspondence

8212280176 Notifies of change in mailing address for NRC licensing mail
WRIGHT, O N Illinois, State of, Dept Nuc Safety (formerly Dept
Public Health) 82/12/20 EISENHUT, D O Division of Licensing
1p 16556 135 24X Fiche 50-000, 82/12/20, 8212280176

P Operating license stage documents & correspondence

8211230066 Generic Ltr 82-27 to all BWR licensees of operating reactors except LACBWR, Big Rock Point, Dresden 1, Humboldt Bay, applicants for OL & holders of CP re transmittal of NUREG-0763 & NUREG-0783 Svc list encl W/o stated encl
EISENHUT, D O Division of Licensing 82/11/15 General Public
Utilities - OPU Service Corp 22pp 16387 004 24X
Fiche 50-000, 82/11/15, 8211230066

8212130275 Forwards safety evaluation of DWR owners group 810522, 0921 & 200902 responses to NUREG-0737, Item II K 3 25, "Effect of Loss of AC Power on Pump Seals" Responses acceptable
VASSALLO, D B Operating Reactors Branch 2 82/12/01 DELOEDROE, L
Commonwealth Edison Co 7pp 16418 213 24X Fiche 50-254, 82/12/01, 8212130275

8212160013 Forwards ltrs from engineering firms supporting spent fuel rack mod at facilities Min gap of 2 5 inches between racks does not invalidate previous seismic analyses if racks symmetrically loaded Restoration of 3-inch gap planned
RAUSCH, T J Commonwealth Edison Co 82/12/10 EISENHUT, D O
Division of Licensing, 3pp 16446 074 24X Fiche 50-254, 82/12/10, 8212160013

8212280397 Informs of removal of two metal specimens from reactor vessel, per Tech Spec 6.4-1 requirements
RAUSCH, T J Commonwealth Edison Co 82/12/13 KEPLER, J O Region
3, Office of Director 1p 16561 041 24X Fiche 50-254, 82/12/13, 8212280397

8212220212 Forwards Revision 22 to CE-1-A, "QA Program for Nuclear Generating Stations."
BHARTZ, E D Commonwealth Edison Co 82/12/14 HAAS, W P Quality
Assurance Branch 1p 16518 007 24X Fiche 50-000, 82/12/14, 8212220212

DOCKETED ITEMS

--8212220231 "QA Program for Nuclear Generating Stations," Revision 22
* Commonwealth Edison Co CE-1-A R22 82/11/01 17pp
16518 009 24X Fiche 50-000,82/12/14,8212220212

8212280117 Forwards addl info re NUREG-0737, Item II F 1, "Addl Accident Monitoring Instrumentation," per NRC 821109 request
Pressure monitoring sys provided w/separate loop for narrow range monitoring
SWARTZ, E D Commonwealth Edison Co 82/12/20 EISENHUT, D O
Division of Licensing 9pp 16564 062 24X Fiche 50-000,82/12/20, 8212280117

8212280343 Forwards addl info re NUREG-0737, Items II F 1, 4, 5 & 6
"Containment Pressure, Water Level & Hydrogen Monitoring,"
per Crutchfield 821109 ltr
SWARTZ, E D Commonwealth Edison Co 82/12/20 EISENHUT, D O
Division of Licensing 9pp 16561 053 24X Fiche 50-000,82/12/20, 8212280343

8212290111 Application for amend to License DPR-29, consisting of change to Tech Specs allowing normal power operation for no more than one refueling cycle w/one main steam drain line isolation valve exhibiting excessive leakage w/o Tech Specs
RAUSCH, T J Commonwealth Edison Co 82/12/20 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 16582 241 24X
Fiche 50-254,82/12/20,8212290111

8212290407 Discusses activities & insps performed on feedwater & control rod driveline nozzles during Fall 1982 refueling outage
RAUSCH, T J Commonwealth Edison Co 82/12/20 KEPLER, J O Region 3, Office of Director 3pp 16586 344 24X Fiche 50-254,82/12/20, 8212290407

8212280212 Forwards updated schedule for ongoing environ qualification testing programs per 810528 commitment
SWARTZ, E D Commonwealth Edison Co 82/12/22 EISENHUT, D O
Division of Licensing 18pp 16556 161 24X Fiche 50-000,82/12/22, 8212280212

8212280243 Clarifies position on classification of major mods to BWR Mark 1 Containment per 821216 ltr
RAUSCH, T J Commonwealth Edison Co 82/12/22 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 16561 307 24X
Fiche 50-000,82/12/22,8212280243

8212300138 Confirms 821220 telcon authorization for change to Tech Spec as requested by 821220 ltr Amend revised Tech Spec allowing operation w/one main steam drain isolation valve inoperable
License amend, evaluation & notice of issuance will be sent
LAHNAS, O C Assistant Director for Operating Reactors 82/12/23
DELEGEORGE, L Commonwealth Edison Co 2pp 16624 191 24X
Fiche 50-254,82/12/23,8212300138

Q Inspection reports, IE Bulletins & correspondence

8208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Svc list encl
DEVOUNO, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000,82/10/28,8208190240

8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 601 & Model 802 Thermoluminescent Dosimeters " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/03 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000,82/11/03,8208190245

8212020308 Forwards IE Insp Repts 50-254/82-15 & 50-265/82-17 on 820830-0902 & notice of violation
MILLER, J R Division of Engineering & Technical Programs 82/11/16
REED, C Commonwealth Edison Co 2pp 16278 147 24X
Fiche 50-254,82/11/16,8212020308

--8212020310 Notice of violation from insp on 820830-0902
MILLER, J R Division of Engineering & Technical Programs 82/11/16 1p 16278 149 24X Fiche 50-254,82/11/16,8212020308

--8212020314 IE Insp Repts 50-254/82-15 & 50-265/82-17 on 820830-0902
Noncompliance noted failure to use strong, tight packages for transportation of low specific activity radwaste
HUETER, L J, GRANT, W B, GREGOR, L R Region 3, Office of Director 82/10/12 9pp 16278 150 24X Fiche 50-254,82/11/16,8212020308

8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X
Fiche 50-000,82/11/18,8208190251

8212030187 Forwards IE Insp Repts 50-254/82-18 & 50-265/82-20 on 820908-1022 No noncompliance noted
STREETTER, J F Division of Project & Resident Programs 82/11/19
REED, C Commonwealth Edison Co 2pp 16307 083 24X
Fiche 50-254,82/11/19,8212030187

--8212030197 IE Insp Repts 50-254/82-18 & 50-265/82-20 on 820908-1022 No noncompliance noted Major areas inspected maint-refueling, training,vessel internal insp,reactor scram,feedwater sparger mod & followups on significant events & LERs
CHRISTODIMOS, N, DUPONT, S G, WALKER, R D Region 3, Office of Director 82/11/19 10pp 16307 085 24X Fiche 50-254,82/11/19, 8212030187

8212060191 Forwards IE Insp Repts 50-254/82-21 & 50-265/82-23 on 821026-29 No noncompliance noted
MILLER, J R Division of Engineering & Technical Programs 82/11/23
REED, C Commonwealth Edison Co 2pp 16313 055 24X
Fiche 50-254,82/11/23,8212060191

--8212060197 IE Insp Repts 50-254/82-21 & 50-265/82-23 on 821026-29 No noncompliance noted Major areas inspected normal operational & refueling radiation protection activities, staffing, training & status of certain NUREG-0737 items
HUETER, L J, MILLER, D E, GREGOR, L R Region 3, Office of Director 82/11/23 9pp 16313 057 24X Fiche 50-254,82/11/23, 8212060191

8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list encl
DEVOUNO, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 049 24X Fiche 50-000,82/11/26,8208190256

8208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000,82/11/30,8208190257

8212030053 Ack receipt of 821108 ltr informing NRC of steps taken to resolve problems identified in IE Emergency Preparedness Appraisal Repts 50-254/82-14 & 50-265/82-16 Clarification re start & stop of 15-minute clock provided
KEPLER, J O Region 3, Office of Director 82/11/30 REED, C Commonwealth Edison Co 1p 16304 143 24X Fiche 50-254,82/11/30, 8212030053

--8212030056 Responds to NRC 820930 ltr re problems identified in Paragraph 5 of IE Emergency Preparedness Appraisal Repts 50-254/82-14 & 50-265/82-16 Addl corporate emergency planning positions budgeted for 1983
RAUSCH, T J Commonwealth Edison Co 82/11/08 KEPLER, J O Region 3, Office of Director 3pp 16304 144 24X
Fiche 50-254,82/11/30,8212030053

8212060029 Forwards response to IE Bulletin 82-03 re stress corrosion cracking in thick wall, large diameter stainless steel recirculation sys piping at DWRs Dresden response only addresses Item 4 Other info will be provided by startup
RAUSCH, T J Commonwealth Edison Co 82/12/01 KEPLER, J O Region 3, Office of Director 10pp 16313 288 24X Fiche 50-000,82/12/01, 8212060029

8212080537 Forwards response to Revision 1 to IE Bulletin 82-03 re stress corrosion cracking in thick-wall, large diameter stainless steel recirculation sys piping Addl info for Dresden 2 due prior to startup from Spring 1983 outage
RAUSCH, T J Commonwealth Edison Co 82/12/01 KEPLER, J O Region 3, Office of Director 10pp 16352 056 24X Fiche 50-000,82/12/01, 8212080537

8208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl
DEVOUNO, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000,82/12/03,8208190259

8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X
Fiche 50-000,82/12/03,8208190261

8212090325 Ack receipt of 821129 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Repts 50-254/82-20 & 50-265/82-21
MILLER, J R Division of Engineering & Technical Programs 82/12/03
REED, C Commonwealth Edison Co 1p 16365 103 24X
Fiche 50-254,82/12/03,8212090325

--B212090338 Responds to NRC B21029 ltr re violations noted in IE Safeguards Insp Repts 50-254/B2-20 & 50-265/B2-21 Corrective actions withheld (ref 10CFR73 21)
DELOERGE, L O Commonwealth Edison Co B2/11/29 KEPPLER, J G
Region 3, Office of Director 1p 16365 104 24X
Fiche 50-254, B2/12/03, B212090325

B212100145 Discusses until B21001 response to IE Insp Repts 50-254/B2-13 & 50-265/B2-15 re multiplet analysis capability in AAIS software Alternative in-depth review of AAIS acceptable, provided that NRC concerns addressed in review
PAPERIELLO, C J Division of Emergency Preparedness & Operational Support B2/12/06 RAUSCH, T J Commonwealth Edison Co 1p 16376 042 24X Fiche 50-254, B2/12/06, B212100145

B208190267 IE Info Notice B2-49, "Correction for Sample Conditions for Air & Gas Monitoring" Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement B2/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, B2/12/16, B208190267

B212270295 Ack receipt of B21124 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-237/B2-21, 50-249/B2-22, 50-254/B2-17 & 50-265/B2-19
NORELIUS, C E Division of Engineering & Technical Programs B2/12/16 REED, C Commonwealth Edison Co 2pp 16530 089 24X Fiche 50-000, B2/12/16, B212270295

--B212270303 Responds to NRC B21026 ltr re violations noted in IE Insp Repts 50-237/B2-21, 50-249/B2-22, 50-254/B2-17 & 50-265/B2-19 Corrective actions annual audits of all active AE firms performing safety-related work required
DELOERGE, L O Commonwealth Edison Co B2/11/24 KEPPLER, J G
Region 3, Office of Director 4pp 16530 087 24X
Fiche 50-000, B2/12/16, B212270295

--B212270307 "EDS-NUTECH Interface Control Instructions," Revision 0
TSHUDJI, W F NUTECH (Nuclear Technology, Inc.) B2/09/30 22pp 16530 091 24X Fiche 50-000, B2/12/16, B212270295

--B212270313 "IE Bulletin 79-14 & TAP Piping Evaluation, Quad Cities Units 1 & 2 & Dresden Units 2 & 3," Revision 0
* NUTECH (Nuclear Technology, Inc.) B2/10/01 9pp 16530 113 24X Fiche 50-000, B2/12/16, B212270295

B212270346 Forwards IE Insp Repts 50-254/B2-25 & 50-265/B2-27 on B21115-19 No noncompliance noted
LITTLE, W S Division of Engineering & Technical Programs B2/12/16 REED, C Commonwealth Edison Co 2pp 16586 177 24X Fiche 50-254, B2/12/16, B212270346

--B212270348 IE Insp Repts 50-254/B2-25 & 50-265/B2-27 on B21115-19 No noncompliance noted Major areas inspected nonlicensed personnel & licensed operator requalification training procedures & records & surveillance scheduling program
FARRELL, R C, PESCHEL, J H, HAWKINS, F C Division of Engineering & Technical Programs B2/12/14 3pp 16586 179 24X Fiche 50-254, B2/12/16, B212270346

B212280110 Provides final status rept of IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Bys" Complete & final listings of portions of sys failing to meet FSAR requirements under NUTECH responsibility encl
RAUSCH, T J Commonwealth Edison Co B2/12/17 KEPPLER, J G Region 3, Office of Director 3pp 16564 191 24X Fiche 50-000, B2/12/17, B212280110

B208190268 IE Info Notice B2-50, "Mod of Solid State AC Undervoltage Relays Type 17E-27" Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance B2/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X Fiche 50-000, B2/12/20, B208190268

B212290407 Discusses activities & insps performed on feedwater & control rod drive line nozzles during Fall 1982 refueling outage
RAUSCH, T J Commonwealth Edison Co B2/12/20 KEPPLER, J G Region 3, Office of Director 3pp 16986 344 24X Fiche 50-254, B2/12/20, B212290407

R Periodic operating reports & related correspondence

B212140443 "Evaluation of Quad Cities Nuclear Power Station - Commonwealth Edison Co, 1982"
* Institute of Nuclear Power Operations B2/11/08 37pp, 16405 210 24X Fiche 50-254, B2/11/08, B212140443

B212130196 Forwards monthly operating reports for Nov 1982
KALIVIANAKIS, N Commonwealth Edison Co B2/12/01 Director's Office, Office of Inspection and Enforcement 1p 16396 151 24X Fiche 50-254, B2/12/01, B212130196

--B212130202 Monthly operating reports for Nov 1982
BUSS, R D Commonwealth Edison Co B2/12/01 21pp 16396 152 24X Fiche 50-254, B2/12/01, B212130196

DOCKET 50-255 PALISADES NUCLEAR PLANT

F Security, medical, emergency & fire protection plans

B212070300 Documents B21202 telcon re emergency operations facility Facilities for four plants completed Table encl
VANDEWALLE, D J Consumers Power Co B2/12/03 CRUTCHFIELD, D
Operating Reactors Branch 5 2pp 16343 156 24X
Fiche 50-000, B2/12/03, B212070300

B212090409 Submits addl info in response to NRC B20701 questions re fire protection Exemption request re disconnect/connect procedure of leads at penetration for auxiliary shutdown panel source range monitor encl
JOHNSON, R D Consumers Power Co B2/12/06 CRUTCHFIELD, D
Operating Reactors Branch 5 3pp 16365 008 24X
Fiche 50-255, B2/12/06, B212090409

B212100218 Responds to B21109 ltr re Revision 5 to security plan Modified screening program changes submitted as Revision 6 in B21105 ltr
VANDEWALLE, D J Consumers Power Co B2/12/08 CRUTCHFIELD, D
Operating Reactors Branch 5 1p 16376 073 24X
Fiche 50-000, B2/12/08, B212100218

B212100285 Advises that changes to security & suitability, training & qualifications plans submitted B21105 do not decrease safeguards effectiveness NRC approval of changes in accordance w/10CFR50 54(p) not required
VANDEWALLE, D J Consumers Power Co B2/12/08 CRUTCHFIELD, D
Operating Reactors Branch 5 1p 16377 145 24X
Fiche 50-000, B2/12/08, B212100285

B212130203 Forwards Safeguards Div regulatory effectiveness review conducted on B20913-17 Response requested within 30 days
Encl withheld (ref 10CFR73 21)
CRUTCHFIELD, D Operating Reactors Branch 5 B2/12/09
VANDEWALLE, D J Consumers Power Co 2pp 16396 179 24X
Fiche 50-255, B2/12/09, B212130203

B212230275 Forwards response to IE Safeguards Insp Rept 50-255/B2-25 Response withheld (ref 10CFR73 21)
VANDEWALLE, D J Consumers Power Co B2/12/15 CRUTCHFIELD, D
Operating Reactors Branch 5 1p 16507 359 24X
Fiche 50-255, B2/12/15, B212230275

B212220306 Discusses layout of communications equipment required in control room, onsite technical support ctr & near-site emergency operations facility
KEPPLER, J G Region 3, Office of Director B2/12/16
Commonwealth Edison Co 3pp 16503 351 24X Fiche 50-000, B2/12/16, B212220306

B212280382 Confirms B21221 telcon extending due date for response to NRC B21213 ltr on regulatory effectiveness review to B30201 Security-related findings & observations will be addressed
VANDEWALLE, D J Consumers Power Co B2/12/22 CRUTCHFIELD, D
Operating Reactors Branch 5 1p 16558 362 24X
Fiche 50-255, B2/12/22, B212280382

D Advisory Committee on Reactor Safeguards reports & correspondence

B212010502 Summary of 265th ACRS meeting on B20806-08 in Washington, DC re Ginna restart safety evaluation, Wolf Creek OL review, Palisades SEP review, emergency response capability of plants & safety-related equipment qualification program
* ACRS - Advisory Committee on Reactor Safeguards B2/11/26
ACRS - Advisory Committee on Reactor Safeguards 605pp 16294 131 24X Fiche 50-000, B2/11/26, B212010502

P Operating license stage documents & correspondence

B212140001 Addl response to FOIA request for five categories of documents re SEP Forwards documents listed in App A No documents located subg to Item 3 of request Review of remaining documents continuing Documents available in PDR
FELTON, J M Division of Rules and Records B2/11/03 QALLD, J
Isham, Lincoln & Beale 2pp 16433 354 24X Fiche 50-000, B2/11/03, B212140001

--7907300565 Discusses pipe support mods made as result of seismic design analysis problems Agrees piping systems as modified conform to ANSI B 31.1 Related info encl
SILVER, R D Operating Reactors Branch 2 (Pre 790625) 79/06/18
EISENHUT, D Q Division of Operating Reactors 14pp 16436 025 24X Fiche 50-000, B2/11/03, B212140001

DOCKETED ITEMS

- B002200995 Notifies that review & performance of audit calculations to be continued per contract & preliminary review work to be completed at LaCrosse Code used for reanalysis of piping sys requires benchmarking per code verification program
SHAD, L C Assistant Director for Engineering Programs 79/10/30
EISENHUT, D G Division of Operating Reactors 1p 16435 111
24X Fiche 50-000, 82/11/03, 8212140001
- B005280555 Forwards rept, "Role of Radiation Damping in Impedance Function Approach to Soil-Structure Interaction Analysis," prepared by NCT Engineering, Inc
MURRAY, R C Lawrence Livermore Laboratory 80/05/19 ALLISON, D
Systematic Evaluation Program Branch 1p 16435 112 24X
Fiche 50-000, 82/11/03, 8212140001
- B005280561 "Role of Radiation Damping in Impedance Function Approach to Soil-Structure Interaction Analysis " Prepared for LLL
TSAL, T NCT Engineering, Inc FIN A-0233 80/05/31 NRC - No
Detailed Affiliation Given 50pp 16435 113 24X
Fiche 50-000, 82/11/03, 8212140001
- B101080118 Trip rept of B01117-19 site visit to observe site-specific features re SEP structural, electrical & sys topic review
Related info encl
MICHAELS, T S Technical Support Branch 80/12/17 RUSSELL, W T
Technical Support Branch 171pp 16436 120 24X
Fiche 50-000, 82/11/03, 8212140001
- B201180567 Forwards Mechanical Engineering Branch review of SEP Topic III-5 D, "High Energy Line Break Outside Containment " High energy line break analysis of auxiliary feedwater sys to be included in licensee response to NUREG-0737 Item II E 1.1
KNIGHT, J P Assistant Director for Components & Structures Engineering 81/12/24 LAINAS, G C Assistant Director for Safety Assessment 10pp 16436 067 24X Fiche 50-000, 82/11/03, 8212140001
- B202180460 Forwards Revision 1 to evaluation rept on SEP Topic VI-4, "Containment Isolation Sys," for facility Rept considers util comments received in B10810 & B20104 ltrs Conclusions of original rept remain unchanged
SPEIS, T P Assistant Director for Reactor Safety 82/01/27
LAINAS, G Assistant Director for Safety Assessment 43pp 16436 078 24X Fiche 50-000, 82/11/03, 8212140001
- B204270491 Submits comments on SEP Topic III-6, "Seismic Design Considerations "
JOHNSTON, H V Assistant Director for Materials & Qualifications Engineering 82/03/30 VOLLMER, R H Division of Engineering 1p 16436 077 24X Fiche 50-000, 82/11/03, 8212140001
- B212070192 Forwards Amend 71 to License DPR-20 & notice of issuance & availability Amend revises Tech Specs to allow revised testing intervals for RHR sys
CRUTCHFIELD, D Operating Reactors Branch 5 82/12/01
VANDEWALLE, D J Consumers Power Co 3pp 16335 118 24X
Fiche 50-255, 82/12/01, 8212070192
- B212070201 Amend 71 to License DPR-20, revising Tech Specs to allow revised testing intervals for RHR sys
CRUTCHFIELD, D Operating Reactors Branch 5 82/12/01 5pp 16335 121 24X Fiche 50-255, 82/12/01, 8212070192
- B212070210 Notice of issuance & availability of Amend 71 to License DPR-20
CRUTCHFIELD, D Operating Reactors Branch 5 82/12/01 2pp 16335 126 24X Fiche 50-255, 82/12/01, 8212070192
- B212080340 Forwards SEP supporting util implementation of TMI Items II B 4, "Training for Mitigating Core Damage" & I A 2.1, "Immediate Upgrading of Reactor Operator & Senior Reactor Operator Training & Qualifications "
CRUTCHFIELD, D Operating Reactors Branch 5 82/12/02
VANDEWALLE, D J Consumers Power Co 4pp 16352 085 24X
Fiche 50-255, 82/12/02, 8212080340
- B209030322 "Improvements in Training & Requalification Programs As Required by TMI Action Items I A 2.1 & II B 4 for Palisades Nuclear Plant," technical evaluation rept
Science Applications, Inc NRC-02-82-095 SAT-186-029-20
82/08/31 NRC - No Detailed Affiliation Given 16pp, 16352 087 24X Fiche 50-255, 82/12/02, 8212080340
- B212130224 Forwards, "SEP, High Energy Line Breaks Inside Containment, Palisades Nuclear Station, Phase IV Summary of Results, Revision 0 " Rept incorporates results of fracture mechanics analysis
TOHER, K A EDS Nuclear, Inc 82/12/09 CRUTCHFIELD, D Operating Reactors Branch 5 2pp 16397, 017 24X Fiche 50-255, 82/12/09, 8212130224
- B212130229 "SEP, High Energy Line Breaks Inside Containment, Palisades Nuclear Station, Phase IV Summary of Results "
EDS Nuclear, Inc 02-0540-1108 R00 82/11/30 317pp 16397 019 24X Fiche 50-255, 82/12/09, 8212130224
- B212200070 Forwards application to amend License DPR-20, changing Tech Spec Section 3.3.1 & Table 4.2.1 to reduce required boron concentration in safety injection tank T-B2B for remainder of Cycle 5
VANDEWALLE, D J Consumers Power Co 82/12/15 CRUTCHFIELD, D
Operating Reactors Branch 5 1p 16473 342 24X
Fiche 50-255, 82/12/15, 8212200070
- B212200075 Application to amend License DPR-20, changing Tech Spec Section 3.3.1 & Table 4.2.1 to reduce required boron concentration in safety injection tank T-B2B for remainder of Cycle 5
DEWITT, R B Consumers Power Co 82/12/15 2pp 16473 343 24X
Fiche 50-255, 82/12/15, 8212200070
- B212200082 Proposed changes to Tech Spec Section 3.3.1 & Table 4.2.1 to reduce required boron concentration in safety injection tank T-B2B for remainder of Cycle 5
Consumers Power Co 82/12/15 3pp 16473 345 24X
Fiche 50-255, 82/12/15, 8212200070
- B212210459 Forwards safety evaluation & technical evaluation rept re TMI Action Item II E 1.2, "Auxiliary Feedwater Sys Automatic Initiation & Flow Indication " Sys comply w/NRC long-term safety requirements
CRUTCHFIELD, D Operating Reactors Branch 5 82/12/16
VANDEWALLE, D J Consumers Power Co 4pp 16489 149 24X
Fiche 50-255, 82/12/16, 8212210459
- B209140103 "Auxiliary Feedwater Sys Automatic Initiation & Flow Indication," technical evaluation rept
KAUCHER, J E Franklin Institute/Franklin Research Center
NRC-03-79-118 TER-C5257-298 82/09/08 KENDALL, R NRC - No
Detailed Affiliation Given 15pp 16489 153 24X
Fiche 50-255, 82/12/16, 8212210459
- B212280083 Forwards application for amend to License DPR-20, changing Tech Specs Section 6 re administrative controls, to include revised working hour guidelines per NRC Generic Ltr 82-12 & NUREG-0737, Item I A 1.3
VANDEWALLE, D J Consumers Power Co 82/12/20 CRUTCHFIELD, D
Operating Reactors Branch 5 2pp 16565 096 24X
Fiche 50-255, 82/12/20, 8212280083
- B212280089 Application for amend of License DPR-20, changing Tech Specs Section 6 re administrative controls, to include revised working hour guidelines per NRC Generic Ltr 82-12 & NUREG-0737, Item I A 1.3
DEWITT, R B Consumers Power Co 82/12/20 6pp 16565 098 24X
Fiche 50-255, 82/12/20, 8212280083
- B212280094 Proposed changes to Tech Specs Section 6 re administrative controls
Consumers Power Co 82/12/20 23pp 16565 104 24X
Fiche 50-255, 82/12/20, 8212280083
- B212300031 Forwards Amend 72 to License DPR-20 & notice of issuance & availability Amend changes Tech Specs re SEP Topics III-7 C, V-10 B & V-11 A
CRUTCHFIELD, D Operating Reactors Branch 5 82/12/21
VANDEWALLE, D J Consumers Power Co 3pp 16598 164 24X
Fiche 50-255, 82/12/21, 8212300031
- B212300038 Amend 72 to License DPR-20, changing Tech Specs re SEP Topics III-7 C, "Dome Delamination," V-10 B, "RHR Sys Reliability" & V-11 A, "Requirements for Isolation of High & Low Pressure Sys "
CRUTCHFIELD, D Operating Reactors Branch 5 82/12/21 9pp 16598 167 24X Fiche 50-255, 82/12/21, 8212300031
- B212300044 Notice of issuance & availability of Amend 72 to License DPR-20
CRUTCHFIELD, D Operating Reactors Branch 5 82/12/21 2pp 16598 176 24X Fiche 50-255, 82/12/21, 8212300031
- Q Inspection Reports, IE Bulletins & correspondence
- B208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Svc list encl
DEVOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co. of New York, Inc
112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240

8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards
82/11/05 Consolidated Edison Co of New York, Inc 110pp
16372 142 24X Fiche 50-000, 82/11/05, 8208190245

8212030121 Forwards IE Insp Rept 50-255/82-26 on 821001-31 No noncompliance noted
STREETER, J F Division of Project & Resident Programs 82/11/17
DEWITT, R B Consumers Power Co 2pp 16303 291 24X
Fiche 50-255, 82/11/17, 8212030121

--8212030129 IE Insp Rept 50-255/82-26 on 821001-31 No noncompliance noted Major areas inspected operational safety verification, plant trip review, monthly maint, monthly surveillance, design changes & mods & independent insp effort
JORGENSEN, B L, HELLER, J K, BOYD, D C Division of Project & Resident Programs 82/11/16 6pp 16303 293 24X
Fiche 50-255, 82/11/17, 8212030121

8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18
Consolidated Edison Co of New York, Inc 109pp 16411 199 24X
Fiche 50-000, 82/11/18, 8208190251

8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Radiolocks " Svc list encl
DEVOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000, 82/11/26, 8208190256

8212020347 Forwards response to 821006 request to rescind Provisions A 1 & C of NRC 810309 order to upgrade regulatory performance Consideration based on NRR approval of 821112 Tech Spec change request re safety mgt function
KEPPLER, J G Region 3, Office of Director 82/11/26 DEWITT, R B Consumers Power Co 1p 16278 177 24X Fiche 50-255, 82/11/26, 8212020347

--8212020351 Requests recinding NRC 810309 order to upgrade regulatory performance due to significant improvement over last 1 5-yrs Schedule for action discussed
VANDEWALLE, D J Consumers Power Co 82/10/06 KEPPLER, J G Region 3, Office of Director 2pp 16278 178 24X
Fiche 50-255, 82/11/26, 8212020347

8208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards
82/11/30 Consolidated Edison Co of New York, Inc 356pp
16387 028 24X Fiche 50-000, 82/11/30, 8208190257

8212170087 Forwards IE Insp Rept 50-255/82-27 on 821118 No noncompliance noted
LITTLE, W S Division of Engineering & Technical Programs 82/11/30
DEWITT, R B Consumers Power Co 2pp 16451 001 24X
Fiche 50-255, 82/11/30, 8212170087

--8212170094 IE Insp Rept 50-255/82-27 on 821118 No noncompliance noted Major areas inspected 10CFR21 activities, previous insp findings & IC Bulletin 78-14 & 82-02 activities
WARD, K D, DANIELSON, D H Region 3, Office of Director 82/11/29 3pp 16452 003 24X Fiche 50-255, 82/11/30, 8212170087

8212280330 Responds to request for plans for corrective action re 821028 IE Insp Rept 50-255/82-22 concerning radiological environ monitoring program Corrective actions instituted to eliminate weaknesses Completion dates listed
JOHNSON, D D Consumers Power Co 82/12/02 KEPPLER, J G Region 3, Office of Director 3pp 16560 094 24X Fiche 50-255, 82/12/02, 8212280330

8208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl
DEVOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259

8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03
Consolidated Edison Co of New York, Inc 110pp 16462 064 24X
Fiche 50-000, 82/12/03, 8208190261

8212230275 Forwards response to IE Safeguards Insp Rept 50-255/82-25 Response withheld (ref 10CFR73 21)
VANDEWALLE, D J Consumers Power Co 82/12/15 CRUTCHFIELD, D Operating Reactors Branch 5 1p 16507 359 24X
Fiche 50-255, 82/12/15, 8212230275

8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
DEVOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16, 8208190267

8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type 1TE-27 " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20
Consolidated Edison Co of New York, Inc 108pp 16628 293 24X
Fiche 50-000, 82/12/20, 8208190268

R Periodic operating reports & related correspondence

8212130247 Forwards monthly operating rept for Nov 1982
KENNEDY, D M Consumers Power Co 82/12/06 NRC - No Detailed Affiliation Given 1p 16396 216 24X Fiche 50-255, 82/12/06, 8212130247

--8212130250 Monthly operating rept for Nov 1982
PETERSON, D A Consumers Power Co 82/12/06 3pp 16396 217 24X Fiche 50-255, 82/12/06, 8212130247

S Reportable occurrences, LERs & related correspondence

8212020325 Forwards LER 82-040/03L-0
JOHNSON, R D Consumers Power Co 82/11/23 KEPPLER, J G Region 3, Office of Director 1p 16279 160 24X Fiche 50-255, 82/11/23, 8212020325

--8212020331 LER 82-040/03L-0 from 821028-1118, safety injection tank B level reached Tech Spec limits 13 times Caused by minor leakage past loop check valve & tank check valve or fill & drain valve Loss of level indication compounded problem
* Consumers Power Co 82/11/23 Region 3, Office of Director 3pp 16279 161 24X Fiche 50-255, 82/11/23, 8212020325

8212060357 Forwards nonradiological NPDES permit violation repts for May-Oct 1982
JOHNSON, D D Consumers Power Co 82/11/24 KEPPLER, J G Region 3, Office of Director 1p 16311 009 24X Fiche 50-255, 82/11/24, 8212060357

--8212060371 NPDES noncompliance notification on 821004, max measured TRC value in mixing basin was 0.75 ppm during chlorination of cooling tower A Caused by excessive chlorine feed for plant conditions Chlorination terminated
F08ES, R L Consumers Power Co 82/10/13 1p 16311 010 24X
Fiche 50-255, 82/11/24, 8212060357

--8212060382 NPDES noncompliance notification on 820927, routine weekly sample for oil & grease collected measured 23.0 mg/l Caused by malfunction of emulsion breaker & oil removal sys Emulsion breaker oil filters changed
F08ES, R L Consumers Power Co 82/10/12 1p 16311 011 24X
Fiche 50-255, 82/11/24, 8212060357

--8212060392 NPDES noncompliance notification on 820920, routine weekly oil & grease sample collected measured 123 mg/l Caused by malfunction of emulsion breaker sys Emulsion breaker oil filters changed on 820921
F08ES, R L Consumers Power Co 82/10/01 1p 16311 012 24X
Fiche 50-255, 82/11/24, 8212060357

--8212060396 NPDES noncompliance notification on 820731, daily max limit of 20 mg/l for oil & grease was exceeded & days, resulting in monthly average limit of 15 mg/l being exceeded Cause unknown Oil absorbent pillows changed
F08ES, R L Consumers Power Co 82/08/16 1p 16311 013 24X
Fiche 50-255, 82/11/24, 8212060357

--8212060412 NPDES noncompliance notification on 820722 & 23, routine oil & grease samples measured 26.5 mg/l & 31.8 mg/l, respectively Cause unknown Oil absorbent pillows changed & floating oil removal devices emptied
F08ES, R L Consumers Power Co 82/08/06 1p 16311 014 24X
Fiche 50-255, 82/11/24, 8212060357

--8212060421 NPDES noncompliance notification on 820720, routine oil & grease sample indicated 23.5 mg/l concentration Cause unknown Oil absorbent pillows in tank 7-41 changed
F08ES, R L Consumers Power Co 82/07/30 1p 16311 015 24X
Fiche 50-255, 82/11/24, 8212060357

--8212060431 NPDES noncompliance notification on 820712, 13 & 14, routine oil & grease samples indicated 21.7 mg/l, 25.5 mg/l & 112.5 mg/l respectively Caused by clogged oil removal filters in emulsion breaking sys Oil filters changed
F08ES, R L Consumers Power Co 82/07/22 1p 16311 016 24X
Fiche 50-255, 82/11/24, 8212060357

DOCKETED ITEMS

--B21206044 NPDES noncompliance notification on B20628, 29 & 30, routine oil & grease samples indicated 37.7 mg/l, 23.1 mg/l & 20.8 mg/l, respectively. Caused by malfunction of oil treatment skid & associated equipment. Oil removal filters changed.
ZIMMERMAN, R L Consumers Power Co B2/07/07 3pp 16311 017
24X Fiche 50-255, B2/11/24, B212060357

B212060067 Forwards LER B2-042/01T-0
JOHNSON, B D Consumers Power Co B2/11/29 KEPLER, J O Region 3,
Office of Director 1p 16314 293 24X Fiche 50-255, B2/11/29,
B212060067

--B212060073 LER B2-042/01T-0 on B21112, monthly sample of T-B2D (D safety injection tank) showed boron concentration below Tech Spec limit. Caused by minor leakage past loop check valve & tank check valve. Primary coolant leak monitored.
* Consumers Power Co B2/11/29 Region 3, Office of Director
2pp 16314 294 24X Fiche 50-255, B2/11/29, B212060067

B212080261 Forwards LER B2-041/03L-0
JOHNSON, B D Consumers Power Co B2/11/30 KEPLER, J O Region 3,
Office of Director 1p 16354 203 24X Fiche 50-255, B2/11/30,
B212080261

--B212080271 LER B2-041/03L-0 on B21030, during startup, primary cooling sys sample indicated dose-equivalent 1-131 at 1.38 mCi exceeding 1.0 mCi limit. Caused by iodine spiking after change in thermal power. Purification flow increased.
* Consumers Power Co B2/11/30 Region 3, Office of Director
4pp 16354 204 24X Fiche 50-255, B2/11/30, B212080261

B212100313 Forwards LER B2-043/03L-0
JOHNSON, B D Consumers Power Co B2/12/02 KEPLER, J O Region 3,
Office of Director 1p 16377 066 24X Fiche 50-255, B2/12/02,
B212100313

--B212100317 LER B2-043/03L-0 on B21102, T-B2D (D safety injection tank) level dropped below Tech Spec limit of 186 inches. Level indicating sys & associated alarms failed to respond to level change. Caused by leakage past fill & drain valve.
* Consumers Power Co B2/12/02 Region 3, Office of Director
1p 16377 067 24X Fiche 50-255, B2/12/02, B212100313

B212100248 RD on B21203, safety injection tank T-B2B boron concentration fell below Tech Specs & could not be restored within required 1-h limit.
KRICH, R M Consumers Power Co B2/12/03 KEPLER, J O Region 3,
Office of Director 3pp 16376 114 24X Fiche 50-255, B2/12/03,
B212100248

B212270215 Forwards LER B2-044/01T-0
JOHNSON, B D Consumers Power Co B2/12/13 KEPLER, J O Region 3,
Office of Director 1p 16536 203 24X Fiche 50-255, B2/12/13,
B212270215

--B212270228 LER B2-044/01T-0 on B21130, determined that feed breakers & cables to MCC-1 & MCC-2 might overload following LOCA. Caused by original load study based on incorrect data. New requirements to shed loads instituted.
* Consumers Power Co B2/12/13 Region 3, Office of Director
2pp 16536 204 24X Fiche 50-255, B2/12/13, B212270215

B212280460 Forwards LER B2-045/01T-0
JOHNSON, B D Consumers Power Co B2/12/15 KEPLER, J O Region 3,
Office of Director 1p 16536 015 24X Fiche 50-255, B2/12/15,
B212280460

--B212280464 LER B2-045/01T-0 on B21203, T-B2B safety injection tank B level reached limit of 198 inches w/boron concentration below limit. Caused by minor leakage past loop check valve & tank check valve or fill & drain valve. Leak rate monitored.
* Consumers Power Co B2/12/15 Region 3, Office of Director
2pp 16536 016 24X Fiche 50-255, B2/12/15, B212280460

DOCKET 50-259 BROWNS FERRY NUCLEAR POWER STATION, UNIT 1

F Security, medical, emergency & fire protection plans

B212030212 Act receipt of B21119 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Repts 50-259/B2-30, 50-260/B2-30 & 50-296/B2-30
LEWIS, R C Division of Project & Resident Programs B2/11/30
PARRIS, H O Tennessee Valley Authority 1p 16307 067 24X
Fiche 50-259, B2/11/30, B212030212

--B212030220 Responds to NRC B21019 ltr re violations noted in IE Safeguards Insp Repts 50-259/B2-30, 50-260/B2-30 & 50-296/B2-30. Corrective actions withheld (ref 10CFR73.21)
MILLS, L M Tennessee Valley Authority B2/11/19 O'REILLY, J P
Region 2, Office of Director 1p 16307 068 24X
Fiche 50-259, B2/11/30, B212030212

--B212030226 Forwards IE Safeguards Insp Repts 50-259/B2-30, 50-260/B2-30 & 50-296/B2-30 on B20920-24 & notice of violation Rept details & notice of violation withheld (ref 10CFR73.21)
LEWIS, R C Division of Project & Resident Programs B2/10/19
PARRIS, H O Tennessee Valley Authority 2pp 16307 069 24X
Fiche 50-259, B2/11/30, B212030212

--B212030232 IE Insp Repts 50-259/B2-30, 50-260/B2-30 & 50-296/B2-30 on B20920-24. Noncompliance noted in areas of locks, keys & combinations, physical barriers - protected areas, lighting & access control. Details withheld (ref 10CFR73.21)
HALL, B L Division of Engineering & Technical Programs B2/10/14
2pp 16307 071 24X Fiche 50-259, B2/11/30, B212030212

B212080100 Releases public version of revised radiological emergency plan implementing procedures.
FELTON, J M Division of Rules and Records B2/12/02 Document
Management Branch 1p 16367 276 24X Fiche 50-259, B2/12/02,
B212080100

--B212080108 Forwards public version of revised radiological emergency plan implementing procedures, including Procedures IP-1 re emergency plan classification logic & IP-4 re site area emergency Receipt form encl.
MILLS, L M Tennessee Valley Authority B2/11/22 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 16367 277
24X Fiche 50-259, B2/12/02, B212080100

--B212080112 Public version of revised radiological emergency plan implementing procedures, including Procedures IP-1 re emergency plan classification logic, IP-4 re site area emergency & IP-21 re operations support ctr.
* Tennessee Valley Authority B2/11/01 76pp 16367 280 24X
Fiche 50-259, B2/12/02, B212080100

B212090080 Act receipt of B21124 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Repts 50-259/B2-36, 50-260/B2-36 & 50-296/B2-36
LEWIS, R C Division of Project & Resident Programs B2/12/06
PARRIS, H O Tennessee Valley Authority 2pp 16357 236 24X
Fiche 50-259, B2/12/06, B212090080

--B212090092 Responds to NRC B21022 ltr re violations noted in IE Safeguards Insp Repts 50-259/B2-36, 50-260/B2-36 & 50-296/B2-36. Corrective actions withheld (ref 10CFR73.21)
MILLS, L M Tennessee Valley Authority B2/11/24 O'REILLY, J P
Region 2, Office of Director 1p 16357 238 24X
Fiche 50-259, B2/12/06, B212090080

--B212090108 Forwards IE Safeguards Insp Repts 50-259/B2-36, 50-260/B2-36 & 50-296/B2-36 on B20908-09 & notice of violation Rept details & notice of violation withheld (ref 10CFR73.21)
O'REILLY, J P Region 2, Office of Director B2/10/22
PARRIS, H O Tennessee Valley Authority 2pp 16357 239 24X
Fiche 50-259, B2/12/06, B212090080

--B212090124 IE Safeguards Insp Repts 50-259/B2-36, 50-260/B2-36 & 50-296/B2-36 on B20908-09. Noncompliance noted in area of access controls. Details withheld (ref 10CFR73.21)
TILLMAN, A Division of Engineering & Technical Programs
B2/10/20 1p 16357 241 24X Fiche 50-259, B2/12/06, B212090080

B212170104 Releases public version of revised emergency plan implementing procedures.
FELTON, J M Division of Rules and Records B2/12/10 Document
Management Branch 1p 16478 104 24X Fiche 50-259, B2/12/10,
B212170104

--B212170108 Forwards public version of revised emergency plan implementing procedures, including Procedures IP-6, -7 & -23 re emergency telephone listings.
MILLS, L M Tennessee Valley Authority B2/12/03 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 16478 105
24X Fiche 50-259, B2/12/10, B212170104

--B212170112 Public version of revised emergency plan implementing procedures, including Procedures IP-6, -7 & -23 re emergency telephone listings.
* Tennessee Valley Authority B2/11/30 7pp 16478 107 24X
Fiche 50-259, B2/12/10, B212170104

B212170229 Provides implementation schedule for generic security training & qualification plan. Public safety employees have completed initial training. Training per 10CFR50.54(p) will be completed by 8/30/01.
MILLS, L M Tennessee Valley Authority B2/12/13 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 16462 020
24X Fiche 50-000, B2/12/13, B212170229

G Adjudicatory correspondence

G212280028 Forwards nonproprietary "RWR-1 - Radwaste Vol Reduction Sys" & NRC topical rept evaluation Matl should aid in settlement negotiations W/o encl
 RAWSON, R J Hearing Branch 4 82/12/23 PYLE, R D Pyle, R D 1p
 16565 143 24X Fiche 50-259, 82/12/23, 8212280028

H General correspondence

G212140478 Forwards missing Pages 65 & 66 of EIA re low level radwaste storage for Browns Ferry Nuclear Plant & SER & EIA on low level radwaste storage facility at Sequoyah Nuclear Plant W/o encl
 LOYSEN, P Advanced Fuel & Spent Fuel Licensing Branch 82/11/23
 DREY, L A Affiliation Unknown 1p 16431 321 24X
 Fiche 50-000, 82/11/23, 8212140478

--8212140486 Requests missing pages to EIA on low level radwaste storage at Browns Ferry Nuclear Plant & copies of SER & EIA for Sequoyah Nuclear Plant
 DREY, L A Affiliation Unknown 82/11/08 Office of Nuclear
 Material Safety & Safeguards, Director 1p 16431 322 24X
 Fiche 50-000, 82/11/23, 8212140478

J Insurance & indemnity information

G212020269 Submits info re const & warehouse values located offsite as result of revised site descriptions under ANI/MAELU nuclear liability insurance facility Form Policies
 DUCK, J R Marsh & McLennan, Inc., M & M Nuclear Consultants, Inc Div
 82/11/18 HAINES, H L American Nuclear Insurers 1p 16208 356
 24X Fiche 50-000, 82/11/18, 8212020269

B212280261 Forwards Endorsement 63 to NELIA Policy NF-198 & Indorsement 53 to MAELU Policy MF-66
 DUCK, J R Marsh & McLennan, Inc., M & M Nuclear Consultants, Inc Div
 82/12/22 SALTZMAN, J Assistant Director for State & License
 Relations 3pp 16561 304 24X Fiche 50-259, 82/12/22, 8212280261

G212290246 Forwards Certificates of Insurance N-38, N-39 & N-40 for Indorsements 1, 2 & 3 to NELIA Policy NF-198 & Certificates of Insurance M-38, M-39 & M-40 for Endorsements 1, 2 & 3 to MAELU Policy MF-66
 DUCK, J R Marsh & McLennan, Inc., M & M Nuclear Consultants, Inc Div
 82/12/23 SALTZMAN, J Assistant Director for State & License
 Relations 55pp 16582 045 24X Fiche 50-259, 82/12/23, 8212290246

K Utility Final Safety Analysis Report (FSAR) & amends

B212140323 Forwards FSAR Figure 10 7-2, "Mechanical Control Diagram Raw Cooling Water Sys." inadvertently omitted from B20812 submittal
 HAMMER, D S Tennessee Valley Authority 82/12/07 DENTON, H R
 Office of Nuclear Reactor Regulation, Director 2pp 16402 054
 24X Fiche 50-259, 82/12/07, 8212140323

P Operating license stage documents & correspondence

G211230066 Generic Ltr 82-27 to all BWR licensees of operating reactors except LACBWR, Big Rock Point, Dresden 1, Humboldt Bay, applicants for OL & holders of CP re transmittal of NUREG-0763 & NUREG-0783 Svc list encl W/o stated encl
 LISENHUT, D G Division of Licensing 82/11/15 General Public
 Utilities - GPU Service Corp 22pp 16387 004 24X
 Fiche 50-000, 82/11/15, 8211230066

B212140479 SBLOCA OUTSIDE CONTAINMENT AT BROWNS FERRY UNIT 1-ACCIDENT SEQUENCE ANALYSIS
 CONDON, W A, HARRINGTON, R M, GREENE, S R Oak Ridge National
 Laboratory FIN B-0452 NUREG/CR-2672 V01 82/11/30 Office of
 Nuclear Regulatory Research, Director 280pp 16433 074 24X
 Fiche 50-259, 82/11/30, 8212140479

B212090118 Confirms arrangements for 821215 meeting in Region 2 ofc re MBIV leakage at Unit 2 Proposed agenda encl
 O'REILLY, J P Region 2, Office of Director 82/12/01 PARRIS, H O
 Tennessee Valley Authority 2pp 16397 274 24X
 Fiche 50-259, 82/12/01, 8212090118

G212090346 Confirms 821102 telcon re 821202 enforcement conference in Atlanta, GA to discuss results of survey of waste oil facilities & plans for disposing of waste oil
 O'REILLY, J P Region 2, Office of Director 82/12/01 PARRIS, H O
 Tennessee Valley Authority 2pp 16365 197 24X
 Fiche 50-259, 82/12/01, 8212090346

B212070288 Advises that NUREG-0737, Item 11 K 3 27, "Common Ref Level," will be reviewed w/control room design review as required by Item I D I Assessment team recommendations will be considered final resolution
 MILLS, L M Tennessee Valley Authority 82/12/03 DENTON, H R
 Office of Nuclear Reactor Regulation, Director 2pp 16339 013
 24X Fiche 50-259, 82/12/03, 8212070288

B212090083 Application for amend to Licenses DPR-33, DPR-52 & DPR-68, changing duration of containment integrated leak rate test from 24-h to 8-h
 MILLS, L M Tennessee Valley Authority 82/12/03 DENTON, H R
 Office of Nuclear Reactor Regulation, Director 3pp 16357 192
 24X Fiche 50-259, 82/12/03, 8212090083

--8212090088 Proposed Tech Spec revisions changing duration of containment integrated leak rate test from 24-h to 8-h
 Justification for proposed revisions encl
 * Tennessee Valley Authority 82/12/03 36pp 16397 193 24X
 Fiche 50-259, 82/12/03, 8212090083

G212270192 Forwards item-by-item description of responses discussed during 821027 telcon w/F Clemenson re technical evaluation rept, "Control of Heavy Loads - NUREG-0694," for facility
 MILLS, L M Tennessee Valley Authority 82/12/14 VASSALLO, D B
 Operating Reactors Branch 2 44pp 16539 303 24X
 Fiche 50-259, 82/12/14, 8212270192

B212280085 Application to amend Licenses DPR-33, DPR-52 & DPR-68, changing Tech Specs re bypassing of main steam line tunnel temp switches for up to 4-h
 MILLS, L M Tennessee Valley Authority 82/12/17 DENTON, H R
 Office of Nuclear Reactor Regulation, Director 2pp 16564 238
 24X Fiche 50-259, 82/12/17, 8212280085

--8212280088 Proposed Tech Spec changes re bypassing of main steam line tunnel temp switches for up to 4-h
 * Tennessee Valley Authority 82/12/17 16pp 16564 240 24X
 Fiche 50-259, 82/12/17, 8212280085

B212280295 Forwards draft response to 821108 request for addl info re implementation of Revision 1 to NUREG-0313 on matl selection & processing for BWR coolant pressure boundary piping
 MILLS, L M Tennessee Valley Authority 82/12/20 DENTON, H R
 Office of Nuclear Reactor Regulation, Director 10pp 16562 007
 24X Fiche 50-259, 82/12/20, 8212280295

--8212280296 Revision 4 to "Liquid Penetrant Exam Using Color Contrast Removable Method"
 * Tennessee Valley Authority 82/03/01 14pp 16562 017 24X
 Fiche 50-259, 82/12/20, 8212280295

--8212280297 Revision 1 to "Ultrasonic Exam of Nuclear Power Plant Piping"
 BENILEY, N R Tennessee Valley Authority 82/09/02 24pp
 16562 031 24X Fiche 50-259, 82/12/20, 8212280295

Q Inspection reports, IE Bulletins & correspondence

B208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel Recirculation Sys Piping at BWR Plants" Svc list encl
 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc
 112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240

B208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model B01 & Model B02 Thermoluminescent Dosimeters" Svc list encl
 COBB, L I Division of Fuel Facilities, Materials & Safeguards
 82/11/05 Consolidated Edison Co of New York, Inc 110pp
 16372 142 24X Fiche 50-000, 82/11/05, 8208190245

B212090456 Ack receipt of 821022 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/82-24, 50-260/82-24 & 50-296/82-24, LEWIS, R C Division of Project & Resident Programs 82/11/12
 PARRIS, H O Tennessee Valley Authority 1p 16364 009 24X
 Fiche 50-259, 82/11/12, 8212090456

--8212090461 Responds to NRC 820921 ltr re violations noted in IE Insp Repts 50-259/82-24, 50-260/82-24 & 50-296/82-24 Corrective actions evaluation concerning adequacy of review process will be provided by 830102
 MILLS, L M Tennessee Valley Authority 82/10/22 O'REILLY, J P
 Region 2, Office of Director 5pp 16364 010 24X
 Fiche 50-259, 82/11/12, 8212090461

DOCKETED ITEMS

- B212090467 Forwards IE Insp Repts 50-259/82-24, 50-260/82-24 & 50-296/82-24 on B20725-0825 & notice of violation
LEWIS, R C Division of Project & Resident Programs 82/09/21
PARRIS, H O Tennessee Valley Authority 2pp 16364 015 24X
Fiche 50-259, 82/11/12, B212090466
- B212090471 Notice of violation from insp on B20726-0825
+ Division of Project & Resident Programs 82/09/21 2pp
16364 017 24X Fiche 50-259, 82/11/12, B212090466
- B212090479 IE Insp Repts 50-259/82-24, 50-260/82-24 & 50-296/82-24 on B20726-0825 Noncompliance noted post-maint testing not conducted on steam pilot valves & test criteria did not incorporate requirements & acceptance limits
CHASE, J W, PAULK, G L, CARRELL, F S Division of Project & Resident Programs 82/09/09 10pp 16364 019 24X
Fiche 50-259, 82/11/12, B212090466
- B208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18
Consolidated Edison Co. of New York, Inc 109pp 16411 199 24X
Fiche 50-000, 82/11/18, B208190251
- B208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co. of New York, Inc 127pp 16411 065 24X Fiche 50-000, 82/11/26, B208190256
- B208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co. of New York, Inc 356pp 16387 028 24X Fiche 50-000, 82/11/30, B208190257
- B212030212 Ack receipt of B21119 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Repts 50-259/82-30, 50-260/82-30 & 50-296/82-30
LEWIS, R C Division of Project & Resident Programs 82/11/30
PARRIS, H O Tennessee Valley Authority 1p 16307 067 24X
Fiche 50-259, 82/11/30, B212030212
- B212030220 Responds to NRC B21019 ltr re violations noted in IE Safeguards Insp Repts 50-259/82-30, 50-260/82-30 & 50-296/82-30 Corrective actions withheld (ref 10CFR73 21)
MILLS, L H Tennessee Valley Authority 82/11/19 O'REILLY, J P Region 2, Office of Director 1p 16307-068 24X
Fiche 50-259, 82/11/30, B212030212
- B212030226 Forwards IE Safeguards Insp Repts 50-259/82-30, 50-260/82-30 & 50-296/82-30 on B20720-24 & notice of violation Rept details & notice of violation withheld (ref 10CFR73 21)
LEWIS, R C Division of Project & Resident Programs 82/10/19
PARRIS, H O Tennessee Valley Authority 2pp 16307 069 24X
Fiche 50-259, 82/11/30, B212030212
- B212030232 IE Insp Repts 50-259/82-30, 50-260/82-30 & 50-296/82-30 on B20720-24 Noncompliance noted in areas of locks, keys & combinations, physical barriers - protected areas, lighting & access control Details withheld (ref 10CFR73 21)
HALL, B L, MCQUEEN, R W, MCQUIRE, D R Division of Engineering & Technical Programs 82/10/14, 2pp 16307 071 24X
Fiche 50-259, 82/11/30, B212030212
- B208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co. of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, B208190259
- B208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co. of New York, Inc 110pp 16462 064 24X
Fiche 50-000, 82/12/03, B208190261
- B212090080 Ack receipt of B21124 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Repts 50-259/82-36, 50-260/82-36 & 50-296/82-36
LEWIS, R C Division of Project & Resident Programs 82/12/06
PARRIS, H O Tennessee Valley Authority 2pp 16357 236 24X
Fiche 50-259, 82/12/06, B212090080
- B212090092 Responds to NRC B21022 ltr re violations noted in IE Safeguards Insp Repts 50-259/82-36, 50-260/82-36 & 50-296/82-36 Corrective actions withheld (ref 10CFR73 21)
MILLS, L H Tennessee Valley Authority 82/11/24 O'REILLY, J P Region 2, Office of Director 1p 16357 238 24X
Fiche 50-259, 82/12/06, B212090080
- B212090108 Forwards IE Safeguards Insp Repts 50-259/82-36, 50-260/82-36 & 50-296/82-36 on B20908-09 & notice of violation Rept details & notice of violation withheld (ref 10CFR73 21)
O'REILLY, J P Region 2, Office of Director 82/10/22
PARRIS, H O Tennessee Valley Authority 2pp 16357 239 24X
Fiche 50-259, 82/12/06, B212090080
- B212090124 IE Safeguards Insp Repts 50-259/82-36, 50-260/82-36 & 50-296/82-36 on B20908-09 Noncompliance noted in area of access controls Details withheld (ref 10CFR73 21)
TILLMAN, A, MCQUIRE, D R Division of Engineering & Technical Programs 82/10/20 1p 16357 241 24X Fiche 50-259, 82/12/06, B212090080
- B212170345 EN-82-041 on B21217, notice of violation & proposed imposition of civil penalty in amount of \$3,125 will be issued to licensee for defective packaging in two shipments of low-specific activity radwaste to Richland, WA
BRACKETT, T, AXELRAD, J Director's Office, Office of Inspection and Enforcement 82/12/14 1p 16452 362 24X Fiche 50-259, 82/12/14, B212170345
- B208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co. of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16, B208190267
- B208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relay Type ITE-27 " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co. of New York, Inc 108pp 16628 293 24X
Fiche 50-000, 82/12/20, B208190268
- R Periodic operating reports & related correspondence
- B212290281 Forwards monthly operating repts for Oct 1982
JONES, O T Tennessee Valley Authority 82/11/10 Office of Resource Management, Director 1p 16581 074 24X
Fiche 50-259, 82/11/10, B212290281
- B212290287 Monthly operating repts for Oct 1982
THOM, T Tennessee Valley Authority 82/11/01 39pp 16581 075 24X Fiche 50-259, 82/11/10, B212290281
- B212030071 Forwards central emergency control ctr meteorological data availability statistics for Apr-Sept 1982
MILLS, L H Tennessee Valley Authority 82/11/30 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 16304 210 24X Fiche 50-000, 82/11/30, B212030071
- S Reportable occurrences, LERs & related correspondence
- B212020348 Forwards LER 82-088/03L-0
GREEN, H J Tennessee Valley Authority 82/11/23 O'REILLY, J P Region 2, Office of Director 1p 16288 359 24X
Fiche 50-259, 82/11/23, B212020348
- B212020354 LER 82-088/03L-0 on B21028, discovered momentary breach of secondary containment due to personnel access airlock doors between Unit 2 reactor & turbine bldgs being opened at same time Caused by misaligned solenoid Solenoid realigned
CARTER, B Tennessee Valley Authority 82/11/23 Region 2, Office of Director 2pp 16288 360 24X Fiche 50-259, 82/11/23, B212020348
- B212030039 Forwards LER 82-094/03L-0
GREEN, H J Tennessee Valley Authority 82/11/26 O'REILLY, J P Region 2, Office of Director 1p 16304 128 24X
Fiche 50-259, 82/11/26, B212030039
- B212030044 LER 82-094/03L-0 on B21029, smoke detector X5-39-66XM alarmed, potentially masking signals from other detectors Caused by water in detector Firewatch established & water removed
* Tennessee Valley Authority 82/11/26 Region 2, Office of Director 2pp 16304 129 24X Fiche 50-259, 82/11/26, B212030039
- B212090107 Forwards LER 82-093/01T-0
GREEN, H J Tennessee Valley Authority 82/11/30 O'REILLY, J P Region 2, Office of Director 1p 16357 279 24X
Fiche 50-259, 82/11/30, B212090107
- B212090116 LER 82-093/01T-0 on B21118, safety injection valves 4 2 B-31, 4 2 B-36 & 4 2 B-37 left in normally open position contrary to requirement that valves be administratively controlled w/ power lifted Caused by procedural inadequacy
KRAUSE, L L Tennessee Valley Authority 82/11/30 Region 2, Office of Director 2pp 16357 280 24X Fiche 50-259, 82/11/30, B212090109

DOCKETED ITEMS

65

GP12090280 Forwards LER 82-089/03L-0
GREEN, H J Tennessee Valley Authority 82/12/03 O'REILLY, J P
Region 2, Office of Director 1p 16365 267 24X
Fiche 50-259, 82/12/03, 8212090280

--8212090291 LER 82-089/03L-0 on 821103, during primary containment purge
sys filter pressure drop test, primary purge sys failed to
achieve required flow rate. Caused by clogged HEPA filters
New filters installed & satisfactorily tested
MULLINO, K Tennessee Valley Authority 82/12/03 Region 2,
Office of Director 2pp 16365 268 24X Fiche 50-259, 82/12/03,
8212090280

GP12090361 Forwards LER 82-090/03L-0
GREEN, H J Tennessee Valley Authority 82/12/03 O'REILLY, J P
Region 2, Office of Director 1p 16364 190 24X
Fiche 50-259, 82/12/03, 8212090361

--8212090369 LER 82-090/03L-0 on 821104, secondary containment breached
when turbine to reactor bldg doors opened simultaneously
during door interlock maint. Caused by insufficient control
while interlocks inoperable. Door watch instructions written
CARTER, S Tennessee Valley Authority 82/12/03 Region 2,
Office of Director 2pp 16364 191 24X Fiche 50-259, 82/12/03,
8212090361

GP12140440 Forwards LER 82-091/03L-0
GREEN, H J Tennessee Valley Authority 82/12/08 O'REILLY, J P
Region 2, Office of Director 1p 16404 178 24X
Fiche 50-259, 82/12/08, 8212140440

--8212140444 LER 82-091/03L-0 on 821109, during diesel generator monthly
test, control room operator unable to raise speed of diesel
generator. Caused by failed Woodward Governor Co
microswitch. Switch replaced
CHRISTOPHER, W Tennessee Valley Authority 82/12/08 Region 2,
Office of Director 2pp 16404 179 24X Fiche 50-259, 82/12/08,
8212140440

GP12150066 Forwards LER 82-092/03L-0
GREEN, H J Tennessee Valley Authority 82/12/10 O'REILLY, J P
Region 2, Office of Director 1p 16430 191 24X
Fiche 50-259, 82/12/10, 8212150066

--8212150069 LER 82-092/03L-0 on 821116, reactor pressure switches
PS-68-93 & PS-68-64 found operating below Tech Spec
requirements. Caused by calibr drift. Switches recalibr
& returned to svc
IRBY, D J Tennessee Valley Authority 82/12/10 Region 2,
Office of Director 3pp 16430 192 24X Fiche 50-259, 82/12/10,
8212150066

GP12280147 Forwards LER 82-096/01T-0
GREEN, H J Tennessee Valley Authority 82/12/20 O'REILLY, J P
Region 2, Office of Director 1p 16563 119 24X
Fiche 50-259, 82/12/20, 8212280147

--8212280153 LER 82-096/01T-0 on 821206, during startup, control rod 18-51
double notched from 08 to 12, resulting in large reactivity
insertion & causing reactor to scram. Cause attributed to
normal degradation of control rod drive seals
WINDO, M D Tennessee Valley Authority 82/12/20 Region 2,
Office of Director 2pp 16563 120 24X Fiche 50-259, 82/12/20,
8212280147

DOCKET 50-260 BROWNS FERRY NUCLEAR POWER STATION, UNIT 2

F Security, medical, emergency & fire protection plans

GP12030212 Ack receipt of 821119 ltr informing NRC of steps taken to
correct violations noted in IE Safeguards Insp Repts
50-259/82-30, 50-260/82-30 & 50-296/82-30
LEWIS, R C Division of Project & Resident Programs 82/11/30
PARRIS, H O Tennessee Valley Authority 1p 16307 067 24X
Fiche 50-259, 82/11/30, 8212030212

--8212030220 Responds to NRC 821019 ltr re violations noted in IE
Safeguards Insp Repts 50-259/82-30, 50-260/82-30 &
50-296/82-30 Corrective actions withheld (ref 10CFR73 21)
MILLS, L M Tennessee Valley Authority 82/11/19 O'REILLY, J P
Region 2, Office of Director 1p 16307 068 24X
Fiche 50-259, 82/11/30, 8212030212

--8212030226 Forwards IE Safeguards Insp Repts 50-259/82-30, 50-260/82-30
& 50-296/82-30 on 820920-24 & notice of violation Rept
details & notice of violation withheld (ref 10CFR73 21)
LEWIS, R C Division of Project & Resident Programs 82/10/19
PARRIS, H O Tennessee Valley Authority 2pp 16307 069 24X
Fiche 50-259, 82/11/30, 8212030212

--8212030232 IE Insp Repts 50-259/82-30, 50-260/82-30 & 50-296/82-30 on
820920-24 Noncompliance noted in areas of locks, keys &
combinations, physical barriers - protected areas, lighting &
access control Details withheld (ref 10CFR73 21)
HALL, B L Division of Engineering & Technical Programs 82/10/14
2pp 16307 071 24X Fiche 50-259, 82/11/30, 8212030212

GP12080100 Releases public version of revised radiological emergency
plan implementing procedures
FELTON, J M Division of Rules and Records 82/12/02 Document
Management Branch 1p 16367 276 24X Fiche 50-259, 82/12/02,
8212080100

--8212080108 Forwards public version of revised radiological emergency
plan implementing procedures, including Procedures IP-1 re
emergency plan classification logic & IP-4 re site area
emergency Receipt form encl
MILLS, L M Tennessee Valley Authority 82/11/22 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 16367 277
24X Fiche 50-259, 82/12/02, 8212080100

--8212080112 Public version of revised radiological emergency plan
implementing procedures, including Procedures IP-1 re
emergency plan classification logic, IP-4 re site area
emergency & IP-21 re operations support ctr
* Tennessee Valley Authority 82/11/01 7app 16367 280 24X
Fiche 50-259, 82/12/02, 8212080100

GP12090080 Ack receipt of 821124 ltr informing NRC of steps taken to
correct violations noted in IE Safeguards Insp Repts
50-259/82-36, 50-260/82-36 & 50-296/82-36
LEWIS, R C Division of Project & Resident Programs 82/12/06
PARRIS, H O Tennessee Valley Authority 2pp 16357 236 24X
Fiche 50-259, 82/12/06, 8212090080

--8212090092 Responds to NRC 821022 ltr re violations noted in IE
Safeguards Insp Repts 50-259/82-36, 50-260/82-36 &
50-296/82-36 Corrective actions withheld (ref 10CFR73 21)
MILLS, L M Tennessee Valley Authority 82/11/24 O'REILLY, J P
Region 2, Office of Director 1p 16357 238 24X
Fiche 50-259, 82/12/06, 8212090080

--8212090108 Forwards IE Safeguards Insp Repts 50-259/82-36,
50-260/82-36 & 50-296/82-36 on 820908-09 & notice of
violation Rept details & notice of violation withheld
(ref 10CFR73 21)
O'REILLY, J P Region 2, Office of Director 82/10/22
PARRIS, H O Tennessee Valley Authority 2pp 16357 239 24X
Fiche 50-259, 82/12/06, 8212090080

--8212090124 IE Safeguards Insp Repts 50-259/82-36, 50-260/82-36 &
50-296/82-36 on 820908-09 Noncompliance noted in area of
access controls Details withheld (ref 10CFR73 21)
TILLMAN, A Division of Engineering & Technical Programs
82/10/20 1p 16357 241 24X Fiche 50-259, 82/12/06, 8212090080

GP12170104 Releases public version of revised emergency plan
implementing procedures
FELTON, J M Division of Rules and Records 82/12/10 Document
Management Branch 1p 16478 104 24X Fiche 50-259, 82/12/10,
8212170104

--8212170108 Forwards public version of revised emergency plan
implementing procedures, including Procedures IP-6, -7 & -23
re emergency telephone listings
MILLS, L M Tennessee Valley Authority 82/12/03 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 16478 105
24X Fiche 50-259, 82/12/10, 8212170104

--8212170112 Public version of revised emergency plan implementing
procedures, including Procedures IP-6, -7 & -23 re emergency
telephone listings
* Tennessee Valley Authority 82/11/30 7pp 16478 107 24X
Fiche 50-259, 82/12/10, 8212170104

GP12170229 Provides implementation schedule for generic security
training & qualification plan. Public safety employees have
completed initial training. Training per 10CFR50 54(p) will
be completed by 830801
MILLS, L M Tennessee Valley Authority 82/12/13 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 16462 020
24X Fiche 50-000, 82/12/13, 8212170229

0 Adjudicatory correspondence

GP12280028 Forwards nonproprietary "RWR-1 - Radwaste Vol Reduction Sys"
& NRC topical rept evaluation Matl should aid in settlement
negotiations. W/o encl
RAMSON, R J Hearing Branch 4, 82/12/23 PYLE, R B, Pyle, R B 1p
16565 143 24X Fiche 50-259, 82/12/23, 8212280028

DOCKETED ITEMS

H General correspondence

8212140478 Forwards missing Pages 65 & 66 of EIA re low level radwaste storage for Browns Ferry Nuclear Plant & SER & EIA on low level radwaste storage facility at Sequoyah Nuclear Plant w/o encl
 LOYSE, P Advanced Fuel & Spent Fuel Licensing Branch 82/11/23
 DREY, L A Affiliation Unknown 1p 16431 321 24X
 Fiche 50-000, 82/11/23, 8212140478

--8212140486 Requests missing pages to EIA on low level radwaste storage at Browns Ferry Nuclear Plant & copies of SER & EIA for Sequoyah Nuclear Plant
 DREY, L A Affiliation Unknown 82/11/08 Office of Nuclear Material Safety & Safeguards, Director 1p 16431 322 24X
 Fiche 50-000, 82/11/23, 8212140478

J Insurance & indemnity information

8212020269 Submits info re const & warehouse values located offsite as result of revised site descriptions under ANI/MAELU nuclear liability insurance facility form policies
 DUCK, J R Marsh & McLennan, Inc , M & M Nuclear Consultants, Inc Div 82/11/18 HAINES, H L American Nuclear Insurers 1p 16288 356 24X
 Fiche 50-000, 82/11/18, 8212020269

8212280261 Forwards Endorsement 63 to NELIA Policy NF-198 & Indorsement 53 to MAELU Policy MF-66
 DUCK, J R Marsh & McLennan, Inc , M & M Nuclear Consultants, Inc Div 82/12/22 SALTZMAN, J Assistant Director for State & Licensee Relations 3pp 16561 304 24X
 Fiche 50-259, 82/12/22, 8212280261

8212290246 Forwards Certificates of Insurance N-38, N-39 & N-40 for Endorsements 1, 2 & 3 to NELIA Policy NF-198 & Certificates of Insurance M-38, M-39 & M-40 for Endorsements 1, 2 & 3 to MAELU Policy MF-66
 DUCK, J R Marsh & McLennan, Inc , M & M Nuclear Consultants, Inc Div 82/12/23 SALTZMAN, J Assistant Director for State & Licensee Relations 5pp 16582 045 24X
 Fiche 50-259, 82/12/23, 8212290246

K Utility Final Safety Analysis Report (FSAR) & amends

8212140323 Forwards FSAR Figure 10 7-2, "Mechanical Control Diagram Raw Cooling Water Sys," inadvertently omitted from B20B12 submittal
 KAHMER, D S Tennessee Valley Authority 82/12/07 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 16402 054 24X
 Fiche 50-259, 82/12/07, 8212140323

P Operating license stage documents & correspondence

821230066 Generic Ltr 82-27 to all BWR licensees of operating reactors except LACBWR, Big Rock Point, Dresden 1, Humboldt Bay, applicants for OL & holders of CP re transmittal of NUREG-0763 & NUREG-0783 Svc list encl w/o stated encl
 LIGENHUT, D G Division of Licensing 82/11/15 General Public Utilities - OPU Service Corp 22pp 16387 004 24X
 Fiche 50-000, 82/11/15, 821230066

8212090118 Confirms arrangements for 821215 meeting in Region 2 of re MSIV leakage at Unit 2 Proposed agenda encl
 O'REILLY, J P Region 2, Office of Director 82/12/01 PARRIS, H G Tennessee Valley Authority 2pp 16357 274 24X
 Fiche 50-259, 82/12/01, 8212090118

8212090346 Confirms 821102 telcon re 821202 enforcement conference in Atlanta, GA to discuss results of survey of waste oil facilities & plans for disposing of waste oil
 O'REILLY, J P Region 2, Office of Director 82/12/01 PARRIS, H G Tennessee Valley Authority 2pp 16365 157 24X
 Fiche 50-259, 82/12/01, 8212090346

8212070288 Advises that NUREG-0737, Item II K 3 27, "Common Ref Level," will be reviewed w/control room design review as required by Item I D 1 Assessment team recommendations will be considered final resolution
 MILLS, L M Tennessee Valley Authority 82/12/03 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 16339 013 24X
 Fiche 50-259, 82/12/03, 8212070288

8212090083 Application for amend to Licenses DPR-33, DPR-52 & DPR-68, changing duration of containment integrated leak rate test from 24-h to 8-h
 MILLS, L M Tennessee Valley Authority 82/12/03 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 16357 192 24X
 Fiche 50-259, 82/12/03, 8212090083

--8212090088 Proposed Tech Spec revisions changing duration of containment integrated leak rate test from 24-h to 8-h
 Justification for proposed revisions encl
 * Tennessee Valley Authority 82/12/03 36pp 16357 193 24X
 Fiche 50-259, 82/12/03, 8212090083

8212170136 Application to amend License DPR-52, requesting changes needed to reflect surveillance testing of electrical sys info suppl 821015 & 1117 applications
 MILLS, L M Tennessee Valley Authority 82/12/10 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 16453 004 24X
 Fiche 50-260, 82/12/10, 8212170136

--8212170140 Proposed Tech Specs reflecting surveillance testing of electrical sys
 * Tennessee Valley Authority 82/12/10 3pp 16453 006 24X
 Fiche 50-260, 82/12/10, 8212170136

8212270192 Forwards item-by-item description of responses discussed during 821027 telcon w/F Clemenson re technical evaluation rept, "Control of Heavy Loads - NUREG-0654," for facility
 MILLS, L M Tennessee Valley Authority 82/12/14 VASSALLO, D B Operating Reactors Branch 2 44pp 16339 303 24X
 Fiche 50-259, 82/12/14, 8212270192

8212280085 Application to amend Licenses DPR-33, DPR-52 & DPR-68, changing Tech Specs re bypassing of main steam line tunnel temp switches for up to 4-h
 MILLS, L M Tennessee Valley Authority 82/12/17 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 16564 238 24X
 Fiche 50-259, 82/12/17, 8212280085

--8212280088 Proposed Tech Spec changes re bypassing of main steam line tunnel temp switches for up to 4-h
 * Tennessee Valley Authority 82/12/17 16pp 16564 240 24X
 Fiche 50-259, 82/12/17, 8212280085

8212280275 Forwards draft response to 821108 request for addl info re implementation of Revision 1 to NUREG-0313 on matl selection & processing for BWR coolant pressure boundary piping
 MILLS, L M Tennessee Valley Authority 82/12/20 DENTON, H R Office of Nuclear Reactor Regulation, Director 10pp 16562 007 24X
 Fiche 50-259, 82/12/20, 8212280275

Q Inspection reports, IE Bulletins & correspondence

8208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping of BWR Plants" Svc list encl
 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co. of New York, Inc 112pp 16462 163 24X
 Fiche 50-000, 82/10/28, 8208190240

8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model B01 & Model B02 Thermoluminescent Dosimeters" Svc list encl
 COBBL, I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co. of New York, Inc 110pp 16372 142 24X
 Fiche 50-000, 82/11/05, 8208190245

8212090456 Ack receipt of 821022 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/82-24, 50-260/82-24 & 50-276/82-24
 LEWIS, R C Division of Project & Resident Programs 82/11/12 PARRIS, H G Tennessee Valley Authority 1p 16364 009 24X
 Fiche 50-259, 82/11/12, 8212090456

--8212090461 Responds to NRC 820921 ltr re violations noted in IE Insp Repts 50-259/82-24, 50-260/82-24 & 50-276/82-24 Corrective actions evaluation concerning adequacy of review process will be provided by 820102
 MILLS, L M Tennessee Valley Authority 82/10/22 O'REILLY, J P Region 2, Office of Director 5pp 16364 010 24X
 Fiche 50-259, 82/11/12, 8212090456

--8212090467 Forwards IE Insp Repts 50-259/82-24, 50-260/82-24 & 50-276/82-24 on 820723-0825 & notice of violation
 LEWIS, R C Division of Project & Resident Programs 82/09/21 PARRIS, H G Tennessee Valley Authority 2pp 16364 015 24X
 Fiche 50-259, 82/11/12, 8212090456

--8212090471 Notice of violation from insp on 820726-0825
 * Division of Project & Resident Programs 82/09/21 2pp 16364 017 24X
 Fiche 50-259, 82/11/12, 8212090456

-B212090479 IE Insp Repts 50-259/82-24, 50-260/82-24 & 50-296/82-24 on 820726-0825 Noncompliance noted post-maint testing not conducted on scram pilot valves & test criteria did not incorporate requirements & acceptance limits
CHASE, J. W., PAULK, G. L., CANTRELL, F. S. Division of Project & Resident Programs 82/07/09 10pp 16364 019 24X
Fiche 50-259, 82/11/12, 8212090456

B208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X
Fiche 50-000, 82/11/18, 8208190251

B208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list encl
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000, 82/11/26, 8208190256

B208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl
COSB, L. I. Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16367 028 24X Fiche 50-000, 82/11/30, 8208190257

B212030212 Ack receipt of 821119 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Repts 50-259/82-30, 50-260/82-30 & 50-296/82-30
LEWIS, R. C. Division of Project & Resident Programs 82/11/30 PARRIS, H. G. Tennessee Valley Authority 1p 16307 067 24X
Fiche 50-259, 82/11/30, 8212030212

--B212030220 Responds to NRC 821019 ltr re violations noted in IE Safeguards Insp Repts 50-259/82-30, 50-260/82-30 & 50-296/82-30 Corrective actions withheld (ref 10CFR73 21)
MILLS, L. M. Tennessee Valley Authority 82/11/19 O'REILLY, J. P. Region 2, Office of Director 1p 16307 068 24X
Fiche 50-259, 82/11/30, 8212030212

--B212030226 Forwards IE Safeguards Insp Repts 50-259/82-30, 50-260/82-30 & 50-296/82-30 notice of violation Rept details & notice of violation withheld (ref 10CFR73 21)
LEWIS, R. C. Division of Project & Resident Programs 82/10/19 PARRIS, H. G. Tennessee Valley Authority 2pp 16307 069 24X
Fiche 50-259, 82/11/30, 8212030212

--B212030232 IE Insp Repts 50-259/82-30, 50-260/82-30 & 50-296/82-30 on 820920-24 Noncompliance noted in areas of locks, keys & combinations, physical barriers - protected areas, lighting & access control Details withheld (ref 10CFR73 21)
HALL, B. L., OGDEN, R. W., MCGUIRE, D. R. Division of Engineering & Technical Programs 82/10/14 2pp 16307 071 24X
Fiche 50-259, 82/11/30, 8212030212

B208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259

B208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X
Fiche 50-000, 82/12/03, 8208190261

B212090080 Ack receipt of 821124 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Repts 50-259/82-36, 50-260/82-36 & 50-296/82-36
LEWIS, R. C. Division of Project & Resident Programs 82/12/06 PARRIS, H. G. Tennessee Valley Authority 2pp 16357 236 24X
Fiche 50-259, 82/12/06, 8212090080

--B212090092 Responds to NRC 821022 ltr re violations noted in IE Safeguards Insp Repts 50-259/82-36, 50-260/82-36 & 50-296/82-36 Corrective actions withheld (ref 10CFR73 21)
MILLS, L. M. Tennessee Valley Authority 82/11/24 O'REILLY, J. P. Region 2, Office of Director 1p 16357 238 24X
Fiche 50-259, 82/12/06, 8212090080

--B212090108 Forwards IE Safeguards Insp Repts 50-259/82-36, 50-260/82-36 & 50-296/82-36 on 820908-09 & notice of violation Rept details & notice of violation withheld (ref 10CFR73 21)
O'REILLY, J. P. Region 2, Office of Director 82/10/22 PARRIS, H. G. Tennessee Valley Authority 2pp 16357 239 24X
Fiche 50-259, 82/12/06, 8212090080

--B212090124 IE Safeguards Insp Repts 50-259/82-36, 50-260/82-36 & 50-296/82-36 on 820908-09 Noncompliance noted in area of access controls Details withheld (ref 10CFR73 21)
TILLMAN, A., MCGUIRE, D. R. Division of Engineering & Technical Programs 82/10/20 1p 16357 241 24X Fiche 50-259, 82/12/06, 8212090080

B212170345 EN-82-041 on 821217, notice of violation & proposed imposition of civil penalty in amount of \$3,125 will be issued to licensee for defective packaging in two shipments of low-specific activity radwaste to Richland, WA
BROCKETT, T., AXELRAD, J. Director's Office, Office of Inspection and Enforcement 82/12/14 1p 16452 362 24X Fiche 50-259, 82/12/14, 8212170345

B208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16, 8208190267

B208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27 " Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X
Fiche 50-000, 82/12/20, 8208190268

R Periodic operating reports & related correspondence

B212290281 Forwards monthly operating repts for Oct 1982
JOHNS, G. T. Tennessee Valley Authority 82/11/10 Office of Resource Management, Director 1p 16581 074 24X
Fiche 50-259, 82/11/10, 8212290281

--B212290287 Monthly operating repts for Oct 1982
THOM, T. Tennessee Valley Authority 82/11/01 39pp 16581 075 24X Fiche 50-259, 82/11/10, 8212290281

B212030071 Forwards central emergency control ctr meteorological data availability statistics for Apr-Sept 1982
MILLS, L. M. Tennessee Valley Authority 82/11/30 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 2pp 16304 210 24X Fiche 50-000, 82/11/30, 8212030071

S Reportable occurrences, LERs & related correspondence

B212020143 Forwards LER 82-035/03L-0
GREEN, H. J. Tennessee Valley Authority 82/11/23 O'REILLY, J. P. Region 2, Office of Director 1p 16274 167 24X
Fiche 50-260, 82/11/23, 8212020143

--B212020153 LER 82-035/03L-0 on 821101, during refueling outage, upper mechanical snubber on main steam line D found inoperable
Cause unknown Pacific Scientific snubber PSA-10 S/N 474 replaced & functionally tested
KERR, T. Tennessee Valley Authority 82/11/23 Region 2, Office of Director 2pp 16274 168 24X Fiche 50-260, 82/11/23, 8212020143

B212090143 Forwards revised LER 82-026/03X-1
GREEN, H. J. Tennessee Valley Authority 82/11/30 O'REILLY, J. P. Region 2, Office of Director 1p 16359 169 24X
Fiche 50-260, 82/11/30, 8212090143

--B212090153 Revised LER 82-026/03X-1 on 820819, during refueling outage maint on recirculation sys hydraulic snubbers, snubber SS1A found low on fluid & declared inoperable Caused by fluid leakage at O rings in hydraulic oil tube fittings
KERR, T. Tennessee Valley Authority 82/11/30 Region 2, Office of Director 2pp 16359 170 24X Fiche 50-260, 82/11/30, 8212090143

B212150101 Forwards LER 82-036/03L-0
GREEN, H. J. Tennessee Valley Authority 82/12/10 O'REILLY, J. P. Region 2, Office of Director 1p 16430 353 24X
Fiche 50-260, 82/12/10, 8212150101

--B212150104 LER 82-036/03L-0 on 821113, during refueling outage, reactor bldg continuous air monitor 2-90-250 became inoperable due to broken drive belt on sample pump Caused by normal wear Std v-belt for Switzer Model 325 svc air pump replaced
THORPE, D. Tennessee Valley Authority 82/12/10 Region 2, Office of Director 2pp 16430 356 24X Fiche 50-260, 82/12/10, 8212150101

B212220463 Forwards LER 82-039/01X-0
GREEN, H. J. Tennessee Valley Authority 82/12/17 O'REILLY, J. P. Region 2, Office of Director 1p 16504 254 24X
Fiche 50-260, 82/12/17, 8212220463

DOCKETED ITEMS

--B212220472 LER 82-037/01X-0 on B21204, during fuel outage, level switches LS-73-57A & 57B found inoperable. Caused by stuck Robert Shaw Model B2778-C3 level switch floats. Floats freed & level switches recalibrated. IRBY, B J Tennessee Valley Authority 82/12/17 Region 2, Office of Director 2pp 16504 255 24X Fiche 50-260, 82/12/17, B212220463

B212280099 Forwards LER 82-037/03L-0 GREEN, H J Tennessee Valley Authority 82/12/20 O'REILLY, J P Region 2, Office of Director 1p 16564 221 24X Fiche 50-260, 82/12/20, B212280099

--B212280106 LER 82-037/03L-0 on B21122, while performing local leak rate tests during refueling outage, total as-found leakage from primary containment found greater than allowable, per Tech Spec 4.7 A.2 g. Caused by deterioration of valve seating. MCPHERSON, R Tennessee Valley Authority 82/12/20 Region 2, Office of Director 5pp 16564 222 24X Fiche 50-260, 82/12/20, B212280099

B212280453 PNO-11-82-138 cracks detected in two branch connection welds of ring header during ultrasonic exam per IE Bulletin 82-03 & NUREG-0313, Revision 1 Confirmatory radiographic tests planned. Util will contract W/GE for analysis. BLAKE, J J, VERRELLI, D M Region 2, Office of Director 82/12/22 2pp 16556 004 24X Fiche 50-260, 82/12/22, B212280453

DOCKET 50-261 H B ROBINSON PLANT, UNIT 2

F Security, medical, emergency & fire protection plans

B212090345 Forwards IE Insp Rept 50-261/B2-39 on B21012-15 No noncompliance noted. VERRELLI, D M Division of Project & Resident Programs 82/11/03 UTLEY, E E Carolina Power & Light Co 1p 16365 139 24X Fiche 50-261, 82/11/03, B212090345

--B212090351 IE Insp Rept 50-261/B2-39 on B21012-15 No noncompliance noted. Major areas inspected emergency preparedness exercise. CLINE, W E, JENKINS, O R Region 2, Office of Director 82/11/02 12pp 16365 140 24X Fiche 50-261, 82/11/03, B212090345

B212290060 Partial response to FOIA request for seven categories of info. Forwards documents listed in App A Documents 1 & 2 already in PDR App B documents available in PDR LPDR profiles for Ginna & Indian Point 3 encl. FELTON, J M Division of Rules and Records 82/11/30 SCHLESSEL, D A New York, State of 7pp 16607 239 24X Fiche 50-000, 82/11/30, B212290060

--B212290155 Responds to NRC 751211 ltr re violations noted in IE Insp Rept 50-261/75-14. Corrective actions quarterly calibr of survey instruments will be performed per Health Physics Procedure HP-11 by 760131 & Procedure HP-1 will be revised. UTLEY, E E Carolina Power & Light Co 76/01/05 MOSELEY, N C Region 2, Atlanta, Office of the Director 4pp 16608 018 24X Fiche 50-000, 82/11/30, B212290060

--B212290165 IE Insp Rept 50-261/75-14 on 751104-19 Noncompliances noted failure to follow procedures for radiation surveys/maint of instrument records & surveillance testing procedures did not provide for recording "as-found" & "as-left" calibr data. PARKER, R C, LEWIS, R C, WHITENER, H L Region 2, Atlanta, Reactor Operations Nuclear Support Branch 75/12/16 17pp 16608 024 24X Fiche 50-000, 82/11/30, B212290060

B212100015 Confirms & documents previous info submitted in response to Generic Ltr 81-10, "Emergency Operations Facility (EOF) " Original util response submitted 810218 EOF located onsite & constructed of concrete. ZIMMERMAN, S R Carolina Power & Light Co 82/12/06 VARGA, S A Operating Reactors Branch 1 3pp 16379 160 24X Fiche 50-261, 82/12/06, B212100015

B212220487 Forwards draft SER App R exemption request. Exemption denied. Licensee required to provide capability to achieve cold shutdown within 72-h. VARGA, S A Operating Reactors Branch 1 82/12/10 UTLEY, E E Carolina Power & Light Co 38pp 16523 206 24X Fiche 50-261, 82/12/10, B212220487

P Operating license stage documents & correspondence

B212060130 Forwards notice of proposed issuance of amend to License DPR-23, in response to B20701 & 0716 ltrs describing plans to replace steam generators during 1983 refueling outage. VARGA, S A Operating Reactors Branch 1 82/11/18 UTLEY, E E Carolina Power & Light Co 3pp 16322 353 24X Fiche 50-261, 82/11/18, B212060130

--B212060137 Notice of proposed issuance of amend to License DPR-23 VARGA, S A Operating Reactors Branch 1 82/11/18 4pp 16322 354 24X Fiche 50-261, 82/11/18, B212060130

B212060069 Responds to Generic Ltr 82-22 re steam generator tube maintenance. Plant has experienced occasional minor tube leakage over last 4 yrs. Replacement steam generators have been ordered & replacement will start in late 1983. EURY, L W Carolina Power & Light Co 82/11/29 EISENHUT, D G Division of Licensing 2pp 16314 291 24X Fiche 50-261, 82/11/29, B212060069

B212140459 CONCENTRATIONS OF COPPER-BINDING PROTEINS IN LIVERS OF BLUEGILLS FROM THE COOLING LAKE AT THE H B ROBINSON NUCLEAR POWER STATION. HARRISON, F L, LAM, J R Lawrence Livermore Laboratory FIN A-0119 NUREG/CR-2822 82/11/30 Office of Nuclear Regulatory Research, Director 40pp Available at NRC \$4.50 16418 325 24X Fiche 50-261, 82/11/30, B212140459

B212060013 Forwards proprietary "HB Robinson Loss of Feedwater Transient at 1,955 MWt Model Description & Results " Rept withheld (ref 10CFR2.790). ZIMMERMAN, S R Carolina Power & Light Co 82/12/01 VARGA, S A Operating Reactors Branch 1 5pp 16313 279 24X Fiche 50-261, 82/12/01, B212060013

B212100021 Advises that response to deficiencies noted in "Control Room Habitability Evaluation - HB Robinson Steam Electric Generating Plant," will not be submitted until 830601, due to increased scope of evaluation. ZIMMERMAN, S R Carolina Power & Light Co 82/12/07 VARGA, S A Operating Reactors Branch 1 1p 16379 132 24X Fiche 50-261, 82/12/07, B212100021

B212100078 Forwards project plan for resolving pressurized thermal shock issue. Independent consultant will review & assess overall program. UTLEY, E E Carolina Power & Light Co 82/12/07 DENTON, H R Office of Nuclear Reactor Regulation, Director 14pp 16379 163 24X Fiche 50-261, 82/12/07, B212100078

B212150004 Informs that NRC recommendation that util provide plan addressing pressurized thermal shock issue unnecessary until B21207 commitment adequately addresses issue. EURY, L W Carolina Power & Light Co 82/12/08 PALLADINO, N J Commissioners 2pp 16422 331 24X Fiche 50-261, 82/12/08, B212150004

B208190263 Generic Ltr 82-32 to all PWR licensees re potential steam generator-related generic requirements. Forwards Science Applications, Inc draft rept re subj requirements. Comments requested within 30 days of ltr. Svc list encl. EISENHUT, D G Division of Licensing 82/12/09 Consolidated Edison Co of New York, Inc 29pp 16629 247 24X Fiche 50-000, 82/12/09, B208190263

B212130313 Forwards revised "HB Robinson Unit 2 Inservice Insp Program," Interval 2, 810307-910307, incorporating items discussed during B21018, 21 & 26 telcons. Revision supersedes 010310 & 1231 submittals. ZIMMERMAN, S R Carolina Power & Light Co 82/12/09 VARGA, S A Operating Reactors Branch 1 1p 16389 345 24X Fiche 50-261, 82/12/09, B212130313

B212140103 Generic Ltr 82-28 to all licensees of operating Westinghouse & C-E PWRs (except Arkansas Nuclear One, Unit 2 & San Onofre 2 & 3) re inadequate core cooling instrumentation sys. Svc list encl. EISENHUT, D G Division of Licensing 82/12/10 Yankee Atomic Electric Co 27pp 16690 035 24X Fiche 50-000, 82/12/10, B212140103

B212220465 Forwards Amend 73 to License DPR-23, safety evaluation & notice of issuance & availability. Amend removes 3 effective full-power months during Cycle 9 operations. REQUA, Q Operating Reactors Branch 1 82/12/10 UTLEY, E E Carolina Power & Light Co 2pp 16523 180 24X Fiche 50-261, 82/12/10, B212220465

--B212220470 Amend 73 to License DPR-23, removing 3 effective full-power months during Cycle 9 operations. VARGA, S A Operating Reactors Branch 1 82/12/10 2pp 16523 182 24X Fiche 50-261, 82/12/10, B212220465

--B212220474 Safety evaluation supporting Amend 73 to License DPR-23. Office of Nuclear Reactor Regulation, Director 82/12/10 6pp 16523 184 24X Fiche 50-261, 82/12/10, B212220465

- B212220477 Notice of issuance & availability of Amend 73 to License DPR-23. VARGA, S A Operating Reactors Branch 1 82/12/10 2pp 16523 190 24X Fiche 50-261, 82/12/10, B212220465

DOCKETED ITEMS

69

G:12300093 Forwards request for addl info re NUREG-0737, Item II E 1 2, "Auxiliary Feedwater Sys Automatic Initiation & Flow Indication " Response to all open items requested within 60 days
VARGA, S A Operating Reactors Branch 1 82/12/10 UTLEY, E E Carolina Power & Light Co 8pp 16624 266 24X
Fiche 50-261, 82/12/10, 8212300093

G:12210068 Forwards responses to draft technical evaluation rept re util submittals in response to NUREG-0612, "Control of Heavy Loads " Changes to insp of lifting devices, use of qualified operators & replacement of defective devices implemented
ZIMMERMAN, S R Carolina Power & Light Co 82/12/15 VARGA, S A Operating Reactors Branch 1 51pp 16485 176 24X
Fiche 50-261, 82/12/15, 8212210068

G:12210418 Responds to 820724 request for addl design info re NUREG-0737, Item II B 3, "Post-Accident Sampling Sys " Sys will be described in revision to updated FSAR by 830722
ZIMMERMAN, S R Carolina Power & Light Co 82/12/15 VARGA, S A Operating Reactors Branch 1 1p 16493 094 24X
Fiche 50-261, 82/12/15, 8212210418

B212290200 Discusses 820415 response to Generic Ltr 82-05 re NUREG-0737, Item II B 3, "Post-Accident Sampling " & commitment to have sys operational by 830101 Due to problems, operational date revised to 830211
CURR, B J Carolina Power & Light Co 82/12/21 EISENHUT, D G Division of Licensing 2pp 16578 199 24X Fiche 50-261, 82/12/21, 8212290200

B212280078 Responds to Generic Ltr 82-16 re NUREG-0737 Tech Specs, discussing status of items applicable to plant
ZIMMERMAN, S R Carolina Power & Light Co 82/12/23 EISENHUT, D G Division of Licensing 6pp 16565 127 24X Fiche 50-261, 82/12/23, 8212280078

G:12290469 Staff requirements memo summarizing 821209 discussion & vote in Washington, DC re pressurized thermal shock actions
Development of proposed rule establishing radiographic test NDT screening criterion recommended
CHILK, S J Office of the Secretary of the Commission 82/12/23 DIRCKS, W J Office of the Executive Director for Operations 2pp 16606 084 24X Fiche 50-261, 82/12/23, 8212290469

4 Inspection reports, IE Bulletins & correspondence

B208190240 IF Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Svc list encl
DEVOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240

G:12090345 Forwards IE Insp Rept 50-261/82-39 on 821012-15 No noncompliance noted
VERRELL, D M Division of Project & Resident Programs 82/11/03 UTLEY, E E Carolina Power & Light Co 1p 16365 139 24X
Fiche 50-261, 82/11/03, 8212090345

- 8212090351 IE Insp Rept 50-261/82-39 on 821012-15 No noncompliance noted Major areas inspected emergency preparedness exercise
CLINE, W E, JENKINS, O R Region 2, Office of Director 82/11/02 12pp 16365 140 24X Fiche 50-261, 82/11/03, 8212090345

B208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000, 82/11/05, 8208190245

B212090281 Forwards IE Insp Rept 50-261/82-38 on 821103-05 No noncompliance noted
VERRELL, D M Division of Project & Resident Programs 82/11/16 UTLEY, E E Carolina Power & Light Co 2pp 16365 260 24X
Fiche 50-261, 82/11/16, 8212090281

- 8212090288 IE Insp Rept 50-261/82-38 on 821103-05 No noncompliance noted Major areas inspected radiological environ monitoring, mgt & administrative controls, implementation of monitoring program, analytical QC & interlab comparison program
CUMMINGHAM, A L, MONTGOMERY, D M Division of Emergency Preparedness & Operational Support 82/11/15 5pp 16365 262 24X Fiche 50-261, 82/11/16, 8212090281

B208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X
Fiche 50-000, 82/11/18, 8208190251

B212090464 Confirms 821124 mgt meeting in Atlanta, GA to discuss enforcement significance re shipping of contaminated matl
Proposed meeting agenda encl
O'REILLY, J P Region 2, Office of Director 82/11/18 UTLEY, E E Carolina Power & Light Co 2pp 16364 121 24X
Fiche 50-261, 82/11/18, 8212090464

B208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list encl
DEVOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000, 82/11/26, 8208190256

B208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000, 82/11/30, 8208190257

B212290060 Partial response to FOIA request for seven categories of info Forwards documents listed in App A Documents 1 & 2 already in PDR App B documents available in PDR LPDR profiles for Oinna & Indian Point 3 encl
FELTON, J M Division of Rules and Records 82/11/30 SCHLESSEL, D A New York, State of 7pp 16607 239 24X
Fiche 50-000, 82/11/30, 8212290060

--8212290121 Forwards listed documents re IE Insp Rept 50-261/75-15 Documents filed in LPDR
MOSELEY, N C Region 2, Atlanta, Office of the Director 76/01/21 Hartsville, SC 1p 16608 006 24X Fiche 50-000, 82/11/30, 8212290060

--8212290125 Ack receipt of IE Insp Rept 50-261/75-15 on 751124-25 No proprietary info
UTLEY, E E Carolina Power & Light Co 76/01/14 MOSELEY, N C Region 2, Atlanta, Office of the Director 1p 16608 007 24X
Fiche 50-000, 82/11/30, 8212290060

--8212290133 Forwards IE Insp Rept 50-261/75-15 on 751124-25 No noncompliance noted
MOSELEY, N C Region 2, Atlanta, Office of the Director 75/12/24 JONES, J A Carolina Power & Light Co 2pp 16608 008 24X
Fiche 50-000, 82/11/30, 8212290060

--8212290138 IE Insp Rept 50-261/75-15 on 751124-25 No noncompliance noted Major areas inspected inservice insp results & procedures & eddy current insp of steam generator tubes
PARKER, R C, LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch HERDT, A R Region 2, Atlanta, Reactor Construction & Engineering Support Branch 75/12/19 6pp 16608 010 24X Fiche 50-000, 82/11/30, 8212290060

- 8212290144 Forwards listed documents re IE Insp Rept 50-261/75-14 Documents filed in LPDR
MOSELEY, N C Region 2, Atlanta, Office of the Director 76/01/13 Hartsville, SC 1p 16608 016 24X Fiche 50-000, 82/11/30, 8212290060

- 8212290148 Act receipt of 760105 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-261/75-14
LOWE, F J Region 2, Atlanta, Reactor Operations Nuclear Support Branch 76/01/13 JONES, J A Carolina Power & Light Co 1p 16608 017 24X Fiche 50-000, 82/11/30, 8212290060

--8212290155 Responds to NRC 751211 ltr re violations noted in IE Insp Rept 50-261/75-14 Corrective actions quarterly calibr of survey instruments will be performed per Health Physics Procedure HP-11 by 760131 & Procedure HP-1 will be revised
UTLEY, E E Carolina Power & Light Co 76/01/05 MOSELEY, N C Region 2, Atlanta, Office of the Director 4pp 16608 018 24X
Fiche 50-000, 82/11/30, 8212290060

--8212290158 Forwards IE Insp Rept 50-261/75-14 on 751104-19 Noncompliance noted
MOSELEY, N C Region 2, Atlanta, Office of the Director 75/12/11 JONES, J A Carolina Power & Light Co 2pp 16608 022 24X
Fiche 50-000, 82/11/30, 8212290060

--8212290165 IE Insp Rept 50-261/75-14 on 751104-19 Noncompliance noted failure to follow procedures for radiation surveys/maint of instrument records & surveillance testing procedures did not provide for recording "as-found" & "as-left" calibr data
PARKER, R C, LEWIS, R C, WHITENER, H L Region 2, Atlanta, Reactor Operations Nuclear Support Branch 75/12/16 17pp 16608 024 24X Fiche 50-000, 82/11/30, 8212290060

B208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl
DEVOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259

DOCKETED ITEMS

B208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets." Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03
Consolidated Edison Co of New York, Inc 110pp 16462 064 24X
Fiche 50-000, 82/12/03, 8208190261

B212130313 Forwards revised "HB Robinson Unit 2 Inservice Insp Program." Interval 2, 810307-910307, incorporating items discussed during 821018, 21 & 26 telcons. Revision supersedes 810310 & 1231 submittals
ZIMMERMAN, S R Carolina Power & Light Co 82/12/09 VAROA, S A Operating Reactors Branch 1 1p 16387 345 24X
Fiche 50-261, 82/12/09, 8212130313

--8212130317 Revised "HB Robinson Unit 2 Inservice Insp Program." Interval 2, 810307-910307
* Carolina Power & Light Co 82/12/09 78pp 16389 346 24X
Fiche 50-261, 82/12/09, 8212130313

B208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring." Svc list encl
DEVOUNO, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16, 8208190267

B208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27." Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X
Fiche 50-000, 82/12/20, 8208190268

R Periodic operating reports & related correspondence

B212060199 Forwards monthly operating rept for Nov 1982
STARKEY, R B Carolina Power & Light Co 82/12/03 DEVOUNO, R C Director's Office, Office of Inspection and Enforcement 1p 16313 047 24X Fiche 50-261, 82/12/03, 8212060199

--8212060201 Monthly operating rept for Nov 1982
MORRIS, H B Carolina Power & Light Co 82/12/01 3pp 16313 048 24X Fiche 50-261, 82/12/03, 8212060199

S Reportable occurrences, LERs & related correspondence

B212030004 PNO-11-82-131 on 821128, leaking injection valve resulted in caustic contamination of condensate storage tank by 20 gallons of 50% sodium hydroxide. Secondary coolant also contaminated. Sampling & evaluation underway
HEHL, C W, BENNIS, P Region 2, Office of Director 82/11/30 1p 16304 225 24X Fiche 50-261, 82/11/30, 8212030004

B212090120 Forwards LER 82-016/03L-0
STARKEY, R B Carolina Power & Light Co 82/11/30 O'REILLY, J P Region 2, Office of Director 1p 16397 231 24X
Fiche 50-261, 82/11/30, 8212090120

--8212090128 LER 82-016/03L-0 on 821103, containment fan cooler HVH-3 failed to restart during periodic test performance. Caused by defective time delay relay in motor breaker control circuit. Time delay relay replaced
COV, H T Carolina Power & Light Co 82/11/30 Region 2, Office of Director 2pp 16357 232 24X Fiche 50-261, 82/11/30, 8212090120

B212300272 Forwards LER 82-018/01L-0
STARKEY, R B Carolina Power & Light Co 82/12/23 O'REILLY, J P Region 2, Office of Director 1p 16594 001 24X
Fiche 50-261, 82/12/23, 8212300272

--8212300296 LER 82-018/01L-0 on 821213, at 81% power, low temp overpressure protection sys pressure transmitters found calibr incorrectly. Caused by calculational error on zero adjust correction on initial 1978 calibr data sheets
COX, H Y Carolina Power & Light Co 82/12/23 Region 2, Office of Director 3pp 16594 002 24X Fiche 50-261, 82/12/23, 8212300272

V. Operator Examinations

B212090122 Informs that written & oral exams scheduled for 820221. List of encl referenced until required for operator licensing exam must be furnished by 821220 to meet schedule requirements for conducting exams also encl
VERRELLI, D M Division of Project & Resident Programs 82/12/02 FURR, B J Carolina Power & Light Co 4pp 16357 264 24X
Fiche 50-261, 82/12/02, 8212090122

DOCKET 50-262 BRIGHAM YOUNG UNIV RESEARCH REACTOR

F Security, medical, emergency & fire protection plans

B212160731 Releases public version of revised reactor facility emergency plan
FELTON, J M Division of Rules and Records 82/12/10 Document Management Branch 1p 16464 177 24X Fiche 50-262, 82/12/10, 8212160731

--8212160734 Forwards public version of revised reactor facility emergency plan
DIXON, D R Brigham Young Univ 82/12/03 THOMAS, C D Standardization & Special Projects Branch 1p 16464 178 24X
Fiche 50-262, 82/12/10, 8212160731

--8212160742 Public version of revised reactor facility emergency plan
* Brigham Young Univ 82/12/03 9pp 16464 179 24X
Fiche 50-262, 82/12/10, 8212160731

DOCKET 50-263 MONTICELLO NUCLEAR GENERATING PLANT

F Security, medical, emergency & fire protection plans

B212100016 Forwards IE Insp Rept 50-263/82-11 on 820927-30, 1012-13 & 1022 & notice of violation
MORELUS, C E Division of Engineering & Technical Programs 82/11/24 GIBERTS, D E Northern States Power Co 2pp 16375 333 24X Fiche 50-263, 82/11/24, 8212100016

--8212100019 Notice of violation from insp on 820927-30, 1012-13 & 1022
MORELUS, C E Division of Engineering & Technical Programs 82/11/24 2pp 16375 335 24X Fiche 50-263, 82/11/24, 8212100016

--8212100023 IE Insp Rept 50-263/82-11 on 820927-30, 1012-13 & 1022
Noncompliance noted failure to conduct airborne activity survey during operation of box compactor & to conduct filtration sys air flow evaluation
LOVENDALE, P C, GRANT, W B, GREGER, L R Division of Engineering & Technical Programs 82/11/22 9pp 16375 337 24X
Fiche 50-263, 82/11/24, 8212100016

B212090343 Ack receipt of 821122 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Rept 50-263/82-13
MILLER, J R Division of Engineering & Technical Programs 82/12/03 LARSON, C E Northern States Power Co 1p 16365 086 24X
Fiche 50-263, 82/12/03, 8212090343

--8212090352 Responds to NRC 821029 ltr re violations noted in IE Safeguards Insp Rept 50-263/82-13. Corrective actions withheld
LARSON, C E Northern States Power Co 82/11/22 MILLER, J R Division of Engineering & Technical Programs 1p 16365 087 24X
Fiche 50-263, 82/12/03, 8212090343

B212140244 Forwards changes to security plan, to be incorporated in forthcoming revision. Changes withheld (ref 10CFR2 790)
MUSOLF, D Northern States Power Co 82/12/10 Office of Nuclear Reactor Regulation, Director 2pp 16409 306 24X
Fiche 50-263, 82/12/10, 8212140244

B212220306 Discusses layout of communications equipment required in control room, onsite technical support ctr & near-site emergency operations facility
KEPPLER, J G Region 3, Office of Director 82/12/16 Commonwealth Edison Co 3pp 16503 351 24X Fiche 50-000, 82/12/16, 8212220306

P Operating license stage documents & correspondence

B211230066 Generic Ltr 82-27 to all BWR licensees of operating reactors except LACBWR, Big Rock Point, Dresden 1, Humboldt Bay, applicants for OL & holders of CP re transmittal of NUREG-0763 & NUREG-0783 Svc list encl w/o stated encl
EISENHUT, D G Division of Licensing 82/11/15 General Public Utilities - OPU Service Corp 22pp 16387 004 24X
Fiche 50-000, 82/11/15, 8211230066

B212070391 Forwards payment for 820930 license amend request re source range monitor count rate
MUSOLF, D Northern States Power Co 82/11/17 DIOS, R M License Fee Management Branch 2pp 16336 326 24X Fiche 50-263, 82/11/17, 8212070391

B212090008 Forwards Amend 12 to License DPR-22, safety evaluation, technical evaluation rept & notice of issuance & availability Amend incorporates surveillance requirements associated w/reactor protection monitoring sys
VASSALLO, D B Operating Reactors Branch 2 82/11/30 MUSOLF, D M
Northern States Power Co 2pp 16384 274 24X
Fiche 50-263, 82/11/30, 8212090008

--B212090010 Amend 12 to License DPR-22, incorporating limiting conditions for operation & surveillance requirements associated w/reactor protection monitoring sys
VASSALLO, D B Operating Reactors Branch 2 82/11/30 4pp
16384 276 24X Fiche 50-263, 82/11/30, 8212090008

--B212090012 Safety evaluation supporting Amend 12 to License DPR-22
* Office of Nuclear Reactor Regulation, Director 82/11/30 2pp
16384 280 24X Fiche 50-263, 82/11/30, 8212090008

--B212090023 "Technical Evaluation Rept on Monitoring of Electric Power to Reactor Protection Sys for Monticello Nuclear Generating Plant," supporting Amend 12 to License DPR-22
SELAN, J C Lawrence Livermore Laboratory FIN A-0250
UC10-17145 82/07/16 NRC - No Detailed Affiliation Given
9pp 16384 282 24X Fiche 50-263, 82/11/30, 8212090008

--B212090026 Notice of issuance & availability of Amend 12 to License DPR-22
VASSALLO, D B Operating Reactors Branch 2 82/11/30 2pp
16384 292 24X Fiche 50-263, 82/11/30, 8212090008

B212090009 Forwards safety evaluation re BWR owners group 810522, 0921 & 820902 responses to NUREG-0737, Item 11 K 3 25, "Effect of Loss of AC Power on Pump Seals " Response acceptable
VASSALLO, D B Operating Reactors Branch 2 82/12/01 MUSOLF, D M
Northern States Power Co 2pp 16384 267 24X
Fiche 50-263, 82/12/01, 8212090009

--B212090011 Safety evaluation of BWR owners group generic response to NUREG-0737, Item 11 K 3 25, "Effect of Loss of AC Power on Pump Seals "
* Operating Reactors Branch 2 82/12/01 5pp 16384 269 24X
Fiche 50-263, 82/12/01, 8212090009

B212280032 Forwards Amend 13 to License DPR-22, safety evaluation & notice of issuance & availability Amend changes Tech Specs to incorporate revised safety & operating limits associated w/operation during Fuel Cycle 10
VASSALLO, D B Operating Reactors Branch 2 82/12/06 MUSOLF, D M
Northern States Power Co 2pp 16593 088 24X
Fiche 50-263, 82/12/06, 8212280002

- B212280003 Amend 13 to License DPR-22, changing Tech Specs to incorporate revised safety & operating limits associated w/operational facility during Fuel Cycle 10
VASSALLO, D B Operating Reactors Branch 2 82/12/06 9pp
16593 090 24X Fiche 50-263, 82/12/06, 8212280002

--B212280004 Safety evaluation supporting Amend 13 to License DPR-22
* Office of Nuclear Reactor Regulation, Director 82/12/06 8pp
16593 099 24X Fiche 50-263, 82/12/06, 8212280002

--B212280006 Notice of issuance & availability of Amend 13 to License DPR-22
VASSALLO, D B Operating Reactors Branch 2 82/12/06 2pp
16593 107 24X Fiche 50-263, 82/12/06, 8212280002

B212210544 Forwards Amend 14 to License DPR-22, safety evaluation & notice of issuance & availability Amend approves repair to recirculation sys piping & authorizes resumption of power
LISENHUT, D O Division of Licensing 82/12/10 MUSOLF, D M
Northern States Power Co 4pp 16502 239 24X
Fiche 50-263, 82/12/10, 8212210544

- B212210547 Amend 14 to License DPR-22, approving repairs to recirculation sys piping authorizing resumption of power & changing Tech Specs limiting conditions for coolant leak detection sys
VASSALLO, D B Operating Reactors Branch 2 82/12/10 6pp
16502 243 24X Fiche 50-263, 82/12/10, 8212210544

--B212210548 Safety evaluation supporting Amend 14 to License DPR-22
* Office of Nuclear Reactor Regulation, Director 82/12/10 19pp, 16502 249 24X Fiche 50-263, 82/12/10, 8212210544

--B212210552 Notice of issuance & availability of Amend 14 to License DPR-22
VASSALLO, D B Operating Reactors Branch 2 82/12/10 2pp
16502 268 24X Fiche 50-263, 82/12/10, 8212210544

B212210325 Forwards plant-unique analysis repts Vols 1-5 & App A Repts describe analyses conducted for suppression chamber vent sys, suppression chamber internals & safety relief valve discharge piping
MUSOLF, D Northern States Power Co 82/12/15 Office of Nuclear Reactor Regulation, Director 2pp 16497 135 24X
Fiche 50-263, 82/12/15, 8212210325

--B212210327 Vol 1, Revision 1 to plant-unique analysis rept, "General Criteria & Loads Methodology "
BONDRE, J R, MASTERSON, R E, MOLFORD, T J NUTECH (Nuclear Technology, Inc) NSP-74-101 R01 82/11/30 217pp 16497 138 24X Fiche 50-263, 82/12/15, 8212210325

--B212210330 Vol 2, Revision 1 to plant-unique analysis rept, "Suppression Chamber Analysis "
BENTINO, K W, MCINNES, I D, MOLFORD, T J NUTECH (Nuclear Technology, Inc) NSP-74-102 R01 82/11/30 184pp 16497 355 24X Fiche 50-263, 82/12/15, 8212210325

- B212210333 Vol 3, Revision 1 to plant-unique analysis rept, "Vent Sys Analysis "
HSU, T J, MCINNES, I D, MOLFORD, T J NUTECH (Nuclear Technology, Inc) NSP-74-103 R01 82/11/30 209pp 16498 179 24X
Fiche 50-263, 82/12/15, 8212210325

--B212210337 Vol 4, Revision 1 to plant-unique analysis rept, "Internal Structures Analysis "
BENTINO, K W, MCINNES, I D, MOLFORD, T J NUTECH (Nuclear Technology, Inc) NSP-74-104 R01 82/11/30 37pp 16499 028 24X Fiche 50-263, 82/12/15, 8212210325

- B212210342 Vol 5, Revision 1 to plant-unique analysis rept, "Safety Relief Valve Discharge Line Piping Analysis "
HERLEKAR, A S, AXLINE, J W, MOLFORD, T J NUTECH (Nuclear Technology, Inc) NSP-74-105 R01 82/11/30 146pp 16499 061 24X Fiche 50-263, 82/12/15, 8212210325

--B212210346 App A, Revision 1 to plant-unique analysis rept, "Monticello Responses to Previous Plant-Unique Analysis Rept - Current Containment & Piping Licensing Issues "
* NUTECH (Nuclear Technology, Inc) NSP-74-105A R01 82/11/30 90pp 16499 207 24X Fiche 50-263, 82/12/15, 8212210325

B212220545 Requests addl fees re util 820924 application for Tech Spec changes re surveillance clarification, reactor protection sys monitoring requirements & jet pump surveillance
DIGGS, R M License Fee Management Branch 82/12/15 MUSOLF, D
Northern States Power Co 1p 16523 351 24X Fiche 50-263, 82/12/15, 8212220545

Q Inspection reports, IE Bulletins & correspondence

B208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240

B208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000, 82/11/05, 8208190245

B208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X
Fiche 50-000, 82/11/18, 8208190251

B212100016 Forwards IE Insp Rept 50-263/82-11 on 820927-30, 1012-13 & 1022 & notice of violation
NORELIUS, C E Division of Engineering & Technical Programs 82/11/24 OIBERTS, D E Northern States Power Co 2pp 16375 333 24X Fiche 50-263, 82/11/24, 8212100016

--B212100019 Notice of violation from insp on 820927-30, 1012-13 & 1022
NORELIUS, C E Division of Engineering & Technical Programs 82/11/24 2pp 16375 335 24X Fiche 50-263, 82/11/24, 8212100016

--B212100023 IE Insp Rept 50-263/82-11 on 820927-30, 1012-13 & 1022
Noncompliance noted failure to conduct airborne activity survey during operation of box compactor & to conduct filtration sys air flow evaluation
LOVENDALE, P C, GRANT, W B, OREGER, L R Division of Engineering & Technical Programs 82/11/22 9pp 16375 337 24X
Fiche 50-263, 82/11/24, 8212100016

DOCKETED ITEMS

B208190256 IE Info Notice B2-46, "Defective & Obsolete Combination Padlocks " Svc list encl
 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000, B2/11/26, B208190256

B208190257 IE Info Notice B2-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl
 COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000, B2/11/30, B208190257

B212210007 Advises that concerns & requirements re IE Bulletin 80-06, "ESF Reset Controls," satisfied SER & technical evaluation forwarded
 VASSALLO, D B Operating Reactors Branch 2 82/12/01 MUSOLF, D M Northern States Power Co 2pp 16529 346 24X Fiche 50-263, B2/12/01, B212210007

--B212210008 Safety evaluation supporting licensee actions in response to IE Bulletin 80-06, "ESF Reset Controls "
 * Office of Nuclear Reactor Regulation, Director 82/12/01 2pp 16529 348 24X Fiche 50-263, B2/12/01, B212210007

--B105210384 "Technical Evaluation of Licensee's Response to IE Bulletin 80-06 re Engineered Safety Feature Reset Controls for Monticello Nuclear Generating Plant "
 HACKETT, D B E&O, Inc FIN A-0231 E00-1183-4210 B1/03/30 6pp 16529 350 24X Fiche 50-263, B2/12/01, B212210007

B208190259 IE Bulletin B2-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl
 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, B2/12/03, B208190259

B208190261 IE Info Notice B2-48, "Failures of Agastat CR 0095 Relay Hockets " Svc list encl
 JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X Fiche 50-000, B2/12/03, B208190261

B212090343 Ack receipt of B21122 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Rept 50-263/B2-13
 MILLER, J R Division of Engineering & Technical Programs 82/12/03 LARSON, C E Northern States Power Co 1p 16365 086 24X Fiche 50-263, B2/12/03, B212090343

--B212090352 Responds to NRC B21029 ltr re violations noted in IE Safeguards Insp Rept 50-263/B2-13 Corrective actions withheld
 LARSON, C E Northern States Power Co 82/11/22 MILLER, J R Division of Engineering & Technical Programs 1p 16365 087 24X Fiche 50-263, B2/12/03, B212090343

B208190267 IE Info Notice B2-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, B2/12/16, B208190267

B208190268 IE Info Notice B2-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27 " Svc list encl
 JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X Fiche 50-000, B2/12/20, B208190268

B Reportable occurrences, LERs & related correspondence

B212140344 Forwards updated LER B2-013/017-3
 MUSOLF, D Northern States Power Co 82/12/06 Region 3, Office of Director 1p 16401 358 24X Fiche 50-263, B2/12/06, B212140344

--B212140357 Updated LER B2-013/017-3 on B20928, 1020, 31 & 1102, during preparation for repair of E/C & F safe-ends, thru wall leaks found on each safe-end caused by intergranular stress corrosion cracking defects repaired
 HAMMER, S Northern States Power Co 82/12/06 Region 3, Office of Director 1p 16401 359 24X Fiche 50-263, B2/12/06, B212140344

B212210247 PNO-111-B2-135 on B21213, maint worker suffered second degree burns from contaminated steam during replacement of packing on main steam line drain isolation valve Worker treated & released State of MN will be notified
 WALKER, R , BARRETT, P , STREETER, J Region 3, Office of Director 82/12/14 1p 16483 316 24X Fiche 50-263, B2/12/14, B212210247

B212270276 PNO-111-B2-138 on B21217, turbine generator developed high vibration reading on bearing 5 due to worn bearing Unit to be taken to cold shutdown for repair of bearing
 BROWN, C , WALKER, R , STREETER, J Region 3, Office of Director 82/12/17 1p 16530 310 24X Fiche 50-263, B2/12/17, B212270276

DOCKET 50-265 QUAD-CITIES STATION, UNIT 2

F Security, medical, emergency & fire protection plans

B212030053 Ack receipt of B21108 ltr informing NRC of steps taken to resolve problems identified in IE Emergency Preparedness Appraisal Repts 50-254/B2-14 & 50-265/B2-16 Clarification re start & stop of 15-minute clock provided
 KEPPLER, J O Region 3, Office of Director 82/11/30 REED, C Commonwealth Edison Co 1p 16304 143 24X Fiche 50-254, B2/11/30, B212030053

--B212030054 Responds to NRC B20930 ltr re problems identified in Paragraph 5 of IE Emergency Preparedness Appraisal Repts 50-254/B2-14 & 50-265/B2-16 Add corporate emergency planning positions budgeted for 1983
 RAUSCH, T J Commonwealth Edison Co 82/11/08 KEPPLER, J O Region 3, Office of Director 3pp 16304 144 24X Fiche 50-254, B2/11/30, B212030053

B212030268 Releases public version of revised emergency plan implementing procedures
 FELTON, J M Division of Rules and Records 82/11/30 Document Management Branch 1p 16316 276 24X Fiche 50-254, B2/11/30, B212030268

--B212030273 Forwards public version of revised emergency plan implementing procedures, including Procedures QEP 330-6 re air sampling under accident conditions & QEP 330-T9 re air radiation monitoring sys Receipt form encl
 KOVACK, T J , GERNER, L Commonwealth Edison Co 82/10/18 DENTON, H R NRC - No Detailed Affiliation Given 1p 16316 278 24X Fiche 50-254, B2/11/30, B212030268

--B212030279 Public version of revised emergency plan implementing procedures, including Procedures QEP 330-6 re air sampling under accident conditions & QEP 330-T9 re air radiation monitoring sys
 * Commonwealth Edison Co 82/10/18 17pp 16316 279 24X Fiche 50-254, B2/11/30, B212030268

B212060172 Ack receipt of B21116 ltr informing NRC of steps taken to correct violations noted in NRC B21012 ltr re timeliness of emergency planning exercise submittals
 HIND, J A Division of Emergency Preparedness & Operational Support 82/12/01 REED, C Commonwealth Edison Co 1p 16313 086 24X Fiche 50-254, B2/12/01, B212060172

--B212060181 Responds to NRC B21012 ltr re timeliness of scenario submittals to FEMA Region VII FEMA Region VII to be included in submittals & meetings associated w/future exercises
 RAUSCH, T J Commonwealth Edison Co 82/11/16 KEPPLER, J O Region 3, Office of Director 1p 16313 087 24X Fiche 50-254, B2/12/01, B212060172

B212090325 Ack receipt of B21129 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Repts 50-254/B2-20 & 50-265/B2-21
 MILLER, J R Division of Engineering & Technical Programs 82/12/03 REED, C Commonwealth Edison Co 1p 16365 103 24X Fiche 50-254, B2/12/03, B212090325

--B212090338 Responds to NRC B21029 ltr re violations noted in IE Safeguards Insp Repts 50-254/B2-20 & 50-265/B2-21 Corrective actions withheld (ref 10CFR73.21)
 DELGORGHE, L O Commonwealth Edison Co 82/11/29 KEPPLER, J O Region 3, Office of Director 1p 16365 104 24X Fiche 50-254, B2/12/03, B212090325

B212090383 Forwards info re emergency operations facilities per B21122 & 1202 requests info previously submitted by telcon Request for written response unnecessary burden on licensee
 DELGORGHE, L O Commonwealth Edison Co 82/12/03 EISENHUT, D G Division of Licensing 2pp 16365 091 24X Fiche 50-000, B2/12/03, B212090383

B212140179 Responds to items re fire protection safe shutdown analysis, discussed in B20917 telephone conference Core can maintain water level above top of active fuel w/o initiation of RCIC flow for max of 14 minutes
 RAUSCH, T J Commonwealth Edison Co 82/12/06 EISENHUT, D G Division of Licensing 3pp 16410 205 24X Fiche 50-254, B2/12/06, B212140179

0212160127 Ack receipt of 820621 ltr transmitting changes to security plan. Revision 11 Change consistent w/provisions of 10CFR50.54(p) & does not decrease effectiveness of plan VASBALLO, D J Operating Reactors Branch 2 82/12/06 DELOERGE, L D Commonwealth Edison Co 3pp 16447 206 24X Fiche 50-254, 82/12/06, 8212160127

8212130017 Releases public version of Revision 1 to Emergency Plan Implementing Procedure EQ-2, "Pre-Established Onsite & Offsite Monitoring Locations (Maps)" FELTON, J M Division of Rules and Records 82/12/07 Document Management Branch 1p 16417 062 24X Fiche 50-000, 82/12/07, 8212130017

--8212130028 Forwards public version of Revision 1 to Emergency Plan Implementing Procedure EQ-2, "Pre-Established Onsite & Offsite Monitoring Locations (Maps)" Revised table of contents encl PAJONSKI, J Commonwealth Edison Co 82/11/01 DENTON, H R NRC - No Detailed Affiliation Given 2pp 16417 063 24X Fiche 50-000, 82/12/07, 8212130017

--8212130041 Public version of Revision 1 to Emergency Plan Implementing Procedure EQ-2, "Pre-Established Onsite & Offsite Monitoring Locations (Maps)" PAJONSKI, J E Commonwealth Edison Co 82/11/29 4pp 16417 065 24X Fiche 50-000, 82/12/07, 8212130017

0212140243 Advises of distribution of revisions to "Generating Station Emergency Plan" Braidwood annex not prepared TRAMM, T R Commonwealth Edison Co 82/12/07 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 16409 302 24X Fiche 50-000, 82/12/07, 8212140243

0212220175 Releases public version of revised generating station emergency plan implementing procedures FELTON, J M Division of Rules and Records 82/12/10 Document Management Branch 1p 16529 029 24X Fiche 50-000, 82/12/10, 8212220175

--8212220190 Forwards public version of revised generating station emergency plan implementing procedures, including Procedures ED-3 re demand polling of meteorological data & ED-20 re emergency forecast request PAJONSKI, J E Commonwealth Edison Co 82/11/15 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 16529 030 24X Fiche 50-000, 82/12/10, 8212220175

--8212220202 Public version of revised generating station emergency plan implementing procedures, including Procedures ED-3 re demand polling of meteorological data & ED-20 re emergency forecast request LITERSKI, L A Commonwealth Edison Co 82/10/13 48pp 16529 031 24X Fiche 50-000, 82/12/10, 8212220175

0212220306 Discusses layout of communications equipment required in control room, onsite technical support ctr & near-site emergency operations facility KEPLER, J O Region 3, Office of Director 82/12/16 Commonwealth Edison Co 3pp 16503 351 24X Fiche 50-000, 82/12/16, 8212220306

8212300167 Releases public version of revised generating station emergency plan telephone directory FELTON, J M Division of Rules and Records 82/12/20 Document Management Branch 1p 16612 215 24X Fiche 50-000, 82/12/20, 8212300167

--8212300179 Forwards public version of revised generating station emergency plan telephone directory MOORE, R D Commonwealth Edison Co 82/12/02 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 16612 216 24X Fiche 50-000, 82/12/20, 8212300167

--8212300199 Public version of revised generating station emergency plan telephone directory GALLE, D P Commonwealth Edison Co 82/11/05 60pp 16612 217 24X Fiche 50-000, 82/12/20, 8212300167

0212300400 Releases public version of revised emergency plan implementing procedures FELTON, J M Division of Rules and Records 82/12/22 Document Management Branch 1p 16613 203 24X Fiche 50-254, 82/12/22, 8212300400

- 8212300405 Forwards public version of revised emergency plan implementing procedures, including Procedures GEP 310-T3 re prioritized notification listing & GEP 360-3 re site evacuation Receipt form encl * Commonwealth Edison Co 82/12/08 DENTON, H R NRC - No Detailed Affiliation Given 2pp 16613 204 24X Fiche 50-254, 82/12/22, 8212300400

--8212300409 Public version of revised emergency plan implementing procedures, including Procedures GEP 310-T3 re prioritized notification listing & GEP 360-3 re site evacuation * Commonwealth Edison Co 82/12/08 12pp 16613 206 24X Fiche 50-254, 82/12/22, 8212300400

G Adjudicatory correspondence

8212070160 Memorandum & order granting licensee 820818 request to dismiss proceeding w/o prejudice Util received authority to increase spent fuel pool storage capacity, making shipment of spent fuel between plants unnecessary JOHNSON, E B Atomic Safety and Licensing Board Panel 82/12/03 Commonwealth Edison Co 4pp 16336 320 24X Fiche 50-000, 82/12/03, 8212070160

H General correspondence

8212280176 Notices of change in mailing address for NRC licensing matl WRIGHT, O N Illinois, State of, Dept Nuc Safety (formerly Dept Public Health) 82/12/20 EISENHUT, D O Division of Licensing 1p 16556 135 24X Fiche 50-000, 82/12/20, 8212280176

P Operating license stage documents & correspondence

821230066 Generic Ltr 82-27 to all BWR licensees of operating reactors except LACBWR, Big Rock Point, Dresden 1, Humboldt Bay, applicants for OL & holders of CP re transmittal of NUREQ-0763 & NUREQ-0783 Svc list encl w/o stated encl EISENHUT, D O Division of Licensing 82/11/15 General Public Utilities - GPU Service Corp 22pp 16387 004 24X Fiche 50-000, 82/11/15, 821230066

0212130275 Forwards safety evaluation of BWR owners group 810522, 0921 & 820902 responses to NUREQ-0737, Item 11 K 3 25, "Effect of Loss of AC Power on Pump Seals" Responses acceptable VASBALLO, D J Operating Reactors Branch 2 82/12/01 DELOERGE, L Commonwealth Edison Co 7pp 16418 213 24X Fiche 50-254, 82/12/01, 8212130275

0212160013 Forwards ltrs from engineering firms supporting spent fuel rack mod at facilities Min gap of 2 5 inches between racks does not invalidate previous seismic analyses if racks symmetrically loaded Restoration of 3-inch gap planned RAUSCH, T J Commonwealth Edison Co 82/12/10 EISENHUT, D O Division of Licensing 3pp 16446 074 24X Fiche 50-254, 82/12/10, 8212160013

8212220212 Forwards Revision 22 to CE-1-A, "QA Program for Nuclear Generating Stations" SWARTZ, E D Commonwealth Edison Co 82/12/14 HAASS, W P Quality Assurance Branch 1p 16518 007 24X Fiche 50-000, 82/12/14, 8212220212

--8212220231 "QA Program for Nuclear Generating Stations," Revision 22 * Commonwealth Edison Co CE-1-A R22 82/11/01 17pp 16518 009 24X Fiche 50-000, 82/12/14, 8212220212

8212280117 Forwards addl info re NUREQ-0737, Item 11 F 1, "Addl Accident Monitoring Instrumentation," per NRC 821109 request Pressure monitoring sys provided w/separate loop for narrow range monitoring SWARTZ, E D Commonwealth Edison Co 82/12/20 EISENHUT, D O Division of Licensing 9pp 16564 062 24X Fiche 50-000, 82/12/20, 8212280117

8212280343 Forwards addl info re NUREQ-0737, Items 11 F 1 4, 5 & 6 "Containment Pressure, Water Level & Hydrogen Monitoring," per Crutchfield 821109 ltr SWARTZ, E D Commonwealth Edison Co 82/12/20 EISENHUT, D O Division of Licensing 9pp 16561 083 24X Fiche 50-000, 82/12/20, 8212280343

8212290111 Application for amend to License DPR-29, consisting of change to Tech Specs allowing normal power operation for no more than one refueling cycle w/one main steam drain line isolation valve exhibiting excessive leakage w/o Tech Specs, RAUSCH, T J Commonwealth Edison Co 82/12/20 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 16582 241 24X Fiche 50-254, 82/12/20, 8212290111

8212280212 Forwards updated schedule for ongoing environ qualification testing programs, per 810528 commitment SWARTZ, E D Commonwealth Edison Co 82/12/22 EISENHUT, D O Division of Licensing 18pp 16556 161 24X Fiche 50-000, 82/12/22, 8212280212

DOCKETED ITEMS

8212280263 Clarifies position on classification of major mods to BWH Mark I Containment per 821216 1tr
 RAUSCH, T J Commonwealth Edison Co 82/12/22 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 14561 307 24X
 Fiche 50-000, 82/12/22, 8212280263

Q Inspection reports, IE Bulletins & correspondence

8208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sizing Piping at BWR Plants " Svc list encl
 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 14642 163 24X Fiche 50-000, 82/10/28, 8208190240

8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list encl
 COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 14372 142 24X Fiche 50-000, 82/11/05, 8208190245

8212020308 Forwards IE Insp Repts 50-254/82-15 & 50-265/82-17 on 820830-0902 & notice of violation
 MILLER, J R Division of Engineering & Technical Programs 82/11/16 REED, C Commonwealth Edison Co 2pp 16278 147 24X
 Fiche 50-254, 82/11/16, 8212020308

--8212020310 Notice of violation from insp on 820830-0902
 MILLER, J R Division of Engineering & Technical Programs 82/11/16 1p 16278 149 24X Fiche 50-254, 82/11/16, 8212020308

--8212020314 IE Insp Repts 50-254/82-15 & 50-265/82-17 on 820830-0902 Noncompliance noted failure to use strong, tight packages for transportation of low specific activity radwaste
 HUETER, L J, GRANT, W B, GREGER, L R. Region 3, Office of Director 82/10/12 9pp 16278 150 24X Fiche 50-254, 82/11/16, 8212020308

8208190251 IE Info Notice 82-44, "Classification of Emergency Plan Exercise Requirements " Svc list encl
 JORDAN, E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 14411 199 24X
 Fiche 50-000, 82/11/18, 8208190251.

8212030187 Forwards IE Insp Repts 50-254/82-18 & 50-265/82-20 on 820908-1022 No noncompliance noted
 STREETE, J F Division of Project & Resident Programs 82/11/19 REED, C Commonwealth Edison Co 2pp 16307 083 24X
 Fiche 50-254, 82/11/19, 8212030187

--8212030197 IE Insp Repts 50-254/82-18 & 50-265/82-20 on 820908-1022 No noncompliance noted Major areas inspected maint-refueling, training, vessel internal insp, reactor screen, feedwater sparger mod & followups on significant events & LERS
 CHIRISSOTIMOS, N, DUPONT, S G, WALKER, R D Region 3, Office of Director 82/11/19 10pp 16307 085 24X Fiche 50-254, 82/11/19, 8212030187

8212060191 Forwards IE Insp Repts 50-254/82-21 & 50-265/82-23 on 821026-29 No noncompliance noted
 MILLER, J R Division of Engineering & Technical Programs 82/11/23 REED, C Commonwealth Edison Co 2pp 16313 055 24X
 Fiche 50-254, 82/11/23, 8212060191

--8212060197 IE Insp Repts 50-254/82-21 & 50-265/82-23 on 821026-29 No noncompliance noted Major areas inspected normal operational & refueling radiation protection activities, staffing, training & status of certain NUREG-0737 items
 HUETER, L J, MILLER, D E, GREGER, L R Region 3, Office of Director 82/11/23 9pp 16313 057 24X Fiche 50-254, 82/11/23, 8212060191

8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list encl
 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 14411 065 24X Fiche 50-000, 82/11/26, 8208190256.

8208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl
 COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 354pp 16387 028 24X Fiche 50-000, 82/11/30, 8208190257

8212030053 Act receipt of 821108 1tr informing NRC of steps taken to resolve problems identified in IE Emergency Preparedness Appraisal Repts 50-254/82-14 & 50-265/82-16 Clarification re start & stop of 15-minute clock provided
 KEPPLER, J O Region 3, Office of Director 82/11/30 REED, C Commonwealth Edison Co 1p 16304 143 24X Fiche 50-254, 82/11/30, 8212030053

--8212030056 Responds to NRC 820930 1tr re problems identified in Paragraph 5 of IE Emergency Preparedness Appraisal Repts 50-254/82-14 & 50-265/82-16 Addl corporate emergency planning positions budgeted for 1983
 RAUSCH, T J Commonwealth Edison Co 82/11/08 KEPPLER, J O Region 3, Office of Director 3pp 16304 144 24X
 Fiche 50-254, 82/11/30, 8212030053

8208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl
 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 14411 317 24X Fiche 50-000, 82/12/03, 8208190259

8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Societs " Svc list encl
 JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 14642 064 24X
 Fiche 50-000, 82/12/03, 8208190261

8212090325 Ack receipt of 821129 1tr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Repts 50-254/82-20 & 50-265/82-21
 MILLER, J R Division of Engineering & Technical Programs 82/12/03 REED, C Commonwealth Edison Co 1p 16365 103 24X
 Fiche 50-254, 82/12/03, 8212090325

--8212090338 Responds to NRC 821029 1tr re violations noted in IE Safeguards Insp Repts 50-254/82-20 & 50-265/82-21 Corrective actions withheld (ref 10CFR73.21)
 DELGEOERGE, L O Commonwealth Edison Co 82/11/29 KEPPLER, J O Region 3, Office of Director 1p 16365 104 24X
 Fiche 50-254, 82/12/03, 8212090325

8212100145 Discusses until 821001 response to IE Insp Repts 50-254/82-13 & 50-265/82-15 re multiplet analysis capability in AAIB software Alternative in-depth review of AAIB acceptable, provided that NRC concerns addressed in review
 PAPERIELLO, C J Division of Emergency Preparedness & Operational Support 82/12/06 RAUSCH, T J Commonwealth Edison Co 1p 16376 042 24X Fiche 50-254, 82/12/06, 8212100145

8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 14628 191 24X Fiche 50-000, 82/12/16, 8208190267

8212270295 Ack receipt of 821124 1tr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-237/82-21, 50-249/82-22, 50-254/82-17 & 50-265/82-19
 NORELIUB, C E Division of Engineering & Technical Programs 82/12/16 REED, C Commonwealth Edison Co 2pp 16530 085 24X
 Fiche 50-000, 82/12/16, 8212270295

--8212270303 Responds to NRC 821026 1tr re violations noted in IE Insp Repts 50-237/82-21, 50-249/82-22, 50-254/82-17 & 50-265/82-19 Corrective actions annual audits of all active AE firms performing safety-related work required
 DELGEOERGE, L O Commonwealth Edison Co 82/11/24 KEPPLER, J O Region 3, Office of Director 4pp 16530 087 24X
 Fiche 50-000, 82/12/16, 8212270295

--8212270307 "EDS-NUTECH Interface Control Instructions," Revision 0
 TSCHUDI, W F NUTECH (Nuclear Technology, Inc) 82/09/30 22pp 14530 091 24X Fiche 50-000, 82/12/16, 8212270295

--8212270313 "IE Bulletin 79-14 & TAP Piping Evaluation, Quad Cities Units 1 & 2 & Dresden Units 2 & 3," Revision 0
 * NUTECH (Nuclear Technology, Inc) 82/10/01 9pp 16530 113 24X Fiche 50-000, 82/12/16, 8212270295

8212290346 Forwards IE Insp Repts 50-254/82-25 & 50-265/82-27 on 821115-19 No noncompliance noted
 LITTLE, W B Division of Engineering & Technical Programs 82/12/16 REED, C Commonwealth Edison Co 2pp 16586 177 24X
 Fiche 50-254, 82/12/16, 8212290346

--8212290348 IE Insp Repts 50-254/82-25 & 50-265/82-27 on 821115-19 No noncompliance noted Major areas inspected nonlicensed personnel & licensed operator requalification training procedures & records & surveillance scheduling program
 FARRELL, R E, PESCHEL, J M, HAWKINS, F C Division of Engineering & Technical Programs 82/12/14 5pp 16586 179 24X
 Fiche 50-254, 82/12/16, 8212290346

8212280110 Provides final status rept of IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys " Complete & final listings of portions of sys failing to meet FSAR requirements under NUTECH responsibility encl
 RAUSCH, T J Commonwealth Edison Co 82/12/17 KEPPLER, J O Region 3, Office of Director 3pp 16564 191 24X Fiche 50-000, 82/12/17, 8212280110

DOCKETED ITEMS

75

B708190268 IE Info Notice B2-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27, Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20
Consolidated Edison Co of New York, Inc 108pp 16628 293 24X
Fiche 50-000, 82/12/20, 8208190268

R Periodic operating reports & related correspondence

B212140443 "Evaluation of Quad Cities Nuclear Power Station -
Commonwealth Edison Co. 1982 "
* Institute of Nuclear Power Operations 82/11/08 39pp
16405 210 24X Fiche 50-254, 82/11/08, 8212140443

B212130196 Forwards monthly operating repts for Nov 1982
KALIVIANAKIS, N Commonwealth Edison Co 82/12/01 Director's
Office, Office of Inspection and Enforcement 1p 16396 151 24X
Fiche 50-254, 82/12/01, 8212130196

--B212130202 Monthly operating repts for Nov 1982
BUSE, R D Commonwealth Edison Co 82/12/01 21pp 16396 152
24X Fiche 50-254, 82/12/01, 8212130196

S Reportable occurrences, LERs & related correspondence

B212080390 Forwards LER 82-023/03L-0
KALIVIANAKIS, N Commonwealth Edison Co 82/11/30 KEPLER, J
Region 3, Office of Director 1p 16392 314 24X
Fiche 50-265, 82/11/30, 8212080390

--B212080404 LER 82-023/03L-0 on 821104, turbine stop valve could not be
reset during HPCI testing, preventing turbine operation
Caused by corroded contacts on valve hydraulic oil pressure
switch Switch replaced HPCI switches cleaned
BUSE, R Commonwealth Edison Co 82/11/30 Region 3, Office of
Director 1p 16352 315 24X Fiche 50-265, 82/11/30, 8212080390

B212100328 Forwards supplemental LER 82-018/03L-1
KALIVIANAKIS, N Commonwealth Edison Co 82/12/01 KEPLER, J
Region 3, Office of Director 1p 16377 048 24X
Fiche 50-265, 82/12/01, 8212100328

--B212100335 Supplemental LER 82-018/03L-1 on 821006, emergency diesel
generator tripped on high temp after loading Caused by
fouling of diesel generator cooling water sys Both HX
replaced
KAEPPEL, F Commonwealth Edison Co 82/12/01 Region 3, Office
of Director 1p 16377 049 24X Fiche 50-265, 82/12/01,
8212100328

DOCKET 50-266 POINT BEACH NUCLEAR PLANT, UNIT 1

F Security, medical, emergency & fire protection plans

B212070099 Forwards revised Page 10 3 to safeguards plan Page withheld
(ref 10CFR2 790 & 73 21)
BURSTEIN, S Wisconsin Electric Power Co 82/12/02 DENTON, H R
Office of Nuclear Reactor Regulation, Director CLARK, R A
Operating Reactors Branch 3 1p 16327 271 24X
Fiche 50-266, 82/12/02, 8212070099

B212280082 Responds to Burstein 821110 & 1202 ltrs re addition of
Chapter 10 to physical security plan Changes acceptable Ltrs
withheld (ref 10CFR73 21)
CLARK, R A Operating Reactors Branch 3 82/12/13 FAY, C W
Wisconsin Electric Power Co 1p 16593 087 24X
Fiche 50-266, 82/12/13, 8212280082

B212220306 Discusses layout of communications equipment required in
control room, onsite technical support ctr & near-site
emergency operations facility
KEPLER, J O Region 3, Office of Director 82/12/16
Commonwealth Edison Co 3pp 16503 351 24X Fiche 50-000, 82/12/16,
8212220306

B212290324 Confirms plans for 830110 mgt meeting in Milwaukee, WI re
fire protection concerns Written responses to IE Insp Repts
50-266/82-17 & 50-301/82-17 deferred until 830125
NOREL, IUB, C E Division of Engineering & Technical Programs
82/12/23 BURSTEIN, S Wisconsin Electric Power Co 1p 16589 157
24X Fiche 50-266, 82/12/23, 8212290324

G Adjudicatory correspondence

B212080251 Supports steam generator tube sleeving
BLAHAK, Q, ENGELBRECHT, L, SCHMOCK, D Two Rivers, WI 82/11/29
BLOCH, P Atomic Safety and Licensing Board Panel 1p 16394, 126
24X Fiche 50-266, 82/11/29, 8212080251

B212130191 Special prehearing conference order memorializing 821118
conference WI Environ Decade 820810 petition to intervene
dismissed since Decade willfully failed to attend conference
BLOCH, P D, KLINE, J R, PAXTON, H C Atomic Safety and Licensing
Board Panel 82/12/10 Wisconsin's Environmental Decade 18pp
16394 131 24X Fiche 50-266, 82/12/10, 8212130191

B212230357 Forwards licensee proposed findings of fact & conclusions of
law in form of proposed initial decision re repair of
corroded steam generator tubes
CHURCHILL, B W Shaw, Pittman, Potts & Trowbridge CHURCHILL, B W
Wisconsin Electric Power Co 82/12/20 BLOCH, P D, KLINE, J R,
PAXTON, H C Atomic Safety and Licensing Board Panel 1p
16511 207 24X Fiche 50-266, 82/12/20, 8212230357

--B212230357 Proposed findings of fact & conclusions of law in form of
proposed initial decision re repair of corroded steam
generator tubes by inserting sleeves Certificate of Avc
encl
CHURCHILL, B W Wisconsin Electric Power Co CHURCHILL, B W Shaw,
Pittman, Potts & Trowbridge 82/12/20 31pp 16511 208 24X
Fiche 50-266, 82/12/20, 8212230357

B212270316 Notice of appeal from 821210 special prehearing conference
order dismissing Decade 820810 & 1105 petitions to
intervene Affidavit of mailing encl
ANDERSON, P Wisconsin's Environmental Decade 82/12/20 3pp
16530 281 24X Fiche 50-266, 82/12/20, 8212270316

B212270323 Brief supporting appeal from 821210 special prehearing
conference order denying 820810 petition to intervene &
request for extension of time to complete brief Dismissal of
petition on stated grounds contrary to law
ANDERSON, P Wisconsin's Environmental Decade 82/12/20 Atomic
Safety and Licensing Board Panel 15pp 16530 215 24X
Fiche 50-266, 82/12/20, 8212270323

P Operating license stage documents & correspondence

B212170040 Ack receipt of 821123 ltr transmitting Class I fee for
820930 application Basis for not remitting additional
requested fee acceptable
DIGGS, R M License Fee Management Branch 82/12/03 FAY, C W
Wisconsin Electric Power Co 1p 16480 362 24X
Fiche 50-266, 82/12/03, 8212170040

B708190263 Generic Ltr 82-32 to all PWR licensees re potential steam
generator-related generic requirements Forwards Science
Applications, Inc draft repts re subj requirements Comments
requested within 30 days of ltr Svc list encl
EISENHUT, D O Division of Licensing 82/12/09 Consolidated
Edison Co of New York, Inc 2pp 16629 247 24X
Fiche 50-000, 82/12/09, 8208190263

B212140103 Generic Ltr 82-28 to all licensees of operating
Westinghouse & C-E PWRs (except Arkansas Nuclear One, Unit 2
& San Onofre 2 & 3) re inadequate core cooling
instrumentation sys Svc list encl
EISENHUT, D O Division of Licensing 82/12/10 Yankee Atomic
Electric Co 27pp 16690 035 24X Fiche 50-000, 82/12/10,
8212140103

B212170326 Refs Westinghouse 791206 ltr in response to RA Clark 821108
request for ECCS evaluation model addressing two loop upper
plenum injection plants Calculations for worst case large
break & sensitivity studies will be submitted by 830228
FAY, C W Wisconsin Electric Power Co 82/12/10 DENTON, H R
Office of Nuclear Reactor Regulation, Director CLARK, R A
Operating Reactors Branch 3 2pp 16453 224 24X
Fiche 50-266, 82/12/10, 8212170326

B212210056 Comments on technical evaluation repts re seismic
qualification of auxiliary feedwater system 821112 request
Recommendation to acquire complete SSE level of seismic
capacity constitutes unnecessary & expensive backfit
FAY, C W Wisconsin Electric Power Co 82/12/13 DENTON, H R,
Office of Nuclear Reactor Regulation, Director CLARK, R A
Operating Reactors Branch 3 5pp 16492 248 24X
Fiche 50-266, 82/12/13, 8212210056

B212220422 Application to amend Licenses DPR-24 & DPR-27, consisting of
Tech Spec Change Request 86 to address NUREG-0737, Item
II K.3.3, "Reporting Safety & Relief Valve Failures &
Challenges," in response to Generic Ltr 82-16
FAY, C W Wisconsin Electric Power Co 82/12/13 DENTON, H R
Office of Nuclear Reactor Regulation, Director CLARK, R A
Operating Reactors Branch 3 3pp 16503 278 24X
Fiche 50-266, 82/12/13, 8212220422

DOCKETED ITEMS

--B212220427 Proposed Tech Spec Change Request 86 addressing requirements of NUREG-0737, Item II K 3.3, "Reporting Safety & Relief Valve Failures & Challenges," in response to Generic Ltr B2-16
* Wisconsin Electric Power Co 82/12/15 1p 14503 201 24X
Fiche 50-266, 82/12/15, B212220422

B212270125 Discusses installation of RCS gas vent sys during Fall 1982 refueling outage. Several minor mods to as-designed piping & piping supports necessary to accommodate interferences from other components & sys in containment
FAY, C W Wisconsin Electric Power Co 82/12/17 DENTON, H R
Office of Nuclear Reactor Regulation, Director CLARK, R A
Operating Reactors Branch 3 2pp 14538 310 24X
Fiche 50-266, 82/12/17, B212270125

B212290300 Confirms B21215 telcon w/NRC clarifying until B21027 ltr re reg guide & QA program commitments per steam generator replacement project
FAY, C W Wisconsin Electric Power Co 82/12/22 DENTON, H R
Office of Nuclear Reactor Regulation, Director CLARK, R A
Operating Reactors Branch 3 2pp 14581 221 24X
Fiche 50-266, 82/12/22, B212290300

B212290095 Forwards "Evaluation of Pressurizer Safety & Relief Valve Sys for Point Beach Nuclear Plant," in further response to NUREG-0737, Item II D 1 re relief & safety valve testing
FAY, C W Wisconsin Electric Power Co 82/12/23 DENTON, H R
Office of Nuclear Reactor Regulation, Director CLARK, R A
Operating Reactors Branch 3 2pp 14599 169 24X
Fiche 50-266, 82/12/23, B212290095

--B212290104 "Evaluation of Pressurizer Safety & Relief Valve Sys for Point Beach Nuclear Plant" w/two oversize drawings. Aperture cards are available in PDR
HCKINNEY, T R, RAMSEY, B L, RAZLAFF, W J EDS Nuclear, Inc
09-0870-001 R00 82/12/21 4pp 14599 172 24X
Fiche 50-266, 82/12/23, B212290095

B212290143 Forwards response to B21116 request for addl info re steam generator repairs. Approx 900 personnel could receive radiation exposure during repairs
FAY, C W Wisconsin Electric Power Co 82/12/23 DENTON, H R
Office of Nuclear Reactor Regulation, Director CLARK, R A
Operating Reactors Branch 3 9pp 14583 199 24X
Fiche 50-266, 82/12/23, B212290143

G Inspection reports, IE Bulletins & correspondence

B208190240 IE Bulletin B2-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants." Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc
112pp 14462 163 24X Fiche 50-000, 82/10/28, B208190240

B208190245 IE Info Notice B2-42, "Defects Observed in Panasonic Model B01 & Model B02 Thermoluminescent Dosimeters" Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp
16372 142 24X Fiche 50-000, 82/11/05, B208190245

B208190251 IE Info Notice B2-44, "Clarification of Emergency Plan Exercise Requirements" Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 14411 199 24X
Fiche 50-000, 82/11/18, B208190251

B208190256 IE Info Notice B2-46, "Defective & Obsolete Combination Padlocks" Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc
127pp 14411 065 24X Fiche 50-000, 82/11/26, B208190256

B208190257 IE Info Notice B2-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl" Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp
14387 028 24X Fiche 50-000, 82/11/30, B208190257

B212170177 Forwards IE Insp Repts 50-266/82-17 & 50-301/82-17 on B20628-0701 & 08 & notice of violation.
NOREL, JUS, C E Division of Engineering & Technical Programs 82/11/30 BURSTEIN, S Wisconsin Electric Power Co 3pp
14450 192 24X Fiche 50-266, 82/11/30, B212170177

--B212170181 Notice of violation from insp on B20628-0701 & 08
NOREL, JUS, C E Division of Engineering & Technical Programs 82/11/30 4pp 14450 195 24X Fiche 50-266, 82/11/30, B212170177

--B212170189 IE Insp Repts 50-266/82-17 & 50-301/82-17 on B20628-0701 & 08 Noncompliance noted inadequate surveillance testing, nonfunctional penetration fire barrier & incomplete development & implementation of administrative controls
RAMSEY, C, ULIE, J, GROBE, J A Region 3, Office of Director 82/09/20 21pp 14450 199 24X Fiche 50-266, 82/11/30, B212170177

B208190259 IE Bulletin B2-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies" Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc
113pp 14411 317 24X Fiche 50-000, 82/12/03, B208190259

B208190261 IE Info Notice B2-48, "Failures of Agastat CR 0095 Relay Sockets" Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 14462 064 24X
Fiche 50-000, 82/12/03, B208190261

B212100221 Ack receipt of B21129 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-266/82-12 & 50-301/82-12
KEPPLER, J G Region 3, Office of Director 82/12/07 BURSTEIN, S
Wisconsin Electric Power Co 2pp 14377 101 24X
Fiche 50-266, 82/12/07, B212100221

--B212100222 Responds to NRC B20915 ltr re violations noted in IE Insp Repts 50-266/82-12 & 50-301/82-12 Corrective actions review of containment entry control procedures & controls & interchangeability of keys changed
FAY, C W Wisconsin Electric Power Co 82/10/15 KEPPLER, J G
Region 3, Office of Director 4pp 14377 103 24X
Fiche 50-266, 82/12/07, B212100221

--B212100223 Addl response to NRC B20915 ltr re violation noted in IE Insp Repts 50-266/82-12 & 50-301/82-12 Corrective actions areas roped off, conspicuously posted & flashing lights used as warning device
FAY, C W Wisconsin Electric Power Co 82/11/29 KEPPLER, J G
Region 3, Office of Director 3pp 14377 107 24X
Fiche 50-266, 82/12/07, B212100221

B208190267 IE Info Notice B2-49, "Correction for Sample Conditions for Air & Gas Monitoring" Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc
127pp 14628 191 24X Fiche 50-000, 82/12/16, B208190267

B212280361 Responds to IE Bulletin B2-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies" No Bunker Ramo penetration assemblies installed initially or during backfit & mod
FAY, C W Wisconsin Electric Power Co 82/12/17 KEPPLER, J G
Region 3, Office of Director 1p 14560 077 24X
Fiche 50-266, 82/12/17, B212280361

B212290332 Forwards IE Insp Rept 50-266/82-22 on B21102-03 & 18 No noncompliance noted
LITTLE, W S Division of Engineering & Technical Programs 82/12/17 BURSTEIN, S Wisconsin Electric Power Co 2pp 14586 203 24X
Fiche 50-266, 82/12/17, B212290332

--B212290336 IE Insp Rept 50-266/82-22 on B21102-03 & 18 No noncompliance noted Major areas inspected inservice insp procedures, work activities & NDE personnel certifications & data
WARD, K D, KEY, W J, CILIMBERO, R Region 3, Office of Director 82/12/10 7pp 14586 205 24X Fiche 50-266, 82/12/17, B212290332

B208190268 IE Info Notice B2-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27." Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 14628 293 24X
Fiche 50-000, 82/12/20, B208190268

R Periodic operating reports & related correspondence

B212290253 Forwards revised monthly operating repts for Aug 1982 for Units 1 & 2 & revised Sept 1982 rept for Unit 2
FAY, C W Wisconsin Electric Power Co 82/11/17 Office of Resource Management, Director 1p 14582 037 24X
Fiche 50-266, 82/11/17, B212290253

--B212290257 Revised monthly operating repts for Aug 1982
FAY, C W Wisconsin Electric Power Co 82/09/07 2pp 14582 038 24X Fiche 50-266, 82/11/17, B212290253

--B212290262 Revised monthly operating rept for Sept 1982
FAY, C W Wisconsin Electric Power Co 82/10/04 1p 14582 040 24X Fiche 50-266, 82/11/17, B212290253

DOCKETED ITEMS

77

8212210297 Forwards monthly operating repts for Nov 1982
 FAY, C W Wisconsin Electric Power Co 82/12/10 Office of
 Nuclear Reactor Regulation, Director 1p 16497 087 24X
 Fiche 50-266, 82/12/10, 8212210297

--8212210279 Monthly operating repts for Nov 1982
 FAY, C W Wisconsin Electric Power Co 82/12/06 11pp
 16497 090 24X Fiche 50-266, 82/12/10, 8212210279

5 Reportable occurrences, LERs & related correspondence

8212020276 Forwards LER 82-021/03L-0
 FAY, C W Wisconsin Electric Power Co 82/11/24 KEPLER, J G
 Region 3, Office of Director 1p 16288 253 24X
 Fiche 50-266, 82/11/24, 8212020276

--8212020281 LER 82-021/03L-0 on 821102, during installation of new fire
 protection equipment, fire detectors were de-energized. Caused
 by misunderstanding between plant & contractor personnel. New
 detectors installed & tested satisfactorily.
 FAY, C W Wisconsin Electric Power Co 82/11/24 Region 3,
 Office of Director 3pp 16288 254 24X Fiche 50-266, 82/11/24,
 8212020276

8212100224 Forwards LER 82-022/01T-0
 FAY, C W Wisconsin Electric Power Co 82/12/03 KEPLER, J G
 Region 3, Office of Director 1p 16376 067 24X
 Fiche 50-266, 82/12/03, 8212100224

-8212100225 LER 82-022/01T-0 on 821111, eddy current insp verified
 mechanical damage in excess of Tech Spec plugging limit
 after 821105-06 annular search indicated presence of foreign
 objects in steam generator. Cause not stated. Objects removed.
 FAY, C W Wisconsin Electric Power Co 82/12/03 Region 3,
 Office of Director 5pp 16376 068 24X Fiche 50-266, 82/12/03,
 8212100224

8212100202 LER 82-026/01T-0 on 821206, reactor protection rack relay
 dropout time found to be excessive upon being de-energized.
 Caused by coil filler epoxy leak into plunger cavity,
 inhibiting movement. Also reportable per Part 21
 LINK, R E Wisconsin Electric Power Co 82/12/07 KEPLER, J G
 Region 3, Office of Director 1p 16376 214 24X
 Fiche 50-266, 82/12/07, 8212100202

8212170161 Forwards LER 82-024/03L-0
 FAY, C W Wisconsin Electric Power Co 82/12/09 KEPLER, J G
 Region 3, Office of Director 1p 16450 222 24X
 Fiche 50-266, 82/12/09, 8212170161

-8212170172 LER 82-024/03L-0 on 821116, during review of test data, steam
 flow transmitter FT-463 discovered 0.177% nonconservative.
 Caused by nonconservative static zero shift. Instrument
 recalibr.
 FAY, C W Wisconsin Electric Power Co 82/12/09 Region 3,
 Office of Director 2pp 16450 223 24X Fiche 50-266, 82/12/09,
 8212170161

8212270177 Forwards updated LER 82-022/01T-1
 FAY, C W Wisconsin Electric Power Co 82/12/09 KEPLER, J G
 Region 3, Office of Director 1p 16535 116 24X
 Fiche 50-266, 82/12/09, 8212270177

-8212270202 Updated LER 82-022/01T-1 on 821111, eddy current testing
 indications of mechanical damage in excess of plugging
 limit verified. Cause not stated. Foreign objects removed.
 FAY, C W Wisconsin Electric Power Co 82/12/09 Region 3,
 Office of Director 5pp 16535 117 24X Fiche 50-266, 82/12/09,
 8212270177

8212270239 Forwards updated LER 82-017/01T-1
 FAY, C W Wisconsin Electric Power Co 82/12/10 KEPLER, J G
 Region 3, Office of Director 1p 16537 198 24X
 Fiche 50-266, 82/12/10, 8212270239

--8212270246 Updated LER 82-017/01T-1 on 821030, verified that indications
 for four steam generator A tubes & three steam generator B
 tubes exceeded 40% plugging limit during eddy current exam
 on 821026-30. Cause not stated. Tubes mechanically plugged.
 FAY, C W Wisconsin Electric Power Co 82/12/10 Region 3,
 Office of Director 7pp 16537 199 24X Fiche 50-266, 82/12/10,
 8212270239

8212280158 Forwards LER 82-025/03L-0
 FAY, C W Wisconsin Electric Power Co 82/12/16 KEPLER, J G
 Region 3, Office of Director 1p 16564 016 24X
 Fiche 50-266, 82/12/16, 8212280158

--8212280162 LER 82-025/03L-0 on 821117, while reviewing test data, two
 480-volt safeguards undervoltage relays found not meeting
 0 volt time delay spec. Relays adjusted to within spec &
 returned to svc.
 FAY, C W Wisconsin Electric Power Co 82/12/16 Region 3,
 Office of Director 2pp 16564 017 24X Fiche 50-266, 82/12/16,
 8212280158

8212290322 Forwards LER 82-026/01T-0
 FAY, C W Wisconsin Electric Power Co 82/12/20 KEPLER, J G
 Region 3, Office of Director 1p 16589 137 24X
 Fiche 50-266, 82/12/20, 8212290322

--8212290327 LER 82-026/01T-0 on 821206, reactor protection relays found
 to remain in energized position after being de-energized.
 Caused by coil filter epoxy leaking into plunger cavity.
 Failed coils replaced.
 FAY, C W Wisconsin Electric Power Co 82/12/20 Region 3,
 Office of Director 3pp 16589 138 24X Fiche 50-266, 82/12/20,
 8212290322

DOCKET 50-267 FORT ST VRAIN NUCLEAR GENERATING STATION

F Security, medical, emergency & fire protection plans

8212200050 Advises of scheduled medical emergency exercise on 821115.
 Exercise will commence early on day shift & involve
 transport of one or more simulated victims to offsite
 medical facilities for examination & treatment.
 HIRST, F J Public Service Co of Colorado 82/10/19 COLLINS, J T
 Region 4, Office of Director 1p 16474 254 24X
 Fiche 50-267, 82/10/19, 8212200050

8212200006 Informs that 820802 submittal of revised radiological
 emergency response plan implementing procedures reviewed.
 Procedures will be evaluated during next emergency
 preparedness appraisal followup.
 MADSEN, Q L Division of Resident, Reactor Project & Engineering
 Programs 82/11/02 LEE, D R Public Service Co of Colorado 1p
 16473 049 24X Fiche 50-267, 82/11/02, 8212200006

--8212200011 Notifies that revision to radiological emergency response
 plan implementing procedures will be submitted under
 separate cover. Revision includes cross-ref to other related
 procedures.
 WAREMBOURG, D W Public Service Co of Colorado 82/08/02
 COLLINS, J T Region 4, Office of Director 2pp 16473 050 24X
 Fiche 50-267, 82/11/02, 8212200006

8212200025 Ack receipt of 820824 response to NRC 820810 ltr re
 facility early warning sys.
 MADSEN, Q L Division of Resident, Reactor Project & Engineering
 Programs 82/11/02 LEE, D R Public Service Co of Colorado 1p
 16474 007 24X Fiche 50-267, 82/11/02, 8212200025

-8212200035 Responds to NRC 820810 request for info re distribution of
 radios to people who may move into 3-mile emergency planning
 zone (EPZ). Util flagging sys gives high level of confidence
 of identifying changes in 3-mile EPZ.
 WAREMBOURG, D W Public Service Co of Colorado 82/08/24
 MADSEN, Q L Division of Resident, Reactor Project & Engineering
 Programs 3pp 16474 008 24X Fiche 50-267, 82/11/02, 8212200025

8212200084 Ack receipt of 820708 ltr re Confirmatory Action Item 3 from
 820104-15 emergency preparedness appraisal. Response
 acceptable. Full evaluation to be made during followup
 appraisal later in yr.
 MADSEN, Q L Division of Resident, Reactor Project & Engineering
 Programs 82/11/02 LEE, D R Public Service Co of Colorado 3pp
 16474 300 24X Fiche 50-267, 82/11/02, 8212200084

--8212200090 Informs of completion of Confirmatory Action Item 3 re
 offsite radiological monitoring capability from Jan 1982
 emergency preparedness appraisal. Installation of iodine
 monitoring instrumentation completed.
 WAREMBOURG, D W Public Service Co of Colorado 82/07/08
 COLLINS, J T Region 4, Office of Director 2pp 16474 301 24X
 Fiche 50-267, 82/11/02, 8212200084

8212200096 Ack receipt of 820712 ltr submitting updated radiological
 emergency response plan.
 MADSEN, Q L Division of Resident, Reactor Project & Engineering
 Programs 82/11/02 LEE, D R Public Service Co of Colorado 1p
 16474 290 24X Fiche 50-267, 82/11/02, 8212200096

--8212200098 Notifies that updated radiological emergency response plan
 being forwarded under separate cover, per 820315 request.
 WAREMBOURG, D W Public Service Co of Colorado 82/07/12
 COLLINS, J T Region 4, Office of Director 1p 16474 291 24X
 Fiche 50-267, 82/11/02, 8212200096

DOCKETED ITEMS

B212200108 Ack receipt of D Warembourg 820810 ltr containing updated radiological emergency response plan
 MADSEN, O L Division of Resident, Reactor Project & Engineering Programs 82/11/02 LEE, O R Public Service Co of Colorado 1p
 16470 096 24X Fiche 50-267, 82/11/02, 8212200108

--B212200117 Forwards, under separate cover, updated radiological emergency response plan per JT Collins 820315 request Only visitors ctr procedure & radiological emergency response planning field procedure should be retained
 WAREMBOURG, D W Public Service Co of Colorado 82/08/10
 COLLINS, J T Region 4, Office of Director 1p 16470 097 24X
 Fiche 50-267, 82/11/02, 8212200108

B212200109 Ack receipt of 820921 revised radiological emergency response plan implementing procedure All future correspondence re emergency preparedness should be sent to JL Montgomery
 MADSEN, O L Division of Resident, Reactor Project & Engineering Programs 82/11/02 LEE, O R Public Service Co of Colorado 1p
 16470 098 24X Fiche 50-267, 82/11/02, 8212200109

--B212200116 Forwards revised radiological emergency response plan implementing procedures w/o encl
 WAREMBOURG, D W Public Service Co of Colorado 82/09/21
 COLLINS, J T Region 4, Office of Director 1p 16470 099 24X
 Fiche 50-267, 82/11/02, 8212200109

B212210023 Ack receipt of 820908 ltr responding to violations noted in IE Insp Rept 50-267/82-14 Requests date by which radiological emergency kit checklist will be equipped w/items on inventory list
 MADSEN, O L Division of Resident, Reactor Project & Engineering Programs 82/11/02 LEE, O R Public Service Co of Colorado 2pp
 16490 198 24X Fiche 50-267, 82/11/02, 8212210023

--B212210024 Responds to NRC 820811 ltr re violations noted in IE Insp Rept 50-267/82-14 Corrective actions util will provide addl RERP implementing procedure to provide further guidance on assuring personnel accountability of area residents
 WAREMBOURG, D W Public Service Co of Colorado 82/09/08
 MADSEN, O L Division of Resident, Reactor Project & Engineering Programs 7pp 16490 200 24X Fiche 50-267, 82/11/02, 8212210023

B212210167 Ack receipt of 820917 ltr in response to IE Emergency Appraisal Audit Rept 50-267/82-01 on 820104-15
 MADSEN, O L Division of Resident, Reactor Project & Engineering Programs 82/11/02 LEE, O R Public Service Co of Colorado 1p
 16484 237 24X Fiche 50-267, 82/11/02, 8212210167

--B212210173 Responds to IE Emergency Appraisal Audit Rept 50-267/82-01 of App B items on 820104-15 App B preparedness improvement items encl
 WAREMBOURG, D W Public Service Co of Colorado 82/09/17
 COLLINS, J T Region 4, Office of Director 41pp 16484 258 24X
 Fiche 50-267, 82/11/02, 8212210167

B212200043 Advises that medical emergency exercise rescheduled for 821114
 BORST, F J Public Service Co of Colorado 82/11/03 COLLINS, J T
 Region 4, Office of Director 3pp 16470 135 24X
 Fiche 50-267, 82/11/03, 8212200043

B212070425 Responds to FOIA request for documents re 820809 notice of violation & order imposing civil penalty Forwards App A documents App B documents completely withheld & Documents C1-C4 partially withheld (ref FOIA Exemptions 3.5 & 7)
 FELTON, J M Division of Rules and Records 82/11/05 MCGARRY, J M
 Bebovise & Liberman 5pp 16355 003 24X Fiche 50-000, 82/11/05, 8212070425

--B212070473 Concludes that all Region 4 licensees in compliance w/820201 deadline for implementation of prompt notification sys
 COLLINS, J T Region 4, Office of Director 82/02/01 GRINES, B K
 Division of Emergency Preparedness 2pp 16355 104 24X
 Fiche 50-000, 82/11/05, 8212070425

B212200030 Documents telcon between LM McBride & JA Kelly re unescorted access to facility for German THIR 300 staff
 Unescorted access will be granted under listed clearance criteria. Written concurrence requested
 WAREMBOURG, D W Public Service Co of Colorado 82/11/08
 COLLINS, J T Region 4, Office of Director 2pp 16474 266 24X
 Fiche 50-267, 82/11/08, 8212200030

B212290328 Discusses ORNL Rept TM-8171 re emergency warning sys Rept findings invalid in terms of specific refs re effectiveness on improvements needed in facility sys
 WAREMBOURG, D W Public Service Co of Colorado 82/12/09 CLARK, R
 Operating Reactors Branch 3 2pp 16389 141 24X
 Fiche 50-267, 82/12/09, 8212290328

B212290431 Informs that revised Chapter 9 of amended security plan, submitted in 820611 ltr, approved License amend will be issued to update existing license condition on physical protection & incorporate security plan revisions
 MADSEN, O L Division of Resident, Reactor Project & Engineering Programs 82/12/21 LEE, O R Public Service Co of Colorado 2pp
 16585 195 24X Fiche 50-267, 82/12/21, 8212290431

P Operating license stage documents & correspondence

B212290374 Forwards response to telephone inquiries re status of NUREG-0737, Item III D 3 4, "Control Room Habitability"
 WAREMBOURG, D W Public Service Co of Colorado 82/11/18
 CLARK, R A Operating Reactors Branch 3 2pp 16586 307 24X
 Fiche 50-267, 82/11/18, 8212290374

B212020409 Forwards request for addl info re NUREG-0612, "Control of Heavy Loads." Further clarification needed to adequately address areas discussed Comments encl for review Reply requested within 30 days of receipt of ltr
 CLARK, R A Operating Reactors Branch 3 82/11/19 LEE, O R Public Service Co of Colorado 3pp 16297 341 24X Fiche 50-267, 82/11/19, 8212020409

B212290319 Provides proposed resolutions to 821005 requests included in safety evaluation supporting Amend 28 to Tech Specs Method for calculating outlet temp of 7 northwest boundary regions incorporated in operator training program
 WAREMBOURG, D W Public Service Co of Colorado 82/11/22 CLARK, R A
 Operating Reactors Branch 3 11pp 16589 126 24X
 Fiche 50-267, 82/11/22, 8212290319

B212070084 Advises that issue of valve configuration resolved for facility
 CLARK, R A Operating Reactors Branch 3 82/11/26 LEE, O R Public Service Co of Colorado 2pp 16394 318 24X Fiche 50-267, 82/11/26, 8212070084

B212150226 Requests review of encl LASL rept on recommendations re control rod drive mechanism overtemp problem Commitment in form or Tech Spec limitation to ensure temps do not exceed 215 F requested
 CLARK, R A Operating Reactors Branch 3 82/12/02 LEE, O R Public Service Co of Colorado 17pp 16447 001 24X
 Fiche 50-267, 82/12/02, 8212150226

B212210012 Ack receipt of 821015 application proposing update to inservice insp & testing program Tech Specs surveillance requirements Application not exempt from fee requirements Class III fee requested
 BIGGS, R M License Fee Management Branch 82/12/03 LEE, O R Public Service Co of Colorado 1p 16502 360 24X
 Fiche 50-267, 82/12/03, 8212210012

B212280504 Informs of transfer of authority & responsibility for conducting reviews & evaluations commensurate w/implementing established licensing & regulatory requirements from Div of Licensing to Region 4
 EISENHUT, D O Division of Licensing 82/12/03 OAGLIARDO, J
 Division of Resident, Reactor Project & Engineering Programs 2pp
 16590 137 24X Fiche 50-267, 82/12/03, 8212280504

B212210520 Forwards independent evaluation of QA Co Rept QA-A16764, containing analysis of first plateau probe Reasonable agreement exists w/plateout probe measurements
 WAGNER, P C Division of Resident, Reactor Project & Engineering Programs 82/12/06 LEE, O R Public Service Co of Colorado 2pp
 16543 243 24X Fiche 50-267, 82/12/06, 8212210520

B212290403 Forwards proposed revisions to Tech Specs re organization, review & audit-administrative controls Clarifications of submittals, ltrs & discussions provided
 WAREMBOURG, D W Public Service Co of Colorado 82/12/13
 WAGNER, P C Region 4, Office of Director 4pp 16587 002 24X
 Fiche 50-267, 82/12/13, 8212290403

--B212290405 Draft composite for Tech Spec Section AC 7.1 re organization, review & audit-administrative controls
 * Public Service Co of Colorado 82/12/13 24pp 16587 006
 24X Fiche 50-267, 82/12/13, 8212290403

B212290421 Forwards Amend 29 to License DPR-34, safety evaluation & notice of issuance & availability Amend deletes requirement for monthly trip test of ultrasonic steam pipe rupture detectors
 WAGNER, P C Division of Resident, Reactor Project & Engineering Programs 82/12/13 LEE, O R Public Service Co of Colorado 3pp
 16585 201 24X Fiche 50-267, 82/12/13, 8212290421

DOCKETED ITEMS

79

--B212290427 Amend 29 to License DPR-34, deleting requirement for monthly trip tests of ultrasonic steam pipe rupture detectors
MADSEN, Q L Division of Resident, Reactor Project & Engineering Programs 82/12/13 4pp 16585 204 24X Fiche 50-267, 82/12/13, 8212290421

--B212290432 Safety evaluation supporting Amend 29 to License DPR-34
* Office of Nuclear Reactor Regulation, Director 82/12/13 3pp 16585 208 24X Fiche 50-267, 82/12/13, 8212290421

--B212290437 Notice of issuance & availability of Amend 29 to License DPR-34
MADSEN, Q L Division of Resident, Reactor Project & Engineering Programs 82/12/13 2pp 16585 211 24X Fiche 50-267, 82/12/13, 8212290421

B212290423 Responds to B21012 Generic Ltr 82-18 re operator requalification approach contrary to INPD objective of operator training, capability of industry to police itself & long-term proposed accreditation program
WAREMBOURG, D W Public Service Co of Colorado 82/12/13 WILKINSON, E P Institute of Nuclear Power Operations 2pp 16585 168 24X Fiche 50-267, 82/12/13, 8212290423

B212290368 Forwards four oversize P&IDs Aperture cards are available in PDR W/one proprietary oversize P&ID Aperture card is available in Central Files
LEDLANC, J Public Service Co of Colorado 82/12/15 NRC - No Detailed Affiliation Given 1p 16586 154 24X Fiche 50-267, 82/12/15, 8212290368

Q Inspection reports, IE Bulletins & correspondence

B208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Svc list encl
DEVOUNO, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240

B212200084 Ack receipt of B20708 ltr re Confirmatory Action Item 3 from B20104-15 emergency preparedness appraisal Response acceptable Full evaluation to be made during followup appraisal later in yr
MADSEN, Q L Division of Resident, Reactor Project & Engineering Programs 82/11/02 LEE, O R Public Service Co of Colorado 3pp 16474 300 24X Fiche 50-267, 82/11/02, 8212200084

--B212200090 Informs of completion of Confirmatory Action Item 3 re offsite radiological monitoring capability from Jan 1982 emergency preparedness appraisal Installation of iodine monitoring instrumentation completed
WAREMBOURG, D W Public Service Co of Colorado 82/07/08 COLLINS, J T Region 4, Office of Director 2pp 16474 301 24X Fiche 50-267, 82/11/02, 8212200084

B212210023 Ack receipt of B20908 ltr responding to violations noted in IE Insp Rept 50-267/82-14 Requests date by which radiological emergency kit checklist will be equipped w/items on inventory list
MADSEN, Q L Division of Resident, Reactor Project & Engineering Programs 82/11/02 LEE, O R Public Service Co of Colorado 2pp 16490 198 24X Fiche 50-267, 82/11/02, 8212210023

--B212210024 Responds to NRC B20811 ltr re violations noted in IE Insp Rept 50-267/82-14 Corrective actions until will provide addl RERP implementing procedure to provide further guidance on assuring personnel accountability of area residents
WAREMBOURG, D W Public Service Co of Colorado 82/09/08 MADSEN, Q L Division of Resident, Reactor Project & Engineering Programs 7pp 16490 200 24X Fiche 50-267, 82/11/02, 8212210023

B212210167 Ack receipt of B20917 ltr in response to IE Emergency Appraisal Audit Rept 50-267/82-01 on B20104-15
MADSEN, Q L Division of Resident, Reactor Project & Engineering Programs 82/11/02 LEE, O R Public Service Co of Colorado 1p 16484 257 24X Fiche 50-267, 82/11/02, 8212210167

--B212210173 Responds to IE Emergency Appraisal Audit Rept 50-267/82-01 of App B items on B20104-15 App B preparedness improvement items encl
WAREMBOURG, D W Public Service Co of Colorado 82/09/17 COLLINS, J T Region 4, Office of Director 4pp 16484 258 24X Fiche 50-267, 82/11/02, 8212210167

B208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model B01 & Model B02 Thermoluminescent Dosimeters " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000, 82/11/05, 8208190245

B212070255 Forwards IE Insp Rept 50-267/82-24 on B21001-31 & notice of violation
MADSEN, Q L Division of Resident, Reactor Project & Engineering Programs 82/11/17 LEE, O R Public Service Co of Colorado 2pp 16339 127 24X Fiche 50-267, 82/11/17, 8212070255

--B212070256 Notice of violation from insp on B21001-31
* Division of Resident, Reactor Project & Engineering Programs 82/11/17 2pp 16339 129 24X Fiche 50-267, 82/11/17, 8212070255

--B212070260 IE Insp Rept 50-267/82-24 on B21001-31 Noncompliance noted failure to follow std clearance point form requirements & failure to comply w/procedures
DICKERSON, M W, PLUMLEE, G L, WESTERMAN, T F Division of Resident, Reactor Project & Engineering Programs 82/11/09 9pp 16339 131 24X Fiche 50-267, 82/11/17, 8212070255

B208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X Fiche 50-000, 82/11/18, 8208190251

B208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list encl
DEVOUNO, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000, 82/11/26, 8208190256

B212200092 Provides revised paragraph to B21103 response to IE Insp Rept 50-267/82-19 Ltr inadvertently contained error in date when full compliance of CN 653 achieved
LEE, O R Public Service Co of Colorado 82/11/29 COLLINS, J T Region 4, Office of Director 1p 16470 049 24X Fiche 50-267, 82/11/29, 8212200092

--B212200101 Responds to NRC B21006 ltr re violations noted in IE Insp Rept 50-267/82-19 Corrective actions CN 653 completed
LEE, O R Public Service Co of Colorado 82/11/03 COLLINS, J T Region 4, Office of Director 2pp 16470 050 24X Fiche 50-267, 82/11/29, 8212200092

B208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000, 82/11/30, 8208190257

B208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl
DEVOUNO, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259

B208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Solenoids " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X Fiche 50-000, 82/12/03, 8208190261

B212210012 Ack receipt of B21015 application proposing update to inservice insp & testing program Tech Specs surveillance requirements Application not exempt from fee requirements Class III fee requested
D1005, R M License Fee Management Branch 82/12/03 LEE, O R Public Service Co of Colorado 1p 16502 360 24X Fiche 50-267, 82/12/03, 8212210012

B212290357 Responds to NRC B21117 ltr re violations noted in IE Insp Rept 50-267/82-24 Corrective actions std clearance form for control rod drives revised to allow positioning of breaker during removal or installation
LEE, O R Public Service Co of Colorado 82/12/06 COLLINS, J T Region 4, Office of Director 3pp 16586 261 24X Fiche 50-267, 82/12/06, 8212290357

B212290460 Advises that IE Insp Rept 50-267/82-16 canceled
MADSEN, Q L Division of Resident, Reactor Project & Engineering Programs 82/12/15 LEE, O R Public Service Co of Colorado 1p 16585 221 24X Fiche 50-267, 82/12/15, 8212290460

B208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
DEVOUNO, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16, 8208190267

B208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27 " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X Fiche 50-000, 82/12/20, 8208190268

DOCKETED ITEMS

R Periodic operating reports & related correspondence

G12210102 Forwards revised monthly operating rpt for Sept 1982
WAREHBOURG, D Public Service Co of Colorado 82/11/01
GAMMILL, W P Assistant Director for Operating Reactors 1p
16491 051 24X Fiche 50-267, 82/11/01, 8212210102

--8212210112 Revised monthly operating rpt for Sept 1982
MCBRIDE, L M Public Service Co of Colorado 82/10/06 9pp
16491 052 24X Fiche 50-267, 82/11/01, 8212210102

G12200094 Forwards monthly operating rpt for Oct 1982
WAREHBOURG, D Public Service Co of Colorado 82/11/08
Director's Office, Office of Inspection and Enforcement 2pp
16474 283 24X Fiche 50-267, 82/11/08, 8212200094

G12290391 Forwards monthly operating rpt for Nov 1982
WAREHBOURG, D Public Service Co of Colorado 82/12/14
GAMMILL, W P Office of Nuclear Reactor Regulation, Director 1p
16985 282 24X Fiche 50-267, 82/12/14, 8212290391

--8212290394 Monthly operating rpt for Nov 1982
MCBRIDE, L M Public Service Co of Colorado 82/12/07 8pp
16985 283 24X Fiche 50-267, 82/12/14, 8212290391

S Reportable occurrences, LERs & related correspondence

G12200123 Forwards LER 82-043/03L-0 Detailed event analysis encl
WAREHBOURG, D Public Service Co of Colorado 82/11/24
COLLINS, J T Region 4, Office of Director 5pp 16470 142 24X
Fiche 50-267, 82/11/24, 8212200123

--8212200128 LER 82-043/03L-0 on 821027 & 28, average PCRV cooling water
sys inlet & outlet temps fell below 100 F Caused by
insufficient heat to maintain loop averages w/both loops
in svc Auxiliary heat obtained & operators restructured
FULLER, C Public Service Co of Colorado 82/11/24 Region 4,
Office of Director 1p 16470 147 24X Fiche 50-267, 82/11/24,
8212200123

G12290297 Forwards LER 82-044/03L-0 Detailed event analysis encl
WAREHBOURG, D Public Service Co of Colorado 82/12/08
COLLINS, J T Region 4, Office of Director 5pp 16581 215 24X
Fiche 50-267, 82/12/08, 8212290297

--8212290303 LER 82-044/03L-0 on 821110 & 11, primary coolant dewpoint
temp exceeded Tech Spec limits Caused by water in reactor
vessel vaporizing faster than helium purification sys could
function Reactor power decreased
FULLER, C Public Service Co of Colorado 82/12/09 Region 4,
Office of Director 1p 16981 220 24X Fiche 50-267, 82/12/08,
8212290297

G12290426 Forwards LER 82-045/03L-0
WAREHBOURG, D Public Service Co of Colorado 82/12/15
COLLINS, J T Region 4, Office of Director 1p 16583 179 24X
Fiche 50-267, 82/12/15, 8212290426

--8212290440 LER 82-045/03L-0 on 821119, loop 1 PCRV cooling water outlet
temp exceeded Tech Spec limit Caused by inadvertent
operation of wrong valve by nonlicensed personnel Proper
valve lineup established Water temp stabilized
FULLER, C Public Service Co of Colorado 82/12/15 Region 4,
Office of Director 4pp 16583 180 24X Fiche 50-267, 82/12/15,
8212290426

DOCKET 50-269 OCONEE NUCLEAR STATION, UNIT 1

F Security, medical, emergency & fire protection plans

G12130069 Forwards info on emergency offsite facilities (EOF), per
R Birkel 821203 request & Generic LER 81-10 Const of
permanent primary & backup EOF completed
TUCKER, H B Duke Power Co 82/12/03 DENTON, H R Office of
Nuclear Reactor Regulation, Director ADENSAM, E O Licensing Branch
4 2pp 16390 185 24X Fiche 50-000, 82/12/03, 8212130069

G12090044 Reviews until 820419 & 0727 ltrs re security personnel
requalification requirements Annual supervisor observation
considered sufficient requalification test
STOLZ, J F Operating Reactors Branch 4 82/12/07 TUCKER, H B
Duke Power Co 2pp 16384 244 24X Fiche 50-000, 82/12/07,
8212090044

G12230093 Releases public version of revision to crisis mgt plan &
revisions to crisis mgt plan implementing procedures
FELTON, J M Division of Rules and Records 82/12/15 Document
Management Branch 1p 16542 026 24X Fiche 50-000, 82/12/15,
8212230093

--8212230108 Forwards public version of Revision 7 to crisis mgt plan &
revisions to crisis mgt plan implementing procedures
TUCKER, H B Duke Power Co 82/12/02 DENTON, H R Office of
Nuclear Reactor Regulation, Director ADENSAM, E O Operating
Reactors Branch 4 2pp 16542 027 24X Fiche 50-000, 82/12/15,
8212230093

--8212230124 Public version of Revision 7 to crisis mgt plan One oversize
pamphlet encl Aperture card available in PDR
VAUGHN, R E Duke Power Co 82/11/29 9pp 16542 029 24X
Fiche 50-000, 82/12/15, 8212230093

--8212230134 Public version of revised crisis mgt plan implementing
procedures, including Procedures 5 3 2 re crisis news group
plan & 5 3 1 re McGuire crisis phone directory
VAUGHN, R E Duke Power Co 82/11/29 280pp 16542 038 24X
Fiche 50-000, 82/12/15, 8212230093

G12280351 Application to amend Licenses DPR-38, DPR-47 & DPR-55,
revising App A Tech Specs to change frequency of station
security plan & implementing procedure audits from once
every 2 yrs to yearly
TUCKER, H B Duke Power Co 82/12/21 DENTON, H R Office of
Nuclear Reactor Regulation, Director 2pp 16560 087 24X
Fiche 50-269, 82/12/21, 8212280351

--8212280367 Proposed Tech Spec revision changing frequency of station
security plan & implementing procedure audits from once
every 2 yrs to yearly
* Duke Power Co 82/12/21 1p 16560 089 24X
Fiche 50-269, 82/12/21, 8212280351

P Operating license stage documents & correspondence

G12010185 Forwards Amends 116, 116 & 113 to Licenses DPR-38, DPR-47 &
DPR-55, respectively, safety evaluation & EIA & notice of
issuance & availability Amend revises Tech Spec restrictions
on burning low level contaminated oil
WAGNER, P C Operating Reactors Branch 4 82/11/15 TUCKER, H B
Duke Power Co 3pp 16271 232 24X Fiche 50-269, 82/11/15,
8212010185

--8212010193 Amends 116, 116 & 113 to Licenses DPR-38, DPR-47 & DPR-55,
respectively, revising Tech Spec restrictions on burning low
level contaminated oil
STOLZ, J F Operating Reactors Branch 4 82/11/15 8pp
16271 235 24X Fiche 50-269, 82/11/15, 8212010185

--8212010205 Safety evaluation & EIA supporting Amends 116, 116 & 113 to
Licenses DPR-38, DPR-47 & DPR-55, respectively
* Office of Nuclear Reactor Regulation, Director 82/11/15 6pp
16271 243 24X Fiche 50-269, 82/11/15, 8212010185

--8212010276 Notice of issuance & availability & negative declaration of
Amends 116, 116 & 113 to Licenses DPR-38, DPR-47 & DPR-55,
respectively
STOLZ, J F Operating Reactors Branch 4 82/11/15 2pp
16271 249 24X Fiche 50-269, 82/11/15, 8212010185

G12010392 Forwards Amends 117, 117 & 114 to Licenses DPR-38, DPR-47 &
DPR-55, respectively, safety evaluation & notice of issuance
& availability Amends incorporate digital logic channels &
emergency power switching logic
WAGNER, P C Operating Reactors Branch 4 82/11/22 TUCKER, H B
Duke Power Co 3pp 16271 030 24X Fiche 50-269, 82/11/22,
8212010392

--8212010418 Amends 117, 117 & 114 to Licenses DPR-38, DPR-47 & DPR-55,
respectively, incorporating digital logic channels &
emergency power switching logic & revising bases to define
redundant component testing
STOLZ, J F Operating Reactors Branch 4 82/11/22 28pp
16271 033 24X Fiche 50-269, 82/11/22, 8212010392

--8212010421 Safety evaluation supporting Amends 117, 117 & 114 to
Licenses DPR-38, DPR-47 & DPR-55, respectively
* Office of Nuclear Reactor Regulation, Director 82/11/22 4pp
16271 061 24X Fiche 50-269, 82/11/22, 8212010392

--8212010488 Notice of issuance & availability of Amends 117, 117 & 114 to
Licenses DPR-38, DPR-47 & DPR-55, respectively
STOLZ, J F Operating Reactors Branch 4 82/11/22 2pp
16271 065 24X Fiche 50-269, 82/11/22, 8212010392

G12070370 Forwards license amend fee in response to 821108 ltr
TUCKER, H B Duke Power Co 82/11/22 DIOGS, R M License Fee
Management Branch 2pp 16336 324 24X Fiche 50-269, 82/11/22,
8212070370

DOCKETED ITEMS

81

B212070341 Forwards responses to NUREG-0737, Item II B 3. "Post-Accident Sampling Sys " W/14 oversize drawings Aperture cards are available in PDR
TUCKER, H B Duke Power Co 82/12/01 DENTON, H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors Branch 4 32pp 16340 252 24X Fiche 50-269, 82/12/01, 8212070341

--B212070348 "Estimate of Failed Fuel Based on I-131 Concentration " HULL, P, OWEN, T B Duke Power Co 82/08/03 22pp 16340 283 24X Fiche 50-269, 82/12/01, 8212070341

--B212070353 "Operating Procedure for Operation of Post-Accident Liquid Sample Sys " DEAK, A M, MCCONNELL, T Duke Power Co 82/05/17 18pp 16340 305 24X Fiche 50-269, 82/12/01, 8212070341

--B212070392 "Post-Accident Containment Air Sampling System " W/twelve oversize drawings Aperture cards are available in PDR
* Duke Power Co 82/01/29 89pp 16340 324 24X Fiche 50-269, 82/12/01, 8212070341

--B212070395 "Post-Accident Liquid Sampling System " W/nine oversize drawings Aperture cards are available in PDR
* Duke Power Co 82/01/29 376pp 16341 053 24X Fiche 50-269, 82/12/01, 8212070341

G212100355 Summary of 821130 meeting w/util re use of Mark BZ fuel assemblies in future reload cores Viewgraphs encl
HAGHER, P C Operating Reactors Branch 4 82/12/01 Operating Reactors Branch 4 54pp 16399 041 24X Fiche 50-269, 82/12/01, 8212100355

O/12150073 Requests clarification of conditional snubber operability as described in certain Tech Specs Request due to discussion in IE Insp Repts 50-269/82-37, 50-270/82-37 & 50-287/82-37
TUCKER, H B Duke Power Co 82/12/08 DENTON, H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors Branch 4 3pp 16427 339 24X Fiche 50-269, 82/12/08, 8212150073

B208190263 Generic Ltr 82-32 to all PWR licensees re potential steam generator-related generic requirements Forwards Science Applications, Inc draft repts re subj requirements Comments requested within 30 days of ltr Svc list encl
EISENHUT, D O Division of Licensing 82/12/09 Consolidated Edison Co of New York, Inc 29pp 16629 247 24X Fiche 50-000, 82/12/09, 8208190263

B212130190 Comments on status of Unresolved Safety Issue A-49 re pressurized thermal shock for facilities Recent calculations confirming that no near-term safety concern exists should be reflected in NRC rept
TUCKER, H B Duke Power Co 82/12/09 DENTON, H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors Branch 4 2pp 16376 129 24X Fiche 50-269, 82/12/09, 8212130190

G212270335 Forwards order for license mod re installation of inadequate core cooling instrumentation sys as specified in NUREG-0737, Item II F 2. "Inadequate Core Cooling "
EISENHUT, D O Division of Licensing 82/12/10 TUCKER, H B Duke Power Co 2pp 16555 338 24X Fiche 50-269, 82/12/10, 8212270335

--B212270338 Order for license mod to conform w/specs of NUREG-0737, Item II F 2 Checklist for specific review encl
EISENHUT, D O Division of Licensing 82/12/10 Duke Power Co 11pp 16555 339 24X Fiche 50-269, 82/12/10, 8212270335

G212210079 Advises that submittal of revised radiological effluent Tech Specs incorporating agreements reached during 820818-19 meetings delayed until 830131, per util 821110 commitment
TUCKER, H B Duke Power Co 82/12/15 DENTON, H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors Branch 4 1p 16485 247 24X Fiche 50-269, 82/12/15, 8212210079

B212280351 Application to amend Licenses DPR-38, DPR-47 & DPR-55, revising App A Tech Specs to change frequency of station security plan & implementing procedure audits from once every 2 yrs to yearly
TUCKER, H B Duke Power Co 82/12/21 DENTON, H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors Branch 4 2pp 16560 087 24X Fiche 50-269, 82/12/21, 8212280351

--B212280367 Proposed Tech Spec revision changing frequency of station security plan & implementing procedure audits from once every 2 yrs to yearly
* Duke Power Co 82/12/21 1p 16560 089 24X Fiche 50-269, 82/12/21, 8212280351

O Inspection reports, IE Bulletins & correspondence

B208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 14462 163 24X Fiche 50-000, 82/10/28, 8208190240

B212090181 Forwards IE Insp Repts 50-269/82-39, 50-270/82-39 & 50-287/82-39 on 820915-1010 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 82/10/29 TUCKER, H B Duke Power Co 2pp 16359 197 24X Fiche 50-269, 82/10/29, 8212090181

--B212090189 IE Insp Repts 50-269/82-39, 50-270/82-39 & 50-287/82-39 on 820915-1010 No noncompliance noted Major areas inspected operation safety verification, maint activities, surveillance testing, startup testing & THM action item implementation
ORDERS, W, FALCONER, D, BRYANT, J C Division of Project & Resident Programs 82/10/28 7pp 16359 199 24X Fiche 50-269, 82/10/29, 8212090181

B208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model B01 & Model B02 Thermoluminescent Dosimeters " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000, 82/11/05, 8208190245

B212090420 Forwards response to IE Bulletin 82-02, "Degradation of Threaded Fasteners in RCPB of PWR Plants," Item I for Unit 1 & Items 2 & 4 for Unit 3 Response to Items 2 & 4 for Units 1 & 2 will be provided following next refueling outage
TUCKER, H B Duke Power Co 82/11/15 O'REILLY, J P Region 2, Office of Director 4pp 16365 033 24X Fiche 50-269, 82/11/15, 8212090420

B212060310 Grants 820830 request for relief from volumetric exams of piping welds in sections of containment sump & reactor bldg spray sys piping Safety evaluation encl
STOLZ, J F Operating Reactors Branch 4 82/11/16 TUCKER, H B Duke Power Co 6pp 16323 351 24X Fiche 50-269, 82/11/16, 8212060310

--B212060313 Notice of granting relief from ASME Code requirements for volumetric exams of piping welds in sections of containment sump & reactor bldg spray sys piping
STOLZ, J F Operating Reactors Branch 4 82/11/16 2pp 16323 337 24X Fiche 50-269, 82/11/16, 8212060310

B208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 107pp 16411 199 24X Fiche 50-000, 82/11/18, 8208190251

B208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411, 065 24X Fiche 50-000, 82/11/26, 8208190256

B208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000, 82/11/30, 8208190257

B208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411, 317, 24X Fiche 50-000, 82/12/03, 8208190259

B208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X Fiche 50-000, 82/12/03, 8208190261

B212270390 Ack receipt of payment of civil penalties in response to notice of violation Addl corrective actions will be examined during future insp
AXELRAD, J A Director's Office, Office of Inspection and Enforcement 82/12/03 TUCKER, H B Duke Power Co 2pp 16366 036 24X Fiche 50-269, 82/12/03, 8212270390

DOCKETED ITEMS

8212150073 Requests clarification of conditional snubber operability as described in certain Tech Specs Request due to discussion in IE Insp Repts 50-269/82-37, 50-270/82-37 & 50-287/82-37
TUCKER, H B Duke Power Co 82/12/08 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 16427 339 24X
Fiche 50-269, 82/12/08, 8212150073

8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16, 8208190267

8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27 " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 273 24X
Fiche 50-000, 82/12/20, 8208190268

R Periodic operating reports & related correspondence

8212210421 Forwards monthly operating repts for Nov 1982
TUCKER, H B Duke Power Co 82/12/15 Director's Office, Office of Inspection and Enforcement 1p 16493 058 24X
Fiche 50-269, 82/12/15, 8212210421

--8212210428 Monthly operating repts for Nov 1982
REAVIS, J A Duke Power Co 82/12/15 16pp 16493 059, 24X
Fiche 50-269, 82/12/15, 8212210428

DOCKET 50-270 OCONEE NUCLEAR STATION, UNIT 2

F Security, medical, emergency & fire protection plans

8212130067 Forwards info on emergency offsite facilities (EOF), per R Birkel 821203 request & Generic Ltr 81-10 Const of permanent primary & backup EOF completed
TUCKER, H B Duke Power Co 82/12/03 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 2pp 16390 186 24X Fiche 50-000, 82/12/03, 8212130067

8212090044 Reviews Util 920419 & 0727 ltrs re security personnel requalification requirements Annual supervisor observation considered sufficient requalification test
STOLZ, J F Operating Reactors Branch 4 82/12/07 TUCKER, H B Duke Power Co 2pp 16384 244 24X Fiche 50-000, 82/12/07, 8212090044

8212230093 Releases public version of revision to crisis mgt plan & revisions to crisis mgt plan implementing procedures
FELTON, J M Division of Rules and Records 82/12/15 Document Management Branch 1p 16542 026 24X Fiche 50-000, 82/12/15, 8212230093

--8212230108 Forwards public version of Revision 7 to crisis mgt plan & revisions to crisis mgt plan implementing procedures
TUCKER, H B Duke Power Co 82/12/02 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Operating Reactors Branch 4 2pp 16542 027 24X Fiche 50-000, 82/12/15, 8212230093

--8212230124 Public version of Revision 7 to crisis mgt plan One oversize pamphlet encl Aperture card available in PDR
VAUGHN, R E Duke Power Co 82/11/29 9pp 16542 029 24X
Fiche 50-000, 82/12/15, 8212230093

--8212230134 Public version of revised crisis mgt plan implementing procedures, including Procedures 5.3.2 re crisis news group plan & 5.3.11 re McGuire crisis phone directory
VAUGHN, R E Duke Power Co 82/11/29 280pp 16542 038 24X
Fiche 50-000, 82/12/15, 8212230093

8212280351 Application to amend Licenses DPR-38, DPR-47 & DPR-55, revising App A Tech Specs to change frequency of station security plan & implementing procedure audits from once every 2 yrs to yearly
TUCKER, H B Duke Power Co 82/12/21 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 16560 087 24X
Fiche 50-269, 82/12/21, 8212280351

--8212280367 Proposed Tech Spec revision changing frequency of station security plan & implementing procedure audits from once every 2 yrs to yearly
* Duke Power Co 82/12/21, 1p 16560 089, 24X
Fiche 50-269, 82/12/21, 8212280351

P Operating license stage documents & correspondence

8212010185 Forwards Amends 116, 116 & 113 to Licenses DPR-38, DPR-47 & DPR-55, respectively, safety evaluation & EIA & notice of issuance & availability Amend revises Tech Spec restrictions on burning low level contaminated oil
WAGNER, P C Operating Reactors Branch 4 82/11/15 TUCKER, H B Duke Power Co 3pp 16271 232 24X Fiche 50-269, 82/11/15, 8212010185

--8212010193 Amends 116, 116 & 113 to Licenses DPR-38, DPR-47 & DPR-55, respectively, revising Tech Spec restrictions on burning low level contaminated oil
STOLZ, J F Operating Reactors Branch 4 82/11/15 8pp
16271 235 24X Fiche 50-269, 82/11/15, 8212010185

--8212010205 Safety evaluation & EIA supporting Amends 116, 116 & 113 to Licenses DPR-38, DPR-47 & DPR-55, respectively
* Office of Nuclear Reactor Regulation, Director 82/11/15 6pp
16271 243 24X Fiche 50-269, 82/11/15, 8212010185

--8212010276 Notice of issuance & availability & negative declaration of Amends 116, 116 & 113 to Licenses DPR-38, DPR-47 & DPR-55, respectively
STOLZ, J F Operating Reactors Branch 4 82/11/15 2pp
16271 249 24X Fiche 50-269, 82/11/15, 8212010185

8212010392 Forwards Amends 117, 117 & 114 to Licenses DPR-38, DPR-47 & DPR-55, respectively, safety evaluation & notice of issuance & availability Amends incorporate digital logic channels & emergency power switching logic
WAGNER, P C Operating Reactors Branch 4 82/11/22 TUCKER, H B Duke Power Co 3pp 16271 030 24X Fiche 50-269, 82/11/22, 8212010392

--8212010418 Amends 117, 117 & 114 to Licenses DPR-38, DPR-47 & DPR-55, respectively, incorporating digital logic channels & emergency power switching logic & revising bases to define redundant component testing
STOLZ, J F Operating Reactors Branch 4 82/11/22 28pp
16271, 033 24X Fiche 50-269, 82/11/22, 8212010392

--8212010421 Safety evaluation supporting Amends 117, 117 & 114 to Licenses DPR-38, DPR-47 & DPR-55, respectively
* Office of Nuclear Reactor Regulation, Director 82/11/22 4pp
16271 061 24X Fiche 50-269, 82/11/22, 8212010392

--8212010488 Notice of issuance & availability of Amends 117, 117 & 114 to Licenses DPR-38, DPR-47 & DPR-55, respectively
STOLZ, J F Operating Reactors Branch 4 82/11/22 2pp
16271 065 24X Fiche 50-269, 82/11/22, 8212010392

8212070370 Forwards license amend fee in response to 821108 ltr
TUCKER, H B Duke Power Co 82/11/22 DUGGS, R M License Fee Management Branch 2pp 16336 324 24X Fiche 50-269, 82/11/22, 8212070370

8212070341 Forwards responses to NUREG-0737, Item II B 3, "Post-Accident Sampling Sys W/14 oversize drawings Aperture cards are available in PDR
TUCKER, H B Duke Power Co 82/12/01 DENTON, H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors Branch 4 32pp 16340-252 24X Fiche 50-269, 82/12/01, 8212070341

--8212070348 "Estimate of Failed Fuel Based on I-131 Concentration"
MULL, P, OWEN, T B Duke Power Co 82/08/03 22pp 16340 283
24X Fiche 50-269, 82/12/01, 8212070341

--8212070392 "Post-Accident Containment Air Sampling System " W/twelve oversize drawings Aperture cards are available in PDR
* Duke Power Co 82/01/29 89pp 16340 324 24X
Fiche 50-269, 82/12/01, 8212070341

--8212070395 "Post-Accident Liquid Sampling System " W/nine oversize drawings Aperture cards are available in PDR
* Duke Power Co 82/01/29 376pp 16341 053 24X
Fiche 50-269, 82/12/01, 8212070341

8212100355 Summary of 821130 meeting w/util re use of Mark 8Z Fuel assemblies in future reload cores Viewgraphs encl
WAGNER, P C Operating Reactors Branch 4 82/12/01 Operating Reactors Branch 4 54pp 16399, 041 24X Fiche 50-269, 82/12/01, 8212100355

8212150073 Requests clarification of conditional snubber operability as described in certain Tech Specs Request due to discussion in IE Insp Repts 50-269/82-37, 50-270/82-37 & 50-287/82-37
TUCKER, H B Duke Power Co 82/12/08 DENTON, H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors Branch 4 3pp 16427 339 24X Fiche 50-269, 82/12/08, 8212150073

B208190263 Generic Ltr B2-32 to all PWR licensees re potential steam generator-related generic requirements Forwards Science Applications, Inc draft rept re suby requirements Comments requested within 30 days of ltr Svc list encl
EISENHUT, D G Division of Licensing B2/12/09 Consolidated Edison Co of New York, Inc 29pp 16629 247 24X
Fiche 50-000, B2/12/09, B208190263

B21230190 Comments on status of Unresolved Safety Issue A-49 re pressurized thermal shock for Facilities Recent calculations confirming that no near-term safety concern exists should be reflected in NRC rept
TUCKER, H B Duke Power Co B2/12/09 DENTON, H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors Branch 4 2pp 16396 129 24X Fiche 50-269, B2/12/09, B21230190

B212270335 Forwards order for license mod re installation of inadequate core cooling instrumentation sys as specified in NUREG-0737, Item 11 F 2, "Inadequate Core Cooling"
EISENHUT, D G Division of Licensing B2/12/10 TUCKER, H B Duke Power Co 2pp 16555 338 24X Fiche 50-269, B2/12/10, B212270335

--B212270338 Order for license mod to conform w/specs of NUREG-0737, Item 11 F 2 Checklist for specific review encl
EISENHUT, D G Division of Licensing B2/12/10 Duke Power Co 11pp 16555 339 24X Fiche 50-269, B2/12/10, B212270338

B212210079 Advises that submittal of revised radiological effluent Tech Specs incorporating agreements reached during B20818-19 meetings delayed until B20131, per util B21110 commitment
TUCKER, H B Duke Power Co B2/12/15 DENTON, H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors Branch 4 1p 16485 247 24X Fiche 50-269, B2/12/15, B212210079

B212280351 Application to amend Licenses DPR-3B, DPR-47 & DPR-55, revising App A Tech Specs to change frequency of station security plan & implementing procedure audits from once every 2 yrs to yearly
TUCKER, H B Duke Power Co B2/12/21 DENTON, H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors Branch 4 2pp 16560 087 24X Fiche 50-269, B2/12/21, B212280351

--B212280367 Proposed Tech Spec revision changing frequency of station security plan & implementing procedure audits from once every 2 yrs to yearly
* Duke Power Co B2/12/21 1p 16560 087 24X
Fiche 50-269, B2/12/21, B212280367

G Inspection reports, IE Bulletins & correspondence

B208190240 IE Bulletin B2-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement B2/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, B2/10/28, B208190240

B212090181 Forwards IE Insp Repts 50-269/B2-39, 50-270/B2-39 & 50-287/B2-39 on B20915-1010 No noncompliance noted
DANCE, H C Division of Project & Resident Programs B2/10/29 TUCKER, H B Duke Power Co 2pp 16359 197 24X
Fiche 50-269, B2/10/29, B212090181

--B212090189 IE Insp Repts 50-269/B2-39, 50-270/B2-39 & 50-287/B2-39 on B20915-1010 No noncompliance noted Major areas inspected operation safety verification maint activities, surveillance testing, startup testing & TMI action item implementation
ORDERS, W, FALCONER, D, BRYANT, J C Division of Project & Resident Programs B2/10/28 7pp 16359 199 24X Fiche 50-269, B2/10/29, B212090189

B208190245 IE Info Notice B2-42, "Defects Observed in Panasonic Model B01 & Model B02 Thermoluminescent Dosimeters " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards B2/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000, B2/11/05, B208190245

B212090420 Forwards response to IE Bulletin B2-02, "Degradation of Threaded Fasteners in RCPB of PWR Plants," Item 1 for Unit 1 & Items 2 & 4 for Unit 3 Response to Items 2 & 4 for Units 1 & 2 will be provided following next refueling outage
TUCKER, H B Duke Power Co B2/11/15 O'REILLY, J P Region 2, Office of Director 4pp 16365 033 24X Fiche 50-269, B2/11/15, B212090420

B212060310 Grants B20830 request for relief from volumetric exams of piping welds in sections of containment sump & reactor bldg spray sys piping Safety evaluation encl
STOLZ, J F Operating Reactors Branch 4 B2/11/16 TUCKER, H B, Duke Power Co 6pp 16323, 331 24X Fiche 50-269, B2/11/16, B212060310

--B212060313 Notice of granting relief from ASME Code requirements for volumetric exams of piping welds in sections of containment sump & reactor bldg spray sys piping
STOLZ, J F Operating Reactors Branch 4 B2/11/16 2pp 16323 337 24X Fiche 50-269, B2/11/16, B212060310

B208190251 IE Info Notice B2-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance B2/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X
Fiche 50-000, B2/11/18, B208190251

B208190256 IE Info Notice B2-46, "Defective & Obsolete Combination Padlocks " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement B2/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000, B2/11/26, B208190256

B208190257 IE Info Notice B2-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards B2/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000, B2/11/30, B208190257

B208190259 IE Bulletin B2-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement B2/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, B2/12/03, B208190259

B208190261 IE Info Notice B2-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance B2/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X
Fiche 50-000, B2/12/03, B208190261

B212150073 Requests clarification of conditional snubber operability as described in certain Tech Specs Request due to discussion in IE Insp Repts 50-269/B2-37, 50-270/B2-37 & 50-287/B2-37
TUCKER, H B Duke Power Co B2/12/08 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 16427 339 24X
Fiche 50-269, B2/12/08, B212150073

B208190267 IE Info Notice B2-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement B2/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, B2/12/16, B208190267

B208190268 IE Info Notice B2-50, "Mod of Solid State AC Undervoltage Relays Type IIE-27 " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance B2/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X
Fiche 50-000, B2/12/20, B208190268

R Periodic operating reports & related correspondence

B212210421 Forwards monthly operating repts for Nov 1982
TUCKER, H B Duke Power Co B2/12/15 Director's Office, Office of Inspection and Enforcement 1p 16493 058 24X
Fiche 50-269, B2/12/15, B212210421

--B212210428 Monthly operating repts for Nov 1982
REAVIS, J A Duke Power Co B2/12/15 16pp 16493 059 24X
Fiche 50-269, B2/12/15, B212210428

DOCKET 50-271 VERMONT YANKEE NUCLEAR POWER STATION

F Security, medical, emergency & fire protection plans

B212140098 Forwards IE Insp Rept 50-271/B2-19 on B21005-1101 & notice of violation
STAROSTECKI, R Division of Project & Resident Programs B2/11/30 MURPHY, W P Vermont Yankee Nuclear Power Corp 2pp 16409 268 24X Fiche 50-271, B2/11/30, B212140098

--B212140105 Notice of violation from insp on B21005-1101.
* Division of Project & Resident Programs, B2/11/30 1p 16409 270 24X Fiche 50-271, B2/11/30, B212140098

- B212140113 IE Insp Rept 50-271/B2-19 on B21005-1101 Noncompliance noted failure to maintain fire control area free of combustible matls as required by Administrative Procedure AP 0042 & Tech Spec 6 5 A
RAYMOND, W J, GALLO, R M Division of Project & Resident Programs B2/11/16 15pp 16409 271 24X Fiche 50-271, B2/11/30, B212140098

DOCKETED ITEMS

B212210295 Provides addl info re types of questions NRC duty officer may ask in telephone repts made via NRC emergency notification sys Event notification form encl
STAROSTECKI, R Division of Project & Resident Programs 82/12/16
MURPHY, W P Vermont Yankee Nuclear Power Corp 4pp 16497 004
24X Fiche 50-271, 82/12/16, 8212210295

P Operating license stage documents & correspondence

B21230066 Generic Ltr 82-27 to all BWR licensees of operating reactors except LACBWR, Big Rock Point, Dresden 1, Humboldt Bay, applicants for OL & holders of CP re transmittal of NUREG-0763 & NUREG-0783 Svc list encl W/o stated encl
EISENHUT, D G Division of Licensing 82/11/15 General Public
Utilities - CPU Service Corp 22pp 16387 004 24X
Fiche 50-000, 82/11/15, 821230066

B212280005 Forwards Amend 73 to License DPR-28, safety evaluation, notice of issuance & availability & technical evaluation re: Amend changes Tech Specs re scram discharge vol vent & drain valve surveillance
HODNEY, V L Operating Reactors Branch 2 82/11/29 SINCLAIR, J B
Vermont Yankee Nuclear Power Corp 2pp 16592 186 24X
Fiche 50-271, 82/11/29, 8212280005

--B212280007 Amend 73 to License DPR-28, changing Tech Specs re scram discharge vol vent & drain valve surveillance
VASSALLO, D B Operating Reactors Branch 2 82/11/29 7pp
16592 188 24X Fiche 50-271, 82/11/29, 8212280005

--B206160113 "BWR Scram Discharge Vol Long-Term Mods," technical evaluation re:pt
MUCHA, E Franklin Institute/Franklin Research Center
NRC-03-81-130 YER-C5506-64 82/06/11 ECCLESTON, K NRC - No
Detailed Affiliation Given 49pp 16592 195 24X
Fiche 50-271, 82/11/29, 8212280005

--B212280015 Safety evaluation supporting Amend 73 to License DPR-28
* Office of Nuclear Reactor Regulation, Director 82/11/29 2pp
16592 243 24X Fiche 50-271, 82/11/29, 8212280005

--B212280027 Notice of issuance & availability of Amend 73 to License DPR-28
VASSALLO, D B Operating Reactors Branch 2 82/11/29 2pp
16592 245 24X Fiche 50-271, 82/11/29, 8212280005

B212270212 Forwards final "Mark I Containment Program Plant Unique Analysis Rept of Torus Suppression Chamber"
SINCLAIR, J B Vermont Yankee Nuclear Power Corp 82/11/30
VASSALLO, D B Licensing Branch 2 1p 16538 197 24X
Fiche 50-271, 82/11/30, 8212270212

--B212270216 Final "Mark I Containment Program Plant Unique Analysis Rept of Torus Suppression Chamber"
* Teledyne Engineering Services YR-5319-J 82/11/30 140pp
16538 198 24X Fiche 50-271, 82/11/30, 8212270212

B212130158 Forwards safety evaluation of BWR owners group B10822, 09, 1 & B20902 responses to NUREG-0737, Item II K 3 25, "Effect of Loss of AC Power on Pump Seals" Response acceptable
VASSALLO, D B Operating Reactors Branch 2 82/12/01 SINCLAIR, J D
Vermont Yankee Nuclear Power Corp 7pp 16410 288 24X
Fiche 50-271, 82/12/01, 8212130158

B212090374 Advises that util requires addl time before submitting final draft of radiological ETS & offsite dose calculation manual Draft radiological ETS will be submitted by 830117 & offsite dose calculation manual by 830201
SINCLAIR, J B Vermont Yankee Nuclear Power Corp 82/12/06
VASSALLO, D B Operating Reactors Branch 2 1p 16365 055 24X
Fiche 50-271, 82/12/06, 8212090374

B212140379 Application to amend License DPR-28, revising App A Tech Specs to reflect administrative changes Class II fee encl
HEIDER, L H Vermont Yankee Nuclear Power Corp 82/12/07 Office
of Nuclear Reactor Regulation, Director 2pp 16404 190 24X
Fiche 50-271, 82/12/07, 8212140379

--B212140448 Proposed Tech Specs changing title of assistant plant manager to maint superintendent
* Vermont Yankee Nuclear Power Corp 82/12/07 3pp 16404 192
24X Fiche 50-271, 82/12/07, 8212140379

B212280492 Comments on review of NUREG-0737, Action Item II E 4 2, "Containment Isolation Dependability," Positions 6 & 7 Item considered closed
VASSALLO, D B Operating Reactors Branch 2 82/12/09 SINCLAIR, J B
Vermont Yankee Nuclear Power Corp 3pp 16590 352 24X
Fiche 50-271, 82/12/09, 8212280492

B212100310 Responds to NRC B21102 request for addl info re degraded grid voltage protection Info will be submitted 3 months prior to installation of degraded grid voltage mod during 1984 refueling outage
SINCLAIR, J B Vermont Yankee Nuclear Power Corp 82/12/10
VASSALLO, D B Operating Reactors Branch 2 1p 16376 278 24X
Fiche 50-271, 82/12/10, 8212100310

B212210138 Responds to B21104 request for addl info re adequacy of station electrical distribution sys voltages Proposed change to Tech Specs not warranted since transformer operability already covered by existing Tech Specs
SINCLAIR, J B Vermont Yankee Nuclear Power Corp 82/12/16
VASSALLO, D B Operating Reactors Branch 2 2pp 16485 186 24X
Fiche 50-271, 82/12/16, 8212210138

Q Inspection reports, IE Bulletins & correspondence

B208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants" Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc
112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240

B208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model B01 & Model B02 Thermoluminescent Dosimeters" Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp
16372 142 24X Fiche 50-000, 82/11/05, 8208190245

B208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements" Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 107pp 16411 199 24X
Fiche 50-000, 82/11/18, 8208190251

B208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Radiolocks" Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc
127pp 16411 065 24X Fiche 50-000, 82/11/26, 8208190256

B208190257 IE Info Notice 82-47, "Transportation of Type A Quantities or Non-Fissile Radioactive Matl" Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp
16387 028 24X Fiche 50-000, 82/11/30, 8208190257

B212140098 Forwards IE Insp Rept 50-271/82-19 on B21005-1101 & notice of violation
STAROSTECKI, R Division of Project & Resident Programs 82/11/30
MURPHY, W P Vermont Yankee Nuclear Power Corp 2pp 16409 268
24X Fiche 50-271, 82/11/30, 8212140098

--B212140105 Notice of violation from insp on B21005-1101
* Division of Project & Resident Programs 82/11/30 1p
16409 270 24X Fiche 50-271, 82/11/30, 8212140098

--B212140113 IE Insp Rept 50-271/82-19 on B21005-1101 Noncompliance noted failure to maintain fire control area free of combustible matls as required by Administrative Procedure AP 0042 & Tech Spec 6 9 A
RAYMOND, W J, OALLO, R M Division of Project & Resident Programs 82/11/16 15pp 16409 271 24X Fiche 50-271, 82/11/30, 8212140098

B208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies" Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc
113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259

B208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets" Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X
Fiche 50-000, 82/12/03, 8208190261

B212270388 Act receipt of B21112 ltr containing payment of civil penalties in response to B21015 notice of violation
AXELRAD, J A Director's Office, Office of Inspection and Enforcement 82/12/10 CONWAY, W F Vermont Yankee Nuclear Power Corp 2pp 16568 352 24X Fiche 50-271, 82/12/10, 8212270388

B208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring" Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc
127pp 16428 191 24X Fiche 50-000, 82/12/16, 8208190267

8212220423 Forwards list of topic areas for discussion at upcoming Region 1/licenses meeting on drug & alcohol abuse programs, as discussed in IE Info Notice 82-05 & NUREG-0903 Meeting date & time to be arranged
STAROSTECKI, R Division of Project & Resident Programs 82/12/16
MURPHY, W P Vermont Yankee Nuclear Power Corp 4pp 16503 282
24X Fiche 50-271, 82/12/16, 8212220423

8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27 " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20
Consolidated Edison Co of New York, Inc 108pp 16628 293 24X
Fiche 50-000, 82/12/20, 8208190268

H Periodic operating reports & related correspondence

8212150174 Forwards monthly operating rept for Nov 1982
MURPHY, W P Vermont Yankee Nuclear Power Corp 82/12/09 Office
of Resource Management, Director 2pp 16430 150 24X
Fiche 50-271, 82/12/09, 8212150174

--8212150176 Monthly operating rept for Nov 1982
BURGER, F J Vermont Yankee Nuclear Power Corp 82/12/09 6pp
16430 152 24X Fiche 50-271, 82/12/09, 8212150174

S Reportable occurrences, LERs & related correspondence

8212030117 LER 82-091/01P on 82112B, during investigation of leak in svc water piping to component cooling HX 12, radiography of vendor weld joint showed pocket in weld Investigation to determine cause underway
MIDURA, H J Public Service Electric & Gas Co of New Jersey
82/11/30 HAYNES, R C Region 1, Office of Director 1p
16306 030 24X Fiche 50-271, 82/11/30, 8212030117

8212290378 Forwards LER 82-024/03L-0
PELLETIER, J P Vermont Yankee Nuclear Power Corp 82/12/13
Region 1, Office of Director 1p 16586 304 24X
Fiche 50-271, 82/12/13, 8212290378

--8212290384 LER 82-024/03L-0 on 821115, interval for weekly control rod exercise exceeded by 5 & h Caused by personnel error
Applicable personnel restructured in requirements of surveillance testing program
PELLETIER, J P Vermont Yankee Nuclear Power Corp 82/12/13
Region 1, Office of Director 2pp 16586 305 24X
Fiche 50-271, 82/12/13, 8212290378

DOCKET 50-272 SALEM NUCLEAR GENERATING STATION, UNIT 1

1 Security, medical, emergency & fire protection plans

8212010462 Confirms that Div of Safeguards regulatory effectiveness review scheduled for 821203 & 04-10 Info re review encl
Review will evaluate security program & safeguards regulations
VARGA, S A Operating Reactors Branch 1 82/11/23 UDERITZ, R A
Public Service Electric & Gas Co of New Jersey 6pp 16501 327
24X Fiche 50-272, 82/11/23, 8212010462

8212130212 Responds to 821202 telcon re emergency operations facility survey Facility 7.5 miles from generating station & consists of concrete block facility within concrete block bldg
Protection factor is 13 Ventilation sys isolable
LIDEN, E A Public Service Electric & Gas Co of New Jersey
82/12/06 VARGA, S A Operating Reactors Branch 1 2pp 16390 110
24X Fiche 50-272, 82/12/06, 8212130212

8212290435 Forwards IE Enforcement Conference Repts 50-272/82-31 & 50-311/82-28 on 820812 No reply required
HARTMAN, T Division of Engineering & Technical Programs 82/12/14
UDERITZ, R A Public Service Electric & Gas Co of New Jersey 2pp
16585 222 24X Fiche 50-272, 82/12/14, 8212290435

--8212290443 IE Enforcement Conference Repts 50-272/82-31 & 50-311/82-28 on 820812 Areas discussed implementation & mgt of physical security program
SMITH, O C MCKEDOWN, L M, OODY, A T Division of Engineering & Technical Programs 82/12/07 4pp 16585 224 24X
Fiche 50-272, 82/12/14, 8212290435

8212210038 Offers addl info to prepare operating shift crews to respond to types of questions NRC duty officer may ask re telephone repts made via NRC emergency notification sys
STAROSTECKI, R Division of Project & Resident Programs 82/12/16
UDERITZ, R A Public Service Electric & Gas Co of New Jersey 6pp
16490 214 24X Fiche 50-272, 82/12/16, 8212210038

8212300306 Confirms 821220 telcon re fire protection program review Smoke detectors & nonsafety-grade source range neutron flux monitors will be installed & 1 h fire barrier matl will be wrapped on D diesel control cable trays
LIDEN, E A Public Service Electric & Gas Co of New Jersey
82/12/22 VARGA, S A Operating Reactors Branch 1 1p 16594 209
24X Fiche 50-272, 82/12/22, 8212300306

P Operating license stage documents & correspondence

821230066 Generic Ltr 82-27 to all BWR licensees of operating reactors except LACBWR, Big Rock Point, Dresden 1, Humboldt Bay, applicants for DL & holders of CP re transmittal of NUREG-0763 & NUREG-0783 Svc list encl H/o stated encl
EISENHUT, D O Division of Licensing 82/11/15 General Public
Utilities - GPU Service Corp 22pp 16387 004 24X
Fiche 50-000, 82/11/15, 821230066

8212010155 Submits addl info to support 821005 request for amend to Licenses DPR-70 & DPR-75 Info includes analysis results demonstrating motivation for Tech Spec change & effects on core limits & axial offset DNB limits
LIDEN, E A Public Service Electric & Gas Co of New Jersey
82/11/18 VARGA, S A Operating Reactors Branch 1 8pp 16258 094
24X Fiche 50-272, 82/11/18, 8212010155

8212010148 Forwards Revision 1 to "Safety Evaluation of PSEG Rod Exchange Methodology," for info
LIDEN, E A Public Service Electric & Gas Co of New Jersey
82/11/24 VARGA, S A Operating Reactors Branch 1 3pp 16258 111
24X Fiche 50-272, 82/11/24, 8212010148

--8212010150 "Safety Evaluation of PSEG Rod Exchange Methodology,"
Revision 1
BLAKE, R A, BROWN, R T, ROSENFELD, E S Public Service Electric & Gas Co of New Jersey NFO 004 R01 82/11/16 34pp 16258 114
24X Fiche 50-272, 82/11/24, 8212010148

8208190263 Generic Ltr 82-32 to all PWR licensees re potential steam generator-related generic requirements Forwards Science Applications, Inc draft rept re subj requirements Comments requested within 30 days of ltr Svc list encl
EISENHUT, D O Division of Licensing 82/12/09 Consolidated
Edison Co of New York, Inc 29pp 16629 247 24X
Fiche 50-000, 82/12/09, 8208190263

8212140103 Generic Ltr 82-28 to all licensees of operating Westinghouse & C-E PWRs (except Arkansas Nuclear One, Unit 2 & San Onofre 2 & 3) re inadequate core cooling instrumentation sys Svc list encl
EISENHUT, D O Division of Licensing 82/12/10 Yankee Atomic
Electric Co 27pp 16690 035 24X Fiche 50-000, 82/12/10, 8212140103

8212160623 Notification of 821214 meeting w/util in Bethesda, MD to discuss util proposal for restructuring safety review Functions
ROSB, W J Operating Reactors Branch 1 82/12/14 VARGA, S A
Operating Reactors Branch 1 2pp 16466 035 24X
Fiche 50-272, 82/12/14, 8212160623

8212300072 Notification of 830104 significant licensee meeting w/util for presentation of QA organizational & functional changes
TRIPP, L E Division of Project & Resident Programs 82/12/21
Division of Project & Resident Programs 2pp 16624 280 24X
Fiche 50-000, 82/12/21, 8212300072

Q Inspection reports, IE Bulletins & correspondence

8208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Svc list encl
DEVOUNO, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc
112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240

8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model B01 & Model B02 Thermoluminescent Dosimeters " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards
82/11/05 Consolidated Edison Co of New York, Inc 110pp
16372 142 24X Fiche 50-000, 82/11/05, 8208190245

8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18
Consolidated Edison Co of New York, Inc 109pp 16411 199 24X
Fiche 50-000, 82/11/18, 8208190251

DOCKETED ITEMS

B212060278 Forwards IE Insp Repts 50-272/82-27 & 50-311/82-26 on 820928-1108 & notice of violation
STAROSTECKI, R Division of Project & Resident Programs 82/11/22
UDERITZ, R A Public Service Electric & Gas Co of New Jersey 2pp
16312 036 24X Fiche 50-272, 82/11/22, 8212060278

--8212060281 Notice of violation from Insp on 820928-1108
* Division of Project & Resident Programs 82/11/22 2pp
16312 038 24X Fiche 50-272, 82/11/22, 8212060278

--8212060287 IE Insp Repts 50-272/82-27 & 50-311/82-26 on 820928-1108
Noncompliance noted failure to perform surveillance in time specified & failure to observe limiting condition of operation on fire protection instrumentation
NORRHOLM, N J, SUMMERS, R, TRIPP, L E Division of Project & Resident Programs 82/11/09 18pp 16312 040 24X
Fiche 50-272, 82/11/22, 8212060278

B'08190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000, 82/11/26, 8208190256

B'12030144 Ack receipt of 821119 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-272/82-22 & 50-311/82-21
MARTIN, T T Division of Engineering & Technical Programs 82/11/29
UDERITZ, R A Public Service Electric & Gas Co of New Jersey 1p 16306 112 24X Fiche 50-272, 82/11/29, 8212030144

--8212030153 Responds to NRC 821019 ltr re violations noted in IE Insp Repts 50-272/82-22 & 50-311/82-21 Corrective actions
Meter M-137 properly recalibrated, Meters M-76 & M-184 accounted for & inadequate housekeeping conditions corrected
UDERITZ, R A Public Service Electric & Gas Co of New Jersey 82/11/19 HAYNES, R C Region 1, Office of Director 5pp 16306 113 24X Fiche 50-272, 82/11/29, 8212030144

B'08190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl
COBB, L J Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16397 028 24X Fiche 50-000, 82/11/30, 8208190257

B'08190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259

B'08190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Cockets " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X Fiche 50-000, 82/12/03, 8208190261

B212140124 Ack receipt of 821105 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-272/82-25 & 50-311/82-24
STAROSTECKI, R Division of Project & Resident Programs 82/12/06
UDERITZ, R A Public Service Electric & Gas Co of New Jersey 1p 16408 240 24X Fiche 50-272, 82/12/06, 8212140124

--8212140133 Responds to NRC 821006 ltr re violations noted in IE Insp Repts 50-272/82-25 & 50-311/82-24 Corrective actions Tech Spec 3 Q 4 will be discussed w/personnel Tech Spec 3 Q 3 5 limiting condition for operation not violated
UDERITZ, R A Public Service Electric & Gas Co of New Jersey 82/11/05 HAYNES, R C Region 1, Office of Director 4pp 16408 241 24X Fiche 50-272, 82/12/06, 8212140124

B212200020 Submits addl info per IE Bulletin 80-11, "Masonry Wall Design," in response to NRC request One oversize drawing oncl Aperture card is available in PDR
LIDEN, E A Public Service Electric & Gas Co of New Jersey 82/12/08 VARGAS, A Operating Reactors Branch 1 3pp 16470 186 24X Fiche 50-272, 82/12/08, 8212200020

B212290435 Forwards IE Enforcement Conference Repts 50-272/82-31 & 50-311/82-28 on 820812 No reply required
MARTIN, T T Division of Engineering & Technical Programs 82/12/14
UDERITZ, R A Public Service Electric & Gas Co of New Jersey 2pp 16585 222 24X Fiche 50-272, 82/12/14, 8212290435

--8212290443 IE Enforcement Conference Repts 50-272/82-31 & 50-311/82-28 on 820812 Areas discussed: Implementation & mgt of physical security program
SMITH, G C, MCKEOWN, L M, GONY, A T. Division of Engineering & Technical Programs 82/12/07 4pp 16585 224 24X
Fiche 50-272, 82/12/14, 8212290435

B'08190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16, 8208190267

B'12220444 Forwards listing of topic areas for discussion at Region 1/ licensee meeting on drug & alcohol abuse programs per IE Info Notice 82-05 & NUREG-0903 N/o NUREG
STAROSTECKI, R Division of Project & Resident Programs 82/12/16
UDERITZ, R A Public Service Electric & Gas Co of New Jersey 5pp 16503 322 24X Fiche 50-272, 82/12/16, 8212220444

B'08190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27 " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X
Fiche 50-000, 82/12/20, 8208190268

N Periodic operating reports & related correspondence

G'12230268 Forwards monthly operating rept for Nov 1982
MIDURA, H J Public Service Electric & Gas Co of New Jersey 82/12/10 Director's Office, Office of Inspection and Enforcement 1p 16508 251 24X Fiche 50-272, 82/12/10, 8212230268

--8212230271 Monthly operating rept for Nov 1982
MILLER, L K Public Service Electric & Gas Co of New Jersey 82/12/10 13pp 16508 252 24X Fiche 50-272, 82/12/10, 8212230268

B'12280066 Forwards NPDES discharge monitoring rept for Nov 1982
MILLER, L K Public Service Electric & Gas Co of New Jersey 82/12/15 BAKER, R A, LUNDIN, C Environmental Protection Agency 1p 16564 256 24X Fiche 50-272, 82/12/15, 8212280066

--8212280068 NPDES discharge monitoring rept for Nov 1982
MILLER, L K Public Service Electric & Gas Co of New Jersey 82/12/14 19pp 16564 257 24X Fiche 50-272, 82/12/15, 8212280066

S Reportable occurrences, LERs & related correspondence

B'12060291 Forwards LER 82-083/03L-0 Detailed event analysis encl
MIDURA, H J Public Service Electric & Gas Co of New Jersey 82/11/17 HAYNES, R C Region 1, Office of Director 3pp 16312 070 24X Fiche 50-272, 82/11/17, 8212060291

--8212060298 LER 82-083/03L-0 on 821102, during routine shutdown operation, temp recorder for air temp-delta T channels was not printing. Caused by failure of pinion gear on chart drive motor. Motor replaced
FRAHM, R Public Service Electric & Gas Co of New Jersey 82/11/17 Region 1, Office of Director 1p 16312 073 24X
Fiche 50-272, 82/11/17, 8212060291

B212060302 Forwards LER 82-085/01T-0 Detailed event analysis encl
MIDURA, H J Public Service Electric & Gas Co of New Jersey 82/11/17 HAYNES, R C Region 1, Office of Director 3pp 16312 107 24X Fiche 50-272, 82/11/17, 8212060302

--8212060308 LER 82-085/01T-0 on 821113, due to resulting loss of 1 & 2 group buses, automatic starting feature of 1 & 2 diesel fire pumps disabled. Caused by planned maint on station power transformer 12 Maint completed & power restored
FRAHM, R Public Service Electric & Gas Co of New Jersey 82/11/17 Region 1, Office of Director 1p 16312 110 24X
Fiche 50-272, 82/11/17, 8212060302

B'12060309 Forwards LER 82-086/03L-0 Detailed event analysis encl
MIDURA, H J Public Service Electric & Gas Co of New Jersey 82/11/24 HAYNES, R C Region 1, Office of Director 3pp 16312 086 24X Fiche 50-272, 82/11/24, 8212060309

--8212060316 LER 82-086/03L-0 on 821027, five fire barrier penetrations found non-functional during routine surveillance. Caused by inadequate sealing. Original surveillance procedure failed to specifically identify penetrations. Procedure revised
FRAHM, R Public Service Electric & Gas Co of New Jersey 82/11/29 Region 1, Office of Director 1p 16312 089 24X
Fiche 50-272, 82/11/24, 8212060309

B212080356 Forwards LER 82-090/01T-0 Detailed event analysis encl
MIDURA, H J Public Service Electric & Gas Co of New Jersey 82/11/24 HAYNES, R C Region 1, Office of Director 3pp 16393 321 24X Fiche 50-272, 82/11/24, 8212080356

--B212080364 LER 82-090/01T-O on B21121, video insp of removed fuel assemblies revealed cladding ruptures on element in fuel assembly D-20 Cause unknown Vendor to conduct more detailed investigation
 FRAHM, R Public Service Electric & Gas Co of New Jersey
 B2/11/24 Region 1, Office of Director 1p 16353 324 24X
 Fiche 50-272, B2/11/24, B212080364

B212140053 Forwards LER 82-088/03L-O Detailed event analysis encl
 MIDURA, H J Public Service Electric & Gas Co of New Jersey
 B2/11/24 HAYNES, R C Region 1, Office of Director 3pp
 16408 286 24X Fiche 50-272, B2/11/24, B212140053

--B212140060 LER 82-088/03L-O on B21109, fire observed in fire detection instrumentation panel 1FP3 Panel de-energized & several fire detectors rendered inoperable Caused by failure of panel alarm buzzer relay Relay replaced
 FRAHM, R Public Service Electric & Gas Co of New Jersey
 B2/11/24 Region 1, Office of Director 1p 16408 289 24X
 Fiche 50-272, B2/11/24, B212140053

B212140076 Forwards LER 82-087/03L-O Detailed event analysis encl
 MIDURA, H J Public Service Electric & Gas Co of New Jersey
 B2/11/24 HAYNES, R C Region 1, Office of Director 3pp
 16408 247 24X Fiche 50-272, B2/11/24, B212140076

--B212140082 LER 82-087/03L-O on B21109, during refueling operations, alarms indicated fire protection deluge sys had been actuated No apparent cause determined Charcoal filters involved replaced
 FRAHM, R Public Service Electric & Gas Co of New Jersey
 B2/11/24 Region 1, Office of Director 1p 16408 250 24X
 Fiche 50-272, B2/11/24, B212140076

B212060195 PNO-I-82-076 on B21122, through-wall leak discovered in svc water piping associated w/component cooling water HX Caused by corrosion Corrective actions still under development
 TRIPP, L E, KEIMIG, R Region 1, Office of Director B2/12/01 1p
 16313 054 24X Fiche 50-272, B2/12/01, B212060195

B212220330 Forwards LER 82-091/01T-O Detailed event analysis encl
 MIDURA, H J Public Service Electric & Gas Co of New Jersey
 B2/12/08 HAYNES, R C Region 1, Office of Director 3pp
 16517 184 24X Fiche 50-272, B2/12/08, B21220330

--B212220310 LER 82-091/01T-O on B21130, leakage discovered from weld on svc water piping to component cooling HX 12 Caused by degradation of weld & similar joints due to type of filler metal used & corrosive environ of svc water sys
 FRAHM, R Public Service Electric & Gas Co of New Jersey
 B2/12/08 Region 1, Office of Director 1p 16517 187 24X
 Fiche 50-272, B2/12/08, B212220330

DOCKET 50-275 DIABLO CANYON NUCLEAR POWER PLANT, UNIT 1

I Security, medical, emergency & fire protection plans

B212060251 Forwards IE Insp Rept 50-275/B2-36 on B21003-30 No noncompliance noted
 BISHOP, W Division of Resident, Reactor Project & Engineering Programs B2/11/22 CRANE, P A Pacific Gas & Electric Co 2pp
 16312 279 24X Fiche 50-275, B2/11/22, B212060251

--B212060261 IE Insp Rept 50-275/B2-36 on B21003-30 No noncompliance noted Major areas inspected surveillance testing, physical security, maint, TMI task action plan items, emergency drill & design changes & mod
 CARLSON, J D, MENDONCA, M M, KIRSCH, D F Division of Resident, Reactor Project & Engineering Programs B2/11/19 5pp
 16312 283 24X Fiche 50-275, B2/11/22, B212060251

B212080057 Releases public version of revised emergency plan implementing procedures
 FELTON, J H Division of Rules and Records B2/12/02 Document Management Branch 1p 16367 214 24X Fiche 50-275, B2/12/02, B212080057

--B212080063 Forwards public version of revised emergency plan implementing procedures, including Procedures EP OP-18A re loss of charging & EP OP-18B re loss of normal shutdown
 CRANE, P A Pacific Gas & Electric Co B2/11/24 ENGELKEN, R H Region 5, Office of Director 2pp 16367 215 24X
 Fiche 50-275, B2/12/02, B212080057

--B212080071 Public version of revised emergency plan implementing procedures, including Procedures EP OP-18A re loss of charging, EP OP-18B re loss of normal shutdown & EP R-1 re personnel injury or illness (radiologically-related)
 THORNBERRY, R C Pacific Gas & Electric Co B2/11/03 55pp
 16367 217 24X Fiche 50-275, B2/12/02, B212080057

B212130070 Confirms permanent & interim emergency operations facilities info per B21202 verbal request Permanent & interim sites located 11.7 miles from facilities Interim structure complete & successfully tested
 CRANE, P A Pacific Gas & Electric Co B2/12/07 KNIGHTON, G W Licensing Branch 3 1p 16391 164 24X Fiche 50-275, B2/12/07, B212130070

B212280160 Forwards "Verification of Fire Protection Provided for Auxiliary Feedwater Sys, Control Room Ventilation & Pressurization Sys, Safety-Related Portion of 4160-Volt Electrical Sys," Number 18, Revision 0
 KRECHTING, J E Stone & Webster Engineering Corp B2/12/15 DENTON, H R Office of Nuclear Reactor Regulation, Director ENGELKEN, R H Region 5, Office of Director MANEATIS, G A Pacific Gas & Electric Co 1p 16563 124 24X Fiche 50-275, B2/12/15, B212280160

--B212280163 "Verification of Fire Protection Provided for Auxiliary Feedwater Sys, Control Room Ventilation & Pressurization Sys, Safety-Related Portion of 4160-Volt Electrical Sys"
 SESTAK, F Stone & Webster Engineering Corp B2/12/15 16pp
 16563 125 24X Fiche 50-275, B2/12/15, B212280160

B212220217 Forwards application to amend License DPR-76, changing tech Specs to modify audit frequency from 24 to 12 months for emergency & security plans & implementing procedures per Generic Ltrs B2-17 & B2-23
 CRANE, P A Pacific Gas & Electric Co B2/12/17 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 16503 011 24X
 Fiche 50-275, B2/12/17, B212220217

--B212220225 Application to amend License DPR-76, changing Tech Specs to modify audit frequency from 24 to 12 months for emergency & security plans & implementing procedures
 MANEATIS, G A Pacific Gas & Electric Co B2/12/17 2pp
 16503 012 24X Fiche 50-275, B2/12/17, B212220217

--B212220229 Proposed Tech Spec changes modifying audit frequency from 24 to 12 months for emergency & security plans & implementing procedures per Generic Ltrs B2-17 & B2-23
 Pacific Gas & Electric Co B2/12/17 1p 16503 014 24X
 Fiche 50-275, B2/12/17, B212220217

0 Adjudicatory correspondence

B212060104 Order extending time until B21208 for Commission to act to review NRR Director B20922 denial of Joint Intervenor's 10CFR2206 petition
 CHILK, S J Office of the Secretary of the Commission B2/12/01 Commissioners 1p 16314 362 24X Fiche 50-275, B2/12/01, B212060104

B212090084 Motion for extension of time until B21220 to file brief opposing intervenor exceptions to ASLB decision Time extension necessary due to meetings on east coast (Certificate of Svc encl)
 CRANE, P A Pacific Gas & Electric Co B2/12/06 Atomic Safety and Licensing Appeal Panel 4pp 16357 188 24X
 Fiche 50-275, B2/12/06, B212090084

B212090097 Order extending time until B21215 for Commission to act to review NRR Director B20922 denial of Joint Intervenor's 10CFR2206 petition
 CHILK, S J Office of the Secretary of the Commission B2/12/07 Commissioners 1p 16357 283 24X Fiche 50-275, B2/12/07, B212090097

B212150051 Order extending time until B21222 for Commission to act to review NRR Director B20922 denial of Joint Intervenor's 10CFR2206 petition
 CHILK, S J Office of the Secretary of the Commission B2/12/14 Commissioners 1p 16422 323 24X Fiche 50-275, B2/12/14, B212150051

B212150057 Order extending time until B21221 for Commission to respond to ALAB-681
 CHILK, S J Office of the Secretary of the Commission B2/12/14 Commissioners 1p 16431 007 24X Fiche 50-275, B2/12/14, B212150057

B212220374 Brief opposing util & NRC B21108 briefs supporting exceptions to ASLB requirement that NRC receive FEMA finding of adequacy of State of CA radiological emergency response plan before plant can be licensed w/Certificate of Svc
 BROWN, H H California, State of BROWN, H H Kirkpatrick, Lockhart, Hill, Christopher & Phillips B2/12/20 Atomic Safety and Licensing Appeal Panel 9pp 16517 251 24X Fiche 50-275, B2/12/20, B212220374

DOCKETED ITEMS

8212280123 Response in opposition to Joint Intervenor's briefs in support of exceptions to ASLB 820831 order authorizing NRR director to issue full power OL. No new arguments placed before ASLB Certificate of Svc encl
NORTON, B Pacific Gas & Electric Co NORTON, B Norton, Burke, Berry & French 82/12/20 Atomic Safety and Licensing Appeal Panel 40pp 16564 140 24X Fiche 50-275, 82/12/20, 8212280123

8212280288 Brief in opposition to util & NRC briefs in support of exception to 820831 initial decision. Desire for more expeditious licensing is patently inadequate excuse for ignoring regulatory stds Certificate of Svc encl
REYNOLDS, J R Joint Intervenor's- Diablo Canyon REYNOLDS, J R Center for Law in the Public Interest 82/12/20 Atomic Safety and Licensing Appeal Panel 22pp 16961 334 24X Fiche 50-275, 82/12/20, 8212280288

8212230360 Order extending time, until 821229, for Commission to decide whether to review NRR Director 820922 denial of Joint Intervenor's request for action filed under 10CFR2 206
CHILK, S J Office of the Secretary of the Commission 82/12/22 1p 16511 165 24X Fiche 50-275, 82/12/22, 8212230360

8212270217 Memorandum & Order CL1-82-39, ruling on three questions: certified on 820716 Issuance of suspension order & establishment of independent design verification program not intended to deprive adjudicatory boards of jurisdiction
CHILK, S J Office of the Secretary of the Commission 82/12/23 7pp 16536 206 24X Fiche 50-275, 82/12/23, 8212270217

H General correspondence

8212130395 Responds to 821025 request for addl info on design verification program Util corrective action program per SECY 82-414, principal reason for determining that design verification effort goes beyond Commission order
EISENHUT, D O Division of Licensing 82/11/24 SIEGEL, B M Toward Utility Rate Normalization 3pp 16412 085 24X Fiche 50-275, 82/11/24, 8212130395

--8211020166 Requests elaboration on encl newspaper article re mod & investigation program at facility
SIEGEL, B M Affiliation Unknown 82/10/25 DENTON, H NRC - No Detailed Affiliation Given 3pp 16412 088 24X Fiche 50-275, 82/11/24, 8212130395

8212170373 Advises that 821115 ltr to Chairman Palladino re seismic qualification of turbine bldg & recommendation for independent analysis by BNL will be provided to other Commissioners
EISENHUT, D O Division of Licensing 82/12/08 ROESSET, J Roesset, J M 4pp 16478 085 24X Fiche 50-275, 82/12/08, 8212170373

--8212170378 Clarifies 821110 statements re seismic qualification of turbine bldg Recommendation for independent analysis by BNL, justified Transmittal of clarifications to other Commissioners requested
ROESSET, J M Roesset, J M 82/11/15 PALLADINO, N J Commissioners 1p 16478 088 24X Fiche 50-275, 82/12/08, 8212170373

I Operating license stage documents & correspondence

8212030190 Forwards Sections 2.1.5, "Intake Structure," 2.2.2, "Small Bore Piping," 2.2.4, "Small Bore Pipe Supports" & 2.6.3, "Instrumentation Tubing & Tubing Supports," to Phase I final reqt for design verification program
CRANE, P A Pacific Gas & Electric Co 82/11/19 EISENHUT, D O Division of Licensing 127pp 16306 118 24X Fiche 50-275, 82/11/19, 8212030190

8212030253 Board Notification 82-105 forwards RH Vollmer 820930 memo to DO Eisenhut re alleged design deficiency in ASME Code Class 1 piping Effects of local pipe wall stresses due to support loads introduced by pipe clamps not evaluated properly
EISENHUT, D O Division of Licensing 82/11/24 PALLADINO, N J, GILINSKY, V, AHEARNE, J F Commissioners 2pp 16316 240 24X Fiche 50-000, 82/11/24, 8212030253

--8212030265 Discusses alleged design deficiency in ASME Code Class 1 piping Failure to deal w/pipe support-pipe interface design issue would be serious matter if substantiated Ofc of Investigations will assist in evaluation
VOLLMER, R H Division of Engineering 82/09/30 EISENHUT, D O Division of Licensing 5pp 16316, 247 24X Fiche 50-000, 82/11/24, 8212030265

8212060340 Board Notification 82-120 forwards Teledyne Engineering Svc, 821112 rept, RL Cloud Associates 821109 ltr w/open items, S&W 821112 repts & RF Ready, Inc 821112 rept w/open items re design verification program, Phase I
EISENHUT, D O Division of Licensing 82/11/24 PALLADINO, N J, GILINSKY, V, AHEARNE, J F Commissioners 4pp 16323 142 24X Fiche 50-275, 82/11/24, 8212060340

8212270418 Responds to FOIA request for documents re proposed revision &/or update to reactor safety study referred to in NUREG-0784, Chapter 10 as RS 11 & all documents pertaining to reactor cooling methods Forwards documents listed in app
FELTON, J M Division of Rules and Records 82/11/26 SHOLLY, S Union of Concerned Scientists 3pp 16549 233 24X Fiche 50-000, 82/11/26, 8212270418

--8211050027 Forwards summary of semiscale test results & advises that board notification re test results issued w/o encl
NOVAK, T M Assistant Director for Licensing 82/09/24 Division of Licensing 1p 16549 278 24X Fiche 50-000, 82/11/26, 8212270418

8212010190 Submits status update on Wiesel & Seed repts re effects of storm & tsunami waves & seismic events on facility break-water Final repts for ongoing analysis re potential wave forces & request for Tech Spec amend will be sent Dec 1982
CRANE, P A Pacific Gas & Electric Co 82/11/29 KNIGHTON, G W Licensing Branch 3 2pp 16258 085 24X Fiche 50-275, 82/11/29, 8212010190

8212030191 Submits revised schedule for upgrading Class 1E plant vent radioactive gas & particulate monitoring sys, RE-14 A & B & 2B A & B Work will be completed by 830214 contingent on results of qualification test
CRANE, P A Pacific Gas & Electric Co 82/11/29 KNIGHTON, G W Licensing Branch 3 1p 16306 269 24X Fiche 50-275, 82/11/29, 8212030191

8212080697 Forwards list of drawings & data needed for BNL independent analysis, per SECY-82-414 Notification requested if info cannot be provided within 2 wks of receipt of ltr Analysis not substitute for design efforts now underway
EISENHUT, D O Division of Licensing 82/12/01 CRANE, P A Pacific Gas & Electric Co 6pp 16372 346 24X Fiche 50-275, 82/12/01, 8212080697

8212150217 Notification of cancellation of 821209 meeting w/util, Bechtel & contractor in San Francisco, CA to discuss status of design verification program Phases I & II
SCHIERLING, H E Licensing Branch 3 82/12/01 KNIGHTON, G W Licensing Branch 3 4pp 16447 022 24X Fiche 50-275, 82/12/01, 8212150217

8212150223 Notification of 821209 meeting w/util, Bechtel & contractor in San Francisco, CA to discuss status of design verification program Phases I & II
SCHIERLING, H E Licensing Branch 3 82/12/01 KNIGHTON, G W Licensing Branch 3 4pp 16447 018 24X Fiche 50-275, 82/12/01, 8212150223

8212230306 Provides response to 821123 ltr requesting S&W document, change in format of engineering open item file sys & more complete description of 27 files opened to date
JOHNSON, A E Teledyne Engineering Services 82/12/01 HUBBARD, R U MHD Technical Associates 2pp 16507 319 24X Fiche 50-275, 82/12/01, 8212230306

8212070235 Forwards schedule info for 821208 meeting on facility design verification program, per request Info contains estimated schedules for fuel loading, low power testing & full power operation Completion based on three-step licensing approach
CRANE, P A Pacific Gas & Electric Co 82/12/02 EISENHUT, D O Division of Licensing 3pp 16329 317 24X Fiche 50-275, 82/12/02, 8212070235

8212170038 Requests changes to QA program, Revision 1 scope of responsibility Project completion effort responsibility should be clearly defined
EISENHUT, D O Division of Licensing 82/12/02 CRANE, P A Pacific Gas & Electric Co 5pp 16478 008 24X Fiche 50-275, 82/12/02, 8212170038

8212100206 Requests addl info re BNL analysis of containment annulus structure
COOPER, W E, CHIN, S L Teledyne Engineering Services 82/12/03 SCHIERLING, H E Office of Nuclear Reactor Regulation, Director 1p 16377-110 24X Fiche 50-275, 82/12/03, 8212100206

8212100291 Requests info from BNL analysis re containment annulus structure
COOPER, W E, CHIN, S L Teledyne Engineering Services 82/12/03 SCHIERLING, H E Office of Nuclear Reactor Regulation, Director 1p 16376 273 24X Fiche 50-275, 82/12/03, 8212100291

G/12140473 Requests approval of encl three-step licensing proposal for restoration of low power testing authority & issuance of full power license, presented at B21110 meeting w/NRC
CRANE, P A Pacific Gas & Electric Co 82/12/03 EISENHUT, D G
Division of Licensing 19pp 16403 336 24X Fiche 50-275, 82/12/03, 8212140473

G/12080479 Concurs w/licensee B21203 request for restoration of low power license & stepwise licensing schedule to full power
Schedule for proposed 3-step licensing & transmittal forms encl
COOPER, W E Teledyne Engineering Services 82/12/06 EISENHUT, D G
Division of Licensing 3pp 16380 215 24X Fiche 50-275, 82/12/06, 8212080479

G/12130281 Board Notification B2-125 forwards info re recent ACRS evaluation of PWR flow blockage during natural circulation
EISENHUT, D G Division of Licensing 82/12/06 PALLADINO, N J
GILINSKY, V, AHEARNE, J Commissioners 3pp 16418 291 24X
Fiche 50-000, 82/12/06, 8212130281

--H212130289 Requests all PWR licensing & appeal boards be informed of ACRS evaluation of flow blockage during natural circulation
MATTSON, R J Division of Systems Integration (post B11005)
82/12/03 EISENHUT, D Division of Licensing 6pp 16418 254
24X Fiche 50-275, 82/12/06, 8212130281

--G212130293 Advises that encl ACRS B20907 memo is being made publicly available per House Committee on Interior & Insular Affairs request
FRILEY, R F ACRS - Advisory Committee on Reactor Safeguards
82/11/10 DENTON, H R Office of Nuclear Reactor Regulation,
Director 1p 16418 260 24X Fiche 50-275, 82/12/06, 8212130281

--B21230137 Comments on extent of acceptance of proposals re actions & resolution plans for integral sys testing & TMI Action
item II K 3 30 Owners must resolve issues expeditiously to avoid licensing issue delays
DENTON, H R Office of Nuclear Reactor Regulation, Director
82/11/16 PARKER, W D Duke Power Co 5pp 16418 274 24X
Fiche 50-275, 82/12/06, 8212130281

-B212130305 Comments on NRC program to address concerns w/thermal hydraulic behavior of B&W plants during transients & accidents GERDA & SRI-II facilities as now proposed will be inadequate to address NRC concerns
SHEWMON, P ACRS - Advisory Committee on Reactor Safeguards
82/10/13 DIRCKS, W J Office of the Executive Director for Operations 1p 16418 278 24X Fiche 50-275, 82/12/06, 8212130281

G/12230041 Board Notification B2-127 forwards info re status of activities performed under independent design verification program
EISENHUT, D G Division of Licensing 82/12/06 PALLADINO, N J
GILINSKY, V, AHEARNE, J F Commissioners 17pp 16545 001 24X
Fiche 50-275, 82/12/06, 8212230041

G/12140276 Forwards Revision O to "Independent Design Verification Program Boils - Outdoor Water Storage Tanks." Interim Technical Rept 16
DENISON, E Robert L Cloud Associates, Inc 82/12/08 DENTON, H R
Office of Nuclear Reactor Regulation, Director ENGELKEN, R H
Region 5, Office of Director MANEATIS, O A Pacific Gas & Electric Co 1p 16404 272 24X Fiche 50-275, 82/12/08, 8212140276

--G212140277 Revision O to "Independent Design Verification Program Boils - Outdoor Water Storage Tanks." Interim Technical Rept 16
MCNEILL, R DENISON, E Robert L Cloud Associates, Inc 82/12/08
46pp 16404 274 24X Fiche 50-275, 82/12/08, 8212140276

G/12230045 Board Notification B2-128 forwards info re design verification program
EISENHUT, D G Division of Licensing 82/12/08 PALLADINO, N J
GILINSKY, V, AHEARNE, J F Commissioners 4pp 16546 001 24X
Fiche 50-275, 82/12/08, 8212230045

G/12220017 Staff requirements memo re B21209 meeting on Phase II of design verification program per SECY-B2-414 Commission unanimously approved recommendations replacing Figure 3 w/ Figure 1, per until 821203 ltr
CHILK, B J Office of the Secretary of the Commission 82/12/09
DIRCKS, W J Office of the Executive Director for Operations 1p 16529 096 24X Fiche 50-275, 82/12/09, 8212220017

B/12230049 Board Notification B2-125A forwards info re PWR flow blockage info suppl Board Notification B2-125
EISENHUT, D G Division of Licensing 82/12/09 PALLADINO, N J
GILINSKY, V, AHEARNE, J F Commissioners 3pp 16545 338 24X
Fiche 50-000, 82/12/09, 8212230049

--B21230058 Forwards Fraley B21207 memo re flow blockage by steam during natural circulation in PWRs
EISENHUT, D G Division of Licensing 82/12/09 LAINAS, G
Assistant Director for Operating Reactors 1p 16545 341 24X
Fiche 50-000, 82/12/09, 821230049

G/12150195 Forwards Revision O to "Verification of Pressure, Temp, Humidity & Submergency Environ Used for Safety-Related Equipment Spec ." Interim Technical Rept 14 & Open Item Rept Forms 9028 & 9029
SESTAK, F Stone & Webster Engineering Corp 82/12/10 DENTON, H R
Office of Nuclear Reactor Regulation, Director ENGELKEN, R A
Region 5, Office of Director MANEATIS, O A Pacific Gas & Electric Co 3pp 16430 268 24X Fiche 50-275, 82/12/10, 8212150195

--B212150200 Revision O to "Verification of Pressure, Temp, Humidity & Submergency Environ Used for Safety-Related Equipment Spec Outside Containment for Auxiliary Feedwater Sys & Control Room ." Interim Technical Rept 14
SESTAK, F Stone & Webster Engineering Corp 82/12/06 38pp
16430 272 24X Fiche 50-275, 82/12/10, 8212150195

B212210014 Forwards current design details & data in response to NRC B21201 ltr & SECY-B2-414 BNL should elaborate on how info will be used Requests meeting w/NRC & BNL by 821222 to discuss matl
CRANE, P A Pacific Gas & Electric Co 82/12/10 EISENHUT, D G
Division of Licensing 8pp 16490 148 24X Fiche 50-275, 82/12/10, 8212210014

B/12190164 Forwards "Diablo Canyon Unit 1 Independent Design Verification Program HVAC Duct & Supports Interim Technical Rept 15, Revision O " Interim Technical Rept 14 will be issued by S&W
DENISON, E Robert L Cloud Associates, Inc 82/12/13 DENTON, H R
Office of Nuclear Reactor Regulation, Director ENGELKEN, R H
Region 5, Office of Director MANEATIS, O A Pacific Gas & Electric Co 1p 16430 198 24X Fiche 50-275, 82/12/13, 8212150164

--G212150170 "Diablo Canyon Unit 1 Independent Design Verification Program HVAC Duct & Supports Interim Technical Rept 15, Revision O "
HANSON, DENISON, E Robert L Cloud Associates, Inc 82/12/10
52pp 16430 200 24X Fiche 50-275, 82/12/13, 8212150164

G/12210002 Forwards "Pressurizer Safety & Relief Line Evaluation." summary rept
CRANE, P A Pacific Gas & Electric Co 82/12/13 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 16485 276
24X Fiche 50-275, 82/12/13, 8212210002

- B212210005 "Pressurizer Safety & Relief Line Evaluation." summary rept
SMITH, L C, HAZLETT, T L, CHANG, K C Pacific Gas & Electric Co
AM-SSA-2534 82/11/30 71pp 16485 278 24X
Fiche 50-275, 82/12/13, 8212210002

G/12140278 Forwards agenda for B21214-15 meetings in San Francisco, CA for technical discussion of RL Cloud & Associates requests for info
COOPER, W E Teledyne Engineering Services 82/12/14 NRC - No
Detailed Affiliation Given 3pp 16402 107 24X
Fiche 50-275, 82/12/14, 8212140278

G212210037 Provides Natl Register of Historic Places eligibility notification of plant Archeological Site SLO-2
* Interior, Dept of, National Park Service 82/12/14 KERRIGAN, J D
NRC - No Detailed Affiliation Given 2pp 16490 212 24X
Fiche 50-275, 82/12/14, 8212210037

B212220434 Board Notifications B2-125 & B2-125A forwards info re flow blockage during natural circulation All concerns re phenomena of natural circulation flow blockage previously identified by NRC & provided to Commission
EISENHUT, D G Division of Licensing 82/12/14 PALLADINO, N J
GILINSKY, V, AHEARNE, J Commissioners 4pp 16523 103 24X
Fiche 50-000, 82/12/14, 8212220434

--B212220438 Provides suppl to B20907 memo re flow blockage by steam during natural circulation in PWRs Accident analyses upon which operating procedures are based give no credit for condensation by repressurization
ETHERINGTON, E ACRS - Advisory Committee on Reactor Safeguards
82/12/06 SHEWMON, P G ACRS - Advisory Committee on Reactor Safeguards 3pp 16523 131 24X Fiche 50-275, 82/12/14, 8212220438

B212220440 Board Notifications B2-125 & B2-125A forwards info re H Etherington evaluation of flow blockage during natural circulation of PWRs Results do not adversely impact present position on reliance on natural circulation
NOVAK, T M Assistant Director for Licensing 82/12/14 Atomic
Safety and Licensing Board Panel 5pp 16523 135 24X
Fiche 50-000, 82/12/14, 8212220440

DOCKETED ITEMS

--821220448 Forwards suppl to H Etherington 820907 memo re flow blockage by steam during natural circulation in PWRs
 FRALLEY, R F ACRS - Advisory Committee on Reactor Safeguards
 82/12/07 DENTON, H R Office of Nuclear Reactor Regulation,
 Director MINOGUE, R Office of Nuclear Regulatory Research,
 Director 1p 16523 164 24X Fiche 50-275, 82/12/14, 821220440

821220461 Board Notification 82-124 forwards RJ Mattson 821123 memo re Semiscale S-UT-B test results Phenomena of core level depression & loop seal clearing may be more complex than previously supposed
 NGVAK, T M Assistant Director for Licensing 82/12/14 Atomic
 Safety and Licensing Board Panel 7pp 16523 169 24X
 Fiche 50-000, 82/12/14, 821220461

--821220473 Requests that all Westinghouse & C-E PWR licensing boards be notified of results of Semiscale S-UT-B tests Sufficient info to draw conclusion unavailable
 MATTHEW, J Division of Systems Integration (post 811005)
 82/11/23 NRC - No Detailed Affiliation Given 4pp 16523 176
 24X Fiche 50-275, 82/12/14, 821220461

821220482 Board Notification 82-124 forwards RJ Mattson 821123 memo re Semiscale S-UT-B test results Phenomena of core level depression & loop seal clearing may be more complex than previously supposed
 EISENHUT, D G Division of Licensing 82/12/14 PALLADINO, N J,
 GILINSKY, V, AHEARNE, J F Commissioners 4pp 16523 199 24X
 Fiche 50-000, 82/12/14, 821220482

821220080 Forwards, "Diablo Canyon Unit 1 Independent Design Verification Program Piping-Addl Samples," Revision 0, Interim Technical Rept 17
 DENISON, E Robert L. Cloud Associates, Inc 82/12/15 DENTON, H R
 Office of Nuclear Reactor Regulation, Director ENGELKEN, R H
 Region 5, Office of Director MANEATIS, G A Pacific Gas & Electric
 Co 1p 16470 187 24X Fiche 50-275, 82/12/15, 821220080

--821220095 "Diablo Canyon Unit 1 Independent Design Verification Program Piping-Addl Samples," Revision 0, Interim Technical Rept 17
 DENISON, E Robert L. Cloud Associates, Inc 82/12/14 75pp
 16470 191 24X Fiche 50-275, 82/12/15, 821220080

821220217 Forwards application to amend License DPR-76, changing Tech Specs to modify audit frequency from 24 to 12 months for emergency & security plans & implementing procedures per Generic Ltrs 82-17 & 82-23
 CRANE, P A Pacific Gas & Electric Co 82/12/17 DENTON, H R
 Office of Nuclear Reactor Regulation, Director 1p 16503 011 24X
 Fiche 50-275, 82/12/17, 821220217

--821220225 Application to amend License DPR-76, changing Tech Specs to modify audit frequency from 24 to 12 months for emergency & security plans & implementing procedures
 MANEATIS, G A Pacific Gas & Electric Co 82/12/17 2pp
 16503 012 24X Fiche 50-275, 82/12/17, 821220217

--821220229 Proposed Tech Spec changes modifying audit frequency from 24 to 12 months for emergency & security plans & implementing procedures per Generic Ltrs 82-17 & 82-23
 * Pacific Gas & Electric Co 82/12/17 1p 16503 014 24X
 Fiche 50-275, 82/12/17, 821220217

821220371 Forwards addl info re mechanical & HVAC equipment outdoor storage tanks & electrical equipment & instrumentation per Phase I final rept for design verification program Results for large & small bore piping & pipe supports updated
 CRANE, P A Pacific Gas & Electric Co 82/12/17 EISENHUT, D G
 Division of Licensing 120pp 16533 347 24X Fiche 50-275,
 82/12/17, 821220371

821220098 Forwards Piping Problems 8-116, 8-117 & 8-118 to enable BNL to perform analyses Meeting w/NRC & BNL scheduled for 821221 H/o encl
 CRANE, P A Pacific Gas & Electric Co 82/12/17 EISENHUT, D G
 Division of Licensing 2pp 16564 227 24X Fiche 50-275, 82/12/17,
 821220098

821220296 Forwards Interim Technical Repts 19, 20, 21 & 22
 KRECHTING, J E Stone & Webster Engineering Corp 82/12/20
 DENTON, H R Office of Nuclear Reactor Regulation, Director
 ENGELKEN, R H Region 5, Office of Director MANEATIS, G A Pacific
 Gas & Electric Co 2pp 16535 289 24X Fiche 50-275, 82/12/20,
 821220296

--821220299 Interim Technical Rept 19, Revision 0, "Verification of Post-LOCA Portion of Radiation Environments Used for Safety-Related Equipment Spec Outside Containment for Auxiliary Feedwater Sys & Control Room Vent & Pressurization Sys."
 SESTAK, F Stone & Webster Engineering Corp STRATOULY, D
 Teledyne Engineering Services 82/12/16, 21pp 16535 262 24X
 Fiche 50-275, 82/12/20, 821220296

- 821220301 Interim Technical Rept 20, Revision 0, "Verification of Mechanical/Nuclear Design of Control Room Ventilation & Pressurization Sys"
 SESTAK, F Stone & Webster Engineering Corp STRATOULY, D
 Teledyne Engineering Services 82/12/16 23pp 16535 283 24X
 Fiche 50-275, 82/12/20, 821220296

- 821220310 Interim Technical Rept 21, Revision 0, "Verification of Effects of High Energy Line Cracks & Moderate Energy Line Breaks for Auxiliary Feedwater Sys & Control Room Ventilation & Pressurization Sys"
 SESTAK, F Stone & Webster Engineering Corp STRATOULY, D C
 Teledyne Engineering Services 82/12/15 16pp 16535 306 24X
 Fiche 50-275, 82/12/20, 821220296

- 821220312 Interim Technical Rept 22, Revision 0, "Verification of Mechanical/Nuclear Portion of Auxiliary Feedwater Sys"
 SESTAK, F Stone & Webster Engineering Corp STRATOULY, D C
 Teledyne Engineering Services 82/12/17 25pp 16535 323 21X
 Fiche 50-275, 82/12/20, 821220296

821220210 Requests temporary relief from requirements of Tech Spec J 9.7 for 120 days in order to effect mods to fuel handling bldg
 CRANE, P A Pacific Gas & Electric Co 82/12/21 KNIGHTON, G W
 Licensing Branch 3 7pp 16510 313 24X Fiche 50-275, 82/12/21,
 821220210

821220298 Forwards Revision 2 to "Diablo Canyon Project QA Program," in response to DO Eisenhut 821202 request
 CRANE, P A Pacific Gas & Electric Co 82/12/21 KNIGHTON, G W
 Licensing Branch 3 1p 16507 051 24X Fiche 50-275, 82/12/21,
 821220298

--821220304 Revision 2 to "Diablo Canyon Project QA Program"
 * Pacific Gas & Electric Co * Bechtel Corp 80-TOP-1 R02
 82/12/21 16pp 16507 052 24X Fiche 50-275, 82/12/21, 821220298

821220495 Board Notification 82-132 forwards info items re status of activities performed under design verification program
 Submittal includes RF Reedy, Teledyne, SGW & RL Cloud Assoc
 repts
 EISENHUT, D G Division of Licensing 82/12/22 PALLADINO, N,
 GILINSKY, V, AHEARNE, J Commissioners 4pp 16591 001 24X
 Fiche 50-275, 82/12/22, 821220495

821220458 Forwards "Verification of High Energy Line Breaks & Internally Generated Missile Review Outside Containment for Auxiliary Feedwater Sys & Control Room Ventilation & Pressurization Sys," Interim Technical Rept 23, Revision 0
 KRECHTING, J E Stone & Webster, Inc 82/12/22 DENTON, H R Office
 of Nuclear Reactor Regulation, Director ENGELKEN, R H Region 5,
 Office of Director MANEATIS, G A Pacific Gas & Electric Co 1p
 16585 108 24X Fiche 50-275, 82/12/22, 821220458

--821220462 "Verification of High Energy Line Breaks & Internally Generated Missile Review Outside Containment for Auxiliary Feedwater Sys & Control Room Ventilation & Pressurization Sys," Interim Technical Rept 23, Revision 0
 SESTAK, F Stone & Webster, Inc 82/12/20 20pp 16585 109 24X
 Fiche 50-275, 82/12/22, 821220458

821220205 Forwards draft interim technical rept, "Phase II Addl Sample & Addl Verification" Rept will be issued in approved form after incorporation of comments Recommends Jan 1983 meeting to aid in preparing presentation on Phase II efforts
 COOPER, W E Teledyne Engineering Services 82/12/23 DENTON, H R
 Office of Nuclear Reactor Regulation, Director ENGELKEN, R H
 Region 5, Office of Director MANEATIS, G A Pacific Gas & Electric
 Co 2pp 16578 148 24X Fiche 50-275, 82/12/23, 821220205

--821220209 "Phase II Addl Sample & Addl Verification," draft interim technical rept
 SESTAK, F Stone & Webster Engineering Corp 82/12/23 35pp
 16578 150 24X Fiche 50-275, 82/12/23, 821220205

821220231 Forwards Interim Technical Repts 24, 25 & 26, "Verification of 4160-Volt Safety-Related Electrical Distribution Sys Design Review," "Verification of Auxiliary Feedwater Sys Electrical Design" & "Verification of Control Room"
 KRECHTING, J E Stone & Webster Engineering Corp 82/12/23
 DENTON, H R Office of Nuclear Reactor Regulation, Director
 ENGELKEN, R H Region 3, Office of Director MANEATIS, G A Pacific
 Gas & Electric Co 1p 16589 236 24X Fiche 50-275, 82/12/23,
 821220231

--821220237 "Verification of Auxiliary Feedwater Sys Electrical Design," Interim Technical Rept 25, Revision 0
 SESTAK, F Stone & Webster Engineering Corp STRATOULY, D C
 Teledyne Engineering Services 25 R02 82/12/21 19pp
 16589 238 24X Fiche 50-275, 82/12/23, 821220231

--B212290243 "Verification of 4160-Volt Safety-Related Electrical Distribution Sys." Interim Technical Rept 24, Revision 0
SESTAK, F Stone & Webster Engineering Corp STRATOU, D C
Teledyne Engineering Services 24 R00 82/12/21 21pp
14589 257 24X Fiche 50-275, 82/12/23, 8212290231

--B212290250 "Verification of Control Room Ventilation & Pressurization Sys Electrical Design." Interim Technical Rept 26, Revision 0
SESTAK, F Stone & Webster Engineering Corp STRATOU, D C
Teledyne Engineering Services 26 R00 82/12/21 20pp
14589 278 24X Fiche 50-275, 82/12/23, 8212290231

Q Inspection reports, IE Bulletins & correspondence

B2108190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Svc list encl
DEVOUNO, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240

B2108190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model H01 & Model 802 Thermoluminescent Dosimeters " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000, 82/11/05, 8208190245

B212060353 Forwards IE Insp Rept 50-275/82-31 on 821012-15 No noncompliance noted
BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 82/11/15 CRANE, P A Pacific Gas & Electric Co 2pp 16311 082 24X Fiche 50-275, 82/11/15, 8212060353

--B212060364 IE Insp Rept 50-275/82-31 on 821012-15 No noncompliance noted Major areas inspected revised program for handling design changes & modt, implementation procedures, interviews w/licenses & Bechtel personnel & drafting control program
MORRILL, P J, CARLSON, J D, KIRSCH, D F Division of Resident, Reactor Project & Engineering Programs 82/11/15 4pp 16311 084 24X Fiche 50-275, 82/11/15, 8212060353

B2108190251 IE Info Notice 82-44, "Clarification of Emergency Plan (Exercise Requirements " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X fiche 50-000, 82/11/18, 8208190251

B212060251 Forwards IE Insp Rept 50-275/82-36 on 821003-30 No noncompliance noted
BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 82/11/22 CRANE, P A Pacific Gas & Electric Co 2pp 16312 279 24X Fiche 50-275, 82/11/22, 8212060251

--B212060261 IE Insp Rept 50-275/82-36 on 821003-30 No noncompliance noted Major areas inspected surveillance testing, physical security, maint, TMI task action plan items, emergency drill & design changes & mod
CARLSON, J D, MENDONCA, M M, KIRSCH, D F Division of Resident, Reactor Project & Engineering Programs 82/11/19 5pp 16312 283 24X Fiche 50-275, 82/11/22, 8212060251

B212060155 Discusses 820208 ltr re adequacy of NUREG-0862, "Insp Rept of Preliminary Rept, Seismic Reverification Program at Diablo Canyon Nuclear Power Plant, Units 1 & 2 " Questions posed through 820423 Ofc of Inspector & Auditor review answered
PALLADINO, N J Commissioners 82/11/23 UDALL, M K House of Rep, Interior & Insular Affairs 2pp 16325 232 24X fiche 50-275, 82/11/23, 8212060155

--B212060164 Discusses 820204 ltr re adequacy of NUREG-0862, "Insp Rept of Preliminary Rept, Seismic Reverification Program at Diablo Canyon Nuclear Power Plant, Units 1 & 2 " Questions posed through 820423 Ofc of Inspector & Auditor review answered
PALLADINO, N J Commissioners 82/11/23 OTTINGER, R House of Rep, Energy & Commerce 2pp 16325 234 24X Fiche 50-275, 82/11/23, 8212060155

--B212060177 Submits review of NUREG-0862, "Insp Rept of Preliminary Rept, Seismic Reverification Program at Diablo Canyon Nuclear Power Plant, Units 1 & 2." per Udall 820208 & Ottinger 820204 requests Investigation conducted in 2 phases
CUMMINOS, J J Office of Inspector & Auditor 82/07/30 PALLADINO, N Commissioners 7pp 16325 236 24X Fiche 50-275, 82/11/23, 8212060155

B2108190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list encl
DEVOUNO, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000, 82/11/26, 8208190256

B212130169 Forwards IE Insp Rept 50-275/82-35 on 821025-29 No noncompliance noted
BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 82/11/26 CRANE, P A Pacific Gas & Electric Co 4pp 16396 089 24X Fiche 50-275, 82/11/26, 8212130169

--B212130171 IE Insp Rept 50-275/82-35 on 821025-29 No noncompliance noted Major areas inspected const & mod activities, including site tour, mods to piping & electrical raceway supports
BURDOIN, J F, ZWETZIO, O B Division of Resident, Reactor Project & Engineering Programs 82/11/26 6pp 16396 093 24X Fiche 50-275, 82/11/26, 8212130169

B2108190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000, 82/11/30, 8208190257

B2108190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl
DEVOUNO, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259

B2108190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X Fiche 50-000, 82/12/03, 8208190261

B2108190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
DEVOUNO, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16, 8208190267

B2108190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27 " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X Fiche 50-000, 82/12/20, 8208190268

R Periodic operating reports & related correspondence

B212290214 Forwards monthly operating rept for Oct 1982
THORNBERY, R C Pacific Gas & Electric Co 82/11/02 Division of Data Automation & Management Information 1p 16578 190 24X fiche 50-275, 82/11/02, 8212290214

--B212290218 Monthly operating rept for Oct 1982
KELLY, W J Pacific Gas & Electric Co 82/11/01 4pp 16578 191 24X Fiche 50-275, 82/11/02, 8212290214

B212060047 Forwards "Diablo Canyon Verification Program." Semimonthly Rept 26 for 821109-1122
CRANE, P A Pacific Gas & Electric Co 82/11/24 DENTON, H R Office of Nuclear Reactor Regulation, Director ENGELKEN, R H Region 5, Office of Director 1p 16313 205 24X Fiche 50-275, 82/11/24, 8212060047

--B212060053 "Diablo Canyon Verification Program." Semimonthly Rept 26 for 821109-1122
* Pacific Gas & Electric Co 82/11/24 64pp 16313 206 24X Fiche 50-275, 82/11/24, 8212060047

B212010206 Forwards "Independent Design Verification Program Semimonthly Status Rept for Nov 1982 "
COOPER, W E Teledyne Engineering Services 82/11/26 DENTON, H R Office of Nuclear Reactor Regulation, Director ENGELKEN, R H Region 5, Office of Director MANEATIS, G A Pacific Gas & Electric Co 1p 16260 055 24X Fiche 50-275, 82/11/26, 8212010206

--B212010211 "Independent Design Verification Program Semimonthly Status Rept for Nov 1982 "
* Teledyne Engineering Services 82/11/26 83pp 16260 056 24X Fiche 50-275, 82/11/26, 8212010206

--B212010225 Forwards conference notes from 821104 working meeting w/Diablo Canyon Project, util, Bechtel, NRC & Teledyne Engineering re engineering open items generated in electrical & instrument/controls area
KRECHTING, J E Stone & Webster Engineering Corp 82/11/22 DENTON, H R Office of Nuclear Reactor Regulation, Director ENGELKEN, R H Region 5, Office of Director MANEATIS, G A Pacific Gas & Electric Co 22pp 16260 033 24X Fiche 50-275, 82/11/26, 8212010206

DOCKETED ITEMS

8212140281 Forwards "Independent Design Verification Program, TES-SM-Dec Semimonthly Rept "
COOPER, W E Teledyne Engineering Services 82/12/10 DENTON, H R
Office of Nuclear Reactor Regulation, Director ENGELKEN, R H
Region 5, Office of Director MANEATIS, G A Baltimore Gas & Electric Co 1p 16404 207 24X Fiche 50-275, 82/12/10, 8212140281

--8212140285 "Independent Design Verification Program, TES-SM-Dec Semimonthly Rept "
* Teledyne Engineering Services 82/12/10 58pp 16404 208
24X Fiche 50-275, 82/12/10, 8212140281

8212140447 Forwards Semimonthly Progress Rept 22 re independent design verification program for 82112-1210, consisting of Open Item Repts 7003-7006
REEDY, R F R F Reedy, Inc 82/12/10 DENTON, H R Office of Nuclear Reactor Regulation, Director ENGELKEN, R H Region 5, Office of Director MANEATIS, G A Pacific Gas & Electric Co 10pp 16405 001 24X Fiche 50-275, 82/12/10, 8212140447

8212170217 Forwards "Diablo Canyon Design Verification Program," Semimonthly Rept 27 for 821123-1206
CRANE, P A Pacific Gas & Electric Co 82/12/10 DENTON, H R Office of Nuclear Reactor Regulation, Director ENGELKEN, R H Region 5, Office of Director 1p 16461 311 24X Fiche 50-275, 82/12/10, 8212170217

--8212170223 "Diablo Canyon Design Verification Program," Semimonthly Rept 27 for 821123-1206
* Pacific Gas & Electric Co 82/12/10 61pp 16461 312 24X Fiche 50-275, 82/12/10, 8212170217

8212290366 Forwards "Semimonthly Rept 28 - Diablo Canyon Verification Program," summarizing progress of technical work for 821207-20
CRANE, P A Pacific Gas & Electric Co 82/12/23 DENTON, H R Office of Nuclear Reactor Regulation, Director ENGELKEN, R H Region 5, Office of Director 1p 16587 030 24X Fiche 50-275, 82/12/23, 8212290366

--8212290372 "Semimonthly Rept 28 - Diablo Canyon Verification Program "
* Pacific Gas & Electric Co. 82/12/23 62pp, 16587 031 24X Fiche 50-275, 82/12/23, 8212290366

8212290146 Forwards "Diablo Canyon Nuclear Power Plant Independent Design Verification Program Semimonthly Status Rept for Dec 1982 "
COOPER, W E Teledyne Engineering Services 82/12/24 DENTON, H R Office of Nuclear Reactor Regulation, Director ENGELKEN, R H Region 5, Office of Director MANEATIS, G A Pacific Gas & Electric Co 1p 16583 101 24X Fiche 50-275, 82/12/24, 8212290146

--8212290152 "Diablo Canyon Nuclear Power Plant Independent Design Verification Program Semimonthly Status Rept for Dec 1982 "
* Teledyne Engineering Services 82/12/24 97pp 16583 102 24X Fiche 50-275, 82/12/24, 8212290146

B Reportable occurrences, LERs & related correspondence

8212210116 Forwards LER 82-011/03L-0
SHIFFER, J D Pacific Gas & Electric Co 82/11/24 ENGELKEN, R H Region 5, Office of Director 1p 16485 120 24X Fiche 50-275, 82/11/24, 8212210116

--8212210123 LER 82-011/03L-0 on 821024, steam generator blowdown effluent line flow rate measurement device FR-53 found inoperable prior to fuel load caused by worn motor gear assembly. Design change will correct erroneous readings.
KELLY, W J Pacific Gas & Electric Co 82/11/24 Region 5, Office of Director 2pp 16485 121 24X Fiche 50-275, 82/11/24, 8212210116

8212130253 PNS-V-82-004 on 821207, Bureau of Alcohol, Tobacco & Firearms arrested JA Junot & charged Junot w/possession of three destructive devices w/intent to use devices to destroy or damage portions of plant.
SCHUSTER, M D, SCHAEFER, D W Region 5, Office of Director 82/12/07 1p 16396 253 24X Fiche 50-275, 82/12/07, 8212130253

T Hearing transcripts on non-antitrust matters

8212270450 Unofficial transcript of Commission 821208 meeting in Washington, DC re discussion & possible vote on facility Phase II reverification program & ASLB certification Pp 1-21
* Commissioners 82/12/08 24pp 16371 313 24X Fiche 50-275, 82/12/08, 8212270450

DOCKET 50-277 PEACH BOTTOM ATOMIC POWER STATION, UNIT 2

F Security, medical, emergency & fire protection plans

8212160480 Forwards 1E Insp Repts 50-277/82-16 & 50-278/82-16 on 821021-1130 & notice of violation
STAROSTECKI, R Division of Project & Resident Programs 82/12/03 DALTROFF, S L Philadelphia Electric Co 2pp 16442 087 24X Fiche 50-277, 82/12/03, 8212160480

--8212160486 Notice of violation from insp on 821021-1130
* Division of Project & Resident Programs 82/12/03 1p 16442 087 24X Fiche 50-277, 82/12/03, 8212160480

--8212160491 1E Insp Repts 50-277/82-16 & 50-278/82-16 on 821021-1130 Noncompliance noted failure to meet Tech Spec fire watch requirements
BLOUGH, A R, MCCABE, E C Region 1, Office of Director 82/12/03 21pp 16442 090 24X Fiche 50-277, 82/12/03, 8212160480

8212100036 Responds to NRC 821202 telcon questions re design of emergency operations facility Existing shielding sufficient for meeting NUREG-0578 personnel dose criteria, but exceeds Generic Ltr 81-10 criteria
DALTROFF, S L Philadelphia Electric Co 82/12/06 STOLZ, J F Operating Reactors Branch 4 3pp 16379 043 24X Fiche 50-277, 82/12/06, 8212100036

8212210129 Forwards 1E Safeguards Insp Repts 50-277/82-22 & 50-278/82-21 on 821018-22 No noncompliance noted
MARTIN, T T Division of Engineering & Technical Programs 82/12/06 DALTROFF, S L Philadelphia Electric Co 2pp 16485 134 24X Fiche 50-277, 82/12/06, 8212210129

--8212210134 1E Safeguards Insp Repts 50-277/82-22 & 50-278/82-21 on 821018-22 No noncompliance noted Major areas inspected security plans & implementing procedures, security organization met & personnel Safeguards info deleted
DUNLAP, J H, GODY, A T Division of Engineering & Technical Programs 82/11/30 9pp 16485 136 24X Fiche 50-277, 82/12/06, 8212210129

8212150181 Releases public version of revised emergency plan implementing procedures
FELTOW, J M Division of Rules and Records 82/12/07 Document Management Branch 1p 16437 283 24X Fiche 50-277, 82/12/07, 8212150181

--8212150187 Forwards public version of revised emergency plan implementing procedures, including Procedures EP-205B re radiation survey groups & EP-209 re telephone list for emergency use Affidavit of Svc encl
DALTROFF, S L Philadelphia Electric Co 82/11/19 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 16437 284 24X Fiche 50-277, 82/12/07, 8212150181

--8212150193 Public version of revised emergency plan implementing procedures, including Procedures EP-205B re radiation survey groups & EP-209 re telephone list for emergency use
* Philadelphia Electric Co 82/10/20 59pp 16437 288 24X Fiche 50-277, 82/12/07, 8212150181

8212210174 Provides addl info to assist shift crews making telephone repts via NRC emergency notification sys Sample event notification form used by NRC duty officer encl
STAROSTECKI, R Division of Project & Resident Programs 82/12/16 DALTROFF, S L Philadelphia Electric Co 6pp 16484 250 24X Fiche 50-277, 82/12/16, 8212210174

8212230313 Notifies that review of DL & App A Tech Specs performed in response to 821030 Generic Ltr 82-23 re inconsistency between requirements of 10CFR73 40(d) & STS for audits of safeguards contingency plan Contingency plan adopted
DALTROFF, S L Philadelphia Electric Co 82/12/17 EISENHUT, D O Division of Licensing 2pp 16507 360 24X Fiche 50-277, 82/12/17, 8212230313

G Adjudicatory correspondence

8212140186 Request for extension of time until 821224 to file petition for review of ALAB-701 Time necessary due to holidays, sickness & vacations Certificate of Svc encl
JOHNSRUDD, J H Environmental Coalition on Nuclear Power 82/12/08 Commissioners 4pp 16403 167 24X Fiche 50-000, 82/12/08, 8212140186

8212140438 Order extending time until 821227 for TM1 & Peach Bottom intervenors to file petition for review of ALAB-701
CHILK, S J Office of the Secretary of the Commission 82/12/13 Environmental Coalition on Nuclear Power 1p 16404 360 24X Fiche 50-000, 82/12/13, 8212140438

8212210009 Advises that intervenor petition for review of ALAB-701 should be served on NRC when filed
MORDEENICK, B M Hearing Branch 3 82/12/16 JOHNSRUD, J
Affiliation Unknown 2pp 16486 005 24X Fiche 50-000, 82/12/16,
8212210009

8212300134 Petition for review of consolidated radon proceedings
Commission should grant financial assistance to intervenors,
should reopen record on all issues & remand case for full
consideration Certificate of Svc encl
JOHNSRUD, J H Environmental Coalition on Nuclear Power 82/12/27
Commissioners 15pp 16598 112 24X Fiche 50-000, 82/12/27,
8212300134

P Operating license stage documents & correspondence

8212100365 Requests verification that encl acceptance criteria for
NUREG-0737, Item II K 3 22, "Automatic Switchover of RCIC
Sys Suction" satisfied Response requested within 30 days
STOLZ, J F Operating Reactors Branch 4 82/08/04 BAUER, E O
Philadelphia Electric Co 4pp 16389 193 24X
Fiche 50-277, 82/08/04, 8212100365

8212080566 Requests participation, cooperation & support of NRC research
project, "Task Analysis of Nuclear Power Plant Control Room
Crews"
SCHWENGER, A Licensing Branch 2 82/11/09 DALTROFF, S L
Philadelphia Electric Co 2pp 16368 350 24X
Fiche 50-277, 82/11/09, 8212080566

8212300666 Generic Ltr 82-27 to all BWR licensees of operating reactors
except LACBWR, Big Rock Point, Dresden 1, Humboldt Bay,
applicants for OL & holders of CP re transmittal of
NUREG-0763 & NUREG-0783 Svc list encl (1/0 stated encl
EISENHUT, D O Division of Licensing 82/11/15 General Public
Utilities - OPU Service Corp 22pp 16387 004 24X
Fiche 50-000, 82/11/15, 8212300666

8212090119 Forwards info re site geology, confirming telcon
w/MB Fairtile
DALTROFF, S L Philadelphia Electric Co 82/11/30 STOLZ, J F
Operating Reactors Branch 4 20pp 16357 245 24X
Fiche 50-277, 82/11/30, 8212090119

8212060096 Forwards application to amend Licenses DPR-44 & DPR-56,
changing surveillance requirements of Tech Specs to permit
alternate method of performing core spray loop flow rate
test
BRADLEY, E J Philadelphia Electric Co 82/12/01 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 16314 345 24X
Fiche 50-277, 82/12/01, 8212060096

--8212060106 Application to amend Licenses DPR-44 & DPR-56, changing
surveillance requirements of Tech Specs to permit alternate
method of performing core spray loop flow rate test
BAUER, E O, BRADLEY, E J, DALTROFF, S L Philadelphia Electric Co
82/12/01 6pp 16314 346 24X Fiche 50-277, 82/12/01, 8212060096

--8212060109 Proposed changes to surveillance requirements of Tech Specs
to permit alternate method of performing core spray loop
flow rate test
* Philadelphia Electric Co 82/12/01 4pp 16314 352 24X
Fiche 50-277, 82/12/01, 8212060096

8212130211 Responds to NRC 821101 request for addl info re util 811001
response to Generic Ltr 81-04 concerning Revision 1 to
NUREG-0313 Responses to Items 4, 5d & 6d will be submitted no
later than 821215
DALTROFF, S L Philadelphia Electric Co 82/12/03 STOLZ, J F
Operating Reactors Branch 4 13pp 16462 277 24X
Fiche 50-277, 82/12/03, 8212130211

--8212170094 "Manual Ultrasonic Exam of Pressure Piping Welds," Revision
59
WALKER, S Southwest Research Institute 81/11/30 38pp
16462 290 24X Fiche 50-277, 82/12/03, 8212130211

--8212170101 "Induction Heating Stress Improvement, Implementation
Planning & Field Procedure Development," final rept
BERTOSHA, D C, FITZSIMMONS, M, ZSCHALER, W A General Electric Co
EPRI NP-2527-LD 82/08/31 197pp 16462 328 24X
Fiche 50-277, 82/12/03, 8212130211

--8212170111 "Residual Stress Improvement by Means of Induction Heating"
* Ishikawajima - Harima Heavy Industries Co, Ltd EPRI
NP-81-4-LD 81/03/31 354pp 16463 165 24X
Fiche 50-277, 82/12/03, 8212130211

8212140385 Requests relief from 791211 commitment re containment purge
& vent valve operation to allow insp in drywell of primary
sys during low power justification provided
DALTROFF, S L Philadelphia Electric Co 82/12/09 STOLZ, J F
Operating Reactors Branch 4 2pp 16402 113 24X
Fiche 50-277, 82/12/09, 8212140385

8212170063 Confirms approval of 821209 request for extension of time
re 791211 commitment to purge containment for no more than
90-h per yr Purging should be limited to 115-h for one time
only during ongoing shutdown & restart
STOLZ, J F Operating Reactors Branch 4 82/12/09 BAUER, E O
Philadelphia Electric Co 2pp 16480 348 24X
Fiche 50-277, 82/12/09, 8212170063

8212150058 Forwards amend to application to amend Licenses DPR-44 &
DPR-56 Amend revises & updates list of shock suppressors
proposed for inclusion in Tech Specs
BRADLEY, E J Philadelphia Electric Co 82/12/13 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 16427 326 24X
Fiche 50-277, 82/12/13, 8212150058

--8212150062 Amend to application to amend Licenses DPR-44 & DPR-56,
revising & updating list of shock suppressors proposed for
inclusion in Tech Specs
BAUER, E O, BRADLEY, E J Philadelphia Electric Co 82/12/13
12pp 16427 327 24X Fiche 50-277, 82/12/13, 8212150058

8212170315 Responds to NRC request for addl info on Mark I plant-unique
analysis rept submitted on 820430 Results of torus attached
piping sys analyses & questions re safety relief valve
discharge piping will be addressed in addendum to rept
KEMPER, J S Philadelphia Electric Co 82/12/14 STOLZ, J F
Operating Reactors Branch 4 12pp 16453 193 24X
Fiche 50-277, 82/12/14, 8212170315

8212210312 Endorses BWR owners group 810522 rept re NUREG-0737, Item
2 K 3 25 concerning consequences of loss of cooling water to
reactor recirculation pump seal coolers, per 821028 request
DALTROFF, S L Philadelphia Electric Co 82/12/14 EISENHUT, D O
Division of Licensing 2pp 16496 309 24X Fiche 50-277, 82/12/14,
8212210312

8212170248 Identifies need for 3-month delay in schedule to replace
gaseous chlorination sys w/liquid sodium hypochlorite sys,
per NUREG-0737, Item III D 3 4, "Control Room Habitability
Requirements"
DALTROFF, S L Philadelphia Electric Co 82/12/15 EISENHUT, D O
Division of Licensing 2pp 16459 203 24X Fiche 50-277, 82/12/15,
8212170248

8212170265 Forwards application for amend to Licenses DPR-44 & DPR-56,
revising Tech Specs re operability & surveillance
requirements for scram discharge vol vent & drain isolation
valves
BRADLEY, E J Philadelphia Electric Co 82/12/15 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 16456 190 24X
Fiche 50-277, 82/12/15, 8212170265

--8212170275 Application to amend Licenses DPR-44 & DPR-56, revising Tech
Specs re operability & surveillance requirements for scram
discharge vol vent & drain isolation valves Certificate of
Svc encl
* Philadelphia Electric Co 82/12/15 5pp 16456 191 24X
Fiche 50-277, 82/12/15, 8212170265

--8212170280 Revised Tech Spec tables re operability & surveillance
requirements for scram discharge vol & drain isolation
valves
* Philadelphia Electric Co 82/12/15 5pp 16456 196 24X
Fiche 50-277, 82/12/15, 8212170265

8212170289 Forwards proprietary rept, "Induction Heating Stress
Improvement for Stainless Steel Piping" Affidavit encl
Rept withheld (ref 10CFR2 790)
DALTROFF, S L Philadelphia Electric Co 82/12/15 STOLZ, J F
Operating Reactors Branch 4 20pp 16456 033 24X
Fiche 50-277, 82/12/15, 8212170289

8212230220 Forwards SER for environ qualification of safety-related
electrical equipment Requests plans for Categories I, B, II A
& II B & schedule for proposed corrective actions within 90
days Technical evaluation encl Proprietary version withheld
STOLZ, J F Operating Reactors Branch 4 82/12/20 BAUER, E O
Philadelphia Electric Co 3pp 16512 020 24X
Fiche 50-277, 82/12/20, 8212230220

--8212230230 Safety evaluation supporting util compliance w/enviro
qualification of safety-related electrical equipment
* Office of Nuclear Reactor Regulation, Director 82/12/20 5pp
16512 023 24X Fiche 50-277, 82/12/20, 8212230220

DOCKETED ITEMS

--B212230290 Nonproprietary "Review of Licensee Resolution of Outstanding Issues From NRC Equipment Environ Qualification SEERs (F-11 & B-60), Peach Bottom Atomic Power Stations Units 2 & 3, Vols 1 & 2," technical evaluation rept
CRANE, C J Franklin Institute/Franklin Research Center
NRC-03-79-118 TER-C5257-493 82/09/03 LE, N B, SHEMANSKI, P
NRC - No Detailed Affiliation Given 1.461pp 16512 028 24X
Fiche 50-277, 82/12/20, B212230220

B212270167 Verifies that acceptance criteria for mod providing automatic switchover of RCIC sys suction has been satisfied per NUREG-0737, Item II K 3 22 Mod completed on both units
Emergency procedure provided for plant operators
DALTROFF, S L Philadelphia Electric Co 82/12/20 STOLZ, J F
Operating Reactors Branch 4 2pp 16538 345 24X
Fiche 50-277, 82/12/20, B212270167

B212290235 Clarifies program for implementation of NUREG-0737, Item II B 4 re training for mitigating core damage, in response to B21208 meeting request Training for plan manager should be limited considering past experience & knowledge
DALTROFF, S L Philadelphia Electric Co 82/12/22 STOLZ, J F
Operating Reactors Branch 4 3pp 16582 170 24X
Fiche 50-277, 82/12/22, B212290235

B212280452 Informs of need for extension in implementation schedule for installation of new meteorological monitoring sys required by NUREG-0737, Item III A 2, due to structural deficiencies in weather tower Revised schedule expected by 830115
DALTROFF, S L Philadelphia Electric Co 82/12/23 EISENHUT, D G
Division of Licensing 2pp 16556 013 24X Fiche 50-277, 82/12/23, B212280452

Q Inspection reports, IE Bulletins & correspondence

B208190240 IE Bulletin B2-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc
112pp 16462 163 24X Fiche 50-000, 82/10/28, B208190240

B208190245 IE Info Notice B2-42, "Defects Observed in Panasonic Model B01 & Model B02 Thermoluminescent Dosimeters " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/05, Consolidated Edison Co of New York, Inc 110pp
16372 142 24X Fiche 50-000, 82/11/05, B208190245

B208190251 IE Info Notice B2-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X
Fiche 50-000, 82/11/18, B208190251

B208190256 IE Info Notice B2-46, "Defective & Obsolete Combination Padlocks " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc
127pp 16411 065 24X Fiche 50-000, 82/11/26, B208190256

B208190257 IE Info Notice B2-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp
16387 028 24X Fiche 50-000, 82/11/30, B208190257

B208190259 IE Bulletin B2-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies." Svc list encl.
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03, Consolidated Edison Co of New York, Inc
113pp 16411 317 24X Fiche 50-000, 82/12/03, B208190259

B208190261 IE Info Notice B2-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X
Fiche 50-000, 82/12/03, B208190261

B212080314 Ack receipt of B21109 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-277/82-14 & 50-278/82-14
STAROSTECKI, R Division of Project & Resident Programs 82/12/03
DALTROFF, S L Philadelphia Electric Co 1p 16353 390 24X
Fiche 50-277, 82/12/03, B212080314

--B212080323 Responds to NRC 820929 ltr re violations noted in IE Insp Repts 50-277/82-14 & 50-278/82-14 Corrective actions health physics personnel instructed to more forcefully check locked doors when performing surveillance test
DALTROFF, S L Philadelphia Electric Co 82/11/09 STAROSTECKI, R
Division of Project & Resident Programs 2pp 16353 351 24X
Fiche 50-277, 82/12/03, B212080314

B212160480 Forwards IE Insp Repts 50-277/82-16 & 50-278/82-16 on B21021-1130 & notice of violation
STAROSTECKI, R Division of Project & Resident Programs 82/12/03
DALTROFF, S L Philadelphia Electric Co 2pp 16442 087 24X
Fiche 50-277, 82/12/03, B212160480

--B212160486 Notice of violation from insp on B21021-1130
* Division of Project & Resident Programs 82/12/03 1p
16442 089 24X Fiche 50-277, 82/12/03, B212160480

--B212160491 IE Insp Repts 50-277/82-16 & 50-278/82-16 on B21021-1130
Noncompliance noted failure to meet Tech Spec fire watch requirements
BLOUGH, A R, MCCABE, E C Region 1, Office of Director 82/12/03
21pp 16442 090 24X Fiche 50-277, 82/12/03, B212160480

B212210129 Forwards IE Safeguards Insp Repts 50-277/82-22 & 50-278/82-21 on B21018-22 No noncompliance noted
MARTINI, T Division of Engineering & Technical Programs 82/12/06
DALTROFF, S L Philadelphia Electric Co 2pp 16485 134 24X
Fiche 50-277, 82/12/06, B212210129

--B212210134 IE Safeguards Insp Repts 50-277/82-22 & 50-278/82-21 on B21018-22 No noncompliance noted Major areas inspected security plans & implementing procedures, security organization mgt & personnel Safeguards info deleted
DUNLAP, J M, GDDY, A T Division of Engineering & Technical Programs 82/11/30 5pp 16485 136 24X Fiche 50-277, 82/12/06, B212210129

B212140335 Requests relief from 791211 commitment re containment purge & vent valve operation to allow insp in drywell of primary sys during low power Justification provided
DALTROFF, S L Philadelphia Electric Co 82/12/09 STOLZ, J F
Operating Reactors Branch 4 2pp 16402 113 24X
Fiche 50-277, 82/12/09, B212140335

B208190267 IE Info Notice B2-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc
127pp 16628 191 24X Fiche 50-000, 82/12/16, B208190267

B212220412 Advises that meeting will be arranged to discuss IE Info Notice B2-05, "Increasing Frequency of Drug-Related Incidents " List of topic areas to be discussed encl
STAROSTECKI, R Division of Project & Resident Programs 82/12/16
DALTROFF, S L Philadelphia Electric Co 2pp 16503 354 24X
Fiche 50-277, 82/12/16, B212220412

B208190268 IE Info Notice B2-50, "Mod of Solid State AC Undervoltage Relays Type 17E-27 " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X
Fiche 50-000, 82/12/20, B208190268

R Periodic operating reports & related correspondence

B212020349 Forwards "Thermal Mapping Rept B2-7 for B21027 for Thermal Monitoring Requirements " Info covers isotherm surveys per App B ETS reporting requirements
WILLSEY, W B Philadelphia Electric Co 82/11/24 IPPOLITO, T A
Operating Reactors Branch 3 1p 16278 005 24X
Fiche 50-277, 82/11/24, B212020349

--B212020352 "Thermal Mapping Rept B2-7 for B21027 for Thermal Monitoring Requirements "
* Philadelphia Electric Co 82/11/24 4pp 16278 006 24X
Fiche 50-277, 82/11/24, B212020349

B212160055 Forwards monthly operating repts for Nov 1982
COONEY, M J Philadelphia Electric Co 82/12/10 Director's Office, Office of Inspection and Enforcement 1p 16446 131 24X
Fiche 50-277, 82/12/10, B212160055

--B212160058 Monthly operating repts for Nov 1982
ALDEN, N M Philadelphia Electric Co 82/12/10 9pp 16446 132 24X
Fiche 50-277, 82/12/10, B212160055

B212210158 Forwards Thermal Mapping Rept B2-8 re isotherm surveys for B21119, in compliance w/App B to ETS
WILLSEY, W B Philadelphia Electric Co 82/12/15 IPPOLITO, T A
Operating Reactors Branch 3 1p 16484 308 24X
Fiche 50-277, 82/12/15, B212210158

--B212210162 "Thermal Mapping Rept B2-8 for B21119 for Thermal Monitoring Requirements "
* Philadelphia Electric Co 82-8 82/11/19 4pp 16484 309 24X
Fiche 50-277, 82/12/15, B212210158

S Reportable occurrences, LERs & related correspondence

B212150041 LER 82-038/03L-0 on B21106 & OB: isolation valves SV2671C, SV2671D & SV2671A in sample lines to oxygen analyzers failed to fully close. Caused by accumulation of dirt on seat & valve disk. Valves disassembled, cleaned & rebuilt.
COONEY, M J Philadelphia Electric Co 82/12/02 HAYNES, R C
Region 1, Office of Director 1p 16430 251 24X
Fiche 50-277, 82/12/02, B212150061

B212160415 LER 82-032/03L-0 on B21114, during surveillance test, no air flowed from B main control room emergency ventilation fan. Caused by fan damper controller being out of adjustment. Controller adjusted, sys tested & returned to svc.
COONEY, M J Philadelphia Electric Co 82/12/14 Region 1, Office of Director 1p 16442 283 24X Fiche 50-277, 82/12/14, B212160415

DOCKET 50-278 PEACH BOTTOM ATOMIC POWER STATION, UNIT 3

F Security, medical, emergency & fire protection plans

B212160480 Forwards IE Insp Repts 50-277/82-16 & 50-278/82-16 on B21021-1130 & notice of violation.
STAROSTECKI, R Division of Project & Resident Programs 82/12/03
DALTROFF, S L Philadelphia Electric Co 2pp 16442 087 24X
Fiche 50-277, 82/12/03, B212160480

--B212160486 Notice of violation from insp on B21021-1130
* Division of Project & Resident Programs 82/12/03 1p
16442 089 24X Fiche 50-277, 82/12/03, B212160480

--B212160491 IE Insp Repts 50-277/82-16 & 50-278/82-16 on B21021-1130
Noncompliance noted failure to meet Tech Spec fire watch requirements.
BLOUGH, A R Region 1, Office of Director 82/12/03 21pp
16442 090 24X Fiche 50-277, 82/12/03, B212160480

B212100036 Responds to NRC B21202 telcon questions re design of emergency operations facility. Existing shielding sufficient for meeting NUREG-0578 personnel dose criteria, but exceeds Generic Ltr 81-10 criteria.
DALTROFF, S L Philadelphia Electric Co 82/12/06 STOLZ, J F
Operating Reactors Branch 4 3pp 16379 043 24X
Fiche 50-277, 82/12/06, B212100036

B21210129 Forwards IE Safeguards Insp Repts 50-277/82-22 & 50-278/82-21 on B21018-22. No noncompliance noted.
MARTIN, T T Division of Engineering & Technical Programs 82/12/06
DALTROFF, S L Philadelphia Electric Co 2pp 16485 134 24X
Fiche 50-277, 82/12/06, B21210129

--B212210134 IE Safeguards Insp Repts 50-277/82-22 & 50-278/82-21 on B21018-22. No noncompliance noted. Major areas inspected: security plans & implementing procedures, security organization mgt & personnel. Safeguards info deleted.
DUHAP, J M Division of Engineering & Technical Programs 82/11/30 5pp 16485 136 24X Fiche 50-277, 82/12/06, B212210129

B212150181 Releases public version of revised emergency plan implementing procedures.
FELTON, J M Division of Rules and Records 82/12/07 Document Management Branch 1p 16437 283 24X Fiche 50-277, 82/12/07, B212150181

--B212150187 Forwards public version of revised emergency plan implementing procedures, including Procedures EP-205B re radiation survey groups & EP-209 re telephone list for emergency use. Affidavit of Svc encl.
DALTROFF, S L Philadelphia Electric Co 82/11/19 DENTON, H R
Office of Nuclear Reactor Regulation, Director 4pp 16437 284 24X Fiche 50-277, 82/12/07, B212150181

--B212150193 Public version of revised emergency plan implementing procedures, including Procedures EP-205B re radiation survey groups & EP-209 re telephone list for emergency use.
* Philadelphia Electric Co 82/10/20 59pp 16437 288 24X
Fiche 50-277, 82/12/07, B212150181

B212210174 Provides addl info to assist shift crews making telephone repts via NRC emergency notification sys. Sample event notification form used by NRC duty officer encl.
STAROSTECKI, R Division of Project & Resident Programs 82/12/16
DALTROFF, S L Philadelphia Electric Co 6pp 16484 250 24X
Fiche 50-277, 82/12/16, B212210174

B212230313 Notifies that review of QL & App A Tech Specs performed in response to B21030 Generic Ltr 82-23 re inconsistency between requirements of 10CFR73.40(d) & STB for audits of safeguards contingency plan. Contingency plan adopted.
DALTROFF, S L Philadelphia Electric Co 82/12/17 EISENHUT, D G
Division of Licensing 2pp 16507 360 24X Fiche 50-277, 82/12/17, B212230313

G Adjudicatory correspondence

B212140186 Request for extension of time until B21224 to file petition for review of ALAD-701. Time necessary due to holidays, sickness & vacations. Certificate of Svc encl.
JOHNSRUDD, J H Environmental Coalition on Nuclear Power 82/12/08
Commissioners 4pp 16403 167 24X Fiche 50-000, 82/12/08, B212140186

B212140438 Order extending time until B21227 for TH1 & Peach Bottom intervenors to file petition for review of ALAD-701.
CHILK, S J Office of the Secretary of the Commission 82/12/13
Environmental Coalition on Nuclear Power 1p 16404 360 24X
Fiche 50-000, 82/12/13, B212140438

B212210009 Advises that intervenor petition for review of ALAD-701 should be served on NRC when filed.
BORDENICK, B H Hearing Branch 3 82/12/16 JOHNSRUDD, J
Affiliation Unknown 2pp 16486 005 24X Fiche 50-000, 82/12/16, B212210009

B212300134 Petition for review of consolidated radon proceedings. Commission should grant financial assistance to intervenors, should reopen record on all issues & remand case for full consideration. Certificate of Svc encl.
JOHNSRUDD, J H Environmental Coalition on Nuclear Power 82/12/27
Commissioners 15pp 16598 112 24X Fiche 50-000, 82/12/27, B212300134

P Operating license stage documents & correspondence

B212100365 Requests verification that encl acceptance criteria for NUREG-0737, Item II K 3 22, "Automatic Switchover of RCIC Sys Section" satisfied. Response requested within 30 days.
STOLZ, J F Operating Reactors Branch 4 82/08/04 BAUER, E G
Philadelphia Electric Co 4pp 16389 193 24X
Fiche 50-277, 82/08/04, B212100365

B212080566 Requests participation, cooperation & support of NRC research project, "Task Analysis of Nuclear Power Plant Control Room Crews".
SCHWENCER, A Licensing Branch 2 82/11/09 DALTROFF, S L
Philadelphia Electric Co 2pp 16368 350 24X
Fiche 50-277, 82/11/09, B212080566

B2121230066 Generic Ltr 82-27 to all BHR licensees of operating reactors except LACBWR, Big Rock Point, Dresden 1, Humboldt Bay, applicants for QL & holders of CP re transmittal of NUREG-0763 & NUREG-0783 Svc list encl. W/o stated encl.
EISENHUT, D G Division of Licensing 82/11/15 General Public Utilities - OPU Service Corp 22pp 16387 004 24X
Fiche 50-000, 82/11/15, B2121230066

B212020036 Confirms B21119 telephone authorization amending Tech Spec for 1-time extension of 7-day limiting condition for operation re operability of RHR HX. Extension expires on B21124.
LAINAS, O C Assistant Director for Operating Reactors 82/11/23
BAUER, E G Philadelphia Electric Co 4pp 16308 329 24X
Fiche 50-278, 82/11/23, B212020036

B212090119 Forwards info re site geology, confirming telcon w/MD Fairtille.
DALTROFF, S L Philadelphia Electric Co 82/11/30 STOLZ, J F
Operating Reactors Branch 4 20pp 16357 243 24X
Fiche 50-277, 82/11/30, B212090119

B212060096 Forwards application to amend Licenses DPR-44 & DPR-56, changing surveillance requirements of Tech Specs to permit alternate method of performing core spray loop flow rate test.
BRADLEY, E J Philadelphia Electric Co 82/12/01 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 16314 345 24X
Fiche 50-277, 82/12/01, B212060096

--B212060106 Application to amend Licenses DPR-44 & DPR-56, changing surveillance requirements of Tech Specs to permit alternate method of performing core spray loop flow rate test.
BAUER, E G, BRADLEY, E J, DALTROFF, S L Philadelphia Electric Co 82/12/01 6pp 16314 346 24X Fiche 50-277, 82/12/01, B212060096

DOCKETED ITEMS

- B212060109 Proposed changes to surveillance requirements of Tech Specs to permit alternate method of performing core spray loop flow rate test
* Philadelphia Electric Co 82/12/01 4pp 16314 352 24X
Fiche 50-277,82/12/01,8212060096
- B212130211 Responds to NRC B21101 request for addl info re util B11001 response to Generic Ltr B1-04 concerning Revision 1 to NUREG-0313 Responses to Items 4,5d & 6d will be submitted no later than 821215
DALTROFF,S L Philadelphia Electric Co 82/12/03 STOLZ,J F
Operating Reactors Branch 4 13pp 16462 277 24X
Fiche 50-277,82/12/03,8212130211
- B212170094 "Manual Ultrasonic Exam of Pressure Piping Welds," Revision 59
WALKER,S Southwest Research Institute 81/11/30 38pp
16462 290 24X Fiche 50-277,82/12/03,8212130211
- B212170101 "Induction Heating Stress Improvement, Implementation Planning & Field Procedure Development," final rept
BERTOSSA,D C , FITZSIMMONS,M , ZSCHALER,W A General Electric Co
EPRI NP-2527-LD 82/08/31 19pp 16462 328 24X
Fiche 50-277,82/12/03,8212130211
- B212170111 "Residual Stress Improvement by Means of Induction Heating "
* Ishikawajima - Harima Heavy Industries Co.,Ltd EPRI
NP-B1-4-LD 81/03/31 354pp 16463 165 24X
Fiche 50-277,82/12/03,8212130211
- B212100075 Forwards amend to 821019 application for amend to License DPR-56 Amend changes dates required for insp of inaccessible pipe support hydraulic snubbers
BRADLEY,E J Philadelphia Electric Co 82/12/07 DENTON,H R
Office of Nuclear Reactor Regulation, Director 1p 16379 098 24X
Fiche 50-278,82/12/07,8212100075
- B212100079 Amend to 821019 application for amend to License DPR-56, changing dates required for insp of inaccessible pipe support hydraulic snubbers Certificate of Svc encl
BAUER,E O , BRADLEY,E J Philadelphia Electric Co 82/12/07
6pp 16379 099 24X Fiche 50-278,82/12/07,8212100079
- B212160531 Forwards Amend 86 to License DPR-56, safety evaluation & notice of issuance & availability Amend temporarily extends insp interval for two inaccessible hydraulic snubbers
GEARS,O E Operating Reactors Branch 4 82/12/07 BAUER,E O
Philadelphia Electric Co 3pp 16466 236 24X
Fiche 50-278,82/12/07,8212160531
- B212160544 Amend 86 to License DPR-56, temporarily extending insp interval for two inaccessible hydraulic snubbers
STOLZ,J F Operating Reactors Branch 4 82/12/07 4pp
16466 239 24X Fiche 50-278,82/12/07,8212160531
- B212160551 Safety evaluation supporting Amend 86 to License DPR-56
* Office of Nuclear Reactor Regulation, Director 82/12/07 2pp
16466 242 24X Fiche 50-278,82/12/07,8212160531
- B212160560 Notice of issuance & availability of Amend 86 to License DPR-56
STOLZ,J F Operating Reactors Branch 4 82/12/07 2pp
16466 245 24X Fiche 50-278,82/12/07,8212160531
- B212150058 Forwards amend to application to amend Licenses DPR-44 & DPR-56 Amend revises & updates list of shock suppressors proposed for inclusion in Tech Specs
BRADLEY,E J Philadelphia Electric Co 82/12/13 DENTON,H R
Office of Nuclear Reactor Regulation, Director 1p 16427 326 24X
Fiche 50-277,82/12/13,8212150058
- B212150062 Amend to application to amend Licenses DPR-44 & DPR-56, revising & updating list of shock suppressors proposed for inclusion in Tech Specs
BAUER,E O , BRADLEY,E J Philadelphia Electric Co 82/12/13
12pp 16427 327 24X Fiche 50-277,82/12/13,8212150058
- B212170315 Responds to NRC request for addl info on Mark I plant-unique analysis rept submitted on 820430 Results of torus attached piping sys analyses & questions re safety relief valve discharge piping will be addressed in addendum to rept
KEMPER,J S Philadelphia Electric Co. 82/12/14 STOLZ,J F.
Operating Reactors Branch 4 12pp 16493 193 24X
Fiche 50-277,82/12/14,8212170315
- B212210312 Endorses BWR owners group B10522 rept re NUREG-0737, Item 2 K 3 25 concerning consequences of loss of cooling water to reactor recirculation pump seal coolers, per 821028 request Rept results applicable to facilities
DALTROFF,S L Philadelphia Electric Co 82/12/14 EISENHUT,D O
Division of Licensing 2pp 16496 309 24X Fiche 50-277,82/12/14,8212210312
- B212170248 Identifies need for 3-month delay in schedule to replace gaseous chlorination sys w/liquid sodium hypochlorite sys, per NUREG-0737, Item III D 3 4, "Control Room Habitability Requirements "
DALTROFF,S L Philadelphia Electric Co 82/12/15 EISENHUT,D O
Division of Licensing 2pp 16459 203 24X Fiche 50-277,82/12/15,8212170248
- B212170265 Forwards application for amend to Licenses DPR-44 & DPR-56, revising Tech Specs re operability & surveillance requirements for scram discharge vol vent & drain isolation valves
BRADLEY,E J Philadelphia Electric Co 82/12/15 DENTON,H R
Office of Nuclear Reactor Regulation, Director 1p 16456 190 24X
Fiche 50-277,82/12/15,8212170265
- B212170275 Application to amend Licenses DPR-44 & DPR-56, revising Tech Specs re operability & surveillance requirements for scram discharge vol vent & drain isolation valves Certificate of Svc encl
* Philadelphia Electric Co 82/12/15 5pp 16456 191 24X
Fiche 50-277,82/12/15,8212170265
- B212170280 Revised Tech Spec tables re operability & surveillance requirements for scram discharge vol & drain isolation valves
* Philadelphia Electric Co 82/12/15 5pp 16456 196 24X
Fiche 50-277,82/12/15,8212170265
- B212170289 Forwards proprietary rept, "Induction Heating Stress Improvement for Stainless Steel Piping " Affidavit encl Rept withheld (ref 10CFR2 790)
DALTROFF,S L Philadelphia Electric Co 82/12/15 STOLZ,J F
Operating Reactors Branch 4 20pp 16456 033 24X
Fiche 50-277,82/12/15,8212170289
- B212230220 Forwards SER for environ qualification of safety-related electrical equipment Requests plans for Categories I B, II A & II B & schedule for proposed corrective actions within 90 days Technical evaluation encl Proprietary version withheld
STOLZ,J F Operating Reactors Branch 4 82/12/20 BAUER,E O
Philadelphia Electric Co 3pp 16512 020 24X
Fiche 50-277,82/12/20,8212230220
- B212230230 Safety evaluation supporting util compliance w/environ qualification of safety-related electrical equipment
* Office of Nuclear Reactor Regulation, Director 82/12/20 'pp
16512 023 24X Fiche 50-277,82/12/20,8212230220
- B212230250 Nonproprietary "Review of Licensee Resolution of Outstanding Issues From NRC Equipment Environ Qualification SERs (F-11 & D-60), Peach Bottom Atomic Power Stations Units 2 & 3, Vols 1 & 2," technical evaluation rept
CRANE,C J Franklin Institute/Franklin Research Center
NRC-03-79-118 TER-C5297-493 82/08/03 LE,N B , SHEMANSKI,P
NRC - No Detailed Affiliation Given 1,661pp 16512 028 24X
Fiche 50-277,82/12/20,8212230220
- B212270167 Verifies that acceptance criteria for mod providing automatic switchover of RCIC sys suction has been satisfied per NUREG-0737, Item II V 3 22 Mod completed on both units Emergency procedure provided for plant operators
DALTROFF,S L Philadelphia Electric Co 82/12/20 STOLZ,J F
Operating Reactors Branch 4 2pp 16538 345 24X
Fiche 50-277,82/12/20,8212270167
- B212270219 Documents conformance of analyses of Reload 5 lead test assemblies w/approved methods & criteria contained in NEDE-24011-P-A-4, "OE Std Application for Reactor Fuel " Description of assemblies withheld (ref 10CFR2 790)
DALTROFF,S L Philadelphia Electric Co 82/12/20 STOLZ,J F
Operating Reactors Branch 4 7pp 16536 266 24X
Fiche 50-278,82/12/20,8212270219
- B212290235 Clarifies program for implementation of NUREG-0737, Item II B 4 re training for mitigating core damage in response to 821208 meeting request Training for plant manager should be limited considering past experience & knowledge
DALTROFF,S L Philadelphia Electric Co 82/12/22 STOLZ,J F
Operating Reactors Branch 4 3pp 16582 170 24X
Fiche 50-277,82/12/22,8212290235
- B212280452 Informs of need for extension in implementation schedule for installation of new meteorological monitoring sys required by NUREG-0737, Item III A 2, due to structural deficiencies in weather tower Revised schedule expected by 830115
DALTROFF,S L Philadelphia Electric Co 82/12/23 EISENHUT,D O
Division of Licensing 2pp 16556 013 24X Fiche 50-277,82/12/23,8212280452

G Inspection Reports, IE Bulletins & Correspondence

B210190240 IE Bulletin B2-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel Recirculation Sys Piping at BWR Plants " Svc list encl
 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240

B210190245 IE Info Notice B2-42, "Defects Observed in Panasonic Model BQ1 & Model BQ2 Thermoluminescent Dosimeters " Svc list encl
 CQBBL, L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000, 82/11/05, 8208190245

B210190251 IE Info Notice B2-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl
 JORDAN, E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X Fiche 50-000, 82/11/18, 8208190251

B210190256 IE Info Notice B2-46, "Defective & Obsolete Combination Padlocks " Svc list encl
 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000, 82/11/26, 8208190256

B210190257 IE Info Notice B2-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl
 CQBBL, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000, 82/11/30, 8208190257

B210190259 IE Bulletin B2-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl
 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259

B210190261 IE Info Notice B2-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl
 JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X Fiche 50-000, 82/12/03, 8208190261

B212080314 Ack receipt of B21109 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-277/82-14 & 50-278/82-14
 STAROSTECKI, R Division of Project & Resident Programs 82/12/03 DALTROFF, S L Philadelphia Electric Co 1p 16353 350 24X Fiche 50-277, 82/12/03, 8212080314

--B212080323 Responds to NRC B20929 ltr re violations noted in IE Insp Repts 50-277/82-14 & 50-278/82-14 Corrective actions health physics personnel instructed to more forcefully check locked doors when performing surveillance test
 DALTROFF, S L Philadelphia Electric Co 82/11/09 STAROSTECKI, R Division of Project & Resident Programs 2pp 16353 351 24X Fiche 50-277, 82/12/03, 8212080314

B212160480 Forwards IE Insp Repts 50-277/82-16 & 50-278/82-16 on B21021-1130 & notice of violation
 STAROSTECKI, R Division of Project & Resident Programs 82/12/03 DALTROFF, S L Philadelphia Electric Co 2pp 16442 087 24X Fiche 50-277, 82/12/03, 8212160480

--B212160486 Notice of violation from insp on B21021-1130
 * Division of Project & Resident Programs 82/12/03 1p 16442 087 24X Fiche 50-277, 82/12/03, 8212160480

--B212160491 IE Insp Repts 50-277/82-16 & 50-278/82-16 on B21021-1130 Noncompliance noted failure to meet Tech Spec fire watch requirements
 BLOUGH, A R, MCCABE, E C Region 1, Office of Director 82/12/03 21pp 16442 090 24X Fiche 50-277, 82/12/03, 8212160480

B212210129 Forwards IE Safeguards Insp Repts 50-277/82-22 & 50-278/82-21 on B21018-22 No noncompliance noted
 MARTIN, T T Division of Engineering & Technical Programs 82/12/06 DALTROFF, S L Philadelphia Electric Co 2pp 16485 134 24X Fiche 50-277, 82/12/06, 8212210129

--B212210134 IE Safeguards Insp Repts 50-277/82-22 & 50-278/82-21 on B21018-22 No noncompliance noted Major areas inspected security plans & implementing procedures, security organization mgt & personnel Safeguards info deleted
 DUNLAP, J M, GDDY, A T Division of Engineering & Technical Programs 82/11/30 3pp 16485 136 24X Fiche 50-277, 82/12/06, 8212210129

B212100075 Forwards amend to B21019 application for amend to License DPR-56 Amend changes dates required for insp of inaccessible pipe support hydraulic snubbers
 BRADLEY, E J Philadelphia Electric Co 82/12/07 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 16379 098 24X Fiche 50-278, 82/12/07, 8212100075

--B212100079 Amend to B21019 application for amend to License DPR-56, changing dates required for insp of inaccessible pipe support hydraulic snubbers Certificate of Svc encl
 BAUER, E O, BRADLEY, E J Philadelphia Electric Co 82/12/07 6pp 16379 099 24X Fiche 50-278, 82/12/07, 8212100075

B212160531 Forwards Amend B6 to License DPR-56, safety evaluation & notice of issuance & availability Amend temporarily extends insp interval for two inaccessible hydraulic snubbers
 GEARS, O E Operating Reactors Branch 4 82/12/07 BAUER, E O Philadelphia Electric Co 3pp 16466 236 24X Fiche 50-278, 82/12/07, 8212160531

--B212160544 Amend B6 to License DPR-56, temporarily extending insp interval for two inaccessible hydraulic snubbers
 STOLZ, J F Operating Reactors Branch 4 82/12/07 4pp 16466 239 24X Fiche 50-278, 82/12/07, 8212160531

--B212160551 Safety evaluation supporting Amend B6 to License DPR-56
 * Office of Nuclear Reactor Regulation, Director 82/12/07 2pp 16466 243 24X Fiche 50-278, 82/12/07, 8212160531

--B212160560 Notice of issuance & availability of Amend B6 to License DPR-56
 STOLZ, J F Operating Reactors Branch 4 82/12/07 2pp 16466 245 24X Fiche 50-278, 82/12/07, 8212160531

B210190267 IE Info Notice B2-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16, 8208190267

B212220412 Advises that meeting will be arranged to discuss IE Info Notice B2-05, "Increasing Frequency of Drug-Related Incidents " List of topic areas to be discussed encl
 STAROSTECKI, R Division of Project & Resident Programs 82/12/16 DALTROFF, S L Philadelphia Electric Co 2pp 16503 354 24X Fiche 50-277, 82/12/16, 8212220412

B210190268 IE Info Notice B2-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27 " Svc list encl
 JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X Fiche 50-000, 82/12/20, 8208190268

H Periodic operating reports & related correspondence

B212020349 Forwards "Thermal Mapping Rept B2-7 for B21027 for Thermal Monitoring Requirements " Info covers isotherm surveys per App B ETG reporting requirements
 WILBEY, W B Philadelphia Electric Co 82/11/24 IPPOLITO, T A Operating Reactors Branch 3 1p 16278 005 24X Fiche 50-277, 82/11/24, 8212020349

--B212020352 "Thermal Mapping Rept B2-7 for B21027 for Thermal Monitoring Requirements "
 * Philadelphia Electric Co 82/11/24 4pp 16278 006 24X Fiche 50-277, 82/11/24, 8212020349

B212160095 Forwards monthly operating repts for Nov 1982
 COONEY, M J Philadelphia Electric Co 82/12/10 Director's Office, Office of Inspection and Enforcement 1p 16446 131 24X Fiche 50-277, 82/12/10, 8212160095

--B212160098 Monthly operating repts for Nov 1982
 ALDEN, N M Philadelphia Electric Co 82/12/10 9pp 16446 132 24X Fiche 50-277, 82/12/10, 8212160095

B212210158 Forwards Thermal Mapping Rept B2-B re isotherm surveys for B21117, in compliance w/App B to ETG
 WILBEY, W B Philadelphia Electric Co 82/12/15 IPPOLITO, T A Operating Reactors Branch 3 1p 16484 308 24X Fiche 50-277, 82/12/15, 8212210158

--B212210162 "Thermal Mapping Rept B2-B for B21117 for Thermal Monitoring Requirements "
 * Philadelphia Electric Co 82-8 82/11/19 4pp 16484 309 24X Fiche 50-277, 82/12/15, 8212210158

DOCKETED ITEMS

S Reportable occurrences, LERs & related correspondence

B212030205 Forwards LER B2-022/01T-0 Detailed event analysis submitted
COONEY, M J Philadelphia Electric Co 82/11/19 HAYNES, R C
Region 1, Office of Director 2pp 16304 033 24X
Fiche 50-278, 82/11/19, B212030205

--B212030208 LER B2-022/01T-0 on B21104, RHR HX leaked radioactive water
into intake structure via high pressure svc water piping on
B21025-1102 Caused by leak between inner floating head &
drain connector HK repaired
COONEY, M J Philadelphia Electric Co 82/11/19 Region 1,
Office of Director 1p 16304 036 24X Fiche 50-278, 82/11/19,
B212030205

DOCKET 50-280 SURRY POWER STATION, UNIT 1

F Security, medical, emergency & fire protection plans

B212060138 Forwards supplemental SER addressing open items re App R,
including approval of proposed mod concerning relocation of
one charging pump, svc water pump & respective water source
facility in compliance w/App R requirements
VARGA, S A Operating Reactors Branch 1 82/11/18 STEWART, W L
Virginia Electric & Power Co 7pp 16325 355 24X
Fiche 50-280, 82/11/18, B212060138

B212060338 Grants requested exemption from requirement of App R Section
III G to 10CFR50 re installation of fixed fire suppression
sys in control room
VARGA, S A Operating Reactors Branch 1 82/11/24 STEWART, W L
Virginia Electric & Power Co 2pp 16323 345 24X
Fiche 50-280, 82/11/24, B212060338

--B212060339 Exemptions from requirement of App R Section III G to
10CFR50 re installation of fixed fire suppression sys in
control room
EISENHUT, D O Division of Licensing 82/11/24 Virginia
Electric & Power Co 3pp 16323 347 24X Fiche 50-280, 82/11/24,
B212060338

B212060303 Application for amend to Licenses DPR-32 & DPR-37 Amend
revises Tech Specs re hours staff will be performing
safety-related functions & audit frequency of station
emergency plan
STEWART, W L Virginia Electric & Power Co 82/12/01 DENTON, H K
Office of Nuclear Reactor Regulation, Director VARGA, S A
Operating Reactors Branch 1 2pp 16312 112 24X
Fiche 50-280, 82/12/01, B212060303

--B212060315 Proposed Tech Spec changes re hours staff will be
performing safety-related functions & audit frequency of
station emergency plan
* Virginia Electric & Power Co 82/12/01 5pp 16312 114 24X
Fiche 50-280, 82/12/01, B212060303

B212090166 Ack receipt of B21008 & 1117 ltrs informing NRC of steps
taken to correct violations noted in IE Safeguards Insp
Repts 50-280/82-23 & 50-281/82-23
LEWIS, R C Division of Project & Resident Programs 82/12/06
STEWART, W L Virginia Electric & Power Co 2pp 16359 236 24X
Fiche 50-280, 82/12/06, B212090166

--B212090169 Forwards supplemental response to B21008 ltr re B20908 IE
Safeguards Insp Repts 50-280/82-23 & 50-281/82-23 Response
withheld (ref 10CFR73 21)
STEWART, W L Virginia Electric & Power Co 82/11/17
O'REILLY, J P Region 2, Office of Director 1p 16359 238 24X
Fiche 50-280, 82/12/06, B212090166

--B212090175 Responds to NRC B20908 ltr re violations noted in IE Insp
Repts 50-280/82-23 & 50-281/82-23 Corrective actions
withheld (ref 10CFR73 21)
LEASBURG, R H Virginia Electric & Power Co 82/10/08
O'REILLY, J P Region 2, Office of Director 1p 16359 239 24X
Fiche 50-280, 82/12/06, B212090166

--B212090180 Forwards IE Safeguards Insp Repts 50-280/82-23 & 50-281/
82-23 on B20816-20 & notice of violation Notice of violation
& rpt details withheld (ref 10CFR73 21)
LEWIS, R C Division of Project & Resident Programs 82/09/08
LEASBURG, R H Virginia Electric & Power Co 2pp 16359 240 24X
Fiche: 50-280, 82/12/06, B212090166

--B212090185 IE Safeguards Insp Repts 50-280/82-23 & 50-281/82-23 on
B20816-20 Noncompliance noted failure to control access to
defensive position & to equip personnel w/communication
devices for vital areas Details withheld (ref 10CFR73 21)
MOORE, D E, MCQUIRE, D R Division of Engineering & Technical
Programs 82/09/03 2pp 16359 242 24X Fiche 50-280, 82/12/06,
B212090166

B212090419 Forwards addl info re status of emergency response
facilities locations & const, supplementing B10601 & B20408
responses to Generic Ltr 81-10 transmitting NUREG-0696, per
request
STEWART, W L Virginia Electric & Power Co 82/12/06 DENTON, H K
Office of Nuclear Reactor Regulation, Director 2pp 16364 2/6
24X Fiche 50-000, 82/12/06, B212090419

B212150059 Forwards revised security drawings Drawings withheld
(ref 10CFR2 790)
STEWART, W L Virginia Electric & Power Co 82/12/09 DENTON, H K
Office of Nuclear Reactor Regulation, Director VARGA, S A
Operating Reactors Branch 1 1p 16427 362 24X
Fiche 50-000, 82/12/09, B212150059

B212170036 Releases public version of revised emergency plan
implementing procedure
FELTON, J M Division of Rules and Records 82/12/10 Document
Management Branch 1p 16478 003 24X Fiche 50-280, 82/12/10,
B212170036

--B212170041 Forwards public version of Revision 1 to Emergency Plan
Implementing Procedure EPIP-1 Of, "Emergency Manager
Controlling Procedure"
STEWART, W L Virginia Electric & Power Co 82/12/01
O'REILLY, J P Region 2, Office of Director 1p 16478 004 24X
Fiche 50-280, 82/12/10, B212170036

--B212170044 Public version of Revision 1 to Emergency Plan Implementing
Procedure EPIP-1 Of, "Emergency Manager Controlling
Procedure"
COA, F H, SAUNDERS, R T Virginia Electric & Power Co 82/11/18
3pp 16478 005 24X Fiche 50-280, 82/12/10, B212170036

B21220281 Responds to util B21028 ltr re Revision 7 to security
program Revision consistent w/10CFR50 54(a) provisions &
acceptable Encl to B21028 ltr withheld (ref 10CFR73 21)
VARGA, S A Operating Reactors Branch 1 82/12/10 STEWART, W L
Virginia Electric & Power Co 2pp 16523 307 24X
Fiche 50-280, 82/12/10, B21220281

B21220481 Forwards draft SER re App R exemption requests Justification
that level of protection afforded by existing fire
protection measures in emergency switch gear rooms
equivalent to App R requirements not provided
VARGA, S A Operating Reactors Branch 1 82/12/10 STEWART, W L
Virginia Electric & Power Co 7pp 16523 192 24X
Fiche 50-280, 82/12/10, B21220481

B212170024 Forwards request for addl info re security training &
qualification plans, per util B20917 ltr
CLARK, R A Operating Reactors Branch 3 82/12/13 STEWART, W L
Virginia Electric & Power Co 4pp 16480 335 24X
Fiche 50-000, 82/12/13, B212170024

B212170494 Releases public version of revised local govt radiological
emergency response plans
FELTON, J M Division of Rules and Records 82/12/13 Document
Management Branch 1p 16479 142 24X Fiche 50-280, 82/12/13,
B212170454

--B212170457 Forwards public version of revised local govt radiological
emergency response plans for Counties of Surry, Isle of
Wight, York & James City & Cities of Newport News &
Williamsburg, VA
STEWART, W L Virginia Electric & Power Co 82/12/01
O'REILLY, J P Region 2, Office of Director 1p 16479 144 24X
Fiche 50-280, 82/12/13, B212170454

--B212170458 Public version of revised local govt radiological emergency
response plans for Counties of Surry, Isle of Wight, York
& James City & Cities of Newport News & Williamsburg, VA
* Virginia Electric & Power Co 82/11/30 22pp 16479 145
24X Fiche 50-280, 82/12/13, B212170454

B212300195 Responds to B21013 ltr re protection of safeguards info safe
acceptable, provided that safe located within protected area
VARGA, S A Operating Reactors Branch 1 82/12/15 STEWART, W L
Virginia Electric & Power Co 2pp 16612 329 24X
Fiche 50-280, 82/12/15, B212300195

B212270179 Informs that although B21209 ltr forwarding security
drawings failed to contain safeguards statement, drawings
were properly secured, marked & identified as safeguards
info.
STEWART, W L Virginia Electric & Power Co 82/12/20 DENTON, H K
Office of Nuclear Reactor Regulation, Director VARGA, S A
Operating Reactors Branch 1 1p 16539 010 24X
Fiche 50-000, 82/12/20, B212270179

P Operating license stage documents & correspondence

B212060134 Forwards response to NRC B21026 questionnaire re steam generator tube integrity Data for each facility compiled in separate sections
STEWART, W L Virginia Electric & Power Co 82/12/01 DENTON, H R
Office of Nuclear Reactor Regulation, Director EISENHUT, D O
Division of Licensing 5pp 16314 070 24X Fiche 50-000, 82/12/01, 8212060134

B212060284 Notifies that neither facility has addl Tech Specs to be submitted in response to Generic Ltr 82-16 re status of NUREG-0737 items
STEWART, W L Virginia Electric & Power Co 82/12/01 DENTON, H R
Office of Nuclear Reactor Regulation, Director EISENHUT, D O
Division of Licensing 1p 16312 058 24X Fiche 50-000, 82/12/01, 8212060284

GP12060303 Application for amend to Licenses DPR-32 & DPR-37 Amend revises Tech Specs re hours staff will be performing safety-related functions & audit frequency of station emergency plan
STEWART, W L Virginia Electric & Power Co 82/12/01 DENTON, H R
Office of Nuclear Reactor Regulation, Director EISENHUT, D O
Operating Reactors Branch 1 2pp 16312 112 24X
Fiche 50-280, 82/12/01, 8212060303

--B212060315 Proposed Tech Spec changes re hours staff will be performing safety-related functions & audit frequency of station emergency plan
* Virginia Electric & Power Co 82/12/01 5pp 16312 114 24X
Fiche 50-280, 82/12/01, 8212060303

B212100012 Advises that Generic Issue D-24 re containment purge & INI Item II E 4 2 re containment isolation dependability complete Summary of review listed Tech Specs will be issued separately
VARQA, S A Operating Reactors Branch 1 82/12/07 STEWART, W L
Virginia Electric & Power Co 3pp 16399 235 24X
Fiche 50-280, 82/12/07, 8212100012

B208190263 Generic Ltr 82-32 to all PWR licensees re potential steam generator-related generic requirements Forwards Science Applications, Inc draft rept re subj requirements Comments requested within 30 days of ltr Svc list encl
EISENHUT, D O Division of Licensing 82/12/09 Consolidated
Edison Co of New York, Inc 29pp 16669 247 24X
Fiche 50-000, 82/12/09, 8208190263

B212140103 Generic Ltr 82-28 to all licensees of operating Westinghouse & C-E PWRs (except Arkansas Nuclear One, Unit 2 & San Onofre 2 & 3) re inadequate core cooling instrumentation sys Svc list encl
EISENHUT, D O Division of Licensing 82/12/10 Yankee Atomic
Electric Co 27pp 16690 035 24X Fiche 50-000, 82/12/10, 8212140103

B212280257 Forwards remittance for Invoice D-0063 for review of Amend A to Topical Rept VEP-1, "QA Program - Operations Phase," submitted on 820921 & approved on 821006
STEWART, W L Virginia Electric & Power Co 82/12/22 DENTON, H R
Office of Nuclear Reactor Regulation, Director BARRY, L W Division
of Accounting 1p 16561 269 24X Fiche 50-000, 82/12/22, 8212280257

B212290191 Forwards Class II fee to cover review of 821201 suppl to amend Licenses DPR-32 & DPR-37
STEWART, W L Virginia Electric & Power Co 82/12/22 DENTON, H R
Office of Nuclear Reactor Regulation, Director VARQA, S A
Operating Reactors Branch 1 1p 16561 042 24X
Fiche 50-280, 82/12/22, 8212290191

B212290191 Informs that completion date, per 820823 supplemental response to Generic Ltr 82-05, "Post-Accident Sampling Sys," will be extended to 830601 Status rept expected in Mar 1983
STEWART, W L Virginia Electric & Power Co 82/12/27 DENTON, H R
Office of Nuclear Reactor Regulation, Director EISENHUT, D O
Division of Licensing 3pp 16578 052 24X Fiche 50-280, 82/12/27, 8212290191

Q Inspection reports, IE Bulletins & correspondence

B212090267 Forwards IE Insp Repts 50-280/82-26 & 50-281/82-26 on 821004-08 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 82/10/26
LEASBURG, R H Virginia Electric & Power Co 2pp 16362 301 24X
Fiche 50-280, 82/10/26, 8212090267

--B212090277 IE Insp Repts 50-280/82-26 & 50-281/82-26 on 821004-08 No noncompliance noted Major areas inspected pipe supports & restraints & Type B & C containment leakage rate testing
BROOKS, E H, JAPE, F Division of Project & Resident Programs
82/10/25 4pp 16362 303 24X Fiche 50-280, 82/10/26, 8212090267

B208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc
112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240

B212090285 Advises that SALP Repts 50-280/82-19, 50-281/82-19, 50-338/82-24 & 50-339/82-24 have been reviewed & approved
Overall performance adequate No reply required
O'REILLY, J P Region 2, Office of Director 82/11/03
LEASBURG, R H Virginia Electric & Power Co 2pp 16365 208 24X
Fiche 50-000, 82/11/03, 8212090285

--B212090298 Forwards SALP Repts 50-280/82-19, 50-281/82-19, 50-338/82-24 & 50-339/82-24 for Jul 1980-June 1981
LEWIS, R C Division of Project & Resident Programs 82/08/04
LEASBURG, R H Virginia Electric & Power Co 2pp 16365 210 24X
Fiche 50-000, 82/11/03, 8212090285

--B212090306 SALP Repts 50-280/82-19, 50-281/82-19, 50-338/82-24 & 50-339/82-24 for Jul 1980-June 1981 Increased mgt attention should be directed towards plant operations & operational QA
* Region 2, Office of Director 82/08/04 31pp 16365 212 24X
Fiche 50-000, 82/11/03, 8212090285

B208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards
82/11/05 Consolidated Edison Co of New York, Inc 110pp
16372 142 24X Fiche 50-000, 82/11/05, 8208190245

B208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18
Consolidated Edison Co of New York, Inc 109pp 16411 199 24X
Fiche 50-000, 82/11/18, 8208190251

B212090276 Ack receipt of B21029 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-280/82-24 & 50-281/82-24
DANCE, H C Division of Project & Resident Programs 82/11/18
STEWART, W L Virginia Electric & Power Co 1p 16365 270 24X
Fiche 50-280, 82/11/18, 8212090276

--B212090286 Responds to NRC 820929 ltr re violations noted in IE Insp Repts 50-280/82-24 & 50-281/82-24 Corrective actions valve pit roofs covered w/fire retardant plastic & sealed
STEWART, W L Virginia Electric & Power Co 82/10/29
O'REILLY, J P Region 2, Office of Director 3pp 16365 271 24X
Fiche 50-280, 82/11/18, 8212090276

--B212090300 Forwards IE Insp Repts 50-280/82-24 & 50-281/82-24 on 820802-0903 & notice of violation
DANCE, H C Division of Project & Resident Programs 82/09/29
LEASBURG, R H Virginia Electric & Power Co 2pp 16365 274 24X
Fiche 50-280, 82/11/18, 8212090276

--B212090304 Notice of violation from insp on 820802-0903
* Division of Project & Resident Programs 82/09/29 1p
16365 276 24X Fiche 50-280, 82/11/18, 8212090276

--B212090313 IE Insp Repts 50-280/82-24 & 50-281/82-24 on 820802-0903 Noncompliance noted roof leak caused by previous maint work degraded safety-related equipment
BURKE, D J, DAVIS, M J, ORDERS, W J Division of Project & Resident Programs 82/09/28 9pp 16365 277 24X Fiche 50-280, 82/11/18, 8212090276

B212090215 Ack receipt of 820716 & 1105 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-280/82-10 & 50-281/82-10
DANCE, H C Division of Project & Resident Programs 82/11/19
STEWART, W L Virginia Electric & Power Co 1p 16362 279 24X
Fiche 50-280, 82/11/19, 8212090215

--B212090217 Responds to NRC 820607 ltr re violations noted in IE Insp Repts 50-280/82-10 & 50-281/82-10 Corrective actions Administrative Procedure 56 re ignition sources amended to classify areas for purposes of controlling sources
STEWART, W L Virginia Electric & Power Co 82/11/05
O'REILLY, J P Region 2, Office of Director 2pp 16362 280 24X
Fiche 50-280, 82/11/19, 8212090215

--B212090218 Responds to NRC 820607 ltr re violations noted in IE Insp Repts 50-280/82-10 & 50-281/82-10 Corrective actions process vent sys mod designed & Administrative Procedure 56 amended re safety-related areas
LEASBURG, R H Virginia Electric & Power Co 82/07/16
O'REILLY, J P Region 2, Office of Director 4pp 16362 282 24X
Fiche 50-280, 82/11/19, 8212090215

DOCKETED ITEMS

--B212090220 Confirms telcon re IE Insp Repts 50-280/82-10 & 50-281/82-10 Response will be submitted by 820717
LEASBURG, R H Virginia Electric & Power Co 82/07/06
O'REILLY, J P Region 2, Office of Director 1p 16362 286 24X
Fiche 50-280, 82/11/19, 8212090215

--B212090223 Forwards IE Insp Repts 50-280/82-10 & 50-281/82-10 on 820401-30 & notice of violation
DANCE, H C Division of Project & Resident Programs 82/06/07
LEASBURG, R H Virginia Electric & Power Co 2pp 16362 287 24X
Fiche 50-280, 82/11/19, 8212090215

--B212090226 Notice of violation from insp on 820401-30
+ Division of Project & Resident Programs 82/06/07 2pp
16362 287 24X Fiche 50-280, 82/11/19, 8212090215

--B212090234 IE Insp Repts 50-280/82-10 & 50-281/82-10 on 820401-30
Noncompliance noted failure to follow fire protection
program implementing procedures
BURKE, D J, DAVIS, M J, JULIAN, C A Division of Project & Resident
Programs 82/06/04 10pp 16362 291 24X Fiche 50-280, 82/11/19,
8212090215

8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination
Padlocks," Svc list encl
DEVOUNO, R C Director's Office, Office of Inspection and
Enforcement 82/11/26 Consolidated Edison Co of New York, Inc
127pp 16411 045 24X Fiche 50-000, 82/11/26, 8208190256

8208190257 IE Info Notice 82-47, "Transportation of Type A Quantities
of Non-Fissile Radioactive Matl," Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards
82/11/30 Consolidated Edison Co of New York, Inc 354pp
16367 028 24X Fiche 50-000, 82/11/30, 8208190257

8212290060 Partial response to FOIA request for seven categories of
info Forwards documents listed in App A Documents 1 & 2
already in PDR App B documents available in PDR LPDR
profiles for Olmeca & Indian Point 3 encl
FELTON, J H Division of Rules and Records 82/11/30
SCHLESSEL, D A New York, State of 7pp 16607 239 24X
Fiche 50-000, 82/11/30, 8212290060

--B212290170 Ack receipt of 761204 ltr informing NRC of steps taken to
correct violation noted in IE Insp Repts 50-280/76-14 &
50-281/76-14
LONG, F J Region 2, Atlanta, Reactor Operations Nuclear Support
Branch 77/01/14 PROFFITT, W L Virginia Electric & Power Co
1p 16608 041 24X Fiche 50-000, 82/11/30, 8212290060

--B212290172 Responds to NRC 761021 ltr re violation noted in IE Insp
Repts 50-280/76-14 & 50-281/76-14 Corrective actions
Administrative Procedure 29 redistributed & importance of
proper documentation practices emphasized
STALLINGS, C M Virginia Electric & Power Co 76/12/06
MOSELEY, N C Region 2, Atlanta, Office of the Director 4pp
16608 042 24X Fiche 50-000, 82/11/30, 8212290060

--B212290178 Forwards IE Insp Repts 50-280/76-14 & 50-281/76-14 on
760915-17 Noncompliance noted
LONG, F J Region 2, Atlanta, Reactor Operations Nuclear Support
Branch 76/10/21 PROFFITT, W L Virginia Electric & Power Co
2pp 16608 046 24X Fiche 50-000, 82/11/30, 8212290060

--B212290184 IE Insp Repts 50-280/76-14 & 50-281/76-14 on 760915-17
Noncompliance noted failure to follow log book entry &
review & initial requirements specified in Administrative
Procedure 29
SINKULE, M V, LEWIS, R C, ROGERS, R F Region 2, Atlanta, Reactor
Operations Nuclear Support Branch 76/10/19 13pp 16608 048
24X Fiche 50-000, 82/11/30, 8212290060

8208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment
Electrical Penetration Assemblies," Svc list encl
DEVOUNO, R C Director's Office, Office of Inspection and
Enforcement 82/12/03 Consolidated Edison Co of New York, Inc
113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259

8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay
Buckets," Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03
Consolidated Edison Co of New York, Inc 110pp 16462 044 24X
Fiche 50-000, 82/12/03, 8208190261

8212090166 Ack receipt of 821008 & 1117 ltrs informing NRC of steps
taken to correct violations noted in IE Safeguards Insp
Repts 50-280/82-23 & 50-281/82-23
LEWIS, R C Division of Project & Resident Programs 82/12/06
STEWART, W L Virginia Electric & Power Co 2pp 16359 236 24X
Fiche 50-280, 82/12/06, 8212090166

--B212090169 Forwards supplemental response to 821008 ltr re 820908 IE
Safeguards Insp Repts 50-280/82-23 & 50-281/82-23 Response
withheld (ref 10CFR73.21)
STEWART, W L Virginia Electric & Power Co 82/11/17
O'REILLY, J P Region 2, Office of Director 1p 16359 238 24X
Fiche 50-280, 82/12/06, 8212090166

--B212090175 Responds to NRC 820908 ltr re violations noted in IE Insp
Repts 50-280/82-23 & 50-281/82-23 Corrective actions
withheld (ref 10CFR73.21)
LEASBURG, R H Virginia Electric & Power Co 82/10/08
O'REILLY, J P Region 2, Office of Director 1p 16359 239 24X
Fiche 50-280, 82/12/06, 8212090166

--B212090180 Forwards IE Safeguards Insp Repts 50-280/82-23 & 50-281/
82-23 on 820816-20 & notice of violation Notice of violation
& rept details withheld (ref 10CFR73.21)
LEWIS, R C Division of Project & Resident Programs 82/09/08
LEASBURG, R H Virginia Electric & Power Co 2pp 16359 240 24X
Fiche 50-280, 82/12/06, 8212090166

--B212090185 IE Safeguards Insp Repts 50-280/82-23 & 50-281/82-23 on
820816-20 Noncompliance noted failure to control access to
defensive position & to equip personnel w/communication
devices for vital areas Details withheld (ref 10CFR73.21)
MOORE, D E, MCQUIRE, D R Division of Engineering & Technical
Programs 82/09/03 2pp 16359 242 24X Fiche 50-280, 82/12/06,
8212090166

8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for
Air & Gas Monitoring," Svc list encl
DEVOUNO, R C Director's Office, Office of Inspection and
Enforcement 82/12/16 Consolidated Edison Co of New York, Inc
127pp 16628 191 24X Fiche 50-000, 82/12/16, 8208190267

8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage
Relays Type ITE-27," Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/10
Consolidated Edison Co of New York, Inc 108pp 16628 293 24X
Fiche 50-000, 82/12/20, 8208190268

8212290261 Forwards Revision 1 to inservice insp program
STEWART, W L Virginia Electric & Power Co 82/12/27 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 16587 106
24X Fiche 50-280, 82/12/27, 8212290261

--B212290264 Inservice insp program, Revision 1
STEWART, W L Virginia Electric & Power Co 82/12/27 263pp
16587 107 24X Fiche 50-280, 82/12/27, 8212290261

R Periodic operating reports & related correspondence

8212290238 Forwards monthly operating repts for Oct 1982 & corrected
page to monthly operating rept for Sept 1982 w/o corrected
page
STEWART, W L Virginia Electric & Power Co 82/11/15 HALLER, N M
Office of Resource Management, Director 1p 16582 116 24X
Fiche 50-280, 82/11/15, 8212290238

--B212290244 Monthly operating repts for Oct 1982
JONES, V Virginia Electric & Power Co 82/11/03 52pp
16582 117 24X Fiche 50-280, 82/11/15, 8212290238

S Reportable occurrences, LERs & related correspondence

8212020090 Forwards LER 82-121/03L-0
WILSON, J L Virginia Electric & Power Co 82/11/24 O'REILLY, J P
Region 2, Office of Director 1p 16272 022 24X
Fiche 50-280, 82/11/24, 8212020090

--B212020096 LER 82-121/03L-0 on 821026, alarm setpoint for liquid waste
monitor RM-LW-108 exceeded allowable Tech Spec limits Caused
by instrument drift Operator took administrative control for
high alarm isolation Monitor recalibr
WILSON, J L Virginia Electric & Power Co 82/11/24 Region 2,
Office of Director 2pp 16272 023 24X Fiche 50-280, 82/11/24,
8212020090

8212090096 Forwards LERs 82-110/03L-0 & 82-060/03L-0
WILSON, J L Virginia Electric & Power Co 82/11/30 O'REILLY, J P
Region 2, Office of Director 1p 16357 180 24X
Fiche 50-280, 82/11/30, 8212090096

--B212090091 LER 82-110/03L-0 on 821104 & 18, specific activity samples
of RCS indicated dose equivalent 1-131 level greater than
Tech Specs Caused by fuel element defect in reactor core
Sampling frequency implemented until level decreased
WILSON, J L Virginia Electric & Power Co 82/11/30 Region 2,
Office of Director 4pp 16357 181 24X Fiche 50-280, 82/11/30,
8212090096

--B212090098 LER 82-060/03L-0 on 821102, charging pump svc water pump 2-SH-P-10B experienced loss of suction pressure Caused by insufficient NPSH Pump vented to restore NPSH
WILSON, J L Virginia Electric & Power Co 82/11/30 Region 2,
Office of Director 3pp 16337 185 24X Fiche 50-280, 82/11/30,
8212090086

B212290060 Partial response to FOIA request for seven categories of info Forwards documents listed in App A Documents 1 & 2 already in PDR App B documents available in PDR LPDR profiles for Ginna & Indian Point 3 encl
FELTON, J M Division of Rules and Records 82/11/30
SCHLESSEL, D A New York, State of 7pp 16607 239 24X
Fiche 50-000, 82/11/30, 8212290060

--B212290069 RO 76-12 on 760909, low pressure alarm occurred on safety injection accumulator C, resulting in pressure reduction Caused by partially open HCV 1936 & body to bonnet leaks on HCV 1898 & 1549 Valves repaired & accumulator repressurized
STALLINGS, C M Virginia Electric & Power Co 76/10/01
MOSELEY, N C Region 2, Atlanta, Office of the Director 5pp
16607 263 24X Fiche 50-000, 82/11/30, 8212290060

--B212290075 RO 76-13 on 760916, normal boric acid makeup to vol control tank could not be accomplished due to plugging of chemical & vol control sys line 1-inch-CH-56-152 Cause unknown Line will be inspected for indications of solidification
STALLINGS, C M Virginia Electric & Power Co 76/10/20
MOSELEY, N C Region 2, Atlanta, Office of the Director 5pp
16607 267 24X Fiche 50-000, 82/11/30, 8212290060

--B212290080 RO 76-07 on 760913, monthly average of gaseous & airborne particulate wastes for previous 12 months found greater than Tech Spec limit Caused by interpretational changes in Tech Spec Section 3.11 B New limit approved
STALLINGS, C M Virginia Electric & Power Co 76/09/24
MOSELEY, N C Region 2, Atlanta, Office of the Director 5pp
16607 273 24X Fiche 50-000, 82/11/30, 8212290060

B212210365 Forwards LERs 82-070/03L-0, 82-113/03L-0 & 82-116/03L-0
WILSON, J L Virginia Electric & Power Co 82/12/13 O'REILLY, J P
Region 2, Office of Director 1p 16494 278 24X
Fiche 50-280, 82/12/13, 8212210365

--B212210383 LER 82-070/03L-0 on 821119, routine walkdown of svc bldg revealed open barrier penetration w/no fire watch posted Caused by removal of temporary seal on penetration Fire watch posted Penetration resealed
WILSON, J L Virginia Electric & Power Co 82/12/13 Region 2,
Office of Director 2pp 16494 279 24X Fiche 50-280, 82/12/13,
8212210385

--B212210388 LER 82-113/03L-0 on 821121, radiation monitor recorder found inoperable Caused by slipped drive cable Drive cable reinstalled & recorder returned to svc
WILSON, J L Virginia Electric & Power Co 82/12/13 Region 2,
Office of Director 2pp 16494 281 24X Fiche 50-280, 82/12/13,
8212210385

--B212210397 LER 82-116/03L-0 on 821113, containment spray chemical addition tank level decreased below Tech Spec limit Caused by loss of vol due to leakage past manual isolation valve during maint Valve torqued shut Tank refilled
WILSON, J L Virginia Electric & Power Co 82/12/13 Region 2,
Office of Director 3pp 16494 283 24X Fiche 50-280, 82/12/13,
8212210385

B212280126 Forwards LERs 82-105/03L-0, 82-117/03L-0 & 82-072/03L-0
WILSON, J L Virginia Electric & Power Co 82/12/17 O'REILLY, J P
Region 2, Office of Director 1p 16562 306 24X
Fiche 50-280, 82/12/17, 8212280126

--B212280140 LER 82-105/03L-0 on 821123, amplifier reading for heat tracing panel 7, circuit 7A, fell below acceptance criteria On 821126, low reading detected for panel 8 Caused by excessive heat Defective heat tracing replaced & tested
WILSON, J L Virginia Electric & Power Co 82/12/17 Region 2,
Office of Director 2pp 16562 307 24X Fiche 50-280, 82/12/17,
8212280126

--B212280152 LER 82-117/03L-0 on 821129, specific activity samples of RCB indicated dose equivalent I-131 level greater than Tech Spec limit Caused by fuel element defect in reactor core Accelerated sampling frequency implemented
WILSON, J L Virginia Electric & Power Co 82/12/17 Region 2,
Office of Director 3pp 16562 309 24X Fiche 50-280, 82/12/17,
8212280126

--B212280206 LER 82-072/03L-0 on 821126, amplifier readings heat tracing panel 11, circuit 2A, fell below acceptance criteria Caused by overheating due to maladjusted thermostat Defective heat tracing replaced & tested
WILSON, J L Virginia Electric & Power Co 82/12/17 Region 2,
Office of Director 2pp 16562 312 24X Fiche 50-280, 82/12/17,
8212280126

Y Dry Cask Independent Spent Fuel Storage Installations

B212220170 Advises that application for dry cask ISFSI docketed on 821015 Application evaluated for completeness & acceptability Details of cask must be provided to NH Division before licensing action can be completed
ROUSE, L C Advanced Fuel & Spent Fuel Licensing Branch 82/12/03
LEASBURG, R H Virginia Electric & Power Co 2pp 16323 361 24X
Fiche 50-280, 82/12/03, 8212220170

B212220005 Forwards notice of consideration of matl license for storage of spent fuel transmitted to Ofc of FR for publication
ROUSE, L C Advanced Fuel & Spent Fuel Licensing Branch 82/12/06
LEASBURG, R H Virginia Electric & Power Co 2pp 16529 144 24X
Fiche 50-280, 82/12/06, 8212220005

--B212220007 Notice of consideration of matl license for storage of spent fuel
ROUSE, L C Advanced Fuel & Spent Fuel Licensing Branch 82/12/03
4pp 16529 146 24X Fiche 50-280, 82/12/06, 8212220005

B212230147 Notice of correction of typographical error in 821209 FR notice re consideration of matl license for storage of spent fuel
ROUSE, L C Advanced Fuel & Spent Fuel Licensing Branch 82/12/10
2pp 16544 036 24X Fiche 50-280, 82/12/10, 8212230147

DOCKET 50-281 SURRY POWER STATION, UNIT 2

F Security, medical, emergency & fire protection plans

B212060138 Forwards supplemental SER addressing open items re App R, including approval of proposed mod concerning relocation of one charging pump, svc water pump & respective water source Facility in compliance w/App R requirements
VARGA, S A Operating Reactors Branch 1 82/11/18 STEWART, W L
Virginia Electric & Power Co 7pp 16325 355 24X
Fiche 50-280, 82/11/18, 8212060138

B212060338 Grants requested exemption from requirement of App R Section III G to 10CFR50 re installation of fixed fire suppression sys in control room
VARGA, S A Operating Reactors Branch 1 82/11/24 STEWART, W L
Virginia Electric & Power Co 2pp 16323 345 24X
Fiche 50-280, 82/11/24, 8212060338

--B212060339 Exemptions from requirement of App R Section III G to 10CFR50 re installation of fixed fire suppression sys in control room
EISENHUT, D O Division of Licensing 82/11/24 Virginia
Electric & Power Co 3pp 16323 347 24X Fiche 50-280, 82/11/24,
8212060338

B212060303 Application for amend to Licenses DPR-32 & DPR-37 Amend revises Tech Specs re hours staff will be performing safety-related functions & audit frequency of station emergency plan
STEWART, W L Virginia Electric & Power Co 82/12/01 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 16312 112
24X Fiche 50-280, 82/12/01, 8212060303

--B212060315 Proposed Tech Spec changes re hours staff will be performing safety-related functions & audit frequency of station emergency plan
* Virginia Electric & Power Co 82/12/01 5pp 16312 114 24X
Fiche 50-280, 82/12/01, 8212060303

B212090166 Ack receipt of 821008 & 1117 ltrs informing NRC of steps taken to correct violations noted in IE Safeguards Insp Repts 50-280/82-23 & 50-281/82-23
LEWIS, R C Division of Project & Resident Programs 82/12/06
STEWART, W L Virginia Electric & Power Co 2pp 16359 236 24X
Fiche 50-280, 82/12/06, 8212090166

--B212090169 Forwards supplemental response to 821008 ltr re B20908 IE Safeguards Insp Repts 50-280/82-23 & 50-281/82-23 Response withheld (ref 10CFR73.21)
STEWART, W L Virginia Electric & Power Co 82/11/17
O'REILLY, J P Region 2, Office of Director 1p 16359 238 24X
Fiche 50-280, 82/12/06, 8212090166

DOCKETED ITEMS

- 8212090175 Responds to NRC 820908 ltr re violations noted in IE Insp Repts 50-280/82-23 & 50-281/82-23 Corrective actions withheld (ref 10CFR73 21)
LEFSBURG, R H Virginia Electric & Power Co 82/10/08
O'REILLY, J P Region 2, Office of Director 1p 16359 239 24X
Fiche 50-280, 82/12/06, 8212090166
- 8212090180 Forwards IE Safeguards Insp Repts 50-280/82-23 & 50-281/82-23 on 820816-20 & notice of violation Notice of violation & rept details withheld (ref 10CFR73 21)
LEWIS, R C Division of Project & Resident Programs 82/09/08
LEASBURG, R H Virginia Electric & Power Co 2pp 16359 240 24X
Fiche 50-280, 82/12/06, 8212090166
- 8212090185 IE Safeguards Insp Repts 50-280/82-23 & 50-281/82-23 on 820816-20 Noncompliance noted failure to control access to defensive position & to equip personnel w/communication devices for vital areas Details withheld (ref 10CFR73 21)
MOORE, D E Division of Engineering & Technical Programs 82/09/03
82/09/03 2pp 16359 242 24X Fiche 50-280, 82/12/06, 8212090166
- 8212090419 Forwards addl info re status of emergency response facilities locations & const, supplementing 810601 & 820408 responses to Generic Ltr 81-10 transmitting NUREG-0696, per request
STEWART, W L Virginia Electric & Power Co 82/12/06 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 16364 276
24X Fiche 50-000, 82/12/06, 8212090419
- 8212150059 Forwards revised security drawings Drawings withheld (ref 10CFR2 790)
STEWART, W L Virginia Electric & Power Co 82/12/09 DENTON, H R
Office of Nuclear Reactor Regulation, Director VARGA, S A
Operating Reactors Branch 1 1p 16427 362 24X
Fiche 50-000, 82/12/09, 8212150059
- 8212170036 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 82/12/10 Document
Management Branch 1p 16478 003 24X Fiche 50-280, 82/12/10, 8212170036
- 8212170041 Forwards public version of Revision 1 to Emergency Plan Implementing Procedure EPIP-1 01, "Emergency Manager Controlling Procedure"
STEWART, W L Virginia Electric & Power Co 82/12/01
O'REILLY, J P Region 2, Office of Director 1p 16478 004 24X
Fiche 50-280, 82/12/10, 8212170036
- 8212170044 Public version of Revision 1 to Emergency Plan Implementing Procedure EPIP-1 01, "Emergency Manager Controlling Procedure"
COX, F H, SAUNDERS, R T Virginia Electric & Power Co 82/11/18
3pp 16478 005 24X Fiche 50-280, 82/12/10, 8212170036
- 8212200281 Responds to util 821028 ltr re Revision 7 to security program Revision consistent w/10CFR50 54(p) provisions & acceptable Encl to 821028 ltr withheld (ref 10CFR73 21)
VARGA, S A Operating Reactors Branch 1 82/12/10 STEWART, W L
Virginia Electric & Power Co 2pp 16523 307 24X
Fiche 50-280, 82/12/10, 8212200281
- 821220481 Forwards draft SER re App R exemption requests Justification that level of protection afforded by existing fire protection measures in emergency switch gear rooms equivalent to App R requirements not provided
VARGA, S A Operating Reactors Branch 1 82/12/10 STEWART, W L
Virginia Electric & Power Co 7pp 16523 192 24X
Fiche 50-280, 82/12/10, 821220481
- 8212170024 Forwards request for addl info re security training & qualification plans, per util 820917 ltr
CLARK, R A Operating Reactors Branch 3 82/12/13 STEWART, W L
Virginia Electric & Power Co 4pp 16480 335 24X
Fiche 50-000, 82/12/13, 8212170024
- 8212170454 Releases public version of revised local govt radiological emergency response plans
FELTON, J M Division of Rules and Records 82/12/13 Document
Management Branch 1p 16479 142 24X Fiche 50-280, 82/12/13, 8212170454
- 8212170457 Forwards public version of revised local govt radiological emergency response plans for Counties of Surry, Isle of Wight, York & James City & Cities of Newport News & Williamsburg, VA
STEWART, W L Virginia Electric & Power Co 82/12/01
O'REILLY, J P Region 2, Office of Director 1p 16479 144 24X
Fiche 50-280, 82/12/13, 8212170454
- 8212170458 Public version of revised local govt radiological emergency response plans for Counties of Surry, Isle of Wight, York & James City & Cities of Newport News & Williamsburg, VA
* Virginia Electric & Power Co 82/11/30 228pp 16479 145
24X Fiche 50-280, 82/12/13, 8212170454
- 8212300195 Responds to 821013 ltr re protection of safeguards info Safe acceptable, provided that safe located within protected area
VARGA, S A Operating Reactors Branch 1 82/12/15 STEWART, W L
Virginia Electric & Power Co 2pp 16612 329 24X
Fiche 50-280, 82/12/15, 8212300195
- 8212270179 Informs that although 821209 ltr forwarding security drawings failed to contain safeguards statement, drawings were properly secured, marked & identified as safeguards info
STEWART, W L Virginia Electric & Power Co 82/12/20 DENTON, H R
Office of Nuclear Reactor Regulation, Director VARGA, S A
Operating Reactors Branch 1 1p 16539 010 24X
Fiche 50-000, 82/12/20, 8212270179
- P Operating license stage documents & correspondence
- 8212060134 Forwards response to NRC 821026 questionnaire re steam generator tube integrity Data for each facility compiled in separate sections
STEWART, W L Virginia Electric & Power Co 82/12/01 DENTON, H R
Office of Nuclear Reactor Regulation, Director EISENHUT, D G
Division of Licensing 5pp 16314 070 24X Fiche 50-000, 82/12/01, 8212060134
- 8212060284 Notifies that neither facility has addl Tech Specs to be submitted, in response to Generic Ltr 82-16 re status of NUREG-0737 items
STEWART, W L Virginia Electric & Power Co 82/12/01 DENTON, H R
Office of Nuclear Reactor Regulation, Director EISENHUT, D G
Division of Licensing 1p 16312 058 24X Fiche 50-000, 82/12/01, 8212060284
- 8212060303 Application for Amend to Licenses DPR-32 & DPR-37 Amend revises Tech Specs re hours staff will be performing safety-related functions & audit frequency of station emergency plan
STEWART, W L Virginia Electric & Power Co 82/12/01 DENTON, H R
Office of Nuclear Reactor Regulation, Director VARGA, S A
Operating Reactors Branch 1 2pp 16312 112 24X
Fiche 50-280, 82/12/01, 8212060303
- 8212060315 Proposed Tech Spec changes re hours staff will be performing safety-related functions & audit frequency of station emergency plan
* Virginia Electric & Power Co 82/12/01 5pp 16312 114 24X
Fiche 50-280, 82/12/01, 8212060303
- 8212100012 Advises that Generic Issue B-24 re containment purge & TMI Item II E 4 2 re containment isolation dependability complete Summary of review listed Tech Specs will be issued separately
VARGA, S A Operating Reactors Branch 1 82/12/07 STEWART, W L
Virginia Electric & Power Co 3pp 16399 235 24X
Fiche 50-280, 82/12/07, 8212100012
- 8208190263 Generic Ltr 82-32 to all PWR licensees re potential steam generator-related generic requirements Forwards Science Applications, Inc draft rept re subj requirements Comments requested within 30 days of ltr Svc list encl
EISENHUT, D G Division of Licensing 82/12/09 Consolidated
Edison Co. of New York, Inc 29pp 16629 247 24X
Fiche 50-000, 82/12/09, 8208190263
- 8212130327 Advises of repair within ASME Class 2 sys boundary during 821207 maint outage Basis for request for relief from post-repair test requirements per ASME Section XI provided
STEWART, W L Virginia Electric & Power Co 82/12/09 DENTON, H R
Office of Nuclear Reactor Regulation, Director VARGA, S A
Operating Reactors Branch 1 2pp 16389 270 24X
Fiche 50-281, 82/12/09, 8212130327
- 8212140103 Generic Ltr 82-28 to all licensees of operating Westinghouse & C-E PHRs (except Arkansas Nuclear One, Unit 2 & San Onofre 2 & 3) re inadequate core cooling instrumentation sys Svc list encl
EISENHUT, D G Division of Licensing 82/12/10 Yankee Atomic
Electric Co 27pp 16690 035 24X Fiche 50-000, 82/12/10, 8212140103
- 8212280073 Forwards check in payment of fees for review of request for relief from requirements of ASME Section XI
STEWART, W L Virginia Electric & Power Co 82/12/21 DENTON, H R
Office of Nuclear Reactor Regulation, Director VARGA, S A
Operating Reactors Branch 1 1p 16564 235 24X
Fiche 50-281, 82/12/21, 8212280073

DOCKETED ITEMS

103

B212280257 Forwards remittance for Invoice B-0063 for review of Amend A to Topical Rept VEP-1, "QA Program - Operations Phase," submitted on B20921 & approved on B21006
STEWARD, W L Virginia Electric & Power Co B2/12/22 DENTON, H R
Office of Nuclear Reactor Regulation, Director BARRY, L W Division
of Accounting 1p 16561 267 24X Fiche 50-000, B2/12/22,
B212280257

B212280349 Forwards Class II fee to cover review of B21201 suppl to
amend Licenses DPR-32 & DPR-37
STEWARD, W L Virginia Electric & Power Co B2/12/22 DENTON, H R
Office of Nuclear Reactor Regulation, Director VARGA, S A
Operating Reactors Branch 1 1p 16561 042 24X
Fiche 50-280, B2/12/22, B212280349

B212290191 Informs that completion date, per B20823 supplemental
response to Generic Ltr B2-05, "Post-Accident Sampling Sys,"
will be extended to B20601 Status rept expected in Mar 1983
STEWARD, W L Virginia Electric & Power Co B2/12/27 DENTON, H R
Office of Nuclear Reactor Regulation, Director EISENHUT, D O
Division of Licensing 3pp 16578 052 24X Fiche 50-280, B2/12/27,
B212290191

G Inspection reports, IE Bulletins & correspondence

B212090267 Forwards IE Insp Repts 50-280/B2-26 & 50-281/B2-26 on
B21004-08 No noncompliance noted
DANCE, H C Division of Project & Resident Programs B2/10/26
LEASBURG, R H Virginia Electric & Power Co 2pp 16362 301 24X
Fiche 50-280, B2/10/26, B212090267

--B212090277 IE Insp Repts 50-280/B2-26 & 50-281/B2-26 on B21004-08 No
noncompliance noted Major areas inspected pipe supports &
restraints & Type B & C containment leakage rate testing
BROOKS, E H JAE, F Division of Project & Resident Programs
B2/10/25 4pp 16362 303 24X Fiche 50-280, B2/10/26, B212090267

B208190240 IE Bulletin B2-03, Revision 1, "Stress Cracking in Thick-
Wall, Large-Diameter, Stainless Steel Recirculation Sys Piping
at BWR Plants " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and
Enforcement B2/10/28 Consolidated Edison Co of New York, Inc
12pp 16462 163 24X Fiche 50-000, B2/10/28, B208190240

B212090285 Advises that GALP Repts 50-280/B2-19, 50-281/B2-19,
50-338/B2-24 & 50-339/B2-24 have been reviewed & approved
Overall performance adequate No reply required
O'REILLY, J P Region 2, Office of Director B2/11/03
LEASBURG, R H Virginia Electric & Power Co 2pp 16365 208 24X
Fiche 50-000, B2/11/03, B212090285

--B212090298 Forwards GALP Repts 50-280/B2-19, 50-281/B2-19, 50-338/B2-24
& 50-339/B2-24 for Jul 1980-June 1981
LEWIS, R C Division of Project & Resident Programs B2/08/04
LEASBURG, R H Virginia Electric & Power Co 2pp 16365 210 24X
Fiche 50-000, B2/11/03, B212090285

--B212090306 GALP Repts 50-280/B2-19, 50-281/B2-19, 50-338/B2-24 &
50-339/B2-24 for Jul 1980-June 1981 Increased mgt attention
should be directed towards plant operations & operational
QA
* Region 2, Office of Director B2/08/04 31pp 16365 212 24X
Fiche 50-000, B2/11/03, B212090285

B208190245 IE Info Notice B2-42, "Defects Observed in Panasonic Model
B01 & Model B02 Thermoluminescent Dosimeters " Svc list
encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards
B2/11/05 Consolidated Edison Co of New York, Inc 110pp
16372 142 24X Fiche 50-000, B2/11/05, B208190245

B208190251 IE Info Notice B2-44, "Clarification of Emergency Plan
Exercise Requirements " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance B2/11/18
Consolidated Edison Co of New York, Inc 109pp 16411 199 24X
Fiche 50-000, B2/11/18, B208190251

B212090276 Ack receipt of B21029 ltr informing NRC of steps taken to
correct violations noted in IE Insp Repts 50-280/B2-24 &
50-281/B2-24
DANCE, H C Division of Project & Resident Programs B2/11/18
STEWARD, W L Virginia Electric & Power Co 1p 16365 270 24X
Fiche 50-280, B2/11/18, B212090276

--B212090286 Responds to NRC B20929 ltr re violations noted in IE Insp
Repts 50-280/B2-24 & 50-281/B2-24 Corrective actions valve
pit roofs covered w/fire retardant plastic & sealed
STEWARD, W L Virginia Electric & Power Co B2/10/27
O'REILLY, J P Region 2, Office of Director 3pp 16365 271 24X
Fiche 50-280, B2/11/18, B212090276

--B212090300 Forwards IE Insp Repts 50-280/B2-24 & 50-281/B2-24 on
B20802-0903 & notice of violation
DANCE, H C Division of Project & Resident Programs B2/09/29
LEASBURG, R H Virginia Electric & Power Co 2pp 16365 274 24X
Fiche 50-280, B2/11/18, B212090276

--B212090304 Notice of violation from insp on B20802-0903
* Division of Project & Resident Programs B2/09/29 1p
16365 276 24X Fiche 50-280, B2/11/18, B212090276

--B212090313 IE Insp Repts 50-280/B2-24 & 50-281/B2-24 on B20802-0903
Noncompliance noted roof leak caused by previous maint work
degraded safety-related equipment
BURKE, D J, DAVIS, M J, ORDERS, W J Division of Project & Resident
Programs B2/09/28 9pp 16365 277 24X Fiche 50-280, B2/11/18,
B212090276

B212090215 Ack receipt of B20716 & 1105 ltrs informing NRC of steps
taken to correct violations noted in IE Insp Repts
50-280/B2-10 & 50-281/B2-10
DANCE, H C Division of Project & Resident Programs B2/11/19
STEWARD, W L Virginia Electric & Power Co 1p 16362 279 24X
Fiche 50-280, B2/11/19, B212090215

--B212090217 Responds to NRC B20607 ltr re violations noted in IE Insp
Repts 50-280/B2-10 & 50-281/B2-10 Corrective actions
Administrative Procedure 56 re ignition sources amended
to classify areas for purposes of controlling sources
STEWARD, W L Virginia Electric & Power Co B2/11/05
O'REILLY, J P Region 2, Office of Director 2pp 16362 280 24X
Fiche 50-280, B2/11/19, B212090215

--B212090218 Responds to NRC B20607 ltr re violations noted in IE Insp
Repts 50-280/B2-10 & 50-281/B2-10 Corrective actions
process vent sys mod designed & Administrative Procedure 56
amended re safety-related areas
LEASBURG, R H Virginia Electric & Power Co B2/07/16
O'REILLY, J P Region 2, Office of Director 4pp 16362 282 24X
Fiche 50-280, B2/11/19, B212090215

--B212090220 Confirms telcon re IE Insp Repts 50-280/B2-10 &
50-281/B2-10 Response will be submitted by B20717
LEASBURG, R H Virginia Electric & Power Co B2/07/06
O'REILLY, J P Region 2, Office of Director 1p 16362 284 24X
Fiche 50-280, B2/11/19, B212090215

* B212090223 Forwards IE Insp Repts 50-280/B2-10 & 50-281/B2-10 on
B20401-30 & notice of violation
DANCE, H C Division of Project & Resident Programs B2/06/07
LEASBURG, R H Virginia Electric & Power Co 2pp 16362 287 24X
Fiche 50-280, B2/11/19, B212090215

--B212090226 Notice of violation from insp on B20401-30
* Division of Project & Resident Programs B2/06/07 2pp
16362 289 24X Fiche 50-280, B2/11/19, B212090215

--B212090234 IE Insp Repts 50-280/B2-10 & 50-281/B2-10 on B20401-30
Noncompliance noted failure to follow fire protection
program implementing procedures
BURKE, D J, DAVIS, M J, JULIAN, C A Division of Project & Resident
Programs B2/06/04 10pp 16362 291 24X Fiche 50-280, B2/11/19,
B212090215

B208190256 IE Info Notice B2-46, "Defective & Obsolete Combination
Padlocks " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and
Enforcement B2/11/26 Consolidated Edison Co of New York, Inc
127pp 16411 065 24X Fiche 50-000, B2/11/26, B208190256

B208190257 IE Info Notice B2-47, "Transportation of Type A Quantities
of Non-Fissile Radioactive Mail " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards
B2/11/30 Consolidated Edison Co of New York, Inc 354pp
16387 028 24X Fiche 50-000, B2/11/30, B208190257

B212290060 Partial response to FOIA request for seven categories of
info Forwards documents listed in App A Documents 1 & 2
already in PDR App B documents available in PDR LPDR
profiles for Ginn & Indian Point 3 encl
FELTON, J M Division of Rules and Records B2/11/30
SCHLISSEL, D A New York, State of 7pp 16607 239 24X
Fiche 50-000, B2/11/30, B212290060

--B212290170 Ack receipt of 761206 ltr informing NRC of steps taken to
correct violation noted in IE Insp Repts 50-280/76-14 &
50-281/76-14
LONG, F J Region 2, Atlanta, Reactor Operations Nuclear Support
Branch 77/01/14 PROFFITT, W L Virginia Electric & Power Co
1p 16608 041 24X Fiche 50-000, B2/11/30, B212290060

DOCKETED ITEMS

--8212290172 Responds to NRC 761021 ltr re violation noted in IE Insp Repts 50-280/76-14 & 50-281/76-14 Corrective actions Administrative Procedure 29 redistributed & importance of proper documentation practices emphasized
STALLINGS, C M Virginia Electric & Power Co 76/12/06
MOSELEY, N C Region 2, Atlanta, Office of the Director 4pp
16608 042 24X Fiche 50-000, 82/11/30, 8212290060

--8212290178 Forwards IE Insp Repts 50-280/76-14 & 50-281/76-14 on 760915-17 Noncompliance noted
LONG, F J Region 2, Atlanta, Reactor Operations Nuclear Support Branch 76/10/21 PROFFITT, W L Virginia Electric & Power Co 2pp 16608 046 24X Fiche 50-000, 82/11/30, 8212290060

--8212290184 IE Insp Repts 50-280/76-14 & 50-281/76-14 on 760915-17 Noncompliance noted failure to follow log book entry & review & initial requirements specified in Administrative Procedure 29
SINKULE, M V, LEWIS, R C, ROGERS, R F Region 2, Atlanta, Reactor Operations Nuclear Support Branch 76/10/19 13pp 16608 048 24X Fiche 50-000, 82/11/30, 8212290060

8208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies" Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259

8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets" Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X Fiche 50-000, 82/12/03, 8208190261

8212090166 Ack receipt of 821008 & 1117 ltrs informing NRC of steps taken to correct violations noted in IE Safeguards Insp Repts 50-280/82-23 & 50-281/82-23
LEWIS, R C Division of Project & Resident Programs 82/12/06
STEWART, W L Virginia Electric & Power Co 2pp 16359 236 24X Fiche 50-280, 82/12/06, 8212090166

--8212090169 Forwards supplemental response to 821008 ltr re 820908 IE Safeguards Insp Repts 50-280/82-23 & 50-281/82-23 Response withheld (ref 10CFR73.21)
STEWART, W L Virginia Electric & Power Co 82/11/17
O'REILLY, J P Region 2, Office of Director 1p 16359 238 24X Fiche 50-280, 82/12/06, 8212090166

--8212090175 Responds to NRC 820908 ltr re violations noted in IE Insp Repts 50-280/82-23 & 50-281/82-23 Corrective actions withheld (ref 10CFR73.21)
LEASBURG, R H Virginia Electric & Power Co 82/10/08
O'REILLY, J P Region 2, Office of Director 1p 16359 239 24X Fiche 50-280, 82/12/06, 8212090166

--8212090180 Forwards IE Safeguards Insp Repts 50-280/82-23 & 50-281/82-23 & notice of violation Notice of violation & reft details withheld (ref 10CFR73.21)
LEWIS, R C Division of Project & Resident Programs 82/09/08
LEASBURG, R H Virginia Electric & Power Co 2pp 16359 240 24X Fiche 50-280, 82/12/06, 8212090166

--8212090185 IE Safeguards Insp Repts 50-280/82-23 & 50-281/82-23 on 820816-20 Noncompliance noted failure to control access to defensive position & to equip personnel w/communication devices for vital areas Details withheld (ref 10CFR73.21)
MCGRE, D E, MCQUIRE, D R Division of Engineering & Technical Programs 82/09/03 2pp 16359 242 24X Fiche 50-280, 82/12/06, 8212090166

821220296 Advises that 821209 request for relief from 1977 ASME Section XI requirements for inservice insp hydrostatic tests granted Relief allows replacement of 1 3-inch drain valves upstream of main steam trip valve w/o performing test
VAROA, S A Operating Reactors Branch 1 82/12/10 STEWART, W L Virginia Electric & Power Co 3pp 16523 258 24X Fiche 50-281, 82/12/10, 821220296

--821220299 Notice of granting of relief from ASME Code Section XI inservice insp requirements
VAROA, S A Operating Reactors Branch 1 82/12/10 2pp 16523 261 24X Fiche 50-281, 82/12/10, 821220296

8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring" Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16, 8208190267

8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27" Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X Fiche 50-000, 82/12/20, 8208190268

8212290459 Forwards "Inservice Insp Program, Interval 2, 830428-930428" STEWART, W L Virginia Electric & Power Co 82/12/27 DENTON, H R Office of Nuclear Reactor Regulation, Director EISENHUT, D O Division of Licensing 1p 16583 273 24X Fiche 50-281, 82/12/27, 8212290459

--8212290474 "Inservice Insp Program, Interval 2, 830428-930428" * Virginia Electric & Power Co 82/12/22 377pp 16583 274 24X Fiche 50-281, 82/12/27, 8212290459

R Periodic operating reports & related correspondence

8212290238 Forwards monthly operating repts for Oct 1982 & corrected page to monthly operating reft for Sept 1982 w/o corrected page
STEWART, W L Virginia Electric & Power Co 82/11/15 HALLER, N H Office of Resource Management, Director 1p 16582 116 24X Fiche 50-280, 82/11/15, 8212290238

--8212290244 Monthly operating repts for Oct 1982
JONES, V Virginia Electric & Power Co 82/11/05 52pp 16582 117 24X Fiche 50-280, 82/11/15, 8212290238

S Reportable occurrences, LERs & related correspondence

8212090086 Forwards LERs 82-110/03L-0 & 82-060/03L-0
WILSON, J L Virginia Electric & Power Co 82/11/30 O'REILLY, J P Region 2, Office of Director 1p 16357 180 24X Fiche 50-280, 82/11/30, 8212090086

--8212090098 LER 82-060/03L-0 on 821102, charging pump svc water pump 2-SW-P-103 experienced loss of suction pressure Caused by insufficient NPSH Pump vented to restore NPSH
WILSON, J L Virginia Electric & Power Co 82/11/30 Region 2, Office of Director 3pp 16357 185 24X Fiche 50-280, 82/11/30, 8212090086

8212290060 Partial response to FOIA request for seven categories of info Forwards documents listed in App A Documents 1 & 2 already in PDR App B documents available in PDR LPDR profiles for Ginna & Indian Point 3 encl
FELTON, J M Division of Rules and Records 82/11/30
SCHLISSEL, D A New York, State of 7pp 16607 239 24X Fiche 50-000, 82/11/30, 8212290060

--8212290085 RO 76-05 on 760915, pressurizer level fell below 45% level setpoint, resulting in decreases of pressurizer pressure & vol control tank level Caused by leaking tube in steam generator A Cause of tube failure will be evaluated
STALLINGS, C M Virginia Electric & Power Co 76/09/29
MOSELEY, N C Region 2, Atlanta, Office of the Director 5pp 16607 278 24X Fiche 50-000, 82/11/30, 8212290060

8212090130 Forwards LERs 82-068/03L-0, 82-065/03L-0 & 82-069/03L-0
WILSON, J L Virginia Electric & Power Co 82/12/03 O'REILLY, J P Region 2, Office of Director 1p 16359 181 24X Fiche 50-281, 82/12/03, 8212090130

--8212090134 LER 82-065/03L-0 on 821106, charging pump svc water pump 2-SW-P-10A failed to develop sufficient discharge pressure Caused by corroded carbon steel stud on packing gland housing & lack of NPSH Packing matl & studs replaced
WILSON, J L Virginia Electric & Power Co 82/12/03 Region 2, Office of Director 3pp 16359 182 24X Fiche 50-281, 82/12/03, 8212090130

--8212090137 LER 82-069/03L-0 on 821104, charging pump svc water pump 2-SW-P-10B experienced loss of suction pressure Caused by insufficient NPSH Pump vented to restore NPSH
WILSON, J L Virginia Electric & Power Co 82/12/03 Region 2, Office of Director 3pp 16359 185 24X Fiche 50-281, 82/12/03, 8212090130

--8212090144 LER 82-068/03L-0 on 821112, during performance of PT 1B 6B, TV-CC-209B would not close when manually operated from control room Caused by sticking pilot valve that controls air flow from valve actuator Pilot valve replaced
WILSON, J L Virginia Electric & Power Co 82/12/03 Region 2, Office of Director 3pp 16359 188 24X Fiche 50-281, 82/12/03, 8212090130

8212150067 Forwards LER 82-067/03L-0
WILSON, J L Virginia Electric & Power Co 82/12/09 O'REILLY, J P Region 2, Office of Director 1p 16431 021 24X Fiche 50-281, 82/12/09, 8212150067

--B212150087 LER 82-067/03L-0 on 821109, w/unit at Full power, electrical fire barrier penetration found improperly sealed Cause unknown Fire watch established & penetration temporarily sealed Permanent sealing to be completed by 830101
WILSON, J L Virginia Electric & Power Co 82/12/09 Region 2,
Office of Director 2pp 16431 022 24X Fiche 50-281, 82/12/09,
8212150067

B212210365 Forwards LERs 82-070/03L-0, 82-113/03L-0 & 82-116/03L-0
WILSON, J L Virginia Electric & Power Co 82/12/13 O'REILLY, J P
Region 2, Office of Director 1p 16494 278 24X
Fiche 50-280, 82/12/13, 8212210365

--B212210383 LER 82-070/03L-0 on 821119, routine walkdown of svc bldg revealed open barrier penetration w/no fire watch posted
Caused by removal of temporary seal on penetration Fire watch posted Penetration resealed
WILSON, J L Virginia Electric & Power Co 82/12/13 Region 2,
Office of Director 2pp 16494 279 24X Fiche 50-280, 82/12/13,
8212210365

B212280126 Forwards LERs 82-105/03L-0, 82-117/03L-0 & 82-072/03L-0
WILSON, J L Virginia Electric & Power Co 82/12/17 O'REILLY, J P
Region 2, Office of Director 1p 16562 306 24X
Fiche 50-280, 82/12/17, 8212280126

--B212280206 LER 82-072/03L-0 on 821126, amplifier readings heat tracing panel 11, circuit 2A, fell below acceptance criteria
Caused by overheating due to maldadjusted thermostat
Defective heat tracing replaced & tested
WILSON, J L Virginia Electric & Power Co 82/12/17 Region 2,
Office of Director 2pp 16562 312 24X Fiche 50-280, 82/12/17,
8212280126

Y Dry Cask Independent Spent Fuel Storage Installations

B212220170 Advises that application for dry cask 16F81 docketed on 821015 Application evaluated for completeness & acceptability Details of cask must be provided to NH
Revision before licensing action can be completed
ROUSE, L C Advanced Fuel & Spent Fuel Licensing Branch 82/12/03
LEASBURG, R H Virginia Electric & Power Co 2pp 16523 361 24X
Fiche 50-280, 82/12/03, 8212220170

B212220005 Forwards notice of consideration of matl license for storage of spent fuel transmitted to Ofc of PR for publication
ROUSE, L C Advanced Fuel & Spent Fuel Licensing Branch 82/12/06
LEASBURG, R H Virginia Electric & Power Co 2pp 16529 144 24X
Fiche 50-280, 82/12/06, 8212220005

--B212220007 Notice of consideration of matl license for storage of spent fuel
ROUSE, L C Advanced Fuel & Spent Fuel Licensing Branch 82/12/03
4pp 16529 146 24X Fiche 50-280, 82/12/06, 8212220005

B212230147 Notice of correction of typographical error in 821209 FR notice re consideration of matl license for storage of spent fuel
ROUSE, L C Advanced Fuel & Spent Fuel Licensing Branch 82/12/10
2pp 16544 056 24X Fiche 50-280, 82/12/10, 8212230147

DOCKET 50-282 PRAIRIE ISLAND NUCLEAR STATION, UNIT 1

F Security, medical, emergency & fire protection plans

B212030134 Forwards IE Insp Repts 50-282/82-17 & 50-306/82-17 on 820921-1031 No noncompliance noted
STREETER, J F Division of Project & Resident Programs 82/11/17
LARSON, C E Northern States Power Co 2pp 16306 031 24X
Fiche 50-282, 82/11/17, 8212030134

--B212030150 IE Insp Repts 50-282/82-17 & 50-306/82-17 on 820921-1031 No noncompliance noted Major areas inspected: preparation for refueling, fire drills & exercises, operations safety verification, followup on fuel oil spill & followup on LERs
FEIERABEND, C D, REYES, L Division of Project & Resident Programs 82/11/17 8pp 16306 033 24X Fiche 50-282, 82/11/17, 8212030134

B212210329 Forwards IE Insp Repts 50-282/82-18 & 50-306/82-18 on 821013-15 & 1109 No noncompliance noted
HIND, J A Division of Emergency Preparedness & Operational Support 82/12/02
LARSON, C E Northern States Power Co 3pp 16496 229 24X Fiche 50-282, 82/12/02, 8212210329

--B212210340 IE Insp Repts 50-282/82-18 & 50-306/82-18 on 821013-15 & 1109 No noncompliance noted Major areas inspected: emergency exercise, especially command & control of control room, technical support ctr & operations support ctr
PATTERSON, J P, LICKUS, R M, AXELSON, W L Division of Emergency Preparedness & Operational Support 82/12/01 12pp 16496 237 24X Fiche 50-282, 82/12/02, 8212210329

B212140279 Requests exemption, under 10CFR50.48(c)(6), from automatic suppression requirement of App R, Section III G 3 for control room
MUSOLF, D Northern States Power Co 82/12/06 Office of Nuclear Reactor Regulation, Director 3pp 16402 104 24X
Fiche 50-282, 82/12/06, 8212140279

B212220045 Advises that 820520 & 0823 exemption requests granted extending deadline for installation of emergency lighting until 830101 Addl time needed to complete engineering analysis, procurement & installation
EISENHUT, D O Division of Licensing 82/12/08 MUSOLF, D M
Northern States Power Co 4pp 16526 359 24X
Fiche 50-282, 82/12/08, 8212220045

--B212220048 Exemption granting extension for installation of emergency lighting until 830101
DENTON, H R Office of Nuclear Reactor Regulation, Director 82/12/08 Northern States Power Co 7pp 16526 359 24X
Fiche 50-282, 82/12/08, 8212220045

B212220306 Discusses layout of communications equipment required in control room, onsite technical support ctr & near-site emergency operations facility
KEPPLER, J O Region 3, Office of Director 82/12/16 Commonwealth Edison Co 3pp 16503 351 24X Fiche 50-000, 82/12/16, 8212220306

B212300412 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 82/12/22 Document Management Branch 1p 16613 075 24X Fiche 50-282, 82/12/22, 8212300412

--B212300416 Forwards public version of revised Emergency Plan Implementing Procedures F3-5 re emergency notifications, F3-10 re personnel accountability & F3-23 re emergency sampling
WARD, E C Northern States Power Co 82/12/15 Region 3, Office of Director 1p 16613 076 24X Fiche 50-282, 82/12/22, 8212300412

--B212300417 Public version of Emergency Plan Implementing Procedures F3-5 re emergency notifications, F3-10 re personnel accountability & F3-23 re emergency sampling
SCHUELKE, D A Northern States Power Co 82/11/04 102pp 16613 077 24X Fiche 50-282, 82/12/22, 8212300412

P Operating license stage documents & correspondence

B212090057 Forwards Revision 1 to 750847 license amend request to change Tech Specs re containment leakage rate testing, incorporating required changes No fee appropriate since request submitted earlier
MUSOLF, D Northern States Power Co 82/12/03 Office of Nuclear Reactor Regulation, Director 1p 16359 041 24X
Fiche 50-282, 82/12/03, 8212090057

--B212090059 Revision 1 to 750807 license amend request to change Tech Spec re containment leakage rate testing
MUSOLF, D Northern States Power Co 82/12/03 20pp 16359 042 24X Fiche 50-282, 82/12/03, 8212090057

B212090172 Forwards addl info re methods of compliance w/NUREG-0737, item 11 B 3 on post-accident sampling sys, in response to 820908 request
MUSOLF, D Northern States Power Co 82/12/03 Office of Nuclear Reactor Regulation, Director 11pp 16359 221 24X
Fiche 50-282, 82/12/03, 8212090172

B208190263 Generic Ltr 82-32 to all PWR licensees re potential steam generator-related generic requirements Forwards Science Applications, Inc draft repts re suby requirements Comments requested within 30 days of ltr Svc list encl
EISENHUT, D O Division of Licensing 82/12/09 Consolidated Edison Co of New York, Inc 29pp 16629 247 24X
Fiche 50-000, 82/12/09, 8208190263

B212140411 Forwards summary of NRC review of Exxon Nuclear Co thermal hydraulic methodology for mixed cores in PWRs Encl TOPROD, sensitivity & thermal margin studies submitted on 820618 & 29, respectively, remain valid Comments requested
COOKE, G C Exxon Nuclear Co, Inc (subs of Exxon Corp) 82/12/09 HOLDNICH, J J Core Performance Branch 7pp 16403 322 24X Fiche 50-282, 82/12/09, 8212140411

B212140103 Generic Ltr 82-28 to all licensees of operating Westinghouse & C-E PWRs (except Arkansas Nuclear One, Unit 2 & San Onofre 2 & 3) re inadequate core cooling instrumentation sys Svc list encl
EISENHUT, D O Division of Licensing 82/12/10 Yankee Atomic Electric Co 27pp 16690 035 24X Fiche 50-000, 82/12/10, 8212140103

DOCKETED ITEMS

8212170242 Responds to 821104 request for ECCS model, specifically treating upper plenum injection Exxon model will be ready for submittal by 830131
MUSOLF, D Northern States Power Co 82/12/10 Office of Nuclear Reactor Regulation, Director 1p 16456 207 24X
Fiche 50-282, 82/12/10, 8212170242

8212210290 Forwards NSPNAD-8101P, Revision 1, "Qualification of Reactor Physics Methods for Application to Prairie Island Units," & NSPNAD-8102P, Revision 1, "Reload Safety Evaluation Methods for Application " Repts withheld (ref 10CFR2 790)
MUSOLF, D Northern States Power Co 82/12/13 Office of Nuclear Reactor Regulation, Director 1p 16497 134 24X
Fiche 50-282, 82/12/13, 8212210290

4 Inspection reports, IE Bulletins & correspondence

8208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240

8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list encl
CGBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000, 82/11/05, 8208190245

8212030134 Forwards IE Insp Repts 50-282/82-17 & 50-306/82-17 on 820921-1031 No noncompliance noted
STREETER, J F Division of Project & Resident Programs 82/11/17 LARSON, C E Northern States Power Co 2pp 16306 031 24X
Fiche 50-282, 82/11/17, 8212030134

- 8212030150 IE Insp Repts 50-282/82-17 & 50-306/82-17 on 820921-1031 No noncompliance noted Major areas inspected preparation for refueling, fire drills & exercises, operations safety verification, followup on fuel oil spill & followup on LERs
FEIERABEND, C D REYES, L Division of Project & Resident Programs 82/11/17 8pp 16306 033 24X Fiche 50-282, 82/11/17, 8212030134

8209190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X
Fiche 50-000, 82/11/18, 8209190251

8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Radiacks " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000, 82/11/26, 8208190256

8208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl
CGBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000, 82/11/30, 8208190257

8212210329 Forwards IE Insp Repts 50-282/82-18 & 50-306/82-18 on 821013-15 & 1109 No noncompliance noted
HIND, J A Division of Emergency Preparedness & Operational Support 82/12/02 LARSON, C E Northern States Power Co 3pp 16496 229 24X Fiche 50-282, 82/12/02, 8212210329

- 8212210340 IE Insp Repts 50-282/82-18 & 50-306/82-18 on 821013-15 & 1109 No noncompliance noted Major areas inspected emergency exercise, especially command & control of control room, technical support ctr & operations support ctr
PATTERSON, J P, LICKUS, R M, AXELSON, W L Division of Emergency Preparedness & Operational Support 82/12/01 12pp 16496 232 24X Fiche 50-282, 82/12/02, 8212210329

8208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259

8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X
Fiche 50-000, 82/12/03, 8208190261

8212270292 Forwards IE Insp Repts 50-282/82-19 & 50-306/82-19 on 821126 No noncompliance noted
LITTLE, W S Division of Engineering & Technical Programs 82/12/10 LARSON, C E Northern States Power Co 2pp 16530 122 24X
Fiche 50-282, 82/12/10, 8212270292

--8212270305 IE Insp Repts 50-282/82-19 & 50-306/82-19 on 821126 No noncompliance noted Major areas inspected review of inservice insp procedures, NDE personnel certifications & data & IE Bulletin 78-12 activities
WARD, K D, DANIELSON, D H Region 3, Office of Director 82/12/09 4pp 16530 124 24X Fiche 50-282, 82/12/10, 8212270292

8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16, 8208190267

8212280325 Responds to IE Bulletin 82-04 No electrical penetration assemblies referenced in bulletin in use or planned for use in safety-related sys
LARSON, C E Northern States Power Co 82/12/17 KEPLER, J O Region 3, Office of Director 1p 16562 087 24X
Fiche 50-282, 82/12/17, 8212280325

8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relay, Type ITE-27 " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X
Fiche 50-000, 82/12/20, 8208190268

5 Reportable occurrences, LERs & related correspondence

8212020311 Forwards LER 82-020/03L-0
MUSOLF, D Northern States Power Co 82/11/24 Region 3, Office of Director 1p 16291 003 24X Fiche 50-282, 82/11/24, 8212020311

--8212020317 LER 82-020/03L-0 on 821026, during surveillance test, auxiliary bldg special vent sys PAC filter 121 exhibited DDP removal efficiency of 98.6%, less than Tech Specs requirement Caused by loose filters Filters tightened
HUNSTAD, A A Northern States Power Co 82/11/24 Region 3, Office of Director 1p 16291 004 24X Fiche 50-282, 82/11/24, 8212020311

8212080420 Forwards LER 82-022/03L-0
MUSOLF, D Northern States Power Co 82/11/30 Region 3, Office of Director 1p 16352 178 24X Fiche 50-282, 82/11/30, 8212080420

--8212080429 LER 82-022/03L-0 on 821112, during power operation, control power lost to diesel cooling water pump 22, rendering pump inoperable Caused by loose fuse clip Clip repaired & pump tested satisfactorily
HUNSTAD, A A Northern States Power Co 82/11/30 Region 3, Office of Director 1p 16352 179 24X Fiche 50-282, 82/11/30, 8212080420

DOCKET 50-285 FORT CALHOUN STATION, UNIT 1

7 Security, medical, emergency & fire protection plans

8212070425 Responds to FOIA request for documents re 820809 notice of violation & order imposing civil penalty Forwards App A documents App B documents completely withheld & Documents C1-C4 partially withheld (ref FOIA Exemptions 3, 5 & 7)
FELTON, J M Division of Rules and Records 82/11/05 MCARRY, J M Debevoise & Liberman 5pp 16355 003 24X Fiche 50-000, 82/11/05, 8212070425

- 8212070473 Concludes that all Region 4 licensees in compliance w/820201 deadline for implementation of prompt notification sys
COLLINS, J T Region 4, Office of Director 82/02/01 GRIMES, B K Division of Emergency Preparedness 2pp 16355 104 24X
Fiche 50-000, 82/11/05, 8212070425

8212200022 Forwards IE Insp Rept 50-285/82-23 on 820913-16 No noncompliance noted
SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs 82/11/08 JONES, W C Omaha Public Power District 2pp 16473 095 24X Fiche 50-285, 82/11/08, 8212200022

--8212200033 IE Insp Rept 50-285/82-23 on 820913-16 No noncompliance noted Major areas inspected licensee performance & capabilities during full-scale exercise of emergency plans & procedures & review of appropriate licensee documents
MONFOUCHERY, J L, JOHNSON, W D Division of Resident, Reactor Project & Engineering Programs 82/11/04 11pp 16473 097 24X
Fiche 50-285, 82/11/08, 8212200022

- 8212010236 Advises that Revision 11 to physical security plan acceptable NRC must be notified within 2 months of plan change Encls to 820827 ltr withheld (ref 10CFR73.21)
CLARK, R A Operating Reactors Branch 3 82/11/24 JONES, W C
Omaha Public Power District 2pp 16290 310 24X
Fiche 50-285, 82/11/24, 8212010236
- 8212080380 Documents info provided by 821202 telcon re plant emergency operations facility (EOF) Communications will be installed within 2 months in interim, temporary EOF operational
JONES, W C Omaha Public Power District 82/12/03 CLARK, R A
Operating Reactors Branch 3 2pp 16392 289 24X
Fiche 50-285, 82/12/03, 8212080380
- 8212100227 Discusses IE Emergency Preparedness Appraisal Rept 50-285/81-35 on 820915 Rept contains comments re technical support ctr operation which should be reviewed
SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs 82/12/07 JONES, W C Omaha Public Power District 1p 16376 170 24X Fiche 50-285, 82/12/07, 8212100227
- 8212100244 Advises that util officially declared permanent technical support ctr operational on 820912, in response to findings re IE Emergency Preparedness Appraisal Rept 50-285/81-35
JONES, W C Omaha Public Power District 82/10/18 SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs 1p 16376 171 24X Fiche 50-285, 82/12/07, 8212100227
- 8212130312 Responds to 821030 Generic Ltr 82-23 re inconsistency between requirements of 10CFR73.40(d) & STS concerning independent reviews of safeguards contingency programs No Tech Spec changes necessary Audit controls in place
JONES, W C Omaha Public Power District 82/12/07 EISENHUT, D G Division of Licensing 2pp 16389 319 24X Fiche 50-285, 82/12/07, 8212130312
- 8212210021 Ack receipt of 820818 ltr responding to NRC 820625 SALP rept 50-287/81-37
COLLINS, J T Region 4, Office of Director 82/12/14 JONES, W C Omaha Public Power District 1p 16490 191 24X
Fiche 50-285, 82/12/14, 8212210021
- 8212210022 Responds to recommendations noted in NRC 820625 SALP Rept 50-287/81-37 Corrective actions station fire protection revised in Mar 1982 to include mgt responsibility & quarterly fire brigade drills initiated
JONES, W C Omaha Public Power District 82/08/18 SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs 6pp 16490 192 24X Fiche 50-285, 82/12/14, 8212210021
- P Operating license stage documents & correspondence
- 8212010458 Forwards safety evaluation & technical evaluation repts, "Improvements in Training & Requalification Programs as Required by TMI Action Items I A 2 i & II B 4 " Upgraded reactor & senior reactor operator programs acceptable
CLARK, R A Operating Reactors Branch 3 NRC-03-82-096 82/11/17 JONES, W C Omaha Public Power District 2pp 16270 270 24X
Fiche 50-285, 82/11/17, 8212010458
- 8212010464 Safety evaluation supporting upgraded reactor & senior reactor operator training & training to mitigate core damage per NUREG-0737 Items I A 2 i & II B 4
* Operating Reactors Branch 3 82/11/17 3pp 16270 272 24X
Fiche 50-285, 82/11/17, 8212010458
- 8207080445 "Improvements in Training & Requalification Programs as Required by TMI Action Items I A 2 i & II B 4," technical evaluation rept
* Science Applications, Inc NRC-03-82-096 SA1-186-029-25, 82/07/01 NRC - No Detailed Affiliation Given 15pp 16270 275 24X Fiche 50-285, 82/11/17, 8212010458
- 8212020093 Forwards response to congressional request for info (Generic Ltr 82-22) re steam generator tube integrity Only tube-related problems addressed
JONES, W C Omaha Public Power District 82/11/22 EISENHUT, D G Division of Licensing 3pp 16272 025 24X Fiche 50-285, 82/11/22, 8212020093
- 8212020119 Notifies that util decided to pursue approval for installation of revised spent fuel storage rack design which will utilize combination of Boraflex & non-Boraflex racks Revised application will be submitted by 830101
JONES, W C Omaha Public Power District 82/11/23 CLARK, R A Operating Reactors Branch 3 2pp 16272 031 24X
Fiche 50-285, 82/11/23, 8212020119
- 8212060028 Forwards application for amend to License DPR-40, changing Tech Specs to incorporate necessary safety limits & limiting conditions for operation for Cycle B Certificate of Svc encl
* LeBoeuf, Lamb, Leiby & MacRae * Omaha Public Power District 82/11/24 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 16311 181 24X Fiche 50-285, 82/11/24, 8212060028
- 8212060032 Application for amend to License DPR-40, changing Tech Specs to incorporate necessary safety limits & limiting conditions for operation for Cycle B
JONES, W C Omaha Public Power District 82/11/22 2pp 16311 183 24X Fiche 50-285, 82/11/24, 8212060028
- 8212060035 Proposed Tech Specs re safety limits & limiting safety sys settings
* Omaha Public Power District 82/11/22 201pp 16311 185 24X
Fiche 50-285, 82/11/24, 8212060028
- 8212060438 Forwards info re evaluation of raw water pump, charging pump & containment ventilation fan motors
JONES, W C Omaha Public Power District 82/12/01 CLARK, R A Operating Reactors Branch 3 8pp 16311 001 24X
Fiche 50-285, 82/12/01, 8212060438
- 8212070419 Advises that post-accident sampling sys inoperable as of 821130, per TMI Action Item II B 3 Minor software problem identified in microprocessors during 821129 final sys checkout Sys expected to be operational by 830103
JONES, W C Omaha Public Power District 82/12/01 CLARK, R A Operating Reactors Branch 3 1p 16336 351 24X
Fiche 50-285, 82/12/01, 8212070419
- 8212060254 Forwards responses to NRC 820714 ltr re criteria for NUREG-0737, Item II B 3, "Post-Accident Sampling Sys " One oversize drawing encl Aperture card is available in PDR
JONES, W C Omaha Public Power District 82/12/03 CLARK, R A Operating Reactors Branch 3 18pp 16312 121 24X
Fiche 50-285, 82/12/03, 8212060254
- 8208190263 Generic Ltr 82-32 to all PWR licensees re potential steam generator-related generic requirements Forwards Science Applications, Inc draft rept re subj requirements Comments requested within 30 days of ltr Svc list encl
EISENHUT, D G Division of Licensing 82/12/09 Consolidated Edison Co of New York, Inc 29pp 16629 247 24X
Fiche 50-000, 82/12/09, 8208190263
- 8212140416 Forwards responses to NRC 821012 audit findings & recommendations on procedures & training re pressurized thermal shock
JONES, W C Omaha Public Power District 82/12/09 CLARK, R A Operating Reactors Branch 3 3pp 16403 315 24X
Fiche 50-285, 82/12/09, 8212140416
- 8212140103 Generic Ltr 82-28 to all licensees of operating Westinghouse & C-E PWRs (except Arkansas Nuclear One, Unit 2 & San Onofre 2 & 3) re inadequate core cooling instrumentation sys Svc list encl
EISENHUT, D G Division of Licensing 82/12/10 Yankee Atomic Electric Co 27pp 16690 035 24X Fiche 50-000, 82/12/10, 8212140103
- 821210199 Forwards response to 821013 request for addl info re NUREG-0737, TMI Action Item II K 3 25, "Power to Reactor Coolant Pump Seals " Thermal barrier HX type sys utilized
JONES, W C Omaha Public Power District 82/12/17 CLARK, R A Operating Reactors Branch 3 3pp 16484 329 24X
Fiche 50-285, 82/12/17, 821210199
- 8212280197 Provides status of NUREG-0737, Item II B 3, "Post-Accident Sampling Sys " Schedule revised to factor in need for PCB operation New schedule for operation projected 3 months following end of refueling outage
JONES, W C Omaha Public Power District 82/12/17 CLARK, R A Operating Reactors Branch 3 2pp 16562 091 24X
Fiche 50-285, 82/12/17, 8212280197
- 8212230317 Forwards application for amend to License DPR-40, allowing operation of plant at nominal reactor core level of 1,500 Mwt Class III amend fee encl
* LeBoeuf, Lamb, Leiby & MacRae 82/12/22 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 16507 310 24X
Fiche 50-285, 82/12/22, 8212230317
- 8212230326 Application to amend License DPR-40, allowing operation of plant at nominal reactor core power level of 1,500 Mwt
JONES, W C Omaha Public Power District 82/12/21 5pp 16507 311 24X Fiche 50-285, 82/12/22, 8212230317

DOCKETED ITEMS

G Inspection reports, IE Bulletins & correspondence

B208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Svc list encl
 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240

B208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list encl
 COBB, L J Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000, 82/11/05, 8208190245

B212200022 Forwards IE Insp Rept 50-285/82-23 on 820913-16 No noncompliance noted
 SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs 82/11/08 JONES, W C Omaha Public Power District 2pp 16473 095 24X Fiche 50-285, 82/11/08, 8212200022

- G212200033 IE Insp Rept 50-285/82-23 on 820913-16 No noncompliance noted Major areas inspected licensee performance & capabilities during full-scale exercise of emergency plans & procedures & review of appropriate licensee documents
 MONTGOMERY, J L, JOHNSON, W D Division of Resident, Reactor Project & Engineering Programs 82/11/04 11pp 16473 097 24X Fiche 50-285, 82/11/08, 8212200022

B212100228 Forwards IE Insp Rept 50-285/82-20 on 820907-10 No noncompliance noted
 SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs 82/11/09 JONES, W C Omaha Public Power District 2pp 16376 172 24X Fiche 50-285, 82/11/09, 8212100228

--B212100233 IE Insp Rept 50-285/82-20 on 820907-10 No noncompliance noted Major areas inspected environ protection programs for operations including organization & administration, audits & radiological environ, chemical & thermal monitoring
 WILBOR, L, CHANEY, H D, MURRAY, B Region 4, Office of Director 82/11/01 14pp 16376 174 24X Fiche 50-285, 82/11/09, 8212100228

B212030104 Forwards IE Insp Rept 50-285/82-24 on 821018-22 No noncompliance noted
 SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs 82/11/16 JONES, W C Omaha Public Power District 2pp 16303 194 24X Fiche 50-285, 82/11/16, 8212030104

--G212030112 IE Insp Rept 50-285/82-24 on 821018-22 No noncompliance noted Major areas inspected previously identified items, design changes, organization & administration, offsite support, audit program & offsite committee
 JAUDON, J P, MURPHY, M E, JOHNSON, W D Division of Resident, Reactor Project & Engineering Programs 82/11/10 7pp 16303 196 24X Fiche 50-285, 82/11/16, 8212030104

B212030119 Forwards IE Insp Rept 50-285/82-25 on 821001-31 No noncompliance noted
 SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs 82/11/17 JONES, W C Omaha Public Power District 2pp 16303 008 24X Fiche 50-285, 82/11/17, 8212030119

--B212030126 IE Insp Rept 50-285/82-25 on 821001-31 No noncompliance noted Major areas inspected operational safety verification, surveillance testing, maint & plant operations
 YANDELL, L A, JOHNSON, W D Division of Resident, Reactor Project & Engineering Programs 82/11/15 4pp 16303 010 24X Fiche 50-285, 82/11/17, 8212030119

B208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl
 JORDAN, E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 107pp 16411 199 24X Fiche 50-000, 82/11/18, 8208190251

B212070145 Ack receipt of 821101 ltr transmitting 830101 schedule for implementation of 3-yr QA audit matrix, in response to IE Performance Appraisal Rept 50-285/81-24 Schedule acceptable
 SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs 82/11/22 JONES, W C Omaha Public Power District 1p 16327 041 24X Fiche 50-285, 82/11/22, 8212070145

--B212070150 Notifies that util new QA audit matrix will be implemented by 830101, in response to IE Performance Appraisal Rept 50-285/81-24
 JONES, W C Omaha Public Power District 82/11/01 SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs 1p 16327 042 24X Fiche 50-285, 82/11/22, 8212070145

B208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list encl
 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000, 82/11/26, 8208190256

B208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl
 COBB, L J Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000, 82/11/30, 8208190257

B212060266 Forwards inservice insp program plan for 1980-1983, incorporating changes & additions since 780928 transmittal
 JONES, W C Omaha Public Power District 82/12/01 CLARK, R A Operating Reactors Branch 3 2pp 16312 318 24X Fiche 50-285, 82/12/01, 8212060266

--B212060268 Inservice insp program plan for 1980-1983
 * Omaha Public Power District 82/08/31 51pp 16312 322 24X Fiche 50-285, 82/12/01, 8212060266

B208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl
 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259

B208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl
 JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X Fiche 50-000, 82/12/03, 8208190261

B212100227 Discusses IE Emergency Preparedness Appraisal Rept 50-285/81-35 on 820915 Rept contains comments re technical support ctr operation which should be reviewed
 SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs 82/12/07 JONES, W C Omaha Public Power District 1p 16376 170 24X Fiche 50-285, 82/12/07, 8212100227

--B212100244 Advises that util officially declared permanent technical support ctr operational on 820912, in response to findings re IE Emergency Preparedness Appraisal Rept 50-285/81-35
 JONES, W C Omaha Public Power District 82/10/18 SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs 1p 16376 171 24X Fiche 50-285, 82/12/07, 8212100227

B21210021 Ack receipt of 820818 ltr responding to NRC 820625 SALP rept 50-287/81-37
 COLLINS, J T Region 4, Office of Director 82/12/14 JONES, W C Omaha Public Power District 1p 16490 191 24X Fiche 50-285, 82/12/14, 821210021

--B21210022 Responds to recommendations noted in NRC 820625 SALP Rept 50-287/81-37 Corrective actions station fire protection revised in Mar 1982 to include mgt responsibility & quarterly fire brigade drills initiated
 JONES, W C Omaha Public Power District 82/08/18 SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs 6pp 16490 192 24X Fiche 50-285, 82/12/14, 821210021

B208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16, 8208190267

B208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27 " Svc list encl
 JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X Fiche 50-000, 82/12/20, 8208190268

R Periodic operating reports & related correspondence

B212200059 Forwards monthly operating rept for Nov 1982
 JONES, W C Omaha Public Power District 82/12/13 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 1p 16473 304 24X Fiche: 50-285, 82/12/13, 8212200059

--B212200064 Monthly operating rept for Nov 1982
 MATTHEWS, T P Omaha Public Power District 82/12/10 9pp 16473 305 24X Fiche 50-285, 82/12/13, 8212200059

S Reportable occurrences, LERs & related correspondence

B712030009 Forwards LER 82-019/03L-0

JONES, W C Omaha Public Power District 82/11/23 SEIDLE, W C
Division of Resident, Reactor Project & Engineering Programs 1p
16304 226 24X Fiche 50-285, 82/11/23, 8212030009

--B212030013 LER 82-019/03L-0 on 821024, MSIVs HCV-1041A & HCV-1042A
stopped three to four degrees off seat when signaled to
close. Caused by binding between valve packing & shaft
Pacings sprayed w/penetrant oil
ABEL, S L Omaha Public Power District 82/10/28 Region 4,
Office of Director 4pp 16304 227 24X Fiche 50-285, 82/11/23,
8212030009

B212100247 PNO-1V-82-045 on 821203, plant shut down by turbine/reactor
trip. Excessive vibration of turbine reported prior to
shutdown. Caused by two damaged journal bearings on high
pressure turbine. Two wk shutdown estimated.
JOHNSON, W D, VANDELL, L A Region 4, Office of Director 82/12/06
1p 16376 049 24X Fiche 50-285, 82/12/06, 8212100247

DOCKET 50-286 INDIAN POINT STATION, UNIT 3

F Security, medical, emergency & fire protection plans

B212220006 Staff requirements memo re 821119 briefing by FEMA on status
of emergency preparedness findings. Conclusions re removal of
deficiencies & overall adequacy of emergency plans will be
submitted between 821203 & 17
CHILK, S J Office of the Secretary of the Commission 82/11/24
Office of the Secretary of the Commission 1p 16529 191 24X
Fiche 50-286, 82/11/24, 8212220006

B212060307 Ack receipt of 820902 response to NRC 820803 ltr re plans
for correcting significant deficiencies identified in FEMA
820730 rept on radiological emergency preparedness of state &
local govts
HAYNES, R C Region 1, Office of Director 82/11/26 BRONS, J C
Power Authority of the State of New York 2pp 16311 037 24X
Fiche 50-286, 82/11/26, 8212060307

B212130352 Releases public version of revised emergency plan
implementing procedures
FELTON, J M Division of Rules and Records 82/12/07 Document
Management Branch 1p 16413 084 24X Fiche 50-286, 82/12/07,
8212130352

--B212130355 Forwards public version of revised emergency plan
implementing procedures, including Procedures IP-1003 re
obtaining meteorological data & IP-1004 re MIDAS computer
sys - dose assessment models
BRONS, J C Power Authority of the State of New York 82/11/26
HAYNES, R C Region 1, Office of Director 1p 16413 085 24X
Fiche 50-286, 82/12/07, 8212130352

--B212130357 Public version of revised emergency plan implementing
procedures, including Procedures IP-1003 re obtaining
meteorological data & IP-1004 re MIDAS computer sys - dose
assessment models
LOMANACO, L M, BRONS, J C Power Authority of the State of New
York 82/11/24 73pp 16413 086 24X Fiche 50-286, 82/12/07,
8212130352

B212220234 Discusses correction to probabilistic safety study base case
fire risk & quantification of risk reduction due to
installation of alternate cabling sys per 821029 ltr
BAYNE, J P Power Authority of the State of New York 82/12/15
VAROA, S A Operating Reactors Branch 1 5pp 16518 312 24X
Fiche 50-286, 82/12/15, 8212220234

B212280084 Forwards FEMA 821217 ltr transmitting "Update Rept on Status
of Remedial Actions Cited in 820730 Interim Findings on
Adequacy of Radiological Emergency Response Preparation of
State & Local Govts at Indian Point Nuclear Power Station."
HAYNES, R C Region 1, Office of Director 82/12/17 O'TOOLE, J D
Consolidated Edison Co of New York, Inc 2pp 16557 192 24X
Fiche 50-247, 82/12/17, 8212280084

--B212280087 Forwards "Update Rept on Status of Remedial Actions Cited in
820730 Interim Findings on Adequacy of Radiological
Emergency Response Preparation of State & Local Govts at
Indian Point Nuclear Power Station."
THOMAS, L M Federal Emergency Management Agency 82/12/17
DIRCKS, W J Office of the Executive Director for Operations 3pp
16557 194 24X Fiche 50-247, 82/12/17, 8212280084

--B212280092 "Update Rept on Status of Remedial Actions Cited in 820730
Interim Findings on Adequacy of Radiological Emergency
Response Preparation of State & Local Govts at Indian Point
Nuclear Power Station."
PETRONE, F P Federal Emergency Management Agency 82/12/16
52pp 16557 197 24X Fiche 50-247, 82/12/17, 8212280084

B212280186 Forwards FEMA 821217 ltr & update rept on status of remedial
actions cited in 820730 "Interim Findings on Adequacy of
Radiological Emergency Response Preparation of State & Local
Govts at Indian Point Nuclear Power Station."
HAYNES, R C Division of Engineering & Technical Programs 82/12/17
BRONS, J C Power Authority of the State of New York 2pp
16562 199 24X Fiche 50-286, 82/12/17, 8212280186

G Adjudicatory correspondence

B212070073 Forwards Director's Decision DD-82-12, denying 10CFR2 206
petition to suspend operation immediately until FEMA
identified deficiencies corrected
DEVOUNO, R C Director's Office, Office of Inspection and
Enforcement 82/11/26 WEISS, E R Public Interest Research Group,
New York GHOLLY, S C Union of Concerned Scientists WEISS, E R
Herman & Weiss 1p 16354 353 24X Fiche 50-247, 82/11/26,
8212070073

--B212070081 Director's Decision DD-82-12, denying UCS & NY PJRG 820804
10CFR2 206 petition to suspend operation immediately until
FEMA identified deficiencies corrected
DEVOUNO, R C Director's Office, Office of Inspection and
Enforcement 82/11/26 5pp 16354 354 24X
Fiche 50-247, 82/11/26, 8212070073

B212020321 Order granting West Branch Conservation Assoc 821124
request for permission to file replies to licensee
interrogatories on Contention 2. 2a late Good cause shown
GLEASON, J P Atomic Safety and Licensing Board Panel 82/11/30
West Branch Conservation Association 2pp 16279 194 24X
Fiche 50-247, 82/11/30, 8212020321

B212070189 Motion for orders compelling discovery of utils re 820621
Interrogatories 1 - 11 & compelling NRC to produce documents
on routine & unscheduled releases of radiation Certificate
of Svc encl Related correspondence
RODRIGUEZ, P Parents Concerned About Indian Point 82/11/30
Atomic Safety and Licensing Board Panel 3pp 16333 128 24X
Fiche 50-247, 82/11/30, 8212070189

B212020318 Requests ASLB issue order modifying schedule in ASLB 821115
memorandum & order, rescheduling Westchester County testimony
from 830103 to 830110. Time between filing of testimony &
hearing commencement insufficient
MORGAN, C Power Authority of the State of New York BRANDENBURG, B
Consolidated Edison Co of New York, Inc MORGAN, C Morgan
Associates 82/12/01 GLEASON, J P, SHON, F J, PARIS, O H Atomic
Safety and Licensing Board Panel 2pp 16279 198 24X
Fiche 50-247, 82/12/01, 8212020318

B212060103 Motion to dismiss Contentions 2 j(a) & (d) re filtered
vented containment & separate containment respectively &
2 (2b) re specific pressurized thermal shock responses
w/Certificate of Svc
BRANDENBURG, B Consolidated Edison Co of New York, Inc MORGAN, C
Power Authority of the State of New York MORGAN, C Morgan
Associates 82/12/01 Atomic Safety and Licensing Board Panel
10pp 16316 123 24X Fiche 50-247, 82/12/01, 8212060103

B212060241 Memorandum & order granting util 821201 request for
postponement of hearing scheduled for wk of 830103 until wk
of 830110. Parties presenting evidence concerning in request
GLEASON, J P Atomic Safety and Licensing Board Panel 82/12/02
Consolidated Edison Co of New York, Inc 2pp 16312 265 24X
Fiche 50-247, 82/12/02, 8212060241

B212060077 Response to 820716 first set of interrogatories & request
for documents re Commission Questions 1 & 2
GHOLLY, S C, BLUM, J M Union of Concerned Scientists BLUM, J M
New York Univ 82/12/03 Office of the Executive Legal Director
14pp 16314 300 24X Fiche 50-247, 82/12/03, 8212060077

--B212060089 Notice of JF Meyer 821207 deposition in Bethesda, MD re
filtered vented containment sys Certificate of Svc encl
BLUM, J M Union of Concerned Scientists BLUM, J M New York
Univ 82/12/03 5pp 16314 313 24X Fiche 50-247, 82/12/03,
8212060077

B212070246 Motion for mod of hearing schedule, delaying hearings until
020315. Hearing dates as scheduled conflict w/830308
emergency exercise. Both NY State & Suffolk County witnesses
will be engaged in exercise Certificate of Svc encl
FEINBERG, J D New York, State of, Energy Office 82/12/03
Atomic Safety and Licensing Board Panel 8pp 16329 284 24X
Fiche 50-247, 82/12/03, 8212070246

DOCKETED ITEMS

B212090087 Forwards three ads published in listed newspapers sponsored by utility informing of safe plant operation info provided per ASLB oral directive at B20123 public hearing
BRANDENBURG, B Consolidated Edison Co of New York, Inc LEVIN, J J
Power Authority of the State of New York LEVIN, J J Morgan
Associates 82/12/03 GLEASON, J P, SHON, F J, PARIS, D H Atomic
Safety and Licensing Board Panel 3pp 16357 175 24X
Fiche 50-247, 82/12/03, B212090087

B212230337 Urges that plants not return to svc until adequacy of emergency planning & preparedness guaranteed Worst case accident could result in many thousands of fatalities
RYAN, A B New York, NY 82/12/03 PALLADINO, N J, AHEARNE, J
GILINSKY, V Commissioners 2pp 16505 132 24X
Fiche 50-247, 82/12/03, B212230337

B212070209 Response in opposition to licensee B21201 motion to dismiss contentions Requirements arising under Contention 2 2(b) should be transferred to NRC & licensees Certificate of Svc encl
FLEISHER, I S West Branch Conservation Association 82/12/04
Atomic Safety and Licensing Board Panel 3pp 16333 181 24X
Fiche 50-247, 82/12/04, B212070209

B212070213 Motion to compel discovery of Con Ed re evaluation of hybrid closed cooling sys Matl requested for Contention 2 2(a)
Certificate of Svc encl Related correspondence
FLEISHER, I S West Branch Conservation Association 82/12/04
Atomic Safety and Licensing Board Panel 2pp 16329 360 24X
Fiche 50-247, 82/12/04, B212070213

B212080310 Supplemental response to first set of interrogatories & document requests on ASLB Questions 1, 2 & 5
COLARULLI, P F Power Authority of the State of New York
COLARULLI, P F Morgan Associates 82/12/06 Union of Concerned
Scientists 35pp 16354 010 24X Fiche 50-247, 82/12/06, B212080310

B212090090 Advises of attempted contact re W Fleisher deposition Utility intend to take deposition next wk re Contention 2 2(a)
BRANDENBURG, B Consolidated Edison Co of New York, Inc
COLARULLI, P F Power Authority of the State of New York 82/12/06
FLEISHER, I S West Branch Conservation Association 1p 16357 174
24X Fiche 50-247, 82/12/06, B212090090

B212090101 Supplemental response to interrogatories on Commission Questions 1 & 2 Certificate of Svc encl
SHOLLY, S C, BLUM, J M Union of Concerned Scientists 82/12/07
Office of the Executive Legal Director 17pp 16357 284 24X
Fiche 50-247, 82/12/07, B212090101

B212100103 Memorandum & order memorializing rulings of B21203 telcon Schedule for UCS, utility & NRC modified as listed Deadline for notice of depositions of UCS witnesses for Question 1 to be negotiated
GLEASON, J P Atomic Safety and Licensing Board Panel 82/12/08
Upp 16379 105 24X Fiche 50-247, 82/12/08, B212100103

B212140423 Responses opposing West Branch Conservation Assoc B21104 application for reinstatement of Contention 2 2(d) & Assoc B21104 objection to ASLB reinstatement of Contention 2 2(b) Certificate of Svc encl
BRANDENBURG, B Consolidated Edison Co of New York, Inc MORGAN, C
Power Authority of the State of New York MORGAN, C Morgan
Associates 82/12/09 Atomic Safety and Licensing Board Panel
Upp 16404 199 24X Fiche 50-247, 82/12/09, B212140423

B212150017 Answer objecting to State of NY motion for mod of hearing schedule Change in witness testimony schedule burdensome Certificate of Svc encl
MOSENER, P Parents Concerned About Indian Point 82/12/09 Atomic
Safety and Licensing Board Panel 1p 16421 180 24X
Fiche 50-247, 82/12/09, B212150017

B212150022 Notice of concurrence w/Parents Concerned About Indian Point objection to State of NY motion to modify hearing schedule further postponement of witness testimony unwarranted & burdensome to UCS/PIRG of NY & witnesses
HOLT, J Union of Concerned Scientists HOLT, J Public Interest
Research Group, New York 82/12/09 1p 16421 231 24X
Fiche 50-247, 82/12/09, B212150022

B212130208 Order scheduling B30110 evidentiary hearing in White Plains, NY
GLEASON, J P Atomic Safety and Licensing Board Panel 82/12/10
1p 16377 015 24X Fiche 50-247, 82/12/10, B212130208

B212130252 Forwards Westchester County B21205 ltr to Commissioner Palladino re offsite emergency preparedness, to comply w/ex parte communications regulations
STUCKY, B W Docketing & Services Branch 82/12/10 Office of the
Executive Legal Director 1p 16396 230 24X Fiche 50-247,
82/12/10, B212130252

--B212130254 Urges that facilities not be restarted until emergency response plans are fully workable & implementable State of emergency planning & preparedness in Westchester County still inadequate
DEBELLO, A B Westchester County, NY 82/12/05 PALLADINO, N J
Commissioners 12pp 16396 231 24X Fiche 50-247, 82/12/10,
B212130252

B212140242 Response in opposition to State of NY motion for mod of hearing schedule moving hearing commencement on Commission Questions 3 & 4 to B30315 Extension to B30314 for testimony on questions not opposed
KAPLAN, C New York, NY 82/12/10 Atomic Safety and Licensing
Board Panel 2pp 16409 304 24X Fiche 50-247, 82/12/10, B212140242

B212140384 Notification of witnesses on Commission Question 2
BLUM, J M Union of Concerned Scientists 82/12/10 2pp
16404 320 24X Fiche 50-247, 82/12/10, B212140384

--B212140393 Notice of deposition of NRC witnesses HR Denton, SH Hanauer, RM Blund & FH Rausome re testimony to be provided Denton & Hanauer will also be examined on decision criteria & process & CRAC & CRAC2 accident consequence codes
BLUM, J M Union of Concerned Scientists 82/12/10 2pp
16404 322 24X Fiche 50-247, 82/12/10, B212140384

--B212140400 Notice of deposition of utility witnesses DC Bley, BJ Garrick, S Kaplan & DC Richardson re probabilistic safety study Certificate of Svc encl
BLUM, J M Union of Concerned Scientists 82/12/10 2pp
16404 323 24X Fiche 50-247, 82/12/10, B212140384

B212140439 Motion for leave to file encl reply to West Branch Conservation Assoc B21204 reply to licensee B21201 motion to dismiss certain contentions If Assoc had participated in telcon, utility would have orally replied
BRANDENBURG, B Consolidated Edison Co of New York, Inc LEVIN, J J
Power Authority of the State of New York LEVIN, J J Morgan
Associates 82/12/10 Atomic Safety and Licensing Board Panel
2pp 16405 249 24X Fiche 50-247, 82/12/10, B212140439

--B212140446 Reply to West Branch Conservation Assoc B21204 reply to licensee B21201 motion to dismiss certain contentions Assoc misconstrues Commission intent in establishing proceeding Contention 2 2(b) should be struck w/Certificate of Svc
BRANDENBURG, B Consolidated Edison Co of New York, Inc
LEVIN, J J Power Authority of the State of New York LEVIN, J J
Morgan Associates 82/12/10 Atomic Safety and Licensing Board
Panel 7pp 16405 251 24X Fiche 50-247, 82/12/10, B212140439

B212140451 Forwards Rockland County resolution calling for closing of plants for failure to remedy emergency planning deficiencies by expiration of 120-day clock
THORSEN, E O Rockland County, NY 82/12/10 PALLADINO, N J
Commissioners 3pp 16404 355 24X Fiche 50-247, 82/12/10,
B212140451

B212160289 Notice of I Levi, D Pisello & R Piccioni B21229 depositions in NY, NY re testimony on Commission Question 1 Certificate of Svc encl Related correspondence
BRANDENBURG, B Consolidated Edison Co of New York, Inc MORGAN, C
Power Authority of the State of New York MORGAN, C Morgan
Associates 82/12/10 6pp 16446 068 24X Fiche 50-247, 82/12/10,
B212160289

B212150116 Response to licensee B21201 motion to dismiss Contentions 2 1(a), 2 1(d) & 2 2(b) Supports dismissal of Contention 2 2(b) West Branch Conservation Assoc filings show that Assoc will not pursue issue Certificate of Svc encl
MOORE, J E Hearing Branch 1 82/12/13 Atomic Safety and
Licensing Board Panel 8pp 16427 351 24X Fiche 50-247, 82/12/13,
B212150116

B212200032 Qualifications statements for UCS/NY PIRG witnesses on Commission Question 2 Prof qualifications Certificate of Svc encl
BLUM, J M Union of Concerned Scientists 82/12/13 11pp
16473 331 24X Fiche 50-247, 82/12/13, B212200032

B212170169 Advises that NRC does not intend to seek authorization to reply to West Branch Conservation Assoc B21124 objections to reinstatement of Contention 2 2(b) No new arguments raised
MOORE, J E Hearing Branch 1 82/12/14 GLEASON, J P, PARIS, D H,
SHON, F J Atomic Safety and Licensing Board Panel, 1p 16450 221
24X Fiche 50-247, 82/12/14, B212170169

B212160375 Order requesting ASLB provide recommendations called for in CL-81-23 no later than B30729
CHILKIS, J Office of the Secretary of the Commission 82/12/15
Atomic Safety and Licensing Board Panel 1p 16442 341 24X
Fiche 50-247, 82/12/15, B212160375

DOCKETED ITEMS

111

8212170174 Response to Parents Concerned About Indian Point 821130 motion to compel discovery against utility & response opposing Parents request to file new document request on NRC Protective order requested Certificate of Svc encl
MCGURREN, H J Hearing Branch 1 82/12/15 Atomic Safety and Licensing Board Panel 5pp 16450 163 24X Fiche 50-247, 82/12/15, 8212170174

8212200097 Memorandum & order granting NRC motion for protective order re answer to UCS/NY PIRG Interrogatory 5 NRC is not required to compile list of NRC criticisms of plant probabilistic safety study nor to formulate position
GLEASON, J P Atomic Safety and Licensing Board Panel 82/12/15 Office of the Executive Legal Director 2pp 16470 140 24X Fiche 50-247, 82/12/15, 8212200097

8212220293 Reply opposing licensee 821210 motion for leave to file reply to West Branch Conservation Assoc response to licensee 821201 motion Licensee is harassing Assoc Certificate of Svc encl
FLEISHER, I S West Branch Conservation Association 82/12/15 Atomic Safety and Licensing Board Panel 3pp 16517 188 24X Fiche 50-247, 82/12/15, 8212220293

8212220220 Advises that M Kaminski inadvertently omitted from amended witness lists Order of witnesses listed Related correspondence
VETERE, L A Westchester County, NY 82/12/16 GLEASON, J P, PARIS, D H, SHON, F J Atomic Safety and Licensing Board Panel 1p 16503 001 24X Fiche 50-247, 82/12/16, 8212220220

--8212220226 Response to State of NY motion to modify hearing schedule Unnecessary to delay testimony of all other available witnesses until County & State witnesses available Certificate of Svc encl
VETERE, L A Westchester County, NY 82/12/16 Atomic Safety and Licensing Board Panel 2pp 16503 002 24X Fiche 50-247, 82/12/16, 8212220226

8212230261 Urges plants not be reopened until emergency preparedness plans adequate
BIALIK, E I New York, State of 82/12/16 PALLADINO, N Commissioners 1p 16508 188 24X Fiche 50-247, 82/12/16, 8212230261

8212230331 Forwards 821213 ltr inadvertently sent to J Hendrie Attendance at 830110 evidentiary hearing requested
MANTELL, A N Affiliation Unknown 82/12/16 PALLADINO, N Commissioners 1p 16505 157 24X Fiche 50-247, 82/12/16, 8212230331

--8212230336 Ack receipt of 821210 invitation to attend evidentiary hearing in White Plains, NY Attendance certain unless accident postpones hearing
MANTELL, A N Affiliation Unknown 82/12/16 HENDRIE, J Atomic Safety and Licensing Board Panel 1p 16505 198 24X Fiche 50-247, 82/12/16, 8212230336

8212210235 Memorandum & order memorializing 821215 & 16 telcons & dismissing Parents Concerned About Indian Point & West Branch Conservation Assoc 821130 & 1204 discovery motions
PARIS, D H Atomic Safety and Licensing Board Panel 82/12/17 Parents Concerned About Indian Point 2pp 16484 234 24X Fiche 50-247, 82/12/17, 8212210235

8212210238 Supplementation of interrogatory response, naming Question 1 witnesses Certificate of Svc encl
BLUM, J M Union of Concerned Scientists 82/12/17 5pp 16484 236 24X Fiche 50-247, 82/12/17, 8212210238

8212210320 Forwards Congressman RL Ottinger 821201 ltr to util seeking testimony before Congress re investigation Util 821203 response encl
LEVIN, J J Morgan Associates 82/12/17 PALLADINO, N J, AHEARNE, J F, GILINSKY, V Commissioners 6pp 16496 246 24X Fiche 50-247, 82/12/17, 8212210320

8212220246 Supplemental response to first set of interrogatories & document requests under Commission Question 1 Prof qualifications encl Related correspondence
HARTZMAN, R M Friends of the Earth HARTZMAN, R M New York City Audubon Society 82/12/17 Consolidated Edison Co of New York, Inc 3pp 16518 280 24X Fiche 50-247, 82/12/17, 8212220246

8212220271 Responses to interrogatories & document requests re Commission Question & Certificate of Svc encl
BRANDENBURG, B Consolidated Edison Co of New York, Inc PRATT, C M Power Authority of the State of New York PRATT, C M Morgan Associates 82/12/17 Parents Concerned About Indian Point 15pp 16517 280 24X Fiche 50-247, 82/12/17, 8212220271

8212230187 Response to motion to compel discovery re Commission Question & Certificate of Svc encl Related correspondence
BRANDENBURG, B Consolidated Edison Co of New York, Inc PRATT, C M Power Authority of the State of New York PRATT, C M Morgan Associates 82/12/17 Parents Concerned About Indian Point 14pp 16511 007 24X Fiche 50-247, 82/12/17, 8212230187

8212230235 Urges that units not be returned to svc until emergency planning concerns resolved
BRODSKY, R L Westchester County, NY DE MARCO, J W, HOCHBERG, A G Commissioners 82/12/17 PALLADINO, N J, AHEARNE, J F, GILINSKY, V Commissioners 3pp 16511 060 24X Fiche 50-247, 82/12/17, 8212230235

8212280014 Lists documents being withheld as privileged that were requested by SC Sholly (UCS) in UCS/NY PIRG first set of interrogatories & document requests on Commission Questions 1, 2 & 5 NUREG/CR-2666 forthcoming
MCGURREN, H J Hearing Branch 1 82/12/17 BLUM, J M New York Univ 2pp 16564 290 24X Fiche 50-247, 82/12/17, 8212280014

8212280285 Response in opposition to State of NY motion for mod of hearing schedule Since motion relates to scheduling of testimony within allotted time frame, no further hearing delay necessary Certificate of Svc encl
MORGAN, C Power Authority of the State of New York MORGAN, C Morgan Associates 82/12/17 Atomic Safety and Licensing Board Panel 7pp 16561 327 24X Fiche 50-247, 82/12/17, 8212280285

8212210267 Response in support of State of NY 821203 motion for mod of schedule for hearing testimony on Commission Questions 3 & 4 Extension needed in order for witnesses to participate in emergency planning exercises Certificate of Svc encl
MOORE, J E Hearing Branch 1 82/12/20 Atomic Safety and Licensing Board Panel 3pp 16489 170 24X Fiche 50-247, 82/12/20, 8212210267

8212210332 Response opposing Con Ed 821215 mailgram requesting ASLII to grant previously filed motion to dismiss Contentions 2 1(a) & 2 1(d) Prejudice caused by UCS/NY PIRG tardiness not equal to requested sanctions Certificate of Svc encl
MOORE, J E Hearing Branch 1 82/12/20 Atomic Safety and Licensing Board Panel 7pp 16497 013 24X Fiche 50-247, 82/12/20, 8212210332

8212230398 Memorandum supporting Con Ed 821215 renewed motion to dismiss UCS/NY PIRG Contentions 2 1(a) & 2 1(d) UCS continues to act immune from orders of ASLII notwithstanding Judge Paris admonition Certificate of Svc encl
MORGAN, C Power Authority of the State of New York MORGAN, C Morgan Associates 82/12/20 Atomic Safety and Licensing Board Panel 9pp 16503 223 24X Fiche 50-247, 82/12/20, 8212230398

8212230241 Strongly urges that units not be returned to svc until emergency planning concerns resolved
STEINOUTER, R, STERN, H J, GREITZER, C New York, NY 82/12/20 PALLADINO, N J, AHEARNE, J F, GILINSKY, V Commissioners 11pp 16508 145 24X Fiche 50-247, 82/12/20, 8212230241

8212230270 Urges plants not be restarted until workable emergency plan implemented
FINKE, S New York, NY 82/12/20 PALLADINO, N J Commissioners 2pp 16507 358 24X Fiche 50-247, 82/12/20, 8212230270

8212280293 Response in opposition to State of NY motion for mod of hearing schedule State did not meet heavy burden of persuasion required to extend hearings Certificate of Svc encl
BRANDENBURG, B Consolidated Edison Co of New York, Inc 82/12/20 Atomic Safety and Licensing Board Panel 6pp 16562 047 24X Fiche 50-247, 82/12/20, 8212280293

8212230181 Memorandum & order granting licensee 821210 motion to reply to West Branch Conservation Assoc (WBCA) reply to util 821201 motion to dismiss contentions Util 821201 motion to dismiss also granted WBCA motion for reinstatement denied
GLEASON, J P, SHON, F J Atomic Safety and Licensing Board Panel 82/12/21 Consolidated Edison Co of New York, Inc 7pp 16510 230 24X Fiche 50-247, 82/12/21, 8212230181

8212230188 Memorandum & order granting Parents Concerned About Indian Point 821130 request to place specified documents issued by NRC prior to 1979 into LPDR
GLEASON, J P Atomic Safety and Licensing Board Panel 82/12/21 Parents Concerned About Indian Point 6pp 16511 106 24X Fiche 50-247, 82/12/21, 8212230188

8212230358 Order extending time, until 821229, for Commission to decide whether to review IE Director 821126 denial of UCS request for action filed under 10CFR2 206
CHILK, S J Office of the Secretary of the Commission 82/12/21 1p 16511 161 24X Fiche 50-247, 82/12/21, 8212230358

DOCKETED ITEMS

B212230228 Urges FEMA update rept be given consideration in decision to reopen Facilities Large number of emergency deficiencies still remain
WENZEL, J S Affiliation Unknown 82/12/22 PALLADINO, N J, Commissioners 15pp 16511 032 24X
AHEARNE, J F, ASSELSTINE, J K
Fiche 50-247, 82/12/22, B212230228

B212270214 Decision CLI-82-38, ruling that no shutdown or enforcement action required re state of emergency planning FEMA determined that remedial action will be feasible Problems w/ local govts beyond licensee control
CHILK, S J Office of the Secretary of the Commission 82/12/22 27pp 16537 128 24X Fiche 50-247, 82/12/22, B212270214

G21280008 Forwards FEMA 821217 ltr to Ofc of Executive Director for Operations re current status of offsite emergency planning transmitting update rept w/o encl
HASSELL, D F Hearing Branch 1 82/12/22 GLEASON, J P, SHON, F J, PARIS, D H Atomic Safety and Licensing Board Panel 1p 16564 289 24X Fiche 50-247, 82/12/22, B21280008

B21280011 Advises that invoice for copying documents requested by SC Sholly on 821214 forthcoming
MOORE, J E Hearing Branch 1 82/12/22 WEISS, E R Harmon & Weiss 1p 16565 144 24X Fiche 50-247, 82/12/22, B21280011

B21270249 Order CLI-82-41, granting in part & denying in part, UCS 821008 motion to direct NRC to reschedule meeting All parties must be informed of scheduling of meetings
CHILK, S J Office of the Secretary of the Commission 82/12/23 Union of Concerned Scientists 3pp 16530 357 24X
Fiche 50-247, 82/12/23, B21270249

B21230012 Memorandum & order dismissing West Branch Conservation Assoc 821215 motion to deny licensee motion for leave to reply
Licensee motion granted, rendering instant motion moot
GLEASON, J P Atomic Safety and Licensing Appeal Panel 82/12/23 West Branch Conservation Association 2pp 16598 227 24X
Fiche 50-247, 82/12/23, B21230012

B21230014 Memorandum & order denying licensee 821201 motion & 821215 renewed motion to dismiss Contentions 2 1(a) & 2 1(d) UCS failure to meet 821210 deadline minor since delay did not prejudice parties
GLEASON, J P Atomic Safety and Licensing Board Panel 82/12/23 Consolidated Edison Co of New York, Inc 6pp 16598 218 24X
Fiche 50-247, 82/12/23, B21230014

G21280326 Forwards revised Page 3 to NRC Order CLI-82-41 & separate view of Commissioner Roberts
STUCKY, S W Docketing & Services Branch 82/12/27 Power Authority of the State of New York 1p 16562 084 24X
Fiche 50-247, 82/12/27, B21280326

--B212283332 Corrected Page 3 to NRC Order CLI-82-41 & separate view of Commissioner Roberts
CHILK, S J Office of the Secretary of the Commission 82/12/23 Union of Concerned Scientists 2pp 16562 085 24X
Fiche 50-247, 82/12/27, B212283332

G212300191 Ack receipt of summary of Steam Generator Owners Group 820729 meeting Request being filed for delay in delivering testimony on Question 2 1 in order to obtain previously inaccessible info
FLEISHER, Z S West Branch Conservation Association 82/12/27 MOORE, J E Hearing Branch 1 1p 16598 023 24X
Fiche 50-247, 82/12/27, B212300191

G212300197 Notice of continuation of Contentions 3 & 4
FLEISHER, Z S West Branch Conservation Association 82/12/27 1p 16598 024 24X Fiche 50-247, 82/12/27, B212300197

--B212300201 Request for delay in filing testimony on Question 2 1 until 830112 in order to obtain addl info Certificate of Svc encl
FLEISHER, Z S West Branch Conservation Association 82/12/27 Atomic Safety and Licensing Board Panel 2pp 16598 025 24X
Fiche 50-247, 82/12/27, B212300197

G212300230 Motion for expedited order compelling continuation of GR Thompson & SC Sholly depositions as witnesses on Contentions 2 1(a) & 2 1(d) Witness testimony incomplete Certificate of Svc encl
BRANDENBURG, B Consolidated Edison Co of New York, Inc MORGAN, C M Power Authority of the State of New York MORGAN, C M Morgan Associates 82/12/28 Atomic Safety and Licensing Board Panel 14pp 16598 004 24X Fiche 50-247, 82/12/28, B212300230

H General correspondence

B212230323 Forwards Rockland County Resolution 796 calling for closing of plants for failure to remedy emergency planning deficiencies
SEIDERMAN, V K Rockland County, NY 82/12/13 PALLADINO, N Commissioners 2pp 16505 134 24X Fiche 50-247, 82/12/13, B212230323

G212270428 Responds to 821130 ltr forwarding constituent concern re temporary suspension of hearings Approx 10 wks of hearings beginning 830110 scheduled
DIRCKS, W J Office of the Executive Director for Operations 82/12/20 BRADLEY, B Senate 2pp 16568 339 24X
Fiche 50-003, 82/12/20, B212270428

--B212270431 Forwards DK & FL Cinquemani 820730 ltr requesting resumption of hearings on safety of plants
BRADLEY, R Senate 82/11/30 Office of Congressional Affairs 5pp 16568 341 24X Fiche 50-003, 82/12/20, B212270428

D Advisory Committee on Reactor Safeguards reports & correspondence

B212070077 Forwards "Review of Indian Point Probabilistic Safety Study"
AVERY, R Argonne National Laboratory 82/10/20 OKRENT, D ACRS - Advisory Committee on Reactor Safeguards OKRENT, D California, Univ of Los Angeles 1p 16354 320 24X Fiche 50-247, 82/10/20, B212070077

--B212070083 "Review of Indian Point Probabilistic Safety Study"
AVERY, R, CHO, D H, DEITRICH, L W Argonne National Laboratory 82/09/30 ACRS - Advisory Committee on Reactor Safeguards 30pp 16354 321 24X Fiche 50-247, 82/10/20, B212070077

F Operating license stage documents & correspondence

G212090205 Forwards response to 821027 ltr re draft BNWL analysis of liquid pathway consequences due to basement penetration as presented in Indian Point probabilistic safety study
BAYNE, J P Power Authority of the State of New York O'TOOLE, J D Consolidated Edison Co of New York, Inc 82/11/29 VARGA, S A Operating Reactors Branch 1 14pp 16362 346 24X
Fiche 50-247, 82/11/29, B212090205

B212130023 Advises of proposed meeting during second wk of Dec in Bethesda, MD to discuss concerns re seismic qualification of auxiliary feedwater sys
VARGA, S A Operating Reactors Branch 1 82/12/02 SINCLAIR, L H Power Authority of the State of New York 2pp 16410 346 24X
Fiche 50-286, 82/12/02, B212130023

--B211060556 "Indian Point 3 Nuclear Power Plant, Seismic Qualification of Auxiliary Feedwater Sys," technical evaluation rept
* Lawrence Livermore Laboratory 82/10/15 NRC - No Detailed Affiliation Given 9pp 16410 348 24X Fiche 50-286, 82/12/02, B212130023

G212130030 Requests review of Unit 3 technical evaluation rept re seismic qualification of auxiliary feedwater sys Apparent discrepancies between Units 2 & 3 should be addressed
VARGA, S A Operating Reactors Branch 1 82/12/02 O'TOOLE, J D Consolidated Edison Co of New York, Inc 2pp 16417 051 24X
Fiche 50-247, 82/12/02, B212130030

B212130330 Forwards response to Congressional Subcommittee on Oversight & Investigation questionnaire on steam generator tube integrity (Generic Ltr 82-22)
BAYNE, J P Power Authority of the State of New York 82/12/03 EISENHUT, D O Division of Licensing 4pp 16389 274 24X
Fiche 50-286, 82/12/03, B212130330

B212100214 Advises that util will respond to NRC 821130 meeting request for submittal of revised versions of radiological effluent Tech Specs & offsite dose calculation manual by 830201
BAYNE, J P Power Authority of the State of New York 82/12/04 VARGA, S A Operating Reactors Branch 1 2pp 16376 079 24X
Fiche 50-286, 82/12/04, B212100214

B212100288 Forwards response to Items 2 & 4(a) of Encl 1 to 820315 ltr re control of heavy loads Responses to Items 5, 6(b) & 7 will be provided by 830301
BAYNE, J P Power Authority of the State of New York 82/12/04 VARGA, S A Operating Reactors Branch 1 14pp 16377 068 24X
Fiche 50-286, 82/12/04, B212100288

DOCKETED ITEMS

113

821210232 Forwards analyses of control room ceilings w/fragility of ceiling structures & effects of failure on core melt frequency due to seismic events, in fulfillment of 821013 commitment re probabilistic safety study
BAYNE, J P Power Authority of the State of New York 0'TOOLE, J D Consolidated Edison Co of New York, Inc 82/12/06 Operating Reactors Branch I 7pp 16390 136 24X Fiche 50-247, 82/12/06, 821210232

8212270259 Forwards nonproprietary "Indian Point Unit 3 Steam Generator Sleaving Rept." & Westinghouse Authorization CAW-82-62 Submittal supercedes 821018 Authorization CAW-82-50
BAYNE, J P Power Authority of the State of New York 82/12/06 VARGA, S A Operating Reactors Branch I 2pp 16536 273 24X Fiche 50-286, 82/12/06, 8212270259

--8212270263 Authorizes utilization of previously furnished affidavit in support of facility info re proprietary aspects of application for withholding on affidavit should ref CAW-82-62 & be addressed to author w/o encl affidavit
WIESENHANN, R A Westinghouse Electric Corp 82/10/20 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 16536 275 24X Fiche 50-286, 82/12/06, 8212270259

--8212270266 Nonproprietary "Indian Point Unit 3 Steam Generator Sleaving Rept." Proprietary info deleted
* Westinghouse Electric Corp WCAP-10146 82/09/30 21pp 16536 277 24X Fiche 50-286, 82/12/06, 8212270259

8208190263 Generic Ltr 82-32 to all PWR licensees re potential steam generator-related generic requirements Forwards Science Applications, Inc draft rept re subj requirements Comments requested within 30 days of ltr Svc list encl
EISENHUT, D O Division of Licensing 82/12/09 Consolidated Edison Co of New York, Inc 29pp 16629 247 24X Fiche 50-000, 82/12/09, 8208190263

8212140103 Generic Ltr 82-28 to all licensees of operating Westinghouse & C-E PWRs (except Arkansas Nuclear One, Unit 2 & San Onofre 2 & 3) re inadequate core cooling instrumentation sys Svc list encl
EISENHUT, D O Division of Licensing 82/12/10 Yankee Atomic Electric Co 27pp 16690 035 24X Fiche 50-000, 82/12/10, 8212140103

8212210322 Forwards "Reactor Containment Bldg Integrated Leak Rate Test, Local Leakage Rate (Type B & C) Testing" & final rept by Ebasco per 10CFR50 App J
BRONS, J C Power Authority of the State of New York 82/12/15 Office of Nuclear Reactor Regulation, Director 2pp 16496 136 24X Fiche 50-286, 82/12/15, 8212210322

--8212210323 "Reactor Containment Bldg Integrated Leak Rate Test, Local Leakage Rate (Type B & C) Testing"
* Power Authority of the State of New York 82/12/31 30pp 16496 138 24X Fiche 50-286, 82/12/15, 8212210322

--8212210324 "Reactor Containment Bldg Integrated Leak Rate Test," final rept
ORAABB, J, DILLON, P Ebasco Services, Inc (subs of Enserch Corp) 82/08/04 35pp 16496 169 24X Fiche 50-286, 82/12/15, 8212210322

8212210426 Forwards plant-specific evaluation of safety & relief valve performance re NUREG-0737, Item II D 1, per 810929 request Final piping rept expected by Apr 1983 W/two oversize drawings Aperture cards available in PDR
BAYNE, J P Power Authority of the State of New York 82/12/15 VARGA, S A Operating Reactors Branch I 22pp 16490 124 24X Fiche 50-286, 82/12/15, 8212210426

Q Inspection reports, IE Bulletins & correspondence

8208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants" Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240

8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters" Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000, 82/11/05, 8208190245

8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements" Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X Fiche 50-000, 82/11/18, 8208190251

8212030123 Forwards IE Insp Rept 50-286/82-19 on 821016-1115 Noncompliance noted
STAROSTECKI, R Division of Project & Resident Programs 82/11/19 BRONS, J C Power Authority of the State of New York 2pp 16303 309 24X Fiche 50-286, 82/11/19, 8212030123

--8212030128 IE Insp Rept 50-286/82-19 on 821016-1115 Noncompliance noted Major areas inspected shift logs & records, surveillance, maint, receipt of improperly packaged radiological mats & review of monthly operating rept
KENNY, T J, KISTER, H Division of Project & Resident Programs 82/11/17 7pp 16303 311 24X Fiche 50-286, 82/11/19, 8212030123

8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks" Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000, 82/11/26, 8208190256

8208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl" Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000, 82/11/30, 8208190257

8208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies" Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259

8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets" Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X Fiche 50-000, 82/12/03, 8208190261

8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring" Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16, 8208190267

8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27" Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X Fiche 50-000, 82/12/20, 8208190268

R Periodic operating reports & related correspondence

8212290156 Forwards monthly operating rept for Oct 1982
BRONS, J C Power Authority of the State of New York 82/11/10 Office of Resource Management, Director 1p 16582 219 24X Fiche 50-286, 82/11/10, 8212290156

--8212290160 Monthly operating rept for Oct 1982
AUTERINO, L Power Authority of the State of New York 82/11/01 6pp 16582 220 24X Fiche 50-286, 82/11/10, 8212290156

8212140064 Forwards monthly operating rept for Nov 1982
BRONS, J C Power Authority of the State of New York 82/12/09 Office of Nuclear Reactor Regulation, Director 1p 16408 306 24X Fiche 50-286, 82/12/09, 8212140064

- 8212140070 Monthly operating rept for Nov 1982
AUTERINO, L Power Authority of the State of New York 82/12/01 6pp 16408 307 24X Fiche 50-286, 82/12/09, 8212140064

S Reportable occurrences, LERs & related correspondence

8212210417 PND-I-82-081 on 821215, two nuclear electronic technicians suffered third degree burns from electrical shock while working on 6,900-volt bus work in reactor coolant pump breaker panel Caused by employee making contact w/bus
KISTER, GREENMAN Region I, Office of Director 82/12/16 1p 16493 095 24X Fiche 50-286, 82/12/16, 8212210417

T Hearing transcripts on non-antitrust matters

8212070049 Transcript of 821203 telephone conference in Washington, DC Pp 4, 856-4, 888
* Atomic Safety and Licensing Board Panel 82/12/03 33pp 16327 295 24X Fiche 50-247, 82/12/03, 8212070049

DOCKETED ITEMS

B212150008 Forwards RL Goldfarb testimony & lists order of witnesses to testify Related correspondence
 VETERE, L A Westchester County, NY 82/12/09 QLEASDN, J P
 PARIS, O H SHON, F J Atomic Safety and Licensing Board Panel 1p
 16421 130 24X Fiche 50-247, 82/12/09, 8212150008

--B212150013 Testimony of RA Goldfarb re law enforcement concerns w/
 emergency plan ASLB should consider effectiveness of
 emergency plan w/o adequate police communications sys
 Certificate of Svc encl
 GOLDFARB, R A Westchester County, NY GOLDFARB, R A Ossining, NY
 82/12/09 5pp 16421 131 24X Fiche 50-247, 82/12/09, 8212150008

B212300235 Transcript of Commission B21221 meeting in Washington, DC re
 possible action concerning emergency preparedness at
 facilities Supporting documentation & viewgraphs encl
 * Commissioners 82/12/21 121pp 16624 037 24X
 Fiche 50-286, 82/12/21, 8212300235

U Congressional/Executive Correspondence

B212230341 Requests NRC statement of Commission basis for determination
 that reasonable assurance exists that public health & safety
 will be adequately protected in event of large nuclear
 accident
 UDALL, M K House of Rep, Interior & Insular Affairs 82/12/15
 PALLADINO, N J Commissioners 2pp 16511 126 24X
 Fiche 50-247, 82/12/15, 8212230341

GP12230276 Urges consideration of all info re adequacy of emergency
 plans & current state of emergency preparedness All steps
 must be taken to ensure adequacy of emergency planning
 FISH, H, DILMAN, B, BINGHAM, J House of Rep. 82/12/20
 Commissioners 3pp 16508 277 24X Fiche 50-247, 82/12/20,
 8212230276

DOCKET 50-267 OCONEE NUCLEAR STATION, UNIT 3

F Security, medical, emergency & fire protection plans

B212130069 Forwards info on emergency offsite facilities (EOF), per
 R Birkel B21203 request & Generic Ltr 81-10 Const of
 permanent primary & backup EOF completed
 TUCKER, H B Duke Power Co 82/12/03 DENTON, H R Office of
 Nuclear Reactor Regulation, Director ADENBAM, E G Licensing Branch
 4 2pp 16390 186 24X Fiche 50-000, 82/12/03, 8212130069

GP12090044 Reviews util 820419 & 0727 ltrs re security personnel
 requalification requirements Annual supervisor observation
 considered sufficient requalification test
 STOLZ, J F Operating Reactors Branch 4 82/12/07 TUCKER, H B
 Duke Power Co 2pp 16384 244 24X Fiche 50-000, 82/12/07,
 8212090044

GP12230093 Releases public version of revision to crisis mgt plan &
 revisions to crisis mgt plan implementing procedures
 FELTON, J M Division of Rules and Records 82/12/15 Document
 Management Branch 1p 16542 026 24X Fiche 50-000, 82/12/15,
 8212230093

--B212230108 Forwards public version of Revision 7 to crisis mgt plan &
 revisions to crisis mgt plan implementing procedures
 TUCKER, H B Duke Power Co 82/12/02 DENTON, H R Office of
 Nuclear Reactor Regulation, Director ADENBAM, E G Operating
 Reactors Branch 4 2pp 16542 027 24X Fiche 50-000, 82/12/15,
 8212230093

--B212230124 Public version of Revision 7 to crisis mgt plan One oversize
 pamphlet encl Aperture card available in PDR
 VAUGHN, R E Duke Power Co 82/11/29 9pp, 16542 029 24X
 Fiche 50-000, 82/12/15, 8212230093

--B212230134 Public version of revised crisis mgt plan implementing
 procedures, including Procedures 5 3 2 re crisis news group
 plan & 5 3 11 re McGuire crisis phone directory
 VAUGHN, R E Duke Power Co 82/11/29 280pp 16542 038 24X
 Fiche 50-000, 82/12/15, 8212230093

GP12280351 Application to amend Licenses DPR-38, DPR-47 & DPR-55,
 revising App A Tech Specs to change frequency of station
 security plan & implementing procedure audits from once
 every 2 yrs to yearly
 TUCKER, H B Duke Power Co 82/12/21, DENTON, H R Office of
 Nuclear Reactor Regulation, Director 2pp 16860 087, 24X
 Fiche 50-269, 82/12/21, 8212280351

--B212280367 Proposed Tech Spec revision changing frequency of station
 security plan & implementing procedure audits from once
 every 2 yrs to yearly
 * Duke Power Co 82/12/21 1p 16560 089, 24X
 Fiche 50-269, 82/12/21, 8212280351

G Adjudicatory correspondence

B212060098 Response to interrogatories & document requests re
 Commission Questions 2 & 5 Related correspondence
 SHOLLY, S C, BLUM, J M Union of Concerned Scientists BLUM, J M
 New York Univ 82/12/02 Consolidated Edison Co of New York,
 Inc 30pp 16316 133 24X Fiche 50-247, 82/12/02, 8212060098

P Operating license stage documents & correspondence

B212010185 Forwards Amends 116, 116 & 113 to Licenses DPR-38, DPR-47 &
 DPR-55, respectively, safety evaluation & EIA & notice of
 issuance & availability Amend revises Tech Spec restrictions
 on burning low level contaminated oil
 WAGNER, P C Operating Reactors Branch 4 82/11/15 TUCKER, H B
 Duke Power Co 3pp 16271 232 24X Fiche 50-269, 82/11/15,
 8212010185

--B212010193 Amends 116, 116 & 113 to Licenses DPR-38, DPR-47 & DPR-55,
 respectively, revising Tech Spec restrictions on burning low
 level contaminated oil
 STOLZ, J F Operating Reactors Branch 4 82/11/15 8pp
 16271 235 24X Fiche 50-269, 82/11/15, 8212010185

--B212010205 Safety evaluation & EIA supporting Amends 116, 116 & 113 to
 Licenses DPR-38, DPR-47 & DPR-55, respectively
 * Office of Nuclear Reactor Regulation, Director 82/11/15 6pp
 16271 243 24X Fiche 50-269, 82/11/15, 8212010185

--B212010276 Notice of issuance & availability & negative declaration of
 Amends 116, 116 & 113 to Licenses DPR-38, DPR-47 & DPR-55,
 respectively
 STOLZ, J F Operating Reactors Branch 4 82/11/15 2pp
 16271 249 24X Fiche 50-269, 82/11/15, 8212010185

B212010392 Forwards Amends 117, 117 & 114 to Licenses DPR-38, DPR-47 &
 DPR-55, respectively, safety evaluation & notice of issuance
 & availability Amends incorporate digital logic channels &
 emergency power switching logic
 WAGNER, P C Operating Reactors Branch 4 82/11/22 TUCKER, H B
 Duke Power Co 3pp 16271 030 24X Fiche 50-269, 82/11/22,
 8212010392

--B212010418 Amends 117, 117 & 114 to Licenses DPR-38, DPR-47 & DPR-55,
 respectively, incorporating digital logic channels &
 emergency power switching logic & revising bases to define
 redundant component testing
 STOLZ, J F Operating Reactors Branch 4 82/11/22 28pp
 16271 033 24X Fiche 50-269, 82/11/22, 8212010392

--B212010421 Safety evaluation supporting Amends 117, 117 & 114 to
 Licenses DPR-38, DPR-47 & DPR-55, respectively
 * Office of Nuclear Reactor Regulation, Director 82/11/22 4pp
 16271 061 24X Fiche 50-269, 82/11/22, 8212010392

--B212010488 Notice of issuance & availability of Amends 117, 117 & 114 to
 Licenses DPR-38, DPR-47 & DPR-55, respectively
 STOLZ, J F Operating Reactors Branch 4 82/11/22 2pp
 16271 065 24X Fiche 50-269, 82/11/22, 8212010392

B212070370 Forwards license amend fee in response to 821108 ltr
 TUCKER, H B Duke Power Co 82/11/22 DIGN, R M License Fee
 Management Branch 2pp 16336 324 24X Fiche 50-269, 82/11/22,
 8212070370

B212070341 Forwards responses to NUREG-0737, Item II B 3, "Post-Accident
 Sampling Sys " W/14 oversize drawings Aperture cards are
 available in PDR
 TUCKER, H B Duke Power Co 82/12/01 DENTON, H R Office of
 Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors
 Branch 4 32pp, 16340 252 24X Fiche 50-269, 82/12/01, 8212070341.

--B212070348 "Estimate of Failed Fuel Based on I-131 Concentration"
 HULL, P, OWEN, T B Duke Power Co 82/08/03 22pp 16340 283
 24X Fiche 50-269, 82/12/01, 8212070341

--B212070392 "Post-Accident Containment Air Sampling System " W/twelve
 oversize drawings Aperture cards are available in PDR
 * Duke Power Co 82/01/29 376pp 16340 324 24X
 Fiche 50-269, 82/12/01, 8212070341

--B212070395 "Post-Accident Liquid Sampling System " W/nine oversize
 drawings Aperture cards are available in PDR
 * Duke Power Co 82/01/29 376pp 16341 053 24X
 Fiche 50-269, 82/12/01, 8212070341

DOCKETED ITEMS

115

8212100355 Summary of 821130 meeting w/util re use of Mark B2 fuel assemblies in future reload cores Viewgraphs encl
WAGNER, P C Operating Reactors Branch 4 82/12/01 Operating Reactors Branch 4 54pp 16399 041 24X Fiche 50-269, 82/12/01, 8212100355

8212150073 Requests clarification of conditional snubber operability as described in certain Tech Specs Request due to discussion in IE Insp Repts 50-269/82-37, 50-270/82-37 & 50-287/82-37
TUCKER, H B Duke Power Co 82/12/08 DENTON, H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors Branch 4 3pp 16427 339 24X Fiche 50-269, 82/12/08, 8212150073

8208190263 Generic Ltr 82-32 to all PWR licensees re potential steam generator-related generic requirements Forwards Science Applications, Inc draft rept re suby requirements Comments requested within 30 days of ltr Svc list encl
EISENHUT, D O Division of Licensing 82/12/09 Consolidated Edison Co of New York, Inc 27pp 16629 247 24X Fiche 50-000, 82/12/09, 8208190263

8212130190 Comments on status of Unresolved Safety Issue A-49 re pressurized thermal shock for facilities Recent calculations confirming that no near-term safety concern exists should be reflected in NRC rept
TUCKER, H B Duke Power Co 82/12/09 DENTON, H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors Branch 4 2pp 16396 129 24X Fiche 50-269, 82/12/09, 8212130190

8212270335 Forwards order for license mod re installation of inadequate core cooling instrumentation sys as specified in NUREG-0737, Item II F 2, "Inadequate Core Cooling"
EISENHUT, D O Division of Licensing 82/12/10 TUCKER, H B Duke Power Co 2pp 16555 338 24X Fiche 50-269, 82/12/10, 8212270335

--8212270338 Order for license mod to conform w/specs of NUREG-0737, Item II F 2 Checklist for specific review encl
EISENHUT, D O Division of Licensing 82/12/10 Duke Power Co 11pp 16555 339 24X Fiche 50-269, 82/12/10, 8212270338

8212210079 Advises that submittal of revised radiological effluent Tech Specs incorporating agreements reached during 820818-19 meetings delayed until 830131, per util 821110 commitment
TUCKER, H B Duke Power Co 82/12/15 DENTON, H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors Branch 4 1p 16485 247 24X Fiche 50-269, 82/12/15, 8212210079

8212280351 Application to amend Licenses DPR-38, DPR-47 & DPR-55, revising App A Tech Specs to change frequency of station security plan & implementing procedure audits from once every 2 yrs to yearly
TUCKER, H B Duke Power Co 82/12/21 DENTON, H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors Branch 4 2pp 16560 087 24X Fiche 50-269, 82/12/21, 8212280351

--8212280367 Proposed Tech Spec revision changing frequency of station security plan & implementing procedure audits from once every 2 yrs to yearly
* Duke Power Co 82/12/21 1p 16560 089 24X Fiche 50-269, 82/12/21, 8212280367

Q Inspection reports, IE Bulletins & correspondence

8208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants" Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240

8212090181 Forwards IE Insp Repts 50-269/82-39, 50-270/82-39 & 50-287/82-39 on 820915-1010 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 82/10/29 TUCKER, H B Duke Power Co 2pp 16359 197 24X Fiche 50-269, 82/10/29, 8212090181

--8212090189 IE Insp Repts 50-269/82-39, 50-270/82-39 & 50-287/82-39 on 820915-1010 No noncompliance noted Major areas inspected operation safety verification, maint activities, surveillance testing, startup testing & THX action item implementation
ORDER, W, FALCONER, D, BRYANT, J C Division of Project & Resident Programs 82/10/28 7pp 16359 199 24X Fiche 50-269, 82/10/29, 8212090189

8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters" Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000, 82/11/05, 8208190245

8212090420 Forwards response to IE Bulletin 82-02, "Degradation of Threaded Fasteners in RCPB of PWR Plants," Item 1 for Unit 1 & Items 2 & 4 for Unit 3 Response to Items 2 & 4 for Units 1 & 2 will be provided following next refueling outage
TUCKER, H B Duke Power Co 82/11/15 O'REILLY, J P Region 2, Office of Director 4pp 16363 033 24X Fiche 50-269, 82/11/15, 8212090420

8212060310 Grants 820830 request for relief from volumetric exams of piping welds in sections of containment sump & reactor bldg spray sys piping Safety evaluation encl
STOLZ, J F Operating Reactors Branch 4 82/11/16 TUCKER, H B Duke Power Co 6pp 16323 351 24X Fiche 50-269, 82/11/16, 8212060310

--8212060313 Notice of granting relief from ASME Code requirements for volumetric exams of piping welds in sections of containment sump & reactor bldg spray sys piping
STOLZ, J F Operating Reactors Branch 4 82/11/16 2pp 16323 357 24X Fiche 50-269, 82/11/16, 8212060310

8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements" Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X Fiche 50-000, 82/11/18, 8208190251

8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks" Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000, 82/11/26, 8208190256

8208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl" Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000, 82/11/30, 8208190257

8208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies" Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259

8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets" Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X Fiche 50-000, 82/12/03, 8208190261

8212150073 Requests clarification of conditional snubber operability as described in certain Tech Specs Request due to discussion in IE Insp Repts 50-269/82-37, 50-270/82-37 & 50-287/82-37
TUCKER, H B Duke Power Co 82/12/08 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 16427 339 24X Fiche 50-269, 82/12/08, 8212150073

8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring" Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16, 8208190267

8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27" Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16620 293 24X Fiche 50-000, 82/12/20, 8208190268

R Periodic operating reports & related correspondence

8212210421 Forwards monthly operating repts for Nov 1982
TUCKER, H B Duke Power Co 82/12/15 Director's Office, Office of Inspection and Enforcement 1p 16493 058 24X Fiche 50-269, 82/12/15, 8212210421

--8212210428 Monthly operating repts for Nov 1982
REAVIS, J A Duke Power Co 82/12/15 16pp 16493 059 24X Fiche 50-269, 82/12/15, 8212210421

S Reportable occurrences, LERs & related correspondence

8212090221 Forwards LER 82-012/017-0 Detailed event analysis encl
TUCKER, H B Duke Power Co 82/12/01 O'REILLY, J P Region 2, Office of Director 9pp 16361 342 24X Fiche 50-287, 82/12/01, 8212090221

DOCKETED ITEMS

- 8212090225 LER 82-012/017-0 on 821117 steam generator tube leak of 0.5 gpm indicated by condensate steam air ejector offgas radiation monitor. Caused by cracks in tubes 65-1, 68-4, 78-B & 83-5. Tubes removed from svc for lab analysis. MORRIS J F Duke Power Co 82/12/01 Region 2, Office of Director 1p 16351 347 24X Fiche 50-289, 82/12/01, 8212090221
- 8212150144 PJC-11-82-135 on 821211 unit shut down after discovery of 0.2 gpm leak in steam generator. No abnormal release of radioactivity associated w/ event. Unit will be out of svc approx 2 wks. 10*ATC/15 A, DANCE, H C Region 2, Office of Director 82/12/13 4pp 16430 187 24X Fiche 50-289, 82/12/13, 8212150144
- 8212300224 RD on 821213, Region 2 informed of two manual containment isolation valves discovered open. Rept providing details delayed due to investigation. Rept will be completed & submitted by 821231. TUCKER H S Duke Power Co 82/12/23 O'REILLY, J P Region 2, Office of Director 1p 16598 033 24X Fiche 50-289, 82/12/23, 8212300224
- 8212300264 RD 287/82-14 primary to secondary leak discovered in steam generator. JB Rept will not be submitted until 830107 contrary to previous commitment. TUCKER H S Duke Power Co 82/12/23 O'REILLY, J P Region 2, Office of Director 1p 16595 255 24X Fiche 50-289, 82/12/23, 8212300264
- DOCWET 50-289 THREE MILE ISLAND NUCLEAR STATION, UNIT 1
F Security, medical, emergency & fire protection plans
- 8212030193 Forwards IE Insp Rept 50-289/82-17 on 820908-10 & 1004-08 No noncompliance noted. MARTIN T Y Division of Engineering & Technical Programs 82/11/19 HUKILL, H D General Public Utilities - GPU Service Corp 2pp 16304 003 24X Fiche 50-289, 82/11/19, 8212030193
- 8212030207 IE Insp Rept 50-289/82-17 on 820908-10 & 1004-08 No noncompliance noted. Major areas inspected actions taken to resolve deficiencies identified in NUREG-0752, "Control Room Design Review Rept for TMI-1". PETERSON, C RICHARDS, S BETTENHAUSEN, L Region 1, Office of Director 82/11/17 20pp 16304 010 24X Fiche 50-289, 82/11/19, 8212030193
- 8212030215 Forwards IE Insp Rept 50-289/82-23 on 821018-22 No noncompliance noted. MARTIN T Y Division of Project & Resident Programs 82/11/19 HUKILL, H D General Public Utilities - GPU Service Corp 2pp 16307 053 24X Fiche 50-289, 82/11/19, 8212030215
- 8212030221 IE Insp Rept 50-289/82-23 on 821018-22 No noncompliance noted. Major areas inspected fire protection/prevention program including fire brigade training, ignition source & combustible matl control. FRIEDEL A E BETTENHAUSEN, L Division of Project & Resident Programs 82/11/12 7pp 16307 055 24X Fiche 50-289, 82/11/19, 8212030215
- 8212060054 Forwards Revision 16 to modified amended physical security plan. Revision withheld (ref 10CFR2.790) Extension requested to 831231 to install equipment to permit radio communications in all plant areas, eliminating dead spots. HUKILL, H D General Public Utilities - GPU Service Corp 82/11/30 24X Fiche 50-289, 82/11/30, 8212060054
- 8212070251 Forwards tabular listings "Common Encl Identification Rept Equipment" per 821105 request for justification of compliance w/ App R fire protection. HUKILL, H D General Public Utilities - GPU Service Corp 82/12/02 24X Fiche 50-289, 82/12/02, 8212070251
- 8212070253 "Common Encl Identification Rept Equipment" * General Public Utilities - GPU Service Corp 82/11/24 362pp 16333 292 24X Fiche 50-289, 82/12/02, 8212070251
- 8212160397 Forwards IE Insp Rept 50-289/82-12 on 820810-11, 1006-08 & 1103 No noncompliance noted. MARTIN T Y Division of Engineering & Technical Programs 82/12/03 HUKILL, H D General Public Utilities - GPU Service Corp 2pp 16442 346 24X Fiche 50-289, 82/12/03, 8212160397
- 8212160406 IE Insp Rept 50-289/82-12 on 820810-11, 1006-08 & 1103 No noncompliance noted. Major areas inspected emergency preparedness exercise observation, evaluation & insp. YERC, N M, CROCKER, H W Division of Emergency Preparedness & Operational Support 82/12/01 8pp 16442 348 24X Fiche 50-289, 82/12/03, 8212160397
- 8212080519 Forwards info re emergency offsite facility in response to R Jacobs 821203 telcon request Permanent backup emergency offsite facility completed. HUKILL, H D General Public Utilities - GPU Service Corp 82/12/06 24X Fiche 50-289, 82/12/06, 8212080519
- 8212200383 Forwards IE Insp Rept 50-289/82-25 on 821104, 05, 08 & 09 No noncompliance noted. MARTIN T Y Division of Engineering & Technical Programs 82/12/07 HUKILL, H D General Public Utilities - GPU Service Corp 2pp 16517 231 24X Fiche 50-289, 82/12/07, 8212200383
- 8212200388 IE Insp Rept 50-289/82-25 on 821104, 05, 08 & 09 No noncompliance noted. Major areas inspected Followup on items from IE Emergency Preparedness Appraisal Rept 50-289/81-20 on 810713-24. YERC, N M, COHEN, I, CROCKER, H W Division of Emergency Preparedness & Operational Support 82/11/30 6pp 16517 233 24X Fiche 50-289, 82/12/07, 8212200383
- 8212200415 Forwards listings of major employers within facility emergency planning zone, in response to NRC request. HUKILL, H D General Public Utilities - GPU Service Corp 82/12/08 24X Fiche 50-289, 82/12/08, 8212200415
- 8212200421 Forwards listings of hotels, motels, campgrounds & marinas within facility emergency planning zone. HUKILL, H D General Public Utilities - GPU Service Corp 82/11/16 KANTOR, F NRC - No Detailed Affiliation Given 7pp 16504 008 24X Fiche 50-289, 82/12/08, 8212200415
- 8212300141 Notification of 821223 significant licensee meeting w/ util in King of Prussia, PA to discuss 820811 emergency preparedness exercise results. KEIMIG, R R Region 1, Office of Director 82/12/20 Region 1, Office of Director 1p 16624 194 24X Fiche 50-289, 82/12/20, 8212300141
- 8212290371 Confirms 821223 meeting at Region 1 ofc to discuss 820811 emergency preparedness exercise results documented in IE Emergency Preparedness Appraisal Rept 50-289/82-12 & to solicit comments re personnel performance during exercise. STAROSTECKI, R Division of Project & Resident Programs 82/12/22 HUKILL, H D General Public Utilities - GPU Service Corp 2pp 16586 264 24X Fiche 50-289, 82/12/22, 8212290371
- G Adjudicatory correspondence
- 8212010186 Comments on immediate effectiveness of decisions & supply responses to Commission questions re TLDs. ADLER, R W Pennsylvania, State of 82/11/29 PALLADINO, N J, GILINSKY, V, AHEARNE, J F Commissioners 2pp 16258 003 24X Fiche 50-289, 82/11/29, 8212010186
- 8212010192 Opposition to Commonwealth of PA 821112 petition for review of ALAB-698, objecting to portion re dosimetry for offsite emergency workers. No important public policy question raised. ASLB & ASLAB resolved facts in consistent manner. TROWBRIDGE, O F Metropolitan Edison Co TROWBRIDGE, O F Shaw, Pittman, Potts & Trowbridge 82/11/29 Commissioners 10pp 16258 030 24X Fiche 50-289, 82/11/29, 8212010192
- 8212010200 Response to NRC 821112 petition for Commission review of ALAB-698. Licensee does not object to petition. Commission should establish schedule for filing briefs on issue raised by NRC petition Certificate of Svc encl. TROWBRIDGE, O F Metropolitan Edison Co TROWBRIDGE, O F Shaw, Pittman, Potts & Trowbridge 82/11/29 Commissioners 5pp 16258 041 24X Fiche 50-289, 82/11/29, 8212010192
- 8212010195 Response to party & public comments at Commission 821109 meeting in Harrisburg, PA. Public opinion is 100% against decision to restart at present time. Svc list encl. AAMODT, M M Aamodts, The 82/11/29 7pp 16258 046 24X Fiche 50-289, 82/11/29, 8212010195
- 8212010032 Answer opposing MM Aamodt 821115 petition for Commission review of ASLB Decision, ALAB-697, on emergency planning for farmers. Planning for farmers exceeds regulation requirements w/ Certificate of Svc. GRAY, J R Hearing Branch 4 82/11/30 Commissioners 15pp 16260 353 24X Fiche 50-289, 82/11/30, 8212010032
- 8212010034 Response to Commission 821006 order inviting parties to respond to matters raised at Commission 821109 public meeting in Harrisburg, PA re restart. NRC has no comments beyond NRC 821111 Itr Certificate of Svc encl. GOLDBERG, J R Hearing Branch 2 82/11/30 7pp 16260 346 24X Fiche 50-289, 82/11/30, 8212010034

8212020346 Forwards corrected response to public & party comments at Commission 821109 meeting in Harrisburg, PA
AAHODT, M M Aamodts, The 82/11/30 PALLADINO, N J, GILINSKY, V, AHEARNE, J F Commissioners 1p 16291 023 24X
Fiche 50-289, 82/11/30, 8212020346

--8212020401 Corrected version of response to public & party comments at Commission 821109 meeting in Harrisburg, PA Public is 100% against decision to restart plant at present time Svc list encl
AAHODT, M M Aamodts, The 82/11/29 7pp 16291 024 24X
Fiche 50-289, 82/11/30, 8212020346

8212020364 Response opposing Aamodt 821115 petition for review of portions of ALAB-697 re emergency planning for farmers
Factual issues resolved consistently by ASLB & ASLAB
Questions of public policy not raised W/Certificate of Svc
TROUBRIDGE, O F Metropolitan Edison Co TROUBRIDGE, O F Shaw, Pittman, Potts & Trowbridge 82/11/30 Commissioners 8pp
16278 130 24X Fiche 50-289, 82/11/30, 8212020364

8212020377 Comments on matters raised during 821109 oral argument before Commission ASLB findings re resolution of concerns which caused Commission to suspend OL should be affirmed
Certificate of Svc encl
TROUBRIDGE, O F Metropolitan Edison Co 82/11/30 16pp
16291 007 24X Fiche 50-289, 82/11/30, 8212020377

8212030210 Motion for extension of 10 days from date of receipt of Commonwealth of PA 821112 petition for review of ALAB-698 to respond to petition NRC was not served by Commonwealth
Certificate of Svc encl
GRAY, J R Hearing Branch 4 82/12/01 Commissioners 6pp
16304 037 24X Fiche 50-289, 82/12/01, 8212030210

8212060092 Order extending time until 821213 for Commission to act to review ALAB-699
CHILK, S J Office of the Secretary of the Commission 82/12/02 Commissioners 1p 16316 077 24X Fiche 50-289, 82/12/02, 8212060092

8212060242 Order extending time until 821208 for NRC to file response to Commonwealth of PA petition for review of ALAB-698
CHILK, S J Office of the Secretary of the Commission 82/12/03 Office of the Executive Legal Director 1p 16312 264 24X
Fiche 50-289, 82/12/03, 8212060242

8212070134 Advises of personnel changes since close of record on mgt issues, per procedure outlined in util 821001 ltr Svc list encl Related correspondence
BLAKE, E L Shaw, Pittman, Potts & Trowbridge BLAKE, E L Metropolitan Edison Co 82/12/03 EDLES, O J, RUICK, J H, KOHL, C N Atomic Safety and Licensing Appeal Panel 4pp 16327 069 24X
Fiche 50-289, 82/12/03, 8212070134

8212070165 Advises that pleadings should be served on JR Gray at listed address, not on JR Tourtellotte
WAGNER, M E Hearing Branch 4 82/12/06 Metropolitan Edison Co 1p 16335 314 24X Fiche 50-289, 82/12/06, 8212070165

8212070170 Discusses 821203 meeting w/FEMA & Dauphin County, PA Board of Commissioners re Dauphin County May 1982 nonbinding referendum on restart, comments made at Commission 821109 meeting & emergency planning
DENTON, H R Office of Nuclear Reactor Regulation, Director 82/12/06 PALLADINO, N J, GILINSKY, V, AHEARNE, J Commissioners 1p 16335 298 24X Fiche 50-289, 82/12/06, 8212070170

8212070183 Order extending time until 830114 for Commission to act to review ALAB-697 & ALAB-698
CHILK, S J Office of the Secretary of the Commission 82/12/06 Commissioners 1p 16335 262 24X Fiche 50-289, 82/12/06, 8212070183

8212090502 Motion to defer consideration of Commonwealth of PA petition for partial review of ALAB-698, until 830117 Substantial agreement in principle reached on issue of personnel dosimetry requirements W/Certificate of Svc
ADLER, R W Pennsylvania, State of 82/12/06 Commissioners 5pp 16365 327 24X Fiche 50-289, 82/12/06, 8212090502

8212090242 Answer opposing Commonwealth of PA 821112 petition for Commission review of ALAB-698 on dosimetry for emergency workers Through use of self-reading dosimeters & procedures, workers adequately protected Certificate of Svc encl
GRAY, J R Hearing Branch 4 82/12/08 Commissioners 15pp
16363 229 24X Fiche 50-289, 82/12/08, 8212090242

8212140432 Decision ALAB-705, affirming LBP-81-60 which rejected UCS Contention 20 re analysis of environ effects of Class 9 accidents Commission 800613 policy statement on Class 9 accidents applicable Judge Edles dissenting opinion encl
SHOENAKER, C J Atomic Safety and Licensing Appeal Panel 82/12/10 43pp 16405 155 24X Fiche 50-289, 82/12/10, 8212140432

8212150045 Order extending time until 821220 for Commission to act to review ALAB-699
CHILK, S J Office of the Secretary of the Commission 82/12/13 Commissioners 1p 16422 330 24X Fiche 50-289, 82/12/13, 8212150045

8212160271 Motion for partial withdrawal of Commonwealth of PA exceptions as moot Exception 1 as applied to Operator G should be withdrawn Exception 3 should be withdrawn conditioned on ASLAB approval of licensee offer
ADLER, R W Pennsylvania, State of 82/12/13 Atomic Safety and Licensing Appeal Panel 5pp 16442 358 24X Fiche 50-289, 82/12/13, 8212160271

8212160297 Forwards memos of telcons w/citizens re restart
STUCKY, S W Docketing & Services Branch 82/12/15 Office of the Executive Legal Director 4pp 16446 064 24X
Fiche 50-289, 82/12/15, 8212160297

8212120272 Reply to licensee response to 821109 oral argument
Licensee assertions & argument were made in licensee response for first time No sufficient reliable means of DHR exists Certificate of Svc encl
WEISS, E R Union of Concerned Scientists WEISS, E R Harmon & Weiss 82/12/16 9pp 16483 235 24X Fiche 50-289, 82/12/16, 8212120272

8212120336 Forwards corrected Page 3 to UCS 821216 reply to licensee response to 821109 oral arguments
WEISS, E R Harmon & Weiss WEISS, E R Union of Concerned Scientists 82/12/17 PALLADINO, N J, AHEARNE, J, ASSELSTINE, J Commissioners 1p 16496 335 24X Fiche 50-289, 82/12/17, 8212120336

--8212120339 Corrected Page 3 to UCS 821216 reply to licensee response to 821109 oral arguments
* Union of Concerned Scientists 82/12/17 Commissioners 1p 16496 336 24X Fiche 50-289, 82/12/17, 8212120336

8212220266 Order extending time until 821229 for Commission to act to review ALAB-699
CHILK, S J Office of the Secretary of the Commission 82/12/20 Commissioners 1p 16517 362 24X Fiche 50-289, 82/12/20, 8212220266

8212270008 Response supporting Commonwealth of PA 821206 motion to defer consideration of Commonwealth 821112 petition for partial review of ALAB-698 Agreement negotiations underway
Certificate of Svc encl
GRAY, J R Hearing Branch 4 82/12/22 Commissioners 17pp
16598 300 24X Fiche 50-289, 82/12/22, 8212270008

8212300008 Request for extension until 830107 to provide comments on Commission 821217 meeting Delay necessary due to counsel absence & need to analyze NRC generic ltr on emergency feedwater sys & util responses Certificate of Svc encl
WEISS, E R Union of Concerned Scientists WEISS, E R Harmon & Weiss 82/12/27 Commissioners 4pp 16598 132 24X
Fiche 50-289, 82/12/27, 8212300008

8212300002 Petition for review of ALAB-705, upholding ASLB rejection of UCS Contention 20 re NEPA evaluation of Class 9 accident NRC policy statement requires analysis of Class 9 accident in preceding Certificate of Svc encl
WEISS, E R Union of Concerned Scientists WEISS, E R Harmon & Weiss 82/12/28 Commissioners 11pp 16598 153 24X
Fiche 50-289, 82/12/28, 8212300002

8212300142 Order granting UCS 821227 request for extension until 830107 to file comments on Commission 821217 meeting Extension granted to all parties
CHILK, S J Office of the Secretary of the Commission 82/12/29 Union of Concerned Scientists 1p 16597 328 24X
Fiche 50-289, 82/12/29, 8212300142

8212300147 Memorandum & order ALAB-708, reopening record to clarify adequacy of core DHR in event of loss of main feedwater or small break LOCA All testimony due by 830126 Evidentiary hearing will commence on 830208 Briefs due by 830228
TOMPKINS, B A Atomic Safety and Licensing Appeal Panel 82/12/29 45pp 16597 283 24X Fiche 50-289, 82/12/29, 8212300147

DOCKETED ITEMS

B212300242 Forwards corrected copy of petition for review of ALAB-705, filed B21228 Original filed w/o pages numbered & w/some typographical errors W/O encl
WEISS, E R Harmon & Weiss WEISS, E R Union of Concerned Scientists 02/12/29 Atomic Safety and Licensing Board Panel
1p 16595 276 24X Fiche 50-289, 02/12/29, B212300242

B212300246 Comments on Commission B21217 meeting re LLL technical evaluation rept on seismic qualification of auxiliary feedwater sys Comments confirmed in util B21220 ltr to NRC Certificate of Svc encl
TROWBRIDGE, O F Metropolitan Edison Co 02/12/29 App 16595 235 24X Fiche 50-289, 02/12/29, B212300246

B212300250 Response in opposition to UCS B21227 request for extension of time to provide comments on Commission B21217 meeting Insufficient cause shown for delay Certificate of Svc encl
TROWBRIDGE, O F Metropolitan Edison Co TROWBRIDGE, O F Shaw, Pittman, Potts & Trowbridge 02/12/29 Commissioners 7pp 16595 266 24X Fiche 50-289, 02/12/29, B212300250

B212300362 Petition for review of B21213 Decision ALAB-705, which rejects UCS Contention 20 & calls for public assessment of risk Case appropriate for Commission review Certificate of Svc encl
WEISS, E R Union of Concerned Scientists WEISS, E R Harmon & Weiss 02/12/29 Commissioners 11pp 16594 243 24X Fiche 50-289, 02/12/29, B212300362

II General correspondence

B212070062 Responds to B21018 ltr forwarding constituents K & M Scott B21019 ltr re sirens in prompt public notification sys FEMA & local govt agencies should be contacted
DIRKS, W J Office of the Executive Director for Operations 02/11/18 OODLING, B House of Rep App 16356 259, 24X Fiche 50-289, 02/11/18, B212070062

--B212070068 Requests views & comments on constituents K & B Conner B21019 ltr re sirens in prompt public notification sys
OODLING, B House of Rep 02/10/18 KAMMERER, C Office of Congressional Affairs 2pp 16356 265 24X Fiche 50-289, 02/11/18, B212070062

B212080280 Demands Commission order permanent closing of plant ONDRASIK, M, HOLZ, J Public Interest Research Group, New York 02/12/01 PALLADINO, N J, AHEARNE, J, OILINSKY, V Commissioners 2pp 16354 211 24X Fiche 50-289, 02/12/01, B212080280

B212070027 Expounds on NRC B20809 ltr re performance of steam generators in event of transients &/or accidents Preliminary info indicates max tube to tube sheet difference in temp during worst case accident will be less than 30 F
EISENHUT, D O Division of Licensing 02/12/02 LEWIS, M I Lewis, M 1p 16356 280 24X Fiche 50-289, 02/12/02, B212070027

P Operating license stage documents & correspondence

B212270038 Forwards "THI-1 Recovery Regenerative Neutron Source Retainer Exam," Exam of THI-1 Reactor Vessel O-Ring & Control Rod Drive Mechanism Closure Insert, "Final rept & "Final Rept on Failure Analysis of Inconel 600 Tubes" MCCRACKEN, C Chemical Engineering Branch 02/10/27 BENARDY, V Chemical Engineering Branch 1p 16549 001 24X Fiche 50-289, 02/10/27, B212270038

- B212270042 "THI-1 Recovery Regenerative Neutron Source Retainer Exam" MCINTER, W A, BAIN, G M Babcock & Wilcox Co RDD 03 5489 01 02/05/20 22pp 16549 002 24X Fiche 50-289, 02/10/27, B212270038

--B212270047 "Exam of THI-1 Reactor Vessel O-Ring & Control Rod Drive Mechanism Closure Insert," final rept
BATT, D L Babcock & Wilcox Co, RDD 03 5490/5491 02 02/06/03 74pp 16549 024 24X Fiche 50-289, 02/10/27, B212270038

--B212270056 "Final Rept on Failure Analysis of Inconel 600 Tubes from Once Through Steam Generator A & B of THI-1" W/ three oversize figures Aperture cards are available in PDR
AGRAWAL, A K, STEIGELMEYER, W, BERRY, W E Battelle Memorial Institute, Columbus Laboratories 02/06/30 132pp 16549 100 24X Fiche 50-289, 02/10/27, B212270038

B212060147 Requests comments on encl technical evaluation rept re Multi-Plant Action Plan C-14, "Seismic Qualification of Auxiliary Feedwater Sys," for facility Present sys unlikely to withstand SSE Comments & addl info needed by B21220
STOLZ, J F Operating Reactors Branch 4 02/11/16 HUKILL, H D General Public Utilities - GPU Service Corp 13pp 16325 341 24X Fiche 50-289, 02/11/16, B212060147

B212010342 Advises that radiological field operations training program per util B20229 ltr acceptable suby to incorporation of certain experience requirements for radiological control foremen & technicians Safety evaluation forwarded
STOLZ, J F Operating Reactors Branch 4 02/11/17 HUKILL, H D General Public Utilities - GPU Service Corp 3pp 16271 324 24X Fiche 50-289, 02/11/17, B212010342

--B212010347 Safety evaluation supporting radiological field operations training program suby to listed mode
* Office of Nuclear Reactor Regulation, Director 02/11/17 2pp 16271 327 24X Fiche 50-289, 02/11/17, B212010342

B212270041 Board-Notification B2-118 forwards B21103 technical evaluation rept, "THI-1 Seismic Qualification of Auxiliary Feedwater Sys," re hearing on issue of emergency feedwater sys reliability
LAINAS, O C Assistant Director for Operating Reactors 02/11/22 Atomic Safety and Licensing Appeal Panel 5pp 16593 343 24X Fiche 50-289, 02/11/22, B212270041

--B21110403 Forwards "Seismic Qualifications of Auxiliary Feedwater Sys," technical evaluation rept, submitted in response to Multiplant Action Item C-14 per Generic Ltr B1-14 Condenser hotwell supply lines seismic capability questionable
MIRALIA, F J Assistant Director for Safety Assessment 02/11/07 LAINAS, O C Assistant Director for Operating Reactors 11pp 16593 348 24X Fiche 50-289, 02/11/22, B212270041

B212060508 Summary of B21018-19 meetings w/util re steam generator recovery program
JACQUES, R H Operating Reactors Branch 4 02/11/23 Operating Reactors Branch 4 108pp 16344 020 24X Fiche 50-289, 02/11/23, B212060508

B212090284 Forwards application for amend to License DPR-50, proposing Tech Spec Change Request 119 extending current Tech Spec requirements to provide NRC more detailed info on aircraft movements
HUKILL, H D General Public Utilities - GPU Service Corp 02/11/30 STOLZ, J F Operating Reactors Branch 4 2pp 16365 104 24X Fiche 50-289, 02/11/30, B212090284

--B212090293 Application for amend to License DPR-50, proposing Tech Spec Change Request 119, extending current Tech Spec requirements to provide NRC more detailed info on aircraft movements Description of change & Certificate of Svc encl
HUKILL, H D General Public Utilities - GPU Service Corp 02/11/30 3pp 16365 108 24X Fiche 50-289, 02/11/30, B212090284

--B212090277 Proposed Tech Spec Page 6-13 re rept of aircraft movements
* General Public Utilities - GPU Service Corp 02/11/30 1p 16365 109 24X Fiche 50-289, 02/11/30, B212090284

B212090501 Forwards "Pressurizer Relief Sys Piping & Support Evaluation Rept for THI-1" Rept fulfills requirement of NUREG-0737, Item 11 d, "Relief & Safety Valve Testing"
HUKILL, H D General Public Utilities - GPU Service Corp 02/11/03 EISENHUT, D O Division of Licensing 3pp 16364 123 24X Fiche 50-289, 02/12/03, B212090501

--B212090508 "THI-1 Pressurizer Relief Sys - Piping & Support Evaluation Rept"
* General Public Utilities - GPU Service Corp 02/11/29 50pp 16364 123 24X Fiche 50-289, 02/12/03, B212090501

B212130281 Board Notification B2-125 Forwards info re recent ACNH evaluation of PWR flow blockage during natural circulation
EISENHUT, D O Division of Licensing 02/12/06 PALLADINO, N, OILINSKY, V, AHEARNE, J Commissioners 3pp 16418 251 24X Fiche 50-000, 02/12/06, B212130281

B212130104 Forwards summary of Test Procedure TP 664/2, Section 9.5, "Determination of Saturation Margin & RCS Pressure vs Time Following Simulated Loss of Pressurized Heaters," to fulfill B1214 partial initial decision requirements
HUKILL, H D General Public Utilities - GPU Service Corp 02/12/07 STOLZ, J F Licensing Branch 4 HAYNES, R C Region 1, Office of Director 6pp 16390 179 24X Fiche 50-289, 02/12/07, B212130104

B212140466 Notifies that interservice pump & valve testing program upgrade will reflect Section XI, Div 1, of ASME Boiler Pressure Vessel Code, permitting pump testing to be performed quarterly rather than monthly
HUKILL, H D General Public Utilities - GPU Service Corp 02/12/07 STOLZ, J F Operating Reactors Branch 4 1p 16404 348 24X Fiche 50-289, 02/12/07, B212140466

0208190263 Generic Ltr 02-32 to all PWR licensees re potential steam generator-related generic requirements Forwards Science Applications, Inc draft rept re subj requirements Comments requested within 30 days of ltr Bvc list encl
EISENHUT, D O Division of Licensing 02/12/09 Consolidated
Edison Co of New York, Inc 29pp 16629 247 24X
Fiche 50-000, 02/12/09, 0208190263

0212230020 Board Notification 02-118A forwards info re seismic capability of auxiliary feedwater sys
EISENHUT, D O Division of Licensing 02/12/09 PALLADINO, N J ,
GILINSKY, V , AHEARNE, J F Commissioners 4pp 16540 294 24X
Fiche 50-209, 02/12/09, 0212230020

-0212090005 Responds to 021119 request to review LLL technical evaluation rept re seismic capability of auxiliary feedwater sys QC Lainas 021122 board notification memo also reviewed Testimony on hearing unchanged
MATTSON, R J Division of Systems Integration (post 011005)
02/12/03 EISENHUT, D O Division of Licensing 1p 16540 29H
24X Fiche 50-209, 02/12/09, 0212230020

--0212230033 Forwards Miraglia 021103 memo w/LLL rept re seismic qualification of auxiliary feedwater sys Board notification needed Restart hearing record did not include low probability natural events
EISENHUT, D O Division of Licensing 02/11/19 MATTSON, R
Division of Systems Integration (post 011005) VOLLNER, R
Division of Engineering 1p 16540 297 24X
Fiche 50-209, 02/12/09, 0212230033

0212230049 Board Notification 02-125A forwards info re PWR flow blockage info suppl Board Notification 02-125
EISENHUT, D O Division of Licensing 02/12/09 PALLADINO, N J ,
GILINSKY, V , AHEARNE, J F Commissioners 3pp 16545 330 24X
Fiche 50-000, 02/12/09, 0212230049

--0212230058 Forwards Fraley 021207 memo re flow blockage by steam during natural circulation in PWRs
EISENHUT, D O Division of Licensing 02/12/09 LAINAS, O
Assistant Director for Operating Reactors 1p 16545 341 24X
Fiche 50-000, 02/12/09, 0212230049

0212230070 Board Notification 02-129 forwards info re reporting of aircraft movements at Harrisburg Airport & computation of aircraft crash probabilities by util
EISENHUT, D O Division of Licensing 02/12/09 PALLADINO, N J ,
GILINSKY, V , AHEARNE, J F Commissioners 3pp 16545 217 24X
Fiche 50-209, 02/12/09, 0212230070

0212140180 Updates 021124 response to Generic Ltr 02-22, "Steam Generator Tube Integrity " Exposure estimate will be higher than previously indicated
CLARK, P R General Public Utilities - GPU Service Corp 02/12/10
EISENHUT, D O Division of Licensing 2pp 16410 208 24X
Fiche 50-209, 02/12/10, 0212140180

0212150110 Forwards SER for return to svc after repair of steam generators Final plans for steam generator & RCS cleanup & results of post-repair testing will be addressed at later date Affidavit encl Rept withheld (ref 10CFR2 790)
CLARK, P R General Public Utilities - GPU Service Corp 02/12/10
EISENHUT, D O Division of Licensing 2pp 16430 330 24X
Fiche 50-209, 02/12/10, 0212150110

- 0212150113 Affidavit of JH Taylor re SER for return to svc after repair of steam generators B&W info considered proprietary
TAYLOR, J H Babcock & Wilcox Co 02/12/03 7pp 16430 340 24X
Fiche 50-209, 02/12/10, 0212150110

0212230023 Forwards order modifying License DPR-50, requiring installation of inadequate core cooling instrumentation sys conforming to design parameters in NUREG-0737, Item II F 2
EISENHUT, D O Division of Licensing 02/12/10 HUKILL, H D
General Public Utilities - GPU Service Corp 4pp 16546 027 24X
Fiche 50-209, 02/12/10, 0212230023

--0212230030 Order modifying License DPR-50, requiring installation of inadequate core cooling instrumentation sys conforming to design parameters in NUREG-0737, Item II F 2
EISENHUT, D O Division of Licensing 02/12/10 General Public
Utilities - GPU Service Corp 11pp 16546 031 24X
Fiche 50-209, 02/12/10, 0212230030

0212170119 Forwards summary status rept for items requiring NRC certification prior to restart per 790809 order & notice of hearings Items not related to 790809 order, but requiring verification of completion, also encl
ARNOLD, R C General Public Utilities - GPU Service Corp 02/12/14
DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp
16450 300 24X Fiche 50-209, 02/12/14, 0212170119

0212210017 Informs that revisions to NUREG-0737, Item I A 1 3 re staff working hours will be included in Tech Spec change request per 020619 Generic Ltr 02-12 Revision expected by Jan 1993
HUKILL, H D General Public Utilities - GPU Service Corp 02/12/16
EISENHUT, D O Division of Licensing 1p 16490 162 24X
Fiche 50-209, 02/12/16, 0212210017

0212270134 Forwards response to Generic Ltr 02-16 re Tech Specs required by NUREG-0737 items
HUKILL, H D General Public Utilities - GPU Service Corp 02/12/17
EISENHUT, D O Division of Licensing 3pp 16538 017 24X
Fiche 50-209, 02/12/17, 0212270134

0212270268 Forwards responses to issues addressed in 021116 technical evaluation rept for seismic qualification of emergency feedwater sys All identified long-term sys mods will be completed by next refueling outage
HUKILL, H D General Public Utilities - GPU Service Corp 02/12/20
STOLZ, J F Operating Reactors Branch 4 5pp 16530 313 24X
Fiche 50-209, 02/12/20, 0212270268

0212290197 Advises that util has issued Revision 9 to Section 7.3 of Corrective Maint Procedure MP 1407-1 re potential for work on non-QC component to effect nuclear safety, fulfilling intent of 010827 ASLB partial initial decision
HUKILL, H D General Public Utilities - GPU Service Corp 02/12/21
STOLZ, J F Operating Reactors Branch 4 1p 16570 147 24X
Fiche 50-209, 02/12/21, 0212290197

0212300335 Board Notification 02-133 forwards JF Stol 021210 ltr & B&W based on encl nonproprietary & proprietary "Review of Licensee Resolution of Outstanding Issues From NRC Equipment Environ Qualification SERs (F-11 & B-60), TH1-1," Vols 1 & 2
EISENHUT, D O Division of Licensing 02/12/27 PALLADINO, N J ,
GILINSKY, V , ASSELSTINE, J K Commissioners 7pp 16597 211 24X
Fiche 50-209, 02/12/27, 0212300335

--0212300339 Forwards SER based on "Review of Licensee Resolution of Outstanding Issues From NRC Equipment Environ Qualification SERs (F-11 & B-60), TH1-1," Vols 1 & 2 Proprietary rept withheld (ref 10CFR2 790)
STOLZ, J F Operating Reactors Branch 4 02/12/10 HUKILL, H D
General Public Utilities - GPU Service Corp 2pp 16597 210 24X
Fiche 50-209, 02/12/27, 0212300339

--0212300342 SER supporting continued operation pending completion of licensee environ qualification program based on "Review of Licensee Resolution of Outstanding Issues From NRC Equipment Environ Qualification SERs (F-11 & B-60), TH1-1," Vols 1 & 2
* Office of Nuclear Reactor Regulation, Director 02/12/10 6pp
16597 217 24X Fiche 50-209, 02/12/27, 0212300339

- 0212300348 Nonproprietary "Review of Licensee Resolution of Outstanding Issues From NRC Equipment Environ Qualification SERs (F-11 & B-60), TH1-1," technical evaluation rept, Vols 1 & 2
PANDEY, S Franklin Institute/Franklin Research Center
NRC-02-79-110 TCR-C5257-92 02/11/03 GILMANSKI, P NRC No
Detailed Affiliation Given 040pp 16597 223 24X
Fiche 50-209, 02/12/27, 0212300339

0 Inspection reports, IE Bulletins & correspondence

0208190240 IE Bulletin 02-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel Recirculation Sys Piping at BWR Plants " Bvc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 02/10/20 Consolidated Edison Co of New York, Inc
112pp 16462 163 24X Fiche 50-000, 02/10/20, 0208190240

0208190245 IE Info Notice 02-42, "Defects Observed in Panasonic Model 001 & Model 002 Thermoluminescent Dosimeters " Bvc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards
02/11/03 Consolidated Edison Co of New York, Inc 110pp
16372 142 24X Fiche 50-000, 02/11/03, 0208190245

0208190251 IE Info Notice 02-44, "Clarification of Emergency Plan Exercise Requirements " Bvc list encl
JORDAN, C L Division of Engineering & Quality Assurance 02/11/10
Consolidated Edison Co of New York, Inc 107pp 16411 199 24X
Fiche 50-000, 02/11/10, 0208190251

0212030193 Forwards IE Insp Rept 50-209/02-17 on 020908-10 & 1004-00 Noncompliance noted
MARTIN, T T Division of Engineering & Technical Programs 02/11/19
HUKILL, H D General Public Utilities - GPU Service Corp 2pp
16304 008 24X Fiche 50-209, 02/11/19, 0212030193

DOCKETED ITEMS

--B212030207 IE Insp Rept 50-289/82-17 on B20908-10 & 1004-08 No noncompliance noted Major areas inspected actions taken to resolve deficiencies identified in NUREG-0752, "Control Room Design Review Rept for TMI-1"
PETRONI, C., RICHARDS, S., BETTENHAUSEN, L. Region 1, Office of Director 82/11/17 20pp 16304 010 24X Fiche 50-289, 82/11/19, B212030193

B212030215 Forwards IE Insp Rept 50-289/82-23 on B21018-22 No noncompliance noted
MARTIN, T. T. Division of Project & Resident Programs 82/11/19
HUKILL, H. D. General Public Utilities - GPU Service Corp 2pp 16307 053 24X Fiche 50-289, 82/11/19, B212030215

--B212030221 IE Insp Rept 50-289/82-23 on B21018-22 No noncompliance noted Major areas inspected fire protection/prevention program, including fire brigade training, ignition source & combustible matl control
FINKEL, A. E., BETTENHAUSEN, L. Division of Project & Resident Programs 82/11/12 7pp 16307 055 24X Fiche 50-289, 82/11/19, B212030215

B208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list encl
DEVOUNO, R. C. Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co. of New York, Inc 127pp 16411 065 24X Fiche 50-000, 82/11/26, B208190256

B208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl
CARR, L. I. Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co. of New York, Inc 356pp 16397 028 24X Fiche 50-000, 82/11/30, B208190257

B208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl
DEVOUNO, R. C. Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co. of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, B208190259

B208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co. of New York, Inc 110pp 16462 064 24X Fiche 50-000, 82/12/03, B208190261

G212160397 Forwards IE Insp Rept 50-289/82-12 on B20810-11, 1006-08 & 1103 No noncompliance noted
MARTIN, T. T. Division of Engineering & Technical Programs 82/12/03
HUKILL, H. D. General Public Utilities - GPU Service Corp 2pp 16442 346 24X Fiche 50-289, 82/12/03, B212160397

--B212160406 IE Insp Rept 50-289/82-12 on B20810-11, 1006-08 & 1103 No noncompliance noted Major areas inspected emergency preparedness exercise observation, evaluation & insp
TERC, N. M., CROCKER, H. W. Division of Emergency Preparedness & Operational Support 82/12/01 8pp 16442 348 24X Fiche 50-289, 82/12/03, B212160397

B212220383 Forwards IE Insp Rept 50-289/82-25 on B2104, 05, 08 & 09 No noncompliance noted
MARTIN, T. T. Division of Engineering & Technical Programs 82/12/07
HUKILL, H. D. General Public Utilities - GPU Service Corp 2pp 16517 231 24X Fiche 50-289, 82/12/07, B212220383

--B212220388 IE Insp Rept 50-289/82-25 on B2104, 05, 08 & 09 No noncompliance noted Major areas inspected followup on items from IE Emergency Preparedness Appraisal Rept 50-289/81-20 on 810713-24
TERC, N. M., COHEN, I., CROCKER, H. W. Division of Emergency Preparedness & Operational Support 82/11/30 6pp 16517 233 24X Fiche 50-289, 82/12/07, B212220383

B212220459 Forwards IE Insp Rept 50-289/82-21 on B21005-1108 & notice of violation
STAROSTECKI, R. Division of Project & Resident Programs 82/12/09
HUKILL, H. D. General Public Utilities - GPU Service Corp 2pp 16504 264 24X Fiche 50-289, 82/12/09, B212220459

--B212220469 Notice of violation from insp on B21005-1108
* Division of Project & Resident Programs 82/12/09 1p 16504 266 24X Fiche 50-289, 82/12/09, B212220459

--B212220478 IE Insp Rept 50-289/82-21 on B21005-1108 Noncompliance noted failure to perform safety evaluation
CONTER, J., THANUS, L., YOUNG, F. Division of Project & Resident Programs 82/12/09 10pp 16504 267 24X Fiche 50-289, 82/12/09, B212220459

B212220464 Forwards IE Insp Rept 50-289/82-22 on B21012-28 & notice of violation
STAROSTECKI, R. Division of Project & Resident Programs 82/12/09
HUKILL, H. D. General Public Utilities - GPU Service Corp 2pp 16504 034 24X Fiche 50-289, 82/12/09, B212220464

--B212220467 Notice of violation from insp on B21012-28
* Division of Project & Resident Programs 82/12/09 1p 16504 036 24X Fiche 50-289, 82/12/09, B212220464

--B212220471 IE Insp Rept 50-289/82-22 on B21012-28 Noncompliance noted failure to perform adequate radiation survey
O'NEILL, B., BARR, K., FABANO, A. Division of Project & Resident Programs 82/11/29 11pp 16504 037 24X Fiche 50-289, 82/12/09, B212220464

B208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
DEVOUNO, R. C. Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co. of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16, B208190267

B208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27 " Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co. of New York, Inc 108pp 16628 293 24X Fiche 50-000, 82/12/20, B208190268

B212290371 Confirms B21223 meeting at Region 1 ofc to discuss B20811 emergency preparedness exercise results documented in IE Emergency Preparedness Appraisal Rept 50-289/82-12 & to solicit comments re personnel performance during exercise
STAROSTECKI, R. Division of Project & Resident Programs 82/12/22
HUKILL, H. D. General Public Utilities - GPU Service Corp 2pp 16586 264 24X Fiche 50-289, 82/12/22, B212290371

R Periodic operating reports & related correspondence

G21210232 Forwards monthly operating rept for Nov 1982
HUKILL, H. D. General Public Utilities - GPU Service Corp 82/12/15
Division of Data Automation & Management Information 1p 16484 072 24X Fiche 50-289, 82/12/15, B21210232

--B21210234 Monthly operating rept for Nov 1982
SMYTH, C. W. General Public Utilities - GPU Service Corp 82/12/15 6pp 16484 074 24X Fiche 50-289, 82/12/15, B21210232

S Reportable occurrences, LERs & related correspondence

G212140228 Forwards LER 82-015/03L-0
HUKILL, H. D. General Public Utilities - GPU Service Corp 82/12/02
HAYNES, R. C. Region 1, Office of Director 1p 16408 359 24X Fiche 50-289, 82/12/02, B212140228

--B212140239 LER 82-015/03L-0 on B21103, 1 5-inch irregular diameter hole found in floor fire barrier penetration seal caused by unsealed opening Fire watch posted Seal repaired on B21109
STEPHENSON, C. J. General Public Utilities - GPU Service Corp 82/12/02 Region 1, Office of Director 3pp 16408 360 24X Fiche 50-289, 82/12/02, B212140228

T Hearing transcripts on non-antitrust matters

B212300116 Transcript of Commission B21216 meeting in Washington, DC re order to all PHRs, except TMI-1, requiring mod to inadequate core cooling sys Pp 1-3
* Office of the Secretary of the Commission 82/12/16 6pp 16624 241 24X Fiche 50-289, 82/12/16, B212300116

G212280037 Unofficial transcript of B21217 public meeting in Washington, DC re briefing on Board Notification 82-118A, "TMI Seismic Capability of Auxiliary Feedwater Sys " Pp 1-57 Supporting documentation encl
* Commissioners 82/12/17 63pp 16592 291 24X Fiche 50-289, 82/12/17, B212280037

B21210319 Forwards transcript of Commission B21217 meeting re restart Parties have until B21230 to submit comments on transcript W/o encl
CHILK, S. J. Office of the Secretary of the Commission 82/12/20 NRC - No Detailed Affiliation Given 1p 16496 252 24X Fiche 50-289, 82/12/20, B21210319

DOCKET 50-293 PILGRIM NUCLEAR POWER STATION, UNIT 1

F Security, medical, emergency & fire protection plans

B212060270 Ack receipt of B21117 request for approval of rescheduling 1983 annual full-scale emergency exercise from May 1983 to June 1983 Request forwarded to proper branch for consideration
HARTIN, T T Region 1, Office of Director 82/11/29
HARRINGTON, W D Boston Edison Co 1p 16312 142 24X
Fiche 50-293, 82/11/29, B212060270

--B212060272 Requests approval of rescheduled 1983 annual full-scale emergency exercise from May 1983 to June 1983, per FEMA
821027 request FEMA 1tr encl
MORISI, A V Boston Edison Co 82/11/17 BORES, R J Division of Emergency Preparedness & Operational Support 2pp 16312 143
24X Fiche 50-293, 82/11/29, B212060270

B212100031 Submits requested info re primary & backup emergency operations facility (EOF) EOF completed & operational in Mar 1981
MORISI, A V Boston Edison Co 82/12/06 VASSALLO, D B Operating Reactors Branch 2 2pp 16379 031 24X Fiche 50-293, 82/12/06, B212100031

B212130037 Forwards Revision 9 to modified amended security plan Revision withheld (ref 10CFR73.21)
MORISI, A V Boston Edison Co 82/12/06 VASSALLO, D B Operating Reactors Branch 2 1p 16390 173 24X Fiche 50-293, 82/12/06, B212130037

B212150219 Ack receipt of 820915 & 1022 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 50-293/82-19
STAROSTECKI, R Division of Project & Resident Programs 82/12/10
HARRINGTON, W D Boston Edison Co 2pp 16430 252 24X
Fiche 50-293, 82/12/10, B212150219

--B212150224 Responds to NRC 820816 ltr re violations noted in IE Insp Rept 50-293/82-19 Corrective actions watch engineer unblocked fire door & returned door to closed position & door mechanism repaired
HARRINGTON, W D Boston Edison Co 82/09/15 STAROSTECKI, R Division of Project & Resident Programs 7pp 16430 254 24X
Fiche 50-293, 82/12/10, B212150219

--B212150233 Submits supplemental response to NRC 820816 ltr re violation noted in IE Insp Repts 50-293/82-04 & 50-293/82-19 Plan to correct deviations between local leak rate testing sketches & valve lineup checklists encl
HARRINGTON, W D Boston Edison Co 82/10/22 STAROSTECKI, R Division of Project & Resident Programs 3pp 16430 261 24X
Fiche 50-293, 82/12/10, B212150219

B212170305 Application to amend License DPR-35, requesting relief from Tech Spec re fire barrier penetration seals
HONARD, J E Boston Edison Co 82/12/15 VASSALLO, D B Operating Reactors Branch 2 4pp 16456 131 24X Fiche 50-293, 82/12/15, B212170305

--B212170310 Proposed Tech Spec changes to Section 3.12 F, revising limiting condition of operation for specific fire barrier, currently requiring establishing continuous fire patrol when penetration fire barrier not functional
* Boston Edison Co 82/12/15 2pp 16456 135 24X
Fiche 50-293, 82/12/15, B212170305

B212210015 Advises of procedures for reporting events via emergency notification sys Advance knowledge of types of info should improve effectiveness of calls Dissemination of encl forms to shift crews will alleviate further confusion
STAROSTECKI, R Division of Project & Resident Programs 82/12/16
HARRINGTON, W D Boston Edison Co 6pp 16490 156 24X
Fiche 50-293, 82/12/16, B212210015

J Insurance & indemnity information

B212280441 Forwards Certificate of Insurance N-31 for Endorsements 1, 2 & 3 to NELIA Policy NF-188 & Certificate of Insurance M-31 for Endorsements 1, 2 & 3 to MAELU Policy MF-58
SINISI, J M Marsh & McLennan, Inc, M & M Nuclear Consultants, Inc Div 82/12/20 SALTZMAN, J D Assistant Director for State & Licensee Relations 19pp 16556 038 24X Fiche 50-293, 82/12/20, B212280441

P Operating license stage documents & correspondence

B21230066 Generic Ltr 82-27 to all BWR licensees of operating reactors except LACBWR, Big Rock Point, Dresden 1, Humboldt Bay, applicants for OL & holders of CP re transmittal of NUREG-0743 & NUREG-0783 Svc list encl 11/8 stated encl
EISENHUT, D G Division of Licensing 82/11/15 General Public Utilities - OPU Service Corp 22pp 16387 004 24X
Fiche 50-000, 82/11/15, B21230066

B212100014 Advises that util response to TMI Item II K 3.25 re effect of loss of ac power on pump seals acceptable since response endorsed BWR owners group position
VASSALLO, D B Operating Reactors Branch 2 82/12/01 MORISI, A V Boston Edison Co 7pp 16399 228 24X Fiche 50-293, 82/12/01, B212100014

B212140139 Requests scheduler relief from requirements of NUREG-0743, Item I A 1.3, "Shift Manning" Relief required due to high failure rates of exam candidates & attrition rate of existing personnel New implementation date now Apr 1984
MORISI, A V Boston Edison Co 82/12/09 VASSALLO, D B Operating Reactors Branch 2 2pp 16408 233 24X Fiche 50-293, 82/12/09, B212140139

B212170305 Application to amend License DPR-35, requesting relief from Tech Spec re fire barrier penetration seals
HONARD, J E Boston Edison Co 82/12/15 VASSALLO, D B Operating Reactors Branch 2 4pp 16456 131 24X Fiche 50-293, 82/12/15, B212170305

--B212170310 Proposed Tech Spec changes to Section 3.12 F, revising limiting condition of operation for specific fire barrier, currently requiring establishing continuous fire patrol when penetration fire barrier not functional
* Boston Edison Co 82/12/15 2pp 16456 135 24X
Fiche 50-293, 82/12/15, B212170305

B212270474 Comments on NUREG-0737, Item I C 6 "Verify Correct Performance of Operating Activities" Commitment to modify station policy & procedures to reflect criteria requested within 45 days of ltr date
VASSALLO, D B Operating Reactors Branch 2 82/12/20 MORISI, A V Boston Edison Co 3pp 16566 361 24X Fiche 50-293, 82/12/20, B212270474

Q Inspection reports, IE Bulletins & correspondence

B208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants" Svc list encl
DEVOUNO, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, B208190240

B208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters" Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000, 82/11/05, B208190245

B208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements" Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 107pp 16411 199 24X
Fiche 50-000, 82/11/18, B208190251

B212030195 Forwards IE Insp Rept 50-293/82-28 on B21012-14 No noncompliance noted
HARTIN, T T Division of Engineering & Technical Programs 82/11/19
HARRINGTON, W D Boston Edison Co 2pp 16304 070 24X
Fiche 50-293, 82/11/19, B212030195

--B212030200 IE Insp Rept 50-293/82-28 on B21012-14 No noncompliance noted Major areas inspected steam discharge vol & associated piping design, per IE Bulletins 80-17 & 79-14 & NUREG-0803
EAPEN, P K, BETTENHAUSEN, L Division of Engineering & Technical Programs 82/11/17 3pp 16304 092 24X Fiche 50-293, 82/11/19, B212030195

B208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks" Svc list encl
DEVOUNO, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000, 82/11/26, B208190256

B208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl" Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 358pp 16387 028 24X Fiche 50-000, 82/11/30, B208190257

DOCKETED ITEMS

B/08190259 IE Bulletin 82-04 "Deficiencies in Primary Containment Electrical Penetration Assemblies" Svc list encl
 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co. of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259

B/08190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets" Svc list encl
 JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co. of New York, Inc 110pp 16462 064 24X Fiche 50-000 82/12/03, 8208190261

B/12210458 Forwards "Second 10-Yr Insp Program," w/specific request for code relief, per 10CFR50.55a(g) & ASME Section XI 4/13 oversize drawings Aperture cards are available in PDR One drawing illegible
 MORISI, A V Boston Edison Co 82/12/03 VASSALLO, D B Operating Reactors Branch 2 2pp 16486 007 24X Fiche 50-293, 82/12/03, 8212210458

8212210462 "Second 10-Yr Insp Program," Dec 1982
 * Boston Edison Co 82/12/31 38pp 16486 009 24X Fiche 50-293, 82/12/03, 8212210458

B/12150219 Ack receipt of 820915 & 1022 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 50-293/82-19
 STARDSTECKI, R Division of Project & Resident Programs 82/12/10 HARRINGTON, W D Boston Edison Co 2pp 16430 252 24X Fiche 50-293, 82/12/10, 8212150219

-8212150224 Responds to NRC 820816 ltr re violations noted in IE Insp Rept 50-293/82-19 Corrective actions watch engineer unblocked fire door & returned door to closed position & door mechanism repaired
 HARRINGTON, W D Boston Edison Co 82/09/15 STARDSTECKI, R Division of Project & Resident Programs 7pp 16430 254 24X Fiche 50-293, 82/12/10, 8212150219

8212150233 Submits supplemental response to NRC 820816 ltr re violation noted in IE Insp Repts 50-293/82-04 & 50-293/82-19 Plan to correct deviations between local leak rate testing sketches & valve lineup checklist encl
 HARRINGTON, W D Boston Edison Co 82/10/22 STARDSTECKI, R Division of Project & Resident Programs 3pp 16430 261 24X Fiche 50-293, 82/12/10, 8212150219

B/12210025 Forwards summary of 821117 mgt meeting at site re development & implementation of util performance improvement program
 STARDSTECKI, R Division of Project & Resident Programs 82/12/15 HARRINGTON, W D Boston Edison Co 5pp 16490 207 24X Fiche 50-293, 82/12/15, 8212210025

B/08190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring" Svc list encl
 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co. of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16, 8208190267

B/12220402 Forwards NUREG-0903 containing results of initial round of interviews re establishment of drug & alcohol abuse & rehabilitation program conducted per IE Info Notice 82-05 Util Util be contacted to arrange interviews w/o NUREG
 STARDSTECKI, R Division of Project & Resident Programs 82/12/16 HARRINGTON, W D Boston Edison Co 3pp 16503 216 24X Fiche 50-293, 82/12/16, 8212220402

B/08190268 IE Info Notice 82 50, "Mod of Solid State AC Undervoltage Relays Type ITE-27" Svc list encl
 JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co. of New York, Inc 108pp 16628 293 24X Fiche 50-000 82/12/20, 8208190268

B/12290422 Ack receipt of 821214 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-293/82-24
 STARDSTECKI, R Division of Project & Resident Programs 82/12/23 HARRINGTON, W D Boston Edison Co 2pp 16585 184 24X Fiche 50-293, 82/12/23, 8212290422

-8212290433 Responds to NRC 821112 ltr re violations noted in IE Insp Rept 50-293/82-24 Corrective actions missing sign replaced & new sign designed, Procedures 7 9 2 & 2 1 17 revised on 821117 to contain proper language usage re discharges
 HARRINGTON, W D Boston Edison Co 82/12/14 STARDSTECKI, R Division of Project & Resident Programs 2pp 16585 186 24X Fiche 50-293, 82/12/23, 8212290422

S Reportable occurrences, LERs & related correspondence

8212060198 Forwards LER 82-050/03L-0
 MATHIS, C J Boston Edison Co 82/11/26 HAYNES, R C Region 1, Office of Director 1p 16313 051 24X Fiche 50-293, 82/11/26, 8212060198

--8212060200 LER 82-050/03L-0 on 821026, four fire doors did not meet NFPA & UL code criteria Caused by personnel improperly affixing warning sign holders Repairs made, personnel cautioned & procedure revised
 WHITNEY, O G Boston Edison Co 82/11/26 Region 1, Office of Director 2pp 16313 052 24X Fiche 50-293, 82/11/26, 8212060198

8212060210 Forwards LER 82-052/03L-0
 MATHIS, C J Boston Edison Co 82/11/26 HAYNES, R C Region 1, Office of Director 1p 16313 182 24X Fiche 50-293, 82/11/26, 8212060210

--8212060220 LER 82-052/03L-0 on 821028, recirculation pump A MG set inadvertently tripped while troubleshooting ground indication for 125-volt dc circuit Caused by inadequate info available to troubleshooters Info upgraded
 WHITNEY, O G Boston Edison Co 82/11/26 Region 1, Office of Director 1p 16313 183 24X Fiche 50-293, 82/11/26, 8212060210

B/12210067 Forwards LER 82-055/03L-0
 MATHIS, C J Boston Edison Co 82/12/10 HAYNES, R C Region 1, Office of Director 1p 16492 272 24X Fiche 50-293, 82/12/10, 8212210067

-8212210071 LER 82-055/03L-0 on 821115, during surveillance test for R11C sys, sys isolated due to high steam line flow Caused by failure of resistor PN 8270-281 in power supply to ECM of turbine control Resistor replaced
 WHITNEY, O G Boston Edison Co 82/12/10 Region 1, Office of Director 1p 16492 273 24X Fiche 50-293, 82/12/10, 8212210067

8212210148 Forwards LER 82-053/03L-0
 MATHIS, C J Boston Edison Co 82/12/10 HAYNES, R C Region 1, Office of Director 1p 16485 149 24X Fiche 50-293, 82/12/10, 8212210148

-8212210153 LER 82-053/03L-0 on 821110, ground fault alarm observed on 125-volt dc battery circuit & traced to limit switch circuitry for MOV2301-3 Caused by valve packing steam leakage Packing tightened for short-term fix
 WHITNEY, O G Boston Edison Co 82/12/10 Region 1, Office of Director 1p 16485 150 24X Fiche 50-293, 82/12/10, 8212210148

B/12210249 Forwards LER 82-054/03L-0
 MATHIS, C J Boston Edison Co 82/12/10 HAYNES, R C Region 1, Office of Director 1p 16483 314 24X Fiche 50-293, 82/12/10, 8212210249

--8212210264 LER 82-054/03L-0 on 821111, RPS relay 5AK-30 did not respond when D MSIV inboard valve tested for 10% closure Caused by failed limit switch Fuse removed Repairs to limit switch added to next drywell entry procedures
 WHITNEY, O G Boston Edison Co 82/12/10 Region 1, Office of Director 1p 16483 319 24X Fiche 50-293, 82/12/10, 8212210249

DOCKET 50-295 ZID4 NUCLEAR POWER STATION, UNIT 1

F Security, medical, emergency & fire protection plans

B/12060232 Forwards IE Safety Evaluation Repts 50-295/82-23 & 50-304/82-20 or emergency preparedness & SER
 HIND, J A Division of Emergency Preparedness & Operational Support 82/11/19 REED, C Commonwealth Edison Co 2pp 16312 201 24X Fiche 50-295, 82/11/19, 8212060232

--8212060238 IE Safety Evaluation Repts 50-295/82-23 & 50-304/82-20 or emergency preparedness plan Emergency plan acceptable
 PHILLIPS, M P, AXELSON, W L, PAPERIELLO, C J Division of Emergency Preparedness & Operational Support 82/11/18 1p 16312 203 24X Fiche 50-295, 82/11/19, 8212060232

--8212060255 SER of emergency preparedness plan Plan acceptable
 * Region 3, Office of Director 82/11/30 27pp 16312 204 24X Fiche 50-295, 82/11/19, 8212060232

B/12130363 Approves encl route to transport spent reactor fuel Route meets regulatory requirements of 10CFR73.37
 SHERR, T S Material Transfer Safeguards Licensing Branch 82/11/23 DANESSE, F L Nuclear Assurance Corp 8pp 16415 013 24X Fiche 50-295, 82/11/23, 8212130363

8212070065 Forwards revised exemption requests documenting info provided at 821104 & 05 meetings re post-fire shutdown capability
LENTINE, F O Commonwealth Edison Co 82/11/29 DENTON, H R Office of Nuclear Reactor Regulation, Director 88pp 16326 010 24X Fiche 50-295, 82/11/29, 8212070065

8212090383 Forwards info re emergency operations facilities per 821122 & 1202 requests info previously submitted by telcon Request for written response unnecessary burden on licensee
DELGEORGE, L O Commonwealth Edison Co 82/12/03 EISENHUT, D O Division of Licensing 2pp 16365 051 24X Fiche 50-000, 82/12/03, 8212090383

8212130149 Releases public version of revision to emergency plan implementing procedure
FELTON, J M Division of Rules and Records 82/12/03 Document Management Branch 1p 16410 295 24X Fiche 50-295, 82/12/03, 8212130149

--8212130153 Forwards public version of Revision 5 to Emergency Plan Implementing Procedure EPIP 330-1, "Classification of Generation Station Emergency Plan Conditions " Procedure change request form encl
PLIML, G Commonwealth Edison Co 82/11/19 DENTON, H R NRC - Nu Detailed Affiliation Given 3pp 16410 277 24X Fiche 50-295, 82/12/03, 8212130149

--8212130156 Public version of Revision 5 to Emergency Plan Implementing Procedure EPIP 330-1, "Classification of Generating Station Emergency Plan Conditions "
* Commonwealth Edison Co 82/11/16 16pp 16410 300 24X Fiche 50-295, 82/12/03, 8212130149

8212130017 Releases public version of Revision 1 to Emergency Plan Implementing Procedure EQ-2, "Pre-Established Onsite & Offsite Monitoring Locations (Maps) "
FELTON, J M Division of Rules and Records 82/12/07 Document Management Branch 1p 16417 062 24X Fiche 50-000, 82/12/07, 8212130017

--8212130028 Forwards public version of Revision 1 to Emergency Plan Implementing Procedure EQ-2, "Pre-Established Onsite & Offsite Monitoring Locations (Maps) " Revised table of contents encl
PAJOWSKI, J Commonwealth Edison Co 82/11/01 DENTON, H R NRC No Detailed Affiliation Given 2pp 16417 063 24X Fiche 50-000, 82/12/07, 8212130017

--8212130041 Public version of Revision 1 to Emergency Plan Implementing Procedure EQ-2, "Pre-Established Onsite & Offsite Monitoring Locations (Maps) "
PAJOWSKI, J E Commonwealth Edison Co 82/11/29 4pp 16417 065 24X Fiche 50-000, 82/12/07, 8212130017

8212140243 Advises of distribution of revisions to "Generating Station Emergency Plan " Braidwood annex not prepared
TRAHM, T R Commonwealth Edison Co 82/12/07 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 16409 302 24X Fiche 50-000, 82/12/07, 8212140243

8212220175 Releases public version of revised generating station emergency plan implementing procedures
FELTON, J M Division of Rules and Records 82/12/10 Document Management Branch 1p 16529 029 24X Fiche 50-000, 82/12/10, 8212220175

--8212220190 Forwards public version of revised generating station emergency plan implementing procedures, including Procedures ED-3 re demand polling of meteorological data & ED-20 re emergency forecast request
PAJOWSKI, J E Commonwealth Edison Co 82/11/15 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 16529 030 24X Fiche 50-000, 82/12/10, 8212220175

--8212220202 Public version of revised generating station emergency plan implementing procedures, including Procedures ED-3 re demand polling of meteorological data & ED-20 re emergency forecast request
LITERSKI, L A Commonwealth Edison Co 82/10/13 48pp 16529 031 24X Fiche 50-000, 82/12/10, 8212220175

8212210454 Forwards addl info documenting discussions at 821104 & 05 meeting w/NRC & BNL re remaining open items from technical evaluation rpt, "Post-Fire Shutdown Capability "
LENTINE, F O Commonwealth Edison Co 82/12/15 DENTON, H R Office of Nuclear Reactor Regulation, Director 39pp 16489 285 24X Fiche 50-295, 82/12/15, 8212210454

8212220306 Discusses layout of communications equipment required in control room, onsite technical support ctr & near-site emergency operations facility
KEPPLER, J G Region 3, Office of Director 82/12/16 Commonwealth Edison Co 3pp 16503 351 24X Fiche 50-000, 82/12/16, 8212220306

8212290083 Releases public version of corrected page to emergency plan implementing procedure
FELTON, J M Division of Rules and Records 82/12/20 Document Management Branch 1p 16606 343 24X Fiche 50-295, 82/12/20, 8212290083

--8212290086 Forwards public version of corrected Page 4 to Emergency Plan Implementing Procedure EPIP 410-1 Receipt form encl
PLIML, G Commonwealth Edison Co 82/11/30 DENTON, H R NRC - Nu Detailed Affiliation Given 2pp 16606 344 24X Fiche 50-295, 82/12/20, 8212290083

--8212290089 Public version of corrected Page 4 to Emergency Plan Implementing Procedure EPIP 410-1
* Commonwealth Edison Co 82/11/30 1p 16606 346 24X Fiche 50-295, 82/12/20, 8212290083

8212290098 Releases public version of revision to emergency plan implementing procedure
FELTON, J M Division of Rules and Records 82/12/20 Document Management Branch 1p 16606 334 24X Fiche 50-295, 82/12/20, 8212290098

--8212290105 Forwards public version of Revision 6 to Emergency Plan Implementing Procedure EPIP 110-1, "Station Director " Receipt form & procedure change request form encl
PLIML, G Commonwealth Edison Co 82/11/24 DENTON, H R NRC - Nu Detailed Affiliation Given 2pp 16606 339 24X Fiche 50-295, 82/12/20, 8212290098

--8212290110 Public version of Revision 6 to Emergency Plan Implementing Procedure EPIP 110-1, "Station Director " Revised index encl
* Commonwealth Edison Co 82/11/24 6pp 16606 337 24X Fiche 50-295, 82/12/20, 8212290098

8212290509 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 82/12/20 Document Management Branch 1p 16593 349 24X Fiche 50-295, 82/12/20, 8212290509

--8212290511 Forwards public version of Revision 8 to Emergency Plan Implementing Procedure EPIP 700-1, "Emergency Phone List " Procedure change request encl
PLIML, G Commonwealth Edison Co 82/11/24 DENTON, H R NRC - Nu Detailed Affiliation Given 2pp 16593 350 24X Fiche 50-295, 82/12/20, 8212290509

--8212290513 Public version of Revision 8 to Emergency Plan Implementing Procedure EPIP 700-1, "Emergency Phone List "
* Commonwealth Edison Co 82/11/22 6pp 16593 352 24X Fiche 50-295, 82/12/20, 8212290509

8212300167 Releases public version of revised generating station emergency plan telephone directory
FELTON, J M Division of Rules and Records 82/12/20 Document Management Branch 1p 16612 215 24X Fiche 50-000, 82/12/20, 8212300167

--8212300179 Forwards public version of revised generating station emergency plan telephone directory
MOORE, R O Commonwealth Edison Co 82/12/02 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 16612 216 24X Fiche 50-000, 82/12/20, 8212300167

--8212300199 Public version of revised generating station emergency plan telephone directory
OALLE, D P Commonwealth Edison Co 82/11/05 60pp 16612 217 24X Fiche 50-000, 82/12/20, 8212300167

8212290415 Forwards proposed agenda for B30104-05 site visit by security review committee re safeguards requirements
KEPPLER, J O Region 3, Office of Director 82/12/27 REED, C Commonwealth Edison Co 2pp 16387 099 24X Fiche 50-295, 82/12/27, 8212290415

H General correspondence

8212280176 Notifies of change in mailing address for NRC licensing mail
WRIGHT, O N Illinois, State of, Dept Nuc Safety (formerly Dept Public Health) 82/12/20 EISENHUT, D O Division of Licensing 1p 16556 135 24X Fiche 50-000, 82/12/20, 8212280176

DOCKETED ITEMS

P Operating license stage documents & correspondence

G212070411 FOIA request for all records on embrittlement, thermal shock, corrosion & cracking of reactor pressure vessel at facilities
 GUIGO, C Pollution & Environmental Problems, Inc 82/10/18
 Division of Rules and Records 1p 16356 001 24X
 Fiche 50-295, 82/10/18, 8212070411

B212060471 OPERATOR ACTION EVENT TREES FOR THE ZION 1 PRESSURIZED WATER REACTOR
 BRODM, R G, VONHERRMANN, J, GUILLIAM, J F E88G, Inc NUREG/CR-2888
 82/10/31 Office of Nuclear Regulatory Research, Director
 204pp 16348 020 24X Fiche 50-295, 82/10/31, 8212060471

B212070414 Responds to FOIA request for all records on embrittlement, thermal shock, corrosion & cracking of reactor pressure vessel at facility Records available at PDR
 FELTOM, J H Division of Rules and Records 82/11/05 GUIGO, C
 Pollution & Environmental Problems, Inc 4pp 16356 002 24X
 Fiche 50-295, 82/11/05, 8212070414

G212010452 Summary of 821115 meeting w/Util re interim inservice testing program
 WIGGINTON, D L Operating Reactors Branch 1 82/11/19 Operating
 Reactors Branch 1 4pp 16270 222 24X Fiche 50-295, 82/11/19,
 8212010452

B212060086 Clarifies 820712 ltr re seismic design of auxiliary feedwater sys branch piping criteria utilized for all
 IE Bulletin 79-14 work as documented in S/N Procedure ZPP-1
 LENTINE, F O Commonwealth Edison Co 82/11/29 DENTON, H R Office
 of Nuclear Reactor Regulation, Director 1p 16316 120 24X
 Fiche 50-295, 82/11/29, 8212060086

B212060219 Requests approval to delay implementation of due dates to accommodate current schedule requirements for Items II B 2, "Plant Shielding," II B 3, "Post-Accident Sampling," & II F 1, "Accident Monitoring Instrumentation"
 LENTINE, F O Commonwealth Edison Co 82/11/29 EISENHUT, D O
 Division of Licensing 2pp 16313 190 24X Fiche 50-295, 82/11/29,
 8212060219

B212060422 Forwards FR notice of receipt of 821011 request for action to licensee use of high burnup nuclear fuel & ability of facility reactor vessels to withstand embrittlement Request being treated per IOCFR2 206
 DENTON, H R Office of Nuclear Reactor Regulation, Director
 82/11/30 GUIGO, C obsolete code 1p 16343 308 24X
 Fiche 50-295, 82/11/30, 8212060422

--B212060430 Notice of Pollution & Environ Problems, Inc 821011 request for action re licensee use of high burnup nuclear fuel & ability of facility reactor vessels to withstand embrittlement
 DENTON, H R Office of Nuclear Reactor Regulation, Director
 82/11/30 1p 16343 309 24X Fiche 50-295, 82/11/30, 8212060430

B212070472 Forwards Amends 78 & 68 to Licenses DPR-39 & DPR-48, respectively & notice of issuance & availability Amends revise Tech Specs to allow release of radioactive gas decay tank contents
 WIGGINTON, D Operating Reactors Branch 1 82/11/30 DELGEORGE, L O
 Commonwealth Edison Co 3pp 16351 342 24X Fiche 50-295,
 82/11/30, 8212070472

-B212070478 Amends 78 & 68 to Licenses DPR-39 & DPR-48, respectively, revising Tech Specs to allow release of radioactive gas decay tank contents
 VARGA, S A Operating Reactors Branch 1 82/11/30 8pp
 16351 345 24X Fiche 50-295, 82/11/30, 8212070472

-B212070482 Notice of issuance & availability of Amends 78 & 68 to Licenses DPR-39 & DPR-48, respectively
 VARGA, S A Operating Reactors Branch 1 82/11/30 2pp
 16351 353 24X Fiche 50-295, 82/11/30, 8212070472

B212130231 Application to amend Licenses DPR-39 & DPR-48, changing Section 3 9 2 of Tech Specs to clarify operability requirements for containment penetration & weld channel pressurization sys
 LENTINE, F O Commonwealth Edison Co 82/12/03 DENTON, H R Office
 of Nuclear Reactor Regulation, Director 2pp 16397 001 24X
 Fiche 50-295, 82/12/03, 8212130231

--B212130235 Proposed changes to Section 3 9 2 of Tech Specs, clarifying operability requirements for containment penetration & weld channel pressurization sys
 * Commonwealth Edison Co 82/12/03 2pp 16397 003 24X
 Fiche 50-295, 82/12/03, 8212130231

B212090006 Confirms emergency authorization to amend Licenses DPR-39 & DPR-48 on 821203 Amend revises penetration pressurization sys
 LAINAS, O C Assistant Director for Operating Reactors 82/12/06
 DELGEORGE, L O Commonwealth Edison Co 2pp 16379 357 24X
 Fiche 50-295, 82/12/06, 8212090006

B212130035 Informs of addl delay in implementation of offsite dose assessment portion of A-model Required radiation monitoring sys will be installed by 830215, per NUREG-0737,
 Items II F 1 1 & II F 1 2
 LENTINE, F O Commonwealth Edison Co 82/12/07 DENTON, H R Office
 of Nuclear Reactor Regulation, Director 2pp 16390 174 24X
 Fiche 50-295, 82/12/07, 8212130035

B208190263 Generic Ltr 82-32 to all PWR licensees re potential steam generator-related generic requirements Forwards Science Applications, Inc draft rept re subj requirements Comments requested within 30 days of ltr Svc list encl
 EISENHUT, D O Division of Licensing 82/12/09 Consolidated
 Edison Co of New York, Inc 27pp 16629 247 24X
 Fiche 50-000, 82/12/09, 8208190263

B212140103 Generic Ltr 82-28 to all licensees of operating Westinghouse & C-E PWRs (except Arkansas Nuclear One, Unit 2 & San Onofre 2 & 3) re inadequate core cooling instrumentation sys Svc list encl
 EISENHUT, D O Division of Licensing 82/12/10 Yankee Atomic
 Electric Co 27pp 16690 035 24X Fiche 50-000, 82/12/10,
 8212140103

B212150141 Forwards proprietary SER & technical evaluation rept, "Review of Licensee Resolution of Outstanding Issues From NRC Equipment Environ Qualification SERs (F-11.3-60)"
 Justification for continued operation due in 30 days
 VARGA, S A Operating Reactors Branch 1 82/12/14 DELGEORGE, L O
 Commonwealth Edison Co 2pp 16427 345 24X Fiche 50-295, 82/12/14,
 8212150141

B212220212 Forwards Revision 22 to CE-1-A, "QA Program for Nuclear Generating Stations"
 SHWARTZ, E D Commonwealth Edison Co 82/12/14 HAAGS, W P Quality
 Assurance Branch 1p 16318 007 24X Fiche 50-000, 82/12/14,
 8212220212

--B212220231 "QA Program for Nuclear Generating Stations," Revision 22
 * Commonwealth Edison Co CE-1-A R22 82/11/01 17pp
 16518 009 24X Fiche 50-000, 82/12/14, 8212220212

B212220431 Comments on NRC alternative Tech Specs re auxiliary feedwater sys, prepared in response to util 791231 & 800312 submittals Proposed Tech Specs acceptable w/exception of minor editorial changes noted in encl
 LENTINE, F O Commonwealth Edison Co 82/12/15 DENTON, H R Office
 of Nuclear Reactor Regulation, Director 5pp 16503 311 24X
 Fiche 50-295, 82/12/15, 8212220431

B212220517 Forwards approved spent nuclear fuel route as requested in 820914 ltr
 SHERR, T S Material Transfer Safeguards Licensing Branch 82/12/16
 DANES, F L Nuclear Assurance Corp 2pp 16523 041 24X
 Fiche 50-295, 82/12/16, 8212220517

--B212220520 "Spent Nuclear Fuel Route, BMI, West Jefferson, OH to Zion Nuclear Power Station, Zion, IL"
 SHERR, T S Material Transfer Safeguards Licensing Branch
 82/11/23 10pp 16523 043 24X Fiche 50-295, 82/12/16, 8212220517

B212210369 Requests NRC concurrence or comments on revised schedule for implementation of fuel mgt program topical rept
 LENTINE, F O Commonwealth Edison Co 82/12/17 THOMAS, C O
 Standardization & Special Projects Branch 3pp 16494 275 24X
 Fiche 50-295, 82/12/17, 8212210369

B212290453 Forwards Amends 79 & 69 to Licenses DPR-39 & DPR-48, respectively, safety evaluation & notice of issuance & availability Amends revise Tech Specs for penetration pressurization sys to define operating conditions
 WIGGINTON, D L Operating Reactors Branch 1 82/12/20
 DELGEORGE, L O Commonwealth Edison Co 2pp 16606 060 24X
 Fiche 50-295, 82/12/20, 8212290453

--B212290456 Amends 79 & 69 to Licenses DPR-39 & DPR-48, respectively, revising Tech Specs for penetration pressurization sys to define conditions of operation, applicable modes & actions taken for inoperable sys
 VARGA, S A Operating Reactors Branch 1 82/12/20 7pp
 16606 062 24X Fiche 50-295, 82/12/20, 8212290453

--B212290461 Safety evaluation supporting Amends 79 & 69 to Licenses DPR-39 & DPR-48, respectively
 * Office of Nuclear Reactor Regulation, Director 82/12/20 3pp
 16606 069 24X Fiche 50-295, 82/12/20, 8212290453

--B212290464 Notice of issuance & availability of Amends 79 & 69 to
Licenses DPR-39 & DPR-4B, respectively
VARDA, B A Operating Reactors Branch 1 82/12/20 2pp
16606 072 24X Fiche 50-295, 82/12/20, 8212290453

B212280212 Forwards updated schedule for ongoing environ qualification
testing programs, per 810528 commitment
SWARTZ, E D Commonwealth Edison Co 82/12/22 EISENHUT, D O
Division of Licensing 18pp 16556 161 24X Fiche 50-000, 82/12/22,
8212280212

Q Inspection Reports, IE Bulletins & correspondence

B208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-
Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping
at BWR Plants " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and
Enforcement 82/10/28 Consolidated Edison Co of New York, Inc
112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240

B208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model
E01 & Model 802 Thermoluminescent Dosimeters " Svc list
encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards
82/11/05 Consolidated Edison Co of New York, Inc 110pp
16372 142 24X Fiche 50-000, 82/11/05, 8208190245

B212080282 Forwards IE Insp Repts 50-295/82-18 & 50-304/82-16 on
820830-0903 & 20-22 No noncompliance noted
MILLER, J R Division of Engineering & Technical Programs 82/11/12
REED, C Commonwealth Edison Co 2pp 16354 186 24X
Fiche 50-295, 82/11/12, 8212080282

--B212080276 IE Insp Repts 50-295/82-18 & 50-304/82-16 on 820830-0903 &
20-22 No noncompliance noted Major areas inspected
compliance w/NUREG-0737, Item II F 1 3, allegations forwarded
by IL Dept of Nuclear Safety & radiation protection program
MILLER, D E, PAUL, R A, GREGER, L R Division of Engineering &
Technical Programs 82/11/10 15pp 16354 188 24X
Fiche 50-295, 82/11/10, 8212080276

B208190251 IE Info Notice 82-44, "Clarification of Emergency Plan
Exercise Requirements " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18
Consolidated Edison Co of New York, Inc 109pp 16411 199 24X
Fiche 50-000, 82/11/18, 8208190251

B212060232 Forwards IE Safety Evaluation Repts 50-295/82-23 &
50-304/82-20 of emergency preparedness & SER
HIND, J A Division of Emergency Preparedness & Operational Support
82/11/19 REED, C Commonwealth Edison Co 2pp 16312 201 24X
Fiche 50-295, 82/11/19, 8212060232

--B212060238 IE Safety Evaluation Repts 50-295/82-23 & 50-304/82-20 of
emergency preparedness plan Emergency plan acceptable
PHILLIPS, M P, AKELSON, W L, PAPERIELLO, C J Division of Emergency
Preparedness & Operational Support 82/11/18 1p 16312 203
24X Fiche 50-295, 82/11/19, 8212060232

--B212060255 SER of emergency preparedness plan Plan acceptable
* Region 3, Office of Director 82/11/30 27pp 16312 204 24X
Fiche 50-295, 82/11/19, 8212060232

B208190256 IE Info Notice 82-46, "Defective & Obsolete Combination
Padlocks " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and
Enforcement 82/11/26 Consolidated Edison Co of New York, Inc
127pp 16411 065 24X Fiche 50-000, 82/11/26, 8208190256

B212060050 Summaries 821103 meeting w/US Atty & law enforcement
agencies in Chicago, IL re IE Investigation Repts
50-295/81-32 & 50-304/81-30 & status of ongoing
investigation
KEPPLER, J O Region 3, Office of Director 82/11/29 JONES, G C
Illinois, State of 2pp 16314 075 24X Fiche 50-295, 82/11/29,
8212060050

B208190257 IE Info Notice 82-47, "Transportation of Type A Quantities
of Non-Fissile Radioactive Matl " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards
82/11/30 Consolidated Edison Co of New York, Inc 356pp
16387 028 24X Fiche 50-000, 82/11/30, 8208190257

B208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment
Electrical Penetration Assemblies " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and
Enforcement 82/12/03 Consolidated Edison Co of New York, Inc
113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259

B208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay
Sockets " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03
Consolidated Edison Co of New York, Inc 110pp 16462 064 24X
Fiche 50-000, 82/12/03, 8208190261

B212170109 Forwards IE Insp Repts 50-295/82-20 & 50-304/82-18 on
821025-29 & notice of violation
NORELIUS, C E Division of Engineering & Technical Programs
82/12/03 REED, C Commonwealth Edison Co 2pp 16452 336 24X
Fiche 50-295, 82/12/03, 8212170109

--B212170114 Notice of violation from insp on 821025-29
NORELIUS, C E Division of Engineering & Technical Programs
82/12/03 2pp 16452 336 24X Fiche 50-295, 82/12/03, 8212170109

--B212170121 IE Insp Repts 50-295/82-20 & 50-304/82-18 on 821025-29
Noncompliance noted form not used to track operator progress
& current status of operator training Out-of-tolerance
parameters & valve stroke times not recorded
FARRELL, R E, HASSE, R A, PESCHEL, J M Division of Engineering &
Technical Programs 82/12/02 7pp 16452 340 24X
Fiche 50-295, 82/12/03, 8212170109

B212130183 Forwards addl info re IE Bulletin 80-11, "Masonry Walls,"
in response to NRC 821022 ltr Eighteen walls qualified
using horizontal reinforcement
LENTINE, F O Commonwealth Edison Co 82/12/08 EISENHUT, D O
Division of Licensing 18pp 16396 099 24X Fiche 50-295, 82/12/08,
8212130183

B212280058 Forwards IE Insp Repts 50-295/82-27 & 50-304/82-24 on
821115-19 No noncompliance noted
MILLER, J R Division of Engineering & Technical Programs 82/12/10
REED, C Commonwealth Edison Co 2pp 16564 279 24X
Fiche 50-295, 82/12/10, 8212280058

--B212280062 IE Insp Repts 50-295/82-27 & 50-304/82-24 on 821115-19 No
noncompliance noted Major areas inspected radwaste sys,
including effluent release rates, records & repts, procedures
for controlling releases & containment air cleaning sys
MILLER, D E, GRANT, W B, GREGER, L R Division of Engineering &
Technical Programs 82/12/10 7pp 16564 281 24X
Fiche 50-295, 82/12/10, 8212280058

B208190267 IE Info Notice 82-49, "Correction for Sample Conditions for
Air & Gas Monitoring " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and
Enforcement 82/12/16 Consolidated Edison Co of New York, Inc
127pp 16628 191 24X Fiche 50-000, 82/12/16, 8208190267

B212290389 Forwards IE Insp Repts 50-295/82-29 & 50-304/82-26 on
821115-16 No noncompliance noted
LITTLE, W S Division of Engineering & Technical Programs 82/12/17
REED, C Commonwealth Edison Co 2pp 16586 296 24X
Fiche 50-295, 82/12/17, 8212290389

--B212290400 IE Insp Repts 50-295/82-29 & 50-304/82-26 on 821115-16 No
noncompliance noted Major areas inspected actions in
response to IE Bulletin 79-14, work procedure review &
observation of work
YIN, I T, DANIELSON, D H Division of Engineering & Technical
Programs 82/12/10 6pp 16586 298 24X Fiche 50-295, 82/12/17,
8212290389

B208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage
Relays Type ITE-27 " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20
Consolidated Edison Co of New York, Inc 108pp 16628 293 24X
Fiche 50-000, 82/12/20, 8208190268

R Periodic operating reports & related correspondence

B212140055 Forwards monthly operating repts for Nov 1982
GRAESSER, K L Commonwealth Edison Co 82/12/09 Director's
Office, Office of Inspection and Enforcement 1p 16408 290 24X
Fiche 50-295, 82/12/09, 8212140055

--B212140061 Monthly operating repts for Nov 1982
AUSTIN, O Commonwealth Edison Co 82/12/09 11pp 16408 291
24X Fiche 50-295, 82/12/09, 8212140055

S Reportable occurrences, LERs & related correspondence

B212020234 Forwards LER 82-037/03L-0
GRAESSER, K L Commonwealth Edison Co 82/11/24 KEPPLER, J O
Region 3, Office of Director 1p 16274 104 24X
Fiche 50-295, 82/11/24, 8212020234

DOCKETED ITEMS

--8212020237 LER 82-039/03L-0 on 821027, Class 1 pipe tunnel iodine monitor RT-PRO78 failed low & would not respond to source check Caused by high voltage drifting to point below detector knee
JAKUBAITIS, T C Commonwealth Edison Co 82/11/24 Region 3, Office of Director 1p 16274 105 24X Fiche 50-295, 82/11/24, 8212020234

GP12020273 Forwards LER 82-040/99X-0
GRAESSER, K L Commonwealth Edison Co 82/11/24 KEPLER, J O Region 3, Office of Director 1p 16291 005 24X Fiche 50-295, 82/11/24, 8212020272

--8212020285 LER 82-040/99X-0 on 821025, QA fire pump taken out of svc on 821018 found still inoperable Cause not stated Parts on order Diesel driven fire pump tested once per wk Design & procedures adequate Pump returned to svc by end of yr
NYKIEL, A Commonwealth Edison Co 82/11/24 Region 3, Office of Director 1p 16291 006 24X Fiche 50-295, 82/11/24, 8212020272

8212140321 Forwards LER 82-041/03L-0
GRAESSER, K L Commonwealth Edison Co 82/12/08 KEPLER, J O Region 3, Office of Director 1p 16401 282 24X Fiche 50-295, 82/12/08, 8212140321

8212140327 LER 82-041/03L-0 since May 1975, plant operated w/low steamline pressure compensation lead/lag setting different than current Westinghouse large steam break analysis Caused by inadequate precautions, limitations & setpoints manual
CANTHELL, P F Commonwealth Edison Co 82/12/08 Region 3, Office of Director 1p 16401 283 24X Fiche 50-295, 82/12/08, 8212140321

GP12170307 Forwards LER 82-042/03L-0
GRAESSER, K L Commonwealth Edison Co 82/12/09 KEPLER, J O Region 3, Office of Director 1p 16456 137 24X Fiche 50-295, 82/12/09, 8212170307

- 8212170312 LER 82-042/03L-0 on 821116, RHR miniflow control valve switch IFIC-610A failed & miniflow valve would not close at 1,000 gpm per design Caused by Barton Model 288 micro-switch out-of-tolerance Mod initiated to replace switch
BINQUELI, B L Commonwealth Edison Co 82/12/09 Region 3, Office of Director 1p 16456 138 24X Fiche 50-295, 82/12/09, 8212170307

GP12280432 Forwards LER 82-043/03L-0
GRAESSER, K L Commonwealth Edison Co 82/12/17 KEPLER, J O Region 3, Office of Director 1p 16556 066 24X Fiche 50-295, 82/12/17, 8212280432

--8212280442 LER 82-043/03L-0 on 821209, control room makeup charcoal filter sys chemical analysis showed upstream & downstream filter efficiencies below 99% Caused by normal deterioration due to airborne contaminants Filters replaced
STAHEMER, F Commonwealth Edison Co 82/12/17 Region 3, Office of Director 1p 16556 067 24X Fiche 50-295, 82/12/17, 8212280432

GP12280450 Forwards LER 82-043/03L-0
GRAESSER, K L Commonwealth Edison Co 82/12/17 KEPLER, J O Region 3, Office of Director 1p 16556 011 24X Fiche 50-295, 82/12/17, 8212280450

--8212280451 LER 82-043/03L-0 on 821111, heater failure alarm discovered on boric acid tank suction line to boric acid transfer pump One of two heat trace circuits failed Caused by valve on suction line leaking boric acid water Valve repaired
KAPLAN, S A Commonwealth Edison Co 82/12/17 Region 3, Office of Director 1p 16556 012 24X Fiche 50-295, 82/12/17, 8212280450

GP12280244 Forwards LER 82-044/03L-0
GRAESSER, K L Commonwealth Edison Co 82/12/21 KEPLER, J O Region 3, Office of Director 1p 16561 271 24X Fiche 50-295, 82/12/21, 8212280244

--8212280249 LER 82-044/03L-0 on 821129, penetration pressurization (PP) air compressor O failed to unload on demand Caused by corroded inlet valve unloaders All suction/discharge valves & associated internal components rebuilt
SHIM, K Commonwealth Edison Co 82/12/21 Region 3, Office of Director 2pp 16561 272 24X Fiche 50-295, 82/12/21, 8212280244

DOCKET 50-296 BROWNS FERRY NUCLEAR POWER STATION, UNIT 3
F Security, medical, emergency & fire protection plans

8212030212 Ack receipt of 821119 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Repts 50-259/82-30, 50-260/82-30 & 50-296/82-30
LEWIS, R C Division of Project & Resident Programs 82/11/30
PARRIS, H O Tennessee Valley Authority 1p 16307 067 24X Fiche 50-259, 82/11/30, 8212030212

--8212030220 Responds to NRC 821019 ltr re violations noted in IE Safeguards Insp Repts 50-259/82-30, 50-260/82-30 & 50-296/82-30 Corrective actions withheld (ref 10CFR73 21)
MILLS, L M Tennessee Valley Authority 82/11/19 O'REILLY, J P Region 2, Office of Director 1p 16307 068 24X Fiche 50-259, 82/11/30, 8212030212

--8212030226 Forwards IE Safeguards Insp Repts 50-259/82-30, 50-260/82-30 & 50-296/82-30 on 820920-24 & notice of violation Rept details & notice of violation withheld (ref 10CFR73 21)
LEWIS, R C Division of Project & Resident Programs 82/10/19
PARRIS, H O Tennessee Valley Authority 2pp 16307 069 24X Fiche 50-259, 82/11/30, 8212030212

--8212030232 IE Insp Repts 50-259/82-30, 50-260/82-30 & 50-296/82-30 on 820920-24 Noncompliance noted in areas of locks, keys & combinations, physical barriers - protected areas, lighting & access control Details withheld (ref 10CFR73 21)
HALL, B L Division of Engineering & Technical Programs 82/10/14 2pp 16307 071 24X Fiche 50-259, 82/11/30, 8212030212

8212080100 Releases public version of revised radiological emergency plan implementing procedures
FELTON, J M Division of Rules and Records 82/12/02 Document Management Branch 1p 16367 276 24X Fiche 50-259, 82/12/02, 8212080100

--8212080108 Forwards public version of revised radiological emergency plan implementing procedures, including Procedures IP-1 re emergency plan classification logic & IP-4 re site area emergency Receipt form encl
MILLS, L M Tennessee Valley Authority 82/11/22 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 16367 277 24X Fiche 50-259, 82/12/02, 8212080100

--8212080112 Public version of revised radiological emergency plan implementing procedures, including Procedures IP-1 re emergency plan classification logic, IP-4 re site area emergency & IP-21 re operations support ctr
* Tennessee Valley Authority 82/11/01 76pp 16367 280 24X Fiche 50-259, 82/12/02, 8212080100

GP12090080 Ack receipt of 821124 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Repts 50-259/82-36, 50-260/82-36 & 50-296/82-36
LEWIS, R C Division of Project & Resident Programs 82/12/06
PARRIS, H O Tennessee Valley Authority 2pp 16357 236 24X Fiche 50-259, 82/12/06, 8212090080

--8212090092 Responds to NRC 821022 ltr re violations noted in IE Safeguards Insp Repts 50-259/82-36, 50-260/82-36 & 50-296/82-36 Corrective actions withheld (ref 10CFR73 21)
MILLS, L M Tennessee Valley Authority 82/11/24 O'REILLY, J P Region 2, Office of Director 1p 16357 239 24X Fiche 50-259, 82/12/06, 8212090080

--8212090108 Forwards IE Safeguards Insp Repts 50-259/82-36, 50-260/82-36 & 50-296/82-36 on 820908-09 & notice of violation Rept details & notice of violation withheld (ref 10CFR73 21)
O'REILLY, J P Region 2, Office of Director 82/10/22
PARRIS, H O Tennessee Valley Authority 2pp 16357 239 24X Fiche 50-259, 82/12/06, 8212090080

--8212090124 IE Safeguards Insp Repts 50-259/82-36, 50-260/82-36 & 50-296/82-36 on 820908-09 Noncompliance noted in area of access controls Details withheld (ref 10CFR73 21)
TILLMAN, A Division of Engineering & Technical Programs 82/10/20 1p 16357 241 24X Fiche 50-259, 82/12/06, 8212090080

8212170104 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 82/12/10 Document Management Branch 1p 16478 104 24X Fiche 50-259, 82/12/10, 8212170104

--B212170108 Forwards public version of revised emergency plan implementing procedures, including Procedures IP-6, -7 & -23 re emergency telephone listings
MILLS, L. M. Tennessee Valley Authority 82/12/03 DENTON, H. R.
Office of Nuclear Reactor Regulation, Director 2pp 16478 105
24X Fiche 50-259, 82/12/10, 8212170104

--B212170112 Public version of revised emergency plan implementing procedures, including Procedures IP-6, -7 & -23 re emergency telephone listings
* Tennessee Valley Authority 82/11/30 7pp 16478 107 24X
Fiche 50-259, 82/12/10, 8212170104

B212170229 Provides implementation schedule for generic security training & qualification plan Public safety employees have completed initial training Training per 10CFR50 54(p) will be completed by 830801
MILLS, L. M. Tennessee Valley Authority 82/12/13 DENTON, H. R.
Office of Nuclear Reactor Regulation, Director 2pp 16462 020
24X Fiche 50-000, 82/12/13, 8212170229

G Adjudicatory correspondence

B212280028 Forwards nonproprietary "RWR-1 - Radwaste Vol Reduction Sys" & NRC topical rept evaluation Matl should aid in settlement negotiations w/o encl
RAMSON, R. J. Hearing Branch 4 82/12/23 PYLE, R. D. Pyle, R. D. 1p
16565 143 24X Fiche 50-259, 82/12/23, 8212280028

H General correspondence

B212140478 Forwards missing Pages 65 & 66 of EIA re low level radwaste storage for Browns Ferry Nuclear Plant & SER & EIA on low level radwaste storage facility at Sequoyah Nuclear Plant w/o encl
LOVSEN, P. Advanced Fuel & Spent Fuel Licensing Branch 82/11/23
DREY, L. A. Affiliation Unknown 1p 16431 321 24X
Fiche 50-000, 82/11/23, 8212140478

--B212140486 Requests missing pages to EIA on low level radwaste storage at Browns Ferry Nuclear Plant & copies of SER & EIA for Sequoyah Nuclear Plant
DREY, L. A. Affiliation Unknown 82/11/08 Office of Nuclear
Material Safety & Safeguards, Director 1p 16431 322 24X
Fiche 50-000, 82/11/23, 8212140478

J Insurance & indemnity information

B212020269 Submits info re const & warehouse values located offsite as result of revised site descriptions under ANI/MAELU nuclear liability insurance facility form policies
DUCK, J. R. Marsh & McLennan, Inc., M & M Nuclear Consultants, Inc. Div
82/11/18 HAINES, H. L. American Nuclear Insurers 1p 16288 336
24X Fiche 50-000, 82/11/18, 8212020269

B212280261 Forwards Endorsement 63 to NELIA Policy NF-198 & Endorsement 53 to MAELU Policy MF-66
DUCK, J. R. Marsh & McLennan, Inc., M & M Nuclear Consultants, Inc. Div
82/12/22 SALTZMAN, J. Assistant Director for State & Licensee
Relations 3pp 16561 304 24X Fiche 50-259, 82/12/22, 8212280261

B212290246 Forwards Certificates of Insurance N-38, N-39 & N-40 for Endorsements 1, 2 & 3 to NELIA Policy NF-198 & Certificates of Insurance M-38, M-39 & M-40 for Endorsements 1, 2 & 3 to MAELU Policy MF-66
DUCK, J. R. Marsh & McLennan, Inc., M & M Nuclear Consultants, Inc. Div
82/12/23 SALTZMAN, J. Assistant Director for State & Licensee
Relations 5pp 16582 045 24X Fiche 50-259, 82/12/23, 8212290246

K Utility Final Safety Analysis Report (FSAR) & amends

B212140323 Forwards FSAR Figure 10 7-2, "Mechanical Control Diagram Raw Cooling Water Sys," inadvertently omitted from B20812 submittal
KAMMER, D. S. Tennessee Valley Authority 82/12/07 DENTON, H. R.
Office of Nuclear Reactor Regulation, Director 2pp 16402 054
24X Fiche 50-259, 82/12/07, 8212140323

P Operating license stage documents & correspondence

B21230066 Generic Ltr 82-27 to all BWR licensees of operating reactors except LACBWR, Big Rock Point, Dresden 1, Humboldt Bay, applicants for OL & holders of CP re transmittal of NUREG-0763 & NUREG-0783 Svc list encl w/o stated encl
EISENHUT, D. G. Division of Licensing 82/11/15 General Public
Utilities - GPO Service Corp 22pp 16387 004 24X
Fiche 50-000, 82/11/15, 821230066

B212090118 Confirms arrangements for 821215 meeting in Region 2 ofc re MSIV leakage at Unit 2 Proposed agenda encl
O'REILLY, J. P. Region 2, Office of Director 82/12/01 PARRIS, H. G.
Tennessee Valley Authority 2pp 16357 274 24X
Fiche 50-259, 82/12/01, 8212090118

B212090346 Confirms 821102 telcon re 821202 enforcement conference in Atlanta, GA to discuss results of survey of waste oil facilities & plans for disposing of waste oil
O'REILLY, J. P. Region 2, Office of Director 82/12/01 PARRIS, H. G.
Tennessee Valley Authority 2pp 16365 157 24X
Fiche 50-259, 82/12/01, 8212090346

B212070288 Advises that NUREG-0737, Item II K 3 27, "Common Ref Level," will be reviewed w/control room design review as required by Item I D 1 Assessment team recommendations will be considered final resolution
MILLS, L. M. Tennessee Valley Authority 82/12/03 DENTON, H. R.
Office of Nuclear Reactor Regulation, Director 2pp 16339 013
24X Fiche 50-259, 82/12/03, 8212070288

B212090083 Application for amend to Licenses DPR-33, DPR-52 & DPR-6B, changing duration of containment integrated leak rate test from 24-h to 8-h
MILLS, L. M. Tennessee Valley Authority 82/12/03 DENTON, H. R.
Office of Nuclear Reactor Regulation, Director 3pp 16357 192
24X Fiche 50-259, 82/12/03, 8212090083

--B212090088 Proposed Tech Spec revisions changing duration of containment integrated leak rate test from 24-h to 8-h Justification for proposed revisions encl
* Tennessee Valley Authority 82/12/03 36pp 16357 195 24X
Fiche 50-259, 82/12/03, 8212090083

B212270192 Forwards item-by-item description of responses discussed during 821027 telcon w/F. Clemenson re technical evaluation rept, "Control of Heavy Loads - NUREG-0454," for facility
MILLS, L. M. Tennessee Valley Authority 82/12/14 VASSALLO, D. B.
Operating Reactors Branch 2 44pp 16539 303 24X
Fiche 50-259, 82/12/14, 8212270192

B212280085 Application to amend Licenses DPR-33, DPR-52 & DPR-6B, changing Tech Specs re bypassing of main steam line tunnel temp switches for up to 4-h
MILLS, L. M. Tennessee Valley Authority 82/12/17 DENTON, H. R.
Office of Nuclear Reactor Regulation, Director 2pp 16564 238
24X Fiche 50-259, 82/12/17, 8212280085

--B212280088 Proposed Tech Spec changes re bypassing of main steam line tunnel temp switches for up to 4-h
* Tennessee Valley Authority 82/12/17 16pp 16564 240 24X
Fiche 50-259, 82/12/17, 8212280085

B212280295 Forwards draft response to 821108 request for addl info re implementation of Revision 1 to NUREG-0313 on matl selection & processing for BWR coolant pressure boundary piping
MILLS, L. M. Tennessee Valley Authority 82/12/20 DENTON, H. R.
Office of Nuclear Reactor Regulation, Director 10pp 16562 007
24X Fiche 50-259, 82/12/20, 8212280295

Q Inspection reports, IE Bulletins & correspondence

B208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants" Svc list encl
DEYOUNG, R. C. Director's Office, Office of Inspection and
Enforcement 82/10/28 Consolidated Edison Co. of New York, Inc.
112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240

B208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters" Svc list encl
COBB, L. I. Division of Fuel Facilities, Materials & Safeguards
82/11/05 Consolidated Edison Co. of New York, Inc. 110pp
16372 142 24X Fiche 50-000, 82/11/05, 8208190245

B212090456 Ack receipt of 821022 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/82-24, 50-260/82-24 & 50-296/82-24
LEWIS, R. C. Division of Project & Resident Programs 82/11/12
PARRIS, H. G. Tennessee Valley Authority 1p 16364 009 24X
Fiche 50-259, 82/11/12, 8212090456

--B212090461 Responds to NRC 820921 ltr re violations noted in IE Insp Repts 50-259/82-24, 50-260/82-24 & 50-296/82-24 Corrective actions evaluation concerning adequacy of review process will be provided by 830102
MILLS, L. M. Tennessee Valley Authority 82/10/22 O'REILLY, J. P.
Region 2, Office of Director 5pp 16364 010 24X
Fiche 50-259, 82/11/12, 8212090456

DOCKETED ITEMS

- 8212090467 Forwards IE Insp Repts 50-259/82-24, 50-260/82-24 & 50-296/82-24 on 820725-0825 & notice of violation
LEWIS, R C Division of Project & Resident Programs 82/09/21
PARRIS, H G Tennessee Valley Authority 2pp 16364 015 24X
Fiche 50-259, 82/11/12, 8212090456
- 8212090471 Notice of violation from insp on 820726-0825
* Division of Project & Resident Programs 82/09/21 2pp
16364 017 24X Fiche 50-259, 82/11/12, 8212090456
- 8212090479 IE Insp Repts 50-259/82-24, 50-260/82-24 & 50-296/82-24 on 820726-0825 Noncompliance noted post-maint testing not conducted on steam pilot valves & test criteria did not incorporate requirements & acceptance limits
CHASE, J W, PAULK, O L, CANTRELL, F S Division of Project & Resident Programs 82/09/09 10pp 16364 019 24X
Fiche 50-259, 82/11/12, 8212090456
- B'08190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18
Consolidated Edison Co of New York, Inc 109pp 16411 199 24X
Fiche 50-000, 82/11/18, 8208190251
- B'08190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26
Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000, 82/11/26, 8208190256
- B'08190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl
CORB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30
Consolidated Edison Co of New York, Inc 356pp
16387 028 24X Fiche 50-000, 82/11/30, 8208190257
- B'12030212 Ack receipt of 821119 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Repts
50-259/82-30, 50-260/82-30 & 50-296/82-30
LEWIS, R C Division of Project & Resident Programs 82/11/30
PARRIS, H G Tennessee Valley Authority 1p 16307 067 24X
Fiche 50-259, 82/11/30, 8212030212
- 8212030220 Responds to NRC 821019 ltr re violations noted in IE Safeguards Insp Repts 50-259/82-30, 50-260/82-30 & 50-296/82-30 Corrective actions withheld (ref 10CFR73 21)
MILLS, L H Tennessee Valley Authority 82/11/19 O'REILLY, J P
Region 2, Office of Director 1p 16307 068 24X
Fiche 50-259, 82/11/30, 8212030212
- 8212030226 Forwards IE Safeguards Insp Repts 50-259/82-30, 50-260/82-30 & 50-296/82-30 on 820920-24 & notice of violation Rept details & notice of violation withheld (ref 10CFR73 21)
LEWIS, R C Division of Project & Resident Programs 82/10/19
PARRIS, H G Tennessee Valley Authority 2pp 16307 069 24X
Fiche 50-259, 82/11/30, 8212030212
- 8212030232 IE Insp Repts 50-259/82-30, 50-260/82-30 & 50-296/82-30 on 820920-24 Noncompliance noted in areas of locks, keys & combinations, physical barriers - protected areas, lighting & access control Details withheld (ref 10CFR73 21)
HALL, B L, GOODER, R W, MCQUIRE, D R Division of Engineering & Technical Programs 82/10/14 2pp 16307 071 24X
Fiche 50-259, 82/11/30, 8212030212
- B'08190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03
Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259
- B'08190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03
Consolidated Edison Co of New York, Inc 110pp 16462 064 24X
Fiche 50-000, 82/12/03, 8208190261
- B'12090080 Ack receipt of 821124 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Repts
50-259/82-36, 50-260/82-36 & 50-296/82-36
LEWIS, R C Division of Project & Resident Programs 82/12/04
PARRIS, H G Tennessee Valley Authority 2pp 16357 236 24X
Fiche 50-259, 82/12/06, 8212090080
- 8212090092 Responds to NRC 821022 ltr re violations noted in IE Safeguards Insp Repts 50-259/82-36, 50-260/82-36 & 50-296/82-36 Corrective actions withheld (ref 10CFR73 21)
MILLS, L H Tennessee Valley Authority 82/11/24 O'REILLY, J P
Region 2, Office of Director 1p 16357 238 24X
Fiche 50-259, 82/12/06, 8212090080
- 8212090108 Forwards IE Safeguards Insp Repts 50-259/82-36, 50-260/82-36 & 50-296/82-36 on 820908-09 & notice of violation Rept details & notice of violation withheld (ref 10CFR73 21)
O'REILLY, J P Region 2, Office of Director 82/10/22
PARRIS, H G Tennessee Valley Authority 2pp 16357 239 24X
Fiche 50-259, 82/12/06, 8212090080
- 8212090124 IE Safeguards Insp Repts 50-259/82-36, 50-260/82-36 & 50-296/82-36 on 820908-09 Noncompliance noted in area of access controls Details withheld (ref 10CFR73 21)
TILLMAN, A, MCQUIRE, D R Division of Engineering & Technical Programs 82/10/20 1p 16357 241 24X Fiche 50-259, 82/12/06, 8212090080
- B212170345 EN-82-041 on 821217, notice of violation & proposed imposition of civil penalty in amount of \$3,125 will be issued to licensee for defective packaging in two shipments or low-specific activity radwaste to Richland, WA
BROCKETT, T Director's Office, Office of Inspection and Enforcement 82/12/14 1p 16452 362 24X Fiche 50-296, 82/12/14, 8212170345
- B'08190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16
Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16, 8208190267
- B'08190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type IVE-27 " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20
Consolidated Edison Co of New York, Inc 108pp 16628 293 24X
Fiche 50-000, 82/12/20, 8208190268
- R Periodic operating reports & related correspondence
- B212290281 Forwards monthly operating repts for Oct 1982
JONES, O T Tennessee Valley Authority 82/11/10 Office of Resource Management, Director 1p 16581 074 24X
Fiche 50-259, 82/11/10, 8212290281
- 8212290287 Monthly operating repts for Oct 1982
THOM, T Tennessee Valley Authority 82/11/01 39pp 16581 075 24X Fiche 50-259, 82/11/10, 8212290281
- B212030071 Forwards central emergency control ctr meteorological data availability statistics for Apr-Sept 1982
MILLS, L H Tennessee Valley Authority 82/11/30 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 16304 210 24X Fiche 50-000, 82/11/30, 8212030071
- S Reportable occurrences, LERs & related correspondence
- B'12020261 Forwards LER 82-051/03L-0
GREEN, H J Tennessee Valley Authority 82/11/17 O'REILLY, J P
Region 2, Office of Director 1p 16279 360 24X
Fiche 50-296, 82/11/17, 8212020261
- 8212020264 LER 82-051/03L-0 on 821021, during normal operation, drywell CAM 3-90-256 removed from svc for maint due to erratic flow caused by vibration Packing on flow control valve NMC Model AM-331 OF continuous air monitor tightened
THORPE, D Tennessee Valley Authority 82/11/17 Region 2, Office of Director 2pp 16279 361 24X Fiche 50-296, 82/11/17, 8212020261
- B'12020116 Forwards LER 82-052/03L-0
GREEN, H J Tennessee Valley Authority 82/11/23 O'REILLY, J P
Region 2, Office of Director 1p 16272 047 24X
Fiche 50-296, 82/11/23, 8212020116
- 8212020124 LER 82-052/03L-0 on 821103, CAM 3-RR-90-256 (drywell atmosphere monitor) became inoperable Caused by sample pump failure due to normal end of svc life Schuitzer Series 325 vacuum pump rebuilt & returned to svc
PORTER, M R Tennessee Valley Authority 82/11/23 Region 2, Office of Director 2pp 16272 048 24X Fiche 50-296, 82/11/23, 8212020116
- B'12020240 Forwards updated LER 82-043/03X-1
GREEN, H J Tennessee Valley Authority 82/11/23 O'REILLY, J P
Region 2, Office of Director 1p 16274 149 24X
Fiche 50-296, 82/11/23, 8212020240
- 8212020244 Updated LER 82-043/03X-1 on 820909, generator/flywheel ball bearing on 480-volt reactor motor operated valve board 3DN motor generator set became noisy Caused by lack of lubricant film on bearing surfaces Bearing replaced
AARON, J R Tennessee Valley Authority 82/11/23 Region 2, Office of Director 3pp 16274 150 24X Fiche 50-296, 82/11/23, 8212020240

8212150071 Forwards LER 82-054/03L-0
GREEN, H J Tennessee Valley Authority 82/12/09 O'REILLY, J P
Region 2, Office of Director 1p 16431 009 24X
Fiche 50-296, 82/12/09, 8212150071

- 8212150076 LER 82-054/03L-0 on 821110 low-pressure main steamline
pressure switch 3-PS-1-76 had setpoint less than Tech Spec
requirements. Caused by setpoint drift. Switch recalibr &
returned to svc.
IRBY, B J Tennessee Valley Authority 82/12/09 Region 2,
Office of Director 3pp 16431 010 24X Fiche 50-296, 82/12/09,
8212150071

8212150107 Forwards LER 82-053/03L-0
GREEN, H J Tennessee Valley Authority 82/12/09 O'REILLY, J P
Region 2, Office of Director 1p 16431 001 24X
Fiche 50-296, 82/12/09, 8212150107

- 8212150111 LER 82-053/03L-0 on 821111, while performing daily background
source check of turbine bldg continuous air monitor
3-90-251, inlet hose found disconnected. Probably caused by
failure to securely latch quick disconnect fittings.
THORPE, D Tennessee Valley Authority 82/12/09 Region 4,
Office of Director 2pp 16431 002 24X Fiche 50-296, 82/12/09,
8212150107

DOCKET 50-298 COOPER NUCLEAR STATION

F Security, medical, emergency & fire protection plans

8212070425 Responds to FOIA request for documents re 820809 notice of
violation & order imposing civil penalty. Forwards App A
documents App B documents completely withheld & Documents
C1-C4 partially withheld (ref FOIA Exemptions 3, 5 & 7)
FELTON, J M Division of Rules and Records 82/11/05 MCGARRY, J M
Debevoise & Liberman 5pp 16355 003 24X Fiche 50-000, 82/11/05,
8212070425

-- 8212070432 Summary of 820412 meeting w/util in Region 4 of re concerns
& enforcement options being considered pertaining to
inadequacies in installation of emergency warning sys
OAGLIARDO, J E Division of Resident, Reactor Project & Engineering
Programs 82/04/23 COLLINS, J T Region 4, Office of Director
2pp 16355 012 24X Fiche 50-000, 82/11/05, 8212070425

-- 8212070437 Forwards J Pilant 820524 ltr describing util actions taken
to upgrade public notification sys. Tone alert radios will be
available for all residences within 10-mile emergency
planning zone not covered by fixed sirens.
COLLINS, J T Region 4, Office of Director 82/05/26 GRIMES, B K
Division of Emergency Preparedness 1p 16355 014 24X
Fiche 50-000, 82/11/05, 8212070425

-- 8212070441 Forwards questions from Commission Ahearne re facility
enforcement action.
HARDING, V Commissioners 82/05/28 DEYOUNG, R Director's
Office, Office of Inspection and Enforcement 3pp 16355 019
24X Fiche 50-000, 82/11/05, 8212070425

-- 8212070457 Requests draft Commission statement for issuance of proposed
civil penalty to util. Statement should indicate Commission
approval of issuance of notice of violation & proposed civil
penalty re notification sys.
CHILK, B J Office of the Secretary of the Commission 82/07/21
BICKWIT, L Office of the General Counsel 1p 16355 041 24X
Fiche 50-000, 82/11/05, 8212070425

-- 8212070473 Concludes that all Region 4 licensees in compliance w/820401
deadline for implementation of prompt notification sys.
COLLINS, J T Region 4, Office of Director 82/02/01 GRIMES, B K
Division of Emergency Preparedness 2pp 16355 104 24X
Fiche 50-000, 82/11/05, 8212070425

-- 8212070491 Forwards radiological emergency response plans for facility
& state & local entities within emergency planning zones.
Plans do not meet requirements of NUREG-0654, Revision 1
w/ Nebraska Public Power District 81/01/02 DENTON, H R Office
of Nuclear Reactor Regulation, Director 46pp 16355 107 24X
Fiche 50-000, 82/11/05, 8212070425

8212030159 Application for amend to License DPR-46, consisting of
proposed changes to Tech Specs assuring continuous operable
water supply for fire fighting sys from two fire pumps. Class
III amend fee submitted.
PILANT, J M Nebraska Public Power District 82/11/24
VASSALLO, D B Operating Reactors Branch 2 2pp 16307 095 24X
Fiche 50-298, 82/11/24, 8212030159

-- 8212030162 Proposed changes to Tech Specs assuring continuous operable
water supply for fire fighting sys from two fire pumps
w/ Nebraska Public Power District 82/11/24 52pp 16307 097
24X Fiche 50-298, 82/11/24, 8212030159

8212070137 Ack receipt of 820806 ltr informing NRC of steps taken to
correct open items noted in IE Insp Rept 50-298/82-08
HADSEN, O L Division of Resident, Reactor Project & Engineering
Programs 82/12/01 PILANT, J M Nebraska Public Power District
2pp 16326 238 24X Fiche 50-298, 82/12/01, 8212070137

-- 8212070141 Responds to NRC 820701 ltr re open items noted in IE Insp
Rept 50-298/82-08. Corrective actions microfiche reader/
printer & file will be removed from NRC space in technical
support ctr.
PILANT, J M Nebraska Public Power District 82/08/06
COLLINS, J T Region 4, Office of Director 11pp 16326 240 24X
Fiche 50-298, 82/12/01, 8212070137

8212070402 Responds to NRC 821202 telcon request for info re emergency
operation facility. Permanent backup facility presently
available.
PILANT, J M Nebraska Public Power District 82/12/02
VASSALLO, D B Operating Reactors Branch 2 1p 16336 342 24X
Fiche 50-298, 82/12/02, 8212070402

8212080506 Ack receipt of 821118 ltr informing NRC of steps taken to
correct violations noted in IE Insp Rept 50-298/82-28
J Kelly chief of physical security section; plans 821208-09
visit to examine protective resource sys.
COLLINS, J T Region 4, Office of Director 82/12/03 PILANT, J M
Nebraska Public Power District 1p 16352 103 24X
Fiche 50-298, 82/12/03, 8212080506

8212130336 Releases public version of revised emergency plan
implementing procedures.
FELTON, J M Division of Rules and Records 82/12/07 Document
Management Branch 1p 16413 244 24X Fiche 50-298, 82/12/07,
8212130336

-- 8212130342 Forwards public version of revised emergency plan
implementing procedures, including Procedures 5 7 7 re
activation of technical support ctr & 5 7 9 re activation of
emergency operations facility.
PILANT, J M Nebraska Public Power District 82/11/19
DENTON, H R Office of Nuclear Reactor Regulation, Director 1p
16413 245 24X Fiche 50-298, 82/12/07, 8212130336

-- 8212130346 Public version of revised emergency plan implementing
procedures, including Procedures 5 7 7 re activation of
technical support ctr & 5 7 9 re activation of emergency
operations facilities.
LESSOR, L C, BAYER, J, WHITMAN, D Nebraska Public Power District
82/11/08 150pp 16413 246 24X Fiche 50-298, 82/12/07,
8212130336

8212280399 Advises that commitment date, per 820604 ltr, re NUREG-0737,
Item II A 1.2, "Upgrade Emergency Support Facilities," will
not be met due to extensive contractual negotiations & legal
reviews.
PILANT, J M Nebraska Public Power District 82/12/16
EISENHUT, D Q Division of Licensing 1p 16560 052 24X
Fiche 50-298, 82/12/16, 8212280399

P Operating license stage documents & correspondence

8212070425 Responds to FOIA request for documents re 820809 notice of
violation & order imposing civil penalty. Forwards App A
documents App B documents completely withheld & Documents
C1-C4 partially withheld (ref FOIA Exemptions 3, 5 & 7)
FELTON, J M Division of Rules and Records 82/11/05 MCGARRY, J M
Debevoise & Liberman 5pp 16355 003 24X Fiche 50-000, 82/11/05,
8212070425

- 8212070455 Forwards Commissioner Roberts dissenting view on facility
enforcement action (EA-82-46)
LAVERY, J H NRC - No Detailed Affiliation Given 82/07/07
CHILK, B J Office of the Secretary of the Commission 10pp
16355 031 24X Fiche 50-000, 82/11/05, 8212070425

-- 8212070467 Statement by Commissioner Roberts disagreeing w/Commission
decision fine of \$30,000 proposed for failure to comply w/
regulatory requirement. Util should not be cited & fined
for commission of matl false statements. Related info encl
ROBERTS, T H Commissioners 82/11/05 7pp 16355 094 24X
Fiche 50-000, 82/11/05, 8212070425

-- 8212070500 Discusses Commission 820528 briefing re proposed
enforcement action against util.
CHILK, B J Office of the Secretary of the Commission 82/06/08
DRACKS, W J Office of the Executive Director for Operations 1p
16355 254 24X Fiche 50-298, 82/11/05, 8212070425

DOCKETED ITEMS

- 821230046 Generic Ltr 82-27 to all BWR licensees of operating reactors except LACBWR, Big Rock Point, Dresden 1, Humboldt Bay, applicants for OL & holders of CP re transmittal of NUREG-0763 & NUREG-0783 Svc list encl W/o stated encl EISENHUT, D G Division of Licensing 82/11/15 General Public Utilities - OPU Service Corp 22pp 16387 004 24X Fiche 50-000, 82/11/15, 821230046
- 8212030159 Application for amend to License DPR-46, consisting of proposed changes to Tech Specs assuring continuous operable water supply for fire fighting sys from two fire pumps Class III amend fee submitted PILANT, J M Nebraska Public Power District 82/11/24 VASSALLO, D B Operating Reactors Branch 2 2pp 16307 095 24X Fiche 50-298, 82/11/24, 8212030159
- 8212030162 Proposed changes to Tech Specs assuring continuous operable water supply for fire fighting sys from two fire pumps * Nebraska Public Power District 82/11/24 52pp 16307 097 24X Fiche 50-298, 82/11/24, 8212030159
- 8212070175 Responds to Franklin Research Ctr 821029 request for info re plant unique analysis rept concerning Mark I containment program All small & large bore piping associated w/containment sys considered in evaluations PILANT, J M Nebraska Public Power District 82/12/01 VASSALLO, D B Operating Reactors Branch 2 5pp 16334 325 24X Fiche 50-298, 82/12/01, 8212070175
- 8212130276 Forwards safety evaluation of BWR owners group 810522, 0921 & 820902 responses to NUREG-0737, Item II K 3 25, "Effect of Loss of AC Power on Pump Seals" Responses acceptable VASSALLO, D B Operating Reactors Branch 2 82/12/01 PILANT, J M Nebraska Public Power District 7pp 16418 220 24X Fiche 50-298, 82/12/01, 8212130276
- 8212100293 Responds to NRC 821108 request for addl info re response to Generic Ltr 81-04 Selection of welds in loop of large bore reactor recirculation piping will be examined during 1983 refueling outage PILANT, J M Nebraska Public Power District 82/12/02 VASSALLO, D B Operating Reactors Branch 2 48pp 16376 221 24X Fiche 50-298, 82/12/02, 8212100293
- 8212100171 Provides addl info in response to 811005 draft technical evaluation rept re Guideline 4 of NUREG-0612 on special lifting devices PILANT, J M Nebraska Public Power District 82/12/03 EISENHUT, D G Division of Licensing 2pp 16373 348 24X Fiche 50-298, 82/12/03, 8212100171
- 821280086 Forwards SER for NUREG-0737, Items I A 2 1, "Immediate Upgrading or Reactor Operation & Senior Reactor Operator Training & Qualifications" & II B 4, "Training for Mitigating Core Damage" Items complete VASSALLO, D B Operating Reactors Branch 2 82/12/09 PILANT, J M Nebraska Public Power District 16pp 16593 053 24X Fiche 50-298, 82/12/09, 821280086
- G Inspection reports, IE Bulletin & correspondence
- 8207180063 FOIA request for documents re 820809 notice of violation & order imposing civil penalty & proposed requirement concerning conduct of mgt audit set forth in order MCGARRY, J M Debevoise & Liberman 82/09/02 FELTON, J M Division of Rules and Records 2pp 16355 001 24X Fiche 50-298, 82/09/02, 8207180063
- 8208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants" Svc list encl DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240
- 8208190248 IE Info Notice 82-42, "Defects Observed in Panasonic Model B01 & Model B02 Thermoluminescent Dosimeters" Svc list encl COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000, 82/11/05, 8208190248
- 8212070425 Responds to FOIA request for documents re 820809 notice of violation & order imposing civil penalty Forwards App A documents App B documents completely withheld & Documents C1-C4 partially withheld (ref FOIA Exemptions 3, 5 & 7) FELTON, J M Division of Rules and Records 82/11/05 MCGARRY, J M Debevoise & Liberman 3pp 16355 003 24X Fiche 50-000, 82/11/05, 8212070425
- 8206140162 Comments on proposed imposition of civil penalty for failure to complete early warning sys by 820301 Site & classification of penalty discussed SIEGEL, B Operating Reactors Branch 2 82/06/08 NOVAK, T M Assistant Director for Operating Reactors 3pp 16355 027 24X Fiche 50-000, 82/11/05, 8212070425
- 8212070443 Forwards D Siegel views re proposed enforcement action (EA-82-46) Aggressive action warranted Further action will not be taken until response to 820603 memo received DIRCKS, W J Office of the Executive Director for Operations 82/06/16 PALLADINO, N, GILINSKY, V, AHEARNE, J Commissioners 1p 16355 024 24X Fiche 50-000, 82/11/05, 8212070425
- 8212070444 Forwards view expressed by project manager re pending enforcement matter EISENHUT, D G NRC - No Detailed Affiliation Given 82/06/08 CASE, E Office of Nuclear Reactor Regulation, Director LIEBERMAN, J Director's Office, Office of Inspection and Enforcement 1p 16355 025 24X Fiche 50-000, 82/11/05, 8212070425
- 8212070447 Forwards memo from D Siegel re views on pending enforcement action against licensee Encl should be treated as "For Official Use Only" NOVAK, T M NRC - No Detailed Affiliation Given 82/06/08 EISENHUT, D G NRC - No Detailed Affiliation Given 1p 16355 026 24X Fiche 50-000, 82/11/05, 8212070425
- 8212070452 Continues to support enforcement action (EA-82-46) proposed in 820603 ltr DIRCKS, W J Office of the Executive Director for Operations 82/05/21 PALLADINO, N, GILINSKY, V, AHEARNE, J Commissioners 1p 16355 030 24X Fiche 50-000, 82/11/05, 8212070425
- 8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements" Svc list encl JORDAN, E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X Fiche 50-000, 82/11/18, 8208190251
- 8212100197 Discusses issuance of SALP Rept 50-298/82-24 for Jul 1981-June 1982 Since util did not comment on evaluation, SALP board rept issued as NRC rept COLLINS, J T Region 4, Office of Director 82/11/24 PILANT, J M Nebraska Public Power District 2pp 16377 111 24X Fiche 50-298, 82/11/24, 8212100197
- 8212100212 Forwards SALP Rept 50-298/82-24 for Jul 1981-June 1982 Comments requested by 821018 MADSEN, G L Division of Resident, Reactor Project & Engineering Programs 82/09/22 PILANT, J M Nebraska Public Power District 2pp 16377 113 24X Fiche 50-298, 82/11/24, 8212100197
- 8212100213 SALP Rept 50-298/82-24 for Jul 1981-June 1982 Licensee performance rated as Category I WESTERMAN, T F, MADSEN, G L Division of Resident, Reactor Project & Engineering Programs 82/09/20 22pp 16377 115 24X Fiche 50-298, 82/11/24, 8212100197
- 8212100265 Forwards IE Insp Rept 50-298/82-31 on 821001-31 No noncompliance noted MADSEN, G L Division of Resident, Reactor Project & Engineering Programs 82/11/24 PILANT, J M Nebraska Public Power District 2pp 16376 129 24X Fiche 50-298, 82/11/24, 8212100265
- 8212100271 IE Insp Rept 50-298/82-31 on 821001-31 No noncompliance noted Major areas inspected operational safety verifications, monthly surveillance & maint observations, plant trips, safety sys challenges & licensee event followup DUBOIS, D L, MCCORDY, S L, WESTERMAN, T F Division of Resident, Reactor Project & Engineering Programs 82/11/23 6pp 16376 131 24X Fiche 50-298, 82/11/24, 8212100265
- 8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Radiolocks" Svc list encl DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000, 82/11/26, 8208190256
- 8208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl" Svc list encl COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000, 82/11/30, 8208190257
- 8212070137 Act receipt of 820806 ltr informing NRC of steps taken to correct open items noted in IE Insp Rept 50-298/82-08 MADSEN, G L Division of Resident, Reactor Project & Engineering Programs 82/12/01 PILANT, J M Nebraska Public Power District 2pp 16326 238 24X Fiche 50-298, 82/12/01, 8212070137

8212070141 Responds to NRC 820701 ltr re open items noted in IE Insp Rept 50-298/82-08 Corrective actions microfiche reader/printer & file will be removed from NRC space in technical support ctr
PILANT, J M Nebraska Public Power District 82/08/06
COLLINS, J T Region 4, Office of Director 11pp 16326 240 24X
Fiche 50-298, 82/12/01, 8212070137

8208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies" Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co. of New York, Inc 11pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259

8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets" Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co. of New York, Inc 110pp 16462 064 24X
Fiche 50-000, 82/12/03, 8208190261

8212080506 Ack receipt of 821118 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-298/82-28
J Kelly chief of physical security section, plans 821208-09 visit to examine protective resource sys
COLLINS, J T Region 4, Office of Director 82/12/03 PILANT, J M Nebraska Public Power District 1p 16392 105 24X
Fiche 50-298, 82/12/03, 8212080506

8212140403 Approves proposed mgt appraisal plan & schedule described in 821008, 1119 & 23 responses to order modifying license, effective immediately. Plan should be initiated as soon as possible
COLLINS, J T Region 4, Office of Director 82/12/07 JONES, C R Nebraska Public Power District 1p 16405 141 24X
Fiche 50-298, 82/12/07, 8212140403

8212280409 Forwards IE Insp Rept 50-298/82-30 on 821018-22 & notice of violation
MADSEN, G L Division of Resident, Reactor Project & Engineering Programs 82/12/08 PILANT, J M Nebraska Public Power District 7pp 16560 029 24X Fiche 50-298, 82/12/08, 8212280409

8212280413 Notice of violation from insp on 821018-22
* Division of Resident, Reactor Project & Engineering Programs 82/12/08 1p 16560 031 24X Fiche 50-298, 82/12/08, 8212280409

--8212280420 IE Insp Rept 50-298/82-30 on 821018-22 Noncompliance noted multiple failures to perform biennial procedure review, primarily in maint area
REDARD, R T, WESTERMAN, T F Division of Resident, Reactor Project & Engineering Programs 82/11/30 4pp 16560 032 24X
Fiche 50-298, 82/12/08, 8212280409

8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring" Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co. of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16, 8208190267

8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27" Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co. of New York, Inc 108pp 16628 293 24X
Fiche 50-000, 82/12/20, 8208190268

R Periodic operating reports & related correspondence

8212290312 Forwards monthly operating rept for Oct 1982
LESSOR, L C Nebraska Public Power District 82/11/02 Office of Resource Management, Director 1p 16588 029 24X
Fiche 50-298, 82/11/02, 8212290312

--8212290315 Monthly operating rept for Oct 1982
BALLINGER, P L Nebraska Public Power District 82/11/02 4pp 16588 030 24X Fiche 50-298, 82/11/02, 8212290312

S Reportable occurrences, LERs & related correspondence

8212300106 Forwards LER 82-023/03L-0 Detailed event analysis submitted
LESSOR, L C Nebraska Public Power District 82/12/23 COLLINS, J T Region 4, Office of Director 3pp 16598 249 24X
Fiche 50-298, 82/12/23, 8212300106

--8212300111 LER 82-023/03L-0 on 821128, while snubber CS-57 taken out of svc to repair oil leak; snubber found inverted. Caused by loose extension tube locknut allowing snubber to rotate. Snubber replaced
BALLINGER, P Nebraska Public Power District 82/12/23 Region 4, Office of Director 1p 16598 252 24X Fiche 50-298, 82/12/23, 8212300106

T Hearing transcripts on non-antitrust matters

8212070425 Responds to FOIA request for documents re 820809 notice of violation & order imposing civil penalty. Forwards App A documents App B documents completely withheld & Documents C1-C4 partially withheld (ref FOIA Exemptions 3, 5 & 7).
FELTON, J M Division of Rules and Records 82/11/05 MCGARRY, J M Debevoise & Liberman 5pp 16355 003 24X Fiche 50-000, 82/11/05, 8212070425

--8212070496 Forwards transcript of closed Commission 820528 discussion of enforcement action Exemption 5 used to close meeting. Recommendations re release of portions to public needed by 820611
CHILK, S J Office of the Secretary of the Commission 82/06/01 DIRCKS, W J Office of the Executive Director for Operations 4pp 16355 154 24X Fiche 50-000, 82/11/05, 8212070425

DOCKET 50-301 POINT BEACH NUCLEAR PLANT, UNIT 2

F Security, medical, emergency & fire protection plans

8212070079 Forwards revised Page 10 3 to safeguards plan Page withheld (ref 10CFR2 790 & 73 21)
BURSTEIN, S Wisconsin Electric Power Co 82/12/02 DENTON, H R Office of Nuclear Reactor Regulation, Director CLARK, R A Operating Reactors Branch 3 1p 16327 271 24X
Fiche 50-266, 82/12/02, 8212070079

8212280082 Responds to Burstein 821110 & 1202 ltrs re addition of Chapter 10 to physical security plan. Changes acceptable. Ltrs withheld (ref 10CFR73 21)
CLARK, R A Operating Reactors Branch 3 82/12/13 FAY, C W Wisconsin Electric Power Co 1p 16593 087 24X
Fiche 50-266, 82/12/13, 8212280082

8212220306 Discusses layout of communications equipment required in control room, onsite technical support ctr & near-site emergency operations facility
KEPPLER, J O Region 3, Office of Director 82/12/16 Commonwealth Edison Co 3pp 16503 351 24X Fiche 50-000, 82/12/16, 8212220306

8212290324 Confirms plans for 830110 mgt meeting in Milwaukee, WI re fire protection concerns. Written responses to IE Insp Repts 50-266/82-17 & 50-301/82-17 deferred until 830125
NORELIUS, C E Division of Engineering & Technical Programs 82/12/23 BURSTEIN, S Wisconsin Electric Power Co 1p 16589 157 24X Fiche 50-266, 82/12/23, 8212290324

G Adjudicatory correspondence

8212080251 Supports steam generator tube sleeving
BLAHA, O, ENOELBRECHT, L, SCHMIDCK, D Two Rivers, WI 82/11/29 BLOCH, P Atomic Safety and Licensing Board Panel 1p 16354 126 24X Fiche 50-266, 82/11/29, 8212080251

8212230357 Forwards licensee proposed findings of fact & conclusions of law in form of proposed initial decision re repair of corroded steam generator tubes
CHURCHILL, B W Shaw, Pittman, Potts & Trowbridge CHURCHILL, B W Wisconsin Electric Power Co 82/12/20 BLOCH, P B, KLINE, J R, PAXTON, H C Atomic Safety and Licensing Board Panel 1p 16511 207 24X Fiche 50-266, 82/12/20, 8212230357

--8212230359 Proposed findings of fact & conclusions of law in form of proposed initial decision re repair of corroded steam generator tubes by inserting sleeves. Certificate of Svc encl
CHURCHILL, B W Wisconsin Electric Power Co CHURCHILL, B W Shaw, Pittman, Potts & Trowbridge 82/12/20 31pp 16511 208 24X
Fiche 50-266, 82/12/20, 8212230357

8212270316 Notice of appeal from 821210 special prehearing conference order dismissing Decade 820810 & 1105 petitions to intervene. Affidavit of mailing encl
ANDERSON, P Wisconsin's Environmental Decade 82/12/20 3pp 16530 281 24X Fiche 50-266, 82/12/20, 8212270316

8212270323 Brief supporting appeal from 821210 special prehearing conference order denying 820810 petition to intervene & request for extension of time to complete brief. Dismissal of petition on stated grounds contrary to law
ANDERSON, P Wisconsin's Environmental Decade 82/12/20 Atomic Safety and Licensing Board Panel 15pp 16530 215 24X
Fiche 50-266, 82/12/20, 8212270323

DOCKETED ITEMS

P Operating license stage documents & correspondence

0212170040 Ack receipt of 821123 ltr transmitting Class I fee for 020930 application Basis for not remitting additional requested fee acceptable
DIGGS, R M License Fee Management Branch 82/12/03 FAY, C W
Wisconsin Electric Power Co 1p 16480 362 24X
Fiche 50-000, 82/12/03, 8212170040

8208190263 Generic Ltr 82-32 to all PWR licensees re potential steam generator-related generic requirements Forwards Science Applications, Inc draft rept re subj requirements Comments requested within 30 days of ltr Svc list encl
EISENHUT, D G Division of Licensing 82/12/09 Consolidated Edison Co of New York, Inc 29pp 16629 247 24X
Fiche 50-000, 82/12/09, 8208190263

0212140103 Generic Ltr 82-28 to all licensees of operating Westinghouse & C-E PWRs (except Arkansas Nuclear One, Unit 2 & San Onofre 2 & 3) re inadequate core cooling instrumentation sys Svc list encl
EISENHUT, D G Division of Licensing 82/12/10 Yankee Atomic Electric Co 27pp 16690 035 24X Fiche 50-000, 82/12/10, 8212140103

8212170326 Refs Westinghouse 791206 ltr in response to RA Clark 821108 request for ECCS evaluation model addressing two loop upper plenum injection plants Calculations for worst case large break & sensitivity studies will be submitted by 830225
FAY, C W Wisconsin Electric Power Co 82/12/10 DENTON, H R Office of Nuclear Reactor Regulation, Director CLARK, R A Operating Reactors Branch 3 2pp 16453 224 24X
Fiche 50-266, 82/12/10, 8212170326

0212100356 Comments on technical evaluation rept re seismic qualification or auxiliary feedwater sys per 821112 request Recommendation to acquire complete SSE level of seismic capacity constitutes unnecessary & expensive backfit
FAY, C W Wisconsin Electric Power Co 82/12/15 DENTON, H R Office of Nuclear Reactor Regulation, Director CLARK, R A Operating Reactors Branch 3 5pp 16492 248 24X
Fiche 50-266, 82/12/15, 8212100356

8212220422 Application to amend Licenses DPR-24 & DPR-27, consisting of Tech Spec Change Request B6 to address NUREG-0737, Item II K 3 3, "Reporting Safety & Relief Valve Failures & Challenges," in response to Generic Ltr 82-16
FAY, C W Wisconsin Electric Power Co 82/12/15 DENTON, H R Office of Nuclear Reactor Regulation, Director CLARK, R A Operating Reactors Branch 3 3pp 16503 278 24X
Fiche 50-266, 82/12/15, 8212220422

8212220427 Proposed Tech Spec Change Request B6 addressing requirements of NUREG-0737, Item II K 3 3, "Reporting Safety & Relief Valve Failures & Challenges," in response to Generic Ltr 82-16
* Wisconsin Electric Power Co 82/12/15 1p 16503 281 24X
Fiche 50-266, 82/12/15, 8212220422

8212290075 Forwards "Evaluation of Pressurizer Safety & Relief Valve Sys for Point Beach Nuclear Plant," in further response to NUREG-0737, Item II D 1 re relief & safety valve testing
FAY, C W Wisconsin Electric Power Co 82/12/23 DENTON, H R Office of Nuclear Reactor Regulation, Director CLARK, R A Operating Reactors Branch 3 2pp 16589 169 24X
Fiche 50-266, 82/12/23, 8212290075

8212290104 "Evaluation of Pressurizer Safety & Relief Valve Sys for Point Beach Nuclear Plant" H/two oversize drawings Aperture cards are available in PDR
MCKINNEY, T R, RAMSEY, B L, RAZLAFF, W J EDS Nuclear, Inc 09-0970-001 R00 82/12/21 64pp 16589 172 24X
Fiche 50-266, 82/12/23, 8212290095

G Inspection reports, IE Bulletins & correspondence

8208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel Recirculation Sys Piping at BWR Plants " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240

8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model H01 & Model 802 Thermoluminescent Dosimeters " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000, 82/11/05, 8208190245

8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X
Fiche 50-000, 82/11/18, 8208190251

8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000, 82/11/26, 8208190256

8208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000, 82/11/30, 8208190257

8212170177 Forwards IE Insp Repts 50-266/82-17 & 50-301/82-17 on 820628-0701 & 08 & notice of violation
NORELIUS, C E Division of Engineering & Technical Programs 82/11/30 BURSTEIN, S Wisconsin Electric Power Co 3pp 16450 192 24X Fiche 50-266, 82/11/30, 8212170177

8212170181 Notice of violation from insp on 820628-0701 & 08
NORELIUS, C E Division of Engineering & Technical Programs 82/11/30 4pp 16450 195 24X Fiche 50-266, 82/11/30, 8212170177

8212170189 IE Insp Repts 50-266/82-17 & 50-301/82-17 on 820628-0701 & 08 Noncompliance noted inadequate surveillance testing, nonfunctional penetration fire barrier & incomplete development & implementation of administrative controls
RAMSEY, C, ULIE, J, GROBE, J A Region 3, Office of Director 82/09/20 21pp 16450 199 24X Fiche 50-266, 82/11/30, 8212170177

8208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259

8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Baskets " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X
Fiche 50-000, 82/12/03, 8208190261

8212100221 Ack receipt of 821129 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-266/82-12 & 50-301/82-12
KEPPLER, J O Region 3, Office of Director 82/12/07 BURSTEIN, S Wisconsin Electric Power Co 2pp 16377 101 24X
Fiche 50-266, 82/12/07, 8212100221

8212100222 Responds to NRC 820915 ltr re violations noted in IE Insp Repts 50-266/82-12 & 50-301/82-12 Corrective actions review of containment entry control procedures & controls & interchangeability of keys changed
FAY, C W Wisconsin Electric Power Co 82/10/15 KEPPLER, J O Region 3, Office of Director 4pp 16377 103 24X
Fiche 50-266, 82/12/07, 8212100221

8212100223 Addl response to NRC 820915 ltr re violation noted in IE Insp Repts 50-266/82-12 & 50-301/82-12 Corrective actions area roped off, conspicuously posted & flashing lights used as warning device
FAY, C W Wisconsin Electric Power Co 82/11/29 KEPPLER, J O Region 3, Office of Director 3pp 16377 107 24X
Fiche 50-266, 82/12/07, 8212100221

8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16, 8208190267

8212280361 Responds to IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " No Bunker Ramo penetration assemblies installed initially or during backfit & mod
FAY, C W Wisconsin Electric Power Co 82/12/17 KEPPLER, J O Region 3, Office of Director 1p 16560 077 24X
Fiche 50-266, 82/12/17, 8212280361

8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27 " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X
Fiche 50-000, 82/12/20, 8208190268

R Periodic operating reports & related correspondence

8212290253 Forwards revised monthly operating repts for Aug 1982 for Units 1 & 2 & revised Sept 1982 rept for Unit 2
FAY, C W Wisconsin Electric Power Co 82/11/17 Office of Resource Management, Director 1p 16582 037 24X
Fiche 50-266, 82/11/17, 8212290253

--8212290257 Revised monthly operating repts for Aug 1982
FAY, C W Wisconsin Electric Power Co 82/09/07 2pp 16582 038 24X Fiche 50-266, 82/11/17, 8212290253

--8212290262 Revised monthly operating rept for Sept 1982
FAY, C W Wisconsin Electric Power Co 82/10/04 1p 16582 040 24X Fiche 50-266, 82/11/17, 8212290253

8212210297 Forwards monthly operating repts for Nov 1982
FAY, C W Wisconsin Electric Power Co 82/12/10 Office of Nuclear Reactor Regulation, Director 1p 16497 089 24X
Fiche 50-266, 82/12/10, 8212210297

-8212210299 Monthly operating repts for Nov 1982
FAY, C W Wisconsin Electric Power Co 82/12/06 11pp 16497 090 24X Fiche 50-266, 82/12/10, 8212210297

S Reportable occurrences, LERs & related correspondence

8212100208 Forwards LER 82-009/01T-0
FAY, C W Wisconsin Electric Power Co 82/12/03 KEPLER, J O Region 3, Office of Director 1p 16376 216 24X
Fiche 50-301, 82/12/03, 8212100208

--8212100211 LER 82-009/01T-0 on 821102, axial flux differential monitoring program & alarm found inadvertently halted from 821120-22 w/o manually logging flux differential. Caused by operator diagnosing backup computer problem
FAY, C W Wisconsin Electric Power Co 82/12/03 Region 3, Office of Director 2pp 16376 217 24X Fiche 50-301, 82/12/03, 8212100208

8212280114 Forwards LER 82-010/03L-0
FAY, C W Wisconsin Electric Power Co 82/12/15 KEPLER, J O Region 3, Office of Director 1p 16564 059 24X
Fiche 50-301, 82/12/15, 8212280114

--8212280115 LER 82-010/03L-0 on 821110, during surveillance test TS-11, secondary boric acid heat tracing circuits found inoperable. Caused by internal defect which tripped breaker 1B92-429A. Breaker replaced
FAY, C W Wisconsin Electric Power Co 82/12/15 Region 3, Office of Director 2pp 16564 060 24X Fiche 50-301, 82/12/15, 8212280114

DOCKET 50-302 CRYSTAL RIVER NUCLEAR PLANT, UNIT 3

F Security, medical, emergency & fire protection plans

8212090132 Discusses NRC emergency radio communications & results of 821028 site meeting. Radio sys will be brought to plant during emergency. High frequency established for hurricane alert. Placement of antennas outlined
O'REILLY, J P Region 2, Office of Director 82/11/24 HANCOCK, J A Florida Power Corp 3pp 16357 319 24X Fiche 50-302, 82/11/24, 8212090132

8212100006 Submits info re emergency operations facility, in response to 821202 request. Const completed on 821015
WESTAFER, G R Florida Power Corp 82/12/06 STOLZ, J F Operating Reactors Branch 4 1p 16373 362 24X Fiche 50-302, 82/12/06, 8212100006

8212140089 Documents 821208 telcon responding to NRC request for addl info re 10CFR50 App R fire study, dtd 821029 & superseding 820630 submittal. Revised Table 1 & Figure 2 encl
WESTAFER, G R Florida Power Corp 82/12/09 EIBENHUT, D O Division of Licensing 14pp 16408 256 24X Fiche 50-302, 82/12/09, 8212140089

8212220284 Confirms 821019 telcon re App R submittal. Util response to Item 11, App R encl. Automatic starting of diesel generators on loss of voltage relied upon for safe plant shutdown in event of fire
WESTAFER, G R Florida Power Corp 82/12/17 EIBENHUT, D O Division of Licensing 1p 16517 191 24X Fiche 50-302, 82/12/17, 8212220284

H General correspondence

8212060084 Documents recent organizational change in nuclear licensing area. All previous authorizations withdrawn, effective 821201
HANCOCK, J A Florida Power Corp 82/12/01 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 16316 067 24X
Fiche 50-302, 82/12/01, 8212060084

8212290177 Requests that Bureau of Intergovernmental Relations be removed from distribution list & correspondence previously addressed to DG Mardis be sent to author
WESTAFER, G R Florida Power Corp 82/12/17 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 16578 038 24X
Fiche 50-302, 82/12/17, 8212290177

P Operating license stage documents & correspondence

8211090043 Provides detailed specs re Orion boron & chloride analyzer equipment to be used to fulfill requirements of NUREG-0737, Item 11 B 3, "Post-Accident Sampling Capability". Implementation expected during Refuel 4
HAYNARD, P Y Florida Power Corp 82/11/03 STOLZ, J F Operating Reactors Branch 4 2pp 16004 001 24X Fiche 50-302, 82/11/03, 8211090043

8212010160 Forwards Amend 59 to License DPR-72, safety evaluation & notice of issuance & availability. Amend allows util to change modes w/intermediate pressure relief line isolation valve replaced w/pipe cap
STOLZ, J F Operating Reactors Branch 4 82/11/17 HANCOCK, J A Florida Power Corp 3pp 16290 281 24X Fiche 50-302, 82/11/17, 8212010160

--8212010164 Amend 59 to License DPR-72, allowing util to change modes w/intermediate pressure relief line isolation valve replaced w/pipe cap
STOLZ, J F Operating Reactors Branch 4 82/11/17 4pp 16290 284 24X Fiche 50-302, 82/11/17, 8212010160

-8212010167 Safety evaluation supporting Amend 59 to License DPR-72
* Office of Nuclear Reactor Regulation, Director 82/11/17 2pp 16290 289 24X Fiche 50-302, 82/11/17, 8212010160

--8212010172 Notice of issuance & availability of Amend 59 to License DPR-72
STOLZ, J F Operating Reactors Branch 4 82/11/17 2pp 16290 291 24X Fiche 50-302, 82/11/17, 8212010160

8212010329 Forwards Amend 60 to License DPR-72, safety evaluation & notice of issuance & availability. Amend identifies post-accident monitoring instrument readouts w/recorders & changes measurement units for reactor coolant flow
MINER, S Operating Reactors Branch 4 82/11/23 HANCOCK, J A Florida Power Corp 3pp 16271 284 24X Fiche 50-302, 82/11/23, 8212010329

--8212010330 Amend 60 to License DPR-72, identifying post-accident monitoring instrument readouts w/recorders & changing measurement units for reactor coolant flow from percent to lb per hour
STOLZ, J F Operating Reactors Branch 4 82/11/23 5pp 16271 287 24X Fiche 50-302, 82/11/23, 8212010329

--8212010331 Safety evaluation supporting Amend 60 to License DPR-72
* Office of Nuclear Reactor Regulation, Director 82/11/23 2pp 16271 292 24X Fiche 50-302, 82/11/23, 8212010329

--8212010332 Notice of issuance & availability of Amend 60 to License DPR-72
STOLZ, J F Operating Reactors Branch 4 82/11/23 2pp 16271 294 24X Fiche 50-302, 82/11/23, 8212010329

8212060225 Submits response to NUREG-0612, "Control of Heavy Loads". Increase instrument container hoist derated to capacity of 1,000 lb
HAYNARD, P Y Florida Power Corp 82/12/01 STOLZ, J F Operating Reactors Branch 4 3pp 16312 233 24X Fiche 50-302, 82/12/01, 8212060225

8212150236 Forwards safety evaluation supporting operation of once-through steam generator blowdown lines pressurized from cold shutdown to 15% rated thermal power until Refueling V
STOLZ, J F Operating Reactors Branch 4 82/12/07 HANCOCK, J A Florida Power Corp 2pp 16446 353 24X Fiche 50-302, 82/12/07, 8212150236

--8212150240 Safety evaluation supporting operation of once-through steam generator blowdown lines pressurized from cold shutdown to 15% rated thermal power until Refueling V
* Office of Nuclear Reactor Regulation, Director 82/12/07 1p 16446 355 24X Fiche 50-302, 82/12/07, 8212150236

DOCKETED ITEMS

8/08190263 Generic Ltr 82-32 to all PWR licensees re potential steam generator-related generic requirements Forwards Science Applications, Inc draft rept re subj requirements Comments requested within 30 days of ltr Svc list encl
EISENHUT, D G Division of Licensing 82/12/09 Consolidated Edison Co of New York, Inc 29pp 16629 247 24X
Fiche 50-000, 82/12/09, 8208190263

8/12270391 Forwards SER of util responses to TMI Action Item II E 4 2, "Min Containment Pressure Setpoint" Setpoint acceptable
STOLZ, J F Operating Reactors Branch 4 82/10/10 HANCOCK, J A Florida Power Corp 2pp 16566 039 24X Fiche 50-302, 82/12/10, 8212270391

--8212270395 SER supporting util response to TMI Action Item II E 4 2, "Min Containment Pressure Setpoint"
* Operating Reactors Branch 4 82/12/10 3pp 16566 041 24X
Fiche 50-302, 82/12/10, 8212270391

8/12270409 Forwards order for license mod requiring installation of inadequate core cooling instrumentation sys, per NUREG-0737, Item II F 2
EISENHUT, D G Division of Licensing 82/12/10 HANCOCK, J A Florida Power Corp 2pp 16572 343 24X Fiche 50-302, 82/12/10, 8212270409

--8212270411 Order for license mod requiring installation of inadequate core cooling instrumentation sys, per NUREG-0737, Item II F 2
Checklist for reviewing sys encl
EISENHUT, D G Division of Licensing 82/12/10 Florida Power Corp 11pp 16572 345 24X Fiche 50-302, 82/12/10, 8212270409

8/12280270 Responds to Item 10 of 820819 request for addl info re TMI Item II E 1 1, "Auxiliary Feedwater Sys Evaluation"
Response to Item 4 & 8 re TMI Item II E 1 2, "Emergency feedwater Upgrade," to be submitted upon resolution
WESTAFER, G R Florida Power Corp 82/12/17 STOLZ, J F Operating Reactors Branch 4 9pp 16517 353 24X Fiche 50-302, 82/12/17, 8212280270

Q Inspection reports, IE Bulletins & correspondence

8/08190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants" Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240

8/08190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters" Svc list encl
COBB, L J Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000, 82/11/05, 8208190245

8/12090423 Confirms 821105 telcon re arrangements for 821124 mgt meeting in St Petersburg, FL Meeting will review results of first phase of NRC annual appraisal of util regulatory performance Proposed agenda encl
LEWIS, R C Division of Project & Resident Programs 82/11/16 HANCOCK, J A Florida Power Corp 3pp 16364 266 24X
Fiche 50-302, 82/11/16, 8212090423

8/08190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements" Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X
Fiche 50-000, 82/11/18, 8208190251

8/08190256 IE Info Notice 82-46, "Defective & Obsolete Combination Radiacks" Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000, 82/11/26, 8208190256

8/08190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl" Svc list encl
COBB, L J Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000, 82/11/30, 8208190257

8/08190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies" Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259

8/08190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets" Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X
Fiche 50-000, 82/12/03, 8208190261

8/08190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring" Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16, 8208190267

8212220530 Ack receipt of 820119 & 0827 applications for changes in administrative controls section of Tech Specs & relief from requirements of ASME Code Section XI for visual & volumetric insp of reactor vessels & head cladding
MILLER, W D License Fee Management Branch 82/12/16 HANCOCK, J A Florida Power Corp 2pp 16523 039 24X Fiche 50-302, 82/12/16, 8212220530

8/08190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27" Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X
Fiche 50-000, 82/12/20, 8208190268

R Periodic operating reports & related correspondence

8/12140048 Forwards monthly operating rept for Nov 1982
WESTAFER, G R Florida Power Corp 82/12/09 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 1p 16408 281 24X Fiche 50-302, 82/12/09, 8212140048

- 8212140051 Monthly operating rept for Nov 1982
BOGART, D Florida Power Corp 82/12/02 4pp 16408 282 24X
Fiche 50-302, 82/12/09, 8212140048

S Reportable occurrences, LERs & related correspondence

8212020049 Forwards LER 82-068/03L-0
BAYNARD, P Y Florida Power Corp 82/11/24 O'REILLY, J P Region 2, Office of Director 1p 16272 057 24X Fiche 50-302, 82/11/24, 8212020045

--8212020052 LER 82-068/03L-0 on 821029, feedwater ultrasonic flow indicator FW-312-FI found inoperable during daily surveillance, rendering emergency feedwater train A inoperable Caused by insufficient cable clearance
BROWN, C O Florida Power Corp 82/11/26 Region 2, Office of Director 2pp 16272 058 24X Fiche 50-302, 82/11/24, 8212020045

8212020063 Forwards LER 82-067/03L-0
BAYNARD, P Y Florida Power Corp 82/11/24 O'REILLY, J P, Region 2, Office of Director 1p 16272 001 24X Fiche 50-302, 82/11/24, 8212020063

--8212020071 LER 82-067/03L-0 on 821028, feedwater ultrasonic flow indicator FW-313-FI discovered inoperable Caused by defective scale card Scale card replaced & functional check satisfactorily completed
HUGHES, P O Florida Power Corp 82/11/26 Region 2, Office of Director 2pp 16272 002 24X Fiche 50-302, 82/11/24, 8212020063

8212020077 Forwards LER 82-069/03L-0
BAYNARD, P Y Florida Power Corp 82/11/24 O'REILLY, J P Region 2, Office of Director 1p 16272 011 24X Fiche 50-302, 82/11/24, 8212020077

--8212020087 LER 82-069/03L-0 on 821029, remote & local 175-ft wind direction channels found out of tolerance Caused by failed direction sensor, sensor replaced & instrument recalibrated
Meteorological monitoring sys under evaluation
BROWN, C O Florida Power Corp 82/11/26 Region 2, Office of Director 2pp 16272 012 24X Fiche 50-302, 82/11/24, 8212020077

8212030102 PND-11-82-130 on 821125, high airborne radioactivity levels caused evacuation of plant auxiliary bldg Caused by packing plug hole in letdown valve, No personnel contaminated Gaseous release 8% of Tech Spec limit
ROOPE, J F, DANCE, H C Region 2, Office of Director 82/11/29 2pp 16304 111 24X Fiche 50-302, 82/11/29, 8212030102

8212150085 PND-11-82-130A on 821125, inadvertent release of radioactive water amounted to 80X of plant instantaneous liquid concentration release limit Preliminary licensee calculation indicated limit exceeded 40X
NEJFELT, O M, DANCE, H C Region 2, Office of Director 82/12/07 1p 16430 160 24X Fiche 50-302, 82/12/07, 8212150085

8212150099 Forwards LER 82-070/03L-0 Detailed event analysis encl
WESTAFER, O R Florida Power Corp 82/12/07 O'REILLY, J P Region
2, Office of Director 2pp 16427 359 24X Fiche 50-302, 82/12/07,
8212150099

--8212150102 LER 82-070/03L-0 on 821107, during Mode 1, nuclear overpower
Channel B tripped due to failure of reactor coolant flow
transmitter RC-14A-F12 Caused by shorted capacitor in power
supply Capacitor replaced & transmitter returned to svc
HUOHES, P O Florida Power Corp 82/12/07 Region 2, Office of
Director 1p 16427 361 24X Fiche 50-302, 82/12/07, 8212150099

8212150105 Forwards LER 82-071/03L-0
WESTAFER, O R Florida Power Corp 82/12/07 O'REILLY, J P Region
2, Office of Director 1p 16430 360 24X Fiche 50-302, 82/12/07,
8212150105

--8212150108 LER 82-071/03L-0 on 821114, during Mode 1, radiation monitor
RM-A5, control room iodine channel found inoperable Caused by
failure of rotary selector switch Switch replaced & monitor
placed in svc
BRGNN, C O Florida Power Corp 82/12/07 Region 2, Office of
Director 2pp 16430 361 24X Fiche 50-302, 82/12/07, 8212150105

8212150046 Forwards LER 82-073/04T-0
BAYNARD, P Y Florida Power Corp 82/12/10 O'REILLY, J P Region
2, Office of Director 1p 16422 324 24X Fiche 50-302, 82/12/10,
8212150046

--8212150053 LER 82-073/04T-0 on 821126, isolation setpoint on liquid
waste effluent monitor (RM-L7) not sufficiently conservative
to preclude release in excess of 10CFR20 Caused by
inadequate process Procedure revised
HUOHES, P O Florida Power Corp 82/12/10 Region 2, Office of
Director 5pp 16422 325 24X Fiche 50-302, 82/12/10, 8212150046

8212150060 Forwards LER 82-072/03L-0
BAYNARD, P Y Florida Power Corp 82/12/10 O'REILLY, J P Region
2, Office of Director 1p 16427 323 24X Fiche 50-302, 82/12/10,
8212150060

--8212150064 LER 82-072/03L-0 on 821125, determined reactor coolant water
leaking to nuclear svcs closed cycle cooling sys through
letdown cooler B Caused by thermal shock due to long
isolation during rapid restoration to svc Cooler replaced
HUOHES, P O Florida Power & Light Co 82/12/10 Region 2,
Office of Director 2pp 16427 324 24X Fiche 50-302, 82/12/10,
8212150060

8212220314 Forwards LER 82-074/03L-0
BAYNARD, P Y Florida Power Corp 82/12/16 O'REILLY, J P Region
2, Office of Director 1p 16517 181 24X Fiche 50-302, 82/12/16,
8212220314

--8212220322 LER 82-074/03L-0 on 821116, during performance of 8P-186,
control complex charcoal filters failed Freon portion of
surveillance required by Tech Specs Caused by moisture
absorption by charcoal filters Filters replaced & tested
BROWN, C O Florida Power Corp 82/12/16 Region 2, Office of
Director 2pp 16517 182 24X Fiche 50-302, 82/12/16, 8212220314

8212280060 PND-11-82-139 on 821222, during feed & bleed operation to
remove boron from reactor coolant water, radiation monitor in
auxiliary bldg sounded twice resulting in two evacuations
Probably caused by compressor leak
BROWNLEE, V Region 2, Office of Director 82/12/22 2pp
16565 139 24X Fiche 50-302, 82/12/22, 8212280060

DOCKET 50-304 ZION NUCLEAR POWER STATION, UNIT 2

F Security, medical, emergency & fire protection plans

8212060232 Forwards IE Safety Evaluation Repts 50-295/82-23 &
50-304/82-20 of emergency preparedness & SER
HIND, J A Division of Emergency Preparedness & Operational Support
82/11/19 REED, C Commonwealth Edison Co 2pp 16312 201 24X
Fiche 50-295, 82/11/19, 8212060232

--8212060238 IE Safety Evaluation Repts 50-295/82-23 & 50-304/82-20 of
emergency preparedness plan Emergency plan acceptable
PHILLIPS, M P Division of Emergency Preparedness & Operational
Support 82/11/18 1p 16312 203 24X Fiche 50-295, 82/11/19,
8212060232

--8212060255 SER of emergency preparedness plan Plan acceptable
* Region 3, Office of Director 82/11/30 27pp 16312 204 24X
Fiche 50-295, 82/11/19, 8212060232

8212070065 Forwards revised exemption requests documenting info
provided at 821104 & 05 meetings re post-fire shutdown
capability
LENTINE, F O Commonwealth Edison Co 82/11/29 DENTON, H R Office
of Nuclear Reactor Regulation, Director 88pp 16326 010 24X
Fiche 50-295, 82/11/29, 8212070065

8212090383 Forwards info re emergency operations facilities per
821122 & 1202 requests Info previously submitted by telcon
Request for written response unnecessary burden on licensee
DELGEOERGE, L O Commonwealth Edison Co 82/12/03 EISENHUT, D G
Division of Licensing 2pp 16365 051 24X Fiche 50-000 82/12/03,
8212090383

8212130149 Releases public version of revision to emergency plan
implementing procedure
FELTON, J M Division of Rules and Records 82/12/03 Document
Management Branch 1p 16410 295 24X Fiche 50-295, 82/12/03,
8212130149

--8212130153 Forwards public version of Revision 5 to Emergency Plan
Implementing Procedure EPIP 330-1, "Classification of
Generating Station Emergency Plan Conditions " Procedure
change request form encl
PLIML, G Commonwealth Edison Co 82/11/19 DENTON, H R NRC - Nt
Detailed Affiliation Given 3pp 16410 297 24X
Fiche 50-295, 82/12/03, 8212130149

--8212130156 Public version of Revision 5 to Emergency Plan Implementing
Procedure EPIP 330-1, "Classification of Generating Station
Emergency Plan Conditions "
* Commonwealth Edison Co 82/11/16 16pp 16410 300 24X
Fiche 50-295, 82/12/03, 8212130149

8212130017 Releases public version of Revision 1 to Emergency Plan
Implementing Procedure EQ-2, "Pre-Established Onsite &
Offsite Monitoring Locations (Maps) "
FELTON, J M Division of Rules and Records 82/12/07 Document
Management Branch 1p 16417 062 24X Fiche 50-000, 82/12/07,
8212130017

--8212130028 Forwards public version of Revision 1 to Emergency Plan
Implementing Procedure EQ-2, "Pre-Established Onsite &
Offsite Monitoring Locations (Maps) " Revised table of
contents encl
PAJOWSKI, J E Commonwealth Edison Co 82/11/01 DENTON, H R NRC
No Detailed Affiliation Given 2pp 16417 063 24X
Fiche 50-000, 82/12/07, 8212130017

--8212130041 Public version of Revision 1 to Emergency Plan Implementing
Procedure EQ-2, "Pre-Established Onsite & Offsite Monitoring
Locations (Maps) "
PAJOWSKI, J E Commonwealth Edison Co 82/11/29 4pp 16417 065
24X Fiche 50-000, 82/12/07, 8212130017

8212140243 Advises of distribution of revisions to "Generating Station
Emergency Plan " Braidwood annex not prepared
FRAMM, T R Commonwealth Edison Co 82/12/07 DENTON, H R Office
of Nuclear Reactor Regulation, Director 2pp 16409 302 24X
Fiche 50-000, 82/12/07, 8212140243

8212220175 Releases public version of revised generating station
emergency plan implementing procedures
FELTON, J M Division of Rules and Records 82/12/10 Document
Management Branch 1p 16529 029 24X Fiche 50-000, 82/12/10,
8212220175

--8212220190 Forwards public version of revised generating station
emergency plan implementing procedures, including Procedures
ED-3 re demand polling of meteorological data & ED-20 re
emergency forecast request
PAJOWSKI, J E Commonwealth Edison Co 82/11/15 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 16529 030
24X Fiche 50-000, 82/12/10, 8212220175

--8212220202 Public version of revised generating station emergency plan
implementing procedures, including Procedures ED-3 re demand
polling of meteorological data & ED-20 re emergency
forecast request
LITERSKI, L A Commonwealth Edison Co 82/10/13 48pp
16529 031 24X Fiche 50-000, 82/12/10, 8212220175

8212210454 Forwards addl info documenting discussions at 821104 & 05
meeting w/NRC & BNL re remaining open items from technical
evaluation rept, "Post-Fire Shutdown Capability "
LENTINE, F O Commonwealth Edison Co 82/12/15 DENTON, H R Office
of Nuclear Reactor Regulation, Director 39pp 16489 285 24X
Fiche 50-295, 82/12/15, 8212210454

DOCKETED ITEMS

B212220306 Discusses layout of communications equipment required in control room, onsite technical support ctr & near-site emergency operations facility
KEPPLER, J O Region 3, Office of Director 82/12/16
Commonwealth Edison Co 3pp 16503 351 24X Fiche 50-000, 82/12/16, 8212220306

B212290083 Releases public version of corrected page to emergency plan implementing procedure
FELTON, J M Division of Rules and Records 82/12/20 Document
Management Branch 1p 16606 343 24X Fiche 50-295, 82/12/20, 8212290083

--B212290086 Forwards public version of corrected Page 4 to Emergency Plan Implementing Procedure EPIP 410-1 Receipt form encl
PLIML, G Commonwealth Edison Co 82/11/30 DENTON, H R NRC - Nu
Detailed Affiliation Given 2pp 16606 344 24X
Fiche 50-295, 82/12/20, 8212290083

--B212290089 Public version of corrected Page 4 to Emergency Plan Implementing Procedure EPIP 410-1
* Commonwealth Edison Co 82/11/30 1p 16606 346 24X
Fiche 50-295, 82/12/20, 8212290083

B212290098 Releases public version of revision to emergency plan implementing procedure
FELTON, J M Division of Rules and Records 82/12/20 Document
Management Branch 1p 16606 334 24X Fiche 50-295, 82/12/20, 8212290098

--B212290105 Forwards public version of Revision 6 to Emergency Plan Implementing Procedure EPIP 110-1, "Station Director"
Receipt form & procedure change request form encl
PLIML, G Commonwealth Edison Co 82/11/24 DENTON, H R NRC - Nu
Detailed Affiliation Given 2pp 16606 335 24X
Fiche 50-295, 82/12/20, 8212290098

--B212290110 Public version of Revision 6 to Emergency Plan Implementing Procedure EPIP 110-1, "Station Director" Revised index encl
* Commonwealth Edison Co 82/11/24 6pp 16606 337 24X
Fiche 50-295, 82/12/20, 8212290098

B212290509 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 82/12/20 Document
Management Branch 1p 16593 349 24X Fiche 50-295, 82/12/20, 8212290509

--B212290511 Forwards public version of Revision 8 to Emergency Plan Implementing Procedure EPIP 700-1, "Emergency Phone List"
Procedure change request encl
PLIML, G Commonwealth Edison Co 82/11/24 DENTON, H R NRC - Nu
Detailed Affiliation Given 2pp 16593 350 24X
Fiche 50-295, 82/12/20, 8212290509

--B212290513 Public version of Revision 8 to Emergency Plan Implementing Procedure EPIP 700-1, "Emergency Phone List"
* Commonwealth Edison Co 82/11/22 6pp 16593 352 24X
Fiche 50-295, 82/12/20, 8212290509

B212300167 Releases public version of revised generating station emergency plan telephone directory
FELTON, J M Division of Rules and Records 82/12/20 Document
Management Branch 1p 16612 215 24X Fiche 50-000, 82/12/20, 8212300167

--B212300179 Forwards public version of revised generating station emergency plan telephone directory
MOORE, R D Commonwealth Edison Co 82/12/02 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 16612 216 24X
Fiche 50-000, 82/12/20, 8212300167

--B212300199 Public version of revised generating station emergency plan telephone directory
GALLE, D P Commonwealth Edison Co 82/11/05 60pp 16612 211 24X
Fiche 50-000, 82/12/20, 8212300167

B212290415 Forwards proposed agenda for 830104-05 site visit by security review committee re safeguards requirements
KEPPLER, J O Region 3, Office of Director, 82/12/27 REED, C
Commonwealth Edison Co 2pp 16587 099 24X Fiche 50-295, 82/12/27, 8212290415

H General correspondence

B212280176 Notifies of change in mailing address for NRC licensing mail
WRIGHTE, G N Illinois, State of, Dept Nuc Safety (formerly Dept Public Health) 82/12/20 EISENHUT, D O Division of Licensing
1p 16556 135 24X Fiche 50-000, 82/12/20, 8212280176

P Operating license stage documents & correspondence

B212070411 FOIA request for all records on embrittlement, thermal shock, corrosion & cracking of reactor pressure vessel at Facilities
GUIGG, C Pollution & Environmental Problems, Inc 82/10/18
Division of Rules and Records 1p 16356 001 24X
Fiche 50-295, 82/10/18, 8212070411

B212070414 Responds to FOIA request for all records on embrittlement, thermal shock, corrosion & cracking of reactor pressure vessel at Facility Records available at PDR
FELTON, J M Division of Rules and Records 82/11/05 GUIGG, C
Pollution & Environmental Problems, Inc 4pp 16356 002 24X
Fiche 50-295, 82/11/05, 8212070414

B212010452 Summary of 821115 meeting w/util re interim inservice testing program
WIGGINTON, D L Operating Reactors Branch 1 82/11/19 Operating Reactors Branch 1 4pp 16270 222 24X Fiche 50-295, 82/11/19, 8212010452

B212060096 Clarifies 820712 ltr re seismic design of auxiliary feedwater sys branch piping criteria utilized for all IE Bulletin 79-14 work as documented in S&W Procedure ZPP-1
LENTINE, F O Commonwealth Edison Co 82/11/29 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 16316 120 24X
Fiche 50-295, 82/11/29, 8212060096

B212060219 Requests approval to delay implementation of due dates to accommodate current schedule requirements for Items 11 B 2, "Plant Shielding," 11 B 3, "Post-Accident Sampling," & 11 F 1, "Accident Monitoring Instrumentation"
LENTINE, F O Commonwealth Edison Co 82/11/29 EISENHUT, D O
Division of Licensing 2pp 16313 190 24X Fiche 50-295, 82/11/29, 8212060219

B212060422 Forwards FR notice of receipt of 821011 request for action re licensee use of high burnup nuclear fuel & ability of facility reactor vessels to withstand embrittlement Request being treated per 10CFR2.206
DENTON, H R Office of Nuclear Reactor Regulation, Director 82/11/30 GUIGG, C obsolete code 1p 16343 308 24X
Fiche 50-295, 82/11/30, 8212060422

--B212060430 Notice of Pollution & Environ Problems, Inc 821011 request for action re licensee use of high burnup nuclear fuel & ability of facility reactor vessels to withstand embrittlement
DENTON, H R Office of Nuclear Reactor Regulation, Director 82/11/30 1p 16343 309 24X Fiche 50-295, 82/11/30, 8212060422

B212070472 Forwards Amends 7B & 6B to Licenses DPR-39 & DPR-48, respectively & notice of issuance & availability Amends revise Tech Specs to allow release of radioactive gas decay tank contents
WIGGINTON, D Operating Reactors Branch 1 82/11/30 DELGEORE, L O
Commonwealth Edison Co 3pp 16351 342 24X Fiche 50-295, 82/11/30, 8212070472

--B212070478 Amends 7B & 6B to Licenses DPR-39 & DPR-48, respectively, revising Tech Specs to allow release of radioactive gas decay tank contents
VARGA, S A Operating Reactors Branch 1 82/11/30 8pp 16351 345 24X Fiche 50-295, 82/11/30, 8212070472

--B212070482 Notice of issuance & availability of Amends 7B & 6B to Licenses DPR-39 & DPR-48, respectively
VARGA, S A Operating Reactors Branch 1 82/11/30 2pp 16351 353 24X Fiche 50-295, 82/11/30, 8212070472

B212130231 Application to amend Licenses DPR-39 & DPR-48, changing Section 3 9 2 of Tech Specs to clarify operability requirements for containment penetration & weld channel pressurization sys
LENTINE, F O Commonwealth Edison Co 82/12/03 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 16397 001 24X
Fiche 50-295, 82/12/03, 8212130231

--B212130236 Proposed changes to Section 3 9 2 of Tech Specs, clarifying operability requirements for containment penetration & weld channel pressurization sys
* Commonwealth Edison Co 82/12/03 2pp 16397 003 24X
Fiche 50-295, 82/12/03, 8212130231

B212090006 Confirms emergency authorization to amend Licenses DPR-39 & DPR-48 on 821203 Amend revises penetration pressurization sys
LAINAS, G C Assistant Director for Operating Reactors 82/12/06 DELGEORE, L O Commonwealth Edison Co 2pp 16379 357 24X
Fiche 50-295, 82/12/06, 8212090006

8212130035 Informs of addl delay in implementation of offsite dose assessment portion of A-model Required radiation monitoring sys will be installed by 830215, per NUREG-0737, Items II F 1 1 & II F 1 2
LENTINE, F G Commonwealth Edison Co 82/12/07 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 16390 174 24X
Fiche 50-295, 82/12/07, 8212130035

8208190263 Generic Ltr 82-32 to all PWR licensees re potential steam generator-related generic requirements Forwards Science Applications, Inc draft rept re subj requirements Comments requested within 30 days of ltr Svc list encl
EISENHUT, D G Division of Licensing 82/12/09 Consolidated Edison Co of New York, Inc 29pp 16629 247 24X
Fiche 50-000, 82/12/09, 8208190263

8212140103 Generic Ltr 82-28 to all licensees of operating Westinghouse & C-E PWRs (except Arkansas Nuclear One, Unit 2 & San Onofre 2 & 3) re inadequate core cooling instrumentation sys Svc list encl
EISENHUT, D G Division of Licensing 82/12/10 Yankee Atomic Electric Co 27pp 16690 035 24X Fiche 50-000, 82/12/10, 8212140103

8212150141 Forwards proprietary SER & technical evaluation rept, "Review of Licensee Resolution of Outstanding Issues From NRC Equipment Environ Qualification SERs (F-11, G-60) " Justification for continued operation due in 30 days
VARGA, S A Operating Reactors Branch 1 82/12/14 DELGEORGE, L U Commonwealth Edison Co 2pp 16427 345 24X Fiche 50-295, 82/12/14, 8212150141

8212220212 Forwards Revision 22 to CE-1-A, "QA Program for Nuclear Generating Stations "
SWARTZ, E D Commonwealth Edison Co 82/12/14 HAAS, W P Quality Assurance Branch 1p 16518 007 24X Fiche 50-000, 82/12/14, 8212220212

--8212220231 "QA Program for Nuclear Generating Stations," Revision 2d * Commonwealth Edison Co CE-1-A R22 82/11/01 17pp 16518 009 24X Fiche 50-000, 82/12/14, 8212220212

8212220431 Comments on NRC alternative Tech Specs re auxiliary feedwater sys, prepared in response to util 791231 & 800312 submittals Proposed Tech Specs acceptable, w/exception of minor editorial changes noted in encl
LENTINE, F G Commonwealth Edison Co 82/12/15 DENTON, H R Office of Nuclear Reactor Regulation, Director 5pp 16503 311 24X
Fiche 50-295, 82/12/15, 8212220431

8212220517 Forwards approved spent nuclear fuel route as requested in 0420914 ltr
SHERR, T S Material Transfer Safeguards Licensing Branch 82/12/16 DANESSE, F L Nuclear Assurance Corp 2pp 16523 041 24X
Fiche 50-295, 82/12/16, 8212220517

--8212220520 "Spent Nuclear Fuel Route, BMI, West Jefferson, OH to Zion Nuclear Power Station, Zion, IL "
SHERR, T S Material Transfer Safeguards Licensing Branch 82/11/23 10pp 16523 043 24X Fiche 50-295, 82/12/16, 8212220517

8212210369 Requests NRC concurrence or comments on revised schedule for implementation of fuel mgt program topical rept
LENTINE, F G Commonwealth Edison Co 82/12/17 THOMAS, C D Standardization & Special Projects Branch 3pp 16494 275 24X
Fiche 50-295, 82/12/17, 8212210369

8212290453 Forwards Amends 79 & 69 to Licenses DPR-39 & DPR-48, respectively, safety evaluation & notice of issuance & availability Amends revise Tech Specs for penetration pressurization sys to define operating conditions
WIGGINTON, D L Operating Reactors Branch 1 82/12/20 DELGEORGE, L U Commonwealth Edison Co 2pp 16606 060 24X
Fiche 50-295, 82/12/20, 8212290453

--8212290456 Amends 79 & 69 to Licenses DPR-39 & DPR-48, respectively, revising Tech Specs for penetration pressurization sys to define conditions of operation, applicable modes & actions taken for inoperable sys
VARGA, S A Operating Reactors Branch 1 82/12/20 7pp 16606 062 24X Fiche 50-295, 82/12/20, 8212290453

--8212290461 Safety evaluation supporting Amends 79 & 69 to Licenses DPR-39 & DPR-48, respectively
* Office of Nuclear Reactor Regulation, Director 82/12/20 3pp 16606 069 24X Fiche 50-295, 82/12/20, 8212290453

--8212290464 Notice of issuance & availability of Amends 79 & 69 to Licenses DPR-39 & DPR-48, respectively
VARGA, S A Operating Reactors Branch 1 82/12/20 2pp 16606 072 24X Fiche 50-295, 82/12/20, 8212290453

8212280212 Forwards updated schedule for ongoing environ qualification testing programs, per 810528 commitment
SWARTZ, E D Commonwealth Edison Co 82/12/22 EISENHUT, D G Division of Licensing 18pp 16556 161 24X Fiche 50-000, 82/12/22, 8212280212

0 Inspection reports, IE Bulletins & correspondence

8208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel Recirculation Sys Piping at BWR Plants " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240

8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model B01 & Model B02 Thermoluminescent Dosimeters " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000, 82/11/05, 8208190245

8212080282 Forwards IE Insp Repts 50-295/82-18 & 50-304/82-16 on 820830-0903 & 20-22 No noncompliance noted
MILLER, J R Division of Engineering & Technical Programs 82/11/12 REED, C Commonwealth Edison Co 2pp 16354 186 24X
Fiche 50-295, 82/11/12, 8212080282

--8212080296 IE Insp Repts 50-295/82-18 & 50-304/82-16 on 820830-0903 & 20-22 No noncompliance noted Major areas inspected compliance w/NUREG-0737, Item II F 1 3, allegations forwarded by IL Dept of Nuclear Safety & radiation protection program
MILLER, D E, PAUL, R A, GREGG, L R Division of Engineering & Technical Programs 82/11/10 15pp 16354 188 24X
Fiche 50-295, 82/11/12, 8212080282

8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X
Fiche 50-000, 82/11/18, 8208190251

8212060232 Forwards IE Safety Evaluation Repts 50-295/82-23 & 50-304/82-20 of emergency preparedness & SER
HIND, J A Division of Emergency Preparedness & Operational Support 82/11/19 REED, C Commonwealth Edison Co 2pp 16312 201 24X
Fiche 50-295, 82/11/19, 8212060232

--8212060238 IE Safety Evaluation Repts 50-295/82-23 & 50-304/82-20 of emergency preparedness plan Emergency plan acceptable
PHILLIPS, M P, AXELSON, W L, PAPERIELLO, C J Division of Emergency Preparedness & Operational Support 82/11/18 1p 16312 203 24X Fiche 50-295, 82/11/19, 8212060232

8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Radiolocks " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000, 82/11/26, 8208190256

8212060050 Summarizes 821103 meeting w/US Atty & law enforcement agencies in Chicago, IL re IE Investigation Repts 50-295/81-32 & 50-304/81-30 & status of ongoing investigation
KEPPLER, J O Region 3, Office of Director 82/11/29 JONES, O C Illinois, State of 2pp 16314 075 24X Fiche 50-295, 82/11/29, 8212060050

8208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 355pp 16387 028 24X Fiche 50-000, 82/11/30, 8208190257

8208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259

8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X
Fiche 50-000, 82/12/03, 8208190261

8212170109 Forwards IE Insp Repts 50-295/82-20 & 50-304/82-18 on 821025-27 & notice of violation
NORELIVS, C E Division of Engineering & Technical Programs 82/12/03 REED, C Commonwealth Edison Co 2pp 16452 336 24X
Fiche 50-295, 82/12/03, 8212170109

DOCKETED ITEMS

--8212170114 Notice of violation from insp on 821025-29
MORRELL, C E Division of Engineering & Technical Programs
82/12/03 2pp 16452 338 24X Fiche 50-295, 82/12/03, 8212170109

--8212170121 IE Insp Repts 50-295/82-20 & 50-304/82-18 on 821025-29
Noncompliance noted form not used to track operator progress
& current status of operator training Out-of-tolerance
parameters & valve stroke times not recorded
FARRELL, R E, HASSE, R A, PESCHEL, J M Division of Engineering &
Technical Programs 82/12/02 9pp 16452 340 24X
Fiche 50-295, 82/12/03, 8212170109

8212130183 Forwards addl info re IE Bulletin 80-11, "Masonry Walls."
in response to NRC 821022 ltr Eighteen walls qualified
using horizontal reinforcement
LENTINE, F O Commonwealth Edison Co 82/12/08 EISENHUT, D O
Division of Licensing 18pp 16396 099 24X Fiche 50-295, 82/12/08,
8212130183

8212280058 Forwards IE Insp Repts 50-295/82-27 & 50-304/82-24 on
821115-19 No noncompliance noted
MILLER, J R Division of Engineering & Technical Programs 82/12/10
REED, C Commonwealth Edison Co 2pp 16564 279 24X
Fiche 50-295, 82/12/10, 8212280058

--8212280062 IE Insp Repts 50-295/82-27 & 50-304/82-24 on 821115-19 No
noncompliance noted Major areas inspected radwaste sys,
including effluent release rates, records & repts, procedures
for controlling releases & containment air cleaning sys
MILLER, D E, GRANT, W B, GREGOR, L R Division of Engineering &
Technical Programs 82/12/10 7pp 16364 281 24X
Fiche 50-295, 82/12/10, 8212280058

8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for
Air & Gas Monitoring " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and
Enforcement 82/12/16 Consolidated Edison Co of New York, Inc
127pp 16628 191 24X Fiche 50-000, 82/12/16, 8208190267

8212290389 Forwards IE Insp Repts 50-295/82-29 & 50-304/82-26 on
821115-16 No noncompliance noted
LITTLE, W S Division of Engineering & Technical Programs 82/12/17
REED, C Commonwealth Edison Co 2pp 16586 296 24X
Fiche 50-295, 82/12/17, 8212290389

--8212290400 IE Insp Repts 50-295/82-29 & 50-304/82-26 on 821115-16 No
noncompliance noted Major areas inspected actions in
response to IE Bulletin 79-14, work procedure review &
observation of work
YIN, I T, DANIELSON, D H Division of Engineering & Technical
Programs 82/12/10 6pp 16586 298 24X Fiche 50-295, 82/12/17,
8212290389

8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage
Relays Type ITE-27 " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20
Consolidated Edison Co of New York, Inc 108pp 16628 293 24X
Fiche 50-000, 82/12/20, 8208190268

R Periodic operating reports & related correspondence

8212140055 Forwards monthly operating repts for Nov 1982
GROSSER, K L Commonwealth Edison Co. 82/12/09 Director's
Office, Office of Inspection and Enforcement 1p 16408 290 24X
Fiche 50-295, 82/12/09, 8212140055

--8212140061 Monthly operating repts for Nov 1982
AUSTIN, G Commonwealth Edison Co 82/12/09 1pp 16408 291
24X Fiche 50-295, 82/12/09, 8212140055

DOCKET 50-305 KEWAUNEE NUCLEAR POWER PLANT

F Security, medical, emergency & fire protection plans

8212090257 Notifies of relocation of emergency operations facility
Relocation satisfies requirements of NUREG-0696
Communications drill will be conducted prior to move
GIESLER, C W Wisconsin Public Service Corp 82/11/29 GRIMES, B
Division of Emergency Preparedness 1p 16363 244 24X
Fiche 50-305, 82/11/29, 8212090257

8212220306 Discusses layout of communications equipment required in
control room, onsite technical support ctr & near-site
emergency operations facility
KEPPLER, J O Region 3, Office of Director 82/12/16
Commonwealth Edison Co 3pp. 16503 351. 24X Fiche: 50-000, 82/12/16,
8212220306

8212270003 Releases public version of revised radiological emergency
response plan implementing procedure
FELTON, J M Division of Rules and Records 82/12/16 Document
Management Branch 1p 16551 276 24X Fiche 50-305, 82/12/16,
8212270003

--8212270007 Forwards public version of Revision A to Radiological
Emergency Response Plan Implementing Procedure EP-ENV-6B,
"Site Access Facility Environ Sample Analysis Relocation "
GIESLER, C W Wisconsin Public Service Corp 82/12/09
DENTON, H R Office of Nuclear Reactor Regulation, Director 1p
16551 277 24X Fiche 50-305, 82/12/16, 8212270003

--8212270010 Public version of Revision A to Radiological Emergency
Response Plan Implementing Procedure EP-ENV-6B, "Site
Access Facility Environ Sample Analysis Relocation "
LUNA, C R Wisconsin Public Service Corp 82/11/24 9pp
16551 278 24X Fiche 50-305, 82/12/16, 8212270003

8212280230 Requests approval of proposed change to emergency plan re
first aid training requirements, clarifying Red Cross 3-yr
refresher training schedule
GIESLER, C W Wisconsin Public Service Corp 82/12/22 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 16562 264
24X Fiche 50-305, 82/12/22, 8212280230

J Insurance & indemnity information

8212030076 Forwards Endorsement 46 to MAELU Policy MF-71 &
Endorsement 58 to NELIA Policy NF-204
GIESLER, C W Wisconsin Public Service Corp 82/11/30 DINI, T J
Division of Engineering 3pp 16304 298 24X Fiche 50-305,
82/11/30, 8212030076

P Operating license stage documents & correspondence

8212030267 Forwards request for addl info re SER on environ
qualification of safety-related equipment & on SER Item 3 4
re temp, pressure & humidity conditions outside containment
VARQA, S A Operating Reactors Branch 1 82/11/30 GIESLER, C W
Wisconsin Public Service Corp 3pp 16316 346 24X
Fiche 50-305, 82/11/30, 8212030267

8212160003 Forwards addl info re environ qualification of safety-
related electrical equipment installed per TMI action plan
items Qualification documentation will be submitted by
820117
GIESLER, C W Washington Public Power Supply System 82/11/15
VARQA, S A Operating Reactors Branch 1 605pp 16444 154 24X
Fiche 50-305, 82/11/15, 8212160003

8212030342 Requests that licensee propose license conditions, similar to
condition included in NRC 790801 ltr, re implementation of
secondary water chemistry program, within 60 days
VARQA, S A Operating Reactors Branch 1 82/11/29 GIESLER, C W
Wisconsin Public Service Corp 2pp 16316 163 24X
Fiche 50-305, 82/11/29, 8212030342

8212070492 Forwards Amend 47 to License DPR-43, safety evaluation &
notice of issuance & availability Amend revises Tech Specs
to include revised table of contents & corrects
typographical errors
GROTHENHUIS, M Operating Reactors Branch 1 82/11/29 GIESLER, C W
Wisconsin Public Service Corp 2pp 16351 305 24X
Fiche 50-305, 82/11/29, 8212070492

--8212070498 Amend 47 to License DPR-43, revising Tech Specs to include
rearrangement of table of contents & correcting
typographical errors
VARQA, S A Operating Reactors Branch 1 82/11/29 29pp
16351 307 24X Fiche 50-305, 82/11/29, 8212070492

--8212070501 Safety evaluation supporting Amend 47 to License DPR-43
" Office of Nuclear Reactor Regulation, Director 82/11/29 4pp
16351 336 24X Fiche 50-305, 82/11/29, 8212070492

--8212070504 Notice of issuance & availability of Amend 47 to License
DPR-43
VARQA, S A Operating Reactors Branch 1 82/11/29 2pp
16351 340 24X Fiche 50-305, 82/11/29, 8212070492

8212070149 Forwards status rept on NUREG-0737, Items II B 3, "Post-
Accident Sampling," II B 4, "Training for Mitigating Core
Damage" & II F 1, "Noble Gas Effluent Monitor" & "Sampling &
Analysis of Plant Effluents "
GIESLER, C W Wisconsin Public Service Corp 82/11/30
EISENHUT, D O Division of Licensing 5pp 16327 080 24X
Fiche 50-305, 82/11/30, 8212070149

DOCKETED ITEMS

139

B212080026 Ack receipt of B11217 ltr re application fees for review of adequacy of station electrical distribution sys voltages
Voltages relate to proposed Amend 29 No fees due
MILLER, W D License Fee Management Branch 82/11/30 GIESLER, C W
Wisconsin Public Service Corp 1p 16367 164 24X
Fiche 50-305, 82/11/30, B212080026

B212070333 Anticipates submittal of proposed Amend 51 to Tech Specs
revising item re RCS leakage, before 821228
GIESLER, C W Wisconsin Public Service Corp 82/12/02 VARQA, S A
Operating Reactors Branch 1 1p 16339 009 24X
Fiche 50-305, 82/12/02, B212070333

B212140407 Submits results of evaluation of need to provide
around-the-clock chemistry coverage by radiological
chemistry technologist Commitment to provide coverage,
made in 810910 ltr, retracted
GIESLER, C W Wisconsin Public Service Corp 82/12/08
EISENHUT, D G Division of Licensing 3pp 16403 333 24X
Fiche 50-305, 82/12/08, B212140407

B208190263 Generic Ltr 82-32 to all PWR licensees re potential steam
generator-related generic requirements Forwards Science
Applications, Inc draft rept re subj requirements Comments
requested within 30 days of ltr Svc list encl
EISENHUT, D G Division of Licensing 82/12/09 Consolidated
Edison Co of New York, Inc 2pp 16629 247 24X
Fiche 50-000, 82/12/09, B208190263

B212140103 Generic Ltr 82-28 to all licensees of operating
Westinghouse & C-E PWRs (except Arkansas Nuclear One, Unit 2
& San Onofre 2 & 3) re inadequate core cooling
instrumentation sys Svc list encl
EISENHUT, D G Division of Licensing 82/12/10 Yankee Atomic
Electric Co 27pp 16690 035 24X Fiche 50-000, 82/12/10,
B212140103

B212140143 Corrects typographical error in B21123 ltr re NUREG-0737,
Item III D 3 4, "Control Room Habitability " Physical mods
expected to be completed by June 1983
GIESLER, C W Wisconsin Public Service Corp 82/12/10
EISENHUT, D G Division of Licensing 1p 16408 180 24X
Fiche 50-305, 82/12/10, B212140143

B212210181 Advises that info re ECCS models incorporating upper plenum
injection, per 821101 request, will be submitted no later than
830215
GIESLER, C W Wisconsin Public Service Corp 82/12/15 VARQA, S A
Operating Reactors Branch 1 1p 16484 338 24X
Fiche 50-305, 82/12/15, B212210181

B212270197 Application to amend License DPR-43, revising Tech Specs re
limiting conditions for operation, surveillance
requirements & administrative controls
GIESLER, C W Wisconsin Public Service Corp 82/12/20 DENTON, H R
Office of Nuclear Reactor Regulation, Director 6pp 16535 155
24X Fiche 50-305, 82/12/20, B212270197

--B212270203 Proposed Tech Spec changes re limiting conditions for
operation, surveillance requirements & administrative
controls
* Wisconsin Public Service Corp 82/12/20 24pp 16535 161
24X Fiche 50-305, 82/12/20, B212270197

B212280193 Provides accuracy & time response info on NUREG-0737, Items
I F 1 4, 5 & 6 re wide-range containment pressure monitoring
sys, sump water level sys & placement of hydrogen monitoring
sys
GIESLER, C W Wisconsin Public Service Corp 82/12/22 VARQA, S A
Operating Reactors Branch 1 2pp 16562 088 24X
Fiche 50-305, 82/12/22, B212280193

B212280318 Discusses NUREG-0737 items to be incorporated in revisions
to Tech Specs, per Generic Ltr 82-16 & until 821220 ltr
GIESLER, C W Wisconsin Public Service Corp 82/12/23
EISENHUT, D G Division of Licensing 4pp 16562 073 24X
Fiche 50-305, 82/12/23, B212280318

B212280467 Forwards "Control of Heavy Loads," 6-month response to
Generic Ltr B1-07, NUREG-0612 Response to Section 2 2 through
2 4 scheduled to be submitted by 830215
GIESLER, C W Wisconsin Public Service Corp 82/12/23
EISENHUT, D G Division of Licensing 2pp 16556 179 24X
Fiche 50-305, 82/12/23, B212280467

--B212280473 "Control of Heavy Loads," 6-month response to Generic Ltr
B1-07, NUREG-0612
* Wisconsin Public Service Corp 82/12/23 68pp 16556 181
24X Fiche 50-305, 82/12/23, B212280467

G Inspection reports, IE Bulletins & correspondence

B208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-
Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping
at BWR Plants " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and
Enforcement 82/10/28 Consolidated Edison Co of New York, Inc
112pp 16462 163 24X Fiche 50-000, 82/10/28, B208190240

B208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model
B01 & Model B02 Thermoluminescent Dosimeters " Svc list
encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards
82/11/05 Consolidated Edison Co of New York, Inc 110pp
16372 142 24X Fiche 50-000, 82/11/05, B208190245

B208190251 IE Info Notice 82-44, "Clarification of Emergency Plan
Exercise Requirements " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18
Consolidated Edison Co of New York, Inc 109pp 16411 199 24X
Fiche 50-000, 82/11/18, B208190251

B212100141 Forwards IE Insp Rept 50-305/82-18 on 820901-1031 & notice
of violation
SPESARD, R L Division of Project & Resident Programs 82/11/23
GIESLER, C W Wisconsin Public Service Corp 2pp 16376 020 24X
Fiche 50-305, 82/11/23, B212100141

--B212100144 Notice of violation from insp on 820901-1031
SPESARD, R L Division of Project & Resident Programs 82/11/23
1p 16376 022 24X Fiche 50-305, 82/11/23, B212100141

--B212100149 IE Insp Rept 50-305/82-18 on 820901-1031 Noncompliance
noted failure to perform required surveillance for
radiation monitoring channels R-11 & R-12
NELSON, R L, REYES, R A Division of Project & Resident Programs
82/11/23 6pp 16376 023 24X Fiche 50-305, 82/11/23, B212100141

B208190256 IE Info Notice 82-46, "Defective & Obsolete Combination
Padilocks " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and
Enforcement 82/11/26 Consolidated Edison Co of New York, Inc
127pp 16411 065 24X Fiche 50-000, 82/11/26, B208190256

B212060044 Ack receipt of B21112 ltr informing NRC of steps taken to
correct violations noted in IE Insp Rept 50-305/82-13
STREETEER, J F Division of Project & Resident Programs 82/11/26
GIESLER, C W Wisconsin Public Service Corp 1p 16313 202 24X
Fiche 50-305, 82/11/26, B212060044

--B212060049 Responds to NRC B21013 ltr re violations noted in IE Insp
Rept 50-305/82-13 Corrective actions duplicate file will be
established to assure that documentation of memos will be
established
GIESLER, C W Wisconsin Public Service Corp 82/11/12
SPESARD, R L Division of Project & Resident Programs 2pp
16313 203 24X Fiche 50-305, 82/11/26, B212060044

B208190257 IE Info Notice 82-47, "Transportation of Type A Quantities
of Non-Fissile Radioactive Matl " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards
82/11/30 Consolidated Edison Co of New York, Inc 356pp
16387 028 24X Fiche 50-000, 82/11/30, B208190257

B208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment
Electrical Penetration Assemblies " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and
Enforcement 82/12/03 Consolidated Edison Co of New York, Inc
113pp 16411 317 24X Fiche 50-000, 82/12/03, B208190259

B208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay
Sockets " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03
Consolidated Edison Co of New York, Inc 110pp, 16462 064 24X
Fiche 50-000, 82/12/03, B208190261

B212270334 Forwards IE Insp Rept 50-305/82-22 on 821110-12 No
noncompliance noted
LITTLE, W S Division of Engineering & Technical Programs 82/12/10
GIESLER, C W Wisconsin Public Service Corp 2pp 16530 037 24X
Fiche 50-305, 82/12/10, B212270334

--B212270339 IE Insp Rept 50-305/82-22 on 821110-12 No noncompliance
noted Major areas inspected followup on previous insp
findings & review of non-licenses personnel training &
licensed personnel requalification programs
HASSE, R A, HAWKINS, F C Region 3, Office of Director 82/12/08
5pp 16530 039, 24X Fiche 50-305, 82/12/10, B212270334

DOCKETED ITEMS

8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
DEVOUNO, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16, 8208190267

8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27 " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X Fiche 50-000, 82/12/20, 8208190268

R Periodic operating reports & related correspondence

8212290211 Forwards monthly operating rept for Oct 1982
GIESLER, C W Wisconsin Public Service Corp 82/11/09 Management Information Branch 1p 16578 135 24X Fiche 50-305, 82/11/09, 8212290211

--8212290216 Monthly operating rept for Oct 1982
RUITER, G H Wisconsin Public Service Corp 82/11/01 4pp 16578 136 24X Fiche 50-305, 82/11/09, 8212290211

S Reportable occurrences, LERs & related correspondence

8212060090 Lists correct LER numbers for cover ltrs transmitting repts
GIESLER, C W Wisconsin Public Service Corp 82/11/24 KEPLER, J G Region 3, Office of Director 1p 16316 078 24X Fiche 50-305, 82/11/24, 8212060090

8212170167 Forwards LER 82-034/03L-0
GIESLER, C W Wisconsin Public Service Corp 82/12/10 KEPLER, J G Region 3, Office of Director 1p 16462 028 24X Fiche 50-305, 82/12/10, 8212170167

--8212170171 LER 82-034/03L-0 on 821111, valve MS-100A, main steam to turbine driven auxiliary feedwater pump, torqued out when closing Caused by torque switch sticking & manual de-clutch unit out of adjustment Switch & tripper assembly replaced
BERNHOF, S L Wisconsin Public Service Corp 82/12/10 Region 3, Office of Director 1p 16462 029 24X Fiche 50-305, 82/12/10, 8212170167

DOCKET 50-306 PRAIRIE ISLAND NUCLEAR STATION, UNIT 2

F Security, medical, emergency & fire protection plans

8212030134 Forwards IE Insp Repts 50-282/82-17 & 50-306/82-17 on 820921-1031 No noncompliance noted
STREETER, J F Division of Project & Resident Programs 82/11/17 LARSON, C E Northern States Power Co 2pp 16306 031 24X Fiche 50-282, 82/11/17, 8212030134

--8212030150 IE Insp Repts 50-282/82-17 & 50-306/82-17 on 820921-1031 No noncompliance noted Major areas inspected preparation for refueling, fire drills & exercises, operations safety verification, followup on fuel oil spill & followup on LERs
FEIERABEND, C D Division of Project & Resident Programs 82/11/17 8pp 16306 033 24X Fiche 50-282, 82/11/17, 8212030134

821210329 Forwards IE Insp Repts 50-282/82-18 & 50-306/82-18 on 821013-15 & 1109 No noncompliance noted
HIND, J A Division of Emergency Preparedness & Operational Support 82/12/02 LARSON, C E Northern States Power Co 3pp 16496 229 24X Fiche 50-282, 82/12/02, 821210329

- 821210340 IE Insp Repts 50-282/82-18 & 50-306/82-18 on 821013-15 & 1109 No noncompliance noted Major areas inspected emergency exercise, especially command & control of control room, technical support ctr & operations support ctr
PATTERSON, J P, PAPERIELLO, C J Division of Emergency Preparedness & Operational Support 82/12/01 12pp 16496 232 24X Fiche 50-282, 82/12/02, 821210329

8212140279 Requests exemption, under 10CFR50.48(c)(15), from automatic suppression Requirement of App R, Section III Q 3 for control room
MUSOLF, D Northern States Power Co 82/12/06 Office of Nuclear Reactor Regulation, Director 3pp 16402 104 24X Fiche 50-282, 82/12/06, 8212140279

8212220045 Advises that 820520 & 0823 exemption requests granted extending deadline for installation of emergency lighting until 830101 Addl time needed to complete engineering analysis, procurement & installation
EISENHUT, D O Division of Licensing 82/12/08 MUSOLF, D M Northern States Power Co 4pp 16526 355 24X Fiche 50-282, 82/12/08, 8212220045

--8212220048 Exemption granting extension for installation of emergency lighting until 830101
DENTON, H R Office of Nuclear Reactor Regulation, Director 82/12/08 Northern States Power Co 7pp 16526 359 24X Fiche 50-282, 82/12/08, 8212220045

8212220306 Discusses layout of communications equipment required in control room, onsite technical support ctr & near-site emergency operations facility
KEPLER, J O Region 3, Office of Director 82/12/16 Commonwealth Edison Co 3pp 16503 351 24X Fiche 50-000, 82/12/16, 8212220306

8212300412 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 82/12/22 Document Management Branch 1p 16613 075 24X Fiche 50-282, 82/12/22, 8212300412

--8212300416 Forwards public version of revised Emergency Plan Implementing Procedures F3-5 re emergency notifications, F3-10 re personnel accountability & F3-23 re emergency sampling
WARD, E C Northern States Power Co 82/12/15 Region 3, Office of Director 1p 16613 076 24X Fiche 50-282, 82/12/22, 8212300412

--8212300417 Public version of Emergency Plan Implementing Procedures F3-5 re emergency notifications, F3-10 re personnel accountability & F3-23 re emergency sampling
SCHUELKE, D A Northern States Power Co 82/11/04 102pp 16613 077 24X Fiche 50-282, 82/12/22, 8212300412

P Operating license stage documents & correspondence

8212090057 Forwards Revision 1 to 750847 license amend request to change Tech Specs re containment leakage rate testing, incorporating required changes No fee appropriate since request submitted earlier
MUSOLF, D Northern States Power Co 82/12/03 Office of Nuclear Reactor Regulation, Director 1p 16399 041 24X Fiche 50-282, 82/12/03, 8212090057

--8212090059 Revision 1 to 750807 license amend request to change Tech Spec re containment leakage rate testing
MUSOLF, D Northern States Power Co 82/12/03 20pp 16399 042 24X Fiche 50-282, 82/12/03, 8212090057

8212090172 Forwards addl info re methods of compliance w/NUREG-0737, Item II B 3 on post-accident sampling sys. in response to 820908 request
MUSOLF, D Northern States Power Co 82/12/03 Office of Nuclear Reactor Regulation, Director 11pp 16399 221 24X Fiche 50-282, 82/12/03, 8212090172

8208190263 Generic Ltr 82-32 to all PWR licensees re potential steam generator-related generic requirements Forwards Science Applications, Inc draft rept re subj requirements Comments requested within 30 days of ltr Svc list encl
EISENHUT, D O Division of Licensing 82/12/09 Consolidated Edison Co of New York, Inc 29pp 16629 247 24X Fiche 50-000, 82/12/09, 8208190263

8212140411 Forwards summary of NRC review of Exxon Nuclear Co thermal hydraulic methodology for mixed cores in PWRs Encl TOPROD sensitivity & thermal margin studies submitted on 820618 & 29, respectively, remain valid Comments requested
COWKE, G C Exxon Nuclear Co, Inc (subs of Exxon Corp) 82/12/09 HOLONICH, J J Core Performance Branch 7pp 16403 322 24X Fiche 50-282, 82/12/09, 8212140411

8212140103 Generic Ltr 82-28 to all licensees of operating Westinghouse & C-E PWRs (except Arkansas Nuclear One, Unit 2 & San Onofre 2 & 3) re inadequate core cooling instrumentation sys Svc list encl
EISENHUT, D O Division of Licensing 82/12/10 Yankee Atomic Electric Co 27pp 16690 035 24X Fiche 50-000, 82/12/10, 8212140103

8212170262 Responds to 821104 request for ECCS model, specifically treating upper plenum injection Exxon model will be ready for submittal by 830131
MUSOLF, D Northern States Power Co 82/12/10 Office of Nuclear Reactor Regulation, Director 1p 16456 207 24X Fiche 50-282, 82/12/10, 8212170262

821210290 Forwards NSPNAD-8101P, Revision 1, "Qualification of Reactor Physics Methods for Application to Prairie Island Units," & NSPNAD-8102P, Revision 1, "Reload Safety Evaluation Methods for Application " Repts withheld (ref 10CFR2.790)
MUSOLF, D Northern States Power Co 82/12/13 Office of Nuclear Reactor Regulation, Director 1p 16497 134 24X Fiche 50-282, 82/12/13, 821210290

Q Inspection reports, IE Bulletins & correspondence

B20B190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel Recirculation Sys Piping at BWR Plants " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, 820B190240

B20B190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model G01 & Model B02 Thermoluminescent Dosimeters " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000, 82/11/05, 820B190245

B212030134 Forwards IE Insp Repts 50-282/82-17 & 50-306/82-17 on 820921-1031 No noncompliance noted
STREETEER, J F Division of Project & Resident Programs 82/11/17 LARSON, C E Northern States Power Co 2pp 16306 031 24X Fiche 50-282, 82/11/17, 8212030134

--B212030150 IE Insp Repts 50-282/82-17 & 50-306/82-17 on 820921-1031 No noncompliance noted Major areas inspected preparation for refueling, fire drills & exercises, operations safety verification, followup on fuel oil spill & followup on LERs
FEIERABEND, C D, REYES, L Division of Project & Resident Programs 82/11/17 8pp 16306 033 24X Fiche 50-282, 82/11/17, 8212030134

B20B190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X Fiche 50-000, 82/11/18, 820B190251

B20B190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000, 82/11/26, 820B190256

B20B190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000, 82/11/30, 820B190257

B212210329 Forwards IE Insp Repts 50-282/82-18 & 50-306/82-18 on 821013-15 & 1109 No noncompliance noted
HIND, J A Division of Emergency Preparedness & Operational Support 82/12/02 LARSON, C E Northern States Power Co 3pp 16496 224 24X Fiche 50-282, 82/12/02, 8212210329

--B212210340 IE Insp Repts 50-282/82-18 & 50-306/82-18 on 821013-15 & 1109 No noncompliance noted Major areas inspected emergency exercise, especially command & control of control room, technical support ctr & operations support ctr
PATTERSON, J P, LICKUS, R H, AXELSON, W L Division of Emergency Preparedness & Operational Support 82/12/01 12pp 16496 237 24X Fiche 50-282, 82/12/02, 8212210329

B20B190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, 820B190259

B20B190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X Fiche 50-000, 82/12/03, 820B190261

B212270292 Forwards IE Insp Repts 50-282/82-19 & 50-306/82-19 on 821126 No noncompliance noted
LITTLE, W S Division of Engineering & Technical Programs 82/12/10 LARSON, C E Northern States Power Co 2pp 16530 122 24X Fiche 50-282, 82/12/10, 8212270292

--B212270305 IE Insp Repts 50-282/82-19 & 50-306/82-19 on 821126 No noncompliance noted Major areas inspected review of inservice insp procedures, NDE personnel certifications & data & IE Bulletin 78-12 activities
WARD, K D, DANIELSON, D H Region 3, Office of Director 82/12/09 4pp 16530 124 24X Fiche 50-282, 82/12/10, 8212270292

B20B190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16, 820B190267

B212280325 Responds to IE Bulletin 82-04 No electrical penetration assemblies referenced in bulletin in use or planned for use in safety-related sys
LARSON, C E Northern States Power Co 82/12/17 KEPLER, J G Region 3, Office of Director 1p 16562 087 24X Fiche 50-282, 82/12/17, 8212280325

B20B190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27 " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 29J 24X Fiche 50-000, 82/12/20, 820B190268

DOCKET 50-309 MAINE YANKEE ATOMIC POWER PLANT

F Security, medical, emergency & fire protection plans

B212140435 Forwards "1982 ME Yankee Nuclear Power Station Emergency Response Exercise & Evaluation Plan," detailing scenario & evaluation criteria for 821211 emergency plan exercise
GARRITY, J H Maine Yankee Atomic Power Co 82/11/24 HAYNES, R C Region 1, Office of Director 2pp 16405 258 24X Fiche 50-309, 82/11/24, 8212140435

--B212140442 "1982 ME Yankee Nuclear Power Station Emergency Response Exercise & Evaluation Plan "
* Maine Yankee Atomic Power Co 82/12/31 192pp 16405 260 24X Fiche 50-309, 82/11/24, 8212140435

--B212140453 Forwards util & State of ME objectives for 821211 emergency plan exercise
GARRITY, J H Maine Yankee Atomic Power Co 82/09/28 HAYNES, R C Region 1, Office of Director 5pp 16404 358 24X Fiche 50-309, 82/11/24, 8212140435

B212030291 Releases public version of revision to emergency plan implementing procedure
FELTON, J M Division of Rules and Records 82/11/30 Document Management Branch 1p 16322 231 24X Fiche 50-309, 82/11/30, 8212030291

--B212030299 Forwards public version of Revision 2 to Emergency Plan Implementing Procedure 2 50 7, "Emergency Onsite Radiation Monitoring Procedure " Receipt form encl
* Maine Yankee Atomic Power Co 82/11/20 Office of Nuclear Reactor Regulation, Director 1p 16322 232 24X Fiche 50-309, 82/11/30, 8212030291

--B212030304 Public version of Revision 2 to Emergency Plan Implementing Procedure 2 50 7, "Emergency Onsite Radiation Monitoring Procedure " Index of Series 250 procedures encl
* Maine Yankee Atomic Power Co 82/11/20 33pp 16322 233 24X Fiche 50-309, 82/11/30, 8212030291

B212150159 Forwards IE Insp Rept 50-309/82-16 on 820824-1005 & notice of violation
STAROSTECKI, R Division of Project & Resident Programs 82/12/02 RANDAZZA, J B Maine Yankee Atomic Power Co 2pp 16430 165 24X Fiche 50-309, 82/12/02, 8212150159

--B212150169 IE Insp Rept 50-309/82-16 on 820824-1005 Noncompliance noted failure to review & update written Class A procedures for new fuel insp within 2 yr period
SWETLAND, P, GALLOR, Division of Project & Resident Programs 82/11/18 14pp 16430 168 24X Fiche 50-309, 82/12/02, 8212150159

B212210349 Forwards IE Safeguards Insp Rept 50-309/82-20 on 821025-28 No noncompliance noted
MARTIN, T T Division of Engineering & Technical Programs 82/12/06 RANDAZZA, J B Maine Yankee Atomic Power Co 2pp 16495 163 24X Fiche 50-309, 82/12/06, 8212210349

--B212210351 IE Safeguards Insp Rept 50-309/82-20 on 821025-28 No noncompliance noted Major areas inspected security plan & implementing procedures, security organization, security program audit & records Safeguards info deleted
MADDEN, W, ODDY, A T Region 1, Office of Director 82/12/03 4pp 16495 165 24X Fiche 50-309, 82/12/06, 8212210349

B212270025 Forwards request for addl info to complete review of App R fire protection & safe shutdown Plant manager should be contacted within 10 days of receipt of ltr to arrange suitable meeting
CLARK, R A Operating Reactors Branch 3 82/12/08 GARRITY, J Maine Yankee Atomic Power Co 6pp 16551 336 24X Fiche 50-309, 82/12/08, 8212270025

GP12160751 Summarizes status of reactor coolant pump lube oil fire exemption request & containment leak testing meeting requested
CLARK, R A Operating Reactors Branch 3 82/12/10 GARRITY, J H
Maine Yankee Atomic Power Co 3pp 16465 357 24X
Fiche 50-309, 82/12/10, 8212160751

GP12230046 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 82/12/15 Document
Management Branch 1p 16545 110 24X Fiche 50-309, 82/12/15,
8212230046

--8212230057 Forwards public version of revised emergency plan implementing procedures, including Procedure 2 50 0 re declaration & categorization of emergency condition & 2 50 5 re emergency plan training & exercise
* Maine Yankee Atomic Power Co 82/12/06 Office of Nuclear Reactor Regulation, Director 2pp 16545 111 24X
Fiche 50-309, 82/12/15, 8212230046

--8212230068 Public version of revised emergency plan implementing procedures, including Procedures 2 50 0 re declaration & categorization of emergency condition & 2 50 5 re emergency plan training & exercise
* Maine Yankee Atomic Power Co 82/12/04 104pp 16545 113 24X Fiche 50-309, 82/12/15, 8212230046

B21210308 Updates plans for upgraded emergency response facilities Primary emergency operations facility & technical support ctr will be relocated to new staff bldg per NUREG-0696 final design criteria not yet established
GARRITY, J H Maine Yankee Atomic Power Co 82/12/16 HEITNER, K
Operating Reactors Branch 3 2pp 16497 107 24X
Fiche 50-309, 82/12/16, 821210308

B21210344 Provides addl info to better prepare util shift crews for types or questions NRC duty officer may ask during telephone repts via NRC emergency notification sys Revised event notification form (Parts I & II) encl
STARGSTECKI, R Division of Project & Resident Programs 82/12/16 RANDAZZA, J B Maine Yankee Atomic Power Co 6pp 16496 328 24X
Fiche 50-309, 82/12/16, 821210344

G Adjudicatory correspondence

GP12060042 Ack receipt of 821020 request for issuance of order to show cause why license should not be revoked or suspended, submitted on behalf of Safe Power for ME Request will be treated as petition under 10CFR2 206
DENTON, H R Office of Nuclear Reactor Regulation, Director 82/11/30 MURRAY, P L Murray, Plumb & Murray 1p 16343 221 24X
Fiche 50-309, 82/11/30, 8212060042

--8212060046 Notice of Safe Power for ME 821020 request under 10CFR2 206 for issuance of order to show cause why license should not be suspended or revoked
DENTON, H R Office of Nuclear Reactor Regulation, Director 82/11/30 1p 16343 222 24X Fiche 50-309, 82/11/30, 8212060042

P Operating license stage documents & correspondence

GP121010334 Forwards safety evaluation & E&G technical evaluation on degraded grid protection for Class IE power sys Plant operating procedures, design details & Tech Specs to cover relay setpoint & time delay requested within 120 days
CLARK, R A Operating Reactors Branch 3 82/11/12 GARRITY, J H
Maine Yankee Atomic Power Co 3pp 16271 296 24X
Fiche 50-309, 82/11/12, 8212010334

--8212010335 Safety evaluation supporting licensee proposed Level 2 degraded voltage design providing automatic separation of Class IE power sys from offsite sys if degraded grid exists coincident w/safety injection sys Addl info required
PREVATTE, R NRC - No Detailed Affiliation Given 82/11/12 6pp 16271 299 24X Fiche 50-309, 82/11/12, 8212010334

B212010417 Advises that requirements of NUREG-0737, TMI Action Plan Items I A 2 4, "Upgrading of Reactor Operator & Senior Reactor Operator Training," & II B 4 I, "Training for Mitigating Core Damage," has been met
CLARK, R A Operating Reactors Branch 3 82/11/18 GARRITY, J H
Maine Yankee Atomic Power Co 2pp 16267 341 24X
Fiche 50-309, 82/11/18, 8212010417

--8212010422 Safety evaluation re implementation of NUREG-0737, TMI Action Items I A 2 4, "Upgrading of Reactor Operator & Senior Reactor Operator Training," & II B 4 I, "Training for Mitigating Core Damage" Items met
WIGGINS, J T Operating Reactors Branch 3 82/11/18 2pp 16267 343 24X Fiche 50-309, 82/11/18, 8212010417

--8212010427 "Improvements in Training & Regualification Programs As Required by TMI Action Items I A 2 I & II B 4," technical evaluation rept
* Science Applications, Inc SAI-186-029-23 82/08/17 NRC -
No Detailed Affiliation Given 14pp 16267 345 24X
Fiche 50-309, 82/11/18, 8212010417

B212070454 Forwards questions re instrumentation & control concerns for feedwater trip sys design Meeting to discuss responses should be arranged within 30 days
CLARK, R A Operating Reactors Branch 3 82/11/24 GARRITY, J H
Maine Yankee Atomic Power Co 4pp 16355 325 24X
Fiche 50-309, 82/11/24, 8212070454

B212130092 Forwards Amend 6B to License DPR-36, safety evaluation & notice of issuance & availability Amend revises Tech Specs to support operation of plant at full rated power during Cycle 7
CLARK, R A Operating Reactors Branch 3 82/11/29 GARRITY, J H
Maine Yankee Atomic Power Co 4pp 16417 072 24X
Fiche 50-309, 82/11/29, 8212130092

--8212130095 Amend 6B to License DPR-36, revising Tech Specs to support operation of plant at full rated power during Cycle 7
CLARK, R A Operating Reactors Branch 3 82/11/29 31pp 16417 076 24X Fiche 50-309, 82/11/29, 8212130092

--8212130099 Safety evaluation supporting Amend 6B to License DPR-36
* Office of Nuclear Reactor Regulation, Director 82/11/29 40pp 16417 107 24X Fiche 50-309, 82/11/29, 8212130092

--8212130102 Notice of issuance & availability of Amend 6B to License DPR-36
CONNER, E L Operating Reactors Branch 3 82/11/29 2pp 16417 147 24X Fiche 50-309, 82/11/29, 8212130092

B212060042 Ack receipt of 821020 request for issuance of order to show cause why license should not be revoked or suspended, submitted on behalf of Safe Power for ME Request will be treated as petition under 10CFR2 206
DENTON, H R Office of Nuclear Reactor Regulation, Director 82/11/30 MURRAY, P L Murray, Plumb & Murray 1p 16343 221 24X
Fiche 50-309, 82/11/30, 8212060042

--8212060046 Notice of Safe Power for ME 821020 request under 10CFR2 206 for issuance of order to show cause why license should not be suspended or revoked
DENTON, H R Office of Nuclear Reactor Regulation, Director 82/11/30 1p 16343 222 24X Fiche 50-309, 82/11/30, 8212060042

B212060259 Forwards updates on selected TMI action items per Generic Ltrs 82-05 & 82-10, "Post-TMI Requirements" TMI Action Items II B 2, II B 3, II E 1 2, II F 1, II D 1 2, II D 1 3 & III D 3 4 discussed
GARRITY, J H Maine Yankee Atomic Power Co 82/11/30 CLARK, R A
Operating Reactors Branch 3 3pp 16312 269 24X
Fiche 50-309, 82/11/30, 8212060259

B212150229 Forwards interim position on radiation environs for environ qualification of safety-related electrical equipment open issues Response requested in 30 days
CLARK, R A Operating Reactors Branch 3 82/12/06 GARRITY, J H
Maine Yankee Atomic Power Co 3pp 16437 358 24X
Fiche 50-309, 82/12/06, 8212150229

B212100266 Provides addl info supplementing B1091B & B20827 ltrs to clarify items discussed during 821029 telcon re control of heavy loads
GARRITY, J H Maine Yankee Atomic Power Co 82/12/07 CLARK, R A
Operating Reactors Branch 3 2pp 16376 137 24X
Fiche 50-309, 82/12/07, 8212100266

B212130324 Advises that training program re pressurized thermal shock will not be revised Training program fulfills intent of post-TMI Action Item I C 5
GARRITY, J H Maine Yankee Atomic Power Co 82/12/08 CLARK, R A
Operating Reactors Branch 3 2pp 16389 268 24X
Fiche 50-309, 82/12/08, 8212130324

B212140204 Provides recommendations to improve control room habitability, per NUREG-0737, Item III D 3 4 Redundant dampers not necessary to ensure habitability
GARRITY, J H Maine Yankee Atomic Power Co 82/12/08 CLARK, R A
Operating Reactors Branch 3 3pp 16409 341 24X
Fiche 50-309, 82/12/08, 8212140204

B208190263 Generic Ltr 82-32 to all PWR licensees re potential steam generator-related generic requirements Forwards Science Applications, Inc draft rept re subj requirements Comments requested within 30 days of ltr Svc list encl
EISENHUT, D O Division of Licensing 82/12/09 Consolidated
Edison Co of New York, Inc 2pp 16629 247 24X
Fiche 50-000, 82/12/09, 8208190263

8212140103 Generic Ltr 82-28 to all licensees of operating Westinghouse & C-E PWRs (except Arkansas Nuclear One, Unit 2 & San Onofre 2 & 3) re inadequate core cooling instrumentation sys Svc list encl
EISENHUT, D O Division of Licensing 82/12/10 Yankee Atomic Electric Co 27pp 16690 035 24X Fiche 50-000, 82/12/10, 8212140103

8212160751 Summarizes status of reactor coolant pump lube oil fire exemption request & containment leak testing Meeting requested
CLARK, R A Operating Reactors Branch 3 82/12/10 GARRITY, J H Maine Yankee Atomic Power Co 3pp 16465 357 24X Fiche 50-309, 82/12/10, 8212160751

Q Inspection reports, IE Bulletins & correspondence

8208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BHR Plants " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240

8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000, 82/11/05, 8208190245

8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X Fiche 50-000, 82/11/18, 8208190251

8212060215 Forwards IE Insp Rept 50-309/82-21 on 821025-27 No noncompliance noted
MARTIN, T T Division of Engineering & Technical Programs 82/11/22 RANDAZZA, J B Maine Yankee Atomic Power Co 2pp 16312 029 24X Fiche 50-309, 82/11/22, 8212060215

--8212060217 IE Insp Rept 50-309/82-21 on 821025-27 No noncompliance noted Major areas inspected inservice insp program
KERCH, H, DURR, J Region 1, Office of Director 82/11/19 3pp 16312 031 24X Fiche 50-309, 82/11/22, 8212060215

8212070144 Forwards IE Insp Rept 50-309/82-18 on 820927-1001 No noncompliance noted
MARTIN, T T Division of Engineering & Technical Programs 82/11/23 RANDAZZA, J B Maine Yankee Atomic Power Co 2pp 16327 043 24X Fiche 50-309, 82/11/23, 8212070144

--8212070148 IE Insp Rept 50-309/82-18 on 820927-1001 No noncompliance noted Major areas inspected procedure review, test witnessing & results, evaluation of local leak rate test & integrated leak rate test & facility tours
PULLANI, S V, BETTENHAUSEN, L Division of Engineering & Technical Programs 82/11/12 9pp 16327 045 24X Fiche 50-309, 82/11/23, 8212070144

8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000, 82/11/26, 8208190256

8208190297 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000, 82/11/30, 8208190297

8212150159 Forwards IE Insp Rept 50-309/82-16 on 820824-1005 & notice of violation
STAROSTECKI, R Division of Project & Resident Programs 82/12/02 RANDAZZA, J B Maine Yankee Atomic Power Co 2pp 16430 165 24X Fiche 50-309, 82/12/02, 8212150159

--8212150163 Notice of violation from insp on 820824-1005
* Division of Project & Resident Programs 82/12/02 1p 16430 167 24X Fiche 50-309, 82/12/02, 8212150159

--8212150169 IE Insp Rept 50-309/82-16 on 820824-1005 Noncompliance noted failure to review & update written Class A procedures for new fuel insp within 2 yr period
SHETLAND, P, GALLD, R Division of Project & Resident Programs 82/11/18 14pp 16430 168 24X Fiche 50-309, 82/12/02, 8212150159

8208190239 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190239

8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X Fiche 50-000, 82/12/03, 8208190261

8212210349 Forwards IE Safeguards Insp Rept 50-309/82-20 on 821025-28 No noncompliance noted
MARTIN, T T Division of Engineering & Technical Programs 82/12/06 RANDAZZA, J B Maine Yankee Atomic Power Co 2pp 16495 163 24X Fiche 50-309, 82/12/06, 8212210349

--8212210351 IE Safeguards Insp Rept 50-309/82-20 on 821025-28 No noncompliance noted Major areas inspected security plan & implementing procedures, security organization, security program audit & records Safeguards info deleted
MADDELL, W, GODY, A T Region 1, Office of Director 82/12/03 4pp 16495 165 24X Fiche 50-309, 82/12/06, 8212210349

8212210263 Ack receipt of 821108 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-309/82-11
MARTIN, T T Division of Engineering & Technical Programs 82/12/13 RANDAZZA, J B Maine Yankee Atomic Power Co 1p 16483 254 24X Fiche 50-309, 82/12/13, 8212210263

--8212210266 Responds to NRC 821007 ltr re violations noted in IE Insp Rept 50-309/82-11 Corrective actions site inventory of all sources & detectors involving SNM completed & discrepancies identified
RANDAZZA, J B Maine Yankee Atomic Power Co 82/11/08 HAYNES, R C Region 1, Office of Director 3pp 16483 255 24X Fiche 50-309, 82/12/13, 8212210263

8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16, 8208190267

8212220430 Forwards NUREG-0903 containing results of interviews re drug & alcohol abuse & rehabilitation programs per IE Info Notice 82-05 Util will be contacted shortly to arrange similar interviews w/o NUREG
STAROSTECKI, R Division of Project & Resident Programs 82/12/16 RANDAZZA, J B Maine Yankee Atomic Power Co 3pp 16503 307 24X Fiche 50-309, 82/12/16, 8212220430

8212220386 Ack receipt of 820727, 28, 29 & 1124 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 50-309/82-26
STAROSTECKI, R Division of Project & Resident Programs 82/12/17 RANDAZZA, J B Maine Yankee Atomic Power Co 1p 16517 239 24X Fiche 50-309, 82/12/17, 8212220386

--8212220390 Responds to NRC 820722 ltr re violations noted in IE Insp Rept 50-309/82-26 Corrective actions low pressure safety injection pumps verified to be limiting re NPSH
GARRITY, J H Maine Yankee Atomic Power Co 82/07/27 HAYNES, R C Region 1, Office of Director 2pp 16517 240 24X Fiche 50-309, 82/12/17, 8212220386

--8212220396 Responds to NRC 820722 ltr re violations noted in IE Insp Rept 50-309/82-26 Corrective actions evaluation to confirm & redefine refueling water tank level & temp limits which ensure NPSH for all safeguards pumps completed
GARRITY, J H Maine Yankee Atomic Power Co 82/11/24 HAYNES, R C Region 1, Office of Director 3pp 16517 246 24X Fiche 50-309, 82/12/17, 8212220386

8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27 " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X Fiche 50-000, 82/12/20, 8208190268

R Periodic operating reports & related correspondence

8212290116 Forwards monthly operating rept for Oct 1982
GROCE, R H Maine Yankee Atomic Power Co 82/11/05 Office of Resource Management, Director 1p 16583 228 24X Fiche 50-309, 82/11/05, 8212290116

--8212290128 Monthly operating rept for Oct 1982
PHILLIPS, J Maine Yankee Atomic Power Co 82/11/04 5pp 16583 229 24X Fiche 50-309, 82/11/05, 8212290116

5 Reportable occurrences, LERs & related correspondence

8212210165 Forwards updated LER 82-031/03X-1
GARRITY, J H Maine Yankee Atomic Power Co 82/12/07 Region 1,
Office of Director 1p 16484 299 24X Fiche 50-309, 82/12/07,
8212210165

--8212210170 Updated LER 82-031/03X-1 on 820924, scheduled inservice insp
of shock suppressors revealed empty hydraulic reservoir on
snubber 72, SHP-HSS-110 Caused by leakage through cylinder
seals & valve fittings. Snubber rebuilt
NELSON, R H Maine Yankee Atomic Power Co 82/12/07 Region 1,
Office of Director 2pp 16484 300 24X Fiche 50-309, 82/12/07,
8212210165

8212220456 LER 82-039/01T-0 on 821210, detector response to given core
power level found low caused by reduced leakage neutron flux
at ex-core detectors. Ex-core detectors adjusted using
analytical calibr factor
WOOD, E C Maine Yankee Atomic Power Co 82/12/10 Region 1,
Office of Director 1p 16503 258 24X Fiche 50-309, 82/12/10,
8212220456

8212290291 Forwards LER 82-038/03L-0
GARRITY, J H Maine Yankee Atomic Power Co 82/12/14 Region 1,
Office of Director 1p 16588 010 24X Fiche 50-309, 82/12/14,
8212290291

--8212290306 LER 82-038/03L-0 on 821109, RHR pump P-12A removed from svr &
water level in core dropped below 23 ft caused by need to
install emergency diesel generator improvement mod, coupled
w/ lack of clearly worded Tech Specs License mod forthcoming
NELSON, R H, CAYIA, A J Maine Yankee Atomic Power Co 82/12/14
Region 1, Office of Director 5pp 16588 011 24X
Fiche 50-309, 82/12/14, 8212290291

8212220276 PNO-1-82-082 on 821217, confirmatory surface measurements
on Chem-Nuclear cask containing 21 drums of compacted
radioactive dry waste above spec requirements. State of SC
considering fine & suspension of waste disposal privileges
WHITE, J J, DORES, R Region 1, Office of Director 82/12/17 1p
16518 029 24X Fiche 50-309, 82/12/17, 8212220276

DOCKET 50-311 SALEM NUCLEAR GENERATING STATION, UNIT 2

F Security, medical, emergency & fire protection plans

8212010462 Confirms that Div of Safeguards regulatory effectiveness
review scheduled for 821203 & 06-10 info re review encl
Review will evaluate security program & safeguards
regulations
VARGA, S A Operating Reactors Branch 1 82/11/23 UDERITZ, R A
Public Service Electric & Gas Co of New Jersey 6pp 16501 327
24X Fiche 50-272, 82/11/23, 8212010462

8212290525 Forwards Amend 15 to License DPR-75, safety evaluation &
notice of issuance & availability. Amend authorizes deferral
of fire protection Tech Spec surveillance requirement from
821205 until first refueling outage in Jan 1983
ROSS, W J Operating Reactors Branch 1 82/12/03 UDERITZ, R A
Public Service Electric & Gas Co of New Jersey 3pp 16605 152
24X Fiche 50-311, 82/12/03, 8212290525

--8212290528 Amend 15 to License DPR-75, deferring 18-month fire
protection Tech Spec surveillance item from required date of
821205 to startup following final refueling outage in Jan
1983
VARGA, S A Operating Reactors Branch 1 82/12/03 4pp
16605 155 24X Fiche 50-311, 82/12/03, 8212290525

--8212290530 Safety evaluation supporting Amend 15 to License DPR-75
* Office of Nuclear Reactor Regulation, Director 82/12/03 3pp
16605 159 24X Fiche 50-311, 82/12/03, 8212290525

--8212290532 Notice of issuance & availability of Amend 15 to
License DPR-75
VARGA, S A Operating Reactors Branch 1 82/12/03 2pp
16605 162 24X Fiche 50-311, 82/12/03, 8212290525

8212130212 Responds to 821202 telcon re emergency operations facility
survey. Facility 7.5 miles from generating station & consists
of concrete block facility within concrete block bldg.
Protection factor is 13. Ventilation sys isolable
LIDEN, E A Public Service Electric & Gas Co of New Jersey
82/12/06 VARGA, S A Operating Reactors Branch 1 2pp 16390 118
24X Fiche 50-272, 82/12/06, 8212130212

8212290435 Forwards IE Enforcement Conference Repts 50-272/82-31 &
50-311/82-28 on 820812. No reply required
MARTIN, T T Division of Engineering & Technical Programs 82/12/14
UDERITZ, R A Public Service Electric & Gas Co of New Jersey 2pp
16585 222 24X Fiche 50-272, 82/12/14, 8212290435

--8212290443 IE Enforcement Conference Repts 50-272/82-31 & 50-311/82-28
on 820812. Areas discussed implementation & mgt of physical
security program
SMITH, G C Division of Engineering & Technical Programs
82/12/07 4pp 16585 224 24X Fiche 50-272, 82/12/14, 8212290435

8212210038 Offers addl info to prepare operating shift crews to
respond to types of questions NRC duty officer may ask re
telephone repts made via NRC emergency notification sys
STAROSTECKI, R Division of Project & Resident Programs 82/12/16
UDERITZ, R A Public Service Electric & Gas Co of New Jersey 6pp
16490 214 24X Fiche 50-272, 82/12/16, 8212210038

8212300306 Confirms 821220 telcon re fire protection program review
Smoke detectors & nonsafety-grade source range neutron flux
monitors will be installed & 1 h fire barrier matl will be
wrapped on B diesel control cable trays
LIDEN, E A Public Service Electric & Gas Co of New Jersey
82/12/22 VARGA, S A Operating Reactors Branch 1 1p 16594 204
24X Fiche 50-272, 82/12/22, 8212300306

P Operating license stage documents & correspondence

821230066 Generic Ltr 82-27 to all DNR licensees of operating reactors
except LACBHR, Big Rock Point, Dresden 1, Humboldt Bay,
applicants for QL & holders of CP re transmittal of
NUREG-0763 & NUREG-0783 Evc list encl w/o stated encl
GISENHUT, D O Division of Licensing 82/11/15 General Public
Utilities - GPU Service Corp 22pp 16397 004 24X
Fiche 50-000, 82/11/15, 821230066

8212010159 Submits addl info to support 821005 request for amend to
License DPR-70 & DPR-75. Info includes analysis results
demonstrating motivation for Tech Spec change & effects on
core limits & axial offset DNB limits
LIDEN, E A Public Service Electric & Gas Co of New Jersey
82/11/18 VARGA, S A Operating Reactors Branch 1 8pp 16258 094
24X Fiche 50-272, 82/11/18, 8212010159

8212010400 Advises that License DPR-75 is amended per 821122 telecopy
Amend extends deadline for completion of repairs to
component cooling HX22
LAINAS, G C Assistant Director for Operating Reactors 82/11/23
UDERITZ, R A Public Service Electric & Gas Co of New Jersey 3pp
16271 080 24X Fiche 50-311, 82/11/23, 8212010400

8212010148 Forwards Revision 1 to "Safety Evaluation of PSEG Rod
Exchange Methodology," for info
LIDEN, E A Public Service Electric & Gas Co of New Jersey
82/11/24 VARGA, S A Operating Reactors Branch 1 3pp 16248 111
24X Fiche 50-272, 82/11/24, 8212010148

--8212010150 "Safety Evaluation of PSEG Rod Exchange Methodology,"
Revision 1
BLAKE, R A, BROWN, R T, ROSENFELD, E S Public Service Electric &
Gas Co of New Jersey NFG 004 R01 82/11/16 34pp 16258 114
24X Fiche 50-272, 82/11/24, 8212010148

8212130192 Requests License Condition 2 L be expanded to include
deferral of 18-month surveillance Tech Spec by adding addl
safety evaluation page to Amend 14 granted on 821027 Change
is Class III amend Fee to be forwarded
LIDEN, E A Public Service Electric & Gas Co of New Jersey
82/12/02 VARGA, S A Operating Reactors Branch 1 2pp 16396 147
24X Fiche 50-311, 82/12/02, 8212130192

8212290525 Forwards Amend 15 to License DPR-75, safety evaluation &
notice of issuance & availability. Amend authorizes deferral
of fire protection Tech Spec surveillance requirement from
821205 until first refueling outage in Jan 1983
ROSS, W J Operating Reactors Branch 1 82/12/03 UDERITZ, R A
Public Service Electric & Gas Co of New Jersey 3pp 16605 152
24X Fiche 50-311, 82/12/03, 8212290525

--8212290528 Amend 15 to License DPR-75, deferring 18-month fire
protection Tech Spec surveillance item from required date of
821205 to startup following final refueling outage in Jan
1983
VARGA, S A Operating Reactors Branch 1 82/12/03 4pp
16605 155 24X Fiche 50-311, 82/12/03, 8212290525

--8212290530 Safety evaluation supporting Amend 15 to License DPR-75
* Office of Nuclear Reactor Regulation, Director 82/12/03 3pp
16605 159 24X Fiche 50-311, 82/12/03, 8212290525

--B212290532 Notice of issuance & availability of Amend 15 to License DPR-75
VARQA, S A Operating Reactors Branch 1 82/12/03 2pp
16605 162 24X Fiche 50-311, 82/12/03, 8212290525

B208190263 Generic Ltr 82-32 to all PWR licensees re potential steam generator-related generic requirements Forwards Science Applications, Inc draft rept re subj requirements Comments requested within 30 days of ltr Svc list encl
EISENHUT, D O Division of Licensing 82/12/09 Consolidated Edison Co of New York, Inc 29pp 16629 247 24X
Fiche 50-000, 82/12/09, 8208190263

B212140623 Notification of B21214 meeting w/uttl in Bethesda, MD to discuss util proposal for restructuring safety review Functions
ROSS, W J Operating Reactors Branch 1 82/12/14 VARQA, S A Operating Reactors Branch 1 2pp 16466 035 24X
Fiche 50-272, 82/12/14, 8212140623

B212300072 Notification of 820104 significant licensee meeting w/uttl for presentation of QA organizational & functional changes TRIPP, L E Division of Project & Resident Programs 82/12/21 Division of Project & Resident Programs 2pp 16624 280 24X
Fiche 50-000, 82/12/21, 8212300072

G Inspection reports, IE Bulletins & correspondence

B208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240

B208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000, 82/11/05, 8208190245

B208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X
Fiche 50-000, 82/11/18, 8208190251

B212060278 Forwards IE Insp Repts 50-272/82-27 & 50-311/82-26 on 820928-1108 & notice of violation STAROSTECKI, R Division of Project & Resident Programs 82/11/22 UDERITZ, R A Public Service Electric & Gas Co of New Jersey 2pp 16312 036 24X Fiche 50-272, 82/11/22, 8212060278

--B212060281 Notice of violation from insp on 820928-1108
* Division of Project & Resident Programs 82/11/22 2pp
16312 038 24X Fiche 50-272, 82/11/22, 8212060278

-B212060287 IE Insp Repts 50-272/82-27 & 50-311/82-26 on 820928-1108 Noncompliance noted failure to perform surveillance in time specified & failure to observe limiting condition of operation on fire protection instrumentation
NORRKHOLM, H J, SUMMERS, R, TRIPP, L E Division of Project & Resident Programs 82/11/09 18pp 16312 040 24X
Fiche 50-272, 82/11/22, 8212060278

B208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000, 82/11/26, 8208190256

B212030144 Ack receipt of 821119 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-272/82-22 & 50-311/82-21
MARTIN, T T Division of Engineering & Technical Programs 82/11/29 UDERITZ, R A Public Service Electric & Gas Co of New Jersey 1p 16306 112 24X Fiche 50-272, 82/11/29, 8212030144

--B212030153 Responds to NRC 821019 ltr re violations noted in IE Insp Repts 50-272/82-22 & 50-311/82-21 Corrective actions Meter M-137 properly recalibr. Meters M-76 & M-184 accounted for & inadequate housekeeping conditions corrected
UDERITZ, R A Public Service Electric & Gas Co of New Jersey 82/11/19 HAYNES, R C Region 1, Office of Director 5pp 16306 113 24X Fiche 50-272, 82/11/29, 8212030144

B208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000, 82/11/30, 8208190257

B208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259

B208190261 IE Info Notice 82-48, "Failures of Ageslat CR 0095 Relay Sockets " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X
Fiche 50-000, 82/12/03, 8208190261

B212140124 Ack receipt of 821105 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-272/82-25 & 50-311/82-24
STAROSTECKI, R Division of Project & Resident Programs 82/12/06 UDERITZ, R A Public Service Electric & Gas Co of New Jersey 1p 16408 240 24X Fiche 50-272, 82/12/06, 8212140124

--B212140133 Responds to NRC 821006 ltr re violations noted in IE Insp Repts 50-272/82-25 & 50-311/82-24 Corrective actions Tech Spec 3 0 4 will be discussed w/personnel Tech Spec 3 3 3 5 limiting condition for operation not violated
UDERITZ, R A Public Service Electric & Gas Co of New Jersey 82/11/05 HAYNES, R C Region 1, Office of Director 4pp 16408 241 24X Fiche 50-272, 82/12/06, 8212140124

B212200020 Submits addl info per IE Bulletin 80-11, "Masonry Wall Design," in response to NRC request One oversize drawing encl Aperture card is available in PDR
LIDENE, A Public Service Electric & Gas Co of New Jersey 82/12/08 VARQA, S A Operating Reactors Branch 1 3pp 16470 186 24X Fiche 50-272, 82/12/08, 8212200020

B212290435 Forwards IE Enforcement Conference Repts 50-272/82-31 & 50-311/82-28 on 820812 No reply required
MARTIN, T T Division of Engineering & Technical Programs 82/12/14 UDERITZ, R A Public Service Electric & Gas Co of New Jersey 2pp 16585 222 24X Fiche 50-272, 82/12/14, 8212290435

--B212290443 IE Enforcement Conference Repts 50-272/82-31 & 50-311/82-28 on 820812 Areas discussed implementation & mgt of physical security program
SMITH, G C, MCKEDON, L M, GDDY, A T Division of Engineering & Technical Programs 82/12/07 4pp 16585 224 24X
Fiche 50-272, 82/12/14, 8212290435

B208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16, 8208190267

B212220444 Forwards listing of topic areas for discussion at Region 1/ licensee meeting on drug & alcohol abuse programs per IE Info Notice 82-05 & NUREG-0903 W/o NUREG
STAROSTECKI, R Division of Project & Resident Programs 82/12/16 UDERITZ, R A Public Service Electric & Gas Co of New Jersey 3pp 16503 322 24X Fiche 50-272, 82/12/16, 8212220444

B208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27 " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X
Fiche 50-000, 82/12/20, 8208190268

R Periodic operating reports & related correspondence

B212270274 Forwards monthly operating rept for Nov 1982
MIDURA, H J Public Service Electric & Gas Co of New Jersey 82/12/10 Director's Office, Office of Inspection and Enforcement 1p 16530 332 24X Fiche 50-311, 82/12/10, 8212270274

--B212270280 Monthly operating rept for Nov 1982
MILLER, L K Public Service Electric & Gas Co of New Jersey 82/12/10 19pp 16530 333 24X Fiche 50-311, 82/12/10, 8212270274

B212280066 Forwards NPDES discharge monitoring rept for Nov 1982
MILLER, L K Public Service Electric & Gas Co of New Jersey 82/12/15 BAKER, R A, LUNDIN, C Environmental Protection Agency 1p 16564 256 24X Fiche 50-272, 82/12/15, 8212280066

--B212280068 NPDES discharge monitoring rept for Nov 1982
MILLER, L K Public Service Electric & Gas Co of New Jersey 82/12/14 19pp 16564 257 24X Fiche 50-272, 82/12/15, 8212280066

DOCKETED ITEMS

S Reportable occurrences, LERs & related correspondence

8210210078 Forwards LER 82-111/01T-0 Detailed event analysis encl
MIDURA, H J Public Service Electric & Gas Co of New Jersey
82/10/06 HAYNES, R C Region 1, Office of Director 3pp
15765 327. 24X Fiche 50-311,82/10/06,8210210078

--8210210095 LER 82-111/01T-0 on 821002, small svc water leak of 0.5 gpm
discovered on cooling coils of containment fan coil unit 23
Caused by erosion of cooling coils by silt in svc water
Belzona metal filler used in repair New coils purchased
FRAHM, R Public Service Electric & Gas Co of New Jersey
82/10/06 Region 1, Office of Director 1p 15765 333 24X
Fiche 50-311,82/10/06,8210210078

8212060165 Forwards LER 82-131/03L-0 Detailed event analysis encl
MIDURA, H J Public Service Electric & Gas Co of New Jersey
82/11/17 HAYNES, R C Region 1, Office of Director 3pp
16311 056 24X Fiche 50-311,82/11/17,8212060165

--8212060174 LER 82-131/03L-0 on 821028 & 1106, P-250 computer observed
operating erratically & RCS subcooling margin monitor
declared inoperable Caused by 4-volt dc power supply
drifting low Power supply adjusted
FRAHM, R Public Service Electric & Gas Co of New Jersey
82/11/17 Region 1, Office of Director 1p 16311 067 24X
Fiche 50-311,82/11/17,8212060165

8212060202 Forwards LER 82-130/03L-0 Detailed event analysis encl
MIDURA, H J Public Service Electric & Gas Co of New Jersey
82/11/17 HAYNES, R C Region 1, Office of Director 3pp
16313 198 24X Fiche 50-311,82/11/17,8212060202

--8212060214 LER 82-130/03L-0 on 821031 & 1105, svc water flow to
containment fan coil unit 23 observed low. Caused by silt
clogging back pressure control valves Valves cycled during
cooler leak repair Low flow eliminated when unit started
FRAHM, R Public Service Electric & Gas Co of New Jersey
82/11/17 Region 1, Office of Director 1p 16313 201 24X
Fiche 50-311,82/11/17,8212060202

8212080434 Forwards LER 82-135/01T-0 Detailed event analysis encl
MIDURA, H J Public Service Electric & Gas Co of New Jersey
82/11/24 HAYNES, R C Region 1, Office of Director 3pp
16352 171 24X Fiche 50-311,82/11/24,8212080434

--8212080443 LER 82-135/01T-0 on 821121, during routine surveillance, small
svc water leak discovered on cooling coil of containment fan
coil unit 25 Caused by silt in svc water Coil repaired New
design coils will be installed during next refueling
FRAHM, R Public Service Electric & Gas Co of New Jersey
82/11/24 Region 1, Office of Director 1p 16352 174 24X
Fiche 50-311,82/11/24,8212080434

8212140079 Forwards LER 82-132/03L-0 Detailed event analysis encl
MIDURA, H J Public Service Electric & Gas Co of New Jersey
82/11/24 HAYNES, R C Region 1, Office of Director 3pp
16408 251 24X Fiche 50-311,82/11/24,8212140079

--8212140085 LER 82-132/03L-0 on 821106 & 15, spurious actuation of
safeguards equipment control cabinet 2A resulted in
de-energization of vital bus 2A Caused by noise in sys
control circuitry. Noise suppression devices will be added
FRAHM, R Public Service Electric & Gas Co of New Jersey
82/11/24 Region 1, Office of Director 1p 16408 254 24X
Fiche 50-311,82/11/24,8212140079

8212140099 Forwards LER 82-134/03L-0 Detailed event analysis encl
MIDURA, H J Public Service Electric & Gas Co of New Jersey
82/11/24 HAYNES, R C Region 1, Office of Director 3pp
16409 264 24X Fiche 50-311,82/11/24,8212140099

--8212140107 LER 82-134/03L-0 on 821110, during routine surveillance,
turbine trip low autostop oil pressure channel II bistable
observed to trip low Caused by mechanical wear in channel
pressure switch. Switch replaced
FRAHM, R Public Service Electric & Gas Co of New Jersey
82/11/24 Region 1, Office of Director 1p 16409 267 24X
Fiche 50-311,82/11/24,8212140099

8212160048 Forwards LER 82-137/03L-0 Detailed event analysis encl
MIDURA, H J Public Service Electric & Gas Co of New Jersey
82/12/01 HAYNES, R C Region 1, Office of Director 3pp
16446 203. 24X Fiche 50-311,82/12/01,8212160048

--8212160054 LER 82-137/03L-0 on 821115, during routine operation, control
room operator discovered that auxiliary alarm typewriter
not printing intelligibly Caused by tilt ring assembly being
out of adjustment Assembly readjusted
FRAHM, R Public Service Electric & Gas Co of New Jersey
82/12/01 Region 1, Office of Director 1p 16446 206 24X
Fiche 50-311,82/12/01,8212160048

8212160381 Forwards LER 82-133/03L-0 Detailed event analysis encl
MIDURA, H J Public Service Electric & Gas Co of New Jersey
82/12/01 HAYNES, R C Region 1, Office of Director 3pp
16442 342 24X Fiche 50-311,82/12/01,8212160381

--8212160390 LER 82-133/03L-0 on 821107, during routine operation, control
room operator discovered containment gaseous activity
monitor malfunctioned Caused by intermittent connection on
integrated circuit on circuit board Units reseated
FRAHM, R Public Service Electric & Gas Co of New Jersey
82/12/01 Region 1, Office of Director 1p 16442 345 24X
Fiche 50-311,82/12/01,8212160381

8212160399 Forwards LER 82-136/01T-0 Detailed event analysis encl
MIDURA, H J Public Service Electric & Gas Co of New Jersey
82/12/01 HAYNES, R C Region 1, Office of Director 3pp
16442 147 24X Fiche 50-311,82/12/01,8212160399

--8212160414 LER 82-136/01T-0 on 821124, small svc water leak of 0.5 gpm
discovered on cooling coil of containment fan coil unit 23
Caused by erosion of cooling coil by silt in svc water
Coil blanked off to seal leak
FRAHM, R Public Service Electric & Gas Co of New Jersey
82/12/01 Region 1, Office of Director 1p 16442 150 24X
Fiche 50-311,82/12/01,8212160399

8212220381 Forwards LER 82-142/03L-0 Detailed event analysis encl
MIDURA, H J Public Service Electric & Gas Co of New Jersey
82/12/08 HAYNES, R C Region 1, Office of Director 3pp
16517 260 24X Fiche 50-311,82/12/08,8212220381

--8212220385 LER 82-142/03L-0 on 821123, steam generator 21 level channel
IV indication read 4/ higher than other channels & declared
inoperable Caused by failure of channel level transmitter
Transmitter replaced
FRAHM, R Public Service Electric & Gas Co of New Jersey
82/12/08 Region 1, Office of Director 1p 16517 263 24X
Fiche 50-311,82/12/08,8212220381

8212220395 Forwards LER 82-138/03L-0 Detailed event analysis encl
MIDURA, H J Public Service Electric & Gas Co of New Jersey
82/12/08 HAYNES, R C Region 1, Office of Director 3pp
16503 212 24X Fiche 50-311,82/12/08,8212220395

--8212220406 LER 82-138/03L-0 on 821119, shift supervisor realized that
surveillance requirement to check local sightglass levels
of accumulators 23 & 24 was overdue Caused by personnel
oversight Personnel counseled
DICKEY, F Public Service Electric & Gas Co of New Jersey
82/12/08 Region 1, Office of Director 1p 16503 215 24X
Fiche 50-311,82/12/08,8212220395

8212220420 Forwards LER 82-139/03L-0 Detailed event analysis encl
MIDURA, H J Public Service Electric & Gas Co of New Jersey
82/12/08 HAYNES, R C Region 1, Office of Director 3pp
16503 274 24X Fiche 50-311,82/12/08,8212220420

--8212220424 LER 82-139/03L-0 on 821119, auxiliary feedwater storage tank
dropped below Tech Spec min vol of 200,000 gallons Caused by
personnel error Tank level restored & operator counseled
DICKEY, F Public Service Electric & Gas Co of New Jersey
82/12/08 Region 1, Office of Director 1p 16503 277 24X
Fiche 50-311,82/12/08,8212220420

8212220433 Forwards LER 82-143/03L-0 Detailed event analysis encl
MIDURA, H J Public Service Electric & Gas Co of New Jersey
82/12/08 HAYNES, R C Region 1, Office of Director 3pp
16503 317 24X Fiche 50-311,82/12/08,8212220433

--8212220435 LER 82-143/03L-0 on 821124, during surveillance review,
discovered reactor trip breaker manual trip feature not
tested before 821119 startup Caused by confusion involving
recent changes in procedures re testing of trip breaker
FRAHM, R Public Service Electric & Gas Co of New Jersey
82/12/08 Region 1, Office of Director 1p 16503 321 24X
Fiche 50-311,82/12/08,8212220433

DOCKET 50-312 RANCHO SECO NUCLEAR GENERATING STATION

F Security, medical, emergency & fire protection plans

8212130337 Forwards response to S Miner 821202 telcon request re
emergency operations facility (EOF) Permanent primary EOF
located 23 miles from reactor bldg
MATTING, J J Sacramento Municipal Utility District 82/12/07.
STOLZ, J F Operating Reactors Branch 4 2pp 16389 272 24X
Fiche 50-312,82/12/07,8212130337

B212170319 Application for proposed Amend B7 to License DPR-54 relocating one fire hydrant to permit const of new training & records bldg
MATTIMOE, J J Sacramento Municipal Utility District 82/12/07
EISENHUT, D O Division of Licensing 1p 16453 191 24X
Fiche 50-312, 82/12/07, 8212170319

--B212170320 Proposed Tech Specs for Amend B7 to License DPR-54, relocating one fire hydrant to permit const of new training & records bldg
+ Sacramento Municipal Utility District 82/12/07 1p
16453 192 24X Fiche 50-312, 82/12/07, 8212170319

G12130163 Forwards IE Safeguards Insp Rept 50-312/82-39 on 821115-19 No noncompliance noted Rept withheld (ref 10CFR2 790)
NORDERHAUG, L R Division of Radiological Safety & Safeguards Program 82/12/08 MATTIMOE, J J Sacramento Municipal Utility District 2pp 16396 070 24X Fiche 50-312, 82/12/08, 8212130163

G12170198 Forwards response to Region 5 comments on security training & qualification plan, Revision 4
MATTIMOE, J J Sacramento Municipal Utility District 82/12/10
STOLZ, J F Operating Reactors Branch 4 4pp 16450 008 24X
Fiche 50-312, 82/12/10, 8212170198

B212210439 Informs that next requalification cycle for station blackout training begins after annual operator exams scheduled to be completed by Jan 1983
MATTIMOE, J J Sacramento Municipal Utility District 82/12/15
STOLZ, J F Operating Reactors Branch 4 1p 16493 126 24X
Fiche 50-312, 82/12/15, 8212210439

G Adjudicatory correspondence

B212220136 Forwards NUREG/CR-3013 & ED Sylvester affidavit in response to ASLAB 820930 order NRC position in SER re acceptability of current auxiliary feedwater sys until upgraded sys complete remains unchanged
LESSY, R P Hearing Branch 3 82/12/01 ROSENTHAL, A S, BUCK, J H, KOHL, C N Atomic Safety and Licensing Appeal Panel 49pp
16503 099 24X Fiche 50-312, 82/12/01, 8212220136

--B212220141 Affidavit of ED Sylvester in response to ASLAB 820930 order requesting info re auxiliary feedwater sys NRC evaluation awaits licensee info Sys upgrades provide significant improvement over present design w/prof qualifications
SYLVESTER, E D Auxiliary Systems Branch 82/12/01 64pp
16503 148 24X Fiche 50-312, 82/12/01, 8212220136

B212200026 Comments responding to ASLAB 821123 Memorandum & Order ALAB-703 ASLAB should modify tentative conclusion & endorse alternative insp program re HPI nozzle radiographic exam
BAXTER, T A Sacramento Municipal Utility District BAXTER, T A Shaw, Pittman, Potts & Trowbridge 82/12/14 Bpp 16474 273 24X
Fiche 50-312, 82/12/14, 8212200026

B212300004 Advises of status of two items remaining from ALAB-703 NRC comments on Frequency of radiographic insps for HPI Nozzles C & D encl in S Hou affidavit NRC review of licensee info re auxiliary feedwater sys mods will be submitted by 830331
DESSY, R F Hearings Division 82/12/23 ROSENTHAL, A S, BUCK, J H, KOHL, C N Atomic Safety and Licensing Appeal Panel 2pp
16598 144 24X Fiche 50-312, 82/12/23, 8212300004

--B212300007 Affidavit of S Hou re ALAB-703 Item 3 on adequacy of licensee inservice insp program for HPI Nozzles C & D More frequent insps scheduled than schedule proposed by licensee on 821214 warranted Prof qualifications encl
HOU, S Office of Nuclear Reactor Regulation, Director 82/12/20 3pp 16598 146 24X Fiche 50-312, 82/12/23, 8212300004

B212300152 Memorandum & order directing NRC to file supplemental response to licensee 821214 submittal re radiographic insp of HPI Nozzles C & D by 830112 S Hou affidavit is of limited assistance Response should focus on util insp schedule
TOMPKINS, B A Atomic Safety and Licensing Appeal Panel 82/12/29 Office of the Executive Legal Director 5pp 16598 087 24X
Fiche 50-312, 82/12/29, 8212300152

P Operating license stage documents & correspondence

B212170078 Forwards notice of consideration of issuance of amend to License DPR-54 re 820928 application to permit expansion of spent fuel storage capacity
MINER, S Operating Reactors Branch 4 82/12/01 MATTIMOE, J J Sacramento Municipal Utility District 4pp 16480 280 24X
Fiche 50-312, 82/12/01, 8212170078

--B212170089 Notice of consideration of issuance of amend to License DPR-54 re 820928 application to permit expansion of spent fuel storage capacity
STOLZ, J F Operating Reactors Branch 4 82/12/01 4pp
16480 284 24X Fiche 50-312, 82/12/01, 8212170078

B212080110 Notification of B21216 meeting w/B&W owners group in Bethesda, MD to discuss results of long-term program for evaluation of cracking problem in B&W plant makeup nozzles
MINER, S Operating Reactors Branch 4 82/12/03 STOLZ, J F Operating Reactors Branch 4 3pp 16368 296 24X
Fiche 50-312, 82/12/03, 8212080110

B212140351 Forwards proposed Amend 62 to DPR-54, consisting of entire Tech Specs, revising environ portion per EOG request & updating nonenviron portion to include amends approved by NRC as of 790713
MATTIMOE, J J Sacramento Municipal Utility District 82/12/07
EISENHUT, D O Division of Licensing 1p 16402 125 24X
Fiche 50-312, 82/12/07, 8212140351

--B212140356 Proposed Tech Specs, revising environ portion & updating nonenviron portion to include amends approved by NRC as of 790713
+ Sacramento Municipal Utility District 82/12/07 388pp
16402 126 24X Fiche 50-312, 82/12/07, 8212140351

--B212140363 "Rancho Seco Nuclear Generating Station Offsite Dose Calculation Manual"
+ Sacramento Municipal Utility District 82/10/31 77pp
16403 077 24X Fiche 50-312, 82/12/07, 8212140351

B212170009 Concurs w/util conclusion that no Tech Spec changes or addl analyses required to support operation to 305 effective full power days during Cycle 5, per util 820922 & 110211 ltrs
STOLZ, J F Operating Reactors Branch 4 82/12/07 MATTIMOE, J J Sacramento Municipal Utility District 3pp 16480 296 24X
Fiche 50-312, 82/12/07, 8212170009

B212170319 Application for proposed Amend B7 to License DPR-54 relocating one fire hydrant to permit const of new training & records bldg
MATTIMOE, J J Sacramento Municipal Utility District 82/12/07
EISENHUT, D O Division of Licensing 1p 16453 191 24X
Fiche 50-312, 82/12/07, 8212170319

--B212170320 Proposed Tech Specs for Amend B7 to License DPR-54, relocating one fire hydrant to permit const of new training & records bldg
+ Sacramento Municipal Utility District 82/12/07 1p
16453 192 24X Fiche 50-312, 82/12/07, 8212170319

B212170110 Forwards request for addl info & status rept re NUREG-0737, Item II E 1.1, "Auxiliary Feedwater Sys Evaluation"
Confirmation that required info will be submitted by 830114 requested within 7 days
STOLZ, J F Operating Reactors Branch 4 82/12/08 MATTIMOE, J J Sacramento Municipal Utility District 62pp 16478 023 24X
Fiche 50-312, 82/12/08, 8212170110

B208190263 Generic Ltr 82-32 to all PWR licensees re potential steam generator-related generic requirements Forwards Science Applications, Inc draft rept re subj requirements Comments requested within 30 days of ltr Svc list encl
EISENHUT, D O Division of Licensing 82/12/09 Consolidated
Edison Co of New York, Inc 29pp 16629 247 24X
Fiche 50-000, 82/12/09, 8208190263

B212170220 Forwards list of hook travel speeds for cranes util reported in response to NUREG-0612 info requested by C Bomberger of Hestec Svcs, Inc for evaluation of util response
MATTIMOE, J J Sacramento Municipal Utility District 82/12/09
MINER, S Office of Nuclear Reactor Regulation, Director 2pp
16462 011 24X Fiche 50-312, 82/12/09, 8212170220

B212140391 Application to amend License DPR-54, extending 18-month interval between normal reactor refuelings to 24 months for one time only, due to shutdowns resulting from turbine rotor repairs & auxiliary feedwater spray header mods
MATTIMOE, J J Sacramento Municipal Utility District 82/12/10
EISENHUT, D O Division of Licensing 3pp 16402 110 24X
Fiche 50-312, 82/12/10, 8212140391

B212140401 Advises that operability test performed on HPIS during refueling outages Monthly operability test conducted on individual pumps, breakers & valves Failure of integrated mode response considered remote
COLOMBO, R Sacramento Municipal Utility District 82/12/10
MINER, S NRC - No Detailed Affiliation Given 1p 16404 319 24X
Fiche 50-312, 82/12/10, 8212140401

DOCKETED ITEMS

B212270396 Forwards order for license mod to implement NUREG-0737, Item 11 F 2 "Inadequate Core Cooling"
EISENHUT, D O Division of Licensing 82/12/10 MATTIME, J J
Sacramento Municipal Utility District 3pp 16573 349 24X
Fiche 50-312, 82/12/10, B212270396

- B212270399 Order for license mod to implement NUREG-0737, Item 11 F 2, "Inadequate Core Cooling"
EISENHUT, D O Division of Licensing 82/12/10 Sacramento
Municipal Utility District 11pp 16573 353 24X
Fiche 50-312, 82/12/10, B212270396

B212170255 Notifies that final rept re safety & relief valve testing will not be completed until Mar 1983 PORV block valve issue satisfies NUREG-0737, Item 11 D 1, closing issue
Qualification based on CPC 820601 submittal
MATTIME, J J Sacramento Municipal Utility District 82/12/13
STOLZ, J F Operating Reactors Branch 4 1p 16496 208 24X
Fiche 50-312, 82/12/13, B212170255

B212220241 Lists reasons for delay in implementation of abnormal transient operating guideline (NUREG-0737, Item 1 C 1) & delay in operator training as stated in 820604 response to Generic Ltr 82-10
MATTIME, J J Sacramento Municipal Utility District 82/12/14
STOLZ, J F Operating Reactors Branch 4 2pp 16518 005 24X
Fiche 50-312, 82/12/14, B212220241

B212270285 Forwards check to cover fees for Tech Spec waiver re addition to Amend 38 to License DPR-54
COLONBO, R W Sacramento Municipal Utility District 82/12/20
EISENHUT, D O Division of Licensing 1p 16530 318 24X
Fiche 50-312, 82/12/20, B212270285

B212290283 Forwards Amend 42 to License DPR-54, safety evaluation & notice of issuance & availability Amend changes Tech Spec refueling interval from 18 to 24 months if outage starts on or before 830228
MINER, S Operating Reactors Branch 4 82/12/20 MATTIME, J J
Sacramento Municipal Utility District 5pp 16606 249 24X
Fiche 50-312, 82/12/20, B212290283

--B212290288 Amend 42 to License DPR-54, changing Tech Specs for surveillance tests for refueling interval to 24 months provided refueling outage starts by 830228 Upon 1983 startup, definition of interval expires
STOLZ, J F Operating Reactors Branch 4 82/12/20 4pp
16606 254 24X Fiche 50-312, 82/12/20, B212290283

--B212290293 Safety evaluation supporting Amend 42 to License DPR-54
Office of Nuclear Reactor Regulation, Director 82/12/20 2pp
16606 258 24X Fiche 50-312, 82/12/20, B212290283

--B212290299 Notice of issuance & availability of Amend 42 to License DPR-54
STOLZ, J F Operating Reactors Branch 4 82/12/20 2pp
16606 260 24X Fiche 50-312, 82/12/20, B212290283

B212280233 Advises that current facility operation acceptable since reactor vessel metal irradiation Tech Specs valid for accumulated neutron fluence corresponding to 5 EPFY Tech Specs being revised to extend applicability period
MATTIME, J J Sacramento Municipal Utility District 82/12/22
STOLZ, J F Operating Reactors Branch 4 2pp 16562 266 24X
Fiche 50-312, 82/12/22, B212280233

4 Inspection reports, IE Bulletins & correspondence

B208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BHR Plants" Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, B208190240

B208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model B01 & Model B02 Thermoluminescent Dosimeters" Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000, 82/11/05, B208190245

B212060163 Forwards IE Insp Rept 50-312/82-38 on 821001-1104 & notice of violation
STERNBERG, D Division of Resident, Reactor Project & Engineering Programs 82/11/16 MATTIME, J J Sacramento Municipal Utility District 2pp 16313 101 24X Fiche 50-312, 82/11/16, B212060163

--B212060167 Notice of violation from Insp on 821001-1104
YOUNG, T Division of Resident, Reactor Project & Engineering Programs 82/11/16 1p 16313 103 24X Fiche 50-312, 82/11/16, B212060163

--B212060171 IE Insp Rept 50-312/82-38 on 821001-1104 Noncompliance noted failure to log changes in plant status rept
CAMTER, H L, O'BRIEN, J P, YOUNG, T Division of Resident, Reactor Project & Engineering Programs 82/11/15 11pp 16313 101 24X
Fiche 50-312, 82/11/16, B212060163

B208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements" Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X
Fiche 50-000, 82/11/18, B208190251

B212060024 Requests addl info within 30 days re IE Bulletin 80-11 on masonry wall design
STOLZ, J F Operating Reactors Branch 4 82/11/22 MATTIME, J J
Sacramento Municipal Utility District 4pp 16325 324 24X
Fiche 50-312, 82/11/22, B212060024

--B212060027 "Structural Engineering Branch Criteria for Safety-Related Masonry Wall Evaluation"
Operating Reactors Branch 4 81/07/31 8pp 16325 328 24X
Fiche 50-312, 82/11/22, B212060024

B212070033 Forwards order extending time within which penalties must be paid or hearing requested re Enforcement Action 82-50
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/24 MATTIME, J J Sacramento Municipal Utility District 2pp 16334 306 24X Fiche 50-312, 82/11/24, B212070033

--B212070146 Order extending time within which licensee must pay civil penalty or request hearing on Enforcement Action 82-50 until 30 days after issuance of decision on request for reconsideration
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/24 Sacramento Municipal Utility District 2pp 16334 308 24X Fiche 50-312, 82/11/24, B212070033

B208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks" Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 12pp 16411 065 24X Fiche 50-000, 82/11/26, B208190256

B212070277 Forwards addl info re diesel generator relays reset from control room for reconsideration of order imposing penalties Encl Qualification Evaluation Sys Corp rept to be attached to 821223 ltr
MATTIME, J J Sacramento Municipal Utility District 82/11/29 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 35pp 16339 075 24X Fiche 50-312, 82/11/29, B212070277

B208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl" Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000, 82/11/30, B208190257

B212070410 Submits results of steam generator insp & safety evaluation re future plant operation On 821120, 4-5 gpm primary to secondary leak identified in A steam generator Deposits in insp area region determined to enhance tube corrosion
MATTIME, J J Sacramento Municipal Utility District 82/12/01
STOLZ, J F Operating Reactors Branch 4 2pp 16336 347 24X
Fiche 50-312, 82/12/01, B212070410

B208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies" Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, B208190259

B208190261 IE Info Notice 82-48, "Failures of Agastat CR 0075 Relay Gaskets" Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X
Fiche 50-000, 82/12/03, B208190261

B212070220 Informs of results of fiberoptic insp of leaking steam generator A tube 77-2 Results do not change 821201 evaluation B&W will review insp documentation
MATTIME, J J Sacramento Municipal Utility District 82/12/03
STOLZ, J F Operating Reactors Branch 4 1p 16329 356 24X
Fiche 50-312, 82/12/03, B212070220

B212130163 Forwards IE Safeguards Insp Rept 50-312/82-39 on 821115-19 No noncompliance noted Rept withheld (ref 10CFR2 790)
NORDEHAUG, L R Division of Radiological Safety & Safeguards Program 82/12/08 MATTIME, J J Sacramento Municipal Utility District 2pp 16396 070 24X Fiche 50-312, 82/12/08, B212130163

DOCKETED ITEMS

149

8212170301 Notifies that util unable to provide response to 821103 request for addl analysis re IE Bulletin 80-04, "Main Steam Line Break W/Continued Feedwater Addition," until 830415
MATTIMOE, J J Sacramento Municipal Utility District 82/12/13
STOLZ, J F Operating Reactors Branch 4 1p 16456 128 24X
Fiche 50-312, 82/12/13, 8212170301

G/08190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16, 8208190267

G/08190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27 " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X
Fiche 50-000, 82/12/20, 8208190268

8212300350 Ack receipt of 821215 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-312/82-38
STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 82/12/23 MATTIMOE, J J Sacramento Municipal Utility District 1p 16594 229 24X Fiche 50-312, 82/12/23, 8212300350

--8212300353 Responds to NRC 821116 ltr re violations noted in IE Insp Rept 50-312/82-38 Corrective actions operators personally directed to comply w/ alarm logging requirements in Administrative Procedure 23, Revision 11
MATTIMOE, J J Sacramento Municipal Utility District 82/12/15
ENGELKEN, R H Region 5, Office of Director 2pp 16594 230 24X
Fiche 50-312, 82/12/23, 8212300350

It Periodic operating reports & related correspondence

G/12170231 Forwards monthly operating rept for Nov 1982
RODRIGUEZ, R J Sacramento Municipal Utility District 82/12/07
Director's Office, Office of Inspection and Enforcement 1p 16462 013 24X Fiche 50-312, 82/12/07, 8212170231

--8212170235 Monthly operating rept for Nov 1982
COLOMB, R Sacramento Municipal Utility District 82/12/07 6pp
16462 014 24X Fiche 50-312, 82/12/07, 8212170231

G/12200042 Forwards revised monthly operating rept for Oct 1982
RODRIGUEZ, R J Sacramento Municipal Utility District 82/12/13
Director's Office, Office of Inspection and Enforcement 1p 16474 281 24X Fiche 50-312, 82/12/13, 8212200042

- 8212200048 Revised monthly operating rept for Oct 1982
COLOMB, R Sacramento Municipal Utility District 82/11/30 1p
16474 282 24X Fiche 50-312, 82/12/13, 8212200042

G/12270283 Forwards Revision 1 to monthly operating repts for Apr & May 1982
RODRIGUEZ, R J Sacramento Municipal Utility District 82/12/15
Director's Office, Office of Inspection and Enforcement 1p 16530 161 24X Fiche 50-312, 82/12/15, 8212270283

--8212270288 Revision 1 to monthly operating rept for Apr 1982
COLOMB, R Sacramento Municipal Utility District 82/04/30 5pp
16530 162 24X Fiche 50-312, 82/12/15, 8212270283

- 8212270291 Revision 1 to monthly operating rept for May 1982
COLOMB, R Sacramento Municipal Utility District 82/05/31 5pp
16530 167 24X Fiche 50-312, 82/12/15, 8212270283

5 Reportable occurrences, LERs & related correspondence

G/12030110 Forwards LER 82-023/03L-0 Detailed event analysis submitted
MATTIMOE, J J Sacramento Municipal Utility District 82/10/06
ENGELKEN, R H Region 5, Office of Director 1p 16303 027 24X
Fiche 50-312, 82/10/06, 8212030110

8212030116 LER 82-023/03L-0 on 820909, weekly nitrogen sys surveillance showed Xe-133 activity in auxiliary bldg nitrogen header
Cause undetermined Investigation will be conducted Followup rept on cause & corrective actions will be provided
COLOMB, R W Sacramento Municipal Utility District 82/10/06
Region 5, Office of Director 1p 16303 028 24X
Fiche 50-312, 82/10/06, 8212030110

G/12030081 Forwards LER 82-027/03L-0 Detailed event analysis submitted
MATTIMOE, J J Sacramento Municipal Utility District 82/11/16
ENGELKEN, R H Region 5, Office of Director 1p 16303 206 24X
Fiche 50-312, 82/11/16, 8212030081

--8212030095 LER 82-027/03L-0 on 821012, weekly surveillance of nitrogen sys revealed presence of contamination in form of Xe-133
Cause undetermined Sys purged & activities reduced to below detectable levels Investigation underway Rept will follow
COLOMB, R W Sacramento Municipal Utility District 82/11/08
Region 5, Office of Director 1p 16303 207 24X
Fiche 50-312, 82/11/16, 8212030081

8212060294 Forwards supplemental LER 82-025/04X-1
MATTIMOE, J J Sacramento Municipal Utility District 82/11/19
ENGELKEN, R H Region 5, Office of Director 1p 16312 034 24X
Fiche 50-312, 82/11/19, 8212060294

--8212060300 Supplemental LER 82-025/04X-1 on 820918, low oxygen detected downstream in Hadselville Creek during CA Water Quality Board review Caused by impoundment for irrigation purposes
Analyst instructed to sample downstream of impoundment
COLOMB, R W Sacramento Municipal Utility District 82/10/27
Region 5, Office of Director 1p 16312 035 24X
Fiche 50-312, 82/11/19, 8212060294

G/12030062 RD 82-31 on 821120, once-through steam generator A developed 4-5 gpm leak & controlled shutdown commenced Event terminated on 821121 after reaching cold shutdown Followup rept will be provided in 14 days
RODRIGUEZ, R J Sacramento Municipal Utility District 82/11/22
ENGELKEN, R H Region 5, Office of Director 1p 16304 190 24X
Fiche 50-312, 82/11/22, 8212030062

8212030091 PND-V-82-047 on 821120, steam generator tube leak occurred in A steam generator Noble gas release less than 1% of amount allowed by Tech Specs Facility will be shut down for approx. 4 wks
JOHNSON, P Region 5, Office of Director 82/11/22 1p 16304 103 24X Fiche 50-312, 82/11/22, 8212030091

8212030084 Forwards LER 82-029/03L-0 Detailed event analysis submitted
MATTIMOE, J J Sacramento Municipal Utility District 82/11/24
ENGELKEN, R H Region 5, Office of Director 2pp 16303 203 24X
Fiche 50-312, 82/11/24, 8212030084

- 8212030106 LER 82-029/03L-0 on 821026, QA dept reported that portion of auxiliary feedwater start circuit was not being tested per requirements Caused by transposed requirements in Tech Specs Tech Specs will be amended
COLOMB, R W Sacramento Municipal Utility District 82/10/26
Region 5, Office of Director 1p 16303 205 24X
Fiche 50-312, 82/11/24, 8212030084

8212060347 PND-V-82-049 on 821127, employee fell 20 ft while setting up testing equipment on A steam generator Contamination of 200 dpm received Individual hospitalized w/ broken arm & bruises
JOHNSON, P, YOUNG, T Region 5, Office of Director 82/11/29 1p 16311 081 24X Fiche 50-312, 82/11/29, 8212060347

V Operator Examinations

G/12210439 Informs that next requalification cycle for station blackout training begins after annual operator exams scheduled to be completed by Jan 1983
MATTIMOE, J J Sacramento Municipal Utility District 82/12/19
STOLZ, J F Operating Reactors Branch 4 1p 16493 126 24X
Fiche 50-312, 82/12/15, 8212210439

BOOKER 50-313 ARKANSAS NUCLEAR ONE, UNIT 1

F Security, medical, emergency & fire protection plans

8212070425 Responds to FOIA request for documents re 820809 notice of violation & order imposing civil penalty Forwards App A documents App B documents completely withheld & Documents C1-C4 partially withheld (ref FOIA Exemptions 3, 5 & 7)
FELTON, J M Division of Rules and Records 82/11/05 MCGARRY, J H Debevoise & Liberman 5pp 16355 003 24X Fiche 50-000, 82/11/05, 8212070425

- 8212070473 Concludes that all Region 4 licensees in compliance w/ 820701 deadline for implementation of prompt notification sys
COLLINS, J T Region 4, Office of Director 82/02/01 GRIMES, B K Division of Emergency Preparedness 2pp 16355 104 24X
Fiche 50-000, 82/11/05, 8212070425

8212080074 Releases public version of revised emergency plan procedure
FELTON, J M Division of Rules and Records 82/12/01 Document Management Branch 1p 16367 185 24X Fiche 50-313, 82/12/01, 8212080074

DOCKETED ITEMS

- B212080082 Forwards public version of Revision 4 to Emergency Plan Procedure 1903 30, "Plant Evacuation " Receipt form encl
* Arkansas Power & Light Co 82/11/12 NRC - No Detailed
Affiliation Given 1p 16367 186 24X Fiche 50-313,82/12/01, 8212080074
- B212080085 Public version of Revision 4 to Emergency Plan Procedure 1903 30, "Plant Evacuation "
* Arkansas Power & Light Co 82/11/11 3pp 16367 187 24X
Fiche 50-313,82/12/01,8212080074
- B212090311 Forwards emergency operations facility (EOF) summary info, per O Vissing B21203 request & Generic Ltr 82-10 Const of permanent backup EOF completed
MARSHALL, J R Arkansas Power & Light Co 82/12/06 STOLZ, J F
Operating Reactors Branch 4 CLARK, R A Operating Reactors Branch 3 2pp 16365 127 24X Fiche 50-313,82/12/06,8212090311
- B212100380 Releases public version of revision to emergency plan implementing procedure
FELTON, J M Division of Rules and Records 82/12/07 Document
Management Branch 1p 16389 224 24X Fiche 50-313,82/12/07, 8212100380
- B212100385 Forwards public version of Revision 3 to Emergency Plan Implementing Procedure 1903 60, "Emergency Supplies & Equipment " Receipt form encl
* Arkansas Power & Light Co 82/11/29 NRC - No Detailed
Affiliation Given 1p 16389 225 24X Fiche 50-313,82/12/07, 8212100380
- B212100394 Public version of Revision 3 to Emergency Plan Implementing Procedure 1903 60, "Emergency Supplies & Equipment "
LEVINE, J M Arkansas Power & Light Co 82/11/24 75pp
16389 226 24X Fiche 50-313,82/12/07,8212100380
- B212150272 Releases public version of ack of receipt of licensee ltr transmitting amend to emergency plan
FELTON, J M Division of Rules and Records 82/12/08 Document
Management Branch 1p 16446 276 24X Fiche 50-313,82/12/08, 8212150272
- B212150280 Submits public version of ack of receipt of licensee B2082/ ltr transmitting Amend 5 to emergency plan info re compliance w/requirements of 10CFR50.54(f) re annual review & audits of emergency plan requested
SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs 82/11/24 CAVANAUGH, W Arkansas Power & Light Co 2pp 16446 278 24X Fiche 50-313,82/12/08,8212150272
- B212150288 Forwards public version of transmittal of Amend 5 to emergency plan, incorporating both State of AR & in-house comments w/o encl
MARSHALL, J R Arkansas Power & Light Co 82/08/27 COLLINS, J
Office of Nuclear Regulatory Research, Director DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 16446 280
24X Fiche 50-313,82/12/08,8212150272
- B212160542 Forwards draft safety evaluations of util requests for exemptions from fire protection of safe shutdown capability & of safe shutdown capability in event of fire Proposed mods will be reviewed in 1983 Confirmation of B2111 ltr needed
CLARK, R A Operating Reactors Branch 3 STOLZ, J F Operating Reactors Branch 4 82/12/08 CAVANAUGH, W Arkansas Power & Light Co 57pp 16447 125 24X Fiche 50-313,82/12/08,8212160542
- B212160772 Releases public version of change to Revision 3 to emergency plan implementing procedure
FELTON, J M Division of Rules and Records 82/12/10 Document
Management Branch 1p 16464 160 24X Fiche 50-313,82/12/10, 8212160772
- B212160782 Forwards public version of Permanent Change PC-1 to Revision 3 to Emergency Plan Implementing Procedure 1903 22, "Fire or Explosion " Revised index encl
LEVINE, J M Arkansas Power & Light Co 82/11/30 NRC - No Detailed
Affiliation Given 1p 16464 161 24X
Fiche 50-313,82/12/10,8212160772
- B212160787 Public version of Permanent Change PC-1 to Revision 3 to Emergency Plan Implementing Procedure 1903 22, "Fire or Explosion "
* Arkansas Power & Light Co 82/11/29 3pp 16464 162 24X
Fiche 50-313,82/12/10,8212160772
- B212170012 Releases public version of change to revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 82/12/10 Document
Management Branch 1p 16480 299 24X Fiche 50-313,82/12/10, 8212170012
- B212170018 Forwards public version of Change PC-1 to Revision 2 of Emergency Plan Implementing Procedure 1903 24, "Oil Spill Prevention Control & Countermeasure Plan "
* Arkansas Power & Light Co 82/11/30 NRC - No Detailed
Affiliation Given 1p 16480 300 24X Fiche 50-313,82/12/10, 8212170012
- B212170025 Public version of Change PC-1 to Revision 2 of Emergency Plan Implementing Procedure 1903 24, "Oil Spill Prevention Control & Countermeasure Plan " Revision index encl
* Arkansas Power & Light Co 82/11/29 3pp 16480 301 24X
Fiche 50-313,82/12/10,8212170012
- B212170445 Releases public version of changes to revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 82/12/10 Document
Management Branch 1p 16478 161 24X Fiche 50-313,82/12/10, 8212170445
- B212170448 Forwards public version of Change PC-2 to Revision 1 of Emergency Plan Implementing Procedure 1903 61, "Communications Equipment Tests "
* Arkansas Power & Light Co 82/11/30 NRC - No Detailed
Affiliation Given 1p 16478 162 24X Fiche 50-313,82/12/10, 8212170445
- B212170453 Public version of Change PC-2 to Revision 1 of Emergency Plan Implementing Procedure 1903 61, "Communications Equipment Tests "
LEVINE, J M Arkansas Power & Light Co 82/11/29 2pp
16478 163 24X Fiche 50-313,82/12/10,8212170445
- B212210508 Releases public version of Revision 2 to Emergency Plan Procedure 1903 01
FELTON, J M Division of Rules and Records 82/12/10 Document
Management Branch 1p 16502 352 24X Fiche 50-313,82/12/10, 8212210508
- B212210514 Forwards public version of Permanent Change PC-2 to Revision 2 to Emergency Plan Procedure 1903 01, "Organization & Use of Emergency Plan Implementing Procedures " Revised index encl
LEVINE, J M Arkansas Power & Light Co 82/11/30 NRC - No Detailed
Affiliation Given 1p 16502 353 24X
Fiche 50-313,82/12/10,8212210508
- B212210521 Public version of Permanent Change PC-2 to Revision 2 to Emergency Plan Procedure 1903 01, "Organization & Use of Emergency Plan Implementing Procedures "
* Arkansas Power & Light Co 82/11/19 1p 16502 354 24X
Fiche 50-313,82/12/10,8212210508
- B212220001 Releases public version of revised emergency plan procedure
FELTON, J M Division of Rules and Records 82/12/10 Document
Management Branch 1p 16529 152 24X Fiche 50-313,82/12/10, 8212220001
- B212220002 Forwards public version of Change PC-3 to Revision 4 of Emergency Plan Procedure 1903 43, "Duties of Emergency Radiation Team " Revised index encl
* Arkansas Power & Light Co 82/11/30 NRC - No Detailed
Affiliation Given 1p 16529 153 24X Fiche 50-313,82/12/10, 8212220001
- B212220004 Public version of Change PC-3 to Revision 4 of Emergency Plan Procedure 1903 43, "Duties of Emergency Radiation Team "
* Arkansas Power & Light Co 82/11/19 3pp 16529 154 24X
Fiche 50-313,82/12/10,8212220001
- B212280224 Discusses util B20701 response documenting results of review of fire zones for compliance w/10CFR50.48 & App R Alternate shutdown capability would be provided by cross-feed between Units 1 & 2 Special entry for 9 valves will not be made
MARSHALL, J R Arkansas Power & Light Co 82/12/10 EISENHUI, D O
Division of Licensing 1p 16562 176 24X Fiche 50-313,82/12/10, 8212280224
- B212210526 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 82/12/13 Document
Management Branch 1p 16502 316 24X Fiche 50-313,82/12/13, 8212210526
- B212210534 Forwards public version of revised emergency plan implementing procedures, including Procedures 1903 31 re exclusion area evacuation & 1904 03 re auxiliary bldg ventilation exhaust emergency radiation monitor
* Arkansas Power & Light Co 82/12/06 NRC - No Detailed
Affiliation Given 4pp 16502 317 24X Fiche 50-313,82/12/13, 8212210526

--G212210539 Public version of revised emergency plan implementing procedures, including Procedures 1903 31 re exclusion area evacuation & 1904 03 re auxiliary bldg ventilation exhaust emergency radiation monitor
LEVINE, J M Arkansas Power & Light Co 82/12/03 23pp
16502 321 24X Fiche 50-313, 82/12/13, 8212210526

G212230152 Releases public version of revised nuclear contingency plan procedure
FELTON, J M Division of Rules and Records 82/12/15 Document
Management Branch 1p 16543 279 24X Fiche 50-313, 82/12/15,
8212230152

--8212230165 Forwards public version of Revision 1 to Nuclear Contingency Plan Procedure 9, "Emergency Response Support"
MARSHALL, J R Arkansas Power & Light Co 82/12/10 COLLINS, J T
Region 4, Office of Director EISENHUT, D G Division of
Licensing 1p 16543 280 24X Fiche 50-313, 82/12/15, 8212230162

--G212230172 Public version of Revision 1 to Nuclear Contingency Plan Procedure 9, "Emergency Response Support"
* Arkansas Power & Light Co 82/11/15 86pp 16543 282 24X
Fiche 50-313, 82/12/15, 8212230152

P Operating license stage documents & correspondence

G212060492 INTERIM RELIABILITY EVALUATION PROGRAM ANALYSIS OF THE ARKANSAS NUCLEAR ONE-UNIT 1 NUCLEAR POWER PLANT Appendices
A-D Docket No. 50-313 (Arkansas Power and Light Company)
KOLB, G J Sandia Laboratories NUREG/CR-2787 V02 82/10/31
Division of Risk Analysis 109pp 16348 294 24X
Fiche 50-313, 82/10/31, 8212060492

G212030169 Forwards info re NUREG-0737, Item II B 3, "Post-Accident Sampling Sys," in response to NRC 820701 request Grab sample sys utilized as backup to online sampling sys
MARSHALL, J R Arkansas Power & Light Co 82/11/24 CLARK, R A
Operating Reactors Branch 3 STOLZ, J F Operating Reactors Branch 4
12pp 16306 254 24X Fiche 50-313, 82/11/24, 8212030169

G212060262 Requests extension until 830228 to respond to NRC 820721 request for Tech Spec revision re snubber surveillance
Extension needed to review implications of ANSI/ASME
UM-1982
MARSHALL, J R Arkansas Power & Light Co 82/11/26 STOLZ, J F
Operating Reactors Branch 4 CLARK, R A Operating Reactors Branch 3
2pp 16312 272 24X Fiche 50-313, 82/11/26, 8212060262

G212060333 Requests extension to 830228 for submittal of App I revisions
MARSHALL, J R Arkansas Power & Light Co 82/11/30 STOLZ, J F
Operating Reactors Branch 4 CLARK, R A Operating Reactors Branch 3
2pp 16312 190 24X Fiche 50-313, 82/11/30, 8212060333

G212070284 Forwards summary of analysis of pressurizer safety & relief valve discharge piping as required by NUREG-0737, Item II D 3 Piping stresses & support loads do not meet code, however, piping & valves will remain operable
MARSHALL, J R Arkansas Power & Light Co 82/11/30 STOLZ, J F
Operating Reactors Branch 4 CLARK, R A Operating Reactors Branch 3
4pp 16343 195 24X Fiche 50-313, 82/11/30, 8212070284

G212100113 Forwards SER on NUREG-0737, Item II A 2 1, "Upgraded Reactor Operator & Senior Reactor Operator Training" & Item II B 4, "Training for Mitigating Core Damage" Items resolved
STOLZ, J F Operating Reactors Branch 4 CLARK, R A Operating Reactors Branch 3
82/12/01 CAVANAUGH, W Arkansas Power & Light Co 8pp 16543 221 24X Fiche 50-313, 82/12/01, 8212100113

G212100110 Discusses util request for changes to Tech Specs re steam line break instrumentation & control sys setpoints Schedule for resolving listed concerns requested within 10 days of receipt of ltr
STOLZ, J F Operating Reactors Branch 4 82/12/06 CAVANAUGH, W
Arkansas Power & Light Co 2pp 16502 361 24X
Fiche 50-313, 82/12/06, 8212100110

G212100488 Requests confirmation on failures re core flood tanks Submittal on NUREG-0737, Item II K 3 17, "ECCS Outages," did not specifically identify failures
STOLZ, J F Operating Reactors Branch 4 82/12/08 CAVANAUGH, W
Arkansas Power & Light Co 2pp 16389 056 24X
Fiche 50-313, 82/12/08, 8212100488

G208190263 Generic Ltr 82-32 to all PWR licensees re potential steam generator-related generic requirements Forwards Science Applications, Inc draft rept re subj requirements Comments requested within 30 days of ltr Svc list encl
EISENHUT, D G Division of Licensing 82/12/09 Consolidated
Edison Co of New York, Inc 29pp 16629 247 24X
Fiche 50-000, 82/12/09, 8208190263

G212170113 Responds to NRC 821109 ltr re NUREG/CR-2787, "Interim Reliability Evaluation Program Analysis of AR Nuclear One Unit 1" Addl mods to facility design or operation beyond mods underway not required
MARSHALL, J R Arkansas Power & Light Co 82/12/09 STOLZ, J F
Operating Reactors Branch 4 2pp 16450 303 24X
Fiche 50-313, 82/12/09, 8212170113

G212270421 Forwards order for mod of licenses, requiring installation of inadequate core cooling instrumentation sys conforming w/ NUREG-0737, Item II F 2
EISENHUT, D G Division of Licensing 82/12/10 CAVANAUGH, W
Arkansas Power & Light Co 2pp 16572 330 24X
Fiche 50-313, 82/12/10, 8212270421

--8212270427 Order for mod of licenses requiring installation of inadequate core cooling instrumentation sys conforming w/ NUREG-0737, Item II F 2 Checklist for review of sys encl
EISENHUT, D G Division of Licensing 82/12/10 Arkansas Power & Light Co 11pp 16572 332 24X Fiche 50-313, 82/12/10, 8212270421

G212290022 Responds to 821130 ltr requesting extension of response date re App I submittal to 830228 Delay acceptable
CLARK, R A Operating Reactors Branch 3 STOLZ, J F Operating Reactors Branch 4 82/12/14 CAVANAUGH, W Arkansas Power & Light Co 2pp 16607 181 24X Fiche 50-313, 82/12/14, 8212290022

G212220515 Requests remittance of addl sum for 821105 application for spent fuel pool expansion
HILLER, W D License Fee Management Branch 82/12/15 CAVANAUGH, W
Arkansas Power & Light Co 2pp 16523 027 24X
Fiche 50-313, 82/12/15, 8212220515

G212280307 Application for amend to License DPR-51, proposing change to Tech Spec 4 1B re steam generator tubing surveillance to assure that known problem areas are adequately inspected
Class III amend fee encl
ORIFFIN, J M Arkansas Power & Light Co 82/12/17 STOLZ, J F
Operating Reactors Branch 4 4pp 16561 086 24X
Fiche 50-313, 82/12/17, 8212280307

--8212280309 Proposed Tech Spec 4 1B re steam generator tubing surveillance
* Arkansas Power & Light Co 82/12/17 5pp 16561 090 24X
Fiche 50-313, 82/12/17, 8212280307

G Inspection reports, IE Bulletins & correspondence

G208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants" Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc
112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240

G208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model B01 & Model B02 Thermoluminescent Dosimeters" Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards
82/11/05 Consolidated Edison Co of New York, Inc 110pp
16372 142 24X Fiche 50-000, 82/11/05, 8208190245

G21210245 Forwards IE Insp Repts 50-313/82-21 & 50-368/82-18 on 820802-06 No noncompliance noted
SEIDLE, W C Division of Resident Reactor Project & Engineering Programs 82/11/05 CAVANAUGH, W Arkansas Power & Light Co 2pp 16463 317 24X Fiche 50-313, 82/11/05, 821210245

- 8212210250 IE Insp Repts 50-313/82-21 & 50-368/82-18 on 820802-06 No noncompliance noted Major areas inspected licensee action on previous insp findings, procedures review qualification & exposure control
BAER, R, WILBORN, L, HOLLEY, W Division of Resident Reactor Project & Engineering Programs 82/10/28 27pp 16483 319 24X
Fiche 50-313, 82/11/05, 8212210245

G212140481 Forwards addl info re IE Bulletin 82-02, clarifying 820729 commitments Results of mail review to determine number of leaks on bolted closures listed
MARSHALL, J R Arkansas Power & Light Co 82/11/08 COLLINS, J T
Region 4, Office of Director 5pp 16403 335 24X
Fiche 50-313, 82/11/08, 8212140481

G208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements" Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 107pp 16411 197 24X
Fiche 50-000, 82/11/18, 8208190251

DOCKETED ITEMS

8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000, 82/11/26, 8208190256

8208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000, 82/11/30, 8208190257

8212060087 Forwards response to NRC 820914 request for addl info re inservice insp of reactor coolant pump flywheels Util 820818 ltr requested acoustic emission insp as alternative to ultrasonic testing method
MARSHALL, J R Arkansas Power & Light Co 82/11/30 STOLZ, J F Operating Reactors Branch 4 13pp 16316 108 24X Fiche 50-313, 82/11/30, 8212060087

8208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259

8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X Fiche 50-000, 82/12/03, 8208190261

8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16, 8208190267

8212280307 Application for amend to License DPR-51, proposing change to Tech Spec 4.18 re steam generator tubing surveillance to assure that known problem areas are adequately inspected
Class III amend fee encl
GRIFFIN, J H Arkansas Power & Light Co 82/12/17 STOLZ, J F Operating Reactors Branch 4 4pp 16561 086 24X Fiche 50-313, 82/12/17, 8212280307

--8212280309 Proposed Tech Spec 4.18 re steam generator tubing surveillance
* Arkansas Power & Light Co 82/12/17, 5pp 16561 090 24X Fiche 50-313, 82/12/17, 8212280309

8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITC-27 " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X Fiche 50-000, 82/12/20, 8208190268

8212290192 Ack receipt of 821105 ltr informing NRC of steps taken to correct deviation noted in IE Insp Repts 50-313/82-19 & 50-368/82-16
SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs 82/12/23 CAVANAUGH, W Arkansas Power & Light Co 1p 16578 132 24X Fiche 50-313, 82/12/23, 8212290192

--8212290198 Responds to NRC 821007 ltr re deviation noted in IE Insp Repts 50-313/82-19 & 50-368/82-16 Corrective actions environ qualification info submitted in 820729 & 0813 ltrs
Commitment tracking sys implemented
MARSHALL, J R Arkansas Power & Light Co 82/11/05 SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs 12pp 16578 133 24X Fiche 50-313, 82/12/23, 8212290192

R Periodic operating reports & related correspondence

8212290168 Forwards suppl to "Annual Environ Monitoring Rept, 1981 "
MARSHALL, J R Arkansas Power & Light Co 82/11/12 COLLINS, J T Region 4, Office of Director 1p 16582 181 24X Fiche 50-313, 82/11/12, 8212290168

--8212290171 Suppl to "Annual Environ Monitoring Rept, 1981 "
* Arkansas Power & Light Co 82/11/12 15pp 16582 182 24X Fiche 50-313, 82/11/12, 8212290168

8212290194 Forwards monthly operating rept for Oct 1982
MARSHALL, J R Arkansas Power & Light Co 82/11/15 HALLER, N M Management Information Branch 1p 16578 140 24X Fiche 50-313, 82/11/15, 8212290194

--8212290196 Monthly operating rept for Oct 1982
CERTSCH, A J Arkansas Power & Light Co 82/11/15 3pp, 16578 141 24X Fiche 50-313, 82/11/15, 8212290194

S Reportable occurrences, LERs & related correspondence

8212030077 Advises that historical documentation re LER 82-018/03L-0 on 821119, concerning fire barrier penetrations, difficult to retrieve Info will be provided by 821220
MARSHALL, J R Arkansas Power & Light Co 82/11/19 SEIDLE, W C Region 4, Office of Director 1p 16304 110 24X Fiche 50-313, 82/11/19, 8212030077

8212100254 PND-IV-82-044 on 821203, normal phone communication lost due to local flooding caused by heavy rains & severe weather
Backup radio communications feasible from elevated ground northwest of Little Rock Addl heavy rain possible
SEIDLE, W C, GAOLLIARD, J E Region 4, Office of Director 82/12/03 2pp 16376 127 24X Fiche 50-313, 82/12/03, 8212100254

821210166 Forwards LER 82-024/03L-0
MARSHALL, J R Arkansas Power & Light Co 82/12/06 SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs 1p 16483 017 24X Fiche 50-313, 82/12/06, 821210166

--821210169 LER 82-024/03L-0 on 821104, at 68% power, control rod drive B ac breaker failed to trip Caused by latch adjusting screw being improperly adjusted Breaker replaced
MARSHALL, J R Arkansas Power & Light Co 82/12/06 Region 4, Office of Director 1p 16483 018 24X Fiche 50-313, 82/12/06, 821210166

8212270143 LER 82-030/01T-0 on 821214, five tubes in once-through steam generator B found w/greater than or equal to 40% through-wall indications during expanded testing program Further info will be provided in followup rept
LEVINE, J H Arkansas Power & Light Co 82/12/13 COLLINS, J T Region 4, Office of Director 2pp 16538 338 24X Fiche 50-313, 82/12/13, 8212270143

8212290486 LER 82-031/01T-0 plugs found installed in two reactor bldg transmitter sensing input ports, rendering input to engineered safety actuation sys analog channel outside Tech Spec limit Cause not stated
LEVINE, J H Arkansas Power & Light Co 82/12/16 COLLINS, J T Region 4, Office of Director 2pp 16583 263 24X Fiche 50-313, 82/12/16, 8212290486

8212280345 PND-IV-82-049 ports on two transmitters found blocked w/brass pipe plugs Transmitter provided signal to one of three safety channels Licenses conducting investigation
JOHNSON, W D, CALLAN, L J Region 4, Office of Director 82/12/20 1p 16561 031 24X Fiche 50-313, 82/12/20, 8212280345

8212290321 Responds to 821018 ltr requesting addl info re fire barrier penetration seals per LER 82-018/03L-0 All penetrations & conduits properly sealed
MARSHALL, J R Arkansas Power & Light Co 82/12/20 SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs 3pp 16589 134 24X Fiche 50-313, 82/12/20, 8212290321

8212290210 PND-IV-82-050 while in refueling outage, special insp found cracked thermal shield bolts During replacement of bolts, bolt heads found separated from bolts Bolts to be replaced w/acceptable fasteners
JOHNSON, W D, CALLAN, L J Region 4, Office of Director 82/12/21 1p 16578 201 24X Fiche 50-313, 82/12/21, 8212290210

DOCKET 50-315 DONALD C COOK NUCLEAR POWER PLANT, UNIT 1

F Security, medical, emergency & fire protection plans

8212060009 Forwards IE Emergency Preparedness Insp Repts 50-315/82-18 & 50-316/82-18 on 821020-22 Discussion of excessive weaknesses encl
HIND, J A Division of Emergency Preparedness & Operational Support 82/11/15 DOLAN, J E American Electric Power Service Corp
DOLAN, J E Indiana & Michigan Electric Co 3pp 16313, 336 24X Fiche 50-315, 82/11/15, 8212060009

--8212060017 IE Emergency Preparedness Insp Repts 50-315/82-18 & 50-316/82-18 on 821020-22 No noncompliance noted Major areas inspected emergency preparedness exercise involving observation of key functions & locations
FLOSKIT, J, SMITH, M J, AXELSON, W L Division of Emergency Preparedness & Operational Support 82/11/10 32pp 16313 339 24X Fiche 50-315, 82/11/15, 8212060009

8212010033 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 82/11/24 Document Management Branch 1p 16289 106 24X Fiche 50-315, 82/11/24, 8212010033

--B212010037 Forwards public version of revised emergency plan implementing procedures, including Procedures PMP 2080 EPP 011 re natural emergency guidelines & PMP 2082 EPP 009 re maint of emergency plan procedures Receipt form encl
* Indiana & Michigan Electric Co 82/11/16 GRIMES, B NRC - No
Detailed Affiliation Given 1p 16289 107 24X
Fiche 50-315, 82/11/24, 8212010033

--B212010039 Public version of revised emergency plan implementing procedures, including Procedures PMP 2080 EPP 011 re natural emergency guidelines & PMP 2082 EPP 009 re maint of emergency plan procedures
* Indiana & Michigan Electric Co 82/11/16 23pp 16289 108
24X Fiche 50-315, 82/11/24, 8212010033

B212080089 Releases public version of revised pages to emergency plan procedures index
FELTON, J M Division of Rules and Records 82/12/02 Document
Management Branch 1p 16367 190 24X Fiche 50-315, 82/12/02,
8212080089

--B212080091 Forwards public version of revised Pages 6-13 to emergency plan procedures index re list of exhibits Receipt form encl
* Indiana & Michigan Electric Co 82/11/23 GRIMES, B NRC - No
Detailed Affiliation Given 1p 16367 191 24X
Fiche 50-315, 82/12/02, 8212080089

--B212080096 Public version of revised Pages 6-13 to emergency plan procedures index re list of exhibits
* Indiana & Michigan Electric Co 82/11/23 8pp 16367 192
24X Fiche 50-315, 82/12/02, 8212080089

B212150323 Releases public version of revision to emergency plan implementing procedures
FELTON, J M Division of Rules and Records 82/12/07 Document
Management Branch 1p 16446 219 24X Fiche 50-315, 82/12/07,
8212150323

--B212150329 Forwards public version of Revision 1 to Emergency Plan Implementing Procedure PMP 2080 EPP 014, "Personnel Injury" & Revision 1 to PMP 2081 EPP 008, "Emergency Medical Plan Guidelines" Receipt form encl
* Indiana & Michigan Electric Co 82/12/01 GRIMES, B NRC - No
Detailed Affiliation Given 1p 16446 220 24X
Fiche 50-315, 82/12/01, 8212150323

--B212150335 Public version of Revision 1 to Emergency Plan Implementing Procedure PMP 2080 EPP 014, "Personnel Injury" & Revision 1 to PMP 2081 EPP 008, "Emergency Medical Plan Guidelines"
* Indiana & Michigan Electric Co 82/12/01 12pp 16446 222
24X Fiche 50-315, 82/12/07, 8212150323

B212160001 Forwards proposed Tech Spec Page 6-11 for performing audits of emergency preparedness programs & safeguards contingency plans (security plan), in response to Generic Ltrs 82-17 & 82-23
HUNTER, R S Indiana & Michigan Electric Co 82/12/09 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 16446 141
24X Fiche 50-315, 82/12/09, 8212160001

--B212160002 Proposed Tech Spec Page 6-11 for performing audits of emergency preparedness programs & safeguards contingency plans (security plan)
* Indiana & Michigan Electric Co 82/12/09 3pp 16446 143
24X Fiche 50-315, 82/12/09, 8212160001

B212220306 Discusses layout of communications equipment required in control room, onsite technical support ctr & near-site emergency operations facility
KEPPLER, J G Region 3, Office of Director 82/12/16
Commonwealth Edison Co 3pp 16503 391 24X Fiche 50-000, 82/12/16,
8212220306

J Insurance & indemnity information

B212100253 Forwards Endorsement 41 to MAELU Policy NF-79, Endorsement 51 to NELIA Policy NF-206 & Endorsements 10 & 9 to NELIA Winders EB-64 & EB-45, respectively
ALEXICH, M P American Electric Power Service Corp 82/12/07
DENTON, H R Office of Nuclear Reactor Regulation, Director 8pp
16376 117 24X Fiche 50-315, 82/12/07, 8212100253

B212290213 Forwards Endorsements 55 to NELIA Policy NF-206/45 to MAELU Policy NF-79/1, 2, 3 & 4 to NELIA Policy N-64/1, 2, 3 & 4 to MAELU Policy M-64/1, 2, 3 & 4 to NELIA Policy M-45 & 1, 2, 3 & 4 to MAELU Policy M-45
BUCKLES, J Marsh & McLennan, Inc, M & H Nuclear Consultants, Inc
Div 82/12/22 SALTZMAN, J Assistant Director for State & Licensee
Relations 43pp 16978 089 24X Fiche 50-315, 82/12/22, 8212290213

P Operating license stage documents & correspondence

B212020002 Notification of 821202 meeting w/util & Exxon in Bethesda, MD to discuss outstanding questions on Exxon analysis method for Cycle 4 reload
WIGGINTON, D Operating Reactors Branch 1 82/11/24 VARQA, S A
Operating Reactors Branch 1 2pp 16317 063 24X
Fiche 50-315, 82/11/24, 8212020002

B212030125 Follows up 821014 ltr re emergency request for relief from Tech Spec 3.5.2 on safety injection pump operability requirements Repairs to south safety injection pump completed & pump returned to operable status on 821016
HUNTER, R S Indiana & Michigan Electric Co 82/11/29 DENTON, H R
Office of Nuclear Reactor Regulation, Director 4pp 16303 318
24X Fiche 50-315, 82/11/29, 8212030125

--B212030145 Application to amend License DPR-58, requesting relief from Tech Spec 3.5.2 to allow addl 10 days to restore south safety injection pump to operable status Safety evaluation encl Class III amend fee forthcoming
HUNTER, R S Indiana & Michigan Electric Co 82/10/14
DENTON, H R Office of Nuclear Reactor Regulation, Director
VARQA, S A Operating Reactors Branch 1 4pp 16303 322 24X
Fiche 50-315, 82/11/29, 8212030125

B212060072 Forwards completed questionnaire in response to Generic Ltr 82-22 re steam generator tube integrity
HUNTER, R S Indiana & Michigan Electric Co 82/11/29 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 16314 318
24X Fiche 50-315, 82/11/29, 8212060072

B212090296 Forwards Phase II b response to Encl 3, Section 2.4 of DO Eisenhut 801222 ltr re overhead handling sys operation for control of heavy loads, per NUREG-0612 Two aperture cards available in PDR
HUNTER, R S Indiana & Michigan Electric Co 82/12/03 DENTON, H R
Office of Nuclear Reactor Regulation, Director 16pp 16365 190
24X Fiche 50-315, 82/12/03, 8212090296

B212100290 Forwards revised inservice test program for safety-related pumps Tech Spec change request reflecting revisions will be provided under separate cover
HUNTER, R S Indiana & Michigan Electric Co 82/12/04 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 16377 082
24X Fiche 50-315, 82/12/04, 8212100290

--B212100300 Revision 1 to pump inservice test program
* Indiana & Michigan Electric Co 82/11/30 3pp 16377 084
24X Fiche 50-315, 82/12/06, 8212100290

B212210125 Forwards update on activities re NUREG-0737, Items II D 3, "Post-Accident Sampling," II F 1, "Noble Gas Monitoring" & III D 3.4, "Control Room Habitability" Info supersedes previous correspondence on topics
HUNTER, R S Indiana & Michigan Electric Co 82/12/14 DENTON, H R
Office of Nuclear Reactor Regulation, Director 4pp 16485 130
24X Fiche 50-315, 82/12/14, 8212210125

B212270136 Forwards description of coding errors recently discovered in CLABIX computer program Errors associated only w/modeling of flame propagation between containment compartments Coding errors do not affect previously transmitted analyses
HUNTER, R S Indiana & Michigan Electric Co 82/12/17 DENTON, H R
Office of Nuclear Reactor Regulation, Director 4pp 16538 137
24X Fiche 50-315, 82/12/17, 8212270136

Q Inspection reports, IE Bulletins & correspondence

B2108190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Bypass Piping at BWR Plants" Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc
112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240

B2108190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters" Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp
16372 142 24X Fiche 50-000, 82/11/05, 8208190245

B212060009 Forwards IE Emergency Preparedness Insp Repts 50-315/82-18 & 50-316/82-18 on 821020-22 Discussion of excessive weaknesses encl
HIND, J A Division of Emergency Preparedness & Operational Support 82/11/15 DOLAN, J E American Electric Power Service Corp
DOLAN, J E Indiana & Michigan Electric Co 3pp 16313 336 24X
Fiche 50-315, 82/11/15, 8212060009

DOCKETED ITEMS

--B212060017 IE Emergency Preparedness Insp Repts 50-315/82-18 & 50-316/82-18 on 821020-22 No noncompliance noted Major areas inspected emergency preparedness exercise involving observation of key functions & locations
PLOSKE, T J, SMITH, M J, AXELSON, H L Division of Emergency Preparedness & Operational Support 82/11/10 32pp 16313 339
24X Fiche 50-315, 82/11/15, 8212060009

B208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X Fiche 50-000, 82/11/18, 8208190251

B208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000, 82/11/26, 8208190256

B208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000, 82/11/30, 8208190257

B208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259

B208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X Fiche 50-000, 82/12/03, 8208190261

B212280242 Forwards IE Insp Repts 50-315/82-15 & 50-316/82-15 on 820901-0915 & notice of violation (Insp date changes noted throughout rept)
SPESSARD, R L Division of Project & Resident Programs 82/12/10 DOLAN, J E American Electric Power Service Corp DOLAN, J E Indiana & Michigan Electric Co 2pp 16561 184 24X Fiche 50-315, 82/12/10, 8212280242

--B212280246 Notice of violation from insp on 820901-0914
SPESSARD, R L Division of Project & Resident Programs 82/12/10 2pp 16561 186 24X Fiche 50-315, 82/12/10, 8212280246

--B212280251 IE Insp Repts 50-315/82-15 & 50-316/82-15 on 820901-0915 Noncompliance noted failure to remove addl charging pump & safety injection pump circuit breakers from electrical power circuit within 1-h
SHANSON, E R, DUBRY, N E, WILLIAMS, D Division of Project & Resident Programs 82/12/03 17pp 16561 188 24X Fiche 50-315, 82/12/10, 8212280242

B212290330 Forwards IE Insp Repts 50-315/82-19 & 50-316/82-19 on 820916-1031 & notice of violation
SPESSARD, R L Division of Project & Resident Programs 82/12/15 DOLAN, J E American Electric Power Service Corp DOLAN, J E Indiana & Michigan Electric Co 2pp 16586 189 24X Fiche 50-315, 82/12/15, 8212290330

--B212290331 Notice of violation from insp on 820916-1031
SPESSARD, R L Division of Project & Resident Programs 82/12/15 2pp 16586 190 24X Fiche 50-315, 82/12/15, 8212290330

--B212290335 IE Insp Repts 50-315/82-19 & 50-316/82-19 on 820916-1031 Noncompliance noted failure to comply w/action requirement & failure to follow clearance permit sys procedure
SHANSON, E R, DUBRY, N E, BOYD, O C Division of Project & Resident Programs 82/12/15 11pp 16586 192 24X Fiche 50-315, 82/12/15, 8212290330

B208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16, 8208190267

B208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27 " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X Fiche 50-000, 82/12/20, 8208190268

B212280165 Forwards addl info re inservice insp wold program Revised pages to Table 1, Class 2 components & welds & to Table 2 for components & welds for which relief requested encl
HERING, R F Indiana & Michigan Electric Co 82/12/20 DENTON, H R Office of Nuclear Reactor Regulation, Director 43pp 16563 335 24X Fiche 50-315, 82/12/20, 8212280165

R Periodic operating reports & related correspondence

B212290419 Forwards monthly operating rept for Oct 1982 & revised repts for Aug & Sept 1982
SMITH, W O Indiana & Michigan Electric Co 82/11/12 Office of Resource Management, Director 1p 16584 317 24X Fiche 50-315, 82/11/12, 8212290419

--B212290424 Monthly operating rept for Oct 1982
GILLET, W T Indiana & Michigan Electric Co 82/11/02 6pp 16584 318 24X Fiche 50-315, 82/11/12, 8212290419

--B212290428 Revised monthly operating rept for Aug 1982
GILLET, W T Indiana & Michigan Electric Co 82/09/07 1p 16526 326 24X Fiche 50-315, 82/11/12, 8212290419

--B212290434 Revised monthly operating rept for Sept 1982
TETZLAFF, A L Indiana & Michigan Electric Co 82/10/04 1p 16584 327 24X Fiche 50-315, 82/11/12, 8212290419

B212200119 Forwards monthly operating rept for Nov 1982
SMITH, W O Indiana & Michigan Electric Co 82/12/14 Office of Resource Management, Director 1p 16470 176 24X Fiche 50-315, 82/12/14, 8212200119

--B212200122 Monthly operating rept for Nov 1982
GILLET, W T, MIGHT, A, SVENSSON, B A Indiana & Michigan Electric Co 82/12/02 6pp 16470 177 24X Fiche 50-315, 82/12/14, 8212200119

S Reportable occurrences, LERs & related correspondence

B212020283 Forwards LER 82-099/03L-0
SMITH, W O Indiana & Michigan Electric Co 82/11/23 KEPLER, J O Region 3, Office of Director 1p 16288 251 24X Fiche 50-315, 82/11/23, 8212020283

--B212020289 LER 82-099/03L-0 on 821025, during Mode 1, Channel 2 lower containment pressure indication (PPP-320) found reading approx 1/2 lb higher than other channels Caused by water collecting in transmitter junction box causing corrosion
PALMER, R A Indiana & Michigan Electric Co 82/11/23 Region 3, Office of Director 1p 16288 252 24X Fiche 50-315, 82/11/23, 8212020283

B212060031 RO on 821123, essential svc water sys motor operated valve WMD-753 failed to open Caused by reverse operation or valve due to incorrect installation of cable feeding motor control ctr during 821117 design change
SMITH, W O Indiana & Michigan Electric Co 82/11/24 KEPLER, J O Region 3, Office of Director 2pp 16313 271 24X Fiche 50-315, 82/11/24, 8212060031

B212100251 Forwards LER 82-101/01T-0
SMITH, W O Indiana & Michigan Electric Co 82/12/03 KEPLER, J O Region 3, Office of Director 1p 16376 046 24X Fiche 50-315, 82/12/03, 8212100251

--B212100259 LER 82-101/01T-0 on 821123, motor operated valve WMD-753 to west turbine driven auxiliary feed pump would not open Caused by motor damage to WMD-753 & exhaust fan 1HV-AFP-T2 for pump room operating in reverse
PALMER, R A Indiana & Michigan Electric Co 82/12/03 Region 3, Office of Director 2pp 16376 047 24X Fiche 50-315, 82/12/03, 8212100251

B212100322 Forwards LER 82-100/03L-0
SMITH, W O Indiana & Michigan Electric Co 82/12/03 KEPLER, J O Region 3, Office of Director 1p 16377 064 24X Fiche 50-315, 82/12/03, 8212100322

--B212100327 LER 82-100/03L-0 on 821105, during normal operation, fire door 437 found inoperable Caused by door scraping on stair step Clearance between door & step improved
PIEHL, R H Indiana & Michigan Electric Co 82/12/03 Region 3, Office of Director 1p 16377 065 24X Fiche 50-315, 82/12/03, 8212100322

B212170283 Forwards LERs 82-102/03L-0 & 82-103/03L-0
SMITH, W O Indiana & Michigan Electric Co 82/12/08 KEPLER, J O Region 3, Office of Director 1p 16458 049 24X Fiche 50-315, 82/12/08, 8212170283

--8212170292 LER 82-102/03L-0 on 821118, Pryralarm fire detector in auxiliary bldg Zone 2 alarmed Caused by low setpoint Detector assembly cleaned, verified & returned to svc Setpoint adjusted
PALMER, R A Indiana & Michigan Electric Co 82/12/08 Region 3, Office of Director 1p 1645B 050 24X Fiche 50-315, 82/12/08, 8212170283

--8212170296 LER 82-103/03L-0 on 821127, fire door 387 at entrance to quadrant 2 of auxiliary bldg around containment found in nonconservative configuration Caused by active leaf of double doors closing before inactive leaf
WITNER, D G Indiana & Michigan Electric Co 82/12/08 Region 3, Office of Director 1p 1645B 051 24X Fiche 50-315, 82/12/08, 8212170283

DOCKET 50-316 DONALD C COOK NUCLEAR POWER PLANT, UNIT 2

F Security, medical, emergency & fire protection plans

8212060009 Forwards IE Emergency Preparedness Insp Repts 50-315/82-18 & 50-316/82-18 on 821020-22 Discussion of excessive weaknesses encl
HIND, J A Division of Emergency Preparedness & Operational Support 82/11/15 DDLAN, J E American Electric Power Service Corp 3pp 16313 336 24X Fiche 50-315, 82/11/15, 8212060009

--8212060017 IE Emergency Preparedness Insp Repts 50-315/82-18 & 50-316/82-18 on 821020-22 No noncompliance noted Major areas inspected emergency preparedness exercise involving observation of key functions & locations
PLOSKE, T J Division of Emergency Preparedness & Operational Support 82/11/10 32pp 16313 339 24X Fiche 50-315, 82/11/15, 8212060009

8212010033 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 82/11/24 Document Management Branch 1p 16289 106 24X Fiche 50-315, 82/11/24, 8212010033

- 8212010037 Forwards public version of revised emergency plan implementing procedures, including Procedures PHP 2080 EPP 011 re natural emergency guidelines & PHP 2082 EPP 009 re maint of emergency plan procedures Receipt form encl
* Indiana & Michigan Electric Co 82/11/16 GRIMES, B NRC - No Detailed Affiliation Given 1p 16289 107 24X Fiche 50-315, 82/11/24, 8212010033

--8212010039 Public version of revised emergency plan implementing procedures, including Procedures PHP 2080 EPP 011 re natural emergency guidelines & PHP 2082 EPP 009 re maint of emergency plan procedures
* Indiana & Michigan Electric Co 82/11/16 23pp 16289 108 24X Fiche 50-315, 82/11/24, 8212010033

8212080089 Releases public version of revised pages to emergency plan procedures index
FELTON, J M Division of Rules and Records 82/12/02 Document Management Branch 1p 16367 190 24X Fiche 50-315, 82/12/02, 8212080089

--8212080091 Forwards public version of revised Pages 6-13 to emergency plan procedures index re list of exhibits Receipt form encl
* Indiana & Michigan Electric Co 82/11/23 GRIMES, B NRC - No Detailed Affiliation Given 1p 16367 191 24X Fiche 50-315, 82/12/02, 8212080089

--8212080096 Public version of revised Pages 6-13 to emergency plan procedures index re list of exhibits
* Indiana & Michigan Electric Co 82/11/23 8pp 16367 192 24X Fiche 50-315, 82/12/02, 8212080089

8212150323 Releases public version of revision to emergency plan implementing procedures
FELTON, J M Division of Rules and Records 82/12/07 Document Management Branch 1p 16446 219 24X Fiche 50-315, 82/12/07, 8212150323

--8212150329 Forwards public version of Revision 1 to Emergency Plan Implementing Procedure PHP 2080 EPP 014, "Personnel Injury" & Revision 1 to PHP 2081 EPP 008, "Emergency Medical Plan Guidelines" Receipt form encl
* Indiana & Michigan Electric Co 82/12/01 GRIMES, B NRC - No Detailed Affiliation Given 1p 16446 220 24X Fiche 50-315, 82/12/07, 8212150323

--8212150335 Public version of Revision 1 to Emergency Plan Implementing Procedure PHP 2080 EPP 014, "Personnel Injury" & Revision 1 to PHP 2081 EPP 008, "Emergency Medical Plan Guidelines"
* Indiana & Michigan Electric Co 82/12/01 12pp 16446 222 24X Fiche 50-315, 82/12/07, 8212150323

8212160001 Forwards proposed Tech Spec Page 6-11 for performing audits of emergency preparedness programs & safeguards contingency plans (security plan), in response to Generic Ltrs 82-17 & 82-23
HUNTER, R S Indiana & Michigan Electric Co 82/12/09 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 16446 141 24X Fiche 50-315, 82/12/09, 8212160001

--8212160002 Proposed Tech Spec Page 6-11 for performing audits of emergency preparedness programs & safeguards contingency plans (security plan)
* Indiana & Michigan Electric Co 82/12/09 3pp 16446 143 24X Fiche 50-315, 82/12/09, 8212160001

8212220306 Discusses layout of communications equipment required in control room, onsite technical support ctr & near-site emergency operations facility
KEPPLER, J O Region 3, Office of Director 82/12/16 Commonwealth Edison Co 3pp 16503 351 24X Fiche 50-000, 82/12/16, 8212220306

J Insurance & indemnity information

8212100253 Forwards Endorsement 41 to MAELU Policy MF-79, Endorsement 51 to NELIA Policy NF-206 & Endorsements 10 & 9 to NELIA Binders EB-64 & EB-45, respectively
ALEXICH, M P American Electric Power Service Corp 82/12/07 DENTON, H R Office of Nuclear Reactor Regulation, Director 8pp 16376 117 24X Fiche 50-315, 82/12/07, 8212100253

8212290213 Forwards Endorsements 55 to NELIA Policy NF-206, 45 to MAELU Policy MF-79, 1, 2, 3 & 4 to NELIA Policy N-64, 1, 2, 3 & 4 to MAELU Policy M-64, 1, 2, 3 & 4 to NELIA Policy N-45 & 1, 2, 3 & 4 to MAELU Policy M-45
BUCKLEB, J Marsh & McLennan, Inc, M & M Nuclear Consultants, Inc Div 82/12/22 SALTZMAN, J Assistant Director for State & Licensee Relations 43pp 16578 089 24X Fiche 50-315, 82/12/22, 8212290213

P Operating license stage documents & correspondence

8212060072 Forwards completed questionnaire in response to Generic Ltr 82-22 re steam generator tube integrity
HUNTER, R S Indiana & Michigan Electric Co 82/11/29 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 16314 318 24X Fiche 50-315, 82/11/29, 8212060072

8212090296 Forwards Phase II b response to Encl 3, Section 2 4 of DO Eisenhower 801222 ltr re overhead handling sys operation for control of heavy loads per NUREG-0612 Two aperture cards available in PDR
HUNTER, R S Indiana & Michigan Electric Co 82/12/03 DENTON, H R Office of Nuclear Reactor Regulation, Director 16pp 16365 190 24X Fiche 50-315, 82/12/03, 8212090296

8212100290 Forwards revised inservice test program for safety-related pumps Tech Spec change request reflecting revisions will be provided under separate cover
HUNTER, R S Indiana & Michigan Electric Co 82/12/06 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 16377 082 24X Fiche 50-315, 82/12/06, 8212100290

--8212100300 Revision 1 to pump inservice test program
* Indiana & Michigan Electric Co 82/11/30 3pp 16377 084 24X Fiche 50-315, 82/12/06, 8212100290

8212160573 Summary of 821202 meeting w/ licensee & Excon re fuel reload for Cycle 4 Tech Spec description encl
WIGGINTON, D L Operating Reactors Branch 1 82/12/07 Operating Reactors Branch 1 140pp 16466 039 24X Fiche 50-316, 82/12/07, 8212160573

8212140167 Responds to question re basis for full ECCB flow used in LOCA-ECCB analysis in XN-NF-82-35, Suppl 1, per 821208 telcon, JENSEN, S E Excon Nuclear Co, Inc (subs of Excon Corp) 82/12/09 QRR, F, Reactor Systems Branch 2pp 16409 361 24X Fiche 50-316, 82/12/09, 8212140167

8212170179 Application for amend to License DPR-74, consisting of proposed changes to Tech Specs allowing Cycle 4 operation w/Excon fuel at reactor thermal power level of 9,411 MWt
HUNTER, R S Indiana & Michigan Electric Co 82/12/09 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 16462 038 24X Fiche 50-316, 82/12/09, 8212170179

DOCKETED ITEMS

--8212170188 Proposed changes to Tech Specs allowing Cycle 4 operation w/Exxon fuel at reactor thermal power level of 3.411 MWt
 * Indiana & Michigan Electric Co 82/12/09 20pp 16462 040
 24X Fiche 50-316,82/12/09,8212170179

8212210125 Forwards update on activities re NUREG-0737, Items II B 3, "Post-Accident Sampling," II F 1, "Noble Gas Monitoring" & II F D 3 4, "Control Room Habitability" Info supersedes previous correspondence on topics
 HUNTER, R S Indiana & Michigan Electric Co 82/12/14 DENTON, H R
 Office of Nuclear Reactor Regulation, Director 4pp 16485 130
 24X Fiche 50-315,82/12/14,8212210125

8212270136 Forwards description of coding errors recently discovered in CLASIX computer program Errors associated only w/modeling of flame propagation between containment compartments Coding errors do not affect previously transmitted analyses
 HUNTER, R S Indiana & Michigan Electric Co 82/12/17 DENTON, H R
 Office of Nuclear Reactor Regulation, Director 6pp 16538 137
 24X Fiche 50-315,82/12/17,8212270136

8212280404 Forwards Table 1 providing reactivity parameters for Unit 2, consistent w/parameters used in FSAR issued in Jul 1982
 QWLEY, O F Exxon Nuclear Co, Inc (subs of Exxon Corp)
 82/12/20 LICCARDO, R Reactor Systems Branch 2pp 16560 024
 24X Fiche 50-316,82/12/20,8212280404

Q Inspection reports, IE Bulletins & correspondence

8208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel Recirculation Sys Piping at BWR Plants" Svc list encl
 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc
 112pp 16462 163 24X Fiche 50-000,82/10/28,8208190240

8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters" Svc list encl
 COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp
 16372 142 24X Fiche 50-000,82/11/05,8208190245

8212060009 Forwards IE Emergency Preparedness Insp Repts 50-315/82-18 & 50-316/82-18 on 821020-22 Discussion of excessive weaknesses encl
 HIND, J A Division of Emergency Preparedness & Operational Support 82/11/15 DOLAN, J E American Electric Power Service Corp
 DOLAN, J E Indiana & Michigan Electric Co 3pp 16313 336 24X
 Fiche 50-315,82/11/15,8212060009

--8212060017 IE Emergency Preparedness Insp Repts 50-315/82-18 & 50-316/82-18 on 821020-22 No noncompliance noted Major areas inspected emergency preparedness exercise involving observation of key functions & locations
 PLOSKI, T J, SMITH, M J, AXELSON, W L Division of Emergency Preparedness & Operational Support 82/11/10 32pp 16313 339
 24X Fiche 50-315,82/11/10,8212060009

8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements" Svc list encl
 JORDAN, E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X
 Fiche 50-000,82/11/18,8208190251

8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks" Svc list encl
 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc
 127pp 16411 065 24X Fiche 50-000,82/11/26,8208190256

8208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl" Svc list encl
 COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp
 16287 028 24X Fiche 50-000,82/11/30,8208190257

8208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies" Svc list encl
 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc
 113pp 16411 317 24X Fiche 50-000,82/12/03,8208190259

8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets" Svc list encl
 JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X
 Fiche 50-000,82/12/03,8208190261

8212280242 Forwards IE Insp Repts 50-315/82-15 & 50-316/82-15 on 820801-0915 & notice of violation (Insp data changes noted throughout rept)
 SPESSARD, R L Division of Project & Resident Programs 82/12/10 DOLAN, J E American Electric Power Service Corp DOLAN, J E
 Indiana & Michigan Electric Co 2pp 16561 184 24X
 Fiche 50-315,82/12/10,8212280242

--8212280246 Notice of violation from Insp on 820801-0914
 SPESSARD, R L Division of Project & Resident Programs 82/12/10
 2pp 16561 186 24X Fiche 50-315,82/12/10,8212280242

--8212280251 IE Insp Repts 50-315/82-15 & 50-316/82-15 on 820801-0915 Noncompliance noted failure to remove addl charging pump & safety injection pump circuit breakers from electrical power circuit within 1-h
 SWANSON, E R, DUBRY, N E, WILLIAMS, D Division of Project & Resident Programs 82/12/03 17pp 16561 188 24X
 Fiche 50-315,82/12/10,8212280242

8212290330 Forwards IE Insp Repts 50-315/82-19 & 50-316/82-19 on 820916-1031 & notice of violation
 SPESSARD, R L Division of Project & Resident Programs 82/12/15 DOLAN, J E American Electric Power Service Corp DOLAN, J E
 Indiana & Michigan Electric Co 2pp 16586 188 24X
 Fiche 50-315,82/12/15,8212290330

--8212290335 IE Insp Repts 50-315/82-19 & 50-316/82-19 on 820916-1031 Noncompliance noted failure to comply w/action requirement & failure to follow clearance permit sys procedure
 SWANSON, E R, DUBRY, N E, BOYD, D C Division of Project & Resident Programs 82/12/15 11pp 16586 192 24X Fiche 50-315,82/12/15,8212290330

8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring" Svc list encl
 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc
 127pp 16628 191 24X Fiche 50-000,82/12/16,8208190267

8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27" Svc list encl
 JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X
 Fiche 50-000,82/12/20,8208190268

8212280165 Forwards addl info re inservice insp weld program Revised pages to Table 1, Class 2 components & welds & to Table 2 for components & welds for which relief requested encl
 HERINO, R F Indiana & Michigan Electric Co 82/12/20 DENTON, H R
 Office of Nuclear Reactor Regulation, Director 43pp 16563 335
 24X Fiche 50-315,82/12/20,8212280165

8212280310 Forwards description of post-irradiation fuel surveillance program implemented for Exxon 17x17 fuel
 HUNTER, R S Indiana & Michigan Electric Co 82/12/22 DENTON, H R
 Office of Nuclear Reactor Regulation, Director 2pp 16561 138
 24X Fiche 50-316,82/12/22,8212280310

R Periodic operating reports & related correspondence

8212290217 Forwards monthly operating rept for Oct 1982
 SMITH, W O Indiana & Michigan Electric Co 82/11/12 Management Information Branch 1p 16578 072 24X Fiche 50-316,82/11/12,8212290217

--8212290228 Monthly operating rept for Oct 1982
 GILLET, W T, LEASE, R S, SVENSSON, B A Indiana & Michigan Electric Co 82/11/02 6pp 16578 073 24X
 Fiche 50-316,82/11/12,8212290217

8212200056 Forwards monthly operating rept for Nov 1982
 SMITH, W O Indiana & Michigan Electric Co 82/12/14 Management Information Branch 1p 16470 016 24X Fiche 50-316,82/12/14,8212200056

--8212200065 Monthly operating rept for Nov 1982
 SMITH, W O Indiana & Michigan Electric Co 82/12/02 6pp 16470 017 24X Fiche 50-316,82/12/14,8212200056

S Reportable occurrences, LERs & related correspondence

8212020229 Forwards LER 82-088/03L-0
 SMITH, W O Indiana & Michigan Electric Co 82/11/23 KEPPLER, J G
 Region 3, Office of Director 1p 16274 090 24X
 Fiche 50-316,82/11/23,8212020229

--B212020232 LER 82-08B/03L-0 on 821029, containment sample isolation valve ECR-21 would not cycle Caused by defective solenoid coil Coil replaced
PALMER, R A Indiana & Michigan Electric Co 82/11/23 Region
3, Office of Director 1p 16274 091 24X Fiche 50-316, 82/11/23, 8212020229

B212060048 Forwards LERs 82-089/03L-0 & 82-090/03L-0
SMITH, W O Indiana & Michigan Electric Co 82/11/24 KEPLER, J O
Region 3, Office of Director 1p 16314 009 24X
Fiche 50-316, 82/11/24, 8212060048

--B212060057 LER 82-089/03L-0 on 821027, fire damper 2-MV-ACES-1 failed to close during automatic actuation of carbon dioxide fire protection sys in auxiliary cable vault Caused by failure of guillotine door to close due to dent in door Door repaired
WIZNER, D O Indiana & Michigan Electric Co 82/11/24 Region
3, Office of Director 1p 16314 010 24X Fiche 50-316, 82/11/24, 8212060048

--B212060060 LER 82-090/03L-0 on 821026, stem leakage discovered at valve CS-386 in boric acid makeup sys Caused by hole in diaphragm of ITT Orinell 2-inch valve Cause of hole unknown
Diaphragm replaced & flow path returned to svc
PIEHL, R H, PALMER, R A Indiana & Michigan Electric Co 82/11/24
Region 3, Office of Director 1p 16314 011 24X
Fiche 50-316, 82/11/24, 8212060048

B212100177 RO on 821201, west centrifugal charging pump rendered inoperable following mod on east & west centrifugal pump common mini flow line Caused by cut made on pressurized portion of piping Investigation in progress
SMITH, W O Indiana & Michigan Electric Co 82/12/02 KEPLER, J O
Region 3, Office of Director 2pp 16373 331 24X
Fiche 50-316, 82/12/02, 8212100177

B212140156 Forwards LER 82-091/03L-0
SMITH, W O Indiana & Michigan Electric Co 82/12/06 KEPLER, J O
Region 3, Office of Director 1p 16410 176 24X
Fiche 50-316, 82/12/06, 8212140156

--B212140165 LER 82-091/03L-0 on 821105, during steam generator blowdown, radiation monitor R-19 alarmed, indicating flow continued through Loop 1 sample valve DCR-301 Caused by leakage due to valve stroke not maintaining positive seat Valve replaced
WIZNER, D O, PALMER, R A Indiana & Michigan Electric Co 82/12/06
Region 3, Office of Director 1p 16410 177 24X
Fiche 50-316, 82/12/06, 8212140156

B212170224 Forwards LERs 82-092/03L-0, 82-093/03L-0 & 82-094/03L-0
SMITH, W O Indiana & Michigan Electric Co 82/12/08 KEPLER, J O
Region 3, Office of Director 1p 16459 323 24X
Fiche 50-316, 82/12/08, 8212170224

--B212170228 LER 82-092/03L-0 on 821109, during normal operation, auxiliary cable vault (Zone 11) experienced inadvertent carbon dioxide discharge & Pyralarm detector alarming Caused by water entering base Detector & base replaced
PALMER, R A Indiana & Michigan Electric Co 82/12/08 Region
3, Office of Director 1p 16459 324 24X Fiche 50-316, 82/12/08, 8212170224

--B212170232 LER 82-093/03L-0 on 821121, following shutdown, RCS dose equivalent I-131 concentration exceeded Tech Specs Cause not stated Fuel sipping will be performed during refueling operation
PALMER, R A Indiana & Michigan Electric Co 82/12/08 Region
3, Office of Director 2pp 16459 325 24X Fiche 50-316, 82/12/08, 8212170224

--B212170237 LER 82-094/03L-0 on 821122, during Mode 5 operation, RCS temp decreased below Tech Spec limit for charging pump operation Caused by loss of four reactor coolant pumps & RHR trains Two of three pumps racked out
KRAUSE, D F Indiana & Michigan Electric Co 82/12/08 Region
3, Office of Director 1p 16459 331 24X Fiche 50-316, 82/12/08, 8212170224

B212170267 Forwards LER 82-095/03L-0
SMITH, W O Indiana & Michigan Electric Co 82/12/10 KEPLER, J O
Region 3, Office of Director 1p 16457 167 24X
Fiche 50-316, 82/12/10, 8212170267

- B212170268 LER 82-095/03L-0 on 821111, door to U-2 CD diesel engine fuel oil day tank room designated as Tech Spec related fire door found held open Cause not determined Door secured & redesignated as nonsafety-related fire door
SVENSSON, B A Indiana & Michigan Electric Co 82/12/10 Region
3, Office of Director 2pp 16457 168 24X Fiche 50-316, 82/12/10, 8212170267

B212290355 Forwards LER 82-096/01T-0
SMITH, W O Indiana & Michigan Electric Co 82/12/15 KEPLER, J O
Region 3, Office of Director 1p 16586 220 24X
Fiche 50-316, 82/12/15, 8212290355

--B212290358 LER 82-096/01T-0 on 821201, west centrifugal charging pump rendered inoperable by incorrect cut on mini flow line from pump Caused by poor communication between plant & contractor Cut locations will be verified prior to work
BEILMAN, T P Indiana & Michigan Electric Co 82/12/15 Region
3, Office of Director 2pp 16586 221 24X Fiche 50-316, 82/12/15, 8212290355

DOCKET 50-317 CALVERT CLIFFS NUCLEAR POWER PLANT, UNIT 1

F Security, medical, emergency & fire protection plans

B212100442 Releases public version of revised emergency response plan implementing procedures
FELTON, J M Division of Rules and Records 82/11/24 Document
Management Branch 1p 16289 131 24X Fiche 50-317, 82/11/24, 8212100442

--B21210050 Forwards public version of revised emergency response plan implementing procedures, including Procedures ERPIP 3 8 re immediate action - alert & ERPIP 3 9 re immediate action - site emergency Receipt form encl
* Baltimore Gas & Electric Co 82/11/12 CLARK, R A Operating
Reactors Branch 3 1p 16289 132 24X Fiche 50-317, 82/11/24, 8212100442

--B21210055 Public version of revised emergency response plan implementing procedures, including Procedures ERPIP 3 8 re immediate action - alert & ERPIP 3 9 re immediate action - site emergency
* Baltimore Gas & Electric Co 82/11/05 19pp 16289 133 24X
Fiche 50-317, 82/11/24, 8212100442

B212130065 Responds to Generic Ltr 82-17, "Inconsistency Between Requirements of 10CFR50 54(b) & STS for Performing Audits of Emergency Preparedness Programs " Difference between "audit" & "review" should be clarified
LUNDVALL, A E Baltimore Gas & Electric Co 82/11/29 CLARK, R A
Operating Reactors Branch 3 3pp 16391 165 24X
Fiche 50-317, 82/11/29, 8212130065

B212080491 Confirms info provided in 821202 telcon re status of emergency operations facility (EOF) EOF located on company property, 1 mile from plant structures
OLSON, R C Baltimore Gas & Electric Co 82/12/03 CLARK, R A
Operating Reactors Branch 3 1p 16352 262 24X
Fiche 50-317, 82/12/03, 8212080491

B212300204 Releases public version of change to revised list of effective pages to emergency response plan implementing procedures
FELTON, J M Division of Rules and Records 82/12/20 Document
Management Branch 1p 16624 158 24X Fiche 50-317, 82/12/20, 8212300204

--B212300209 Forwards public version of Change 5 to Revision B of list of effective pages to emergency response plan implementing procedures Receipt form encl
* Baltimore Gas & Electric Co 82/12/08 CLARK, R A Operating
Reactors Branch 3 1p 16624 159 24X Fiche 50-317, 82/12/20, 8212300204

--B212300211 Public version of Change 5 to Revision B of list of effective pages to emergency response plan implementing procedures
* Baltimore Gas & Electric Co 82/12/08 17pp 16624 161 24X
Fiche 50-317, 82/12/20, 8212300204

B212280200 Ack receipt of 821027 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Repts 50-317/82-1B & 50-318/82-22
MARTIN, T T Division of Engineering & Technical Programs 82/12/21
BOWMAKER, N J Baltimore Gas & Electric Co 2pp 16562 093 24X
Fiche 50-317, 82/12/21, 8212280200

--B212280208 Responds to NRC 821008 ltr re violations noted in IE Safeguards Insp Repts 50-317/82-1B & 50-318/82-22 Corrective actions withheld (ref 10CFR73 21)
BOWMAKER, N J Baltimore Gas & Electric Co 82/10/27 MARTIN, T T
Division of Engineering & Technical Programs 1p 16562 095
24X Fiche 50-317, 82/12/21, 8212280200

DOCKETED ITEMS

F Operating license stage documents & correspondence

8212080012 Responds to 820922 request to withhold info submitted in "Results of Eddy Current Testing on Guide Tubes at Calvert Cliffs Unit 1 After Cycle 5" Document withheld (ref 10CFR2 790)
CLARK, R A Operating Reactors Branch 3 82/11/03 LUNDVALL, A E
Baltimore Gas & Electric Co 3pp 16367 179 24X
Fiche 50-317, 82/11/03, 8212080012

8212040071 Responds to Generic Ltr 82-22 Plant reduction or outage has not been attributed to leak of maint on steam generators
Occupational radiation exposure resulting from routine insp minimal
LUNDVALL, A E Baltimore Gas & Electric Co 82/11/24 EISENHUT, D G
Division of Licensing 1p 16316 106 24X Fiche 50-317, 82/11/24, 8212060071

8212070082 Advises that CEN-220(B)-P, "Supplemental Info on FATES3 Stored Energy Conservatism," will be withheld per 10CFR2 790
CLARK, R A Operating Reactors Branch 3 82/11/24 LUNDVALL, A E
Baltimore Gas & Electric Co 3pp 16356 271 24X
Fiche 50-317, 82/11/24, 8212070082

8212070105 Forwards SER & technical evaluation of "Improvements in Training & Requalification Programs as Required by TMI Action Items I A 2 I & II B 4 for Calvert Cliffs, Units 1 & 2"
CLARK, R A Operating Reactors Branch 3 82/11/24 LUNDVALL, A E
Baltimore Gas & Electric Co 4pp 16354 289 24X
Fiche 50-317, 82/11/24, 8212070105

--8212070115 "Improvements in Training & Requalification Programs as Required by TMI Action Items I A 2 I & II B 4, Calvert Cliffs, Units 1 & 2," technical evaluation rept
Science Applications, Inc NRC-03-82-096 SAI-186-029-19
82/08/31 NRC - No Detailed Affiliation Given 13pp
16354 293 24X Fiche 50-317, 82/11/24, 8212070105

8212070054 Forwards documentation satisfying each criterion of NUREG-0737, Item II B 3, "Post-Accident Sampling," per NRC 820630 request W/one oversize drawing Aperture card is available in PDR
LUNDVALL, A E Baltimore Gas & Electric Co 82/11/30 CLARK, R A
Operating Reactors Branch 3 9pp 16326 001 24X
Fiche 50-317, 82/11/30, 8212070054

8212090032 Forwards notice of consideration of issuance of amend re util 820929 application for revised pressurizer level Tech Specs
CLARK, R A Operating Reactors Branch 3 82/11/30 LUNDVALL, A E
Baltimore Gas & Electric Co 3pp 16384 260 24X
Fiche 50-317, 82/11/30, 8212090032

--8212090036 Notice of consideration of issuance of amend for revised pressurizer level Tech Specs
CONNER, E L Operating Reactors Branch 3 82/11/30 4pp
16384 263 24X Fiche 50-317, 82/11/30, 8212090032

8212210447 Forwards "Integrated Leak Rate Test Rept"
LUNDVALL, A E Baltimore Gas & Electric Co 82/11/30 CLARK, R A
Operating Reactors Branch 3 1p 16486 231 24X
Fiche 50-317, 82/11/30, 8212210447

--8212210448 "Integrated Leak Rate Test Rept"
Baltimore Gas & Electric Co 82/11/30 47pp 16486 232 24X
Fiche 50-317, 82/11/30, 8212210447

8212080197 Discusses ambiguity re use of terminology "review" & "audit" in Generic Ltr 82-23 & 10CFR73 40 ANSI Std N18 7-1976 used for strict definition of terms
BCKMAKER, N J Baltimore Gas & Electric Co 82/12/02 CLARK, R A
Operating Reactors Branch 3 3pp 16354 007 24X
Fiche 50-317, 82/12/02, 8212080197

8208190263 Generic Ltr 82-32 to all PWR licensees re potential steam generator-related generic requirements Forwards Science Applications, Inc draft rept re sub requirements Comments requested within 30 days of ltr. Svc list encl
EISENHUT, D G Division of Licensing 82/12/09 Consolidated
Edison Co of New York, Inc 29pp 16629 247 24X
Fiche 50-000, 82/12/09, 8208190263

8212140103 Generic Ltr 82-28 to all licensees of operating Westinghouse & C-E PWRs (except Arkansas Nuclear One, Unit 2 & San Onofre 2 & 3) re inadequate core cooling instrumentation sys Svc list encl
EISENHUT, D G Division of Licensing 82/12/10 Yankee Atomic
Electric Co 27pp 16690 035 24X Fiche 50-000, 82/12/10, 8212140103

8212170252 Informs that source range flux monitoring capability now scheduled to be provided at alternate shutdown panel for Unit 1 by end of Fall 1983 refueling outage & for Unit 2 by end of Spring 1984 outage
LUNDVALL, A E Baltimore Gas & Electric Co 82/12/10 CLARK, R A
Operating Reactors Branch 3 2pp 16456 209 24X
Fiche 50-317, 82/12/10, 8212170252

8212300041 Forwards safety evaluation & technical evaluation repts supporting environ qualification of safety-related electrical equipment Justification for continued operation & qualification or replacement of equipment requested
CLARK, R A Operating Reactors Branch 3 82/12/16 LUNDVALL, A E
Baltimore Gas & Electric Co 3pp 16624 288 24X
Fiche 50-317, 82/12/16, 8212300041

--8212300048 Safety evaluation supporting environ qualification of safety-related electrical equipment Plans for qualification or replacement of equipment in Topics I B, II A & II B requested
Office of Nuclear Reactor Regulation, Director 82/12/16 5pp
16624 291 24X Fiche 50-317, 82/12/16, 8212300041

--8210220483 "Review of Licensee Resolution of Outstanding Issues From NRC Equipment Environ Qualification SERs (F-11 & B-60), Calvert Cliffs Nuclear Power Plant Unit 1," technical evaluation rept
PANDEY, B Franklin Institute/Franklin Research Center
NRC-03-79-118 TER-CS257-487 82/10/13 LE, N B NRC - No
Detailed Affiliation Given 650pp 16624 296 24X
Fiche 50-317, 82/12/16, 8212300041

--8210220470 "Review of Licensee Resolution of Outstanding Issues From NRC Equipment Environ Qualification SERs (F-11 & B-60), Calvert Cliffs Nuclear Power Plant Unit 2," technical evaluation rept
PANDEY, B Franklin Institute/Franklin Research Center
NRC-03-79-118 TER-CS257-488 82/10/13 LE, N B NRC - No
Detailed Affiliation Given 681pp 16627 001 24X
Fiche 50-317, 82/12/16, 8212300041

8212210420 Forwards results of review of TMI Action Items I A 1 3, "Limit Overtime," II E 1 1, "Short Term Auxiliary Feedwater Sys Evaluation" & II E 1 2 & II K 3 3 Tech Spec change under review
LUNDVALL, A E Baltimore Gas & Electric Co 82/12/17 EISENHUT, D G
Division of Licensing 3pp 16493 075 24X Fiche 50-317, 82/12/17, 8212210420

8212230274 Forwards response to NRC questions on pressurized level limiting conditions Tech Specs Table presenting summary of evaluation of impact of changing water level for each DBE encl
LIPPOLD, W J Baltimore Gas & Electric Co 82/12/17 CLARK, R A
Operating Reactors Branch 3 8pp 16508 265 24X
Fiche 50-317, 82/12/17, 8212230274

G Inspection reports, IE Bulletins & correspondence

8208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel Recirculation Bypass Piping at DNR Plants" Svc list encl
DEVOUNO, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc
112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240

8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model B01 & Model B02 Thermoluminescent Dosimeters" Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards
82/11/05 Consolidated Edison Co of New York, Inc 110pp
16372 142 24X Fiche 50-000, 82/11/05, 8208190245

8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements" Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18
Consolidated Edison Co of New York, Inc 107pp 16411 199 24X
Fiche 50-000, 82/11/18, 8208190251

8212020003 Notification of 821214 significant licensee meeting w/util in Lusby, MD to discuss SALP
McCABE, E Region 1, Office of Director 82/11/19 Region 1,
Office of Director 1p 16317 089 24X Fiche 50-317, 82/11/19, 8212020003

8212100007 Forwards IE Insp Repts 50-317/82-27 & 50-318/82-23 on 821012-1109 & notice of violation
STAROSTECKI, R Division of Project & Resident Programs 82/11/24
LUNDVALL, A E Baltimore Gas & Electric Co 2pp 16379 133 24X
Fiche 50-317, 82/11/24, 8212100007

--B212100010 Notice of violation from insp on B21012-1109
* Region 1, Office of Director 82/11/24 1p 16379 135 24X
Fiche 50-317, 82/11/24, B212100007

--B212100013 IE Insp Repts 50-317/82-27 & 50-318/82-23 on B21012-1109
Noncompliance noted Unit 2 placed in Mode 6 w/o operable
audible indication of source range neutron flux in control
room
ARCHITZEL, R E, TRIMBLE, D C, MCCABE, E C Division of Project &
Resident Programs 82/11/17 13pp 16379 136 24X
Fiche 50-317, 82/11/24, B212100007

B208190256 IE Info Notice 82-46, "Defective & Obsolete Combination
Padlocks " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and
Enforcement 82/11/26 Consolidated Edison Co of New York, Inc
127pp 16411 065 24X Fiche 50-000, 82/11/26, B208190256

B208190257 IE Info Notice 82-47, "Transportation of Type A Quantities
of Non-Fissile Radioactive Matl " Svc list encl
CDBB, L I Division of Fuel Facilities, Materials & Safeguards
82/11/30 Consolidated Edison Co of New York, Inc 356pp
16387 028 24X Fiche 50-000, 82/11/30, B208190257

B212060285 Ack receipt of B21028 ltr informing NRC of steps taken to
correct violations noted in IE Insp Repts 50-317/82-07 &
50-318/82-07
STAROSTECKI, R Division of Project & Resident Programs 82/12/02
LUNDVALL, A E Baltimore Gas & Electric Co 1p 16312 059 24X
Fiche 50-317, 82/12/02, B212060285

--B212060293 Responds to NRC B20929 ltr re violations noted in IE Insp
Repts 50-317/82-07 & 50-318/82-07 Corrective actions audit
by OA of selected plant procedures which incorporate Tech
Spec limits completed
LUNDVALL, A E Baltimore Gas & Electric Co 82/10/28
STAROSTECKI, R Division of Project & Resident Programs 3pp
16312 060 24X Fiche 50-317, 82/12/02, B212060285

B208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment
Electrical Penetration Assemblies " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and
Enforcement 82/12/03 Consolidated Edison Co of New York, Inc
113pp 16411 317 24X Fiche 50-000, 82/12/03, B208190259

B208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay
Sockets " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03
Consolidated Edison Co of New York, Inc 110pp 16462 064 24X
Fiche 50-000, 82/12/03, B208190261

B212160384 Forwards response to B20914 request to suppl response to IE
Bulletin 80-11, "Masonry Wall Design " One oversize drawing
encl Aperture card available in PDR
LUNDVALL, A E Baltimore Gas & Electric Co 82/12/13 CLARK, R A
Operating Reactors Branch 3 9pp 16442 151 24X
Fiche 50-317, 82/12/13, B212160384

B208190267 IE Info Notice 82-49, "Correction for Sample Conditions for
Air & Gas Monitoring " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and
Enforcement 82/12/16 Consolidated Edison Co of New York, Inc
127pp 16628 191 24X Fiche 50-000, 82/12/16, B208190267

B208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage
Relays Type ITE-27 " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20
Consolidated Edison Co of New York, Inc 108pp 16628 293 24X
Fiche 50-000, 82/12/20, B208190268

B212280200 Ack receipt of B21027 ltr informing NRC of steps taken to
correct violations noted in IE Safeguards Insp Repts
50-317/82-18 & 50-318/82-22
MARTIN, T T Division of Engineering & Technical Programs 82/12/21
BOWMAKER, N J Baltimore Gas & Electric Co 2pp 16562 093 24X
Fiche 50-317, 82/12/21, B212280200

--B212280208 Responds to NRC B21008 ltr re violations noted in IE
Safeguards Insp Repts 50-317/82-18 & 50-318/82-22 Corrective
actions withheld (ref 10CFR73.21)
BOWMAKER, N J Baltimore Gas & Electric Co 82/10/27 MARTIN, T T
Division of Engineering & Technical Programs 1p 16562 095
24X Fiche 50-317, 82/12/21, B212280200

R Periodic operating reports & related correspondence

B212220208 Forwards monthly operating repts for Nov 1982
LOTITO, E M Baltimore Gas & Electric Co 82/12/15 Director's
Office, Office of Inspection and Enforcement 1p 16518 317 24X
Fiche: 50-317, 82/12/15, B212220208

--B212220210 Monthly operating repts for Nov 1982
LOTITO, E M Baltimore Gas & Electric Co 82/12/15 10pp
16518 318 24X Fiche 50-317, 82/12/15, B212220208

S Reportable occurrences, LERs & related correspondence

B212160259 Forwards LER B1-034/03L-0
RUSSELL, L B Baltimore Gas & Electric Co 81/06/01 GRIER, B H
Region 1, Philadelphia, Office of the Director (B1/03/01) 1p
16442 356 24X Fiche 50-317, 81/06/01, B212160259

--B212160270 LER B1-034/03L-0 on B10508, emergency diesel generator 11
failed to reach rated speed while returning generator to
svc Caused by fuel racks & operating linkages sticking &
damaged set screw rubbing against linkage
LAOIEWSKI, J S, HUBBARD, D E Baltimore Gas & Electric Co
81/06/01 Region 1, Philadelphia, Office of the Director
(B1/03/01) 1p 16442 357 24X Fiche 50-317, 81/06/01, B212160259

B212060149 Nonroutine radiological environ operating rept on B21021,
oyster samples collected from Camp Conoy revealed presence
of Ag-110m less than Aug samples Probably due to
deposition
FUHRMAN, O R Baltimore Gas & Electric Co 82/11/23 HAYNES, R C
Region 1, Office of Director 3pp 16313 146 24X
Fiche 50-317, 82/11/23, B212060149

B212060196 Forwards LER B2-046/03L-0
RUSSELL, L B Baltimore Gas & Electric Co 82/11/24 HAYNES, R C
Region 1, Office of Director 1p 16313 196 24X
Fiche 50-317, 82/11/24, B212060196

--B212060206 LER B2-066/03L-0 on B21026, reactor protective sys channel W
trip units for highpower, thermal margin/low pressure & axial
shape index bypassed when Tc failed high Caused by noise
producing transmitter circuitry oscillations
LAOIEWSKI, J S, HINKLE, L S Baltimore Gas & Electric Co
82/11/24 Region 1, Office of Director 1p 16313 197 24X
Fiche 50-317, 82/11/24, B212060196

B212060301 Forwards LER B2-065/03L-0
RUSSELL, L B Baltimore Gas & Electric Co 82/11/24 HAYNES, R C
Region 1, Office of Director 1p 16312 119 24X
Fiche 50-317, 82/11/24, B212060301

--B212060306 LER B2-065/03L-0 on B21025, electrical bus supplying power to
containment atmosphere particulate & gaseous radioactivity
monitoring sys de-energized Caused by ground on tendon insp
platform power cable, induced by high winds
JUNOE, M A, BASSO, L F Baltimore Gas & Electric Co 82/11/24
Region 1, Office of Director 1p 16312 120 24X
Fiche 50-317, 82/11/24, B212060301

B212080441 Forwards LER B2-072/04X-0
RUSSELL, L B Baltimore Gas & Electric Co 82/11/29 HAYNES, R C
Region 1, Office of Director 1p 16352 112 24X
Fiche 50-317, 82/11/29, B212080441

--B212080448 LER B2-072/04X-0 on B21027, higher than normal background
radioactive Ag-110m levels found in oyster samples taken
from Camp Conoy location on B21123 Caused by natural
tendency of oysters to concentrate environ silver
BROBST, O E Baltimore Gas & Electric Co 82/11/29 Region 1,
Office of Director 1p 16352 113 24X Fiche 50-317, 82/11/29,
B212080441

B212080456 Corrects B21123 ltr re nonroutine radiological environ
operating rept Capacity factor for Oct 1982 was 105.20%, not
72.51%
FUHRMAN, O R Baltimore Gas & Electric Co 82/11/29 HAYNES, R C
Region 1, Office of Director 1p 16352 163 24X
Fiche 50-317, 82/11/29, B212080456

B212060305 PND-1-B2-077 on B21201, contractor employee intentionally
poisoned lunch & placed in refrigerator Employee
notified licensee of actions upon discovering lunch missing
Warning announced on page sys No known harm occurred
ARCHITZEL, MCCABE Region 1, Office of Director 82/12/01 1p
16312 111 24X Fiche 50-317, 82/12/01, B212060305

B212140125 Forwards LER B2-070/01T-0
RUSSELL, L B Baltimore Gas & Electric Co 82/12/02 HAYNES, R C
Region 1, Office of Director 1p 16408 236 24X
Fiche 50-317, 82/12/02, B212140125

--B212140131 LER B2-070/01T-0 on B21118, chemical vol & control isolation
signal (CVCIS) sys declared inoperable since generation of
CVCIS may be prohibited by single failure Cause not stated
Corrective action ongoing to verify sys design adequacy
PAVIS, O S, WENGER, L O Baltimore Gas & Electric Co 82/12/02
Region 1, Office of Director 3pp 16408 237 24X
Fiche 50-317, 82/12/02, B212140125

DOCKETED ITEMS

- 8212210378 Forwards LER 82-068/03L-0
 RUSSELL, L. B. Baltimore Gas & Electric Co 82/12/08 HAYNES, R. C.
 Region 1, Office of Director 1p 16494 302 24X
 Fiche 50-317, 82/12/08, 8212210378
- 8212210384 LER 82-068/03L-0 on 821109, during Mode 1, power lost to 120-volt ac vital bus caused by inadvertent opening of dc input breaker to inverter supplying bus Mod will be performed to inverter cabinets to prevent inadvertent breaker opening
 WENDERLICH, R. L. Baltimore Gas & Electric Co 82/12/08 Region 1, Office of Director 2pp 16494 303 24X Fiche 50-317, 82/12/08, 8212210378
- 8212210042 Forwards LER 82-071/03L-0
 RUSSELL, L. B. Baltimore Gas & Electric Co 82/12/09 HAYNES, R. C.
 Region 1, Office of Director 1p 16490 224 24X
 Fiche 50-317, 82/12/09, 8212210042
- 8212210048 LER 82-071/03L-0 on 821109, during reactor trip recovery, charging pump 12 breaker would not close Caused by dirty breaker charging motor cutoff switch contacts Coil replaced & cutoff switch contacts cleaned
 JUNGE, M. A. BASCO, L. F. Baltimore Gas & Electric Co 82/12/09 Region 1, Office of Director 2pp 16490 225 24X
 Fiche 50-317, 82/12/09, 8212210042
- 8212210076 Forwards LER 82-073/03L-0
 RUSSELL, L. B. Baltimore Gas & Electric Co 82/12/09 HAYNES, R. C.
 Region 1, Office of Director 1p 16465 250 24X
 Fiche 50-317, 82/12/09, 8212210076
- 8212210080 LER 82-073/03L-0 on 821110, pressurizer level deviated from program level by more than +/-5% several times Caused by loading of main turbine generator Reanalysis for justification of relaxation of Tech Specs in progress
 JUNGE, M. A. Baltimore Gas & Electric Co 82/12/09, Region 1, Office of Director 1p 16485 251 24X Fiche 50-317, 82/12/09, 8212210076
- 8212210294 Forwards LER 82-067/03L-0
 RUSSELL, L. B. Baltimore Gas & Electric Co 82/12/09 HAYNES, R. C.
 Region 1, Office of Director 1p 16497 010 24X
 Fiche 50-317, 82/12/09, 8212210294
- 8212210303 LER 82-067/03L-0 on 821109, safety injection tank high level alarm annunciated despite indicated level within Tech Spec limits Caused by level transmitter 1-LT-341 being out of calibr Transmitter to be replaced during next cold shutdown
 PAVIB, G. S., RAYNOR, J. W. Baltimore Gas & Electric Co 82/12/09 Region 1, Office of Director 2pp 16497 011 24X
 Fiche 50-317, 82/12/09, 8212210294
- 8212290275 Forwards updated LER 82-071/01X-1
 RUSSELL, L. B. Baltimore Gas & Electric Co 82/12/16 HAYNES, R. C.
 Region 1, Office of Director 1p 16581 061 24X
 Fiche 50-317, 82/12/16, 8212290275
- 8212290282 Updated LER 82-071/01X-1 on 821109, charging pump 12 breaker would not close, rendering pump inoperable Caused by dirty breaker charging motor cutoff switch contacts resulting in long coil charging time Burnt coil replaced
 JUNGE, M. A., BASCO, L. F. Baltimore Gas & Electric Co 82/12/16 Region 1, Office of Director 2pp 16581 062 24X
 Fiche 50-317, 82/12/16, 8212290275
- DOCKET 50-318 CALVERT CLIFFS NUCLEAR POWER PLANT, UNIT 2
 F Security, medical, emergency & fire protection plans
- 8212010042 Releases public version of revised emergency response plan implementing procedures
 FELTON, J. M. Division of Rules and Records 82/11/24 Document Management Branch 1p 16289 131 24X Fiche 50-317, 82/11/24, 8212010042
- 8212010050 Forwards public version of revised emergency response plan implementing procedures, including Procedures ERPIP 3 B re immediate action - alert & ERPIP 3 9 re immediate action - site emergency Receipt form encl
 * Baltimore Gas & Electric Co 82/11/12 CLARK, R. A. Operating Reactors Branch 3 1p. 16289 132 24X Fiche 50-317, 82/11/24, 8212010042
- 8212010055 Public version of revised emergency response plan implementing procedures, including Procedures ERPIP 3 B re immediate action - alert & ERPIP 3 9 re immediate action - site emergency
 * Baltimore Gas & Electric Co 82/11/09 19pp 16289 133 24X
 Fiche 50-317, 82/11/24, 8212010042
- 8212130065 Responds to Generic Ltr 82-17, "Inconsistency Between Requirements of 10CFR50 54(c) & STS for Performing Audits of Emergency Preparedness Programs " Difference between "audit" & "review" should be clarified
 LUNDVALL, A. E. Baltimore Gas & Electric Co 82/11/29 CLARK, R. A. Operating Reactors Branch 3 3pp 16391 165 24X
 Fiche 50-317, 82/11/29, 8212130065
- 8212080491 Confirms info provided in 821202 telcon re status of emergency operations facility (EOF) EOF located on company property, 1 mile from plant structures
 OLSON, R. C. Baltimore Gas & Electric Co 82/12/03 CLARK, R. A. Operating Reactors Branch 3 1p 16352 262 24X
 Fiche 50-317, 82/12/03, 8212080491
- 8212300204 Releases public version of change to revised list of effective pages to emergency response plan implementing procedures
 FELTON, J. M. Division of Rules and Records 82/12/20 Document Management Branch 1p 16624 158 24X Fiche 50-317, 82/12/20, 8212300204
- 8212300209 Forwards public version of Change 5 to Revision B of list of effective pages to emergency response plan implementing procedures Receipt form encl
 * Baltimore Gas & Electric Co 82/12/08 CLARK, R. A. Operating Reactors Branch 3 1p 16624 159 24X Fiche 50-317, 82/12/20, 8212300204
- 8212300211 Public version of Change 5 to Revision B of list of effective pages to emergency response plan implementing procedures
 * Baltimore Gas & Electric Co 82/12/08 17pp 16624 161 24X
 Fiche 50-317, 82/12/20, 8212300204
- 8212280200 Ack receipt of 821027 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Rpts
 50-317/82-18 & 50-318/82-22
 MARTIN, T. T. Division of Engineering & Technical Programs 82/12/21
 BOMMAKER, H. J. Baltimore Gas & Electric Co 2pp 16562 093 24X
 Fiche 50-317, 82/12/21, 8212280200
- 8212280208 Responds to NRC 821008 ltr re violations noted in IE Safeguards Insp Rpts 50-317/82-18 & 50-318/82-22 Corrective actions withheld (ref 10CFR73 21)
 BOMMAKER, H. J. Baltimore Gas & Electric Co 82/10/27 MARTIN, T. T. Division of Engineering & Technical Programs 1p 16562 093 24X
 Fiche 50-317, 82/12/21, 8212280200
- F Operating license stage documents & correspondence
- 8212080031 Provides relief from ASME Boiler & Vessel Code, Section XI requirement re hydrostatic test pressure, found impractical in 820830 application Acceptable alternate test method approved in accordance w/10CFR50 55a
 CLARK, R. A. Operating Reactors Branch 3 82/11/19 LUNDVALL, A. E. Baltimore Gas & Electric Co 2pp 16367 147 24X
 Fiche 50-318, 82/11/19, 8212080031
- 8212080036 SER supporting 820830 request for relief from pressure testing requirements of ASME Boiler & Pressure Vessel Code after mod of auxiliary feedwater sys piping & components
 * Office of Nuclear Reactor Regulation, Director 82/11/19 3pp 16367 149 24X Fiche 50-318, 82/11/19, 8212080031
- 8212080040 Notice of granting of relief from ASME Section XI, inservice insp requirements
 CLARK, R. A. Operating Reactors Branch 3 82/11/19 2pp 16367 152 24X Fiche 50-318, 82/11/19, 8212080031
- 8212060071 Responds to Generic Ltr 82-22 Plant reduction or outage has not been attributed to leak of maint on steam generators
 Occupational radiation exposure resulting from routine insp minimal
 LUNDVALL, A. E. Baltimore Gas & Electric Co 82/11/24 EISENHUT, D. G. Division of Licensing 1p 16316 106 24X Fiche 50-317, 82/11/24, 8212060071
- 8212070105 Forwards SER & technical evaluation of "Improvements in Training & Requalification Programs as Required by TMI Action Items 1 A 2 i & 11 B 4 for Calvert Cliffs, Units 1 & 2"
 CLARK, R. A. Operating Reactors Branch 3 82/11/24 LUNDVALL, A. E. Baltimore Gas & Electric Co 4pp 16354 289 24X
 Fiche 50-317, 82/11/24, 8212070105
- 8212070115 "Improvements in Training & Requalification Programs as Required by TMI Action Items 1 A 2 i & 11 B 4, Calvert Cliffs, Units 1 & 2," technical evaluation rept
 * Science Applications, Inc. NRC-03-82-096 821-186-027-19 82/08/31 NRC - No Detailed Affiliation Given 13pp 16354 293 24X Fiche 50-317, 82/11/24, 8212070105

B212070034 Forwards documentation satisfying each criterion of NUREG-0737, Item II B 3, "Post-Accident Sampling," per NRC B20630 request W/done oversize drawing Aperture card is available in PDR
LUNDVALL, A E Baltimore Gas & Electric Co 82/11/30 CLARK, R A
Operating Reactors Branch 3 9pp 16326 001 24X
Fiche 50-317, 82/11/30, B212070034

B212090032 Forwards notice of consideration of issuance of amend re until 820929 application for revised pressurizer level Tech Specs
CLARK, R A Operating Reactors Branch 3 82/11/30 LUNDVALL, A E
Baltimore Gas & Electric Co 3pp 16384 260 24X
Fiche 50-317, 82/11/30, B212090032

--B212090036 Notice of consideration of issuance of amend for revised pressurizer level Tech Specs
CONNER, E L Operating Reactors Branch 3 82/11/30 4pp
16384 263 24X Fiche 50-317, 82/11/30, B212090032

B212090050 Forwards notice of consideration of issuance of amend re until 821015 application for Cycle 5 operation
CLARK, R A Operating Reactors Branch 3 82/11/30 LUNDVALL, A E
Baltimore Gas & Electric Co 3pp 16384 237 24X
Fiche 50-318, 82/11/30, B212090050

--B212090053 Notice of consideration of issuance of amend for Cycle 5 operation
CLARK, R A Operating Reactors Branch 3 82/11/30 4pp
16384 240 24X Fiche 50-318, 82/11/30, B212090050

B212080197 Discusses ambiguity re use of terminology "review" and "audit" in Generic Ltr 82-23 & 10CFR73.40 ANSI Std N18.7-1976 used for strict definition of terms
ROTHAKER, N J Baltimore Gas & Electric Co 82/12/02 CLARK, R A
Operating Reactors Branch 3 3pp 16354 007 24X
Fiche 50-317, 82/12/02, B212080197

B212200088 Forwards responses to NRC questions re B21015 amend to Cycle 5 license application
LUNDVALL, A E Baltimore Gas & Electric Co 82/12/06 CLARK, R A
Operating Reactors Branch 3 3pp 16474 303 24X
Fiche 50-318, 82/12/06, B212200088

B212270542 Forwards notice of consideration of issuance of amends to License DPR-69 Amend revises Tech Specs re auxiliary feedwater sys
CLARK, R A Operating Reactors Branch 3 82/12/06 LUNDVALL, A E
Baltimore Gas & Electric Co 3pp 16546 346 24X
Fiche 50-318, 82/12/06, B212270542

--B212270546 Notice of consideration of issuance of amends to License DPR-69
CLARK, R A Operating Reactors Branch 3 82/12/06 4pp
16546 349 24X Fiche 50-318, 82/12/06, B212270542

B2108190263 Generic Ltr 82-32 to all PWR licensees re potential steam generator-related generic requirements Forwards Science Applications, Inc draft rept re subj requirements Comments requested within 30 days of ltr Svc list encl
EISENHUT, D G Division of Licensing 82/12/09 Consolidated
Edison Co of New York, Inc 29pp 16629 247 24X
Fiche 50-000, 82/12/09, B208190263

B212140103 Generic Ltr 82-28 to all licensees of operating Westinghouse & C-E PWRs (except Arkansas Nuclear One, Unit 2 & San Onofre 2 & 3) re inadequate core cooling instrumentation sys Svc list encl
EISENHUT, D G Division of Licensing 82/12/10 Yankee Atomic
Electric Co 27pp 16690 035 24X Fiche 50-000, 82/12/10, B212140103

B212170252 Informs that source range flux monitoring capability now scheduled to be provided at alternate shutdown panel for Unit 1 by end of Fall 1983 refueling outage & for Unit 2 by end of Spring 1984 outage
LUNDVALL, A E Baltimore Gas & Electric Co 82/12/10 CLARK, R A
Operating Reactors Branch 3 2pp 16456 209 24X
Fiche 50-317, 82/12/10, B212170252

B212300041 Forwards safety evaluation & technical evaluation repts supporting environ qualification of safety-related electrical equipment Justification for continued operation & qualification or replacement of equipment requested
CLARK, R A Operating Reactors Branch 3 82/12/16 LUNDVALL, A E
Baltimore Gas & Electric Co 3pp 16624 288 24X
Fiche 50-317, 82/12/16, B212300041

--B21020470 "Review of Licensee Resolution of Outstanding Issues From NRC Equipment Environ Qualification SERs (F-11 & B-60), Calvert Cliffs Nuclear Power Plant Unit 2," technical evaluation rept
PAHDEY, B Franklin Institute/Franklin Research Center
NRC-03-79-118 TER-C5257-488 82/10/13 LE, N B NRC - No
Detailed Affiliation Given 681pp 16627 001 24X
Fiche 50-317, 82/12/16, B212300041

B212210420 Forwards results of review of TMI Action Items I A 1 3, "Limit Overtime," II E 1 1, "Short Term Auxiliary Feedwater Sys Evaluation" & II E 1 2 & II K 3 Tech Spec change under review
LUNDVALL, A E Baltimore Gas & Electric Co 82/12/17 EISENHUT, D G
Division of Licensing 3pp 16493 075 24X Fiche 50-317, 82/12/17, B212210420

B212230274 Forwards response to NRC questions on pressurized level limiting conditions Tech Specs Table presenting summary of evaluation of impact of changing water level for each DBE encl
LIPPOLD, W J Baltimore Gas & Electric Co 82/12/17 CLARK, R A
Operating Reactors Branch 3 8pp 16308 265 24X
Fiche 50-317, 82/12/17, B212230274

B212230312 Responds to NRC question on Cycle 5 instrument loop uncertainties Uncertainty includes allowance for drift based on plant experience
LIPPOLD, W J Baltimore Gas & Electric Co 82/12/17 CLARK, R A
Operating Reactors Branch 3 3pp 16507 071 24X
Fiche 50-318, 82/12/17, B212230312

B212290120 Responds to NRC question re Cycle 5 instrument loop uncertainties Instrument loop uncertainty is added algebraically to setpoint of plant parameter used in safety analysis which yields value stated in Tech Specs
LIPPOLD, W J Baltimore Gas & Electric Co 82/12/17 CLARK, R A
Operating Reactors Branch 3 2pp 16583 226 24X
Fiche 50-318, 82/12/17, B212290120

B212280199 Application for amend to License DPR-69, changing measurement range for Tech Spec Table 3 3-9 re remote shutdown monitoring instrumentation Class III fee encl
LUNDVALL, A E Baltimore Gas & Electric Co 82/12/23 CLARK, R A
Operating Reactors Branch 3 4pp 16562 289 24X
Fiche 50-318, 82/12/23, B212280199

--B212280202 Proposed changes to Tech Spec Table 3 3-9 re measurement range changes to remote shutdown monitoring instrumentation
* Baltimore Gas & Electric Co 82/12/23 ip 16562 293 24X
Fiche 50-318, 82/12/23, B212280199

B212290122 Forwards response to NRC question re impact of NRC-imposed FATES3 grain size restriction on Cycle 5 operating limits
LIPPOLD, W J Baltimore Gas & Electric Co 82/12/27 CLARK, R A
Operating Reactors Branch 3 2pp 16583 208 24X
Fiche 50-318, 82/12/27, B212290122

G Inspection reports, IE Bulletins & correspondence

B208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel Recirculation Sys Piping at BWR Plants" Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc
112pp 16462 163 24X Fiche 50-000, 82/10/28, B208190240

B208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters" Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards
82/11/05 Consolidated Edison Co of New York, Inc 110pp
16372 142 24X Fiche 50-000, 82/11/05, B208190245

B208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements" Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18
Consolidated Edison Co of New York, Inc 109pp 16411 199 24X
Fiche 50-000, 82/11/18, B208190251

B212020003 Notification of B21214 significant licensee meeting w/util in Lusby, MD to discuss SALP
MCABE, E Region 1, Office of Director 82/11/19 Region 1,
Office of Director 1p 16317 089 24X Fiche 50-317, 82/11/19, B212020003

B212080031 Provides relief from ASME Boiler & Vessel Code, Section XI requirement re hydrostatic test pressure, found impractical in B20830 application Acceptable alternate test method approved in accordance w/10CFR50.55a
CLARK, R A Operating Reactors Branch 3 82/11/19 LUNDVALL, A E
Baltimore Gas & Electric Co 2pp 16367 147 24X
Fiche 50-318, 82/11/19, B212080031

DOCKETED ITEMS

--8212080036 SER supporting 820830 request for relief from pressure testing requirements of ASME Boiler & Pressure Vessel Code after mod of auxiliary feedwater sys piping & components
* Office of Nuclear Reactor Regulation, Director 82/11/19 3pp
16367 149 24X Fiche 50-318, 82/11/19, 8212080031

--8212080040 Notice of granting of relief from ASME Section XI, inservice insp requirements
CLARK, R A Operating Reactors Branch 3 82/11/19 2pp
16367 152 24X Fiche 50-318, 82/11/19, 8212080031

8212100007 Forwards IE Insp Repts 50-317/82-27 & 50-318/82-23 on 821012-1109 & notice of violation
STAROSTECKI, R Division of Project & Resident Programs 82/11/24
LUNDVALL, A E Baltimore Gas & Electric Co 2pp 16379 133 24X
Fiche 50-317, 82/11/24, 8212100007

--8212100010 Notice of violation from insp on 821012-1109
* Region 1, Office of Director 82/11/24 1p 16379 135 24X
Fiche 50-317, 82/11/24, 8212100007

- 8212100013 IE Insp Repts 50-317/82-27 & 50-318/82-23 on 821012-1109
Noncompliance noted Unit 2 placed in Mode 6 w/o operable audible indication of source range neutron flux in control room
ARCHITZEL, R E, TRIMBLE, D C, MCCABE, E C Division of Project & Resident Programs 82/11/17 13pp 16379 136 24X
Fiche 50-317, 82/11/24, 8212100007

8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc
127pp 16411 045 24X Fiche 50-000, 82/11/26, 8208190256

8208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp
16387 028 24X Fiche 50-000, 82/11/30, 8208190257

8212060285 Ack receipt of 821028 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-317/82-07 & 50-318/82-07
STAROSTECKI, R Division of Project & Resident Programs 82/12/02
LUNDVALL, A E Baltimore Gas & Electric Co 1p 16312 059 24X
Fiche 50-317, 82/12/02, 8212060285

--8212060293 Responds to NRC 820929 ltr re violations noted in IE Insp Repts 50-317/82-07 & 50-318/82-07 Corrective actions audit by OA of selected plant procedures which incorporate Tech Spec limits completed
LUNDVALL, A E Baltimore Gas & Electric Co 82/10/28
STAROSTECKI, R Division of Project & Resident Programs 3pp
16312 060 24X Fiche 50-317, 82/12/02, 8212060285

8208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc
113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259

8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 044 24X
Fiche 50-000, 82/12/03, 8208190261

8212170349 Informs of results of Nov 1982 steam generator eddy current tests Two tubes, one each in steam generators 21 & 22 sludge areas, showed excessive tube wall loss Tubes removed from svc by plugging ends w/mechanical plugs
LUNDVALL, A E Baltimore Gas & Electric Co 82/12/09 DEYOUNG, R C
Director's Office, Office of Inspection and Enforcement 2pp
16456 113 24X Fiche 50-318, 82/12/09, 8212170349

8212160384 Forwards response to 820914 request to suppl response to IE Bulletin 80-11, "Masonry Wall Design " One oversize drawing encl Aperture card available in PDR
LUNDVALL, A E Baltimore Gas & Electric Co 82/12/13 CLARK, R A
Operating Reactors Branch 3 9pp 16442 151 24X
Fiche 50-317, 82/12/13, 8212160384

8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc
127pp 16428 191 24X Fiche 50-000, 82/12/16, 8208190267

8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type 17E-27 " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16428 293 24X
Fiche 50-000, 82/12/20, 8208190268

8212280200 Ack receipt of 821027 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Repts 50-317/82-18 & 50-318/82-22
MARTIN, T T Division of Engineering & Technical Programs 82/12/21
BOWMAKER, N J Baltimore Gas & Electric Co 2pp 16562 093 24X
Fiche 50-317, 82/12/21, 8212280200

--8212280208 Responds to NRC 821008 ltr re violations noted in IE Safeguards Insp Repts 50-317/82-18 & 50-318/82-22 Corrective actions withheld (ref 10CFR73.21)
BOWMAKER, N J Baltimore Gas & Electric Co 82/10/27 MARTIN, T T
Division of Engineering & Technical Programs 1p 16562 095
24X Fiche 50-317, 82/12/21, 8212280200

8212290338 Forwards fee for inservice insp program request for relief from ASME Code Section XI re hydrostatic pressure testing requirements for mods made to safety-related sys Request classified & flow diagrams encl
LUNDVALL, A E Baltimore Gas & Electric Co 82/12/21 CLARK, R A
Operating Reactors Branch 3 5pp 16586 212 24X
Fiche 50-318, 82/12/21, 8212290338

R Periodic operating reports & related correspondence

8212220208 Forwards monthly operating repts for Nov 1982
LOTITO, E M Baltimore Gas & Electric Co 82/12/15 Director's
Office, Office of Inspection and Enforcement 1p 16518 317 24X
Fiche 50-317, 82/12/15, 8212220208

--8212220210 Monthly operating repts for Nov 1982
LOTITO, E M Baltimore Gas & Electric Co 82/12/15 10pp
16518 318 24X Fiche 50-317, 82/12/15, 8212220208

S Reportable occurrences, LERs & related correspondence

8212060149 Nonroutine radiological environ operating rept on 821027, nuclear samples collected from Camp Canoy revealed presence of Ag-110m, less than Aug samples Probably due to degradation
FUHRMAN, G R Baltimore Gas & Electric Co 82/11/23 HAYNES, R C
Region 1, Office of Director 3pp 16313 146 24X
Fiche 50-317, 82/11/23, 8212060149

8212080456 Corrects 821123 ltr re nonroutine radiological environ operating rept Capacity factor for Oct 1982 was 105.20%, not 72.31%
FUHRMAN, G R Baltimore Gas & Electric Co 82/11/29 HAYNES, R C
Region 1, Office of Director 1p 16352 143 24X
Fiche 50-317, 82/11/29, 8212080456

8212060305 PNO-I-82-077 on 821201, contractor employee intentionally poisoned lunch & placed in refrigerator Employee notified licensee of actions upon discovering lunch missing Warning announced on page sys No known harm occurred
ARCHITZEL, MCCABE Region 1, Office of Director 82/12/01 1p
16312 111 24X Fiche 50-317, 82/12/01, 8212060305

DOCKET 50-320 THREE MILE ISLAND NUCLEAR STATION, UNIT 2

F Security, medical, emergency & fire protection plans

8212010092 Releases public version of revision to emergency plan implementing procedure
FELTON, J M Division of Rules and Records 82/11/24 Document
Management Branch 1p 16289 338 24X Fiche 50-320, 82/11/24, 8212010092

--8212010097 Public version of Revision 5 to Emergency Plan Implementing Procedure 1054.6, "Add'l Assistance & Notification "
* General Public Utilities - GPU Service Corp 82/11/05 24pp
16289 339 24X Fiche 50-320, 82/11/24, 8212010092

8212130318 Summarizes dose reduction at facility in three phases per 821118 presentation Implementation will require close coordination of recovery efforts consistent w/ALARA practices
KANDA, B K General Public Utilities - GPU Service Corp 82/12/03
BARRETT, L H TMI Program Office 4pp 16389 278 24X
Fiche 50-320, 82/12/03, 8212130318

DOCKETED ITEMS

163

B212220415 Forwards listings of major employers within facility emergency planning zone, in response to NRC request
MCKELVY, G A General Public Utilities - GPU Service Corp 82/12/08
KANTOR, F NRC - No Detailed Affiliation Given 7pp 16504 001
24X Fiche 50-289, 82/12/08, 8212220415

--B212220421 Forwards listings of hotels, motels, campgrounds & marinas within facility emergency planning zone
MCKELVY, G A General Public Utilities - GPU Service Corp 82/11/16
KANTOR, F NRC - No Detailed Affiliation Given 7pp
16504 008 24X Fiche 50-289, 82/12/08, 8212220415

G212160745 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 82/12/10 Document
Management Branch 1p 16464 165 24X Fiche 50-320, 82/12/10, 8212160745

--B212160752 Forwards public version of revised Emergency Plan Implementing Procedures 1054 16, "Contaminated Injuries/Radiation Overexposure" & 1054 21, "Emergency Repair/Operations"
SHAWER, L General Public Utilities - GPU Service Corp 82/12/03
DENTON, H R NRC - No Detailed Affiliation Given 1p 16464 166
24X Fiche 50-320, 82/12/10, 8212160745

--B212160764 Public version of revised Emergency Plan Implementing Procedures 1054 16, "Contaminated Injuries/Radiation Overexposure" & 1054 21, "Emergency Repair/Operations"
KANGA, B K General Public Utilities - GPU Service Corp 82/11/23
10pp 16464 167 24X Fiche 50-320, 82/12/10, 8212160745

G212270149 Forwards interim security precautions, pending completion of requested clarification of security plan Encl withheld
(ref 10CFR 790 & 10CFR 73 21)
KANGA, B K General Public Utilities - GPU Service Corp 82/12/20
SNYDER, B J TMI Program Office 1p 16338 340 24X
Fiche 50-320, 82/12/20, 8212270149

G212280385 Ack receipt of 821108 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Rept 50-320/82-09
MARTIN, T T Division of Engineering & Technical Programs 82/12/21
KANGA, B K General Public Utilities - GPU Service Corp 2pp
16559 018 24X Fiche 50-320, 82/12/21, 8212280385

--B212280390 Responds to NRC 821008 ltr re violations noted in IE Safeguards Insp Rept 50-320/82-09 Corrective actions withheld (ref 10CFR 790 & 73 21)
KANGA, B K General Public Utilities - GPU Service Corp 82/11/08
HAYNES, R C Region 1, Office of Director 1p 16559 020 24X
Fiche 50-320, 82/12/21, 8212280385

G Adjudicatory correspondence

G212140186 Request for extension of time until 821224 to file petition for review of ALAB-701 Time necessary due to holidays, sickness & vacations Certificate of Evc encl
JOHNSRUD, J H Environmental Coalition on Nuclear Power 82/12/08
Commissioners 4pp 16403 167 24X Fiche 50-000, 82/12/08, 8212140186

G212140438 Order extending time until 821227 for TMI & Peach Bottom intervenors to file petition for review of ALAB-701
CHILK, S J Office of the Secretary of the Commission 82/12/13
Environmental Coalition on Nuclear Power 1p 16404 360 24X
Fiche 50-000, 82/12/13, 8212140438

B212210009 Advises that intervenor petition for review of ALAB-701 should be served on NRC when filed
BORDENICK, B M Hearing Branch 3 82/12/16 JOHNSRUD, J
Affiliation Unknown 2pp 16486 005 24X Fiche 50-000, 82/12/16, 8212210009

B212300134 Petition for review of consolidated radon proceedings
Commission should grant financial assistance to intervenors, should reopen record on all issues & remand case for full consideration Certificate of Evc encl
JOHNSRUD, J H Environmental Coalition on Nuclear Power 82/12/27
Commissioners 15pp 16598 112 24X Fiche 50-000, 82/12/27, 8212300134

P Operating license stage documents & correspondence

B005071094 Research Info Ltr 82 transmits preliminary results of research on socio-economic effects of TMI accident Direct economic effects include interrupted local production & reduced local income & employment
BUDNITZ, R J Office of Nuclear Regulatory Research, Director
KIL-082 80/02/29 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 16565 348 24X Fiche 50-320, 80/02/29, B005071094

B212060395 Supplemental response to B20906 FOIA request for eight categories of documents Forwards documents listed in App A for items 4 & 5 No other documents sub j to request located
FELTON, J M Division of Rules and Records 82/11/08 AUDIN, L
Affiliation Unknown 2pp 16322 342 24X Fiche 50-320, 82/11/08, 8212060395

--B212060403 Items of interest re CRBR fuel cycle environ review, spent fuel reprocessing & TMI-2 waste mgt task force for wk ending 820709
Office of Nuclear Material Safety & Safeguards, Director
82/07/09 1p 16322 345 24X Fiche 50-000, 82/11/08, 8212060395

B212010366 Concurs that adequate radiological controls considered in B20721 plan to remove radioactive matls in once through steam generator 2B Detailed procedures (per Tech Spec 6 B 2) required for approval of final sys operation
BARRETT, L H TMI Program Office 82/11/16 KANGA, B K General Public Utilities - GPU Service Corp 3pp 16271 098 24X
Fiche 50-320, 82/11/16, 8212010366

B212270028 Responds to B21015 request for comments on Commission paper "Development of Scope of Guidelines to Facilitate Recovery Efforts in Event of Nuclear-Related Accidents at Operating Power Plants"
DENTON, H R Office of Nuclear Reactor Regulation, Director
82/11/22 HINDOQUE, R B Office of Nuclear Regulatory Research, Director 2pp 16351 344 24X Fiche 50-320, 82/11/22, 8212270028

G212020408 Submits review of util 821013 & 1111 SERs re submerged demineralizer sys liner recombiner & vacuum outgassing sys
SER acceptable
BARRETT, L H TMI Program Office 82/11/23 KANGA, B K General Public Utilities - GPU Service Corp 4pp 16297 344 24X
Fiche 50-320, 82/11/23, 8212020408

G212020405 Responds to util 821014 proposal to modify nitrogen gas inerting of shipping casks for future EPICOR II prefiler shipments Proposed change in conformance w/requirements in NRC 820723 ltr
BARRETT, L H TMI Program Office 82/11/24 KANGA, B K General Public Utilities - GPU Service Corp 2pp 16297 351 24X
Fiche 50-320, 82/11/24, 8212020405

G212020407 Submits review of 821103 suppl to reactor coolant processing plan to assess safety aspects of processing reactor coolant w/RCS in depressurized & drained down condition Approves implementation of suppl
BARRETT, L H TMI Program Office 82/11/24 KANGA, B K General Public Utilities - GPU Service Corp 1p 16297 348 24X
Fiche 50-320, 82/11/24, 8212020407

G212060015 Forwards application for amend to License DPR-73 for proposed Tech Spec Change 40, consisting of administrative control changes in areas of responsibility, organization, staff qualifications, review & audit & RO action
ARNOLD, R C General Public Utilities - GPU Service Corp 82/11/29
SNYDER, B J TMI Program Office 1p 16311 020 24X
Fiche 50-320, 82/11/29, 8212060015

--B212060019 Application to amend License DPR-73 for proposed Tech Spec Change 40, consisting of administrative control changes in areas of responsibility, organization, staff qualifications, review & audit & RO action
ARNOLD, R C General Public Utilities - GPU Service Corp ARNOLD, R
Metropolitan Edison Co ARNOLD, R Jersey Central Power & Light Co 82/11/29 2pp 16311 021 24X Fiche 50-320, 82/11/29, 8212060019

--B212060022 Proposed Tech Spec Change 40, consisting of administrative control changes in areas of responsibility, organization, staff qualifications, review & audit & RO action
General Public Utilities - GPU Service Corp 82/11/29 14pp
16311 023 24X Fiche 50-320, 82/11/29, 8212060015

B212060085 Forwards proposed organization plan, Revision 6 Mutually agreeable implementation plan will be established after approval
ARNOLD, R C General Public Utilities - GPU Service Corp 82/11/29
SNYDER, B J TMI Program Office 17pp 16314 325 24X
Fiche 50-320, 82/11/29, 8212060085

G212090004 Forwards amended sections to recovery operations plan, as approved Change 18, which changes operability requirements for airborne particulate monitor H/o encl
BARRETT, L H TMI Program Office 82/11/30 KANGA, B K General Public Utilities - GPU Service Corp 2pp 16379 359 24X
Fiche 50-320, 82/11/30, 8212090004

DOCKETED ITEMS

B212280514 "Characterization of TMI-Type Wastes & Solid Products," quarterly progress rpt for Jul-Sept 1982
 SWYLER, K J, DAYAL, R Brookhaven National Laboratory FIN A-3236
 B212280514 82/11/30 KIM, K Office of Nuclear Regulatory Research, Director 27pp 16590 115 24X Fiche 50-320, 82/11/30, B212280514

B212130059 Forwards Procedure 1000-PLN-4010 01, "GPU Nuclear Corp Radiation Protection Plan"
 KANQA, B K General Public Utilities - GPU Service Corp 82/12/06
 BARRETT, L H TMI Program Office 1p 16391 168 24X
 Fiche 50-320, 82/12/06, B212130059

--B212130060 Procedure 1000-PLN-4010 01, "GPU Nuclear Corp Radiation Protection Plan," Revision 0
 HILDEBRAND, J E, LONG, R L, HUKILL, H D General Public Utilities - GPU Service Corp 82/11/05 15pp 16391 169 24X
 Fiche 50-320, 82/12/06, B212130059

B212230056 Forwards Tech Spec inadvertently omitted from NRC B21130 ltr forwarding amended sections to recovery operations plan as approved Change 18
 BARRETT, L H TMI Program Office 82/12/08 KANQA, B K General Public Utilities - GPU Service Corp 2pp 16345 333 24X
 Fiche 50-320, 82/12/08, B212230056

--B212230061 Tech Spec 4.3 re instrumentation surveillance requirements, inadvertently omitted from NRC B21130 ltr forwarding amended sections to recovery operations plan as approved Change 18
 * TMI Program Office 82/12/08 3pp 16345 335 24X
 Fiche 50-320, 82/12/08, B212230056

B208190263 Generic Ltr B2-32 to all PWR licensees re potential steam generator-related generic requirements Forwards Science Applications, Inc draft rpt re subj requirements Comments requested within 30 days of ltr Svc list encl
 EISENHUT, D O Division of Licensing 82/12/09 Consolidated Edison Co of New York, Inc 29pp 16629 247 24X
 Fiche 50-000, 82/12/09, B208190263

B212300260 Requests temporary exemption from surveillance requirements of recovery operations plan Sections 4.7.3.1.4.7.3.2 & 4.7.3.3 until RCS refilled
 KANQA, B K General Public Utilities - GPU Service Corp 82/12/09
 BARRETT, L H TMI Program Office 1p 16395 256 24X
 Fiche 50-320, 82/12/09, B212300260

B212230384 Advises that recovery operations plan Change Request 21 re suspension of selected surveillance requirements & mod to Section 4.0.2 b clarifying max time interval for testing denied
 SNYDER, B J TMI Program Office 82/12/13 KANQA, B K General Public Utilities - GPU Service Corp 3pp 16540 245 24X
 Fiche 50-320, 82/12/13, B212230384

B212210018 Informs of changes in plans for refilling RCS During refill, pressurizer will not be vented, providing added measure of protection against sys overpressurization
 KANQA, B K General Public Utilities - GPU Service Corp 82/12/14
 BARRETT, L H TMI Program Office 1p 16490 163 24X
 Fiche 50-320, 82/12/14, B212210018

B212290040 Responds to B21122 ltr re filling & pressurizing of RCS Proposed plan approved
 BARRETT, L H TMI Program Office 82/12/14 KANQA, B K General Public Utilities - GPU Service Corp 1p 16607 177 24X
 Fiche 50-320, 82/12/14, B212290040

B212300113 Discusses schedule for EPICOR II prefilter shipments Shipments should be completed by end of Third Quarter 1983 based on commitments from cask vendors Estimated 15 prefilters will be shipped by end of 1982
 KANQA, B K General Public Utilities - GPU Service Corp 82/12/15
 BARRETT, L H TMI Program Office 1p 16598 256 24X
 Fiche 50-320, 82/12/15, B212300113

B212230295 Informs of intent to commence shipping submerged demineralizer sys spent liners requiring special passification sys Info demonstrates compliance w/Certificate of Compliance 9152 for CNS I-13C II shipping container
 KANQA, B K General Public Utilities - GPU Service Corp 82/12/17
 BARRETT, L H TMI Program Office 3pp 16508 280 24X
 Fiche 50-320, 82/12/17, B212230295

B212280029 Requests proprietary drawings containing info on dimensions of all internal components of reactor vessel, thermal limits & composition of components, shear stress limits & vessel exterior drawings & dimensions
 SNYDER, B J TMI Program Office 82/12/17 KULYNYCH, O E Babcock & Wilcox Co 3pp 16593 124 24X Fiche 50-320, 82/12/17, B212280029

B212300190 Requests remittance of Class III fee for review of B20419 & 0707 applications to separate auxiliary bldg & fuel handling bldg air cleanup exhaust sys, approved B20924
 DIGGS, R M License Fee Management Branch 82/12/17 BARTON, J J General Public Utilities - GPU Service Corp 1p 16624 033 24X
 Fiche 50-320, 82/12/17, B212300190

G Inspection Reports, IE Bulletins & correspondence

B208190240 IE Bulletin B2-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel Recirculation Sys Piping at BWR Plants" Svc list encl
 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, B208190240

B208190245 IE Info Notice B2-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters" Svc list encl
 COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000, 82/11/05, B208190245

B208190251 IE Info Notice B2-44, "Clarification of Emergency Plan Exercise Requirements" Svc list encl
 JORDAN, E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X
 Fiche 50-000, 82/11/18, B208190251

B212070106 Forwards IE Insp Rept 50-320/82-13 on B21010-1106 No noncompliance noted
 STAROSTECKI, R Division of Project & Resident Programs 82/11/23 KANQA, B K General Public Utilities - GPU Service Corp 2pp 16327 334 24X Fiche 50-320, 82/11/23, B212070106

--B212070111 IE Insp Rept 50-320/82-13 on B21010-1106 No noncompliance noted Major areas inspected licensee action on previous insp findings, routine plant operations, health physics & environ areas & reactor bldg entries
 WIEBE, J, BARR, K, O'NEILL, B Division of Project & Resident Programs 82/11/22 6pp 16327 336 24X Fiche 50-320, 82/11/23, B212070106

B208190256 IE Info Notice B2-46, "Defective & Obsolete Combination Padlocks" Svc list encl
 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000, 82/11/26, B208190256

B208190257 IE Info Notice B2-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl" Svc list encl
 COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000, 82/11/30, B208190257

B212140311 Forwards IE Insp Rept 50-320/82-12 on B20912-1009 & notice of violation
 STAROSTECKI, R Division of Project & Resident Programs 82/11/30 KANQA, B K General Public Utilities - GPU Service Corp 3pp 16402 057 24X Fiche 50-320, 82/11/30, B212140311

--B212140315 Notice of violation from insp on B20912-1009
 * Division of Project & Resident Programs 82/11/30 1p 16402 060 24X Fiche 50-320, 82/11/30, B212140311

--B212140319 IE Insp Rept 50-320/82-12 on B20912-1009 Noncompliance noted procedures/instructions or procedure changes affecting quality not technically adequate
 CONTE, R, MOSLAK, T, O'NEILL, B Division of Project & Resident Programs 82/11/04 17pp 16402 061 24X Fiche 50-320, 82/11/30, B212140311

B208190259 IE Bulletin B2-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies" Svc list encl
 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, B208190259

B208190261 IE Info Notice B2-48, "Failures of Agastat CR 0095 Relay Sockets" Svc list encl
 JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X
 Fiche 50-000, 82/12/03, B208190261

B208190267 IE Info Notice B2-49, "Correction for Sample Conditions for Air & Gas Monitoring" Svc list encl
 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16, B208190267

B*08190268 IC Info Notice B2-50, "Mod of Solid State AC Undervoltage
(relays Type ITE-27 ' Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20
Consolidated Edison Co. of New York, Inc 108pp 16628 293 24X
Fiche 50-300, 82/12/20, B208190268

B*12280385 Act receipt of B21108 ltr informing NRC of steps taken to
correct violations noted in IE Safeguards Insp Rept
50-320/B2-09
MARTIN, T T Division of Engineering & Technical Programs 82/12/21
KANOA, B K General Public Utilities - GPU Service Corp 2pp
16559 018 24X Fiche 50-320, 82/12/21, B212280385

--G212280390 Responds to NRC B21008 ltr re violations noted in IE
Safeguards Insp Rept 50-320/B2-09 Corrective actions
withheld (ref 10CFR2 790 & 73 21)
KANOA, B K General Public Utilities - GPU Service Corp 82/11/08
HAYNES, R C Region 1, Office of Director 1p 16559 020 24X
Fiche 50-320, 82/12/21, B212280385

B*12290350 Act receipt of B21130 ltr informing NRC of steps taken to
correct violations noted in IE Investigation Rept
50-320/79-10
STAROSTECKI, R Division of Project & Resident Programs 82/12/22
KANOA, B K General Public Utilities - GPU Service Corp 2pp
16586 236 24X Fiche 50-320, 82/12/22, B212290350

--B212290353 Responds to NRC B01121 ltr re violations noted in IE
Investigation Rept 50-320/79-10 Corrective actions periodic
review of applicable procedures will be conducted to assure
operability verification criteria
KANOA, B K General Public Utilities - GPU Service Corp 82/11/30
HAYNES, R C Region 1, Office of Director 2pp 16586 238 24X
Fiche 50-320, 82/12/22, B212290350

K Periodic operating reports & related correspondence

B*12100176 Submits TMI Program Ofc weekly status rept for wk of
B21031-1106
BARRETT, L H TMI Program Office 82/11/08 DENTON, H R Office of
Nuclear Reactor Regulation, Director SNYDER, B J TMI Program
Office 6pp 16398 352 24X Fiche 50-320, 82/11/08, B212100176

B*12100170 Submits TMI Program Ofc weekly status rept for wk of
B21107-13
BARRETT, L H TMI Program Office 82/11/15 DENTON, H R Office of
Nuclear Reactor Regulation, Director SNYDER, B J TMI Program
Office 7pp 16398 342 24X Fiche 50-320, 82/11/15, B212100170

B*12030113 Forwards "Effluent Summary, TMI-2 Liquid & Gaseous Effluents,
Jul-Sept 1982 " Rept doses extracted from calculational
models & are bounding doses for all cases
KANOA, B K General Public Utilities - GPU Service Corp 82/11/19
HAYNES, R C Region 1, Office of Director 1p 16303 016 24X
Fiche 50-320, 82/11/19, B212030113

--B212030120 "Effluent Summary, TMI-2 Liquid & Gaseous Effluents, Jul-Sept
1982 "
* General Public Utilities - GPU Service Corp 82/11/19 5pp
16303 017 24X Fiche 50-320, 82/11/19, B212030113

B*12130154 Forwards TMI Program Ofc weekly status rept for wk of
B21114-20
BARRETT, L H TMI Program Office 82/11/22 DENTON, H R Office of
Nuclear Reactor Regulation, Director SNYDER, B J TMI Program
Office 8pp 16410 317 24X Fiche 50-320, 82/11/22, B212130154

B*12070143 Errata to "Annual Environ Operating Rept for 1981 " Extent &
nature of herbicide application corrected
KANOA, B K General Public Utilities - GPU Service Corp 82/11/29
HAYNES, R C Region 1, Office of Director 1p 16327 079 24X
Fiche 50-320, 82/11/29, B212070143

B*12270019 Forwards TMI Program Ofc weekly status rept for wk of
B21121-1204
BARRETT, L H TMI Program Office 82/12/06 DENTON, H R Office of
Nuclear Reactor Regulation, Director SNYDER, B J TMI Program
Office 8pp 16591 309 24X Fiche 50-320, 82/12/06, B212270019

B*12280519 Forwards TMI program ofc weekly status rept for wk of
B21205-11
BARRETT, L H TMI Program Office 82/12/13 DENTON, H R Office of
Nuclear Reactor Regulation, Director SNYDER, B J TMI Program
Office 7pp 16572 357 24X Fiche 50-320, 82/12/13, B212280519

B*12300101 Forwards TMI Program Ofc weekly status rept for wk of
B21212-18
BARRETT, L H TMI Program Office 82/12/20 DENTON, H R Office of
Nuclear Reactor Regulation, Director SNYDER, B J TMI Program
Office 7pp 16624 234 24X Fiche 50-320, 82/12/20, B212300101

S Reportable occurrences, LERs & related correspondence

B212060322 Forwards LER B2-034/01L-O
KANOA, B K General Public Utilities - GPU Service Corp 82/11/21
HAYNES, R C Region 1, Office of Director 1p 16312 082 24X
Fiche 50-320, 82/11/22, B212060322

--B212060326 LER B2-034/01L-O on B21021, A & B once through steam
generator (QTSO) level indications failed Caused by
separated electrical connector, failed power supply &
inadequate procedure Level indicator repaired & calibr
CHAPLIN, S D General Public Utilities - GPU Service Corp
82/11/22 Region 1, Office of Director 3pp 16312 083 24X
Fiche 50-320, 82/11/22, B212060322

B212150038 Forwards LER B2-036/03L-O
KANOA, B K General Public Utilities - GPU Service Corp 82/12/01
HAYNES, R C Region 1, Office of Director 1p 16421 251 24X
Fiche 50-320, 82/12/01, B212150038

--B212150044 LER B2-036/03L-O on B21028, tested smoke detectors failed to
provide required trip functions & alarms Caused by high
voltage dc power supply failing to provide proper voltage
due to capacitor failure Capacitor replaced
CHAPLIN, S D General Public Utilities - GPU Service Corp
82/12/01 Region 1, Office of Director 2pp 16421 252 24X
Fiche 50-320, 82/12/01, B212150038

B*12220449 Forwards LER B2-035/01L-O
KANOA, B K General Public Utilities - GPU Service Corp 82/12/10
HAYNES, R C Region 1, Office of Director 1p 16503 238 24X
Fiche 50-320, 82/12/10, B212220449

--B212220454 LER B2-035/01L-O on B21110, reactor bldg sump level indicator
observed reading high Caused by buildup of sludge in end of
sump indicator Indicator line blown free w/20 lb of
pressure
CHAPLIN, S D General Public Utilities - GPU Service Corp
82/12/10 Region 1, Office of Director 3pp 16503 239 24X
Fiche 50-320, 82/12/10, B212220449

B*12290233 Forwards LER B2-037/01L-O
KANOA, B K General Public Utilities - GPU Service Corp 82/12/15
HAYNES, R C Region 1, Office of Director 1p 16582 112 24X
Fiche 50-320, 82/12/15, B212290233

--B212290240 LER B2-037/01L-O on B21115, once-through steam generator
level indication failed low Cause unknown Instrumentation
verified operable & returned to svc
CHAPLIN, S D General Public Utilities - GPU Service Corp
82/12/15 Region 1, Office of Director 3pp 16582 113 24X
Fiche 50-320, 82/12/15, B212290233

B*12270233 PHO-TMI-B2-021 on B21219, while replacing aircraft warning
lights, employee fell from natural draft cooling tower &
listed in serious condition at local hosp
WIEDE, J J, FASANO, A J, BARRETT, L H Region 1, Office of Director
82/12/20 1p 16537 206 24X Fiche 50-320, 82/12/20, B212270233

I Hearing transcripts on non-antitrust matters

B212270475 Transcript of Advisory Panel on Decontamination of TMI-2
B21117 meeting in Harrisburg, PA pp J-109
* Commissioners 82/11/17 11pp 16571 182 24X
Fiche 50-320, 82/11/17, B212270475

DOCKET 50-321 EDWIN I HATCH NUCLEAR PLANT, UNIT 1

F Security, medical, emergency & fire protection plans

B*12150009 Confirms telcon re emergency facility status per Generic
Ltr B2-10 Structure complete & habitable Info equipment not
completely installed, but facility operable
BECKHAM, J T Georgia Power Co 82/12/08 Office of Nuclear
Reactor Regulation, Director 1p 16421 138 24X
Fiche 50-321, 82/12/08, B212150009

J Insurance & indemnity information

B*12280222 Forwards ANI & MAELU secondary financial protection
certificates of insurance N-51, N-67, M-51 & M-67
BUCK, J R Marsh & McLennan, Inc (H & M Nuclear Consultants, Inc Div
82/12/20 SALTZMAN, J Assistant Director for State & License
Relations 41pp 16562 135 24X Fiche 50-321, 82/12/20, B212280222

DOCKETED ITEMS

B212280367 Forwards Endorsement 74 to NELIA Policy NF-215 & Endorsement 60 to MAELV Policy MF-78
 DUCK, J R Marsh & McLennan, Inc , M & M Nuclear Consultants, Inc Div
 82/12/20 SALTZMAN, J Assistant Director for State & Licensee
 Relations 3pp 16560 067 24X Fiche 50-321, 82/12/20, B212280367

P Operating license stage documents & correspondence

B212100393 Requests verification that encl acceptance criteria for NUREG-0737, Item II K 3 22, "Automatic Switchover of RCIC Sys Suction," satisfied Response requested within 30 days
 STOLZ, J F Operating Reactors Branch 4 82/08/04 BECKHAM, J T
 Georgia Power Co 4pp 16389 220 24X Fiche 50-321, 82/08/04, B212100393

B21230066 Generic Ltr 82-27 to all BWR licensees of operating reactors except LACBWR, Big Rock Point, Dresden 1, Humboldt Bay, applicants for OL & holders of CP re transmittal of NUREG-0763 & NUREG-0783 Svc list encl W/o stated encl
 EISENHUT, D G Division of Licensing 82/11/15 General Public
 Utilities - CPU Service Corp 22pp 16387 004 24X
 Fiche 50-000, 82/11/15, B21230066

B212170246 Advises that specific containment & purge valves identified in NRC B21110 ltr are not applicable to facilities Meeting requested to determine status of remaining issue re purging & venting
 BECKHAM, J T Georgia Power Co 82/12/13 Office of Nuclear
 Reactor Regulation, Director 1p 16457 178 24X
 Fiche 50-321, 82/12/13, B212170246

B212290450 Informs of post-implementation review of NUREG-0737, Items I F 1 A, I F 1 5 & I F 1 6 re containment pressure, water level & hydrogen monitors Addl info & guidance for answering questions encl
 STOLZ, J F Operating Reactors Branch 4 82/12/17 BECKHAM, J T
 Georgia Power Co 10pp 16606 074 24X Fiche 50-321, 82/12/17, B212290450

B212290151 Revises estimated completion date for implementation of NUREG-0737, Item II B 3 to 830401, in response to Generic Ltr 82-05 Interim sampling capabilities per NUREG-0578 provided in B20607 ltr
 GUCHA, L T Georgia Power Co 82/12/20 Office of Nuclear Reactor
 Regulation, Director 1p 16582 239 24X Fiche 50-321, 82/12/20, B212290151

Q Inspection reports, IE Bulletins & correspondence

B208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Svc list encl
 DEYOUNG, R C Director's Office, Office of Inspection and
 Enforcement 82/10/28 Consolidated Edison Co of New York, Inc
 112pp 16462 163 24X Fiche 50-000, 82/10/28, B208190240

B208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list encl
 COBB, L I Division of Fuel Facilities, Materials & Safeguards
 82/11/05 Consolidated Edison Co of New York, Inc 110pp
 16372 142 24X Fiche 50-000, 82/11/05, B208190245

B208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl
 JORDAN, E L Division of Engineering & Quality Assurance 82/11/18
 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X
 Fiche 50-000, 82/11/18, B208190251

B208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Radiacks " Svc list encl
 DEYOUNG, R C Director's Office, Office of Inspection and
 Enforcement 82/11/26 Consolidated Edison Co of New York, Inc
 127pp 16411 065 24X Fiche 50-000, 82/11/26, B208190256

B208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl
 COBB, L I Division of Fuel Facilities, Materials & Safeguards
 82/11/30 Consolidated Edison Co of New York, Inc 356pp
 16387 028 24X Fiche 50-000, 82/11/30, B208190257

B212090127 Informs that visual insp conducted on spargers & associated piping & bracket lug, per IE Bulletin 80-13, "Cracking in Core Spray Spargers " No cracking observed
 GUCHA, L T Georgia Power Co. 82/11/30, O'REILLY, J P Region 2,
 Office of Director 1p 16337 234 24X Fiche 50-321, 82/11/30, B212090127

B212090492 Requests extension until 821215 for submittal of response to IE Bulletin 82-03 re inservice insp of reactor recirculation sys piping Request granted per B21124 telcon
 GUCHA, L T Georgia Power Co 82/11/30 O'REILLY, J P Region 2,
 Office of Director 1p 16363 287 24X Fiche 50-321, 82/11/30, B212090492

B208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl
 DEYOUNG, R C Director's Office, Office of Inspection and
 Enforcement 82/12/03 Consolidated Edison Co of New York, Inc
 113pp 16411 317 24X Fiche 50-000, 82/12/03, B208190259

B208190261 IE Info Notice 82-48, "Failures of Agastat CR 0075 Relay Sockets " Svc list encl
 JORDAN, E L Division of Engineering & Quality Assurance 82/12/03
 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X
 Fiche 50-000, 82/12/03, B208190261

B208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
 DEYOUNG, R C Director's Office, Office of Inspection and
 Enforcement 82/12/16 Consolidated Edison Co of New York, Inc
 127pp 16628 191 24X Fiche 50-000, 82/12/16, B208190267

B208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27 " Svc list encl
 JORDAN, E L Division of Engineering & Quality Assurance 82/12/20
 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X
 Fiche 50-000, 82/12/20, B208190268

B212300189 Advises that NRC has no objection to use of 1980 Edition of ASME Section XI & addenda through Winter 1980 for inservice insp of Category B-H welded supports, in response to B20830 request for relief from 1974 Edition requirements
 STOLZ, J F Operating Reactors Branch 4 82/12/20 BECKHAM, J T
 Georgia Power Co 2pp 16624 034 24X Fiche 50-321, 82/12/20, B212300189

R Periodic operating reports & related correspondence

B212170353 Forwards monthly operating repts for Nov 1982
 NIX, H C Georgia Power Co 82/12/07 Director's Office, Office
 of Inspection and Enforcement 1p 16459 191 24X
 Fiche 50-321, 82/12/07, B212170353

--B212170359 Monthly operating repts for Nov 1982
 SMITH, A Georgia Power Co 82/12/07 10pp 16459 192 24X
 Fiche 50-321, 82/12/07, B212170359

S Reportable occurrences, LERs & related correspondence

B212030170 Forwards revised LER 82-089/O1X-1
 NIX, H C Georgia Power Co 82/11/18 O'REILLY, J P Region 2,
 Office of Director 1p 16303 280 24X Fiche 50-321, 82/11/18, B212030170

--B212030174 Revised LER 82-089/O1X-1 on 821026 & 1104, during refueling shutdown, rejectable linear indications discovered on welds on RHR suction line from recirculation loop B & on loops A & B of recirculation sys piping Cause unknown
 SUMNER, H L Georgia Power Co 82/11/18 Region 2, Office of
 Director 2pp 16303 281 24X Fiche 50-321, 82/11/18, B212030170

B212070297 RO 50-321/1982-02 on 821014, smoke detection for control room & sprinkler sys isolated due to mod activities Smoke detectors disconnected due to dust created by chipping activities causing spurious alarms
 NIX, H C Georgia Power Co 82/11/23 O'REILLY, J P Region 2,
 Office of Director 2pp 16339 114 24X Fiche 50-321, 82/11/23, B212070297

B212090216 Forwards LER 82-085/O3L-0
 NIX, H C Georgia Power Co 82/11/23 O'REILLY, J P Region 2,
 Office of Director 1p 16363 002 24X Fiche 50-321, 82/11/23, B212090216

--B212090219 LER 82-085/O3L-0 on 821103, walkdown of TIP withdrawal LSF1 logic relay wiring revealed two wires installed onto wrong relay Caused by incorrect relay connection diagram Wires will be terminated to correct terminal relays
 SUMNER, H L Georgia Power Co 82/11/23 Region 2, Office of
 Director 1p 16363 003 24X Fiche 50-321, 82/11/23, B212090219

B212090330 Forwards updated LER 79-082/O3X-2
 NIX, H C Georgia Power Co 82/11/23 O'REILLY, J P Region 2,
 Office of Director 1p 16365 123 24X Fiche 50-321, 82/11/23, B212090330

--B212090341 Updated LER 79-082/03X-2 on 790825-27, attempt to perform RCIC pump operability procedure unsuccessful when turbine failed to trip upon manual signal. Caused by burned out turbine trip actuator coils & binding assembly
TIPPS, S B Georgia Power Co 82/11/23 Region 2, Office of Director 1p 16365 124 24X Fiche 50-321, 82/11/23, 8212090330

G212090379 RD 50-321/1979-021, Revision 5 Provides updated data on tritium levels in groundwater samples taken from locations where average value over third quarter of 1982 exceeded samples per ETS Table 3 2-3
NIX, H C Georgia Power Co 82/11/23 O'REILLY, J P Region 2, Office of Director 4pp 16364 262 24X Fiche 50-321, 82/11/23, 8212090379

G212090140 Forwards LER 82-097/01T-O Detailed event analysis encl
NIX, H C Georgia Power Co 82/11/30 O'REILLY, J P Region 2, Office of Director 2pp 16359 174 24X Fiche 50-321, 82/11/30, 8212090140

--B212090145 LER 82-097/01T-O on 821116, spent fuel rod broken during visual insp of several spent fuel bundles. Caused by severely degraded cladding at point of separation due to corrosion. Rod will be placed back into bundle & bundle flagged
SUMNER, H L Georgia Power Co 82/11/30 Region 2, Office of Director 1p 16359 176 24X Fiche 50-321, 82/11/30, 8212090140

G212090202 Forwards updated LER 80-098/03X-1
NIX, H C Georgia Power Co 82/11/30 O'REILLY, J P Region 2, Office of Director 1p 16362 361 24X Fiche 50-321, 82/11/30, 8212090202

--B212090207 Updated LER 80-098/03X-1 on 800816, while performing suppression chamber to drywell vacuum breaker sys operability procedure, one closed indication lamp on vacuum breaker H failed to extinguish
TIPPS, S B Georgia Power Co 82/11/30 Region 2, Office of Director 1p 16362 362 24X Fiche 50-321, 82/11/30, 8212090202

G212140269 Forwards updated LER 81-095/03X-1
NIX, H C Georgia Power Co 82/11/30 O'REILLY, J P Region 2, Office of Director 1p 16401 019 24X Fiche 50-321, 82/11/30, 8212140269

--G212140271 Updated LER 81-095/03X-1 on 810908, RCIC steam line differential pressure switch N018 found actuating above Tech Spec. Caused by setpoint drift. Switch recalibr, tested & returned to svc
TIPPS, S B Georgia Power Co 82/11/30 Region 2, Office of Director 1p 16401 020 24X Fiche 50-321, 82/11/30, 8212140269

G21210083 Forwards LER 82-093/03L-0
NIX, H C Georgia Power Co 82/12/02 O'REILLY, J P Region 2, Office of Director 1p 16493 036 24X Fiche 50-321, 82/12/02, 821210083

--B21210088 LER 82-093/03L-0 on 821107, liquid radwaste discharge monitor auto control to discharge isolation valve found inoperable during liquid radwaste discharge. Caused by jumper not being removed after completion of corrective maint. Jumper removed
TIPPS, S B Georgia Power Co 82/12/02 Region 2, Office of Director 1p 16493 037 24X Fiche 50-321, 82/12/02, 821210083

G212150007 Forwards updated LER 81-131/03X-1
NIX, H C Georgia Power Co 82/12/07 O'REILLY, J P Region 2, Office of Director 1p 16421 136 24X Fiche 50-321, 82/12/07, 8212150007

--B212150011 Updated LER 81-131/03X-1 on 811202, during HPCI steamline pressure switch test, N001D switch actuated at 106 psig. Caused by setpoint drift. Switches recalibr
TIPPS, S B Georgia Power Co 82/12/07 Region 2, Office of Director 1p 16421 137 24X Fiche 50-321, 82/12/07, 8212150007

G212150014 Forwards updated LER 80-114/03X-1
NIX, H C Georgia Power Co 82/12/07 O'REILLY, J P Region 2, Office of Director 1p 16421 178 24X Fiche 50-321, 82/12/07, 8212150014

- B212150018 Updated LER 80-114/03X-1 on 801027, during HPCI steamline pressure switch test, N001A & C switches actuated at 103 psig & H031B & D switches actuated at 106 psig. Caused by setpoint drift. Switches recalibr
TIPPS, S B Georgia Power Co 82/12/07 Region 2, Office of Director 1p 16421 179 24X Fiche 50-321, 82/12/07, 8212150014

G212150031 Forwards updated LER 80-059/03X-1
NIX, H C Georgia Power Co 82/12/07 O'REILLY, J P Region 2, Office of Director 1p 16421 246 24X Fiche 50-321, 82/12/07, 8212150031

--B212150037 Updated LER 80-059/03X-1 on 800617, 2-h after performance of suppression chamber to drywell vacuum breaker sys operability procedure, closed indication F vacuum breaker light found extinguished. Caused by burned out lamp
TIPPS, S B Georgia Power Co 82/12/07 Region 2, Office of Director 1p 16421 247 24X Fiche 50-321, 82/12/07, 8212150031

G212170092 Forwards updated LER 81-109/03X-1
NIX, H C Georgia Power Co 82/12/07 O'REILLY, J P Region 2, Office of Director 1p 16452 332 24X Fiche 50-321, 82/12/07, 8212170092

--B212170099 Updated LER 81-109/03X-1 on 810929, surveillance test indicated HPCI steam line pressure switches N001A & N001D actuated at 103 & 105 psig, respectively, contrary to Tech Specs. Caused by setpoint drift. Barksdale switches recalibr
TIPPS, S B Georgia Power Co 82/12/07 Region 2, Office of Director 1p 16452 333 24X Fiche 50-321, 82/12/07, 8212170092

G212170166 Forwards revised LER 80-003/03X-1
NIX, H C Georgia Power Co 82/12/07 O'REILLY, J P Region 2, Office of Director 1p 16459 343 24X Fiche 50-321, 82/12/07, 8212170166

--G212170202 Revised LER 80-003/03X-1 on 800105, while performing RHV valve operability procedure, outboard shutdown cooling isolation valve F008 opened in 25 S-S. Caused by normal wear & human reaction time. Valve operator adjusted
TIPPS, S B Georgia Power Co 82/12/07 Region 2, Office of Director 1p 16459 344 24X Fiche 50-321, 82/12/07, 8212170166

G212210188 Forwards LER 82-098/03L-0
NIX, H C Georgia Power Co 82/12/07 O'REILLY, J P Region 2, Office of Director 1p 16484 351 24X Fiche 50-321, 82/12/07, 8212210188

--B212210196 LER 82-098/03L-0 on 821108, discovered that liquid radwaste monitor instrument procedures not performed monthly. Caused by inadequate procedures. Correct procedures performed monthly
TIPPS, S B Georgia Power Co 82/12/07 Region 2, Office of Director 1p 16484 352 24X Fiche 50-321, 82/12/07, 8212210188

G212150090 PND-11-82-134 on 821208, bomb threat received while in final preparation for full scale emergency drill. Security determined call came from security guard posted at entry gate to owner controlled area. Guard fired & arrested
TILLMAN, A, McGUIRE, D R Region 2, Office of Director 82/12/09 2pp 16430 167 24X Fiche 50-321, 82/12/09, 8212150090

G212280387 Forwards LER 82-090/03L-0
NIX, H C Georgia Power Co 82/12/14 O'REILLY, J P Region 2, Office of Director 1p 16558 355 24X Fiche 50-321, 82/12/14, 8212280387

--B212280392 LER 82-090/03L-0 on 821116, during hydraulic shock & sway arrestor insp & functional test procedure, snubber found inoperable. Caused by component failure due to worn piston rod seal. Snubber replaced & returned to operable status
TIPPS, S B Georgia Power Co 82/12/14 Region 2, Office of Director 1p 16558 356 24X Fiche 50-321, 82/12/14, 8212280387

G212300091 Forwards updated LER 80-058/03X-1
NIX, H C Georgia Power Co 82/12/16 O'REILLY, J P Region 2, Office of Director 1p 16599 032 24X Fiche 50-321, 82/12/16, 8212300091

--B212300095 Updated LER 80-058/03X-1 on 800616, during steady-state operation, control rod drive units could not maintain required pressure. Caused by cartridge valve 1C11-F111 leaking at steam packing. Valves rebuilt
TIPPS, S B Georgia Power Co 82/12/16 Region 2, Office of Director 1p 16599 033 24X Fiche 50-321, 82/12/16, 8212300091

G212300265 Forwards updated LER 80-013/03X-1
NIX, H C Georgia Power Co 82/12/16 O'REILLY, J P Region 2, Office of Director 1p 16595 206 24X Fiche 50-321, 82/12/16, 8212300265

--B212300270 Updated LER 80-013/03X-1 on 800127, reactor recirculation pump A tripped causing power reduction. Caused by electrical short circuit due to steam leak in drywell terminal board replaced & tested
TIPPS, S B Georgia Power Co 82/12/16 Region 2, Office of Director 1p 16595 207 24X Fiche 50-321, 82/12/16, 8212300265

G212300271 Forwards updated LER 81-090/01X-1
NIX, H C Georgia Power Co 82/12/16 O'REILLY, J P Region 2, Office of Director 1p 16595 250 24X Fiche 50-321, 82/12/16, 8212300271

DOCKETED ITEMS

--B212300275 Updated LER 81-090/01X-1 on 810921, performance of RCIC turbine exhaust diaphragm pressure instrument showed NO12 A-D switches actuating above Tech Spec Caused by setpoint drift Switches recaliber Design changes implemented
TIPPS, S B Georgia Power Co 82/12/16 Region 2, Office of Director 1p 16595 291 24X Fiche 50-321, 82/12/16, 8212300271

B212300277 Forwards updated LER 80-023/03X-1
NIX, H C Georgia Power Co 82/12/16 O'REILLY, J P Region 2, Office of Director 1p 16595 193 24X Fiche 50-321, 82/12/16, 8212300277

--B212300281 Updated LER 80-023/03X-1 on 800224, HPIC did not actuate until Tech Spec limit passed Caused by instrument drift Switches calibr & necessary design changes will be implemented
TIPPS, S B Georgia Power Co 82/12/16 Region 2, Office of Director 1p 16595 194 24X Fiche 50-321, 82/12/16, 8212300277

B212300287 Forwards updated LER 80-121/03X-1
NIX, H C Georgia Power Co 82/12/16 O'REILLY, J P Region 2, Office of Director 1p 16595 131 24X Fiche 50-321, 82/12/16, 8212300287

--B212300289 Updated LER 80-121/03X-1 on 801211, all points of drywell temp recorder R611 found reading high Caused by faulty slidewire contacts & printhead mechanism New points installed
TIPPS, S B Georgia Power Co 82/12/16 Region 2, Office of Director 1p 16595 132 24X Fiche 50-321, 82/12/16, 8212300289

B212300329 Forwards updated LER 80-050/03X-1
NIX, H C Georgia Power Co 82/12/16 O'REILLY, J P Region 2, Office of Director 1p 16594 232 24X Fiche 50-321, 82/12/16, 8212300329

--B212300337 Updated LER 80-050/03X-1 on 800514, RCIC turbine tripped during manual start attempt, after low reactor water level alarm & reactor half scram Caused by incorrect mode of RCIC operation Operating procedure revised
TIPPS, S B Georgia Power Co 82/12/16 Region 2, Office of Director 1p 16594 233 24X Fiche 50-321, 82/12/16, 8212300329

B212280180 RD 50-321/1982-003 on 821127, air compressor in cooling tower 1B fire protection spray sys failed, dropping air pilot detection sys pressure Dropped pressure caused activation of two deluge valves which started fire pumps
NIX, H C Georgia Power Co 82/12/17 O'REILLY, J P Region 2, Office of Director 3pp 16562 317 24X Fiche 50-321, 82/12/17, 8212280180

B212300328 Forwards LER 82-101/01T-0
NIX, H C Georgia Power Co 82/12/21 O'REILLY, J P Region 2, Office of Director 1p 16594 268 24X Fiche 50-321, 82/12/21, 8212300328

--B212300336 LER 82-101/01T-0 on 821208, bomb threat received warning of bomb in switchyard Call traced to security officer from security badge island in security headquarters Officer fired
WILKES, T C Georgia Power Co 82/12/21 Region 2, Office of Director 2pp 16594 269 24X Fiche 50-321, 82/12/21, 8212300328

DOCKET 50-322 SHOREHAM NUCLEAR POWER STATION

A Application/construction stage documents & correspondence

B208290118 FOIA request for documents re suppression pool dynamic loads for facility from 750418-1231
HAFNER, B Affiliation Unknown 82/09/22 Office of Administration 1p 16553 329 24X Fiche 50-322, 82/09/22, 8208290118

Q709150064 FOIA request for documents re suppression pool temp from 770830-1201
HAFNER, B Affiliation Unknown 82/10/06 Office of Administration 1p 16607 048 24X Fiche 50-322, 82/10/06, 8209150064

B212290006 FOIA request for documents re pool cooling mode of RHR from Mar - Oct 1981
HAFNER, B Affiliation Unknown 82/10/24 Office of Administration 1p 16607 167 24X Fiche 50-322, 82/10/24, 8212290006

B212010361 Partial response to FOIA request for documents re suppression pool dynamic loads for facility from 750418-1231 App A documents encl App B documents available at PDR.
FELTON, J M Division of Rules and Records 82/11/09 HAFNER, B Affiliation Unknown 3pp 16267 302 24X Fiche 50-322, 82/11/09, 8212010361

--B212010368 Requests info re design of containment relief valve loads Request should be filed within 90 days of receipt of ltr If schedule cannot be met, NRC should be advised within 15 days
STOLZ, J F Light Water Reactors Branch 1 75/04/21 WOFFORD, A W Long Island Lighting Co 4pp 16267 305 24X Fiche 50-322, 82/11/09, 8212010361

--B212010371 Advises that schedule for submitting requested containment design info & evaluation will be provided by wk of 750602 Schedule & program being developed in conjunction w/other utility owning Mark II containments & GE
WOFFORD, A W Long Island Lighting Co 75/05/15 STOLZ, J F Light Water Reactors Branch 1 1p 16267 309 24X Fiche 50-322, 82/11/09, 8212010361

--B212010393 Forwards list of suppression pool & relief valve drawings & info re operation of safety relief valves Description of valves under prompt relief trip & automatic depressurization sys operation will be submitted on 750915
WOFFORD, A W Long Island Lighting Co 75/07/30 STOLZ, J F Light Water Reactors Branch 1 3pp 16267 310 24X Fiche 50-322, 82/11/09, 8212010361

--B212010397 Forwards description of BWR Mark II containment supporting program presented at 750630 meeting w/NRC Support program intended to confirm preliminary forcing function rept scheduled to be submitted Sept 1975
WOFFORD, A W Long Island Lighting Co 75/08/25 STOLZ, J F Light Water Reactors Branch 1 6pp 16267 313 24X Fiche 50-322, 82/11/09, 8212010361

--B212010401 Discusses schedule for submitting five items for assessment of BWR Mark II containment structures
WOFFORD, A W Long Island Lighting Co 75/11/25 STOLZ, J F Light Water Reactors Branch 1 3pp 16267 319 24X Fiche 50-322, 82/11/09, 8212010361

B211230066 Generic Ltr 82-27 to all BWR licensees of operating reactors except LACSWR, Big Rock Point, Dresden 1, Humboldt Bay, applicants for GL & holders of CP re transmittal of NUREG-0763 & NUREG-0783 Svc list encl W/o stated encl
EISENHUT, D O Division of Licensing 82/11/15 General Public Utilities - OPU Service Corp 22pp 16387 004 24X Fiche 50-000, 82/11/15, 8211230066

B212060037 Requests response to encl evaluation of flood risk estimate within 30 days
SCHMENCER, A Licensing Branch 2 82/11/24 POLLOCK, M S Long Island Lighting Co 10pp 16343 205 24X Fiche 50-322, 82/11/24, 8212060037

B212270039 Addl response to FOIA request for documents re suppression pool dynamic loads from 750418-1231 Addl documents available in PDR Forwards index of PDR file subjs W/o encl
FELTON, J M Division of Rules and Records 82/11/24 HAFNER, B Affiliation Unknown 1p 16553 330 24X Fiche 50-322, 82/11/24, 8212270039

B212290009 Responds to FOIA request for documents re pool cooling mode of RHR from Mar - Oct 1981 NRC unable to locate documents subj to request Existing info published in SER, NUREG-0420
FELTON, J M Division of Rules and Records 82/11/24 HAFNER, B Affiliation Unknown 1p 16607 168 24X Fiche 50-322, 82/11/24, 8212290009

B212290015 Responds to FOIA request for documents re suppression pool temp from 770830-1201 Forwards 770923 ltr to DD Parr transmitting "Comparison of 1/13 Scale Mark II Containment Multivent Pool Swell Data W/Analytical Method"
FELTON, J M Division of Rules and Records 82/11/24 HAFNER, B Affiliation Unknown 1p 16607 049 24X Fiche 50-322, 82/11/24, 8212290015

B212010082 Provides substantiation of adequacy of leak test angle during postulated design basis events, per 820809 ltr Containment liner serves as pressure boundary & leak tight membrane during postulated accident
SMITH, J L Long Island Lighting Co 82/11/26 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 16260 317 24X Fiche 50-322, 82/11/26, 8212010082

B212010165 Forwards sample set of graphs typical of graphs used in plant emergency procedures, in response to verbal request Submittal closes SER Item I C B
SMITH, J L Long Island Lighting Co 82/11/26 DENTON, H R Office of Nuclear Reactor Regulation, Director 7pp 16258 087 24X Fiche 50-322, 82/11/26, 8212010165

B212130235 Board Notification 82-121 forwards evaluation of flood risk estimates as supplemental info to PRA W/o encl
NOVAK, T M Assistant Director for Licensing 82/11/25 Atomic Safety and Licensing Board Panel 6pp 16410 340 24X Fiche 50-322, 82/11/26, 8212130235

G212070219 Responds to NRC 820929 ltr requesting evaluation of concerns expressed by Future Resources Assoc re reactor bldg internal flooding sequences Internal flooding initiator is highly improbable event
SMITH, J L Long Island Lighting Co 82/12/02 DENTON, H R Office of Nuclear Reactor Regulation, Director 9pp 16335 014 24X
Fiche 50-322, 82/12/02, 8212070219

G212140339 Discusses engineering evaluations determining that leak channels retain pressure boundary integrity for load combinations which containment liner will see during design basis events
SMITH, J L Long Island Lighting Co 82/12/04 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 16401 360 24X
Fiche 50-322, 82/12/04, 8212140339

G212210224 Forwards info re adequacy of design margins of Mark I & II containment sys per NRC 820708 request Rept addresses all items w/exception of Items 3 & 3 4 Completion expected by mid-Jan 1983
SMITH, J L Long Island Lighting Co 82/12/09 DENTON, H R Office of Nuclear Reactor Regulation, Director 25p 16484 202 24X
Fiche 50-322, 82/12/09, 8212210224

G212170069 Notification of 821215 meeting w/uttl & BNL in Brookhaven, NY to discuss seismic qualification review team open items
WEINKAM, E J Licensing Branch 2 82/12/13 SCHWENCER, A Licensing Branch 2 3pp 16480 351 24X Fiche 50-322, 82/12/13, 8212170069

G212210338 Assures that uttl will continue to maintain safe & reliable facility per General Design Criterion 1 Commitment discussed
POLLOCK, M S Long Island Lighting Co 82/12/16 NOVAK, T H Assistant Director for Licensing 3pp 16497 026 24X
Fiche 50-322, 82/12/16, 8212210338

E NRC Safety Evaluation Report (SER), suppl & correspondence

G211080125 Forwards Revision 4 to S&W "Environ Qualification Rept for Class IE Equipment for Shoreham Nuclear Power Station - Unit 1, Long Island Lighting Co," consisting of changes to Appx B, F, & H, to resolve SER Issue 9
SMITH, J L Long Island Lighting Co 82/11/03 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 15981 123 24X
Fiche 50-322, 82/11/03, 8211080125

--8211090129 Revision 4 to "Environ Qualification Rept for Class IF Equipment for Shoreham Nuclear Power Station - Unit 1, Long Island Lighting Co" One aperture card available in PDR
* Stone & Webster, Inc 82/10/31 2247pp 15981 126 24X
Fiche 50-322, 82/11/03, 8211090129

G212010005 Forwards request for specific info re multiple control sys failure issue addressed in 820827 ltr, per SER Section 7 7
SCHWENCER, A Licensing Branch 2 82/11/24 POLLOCK, M S Long Island Lighting Co 5pp 16290 225 24X Fiche 50-322, 82/11/24, 8212010005

G212010087 Forwards location-specific radiation dose calculation for OF Series 200 electric penetrations requested at 821105 meeting Calculations submitted per SER, Item 9, "Environ Qualification"
SMITH, J L Long Island Lighting Co 82/11/26 DENTON, H R Office of Nuclear Reactor Regulation, Director 31pp 16260 276 24X
Fiche 50-322, 82/11/26, 8212010087

G212010165 Forwards sample set of graphs typical of graphs used in plant emergency procedures, in response to verbal request Submittal closes SER Item 1 C B
SMITH, J L Long Island Lighting Co 82/11/26 DENTON, H R Office of Nuclear Reactor Regulation, Director 7pp 16258 087 24X
Fiche 50-322, 82/11/26, 8212010165

G212220106 Forwards Appx A & D to SER input on environ qualification of safety-related equipment, inadvertently missing from 821124 transmittal
REPKA, D A Hearing Branch 3 82/11/29 BRENNER, L, CARPENTER, J L, MORRIS, P A Atomic Safety and Licensing Board Panel 7pp 16503 015 24X Fiche 50-322, 82/11/29, 8212220106

G212070129 Responds to NRC 820909 ltr re NRC position on procedures for suppression pool pumpback sys per SER Open Item 39 Alarm response & operating procedures modified
SMITH, J L Long Island Lighting Co 82/12/03 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 16329 343 24X
Fiche 50-322, 82/12/03, 8212070129

G212210406 Forwards "Shoreham Nuclear Power Station Qualification Rept, GE 200 Series Electric Penetrations" & Revision 1 to "200 Series Low Voltage Electric Penetration Qualification Test Rept," per NRC 820920 ltr, 821105 meeting & SER, Item 9
SMITH, J L Long Island Lighting Co 82/12/14 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 16493 127 24X
Fiche 50-322, 82/12/14, 8212210406

--8212210410 "Shoreham Nuclear Power Station Qualification Rept, GE 200 Series Electric Penetrations"
* Long Island Lighting Co 82/12/31 48pp 16493 128 24X
Fiche 50-322, 82/12/14, 8212210406

- 8212210414 Revision 1 to "200 Series Low Voltage Electric Penetration Qualification Test Rept"
SCHUSTER, R M, LURIA, N G, TERHUNE, J H Long Island Lighting Co 994-76-018 RO1 77/01/20 184pp 16493 176 24X
Fiche 50-322, 82/12/14, 8212210406

G212230259 Discusses SER Issue II D 1 re safety relief valve operability test program, per NRC 820708 request & uttl 810923 response Valve discharge piping adequate to sustain effects of low pressure liquid discharge
SMITH, J L Long Island Lighting Co 82/12/15 DENTON, H R Office of Nuclear Reactor Regulation, Director 9pp 16508 156 24X
Fiche 50-322, 82/12/15, 8212230259

G212270380 Forwards "List of Active Safety-Related Equipment at Qualification Level," per SER Issue B, "Dynamic Qualification"
SMITH, J L Long Island Lighting Co 82/12/22 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 16536 107 24X
Fiche 50-322, 82/12/22, 8212270380

--8212270384 "List of Active Safety-Related Equipment at Qualification Level"
* Stone & Webster Engineering Corp 82/12/20 51pp 16536 108 24X Fiche 50-322, 82/12/22, 8212270380

F Security, medical, emergency & fire protection plans

G212210213 Forwards addl info to prepare operating shift crews for types of questions NRC duty officer may ask re telephone repts made via emergency notification sys
STAROSTECKI, R Division of Project & Resident Programs 82/12/16 POLLOCK, M S Long Island Lighting Co 6pp 16485 003 24X
Fiche 50-322, 82/12/16, 8212210213

G Adjudicatory correspondence

G212030040 Advises that QA insp entrance meeting will be conducted on 821129 E Greenman will be contact in Region 1 ofc Separate arrangements should be made w/uttl to assure entrance Completion of encl protocol requested
HAYNES, R C Region 1, Office of Director 82/11/26 DEMPSEY, P Suffolk County, NY 4pp 16304 134 24X Fiche 50-322, 82/11/26, 8212030040

G212020381 Response opposing Suffolk County 821122 schedule & proposing alternate schedule for consideration of Torrey Pines Review of rept should not be delayed due to lengthy background of QA litigation Certificate of Svc encl
LAWLEY, A F Long Island Lighting Co LAWLEY, A F Hutton & Williams 82/11/29 6pp 16278 113 24X Fiche 50-322, 82/11/29, 8212020381

G212220106 Forwards Appx A & D to SER input on environ qualification of safety-related equipment, inadvertently missing from 821124 transmittal
REPKA, D A Hearing Branch 3 82/11/29 BRENNER, L, CARPENTER, J L, MORRIS, P A Atomic Safety and Licensing Board Panel 7pp 16503 015 24X Fiche 50-322, 82/11/29, 8212220106

G212220128 Forwards IE Insp Rept 50-322/82-26
BORDENICK, B M Hearing Branch 3 82/11/29 BRENNER, L J, CARPENTER, J L, MORRIS, P A Atomic Safety and Licensing Board Panel 4pp 16503 029 24X Fiche 50-322, 82/11/29, 8212220128

G212070003 Forwards EG&Q draft rept COQ-EA-6107, "Identification & Ranking of Nuclear Plant Structures, Sys & Components & Graded QA Guidelines - Draft"
RAHSON, R J Hearing Branch 4 FIN A-6479 82/12/03 BRENNER, L J, MORRIS, P A, CARPENTER, J L Atomic Safety and Licensing Board Panel 129pp 16327 106 24X Fiche 50-322, 82/12/03, 8212070003

G212070167 Memorandum & order canceling 821213 hearing, approving final security settlement agreement, granting joint request to terminate proceeding & dismissing proceeding Agreement resolves all concerns
LAURENSEN, J A, HARBOUR, J Atomic Safety and Licensing Board Panel 82/12/03 Long Island Lighting Co 3pp 16335 311 24X
Fiche 50-322, 82/12/03, 8212070167

DOCKETED ITEMS

8212220135 Forwards IE Insp Rept 50-322/82-20
BORDENICK, R M Hearing Branch 3 82/12/03 BRENNER, L ,
CARPENTER, J L , MORRIS, P A Atomic Safety and Licensing Board Panel
4pp 16803 083 24X Fiche 50-322, 82/12/03, 8212220135

8212080247 Provides latest status of SER open items affecting
contentions in proceeding & NRC response to two ASLB
questions; per ASLB 821130 requests
REPKA, D A Hearing Branch 3 82/12/06 BRENNER, L , CARPENTER, J L ,
MORRIS, P A Atomic Safety and Licensing Board Panel 3pp
16354 107 24X Fiche 50-322, 82/12/06, 8212080247

8212140463 Joint rept of parties on status & potential litigation
schedule of remaining safety issues Certificate of Svc
encl
REPKA, D A Hearing Branch 3 IRWIN, D P Long Island Lighting Co
LETSCHKE, K J Suffolk County, NY 82/12/09 8pp 16404 336 24X
Fiche 50-322, 82/12/09, 8212140463

8212200111 Resolution of Suffolk County Contention 1 re remote shutdown
panel bases provided Certificate of Svc encl
REPKA, D A Hearing Branch 3 IRWIN, D P Long Island Lighting Co
82/12/14 12pp 16470 152 24X Fiche 50-322, 82/12/14, 8212200111

8212220166 Forwards NRC 821210 memo & SER input, delineating NRC final
position on implementation of TMI Item 1 E 4 2 re high
radiation closure signal on purge/vent containment isolation
valves info relevant to Suffolk County Contention 23
REPKA, D A Hearing Branch 3 82/12/14 BRENNER, L , CARPENTER, J L ,
MORRIS, P A Atomic Safety and Licensing Board Panel 6pp
16503 049 24X Fiche 50-322, 82/12/14, 8212220166

8212270324 Forwards responses to ASLB 821130 request for addl info re
IE Insp Repts 50-322/82-26 & 50-322/82-27
MUSELER, W J Long Island Lighting Co 82/12/18 EARLEY, A ,
ELLIS, T Hutton & Williams 19pp 16530 196 24X
Fiche 50-322, 82/12/18, 8212270324

8212220142 Provides progress rept on differing prof opinion of
Halapatt & SER Open Item 27 re further analysis on multiple
control sys failures
REPKA, D A Hearing Branch 3 82/12/20 BRENNER, L , CARPENTER, J L ,
MORRIS, P A Atomic Safety and Licensing Board Panel 2pp
16503 097 24X Fiche 50-322, 82/12/20, 8212220142

8212270196 Responses to ASLB 821130 requests for info re IE insp repts
Certificate of Svc encl
ELLIS, T S Long Island Lighting Co ELLIS, T S Hutton & Williams
82/12/21 5pp 16530 064 24X Fiche 50-322, 82/12/21, 8212270196

8212270220 Memorandum & order confirming 821123 & 30 rulings on
intervenor refusal to comply w/order to participate in
prehearing exams Intervenor waived rights to cross-examine
re Phase 2 emergency planning contentions
BRENNER, L , CARPENTER, J H , MORRIS, P A Atomic Safety and Licensing
Board Panel 82/12/22 Palmetto Alliance 24pp 16536 213 24X
Fiche 50-322, 82/12/22, 8212270220

II General correspondence

8209150058 FOIA request for documents re Paragraph IV A 2 C of
10CFR50, App G for 810401-0901
HAFNER, B Affiliation Unknown 82/09/29 Office of
Administration 1p 16607 006 24X Fiche 50-322, 82/09/29,
8209150058

8212290025 Responds to FOIA request for documents re Paragraph IV A 2 C
of 10CFR50, App G for 810401-0901 Forwards documents listed
in App A
FELTON, J M Division of Rules and Records 82/11/24 HAFNER, B
Affiliation Unknown 2pp 16607 007 24X Fiche 50-322, 82/11/24,
8212290025

--8107140119 Forwards Matls Engineering Branch SER input re RCPB
fracture toughness Exemptions from requirements of Apps
G & H of 10CFR50 can be granted
JOHNSTON, H V Assistant Director for Materials & Qualifications
Engineering 81/07/02 TEDESCO, R L Assistant Director for
Licensing 17pp 16607 009 24X Fiche 50-322, 82/11/24,
8212290025

8212080672 Responds to 821124 memo re inquiry from Congressman W Carney
concerning interim licensing of facility Interim licensing
will only allow low power testing at earlier time in
licensing procedure than now exists
DENTON, H R Office of Nuclear Reactor Regulation, Director
82/12/03 BOLLWERK, P Office of the General Counsel 4pp
16379 296 24X Fiche 50-322, 82/12/03, 8212080672

--8212080684 Requests response to Congressman W Carney constituent ltrs
re impact of interim licensing provisions of S B 2330 on NRC
budgetary or manpower resources Requests response by 821202
BOLLWERK, P Office of the General Counsel 82/11/24 REHM, T
Office of the Executive Director for Operations 1p 16379 304
24X Fiche 50-322, 82/12/03, 8212080672

--8212080489 Forwards constituent ltrs re NRC policy on possible interim
licensing of facility
CARNEY, W House of Rep 82/10/26 PALLADINO, N J Commissioners
5pp 16379 305 24X Fiche 50-322, 82/12/03, 8212080672

Q Inspection reports, IE Bulletins & correspondence

8208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-
Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping
at BWR Plants " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and
Enforcement 82/10/28 Consolidated Edison Co of New York, Inc
112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240

8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model
801 & Model 802 Thermoluminescent Dosimeters " Svc list
encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards
82/11/03 Consolidated Edison Co of New York, Inc 110pp
16372 142 24X Fiche 50-000, 82/11/03, 8208190245

8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan
Exercise Requirements " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18
Consolidated Edison Co of New York, Inc 109pp 16411 199 24X
Fiche 50-000, 82/11/18, 8208190251

8212030069 Forwards IE Insp Rept 50-322/82-29 on 821001-29 No
noncompliance noted
STAROSTECKI, R Division of Project & Resident Programs 82/11/18
POLLOCK, M S Long Island Lighting Co 2pp 16304 172 24X
Fiche 50-322, 82/11/18, 8212030069

--8212030083 IE Insp Rept 50-322/82-29 on 821001-29 No noncompliance
noted Major areas inspected allegations re corroded valves
& faulty fiberglass piping
HIGGINS, J C , GALLO, R M Division of Project & Resident Programs
82/11/10 13pp 16304 174 24X Fiche 50-322, 82/11/18, 8212030069

8212060234 Forwards IE Insp Rept 50-322/82-27 on 821018-22 No
noncompliance noted
MARTIN, T T Division of Engineering & Technical Programs 82/11/22
POLLOCK, M S Long Island Lighting Co 2pp 16312 192 24X
Fiche 50-322, 82/11/22, 8212060234

--8212060258 IE Insp Rept 50-322/82-27 on 821018-22 No noncompliance
noted Major areas inspected preoperational test program
status, including test procedure implementation, test
procedure review, procedure mods & test results evaluation
NICHOLAS, H H , BETTENHAUSEN, L Region 1, Office of Director
82/11/17 7pp 16312 194 24X Fiche 50-322, 82/11/22, 8212060234

8212070120 Forwards IE Insp Rept 50-322/82-28 on 821018-21 No
noncompliance noted
MARTIN, T T Division of Engineering & Technical Programs 82/11/23
POLLOCK, M S Long Island Lighting Co 2pp 16327 034 24X
Fiche 50-322, 82/11/23, 8212070120

--8212070136 IE Insp Rept 50-322/82-28 on 821018-21 No noncompliance
noted Major areas inspected licensee work & QC activities re
corrective actions for significant deficiencies &
outstanding items
NARRD, L , DURR, J P Region 1, Office of Director 82/11/19
5pp 16327 036 24X Fiche 50-322, 82/11/23, 8212070120

8208190254 IE Info Notice 82-46, "Defective & Obsolete Combination
Padlocks " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and
Enforcement 82/11/26 Consolidated Edison Co of New York, Inc
127pp 16411 045 24X Fiche 50-000, 82/11/26, 8208190254

8212030040 Advises that QA insp entrance meeting will be conducted on
821127 E Greenman will be contact in Region 1 of Separate
arrangements should be made w/utl to assure entrance
completion of encl protocol requested
HAYNES, R C Region 1, Office of Director, 82/11/26 DEMPSEY, P
Suffolk County, NY 4pp 16304 134 24X Fiche 50-322, 82/11/26,
8212030040

8208190257 IE Info Notice 82-47, "Transportation of Type A Quantities
of Non-Fissile Radioactive Matl " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards
82/11/30 Consolidated Edison Co of New York, Inc 356pp
16387 028 24X Fiche 50-000, 82/11/30, 8208190257

DOCKETED ITEMS

171

B208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259

B208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X Fiche 50-000, 82/12/03, 8208190261

B208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16, 8208190267

G212220453 Forwards listing of topic areas for discussion at Region 1/ licensee meeting on drug & alcohol abuse programs per IE
Info Notice 82-05 & NUREG-0903 W/o NUREG
STAROSTECKI, R Division of Project & Resident Programs 82/12/16
POLLACK, M S Long Island Lighting Co 3pp 16304 257 24X Fiche 50-322, 82/12/16, 8212220453

B208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27 " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X Fiche 50-000, 82/12/20, 8208190268

5 Reportable occurrences, LERs & related correspondence

G212160065 Interim deficiency rept re HMA type relays mfg by GE
Initially reported on 821101 GE notified to determine which specific groupings of HMA relays are affected & what actions should be taken
MILLIGAN, M H Long Island Lighting Co 82/12/07 HAYNES, R C Region 1, Office of Director 2pp 16446 191 24X Fiche 50-322, 82/12/07, 8212160065

1 Hearing transcripts on non-antitrust matters

G212020384 Transcript of 821130 hearing in Bethesda, MD Pp 14,750-14,756 Supporting documentation encl
* Atomic Safety and Licensing Board Panel 82/11/30 233pp 16278 260 24X Fiche 50-322, 82/11/30, 8212020384

G212030101 Transcript of 821201 hearing in Bethesda, MD Pp 14,959-15,157
* Atomic Safety and Licensing Board Panel 82/12/01 199pp 16305 174 24X Fiche 50-322, 82/12/01, 8212030101

B212060065 Transcript of 821202 hearing in Bethesda, MD Pp 15,158-15,352
* Atomic Safety and Licensing Board Panel 82/12/02 197pp 16314 094 24X Fiche 50-322, 82/12/02, 8212060065

G212070140 Transcript of 821203 hearing in Bethesda, MD Pp 15,353-15,476 Supporting documentation encl
* Atomic Safety and Licensing Board Panel 82/12/03 132pp 16326 251 24X Fiche 50-322, 82/12/03, 8212070140

G212090171 Transcript of 821207 OL hearing in Bethesda, MD Pp 15,477-15,661 Supportive documentation encl
* Atomic Safety and Licensing Board Panel 82/12/07 231pp 16358 170 24X Fiche 50-322, 82/12/07, 8212090171

G212100024 Transcript of 821208 hearing in Bethesda, MD Pp 15,662-15,826
* Atomic Safety and Licensing Board Panel 82/12/08 168pp 16375 165 24X Fiche 50-322, 82/12/08, 8212100024

G212130042 Transcript of 821209 hearing in Bethesda, MD Pp 15,827-16,017
* Atomic Safety and Licensing Board Panel 82/12/09 194pp 16391 184 24X Fiche 50-322, 82/12/09, 8212130042

G212140039 Transcript of 821210 hearing in Bethesda, MD Pp 16,018-16,190
* Atomic Safety and Licensing Board Panel 82/12/10 175pp 16410 001 24X Fiche 50-322, 82/12/10, 8212140039

G212160030 Transcript of 821214 OL hearing in Bethesda, MD Pp 16,191-16,408 Supporting documentation encl
* Atomic Safety and Licensing Board Panel 82/12/14 241pp 16443 273 24X Fiche 50-322, 82/12/14, 8212160030

B212170251 Transcript of 821215 hearing in Bethesda, MD Pp 16,409-16,634
* Atomic Safety and Licensing Board Panel 82/12/15 230pp 16457 179 24X Fiche 50-322, 82/12/15, 8212170251

G212200018 Transcript of 821216 hearing in Bethesda, MD Pp 16,635-16,821
* Atomic Safety and Licensing Board Panel 82/12/16 189pp 16473 108 24X Fiche 50-322, 82/12/16, 8212200018

G212210302 Transcript of 821217 hearing in Bethesda, MD Pp 16,822-17,006
* Atomic Safety and Licensing Board Panel 82/12/17 184pp 16495 312 24X Fiche 50-322, 82/12/17, 8212210302

G212220455 Transcript of 821220 hearing in Bethesda, MD Pp 17,007-17,193
* Atomic Safety and Licensing Board Panel 82/12/20 189pp 16504 048 24X Fiche 50-322, 82/12/20, 8212220455

G212230316 Transcript of 821221 hearing in Bethesda, MD Pp 17,194-17,394 Supporting documentation encl
* Atomic Safety and Licensing Board Panel 82/12/21 219pp 16507 074 24X Fiche 50-322, 82/12/21, 8212230316

B212270227 Testimony of RB Hubbard & FJ Samaniego re Torrey Pines Technology insp of facility Certificate of Svc encl
HUBBARD, R B , SAMANIEGO, F J Suffolk County, NY HUBBARD, R B MHB Technical Associates 82/12/21 36pp 16536 160 24X Fiche 50-322, 82/12/21, 8212270227

G212270230 Transcript of 821222 OL hearing in Bethesda, MD Pp 17,395-17,533 Supporting documentation encl
* Atomic Safety and Licensing Board Panel 82/12/22 136pp 16537 220 24X Fiche 50-322, 82/12/22, 8212270230

DOCKET 50-323 DIABLO CANYON NUCLEAR POWER PLANT, UNIT 2

A Application/construction stage documents & correspondence

G212030253 Board Notification 82-105 forwards RH Vollmer 820930 memo to DG Eisenhower re alleged design deficiency in ASME Code Class 1 piping Effects of local pipe wall stresses due to support loads introduced by pipe clamps not evaluated properly
EISENHUT, D O Division of Licensing 82/11/24 PALLADINO, N J , GILINSKY, V , AHEARNE, J F Commissioners 2pp 16316 240 24X Fiche 50-000, 82/11/24, 8212030253

--8212030265 Discusses alleged design deficiency in ASME Code Class 1 piping Failure to deal w/pipes support-pipe interface design issue would be serious matter if substantiated Ofc of Investigations will assist in evaluation
VOLLMER, R H Division of Engineering 82/09/30 EISENHUT, D O Division of Licensing 3pp 16316 247 24X Fiche 50-000, 82/11/24, 8212030265

G212270418 Responds to FOIA request for documents re proposed revision &/or update to reactor safety study referred to in NUREG-0784, Chapter 10 as RB II & all documents pertaining to reactor cooling methods Forwards documents listed in app
FELTON, J M Division of Rules and Records 82/11/26 HOLLY, B C Union of Concerned Scientists 3pp 16549 233 24X Fiche 50-000, 82/11/26, 8212270418

--8211050027 Forwards summary of semiscale test results & advises that board notification re test results issued W/o encl
NOVAK, T M Assistant Director for Licensing 82/09/24 Division of Licensing 1p 16949 278 24X Fiche 50-000, 82/11/26, 8212270418

B212010190 Submits status update on Wiegand & Bend repts re effects of storm & tsunami waves & seismic events on facility break-water Final repts for ongoing analysis re potential wave forces & request for Tech Spec amend will be sent Dec 1982
CRANE, P A Pacific Gas & Electric Co 82/11/29 KNIGHTON, O W Licensing Branch 3 2pp 16258 085 24X Fiche 50-275, 82/11/29, 8212010190

G212230306 Provides response to 821123 ltr requesting GSW document, change in format of engineering open item file sys & more complete description of 27 files opened to date
JOHNSON, A E Teledyne Engineering Services 82/12/01 HUBBARD, R B MHB Technical Associates 2pp 16507 319 24X Fiche 50-275, 82/12/01, 8212230306

B212170038 Requests changes to QA program, Revision 1 scope of responsibility Project completion effort responsibility should be clearly defined
EISENHUT, D O Division of Licensing 82/12/02 CRANE, P A Pacific Gas & Electric Co 5pp 16478 008 24X Fiche 50-275, 82/12/02, 8212170038

8212130281 Board Notification 82-123 forwards info re recent ACRS evaluation of PWR flow blockage during natural circulation
EISENHUT, D G Division of Licensing 82/12/06 PALLADINO, N J,
GILINSKY, V, AHEARNE, J Commissioners 3pp 16418 231 24X
Fiche 50-000, 82/12/06, 8212130281

8212220017 Staff requirements memo re 821209 meeting on Phase II of design verification program per SECY-82-414 Commission unanimously approved recommendations replacing Figure 3 w/ Figure 1, per util 821203 ltr
CHILK, S J Office of the Secretary of the Commission 82/12/09
DIRKS, W J Office of the Executive Director for Operations 1p 16529 096 24X Fiche 50-275, 82/12/09, 8212220017

8212230049 Board Notification 82-125A forwards info re PWR flow blockage info suppl Board Notification 82-125
EISENHUT, D G Division of Licensing 82/12/09 PALLADINO, N J,
GILINSKY, V, AHEARNE, J F Commissioners 3pp 16545 338 24X
Fiche 50-000, 82/12/09, 8212230049

--8212230058 Forwards Fraley 821207 memo re flow blockage by steam during natural circulation in PWRs
EISENHUT, D G Division of Licensing 82/12/09 LAINAS, G
Assistant Director for Operating Reactors 1p 16545 341 24X
Fiche 50-000, 82/12/09, 8212230049

8212210002 Forwards "Pressurizer Safety & Relief Line Evaluation," summary rept
CRANE, P A Pacific Gas & Electric Co 82/12/13 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 16485 276 24X Fiche 50-275, 82/12/13, 8212210002

--8212210005 "Pressurizer Safety & Relief Line Evaluation," summary rept
SMITH, L C, HAZLETT, T L, CHANOK, K C Pacific Gas & Electric Co
AM-55A-2534 82/11/30 71pp 16485 278 24X
Fiche 50-275, 82/12/13, 8212210002

8212210037 Provides Natl Register of Historic Places eligibility notification of plant Archeological Site SLD-2
* Interior, Dept of, National Park Service 82/12/14 KERRIGAN, J D
NRC - No Detailed Affiliation Given 2pp 16490 212 24X
Fiche 50-275, 82/12/14, 8212210037

8212220434 Board Notifications 82-125 & 82-125A forwards info re flow blockage during natural circulation All concerns re phenomena of natural circulation flow blockage previously identified by NRC & provided to Commission
EISENHUT, D G Division of Licensing 82/12/14 PALLADINO, N J,
GILINSKY, V, AHEARNE, J Commissioners 4pp 16523 103 24X
Fiche 50-000, 82/12/14, 8212220434

8212220440 Board Notifications 82-125 & 82-125A forwards info re H Etherington evaluation of flow blockage during natural circulation of PWRs Results do not adversely impact present position on reliance on natural circulation
NOVAK, T M Assistant Director for Licensing 82/12/14 Atomic Safety and Licensing Board Panel 5pp 16523 135 24X
Fiche 50-000, 82/12/14, 8212220440

8212220461 Board Notification 82-124 forwards RJ Mattison 821123 memo re Semiscale S-UT-B test results Phenomena of core level depression & loop seal clearing may be more complex than previously supposed
NOVAK, T M Assistant Director for Licensing 82/12/14 Atomic Safety and Licensing Board Panel 7pp 16523 169 24X
Fiche 50-000, 82/12/14, 8212220461

8212220482 Board Notification 82-124 forwards RJ Mattison 821123 memo re Semiscale S-UT-B test results Phenomena of core level depression & loop seal clearing may be more complex than previously supposed
EISENHUT, D G Division of Licensing 82/12/14 PALLADINO, N J,
GILINSKY, V, AHEARNE, J F Commissioners 4pp 16523 199 24X
Fiche 50-000, 82/12/14, 8212220482

8212210090 Advises that results of design verification program require mods to fuel handling bldg Temporary relief from Tech Spec Action Statement 3 9 7 re handling of loads over fuel pool will be requested
CRANE, P A Pacific Gas & Electric Co 82/12/16 KNIGHTON, G W
Licensing Branch 3 2pp 16493 016 24X Fiche 50-323, 82/12/16, 8212210090

8212230298 Forwards Revision 2 to "Diablo Canyon Project QA Program," in response to D9 Eisenhut 821202 request
CRANE, P A Pacific Gas & Electric Co 82/12/21 KNIGHTON, G W
Licensing Branch 3 1p 16507 051 24X Fiche 50-275, 82/12/21, 8212230298

--8212230304 Revision 2 to "Diablo Canyon Project QA Program"
* Pacific Gas & Electric Co * Bechtel Corp 82-TOP-1 R02
82/12/21 16pp 16507 052 24X Fiche 50-275, 82/12/21, 8212230298

F Security, medical, emergency & fire protection plans

8212080057 Releases public version of revised emergency plan implementing procedures
FEATON, J M Division of Rules and Records 82/12/02 Document Management Branch 1p 16367 214 24X Fiche 50-275, 82/12/02, 8212080057

--8212080063 Forwards public version of revised emergency plan implementing procedures, including Procedures EP OP-18A re loss of charging & EP OP-18B re loss of normal letdown
CRANE, P A Pacific Gas & Electric Co 82/11/24 ENGELKEN, R H
Region 5, Office of Director 2pp 16367 215 24X
Fiche 50-275, 82/12/02, 8212080057

--8212080071 Public version of revised emergency plan implementing procedures, including Procedures EP OP-18A re loss of charging, EP OP-18B re loss of normal letdown & EP R-1 re personnel injury or illness (radiologically-related)
THORNBERRY, R C Pacific Gas & Electric Co 82/11/03 55pp 16367 217 24X Fiche 50-275, 82/12/02, 8212080057

8212130070 Confirms permanent & interim emergency operations facilities info per 821202 verbal request Permanent & interim sites located 11 7 miles from facilities Interim structure complete & successfully tested
CRANE, P A Pacific Gas & Electric Co 82/12/07 KNIGHTON, G W
Licensing Branch 3 1p 16391 164 24X Fiche 50-275, 82/12/07, 8212130070

G Adjudicatory correspondence

8212060104 Order extending time until 821208 for Commission to act to review NRR Director 820922 denial of Joint Intervenor's 10CFR2 206 petition
CHILK, S J Office of the Secretary of the Commission 82/12/01 Commissioners 1p 16314 362 24X Fiche 50-275, 82/12/01, 8212060104

8212090084 Motion for extension of time until 821220 to file brief opposing intervenor exceptions to ASLB decision Time extension necessary due to meetings on east coast Certificate of Svc encl
CRANE, P A Pacific Gas & Electric Co 82/12/06 Atomic Safety and Licensing Appeal Panel 4pp 16357 188 24X
Fiche 50-275, 82/12/06, 8212090084

8212090097 Order extending time until 821215 for Commission to act to review NRR Director 820922 denial of Joint Intervenor's 10CFR2 206 petition
CHILK, S J Office of the Secretary of the Commission 82/12/07 Commissioners 1p 16357 283 24X Fiche 50-275, 82/12/07, 8212090097

8212150051 Order extending time until 821222 for Commission to act to review NRR Director 820922 denial of Joint Intervenor's 10CFR2 206 petition
CHILK, S J Office of the Secretary of the Commission 82/12/14 Commissioners 1p 16422 323 24X Fiche 50-275, 82/12/14, 8212150051

8212150057 Order extending time until 821221 for Commission to respond to ALAB-681
CHILK, S J Office of the Secretary of the Commission 82/12/14 Commissioners 1p 16431 007 24X Fiche 50-275, 82/12/14, 8212150057

8212220394 Brief opposing util & NRC 821108 briefs supporting exceptions to ASLB requirement that NRC receive FEMA finding of adequacy of State of CA radiological emergency response plan before plant can be licensed w/Certificate of Svc
BROWN, H H California, State of BROWN, H H Kirpatrick, Lockhart, Hill, Christopher & Phillips 82/12/20 Atomic Safety and Licensing Appeal Panel 9pp 16517 251 24X Fiche 50-275, 82/12/20, 8212220394

8212280123 Response in opposition to Joint Intervenor's briefs in support of exceptions to ASLB 820831 order authorizing NRR director to issue full power OL No new arguments placed before ASLB Certificate of Svc encl
NORTON, B Pacific Gas & Electric Co NORTON, B Norton, Burke, Berry & French 82/12/20 Atomic Safety and Licensing Appeal Panel 40pp 16564 140 24X Fiche 50-275, 82/12/20, 8212280123

8212280288 Brief in opposition to util & NRC briefs in support of exception to 820831 initial decision Desire for more expeditious licensing is patently inadequate excuse for ignoring regulatory stds, Certificate of Svc encl
REYNOLDS, J R Joint Intervenor-Diablo Canyon REYNOLDS, J R Center for Law in the Public Interest 82/12/20 Atomic Safety and Licensing Appeal Panel 22pp 16561 334 24X
Fiche 50-275, 82/12/20, 8212280288

B212230360 Order extending time, until B21229, for Commission to decide whether to review NRR Director B20922 denial of Joint Intervenor's request for action filed under 10CFR2 206 CHILK, S J Office of the Secretary of the Commission 82/12/22
 1p 16511 165 24X Fiche 50-275, 82/12/22, B212230360

B212270217 Memorandum & Order CLI-82-39, ruling on three questions certified on B20716 issuance of suspension order & establishment of independent design verification program not intended to deprive adjudicatory boards of jurisdiction CHILK, S J Office of the Secretary of the Commission 82/12/23
 7pp 16536 206 24X Fiche 50-275, 82/12/23, B212270217

II General correspondence

B212130375 Responds to B21025 request for addl info on design verification program Util corrective action program per SECY B2-414, principal reason for determining that design verification effort goes beyond Commission order EISENHUT, D O Division of Licensing 82/11/24 SIEGEL, S M Toward Utility Rate Normalization 3pp 16412 085 24X
 Fiche 50-275, 82/11/24, B212130375

--B211020166 Requests elaboration on encl newspaper article re mod & investigation program at facility SIEGEL, S M Affiliation Unknown 82/10/25 DENTON, H NRC - No Detailed Affiliation Given 3pp 16412 088 24X
 Fiche 50-275, 82/11/24, B212130375

B212170373 Advises that B21115 ltr to Chairman Palladino re seismic qualification of turbine bldg & recommendation for independent analysis by BNL will be provided to other Commissioners EISENHUT, D O Division of Licensing 82/12/08 ROESSET, J Roesset, J M App 16478 085 24X Fiche 50-275, 82/12/08, B212170373

--B212170378 Clarifies B21110 statements re seismic qualification of turbine bldg Recommendation for independent analysis by BNL justified Transmittal of clarifications to other Commissioners requested ROESSET, J M Roesset, J M 82/11/15 PALLADINO, N J Commissioners 1p 16478 088 24X Fiche 50-275, 82/12/08, B212170373

I Operating license stage documents & correspondence

B212140278 Forwards agenda for B21214-15 meetings in San Francisco, CA For technical discussion of RL Cloud & Associates requests for info COOPER, W E Teledyne Engineering Services 82/12/14 NRC - No Detailed Affiliation Given 3pp 16402 107 24X
 Fiche 50-275, 82/12/14, B212140278

G Inspection reports, IE Bulletins & correspondence

B208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Svc list encl DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, B208190240

B208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model B01 & Model B02 Thermoluminescent Dosimeters " Svc list encl COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000, 82/11/05, B208190245

B208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl JORDAN, E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X
 Fiche 50-000, 82/11/18, B208190251

B212060155 Discusses B20208 ltr re adequacy of NUREG-0862, "Insp Rept of Preliminary Rept, Seismic Reverification Program at Diablo Canyon Nuclear Power Plant, Units 1 & 2 " Questions posed through B20423 Ofc of Inspector & Auditor review answered PALLADINO, N J Commissioners 82/11/23 UDALL, M K House of Rep, Interior & Insular Affairs 2pp 16325 232 24X
 Fiche 50-275, 82/11/23, B212060155

--B212060164 Discusses B20204 ltr re adequacy of NUREG-0862, "Insp Rept of Preliminary Rept, Seismic Reverification Program at Diablo Canyon Nuclear Power Plant, Units 1 & 2 " Questions posed through B20423 Ofc of Inspector & Auditor review answered PALLADINO, N J Commissioners 82/11/23 OTTINGER, R House of Rep, Energy & Commerce 2pp 16325 234 24X
 Fiche 50-275, 82/11/23, B212060155

--B212060177 Submits review of NUREG-0862, "Insp Rept of Preliminary Rept, Seismic Reverification Program at Diablo Canyon Nuclear Power Plant, Units 1 & 2," per Udall B20208 & Ottinger B20204 requests Investigation conducted in 2 phases CUMMINOS, J J Office of Inspector & Auditor 82/07/30 PALLADINO, N Commissioners 7pp 16325 236 24X
 Fiche 50-275, 82/11/23, B212060155

B208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list encl DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000, 82/11/26, B208190256

B208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16397 028 24X Fiche 50-000, 82/11/30, B208190257

B208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, B208190259

B208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Buckets " Svc list encl JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X
 Fiche 50-000, 82/12/03, B208190261

B208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16, B208190267

B208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27 " Svc list encl JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X
 Fiche 50-000, 82/12/20, B208190268

S Reportable occurrences, LERs & related correspondence

B212060078 Final deficiency rept re water hammer phenomenon in auxiliary saltwater sys Initially reported on B21008 Isolable vacuum breaker added to auxiliary saltwater sys to eliminate water hammer effect Design change forthcoming CRANE, P A Pacific Gas & Electric Co 82/11/08 ENGELKEN, R H Region 5, Office of Director 2pp 16314 356 24X
 Fiche 50-323, 82/11/08, B212060078

DOCKET 90-324 BRUNSWICK STEAM ELECTRIC PLANT, UNIT 2

F Security, medical, emergency & fire protection plans

B212090273 Ack receipt of B21027 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-324/82-37 & 50-325/82-37 VERRELLI, D M Division of Project & Resident Programs 82/11/16 UTLEY, E E Carolina Power & Light Co 1p 16365 289 24X
 Fiche 50-324, 82/11/16, B212090273

--B212090289 Responds to NRC B21006 ltr re violations noted in IE Insp Repts 50-324/82-37 & 50-325/82-37 Corrective actions eight addl spare cylinders purchased & weekly review to be conducted to ensure fire brigade training current DIETZ, C R Carolina Power & Light Co 82/10/27 O'REILLY, J P Region 2, Office of Director 3pp 16365 270 24X
 Fiche 50-324, 82/11/16, B212090273

--B212090299 Forwards IE Insp Repts 50-324/82-37 & 50-325/82-37 on B20907-10 & notice of violation LEWIS, R C Division of Project & Resident Programs 82/10/06 JONES, J A Carolina Power & Light Co 2pp 16365 293 24X
 Fiche 50-324, 82/11/16, B212090273

--B212090309 Notice of violation from insp on B20907-10 * Division of Project & Resident Programs 82/10/06 2pp 16365 295 24X Fiche 50-324, 82/11/16, B212090273

--B212090321 IE Insp Repts 50-324/82-37 & 50-325/82-37 on B20907-10 Noncompliance noted failure to train all personnel required to use respirator protection properly & to have adequate number of spare air cylinders available MILLER, W H CONLON, T E Division of Engineering & Technical Programs 82/09/28 Bpp 16365 297 24X Fiche 50-324, 82/11/16, B212090273

8212100032 Forwards info re emergency operations facility in response to NRC 821202 verbal request & Generic Ltr 81-10 Info based on util understanding of SECY-82-111
ZIMMERMAN, S R Carolina Power & Light Co 82/12/06 VASSALLO, D B
Operating Reactors Branch 2 2pp 16379 033 24X
Fiche 50-324, 82/12/06, 8212100032

P Operating license stage documents & correspondence

82121230066 Generic Ltr 82-27 to all BWR licensees of operating reactors except LACBWR, Big Rock Point, Dresden 1, Humboldt Bay, applicants for DL & holders of CP re transmittal of NUREG-0743 & NUREG-0783 Svc list encl w/o stated encl
EISENHUT, D G Division of Licensing 82/11/15 General Public
Utilities - GPU Service Corp 22pp 16387 004 24X
Fiche 50-000, 82/11/15, 821230066

8212060160 Forwards request for addl info to complete review of NUREG-0737, Action Items I A 2 I 4, "Upgrading of Reactor Operator & Senior Reactor Operator Training" & I I B 4, "Training to Mitigate Core Damage" Response requested within 60 days
VASSALLO, D B Operating Reactors Branch 2 82/11/16 UTLEY, E E
Carolina Power & Light Co 2pp 16325 246 24X
Fiche 50-324, 82/11/16, 8212060160

8212060111 Forwards safety evaluation re NUREG-0737, Item II F 1 3, "Add'l Accident Monitoring Instrumentation," in response to B10630 & B20804 submittals Licensee proposed calibr procedures acceptable
VASSALLO, D B Operating Reactors Branch 2 82/11/22 UTLEY, E E
Carolina Power & Light Co 3pp 16323 013 24X
Fiche 50-324, 82/11/22, 8212060111

8212090307 Endorses BWR owners group B10522 & 0921 repts re NUREG-0737, Item II K 3 25, "Effect of Loss of AC Power on Pump Seals" Loss of ac power will not significantly degrade recirculation pump seals
ZIMMERMAN, S R Carolina Power & Light Co 82/12/06 VASSALLO, D B
Operating Reactors Branch 2 2pp 16365 149 24X
Fiche 50-324, 82/12/06, 8212090307

8212100082 Application for amend to License DPR-62, requesting temporary exemption from Tech Spec 3 6 & 3, permitting 72-h for repairs of 821205 rupture in containment atmosphere control inerting line Expedited review requested
EURY, L W Carolina Power & Light Co 82/12/06 VASSALLO, D B
Operating Reactors Branch 2 3pp 16379 177 24X
Fiche 50-324, 82/12/06, 8212100082

--8212100085 Proposed Tech Spec 3 6 & 3 re containment atmosphere oxygen concentration
* Carolina Power & Light Co 82/12/06 1p 16379 180 24X
Fiche 50-324, 82/12/06, 8212100085

8212140250 Forwards supplemental info re status of selected NUREG-0737 requirements covered by Generic Ltrs 82-05 & 82-10, in response to NRC 820317 & 0505 requests
UTLEY, E E Carolina Power & Light Co 82/12/06 EISENHUT, D G
Division of Licensing 3pp 16409 327 24X Fiche 50-324, 82/12/06, 8212140250

8212140255 Request for amend to Licenses DPR-71 & DPR-62, revising, clarifying & providing editorial corrections to Tech Specs re ATWS
EURY, L W Carolina Power & Light Co 82/12/06 VASSALLO, D B
Operating Reactors Branch 3 2pp 16401 332 24X
Fiche 50-324, 82/12/06, 8212140255

--8212140257 Proposed Tech Specs for Licenses DPR-71 & DPR-62, revising, clarifying & providing editorial corrections re ATWS
* Carolina Power & Light Co 82/12/06 22pp 16401 334 24X
Fiche 50-324, 82/12/06, 8212140257

8212150296 Requests application fee for Tech Spec changes re removal of MAPLHGR reduction penalty be remitted within 15 days of ltr receipt
MILLER, W G License Fee Management Branch 82/12/09 JONES, J A
Carolina Power & Light Co 1p 16446 269 24X
Fiche 50-324, 82/12/09, 8212150296

8212170355 Application to amend Licenses DPR-71 & DPR-62, revising Tech Specs to incorporate organization changes Revisions suppl B10728 submittal
EURY, L W Carolina Power & Light Co 82/12/10 VASSALLO, D B
Operating Reactors Branch 2 2pp 16456 053 24X
Fiche 50-324, 82/12/10, 8212170355

--8212170363 Proposed Tech Spec changes re administrative controls
* Carolina Power & Light Co 82/12/10 58pp 16456 055 24X
Fiche 50-324, 82/12/10, 8212170363

8212170338 Supplemental application for amend to Licenses DPR-71 & DPR-62 Changes include mods to digital-to-analog instrumentation & reactor vessel ref water level, per 821005 meeting Revisions supersede 790531 revisions
EURY, L W Carolina Power & Light Co 82/12/13 VASSALLO, D B
Operating Reactors Branch 2 3pp 16454 154 24X
Fiche 50-324, 82/12/13, 8212170338

--8212170343 Proposed Tech Spec pages including mods to digital-to-analog instrumentation, reactor vessel ref water level, special test exception for core spray sys, administrative controls & safety/relief valve challenges
* Carolina Power & Light Co 82/12/13 287pp 16454 157 24X
Fiche 50-324, 82/12/13, 8212170338

--8212170350 "Brunswick Steam Electric Plant Offsite Dose Calculation Manual (DDCM)"
* Carolina Power & Light Co 82/12/13 190pp 16455 084 24X
Fiche 50-324, 82/12/13, 8212170338

--8212170356 "Brunswick Steam Electric Plant Process Control Program (PCP)"
* Carolina Power & Light Co 82/12/13 5pp 16455 274 24X
Fiche 50-324, 82/12/13, 8212170338

821210004 Application for amends to Licenses DPR-62 & DPR-71, correcting administrative inconsistency re min number of operable channels per trip sys requirements for certain HPCI & RCIC sys instruments
EURY, L W Carolina Power & Light Co 82/12/13 VASSALLO, D B
Operating Reactors Branch 2 4pp 16485 262 24X
Fiche 50-324, 82/12/13, 821210004

--8212210006 Proposed Tech Spec revisions correcting administrative inconsistency re min number of operable channels per trip sys requirements for certain HPCI & RCIC sys isolation actuation instruments
* Carolina Power & Light Co 82/12/13 10pp 16485 266 24X
Fiche 50-324, 82/12/13, 8212210004

8212170210 Commits to perform qualification testing of certain Raychem radiation cross-linked polyethylene cable having combined insulation thickness of 120 mils or greater Proposed cable qualification program forthcoming
UTLEY, E E Carolina Power & Light Co 82/12/15 VASSALLO, D B
Operating Reactors Branch 2 1p 16459 362 24X
Fiche 50-324, 82/12/15, 8212170210

8212300145 Forwards two supplemental repts to 820808 Franklin Research Ctr rept re environ qualification of safety-related electrical equipment submitted on 821220 w/evaluation Space charges phenomenon valid concern w/o encl
VASSALLO, D B Operating Reactors Branch 2 82/12/23 UTLEY, E E
Carolina Power & Light Co 3pp 16624 188 24X
Fiche 50-324, 82/12/23, 8212300145

G Inspection reports, IE Bulletins & correspondence

8208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants" Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc
112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240

8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters" Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp
16372 142 24X Fiche 50-000, 82/11/05, 8208190245

8212090273 Ack receipt of 821027 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-324/82-37 & 50-325/82-37
VERRELLI, D M Division of Project & Resident Programs 82/11/16 UTLEY, E E Carolina Power & Light Co 1p 16365 289 24X
Fiche 50-324, 82/11/16, 8212090273

--8212090289 Responds to NRC 821006 ltr re violations noted in IE Insp Repts 50-324/82-37 & 50-325/82-37 Corrective actions eight add spare cylinders purchased & weekly review to be conducted to ensure fire brigade training current
DIETZ, C R Carolina Power & Light Co 82/10/27 O'REILLY, J P
Region 2, Office of Director 3pp 16365 290 24X
Fiche 50-324, 82/11/16, 8212090273

--8212090299 Forwards IE Insp Repts 50-324/82-37 & 50-325/82-37 on 820907-10 & notice of violation.
LEWIS, R C Division of Project & Resident Programs 82/10/06 JONES, J A Carolina Power & Light Co 2pp 16365 293 24X
Fiche 50-324, 82/11/16, 8212090273

DOCKETED ITEMS

--8212090309 Notice of violation from insp on 820907-10
 * Division of Project & Resident Programs 82/10/06 2pp
 16365 295 24X Fiche 50-324,82/11/16,8212090273

--8212090321 IE Insp Repts 50-324/82-37 & 50-325/82-37 on 820907-10
 Noncompliance noted failure to train all personnel required
 to use respirator protection properly & to have adequate
 number of spare air cylinders available
 MILLER, W H , CONLON, T E Division of Engineering & Technical
 Programs 82/09/28 8pp 16365 297 24X Fiche 50-324,82/11/16,
 8212090273

8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan
 Exercise Requirements " Svc list encl
 JORDAN, E L Division of Engineering & Quality Assurance 82/11/18
 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X
 Fiche 50-000,82/11/18,8208190251

8212090111 Forwards summary of 821110 meeting w/util in Atlanta, GA re
 actions taken by util to improve overall performance
 O'REILLY, J P Region 2, Office of Director 82/11/24 UTLEY, C E
 Carolina Power & Light Co 3pp 16357 242 24X
 Fiche 50-324,82/11/24,8212090111

8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination
 Padlocks " Svc list encl
 DEYOUNG, R C Director's Office, Office of Inspection and
 Enforcement 82/11/26 Consolidated Edison Co of New York, Inc
 127pp 16411 065 24X Fiche 50-000,82/11/26,8208190256

8208190257 IE Info Notice 82-47, "Transportation of Type A Quantities
 of Non-Fissile Radioactive Matl " Svc list encl
 COBB, L I Division of Fuel Facilities, Materials & Safeguards
 82/11/30 Consolidated Edison Co of New York, Inc 356pp
 16387 028 24X Fiche 50-000,82/11/30,8208190257

8212090375 Advises that stress rule index & carbon content adopted as
 criteria for weld sample selection per MREQ-0313,
 Revision 1 Info required by Item 4 of IE Bulletin 82-03,
 Revision 1 will be provided by 821217
 HOWE, P W Carolina Power & Light Co 82/11/30 O'REILLY, J P
 Region 2, Office of Director 1p 16365 056 24X
 Fiche 50-324,82/11/30,8212090375

8212090129 Forwards summary of 821117 meeting at site re integrated &
 local leak test programs & cracked weld in RHR shutdown
 cooling suction piping per IE Insp Rept 50-324/82-41
 O'REILLY, J P Region 2, Office of Director 82/12/02 UTLEY, C E
 Carolina Power & Light Co 3pp 16357 322 24X
 Fiche 50-324,82/12/02,8212090129

8208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment
 Electrical Penetration Assemblies " Svc list encl
 DEYOUNG, R C Director's Office, Office of Inspection and
 Enforcement 82/12/03 Consolidated Edison Co of New York, Inc
 113pp 16411 317 24X Fiche 50-000,82/12/03,8208190259

8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay
 Sockets " Svc list encl
 JORDAN, E L Division of Engineering & Quality Assurance 82/12/03
 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X
 Fiche 50-000,82/12/03,8208190261

8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for
 Air & Gas Monitoring " Svc list encl
 DEYOUNG, R C Director's Office, Office of Inspection and
 Enforcement 82/12/16 Consolidated Edison Co of New York, Inc
 127pp 16628 191 24X Fiche 50-000,82/12/16,8208190267

8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage
 Relays Type ITE-27 " Svc list encl
 JORDAN, E L Division of Engineering & Quality Assurance 82/12/20
 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X
 Fiche 50-000,82/12/20,8208190268

It Periodic operating reports & related correspondence

8212100241 Forwards monthly operating repts for Nov 1982
 DIETZ, C R Carolina Power & Light Co 82/12/06 DEYOUNG, R C
 Director's Office, Office of Inspection and Enforcement 1p
 16376 050 24X Fiche 50-324,82/12/06,8212100241

--8212100250 Monthly operating repts for Nov 1982
 HARRISON, F Carolina Power & Light Co 82/12/01 13pp
 16376 051 24X Fiche 50-324,82/12/06,8212100241

S Reportable occurrences, LERs & related correspondence

8212020273 Forwards LER 82-126/03L-0
 DIETZ, C R Carolina Power & Light Co 82/11/23 O'REILLY, J P
 Region 2, Office of Director 1p 16279 138 24X
 Fiche 50-324,82/11/23,8212020273

--8212020297 LER 82-126/03L-0 on 821024, standby liquid control sys piping
 heat tracing on lines between sys accumulators 2-C41-A003A
 & B & common discharge line found inoperable Caused by
 electrical failure Tracing section Model FP-10 replaced
 PASTVA, M J Carolina Power & Light Co 82/11/23 Region 2,
 Office of Director 1p 16279 139 24X Fiche 50-324,82/11/23,
 8212020293

8212020315 Forwards LER 82-125/03L-0
 DIETZ, C R Carolina Power & Light Co 82/11/23 O'REILLY, J P
 Region 2, Office of Director 1p 16279 200 24X
 Fiche 50-324,82/11/23,8212020315

--8212020319 LER 82-125/03L-0 on 821024, during steady-state plant
 operation, reactor recirculation pump 2A tripped w/receipt of
 ATWS high reactor pressure/low level trip annunciator Caused by
 by setpoint drift Instrument calibr & returned to svc
 PASTVA, M J Carolina Power & Light Co 82/11/23 Region 2,
 Office of Director 2pp 16279 201 24X Fiche 50-324,82/11/23,
 8212020315

8212020362 Forwards LER 82-113/03L-0
 DIETZ, C R Carolina Power & Light Co 82/11/23 O'REILLY, J P
 Region 2, Office of Director 1p 16278 182 24X
 Fiche 50-324,82/11/23,8212020362

--8212020365 LER 82-117/03L-0 on 821026, fire watch patrol not posted
 during removal of five fire barrier penetration seals in
 control bldg Caused by unfamiliarity w/limiting conditions
 for operation & fire watch requirements
 PASTVA, M J Carolina Power & Light Co 82/11/23 Region 2,
 Office of Director 1p 16278 183 24X Fiche 50-324,82/11/23,
 8212020362

8212020068 Forwards LER 82-098/03L-0
 DIETZ, C R Carolina Power & Light Co 82/11/24 O'REILLY, J P
 Region 2, Office of Director 1p 16272 004 24X
 Fiche 50-324,82/11/24,8212020068

--8212020083 LER 82-098/03L-0 on 821027, measured vibration reading of
 2B RHR svc water pump exceeded 1.5 mils vibration Caused by
 failed gasket at pump rear bearing housing allowing loss of
 casing oil, resulting in increased operating temp
 PASTVA, M J Carolina Power & Light Co 82/11/24 Region 2,
 Office of Director 1p 16272 005 24X Fiche 50-324,82/11/24,
 8212020068

8212020152 Forwards LER 82-129/03L-0
 DIETZ, C R Carolina Power & Light Co 82/11/24 O'REILLY, J P
 Region 2, Office of Director 1p 16274 170 24X
 Fiche 50-324,82/11/24,8212020152

--8212020161 LER 82-129/03L-0 on 821028, while verifying rod drive
 coupling for rod 18-07, rod overtravel annunciator received
 Cause unknown Rod will be inspected for irregularities
 during next scheduled control rod drive rebuilding outage
 PASTVA, M J Carolina Power & Light Co 82/11/24 Region 2,
 Office of Director 1p 16274 171 24X Fiche 50-324,82/11/24,
 8212020152

8212070273 Forwards LER 82-128/03L-0
 DIETZ, C R Carolina Power & Light Co 82/11/24 O'REILLY, J P
 Region 2, Office of Director 1p 16339 073 24X
 Fiche 50-324,82/11/24,8212070273

--8212070275 LER 82-128/03L-0 on 821028, instrument recorder 2-CAC-AR-10,
 showed downscale indication of primary containment
 atmosphere hydrogen & oxygen concentration Caused by failed
 recorder print drive motor Drive motor replaced
 PASTVA, M J Carolina Power & Light Co 82/11/24 Region 2,
 Office of Director 1p 16339 074 24X Fiche 50-324,82/11/24,
 8212070273

8212070275 Part 21 rept re discrepancies between orientation of
 snubbers as shown on pipe support details & orientation as
 used in analysis of record Review of supports, design & issue
 of any fixes scheduled for completion by 821201 for Unit 1
 SARSTEN, O E United Engineers & Constructors, Inc. (subs of
 Raytheon Co) 82/11/30 Director's Office, Office of Inspection
 and Enforcement 2pp 16339 064 24X Fiche 50-324,82/11/30,
 8212070275

B212090314 Forwards LER B2-124/01T-0 Detailed event analysis encl
DIETZ, C R Carolina Power & Light Co 82/12/03 O'REILLY, J P
Region 2, Office of Director 2pp 16365 120 24X
Fiche 50-324, 82/12/03, B212090314

--B212090318 LER B2-124/01T-0 on B21121, quick start testing of diesel
generators 1, 2 & 4 not performed within required 2-h period
caused by misinterpretation of plant standing instructions
Quick starts performed. Instructions revised
PASTVA, M J Carolina Power & Light Co 82/12/03 Region 2,
Office of Director 1p 16365 122 24X Fiche 50-324, 82/12/03,
B212090314

B212300067 RD 2-82-139 on B21216, reactor water cleanup sys high
differential flow isolation instrumentation declared
inoperable due to erratic flow transmitter. Caused by
personnel error. Instrumentation repaired & restored to svc
DIETZ, C R Carolina Power & Light Co 82/12/17 O'REILLY, J P
Region 2, Office of Director 2pp 16598 202 24X
Fiche 50-324, 82/12/17, B212300067

B212280278 PND-11-82-137 on B21213, malfunctioning delta flow
instrument on reactor water cleanup sys identified. On B21216
operability of isolation instrumentation questioned. Sys
isolated. Investigation of circumstances ongoing
HARDIN, A K, VERRELLI, D M Region 2, Office of Director 82/12/20
2pp 16561 228 24X Fiche 50-324, 82/12/20, B212280278

DOCKET 50-325 BRUNSWICK STEAM ELECTRIC PLANT, UNIT 1

F Security, medical, emergency & fire protection plans

B212090273 Ack receipt of B21027 ltr informing NRC of steps taken to
correct violations noted in IE Insp Repts 50-324/82-37 &
50-325/82-37
VERRELLI, D M Division of Project & Resident Programs 82/11/16
UTLEY, E E Carolina Power & Light Co 1p 16365 287 24X
Fiche 50-324, 82/11/16, B212090273

--B212090289 Responds to NRC B21006 ltr re violations noted in IE Insp
Repts 50-324/82-37 & 50-325/82-37 Corrective actions eight
add spare cylinders purchased & weekly review to be
conducted to ensure fire brigade training current
DIETZ, C R Carolina Power & Light Co 82/10/27 O'REILLY, J P
Region 2, Office of Director 3pp 16365 290 24X
Fiche 50-324, 82/11/16, B212090273

--B212090299 Forwards IE Insp Repts 50-324/82-37 & 50-325/82-37 on
B20907-10 & notice of violation
LEHIS, R C Division of Project & Resident Programs 82/10/06
JONES, J A Carolina Power & Light Co 2pp 16365 293 24X
Fiche 50-324, 82/11/16, B212090273

--B212090309 Notice of violation from insp on B20907-10
* Division of Project & Resident Programs 82/10/06 2pp
16365 295 24X Fiche 50-324, 82/11/16, B212090273

--B212090321 IE Insp Repts 50-324/82-37 & 50-325/82-37 on B20907-10
Noncompliance noted failure to train all personnel required
to use respirator protection properly & to have adequate
number of spare air cylinders available
MILLER, W H Division of Engineering & Technical Programs
82/09/28 8pp 16365 297 24X Fiche 50-324, 82/11/16, B212090273

B212100032 Forwards info re emergency operations facility in response
to NRC B21202 verbal request & Generic Ltr B1-10 Info based
on util understanding of SECY-82-111
ZIMMERMAN, S R Carolina Power & Light Co 82/12/06 VASSALLO, D B
Operating Reactors Branch 2 2pp 16379 033 24X
Fiche 50-324, 82/12/06, B212100032

P Operating license stage documents & correspondence

B212300066 Generic Ltr B2-27 to all BWR licensees of operating reactors
except LACBWR, Big Rock Point, Dresden 1, Humboldt Bay,
applicants for DL & holders of CP re transmittal of
NUREG-0763 & NUREG-0783 Svc list encl W/o stated encl
EISENHUT, D O Division of Licensing 82/11/15 General Public
Utilities - OPU Service Corp 22pp 16387 004 24X
Fiche 50-000, 82/11/15, B212300066

B212060160 Forwards request for addl info to complete review of NUREG-
0737, Action Items I A 2 I 4, "Upgrading of Reactor Operator
& Senior Reactor Operator Training" & I B 4, "Training to
Mitigate Core Damage." Response requested within 60 days
VASSALLO, D B Operating Reactors Branch 2, 82/11/16 UTLEY, E E
Carolina Power & Light Co 2pp 16325 246 24X
Fiche 50-324, 82/11/16, B212060160

B212060111 Forwards safety evaluation re NUREG-0737, Item I F 1 3,
"Add'l Accident Monitoring Instrumentation," in response to
B10630 & B20804 submittals. Licensee proposed calibr
procedures acceptable
VASSALLO, D B Operating Reactors Branch 2 82/11/22 UTLEY, E E
Carolina Power & Light Co 3pp 16323 013 24X
Fiche 50-324, 82/11/22, B212060111

B212090307 Endorses BWR owners group B10522 & 0921 repts re NUREG-0737,
Item I K 3 23, "Effect of Loss of AC Power on Pump Seals."
Loss of ac power will not significantly degrade
recirculation pump seals
ZIMMERMAN, S R Carolina Power & Light Co 82/12/06 VASSALLO, D B
Operating Reactors Branch 2 2pp 16365 129 24X
Fiche 50-324, 82/12/06, B212090307

B212140250 Forwards supplemental info re status of selected NUREG-0737
requirements covered by Generic Ltrs B2-05 & B2-10, in
response to NRC B20317 & 0509 requests
UTLEY, E E Carolina Power & Light Co 82/12/06 EISENHUT, D O
Division of Licensing 3pp 16409 327 24X Fiche 50-324, 82/12/06,
B212140250

B212140255 Request for amend to Licenses DPR-71 & DPR-62, revising,
clarifying & providing editorial corrections to Tech Specs
re ATWS
EURY, L W Carolina Power & Light Co 82/12/06 VASSALLO, D B
Operating Reactors Branch 3 2pp 16401 332 24X
Fiche 50-324, 82/12/06, B212140255

--B212140257 Proposed Tech Specs for Licenses DPR-71 & DPR-62, revising,
clarifying & providing editorial corrections re ATWS
* Carolina Power & Light Co 82/12/06 22pp 16401 334 24X
Fiche 50-324, 82/12/06, B212140255

B212170355 Application to amend Licenses DPR-71 & DPR-62, revising Tech
Specs to incorporate organization changes. Revisions suppl
B10728 submittal
EURY, L W Carolina Power & Light Co 82/12/10 VASSALLO, D B
Operating Reactors Branch 2 2pp 16456 053 24X
Fiche 50-324, 82/12/10, B212170355

--B212170363 Proposed Tech Spec changes re administrative controls
* Carolina Power & Light Co 82/12/10 58pp 16456 085 24X
Fiche 50-324, 82/12/10, B212170355

B212170338 Supplemental application for amend to Licenses DPR-71 &
DPR-62. Changes include mods to digital-to-analog
instrumentation & reactor vessel ref water level, per B21005
meeting. Revisions supersede 790531 revisions
EURY, L W Carolina Power & Light Co 82/12/13 VASSALLO, D B
Operating Reactors Branch 2 3pp 16454 154 24X
Fiche 50-324, 82/12/13, B212170338

--B212170343 Proposed Tech Spec pages including mods to digital-to-analog
instrumentation, reactor vessel ref water level, special test
exception for core spray sys, administrative controls &
safety/relief valve challenges
* Carolina Power & Light Co 82/12/13 287pp 16454 157 24X
Fiche 50-324, 82/12/13, B212170338

--B212170350 "Brunswick Steam Electric Plant Offsite Dose Calculation
Manual (DOCH)"
* Carolina Power & Light Co 82/12/13 190pp 16455 084 24X
Fiche 50-324, 82/12/13, B212170338

--B212170356 "Brunswick Steam Electric Plant Process Control Program
(PCP)"
* Carolina Power & Light Co 82/12/13 5pp 16455 274 24X
Fiche 50-324, 82/12/13, B212170338

B212210004 Application for amends to Licenses DPR-62 & DPR-71,
correcting administrative inconsistency re min number of
operable channels per trip sys requirements for certain HPCI
& RCIC sys instruments
EURY, L W Carolina Power & Light Co 82/12/13 VASSALLO, D B
Operating Reactors Branch 2 4pp 16483 262 24X
Fiche 50-324, 82/12/13, B212210004

--B212210006 Proposed Tech Spec revisions correcting administrative
inconsistency re min number of operable channels per trip
sys requirements for certain HPCI & RCIC sys isolation
actuation instruments
* Carolina Power & Light Co 82/12/13 10pp 16485 266 24X
Fiche 50-324, 82/12/13, B212210004

B212170210 Commits to perform qualification testing of certain Raychem
radiation cross-linked polyethylene cable having combined
insulation thickness of 120 mils or greater. Proposed cable
qualification program forthcoming
UTLEY, E E Carolina Power & Light Co 82/12/15 VASSALLO, D B
Operating Reactors Branch 2 1p 16459 362 24X
Fiche 50-324, 82/12/15, B212170210

DOCKETED ITEMS

8212300145 Forwards two supplemental repts to 820808 Franklin Research Ctr rept re environ qualification of safety-related electrical equipment submitted on 821220 w/evaluation Space charges phenomenon valid concern W/o encl
VASSALLO, D B Operating Reactors Branch 2 82/12/23 UTLEY, E E
Carolina Power & Light Co 3pp 16624 188 24X
Fiche 50-324, 82/12/23, 8212300145

4 Inspection reports, IE Bulletins & correspondence

8208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240

8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000, 82/11/05, 8208190245

8212090273 Act receipt of 821027 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-324/82-37 & 50-325/82-37
VERRELLI, D M Division of Project & Resident Programs 82/11/16 UTLEY, E E Carolina Power & Light Co 1p 16365 289 24X
Fiche 50-324, 82/11/16, 8212090273

--8212090289 Responds to NRC 821006 ltr re violations noted in IE Insp Repts 50-324/82-37 & 50-325/82-37 Corrective actions eight add spare cylinders purchased & weekly review to be conducted to ensure fire brigade training current
DIETZ, C R Carolina Power & Light Co 82/10/27 O'REILLY, J P Region 2, Office of Director 3pp 16365 290 24X
Fiche 50-324, 82/11/16, 8212090273

--8212090299 Forwards IE Insp Repts 50-324/82-37 & 50-325/82-37 on 820907-10 & notice of violation
LEWIS, R C Division of Project & Resident Programs 82/10/06 JONES, J A Carolina Power & Light Co 2pp 16365 293 24X
Fiche 50-324, 82/11/16, 8212090273

--8212090309 Notice of violation from Insp on 820907-10
* Division of Project & Resident Programs 82/10/06 2pp 16365 295 24X Fiche 50-324, 82/11/16, 8212090273

--8212090321 IE Insp Repts 50-324/82-37 & 50-325/82-37 on 820907-10 Noncompliance noted failure to train all personnel required to use respirator protection properly & to have adequate number of spare air cylinders available
MILLER, H H, CONLON, T E Division of Engineering & Technical Programs 82/09/28 8pp 16365 297 24X Fiche 50-324, 82/11/16, 8212090273

8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X
Fiche 50-000, 82/11/18, 8208190251

8212090111 Forwards summary of 821110 meeting w/util in Atlanta, GA re actions taken by util to improve overall performance
O'REILLY, J P Region 2, Office of Director 82/11/24 UTLEY, E E Carolina Power & Light Co 3pp 16357 242 24X
Fiche 50-324, 82/11/24, 8212090111

8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000, 82/11/26, 8208190256

8208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000, 82/11/30, 8208190257

8212090375 Advises that stress rule index & carbon content adopted as criteria for weld sample selection per NUREG-0313, Revision 1 Info required by Item 4 of IE Bulletin 82-03, Revision 1 will be provided by 821217
HOWE, P W Carolina Power & Light Co 82/11/30 O'REILLY, J P Region 2, Office of Director 1p 16365 036 24X
Fiche 50-324, 82/11/30, 8212090375

8212090129 Forwards summary of 821117 meeting at site re integrated & local leak test programs & cracked weld in RHR shutdown cooling suction piping per IE Insp Rept 50-324/82-41
O'REILLY, J P Region 2, Office of Director 82/12/02 UTLEY, E E Carolina Power & Light Co 3pp 16357 322 24X
Fiche 50-324, 82/12/02, 8212090129

8208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259

8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X
Fiche 50-000, 82/12/03, 8208190261

8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16428 191 24X Fiche 50-000, 82/12/16, 8208190267

8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27 " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X
Fiche 50-000, 82/12/20, 8208190268

R Periodic operating reports & related correspondence

8212100241 Forwards monthly operating repts for Nov 1982
DIETZ, C R Carolina Power & Light Co 82/12/06 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 1p 16376 050 24X Fiche 50-324, 82/12/06, 8212100241

--8212100250 Monthly operating repts for Nov 1982
HARRISON, F Carolina Power & Light Co 82/12/01 13pp 16376 051 24X Fiche 50-324, 82/12/06, 8212100241

S Reportable occurrences, LERs & related correspondence

8212020306 Forwards LER 82-116/03L-0
DIETZ, C R Carolina Power & Light Co 82/11/23 O'REILLY, J P Region 2, Office of Director 1p 16277 334 24X
Fiche 50-325, 82/11/23, 8212020306

--8212020312 LER 82-116/03L-0 on 821027, RHR sys discharge valves to radwaste sys 1-E11-F040 & F049 found not fully closed Cause under investigation Supplemental rept outlining cause & corrective actions will be submitted
PASTVA, M J Carolina Power & Light Co 82/11/23 Region 2, Office of Director 1p 16277 335 24X Fiche 50-325, 82/11/23, 8212020306

8212070008 Forwards LER 82-118/03L-0
DIETZ, C R Carolina Power & Light Co 82/11/24 O'REILLY, J P Region 2, Office of Director 1p 16327 238 24X
Fiche 50-325, 82/11/24, 8212070008

--8212070012 LER 82-118/03L-0 on 821026, RT08 narrow & wide-range instruments showed suppression pool level of -29 inches while actual level -26 5 inches Caused by instrumentation inaccuracies Instrumentation recalibr & pool level restored
PASTVA, M J Carolina Power & Light Co 82/11/24 Region 2, Office of Director 1p 16327 239 24X Fiche 50-325, 82/11/24, 8212070008

8212070112 Forwards LER 82-106/03L-0
DIETZ, C R Carolina Power & Light Co 82/11/24 O'REILLY, J P Region 2, Office of Director 1p 16327 328 24X
Fiche 50-325, 82/11/24, 8212070112

--8212070118 LER 82-106/03L-0 on 821026, primary containment oxygen analyzer 1-CAC-AT-1263-2 indicated drywell oxygen concentration 3% less than indicated by redundant analyzer 1-CAC-AT-1259 Caused by instrument output shift
PASTVA, M J Carolina Power & Light Co 82/11/24 Region 2, Office of Director 1p 16327 329 24X Fiche 50-325, 82/11/24, 8212070112

8212070208 Forwards LER 82-117/03L-0
DIETZ, C R Carolina Power & Light Co 82/11/24 O'REILLY, J P Region 2, Office of Director 1p 16335 113 24X
Fiche 50-325, 82/11/24, 8212070208

DOCKETED ITEMS

--8212070214 LER 82-117/03L-O on 821026, indicators 1-CAC-LI-2601-1 & 3 & 1-CAC-LR-2602 showed level indication of ~29 inches, exceeding Tech Spec limit Caused by instrument drift Trickle flow adjusted & indicator recalibr
 PASTVA, M J Carolina Power & Light Co 82/11/24 Region 2,
 Office of Director 2pp 16335 114 24X Fiche 50-325, 82/11/24,
 8212070208

8212090167 Forwards LER 82-120/03L-O
 DIETZ, C R Carolina Power & Light Co 82/11/29 O'REILLY, J P
 Region 2, Office of Director 1p 16359 234 24X
 Fiche 50-325, 82/11/29, 8212090167

--8212090173 LER 82-120/03L-O on 821030, turbine control valve fast closure control oil pressure low switch EHC-RSL-1759 failed to actuate Cause could not be determined Switch exercised to ensure proper operation
 PASTVA, M J Carolina Power & Light Co 82/11/29 Region 2,
 Office of Director 1p 16359 233 24X Fiche 50-325, 82/11/29,
 8212090167

8212090535 Forwards LER 82-122/03L-O
 DIETZ, C R Carolina Power & Light Co 82/11/29 O'REILLY, J P
 Region 2, Office of Director 1p 16366 025 24X
 Fiche 50-325, 82/11/29, 8212090535

--8212090542 LER 82-122/03L-O on 821030 & 1104, 1A pump tripped On 821101 & 04, 1B pump tripped Tripping concurrent w/receipt of ATWS high reactor pressure/low level trip annunciation Caused by actuation of ATWS due to electrical shorting
 PASTVA, M J Carolina Power & Light Co 82/11/29 Region 2,
 Office of Director 1p 16366 026 24X Fiche 50-325, 82/11/29,
 8212090535

8212090543 Forwards LER 82-124/03L-O
 DIETZ, C R Carolina Power & Light Co 82/11/29 O'REILLY, J P
 Region 2, Office of Director 1p 16366 340 24X
 Fiche 50-325, 82/11/29, 8212090543

--8212090550 LER 82-124/03L-O on 821030, primary containment atmosphere oxygen analyzer 1-CAC-AT-1259-2 falsely indicated sudden downscale indication of drywell oxygen concentration Caused by shift in calibr setpoint due to moisture in lines
 PASTVA, M J Carolina Power & Light Co 82/11/29 Region 2,
 Office of Director 1p 16366 341 24X Fiche 50-325, 82/11/29,
 8212090543

8212070295 Part 21 rept re discrepancies between orientation of snubbers as shown on pipe support details & orientation as used in analysis of record Review of supports, design & issue of any fixes scheduled for completion by 821201 for Unit 1 SARSTEN, O E United Engineers & Constructors, Inc (subs of Raytheon Co) 82/11/30 Director's Office, Office of Inspection and Enforcement 2pp 16339 064 24X Fiche 50-324, 82/11/30,
 8212070295

8212090100 Forwards LER 82-123/03L-O
 DIETZ, C R Carolina Power & Light Co 82/12/01 O'REILLY, J P
 Region 2, Office of Director 1p 16357 309 24X
 Fiche 50-325, 82/12/01, 8212090100

--8212090105 LER 82-123/03L-O on 821101, performance of suppression pool level indicator operability test revealed remote shutdown panel instrument 1-CAC-LI-3342 indicated incorrect level Caused by change in trickle flow to wet ref leg
 PASTVA, M J Carolina Power & Light Co 82/12/01 Region 2,
 Office of Director 2pp 16357 310 24X Fiche 50-325, 82/12/01,
 8212090100

8212090135 Forwards LER 82-128/03L-O
 DIETZ, C R Carolina Power & Light Co 82/12/03 O'REILLY, J P
 Region 2, Office of Director 1p 16359 177 24X
 Fiche 50-325, 82/12/03, 8212090135

--8212090139 LER 82-128/03L-O on 821103, primary containment atmosphere oxygen analyzer 1-CAC-1259-2 tripped & could not be restarted Caused by failed low sample flow relay in instrument photohelic unit Photohelic unit replaced
 PASTVA, M J Carolina Power & Light Co 82/12/03 Region 2,
 Office of Director 1p 16359 178 24X Fiche 50-325, 82/12/03,
 8212090135

8212090147 Forwards LER 82-132/03L-O
 DIETZ, C R Carolina Power & Light Co 82/12/03 O'REILLY, J P
 Region 2, Office of Director 1p 16359 167 24X
 Fiche 50-325, 82/12/03, 8212090147

--8212090152 LER 82-132/03L-O on 821103, routine surveillance revealed lack of position indication for PCIV 1-B32-F042B located at RIP-X-243A Caused by blown valve operator solenoid power supply Fuse Fuse replaced
 PASTVA, M J Carolina Power & Light Co 82/12/03 Region 2,
 Office of Director 1p 16359 168 24X Fiche 50-325, 82/12/03,
 8212090147

8212090453 Forwards LER 82-129/03L-O
 DIETZ, C R Carolina Power & Light Co 82/12/03 O'REILLY, J P
 Region 2, Office of Director 1p 16363 247 24X
 Fiche 50-325, 82/12/03, 8212090453

--8212090463 LER 82-129/03L-O on 821103, suppression chamber water temp recorder 1-CAC-TR-778 on remote shutdown panel showed indications of temps but did not record Caused by worn print ink wheel not advancing due to adjustment problems
 PASTVA, M J Carolina Power & Light Co 82/12/03 Region 2,
 Office of Director 1p 16363 248 24X Fiche 50-325, 82/12/03,
 8212090453

8212140153 Forwards LER 82-130/03L-O
 DIETZ, C R Carolina Power & Light Co 82/12/06 O'REILLY, J P
 Region 2, Office of Director 1p 16409 348 24X
 Fiche 50-325, 82/12/06, 8212140153

--8212140159 LER 82-130/03L-O on 821104, instrument isolation valve 1-B21-F042A, located at RIP X-82B, automatically closed Caused by leakage through ref leg manifold isolation valves Valves will be repaired during next outage
 PASTVA, M J Carolina Power & Light Co 82/12/06 Region 2,
 Office of Director 2pp 16409 349 24X Fiche 50-325, 82/12/06,
 8212140153

8212140196 Forwards LER 82-133/03L-O
 DIETZ, C R Carolina Power & Light Co 82/12/06 O'REILLY, J P
 Region 2, Office of Director 1p 16409 338 24X
 Fiche 50-325, 82/12/06, 8212140196

--8212140202 LER 82-133/03L-O on 821105 & 07, diesel low oil pressure trip occurred Caused by intermittent failures of diesel low lube oil pressure start time relay Relay replaced & generator quick started
 PASTVA, M J Carolina Power & Light Co 82/12/06 Region 2,
 Office of Director 2pp 16409 339 24X Fiche 50-325, 82/12/06,
 8212140196

8212150112 Forwards LER 82-137/03L-O
 DIETZ, C R Carolina Power & Light Co 82/12/08 O'REILLY, J P
 Region 2, Office of Director 1p 16430 347 24X
 Fiche 50-325, 82/12/08, 8212150112

--8212150114 LER 82-137/03L-O on 821111, routine surveillance revealed that indication of drywell oxygen concentration increased abruptly from 1.2 to 3.1% Caused by failure of atmosphere analyzer 1-CAC-AT-1263-2 due to zero shift Unit recalibr
 PASTVA, M J Carolina Power & Light Co 82/12/08 Region 2,
 Office of Director 1p 16430 348 24X Fiche 50-325, 82/12/08,
 8212150112

8212170141 Forwards LER 82-139/03L-O
 DIETZ, C R Carolina Power & Light Co 82/12/10 O'REILLY, J P
 Region 2, Office of Director 1p 16450 226 24X
 Fiche 50-325, 82/12/10, 8212170141

--8212170156 LER 82-139/03L-O on 821114, HPCI sys rendered inoperable when HPCI steamline flow high channel B isolation occurred during operability test Caused by shorted positioning coil in HPCI speed control electrohydraulic governing regulator actuator
 PASTVA, M J Carolina Power & Light Co 82/12/10 Region 2,
 Office of Director 2pp 16450 227 24X Fiche 50-325, 82/12/10,
 8212170141

8212170216 RD on 821209, while performing corrective maint on main steam line high flow isolation instrument, Group I isolation signal mistakenly reset Placement of jumpers in control logic allowed resetting of isolation signal reinserted
 DIETZ, C R Carolina Power & Light Co 82/12/10 O'REILLY, J P
 Region 2, Office of Director 2pp 16459 352 24X
 Fiche 50-325, 82/12/10, 8212170216

8212210399 Forwards LER 82-138/03L-O
 DIETZ, C R Carolina Power & Light Co 82/12/13 O'REILLY, J P
 Region 2, Office of Director 1p 16493 055 24X
 Fiche 50-325, 82/12/13, 8212210399

--8212210405 LER 82-138/03L-O on 821114, primary containment atmosphere oxygen analyzer 1-CAC-AT-1259-2 showed sudden unexpected upscale indication of drywell oxygen concentration Caused by moisture accumulation in sample lines Accumulation removed
 PASTVA, M J Carolina Power & Light Co 82/12/13 Region 2,
 Office of Director 1p 16493 056 24X Fiche 50-325, 82/12/13,
 8212210399

8212210152 Forwards LER 82-119/03L-0
DIETZ, C R Carolina Power & Light Co 82/12/14 O'REILLY, J P
Region 2, Office of Director 1p 16485 159 24X
Fiche 50-325, 82/12/14, 8212210152

--8212210159 LER 82-119/03L-0 on 821120, average power range monitor F
declared inoperable due to erratic output signal from input
local power range monitor 28-21C Cause undetermined Spare
monitor installed
PASTVA, M J Carolina Power & Light Co 82/12/14 Region 2,
Office of Director 1p 16485 160 24X Fiche 50-325, 82/12/14,
8212210152

8212210030 Forwards LER 82-141/03L-0
DIETZ, C R Carolina Power & Light Co 82/12/15 O'REILLY, J P
Region 2, Office of Director 1p 16485 358 24X
Fiche 50-325, 82/12/15, 8212210030

--8212210032 LER 82-141/03L-0 on 821124, post-accident noble gas radiation
detection instrument I-CAC-AT-1261-3 indicated downscale
Caused by moisture accumulation on photomultiplier tubes due
to damaged mylar detector window Window replaced
PASTVA, M J Carolina Power & Light Co 82/12/15 Region 2,
Office of Director 2pp 16485 359 24X Fiche 50-325, 82/12/15,
8212210030

8212220488 Forwards LER 82-142/03L-0
DIETZ, C R Carolina Power & Light Co 82/12/17 O'REILLY, J P
Region 2, Office of Director 1p 16503 242 24X
Fiche 50-325, 82/12/17, 8212220488

--8212220493 LER 82-142/03L-0, on 821121, standby gas treatment train 1B
stopped running Caused by moisture intrusion in train local
control panel Train 1B dried & cleaned & control logic
relays replaced
PASTVA, M J Carolina Power & Light Co 82/12/17 Region 2,
Office of Director 2pp 16503 243 24X Fiche 50-325, 82/12/17,
8212220488

8212220496 Forwards LER 82-143/03L-0
DIETZ, C R Carolina Power & Light Co 82/12/17 O'REILLY, J P
Region 2, Office of Director 1p 16503 256 24X
Fiche 50-325, 82/12/17, 8212220496

- 8212220504 LER 82-143/03L-0 on 821123, inner doors of personnel
secondary containment personnel airlocks discovered
inoperable Caused by excessive leakage around seal Outer
doors sealed & inner doors adjusted
PASTVA, M J Carolina Power & Light Co 82/12/17 Region 2,
Office of Director 1p 16503 257 24X Fiche 50-325, 82/12/17,
8212220496

8212280383 Forwards LER 82-140/03L-0
DIETZ, C R Carolina Power & Light Co 82/12/18 O'REILLY, J P
Region 2, Office of Director 1p 16599 001 24X
Fiche 50-325, 82/12/18, 8212280383

--8212280397 LER 82-140/03L-0 on 821202, determined that min channels
required operable for HPCI & RCIC isolation instruments
identified in Tech Specs incorrect Caused by administrative
error Tech Spec change submitted
POULK, R M Carolina Power & Light Co 82/12/18 Region 2,
Office of Director 2pp 16599 002 24X Fiche 50-325, 82/12/18,
8212280383

8212300229 RO 1-82-154 on 821214, while detensioning reactor vessel
head, operational Mode 5 entered w/o meeting Tech Spec 3 O 4
requirements Investigation underway & Mode 5 requirements
under review
DIETZ, C R Carolina Power & Light Co 82/12/20 O'REILLY, J P
Region 2, Office of Director 2pp 16598 031 24X
Fiche 50-325, 82/12/20, 8212300229

8212300296 Forwards LER 82-144/03L-0
DIETZ, C R Carolina Power & Light Co 82/12/21 O'REILLY, J P
Region 2, Office of Director 1p 16595 260 24X
Fiche 50-325, 82/12/21, 8212300296

--8212300259 LER 82-144/03L-0 on 821127, suppression chamber water temp
recorder I-CAC-TR-778, located on remote shutdown panel,
periodically failed to record Caused by recorder print
mechanism relay K3 out of adjustment Relay adjusted
PASTVA, M J Carolina Power & Light Co 82/12/21 Region 2,
Office of Director 2pp 16595 261 24X Fiche 50-325, 82/12/21,
8212300256

8212300307 Forwards LER 82-131/03L-0
DIETZ, C R Carolina Power & Light Co 82/12/21 O'REILLY, J P
Region 2, Office of Director 1p 16594 218 24X
Fiche 50-325, 82/12/21, 8212300307

--8212300309 LER 82-131/03L-0 on 821127, surveillance revealed output
voltage of battery charger for Div 11 battery 181 offscale
high & charger capacitor on fire Caused by defective
electrical resistor R5 on charger amplifier
PASTVA, M J Carolina Power & Light Co 82/12/21 Region 2,
Office of Director 1p 16594 219 24X Fiche 50-325, 82/12/21,
8212300307

8212300360 RO 1-82-154 on 821222, review revealed Mode 5 entered w/o
meeting Tech Spec requirements Average power range monitors
& bldg ventilation radiation monitors not verified
operational Mode switch not locked in refuel position
DIETZ, C R Carolina Power & Light Co 82/12/22 O'REILLY, J P
Region 2, Office of Director 2pp 16594 241 24X
Fiche 50-325, 82/12/22, 8212300360

8212300221 Forwards updated LER 82-127/01T-1
DIETZ, C R Carolina Power & Light Co 82/12/23 O'REILLY, J P
Region 2, Office of Director 1p 16598 036 24X
Fiche 50-325, 82/12/23, 8212300221

--8212300225 Updated LER 82-127/01T-1 on 821103, quick start testing of
diesel generators 2, 3 & 4 not performed for 12 h period per
Tech Spec Caused by failure to enter requirement into daily
surveillance rept on 821102 Testing performed
PASTVA, M J Carolina Power & Light Co 82/12/23 Region 2,
Office of Director 2pp 16598 037 24X Fiche 50-325, 82/12/23,
8212300221

8212300257 Forwards LER 82-149/01T-0
DIETZ, C R Carolina Power & Light Co 82/12/23 O'REILLY, J P
Region 2, Office of Director 1p 16595 257 24X
Fiche 50-325, 82/12/23, 8212300257

--8212300262 LER 82-149/01T-0 on 821209, limiting conditions for operation
initiated on primary containment isolation sys instrument
I-821-PDTH-N006-U-1 due to downscale indications Caused by
operator error Signal reinserted
PASTVA, M J Carolina Power & Light Co 82/12/23 Region 2,
Office of Director 2pp 16595 258 24X Fiche 50-325, 82/12/23,
8212300257

8212300316 Forwards updated LER 82-110/03L-1
DIETZ, C R Carolina Power & Light Co 82/12/23 O'REILLY, J P
Region 2, Office of Director 1p 16594 210 24X
Fiche 50-325, 82/12/23, 8212300316

- 8212300317 Updated LER 82-110/03L-1 on 821019, four suppression pool
level indicators exceeded Tech Spec value during
operability test Caused by incorrect input signal due to
change in trickle flow to wet leg transmitter
PASTVA, M J Carolina Power & Light Co 82/12/23 Region 2,
Office of Director 2pp 16594 211 24X Fiche 50-325, 82/12/23,
8212300316

8212300331 Forwards supplemental LER 82-135/03L-1
DIETZ, C R Carolina Power & Light Co 82/12/23 O'REILLY, J P
Region 2, Office of Director 1p 16594 238 24X
Fiche 50-325, 82/12/23, 8212300331

--8212300334 Supplemental LER 82-135/03L-1 on 821019, 1.5-inch discrepancy
noted between narrow & wide range instruments Caused by
inoperable RT08 level instruments Plant mod package
developed to increase accuracy
PASTVA, M J Carolina Power & Light Co 82/12/23 Region 2,
Office of Director 2pp 16594 239 24X Fiche 50-325, 82/12/23,
8212300331

DOCKET 50-327 SEQUOIA NUCLEAR PLANT, UNIT 1

C NRC Safety Evaluation Report (SER), supply & correspondence

8212060033 Forwards draft supplemental SER (NUREG-0011, Suppl 6),
addressing review of permanent hydrogen mitigation sys
Final draft will be available for review by 821206
NOVAK, T M Assistant Director for Licensing 82/11/30 FRALEY, R
ACRS - Advisory Committee on Reactor Safeguards 59pp 16325 265
24X Fiche 50-327, 82/11/30, 8212060033

8212130339 Forwards proposed suppl to SER, updating NRC evaluation of
issues re hydrogen mitigation sys License condition on
hydrogen control provisionally resolved
DIRCKS, W J Office of the Executive Director for Operations
82/12/08 PALLADINO, N J, GILLINSKY, V, AHEARNE, J Commissioners
72pp 16412 214 24X Fiche 50-327, 82/12/08, 8212130339

DOCKETED ITEMS

F Security, medical, emergency & fire protection plans

8212070180 Forwards addl info in response to NRC 821112 ltr, item 4, re fire protection program
MILLS, L M Tennessee Valley Authority 82/12/02 ADENSAM, E
Licensing Branch 4 5pp 16334 294 24X Fiche 50-327, 82/12/02, 8212070180

8212170229 Provides implementation schedule for generic security training & qualification plan Public safety employees have completed initial training Training per 10CFR50 54(p) will be completed by 830801
MILLS, L M Tennessee Valley Authority 82/12/13 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 16462 020 24X Fiche 50-000, 82/12/13, 8212170229

8212170259 Notifies that required audit & insp of fire protection & loss prevention program will be completed by 830917
MILLS, L M Tennessee Valley Authority 82/12/14 ADENSAM, E
Licensing Branch 4 1p 16456 206 24X Fiche 50-327, 82/12/14, 8212170259

H General correspondence

8212140478 Forwards missing Pages 65 & 66 of EIA re low level radwaste storage for Browns Ferry Nuclear Plant & SER & EIA on low level radwaste storage facility at Sequoyah Nuclear Plant W/O encl
LOYSEN, P Advanced Fuel & Spent Fuel Licensing Branch 82/11/23
DREY, L A Affiliation Unknown 1p 16431 321 24X Fiche 50-000, 82/11/23, 8212140478

---8212140486 Requests missing pages to EIA on low level radwaste storage at Browns Ferry Nuclear Plant & copies of SER & EIA for Sequoyah Nuclear Plant
DREY, L A Affiliation Unknown 82/11/08 Office of Nuclear Material Safety & Safeguards, Director 1p 16431 031 24X Fiche 50-000, 82/11/23, 8212140478

J Insurance & indemnity information

8212020269 Submits info re const & warehouse values located offsite as result of revised site descriptions under ANI/MAELU nuclear liability insurance facility form policies
DUCK, J R Marsh & McLennan, Inc., M & M Nuclear Consultants, Inc Div 82/11/18 HAINES, H L American Nuclear Insurers 1p 16288 356 24X Fiche 50-000, 82/11/18, 8212020269

8212290150 Forwards Endorsements 1, 2 & 3 to NELIA Certificate H-66, Endorsements 1 & 2 to NELIA Certificate N-75, Endorsements 1, 2 & 3 to MAELU Certificate H-66 & Endorsements 1 & 2 to MAELU Certificate H-75
DUCK, J R Marsh & McLennan, Inc., M & M Nuclear Consultants, Inc Div 82/12/21 SALTZMAN, J Assistant Director for State & Licensee Relations 3pp 16583 066 24X Fiche 50-327, 82/12/21, 8212290150

8212300109 Forwards Endorsement 29 to NELIA Policy NF-247 & Endorsement 24 to MAELU Policy NF-102
DUCK, J R Marsh & McLennan, Inc., M & M Nuclear Consultants, Inc Div 82/12/21 SALTZMAN, J Assistant Director for State & Licensee Relations 3pp 16598 253 24X Fiche 50-327, 82/12/21, 8212300109

O Advisory Committee on Reactor Safeguards reports & correspondence

8212270418 Responds to FOIA request for documents re proposed revision &/or update to reactor safety study referred to in NUREG-0784, Chapter 10 as RS II & all documents pertaining to reactor cooling methods Forwards documents listed in app
FELTON, J M Division of Rules and Records 82/11/26 SHOLLY, S C Union of Concerned Scientists 3pp 16549 233 24X Fiche 50-000, 82/11/26, 8212270418

---8212270466 Discusses feed & bleed DHR for facilities Using PORVs & high pressure injection pumps, decay heat could be removed w/o relying on secondary sys
YOUNG, G G ABBOTT, E C ACRS - Advisory Committee on Reactor Safeguards 80/02/14 CARBON, M H ACRS - Advisory Committee on Reactor Safeguards 8pp 16549 266 24X Fiche 50-000, 82/11/26, 8212270418

P Operating license stage documents & correspondence

8212060061 Forwards response to 821119 verbal request for addl info re equipment survivability Info supls 821101 response re hydrogen combustion & control for ice condenser plants
MILLS, L M Tennessee Valley Authority 82/11/29 ADENSAM, E
Licensing Branch 4 2pp 16314 012 24X Fiche 50-327, 82/11/29, 8212060061

8212060023 Informs that util will upgrade emergency operating instructions (EOIs) as required by NUREG-0737, Item I C 1
EOIs will follow generic guidelines developed by Westinghouse owners group
MILLS, L M Tennessee Valley Authority 82/11/30 ADENSAM, E
Licensing Branch 4 2pp 16313 327 24X Fiche 50-327, 82/11/30, 8212060023

8212060076 Forwards completed questionnaire in response to Generic Ltr 82-22 re steam generator tube integrity Info verbally provided to C Stahle in 821130 telcon
MILLS, L M Tennessee Valley Authority 82/11/30 ADENSAM, E
Licensing Branch 4 2pp 16316 104 24X Fiche 50-327, 82/11/30, 8212060076

8212070176 Forwards responses to NRC verbal questions on util 82091/ proposed Tech Spec change re degraded voltage relaying
MILLS, L M Tennessee Valley Authority 82/12/01 ADENSAM, E
Licensing Branch 4 11pp 16334 314 24X Fiche 50-327, 82/12/01, 8212070176

8212080373 Requests relief from ASME Section XI requirement to hydrostatically pressure test replacement piping of essential raw cooling water sys Justification for deferral & one oversize drawing encl Aperture card is available in PDR
MILLS, L M Tennessee Valley Authority 82/12/03 ADENSAM, E
Licensing Branch 4 3pp 16352 066 24X Fiche 50-327, 82/12/03, 8212080373

8208190263 Generic Ltr 82-32 to all PWR licensees re potential steam generator-related generic requirements Forwards Science Applications, Inc draft rept re subj requirements Comments requested within 30 days of ltr Svc list encl
EISENHUT, D G Division of Licensing 82/12/09 Consolidated Edison Co of New York, Inc 27pp 16629 247 24X Fiche 50-000, 82/12/09, 8208190263

8212150010 Forwards addl info re equipment survivability per 821209 telcon request, revising 821129 submittal Core exit thermocouples located within pressure vessel & not exposed to hydrogen burning
HAMMER, D S Tennessee Valley Authority 82/12/09 ADENSAM, E
Licensing Branch 4 2pp 16421 176 24X Fiche 50-327, 82/12/09, 8212150010

8212140103 Generic Ltr 82-28 to all licensees of operating Westinghouse & C-E PWRs (except Arkansas Nuclear One, Unit 2 & San Onofre 2 & 3) re inadequate core cooling instrumentation sys Svc list encl
EISENHUT, D G Division of Licensing 82/12/10 Yankee Atomic Electric Co 27pp 16690 035 24X Fiche 50-000, 82/12/10, 8212140103

8212170236 Forwards addl info re proposed change in instrument surveillance requirement test frequency of Tables 4 3-1 & 4 3-2 & thermal/hydraulic design parameters for Unit 1 reload safety evaluation
MILLS, L M Tennessee Valley Authority 82/12/13 ADENSAM, E
Licensing Branch 4 6pp 16459 337 24X Fiche 50-327, 82/12/13, 8212170236

8212170239 Requests proposed Tech Spec change for containment ventilation sys not be considered in review of 820917 reload safety evaluation
MILLS, L M Tennessee Valley Authority 82/12/13 ADENSAM, E
Licensing Branch 4 1p 16459 335 24X Fiche 50-327, 82/12/13, 8212170239

8212290356 Notifies that util agrees to comply w/igniter operational temp limit of 1,700 F for permanent hydrogen mitigation sys, per 821223 telcon Temp should be reconsidered upon completion of addl spray tests
MILLS, L M Tennessee Valley Authority 82/12/23 ADENSAM, E
Licensing Branch 4 1p 16586 223 24X Fiche 50-327, 82/12/23, 8212290356

8212300351 Application for amend to Licenses DPR-77 & DPR-79, consisting of proposed changes to Tech Spec 4 B 1 1 2 d 1 re surveillance requirement for ac sources for electrical power sys,
MILLS, L M Tennessee Valley Authority 82/12/23 ADENSAM, E
Licensing Branch 4 2pp 16594 260 24X Fiche 50-327, 82/12/23, 8212300351

---8212300355 Proposed changes to Tech Spec 4 B 1 1 2 d 1 re surveillance requirement for ac sources for electrical power sys
M Tennessee Valley Authority 82/12/23 4pp 16594 262 24X Fiche 50-327, 82/12/23, 8212300351

DOCKETED ITEMS

181

B212300357 Application to amend Licenses DPR-77 & DPR-79, changing surveillance requirements for emergency gas treatment sys cleanup subsystems
MILLS, L M Tennessee Valley Authority 02/12/23 ADENSAM, E
Licensing Branch 4 2pp 16594 254 24X Fiche 50-327, 02/12/23, 0212300357

--B212300359 Proposed Tech Specs for Licenses DPR-77 & DPR-79 re surveillance requirements for emergency gas treatment sys cleanup subsystems Justification to support changes encl
* Tennessee Valley Authority 02/12/23 4pp 16594 256 24X
Fiche 50-327, 02/12/23, 0212300357

G212300293 Forwards 16 proprietary figures referenced in CL amend request for vol reduction sys Figures withheld (ref 10CFR2 790) Affidavit encl
MILLS, L M Tennessee Valley Authority 02/12/27 DENTON, H R
Office of Nuclear Reactor Regulation, Director 9pp 16595 119 24X Fiche 50-327, 02/12/27, 0212300293

G Inspection reports, IE Bulletins & correspondence

B208190240 IE Bulletin 02-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping of BWR Plants " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 02/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, 02/10/28, 0208190240

B212090486 Forwards IE Insp Repts 50-327/02-23 & 50-328/02-23 on 021005-08 & 18-22 No noncompliance noted
VERRELLI, D M Division of Project & Resident Programs 02/11/02
MILLS, L M Tennessee Valley Authority 2pp 16365 356 24X
Fiche 50-327, 02/11/02, 0212090486

--B212090493 IE Insp Repts 50-327/02-23 & 50-328/02-23 on 021005-08 & 18-22 No noncompliance noted Major areas inspected refueling activities & plant tour
THOMAS, M, JAPE, F Division of Engineering & Technical Programs 02/11/01 5pp 16365 358 24X Fiche 50-327, 02/11/02, 0212090486

B208190245 IE Info Notice 02-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 02/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000, 02/11/05, 0208190245

B208190251 IE Info Notice 02-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 02/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X
Fiche 50-000, 02/11/18, 0208190251

G208190256 IE Info Notice 02-46, "Defective & Obsolete Combination Padlocks " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 02/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000, 02/11/26, 0208190256

G208190257 IE Info Notice 02-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 02/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000, 02/11/30, 0208190257

G212090354 Ack receipt of 021108 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-327/02-20 & 50-328/02-20
VERRELLI, D M Division of Project & Resident Programs 02/11/30
PARRIS, H G Tennessee Valley Authority 1p 16364 179 24X
Fiche 50-327, 02/11/30, 0212090354

--B212090365 Responds to NRC 021007 ltr re violations noted in IE Insp Repts 50-327/02-20 & 50-328/02-20 Corrective actions boric acid storage tank ventilation sys temporarily modified to prevent release of radioactive matls to auxiliary bldg
MILLS, L M Tennessee Valley Authority 02/11/08 O'REILLY, J P
Region 2, Office of Director 2pp 16364 180 24X
Fiche 50-327, 02/11/30, 0212090354

--B212090370 Forwards IE Insp Repts 50-327/02-20 & 50-328/02-20 on 020806-0905 & notice of violation
VERRELLI, D M Division of Project & Resident Programs 02/10/07
PARRIS, H G Tennessee Valley Authority 2pp 16364 182 24X
Fiche 50-327, 02/11/30, 0212090354

--B212090378 Notice of violation from insp on 020806-0905
* Division of Project & Resident Programs 02/10/07 1p 16364 184 24X Fiche 50-327, 02/11/30, 0212090354

--B212090384 IE Insp Repts 50-327/02-20 & 50-328/02-20 on 020806-0905
Noncompliance noted failure to post airborne radioactivity area
FORD, C J, BUTLER, S D, QUICK, D R Division of Project & Resident Programs 02/10/06 5pp 16364 185 24X Fiche 50-327, 02/11/30, 0212090354

B208190259 IE Bulletin 02-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 02/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 02/12/03, 0208190259

B208190261 IE Info Notice 02-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 02/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X
Fiche 50-000, 02/12/03, 0208190261

B212170318 Forwards addl info re ice condenser door surveillance insp results Info suppl 020729 & 0812 submittals
MILLS, L M Tennessee Valley Authority 02/12/13 ADENSAM, E
Licensing Branch 4 2pp 16456 156 24X Fiche 50-327, 02/12/13, 0212170318

B208190267 IE Info Notice 02-49, "Correction For Sample Conditions for Air & Gas Monitoring " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 02/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, 02/12/16, 0208190267

B208190268 IE Info Notice 02-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27 " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 02/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X
Fiche 50-000, 02/12/20, 0208190268

R Periodic operating reports & related correspondence

B212290159 Forwards monthly operating repts for Oct 1982
MASON, C C Southern California Edison Co 02/11/12 Division of Data Automation & Management Information 1p 16582 203 24X
Fiche 50-327, 02/11/12, 0212290159

--B212290164 Monthly operating repts for Oct 1982
MASON, C C, EDDINGS, M, JORDAN, M Tennessee Valley Authority 02/11/07 15pp 16582 204 24X Fiche 50-327, 02/11/12, 0212290159

B212030071 Forwards central emergency control ctr meteorological data availability statistics for Apr-Sept 1982
MILLS, L M Tennessee Valley Authority 02/11/30 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 16304 210 24X
Fiche 50-000, 02/11/30, 0212030071

B212170388 Forwards "Annual Environ Operating Rept, B10301-020914," per ETG Section 5.4.1 Future reporting periods will be for period beginning on Sept 15 & ending on Sept 14 of following yr
MILLS, L M Tennessee Valley Authority 02/12/07 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 16453 011 24X
Fiche 50-327, 02/12/07, 0212170388

--B212170390 "Annual Environ Operating Rept, B10301-020914 "
* Tennessee Valley Authority 02/12/07 178pp 16453 012 24X
Fiche 50-327, 02/12/07, 0212170388

S Reportable occurrences, LERs & related correspondence

B212030086 Forwards LER 02-130/03L-0
GREEN, H J Tennessee Valley Authority 02/11/29 O'REILLY, J P
Region 2, Office of Director 1p 16304 259 24X
Fiche 50-327, 02/11/29, 0212030086

--B212030092 LER 02-130/03L-0 on 020928, during routine performance of surveillance instruction 106, group 1, rows 1 & 2 min average ice weight less than required Caused by sublimation of ice in crane wall area Ice added
CARVER, A M, HARDING, M R Tennessee Valley Authority 02/11/29
Region 2, Office of Director 1p 16304 260 24X
Fiche 50-327, 02/11/29, 0212030086

B212140241 Forwards LER 02-131/03L-0
GREEN, H J Tennessee Valley Authority 02/12/07 O'REILLY, J P
Region 2, Office of Director 1p 16409 300 24X
Fiche 50-327, 02/12/07, 0212140241

DOCKETED ITEMS

--B212140247 LER 82-131/03L-0 on B21109, during Mode 6, nuclear instrumentation sys source range detector N-32 declared inoperable due to spiking Caused by heat gun used in work on penetration junction boxes Penetration work suspended ROGERS, H R , HARDING, M R Tennessee Valley Authority 82/12/07 Region 2, Office of Director 1p 16409 301 24X Fiche 50-327, 82/12/07, 8212140241

0212280111 Forwards LER 82-135/03L-0 GREEN, H J Tennessee Valley Authority 82/12/21 O'REILLY, J P Region 2, Office of Director 1p 16564 181 24X Fiche 50-327, 82/12/21, 8212280111

--B212280116 LER 82-135/03L-0 on B21122, during Mode 5, three of four level switches on upper head injection sys found out of tolerance Caused by instrument drift Switches calibr & returned to svc LUDWIG, W C , HARDING, M R Tennessee Valley Authority 82/12/21 Region 2, Office of Director 1p 16564 182 24X Fiche 50-327, 82/12/21, 8212280111

T Hearing transcripts on non-antitrust matters

0212090182 Transcript of 821207 hearing in Washington, DC Pp 1-313 Viewgraphs encl
* ACRS - Advisory Committee on Reactor Safeguards 82/12/07 501pp 16399 248 24X Fiche 50-327, 82/12/07, 8212090182

0212220550 Unofficial transcript of Commission 821215 discussion & possible vote in Washington, DC re hydrogen control Pp 1-80 Viewgraphs & SER (NUREG-0011, Suppl 6) encl
* Commissioners 82/12/15 225pp 16540 001 24X Fiche 50-327, 82/12/15, 8212220550

DOCKET 50-328 SEQUOYAH NUCLEAR PLANT, UNIT 2

E NRC Safety Evaluation Report (SER), suppls & correspondence

0212060033 Forwards draft supplemental SER (NUREG-0011, Suppl 6), addressing review of permanent hydrogen mitigation sys final draft will be available for review by 821206 NOWAK, T M Assistant Director for Licensing 82/11/30 FRALEY, R ACRS - Advisory Committee on Reactor Safeguards 59pp 16325 265 24X Fiche 50-327, 82/11/30, 8212060033

0212130339 Forwards proposed suppl to SER, updating NRC evaluation of issues re hydrogen mitigation sys License condition on hydrogen control provisionally resolved DIRCKS, W J Office of the Executive Director for Operations 82/12/08 PALLADINO, N J, GILINSKY, V, AHEARNE, J Commissioners 92pp 16412 214 24X Fiche 50-327, 82/12/08, 8212130339

F Security, medical, emergency & fire protection plans

0212070180 Forwards addl info in response to NRC 821112 ltr, Item 4, re fire protection program MILLS, L M Tennessee Valley Authority 82/12/02 ADENSAM, E Licensing Branch 4 5pp 16394 294 24X Fiche 50-327, 82/12/02, 8212070180

0212170229 Provides implementation schedule for generic security training & qualification plan Public safety employees have completed initial training Training per 10CFR50 54(p) will be completed by 830801 MILLS, L M Tennessee Valley Authority 82/12/13 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 16462 020 24X Fiche 50-000, 82/12/13, 8212170229

0212170259 Notifies that required audit & insp of fire protection & loss prevention program will be completed by 830917 MILLS, L M Tennessee Valley Authority 82/12/14 ADENSAM, E Licensing Branch 4 1p 16456 206 24X Fiche 50-327, 82/12/14, 8212170259

H General correspondence

-- Forwards missing Pages 65 & 66 of EIA re low level radwaste r Browns Ferry Nuclear Plant & SER & EIA on radwaste storage facility at Sequoyah Nuclear encl
Advanced Fuel & Spent Fuel Licensing Branch 82/11/23 Affiliation Unknown 1p 16431-321 24X 10, 82/11/23, 8212140478

EIA on low level radwaste storage
plans of SER & EIA for

82/11/08 Office of Nuclear
ctor 1p 16431-031 24X

J Insurance & indemnity information

0212020269 Submits info re const & warehouse values located offsite as result of revised site descriptions under ANI/MAELU nuclear liability insurance facility form policies
DUCK, J R Marsh & McLennan, Inc , M & M Nuclear Consultants, Inc Div 82/11/18 HAINES, H L American Nuclear Insurers 1p 16288 356 24X Fiche 50-000, 82/11/18, 8212020269

0212290150 Forwards Endorsements 1, 2 & 3 to NELIA Certificate N-66, Endorsements 1 & 2 to NELIA Certificate N-75, Endorsements 1, 2 & 3 to MAELU Certificate M-66 & Endorsements 1 & 2 to MAELU Certificate M-75
DUCK, J R Marsh & McLennan, Inc , M & M Nuclear Consultants, Inc Div 82/12/21 SALTZMAN, J Assistant Director for State & Licensee Relations 35pp 16583 066 24X Fiche 50-327, 82/12/21, 8212290150

0212300109 Forwards Endorsement 29 to NELIA Policy NF-247 & Endorsement 24 to MAELU Policy MF-102
DUCK, J R Marsh & McLennan, Inc , M & M Nuclear Consultants, Inc Div 82/12/21 SALTZMAN, J Assistant Director for State & Licensee Relations 3pp 16598 253 24X Fiche 50-327, 82/12/21, 8212300109

O Advisory Committee on Reactor Safeguards reports & correspondence

0212270418 Responds to FOIA request for documents re proposed revision &/or update to reactor safety study referred to in NUREG-0789, Chapter 10 as RS 11 & all documents pertaining to reactor cooling methods Forwards documents listed in app
FELTON, J M Division of Rules and Records 82/11/26 SHOLLY, S C Union of Concerned Scientists 3pp 16549 233 24X Fiche 50-000, 82/11/26, 8212270418

--0212270466 Discusses feed & bleed DHR for facilities using PORVs & high pressure injection pumps, decay heat could be removed w/o relying on secondary sys
YOUNG, O O , ABDOTT, E C ACRS - Advisory Committee on Reactor Safeguards 80/02/14 CARBON, M W ACRS - Advisory Committee on Reactor Safeguards 8pp 16549 266 24X Fiche 50-000, 82/11/26, 8212270418

P Operating license stage documents & correspondence

0212060061 Forwards response to 821119 verbal request for addl info re equipment survivability Info suppls 821101 response re hydrogen combustion & control for ice condenser plants MILLS, L M Tennessee Valley Authority 82/11/29 ADENSAM, E Licensing Branch 4 2pp 16314 012 24X Fiche 50-327, 82/11/29, 8212060061

0212060023 Informs that util will upgrade emergency operating instructions (EOIs) as required by NUREG-0737, Item I C 1 EOIs will follow generic guidelines developed by Westinghouse owners group
MILLS, L M Tennessee Valley Authority 82/11/30 ADENSAM, E Licensing Branch 4 2pp 16313 327 24X Fiche 50-327, 82/11/30, 8212060023

0212060076 Forwards completed questionnaire in response to Generic ltr B2-22 re steam generator tube integrity Info verbally provided to C Stahle in 821130 telcon
MILLS, L M Tennessee Valley Authority 82/11/30 ADENSAM, E Licensing Branch 4 2pp 16316 104 24X Fiche 50-327, 82/11/30, 8212060076

0212070176 Forwards responses to NRC verbal questions on util 820917 proposed Tech Spec change re degraded voltage relaying
MILLS, L M Tennessee Valley Authority 82/12/01 ADENSAM, E Licensing Branch 4 11pp 16334 314 24X Fiche 50-327, 82/12/01, 8212070176

0212080373 Requests relief from ASME Section XI requirement to hydrostatically pressure test replacement piping of essential raw cooling water sys Justification for deferral & one oversize drawing encl Aperture card is available in PDR
MILLS, L M Tennessee Valley Authority 82/12/03 ADENSAM, E Licensing Branch 4 3pp 16352 066 24X Fiche 50-327, 82/12/03, 8212080373

021208190263 Generic Ltr 82-32 to all PWR licensees re potential steam generator-related generic requirements Forwards Science Applications, Inc draft rept re subj requirements Comments requested within 30 days of ltr Svc list encl
EISENHUT, D O Division of Licensing 82/12/09 Consolidated Edison Co of New York, Inc 29pp 16629 247 24X Fiche 50-000, 82/12/09, 8208190263

B212150010 Forwards addl info re equipment survivability per B21209 telcon request, revising B21129 submittal. Core exit thermocouples located within pressure vessel & not exposed to hydrogen burning
KAMMER, D S Tennessee Valley Authority 82/12/09 ADENSAM, E Licensing Branch 4 2pp 16421 176 24X Fiche 50-327, 82/12/09, B212150010

G212140103 Generic Ltr 82-28 to all licensees of operating Westinghouse & C-E PWRs (except Arkansas Nuclear One, Unit 2 & San Onofre 2 & 3) re inadequate core cooling instrumentation sys Svc list encl
EISENHUT, D G Division of Licensing 82/12/10 Yankee Atomic Electric Co 27pp 16690 035 24X Fiche 50-000, 82/12/10, B212140103

G212170236 Forwards addl info re proposed change in instrument surveillance requirement test frequency of Tables 4 3-1 & 4 3-2 & thermal/hydraulic design parameters for Unit 1 reload safety evaluation
MILLS, L M Tennessee Valley Authority 82/12/13 ADENSAM, E Licensing Branch 4 6pp 16439 337 24X Fiche 50-327, 82/12/13, B212170236

G212170239 Requests proposed Tech Spec change for containment ventilation sys not be considered in review of B20917 reload safety evaluation
MILLS, L M Tennessee Valley Authority 82/12/13 ADENSAM, E Licensing Branch 4 1p 16439 335 24X Fiche 50-327, 82/12/13, B212170239

G212290356 Notifies that util agrees to comply w/igniter operational temp limit of 1,700 F for permanent hydrogen mitigation sys, per B21223 telcon Temp should be reconsidered upon completion of addl spray tests
MILLS, L M Tennessee Valley Authority 82/12/23 ADENSAM, E Licensing Branch 4 1p 16586 223 24X Fiche 50-327, 82/12/23, B212290356

B212500351 Application for amend to Licenses DPR-77 & DPR-79, consisting of proposed changes to Tech Spec 4 B 1 1 2 d 11 re surveillance requirement for ac sources for electrical power sys
MILLS, L M Tennessee Valley Authority 82/12/23 ADENSAM, E Licensing Branch 4 2pp 16594 260 24X Fiche 50-327, 82/12/23, B212500351

--B212300355 Proposed changes to Tech Spec 4 B 1 1 2 d 11 re surveillance requirement for ac sources for electrical power sys
* Tennessee Valley Authority 82/12/23 4pp 16594 262 24X Fiche 50-327, 82/12/23, B212300355

G212300357 Application to amend Licenses DPR-77 & DPR-79, changing surveillance requirements for emergency gas treatment sys cleanup subsystems
MILLS, L M Tennessee Valley Authority 82/12/23 ADENSAM, E Licensing Branch 4 2pp 16594 254 24X Fiche 50-327, 82/12/23, B212300357

- B212300359 Proposed Tech Specs for Licenses DPR-77 & DPR-79 re surveillance requirements for emergency gas treatment sys cleanup subsystems Justification to support changes encl
* Tennessee Valley Authority 82/12/23 4pp 16594 256 24X Fiche 50-327, 82/12/23, B212300359

G212300293 Forwards 16 proprietary figures referenced in OL amend request for vol reduction sys Figures withheld (ref 10CFR2.790) Affidavit encl
MILLS, L M Tennessee Valley Authority 82/12/27 DENTON, H R Office of Nuclear Reactor Regulation, Director 7pp 16595 119 24X Fiche 50-327, 82/12/27, B212300293

Q Inspection reports, IE Bulletins & correspondence

B2108190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Bys Piping at BWR Plants " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, B2108190240

B212090486 Forwards IE Insp Repts 50-327/82-23 & 50-328/82-23 on B21005-08 & 18-22 No noncompliance noted
VERRELLI, D M Division of Project & Resident Programs 82/11/02 PARRIS, H G Tennessee Valley Authority 2pp 16365 336 24X Fiche 50-327, 82/11/02, B212090486

--B212090493 IE Insp Repts 50-327/82-23 & 50-328/82-23 on B21005-08 & 18-22 No noncompliance noted Major areas inspected
refueling activities & plant tour
THOMAS, M JAPE, F Division of Engineering & Technical Programs 82/11/01 5pp 16365 358 24X Fiche 50-327, 82/11/02, B212090486

B2108190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model B01 & Model B02 Thermoluminescent Dosimeters " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000, 82/11/05, B2108190245

B2108190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 107pp 16411 179 24X Fiche 50-000, 82/11/18, B2108190251

B2108190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000, 82/11/26, B2108190256

B2108190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000, 82/11/30, B2108190257

B212090354 Ack receipt of B21108 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-327/82-20 & 50-328/82-20
VERRELLI, D M Division of Project & Resident Programs 82/11/30 PARRIS, H G Tennessee Valley Authority 1p 16364 179 24X Fiche 50-327, 82/11/30, B212090354

--B212090365 Responds to NRC B21007 ltr re violations noted in IE Insp Repts 50-327/82-20 & 50-328/82-20 Corrective actions boric acid storage tank ventilation sys temporarily modified to prevent release of radioactive matls to auxiliary bldg
MILLS, L M Tennessee Valley Authority 82/11/08 O'REILLY, J P Region 2, Office of Director 2pp 16364 180 24X Fiche 50-327, 82/11/30, B212090354

--B212090370 Forwards IE Insp Repts 50-327/82-20 & 50-328/82-20 on B20806-0905 & notice of violation
VERRELLI, D M Division of Project & Resident Programs 82/10/07 PARRIS, H G Tennessee Valley Authority 2pp 16364 182 24X Fiche 50-327, 82/11/30, B212090354

--B212090378 Notice of violation from insp on B20806-0905
* Division of Project & Resident Programs 82/10/07 1p 16364 184 24X Fiche 50-327, 82/11/30, B212090354

--B212090384 IE Insp Repts 50-327/82-20 & 50-328/82-20 on B20806-0905 Noncompliance noted failure to post airborne radioactivity area
FORD, E J, BUILER, S D, QUICK, D R Division of Project & Resident Programs 82/10/06 5pp 16364 185 24X Fiche 50-327, 82/11/30, B212090354

B2108190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, B2108190259

B2108190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X Fiche 50-000, 82/12/03, B2108190261

B212170318 Forwards addl info re ice condenser door surveillance insp results Info suppl B20727 & B212 submittals
MILLS, L M Tennessee Valley Authority 82/12/13 ADENSAM, E Licensing Branch 4 2pp 16456 156 24X Fiche 50-327, 82/12/13, B212170318

B2108190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16, B2108190267

B2108190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type 17C-27 " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628, 293 24X Fiche 50-000, 82/12/20, B2108190268

DOCKETED ITEMS

R Periodic operating reports & related correspondence

B212290159 Forwards monthly operating repts for Oct 1982
 MASON, C C Southern California Edison Co 82/11/12 Division of
 Data Automation & Management Information 1p 16582 203 24X
 Fiche 50-327, 82/11/12, B212290159

--B212290164 Monthly operating repts for Oct 1982
 MASON, C C, EDDINGS, M, JORDAN, M Tennessee Valley Authority
 82/11/07 15pp 16582 204 24X Fiche 50-327, 82/11/12, B212290159

B212030071 Forwards central emergency control ctr meteorological data
 availability statistics for Apr-Sept 1982
 MILLS, L M Tennessee Valley Authority 82/11/30 DENTON, H R
 Office of Nuclear Reactor Regulation, Director 2pp 16304 210
 24X Fiche 50-000, 82/11/30, B212030071

B212170388 Forwards "Annual Environ Operating Rept, B10301-820914," per
 ETS Section 5.4.1 Future reporting periods will be for
 period beginning on Sept 15 & ending on Sept 14 of
 following yr
 MILLS, L M Tennessee Valley Authority 82/12/07 DENTON, H R
 Office of Nuclear Reactor Regulation, Director 1p 16453 011 24X
 Fiche 50-327, 82/12/07, B212170388

--B212170390 "Annual Environ Operating Rept, B10301-820914"
 * Tennessee Valley Authority 82/12/07 178pp 16453 012 24X
 Fiche 50-327, 82/12/07, B212170388

S Reportable occurrences, LERs & related correspondence

B212020179 Forwards LER 82-125/03L-0
 GREEN, H J Tennessee Valley Authority 82/11/23 O'REILLY, J P
 Region 2, Office of Director 1p 16274 107 24X
 Fiche 50-328, 82/11/23, B212020179

--B212020191 LER 82-125/03L-0 on 821029, essential raw cooling water
 effluent line radiation monitor O-RM-90-134/141 found
 inoperable due to sample flow loss Caused by normal wear of
 motor coupling in monitor pump Coupling replaced.
 ROGERS, H R, HARDING, M R Tennessee Valley Authority 82/11/23
 Region 2, Office of Director 1p 16274 108 24X
 Fiche 50-328, 82/11/23, B212020179

B212090099 Seventh interim deficiency rept re retrievable info from
 valve tag numbers initially reported on B01212 Design
 personnel awaiting approval of design change request to
 revise drawings Final rept will be issued by 030420
 MILLS, L M Tennessee Valley Authority 82/11/30 O'REILLY, J P
 Region 3, Office of Director 1p 16357 312 24X
 Fiche 50-328, 82/11/30, B212090099

B212090551 Forwards LER 82-132/03L-0
 GREEN, H J Tennessee Valley Authority 82/12/01 O'REILLY, J P
 Region 2, Office of Director 1p 16366 342 24X
 Fiche 50-328, 82/12/01, B212090551

--B212090556 LER 82-132/03L-0 on 821103, one RHR pump declared inoperable
 due to discharge flow switch failure to actuate Caused by
 failure of contacts to close due to faulty actuating cam
 Flow switch repaired & recalibr
 ROGERS, H R Tennessee Valley Authority 82/12/01 Region 2,
 Office of Director 1p 16366 343 24X Fiche 50-328, 82/12/01,
 B212090551

B212090174 Forwards LER 82-129/03L-0
 GREEN, H J Tennessee Valley Authority 82/12/02 O'REILLY, J P
 Region 2, Office of Director 1p 16359 219 24X
 Fiche 50-328, 82/12/02, B212090174

B212090178 LER 82-129/03L-0 on 821103, letdown orifice containment
 isolation valve 2-FCV-62-73 failed shut Caused by control
 fuses failing due to shorted coil in relay B149AX Coil &
 fuses replaced. Valve tested & returned to svc on 821104
 ROMINE, W D, HARDING, M R Tennessee Valley Authority 82/12/02
 Region 2, Office of Director 1p 16359 220 24X
 Fiche 50-328, 82/12/02, B212090174

B212140198 Forwards LER 82-133/03L-0
 GREEN, H J Tennessee Valley Authority 82/12/08 O'REILLY, J P
 Region 2, Office of Director 1p 16409 330 24X
 Fiche 50-328, 82/12/08, B212140198

B212140207 LER 82-133/03L-0 on 821109, steam generator 4 level channel
 LT-3-110 declared inoperable due to failing high while in
 Mode 1 Caused by faulty transistor Transistor replaced
 ROGERS, H R, HARDING, M R Tennessee Valley Authority 82/12/08
 Region 2, Office of Director, 1p 16409 331, 24X
 Fiche 50-328, 82/12/08, B212140198

B212210095 Forwards LER 82-136/03L-0
 GREEN, H J Tennessee Valley Authority 82/12/14 O'REILLY, J P
 Region 2, Office of Director 1p 16491 080 24X
 Fiche 50-328, 82/12/14, B212210095

--B212210100 LER 82-136/03L-0 on 821115, inleakage found to be 340 cubic
 ft per minute to annulus during performance of Surveillance
 Instruction 264 Caused by numerous leaks found through
 personnel access & equipment doors & other areas
 CARVER, A M, HARDING, M R Tennessee Valley Authority 82/12/14
 Region 2, Office of Director 2pp 16491 081 24X
 Fiche 50-328, 82/12/14, B212210095

B212280133 Forwards LER 82-137/03L-0
 GREEN, H J Tennessee Valley Authority 82/12/21 O'REILLY, J P
 Region 2, Office of Director 1p 16563 183 24X
 Fiche 50-328, 82/12/21, B212280133

--B212280136 LER 82-137/03L-0 on 821122, during Mode 5, four upper head
 injection switches found out of tolerance & one of four
 valves failed to close Caused by broken micro switch &
 instrument drift Valve failure caused by faulty hydraulics
 LUDWIG, W C, HARDING, M R Tennessee Valley Authority 82/12/21
 Region 2, Office of Director 2pp 16563 184 24X
 Fiche 50-328, 82/12/21, B212280133

T Hearing transcripts on non-antitrust matters

B212090182 Transcript of 821207 hearing in Washington, DC Pp 1-313
 Viewgraphs encl
 * ACRS - Advisory Committee on Reactor Safeguards 82/12/07
 501pp 16359 248 24X Fiche 50-327, 82/12/07, B212090182

B212220550 Unofficial transcript of Commission 821215 discussion &
 possible vote in Washington, DC re hydrogen control Pp 1-80
 Viewgraphs & SER (NUREG-0011, Suppl 6) encl
 * Commissioners 82/12/15 225pp 16540 001 24X
 Fiche 50-327, 82/12/15, B212220550

DOCKET 50-329 MIDLAND PLANT, UNIT 1

A Application/construction stage documents & correspondence

B212010035 Forwards S&W 821109 response to question re jobs undertaken
 on behalf of util & security holdings Two limited
 assignments unrelated to soil activities undertaken No stock
 holdings indicated
 BRUNNER, J E Consumers Power Co 82/11/15 PATON, W D Office of
 the Executive Legal Director 5pp 16260 341 24X
 Fiche 50-329, 82/11/15, B212010035

B212030269 Board Notification 82-117 forwards RH Engelken 821108 memo
 to DG Eisenhower re welding-related allegations made by
 former Bechtel employee W/O encl
 NOVAK, T M Assistant Director for Licensing 82/11/17 Atomic
 Safety & Licensing Appeal Panel 3pp 16316 323 24X
 Fiche 50-000, 82/11/17, B212030269

B212020210 Summary of 821105 meeting w/util, S&W, Parsons, Brinckerhoff
 & Govt Accountability Project in Bethesda, MD re independent
 assessment of auxiliary bldg underpinning
 HODD, D Licensing Branch 4 82/11/22 Licensing Branch 4 1pp
 16302 324 24X Fiche 50-329, 82/11/22, B212020210

B212270418 Responds to FOIA request for documents re proposed revision
 &/or update to reactor safety study referred to in
 NUREG-0784, Chapter 10 as RS II & all documents pertaining to
 reactor cooling methods Forwards documents listed in app
 FELTON, J M Division of Rules and Records 82/11/26 SHOLLY, S C
 Union of Concerned Scientists 3pp 16549 233 24X
 Fiche 50-000, 82/11/26, B212270418

--B211050027 Forwards summary of semiscale test results & advises that
 board notification re test results issued W/O encl
 NOVAK, T M Assistant Director for Licensing 82/09/24
 Division of Licensing 1p 16549 278 24X Fiche 50-000, 82/11/26,
 B212270418

B212060399 Summary of 821109 meeting w/util in Bethesda, MD re
 preliminary results of seismic margins analysis for svc
 water pump structure & borated water storage tank
 HODD, D 5 Licensing Branch 4 82/11/29 Licensing Branch 4
 40pp 16325 075 24X Fiche 50-329, 82/11/29, B212060399

G12280494 Notification of contract execution, Mod 4 to "Foundations & Underpinning Review of Remedial Measures for Structures on Fill for Midland Plants 1 & 2" Contractor Geotechnical Engineers, Inc
 * IELDS, J A Technical Assistance Contracts Branch FIN B-8035
 82/11/29 VOLLMER, R H Division of Engineering KANE, J NRC - No Detailed Affiliation Given 1p 16590 139 24X
 Fiche 50-329, 82/11/29, 8212280494

--G212280501 Mod 4, increasing total funds deobligated, to "Foundations & Underpinning Review of Remedial Measures for Structures on Fill for Midland Plants 1 & 2"
 * Geotechnical Engineers, Inc HAQAN, T F Division of Contracts
 FIN B-8035 82/11/29 1p 16590 140 24X Fiche 50-329, 82/11/29, 8212280494

G12030275 Board Notification 82-117 forwards RH Engelken 821108 memo to GO Eisenhower re welding-related allegations made by former Bechtel employee W/o encl
 NOVAK, T H Assistant Director for Licensing 82/11/30 Atomic Safety and Licensing Board Panel 5pp 16316 315 24X
 Fiche 50-000, 82/11/30, 8212030275

G12080392 Proposes changes to independent review program submitted at 821005 meeting & discussed in 821025 & 1108 meetings w/TERA & Hgt Analysis Co
 COOK, J W Consumers Power Co 82/12/03 DENTON, H R Office of Nuclear Reactor Regulation, Director KEPPLER, J G Region 3, Office of Director 4pp 16352 307 24X Fiche 50-329, 82/12/03, 8212080392,

G12090056 Forwards Revision 1 to QA Dept Procedure B-3M-1, "Qualification & Certification of Insp & Test Personnel"
 Responses to requests for addl info provided
 COOK, J W Consumers Power Co 82/12/03 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 16359 062 24X
 Fiche 50-329, 82/12/03, 8212090056

--G212090069 Revision 1 to QA Dept Procedure B-3M-1, "Qualification & Certification of Insp & Test Personnel"
 * Consumers Power Co 82/10/25 20pp 16359 066 24X
 Fiche 50-329, 82/12/03, 8212090066

G12100161 Authorizes remedial soils work activities for Dec 1982 details requested
 SHAFER, W D Region 3, Office of Director 82/12/07 MILLER, D D Consumers Power Co 3pp 16373 355 24X Fiche 50-329, 82/12/07, 8212100161

G12140293 Forwards corrected Page 1 to util 821203 ltr re qualification of insp, exam & testing & audit personnel
 Correction changes 820201 date in first paragraph to 830201
 RICHARDS, L NRC - No Detailed Affiliation Given 82/12/09 NRC -
 No Detailed Affiliation Given 1p 16401 356 24X
 Fiche 50-329, 82/12/09, 8212140293

--G212140256 Corrected Page 1 to util 821203 ltr re qualification of insp, exam & testing & audit personnel
 * Consumers Power Co 82/12/09 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 16401 357 24X
 Fiche 50-329, 82/12/09, 8212140253

G12140361 Lists remedial soils work activities authorized for implementation on Piers 12 East & 12 West under turbine bldg, per 821206 request
 WERNICK, R F Region 3, Office of Director 82/12/09 COOK, J W Consumers Power Co 2pp 16418 279 24X Fiche 50-329, 82/12/09, 8212140361

--G212140367 Requests authorization to resume const of remedial soils project on Piers 12 East & 12 West Commitments listed in util 820917 ltr implemented
 COOK, J W Consumers Power Co 82/12/06 KEPPLER, J G Region 3, Office of Director 4pp 16418 281 24X Fiche 50-329, 82/12/09, 8212140361

G12170144 Advises that Revision 9 of Drawing 7220-C-45 resolves four NRC items of concern identified in Encl 7 of 820525 ltr
 No Seismic Category I utils located outside G-listed areas shown on drawing
 COOK, J W Consumers Power Co 82/12/10 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 16450 271 24X
 Fiche 50-329, 82/12/10, 8212170144

G212210309 Forwards Revision 1 to 820430 "Environ Qualification Rept," Vols 1 & 2 Revision reflects changes in regulatory requirements
 COOK, J W Consumers Power Co 82/12/13 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 16601 343 24X
 Fiche 50-329, 82/12/13, 8212210309

- G212300149 Revision 1 to "Environ Qualification Rept," Vols 1 & 2
 * Consumers Power Co 82/12/31 1,207pp 16601 347 24X
 Fiche 50-329, 82/12/13, 8212210309

G12220440 Board Notifications 82-125 & 82-125A forwards info re H Etherington evaluation of flow blockage during natural circulation of PWRs Results do not adversely impact present circulation on reliance on natural circulation
 NOVAK, T H Assistant Director for Licensing 82/12/14 Atomic Safety and Licensing Board Panel 5pp 16523 135 24X
 Fiche 50-000, 82/12/14, 8212220440

G12290508 Notification of 830208 meeting w/util & Bechtel in Bethesda, MD to discuss seismic/dynamic equipment qualification status & application of seismic margin study results to program
 HERNAN, R W Licensing Branch 4 82/12/16 ADENSA, E O Licensing Branch 4 4pp 16593 359 24X Fiche 50-329, 82/12/16, 8212290508

G12300185 Summary of 821022 meeting w/util in Bethesda, MD re util proposal to qualify operators on both Units 1 & 2 Viewgraphs encl
 HERNAN, R W Licensing Branch 4 82/12/16 Licensing Branch 4 29pp 16612 277 24X Fiche 50-329, 82/12/16, 8212300185

G12290203 Forwards Amend III to application for DL, consisting of Revision 14 to responses to requests re plant fill
 COOK, J W Consumers Power Co 82/12/17 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 16578 203 24X
 Fiche 50-329, 82/12/17, 8212290203

--8212290208 Amend III to application for DL, consisting of Revision 14 to responses to requests re plant fill
 COOK, J W Consumers Power Co 82/12/20 607pp 16578 204 24X
 Fiche 50-329, 82/12/17, 8212290203

D NRC Draft/Final Environmental Statements, supp's & correspondence

G12070356 Summary of 821122 meeting w/util in Bethesda, MD re acceptability of environ protection plan in FES Minor changes suggested to improve clarity
 HERNAN, R W Licensing Branch 4 82/12/01 Licensing Branch 4 19pp 16356 227 24X Fiche 50-329, 82/12/01, 8212070356

G12280207 Outlines characteristics of effluent discharges from Dow Chemical tertiary treatment pond to Tittabawassee River during 801221-821120, per 821213 telcon & FES Assumptions used reasonable
 COOK, J W Consumers Power Co 82/12/21 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 16562 107 24X
 Fiche 50-329, 82/12/21, 8212280207

I NRC Safety Evaluation Report (SER), supp's & correspondence

G212100409 Forwards request for addl info on SER outstanding items re vessel head vent & locked rotor accident Response due within 30 days
 ADENSA, E O Licensing Branch 4 82/12/07 COOK, J W Consumers Power Co 5pp 16389 077 24X Fiche 50-329, 82/12/07, 8212100409

G12170074 Summary of 821014 & 20 meetings w/util & Summit Nuclear Resources in Bethesda, MD re util proposal to establish independent safety engineering group per NUREG-0737, Item 1 B 12 & SER
 HERNAN, R W Licensing Branch 4 82/12/13 Licensing Branch 4 5pp 16480 355 24X Fiche 50-329, 82/12/13, 8212170074

G12220548 Notification of 830111-14 meetings w/util & Bechtel in Ann Arbor, MI & 830113 site visit to conduct audit of environ equipment qualification program, as discussed in Section 3.11 of SER
 HERNAN, R W Licensing Branch 4 82/12/16 ADENSA, E O Licensing Branch 4 5pp 16523 352 24X Fiche 50-329, 82/12/16, 8212220548

G212290475 Summary of 821123 meeting w/util, NUS & Stoner Associates in Bethesda, MD re natural gas pipeline issue, SER Outstanding Open Item 1
 HERNAN, R W Licensing Branch 4 82/12/16 Licensing Branch 4 8pp 16606 040 24X Fiche 50-329, 82/12/16, 8212290475

G212280513 Summary of 821222 meeting w/util, Bechtel, B&H & NUS in Bethesda, MD re resolution of SER open items concerning fire protection
 HERNAN, R W Licensing Branch 4 82/12/22 Licensing Branch 4 17pp 16592 132 24X Fiche 50-329, 82/12/22, 8212280513

- 8212280516 "Resolution of NRC Staff Concerns of Midland Fire Protection Program"
 * NRC - No Detailed Affiliation Given 82/04/02 34pp 16592 149 24X Fiche 50-329, 82/12/22, 8212280513

DOCKETED ITEMS

F Security medical, emergency & fire protection plans

B'12010506 Forwards request for addl info & guidance on associated circuits re fire protection saf shutdown
ADENAM, E O Licensing Branch 4 82/11/26 COOK, J W Consumers Power Co 12pp 16270 197 24X Fiche 50-329, 82/11/26, 8212010506

B'12070300 Documents 821202 telcon re emergency operations facility facilities for four plants completed Table encl
VANDEVALLE, D J Consumers Power Co 82/12/03 CRUTCHFIELD, D Operating Reactors Branch 5 2pp 16343 156 24X
Fiche 50-000, 82/12/03, 8212070300

B212220304 Discusses layout of communications equipment required in control room, on-site technical support ctr & near-site emergency operations facility
KEPPLER, J O Region 3, Office of the Director 82/12/16 Commonwealth Edison Co 3pp 16503 351 24X Fiche 50-000, 82/12/16, 8212220304

G'12680225 Advises that util will submit milestone schedule on 830201 to identify when util responses to NRC 821126 request for info re fire protection shutdown associated circuits will be provided
COOK, J W Consumers Power Co 82/12/17 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 16562 177 24X
Fiche 50-329, 82/12/17, 8212280225

G'12280513 Summary of 821222 meeting w/util, Bechtel, B&W & NUS in Bethesda, MD re resolution of SER open items concerning fire protection
HERMAN, R W Licensing Branch 4 82/12/22 Licensing Branch 4 17pp 16592 132 24X Fiche 50-329, 82/12/22, 8212280513

-8212280516 "Resolution of NRC Staff Concerns of Midland Fire Protection Program"
* NRC - No Detailed Affiliation Given 82/04/02 34pp 16592 149 24X Fiche 50-329, 82/12/22, 8212280513

G Adjudicatory correspondence

G'11080148 Forwards Rulemaking RM-50-3, "Licensing & Regulatory Policy & Procedures re Environ Protection, U Fuel Cycle Impacts" Certificate of Svc encl
PATOL, W D Hearing Branch 2 82/11/05 BECHHOEFER, C, COWAN, F P, HARBOUR, J Atomic Safety and Licensing Board Panel 6pp 15943 219 24X Fiche 50-329, 82/11/05, 8211080148

G'12020343 Interrogatories & request for production of documents on Stamiris cost/benefit contention, per ASLB 821029 memorandum & order Related correspondence
STAMIRIS, B Stamiris, B 82/11/26 Office of the Executive Legal Director 4pp 16277 314 24X Fiche 50-329, 82/11/26, 8212020343

G212020345 Interrogatories & request for production of documents on Stamiris cost/benefit contention, per ASLB 821029 memorandum & order Related correspondence
STAMIRIS, B Stamiris, B 82/11/26 Consumers Power Co 4pp 16277 310 24X Fiche 50-329, 82/11/26, 8212020345

B'12100075 Interrogatories re nonfuel operation & maint cost considerations Related correspondence
STAMIRIS, B Stamiris, B 82/12/02 Office of the Executive Legal Director 2pp 16379 189 24X Fiche 50-329, 82/12/02, 8212100075

G'12060014 Advises that NRC intends to respond voluntarily to N Stamiris 821201 interrogatories
WRIGHT, N A Hearing Branch 2 82/12/03 BECHHOEFER, C, COWAN, F P, HARBOUR, J Atomic Safety and Licensing Board Panel 2pp 16313 334 24X Fiche 50-329, 82/12/03, 8212060014

B'12070164 Order denying NRC request to postpone 821206-11 hearings testimony presented at hearings will be sub j to re-examination if any Region 3 investigative findings relevant
BECHHOEFER, C Atomic Safety and Licensing Board Panel 82/12/03 Office of the Executive Legal Director 1p 16335 315 24X
Fiche 50-329, 82/12/03, 8212070164

B'12070174 Order extending time until 821223 for Commission to act to review ALAB-691
CHILK, S J Office of the Secretary of the Commission 82/12/03 Commissioners 1p 16334 330 24X Fiche 50-329, 82/12/03, 8212070174

B'12140387 Objections to 820920 interrogatories to util on ZACK issues Interrogatory issues sub j of independent investigation by Region 3 W/Certificate of Svc Related correspondence
STAHL, D M Consumers Power Co STAHL, D M Isham, Lincoln & Beale 82/12/10 Sinclair, M 17pp 16401 288 24X
Fiche 50-329, 82/12/10, 8212140387

B'12210314 Forwards nonconformance repts re grinding wheels & Q-listing of certain equipment components in diesel generator bldg, per util prior commitments Related correspondence
WRIGHT, N A Consumers Power Co 82/12/14 BECHHOEFER, C Atomic Safety and Licensing Board Panel 6pp 16497 121 24X
Fiche 50-329, 82/12/14, 8212210314

B'12220197 Requests info re exemption of facility from 1975 safety rules, compliance w/safety rules & regulations & time interval between accident & automatic closing of containment to seal shut & airtight condition
HARBALL, W H Mapleton Intervenor 82/12/14 Office of Nuclear Reactor Regulation, Director 2pp 16503 333 24X
Fiche 50-329, 82/12/14, 8212220197

B21230350 Notice of appearance in proceeding Certificate of Svc encl
DARTH, D E Consumers Power Co 82/12/15 3pp 16511 128 24X
Fiche 50-329, 82/12/15, 8212230350

B'12270005 Advises that NRC will voluntarily respond to B Stamiris 821202 interrogatories after requests reviewed No objections waived
WRIGHT, N A Hearing Branch 2 82/12/22 BECHHOEFER, C, COWAN, F P, HARBOUR, J Atomic Safety and Licensing Board Panel 2pp 16538 298 24X Fiche 50-329, 82/12/22, 8212270005

B212300026 Grants extension until 830128 for Commission to act to review ALAB-691
CHILK, S J Office of the Secretary of the Commission 82/12/23 Commissioners 1p 16598 311 24X Fiche 50-329, 82/12/23, 8212300026

D Advisory Committee on Reactor Safeguards reports & correspondence

B212010512 Summary of 266th ACRS meeting on 820603-05 in Washington, DC re Midland DL review, reactor vessel integrity, seismic events in emergency planning & control room habitability
* ACRS - Advisory Committee on Reactor Safeguards 82/11/26 ACRS - Advisory Committee on Reactor Safeguards 255pp 16293 236 24X Fiche 50-329, 82/11/26, 8212010512

G Inspection reports, IE Bulletins & correspondence

B'08190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BNR Plants" Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 14662 163 24X Fiche 50-000, 82/10/28, 8208190240

B'08190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters" Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000, 82/11/05, 8208190245

B'08190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements" Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 14411 199 24X
Fiche 50-000, 82/11/18, 8208190251

B'08190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks" Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 14411 065 24X Fiche 50-000, 82/11/26, 8208190256

B'08190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl" Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000, 82/11/30, 8208190257

B208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies" Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 14411 317 24X Fiche 50-000, 82/12/03, 8208190259

B'08190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Bockets" Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 14462 064 24X
Fiche 50-000, 82/12/03, 8208190261

8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16, 8208190267

8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27 " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X Fiche 50-000, 82/12/20, 8208190268

H Periodic operating reports & related correspondence

8212070017 Forwards nonconformance repts for Oct 1982, per Memorandum & Order ALAB-106 & Amend 1 to CPPR-81 & CPPR-82
COOK, J W Consumers Power Co 82/11/24 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 1,260pp 16330 001 24X Fiche 50-329, 82/11/24, 8212070017

S Reportable occurrences, LERs & related correspondence

8212020313 Third interim deficiency rept re G-related equipment cooled by non-G HVAC sys Initially reported on 820625 Corrective actions to be implemented by Bechtel listed Next rept will be submitted by 830214
COOK, J W Consumers Power Co 82/11/22 KEPLER, J G Region 3, Office of Director 9pp 16279 203 24X Fiche 50-329, 82/11/22, 8212020313

8212060112 PNO-111-82-130 on 821130, all safety-related welding on HVAC stopped after licensee determined QA program for welder certification & procedure qualification inadequate Photon Testing removed from list of approved vendors
GARDNER, R , SHAHER, W , WARNICK, R Region 3, Office of Director 82/12/01 1p 16316 102 24X Fiche 50-329, 82/12/01, 8212060112

8212100237 Final deficiency rept re cable substitutions on four Class IE cables not sized per design requirements Initially reported on 821028 Verification of correct cable type included as part of cable routing reinspect plan
COOK, J W Consumers Power Co 82/12/01 KEPLER, J G Region 3, Office of Director 6pp 16376 105 24X Fiche 50-329, 82/12/01, 8212100237

8212060416 PNO-111-82-131 on 821202, util notified Region 3 of substantial reductions in safety-related work Total of 4,000 personnel remain Engineering & const teams will be responsible for completion of one or more safety sys
SHAHER, W , WARNICK, R F , DAVIS, A B Region 3, Office of Director 82/12/03 3pp 16352 263 24X Fiche 50-329, 82/12/03, 8212060416

8212100273 Interim deficiency rept re potentially insufficient design of steel embedments in concrete using shear lugs located in tension zones Initially reported on 821105 Review criterion being developed Next rept will be submitted by 830301
COOK, J W Consumers Power Co 82/12/03 KEPLER, J G Region 3, Office of Director 6pp 16376 139 24X Fiche 50-329, 82/12/03, 8212100273

8212280046 Board Notification 82-126 forwards Warnick 821201 & 03 memos re adequacy of welder qualifications & weld procedures at sites & reduction of safety-related work in progress imposed by util
NOVAK, T M Assistant Director for Licensing 82/12/07 Atomic Safety and Licensing Board Panel 3pp 16593 011 24X Fiche 50-329, 82/12/07, 8212280046

--8212280050 Recommends ASLB be notified of encl PNO re adequacy of welder qualifications & weld procedures at site
WARNICK, R F Region 3, Office of Director 82/12/01 EISENHUT, D Division of Licensing 1p 16593 015 24X Fiche 50-329, 82/12/07, 8212280046

--8212280054 Forwards PNO re substantial reduction in amount of safety-related work at site for board notification
WARNICK, R F Region 3, Office of Director 82/12/03 EISENHUT, D O Division of Licensing 1p 16593 017 24X Fiche 50-329, 82/12/07, 8212280046

8212210156 Interim deficiency rept re possibility of frail ice formation in svc water intake structure Initially reported on 821112 Possible corrective actions under evaluation
COOK, J W Consumers Power Co 82/12/12 KEPLER, J G Region 3, Office of Director 8pp 16485 151 24X Fiche 50-329, 82/12/12, 8212210156

8212210314 Forwards nonconformance repts re grinding wheels & G-listing of certain equipment components in diesel generator bldg, per util prior commitments Related correspondence
BRUNNER, J E Consumers Power Co 82/12/14 BECHHOEFER, C Atomic Safety and Licensing Board Panel 6pp 16497 121 24X Fiche 50-329, 82/12/14, 8212210314

8212280320 Interim deficiency rept re lack of overpressurization protection on piping Initially reported on 821116 Investigation & review continuing Next rept will be submitted by 830310
COOK, J W Consumers Power Co 82/12/14 KEPLER, J G Region 3, Office of Director 7pp 16561 068 24X Fiche 50-329, 82/12/14, 8212280320

8212270126 Interim deficiency rept re adequacy of shear reinforcements at major containment penetrations SAR Change Notice 2648 Incorporated in FSAR Revision 41 Next rept will be sent by 830318
COOK, J W Consumers Power Co 82/12/17 KEPLER, J G Region 3, Office of Director 5pp 16538 152 24X Fiche 50-329, 82/12/17, 8212270126

I Hearing transcripts on non-antitrust matters

8212090188 Forwards RB Peck revised testimony Certificate of Svc encl
LAUER, R J Isham, Lincoln & Beale LAUER, R J Consumers Power Co 82/12/06 Atomic Safety and Licensing Board Panel 3pp 16362 001 24X Fiche 50-329, 82/12/06, 8212090188

--8212090194 Revised testimony of RB Peck Surcharge program at diesel generator bldg eliminated potential future settlement problems due to compressibility of plant fill matl & lack of homogeneity
PECK, R B Consumers Power Co 82/12/06 275pp 16362 004 24X Fiche 50-329, 82/12/06, 8212090188

8212100030 Transcript of 821206 hearing in Midland, MI Pp 10,149-10,345 Supporting documentation encl
* Atomic Safety and Licensing Board Panel 82/12/06 121pp 16377 277 24X Fiche 50-329, 82/12/06, 8212100030

8212140044 Transcript of 821207 hearing in Midland, MI Pp 10,346-10,597
* Atomic Safety and Licensing Board Panel 82/12/07 256pp 16409 005 24X Fiche 50-329, 82/12/07, 8212140044

8212100048 Forwards corrected Pages 8548-A, 8628, 8629 & 9194-B to transcripts of 821115 & 18 evidentiary hearings in Midland, MI
MURPHY, B M Alderson Reporting 82/12/08 MCNAMARA, A NRC - No Detailed Affiliation Given 1p 16379 072 24X Fiche 50-329, 82/12/08, 8212100048

- 8212100056 Corrected Pages 8548-A, 8628 & 8629 to transcript of 821115 evidentiary hearing in Midland, MI
* Atomic Safety and Licensing Board Panel 82/11/15 3pp 16379 073 24X Fiche 50-329, 82/12/08, 8212100048

- 8212100077 Corrected Page 7194-B to transcript of 821118 evidentiary hearing in Midland, MI
* Atomic Safety and Licensing Board Panel 82/11/18 1p 16379 076 24X Fiche 50-329, 82/12/08, 8212100048

8212140106 Transcript of 821208 hearing in Midland, MI Pp 10,598-10,803 Supporting documentation encl
* Atomic Safety and Licensing Board Panel 82/12/08 290pp 16407 236 24X Fiche 50-329, 82/12/08, 8212140106

8212150002 Transcript of 821209 hearing in Midland, MI Pp 10,804-11,007 Supporting documentation encl
* Atomic Safety and Licensing Board Panel 82/12/09 323pp 16421 331 24X Fiche 50-329, 82/12/09, 8212150002

8212150006 Transcript of 821210 evidentiary hearing in Midland, MI Pp 11,008-11,228 Supporting documentation encl
* Atomic Safety and Licensing Board Panel 82/12/10 352pp 16425 249 24X Fiche 50-329, 82/12/10, 8212150006

U Congressional/Executive Correspondence

8212100042 Responds to 821103 ltr expressing concern re implementation of QA programs Special measures taken to monitor activities
Soils settlement problem focused NRC attention Problems must be resolved before DL issued
DIRCKS, W J Office of the Executive Director for Operations 82/12/07 LEVIN, C Senate 11pp 16399 346 24X Fiche 50-329, 82/12/07, 8212100042

DOCKETED ITEMS

--B212100045 Expresses concern re implementation of QA programs Info re discussions w/J Keppler requested
LEVIN, C Senate 82/11/03 DENTON, H Office of Nuclear Reactor Regulation, Director 3pp 16399 357 24X Fiche 50-329, 82/12/07, 8212100042

DOCKET 50-330 MIDLAND PLANT, UNIT 2

A Application/construction stage documents & correspondence

B212010035 Forwards B2H 821109 response to question re jobs undertaken on behalf of util & security holdings Two limited assignments unrelated to soil activities undertaken No stock holdings indicated
BRUNNER, J E Consumers Power Co 82/11/15 PATON, H D Office of the Executive Legal Director 5pp 16260 341 24X Fiche 50-329, 82/11/15, 8212010035

B212030269 Board Notification 82-117 forwards RH Engelken 821108 memo to DG Eisenhower re welding-related allegations made by former Bechtel employee W/o encl
NOVAK, T M Assistant Director for Licensing 82/11/17 Atomic Safety and Licensing Board Panel 3pp 16316 323 24X Fiche 50-000, 82/11/17, 8212030269

B212020210 Summary of 821105 meeting w/util, S&W, Parsons, Brinckerhoff & Govt Accountability Project in Bethesda, MD re independent assessment of auxiliary bldg underpinning
HODD, D S Licensing Branch 4 82/11/22 Licensing Branch 4 12pp 16302 324 24X Fiche 50-329, 82/11/22, 8212020210

B212270418 Responds to FOIA request for documents re proposed revision &/or updates to reactor safety study referred to in NUREG-0784, Chapter 10 as RS 11 & all documents pertaining to reactor cooling methods Forwards documents listed in app
FELTON, J M Division of Rules and Records 82/11/26 SHOLLY, S C Union of Concerned Scientists 3pp 16549 233 24X Fiche 50-000, 82/11/26, 8212270418

--B211050027 Forwards summary of semiscale test results & advises that board notification re test results issued W/o encl
NOVAK, T M Assistant Director for Licensing 82/09/24 Division of Licensing 1p 16549 278 24X Fiche 50-000, 82/11/26, 8212270418

B212060389 Summary of 821109 meeting w/util in Bethesda, MD re preliminary results of seismic margins analysis for svc water pump structure & borated water storage tank
HODD, D S Licensing Branch 4 82/11/29 Licensing Branch 4 40pp 16325 075 24X Fiche 50-329, 82/11/29, 8212060389

B212280494 Notification of contract execution, Mod 4 to "Foundations & Underpinning Review of Remedial Measures for Structures on Fill for Midland Plants 1 & 2" Contractor Geotechnical Engineers, Inc
FIELDS, J A Technical Assistance Contracts Branch FIN B-8035 82/11/29 VOLLMER, R M Division of Engineering WANE, J NRC - No Detailed Affiliation Given 1p 16590 139 24X Fiche 50-329, 82/11/29, 8212280494

--B212280501 Mod 4, increasing total funds deobligated, to "Foundations & Underpinning Review or Remedial Measures for Structures on Fill for Midland Plants 1 & 2"
* Geotechnical Engineers, Inc HAQAN, T F Division of Contracts FIN B-8035 82/11/29 1p 16590 140 24X Fiche 50-329, 82/11/29, 8212280494

B212030275 Board Notification 82-117 forwards RH Engelken 821108 memo to DG Eisenhower re welding-related allegations made by former Bechtel employee W/o encl
NOVAK, T M Assistant Director for Licensing 82/11/30 Atomic Safety and Licensing Board Panel 5pp 16316 315 24X Fiche 50-000, 82/11/30, 8212030275

B212080392 Proposes changes to independent review program submitted at 821003 meeting & discussed in 821025 & 1108 meetings w/TERA & Mgt Analysis Co
COOK, J W Consumers Power Co 82/12/03 DENTON, H R Office of Nuclear Reactor Regulation, Director KEPLER, J G Region 3, Office of Director 4pp 16352 307 24X Fiche 50-329, 82/12/03, 8212080392

B212090066 Forwards Revision 1 to QA Dept Procedure B-3M-1, "Qualification & Certification of Insp & Test Personnel" Responses to requests for addl info provided
COOK, J W Consumers Power Co 82/12/03 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 16359 062 24X Fiche 50-329, 82/12/03, 8212090066

--B212090069 Revision 1 to QA Dept Procedure B-3M-1, "Qualification & Certification of Insp & Test Personnel"
* Consumers Power Co 82/10/25, 20pp 16359 066 24X Fiche 50-329, 82/12/03, 8212090066

B212100161 Authorizes remedial soils work activities for Dec 1982 Details requested
SHAFER, W D Region 3, Office of Director 82/12/07 MILLER, D D Consumers Power Co 3pp 16373 355 24X Fiche 50-329, 82/12/07, 8212100161

B212140253 Forwards corrected Page 1 to util 821203 ltr re qualification of insp, exam & testing & audit personnel Correction changes 820201 date in first paragraph to 830201
RICHARDS, L NRC - No Detailed Affiliation Given 82/12/09 NRC - No Detailed Affiliation Given 1p 16401 356 24X Fiche 50-329, 82/12/09, 8212140253

- B212140256 Corrected Page 1 to util 821203 ltr re qualification of insp, exam & testing & audit personnel
* Consumers Power Co 82/12/09 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 16401 357 24X Fiche 50-329, 82/12/09, 8212140253

B212140361 Lists remedial soils work activities authorized for implementation on Piers 12 East & 12 West under turbine bldg, per 821206 request
WARRICK, R F Region 3, Office of Director 82/12/09 COOK, J W Consumers Power Co 2pp 16418 279 24X Fiche 50-329, 82/12/09, 8212140361

--B212140367 Requests authorization to resume const of remedial soils project on Piers 12 East & 12 West Commitments listed in util 820917 ltr implemented
COOK, J W Consumers Power Co 82/12/06 KEPLER, J G Region 3, Office of Director 4pp 16418 281 24X Fiche 50-329, 82/12/09, 8212140361

B212170144 Advises that Revision 9 of Drawing 7220-C-45 resolves four NRC items of concern identified in Encl 7 of 820525 ltr No Seismic Category I utils located outside G-listed areas shown on drawing
COOK, J W Consumers Power Co 82/12/10 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 16450 271 24X Fiche 50-329, 82/12/10, 8212170144

B212210309 Forwards Revision 1 to 820430 "Environ Qualification Rept," Vols 1 & 2 Revision reflects changes in regulatory requirements
COOK, J W Consumers Power Co 82/12/13 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 16601 343 24X Fiche 50-329, 82/12/13, 8212210309

- B212300149 Revision 1 to "Environ Qualification Rept," Vols 1 & 2
* Consumers Power Co 82/12/31 1,207pp 16601 347 24X Fiche 50-329, 82/12/13, 8212210309

B212220440 Board Notifications 82-125 & 82-125A forwards info re H Etherington evaluation of flow blockage during natural circulation of PWRs Results do not adversely impact present position on reliance on natural circulation
NOVAK, T M Assistant Director for Licensing 82/12/14 Atomic Safety and Licensing Board Panel 5pp 16523 135 24X Fiche 50-000, 82/12/14, 8212220440

B212290508 Notification of 830208 meeting w/util & Bechtel in Bethesda, MD to discuss seismic/dynamic equipment qualification status & application of seismic margin study results to program
HERNAN, R W Licensing Branch 4 82/12/16 ADENSA, M E Licensing Branch 4 4pp 16593 359 24X Fiche 50-329, 82/12/16, 8212290508

B212300185 Summary of 821022 meeting w/util in Bethesda, MD re util proposal to qualify operators on both Units 1 & 2 Viewgraphs encl
HERNAN, R W Licensing Branch 4 82/12/16 Licensing Branch 4 25pp 16612 277 24X Fiche 50-329, 82/12/16, 8212300185

B212290203 Forwards Amend 111 to application for OL, consisting of Revision 14 to responses to requests re plant fill
COOK, J W Consumers Power Co 82/12/17 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 16578 203 24X Fiche 50-329, 82/12/17, 8212290203

--B212290208 Amend 111 to application for OL, consisting of Revision 14 to responses to requests re plant fill
COOK, J W Consumers Power Co 82/12/20 407pp 16578 204 24X Fiche 50-329, 82/12/17, 8212290203

D NRC Draft/Final Environmental Statements, supp's & correspondence

B212070356 Summary of 821122 meeting w/util in Bethesda, MD re acceptability of environ protection plan in FES Minor changes suggested to improve clarity
HERNAN, R W Licensing Branch 4 82/12/01 Licensing Branch 4 19pp 16356 227 24X Fiche 50-329, 82/12/01, 8212070356

DOCKETED ITEMS

189

8212280207 Outlines characteristics of effluent discharges from Dow Chemical tertiary treatment pond to Tittabawassee River during 801221-821120, per 821215 telcon & FES Assumptions used reasonable
COOK, J W Consumers Power Co 82/12/21 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 16562 107 24X Fiche 50-329, 82/12/21, 8212280207

E NRC Safety Evaluation Report (SER), suppl & correspondence

8212100409 Forwards request for addl info on SER outstanding items re vessel head vent & locked rotor accident Response due within 30 days
ADENSAM, E O Licensing Branch 4 82/12/07 COOK, J W Consumers Power Co 5pp 16389 077 24X Fiche 50-329, 82/12/07, 8212100409

8212170074 Summary of 821014 & 20 meetings w/util & Summit Nuclear Resources in Bethesda, MD re util proposal to establish independent safety engineering group per NUREG-0737, Item 3 B 1 2 & SER
HERNAN, R W Licensing Branch 4 82/12/13 Licensing Branch 4 5pp 16480 355 24X Fiche 50-329, 82/12/13, 8212170074

821220548 Notification of 830111-14 meetings w/util & Bechtel in Ann Arbor, MI & 830113 site visit to conduct audit of environ qualification program, as discussed in Section 3 11 of SER
HERNAN, R W Licensing Branch 4 82/12/16 ADENSAM, E O Licensing Branch 4 5pp 16523 352 24X Fiche 50-329, 82/12/16, 821220548

8212290475 Summary of 821123 meeting w/util, NUS & Stoner Associates in Bethesda, MD re natural gas pipeline issue, SER Outstanding Open Item 1
HERNAN, R W Licensing Branch 4 82/12/16 Licensing Branch 4 8pp 16606 040 24X Fiche 50-329, 82/12/16, 8212290475

8212280513 Summary of 821222 meeting w/util, Bechtel, B&W & NUS in Bethesda, MD re resolution of SER open items concerning fire protection
HERNAN, R W Licensing Branch 4 82/12/22 Licensing Branch 4 17pp 16592 132 24X Fiche 50-329, 82/12/22, 8212280513

F Security, medical, emergency & fire protection plans

8212010506 Forwards request for addl info & guidance on associated circuits re fire protection safe shutdown
ADENSAM, E O Licensing Branch 4 82/11/26 COOK, J W Consumers Power Co 12pp 16270 197 24X Fiche 50-329, 82/11/26, 8212010506

8212070300 Documents 821202 telcon re emergency operations facility facilities for four plants completed Table encl
VANDEWALLE, D J Consumers Power Co 82/12/03 CRUTCHFIELD, D Operating Reactors Branch 5 2pp 16343 156 24X Fiche 50-000, 82/12/03, 8212070300

8212220306 Discusses layout of communications equipment required in control room, onsite technical support ctr & near-site emergency operations facility
KEPPLER, J O Region 3, Office of Director 82/12/16 Commonwealth Edison Co 3pp 16503 351 24X Fiche 50-000, 82/12/16, 8212220306

8212280225 Advises that util will submit milestone schedule on 830201 to identify when util responses to NRC 821126 request for info re fire protection shutdown associated circuits will be provided
COOK, J W Consumers Power Co 82/12/17 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 16362 177 24X Fiche 50-329, 82/12/17, 8212280225

8212280513 Summary of 821222 meeting w/util, Bechtel, B&W & NUS in Bethesda, MD re resolution of SER open items concerning fire protection
HERNAN, R W Licensing Branch 4 82/12/22 Licensing Branch 4 17pp 16592 132 24X Fiche 50-329, 82/12/22, 8212280513

--8212280516 "Resolution of NRC Staff Concerns of Midland Fire Protection Program"
* NRC - No Detailed Affiliation Given 82/04/02 34pp 16592 149 24X Fiche 50-329, 82/12/22, 8212280513

G Adjudicatory correspondence

8211080148 Forwards Rulemaking RM-50-3, "Licensing & Regulatory Policy & Procedures for Environ Protection, U Fuel Cycle Impacts" Certificate of Bvc encl
PATON, W D Hearing Branch 2 82/11/05 BECHHOEFER, C, COWAN, F P, HARBOUR, J Atomic Safety and Licensing Board Panel 6pp 13993 219 24X Fiche 50-329, 82/11/05, 8211080148

8212020343 Interrogatories & request for production of documents on Stamiris cost/benefit contention, per ASLB 821029 memorandum & order Related correspondence
STAMIRIS, B Stamiris, B 82/11/26 Office of the Executive Legal Director App 16277 314 24X Fiche 50-329, 82/11/26, 8212020343

8212020345 Interrogatories & request for production of documents on Stamiris cost/benefit contention, per ASLB 821029 memorandum & order Related correspondence
STAMIRIS, B Stamiris, B 82/11/26 Consumers Power Co App 16277 310 24X Fiche 50-329, 82/11/26, 8212020345

8212100095 Interrogatories re nonfuel operation & maint cost considerations Related correspondence
STAMIRIS, B Stamiris, B 82/12/02 Office of the Executive Legal Director App 16379 189 24X Fiche 50-329, 82/12/02, 8212100095

8212060014 Advises that NRC intends to respond voluntarily to R Stamiris 821201 interrogatories
WRIGHT, N A Hearing Branch 2 82/12/03 BECHHOEFER, C, COWAN, F P, HARBOUR, J Atomic Safety and Licensing Board Panel 2pp 16313 334 24X Fiche 50-329, 82/12/03, 8212060014

8212070164 Order denying NRC request to postpone 821206-11 hearings Testimony presented at hearings will be subj to re-examination if any Region 3 investigative findings relevant
BECHHOEFER, C Atomic Safety and Licensing Board Panel 82/12/03 Office of the Executive Legal Director 1p 16335 315 24X Fiche 50-329, 82/12/03, 8212070164

8212070174 Order extending time until 821223 for Commission to act to review ALAD-691
CHILK, S J Office of the Secretary of the Commission 82/12/03 Commissioners 1p 16334 330 24X Fiche 50-329, 82/12/03, 8212070174

8212140387 Objections to 820720 interrogatories to util on ZACK issues Interrogatory issues subj of independent investigation by Region 3 W/Certificate of Bvc Related correspondence
STAHL, D M Consumers Power Co STAHL, D M Isham, Lincoln & Beale 82/12/10 Sinclair, M 17pp 16401 288 24X Fiche 50-329, 82/12/10, 8212140387

8212210314 Forwards nonconformance repts re grinding wheels & 0-listing of certain equipment components in diesel generator bldg, per util prior commitments Related correspondence
BRUNKER, J E Consumers Power Co 82/12/14 BECHHOEFER, C Atomic Safety and Licensing Board Panel 6pp 16497 121 24X Fiche 50-329, 82/12/14, 8212210314

8212220197 Requests info re exemption of facility from 1975 safety rules, compliance w/safety rules & regulations & time interval between accident & automatic closing of containment to seal shut & airtight condition
MARSHALL, W H Kaplan Interventionors 82/12/14 Office of Nuclear Reactor Regulation, Director 2pp 16503 333 24X Fiche 50-329, 82/12/14, 8212220197

8212230350 Notice of appearance in proceeding Certificate of Bvc encl
BARTH, D E Consumers Power Co 82/12/15 3pp 16511 128 24X Fiche 50-329, 82/12/15, 8212230350

8212270005 Advises that NRC will voluntarily respond to B Stamiris 821202 interrogatories after requests reviewed No objections waived
WRIGHT, N A Hearing Branch 2 82/12/22 BECHHOEFER, C, COWAN, F P, HARBOUR, J Atomic Safety and Licensing Board Panel 2pp 16538 298 24X Fiche 50-329, 82/12/22, 8212270005

8212300026 Grants extension until 830128 for Commission to act to review ALAD-691
CHILK, S J Office of the Secretary of the Commission 82/12/23, Commissioners 1p 16598 311 24X Fiche 50-329, 82/12/23, 8212300026

O Advisory Committee on Reactor Safeguards reports & correspondence

8212010512 Summary of 266th ACRS meeting on 820603-05 in Washington, DC re Midland OL review, reactor vessel integrity, seismic events in emergency planning & control room habitability
* ACRS - Advisory Committee on Reactor Safeguards 82/11/26 ACRS - Advisory Committee on Reactor Safeguards 255pp 16293 236 24X Fiche 50-329, 82/11/26, 8212010512

DOCKETED ITEMS

Q Inspection reports, IE Bulletins & correspondence

B208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel Recirculation Sys Piping at BWR Plants." Svc list encl
 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co. of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, B208190240

B208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters." Svc list encl
 COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co. of New York, Inc 110pp 16372 142 24X Fiche 50-000, 82/11/05, B208190245

B208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements." Svc list encl
 JORDAN, E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co. of New York, Inc 109pp 16411 199 24X Fiche 50-000, 82/11/18, B208190251

B208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Radiolocks." Svc list encl
 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co. of New York, Inc 127pp 16411 065 24X Fiche 50-000, 82/11/26, B208190256

B208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl." Svc list encl
 COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co. of New York, Inc 356pp 16387 028 24X Fiche 50-000, 82/11/30, B208190257

B208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies." Svc list encl
 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co. of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, B208190259

B208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets." Svc list encl
 JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co. of New York, Inc 110pp 16462 064 24X Fiche 50-000, 82/12/03, B208190261

B208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring." Svc list encl
 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co. of New York, Inc 127pp 16428 191 24X Fiche 50-000, 82/12/16, B208190267

B208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27." Svc list encl
 JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co. of New York, Inc 108pp 16628 293 24X Fiche 50-000, 82/12/20, B208190268

R Periodic operating reports & related correspondence

B212070017 Forwards nonconformance repts for Oct 1982 per Memorandum & Order ALAB-106 & Amend 1 to CPPR-81 & CPPR-82
 COOK, J W Consumers Power Co 82/11/24 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 1,260pp 16330 001 24X Fiche 50-329, 82/11/24, B212070017

S Reportable occurrences, LERs & related correspondence

B212020313 Third interim deficiency rept re Q-related equipment cooled by non-Q HVAC sys initially reported on 820625 Corrective actions to be implemented by Bechtel listed Next rept will be submitted by 830214
 COOK, J W Consumers Power Co 82/11/22 KEPLER, J O Region 3, Office of Director 9pp 16279 203 24X Fiche 50-329, 82/11/22, B212020313

B212060112 PNO-111-82-130 on 821130, all safety-related welding on HVAC stopped after license determined QA program for welder certification & procedure qualification inadequate Photon Testing removed from list of approved vendors
 GARDNER, R, SHAFER, W. W. WARNICK, R F Region 3, Office of Director 82/12/01 1p 16316-102 24X Fiche 50-329, 82/12/01, B212060112

B212100237 Final deficiency rept re cable substitutions on four Class IE cables not sized per design requirements Initially reported on 821028 Verification of correct cable type included as part of cable routing reinspect plan
 COOK, J W Consumers Power Co 82/12/01 KEPLER, J O Region 3, Office of Director 6pp 16376 105 24X Fiche 50-329, 82/12/01, B212100237

B212100273 Interim deficiency rept re potentially insufficient design of steel embedments in concrete using shear lugs located in tension zones Initially reported on 821105 Review criterion being developed Next rept will be submitted by 830301
 COOK, J W Consumers Power Co 82/12/03 KEPLER, J O Region 3, Office of Director 6pp 16376 139 24X Fiche 50-329, 82/12/03, B212100273

B212280046 Board Notification 82-126 forwards Warnick 821201 & 03 memos re adequacy of welder qualifications & weld procedures at sites & reduction of safety-related work in progress imposed by util
 NOVAK, T M Assistant Director for Licensing 82/12/07 Atomic Safety and Licensing Board Panel 5pp 16593 011 24X Fiche 50-329, 82/12/07, B212280046

--B212280050 Recommends ASLB be notified of encl PNO re adequacy of welder qualifications & weld procedures at site
 WARNICK, R F Region 3, Office of Director 82/12/01 EISENHUT, D Division of Licensing 1p 16593 015 24X Fiche 50-329, 82/12/07, B212280046

--B212280054 Forwards PNO re substantial reduction in amount of safety-related work at site for board notification
 WARNICK, R F Region 3, Office of Director 82/12/03 EISENHUT, D Division of Licensing 1p 16593 017 24X Fiche 50-329, 82/12/07, B212280046

B212210156 Interim deficiency rept re possibility of freeze ice formation in svc water intake structure Initially reported on 821112 Possible corrective actions under evaluation
 COOK, J W Consumers Power Co 82/12/12 KEPLER, J O Region 3, Office of Director 6pp 16485 151 24X Fiche 50-329, 82/12/12, B212210156

B212210314 Forwards nonconformance repts re grinding wheels & Q-listing of certain equipment components in diesel generator bldg, per util prior commitments Related correspondence
 BRUNNER, J E Consumers Power Co 82/12/14 BECHTOLD, C Atomic Safety and Licensing Board Panel 6pp 16497 121 24X Fiche 50-329, 82/12/14, B212210314

B212280320 Interim deficiency rept re lack of overpressurization protection on piping Initially reported on 821116 Investigation & review continuing Next rept will be submitted by 830310
 COOK, J W Consumers Power Co 82/12/14 KEPLER, J O Region 3, Office of Director 7pp 16561 068 24X Fiche 50-329, 82/12/14, B212280320

B212270126 Interim deficiency rept re adequacy of shear reinforcements at major containment penetrations SAR Change Notice 2648 incorporated in FSAR Revision 41 Next rept will be sent by 830318
 COOK, J W Consumers Power Co 82/12/17 KEPLER, J O Region 3, Office of Director 5pp 16538 192 24X Fiche 50-329, 82/12/17, B212270126

1 Hearing transcripts on non-antitrust matters

B212090188 Forwards RB Peck revised testimony Certificate of Svc encl
 LAUER, R J Ishaw, Lincoln & Beale LAUER, R J Consumers Power Co 82/12/06 Atomic Safety and Licensing Board Panel 3pp 16362 001 24X Fiche 50-329, 82/12/06, B212090188

--B212090194 Revised testimony of RB Peck Surcharge program at diesel generator bldg eliminated potential future settlement problems due to compressibility of plant fill matl & lack of homogeneity
 PECK, R B Consumers Power Co 82/12/06 275pp 16362 004 24X Fiche 50-329, 82/12/06, B212090188

B212100030 Transcript of 821206 hearing in Midland, MI Pp 10, 149-10, 349 Supporting documentation encl
 * Atomic Safety and Licensing Board Panel 82/12/06 121pp 16377 277 24X Fiche 50-329, 82/12/06, B212100030

B212140044 Transcript of 821207 hearing in Midland, MI Pp 10, 346-10, 597
 * Atomic Safety and Licensing Board Panel 82/12/07 256pp 16409 005 24X Fiche 50-329, 82/12/07, B212140044

B212100048 Forwards corrected Pages 8548-A, 8628, 8629 & 9194-0 to transcripts of 821115 & 18 evidentiary hearings in Midland, MI
 MURPHY, B M Alderson Reporting 82/12/08 MCNAMARA, A NRC - NRC Detailed Affiliation Given 1p 16379 072 24X Fiche 50-329, 82/12/08, B212100048

--B212100056 Corrected Pages 8548-A, 8628 & 8629 to transcript of B21115 evidentiary hearing in Midland, MI
 * Atomic Safety and Licensing Board Panel 82/11/15 3pp
 16379 073 24X Fiche 50-329, 82/12/08, B212100048

--B212100077 Corrected Page 9194-B to transcript of B21118 evidentiary hearing in Midland, MI
 * Atomic Safety and Licensing Board Panel 82/11/18 1p
 16379 076 24X Fiche 50-329, 82/12/08, B212100048

B212140106 Transcript of B21208 hearing in Midland, MI Pp 10, 598-10, 803 Supporting documentation encl
 * Atomic Safety and Licensing Board Panel 82/12/08 290pp
 16407 236 24X Fiche 50-329, 82/12/08, B212140106

B212150002 Transcript of B21209 hearing in Midland, MI Pp 10, 804-11, 007 Supporting documentation encl
 * Atomic Safety and Licensing Board Panel 82/12/09 323pp
 16421 331 24X Fiche 50-329, 82/12/09, B212150002

B212150006 Transcript of B21210 evidentiary hearing in Midland, MI Pp 11, 008-11, 228 Supporting documentation encl
 * Atomic Safety and Licensing Board Panel 82/12/10 352pp
 16425 249 24X Fiche 50-329, 82/12/10, B212150006

U Congressional/Executive Correspondence

B212100042 Responds to B21103 ltr expressing concern re implementation of QA programs Special measures taken to monitor activities
 Soils settlement problem focused NRC attention Problems must be resolved before OL issued
 DIRCKS, W J Office of the Executive Director for Operations 82/12/07 LEVIN, C Senate 11pp 16399 346 24X
 Fiche 50-329, 82/12/07, B212100042

--B212100045 Expresses concern re implementation of QA programs Info re discussions w/J Keppler requested
 LEVIN, C Senate 82/11/03 DENTON, H Office of Nuclear Reactor Regulation, Director 3pp 16399 357 24X Fiche 50-329, 82/12/07, B212100042

POCKET 50-331 DUANE ARNOLD ENERGY CENTER

I Security, medical, emergency & fire protection plans

B212090337 Submits info on emergency operations facility (EOF) per F Apicella request EOF established in tower at util corporate ofcs located more than 10 miles from facility per NUREG-0696
 ROOT, L D Iowa Electric Light & Power Co 82/12/03 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 16365 088 24X
 Fiche 50-331, 82/12/03, B212090337

B212170193 Forwards revision to modified amended security plan Revision withheld (ref 10CFR73.21)
 ROOT, L D Iowa Electric Light & Power Co 82/12/10 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 16462 022 24X
 Fiche 50-331, 82/12/10, B212170193

B212230369 Releases public version of special orders re communication w/NRC, state & local authorities during unusual events, alerts & emergencies
 FELTON, J M Division of Rules and Records 82/12/15 Document Management Branch 1p 16544 059 24X Fiche 50-331, 82/12/15, B212230369

--B212230374 Forwards public version of Special Orders 519 re communication w/NRC, state & local authorities during unusual events, alerts, emergencies & significant events & 522 re emergency response organization notification list
 MEYER, K A Iowa Electric Light & Power Co 82/12/07 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 16544 062 24X Fiche 50-331, 82/12/15, B212230369

--B212230377 Public version of Special Orders 519 re communication w/NRC, state & local authorities during unusual events, alerts, emergencies & significant events & 522 re emergency response organization notification list
 MEYER, K A Iowa Electric Light & Power Co 82/12/07 32pp 16544 063 24X Fiche 50-331, 82/12/15, B212230369

B212220306 Discusses layout of communications equipment required in control room, onsite technical support ctr & near-site emergency operations facility
 KEPPLER, J O Region 3, Office of Director 82/12/16 Commonwealth Edison Co 3pp 16503 351 24X Fiche 50-000, 82/12/16, B212220306

B212270168 Application to amend License DPR-49, modifying Tech Specs re Mark I containment mod program, compliance w/ANSI-N18.7, safety committee quorum & frequency of audits of emergency & security plans
 ROOT, L D Iowa Electric Light & Power Co 82/12/20 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 16538 033 24X Fiche 50-331, 82/12/20, B212270168

--B212270176 Proposed Tech Specs re Mark I containment mod program, compliance w/ANSI-N18.7, safety committee quorum & frequency of audits of emergency & security plans
 * Iowa Electric Light & Power Co 82/12/20 8pp 16538 035 24X Fiche 50-331, 82/12/20, B212270168

J Insurance & indemnity information

B212150132 Applies for pro-rata refund due to reduction of indemnity fee to mth re licensing of B80th unit
 SECKMAN, P E Iowa Electric Light & Power Co 82/12/10 SALTZMAN, J Antitrust & Economic analysis Branch (Utility Finance) 1p 16425 228 24X Fiche 50-331, 82/12/10, B212150132

P Operating license stage documents & correspondence

B21230066 Generic Ltr 82-27 to all BWR licensees of operating reactors except LACBWR, Big Rock Point, Dresden I, Humboldt Bay, applicants for OL & holders of CP re transmittal of NUREG-0763 & NUREG-0783 Svc list encl w/o stated encl
 EISENHUT, D G Division of Licensing 82/11/15 General Public Utilities - OPU Service Corp 22pp 16387 004 24X
 Fiche 50-000, 82/11/15, B21230066

B212020007 Forwards SER & technical evaluation rept re TMI Items I A 2 1 4, "Upgrading of Reactor Operator & Senior Reactor Operator Training" & II B 4, "Training for Mitigating Core Damage" Items considered resolved
 VASSALLO, D B Operating Reactors Branch 2 82/11/23 ARNOLD, D Iowa Electric Light & Power Co 8pp 16308 303 24X
 Fiche 50-331, 82/11/23, B212020007

--B208310315 "Improvements in Training & Requalification Programs As Required By TMI Action Items I A 2 1 & II B 4 for Duane Arnold Energy Ctr." technical evaluation rept
 * Science Applications, Inc NRC-03-82-096 SAI-186-029-35 82/08/26 NRC - No Detailed Affiliation Given 15pp 16308 312 24X Fiche 50-331, 82/11/23, B212020007

B212100278 Application to amend License DPR-49, revising App A Tech Specs to incorporate changes to surveillance requirements for functional testing of mechanical snubbers
 ROOT, L D Iowa Electric Light & Power Co 82/11/24 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 16377 052 24X
 Fiche 50-331, 82/11/24, B212100278

--B212100284 Proposed Tech Specs re surveillance requirement for functional testing of mechanical snubbers
 * Iowa Electric Light & Power Co 82/11/24 3pp 16377 053 24X Fiche 50-331, 82/11/24, B212100278

B212070216 Forwards Class III amend fee for review of definition of "insuperable," in response to NRC B21110 ltr Protests fee classification
 ROOT, L D Iowa Electric Light & Power Co 82/11/29 MILLER, W D License Fee Management Branch 2pp 16329 357 24X
 Fiche 50-331, 82/11/29, B212070216

B212130280 Forwards safety evaluation of BWR owners group 810522, 0721 & 820902 responses to NUREG-0737, Item II K 3 25, "Effect of Loss of AC Power on Pump Seals" Responses acceptable
 VASSALLO, D B Operating Reactors Branch 2 82/12/01 ARNOLD, D Iowa Electric Light & Power Co 7pp 16418 234 24X
 Fiche 50-331, 82/12/01, B212130280

B212070308 Suppls util 811215 rept on NUREG-0612, "Control of Heavy Loads at Nuclear Power Plants," in response to Franklin Research Ctr draft technical evaluation rept dtd 811023
 ROOT, L D Iowa Electric Light & Power Co 82/12/02 DENTON, H R Office of Nuclear Reactor Regulation, Director 6pp 16343 162 24X Fiche 50-331, 82/12/02, B212070308

B212070463 Authorizes refund of duplicate fee submitted for amend request re plan for integrated scheduling of plant mods
 MILLER, W D License Fee Management Branch 82/12/03 BATTIE, D Iowa Electric Light & Power Co 1p 16355 318 24X
 Fiche 50-331, 82/12/03, B212070463

DOCKETED ITEMS

8212090322 Application to amend License DPR-49, revising App A Tech Specs to clarify conditions under which refueling operations may continue concurrent w/ torus water level below min Tech Spec vol Class III amend fee encl
RODT, L D Iowa Electric Light & Power Co 82/12/06 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 16365 115
24X Fiche 50-331, 82/12/06, 8212090322

--8212090328 Proposed Tech Specs re surveillance requirement for core & containment cooling subsystem condensate storage tank during refueling operations
* Iowa Electric Light & Power Co 82/12/06 3pp 16365 117
24X Fiche 50-331, 82/12/06, 8212090322

8212270525 Forwards Amend 79 to License DPR-49, & notice of issuance & availability Amend changes limiting conditions for operation & surveillance requirements for reactor protection sys power monitoring sys
VASSALLO, D B Operating Reactors Branch 2 82/12/06 ARNOLD, D
Iowa Electric Light & Power Co 3pp 16551 006 24X
Fiche 50-331, 82/12/06, 8212270525

--8212270532 Amend 79 to License DPR-49, changing limiting conditions for operation & surveillance requirements for reactor protection sys power monitoring sys
VASSALLO, D B Operating Reactors Branch 2 82/12/06 3pp 16551 009 24X Fiche 50-331, 82/12/06, 8212270532

--8212270536 Notice of issuance & availability of Amend 79 to License DPR-49
VASSALLO, D B Operating Reactors Branch 2 82/12/06 2pp 16551 014 24X Fiche 50-331, 82/12/06, 8212270536

8212130350 Advises that since facility venting capability is acceptable, TMI Item II B 1 re RCS high point vents is resolved Review did not evaluate 10CFR50.44 compliance or automatic depressurization sys valve accumulator capacity
VASSALLO, D B Operating Reactors Branch 2 82/12/07 ARNOLD, D
Iowa Electric Light & Power Co 3pp 16412 091 24X
Fiche 50-331, 82/12/07, 8212130350

--8209220453 "Operating Reactors - TMI Lessons Learned NUREG-0737 Response Evaluations (Program II), Project 1 - RCS vents (Item II B 1)," final technical evaluation rept for Duane Arnold
* Energy Incorporated FIN A-0246-2 82/07/01 BUTCHER, E
Division of Licensing 4pp 16412 094 24X Fiche 50-331, 82/12/07, 8212130350

--8209220450 Advises that plant venting capability acceptable if confirmatory items satisfactorily resolved
SPEIB, T P Assistant Director for Reactor Safety 82/08/31
LAINAS, Q C Assistant Director for Operating Reactors 2pp 16412 098 24X Fiche 50-331, 82/12/07, 8212130350

8212130365 Advises that fundamental changes in radiological effluent Tech Specs unacceptable Tech Specs must include listed requirements Detailed discussion of unresolved items encl
responses due in 60 days
VASSALLO, D B Operating Reactors Branch 2 82/12/07 ARNOLD, D
Iowa Electric Light & Power Co 7pp 16413 235 24X
Fiche 50-331, 82/12/07, 8212130365

8212150070 Forwards Revision 4 to ASME Inservice Testing Program IOW-45-201 for pumps & valves for Jan 1983-May 1984 Revision written & implemented per 1980 edition, including 1980 addenda of ASME Section XI
RODT, L D Iowa Electric Light & Power Co 82/12/08 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 16430 010 24X
Fiche 50-331, 82/12/08, 8212150070

--8212150072 Revision 4 to ASME Inservice Testing Program IOW-45-201 for pumps & valves for Jan 1983 - May 1984
KIH, J W, PICKENS, T A, GAVULA, J J NUTECH (Nuclear Technology, Inc) 82/10/22 139pp 16430 011 24X Fiche 50-331, 82/12/08, 8212150070

8212210315 Application to amend License DPR-49, changing Tech Specs to incorporate common ref level for reactor vessel water level instrumentation
RODT, L D Iowa Electric Light & Power Co 82/12/13 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 16496 295 24X
Fiche 50-331, 82/12/13, 8212210315

--8212210316 Proposed Tech Spec changes, incorporating common ref level for reactor vessel water level instrumentation
* Iowa Electric Light & Power Co 82/12/13 13pp 16496 296 24X
Fiche 50-331, 82/12/13, 8212210315

8212170308 Forwards response to 820728 request for addl info re NUREG-0737, Item II D 1, "Relief & Safety Valve Test " No functional valve deficiencies or anomalies experienced during Hyle Lab testing
RODT, L D Iowa Electric Light & Power Co 82/12/14 DENTON, H R
Office of Nuclear Reactor Regulation, Director 11pp 16456 139 24X Fiche 50-331, 82/12/14, 8212170308

- 8212170311 "Operability Test Rept for Target Rock Three Stage Svc for Low Pressure Water Tests for GE "
HILSAP, L J, DALEY, C, MOSELY, T Hyle Laboratories 82/12/14 3pp 16456 150 24X Fiche 50-331, 82/12/14, 8212170308

8212270168 Application to amend License DPR-49, modifying Tech Specs re Mark I containment mod program, compliance w/ANSI-N18.7, safety committee quorum & frequency of audits of emergency & security plans
RODT, L D Iowa Electric Light & Power Co 82/12/20 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 16538 033 24X Fiche 50-331, 82/12/20, 8212270168

- 8212270176 Proposed Tech Specs re Mark I containment mod program, compliance w/ANSI-N18.7, safety committee quorum & frequency of audits of emergency & security plans
* Iowa Electric Light & Power Co 82/12/20 8pp 16538 035 24X Fiche 50-331, 82/12/20, 8212270168

8212280065 Forwards response to request for addl info re NUREG-0313, "Technical Rept on Matl Selection & Processing Guidelines for BWR Coolant Pressure Boundary Piping "
RODT, L D Iowa Electric Light & Power Co 82/12/21 DENTON, H R
Office of Nuclear Reactor Regulation, Director 130pp 16564 292 24X Fiche 50-331, 82/12/21, 8212280065

0 Inspection reports, IE Bulletins & correspondence

8208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel Recirculation Sys Piping at BWR Plants " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240

8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model B01 & Model B02 Thermoluminescent Dosimeters " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000, 82/11/05, 8208190245

8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 107pp 16411 199 24X
Fiche 50-000, 82/11/18, 8208190251

8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Radiacks " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000, 82/11/26, 8208190256

8208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000, 82/11/30, 8208190257

8212060318 Ack receipt of 821119 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-331/82-04
NORELIUS, C E Division of Engineering & Technical Programs 82/11/30 ARNOLD, D Iowa Electric Light & Power Co 1p 16312 090 24X Fiche 50-331, 82/11/30, 8212060318

--8212060324 Responds to NRC 821005 ltr re violations noted in IE Insp Rept 50-331/82-04 Corrective actions audits for scope & scheduling requirements & safety committee review of QA audit violations completed
RODT, L D Iowa Electric Light & Power Co 82/11/19 KEPPLER, J O
Region 3, Office of Director 16pp 16312 091 24X
Fiche 50-331, 82/11/30, 8212060318

821200275 Forwards response to Revision 1 to IE Bulletin 82-03 re stress corrosion cracking in thick wall, large diameter, stainless steel recirculation sys piping at BWRs Addl info to be developed during Cycle 7 outage scheduled for 830211
RODT, L D Iowa Electric Light & Power Co 82/12/01 KEPPLER, J O
Region 3, Office of Director 14pp 16376 302 24X
Fiche 50-331, 82/12/01, 821200275

- 8212100303 "Stress Corrosion Cracking Evaluation Program, Duane Arnold Energy Ctr "
MARTIN, J B , SULLIVAN, M D , RICCARDELLA, P NUTECH (Nuclear Technology, Inc) 80/04/23 75pp 16376 316 24X
Fiche 50-331, 82/12/01, 8212100295

8212080274 Responds to B20930 ltr re regulatory improvement program
Program acceptable
KEPPLER, J O Region 3, Office of Director 82/12/02 ARNOLD, D
Iowa Electric Light & Power Co 1p 16354 240 24X
Fiche 50-331, 82/12/02, 8212080274

8208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl
DEVOUNO, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc
113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259

8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X
Fiche 50-000, 82/12/03, 8208190261

8212270298 Provides clarification for util commitments re IE Insp Repts 50-331/81-03 Item 48 & 50-331/81-13 Item 2 Commitment to revise emergency & plant operating instructions changed to cycle & refueling outage
HILL, K L Iowa Electric Light & Power Co 82/12/03 KEPPLER, J O
Region 3, Office of Director 2pp 16530 172 24X
Fiche 50-331, 82/12/03, 8212270298

8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
DEVOUNO, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc
127pp 16628 191 24X Fiche 50-000, 82/12/16, 8208190267

8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27 " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/00 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X
Fiche 50-000, 82/12/20, 8208190268

8 Periodic operating reports & related correspondence

8212140134 Corrects error discovered in semiannual rept for Jan-June 1979 in values reported for Sr-89 & Sr-90 for liquid effluents Caused by conversion error
MINECK, D L Iowa Electric Light & Power Co 82/11/17 Director's Office, Office of Inspection and Enforcement 1p 16408 235 24X
Fiche 50-331, 82/11/17, 8212140134

8212210209 Forwards monthly operating rept for Nov 1982
MINECK, D L Iowa Electric Light & Power Co 82/12/15 Director's Office, Office of Inspection and Enforcement 1p 16484 358 24X
Fiche 50-331, 82/12/15, 8212210209

- 8212210210 Monthly operating rept for Nov 1982
WATSON, M Iowa Electric Light & Power Co 82/12/15 4pp
16484 359 24X Fiche 50-331, 82/12/15, 8212210209

5 Reportable occurrences, LERs & related correspondence

8212060221 Forwards LER 82-073/03L-0
MINECK, D L Iowa Electric Light & Power Co 82/11/24 KEPPLER, J O
Region 3, Office of Director 1p 16313 187 24X
Fiche 50-331, 82/11/24, 8212060221

--8212060224 LER 82-073/03L-0 on 821102, monthly surveillance test of standby diesel generator fuel oil not performed in prescribed time for Oct Caused by personnel error
Responsible personnel disciplined
HILL, K L Iowa Electric Light & Power Co 82/11/24 Region 3, Office of Director 1p 16313 188 24X Fiche 50-331, 82/11/24, 8212060221

8212140142 Forwards LER 82-074/03L-0
MINECK, D L Iowa Electric Light & Power Co 82/12/03 KEPPLER, J O
Region 3, Office of Director 1p 16408 178 24X
Fiche 50-331, 82/12/03, 8212140142

--8212140147 LER 82-074/03L-0 on 821108, during shutdown surveillance testing, drywell pressure switch PS-4310C tripped at 2.2 psig instead of Tech Spec setpoint of 1.5 plus/minus 0.3 psig increasing Caused by setpoint drift Switch recalibr
HILL, K L Iowa Electric Light & Power Co 82/12/03 Region 3, Office of Director 1p 16408 179 24X Fiche 50-331, 82/12/03, 8212140142

8212140332 Forwards LER 82-075/03L-0
MINECK, D L Iowa Electric Light & Power Co 82/12/03 KEPPLER, J O
Region 3, Office of Director 1p 16401 361 24X
Fiche 50-331, 82/12/03, 8212140332

--8212140338 LER 82-075/03L-0 on 821106, during shutdown, drywell purge, PDIS-4305 opened drywell to suppression chamber vacuum breaker CV-4305 conservatively & would not reset to close
Caused by instrument drift Switch recalibr
HILL, K L Iowa Electric Light & Power Co 82/12/03 Region 3, Office of Director 1p 16401 362 24X Fiche 50-331, 82/12/03, 8212140332

8212210033 Forwards LER 82-081/03L-0
MINECK, D L Iowa Electric Light & Power Co 82/12/10 KEPPLER, J O
Region 3, Office of Director 1p 16485 356 24X
Fiche 50-331, 82/12/10, 8212210033

--8212210034 LER 82-081/03L-0 on 821123, standby filter unit heater B tripped on overtemp Caused by inoperable controller EC-7304B due to failure of operable amplifier in controller circuitry Operable amplifier replaced
HILL, K L Iowa Electric Light & Power Co 82/12/10 Region 3, Office of Director 1p 16485 357 24X Fiche 50-331, 82/12/10, 8212210033

8212210070 Forwards LER 82-079/03L-0
MINECK, D L Iowa Electric Light & Power Co 82/12/10 KEPPLER, J O
Region 3, Office of Director 1p 16492 276 24X
Fiche 50-331, 82/12/10, 8212210070

--8212210074 LER 82-079/03L-0 on 821117, B core spray sys header to top of core plate high differential pressure switch tripped at 2.1 psid Caused by instrument drift Switch recalibr & tested satisfactorily
HILL, K L Iowa Electric Light & Power Co 82/12/10 Region 3, Office of Director 1p 16492 277 24X Fiche 50-331, 82/12/10, 8212210070

8212210352 Forwards LER 82-077/03L-0
MINECK, D L Iowa Electric Light & Power Co 82/12/10 KEPPLER, J O
Region 3, Office of Director 1p 16495 169 24X
Fiche 50-331, 82/12/10, 8212210352

- 8212210358 LER 82-077/03L-0 on 821116, during surveillance testing, RHH svc water pump IP-22D failed to meet Tech Spec requirements
Caused by loose impeller on shaft Cause under investigation
Pump rebuilt
HILL, K L Iowa Electric Light & Power Co 82/12/10 Region 3, Office of Director 1p 16495 170 24X Fiche 50-331, 82/12/10, 8212210352

8212280454 Forwards LER 82-080/03L-0
MINECK, D L Iowa Electric Light & Power Co 82/12/17 KEPPLER, J O
Region 3, Office of Director 1p 16556 031 24X
Fiche 50-331, 82/12/17, 8212280454

--8212280457 LER 82-080/03L-0 on 821122, wash pump IP-112B had discharge head of approx 33 psig instead of required 60 psig Caused by slippage of coupling between motor & pump on motor shaft
Pump & motor aligned & set screws tightened
HILL, K L Iowa Electric Light & Power Co 82/12/17 Region 3, Office of Director 1p 16556 032 24X Fiche 50-331, 82/12/17, 8212280454

8212300327 EN-82-029A on 821227, notice of proposed imposition of civil penalty in amount of \$40,000 issued Action based on violation of Tech Spec in which one emergency diesel generator could not be started within design requirements
BARBER, G , AXELRAD, J Director's Office, Office of Inspection and Enforcement 82/12/27 1p 16594 267 24X Fiche 50-331, 82/12/27, 8212300327

V Operator Examinations

8212020007 Forwards SER & technical evaluation rept re TMI Items I A 2.1, "Upgrading of Reactor Operator & Senior Reactor Operator Training" & II B 4, "Training for Mitigating Core Damage " Items considered resolved
VASSALLO, D B Operating Reactors Branch 2 82/11/23 ARNOLD, D
Iowa Electric Light & Power Co 8pp 16308 303 24X
Fiche 50-331, 82/11/23, 8212020007

- 8208310315 "Improvements in Training & Requalification Programs As Required By TMI Action Items I A 2.1 & II B 4 for Duane Arnold Energy Ctr," technical evaluation rept
Science Applications, Inc NRC-03-82-096 SAI-186-029-35
82/08/26 NRC - No Detailed Affiliation Given 15pp
16308 312 24X Fiche 50-331, 82/11/23, 8212080007

DOCKETED ITEMS

DOCKET 50-332 BARNWELL REPROCESSING PLANT

Q Inspection reports, IE Bulletins & correspondence

GP12090447 Forwards IE Insp Rept 50-332/82-03 on 821026-29 No noncompliance noted
 GIBSON, A F Division of Engineering & Technical Programs 82/11/05
 BUCKHAM, J A Allied General Nuclear Services 2pp 16363 260
 24X Fiche 50-332, 82/11/05, 8212090447

--8212090451 IE Insp Rept 50-332/82-03 on 821026-29 No noncompliance noted Major areas inspected procedural control, internal review, audit safety committees, facility status & independent effort
 CORVELL, G P, MCALPINE, E J Division of Engineering & Technical Programs 82/11/04 4pp 16363 262 24X Fiche 50-332, 82/11/05, 8212090447

GP12090405 Ack receipt of IE Insp Rept 50-332/82-03 No proprietary info
 BUCKHAM, J A Allied General Nuclear Services 82/11/17
 GIBSON, A F Division of Engineering & Technical Programs 1p
 16364 251 24X Fiche 50-332, 82/11/17, 8212090405

DOCKET 50-333 JAMES A FITZPATRICK NUCLEAR POWER PLANT

F Security, medical, emergency & fire protection plans

GP12140225 Ack receipt of 821102 ltr requesting extension of completion date for radiation protection procedures per IE Health Physics Appraisal Rept 50-333/80-20 Revised date of 821231 acceptable for rept Items E 1, E 2, D 2, D 3 & D 8
 MARTIN, T T Division of Engineering & Technical Programs 82/12/09
 MCNEILL, C A Power Authority of the State of New York 2pp
 16408 355 24X Fiche 50-333, 82/12/09, 8212140225

--8212140236 Suppls 820430 response to NRC 820120 ltr re violations noted in IE Health Physics Appraisal Rept 50-333/80-20 Requests completion date for radiation protection procedures be extended to 821231
 MCNEILL, C A Power Authority of the State of New York 82/11/02
 MARTIN, T T Division of Engineering & Technical Programs 2pp
 16408 357 24X Fiche 50-333, 82/12/09, 8212140225

GP12140294 Submits requested info from 821202 telcon re emergency operations facilities (EOF) Util in process of converting bldg to serve as alternate EOF
 BAYNE, J P Power Authority of the State of New York 82/12/09
 VASSALL, D B Operating Reactors Branch 2 3pp 16402 082 24X Fiche 50-333, 82/12/09, 8212140294

GP12150121 Ack receipt of 821129 ltr informing NRC of steps taken to correct violations noted in IE Health Physics Appraisal Rept 50-333/80-20
 MARTIN, T T Division of Engineering & Technical Programs 82/12/10
 MCNEILL, C A Power Authority of the State of New York 1p
 16430 195 24X Fiche 50-333, 82/12/10, 8212150121

--8212150126 Responds to NRC 821101 ltr re violations noted in IE Health Physics Appraisal Rept 50-333/80-20 Corrective actions offgas sys undergoing testing & repair Next status rept will be filed by 830201
 MCNEILL, C A Power Authority of the State of New York 82/11/29
 MARTIN, T T Division of Engineering & Technical Programs 2pp
 16430 196 24X Fiche 50-333, 82/12/10, 8212150121

GP12210177 Provides addl info to assist shift crews making telephone repts via NRC emergency notification sys Sample event notification form used by NRC duty officer encl
 STAROSTECKI, R Division of Project & Resident Programs 82/12/16
 MCNEILL, C A Power Authority of the State of New York 6pp
 16484 243 24X Fiche 50-333, 82/12/16, 8212210177

GP12220452 Submits clarification of dc power & control circuit definitions telecopied to NRC on 821207, per App R fire protection performance requirements
 BAYNE, J P Power Authority of the State of New York 82/12/17
 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp
 16504 261 24X Fiche 50-333, 82/12/17, 8212220452

P Operating license stage documents & correspondence

GP1230066 Generic Ltr 82-27 to all BWR licensees of operating reactors except LACBWR, Big Rock Point, Dresden 1, Humboldt Bay, applicants for OL & holders of CP re transmittal of NUREG-0763 & NUREG-0783 Svc list encl W/o stated encl
 EISENHUT, D G Division of Licensing 82/11/15, General Public Utilities - OPU Service Corp 22pp, 16397 004 24X Fiche 50-000, 82/11/15, 821230066

GP12130277 Forwards safety evaluation of BWR owners group 810522, 0921 & 820902 responses to NUREG-0737, Item 11 K 3 25, "Effect of Loss of AC Power on Pump Seals" Responses acceptable
 VASSALL, D B Operating Reactors Branch 2 82/12/01 SINCLAIR, L H Power Authority of the State of New York 7pp 16418 227 24X Fiche 50-333, 82/12/01, 8212130277

GP12290175 Forwards revised schedule for post-TMI requirements (Generic Ltr 82-03), NUREG-0737, Items 11 B 3 2 re post-accident sampling mod, 11 F 1 6 re containment hydrogen concentration monitor & 11 A 2 2 re meteorological data
 BAYNE, J P Power Authority of the State of New York 82/12/23
 VASSALL, D B Operating Reactors Branch 2 3pp 16578 045 24X Fiche 50-333, 82/12/23, 8212290175

Q Inspection reports, IE Bulletins & correspondence

B208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel Recirculation Sys Piping at BWR Plants" Svc list encl
 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240

B208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model B01 & Model B02 Thermoluminescent Dosimeters" Svc list encl
 COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000, 82/11/05, 8208190245

B208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements" Svc list encl
 JORDAN, E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X Fiche 50-000, 82/11/18, 8208190251

B212030065 Forwards IE Insp Rept 50-333/82-22 on 821001-31 notice of violation
 STAROSTECKI, R Division of Project & Resident Programs 82/11/18
 MCNEILL, C A Power Authority of the State of New York 2pp
 16304 192 24X Fiche 50-333, 82/11/18, 8212030065

--8212030070 Notice of violation from Insp on 821001-31
 " Division of Project & Resident Programs 82/11/18 1p
 16304 194 24X Fiche 50-333, 82/11/18, 8212030065

--8212030078 IE Insp Rept 50-333/82-22 on 821001-31 Noncompliance noted failure to simulate low condensate storage tank level at level switches 13-LS-76A & 13-LS-77B during performance of F-ST-24D
 LINVILLE, J C, DOERFLEIN, L T, BAUNACK, W H Division of Project & Resident Programs 82/11/18 19pp 16304 193 24X Fiche 50-333, 82/11/18, 8212030065

B212080374 Responds to IE Bulletin 81-02, Suppl 1, "Failure of Gate Type Valves to Close Against Differential Pressure" Valves listed are not installed at facility
 MCNEILL, C A Power Authority of the State of New York 82/11/18
 HAYNES, R C Region 1, Office of Director 1p 16353 313 24X Fiche 50-333, 82/11/18, 8212080374

B208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks" Svc list encl
 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000, 82/11/26, 8208190256

GP08190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl" Svc list encl
 COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000, 82/11/30, 8208190257

GP08190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies" Svc list encl
 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259

GP08190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets" Svc list encl
 JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X Fiche 50-000, 82/12/03, 8208190261

B212140225 Ack receipt of B21102 ltr requesting extension of completion date for radiation protection procedures per IE Health Physics Appraisal Rept 50-333/80-20 Revised date of B21231 acceptable for rept Items E 1, E 2, D 2, D 5 & D 8
MARTIN, T T Division of Engineering & Technical Programs 82/12/09
MCNEILL, C A Power Authority of the State of New York 2pp
16408 355 24X Fiche 50-333, 82/12/09, 8212140225

--B212140236 Suppls B20430 response to NRC B20120 ltr re violations noted in IE Health Physics Appraisal Rept 50-333/80-20 Requests completion date for radiation protection procedures be extended to B21231
MCNEILL, C A Power Authority of the State of New York 82/11/02
MARTIN, T T Division of Engineering & Technical Programs 2pp
16408 357 24X Fiche 50-333, 82/12/09, 8212140225

B212150121 Ack receipt of B21129 ltr informing NRC of steps taken to correct violations noted in IE Health Physics Appraisal Rept 50-333/80-20
MARTIN, T T Division of Engineering & Technical Programs 82/12/10
MCNEILL, C A Power Authority of the State of New York 1p
16430 195 24X Fiche 50-333, 82/12/10, 8212150121

- B212150126 Responds to NRC B21101 ltr re violations noted in IE Health Physics Appraisal Rept 50-333/80-20 Corrective actions offgas sys undergoing testing & repair Next status rept will be filed by B30201
MCNEILL, C A Power Authority of the State of New York 82/11/29
MARTIN, T T Division of Engineering & Technical Programs 2pp
16430 196 24X Fiche 50-333, 82/12/10, 8212150121

B208190267 IE Info Notice B2-49, "Correction for Sample Conditions for Air & Gas Monitoring" Svc list encl
DEVOUNO, R C Director's Office, Office of Inspection and Enforcement 82/12/16
Consolidated Edison Co. of New York, Inc
127pp 16628 191 24X Fiche 50-000, 82/12/16, 8208190267

B212220417 Forwards list of topic areas for discussion at upcoming Region 1/licensee meeting on drug & alcohol abuse programs, as discussed in IE Info Notice B2-05 & NUREG-0903 Meeting date & time to be arranged
STAROSTECKI, R Division of Project & Resident Programs 82/12/16
MCNEILL, C A Power Authority of the State of New York 4pp
16503 264 24X Fiche 50-333, 82/12/16, 8212220417

B208190268 IE Info Notice B2-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27" Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20
Consolidated Edison Co. of New York, Inc 108pp 16628 293 24X
Fiche 50-000, 82/12/20, 8208190268

4 Periodic operating reports & related correspondence

B212130091 Forwards monthly operating rept for Nov 1982
MCNEILL, C A Power Authority of the State of New York 82/12/07
Director's Office, Office of Inspection and Enforcement 2pp
16390 188 24X Fiche 50-333, 82/12/07, 8212130091

--B212130084 Monthly operating rept for Nov 1982
COOK, J Power Authority of the State of New York 82/12/07 8pp
16390 189 24X Fiche 50-333, 82/12/07, 8212130081

5 Reportable occurrences, LERs & related correspondence

B212060292 Forwards LER B2-049/03L-0
MCNEILL, C A Power Authority of the State of New York 82/11/23
HAYNES, R C Region 1, Office of Director 1p 16312 063 24X
Fiche 50-333, 82/11/23, 8212060292

--B212060296 LER B2-049/03L-0 on B21027, during Tech Spec surveillance requirement review, scram discharge vol vents & drains not cycled on quarterly basis Caused by supervisory personnel error Addl surveillance procedure developed
LISEND, R Power Authority of the State of New York 82/10/23
Region 1, Office of Director 2pp 16312 064 24X
Fiche 50-333, 82/11/23, 8212060292

B212060091 Forwards LER B2-051/03L-0
MCNEILL, C A Power Authority of the State of New York 82/11/24
HAYNES, R C Region 1, Office of Director 1p 16316 075 24X
Fiche 50-333, 82/11/24, 8212060091

--B212060101 LER B2-051/03L-0 on B21109, setpoint on reactor low water level scram switch 02-3-L16-101D less conservative than required Caused by instrument drift Set readjusted & test frequency for trend observation increased
* Power Authority of the State of New York 82/11/24 Region
1, Office of Director 1p 16316 076 24X Fiche 50-333, 82/11/24, 8212060091

B212060223 Forwards LER B2-052/03L-0
MCNEILL, C A Power Authority of the State of New York 82/11/24
HAYNES, R C Region 1, Office of Director 1p 16312 239 24X
Fiche 50-333, 82/11/24, 8212060223

--B212060231 LER B2-052/03L-0 on B21110, HPCI turbine high exhaust diaphragm pressure switch 23-PS-86B setpoint found to be less conservative than required setting Caused by instrument drift Switch setpoint adjusted within Tech Spec limit
* Power Authority of the State of New York 82/11/24 Region
1, Office of Director 1p 16312 240 24X Fiche 50-333, 82/11/24, 8212060223

B212080394 Forwards LER B2-050/03L-0
MCNEILL, C A Power Authority of the State of New York 82/12/01
HAYNES, R C Region 1, Office of Director 1p 16352 277 24X
Fiche 50-333, 82/12/01, 8212080394

--B212080406 LER B2-050/03L-0 on B21109, scram discharge vol red block level surveillance test not performed within 7 days of reactor startup per Tech Spec Caused by failure to enter frequency statement in procedure during review of Amend 62
* Power Authority of the State of New York 82/12/01 Region
1, Office of Director 2pp 16352 278 24X Fiche 50-333, 82/12/01, 8212080394

B212210268 Forwards updated LER B2-051/03L-1
MCNEILL, C A Power Authority of the State of New York 82/12/09
HAYNES, R C Region 1, Office of Director 1p 16483 251 24X
Fiche 50-333, 82/12/09, 8212210268

- B212210274 Updated LER B2-051/03L-1 on B21109, while conducting surveillance testing on reactor low water scram switch 02-3-L15-101D, setpoint found less conservative than required Caused by instrument drift Setpoint adjusted
KEITH, H Power Authority of the State of New York 82/12/07
Region 1, Office of Director 2pp 16483 252 24X
Fiche 50-333, 82/12/09, 8212210268

B212210415 Forwards updated LER B2-030/03L-1
MCNEILL, C A Power Authority of the State of New York 82/12/13
HAYNES, R C Region 1, Office of Director 1p 16493 103 24X
Fiche 50-333, 82/12/13, 8212210415

--B212210425 Updated LER B2-030/03L-1 on B20709, rod block monitor B found out of calibr Caused by instrument drift Monitor recalibr & returned to svc Surveillance calibr test frequency increased to once per month
KEITH, H Power Authority of the State of New York 82/12/13
Region 1, Office of Director 2pp 16493 104 24X
Fiche 50-333, 82/12/13, 8212210415

DOCKET 50-334 BEAVER VALLEY POWER STATION, UNIT 1

F Security, medical, emergency & fire protection plans

B212100038 Ack receipt of B21115 ltr informing NRC of steps taken to correct violations noted in IE Emergency Preparedness Rept 50-334/82-15
MARTIN, T T Division of Engineering & Technical Programs 82/12/06
CAREY, J J Duquesne Light Co 2pp 16379 046 24X
Fiche 50-334, 82/12/06, 8212100038

--B212100041 Responds to NRC B20727 ltr re violations noted in IE Emergency Preparedness Rept 50-334/82-15 Corrective actions line level of radio base stations turned up, enclaring sys activation & control sys tested monthly
CAREY, J J Duquesne Light Co 82/11/15 HAYNES, R C Region 1, Office of Director 2pp 16379 048 24X Fiche 50-334, 82/12/06, 8212100038

B212170200 Summarizes B21130 meeting w/NRC & documents understanding mutually agreed upon re App R fire protection rule Finalized responses to B21118 questions encl
CAREY, J J Duquesne Light Co 82/12/10 VARQA, S A Operating Reactors Branch 1 112pp 16450 012 24X Fiche 50-334, 82/12/10, 8212170200

B212170032 Responds to B20920 ltr re changes to guard training & qualification plan Proposed changes acceptable Final determination cannot be made until listed changes implemented into plan
VARQA, S A Operating Reactors Branch 1 82/12/13 CAREY, J J Duquesne Light Co 1p 16480 361 24X Fiche 50-334, 82/12/13, 8212170032

DOCKETED ITEMS

B212210334 Provides addl info to better prepare shift crews operating nuclear power plants for questions NRC duty officer may ask during telephone notifications Revised event notification form encl
STAROSTECKI, R Division of Project & Resident Programs 82/12/14
CAREY, J J Duquesne Light Co 6pp 16496 322 24X
Fiche 50-334, 82/12/16, 8212210334

B212300107 Forwards addl info to clarify & substantiate B20630 request for exemption from App R to JOCFR50 re control room & primary auxiliary bldg
CAREY, J J Duquesne Light Co 82/12/21 VARQA, S A Operating
Reactors Branch 1 15pp 16598 234 24X Fiche 50-334, 82/12/21, 8212300107

P Operating license stage documents & correspondence

B212030142 Responds to B20827 Question 7 re two loop operation Revised table of sequence of events for major rupture of main steam pipe encl
CAREY, J J Duquesne Light Co 82/11/22 VARQA, S A Operating
Reactors Branch 1 3pp 16303 022 24X Fiche 50-334, 82/11/22, 8212030142

B212020078 Forwards application for amend to License DPR-66, permitting operation if second licensed reactor operator on shift unavailable due to conflicts between requirements for min shift crew composition & NRC policy statement on overtime
CAREY, J J Duquesne Light Co 82/11/23 VARQA, S A Operating
Reactors Branch 1 2pp 16272 014 24X Fiche 50-334, 82/11/23, 8212020078

--B212020084 Application for amend to License DPR-66, permitting operation if second licensed reactor operator on shift unavailable due to conflicts between requirements for min shift crew composition & NRC policy statement on overtime
CAREY, J J Duquesne Light Co 82/11/23 1p 16272 016 24X
Fiche 50-334, 82/11/23, 8212020078

- B212020089 Proposed Tech Spec Page 6-4 re min shift crew composition
* Duquesne Light Co 82/11/23 4pp 16272 017 24X
Fiche 50-334, 82/11/23, 8212020078

B212080474 Forwards application for amend to License DPR-66, revising Tables 3 7-4a & 3 7-4b re safety-related hydraulic & mechanical snubbers
CAREY, J J Duquesne Light Co 82/11/23 VARQA, S A Operating
Reactors Branch 1, 1p 16352 152 24X Fiche 50-334, 82/11/23, 8212080474

--B212080480 Application to amend License DPR-66, revising Tables 3 7-4a & 3 7-4b re safety-related hydraulic & mechanical snubbers
CAREY, J J Duquesne Light Co 82/11/23 2pp 16352 153 24X
Fiche 50-334, 82/11/23, 8212080474

--B212080484 Proposed Tech Spec change revising Table 3 7-4a & 3 7-4b re safety-related hydraulic & mechanical snubbers
* Duquesne Light Co 82/11/23 8pp 16352 155 24X
Fiche 50-334, 82/11/23, 8212080474

B212030148 Forwards completed questionnaire re steam generator tube integrity, in response to Generic Ltr 82-22, "Request for Info re Steam Generator Tube Integrity"
CAREY, J J Duquesne Light Co 82/11/24 EISENHUT, D O Division of Licensing 5pp 16303 003 24X Fiche 50-334, 82/11/24, 8212030148

B212090520 Forwards revision to "Beaver Valley Unit 1 Offsite Dose Calculation Manual," supporting B21022 Revision 3 to proposed Tech Spec Change 3b Revisions to Section 2 2 2, deleting refs to food & ground pathways, forthcoming
CAREY, J J Duquesne Light Co 82/12/01 VARQA, S A Operating
Reactors Branch 1 1p 16366 132 24X Fiche 50-334, 82/12/01, 8212090520

--B212090526 Revision to "Beaver Valley Unit 1 Offsite Dose Calculation Manual"
* Duquesne Light Co 82/11/19 159pp 16366 133 24X
Fiche 50-334, 82/12/01, 8212090520

B212130243 Forwards application to amend License DPR-66, consisting of Proposed Change Request 83 revising Section 6 Tech Specs re onsite safety committee & offsite review committee membership & responsibilities, per Generic Ltrs 82-17 & 23.
CAREY, J J Duquesne Light Co 82/12/06 VARQA, S A Operating
Reactors Branch 1 1p 16396 254 24X Fiche 50-334, 82/12/06, 8212130243

--B212130248 Application to amend License DPR-66, consisting of Proposed Change Request 83 revising Section 6 Tech Specs re onsite safety committee & offsite review committee membership & responsibilities
CAREY, J J Duquesne Light Co 82/12/06 1p 16396 255 24X
Fiche 50-334, 82/12/06, 8212130243

--B212130264 Proposed changes to Section 6 Tech Specs re onsite safety committee & offsite review committee membership & responsibilities
* Duquesne Light Co 82/12/06 8pp 16396 256 24X
Fiche 50-334, 82/12/06, 8212130243

B212220373 Forwards fee for B21123 Tech Spec Change Request 82
SIEBER, J D Duquesne Light Co 82/12/06 License Fee Management
Branch 1p 16317 150 24X Fiche 50-334, 82/12/06, 8212220373

B212220425 Forwards Class III license fee for B21123 Tech Spec Change Request 78
SIEBER, J D Duquesne Light Co 82/12/06 License Fee Management
Branch 1p 16303 286 24X Fiche 50-334, 82/12/06, 8212220425

B212130242 Forwards Procedure G, "Response to Void in Reactor Vessel," per NUREG-0737, Item II B 1
CAREY, J J Duquesne Light Co 82/12/07 VARQA, S A Operating
Reactors Branch 1 2pp 16396 220 24X Fiche 50-334, 82/12/07, 8212130242

--B212130245 Procedure G, "Response to Void in Reactor Vessel"
* Duquesne Light Co 82/12/07 8pp 16396 222 24X
Fiche 50-334, 82/12/07, 8212130242

B212160339 Forwards "Analog Rod Position Indication Sys Special Rept," based on matl presented at B21014 meeting by util A, Westinghouse Analog or digital indicators in Modes 3, 4 & 5 should have no accuracy requirements
CAREY, J J Duquesne Light Co 82/12/08 VARQA, S A Operating
Reactors Branch 1 2pp 16442 294 24X Fiche 50-334, 82/12/08, 8212160339

--B212160346 "Analog Rod Position Indication Sys Special Rept"
* Westinghouse Electric Corp 82/12/08 23pp 16442 296 24X
Fiche 50-334, 82/12/08, 8212160339

B212220409 Forwards Class II license fee for B21206 Tech Spec Change Request 83
SIEBER, J D Duquesne Light Co 82/12/08 License Fee Management
Branch 1p 16304 281 24X Fiche 50-334, 82/12/08, 8212220409

B21208190263 Generic Ltr 82-32 to all PWR licensees re potential steam generator-related generic requirements Forwards Science Applications, Inc draft rept re subv requirements Comments requested within 30 days of ltr Svc list encl
EISENHUT, D O Division of Licensing 82/12/09 Consolidated
Edison Co of New York, Inc 29pp 16629 247 24X
Fiche 50-000, 82/12/09, 8208190263

B212270155 Forwards amended application for amend to License DPR-66, revising Tech Spec 6 2-1, "Min Shift Crew Composition"
CAREY, J J Duquesne Light Co 82/12/15 VARQA, S A Operating
Reactors Branch 1 1p 16538 054 24X Fiche 50-334, 82/12/15, 8212270155

--B212270161 Amended application to amend License DPR-66, revising Tech Spec 6 2-1, "Min Shift Crew Composition"
CAREY, J J Duquesne Light Co 82/12/16 2pp 16538 055 24X
Fiche 50-334, 82/12/15, 8212270155

--B212270163 Proposed Tech Spec 6 2-1, "Min Shift Crew Composition"
* Duquesne Light Co 82/12/15 3pp 16538 057 24X
Fiche 50-334, 82/12/15, 8212270155

B212270201 Forwards application for amend to License DPR-66, reducing to 50% number of income moveable detector thimbles required for sys to be operable
CAREY, J J Duquesne Light Co 82/12/16 VARQA, S A Operating
Reactors Branch 1 1p 16535 122 24X Fiche 50-334, 82/12/16, 8212270201

--B212270207 Application for amend to License DPR-66, reducing to 50% number of income moveable detector thimbles required for sys to be operable
CAREY, J J Duquesne Light Co 82/12/16 2pp 16535 123 24X
Fiche 50-334, 82/12/16, 8212270201

--B212270209 Proposed Tech Specs re number of income moveable detector thimbles required for sys to be operable
* Duquesne Light Co 82/12/16 10pp 16535 125 24X
Fiche 50-334, 82/12/16, 8212270201

Q Inspection reports, IE Bulletins & correspondence

B208190240 IE Bulletin B2-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel Recirculation Sys Piping at BWR Plants " Svc list encl
 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, B208190240

B208190245 IE Info Notice B2-42, "Defects Observed in Panasonic Model 601 & Model 802 Thermoluminescent Dosimeters " Svc list encl
 COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000, 82/11/05, B208190245

B208190251 IE Info Notice B2-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl
 JORDAN, E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X Fiche 50-000, 82/11/18, B208190251

B208190256 IE Info Notice B2-46, "Defective & Obsolete Combination Padlocks " Svc list encl
 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000, 82/11/26, B208190256

B208190257 IE Info Notice B2-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl
 COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000, 82/11/30, B208190257

B212140150 Forwards IE Insp Rept 50-334/B2-25 on B20928-1025 & notice of violation
 STAROSTECKI, R Division of Project & Resident Programs 82/11/30 CAREY, J J Duquesne Light Co 2pp 16410 178 24X Fiche 50-334, 82/11/30, B212140150

- B212140154 Notice of violation from insp on B20928-1025
 * Division of Project & Resident Programs 82/11/30 2pp 16410 180 24X Fiche 50-334, 82/11/30, B212140150

--B212140160 IE Insp Rept 50-334/B2-25 on B20928-1025 Noncompliance noted failure to follow nuclear safety procedures & review & approve control room tank curve procedures & failure to implement radiation work permit
 TROSKOSKI, W M, LAZARUS, W, TRIPP, L E Division of Project & Resident Programs 82/11/26 15pp 16410 182 24X Fiche 50-334, 82/11/30, B212140150

B208190259 IE Bulletin B2-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl
 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, B208190259

B208190261 IE Info Notice B2-48, "Failures of Agestat CR 0095 Relay Sockets " Svc list encl
 JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X Fiche 50-000, 82/12/03, B208190261

B212100038 Ack receipt of B21115 ltr informing NRC of steps taken to correct violations noted in IE Emergency Preparedness Rept 50-334/B2-15
 MARTIN, T I Division of Engineering & Technical Programs 82/12/06 CAREY, J J Duquesne Light Co 2pp 16379 046 24X Fiche 50-334, 82/12/06, B212100038

- B212100041 Responds to NRC B20727 ltr re violations noted in IE Emergency Preparedness Rept 50-334/B2-15 Corrective actions line level of radio base stations turned up, ensuring sys activation & control sys tested monthly
 CAREY, J J Duquesne Light Co 82/11/15 HAYNES, R C Region 1, Office of Director 2pp 16379 048 24X Fiche 50-334, 82/12/06, B212100038

B208190267 IE Info Notice B2-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16, B208190267

B21220490 Advises of upcoming meeting to discuss IE Info Notice B2-05, "Increasing Frequency of Drug-Related Incidents " Info notice, list of topics to be covered at meeting & NUREG-0903 encl W/o NUREG
 STAROSTECKI, R Division of Project & Resident Programs 82/12/16 CAREY, J J Duquesne Light Co 3pp 16503 252 24X Fiche 50-334, 82/12/16, B21220490

B208190268 IE Info Notice B2-50, "Mod or Solid State AC Undervoltage Relays Type ITE-27 " Svc list encl
 JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X Fiche 50-000, 82/12/20, B208190268

B212290280 Ack receipt of B21123 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-334/B2-22 STAROSTECKI, R Division of Project & Resident Programs 82/12/22 CAREY, J J Duquesne Light Co 2pp 16581 067 24X Fiche 50-334, 82/12/22, B212290280

--B212290289 Responds to NRC B21022 ltr re violations noted in IE Insp Rept 50-334/B2-22 Corrective actions revision will be made to startup checklist Drawings & status boards corrected to reflect current plant conditions
 CAREY, J J Duquesne Light Co 82/11/23 STAROSTECKI, R Division of Project & Resident Programs 3pp 16581 069 24X Fiche 50-334, 82/12/22, B212290280

R Periodic operating reports & related correspondence

B212290225 Forwards monthly operating rept for Oct 1982
 CAREY, J J Duquesne Light Co 82/11/08 Management Information Branch 1p 16578 063 24X Fiche 50-334, 82/11/08, B212290225

--B212290230 Monthly operating rept for Oct 1982
 WEAVER, L W Duquesne Light Co 82/11/05 6pp 16578 064 24X Fiche 50-334, 82/11/08, B212290225

B212070204 Forwards B21129 ltr to PA Bureau of Water Quality Mgt advising that NPDES monthly rept for facility unavailable at present time
 FEITKNECHT, C Duquesne Light Co 82/11/27 REID, R W Operating Reactors Branch 4 2pp 16335 116 24X Fiche 50-334, 82/11/27, B212070204

S Reportable occurrences, LERs & related correspondence

B212080419 Forwards updated LER B1-078/03X-1
 LACEY, W S Duquesne Light Co 82/11/26 HAYNES, R C Region 1, Office of Director 2pp 16352 108 24X Fiche 50-334, 82/11/26, B212080419

--B212080440 Updated LER B1-078/03X-1 on B10823, discovered leakage through containment airlock inner door seals inner door sealing surfaces & G-rings wiped down & regreased Design change procedure approved on B20605
 * Duquesne Light Co 82/11/18 Region 1, Office of Director 2pp 16352 110 24X Fiche 50-334, 82/11/26, B212080419

B212080451 Forwards updated LER B1-077/03X-1
 LACEY, W S Duquesne Light Co 82/11/26 HAYNES, R C Region 1, Office of Director 2pp 16352 164 24X Fiche 50-334, 82/11/26, B212080451

--B212080497 Updated LER B1-077/03X-1 on B10817, increased radiation levels in auxiliary bldg discovered caused by crack in welded pipe connection joining two IA degassifier recovery HX Crack due to thermal stress fatigue
 * Duquesne Light Co 82/11/26 Region 1, Office of Director 2pp 16352 166 24X Fiche 50-334, 82/11/26, B212080451

B212080526 Forwards LER B2-051/03L-0
 LACEY, W S Duquesne Light Co 82/11/26 HAYNES, R C Region 1, Office of Director 2pp 16352 052 24X Fiche 50-334, 82/11/26, B212080526

--B212080530 LER B2-051/03L-0 on B21104, while performing routine surveillance, area radiation monitor RIS-RM207 failed pff scale low Caused by multiple electrical component failures Faulty parts replaced & monitor returned to svc on B21117
 * Duquesne Light Co 82/11/05 Region 1, Office of Director 2pp 16352 054 24X Fiche 50-334, 82/11/26, B212080526

B212140174 Forwards LER B2-049/03L-0
 LACEY, W S Duquesne Light Co 82/11/26 HAYNES, R C Region 1, Office of Director 2pp 16409 351 24X Fiche 50-334, 82/11/26, B212140174

--B212140191 LER B2-049/03L-0 on B21111, containment vacuum pump 1A observed not rotating Caused by binding between pump rotor & vanes due to corrosion buildup Pump shaft manually rotated & freed Design change being investigated
 * Duquesne Light Co 82/11/19 Region 1, Office of Director 2pp 16409 353 24X Fiche 50-334, 82/11/26, B212140174

DOCKETED ITEMS

8212150020 Forwards LER 82-053/03L-0
LACEY, W S Duquesne Light Co 82/12/02 HAYNES, R C Region 1,
Office of Director 2pp 16421 214 24X Fiche 50-334, 82/12/02,
8212150020

--8212150025 LER 82-053/03L-0 on 820916, chemistry personnel failed to
obtain boron sample of safety injection accumulator 1A
during two sampling periods in 1981 Caused by
misunderstanding among chemists over sampling frequency
LACEY, W S Duquesne Light Co 82/12/03 Region 1, Office of
Director 2pp 16421 216 24X Fiche 50-334, 82/12/02, 8212150020

8212150075 Forwards LER 82-052/03L-0
LACEY, W S Duquesne Light Co 82/12/02 HAYNES, R C Region 1,
Office of Director 2pp 16431 015 24X Fiche 50-334, 82/12/02,
8212150075

--8212150078 LER 82-052/03L-0 on 821105, leaking fire hydrant reported in
southeast yard Cause not stated Leak isolated & temporary
fire hose installed in fuel bldg to insure adequate fire
protection
LACEY, W S Duquesne Light Co 82/12/02 Region 1, Office of
Director 2pp 16431 017 24X Fiche 50-334, 82/12/02, 8212150075

8212290339 Forwards LER 82-054/04L-0
LACEY, W S Duquesne Light Co 82/12/13 HAYNES, R C Region 1,
Office of Director 2pp 16586 227 24X Fiche 50-334, 82/12/13,
8212290339

--8212290340 LER 82-054/04L-0 on 820923, continuous chlorination of
circulating water sys occurred over 7-h period Highest free
chlorine residual measured 0.45 mg/l Caused by personnel
error Sys given to chemistry group & will be automated
* Duquesne Light Co 82/12/06 Region 1, Office of Director
2pp 16586 229 24X Fiche 50-334, 82/12/13, 8212290339

8212290373 Forwards LER 81-105/03L-1
LACEY, W S Duquesne Light Co 82/12/15 HAYNES, R C Region 1,
Office of Director 2pp 16586 266 24X Fiche 50-334, 82/12/15,
8212290373

--8212290382 LER 81-105/03L-1 on 811223, during surveillance test on
HV-RT-10, preheater discharge air temp failed to reach
required temp in specified time Caused by overpowering of
two resistors in temp control unit Resistors replaced
* Duquesne Light Co 82/12/13 Region 1, Office of Director
2pp 16586 268 24X Fiche 50-334, 82/12/15, 8212290373

8212290404 Forwards updated LER 82-012/01X-1
LACEY, W S Duquesne Light Co 82/12/15 HAYNES, R C Region 1,
Office of Director 2pp 16586 155 24X Fiche 50-334, 82/12/15,
8212290404

--8212290411 Updated LER 82-012/01X-1 on 820416, total of seven
overstressed pipe supports found upstream of main steam
line containment isolation valves Caused by failure to
include branch line loading in calculations
* Duquesne Light Co 82/12/15 Region 1, Office of Director
2pp 16586 157 24X Fiche 50-334, 82/12/15, 8212290404

8212290439 Forwards LER 82-056/03L-0
LACEY, W S Duquesne Light Co 82/12/15 HAYNES, R C Region 1,
Office of Director 2pp 16585 228 24X Fiche 50-334, 82/12/15,
8212290439

--8212290448 LER 82-056/03L-0 on 821126, during normal power operation,
hydrogen recombiner 1B failed surveillance test 1 46.4 due
to inability to achieve acceptance criteria temp of 700 F
Caused by design problem w/resistors in temp control unit
* Duquesne Light Co 82/12/06 Region 1, Office of Director
2pp 16585 230 24X Fiche 50-334, 82/12/15, 8212290439

DOCKET 50-335 ST LUCIE PLANT, UNIT 1

F Security, medical, emergency & fire protection plans

8212090017 Notification of 821213 meeting w/util in Bethesda, MD to
discuss fire protection plan & factor mutual test programs
SELLS, D E Operating Reactors Branch 3 82/12/06 CLARK, R A
Operating Reactors Branch 3 2pp 16379 355 24X
Fiche 50-335, 82/12/06, 8212090017

8212170053 Releases public version of revised offnormal & emergency
operating procedures
FELTON, J M Division of Rules and Records 82/12/10 Document
Management Branch 1p 16480 339 24X Fiche 50-335, 82/12/10,
8212170053

--8212170060 Forwards public version of Revision 2 to Offnormal &
Emergency Operating Procedure 1-0510030, "Uncontrolled
Release of Radioactive Liquids" & Revision 1 to 1560030,
"Primary Water Sys - Offnormal Operation"
WETHY, C M Florida Power & Light Co 82/12/01 Director's
Office, Office of Inspection and Enforcement 1p 16480 340 24X
Fiche 50-335, 82/12/10, 8212170053

--8212170065 Public version of Revision 2 to Offnormal & Emergency
Operating Procedure 1-0510030, "Uncontrolled Release of
Radioactive Liquids" & Revision 1 to 1560030, "Primary
Water Sys - Offnormal Operation"
* Florida Power & Light Co 82/11/29 7pp 16480 341 24X
Fiche 50-335, 82/12/10, 8212170053

8212290357 Application to amend App A to License DPR-67 in response to
NRC 821027 ltr re add'l Tech Spec fire protection items No
amend fee required per 810204 ltr
UHR10, R E Florida Power & Light Co 82/12/22 EISENHUT, D G
Division of Licensing 2pp 16586 244 24X Fiche 50-335, 82/12/22,
8212290357

--8212290361 Proposed Tech Spec changes to App A re fire protection
items
UHR10, R E Florida Power & Light Co 82/12/22 10pp 16586 246
24X Fiche 50-335, 82/12/22, 8212290357

J Insurance & indemnity information

8212300294 Forwards Endorsements 1/2 & 3 to NELIA Certificate N-59 &
MAELU Certificate M-59
DUECK, J R Marsh & McLennan, Inc, M & M Nuclear Consultants, Inc Div
82/12/27 SALTZMAN, J Assistant Director for State & Licensee
Relations 19pp 16594 271 24X Fiche 50-335, 82/12/27, 8212300294

P Operating license stage documents & correspondence

8212090030 Forwards Amend 54 to License DPR-67, safety evaluation &
notice of issuance & availability Amend revises Tech Specs
to reflect new UHS flow barrier configuration & deletes max
water temp limitation
WAGNER, D H Operating Reactors Branch 3 82/12/03 UHR10, R E
Florida Power & Light Co 3pp 16385 182 24X
Fiche 50-335, 82/12/03, 8212090030

--8212090033 Amend 54 to License DPR-67, revising Tech Specs to reflect
new UHS flow barrier configuration & deleting max water temp
limitation
CLARK, R Operating Reactors Branch 3 82/12/03 7pp 16385 185
24X Fiche 50-335, 82/12/03, 8212090030

--8212090035 Safety evaluation supporting Amend 54 to License DPR-67
* Office of Nuclear Reactor Regulation, Director 82/12/03 3pp
16385 192 24X Fiche 50-335, 82/12/03, 8212090030

--8212090037 Notice of issuance & availability of Amend 54 to License
DPR-67
CLARK, R Operating Reactors Branch 3 82/12/03 2pp 16385 193
24X Fiche 50-335, 82/12/03, 8212090030

8212150068 Forwards responses to NRC 820713 ltr re NUREG-0737, Item
11 B 3, "Post-Accident Sampling Sys" W/ three oversize
drawings Aperture cards are available in PDR
UHR10, R E Florida Power & Light Co 82/12/06 CLARK, R A
Operating Reactors Branch 3 13pp 16429 089 24X
Fiche 50-335, 82/12/06, 8212150068

8212190263 Generic Ltr 82-32 to all PWR licensees re potential steam
generator-related generic requirements Forwards Science
Applications, Inc draft rept re subj requirements Comments
requested within 30 days of ltr Svc list encl
EISENHUT, D G Division of Licensing 82/12/09 Consolidated
Edison Co of New York, Inc 29pp 16629 247 24X
Fiche 50-000, 82/12/09, 8208190263

8212140103 Generic Ltr 82-28 to all licensees of operating
Westinghouse & C-E PWRs (except Arkansas Nuclear One, Unit 2
& San Onofre 2 & 3) re inadequate core cooling
instrumentation sys. Svc list encl
EISENHUT, D G Division of Licensing 82/12/10 Yankee Atomic
Electric Co 27pp 16690 035 24X Fiche 50-000, 82/12/10,
8212140103

8212170127 Application for amend to App A of License DPR-67 providing
Tech Specs on undervoltage relays for degraded grid
conditions.
UHR10, R E Florida Power & Light Co 82/12/10 EISENHUT, D G
Division of Licensing 2pp 16452 355 24X Fiche 50-335, 82/12/10,
8212170127

- B212170129 Proposed Tech Specs re undervoltage relays for degraded grid conditions
* Florida Power & Light Co 82/12/10 5pp 16452 357 24X
Fiche 50-335, 82/12/10, 8212170127
- B212170274 Forwards responses to B20913 request for addl info re degraded grid voltage protection. Questions 1-4 Proposed Tech Spec change to verify load shedding of emergency busses not warranted since present test adequate
UHRIO, R E Florida Power & Light Co 82/12/10 CLARK, R A
Operating Reactors Branch 3 18pp 16498 052 24X
Fiche 50-335, 82/12/10, 8212170274
- B212220551 Concurs w/util postponed installation of auxiliary feedwater sys logic cabinet until Fall 1984 refueling outage
Application for Tech Spec changes should provide summary of testing & trouble shooting experience from Unit 2
CLARK, R A Operating Reactors Branch 3 82/12/13 UHRIO, R E
Florida Power & Light Co 2pp 16523 347 24X
Fiche 50-335, 82/12/13, 8212220551
- B212290496 Forwards Amend 55 to License DPR-67 & notice of issuance & availability Amend updates Tech Specs re offsite & facility organization & membership of review board
CLARK, R A Operating Reactors Branch 3 82/12/14 UHRIO, R E
Florida Power & Light Co 4pp 16605 166 24X
Fiche 50-335, 82/12/14, 8212290496
- B212290499 Amend 55 to License DPR-67 updating offsite & facility organization figures & membership of nuclear review board in administrative controls section of Tech Specs
CLARK, R A Operating Reactors Branch 3 82/12/14 9pp
16605 170 24X Fiche 50-335, 82/12/14, 8212290496
- B212290501 Notice of issuance & availability of Amend 55 to License DPR-67
CLARK, R A Operating Reactors Branch 3 82/12/14 2pp
16605 179 24X Fiche 50-335, 82/12/14, 8212290496
- B212290357 Application to amend App A to License DPR-67 in response to NRC B21027 ltr re addl Tech Spec fire protection items No amend fee required per 810204 ltr
UHRIO, R E Florida Power & Light Co 82/12/22 EISENHUT, D O
Division of Licensing 2pp 16586 244 24X Fiche 50-335, 82/12/22, 8212290357
- B212290361 Proposed Tech Spec changes to App A re fire protection items
UHRIO, R E Florida Power & Light Co 82/12/22 10pp 16586 246
24X Fiche 50-335, 82/12/22, 8212290357
- B212290359 Responds to Generic Ltr 82-16 re Tech Specs for NUREG-0737 items Existing Tech Specs adequately cover anticipatory reactor trip on turbine trip
UHRIO, R E Florida Power & Light Co 82/12/22 EISENHUT, D O
Division of Licensing 3pp 16586 165 24X Fiche 50-335, 82/12/22, 8212290359
- G Inspection reports, IE Bulletins & correspondence
- B208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc
112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240
- B212090302 Forwards IE Insp Repts 50-335/82-35 & 50-389/82-50 on 821019-22 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 82/11/02 UHRIO, R E
Florida Power & Light Co 2pp 16365 171 24X
Fiche 50-335, 82/11/02, 8212090302
- B212090308 IE Insp Repts 50-335/82-35 & 50-389/82-50 on 821019-22 No noncompliance noted Major areas inspected IE Circular 81-08, previous insp findings & quality records for foundations
LEMAHAI, J J, CONLON, T E Division of Engineering & Technical Programs 82/11/01 4pp 16365 173 24X Fiche 50-335, 82/11/02, 8212090302
- B212090531 Forwards IE Insp Repts 50-335/82-32 & 50-389/82-44 on 820911-1010 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 82/11/02 UHRIO, R E
Florida Power & Light Co 2pp 16367 001 24X
Fiche 50-335, 82/11/02, 8212090531
- B212090537 IE Insp Repts 50-335/82-32 & 50-389/82-44 on 820911-1010 No noncompliance noted Major areas inspected maint & surveillance observation, operational safety verification, bulletins, circulars, intro notices & preoperational testing
ELROD, S A, BIRB, H C, JULIAN, C A Division of Project & Resident Programs 82/11/02 11pp 16367 003 24X Fiche 50-335, 82/11/02, 8212090537
- B208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model B01 & Model B02 Thermoluminescent Dosimeters " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards
* 82/11/05 Consolidated Edison Co of New York, Inc 110pp
16372 142 24X Fiche 50-000, 82/11/05, 8208190245
- B212090553 Ack receipt of B21103 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-335/82-29 & 50-389/82-39
DANCE, H C Division of Project & Resident Programs 82/11/17 UHRIO, R E
Florida Power & Light Co 1p 16367 038 24X
Fiche 50-335, 82/11/17, 8212090553
- B212090559 Responds to NRC 821005 ltr re violations noted in IE Insp Repts 50-335/82-29 & 50-389/82-39 Corrective actions clearance orders corrected & personnel re instructed re need to designate "locked open" or "locked closed" on orders
UHRIO, R E Florida Power & Light Co 82/11/03 O'REILLY, J P
Region 2, Office of Director 2pp 16367 039 24X
Fiche 50-335, 82/11/17, 8212090559
- B212090561 Forwards IE Insp Repts 50-335/82-29 & 50-389/82-29 on 820811-0910 & notice of violation
DANCE, H C Division of Project & Resident Programs 82/10/05 UHRIO, R E
Florida Power & Light Co 2pp 16367 041 24X
Fiche 50-335, 82/11/17, 8212090561
- B212090563 Notice of violation from insp on 820811-0910
* Division of Project & Resident Programs 82/10/05 1p
16367 043 24X Fiche 50-335, 82/11/17, 8212090563
- B212090564 IE Insp Repts 50-335/82-29 & 50-389/82-39 on 820811-0910 Noncompliance noted failure to implement procedure for locking safety-related valves in required position
ELROD, S A, BIRB, H E, JULIAN, C A Division of Project & Resident Programs 82/10/04 13pp 16367 044 24X Fiche 50-335, 82/11/17, 8212090564
- B208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X
Fiche 50-000, 82/11/18, 8208190251
- B208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc
127pp 16411 065 24X Fiche 50-000, 82/11/26, 8208190256
- B212090544 Ack receipt of B20907 & 1015 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 50-335/82-22
O'REILLY, J P Region 2, Office of Director 82/11/29 UHRIO, R E
Florida Power & Light Co 1p 16366 315 24X Fiche 50-335, 82/11/29, 8212090544
- B212090549 Updates 820907 response to NRC 820805 ltr re violations noted in IE Insp Rept 50-335/82-22 Corrective actions more specific signs installed on shield bldg access doors & personnel re instructed
UHRIO, R E Florida Power & Light Co 82/10/15 O'REILLY, J P
Region 2, Office of Director 1p 16366 316 24X
Fiche 50-335, 82/11/29, 8212090549
- B212090554 Responds to NRC 820805 ltr re violations noted in IE Insp Rept 50-335/82-22 Corrective actions door shut, signs installed & personnel instructed
UHRIO, R E Florida Power & Light Co 82/09/07 O'REILLY, J P
Region 2, Office of Director 2pp 16366 317 24X
Fiche 50-335, 82/11/29, 8212090554
- B212090558 Forwards IE Insp Rept 50-335/82-22 on 820527-0610 & notice of violation
O'REILLY, J P Region 2, Office of Director 82/08/05 UHRIO, R E
Florida Power & Light Co 2pp 16366 319 24X
Fiche 50-335, 82/11/29, 8212090558
- B212090560 Notice of violation from insp on 820527-0610
* Region 2, Office of Director 82/08/05 1p 16366 321 24X
Fiche 50-335, 82/11/29, 8212090560

DOCKETED ITEMS

- 8212090552 IE Insp Rept 50-335/82-22 on 820527-0610 Noncompliance noted on 820524, shield bldg integrity not maintained as plant entered Mode 2 from Mode 3 due to tied open door ELROD, S A. 81BB, H E. JULIAN, C A Division of Project & Resident Programs 82/08/02 3pp 16366 322 24X Fiche 50-335, 82/11/29, 8212090544
- 82/08190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000, 82/11/30, 8208190257
- 82/08190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259
- 82/08190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X Fiche 50-000, 82/12/03, 8208190261
- 82/12220505 Requests written statement within 30 days of ltr re use or disposition of Raychem-Flamtrol cables Generic qualification tests for cables no longer acceptable JORDAN, E L Division of Engineering & Quality Assurance 82/12/10 UHRIE, R E Florida Power & Light Co 2pp 16523 100 24X Fiche 50-335, 82/12/10, 8212220505
- 82/08190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16428 191 24X Fiche 50-000, 82/12/16, 8208190267
- K Periodic operating reports & related correspondence
- 82/12290153 Forwards monthly operating repts for Oct 1982 WILLIAMS, J W Florida Power & Light Co 82/11/15 Office of Resource Management Director 1p 16582 226 24X Fiche 50-000, 82/11/15, 8212290153
- 8212290169 Monthly operating repts for Oct 1982 PACE, P Florida Power & Light Co 82/11/15 12pp 16582 327 24X Fiche 50-000, 82/11/15, 8212290153
- S Reportable occurrences, LERs & related correspondence
- 82/11040086 Forwards LER 82-043/03L-0 WILLIAMS, J W Florida Power & Light Co 82/10/25 O'REILLY, J P Region 2, Office of Director 1p 15927 036 24X Fiche 50-335, 82/10/25, 8211040086
- 8211040090 LER 82-043/03L-0 on 820923, at 100% power, T hot input to subcooled margin monitor became erratic, giving false indication & alarms Cause undetermined Malfunction cleared when cover of junction box removed GREEN, P X Florida Power & Light Co 82/10/25 Region 2, Office of Director 1p 15927 037 24X Fiche 50-335, 82/10/25, 8211040090
- 82/12020369 Forwards LER 82-051/03L-0 WILLIAMS, J W Florida Power & Light Co 82/11/23 O'REILLY, J P Region 2, Office of Director 1p 16278 145 24X Fiche 50-335, 82/11/23, 8212020369
- 8212020371 LER 82-051/03L-0 on 821024, while moving control rods during ascent to full power, control element assembly 40 dropped to full insertion Cause undetermined Control element assembly recovered Plant operation resumed LAUR, S Florida Power & Light Co 82/11/23 Region 2, Office of Director 1p 16278 146 24X Fiche 50-335, 82/11/23, 8212020369
- 82/12090403 Forwards LER 82-052/03L-0 WILLIAMS, J W Florida Power & Light Co 82/12/01 O'REILLY, J P Region 2, Office of Director 1p 16364 352 24X Fiche 50-335, 82/12/01, 8212090403
- 8212090410 LER 82-052/03L-0 on 821101, during test to check ability of IC auxiliary feedwater pump to take suction, condensate storage tank MV-09-11 failed to open Caused by torque limiter switch malfunction Switch readjusted BRANNIN, J P Florida Power & Light Co 82/12/01 Region 2, Office of Director 1p 16364 353 24X Fiche 50-335, 82/12/01, 8212090403
- 8212200071 Forwards LER 82-053/03L-0 WILLIAMS, J W Florida Power & Light Co 82/12/08 O'REILLY, J P Region 2, Office of Director 1p 16470 023 24X Fiche 50-335, 82/12/08, 8212200071
- 8212200085 LER 82-053/03L-0 on 821108, while performing post-maint surveillance test of IC steam driven auxiliary feedwater pump, steam supply valve from 1A steam generator failed to open Caused by failure of contact in switch BRANNIN, J P Florida Power & Light Co 82/12/08 Region 2, Office of Director 1p 16470 024 24X Fiche 50-335, 82/12/08, 8212200071
- 8212150156 Forwards LER 82-055/03L-0 WILLIAMS, J W Florida Power & Light Co 82/12/09 O'REILLY, J P Region 2, Office of Director 1p 16430 185 24X Fiche 50-335, 82/12/09, 8212150156
- 8212150158 LER 82-055/03L-0 on 821109, control element assembly motion inhibit circuit for control element assembly out of sequence deviation scanner failed Caused by failure of relay in out of sequence circuitry Relay replaced ROTELLA, T S Florida Power & Light Co 82/12/09 Region 2, Office of Director 1p 16430 186 24X Fiche 50-335, 82/12/09, 8212150156
- 8212210389 Forwards LER 82-056/03L-0 WILLIAMS, J W Florida Power & Light Co 82/12/13 O'REILLY, J P Region 2, Office of Director 1p 16494 300 24X Fiche 50-335, 82/12/13, 8212210389
- 8212210396 LER 82-056/03L-0 on 821111, control element assembly motion inhibit circuit for out-of-sequence deviation scanner failed Caused by loose relay socket in circuitry Relay reseated & circuitry returned to svc ROTELLA, T S Florida Power & Light Co 82/12/13 Region 2, Office of Director 1p 16494 301 24X Fiche 50-335, 82/12/13, 8212210389
- 82/12210175 Forwards LER 82-057/03L-0 WILLIAMS, J W Florida Power & Light Co 82/12/14 O'REILLY, J P Region 2, Office of Director 1p 16484 342 24X Fiche 50-335, 82/12/14, 8212210175
- 8212210186 LER 82-057/03L-0 on 821114, dose equivalent I-131 exceeded Tech Spec 3.4.8 a limit after reactor trip Caused by iodine buildup in primary coolant due to power transient after operation w/nominal fuel leakage ROTELLA, T S Florida Power & Light Co 82/12/14 Region 2, Office of Director 4pp 16484 343 24X Fiche 50-335, 82/12/14, 8212210175
- 82/12220441 Forwards LER 82-058/03L-0 WILLIAMS, J W Florida Power & Light Co 82/12/17 O'REILLY, J P Region 2, Office of Director 1p 16503 331 24X Fiche 50-335, 82/12/17, 8212220441
- 8212220442 LER 82-058/03L-0 on 821117, during full power operation, containment escape lock mechanical interlock failed during Surveillance Test 4 & 1.3 C Caused by misaligned locking mechanism Mechanism realigned ROTELLA, T S Florida Power & Light Co 82/12/17 Region 2, Office of Director 1p 16503 332 24X Fiche 50-335, 82/12/17, 8212220441
- 82/12280359 Forwards LER 82-060/03L-0 WILLIAMS, J W Florida Power & Light Co 82/12/17 O'REILLY, J P Region 2, Office of Director 1p 16599 004 24X Fiche 50-335, 82/12/17, 8212280359
- 8212280366 LER 82-060/03L-0 on 821117, during full power operation, auxiliary feedwater flow recorder IB & sigma indicated flow when actual flow zero Caused by defective force motor internal to transmitter Transmitter replaced ROTELLA, T S Florida Power & Light Co 82/12/17 Region 2, Office of Director 1p 16599 005 24X Fiche 50-335, 82/12/17, 8212280359
- 82/12280418 Forwards LER 82-059/03L-0 WILLIAMS, J W Florida Power & Light Co 82/12/17 O'REILLY, J P Region 2, Office of Director 1p 16560 026 24X Fiche 50-335, 82/12/17, 8212280418
- 8212280425 LER 82-059/03L-0 on 821117, during surveillance testing of diesel generator IB, solenoid operated fill valve for engine mount fuel oil tank failed to open Caused by stuck level float switch Switch moved, cleaned & satisfactorily tested, ROTELLA, T S Florida Power & Light Co 82/12/17 Region 2, Office of Director 1p 16560 027 24X Fiche 50-335, 82/12/17, 8212280418

12300051 Forwards LER 82-054/03L-0
WILLIAMS, J H Florida Power & Light Co 82/12/22 O'REILLY, J P
Region 2, Office of Director 1p 16598 204 24X
Fiche 50-335, 82/12/22, 8212300051

8212300055 LER 82-054/03L-0 on 821123, DDPS declared inoperable during
normal operation, resulting in loss of control element
assembly pulse counting backup position indication & linear
heat rate monitor Loss of DDPS software related
BRANNITH, J P Florida Power & Light Co 82/12/22 Region 2,
Office of Director 1p 16598 205 24X Fiche 50-335, 82/12/22
8212300051

KEY 50-336 MILLSTONE NUCLEAR POWER STATION, UNIT 2

Security, medical, emergency & fire protection plans

12030167 Forwards IE Safeguards Insp Rept 50-336/82-21 on 820928-29
No noncompliance noted
MARTIN, T T Division of Engineering & Technical Programs 82/11/17
COUNCIL, W G Northeast Nuclear Energy Co (subs of Northeast
Utilities) 2pp 16304 001 24X Fiche 50-336, 82/11/17, 8212030167

8212030177 IE Safeguards Insp Rept 50-336/82-21 on 820928-29 No
noncompliance noted Major areas inspected SNM control &
accounting, facility organization & operation, shipping &
receiving, storage & internal control
WOLTER, E, GODY, A T Division of Engineering & Technical
Programs 82/10/22 5pp 16304 003 24X Fiche 50-336, 82/11/17,
8212030167

12070124 Forwards proposal for revision to modified amended security
plan Proposal withheld (ref 10CFR73.21)
COUNCIL, W G, WERNER, R P Northeast Nuclear Energy Co (subs of
Northeast Utilities) COUNCIL, W G Northeast Utilities 82/11/18
CLARK, R A Operating Reactors Branch 3 CRUTCHFIELD, D Operating
Reactors Branch 5 2pp 16329 341 24X Fiche 50-245, 82/11/18,
8212070124

*12090114 Responds to Generic Ltr 82-25 re BNL request for assistance
in field testing new measurement equipment & inventory
techniques developed to aid in strengthening IAEA
safeguards Addl info available should be sent expeditiously
COUNCIL, W G Connecticut Yankee Atomic Power Co COUNCIL, W G
Northeast Nuclear Energy Co (subs of Northeast Utilities)
82/11/30 EISENHUT, D G Division of Licensing 1p 16357 272
24X Fiche 50-000, 82/11/30, 8212090114

Insurance & indemnity information

12280063 Forwards Endorsement B3 to NELIA Policy NF-173 &
Endorsement 75 to MAELU Policy MF-52
SINIS, J M Marsh & McLennan, Inc, M & M Nuclear Consultants, Inc
Div 82/12/21 SALTZMAN, J D Assistant Director for State &
Licensee Relations 3pp 16564 276 24X Fiche 50-245, 82/12/21,
8212280063

Operating license stage documents & correspondence

*12170321 Application to amend Licenses DPR-21 & DPR-65 by
incorporating radiological effluent Tech Specs into
safety Tech Specs
COUNCIL, W G Northeast Nuclear Energy Co (subs of Northeast
Utilities) COUNCIL, W G Northeast Utilities 82/11/22
CLARK, R A Operating Reactors Branch 3 3pp 16453 280 24X
Fiche 50-245, 82/11/22, 8212170321

-8212170322 Proposed radiological effluent Tech Specs for incorporation
into safety Tech Specs
* Northeast Nuclear Energy Co (subs of Northeast Utilities)
82/11/30 114pp 16453 283 24X Fiche 50-245, 82/11/22,
8212170321

-8212170323 Radiological effluent monitoring & offsite dose calculation
manual
* Northeast Utilities 82/11/30 117pp 16454 037 24X
Fiche 50-245, 82/11/22, 8212170321

*12060157 Responds to Generic Ltr 82-22 re steam generators Haddam
Nec steam generator performance excellent Max of 21 tubes
replaced since 1979 Millstone Unit 2 replaced max of 429
Radiation protection program established
COUNCIL, W G Connecticut Yankee Atomic Power Co COUNCIL, W G
Northeast Utilities 82/11/29 EISENHUT, D G Division of
Licensing 3pp 16313 117 24X Fiche 50-000, 82/11/29, 8212060157

8212140144 Forwards addl fee for Class II changes re large & small
break LOCA evaluations, per NRC 821118 request
COUNCIL, W G Northeast Nuclear Energy Co (subs of Northeast
Utilities) COUNCIL, W G Northeast Utilities 82/12/06 DIGGS, H
License Fee Management Branch 2pp 16408 176 24X
Fiche 50-336, 82/12/06, 8212140144

8212150128 Forwards application for amend of Licenses DPR-21 & DPR-65,
reflecting merger of CT Light & Power Co & Hartford
Electric Co Class I & II Fees encl
COUNCIL, W G Northeast Nuclear Energy Co (subs of Northeast
Utilities) COUNCIL, W G Northeast Utilities 82/12/08
CLARK, R A Operating Reactors Branch 3 CRUTCHFIELD, D Operating
Reactors Branch 5 2pp 16425 329 24X Fiche 50-245, 82/12/08,
8212150128

--8212150142 Application for amend of Licenses DPR-21 & DPR-65, reflecting
merger of CT Light & Power Co & Hartford Electric Co
* Northeast Nuclear Energy Co (subs of Northeast Utilities)
82/12/08 7pp 16425 231 24X Fiche 50-245, 82/12/08, 8212150128

8212170199 Application to amend Licenses DPR-21 & DPR-65, reflecting
merger of Hartford Electrical Light Co w/CT Light & Power
Co
COUNCIL, W G Northeast Nuclear Energy Co (subs of Northeast
Utilities) COUNCIL, W G Northeast Utilities 82/12/08
CLARK, R A Operating Reactors Branch 3 CRUTCHFIELD, D Operating
Reactors Branch 5 9pp 16450 144 24X Fiche 50-245, 82/12/08,
8212170199

8208190263 Generic Ltr 82-32 to all PWR licensees re potential steam
generator-related generic requirements Forwards Science
Applications, Inc draft rept re subj requirements Comments
requested within 30 days of ltr Svc list encl
EISENHUT, D G Division of Licensing 82/12/09 Consolidated
Edison Co of New York, Inc 29pp 16629 247 24X
Fiche 50-000, 82/12/09, 8208190263

8212140103 Generic Ltr 82-28 to all licensees of operating
Westinghouse & C-E PWRs (except Arkansas Nuclear One, Unit 2
& San Onofre 2 & 3) re inadequate core cooling
instrumentation sys Svc list encl
EISENHUT, D G Division of Licensing 82/12/10 Yankee Atomic
Electric Co 27pp 16690 035 24X Fiche 50-000, 82/12/10,
8212140103

8212210121 Submits results of discharge piping analyses in response to
NUREG-0737, Item II D 1, "Performance Testing of PWR Relief
& Safety Valves"
COUNCIL, W G Connecticut Yankee Atomic Power Co COUNCIL, W G
Northeast Nuclear Energy Co (subs of Northeast Utilities)
COUNCIL, W G Northeast Utilities 82/12/15 EISENHUT, D G
Division of Licensing 4pp 16485 084 24X Fiche 50-000, 82/12/15,
8212210121

G Inspection reports, IE Bulletins & correspondence

8208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-
Wall, Large-Diameter, Stainless Steel Recirculation Sys Piping
at BWR Plants" Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and
Enforcement 82/10/28 Consolidated Edison Co of New York, Inc
112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240

8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model
B01 & Model B02 Thermoluminescent Dosimeters" Svc list
encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards
82/11/05 Consolidated Edison Co of New York, Inc 110pp
16372 142 24X Fiche 50-000, 82/11/05, 8208190245

8212030167 Forwards IE Safeguards Insp Rept 50-336/82-21 on 820928-29
No noncompliance noted
MARTIN, T T Division of Engineering & Technical Programs 82/11/17
COUNCIL, W G Northeast Nuclear Energy Co (subs of Northeast
Utilities) 2pp 16304 001 24X Fiche 50-336, 82/11/17, 8212030167

--8212030177 IE Safeguards Insp Rept 50-336/82-21 on 820928-29 No
noncompliance noted Major areas inspected SNM control &
accounting, facility organization & operation, shipping &
receiving, storage & internal control
WOLTER, E, GODY, A T Division of Engineering & Technical
Programs 82/10/22 5pp 16304 003 24X Fiche 50-336, 82/11/17,
8212030167

8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan
Exercise Requirements" Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18
Consolidated Edison Co of New York, Inc 109pp 16411 199 24X
Fiche 50-000, 82/11/18, 8208190251

B212030045 Forwards IE Insp Rept 50-336/B2-23 on B21019-21 No noncompliance noted
MARTIN, T T Division of Engineering & Technical Programs 82/11/17
CGUNSL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 16307 073 24X Fiche 50-336, 82/11/19, B212030045

--B212030031 IE Insp Rept 50-336/B2-23 on B21019-21 No noncompliance noted Major areas inspected followed up on B10102 loss of dc power event & review of diesel generator trip design & design changes
EAPEN, P K, BETTENHAUSEN, L Region 1, Office of Director 82/11/17 5pp 16307 073 24X Fiche 50-336, 82/11/19, B212030045

B208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list encl
BEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000, 82/11/26, B208190256

B208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl
COBB, L L Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000, 82/11/30, B208190257

B208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl
BEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, B208190259

B208190261 IE Info Notice 82-48, "Failures of Agastat CR 0075 Relay Sockets " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X Fiche 50-000, 82/12/03, B208190261

B208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
BEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16, B208190267

B208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type IRE-27 " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X Fiche 50-000, 82/12/20, B208190268

R Periodic operating reports & related correspondence

B212290139 Forwards monthly operating rept for Oct 1982
MROCKA, E J Northeast Nuclear Energy Co (subs of Northeast Utilities) MROCKA, E J Northeast Utilities 82/11/12 Office of Resource Management, Director 1p 16583 059 24X Fiche 50-336, 82/11/12, B212290139

--B212290142 Monthly operating rept for Oct 1982
GIBSON, J Northeast Nuclear Energy Co (subs of Northeast Utilities) 82/11/12 6pp 16583 060 24X Fiche 50-336, 82/11/12, B212290139

S Reportable occurrences, LERs & related correspondence

B212030201 Forwards LER 82-045/03L-0
MROCKA, E J Northeast Nuclear Energy Co (subs of Northeast Utilities) MROCKA, E J Northeast Utilities 82/11/24 HAYNES, R C Region 1, Office of Director 1p 16304 097 24X Fiche 50-336, 82/11/24, B212030201

--B212030204 LER 82-045/03L-0 on B21027, at 100% power, control room air conditioning sys l was lost Caused by broken wire which shifted shorting power supply due to personnel error Wire repaired & air conditioning sys returned to svc
FILBURN, T Northeast Nuclear Energy Co (subs of Northeast Utilities) 82/11/24 Region 1, Office of Director 1p 16304 098 24X Fiche 50-336, 82/11/24, B212030201

B212030227 Forwards LER 82-043/03L-0
MROCKA, E J Northeast Nuclear Energy Co (subs of Northeast Utilities) MROCKA, E J Northeast Utilities 82/11/24 HAYNES, R C Region 1, Office of Director 1p 16307 065 24X Fiche 50-336, 82/11/24, B212030227

--B212030234 LER 82-043/03L-0 on B21102, broken 1 1/4-inch hydraulic snubber stud discovered & traced to hanger 490001 on one main steam lead to high pressure turbine Caused by constant high vibration & increased loads during plant trips
STADNICK, S Northeast Nuclear Energy Co (subs of Northeast Utilities) 82/11/24 Region 1, Office of Director 1p 16307 066 24X Fiche 50-336, 82/11/24, B212030227

B212080414 Forwards LER 82-044/03L-0
MROCKA, E J Northeast Nuclear Energy Co (subs of Northeast Utilities) MROCKA, E J Northeast Utilities 82/12/03 HAYNES, R C Region 1, Office of Director 1p 16352 268 24X Fiche 50-336, 82/12/03, B212080414

--B212080415 LER 82-044/03L-0 on B21105, while performing in-core detector alarm update, alarm values updated incorrectly, resulting in nonconservative values Caused by calorimetric being temporarily out of svc Personnel restructured in procedures
BORCHERT, R Northeast Nuclear Energy Co (subs of Northeast Utilities) 82/12/03 Region 1, Office of Director 1p 16352 269 24X Fiche 50-336, 82/12/03, B212080414

B212210229 Forwards updated LER 82-044/03X-1
MROCKA, E J Northeast Nuclear Energy Co (subs of Northeast Utilities) MROCKA, E J Northeast Utilities 82/12/10 HAYNES, R C Region 1, Office of Director 1p 16483 357 24X Fiche 50-336, 82/12/10, B212210229

--B212210233 Updated LER 82-044/03X-1 on B21104, while performing in core detector alarm update, alarm values updated incorrectly, resulting in nonconservative alarm values for in-core detectors Caused by plant calorimetric out-of-svc
BORCHERT, R Northeast Nuclear Energy Co (subs of Northeast Utilities) 82/12/03 Region 1, Office of Director 1p 16483 358 24X Fiche 50-336, 82/12/10, B212210229

DOCKET 50-338 NORTH ANNA POWER STATION, UNIT 1

F Security, medical, emergency & fire protection plans

B212070195 Forwards IE Safeguards Insp Repts 50-338/B2-38 & 50-339/B2-38 on B21108-10 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 82/12/02 STEWART, W L Virginia Electric & Power Co 2pp 16335 011 24X Fiche 50-338, 82/12/02, B212070195

--B212070206 IE Safeguards Insp Repts 50-338/B2-38 & 50-339/B2-38 on B21108-10 No noncompliance noted Major areas inspected security plan & implementing procedures, organization, audit & power supply Details withheld (ref 10CFR73 21)
STANSBERRY, W H, MCGUIRE, D R Division of Engineering & Technical Programs 82/12/01 1p 16335 013 24X Fiche 50-338, 82/12/01, B212070195

B212090419 Forwards addl info re status of emergency response facilities locations & const, supplementing B10601 & B20408 responses to Generic Ltr 81-10 transmitting NUREG-0696, per request
STEWART, W L Virginia Electric & Power Co 82/12/06 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 16364 2/6 24X Fiche 50-000, 82/12/06, B212090419

B212150059 Forwards revised security drawings Drawings withheld (ref 10CFR2 790)
STEWART, W L Virginia Electric & Power Co 82/12/09 DENTON, H R Office of Nuclear Reactor Regulation, Director VARGA, S A Operating Reactors Branch 1 1p 16427 362 24X Fiche 50-000, 82/12/09, B212150059

B212170024 Forwards request for addl info re security training & qualification plans, per util B20917 ltr
CLARK, R A Operating Reactors Branch 3 82/12/13 STEWART, W L Virginia Electric & Power Co 4pp 16480 335 24X Fiche 50-000, 82/12/13, B212170024

B212270179 Informs that although B21209 ltr forwarding security drawings failed to contain safeguards statement, drawings were properly secured, marked & identified as safeguards info
STEWART, W L Virginia Electric & Power Co 82/12/20 DENTON, H R Office of Nuclear Reactor Regulation, Director VARGA, S A Operating Reactors Branch 1 1p 16539 010 24X Fiche 50-000, 82/12/20, B212270179

G Adjudicatory correspondence

B212070139 Notice of B20216 special prehearing conference in Bethesda, MD to permit key issue identification, to consider intervention petitions & to establish schedule for further actions
WOLFE, S J Atomic Safety and Licensing Board Panel 82/12/03 5pp 16327 023 24X Fiche 50-338, 82/12/03, B212070139

B212070147 Notice of B20216 special prehearing conference in Bethesda, MD to permit key issue identification, to consider intervention petitions & to establish schedule for further actions
WOLFE, S J Atomic Safety and Licensing Board Panel 82/12/03 5pp 16327 074 24X Fiche 50-338, 82/12/03, B212070147

- BP12070236 Memorandum memorializing B21202 telcon w/util. Concerned Citizens of Louisa County, Louisa County & Board of Supervisors & NRC re scheduling special prehearing conference
WOLFE, S J Atomic Safety and Licensing Board Panel 82/12/03 App 16329 313 24X Fiche 50-338, 82/12/03, 8212070236
- BP12100104 Objects to B30117 deadline for submittal of contentions. Deadline hampers identification of valid contentions & increases likelihood of burdening proceeding due to submittal of unreviewed contentions.
COLEMAN, J M Beveridge, Fairbanks & Diamond COLEMAN, J M Louisa County, VA 82/12/07 WOLFE, S J Atomic Safety and Licensing Board Panel 3pp 16379 113 24X Fiche 50-338, 82/12/07, 8212100104
- GP12140245 Motion to stay proceedings on applications for license amends to allow receipt & storage of Surry spent fuel. Proceeding should be stayed until Commission completes waste confidence proceeding Certificate of Svc encl
COLEMAN, J M Louisa County, VA COLEMAN, J M Beveridge, Fairbanks & Diamond 82/12/10 Commissioners 8pp 16409 316 24X Fiche 50-338, 82/12/10, 8212140245
- GP12140249 Motion to stay proceedings on applications for license amends to expand spent fuel pool. Proceeding should be stayed until Commission completes waste confidence proceeding Certificate of Svc encl
COLEMAN, J M Louisa County, VA COLEMAN, J M Beveridge, Fairbanks & Diamond 82/12/10 Commissioners 8pp 16409 308 24X Fiche 50-338, 82/12/10, 8212140249
- GP12280122 Answer in opposition to Louisa County, VA B21210 motion for stay of proceeding until completion of waste confidence rulemaking. Delay would be inconsistent w/NRC regulations & would prejudice util Certificate of Svc encl
MAUPITZ, M W Virginia Electric & Power Co 82/12/22 Commissioners 10pp 16564 124 24X Fiche 50-338, 82/12/22, 8212280122
- GP12280130 Affidavit of ML Smith re transshipment of spent fuel. Unless VEPCC can secure addl storage space for Surry spent fuel, Surry will lose full discharge capability.
SMITH, M L Virginia Electric & Power Co 82/12/21 6pp 16564 134 24X Fiche 50-338, 82/12/22, 8212280130
- GP12280135 Answer in opposition to Louisa County, VA B21210 motion for stay of proceeding until completion of waste confidence rulemaking. Delay would be inconsistent w/NRC regulations & would prejudice util Certificate of Svc encl
MAUPITZ, M W Virginia Electric & Power Co 82/12/22 Commissioners 10pp 16556 117 24X Fiche 50-338, 82/12/22, 8212280135
- GP12290001 Response in opposition to Louisa County, VA motions to stay proceedings until completion of waste confidence rulemaking. Delay would be inconsistent w/NRC regulations & would prejudice util Certificate of Svc encl
TREGG, S A Hearing Branch 1 82/12/27 Atomic Safety and Licensing Board Panel 5pp 16583 248 24X Fiche 50-338, 82/12/27, 8212290001
- I Operating license stage documents & correspondence
- GP12020391 Forwards requests for addl info re NUREG-0737, Items 11 F 1, 4.5 b & 6 concerning containment pressure, water level & hydrogen monitors. Response requested within 30 days.
CLARK, R A Operating Reactors Branch 3 82/11/12 STEWART, W L Virginia Electric & Power Co 9pp 16308 134 24X Fiche 50-338, 82/11/12, 8212020391
- GP12010370 Informs that Class 11 fee appropriate for review of B21108 application for Amend 44 to CL changing Type C testing of isolation valves. Refund forthcoming.
DIGGS, R H License Fee Management Branch 82/11/23 STEWART, W L Virginia Electric & Power Co 1p 16271 097 24X Fiche 50-338, 82/11/23, 8212010370
- GP12060134 Forwards response to NRC B21026 questionnaire re steam generator tube integrity. Data for each facility compiled in separate sections.
STEWART, W L Virginia Electric & Power Co 82/12/01 DENTON, H R Office of Nuclear Reactor Regulation, Director EISENHUT, D G Division of Licensing 5pp 16314 070 24X Fiche 50-000, 82/12/01, 8212060134
- GP12060284 Notifies that neither facility has addl Tech Specs to be submitted, in response to Generic Ltr 82-16 re status of NUREG-0737 items.
STEWART, W L Virginia Electric & Power Co 82/12/01 DENTON, H R Office of Nuclear Reactor Regulation, Director EISENHUT, D G Division of Licensing 1p 16312 058 24X Fiche 50-000, 82/12/01, 8212060284
- GP12130326 Lists as-found ring settings & EPRI as-left ring settings for plant relief & safety valves. As-found settings will provide acceptable performance. As-left settings add increased conservatism to valve performance.
STEWART, W L Virginia Electric & Power Co 82/12/07 DENTON, H R Office of Nuclear Reactor Regulation, Director EISENHUT, D G Division of Licensing 2pp 16389 327 24X Fiche 50-338, 82/12/07, 8212130326
- B12130319 Advises that util intends to terminate hydrogen monitoring program. Parameters of data received impossible to control in power plant environ to degree necessary to perform accurate & meaningful interpretation of collected data.
STEWART, W L Virginia Electric & Power Co 82/12/08 DENTON, H R Office of Nuclear Reactor Regulation, Director CLARK, R A Operating Reactors Branch 3 1p 16389 332 24X Fiche 50-338, 82/12/08, 8212130319
- B12150048 Application to amend Licenses NPF-4 & NPF-7, allowing optimization of core loading patterns & providing addl operating flexibility.
STEWART, W L Virginia Electric & Power Co 82/12/08 DENTON, H R Office of Nuclear Reactor Regulation, Director CLARK, R A Operating Reactors Branch 3 9pp 16422 294 24X Fiche 50-338, 82/12/08, 8212150048
- B212150052 Proposed Tech Specs allowing optimization of core loading patterns & providing addl operating flexibility.
* Virginia Electric & Power Co 82/12/08 21pp 16422 302 24X Fiche 50-338, 82/12/08, 8212150048
- BP08190263 Generic Ltr 82-32 to all PWR licensees re potential steam generator-related generic requirements. Forwards Science Applications, Inc draft rept re subj requirements. Comments requested within 30 days of ltr Svc list encl.
EISENHUT, D G Division of Licensing 82/12/09 Consolidated Edison Co of New York, Inc 29pp 16627 247 24X Fiche 50-000, 82/12/09, 8208190263
- GP12140103 Generic Ltr 82-28 to all licensees of operating Westinghouse & C-E PWRs (except Arkansas Nuclear One, Unit 2 & San Onofre 2 & 3) re inadequate core cooling instrumentation sys. Svc list encl.
EISENHUT, D G Division of Licensing 82/12/10 Yankee Atomic Electric Co 27pp 16690 035 24X Fiche 50-000, 82/12/10, 8212140103
- GP12210187 Responds to NRC comments on conclusions & recommendations re NUREG-0612, "Control of Heavy Loads," per B21022 telcon.
STEWART, W L Virginia Electric & Power Co 82/12/15 DENTON, H R Office of Nuclear Reactor Regulation, Director CLARK, R A Operating Reactors Branch 3 4pp 16484 347 24X Fiche 50-338, 82/12/15, 8212210187
- B212270407 Trip rept of B21129 visit to Region 2 of re investigation into latest Westinghouse main transformer fault to occur at facility.
ENGLE, L B Operating Reactors Branch 3 82/12/17 CLARK, R A Operating Reactors Branch 3 5pp 16555 353 24X Fiche 50-338, 82/12/17, 8212270407
- B212270490 Trip rept of B21207 briefing at site re B21205 main transformer fault, resulting in turbine & reactor trip. Cause undetermined. Plant extensively damaged. Task force organized to monitor util investigations.
ENGLE, L B Operating Reactors Branch 3 82/12/17 CLARK, R A Operating Reactors Branch 3 11pp 16551 056 24X Fiche 50-338, 82/12/17, 8212270490
- GP12290248 Application to amend Licenses NPF-4 & NPF-7 changing radiological effluent Tech Specs to delete radiological sampling, monitoring & reporting requirements in accordance w/NUREG-0472, Revision 3.
STEWART, W L Virginia Electric & Power Co 82/12/17 DENTON, H R Office of Nuclear Reactor Regulation, Director CLARK, R A Operating Reactors Branch 3 3pp 16588 034 24X Fiche 50-338, 82/12/17, 8212290248
- GP12290252 Proposed Tech Spec changes re sampling frequency of waste decay tank encl. Justifications for deviations from NUREG-0472, Revision 3 encl.
* Virginia Electric & Power Co 82/12/17 252pp 16588 037 24X Fiche 50-338, 82/12/17, 8212290248
- B212290255 Offsite dose calculation manual.
* Virginia Electric & Power Co 82/12/17 166pp 16588 289 24X Fiche 50-338, 82/12/17, 8212290248
- B212290256 Process control program.
* Virginia Electric & Power Co 82/12/17 30pp 16589 095 24X Fiche 50-338, 82/12/17, 8212290248

B-12280201 Forwards addl info re NUREG-0737, Items I I F 1 4 I I F 1 5 & I I F 1 6 concerning accuracies & time responses of containment post-accident monitoring equipment & placement of hydrogen monitor intake ports, per B21112 request
STEWART, W L Virginia Electric & Power Co 82/12/21 DENTON, H
Office of Nuclear Reactor Regulation, Director Bpp 16562 096
24X Fiche 50-338, 82/12/21, 8212280201

B-12280257 Forwards remittance for Invoice B-0063 For review of Amend 4 to Topical Rept VEP-1, "QA Program - Operations Phase," submitted on 820921 & approved on 821006
STEWART, W L Virginia Electric & Power Co 82/12/22 DENTON, H R
Office of Nuclear Reactor Regulation, Director BARRY, L W Division of Accounting 1p 16561 269 24X Fiche 50-000, 82/12/22, 8212280257

G Inspection reports, IE Bulletins & correspondence

B-08190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240

B-12090285 Advises that SALP Repts 50-280/82-19, 50-281/82-19, 50-338/82-24 & 50-339/82-24 have been reviewed & approved. Overall performance adequate. No reply required
O'REILLY, J P Region 2, Office of Director 82/11/03
LEASBURG, R H Virginia Electric & Power Co 2pp 16365 208 24X Fiche 50-000, 82/11/03, 8212090285

--B-12090298 Forwards SALP Repts 50-280/82-19, 50-281/82-19, 50-338/82-24 & 50-339/82-24 for Jul 1980-June 1981
LEWIS, R C Division of Project & Resident Programs 82/08/04
LEASBURG, R H Virginia Electric & Power Co 2pp 16365 210 24X Fiche 50-000, 82/11/03, 8212090285

--B-12090306 SALP Repts 50-220/82-19, 50-281/82-19, 50-338/82-24 & 50-339/82-24 for Jul 1980-June 1981 Increased mgt attention should be directed towards plant operations & operational QA
* Region 2, Office of Director 82/08/04 31pp 16365 212 24X Fiche 50-000, 82/11/03, 8212090285

B-08190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model B91 & Model B92 Thermoluminescent Dosimeters " Svc list encl
OBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/03 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000, 82/11/03, 8208190245

B-12090515 Forwards IE Insp Repts 50-338/82-36 & 50-339/82-36 on 821018-22 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 82/11/09
LEASBURG, R H Virginia Electric & Power Co 2pp 16366 292 24X Fiche 50-338, 82/11/09, 8212090515

--B-12090521 IE Insp Repts 50-338/82-36 & 50-339/82-36 on 821018-22 No noncompliance noted. Major areas inspected QC & confirmatory measurements, including lab QC program, chemical & radiochemical procedures & airborne effluent sampling
EVANS, C D, MONTGOMERY, D M Division of Emergency Preparedness & Operational Support 82/11/08 9pp 16366 294 24X Fiche 50-338, 82/11/09, 8212090515

B-12090478 Ack receipt of 821103 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-338/82-32 & 50-339/82-32
DANCE, H C Division of Project & Resident Programs 82/11/12
STEWART, W L Virginia Electric & Power Co 1p 16365 314 24X Fiche 50-338, 82/11/12, 8212090478

--B-12090485 Responds to NRC 821005 ltr re violations noted in IE Insp Repts 50-338/82-32 & 50-339/82-32 Corrective actions chemistry periodic test for dose equivalent I-131 level revised to require deviation rept if limit exceeded
STEWART, W L Virginia Electric & Power Co 82/11/03
O'REILLY, J P Region 2, Office of Director 3pp 16365 315 24X Fiche 50-338, 82/11/12, 8212090478

--B-12090491 Forwards IE Insp Repts 50-338/82-32 & 50-339/82-32 on 820913-17 & notice of violation
DANCE, H C Division of Project & Resident Programs 82/10/05
LEASBURG, R H Virginia Electric & Power Co 2pp 16365 318 24X Fiche 50-338, 82/11/12, 8212090478

--B-12090496 Notice of violation from insp on 820913-17
* Division of Project & Resident Programs 82/10/05 1p 16365 320 24X Fiche 50-338, 82/11/12, 8212090478

--B-12090505 IE Insp Repts 50-338/82-32 & 50-339/82-32 on 820913-17 Noncompliance noted failure to rept reactor coolant dose equivalent I-131 level in excess of Tech Spec limit
WRAV, J R, BARR, K P Division of Engineering & Technical Programs 82/10/04 6pp 16365 321 24X Fiche 50-338, 82/11/12, 8212090478

B-08190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 107pp 16411 199 24X Fiche 50-000, 82/11/18, 8208190251

B-12090161 Confirms 821129 meeting w/ util in Atlanta, GA to discuss results of investigation re causes of repeated main electrical output transformer failures Proposed agenda encl
O'REILLY, J P Region 2, Office of Director 82/11/24 STEWART, W L Virginia Electric & Power Co 2pp 16359 098 24X Fiche 50-338, 82/11/24, 8212090161

B-08190256 IE Info Notice 82-46, "Defective & Obsolete Combination Radiolocks " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000, 82/11/26, 8208190256

B-08190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl
OBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 35pp 16387 028 24X Fiche 50-000, 82/11/30, 8208190257

B-12070195 Forwards IE Safeguards Insp Repts 50-338/82-38 & 50-339/82-38 on 821108-10 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 82/12/02
STEWART, W L Virginia Electric & Power Co 2pp 16335 011 24X Fiche 50-338, 82/12/02, 8212070195

--B-12070206 IE Safeguards Insp Repts 50-338/82-38 & 50-339/82-38 on 821108-10 No noncompliance noted. Major areas inspected security plan & implementing procedures, organization, audit & power supply details withheld (ret 10CFR73.21)
STANSBERRY, W H, MCQUIRE, D R Division of Engineering & Technical Programs 82/12/01 1p 16335 013 24X Fiche 50-338, 82/12/04, 8212070195

B-08190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259

B-08190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X Fiche 50-000, 82/12/03, 8208190261

B-08190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16, 8208190267

B-08190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27 " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/10 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X Fiche 50-000, 82/12/20, 8208190268

R Periodic operating reports & related correspondence

B-12290317 Forwards monthly operating repts for Oct 1982
STEWART, W L Virginia Electric & Power Co 82/11/10 HALLER, N H Office of Resource Management, Director 1p 16589 143 24X Fiche 50-338, 82/11/10, 8212290317

--B-12290318 Monthly operating repts for Oct 1982
SCHMITENDORF, G Virginia Electric & Power Co 82/11/01 10pp 16589 144 24X Fiche 50-338, 82/11/10, 8212290317

S Reportable occurrences, LERs & related correspondence

B-12090112 Forwards LER 82-068/03L-0
CARTWRIGHT, W R Virginia Electric & Power Co 82/11/30
O'REILLY, J P Region 2, Office of Director 1p 16357 274 24X Fiche 50-338, 82/11/30, 8212090112

DOCKETED ITEMS

205

8212090115 LER 82-068/03L-0 on 821102, charging pumps & boric acid flowpaths rendered inoperable Caused by maint on charging pump C normal suction valve MOV-1270A which required removal of valve bonnet Valve bonnet replaced
CARTWRIGHT, W R Virginia Electric & Power Co 82/11/30 Region
2, Office of Director 2pp 16357 277 24X Fiche 50-338, 82/11/30, 8212090112

12090363 Forwards LER 82-072/03L-0
CARTWRIGHT, W R Virginia Electric & Power Co 82/12/01
O'REILLY, J P Region 2, Office of Director 1p 16357 348 24X
Fiche 50-338, 82/12/01, 8212090063

8212090064 LER 82-072/03L-0 on 821115, while testing heat detectors, high pressure carbon dioxide sys automatic actuation valves failed to operate Caused by pneumatic actuation devices being mechanically bound Devices cleaned
CARTWRIGHT, W R Virginia Electric & Power Co 82/12/01 Region
2, Office of Director 3pp 16357 349 24X Fiche 50-338, 82/12/01, 8212090063

12090527 Forwards LER 82-071/03L-0
CARTWRIGHT, W R Virginia Electric & Power Co 82/12/01
O'REILLY, J P Region 2, Office of Director 1p 16365 129 24X
Fiche 50-338, 82/12/01, 8212090527

8212090538 LER 82-071/03L-0 on 821105, B inside recirculation spray pump (1-RS-P-10) did not operate within required time during functional testing Caused by drift in actuation timer setting Timer readjusted & retested
CARTWRIGHT, W R Virginia Electric & Power Co 82/12/01 Region
2, Office of Director 2pp 16365 130 24X Fiche 50-338, 82/12/01, 8212090527

12150151 PNO-11-82-132 on 821205, main transformer B found leaking oil, resulting in severe mechanical damage to transformer case & melting of neutral bus duct Cause under investigation Transformers will be replaced
JULIAN, C A, DANCE, H C Region 2, Office of Director 82/12/06
3pp 16425 226 24X Fiche 50-338, 82/12/06, 8212150151

12150028 Forwards LER 82-074/03L-0
CARTWRIGHT, W R Virginia Electric & Power Co 82/12/08
O'REILLY, J P Region 2, Office of Director 1p 16421 007 24X
Fiche 50-338, 82/12/08, 8212150028

8212150034 LER 82-074/03L-0 on 821117, protection Channel 1 overtemp delta T % overpower delta T placed in trip, rendering channel inoperable Caused by T-hot NRA card (TM-412M) failure Channel recalibr
CARTWRIGHT, W R Virginia Electric & Power Co 82/12/08 Region
2, Office of Director 1p 16421 008 24X Fiche 50-338, 82/12/08, 8212150028

12150094 Forwards LER 82-075/03L-0
CARTWRIGHT, W R Virginia Electric & Power Co 82/12/08
O'REILLY, J P Region 2, Office of Director 1p 16430 352 24X
Fiche 50-338, 82/12/08, 8212150094

8212150096 LER 82-075/03L-0 on 821117, individual rod position indicator for rods B-10 in control bank A, D-4 in control bank C & N-9 in shutdown bank A, deviated from group demand position w/no rod motion Caused by instrument drift Channels recalibr
CARTWRIGHT, W R Virginia Electric & Power Co 82/12/08 Region
2, Office of Director 2pp 16430 353 24X Fiche 50-338, 82/12/08, 8212150094

12200027 Forwards LER 82-069/03L-0
CARTWRIGHT, W R Virginia Electric & Power Co 82/12/09
O'REILLY, J P Region 2, Office of Director 1p 16474 034 24X
Fiche 50-338, 82/12/09, 8212200027

8212200037 LER 82-069/03L-0 on 821110, in Mode 5, pressurizer PORV previously blocked open found closed Caused by PORV block not adequately secured during installation Block reinstated
CARTWRIGHT, W R Virginia Electric & Power Co 82/12/09 Region
2, Office of Director 4pp 16474 035 24X Fiche 50-338, 82/12/09, 8212200027

12150103 PNO-11 82-132A updates 821205 failure of main transformer Extensive damage occurred in main generator Generator disassembled for detailed insp Stator winding damage observed Unit will be out of svc for 12-15 wks
JULIAN, C A, DANCE, H C Region 2, Office of Director 82/12/10
2pp 16430 358 24X Fiche 50-338, 82/12/10, 8212150103

12210137 Forwards LER 82-073/03L-0
CARTWRIGHT, W R Virginia Electric & Power Co 82/12/13
O'REILLY, J P Region 2, Office of Director 1p 16485 172 24X
Fiche 50-338, 82/12/13, 8212210137

--8212210147 LER 82-073/03L-0 on 821118, D reactor trip breaker failed to auto open on simulated reactor signal Caused by stuck undervoltage tripping mechanism Device removed, cleaned, lubricated & reinstalled
CARTWRIGHT, W R Virginia Electric & Power Co 82/12/13 Region
2, Office of Director 2pp 16485 173 24X Fiche 50-338, 82/12/13, 8212210137

8212210163 Forwards LER 82-077/03L-0
CARTWRIGHT, W R Virginia Electric & Power Co 82/12/13
O'REILLY, J P Region 2, Office of Director 1p 16484 305 24X
Fiche 50-338, 82/12/13, 8212210163

--8212210171 LER 82-077/03L-0 on 821119, MOV-1536 could not be opened after period test Caused by loose control cable connection at motor operator Loose connection tightened
CARTWRIGHT, W R Virginia Electric & Power Co 82/12/13 Region
2, Office of Director 2pp 16484 306 24X Fiche 50-338, 82/12/13, 8212210163

8212220244 Forwards LER 82-078/03L-0
CARTWRIGHT, W R Virginia Electric & Power Co 82/12/15
O'REILLY, J P Region 2, Office of Director 1p 16517 192 24X
Fiche 50-338, 82/12/15, 8212220244

--8212220268 LER 82-078/03L-0 on 821125, in Mode 3, 120-volt ac vital bus 1-IV lost voltage Caused by failure of normal power supply inverter 1-VB-1-04 due to failed oscillator board, transformer & fuse Parts replaced & inverter tested
CARTWRIGHT, W R Virginia Electric & Power Co 82/12/15 Region
2, Office of Director 1p 16517 193 24X Fiche 50-338, 82/12/15, 8212220244

8212220399 Forwards LER 82-079/03L-0
CARTWRIGHT, W R Virginia Electric & Power Co 82/12/15
O'REILLY, J P Region 2, Office of Director 1p 16504 285 24X
Fiche 50-338, 82/12/15, 8212220399

--8212220408 LER 82-079/03L-0 on 821126, in Mode 3, flow path from boric acid tanks to RCS inoperable Caused by ruptured diaphragm of boric acid transfer pump suction header isolation valve 1-CH-80 Valve diaphragm replaced
CARTWRIGHT, W R Virginia Electric & Power Co 82/12/15 Region
2, Office of Director 2pp 16504 286 24X Fiche 50-338, 82/12/15, 8212220399

8212220410 Forwards LER 82-070/03L-0
CARTWRIGHT, W R Virginia Electric & Power Co 82/12/16
O'REILLY, J P Region 2, Office of Director 1p 16503 245 24X
Fiche 50-338, 82/12/16, 8212220410

--8212220416 LER 82-070/03L-0 on 821116 & 28, head tracing circuits ET-117N & ET-116N failed, reducing piping temp below 145 F Cause of 821116 event not stated Failure on 821128 caused by loose insulation Failed channel replaced & insulation added
CARTWRIGHT, W R Virginia Electric & Power Co 82/12/16 Region
2, Office of Director 2pp 16503 246 24X Fiche 50-338, 82/12/16, 8212220410

8212300126 Forwards LER 82-080/03L-0
CARTWRIGHT, W R Virginia Electric & Power Co 82/12/20
O'REILLY, J P Region 2, Office of Director 1p 16598 297 24X
Fiche 50-338, 82/12/20, 8212300126

--8212300130 LER 82-080/03L-0 on 821128, while in Mode 3, containment isolation svc air valve found open & unattended Cause unknown Valve closed & locked Investigation underway
CARTWRIGHT, W R Virginia Electric & Power Co 82/12/20 Region
2, Office of Director 3pp 16598 298 24X Fiche 50-338, 82/12/20, 8212300126

8212300217 Forwards LER 82-082/01T-0
CARTWRIGHT, W R Virginia Electric & Power Co 82/12/20
O'REILLY, J P Region 2, Office of Director 1p 16597 353 24X
Fiche 50-338, 82/12/20, 8212300217

--8212300220 LER 82-082/01T-0 on 821206, both trains of automatic safety injection blocked for 22 h & 30 minutes following inadvertent safety injection Caused by emergency procedure which misled operators Procedure revised
CARTWRIGHT, W R Virginia Electric & Power Co 82/12/20 Region
2, Office of Director 3pp 16597 354 24X Fiche 50-338, 82/12/20, 8212300217

8212300171 Forwards LER 82-081/03L-0
CARTWRIGHT, W R Virginia Electric & Power Co 82/12/21
O'REILLY, J P Region 2, Office of Director 1p 16598 092 24X
Fiche 50-338, 82/12/21, 8212300171

DOCKETED ITEMS

--8212300177 LER 82-081/03L-0 on 821203, svc water supply header A to Units 1 & 2 charging pump lube oil coolers & air compressors isolated to repair pinhole leak Caused by corrosion Affected piping cut out & replaced
CARTWRIGHT, W R Virginia Electric & Power Co 82/12/21 Region
2, Office of Director 3pp 16598 093 24X Fiche 50-338, 82/12/21, 8212300171

8212300313 Forwards LER 82-090/03L-0
CARTWRIGHT, W R Virginia Electric & Power Co 82/12/21
O'REILLY, J P Region 2, Office of Director 1p 16594 213 24X
Fiche 50-338, 82/12/21, 8212300313

--8212300315 LER 82-090/03L-0 on 821205, 3A auxiliary feedwater pump removed from svc to determine cause of overcurrent flag drops on A & C phase Cause not determined Flags reset & motor bridged & meggered w/o discrepancies
CARTWRIGHT, W R Virginia Electric & Power Co 82/12/21 Region
2, Office of Director 2pp 16594 214 24X Fiche 50-338, 82/12/21, 8212300313

8212300232 Forwards LER 82-084/03L-0
CARTWRIGHT, W R Virginia Electric & Power Co 82/12/22
O'REILLY, J P Region 2, Office of Director 1p 16598 018 24X
Fiche 50-338, 82/12/22, 8212300232

--8212300238 LER 82-084/03L-0 on 821205, at 20% power, channels FI-1475 & FI-1485 for steam generators A & B steam flow showed below actual flow Caused by transmitter for FI-1475 & multiplier/divider/square root for FI-1485 being out of calibr
CARTWRIGHT, W R Virginia Electric & Power Co 82/12/22 Region
2, Office of Director 1p 16598 019 24X Fiche 50-338, 82/12/22, 8212300232

8212300245 Forwards LER 82-087/03L-0
CARTWRIGHT, W R Virginia Electric & Power Co 82/12/22
O'REILLY, J P Region 2, Office of Director 1p 16595 244 24X
Fiche 50-338, 82/12/22, 8212300245

--8212300247 LER 82-087/03L-0 on 821205, during Mode 1, individual RPI for rod H-02 in control bank D deviated from group demand position by greater than 12 steps w/no rod motion Caused by instrument drift RPI channel recalibr & returned to svc
CARTWRIGHT, W R Virginia Electric & Power Co 82/12/22 Region
2, Office of Director 2pp 16595 245 24X Fiche 50-338, 82/12/22, 8212300245

8212300261 Forwards LER 82-091/03L-0
CARTWRIGHT, W R Virginia Electric & Power Co 82/12/22
O'REILLY, J P Region 2, Office of Director 1p 16595 208 24X
Fiche 50-338, 82/12/22, 8212300261

--8212300267 LER 82-091/03L-0 on 821207, during Mode 4, pressure in nitrogen reservoir B for pressurizing PORV (PCV-1455C) dropped below min Caused by excessive nitrogen leakage through nitrogen reservoir B relief valve Valve repaired
CARTWRIGHT, W R Virginia Electric & Power Co 82/12/22 Region
2, Office of Director 2pp 16595 209 24X Fiche 50-338, 82/12/22, 8212300261

DOCKET 50-339 NORTH ANNA POWER STATION, UNIT 2

F Security, medical, emergency & fire protection plans

8212070195 Forwards IE Safeguards Insp Repts 50-338/82-38 & 50-339/82-38 on 821108-10 No noncompliance noted.
DANCE, H C Division of Project & Resident Programs 82/12/02
STEWART, W L Virginia Electric & Power Co 2pp 16333 011 24X
Fiche 50-338, 82/12/02, 8212070195

--8212070206 IE Safeguards Insp Repts 50-338/82-38 & 50-339/82-38 on 821108-10 No noncompliance noted Major areas inspected security plan & implementing procedures, organization, audit & power supply Details withheld (ref 10CFR73 21)
STANBERRY, W W Division of Engineering & Technical Programs 82/12/01 1p. 16335 013 24X Fiche 50-338, 82/12/02, 8212070195

8212090419 Forwards addl info re status of emergency response facilities locations & const, supplementing 810401 & 820408
----- 1c 1tr 81-10 transmitting NUREG-0464, per

ic & Power Co 82/12/06 DENTON, H R
ation, Director 2pp 16364 276
970419

y drawings Drawings withheld

Power Co 82/12/09 DENTON, H R
tion, Director 1p 16427 362 24X

8212170024 Forwards request for addl info re security training & qualification plans, per util 820917 ltr
CLARK, R A Operating Reactors Branch 3 82/12/13 STEWART, W L
Virginia Electric & Power Co 4pp 16480 335 24X
Fiche 50-000, 82/12/13, 8212170024

8212270179 Informs that although 821209 ltr forwarding security drawings failed to contain safeguards statement, drawings were properly secured, marked & identified as safeguards info
STEWART, W L Virginia Electric & Power Co 82/12/20 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 16539 010 21x
Fiche 50-000, 82/12/20, 8212270179

0 Adjudicatory correspondence

8212070139 Notice of 830216 special prehearing conference in Bethesda, MD to permit key issue identification, to consider intervention petitions & to establish schedule for further actions
WOLFE, S J Atomic Safety and Licensing Board Panel 82/12/03 5pp
16327 023 24X Fiche 50-338, 82/12/03, 8212070139

8212070147 Notice of 820216 special prehearing conference in Bethesda, MD to permit key issue identification, to consider intervention petitions & to establish schedule for further actions
WOLFE, S J Atomic Safety and Licensing Board Panel 82/12/03 5pp
16327 074 24X Fiche 50-338, 82/12/03, 8212070147

8212070236 Memorandum memorializing 821202 telcon w/util, Concerned Citizens of Louisa County, Louisa County & Board of Supervisors & NRC re scheduling special prehearing conference
WOLFE, S J Atomic Safety and Licensing Board Panel 82/12/03 4pp
16329 313 24X Fiche 50-338, 82/12/03, 8212070236

8212100104 Objects to 830117 deadline for submittal of contentions Deadline hampers identification of valid contentions & increases likelihood of burdening proceeding due to submittal of unreviewed contentions
COLEMAN, J M Beveridge, Fairbanks & Diamond COLEMAN, J M Louisa County, VA 82/12/07 WOLFE, S J Atomic Safety and Licensing Board Panel 3pp 16379 113 24X Fiche 50-338, 82/12/07, 8212100104

8212140245 Motion to stay proceedings on applications for license amends to allow receipt & storage of Surry spent fuel Proceeding should be stayed until Commission completes waste confidence proceeding Certificate of Svc encl
COLEMAN, J M Louisa County, VA COLEMAN, J M Beveridge, Fairbanks & Diamond 82/12/10 Commissioners 8pp 16409 316 24X
Fiche 50-338, 82/12/10, 8212140245

8212140249 Motion to stay proceedings on applications for license amends to expand spent fuel pool Proceeding should be stayed until Commission completes waste confidence proceeding Certificate of Svc encl
COLEMAN, J M Louisa County, VA COLEMAN, J M Beveridge, Fairbanks & Diamond 82/12/10 Commissioners 8pp 16409 308 24X
Fiche 50-338, 82/12/10, 8212140249

8212280122 Answer in opposition to Louisa County, VA 821210 motion for stay of proceeding until completion of waste confidence rulemaking Delay would be inconsistent w/NRC regulations & would prejudice util Certificate of Svc encl
HAUPTMAN, H W Virginia Electric & Power Co 82/12/22 Commissioners 10pp 16564 124 24X Fiche 50-338, 82/12/22, 8212280122

--8212280130 Affidavit of ML Smith re transshipment of spent fuel Unless VEPCO can secure addl storage space for Surry spent fuel, Surry will lose full discharge capability
SMITH, M L Virginia Electric & Power Co 82/12/21 6pp
16564 134 24X Fiche 50-338, 82/12/22, 8212280122

8212280135 Answer in opposition to Louisa County, VA 821210 motion for stay of proceeding until completion of waste confidence rulemaking Delay would be inconsistent w/NRC regulations & would prejudice util Certificate of Svc encl
HAUPTMAN, H W Virginia Electric & Power Co 82/12/22 Commissioners 10pp 16556 117 24X Fiche 50-338, 82/12/22, 8212280135

8212290001 Response in opposition to Louisa County, VA motions to stay proceedings until completion of waste confidence rulemaking Delay would be inconsistent w/NRC regulations & would prejudice util Certificate of Svc encl
TREDY, S A Hearing Branch 1 82/12/27 Atomic Safety and Licensing Board Panel 5pp 16583 248 24X Fiche 50-338, 82/12/27, 8212290001

IV Operating license stage documents & correspondence

B212020391 Forwards requests for addl info re NUREG-0737, Items 11 F 1 4, 5 & 6 concerning containment pressure, water level & hydrogen monitors Response requested within 30 days
CLARK, R A Operating Reactors Branch 3 82/11/12 STEWART, W L
Virginia Electric & Power Co 9pp 16308 134 24X
Fiche 50-338, 82/11/12, 8212020391

B212060134 Forwards response to NRC 821026 questionnaire re steam generator tube integrity Data for each facility compiled in separate sections
STEWART, W L Virginia Electric & Power Co 82/12/01 DENTON, H R
Office of Nuclear Reactor Regulation, Director 5pp 16314 070
Fiche 50-000, 82/12/01, 8212060134

B212060284 Notices that neither facility has addl Tech Specs to be submitted, in response to Generic Ltr 82-16 re status of NUREG-0737 items
STEWART, W L Virginia Electric & Power Co 82/12/01 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 16312 058 24X
Fiche 50-000, 82/12/01, 8212060284

B212130326 Lists as-found ring settings & EPRI as-left ring settings for plant relief & safety valves As-found settings will provide acceptable performance As-left settings add increased conservatism to valve performance
STEWART, W L Virginia Electric & Power Co 82/12/07 DENTON, H R
Office of Nuclear Reactor Regulation, Director EISENHUT, D G
Division of Licensing 2pp 16389 327 24X Fiche 50-338, 82/12/07, 8212130326

B212150048 Application to amend Licenses NPF-4 & NPF-7, allowing optimization of core loading patterns & providing addl operating flexibility
STEWART, W L Virginia Electric & Power Co 82/12/08 DENTON, H R
Office of Nuclear Reactor Regulation, Director CLARK, R A
Operating Reactors Branch 3 7pp 16422 294 24X
Fiche 50-338, 82/12/08, 8212150048

--B212150052 Proposed Tech Specs allowing optimization of core loading patterns & providing addl operating flexibility
* Virginia Electric & Power Co 82/12/08 21pp 16422 302 24X
Fiche 50-338, 82/12/08, 8212150048

B212190263 Generic Ltr 82-32 to all PWR licensees re potential steam generator-related generic requirements Forwards Science Applications, Inc draft re subj requirements Comments requested within 30 days of Ltr Svc list encl
EISENHUT, D G Division of Licensing 82/12/09 Consolidated Edison Co. of New York, Inc 29pp 16629 247 24X
Fiche 50-000, 82/12/09, 8208190263

B212140103 Generic Ltr 82-28 to all licensees of operating Westinghouse & C-E PWRs (except Arkansas Nuclear One, Unit 2 & San Onofre 2 & 3) re inadequate core cooling instrumentation sys Svc list encl
EISENHUT, D G Division of Licensing 82/12/10 Yankee Atomic Electric Co 27pp 16690 035 24X Fiche 50-000, 82/12/10, 8212140103

B212210187 Responds to NRC comments on conclusions & recommendations re NUREG-0612, "Control of Heavy Loads," per 821022 telcon
STEWART, W L Virginia Electric & Power Co 82/12/15 DENTON, H R
Office of Nuclear Reactor Regulation, Director CLARK, R A
Operating Reactors Branch 3 4pp 16484 347 24X
Fiche 50-338, 82/12/15, 8212210187

B212270407 Trip rept of 821129 visit to Region 2 ofc re investigation into latest Westinghouse main transformer fault to occur at facility
LNGLE, L B Operating Reactors Branch 3 82/12/17 CLARK, R A
Operating Reactors Branch 3 5pp 16555 353 24X
Fiche 50-338, 82/12/17, 8212270407

B212270490 Trip rept of 821209 briefing at site re 821205 main transformer fault, resulting in turbine & reactor trip Cause undetermined Plant extensively damaged Task force organized to monitor until investigations
LNGLE, L B Operating Reactors Branch 3 82/12/17 CLARK, R A
Operating Reactors Branch 3 11pp 16551 056 24X
Fiche 50-338, 82/12/17, 8212270490

B212290248 Application to amend Licenses NPF-4 & NPF-7 changing radiological effluent Tech Specs to delete radiological sampling, monitoring & reporting requirements in accordance w/NUREG-0472, Revision 3
STEWART, W L Virginia Electric & Power Co 82/12/17 DENTON, H R
Office of Nuclear Reactor Regulation, Director CLARK, R A
Operating Reactors Branch 3 3pp 16588 034 24X
Fiche 50-338, 82/12/17, 8212290248

--B212290252 Proposed Tech Spec changes re sampling frequency of waste decay tank encl Justifications for deviations from NUREG-0472, Revision 3 encl
* Virginia Electric & Power Co 82/12/17 252pp 16588 037
24X Fiche 50-338, 82/12/17, 8212290248

--B212290255 Offsite dose calculation manual
* Virginia Electric & Power Co 82/12/17 166pp 16588 289
24X Fiche 50-338, 82/12/17, 8212290248

- B212290256 Process control program
* Virginia Electric & Power Co 82/12/17 30pp 16589 095 24X
Fiche 50-338, 82/12/17, 8212290248

B212280201 Forwards addl info re NUREG-0737, Items 11 F 1 4, 11 F 1 5 & 11 F 1 6 concerning accuracies & time responses of containment post-accident monitoring equipment & placement of hydrogen monitor intake ports, per 821112 request
STEWART, W L Virginia Electric & Power Co 82/12/21 DENTON, H R
Office of Nuclear Reactor Regulation, Director 8pp 16562 096
24X Fiche 50-338, 82/12/21, 8212280201

B212280259 Comments on second analysis of safety valve loop seals due to potential operability problems posed by draining seals per 820701 Ltr Engineering & required mods on unit planned based on retention of safety valve loop seals
STEWART, W L Virginia Electric & Power Co 82/12/21 DENTON, H R
Office of Nuclear Reactor Regulation, Director EISENHUT, D G
Division of Licensing 1p 16561 249 24X Fiche 50-339, 82/12/21, 8212280259

B212280257 Forwards remittance for Invoice B-0063 for review of Amend 4 to Topical Rept VEP-1, "QA Program - Operations Phase," submitted on 820921 & approved on 821006
STEWART, W L Virginia Electric & Power Co 82/12/22 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 16561 249 24X
Fiche 50-000, 82/12/22, 8212280257

Q Inspection reports, IE Bulletins & correspondence

B21208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel Recirculation Sys Piping at BWR Plants" Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co. of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240

B212090285 Advises that BALP Repts 50-280/82-19, 50-281/82-19, 50-338/82-24 & 50-339/82-24 have been reviewed & approved Overall performance adequate No reply required
O'REILLY, J P Region 2, Office of Director 82/11/03 LEASBURN, R H Virginia Electric & Power Co 2pp 16365 208 24X
Fiche 50-000, 82/11/03, 8212090285

--B212090298 Forwards SALP Repts 50-280/82-19, 50-281/82-19, 50-338/82-24 & 50-339/82-24 for Jul 1980-June 1981
LEWIS, R C Division of Project & Resident Programs 82/08/04 LEASBURN, R H Virginia Electric & Power Co 2pp 16365 210 24X
Fiche 50-000, 82/11/03, 8212090285

--B212090306 BALP Repts 50-280/82-19, 50-281/82-19, 50-338/82-24 & 50-339/82-24 for Jul 1980-June 1981 Increased mgt attention should be directed towards plant operations & operational QA
* Region 2, Office of Director 82/08/04 31pp 16365 212 24X
Fiche 50-000, 82/11/03, 8212090285

B21208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters" Svc list encl
LORD, L I Division of Fuel Facilities, Materials & Safeguards 82/11/03 Consolidated Edison Co. of New York, Inc 110pp 16372 142 24X Fiche 50-000, 82/11/03, 8208190245

B212090315 Forwards IE Insp Repts 50-338/82-36 & 50-339/82-36 on 821018-22 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 82/11/09 LEASBURN, R H Virginia Electric & Power Co 2pp 16366 292 24X
Fiche 50-338, 82/11/09, 8212090315

--B212090521 IE Insp Repts 50-338/82-36 & 50-339/82-36 on 821018-22 No noncompliance noted Major areas inspected GC & confirmatory measurements, including lab GC program, chemical & radiochemical procedures & airborne effluent sampling
EVANS, C D, MONTGOMERY, D M Division of Emergency Preparedness & Operational Support 82/11/08 9pp 16366 294 24X
Fiche 50-338, 82/11/09, 8212090515

DOCKETED ITEMS

B212090478 Act receipt of B21103 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-338/82-32 & 50-339/82-32
DANCE, H C Division of Project & Resident Programs 82/11/12
STEWART, W L Virginia Electric & Power Co 1p 16365 314 24X
Fiche 50-338, 82/11/12, B212090478

--B212090489 Responds to NRC B21005 ltr re violations noted in IE Insp Repts 50-338/82-32 & 50-339/82-32 Corrective actions chemistry periodic test for dose equivalent I-131 level revised to require deviation report if limit exceeded
STEWART, W L Virginia Electric & Power Co 82/11/03
O'REILLY, J P Region 2, Office of Director 3pp 16365 315 24X
Fiche 50-338, 82/11/12, B212090478

--B212090491 Forwards IE Insp Repts 50-338/82-32 & 50-339/82-32 on 820913-17 & notice of violation
DANCE, H C Division of Project & Resident Programs 82/10/05
LEASBURG, R H Virginia Electric & Power Co 2pp 16365 318 24X
Fiche 50-338, 82/11/12, B212090478

--B212090496 Notice of violation from insp on 820913-17
* Division of Project & Resident Programs 82/10/05 1p
16365 320 24X Fiche 50-338, 82/11/12, B212090478

--B212090505 IE Insp Repts 50-338/82-32 & 50-339/82-32 on 820913-17 Noncompliance noted failure to report reactor coolant dose equivalent I-131 level in excess of Tech Spec limit
HRAV, J R, BARR, K P Division of Engineering & Technical Programs 82/10/04 4pp 16365 321 24X Fiche 50-338, 82/11/12, B212090478

B2108190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18
Consolidated Edison Co. of New York, Inc 109pp 16411 199 24X
Fiche 50-000, 82/11/18, B208190251

B212090161 Confirms 821129 meeting w/util in Atlanta, GA to discuss results of investigation re causes of repeated main electrical output transformer failures Proposed agenda encl
O'REILLY, J P Region 2, Office of Director 82/11/24 STEWART, W L
Virginia Electric & Power Co 2pp 16359 098 24X
Fiche 50-338, 82/11/24, B212090161

B208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26
Consolidated Edison Co. of New York, Inc 127pp 16411 065 24X Fiche 50-000, 82/11/26, B208190256

B208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30
Consolidated Edison Co. of New York, Inc 356pp
16387 028 24X Fiche 50-000, 82/11/30, B208190257

B212070195 Forwards IE Safeguards Insp Repts 50-338/82-38 & 50-339/82-38 on B21108-10 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 82/12/02
STEWART, W L Virginia Electric & Power Co 2pp 16335 011 24X
Fiche 50-338, 82/12/02, B212070195

--B212070206 IE Safeguards Insp Repts 50-338/82-38 & 50-339/82-38 on B21108-10 No noncompliance noted Major areas inspected security plan & implementing procedures, organization, audit & power supply Details withheld (ref 10CFR73.21)
STANSBERRY, W W, MCQUIRE, D R Division of Engineering & Technical Programs 82/12/01 1p 16335 013 24X Fiche 50-338, 82/12/02, B212070195

B208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03
Consolidated Edison Co. of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, B208190259

B208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Solenoids " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03
Consolidated Edison Co. of New York, Inc 110pp 16462 064 24X
Fiche 50-000, 82/12/03, B208190261

B208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16
Consolidated Edison Co. of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16, B208190267

B208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type IYE-27 " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20
Consolidated Edison Co. of New York, Inc 108pp 16628 293 24X
Fiche 50-000, 82/12/20, B208190268

R Periodic operating reports & related correspondence

B212290317 Forwards monthly operating reports for Oct 1982
STEWART, W L Virginia Electric & Power Co 82/11/10 HALLER, N M
Office of Resource Management, Director 1p 16589 143 24X
Fiche 50-338, 82/11/10, B212290317

--B212290318 Monthly operating reports for Oct 1982
SCHMITENDORF, G Virginia Electric & Power Co 82/11/01 10pp
16589 144 24X Fiche 50-338, 82/11/10, B212290317

S Reportable occurrences, LERs & related correspondence

B212090102 Forwards LER 82-072/03L-0
CARTWRIGHT, W R Virginia Electric & Power Co 82/11/29
O'REILLY, J P Region 2, Office of Director 1p 16357 307 24X
Fiche 50-339, 82/11/29, B212090102

--B212090107 LER 82-072/03L-0 on 821105, blowdown trip valve TV-0D-200HC would not remain closed when manually closed Caused by closed position limit switch out of adjustment Limit switch can repositioned
CARTWRIGHT, W R Virginia Electric & Power Co 82/11/29 Region
2, Office of Director 1p 16357 308 24X Fiche 50-339, 82/11/29, B212090102

B212090067 Forwards LER 82-073/03L-0
CARTWRIGHT, W R Virginia Electric & Power Co 82/12/01
O'REILLY, J P Region 2, Office of Director 1p 16359 087 24X
Fiche 50-339, 82/12/01, B212090067

--B212090072 LER 82-073/03L-0 on 821108, channel A RCB subcooling monitor declared inoperable after erroneous readings observed Cause not determined Monitor reset & functioned properly
CARTWRIGHT, W R Virginia Electric & Power Co 82/12/01 Region
2, Office of Director 2pp 16359 088 24X Fiche 50-339, 82/12/01, B212090067

B212090272 Forwards updated LER 82-013/03X-1
CARTWRIGHT, W R Virginia Electric & Power Co 82/12/01
O'REILLY, J P Region 2, Office of Director 1p 16365 305 24X
Fiche 50-339, 82/12/01, B212090272

--B212090287 Updated LER 82-013/03X-1 on 820308, during periodic surveillance test, one diesel generator & one offsite power supply for emergency bus 2H became temporarily inoperable Caused by deficiency in procedure Periodic test changed
CARTWRIGHT, W R Virginia Electric & Power Co 82/12/01 Region
2, Office of Director 3pp 16365 306 24X Fiche 50-339, 82/12/01, B212090272

B212210254 Forwards LER 82-074/03L-0
CARTWRIGHT, W R Virginia Electric & Power Co 82/12/13
O'REILLY, J P Region 2, Office of Director 1p 16482 311 24X
Fiche 50-339, 82/12/13, B212210254

--B212210269 LER 82-074/03L-0 on 821122, during Mode 1, RPI for rod C-7 in shutdown bank A deviated from group demand position by greater than 12 steps w/no rod motion On 821123, similar event occurred on rod B-8 Caused by instrument drift
CARTWRIGHT, W R Virginia Electric & Power Co 82/12/13 Region
2, Office of Director 2pp 16483 312 24X Fiche 50-339, 82/12/13, B212210254

B212220387 Forwards LER 82-075/03L-0
CARTWRIGHT, W R Virginia Electric & Power Co 82/12/15
O'REILLY, J P Region 2, Office of Director 1p 16517 228 24X
Fiche 50-339, 82/12/15, B212220387

--B212220391 LER 82-075/03L-0 on 821123, delta flux momentarily exceeded 5% target band during performance of control rod operability periodic test Caused by movement of control rods into core 18 steps for control rod operability test
CARTWRIGHT, W R Virginia Electric & Power Co 82/12/15 Region
2, Office of Director 2pp 16517 229 24X Fiche 50-339, 82/12/15, B212220387

B212220392 Forwards LER 82-081/03L-0
CARTWRIGHT, W R Virginia Electric & Power Co 82/12/15
O'REILLY, J P Region 2, Office of Director 1p 16504 288 24X
Fiche 50-339, 82/12/15, B212220392

DOCKETED ITEMS

209

--B212220397 LER 82-081/03L-0 on B21206, breaker for MOV-SW-2010 discovered open Caused by inadvertent opening of circuit breaker perhaps due to narrow passage Breaker closed & valve control power verified
CARTWRIGHT, W R Virginia Electric & Power Co 82/12/15 Region
2, Office of Director 2pp 16504 289 24X Fiche 50-339, 82/12/15, B212220392

G212220364 Forwards LER 82-077/01T-0
CARTWRIGHT, W R Virginia Electric & Power Co 82/12/16
O'REILLY, J P Region 2, Office of Director 1p 16517 170 24X
Fiche 50-339, 82/12/16, B212220364

--B212220368 LER 82-077/01T-0 on B21206, monthly surveillance tests for power range channels discovered missing Caused by tests being inadvertently marked off by instrument supervisor
Tests completed satisfactorily
CARTWRIGHT, W R Virginia Electric & Power Co 82/12/16 Region
2, Office of Director 2pp 16517 171 24X Fiche 50-339, 82/12/16, B212220364

G212300237 Forwards LER 82-078/03L-0
CARTWRIGHT, W R Virginia Electric & Power Co 82/12/21
O'REILLY, J P Region 2, Office of Director 1p 16595 277 24X
Fiche 50-339, 82/12/21, B212300237

- B212300241 LER 82-078/03L-0 on B21209, during Mode 1, containment average air temp exceeded 105 F Caused by temp increase of chilled water to containment air recirculation cooling coils due to temporary inoperability of mechanical refrigeration unit
CARTWRIGHT, W R Virginia Electric & Power Co 82/12/21 Region
2, Office of Director 2pp 16595 278 24X Fiche 50-339, 82/12/21, B212300237

G212300099 Forwards LER 82-079/03L-0
CARTWRIGHT, W R Virginia Electric & Power Co 82/12/22
O'REILLY, J P Region 2, Office of Director 1p 16598 229 24X
Fiche 50-339, 82/12/22, B212300099

- B212300104 LER 82-079/03L-0 on B21206, axial flux difference went less than 5% from target band for duration of 2 minutes Caused by personnel error during power increase from 30% to 60% Rods withdrawn & difference restored to within limits
CARTWRIGHT, W R Virginia Electric & Power Co 82/12/22 Region
2, Office of Director 1p 16598 230 24X Fiche 50-339, 82/12/22, B212300099

G212300251 Forwards LER 82-080/03L-0
CARTWRIGHT, W R Virginia Electric & Power Co 82/12/22
O'REILLY, J P Region 2, Office of Director 1p 16595 263 24X
Fiche 50-339, 82/12/22, B212300251

--B212300255 LER 82-080/03L-0 on B21206, during Mode 1, individual RPI for rod H-02 in control bank D deviated from group demand position by greater than 12 steps w/no rod motion Caused by instrument drift RPI channel recalibr & returned to svc
CARTWRIGHT, W R Virginia Electric & Power Co 82/12/22 Region
2, Office of Director 2pp 16595 264 24X Fiche 50-339, 82/12/22, B212300251

G212300286 Forwards LER 82-082/03L-0
CARTWRIGHT, W R Virginia Electric & Power Co 82/12/22
O'REILLY, J P Region 2, Office of Director 1p 16594 220 24X
Fiche 50-339, 82/12/22, B212300286

--B212300291 LER 82-082/03L-0 on B21213, fire door 871-1B between RH emergency diesel generator room & turbine bldg failed to latch & lock Caused by latch sticking Latch adjusted & lubricated Design mods pursued
CARTWRIGHT, W R Virginia Electric & Power Co 82/12/22 Region
2, Office of Director 1p 16594 221 24X Fiche 50-339, 82/12/22, B212300286

DOCKET 50-341 ENRICO FERMI ATOMIC POWER PLANT, UNIT 2

A Application/construction stage documents & correspondence

G21230046 Generic Ltr 82-27 to all BWR licensees of operating reactors except LACBWR, Big Rock Point, Dresden 1, Humboldt Bay, applicants for OL & holders of CP re transmittal of NUREG-0763 & NUREG-0783 Svc list encl W/o stated encl
EISENHUT, D O Division of Licensing 82/11/15 General Public
Utilities - OPU Service Corp 2pp 16387 004 24X
Fiche 50-000, 82/11/15, B21230046

G212010147 Forwards Amend 45 to amended & substituted application for OL, consisting of Amend 45 to FSAR
LANDORAF, L C LeBoeuf, Lamb, Leiby & MacRae 82/11/30, DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 16258 203
24X Fiche 50-341, 82/11/30, B212010147

-B212010156 Amend 45 to amended & substituted application for OL, consisting of Amend 45 to FSAR
HEIDEL, C M Detroit Edison Co 82/11/24 1p 16258 204 24X
Fiche 50-341, 82/11/30, B212010147

BP12170042 Forwards Amend 2 to CPPR-B7, safety evaluation & notice of issuance & availability Amend reflects merger of MI Electric Cooperative, Inc into Wolverine Electric Cooperative, Inc
EISENHUT, D O Division of Licensing 82/12/01 TAUBER, H Detroit Edison Co 3pp 16478 013 24X Fiche 50-341, 82/12/01, B212170042

--B212170057 Amend 2 to CPPR-B7, reflecting merger of MI Electric Cooperative, Inc into Wolverine Electric Cooperative, Inc
EISENHUT, D O Division of Licensing 82/12/01 2pp 16478 016 24X Fiche 50-341, 82/12/01, B212170042

--B212170076 Safety evaluation supporting Amend 2 to CPPR-B7
* Office of Nuclear Reactor Regulation, Director 82/11/26 2pp 16478 018 24X Fiche 50-341, 82/12/01, B212170042

--B212170084 Notice of issuance & availability of Amend 2 to CPPR-B7
YOUNGBLOOD, B J Licensing Branch 1 82/11/26 3pp 16478 020 24X Fiche 50-341, 82/12/01, B212170042

BP12100267 Submits table clarifying reactor bldg basemat capacity for torus uplift, per B21118 telcon Listed basemat capacity max for torus uplift after subtraction for hydrostatic & normal foundation loads W/o stated encl
TAUBER, H Detroit Edison Co 82/12/03 KINTNER, L L Division of Licensing 1p 16376 145 24X Fiche 50-341, 82/12/03, B212100267

BP12100166 Forwards approved scope of independent design verification program, per B21029 request Cygna Energy Svcs program plan for independent design verification will be submitted on or before B21215 Approval of plan requested by B21222
TAUBER, H Detroit Edison Co 82/12/07 EISENHUT, D O Division of Licensing 1pp 16373 333 24X Fiche 50-341, 82/12/07, B212100166

B212130303 Forwards Certificate of Svc certifying distribution of Amend 45 to OL application to listed officials & agencies on B21206
MATTERS, B R Detroit Edison Co 82/12/09 Office of Nuclear Reactor Regulation, Director 3pp 16389 324 24X
Fiche 50-341, 82/12/09, B212130303

G212270046 Summary of B21118 meeting w/util & NUS re environ qualification of safety-related electrical equipment
KINTNER, L L Licensing Branch 1 82/12/13 Licensing Branch 1 18pp 16553 182 24X Fiche 50-341, 82/12/13, B212270046

G212300311 Forwards "Independent Design Verification Program," per B21207 ltr Meeting w/Cygna, util & NRC scheduled for B21220
TAUBER, H Detroit Edison Co 82/12/14 EISENHUT, D O Division of Licensing 1p 16594 308 24X Fiche 50-341, 82/12/14, B212300311

- B212300312 "Independent Design Verification Program"
* Cygna Energy Services 82/12/14 11pp 16594 309 24X
Fiche 50-341, 82/12/14, B212300311

BP12290510 Summary of B21201 meeting w/util re independent design verification program Util proposed verification of design of NHR sys. including svc water Schedule acceptable Visigraphs encl
KINTNER, L L Licensing Branch 1 82/12/15 Licensing Branch 1 18pp 16593 327 24X Fiche 50-341, 82/12/15, B212290510

BP12270031 Trip rept of B20824-26 caseload forecast panel site visit re observation of status of const & util basis for currently scheduled completion date
KINTNER, L L Licensing Branch 1 82/12/16 Licensing Branch 1 17pp 16553 165 24X Fiche 50-341, 82/12/16, B212270031

E NRC Safety Evaluation Report (SER), supp's & correspondence

BP12090061 Discusses B20115 ltr re channel box deflection concern Previous commitment indicated in SER Suppl 2 will be modified to adopt Licensing Review Group II position w/ simpler method of friction testing Details encl
TAUBER, H Detroit Edison Co 82/12/03 KINTNER, L L Division of Licensing 3pp 16357 352 24X Fiche 50-341, 82/12/03, B212090061

F Security, medical, emergency & fire protection plans

B212220460 Informs that no changes to comments for individual emergency action levels under each emergency classification required Both sets of emergency action levels identical
MARTIN, J B Battelle Memorial Institute, Pacific Northwest Laboratory 82/11/08 KANTOR, F Emergency Preparedness Licensing Br (after B01119 see 1&E) 1p 16804 237 24X
Fiche 50-341, 82/11/08, B212220460

DOCKETED ITEMS

B210150165 Forwards review of emergency action levels for Enrico Fermi nuclear power station
MARTIN, J B Battelle Memorial Institute, Pacific Northwest Laboratory 82/10/05 PAGANO, F G EP Licensing Branch 15pp 16534 238 24X Fiche 50-341, 82/11/08, 821220460

B212140375 Forwards info re emergency operations facilities (EOF), per LL Kintner 821202 request Const of permanent primary EOF complete
TAUBER, H Detroit Edison Co 82/12/06 YOUNGLOOD, B J Licensing Branch 1 2pp 16401 008 24X Fiche 50-341, 82/12/06, 8212140375

B212220306 Discusses layout of communications equipment required in control room, onsite technical support ctr & near-site emergency operations facility
KEPPLER, J G Region 3, Office of Director 82/12/16 Commonwealth Edison Co 3pp 16503 351 24X Fiche 50-000, 82/12/14, 821220306

G Adjudicatory correspondence

B212020353 Appeals portion of ASLB 821029 initial decision denying Monroe County, MI 820827 petition to intervene Appeal made under 10CFR2 714(a), since extent of County appeal rights per 10CFR2 762 unclear
WESTOVER, A T Monroe County, MI 82/11/08 Atomic Safety and Licensing Board Panel 3pp 16278 010 24X Fiche 50-341, 82/11/08, 8212020353

B212010191 Disagrees w/NRC decision to treat Monroe County, MI 821108 ltr as appeal under 10CFR2 714a rather than under 2 762 NRC does not have authority to decide issues for ASLB
MINOCK, J R Minock, J MINOCK, J R Citizens for Energy & Employment 82/11/26 EILPERIN, S, MOORE, T S, GOTCHY, R L Atomic Safety and Licensing Appeal Panel 2pp 16258 109 24X Fiche 50-341, 82/11/26, 8212010191

B212010207 Order directing D Howell & persons from Citizens for Employment & Energy who dealt w/Howell to file affidavits on organization representation Affidavits due 821210 Time for util & NRC responses to show cause order extended
SHOEMAKER, C J Atomic Safety and Licensing Appeal Panel 82/11/30 Citizens for Energy & Employment 2pp 16258 001 24X Fiche 50-341, 82/11/30, 8212010207

B212010216 Order granting Citizens for Employment & Energy 10 days after issuance of order to file brief supporting Monroe County, MI intervention appeal Monroe County request for extension of time to file exceptions denied
SHOEMAKER, C J Atomic Safety and Licensing Appeal Panel 82/11/30 3pp 16258 009 24X Fiche 50-341, 82/11/30, 8212010216

B212070234 Erratum to ASLB 821029 initial decision Name of Voigt should be changed to Voigt in cover page list of appearances & in Line 8 of Paragraph 80
MICHOELLIN, O L Atomic Safety and Licensing Board Panel 82/12/03 1p 16329 320 24X Fiche 50-341, 82/12/03, 8212070234

B212140377 Affidavit of DE Howell re employment by & representation of Citizens for Employment & Energy Decision not to file proposed findings of fact & conclusions of law made jointly w/KA Siegfried Certificate of Svc encl
HOWELL, D E Citizens for Energy & Employment 82/12/08 6pp 16401 306 24X Fiche 50-341, 82/12/08, 8212140377

B212140460 Affidavit of KA Siegfried D Howell had full authority from Affiant & Citizens for Employment & Energy to make decisions re legal representation of organization
SIEGFRIED, K A Citizens for Energy & Employment 82/12/08 1p 16405 030 24X Fiche 50-341, 82/12/08, 8212140460

B212140428 Response supporting Monroe County, MI appeal of ASLB 821029 memorandum & order denying County petition to intervene Good cause shown No other means of protecting County interest exists Certificate of Svc encl
MINOCK, J R Citizens for Energy & Employment MINOCK, J R Minock, J 82/12/10 Atomic Safety and Licensing Appeal Panel 12pp 16405 198 24X Fiche 50-341, 82/12/10, 8212140428

B212230211 Order rendering ASLB 821029 decision authorizing NRR to issue QL effective Full power license will not be issued until remaining uncontested issues resolved
CHILK, S J Office of the Secretary of the Commission 82/12/20 2pp 16511 030 24X Fiche 50-341, 82/12/20, 8212230211

B212230355 Response in opposition to Citizens for Employment & Energy response to ASLB 821122 order to show cause why appeal from 821029 initial decision should not be summarily dismissed for failure to file proposed findings w/certificate of Svc
VOIGT, H E Detroit Edison Co 82/12/22 Atomic Safety and Licensing Appeal Panel 9pp 16511 152 24X Fiche 50-341, 82/12/22, 8212230355

B212280139 Response in opposition to Citizens for Employment & Energy (CEE) 821121 answer to ASLB 821112 order to show cause why CEE 821108 appeal to ASLB 821027 order should not be dismissed Certificate of Svc encl
WOODHEAD, C P Hearing Branch 1 82/12/23 Atomic Safety and Licensing Appeal Panel 12pp 16563 191 24X Fiche 50-341, 82/12/23, 8212280139

B212280151 Forwards ALAB-707, denying Monroe County, MI intervention petition & requiring NRR Director to consider petition as request for action under 10CFR2 206
WOODHEAD, C P Hearing Branch 1 82/12/27 PERRY, B Federal Emergency Management Agency 1p 16564 019 24X Fiche 50-341, 82/12/27, 8212280151

--8212280156 Decision ALAB-707, denying Monroe County, MI intervention petition & requiring NRR Director to consider petition as request for action under 10CFR2 206
SHOEMAKER, C J Atomic Safety and Licensing Appeal Panel 82/12/21 15pp 16564 020 24X Fiche 50-341, 82/12/27, 8212280151

K Utility Final Safety Analysis Report (FSAR) & amends

B212010147 Forwards Amend 45 to amended & substituted application for DL, consisting of Amend 45 to FSAR
LANDGRAF, L C LeBoeuf, Lamb, Leiby & MacRae 82/11/30 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 16258 203 24X Fiche 50-341, 82/11/30, 8212010147

--8212010156 Amend 45 to amended & substituted application for DL, consisting of Amend 45 to FSAR
HEIDEL, C M Detroit Edison Co 82/11/24 1p 16258 204 24X Fiche 50-341, 82/11/30, 8212010147

--8212010163 Amend 45 to FSAR
* Detroit Edison Co 82/11/30 408pp 16258 205 24X Fiche 50-341, 82/11/30, 8212010147

Q Inspection reports, IE Bulletins & correspondence

B208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel Recirculation Sys Piping at BWR Plants " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240

B208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model B01 & Model B02 Thermoluminescent Dosimeters " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000, 82/11/05, 8208190245

B208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X Fiche 50-000, 82/11/18, 8208190251

B212100198 Forwards IE Insp Rept 50-341/82-18 on 820901-1031 No noncompliance noted
KNOP, R C Division of Project & Resident Programs 82/11/24 WELLS, D A Detroit Edison Co 2pp 16376 204 24X Fiche 50-341, 82/11/24, 8212100198

--8212100203 IE Insp Rept 50-341/82-18 on 820901-1031 No noncompliance noted Major areas inspected licensee action on previous items, electrical conduit installation & insp activities, NRC/licensee mgt meeting, DL issuance & site visits
LITTLE, B H, BYRON, P M, KONKLIN, J E Division of Project & Resident Programs 82/11/22 6pp 16376 206 24X Fiche 50-341, 82/11/24, 8212100198

B208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000, 82/11/26, 8208190256

B208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000, 82/11/30, 8208190257

B208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259

DOCKETED ITEMS

211

8208190241 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03
Consolidated Edison Co of New York, Inc 110pp 16462 064 24X
Fiche 50-000, 82/12/03, 8208190241

8212170244 Forwards IE Insp Rept 50-341/82-14 on 820908-10 & notice of violation
LITTLE, H S Division of Engineering & Technical Programs 82/12/03
NELLS, D A Detroit Edison Co 2pp 16459 205 24X
Fiche 50-341, 82/12/03, 8212170244

- 8212170247 Notice of violation from insp on 820908-10
LITTLE, H S Division of Engineering & Technical Programs
82/12/03 4pp 16459 207 24X Fiche 50-341, 82/12/03, 8212170244

--8212170253 IE Insp Rept 50-341/82-14 on 820908-10 Noncompliance noted failure to follow procedures, establish & use deviation disposition requests & to take corrective actions
NAIDOU, K R, LITTLE, B H, WILLIAMS, C C Division of Engineering & Technical Programs 82/10/25 7pp 16459 211 24X
Fiche 50-341, 82/12/03, 8212170244

8212170105 Confirmatory action itr re deficiencies identified during review of large bore hangers previously installed & accepted by GC site contractors, per 821210 telcon Independent engineering organization will evaluate all deficiencies
NORELIUS, C E Division of Engineering & Technical Programs 82/12/10
NELLS, D A Detroit Edison Co 2pp 16452 334 24X
Fiche 50-341, 82/12/10, 8212170105

8212230309 Notifies that listed drawings have been sent to G Hammer of Mechanical Engineering Branch & T Cook of EG&G to support review of inservice insp program for pumps & valves
LUSIS, E Detroit Edison Co 82/12/15 LYNCH, D Office of Nuclear Reactor Regulation, Director 1p 16511 124 24X
Fiche 50-341, 82/12/15, 8212230309

8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
DEVOUNO, R C Director's Office, Office of Inspection and Enforcement 82/12/16
Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16, 8208190267

8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITC-27 " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20
Consolidated Edison Co of New York, Inc 108pp 16628 273 24X
Fiche 50-000, 82/12/20, 8208190268

9 Reportable occurrences, LERs & related correspondence

8212210443 Interim Deficiency Rept 74 re sway strut paddle clamped rigid Initially reported on 820702 Training session conducted for GC & craft supervisory personnel revised Next rept will be sent by 830324
NELLS, D A Detroit Edison Co 82/11/24 KEPLER, J O Region 3, Office of Director 2pp 16489 200 24X Fiche 50-341, 82/11/24, 8212210443

8212270359 Interim deficiency rept re frozen reactor mode switch 73 & failure of contacts to maintain position during operation Initially reported on 820701 Switch modified. Qualification work for switch handle in progress Next rept due by 830324
NELLS, D A Detroit Edison Co 82/11/24 KEPLER, J O Region 3, Office of Director 2pp 16530 008 24X Fiche 50-341, 82/11/24, 8212270359

8212270362 Interim deficiency rept re linear indications noted on Class I 5/8-inch stainless steel tee 50 fittings w/heat numbers 19 F & 43 F Initially reported on 820210 Tees removed & replaced Next rept will be submitted by 830325
NELLS, D A Detroit Edison Co 82/11/24 KEPLER, J O Region 3, Office of Director 2pp 16530 010 24X Fiche 50-341, 82/11/24, 8212270362

DOCKET 50-344 TROJAN NUCLEAR PLANT

F. Security, medical, emergency & fire protection plans

8212140280 Forwards 1982 radiological emergency plan exercise objectives & limitations
BRODEH, D J Portland General Electric Co 82/10/20 GRIMES, D K Division of Emergency Preparedness 4pp 16402 098 24X
Fiche 50-344, 82/10/20, 8212140280

8212060384 Forwards IE Insp Rept 50-344/82-30 on 821004-29 No noncompliance noted.
STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 82/11/15 WITHERS, B D Portland General Electric Co 4pp 16311 070 24X Fiche 50-344, 82/11/15, 8212060384

--8212060391 IE Insp Rept 50-344/82-30 on 821004-29 No noncompliance noted Major areas inspected plant operations, surveillance testing, maint, security, environ monitoring & followup on LERs
MALMROS, M H, DDDOS, R T Division or Resident, Reactor Project & Engineering Programs 82/11/12 5pp 16311 074 24X
Fiche 50-344, 82/11/15, 8212060384

8212140349 Requests NRC determination that records storage vault in technical support ctr may be used as security storage container for safeguards info documents
CULP, O H Portland General Electric Co 82/11/19 KASUN, D J Physical Security Licensing Branch 6pp 16401 026 24X
Fiche 50-344, 82/11/19, 8212140349

8212210180 Forwards IE Emergency Preparedness Appraisal Rept 50-344/82-06 on 820222-0304 No noncompliance noted List of areas needing improvement encl
ENDELKE, R H Region 5, Office of Director 82/12/02 WITHERS, B D Portland General Electric Co 3pp 16485 032 24X
Fiche 50-344, 82/12/02, 8212210180

--8212210185 IE Emergency Preparedness Appraisal Rept 50-344/82-06 on 820222-0304 No noncompliance noted Major areas inspected administration of emergency preparedness, emergency organization, training & retraining facilities & equipment
FISH, R F, SCKNN, K, HANCHETT, J O Division of Radiological Safety & Safeguards Program 82/11/30 39pp 16485 035 24X
Fiche 50-344, 82/12/02, 8212210180

8212100399 Releases public version of revised emergency plan implementing procedures
ELTON, J M Division of Rules and Records 82/12/07 Document Management Branch 1p 16389 197 24X Fiche 50-344, 82/12/07, 8212100399

--8212100406 Forwards public version of revised emergency plan implementing procedures, including Procedures EP-19 2 re operation of dedicated telephone sys & EP-29 1 re instructions for use of computer terminal
PUZEY, A M Portland General Electric Co 82/11/23 CLARK, R A Office of Nuclear Reactor Regulation, Director 2pp 16389 198 24X Fiche 50-344, 82/12/07, 8212100399

--8212100411 Public version of revised emergency plan implementing procedures, including Procedures EP-19 2 re operation of dedicated telephone sys & EP-29 1 re instructions for use of computer terminal
YUHOT, C P Portland General Electric Co 82/11/18 20pp 16389 200 24X Fiche 50-344, 82/12/07, 8212100399

8212170304 Forwards IE Safeguards Insp Rept 50-344/82-31 on 821129-1203 No noncompliance noted Rept withheld (ref 10CFR73 21)
NORDERHAUG, L R Division of Radiological Safety & Safeguards Program 82/12/09 WITHERS, B D Portland General Electric Co 2pp 16456 129 24X Fiche 50-344, 82/12/09, 8212170304

8212210201 Forwards replacement Page 5-6a to security plan Section 5 2 1 2 1 Page withheld (ref 10CFR73 21)
WITHERS, B D Portland General Electric Co 82/12/13 CLARK, R A Operating Reactors Branch 3 1p 16484 337 24X
Fiche 50-344, 82/12/13, 8212210201

8212270483 Forwards exemption from requirements of 10CFR50 4B & App R of 10CFR50 re fire protection for equipment important to safe shutdown & emergency lighting Safety evaluation supporting exemption encl
CLARK, R A Operating Reactors Branch 3 82/12/14 WITHERS, B D Portland General Electric Co 4pp 16549 305 24X
Fiche 50-344, 82/12/14, 8212270483

--8212270486 Exemption from requirements of 10CFR50 4B & App R of 10CFR50 re fire protection for equipment important to safe shutdown & emergency lighting
EISENHUT, D O Division of Licensing 82/12/14 Portland General Electric Co 13pp 16549 309 24X Fiche 50-344, 82/12/14, 8212270483

--8212270488 Safety evaluation supporting exemption from 10CFR50, App R requirements
* Office of Nuclear Reactor Regulation, Director 82/12/14 21pp 16549 322 24X Fiche 50-344, 82/12/14, 8212270483

--8206100047 Discusses request for exemption from requirements of Section III C 2 of App R to 10CFR50 re intake structure, fuel bldg, auxiliary bldg, turbine bldg & cable penetration area outside containment
COHN, B M Gage-Babcock Associates, Inc 81/11/20 BENARDYA, V Chemical Engineering Branch, 10pp 16549 343 24X
Fiche 50-344, 82/12/14, 8212270483

DOCKETED ITEMS

P Operating license stage documents & correspondence

G12030027 Forwards completed steam generator questionnaire, per B21026 request Outages, solely for steam generator-related maint, occurred in 1977 & 1981 Remaining maint performed during scheduled refueling outages
WITHERS, B D Portland General Electric Co 82/11/24 EISENHUT, D O Division of Licensing 4pp 16304 334 24X Fiche 50-344, 82/11/24, 8212030027

G12070316 Forwards "Trojan Nuclear Plant Cycle 5 Startup & Power Escalation Physics Testing Rept"
WITHERS, B D Portland General Electric Co 82/11/30 ENGELKEN, R H Region 5, Office of Director 1p 16337 074 24X Fiche 50-344, 82/11/30, 8212070316

--B212070319 "Trojan Nuclear Plant Cycle 5 Startup & Power Escalation Physics Testing Rept"
* Portland General Electric Co PGE-1035 82/11/30 58pp 16337 075 24X Fiche 50-344, 82/11/30, 8212070316

G12100044 Forwards addl info requested on 821007 re inservice testing relief requests for pumps & valves
WITHERS, B D Portland General Electric Co 82/12/03 CLARK, R A Operating Reactors Branch 3 21pp 16379 050 24X Fiche 50-344, 82/12/03, 8212100044

G12130366 Forwards Amend 7B to License NPF-1, safety & technical evaluations & notice of issuance & availability Amend adds operability & surveillance requirements for reactor coolant overpressure mitigation sys
CLARK, R A Operating Reactors Branch 3 82/12/06 WITHERS, B D Portland General Electric Co 3pp 16412 102 24X Fiche 50-344, 82/12/06, 8212130366

--B212130367 Amend 7B to License NPF-1, adding operability & surveillance requirements for reactor coolant overpressure mitigation sys
CLARK, R A Operating Reactors Branch 3 82/12/06 17pp 16412 105 24X Fiche 50-344, 82/12/06, 8212130366

--B212130369 Safety evaluation supporting Amend 7B to License NPF-1
* Office of Nuclear Reactor Regulation, Director 82/12/06 12pp 16412 122 24X Fiche 50-344, 82/12/06, 8212130366

--B212130370 "Technical Evaluation of Electrical Instrumentation & Control Design Aspects of Low Temp Overpressure Protection Sys for Trojan Nuclear Power Plant"
LATORRE, V R, VICTOR, R A Lawrence Livermore Laboratory FIN A-0231 UCID-18670 80/06/30 NRC - No Detailed Affiliation Given 26pp 16412 134 24X Fiche 50-344, 82/12/06, 8212130366

--B212130372 Notice of issuance & availability of Amend 7B to License NPF-1
CLARK, R A Operating Reactors Branch 3 82/12/06 2pp 16412 159 24X Fiche 50-344, 82/12/06, 8212130366

G1208190263 Generic Ltr 82-32 to all PWR licensees re potential steam generator-related generic requirements Forwards Science Applications, Inc draft rept re suby requirements Comments requested within 30 days of ltr Svc list encl
EISENHUT, D O Division of Licensing 82/12/09 Consolidated Edison Co of New York, Inc 29pp 16629 247 24X Fiche 50-000, 82/12/09, 8208190263

G12140103 Generic Ltr 82-28 to all licensees of operating Westinghouse & C-E PWRs (except Arkansas Nuclear One, Unit 2 & San Onofre 2 & 3) re inadequate core cooling instrumentation sys Svc list encl
EISENHUT, D O Division of Licensing 82/12/10 Yankee Atomic Electric Co 27pp 16690 035 24X Fiche 50-000, 82/12/10, 8212140103

G12280283 Forwards exceptions taken to NUREG-0737 requirements re containment pressure monitors, water level monitors & hydrogen monitors, in response to B21112 request for addl info
WITHERS, B D Portland General Electric Co 82/12/17 CLARK, R A Operating Reactors Branch 3 15pp 16361 312 24X Fiche 50-344, 82/12/17, 8212280283

B212280410 Forwards SER & technical evaluation repts supporting environ qualification of safety-related equipment Plans for qualification or replacement of equipment in Categories I B, II A & II B should be submitted in 90 days
CLARK, R A Operating Reactors Branch 3 82/12/17 WITHERS, B D Portland General Electric Co 3pp 16574 001 24X Fiche 50-344, 82/12/17, 8212280410

--B212280419 SER supporting environ qualification of safety-related electrical equipment
* Office of Nuclear Reactor Regulation, Director 82/12/17 5pp 16574 004 24X Fiche 50-344, 82/12/17, 8212280410

--B210250187 "Review of Licensees Resolution of Outstanding Issues From NRC Equipment Environ Qualification SERs (F-11 & B-60), Trojan Nuclear Plant," final technical evaluation rept
Proprietary info deleted
PANDEY, S Franklin Institute/Franklin Research Center NRC-03-79-110 TER-CS257-485 82/10/19 LE, N B NRC - No Detailed Affiliation Given 35pp 16574 009 24X Fiche 50-344, 82/12/17, 8212280410

B212280470 Forwards info re NUREG-0737, Items II D 3, "Post-Accident Sampling Capability" & III D 3 4, "Control Room Habitability," in response to NRC 820630 request W/seven oversize drawings Aperture cards are available in PDR
WITHERS, B D Portland General Electric Co 82/12/17 EISENHUT, D O Division of Licensing 25pp 16556 071 24X Fiche 50-344, 82/12/17, 8212280470

B21270368 Forwards responses to NUREG-0737, Items II E 4 2 7, II K 2 10, II K 3 3, II K 3 12 & I A 1 3, per Generic Ltr 82-16 No addl Tech Specs requested
WITHERS, B D Portland General Electric Co 82/12/21 EISENHUT, D O Division of Licensing 3pp 16530 046 24X Fiche 50-344, 82/12/21, 821270368

Q Inspection reports, IE Bulletins & correspondence

B108190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants" Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240

B108190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters" Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000, 82/11/05, 8208190245

B12060384 Forwards IE Insp Rept 50-344/82-30 on 821004-29 No noncompliance noted
STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 82/11/15 WITHERS, B D Portland General Electric Co 4pp 16311 070 24X Fiche 50-344, 82/11/15, 8212060384

--B212060391 IE Insp Rept 50-344/82-30 on 821004-29 No noncompliance noted Major areas inspected plant operations, surveillance testing, maint, security, environ monitoring & followup on LERS
MALHROS, H H, DODDS, R T Division of Resident, Reactor Project & Engineering Programs 82/11/12 3pp 16311 074 24X Fiche 50-344, 82/11/15, 8212060384

B108190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements" Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X Fiche 50-000, 82/11/18, 8208190251

B208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks" Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000, 82/11/26, 8208190256

B108190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl" Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000, 82/11/30, 8208190257

B212210180 Forwards IE Emergency Preparedness Appraisal Rept 50-344/82-06 on 820222-0304 No noncompliance noted List of areas needing improvement encl
ENGELKEN, R H Region 5, Office of Director 82/12/02 WITHERS, B D Portland General Electric Co 3pp 16485 032 24X Fiche 50-344, 82/12/02, 8212210180

--B212210185 IE Emergency Preparedness Appraisal Rept 50-344/82-06 on 820222-0304 No noncompliance noted Major areas inspected, administration of emergency preparedness, emergency organization, training & retraining facilities & equipment
FISH, R F, SCOWEN, K, HANCHETT, J O Division of Radiological Safety & Safeguards Program 82/11/30 39pp 16485 035 24X Fiche 50-344, 82/12/02, 8212210180

8208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies" Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259

8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets" Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X Fiche 50-000, 82/12/03, 8208190261

8212170304 Forwards IE Safeguards Insp Rept 50-344/82-31 on 821129-1203 No noncompliance noted Rept withheld (ref 10CFR73 21)
NORDERHAUG, L R Division of Radiological Safety & Safeguards Program 82/12/09 WITHERS, B D Portland General Electric Co 2pp 16456 129 24X Fiche 50-344, 82/12/09, 8212170304

8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring" Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16, 8208190267

8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27" Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X Fiche 50-000, 82/12/20, 8208190268

R Periodic operating reports & related correspondence

8212070343 Forwards monthly operating rept for Jul 1982
YUNDT, C P Portland General Electric Co 82/08/05 Office of Management and Program Analysis 1p 16343 199 24X Fiche 50-344, 82/08/05, 8212070343

--8212070346 Monthly operating rept for Jul 1982
NICHOLSON, W D Portland General Electric Co 82/08/04 4pp 16343 200 24X Fiche 50-344, 82/08/05, 8212070343

8212290201 Forwards monthly operating rept for Oct 1982
YUNDT, C P Portland General Electric Co 82/11/03 Office of Resource Management, Director 1p 16578 185 24X Fiche 50-344, 82/11/03, 8212290201

--8212290204 Monthly operating rept for Oct 1982
NICHOLSON, W D Portland General Electric Co 82/11/03 4pp 16578 186 24X Fiche 50-344, 82/11/03, 8212290201

S Reportable occurrences, LERs & related correspondence

8212030011 Forwards LER 82-020/03L-0 Detailed event analysis encl
YUNDT, C P, STEELE, R L Portland General Electric Co 82/11/10 ENGELKEN, R H Region 5, Office of Director 3pp 16304 234 24X Fiche 50-344, 82/11/10, 8212030011

--8212030017 LER 82-020/03L-0 on 821013, manual filter inlet damper on train A control room emergency ventilation sys found closed, isolating fan VC-142A suction path from control room Caused by loose setscrew Improved attachment method implemented
BAIR, G O Portland General Electric Co 82/11/10 Region 5, Office of Director 1p 16304 237 24X Fiche 50-344, 82/11/10, 8212030011

8212140346 Forwards LER 82-021/03L-0 Detailed event analysis encl
YUNDT, C P Portland General Electric Co 82/11/30 ENGELKEN, R H Region 5, Office of Director 3pp 16401 021 24X Fiche 50-344, 82/11/30, 8212140346

--8212140355 LER 82-021/03L-0 on 821101, pressurizer level transmitter LT-461 found out of calibr Setpoint for high pressurizer level reactor trip exceeded max value Caused by setpoint drift Instrument recalibr & returned to svc
BAIR, G O Portland General Electric Co 82/11/30 Region 5, Office of Director 1p 16401 024 24X Fiche 50-344, 82/11/30, 8212140346

8212280421 PNS-V-82-005 on 821217, bomb threat received from unidentified male Plant search yielded negative results
SCHWAB, C A, SCHUSTER, M D Region 5, Office of Director 82/12/17 1p 16560 028 24X Fiche 50-344, 82/12/17, 8212280421

8212280190 Forwards response to request for addl info re resolution of LER 79-15, per 820929-30 meeting in San Francisco, CA w/util & Bachtel Need for addl tornado missile barrier at fuel bldg eliminated Meeting agenda encl
WITHERS, B D Portland General Electric Co 82/12/22 CLARK, R A Operating Reactors Branch 3 7pp 16562 296 24X Fiche 50-344, 82/12/22, 8212280190

DOCKET 50-346 DAVIS-BESSE NUCLEAR POWER STATION, UNIT 1

F Security, medical, emergency & fire protection plans

8212020270 Notifies that alternate dedicated svc water sys will be installed within 30 months of NRC 820602 acceptance date, per 10CFR50 48(c)(4)
CROUSE, R P Toledo Edison Co 82/11/23 STOLZ, J F Operating Reactors Branch 4 1p 16279 353 24X Fiche 50-346, 82/11/23, 8212020270

8212080643 Forwards safety evaluation & notice of exemption from certain technical requirements of App R to 10CFR50, per util 820429 request
EISENHUT, D G Division of Licensing 82/11/23 CROUSE, R P Toledo Edison Co 4pp 16372 352 24X Fiche 50-346, 82/11/23, 8212080643

--8212080649 Safety evaluation supporting exemption from certain requirements of App R to 10CFR50
* Office of Nuclear Reactor Regulation, Director 82/11/23 5pp 16372 356 24X Fiche 50-346, 82/11/23, 8212080643

--8212080652 Notice of exemption from certain requirements of App R to 10CFR50
STOLZ, J F Operating Reactors Branch 4 82/11/23 2pp 16372 361 24X Fiche 50-346, 82/11/23, 8212080643

8212100255 Forwards IE Insp Rept 50-346/82-31 on 821003-30 & notice of violation
BPESSARD, R L Division of Project & Resident Programs 82/11/26 CROUSE, R P Toledo Edison Co 2pp 16376 159 24X Fiche 50-346, 82/11/26, 8212100255

- 8212100257 Notice of violation from insp on 821003-30
BPESSARD, R L Division of Project & Resident Programs 82/11/26 1p 16376 161 24X Fiche 50-346, 82/11/26, 8212100255

--8212100263 IE Insp Rept 50-346/82-31 on 821003-30 Noncompliance noted repair of buried fire piping accomplished w/inadequate procedures, as requirement for restoring backfill to original spec omitted
PEEBLES, T A, ROGERS, W O, BYRON, P M Division of Project & Resident Programs 82/11/24 8pp 16376 162 24X Fiche 50-346, 82/11/26, 8212100255

8212060074 Forwards IE Safeguards Insp Rept 50-346/82-30 on 821025-29 & notice of violation Notice of violation & rept details withheld (ref 10CFR73 21)
NORELIUS, C E Division of Engineering & Technical Programs 82/11/29 CROUSE, R P Toledo Edison Co 2pp 16314 358 24X Fiche 50-346, 82/11/29, 8212060074

--8212060080 IE Safeguards Insp Rept 50-346/82-30 on 821025-29 Noncompliance noted security organization mgt, personnel & response, records & repts, testing & maint & physical barriers Details withheld (ref 10CFR73 21)
PIRTLE, Q L, KNICELEY, J R, CREED, J R Region 3, Office of Director 82/11/23 2pp 16314 360 24X Fiche 50-346, 82/11/29, 8212060074

8212130132 Releases public version of list of effective pages to emergency plan manual
FELTON, J M Division of Rules and Records 82/12/03 Document Management Branch 1p 16410 325 24X Fiche 50-346, 82/12/03, 8212130132

--8212130137 Forwards public version of list of effective pages to emergency plan manual & Figure 5-2 re facility organization
* Toledo Edison Co 82/10/06 Office of Nuclear Reactor Regulation, Director 1p 16410 327 24X Fiche 50-346, 82/12/03, 8212130132

--8212130144 Public version of list of effective pages to emergency plan manual & Figure 5-2 re facility organization
MURRAY, T D Toledo Edison Co 82/09/29 4pp 16410 328 24X Fiche 50-346, 82/12/03, 8212130132

8212100231 Forwards proposed revision to industrial security plan Revision withheld (ref 10CFR73 21)
CROUSE, R P Toledo Edison Co 82/12/06 BENTON, H R Office of Nuclear Reactor Regulation, Director 1p 16376 191 24X Fiche 50-346, 82/12/06, 8212100231

8212150301 Releases public version of revision to emergency plan supporting procedures revision index
FELTON, J M Division of Rules and Records 82/12/08 Document Management Branch 1p 16446 264 24X Fiche 50-346, 82/12/08, 8212150301

DOCKETED ITEMS

- 8212150310 Forwards public version of Revision 157 to emergency plan supporting procedures revision index
 * Toledo Edison Co 82/12/01 NRC - No Detailed Affiliation
 Given 3pp 16446 266 24X Fiche 50-346, 82/12/08, 8212150301

8212160071 Releases public version of revised emergency plan implementing procedure
 FELTON, J M Division of Rules and Records 82/12/08 Document
 Management Branch 1p 16447 209 24X Fiche 50-346, 82/12/08,
 8212160091

- 8212160078 Forwards public version of Revision 4 to Emergency Plan Implementing Procedure EI 1300 01, "Emergency Plan Activation" Receipt form encl
 * Toledo Edison Co 82/11/19 NRC - No Detailed Affiliation
 Given 1p 16447 210 24X Fiche 50-346, 82/12/08, 8212160091

-- 8212160107 Public version of Revision 4 to Emergency Plan Implementing Procedure EI 1300 01, "Emergency Plan Activation" Revision index encl
 HUMRAY, T D, BEVER, B D, BRIDEN, D W Toledo Edison Co 82/11/17
 39pp 16447 211 24X Fiche 50-346, 82/12/08, 8212160091

8212220298 Releases public version of revised emergency plan supporting procedures index
 FELTON, J M Division of Rules and Records 82/12/10 Document
 Management Branch 1p 16523 255 24X Fiche 50-346, 82/12/10,
 8212220298

-- 8212220302 Forwards public version of Revision 158 to emergency plan supporting procedures index Receipt form encl
 * Toledo Edison Co 82/12/03 NRC - No Detailed Affiliation
 Given 1p 16523 256 24X Fiche 50-346, 82/12/10, 8212220298

- 8212220308 Public version of Revision 158 to emergency plan supporting procedures index
 * Toledo Edison Co 82/12/31 1p 16523 257 24X
 Fiche 50-346, 82/12/10, 8212220298

8212300193 Responds to util 821123 schedule for completing mods to provide alternate svc water capability, required by App R to 10CFR50. Mods must be completed in accordance w/schedule for alternative shutdown capability, not dedicated shutdown
 STOLZ, J F Operating Reactors Branch 4 82/12/14 CROUSE, R P
 Toledo Edison Co 2pp 16612 331 24X Fiche 50-346, 82/12/14,
 8212300193

8212220306 Discusses layout of communications equipment required in control room, onsite technical support ctr & nearsite emergency operations facility
 KEEPLER, J O Region 3, Office of Director 82/12/16
 Commonwealth Edison Co 3pp 16503 351 24X Fiche 50-000, 82/12/16,
 8212220306

8212290026 Responds to 821012 ltr re changes to physical security plan changes acceptable Requests administratively correct plan pages be submitted
 STOLZ, J F Operating Reactors Branch 4 82/12/16 CROUSE, R P
 Toledo Edison Co 2pp 16607 178 24X Fiche 50-346, 82/12/16,
 8212290026

M Antitrust correspondence

8212150012 Requests NRC review of Cleveland Electric Illuminating Co 821119 filing w/FERC for increase in rates for firm power svc Also requests NRC consideration of petition to intervene in matter
 PANDY, J Cleveland, OH 82/12/02 TOALSTON, A Antitrust & Economic Analysis Branch (Utility Finance) 37pp 16421 139 24X
 Fiche 50-000, 82/12/02, 8212150012

P Operating license stage documents & correspondence

8212130111 Forwards Amend 49 to License NPF-3, safety evaluation & notice of issuance & availability Amend changes Tech Spec Table 3 7-3 re safety-related hydraulic snubbers.
 DEAGAZIO, A M Operating Reactors Branch 4 82/11/23 CROUSE, R P
 Toledo Edison Co 3pp 16418 007 24X Fiche 50-346, 82/11/23,
 8212130111

-- 8212130117 Amend 49 to License NPF-3, changing Tech Spec Table 3 7-3 re safety-related hydraulic snubbers.
 STOLZ, J F Operating Reactors Branch 4 82/11/23 7pp
 16418 010 24X Fiche 50-346, 82/11/23, 8212130111

-- 8212130121 Safety evaluation supporting Amend 49 to License NPF-3
 * Office of Nuclear Reactor Regulation, Director 82/11/23 2pp,
 16418 017 24X Fiche 50-346, 82/11/23, 8212130111

-- 8212130124 Notice of issuance & availability of Amend 49 to License NPF-3
 STOLZ, J F Operating Reactors Branch 4 82/11/23 2pp
 16418 019 24X Fiche 50-346, 82/11/23, 8212130111

8212100040 Responds to 821013 ltr re Tech Specs for snubber surveillance All snubbers defined in ANSI/ASME OM-4 Std will be listed in Tech Spec tables in manner similar to current table on hydraulic snubbers
 CROUSE, R P Toledo Edison Co 82/11/24 STOLZ, J F Operating Reactors Branch 4 2pp 16379 041 24X Fiche 50-346, 82/11/24,
 8212100040

8212020205 Forwards temporary mods to facility procedures re reactor/turbine trip, auxiliary feedwater sys, station & instrument air, makeup & purification sys & plant startup
 SYROHSKI, J M Toledo Edison Co 82/11/29 MAINES, R NRC - No Detailed Affiliation Given App 16274 096 24X
 Fiche 50-346, 82/11/29, 8212020205

8212030337 Requests confirmation of schedule for resolution of items discussed in 821115 telcon re NUREG-0612, "Control of Heavy Loads at Nuclear Power Plants" Response should be provided by 821210
 STOLZ, J F Operating Reactors Branch 4 82/11/30 CROUSE, R P
 Toledo Edison Co 3pp 16316 326 24X Fiche 50-346, 82/11/30,
 8212030337

8212060158 Updates util 820917 ltr re NUREG-0737, Item II B 3, "Post-Accident Sampling" Util commits to revised completion date of Dec 1983 for installation of RCS sample panel & containment air monitor grab sample due to vendor problems
 CROUSE, R P Toledo Edison Co 82/11/30 STOLZ, J F Operating Reactors Branch 4 2pp 16313 115 24X Fiche 50-346, 82/11/30,
 8212060158

8212100414 Forwards Amend 50 to License NPF-3, safety evaluation & notice of issuance & availability Amend changes Tech Spec Surveillance Requirement 4.6.1.5 re arithmetic averaging of inlet temp to containment air coolers
 STOLZ, J F Operating Reactors Branch 4 82/11/30 CROUSE, R P
 Toledo Edison Co 3pp 16389 061 24X Fiche 50-346, 82/11/30,
 8212100414

-- 8212100453 Amend 50 to License NPF-3, changing Tech Spec Surveillance Requirement 4.6.1.5 re arithmetic averaging of inlet temp to containment air coolers
 STOLZ, J F Operating Reactors Branch 4 82/11/30 7pp
 16389 064 24X Fiche 50-346, 82/11/30, 8212100414

-- 8212100474 Safety evaluation supporting Amend 50 to License NPF-3
 * Office of Nuclear Reactor Regulation, Director 82/11/30 4pp
 16389 071 24X Fiche 50-346, 82/11/30, 8212100414

-- 8212100481 Notice of issuance & availability of Amend 50 to License NPF-3
 STOLZ, J F Operating Reactors Branch 4 82/11/30 2pp
 16389 075 24X Fiche 50-346, 82/11/30, 8212100414

8212070459 Forwards request for addl info re NUREG-0737, Item II B 4, "Training for Mitigating Core Damage" Response requested no later than 821231
 STOLZ, J F Operating Reactors Branch 4 82/12/01 CROUSE, R P
 Toledo Edison Co 3pp 16355 329 24X Fiche 50-346, 82/12/01,
 8212070459

8212130051 Requests modified responses to recommendations in NRC status rept re NUREG-0737, Item II E 1.1, "Auxiliary Feedwater Sys Evaluation" Response to unresolved concerns requested by 821217
 STOLZ, J F Operating Reactors Branch 4 82/12/01 CROUSE, R P
 Toledo Edison Co 3pp 16417 046 24X Fiche 50-346, 82/12/01,
 8212130051

8212070292 Discusses disposal of meteorological data strip charts Space considerations necessitate destroying charts in Dec 1983 Data on magnetic tape will be retained & stored consistent w/ANSI stds
 CROUSE, R P Toledo Edison Co 82/12/03 STOLZ, J F Operating Reactors Branch 4 1p 16339 063 24X Fiche 50-346, 82/12/03,
 8212070292

8212090040 Forwards SER for containment purging & venting during normal operation per Generic Item B-24 & NUREG-0737, Item II E 4.2 Purge sys design & operating practices acceptable except for two listed items
 STOLZ, J F Operating Reactors Branch 4 82/12/03 CROUSE, R P
 Toledo Edison Co 7pp 16384 247 24X Fiche 50-346, 82/12/03,
 8212090040

--B21209043 SER for containment purging & venting during normal operation Debris screens should be installed & leakage integrity tests performed regularly Interim position encl
* Operating Reactors Branch 4 82/12/03 4pp 16384 254 24X
Fiche 50-346,82/12/03,821209040

B212130090 Endorses B&W Topical Repts BAW-10154P, "B&W Small Break LOCA ECCB Evaluation Model" & BAW-10072P, Revision 3, "CRAFT-2," in effort to complete small break LOCA methods program response to NUREG-0737, Item II K 3 30
CROUSE, R P Toledo Edison Co 82/12/07 STOLZ, J F Operating Reactors Branch 4 1p 16389 315 24X Fiche 50-346,82/12/07, 8212130090

B212130088 Forwards B21206 affidavit of JH Taylor requesting proprietary classification of BAW-1719, "Fracture Toughness Test Results From Capsule TEI-F," reactor vessel matl surveillance program
CROUSE, R P Toledo Edison Co 82/12/08 STOLZ, J F Operating Reactors Branch 4 8pp 16390 197 24X Fiche 50-346,82/12/08, 8212130088

B212130263 Generic Ltr B2-32 to all PWR licensees re potential steam generator-related generic requirements Forwards Science Applications, Inc draft rept re subj requirements Comments requested within 30 days of ltr Svc list encl
EISENHUT, D O Division of Licensing 82/12/09 Consolidated Edison Co of New York, Inc 29pp 16629 247 24X
Fiche 50-000,82/12/09,8208190263

B212170392 Advises that anticipatory reactor trip sys main feedwater trip bypass alarm described in util 820729 ltr, represents acceptable alternative to automatic bypass removal
STOLZ, J F Operating Reactors Branch 4 82/12/10 CROUSE, R P Toledo Edison Co 2pp 16478 145 24X Fiche 50-346,82/12/10, 8212170392

B212210081 Provides conceptual design & installation schedule for hot leg level monitoring sys, per NUREG-0737, Item II F 2 3
Present schedule calls for installation of sys during refueling outage of sufficient duration 1-yr after approval
CROUSE, R P Toledo Edison Co 82/12/10 STOLZ, J F Operating Reactors Branch 4 5pp 16493 038 24X Fiche 50-346,82/12/10, 8212210081

B212270363 Forwards order for license mod requiring installation of inadequate core cooling sys which conforms to design parameters specified in NUREG-0737, Item II F 2 "Detection of Inadequate Core Cooling"
EISENHUT, D O Division of Licensing 82/12/10 CROUSE, R P Toledo Edison Co 3pp 16566 215 24X Fiche 50-346,82/12/10, 8212270363

--B212270370 Order for mod of License NPF-3 re NUREG-0737, Item II F 2, "Detection of Inadequate Core Cooling" Checklist for plant specific review of inadequate core cooling instrumentation sys encl
EISENHUT, D O Division of Licensing 82/12/10 Toledo Edison Co 11pp 16566 218 24X Fiche 50-346,82/12/10, 8212270363

B212280069 Forwards Amend 51 to License NPF-3 & notice of issuance & availability Amend proposes license conditions re sys integrity measurements program & improved iodine monitoring program
DEAGAZIO, A H Operating Reactors Branch 4 82/12/10 CROUSE, R P Toledo Edison Co 3pp 16593 076 24X Fiche 50-346,82/12/10, 8212280069

--B212280071 Amend 51 to License NPF-3, adding license conditions re sys integrity measurements program & improved iodine monitoring program
STOLZ, J F Operating Reactors Branch 4 82/12/10 5pp 16593 079 24X Fiche 50-346,82/12/10, 8212280069

--B212280074 Notice of issuance & availability of Amend 51 to License NPF-3
STOLZ, J F Operating Reactors Branch 4 82/12/10 2pp 16593 085 24X Fiche 50-346,82/12/10, 8212280069

B212210092 Responds to B21130 ltr concerning response to draft technical evaluation rept re control of heavy loads Util reviewing request to submit Phase II rept Response will be provided B20131
CROUSE, R P Toledo Edison Co 82/12/14 STOLZ, J F Operating Reactors Branch 4 1p 16493 015 24X Fiche 50-346,82/12/14, 8212210092

B212220273 Requests relief from Class 2 valve testing requirements of ASME Section XI IWW, MSIV MS-100 & MS-101 Permission to perform subj test in lieu of full stroke test at cold shutdown requested Modified code relief Request 1 encl
CROUSE, R P Toledo Edison Co 82/12/14 STOLZ, J F Operating Reactors Branch 4 5pp 16518 026 24X Fiche 50-346,82/12/14, 8212220273

B212270210 Responds to NRC B21201 ltr re NUREG-0737, Item II E 1 1, "Auxiliary Feedwater Sys Reliability Evaluation" & request for util commitment to Recommendation GS-6 Suggested changes to Tech Specs not warranted
CROUSE, R P Toledo Edison Co 82/12/15 STOLZ, J F Operating Reactors Branch 4 3pp 16535 001 24X Fiche 50-346,82/12/15, 8212270210

B212270205 Advises that final evaluation re EPRI relief & safety valve testing per NUREG-0737, Item II D 1, "Reliability Engineering," will not be submitted until B20131 Summary of evaluation submitted
CROUSE, R P Toledo Edison Co 82/12/17 STOLZ, J F Operating Reactors Branch 4 2pp 16534 354 24X Fiche 50-346,82/12/17, 8212270205

G Inspection reports, IE Bulletins & correspondence

B208190240 IE Bulletin B2-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants" Svc list encl
DEVOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000,82/10/28, 8208190240

B208190245 IE Info Notice B2-42, "Defects Observed in Panasonic Model B01 & Model B02 Thermoluminescent Dosimeters" Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000,82/11/05, 8208190245

B208190251 IE Info Notice B2-44, "Clarification of Emergency Plan Exercise Requirements" Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X Fiche 50-000,82/11/18, 8208190251

B208190256 IE Info Notice B2-46, "Defective & Obsolete Combination Padlocks" Svc list encl
DEVOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000,82/11/26, 8208190256

B212100255 Forwards IE Insp Rept 50-346/B2-31 on 821003-30 & notice of violation
SPESSARD, R L Division of Project & Resident Programs 82/11/26 CROUSE, R P Toledo Edison Co 2pp 16376 159 24X
Fiche 50-346,82/11/26, 8212100255

--B212100257 Notice of violation from insp on 821003-30
SPESSARD, R L Division of Project & Resident Programs 82/11/26 1p 16376 161 24X Fiche 50-346,82/11/26, 8212100255

--B212100263 IE Insp Rept 50-346/B2-31 on 821003-30 Noncompliance noted repair of buried fire piping accomplished w/inadequate procedures, as requirement for restoring backfill to original spec omitted
PEEBLES, T A, ROGERS, W G, BYRON, P M Division of Project & Resident Programs 82/11/24 8pp 16376 162 24X
Fiche 50-346,82/11/26, 8212100255

B212060074 Forwards IE Safeguards Insp Rept 50-346/B2-30 on 821025-29 & notice of violation Notice of violation & rept details withheld (ref 10CFR73 21)
NORELIUS, C E Division of Engineering & Technical Programs 82/11/29 CROUSE, R P Toledo Edison Co 2pp 16314 358 24X
Fiche 50-346,82/11/29, 8212060074

--B212060080 IE Safeguards Insp Rept 50-346/B2-30 on 821025-29 Noncompliance noted security organization mgt, personnel & response, records & repts, testing & maint & physical barriers Details withheld (ref 10CFR73 21)
PIRTLE, G L, KNICELEY, J R, CREED, J R Region 3, Office of Director 82/11/23 2pp 16314 360 24X Fiche 50-346,82/11/29, 8212060074

B208190257 IE Info Notice B2-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl." Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000,82/11/30, 8208190257

B208190259 IE Bulletin B2-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies" Svc list encl
DEVOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000,82/12/03, 8208190259

DOCKETED ITEMS

8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03
Consolidated Edison Co of New York, Inc 110pp 16462 064 24X
Fiche 50-000, 82/12/03, 8208190261

8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
DEVOUNO, R C Director's Office, Office of Inspection and Enforcement 82/12/16
Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16, 8208190267

8212210351 Ack receipt of 821209 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 90-346/82-29
STREETER, J F Division of Project & Resident Programs 82/12/16
CROUSE, R P Toledo Edison Co Ip 16493 100 24X
Fiche 50-346, 82/12/16, 8212210351

--8212210368 Responds to NRC 821103 ltr re violations noted in IE Insp Rept 90-346/82-29 Corrective actions reactor theory requalification exam reviewed per Administrative Procedure AD 1818 15 & responsible personnel counseled
CROUSE, R P Toledo Edison Co 82/12/09 STREETER, J F Division of Project & Resident Programs 2pp 16493 101 24X
Fiche 50-346, 82/12/16, 8212210361

8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27 " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20
Consolidated Edison Co of New York, Inc 108pp 16628 293 24X
Fiche 50-000, 82/12/20, 8208190268

8212290224 Responds to IE Bulletin 82-01, Revision 1, Suppl 1 re alteration of radiographs of welds in piping subassemblies supplied by ITT Grinnell Industrial Piping, Inc No alteration found
CROUSE, R P Toledo Edison Co 82/12/21 KEPLER, J G Region 3, Office of Director 2pp 16578 070 24X Fiche 50-346, 82/12/21, 8212290224

8212290449 Ack receipt of 821206 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 90-346/82-27 Corrective actions delineated in LER 82-44 will be implemented to correct noncompliance
STREETER, J F Division of Project & Resident Programs 82/12/23
CROUSE, R P Toledo Edison Co Ip 16585 213 24X
Fiche 50-346, 82/12/23, 8212290449

--8212290455 Responds to NRC 821104 ltr re violations noted in IE Insp Rept 90-346/82-27 Corrective actions Special Order 99 distributed to clarify requirements of Tech Specs re consequences of failure to perform surveillance requirement
CROUSE, R P Toledo Edison Co 82/12/06 SPESSARD, R L Division of Project & Resident Programs 3pp 16585 214 24X
Fiche 50-346, 82/12/23, 8212290449

R Periodic operating reports & related correspondence

8212290307 Forwards monthly operating rept for Oct 1982
MURRAY, T D Toledo Edison Co 82/11/09 HALLER, N Office of Resource Management, Director Ip. 16588 018 24X
Fiche 50-346, 82/11/09, 8212290307

--8212290309 Monthly operating rept for Oct 1982
SARSDUR, B Toledo Edison Co 82/11/09 Bpp 16588 019 24X
Fiche 50-346, 82/11/09, 8212290307

S Reportable occurrences, LERs & related correspondence

8212100229 Forwards LER 82-056/03L-0
MURRAY, T D Toledo Edison Co 82/12/02 KEPLER, J G Region 3, Office of Director Ip 16376 188 24X Fiche 50-346, 82/12/02, 8212100229

--8212100235 LER 82-056/03L-0 on 821104, breaker BF114 tripped, causing loss of power to F12 series motor control ctrs Caused by ground in jacking fire pump motor when pump seized Pump rebuilt & motor replaced
LONG, J Toledo Edison Co 82/12/02 Region 3, Office of Director 2pp 16376 189 24X Fiche 50-346, 82/12/02, 8212100229

8212100325 Forwards LER 82-057/03L-0
MURRAY, T D Toledo Edison Co 82/12/02 KEPLER, J G Region 3, Office of Director Ip 16377 060 24X Fiche 50-346, 82/12/02, 8212100325

--8212100332 LER 82-057/03L-0 on 821105, found door 400 not completely closed & latched Caused by personnel error Personnel to receive add'l training in basic security
RICHTER, L Toledo Edison Co 82/12/02 Region 3, Office of Director 3pp, 16377 061 24X Fiche 50-346, 82/12/02, 8212100325

8212100281 Forwards LER 82-058/03L-0
MURRAY, T D Toledo Edison Co 82/12/03 KEPLER, J G Region 3, Office of Director Ip 16377 142 24X Fiche 50-346, 82/12/03, 8212100281

--8212100287 LER 82-058/03L-0 on 821106, while performing ST 5032 01, setpoints for containment post-accident radiation monitor RE 4597BA found drifted, rendering monitor inoperable
Caused by component failure Microprocessor boards replaced
ELDRD, D T Toledo Edison Co 82/12/03 Region 3, Office of Director 2pp 16377 143 24X Fiche 50-346, 82/12/03, 8212100281

8212170282 Forwards LER 82-059/03L-0
MURRAY, T D Toledo Edison Co 82/12/08 KEPLER, J G Region 3, Office of Director Ip 16461 154 24X Fiche 50-346, 82/12/08, 8212170282

--8212170285 LER 82-059/03L-0 on 821108, containment post-accident radiation monitor, channel 2 read low On 821116 & 22 equipment fail alarm received Caused by failed high voltage power supply board Board replaced & declared operable
ELDRD, D T Toledo Edison Co 82/12/08 Region 3, Office of Director 3pp 16461 155 24X Fiche 50-346, 82/12/08, 8212170282

8212170178 Forwards LER 82-060/03L-0
MURRAY, T D Toledo Edison Co 82/12/09 KEPLER, J G Region 3, Office of Director Ip 16450 137 24X Fiche 50-346, 82/12/09, 8212170178

--8212170187 LER 82-060/03L-0 on 821111, during performance of ST 5031 1A, discovered ventilation duct chase 48 power supply in steam & feedwater rupture control sys channel 2 failing at 1-volt/h Caused by component failure Channel 2 de-energized
YARGER, K Toledo Edison Co 82/12/09 Region 3, Office of Director 2pp 16450 138 24X Fiche 50-346, 82/12/09, 8212170178

8212280247 Forwards LER 82-061/03L-0
MURRAY, T D Toledo Edison Co 82/12/15 KEPLER, J G Region 3, Office of Director Ip 16561 274 24X Fiche 50-346, 82/12/15, 8212280247

--8212280250 LER 82-061/03L-0 on 821116, fire door 509 (control room access door) & door 512 (control alarm station door) declared nonfunctional due to improper fire rating labels
Caused by design error Doors will be replaced
HART, T, RICHTER, L Toledo Edison Co 82/12/15 Region 3, Office of Director 3pp 16561 275 24X Fiche 50-346, 82/12/15, 8212280247

8212280281 Forwards revised LER 82-059/03T-1
MURRAY, T D Toledo Edison Co 82/12/15 KEPLER, J G Region 3, Office of Director Ip 16561 140 24X Fiche 50-346, 82/12/15, 8212280281

--8212280290 Revised LER 82-059/03T-1 on 821108, containment post-accident radiation monitor RE 4597AA Channel 2 discovered reading low On 821116 & 22, equipment fail alarm received on RE 4597AA Caused by failed high voltage power supply board
ELDRD, D T Toledo Edison Co 82/12/15 Region 3, Office of Director 3pp 16561 141 24X Fiche 50-346, 82/12/15, 8212280281

8212270151 PNO-III-82-137 on 821216, unusual event declared after gasoline truck collided w/ auto 1/2 mile south of plant site, spilling approx 4,000 gallons of fuel Gasoline contained in surrounding ditches Unusual event terminated 821217
FEEBLES, T, REYES, L, STREETER, J Region 3, Office of Director 82/12/17 Ip 16538 341 24X Fiche 50-346, 82/12/17, 8212270151

8212280075 Forwards LER 82-062/03L-0
MURRAY, T D Toledo Edison Co 82/12/17 KEPLER, J G Region 3, Office of Director Ip 16565 133 24X Fiche 50-346, 82/12/17, 8212280075

--8212280077 LER 82-062/03L-0 on 821117, discharge check valve CV-186 stuck during ST 5065 02, rendering hydrogen dilution blower 1-1 inoperable Caused by design/fabrication error New valve installed
THOMPSON, T Toledo Edison Co 82/12/17 Region 3, Office of Director 2pp 16565 134 24X Fiche 50-346, 82/12/17, 8212280075

8212280234 Forwards LER 82-063/03L-0
MURRAY, T D Toledo Edison Co 82/12/17 KEPLER, J G Region 3, Office of Director Ip 16562 195 24X Fiche 50-346, 82/12/17, 8212280234

--8212280239 LER 82-063/03L-0 on 821118, offsite ac source operability not demonstrated within 1 h after emergency diesel generator 1-1 taken out of svc for periodic maint Caused by personnel error Personnel counseled
LONG, T Toledo Edison Co 82/12/17 Region 3, Office of Director 3pp 16562 196 24X Fiche 50-346, 82/12/17, 8212280234

DOCKET 50-348 JOSEPH M FARLEY NUCLEAR PLANT, UNIT 1

F Security, medical, emergency & fire protection plans

B212100070 Submits permanent, backup, interim primary & interim backup emergency operations facilities (EOF) info per B21202 verbal request EOF completed & occupied in Oct 1982
CLAYTON, F L Alabama Power Co 82/12/03 VARQA, S A Office of Nuclear Reactor Regulation, Director 3pp 16375 359 24X
Fiche 50-348, 82/12/03, B212100070

J Insurance & indemnity information

B212280223 Forwards Endorsement 48 to NELIA Policy NF-238 & Endorsement 40 to MAELU Policy MF-93
DUCK, J R Marsh & McLennan, Inc, M & M Nuclear Consultants, Inc Div 82/12/20 SALTZMAN, J Assistant Director for State & Licensee Relations 3pp 16562 276 24X Fiche 50-348, 82/12/20, B212280223

B212280348 Forwards Certificates of Insurance N-62 & N-73 for Endorsements 1, 2 & 3 to NELIA Policy NF-238 & Certificates of Insurance M-62 & M-73 for Endorsements 1, 2 & 3 to MAELU Policy MF-93
DUCK, J R Marsh & McLennan, Inc, M & M Nuclear Consultants, Inc Div 82/12/20 SALTZMAN, J Assistant Director for State & Licensee Relations 3pp 16561 146 24X Fiche 50-348, 82/12/20, B212280348

P Operating license stage documents & correspondence

B212020130 Informs that info requested in Generic Ltr 82-22 re steam generator tube integrity, maint, repair & worker exposures submitted via annual CFR repts & until B20412 ltr
CLAYTON, F L Alabama Power Co 82/11/24 EISENHUT, D Q Division of Licensing 2pp 16272 037 24X Fiche 50-348, 82/11/24, B212020130

B208190263 Generic Ltr 82-32 to all PWR licensees re potential steam generator-related generic requirements Forwards Science Applications, Inc draft rept re subj requirements Comments requested within 30 days of ltr Svc list encl
EISENHUT, D Q Division of Licensing 82/12/09 Consolidated Edison Co of New York, Inc 29pp 16629 247 24X
Fiche 50-000, 82/12/09, B208190263

B212280280 Requests approval by B30701 of B20810 ltr re RCS pressure isolation valve leak testing, to support planning & scheduling of next refueling outage
CLAYTON, F L Alabama Power Co 82/12/23 VARQA, S A Office of Nuclear Reactor Regulation, Director 1p 16561 243 24X
Fiche 50-348, 82/12/23, B212280280

Q Inspection reports, IE Bulletins & correspondence

B208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, B208190240

B212090362 Advises that provisions of IE Bulletin B1-03, Item 4 B met, following extensive insp & cleaning of various safety-related & nonsafety-related HXs
CLAYTON, F L Alabama Power Co 82/10/29 O'REILLY, J P Region 2, Office of Director 4pp 16365 160 24X Fiche 50-348, 82/10/29, B212090362

B208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model B01 & Model B02 Thermoluminescent Dosimeters " Svc list encl
CDBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc. 110pp 16372 142 24X Fiche 50-000, 82/11/05, B208190245

B212090412 Advises that IE Bulletin 82-01, Revision 1, Suppl 1, review of radiographs furnished by ITT Grinnell for piping assemblies, revealed two assemblies w/ altered radiographs on total of three welds Penetrator image darkened
CLAYTON, F L Alabama Power Co 82/11/09 O'REILLY, J P Region 2, Office of Director 2pp 16365 042 24X Fiche 50-348, 82/11/09, B212090412

B212090511 Forwards IE Insp Repts 50-348/82-25 & 50-364/82-24 on B20916-1022 No noncompliance noted
VERRELLI, D M Division of Project & Resident Programs 82/11/17 McDONALD, R P Alabama Power Co 2pp 16367 014 24X
Fiche 50-348, 82/11/17, B212090511

--B212090519 IE Insp Repts 50-348/82-25 & 50-364/82-24 on B20916-1022 No noncompliance noted Major areas inspected monthly surveillance observation, monthly maint observation & operational safety verification
BRADFORD, W H, CANTRELL, F Division of Project & Resident Programs 82/11/17 Bpp 16367 016 24X Fiche 50-348, 82/11/17, B212090519

B208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 107pp 16411 199 24X
Fiche 50-000, 82/11/18, B208190251

B208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000, 82/11/26, B208190256

B212090432 Confirms B21123 telcon re B21214 mgt meeting in Birmingham, AL to review results of first phase of annual appraisal of regulatory performance Proposed agenda encl
LEWIS, R C Division of Project & Resident Programs 82/11/29 McDONALD, R P Alabama Power Co 3pp 16364 271 24X
Fiche 50-348, 82/11/29, B212090432

B208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl
CDBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000, 82/11/30, B208190257

B208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, B208190259

B208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X
Fiche 50-000, 82/12/03, B208190261

B208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16, B208190267

B208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27 " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X
Fiche 50-000, 82/12/20, B208190268

R Periodic operating reports & related correspondence

B212170197 Forwards monthly operating rept for Nov 1982
CLAYTON, F L Alabama Power Co 82/12/13 Division of Data Automation & Management Information 1p 16461 302 24X
Fiche 50-348, 82/12/13, B212170197

--B212170207 Monthly operating rept for Nov 1982
HAIRSTON, W O Alabama Power Co 82/12/04 Bpp 16461-303 24X
Fiche 50-348, 82/12/13, B212170197

DOCKET 50-352 LIMERICK GENERATING STATION, UNIT 1

A Application/construction stage documents & correspondence

B210040239 Forwards Amend 39 to application for DL (filed in PDR in Category A)
BRADLEY, E J Philadelphia Electric Co 82/09/30 DENTON, H R Office of Nuclear Reactor Regulation, Director 6pp 15589 170 24X Fiche 50-352, 82/09/30, B210040239

--B210040253 Amend 39 to application for DL, consisting of Revision 10 to FSAR, proprietary & nonproprietary Revision 1 to design assessment rept & Revision 6 to environ rept Certificate of Svc encl Proprietary design rept withheld (ref 10CFR2.790)
BOYER, V B Philadelphia Electric Co 82/09/28 7pp 15589, 176 24X Fiche 50-352, 82/09/30, B210040239

--B210040272 Revision 1 to nonproprietary design assessment rept
* Philadelphia Electric Co 82/09/30 228pp 15590 286 24X
Fiche 50-352, 82/09/30, B210040239

DOCKETED ITEMS

8212060077 Forwards request for addl auxiliary sys info re Revision 10 to FSAR Response should be provided within 7 days
SCHWENCER, A Licensing Branch 2 82/11/17 BAUER, E G
Philadelphia Electric Co 4pp 16323 016 24X
Fiche 50-352, 82/11/17, 8212060077

8212060118 Forwards request for addl info as result of concerns raised during hearing session on Point Pleasant Diversion Project
SCHWENCER, A Licensing Branch 2 82/11/18 BAUER, E G
Philadelphia Electric Co 4pp 16323 007 24X
Fiche 50-352, 82/11/18, 8212060118

8212060510 Notification of 821217 meeting w/util at Limerick Info Ctr to discuss mgt structure & technical resources audit
ABELSON, H Licensing Branch 2 82/11/23 SCHWENCER, A Licensing Branch 2 4pp 16344 016 24X Fiche 50-352, 82/11/23, 8212060510

8212080015 Notification of cancellation of 821217 meeting w/util at site to discuss plant mgt structure & technical resources audit Meeting will be rescheduled
ABELSON, H Licensing Branch 2 82/11/23 SCHWENCER, A Licensing Branch 2 4pp 16347 173 24X Fiche 50-352, 82/11/23, 8212080015

8212010470 Confirms 821214-17 mgt structure & technical resources audit Agenda encl
SCHWENCER, A Licensing Branch 2 82/11/24 BAUER, E G
Philadelphia Electric Co 5pp 16270 215 24X
Fiche 50-352, 82/11/24, 8212010470

8212010513 Forwards EQ&G draft technical evaluation rept, "Control of Heavy Loads at Nuclear Power Plants, Limerick Generating Station Units 1 & 2," for comment
SCHWENCER, A Licensing Branch 2 82/11/24 BAUER, E G
Philadelphia Electric Co 3pp 16268 168 24X
Fiche 50-352, 82/11/24, 8212010513

--8212010519 "Control of Heavy Loads at Nuclear Power Plants, Limerick Generating Station Units 1 & 2"
MARINGAS, N, STICKLEY, T H EQ&G, Inc 82/11/30 NRC - No
Detailed Affiliation Given 30pp 16268 171 24X
Fiche 50-352, 82/11/24, 8212010513

8212060393 Summary of 820903 meeting w/util, OE, Fauske & Associates, Inc., BNL, NUS, Science Applications, Inc., Commonwealth of PA, Limerick Ecology Action & applicant counsel in Bethesda, MD re PRA
ABELSON, H Licensing Branch 2 82/11/29 Licensing Branch 2 47pp 16323 021 24X Fiche 50-352, 82/11/29, 8212060393

8212060398 Summary of 820922 meeting w/util, NUTECH & BMNL in Bethesda, MD re present & future corp & plant mgt structure, staffing, training plans & safety review groups
ABELSON, H Licensing Branch 2 82/11/29 Licensing Branch 2 17pp 16322-318 24X Fiche 50-352, 82/11/29, 8212060398

8212030122 Forwards Amend 42 to application for DL Amend revises FSAR in response to NRC 820809 ltr Certificate of Svc encl
BRADLEY, E J Philadelphia Electric Co 82/11/30 DENTON, H R
Office of Nuclear Reactor Regulation, Director 5pp 16303 283
24X Fiche 50-352, 82/11/30, 8212030122

--8212030132 Amend 42 to application for DL revising FSAR
BOYER, V S Philadelphia Electric Co 82/11/29 3pp 16303 288
24X Fiche 50-352, 82/11/30, 8212030122

8212070493 Notification of 821215 meeting w/util & BNL in Bethesda, MD to discuss questions generated during review of BNL draft rept on PRA Meeting agenda encl
ABELSON, H Licensing Branch 2 82/12/01 SCHWENCER, A Licensing Branch 2 4pp 16351-355 24X Fiche 50-352, 82/12/01, 8212070493

8212070025 Forwards agreement w/ARCO Pipeline Co prohibiting shipping propane through ARCO pipeline, per C Ferrell concern from Aug 1982 environ site visit
BRADLEY, E J Philadelphia Electric Co 82/12/03 SCHWENCER, A
Licensing Branch 2 5pp 16327 349 24X Fiche 50-352, 82/12/03, 8212070025

8212080446 Forwards draft response to NRC 820901 request for addl info to aid E Pedersen audit of util organization
BRADLEY, E J Philadelphia Electric Co 82/12/03 SCHWENCER, A
Licensing Branch 2 71pp 16352 180 24X Fiche 50-352, 82/12/03, 8212080446

8212160747 Forwards request for addl info re pump house noise Corrected numbers for previously submitted 8270 series questions resubmitted Response requested within 7 days of ltr receipt
SCHWENCER, A Licensing Branch 2 82/12/08 BAUER, E G
Philadelphia Electric Co 4pp 16446 001 24X
Fiche 50-352, 82/12/08, 8212160747

8212220541 Requests test case calculation for radiological risk be provided to facilitate review of PRA Case should be calculated w/version of CRAC computer code used in plant PRA
SCHWENCER, A Licensing Branch 2 82/12/13 BAUER, E G
Philadelphia Electric Co 3pp 16523 357 24X
Fiche 50-352, 82/12/13, 8212220541

8212210402 Advises that actual scram valve characteristics will be used in preparing analysis of control rod drive sys hydrodynamic loads Analysis & complete response will be provided by 830315
BRADLEY, E J Philadelphia Electric Co 82/12/16 SCHWENCER, A
Licensing Branch 2 2pp 16494 310 24X Fiche 50-352, 82/12/16, 8212210402

8212210491 Forwards Amend 43 to license application (filed in PDR Category A)
BRADLEY, E J Philadelphia Electric Co 82/12/17 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 16486 048 24X
Fiche 50-352, 82/12/17, 8212210491

--8212210495 Amend 43 to license application consisting of Revision 8 to environ rept & Revision 14 to FSAR
BOYER, V S Philadelphia Electric Co 82/12/15 6pp 16486 050
24X Fiche 50-352, 82/12/17, 8212210491

8212220097 Forwards DOI 821206 ltr transmitting Fish & Wildlife Svc correspondence re Point Pleasant diversion Info relates to testimony before ASLB
HODDON, A P Hearing Branch 2 82/12/20 BRENNER, L, MORRIS, P A, COLE, R F Atomic Safety and Licensing Board Panel 11pp 16516 105 24X Fiche 50-352, 82/12/20, 8212220097

8212270141 Forwards summary of loss of offsite power comments presented at 821215 meeting, compilation of requests for addl info for BNL re PRA review & summary of comments on remaining issues
BOYER, V S Philadelphia Electric Co 82/12/22 EISENHUT, D G
Division of Licensing 23pp 16538 312 24X Fiche 50-352, 82/12/22, 8212270141

8212280209 Forwards responses to Auxiliary Sys Branch Questions 410 94 through 410 99 re spent fuel storage, transmitted by 821222 ltr Responses will be incorporated in FSAR revision scheduled for Jan 1983
BRADLEY, E J Philadelphia Electric Co 82/12/22 SCHWENCER, A
Licensing Branch 2 10pp 16562 110 24X Fiche 50-352, 82/12/22, 8212280209

C Utility Environmental Report (ER), amends & correspondence

8210040239 Forwards Revision 6 to environ rept (filed in PDR in Category C)
BRADLEY, E J Philadelphia Electric Co 82/09/30 DENTON, H R
Office of Nuclear Reactor Regulation, Director 6pp 15589 170
24X Fiche 50-352, 82/09/30, 8210040239

--8210040278 Revision 6 to environ rept
* Philadelphia Electric Co 82/09/30 20pp 15591 154 24X
Fiche 50-352, 82/09/30, 8210040239

8212100274 Advises that response to Siting Analysis Branch Question E310 10 will be provided via environ rept revision in Feb 1983
BRADLEY, E J Philadelphia Electric Co 82/12/07 SCHWENCER, A
Licensing Branch 2 2pp 16376 147 24X Fiche 50-352, 82/12/07, 8212100274

8212210491 Forwards Revision 8 to environ rept (filed in PDR Category C)
BRADLEY, E J Philadelphia Electric Co 82/12/17 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 16486 048 24X
Fiche 50-352, 82/12/17, 8212210491

--8212210498 Revision 8 to environ rept
* Philadelphia Electric Co 82/12/31 23pp 16486 207 24X
Fiche 50-352, 82/12/17, 8212210491

F Security, medical, emergency & fire protection plans

8212070138 Advises that revised fire protection evaluation rept due by Nov 1982, per 820901 commitment, delayed until Jan 1983 Delay due to substantial, unanticipated addl effort required to upgrade rept per NRC 820728 ltr
BRADLEY, E J Philadelphia Electric Co 82/12/03 SCHWENCER, A
Licensing Branch 2 2pp 16327 032 24X Fiche 50-352, 82/12/03, 8212070138

8212100090 Submits info per 821203 telcon request re emergency operations facility (EOF) Response to Generic Ltr 81-10 submitted 810320 EOF const will be completed by Sept 1983
KEMPER, J S Philadelphia Electric Co 82/12/06 SCHWENCER, A
Licensing Branch 2 3pp 16379 240 24X Fiche 50-352, 82/12/06, 8212100090

8212210398 Forwards draft FSAR page changes & responses to QA Branch 820713 request for addl info Sixteen oversize drawings encl
Aperture cards available in PDR
BRADLEY, E J Philadelphia Electric Co 82/12/17 SCHWENCER, A
Licensing Branch 2 92pp 16489 324 24X Fiche 50-352, 82/12/17, 8212210398

8212270144 Forwards response to NRC comments on physical security plan Response withheld (ref 10CFR2 790 & 10CFR73 21)
BRADLEY, E J Philadelphia Electric Co 82/12/17 DENTON, H R
Office of Nuclear Reactor Regulation, Director 3pp 16538 128
24X Fiche 50-352, 82/12/17, 8212270144

0 Adjudicatory correspondence

8212020330 Reply findings of fact & conclusions of law in form of initial decision
CONNER, T B Philadelphia Electric Co CONNER, T B Conner & Wetterhahn 82/11/30 21pp 16277 279 24X Fiche 50-352, 82/11/30, 8212020330

--8212020339 Reply to Del-Aware 821117 response to ASLB request for info re flows in Schuylkill River Response inaccurate & exceeds scope of ASLB limited inquiry Del-Aware is cluttering record w/erroneous & irrelevant matl w/Certificate of Svc
CONNER, T B Philadelphia Electric Co CONNER, T B Conner & Wetterhahn 82/11/29 10pp 16277 300 24X
Fiche 50-352, 82/11/30, 8212020330

8212130358 Notifies that 820702 petition on behalf of Del-Aware Unlimited to suspend or revoke CPs has been denied Decision encl
DENTON, H R Office of Nuclear Reactor Regulation, Director
82/12/07 SUGARMAN, R J Sugarmann, R J 3pp 16413 008 24X
Fiche 50-352, 82/12/07, 8212130358

--8212130359 Director's Decision DD-82-13 denying Del-Aware Unlimited petition to suspend & revoke CPs No major changes in facts matl to resolution of environ issues presented
DENTON, H R, CASE, E G Office of Nuclear Reactor Regulation, Director 82/12/07 42pp 16413 011 24X Fiche 50-352, 82/12/07, 8212130358

--8212130361 Notice of denial of Del-Aware Unlimited petition to suspend & revoke CPs
CASE, E G Office of Nuclear Reactor Regulation, Director
82/12/07 3pp 16413 034 24X Fiche 50-352, 82/12/07, 8212130358

8212140036 Forwards NRR Director 821207 denial of Del-Aware Unlimited request for suspension or revocation of CPs per 10CFR2 202 & 2 206 (4) encl
HODGSDON, A P Hearing Branch 2 82/12/10 BRENNER, L, MORRIS, P A, COLE, R F Atomic Safety and Licensing Board Panel 2pp 16409 293
24X Fiche 50-352, 82/12/10, 8212140036

8212160304 Requests encl DOI 821207 ltr to ASLB be served on parties
LANE, V M Atomic Safety and Licensing Board Panel 82/12/14
GUCKY, S Docketing & Services Branch 1p 16446 039 24X
Fiche 50-352, 82/12/14, 8212160304

--8212160316 Forwards pages from "Design of Water Intake Structures for Fish Protection," re velocity difference across intake & potential for biofouling even in fresh water
MCCOY, R W Interior, Dept of, Fish & Wildlife Service. 82/12/07
BRENNER, L Atomic Safety and Licensing Board Panel 8pp
16446 040 24X Fiche 50-352, 82/12/14, 8212160304

8212200114 Advises that correspondence re Miller & McCoy testimony in DL proceeding sent to ASLB Portions of transcripts where Miller & McCoy testimony appears or is discussed encl W/o encl
HODGSDON, A P Hearing Branch 2 82/12/17 CONTE, A R
Interior, Dept of 1p 16470 184 24X Fiche 50-352, 82/12/17, 8212200114

8212230327 Advises of State court 821216 decision reversing Public Utils Commission 820827 order re Unit 2 Financing Del-Aware Unlimited, Inc preliminary injunction to enjoin work on Point Pleasant Diversion Project denied on 821215
CONNER, T B Conner & Wetterhahn CONNER, T B Philadelphia Electric Co 82/12/17 BRENNER, L, COLE, R F, MORRIS, P A Atomic Safety and Licensing Board Panel 2pp 16505 136 24X Fiche 50-352, 82/12/17, 8212230327

8212230352 Informal discovery re Friends of the Earth/RL Anthony Contentions V-3a & V-3b admitted by ASLB on 821122
ANTHONY, R L Anthony, R L ANTHONY, R L Friends of the Earth
82/12/17 Atomic Safety and Licensing Board Panel 1p
16511 196 24X Fiche 50-352, 82/12/17, 8212230352

8212230356 Response to ASLB 821122 order re Friends of the Earth proposed contentions on hazards from industrial activities & motion to reconsider admission of Contentions 1, 2, 6, 8 & 9
ANTHONY, R L Anthony, R L ANTHONY, R L Friends of the Earth
82/12/19 Atomic Safety and Licensing Board Panel 3pp
16511 182 24X Fiche 50-352, 82/12/19, 8212230356

8212220097 Forwards DOI 821206 ltr transmitting Fish & Wildlife Svc correspondence re Point Pleasant diversion info relates to testimony before ASLB
HODGSDON, A P Hearing Branch 2 82/12/20 BRENNER, L, MORRIS, P A, COLE, R F Atomic Safety and Licensing Board Panel 11pp
16516 103 24X Fiche 50-352, 82/12/20, 8212220097

8212220126 Advises that NRC will not respond to Del-Aware Unlimited 821201 request for leave to respond to applicant reply on flows in Schuylkill River re need for supplemental cooling water for one unit vs two units
HODGSDON, A P Hearing Branch 2 82/12/20 BRENNER, L, MORRIS, P A, COLE, R F Atomic Safety and Licensing Board Panel 3pp 16503 026
24X Fiche 50-352, 82/12/20, 8212220126

8212270216 Notice re contract award & const starting date Mergentime, Inc awarded contract on 821215 to construct Point Pleasant intake Non-contention work will begin on 820107 Certificate of Svc & VS Buyer affidavit encl
CONNER, T B Philadelphia Electric Co CONNER, T B Conner & Wetterhahn 82/12/21 7pp 16536 196 24X Fiche 50-352, 82/12/21, 8212270216

8212280185 Forwards US District Court for Eastern District of PA 821217 order dismissing Del-Aware, Inc claims under Rivers & Harbors Act for lack of jurisdiction
CONNER, T B Conner & Wetterhahn CONNER, T B Philadelphia Electric Co 82/12/23 BRENNER, L, COLE, R F, MORRIS, P A Atomic Safety and Licensing Board Panel 4pp 16556 142 24X Fiche 50-352, 82/12/23, 8212280185

8212300187 Response in opposition to Friends of the Earth 821219 motion to reconsider ASLB 821122 order ruling on proposed contentions on hazards from industrial activities near site Instant request clearly too late Certificate of Svc encl
CONNER, T B Philadelphia Electric Co CONNER, T B Conner & Wetterhahn 82/12/28 Atomic Safety and Licensing Board Panel 8pp 16597 330 24X Fiche 50-352, 82/12/28, 8212300187

K Utility Final Safety Analysis Report (FSAR) & amends

8210040239 Forwards Amend 39 to application for DL (filed at PDR in Category A), consisting of Revision 10 to FSAR (Category K), Revision 6 to environ rept (Category C) & Revision 1 to design assessment rept (Category A)
BRADLEY, E J Philadelphia Electric Co 82/09/30 DENTON, H R
Office of Nuclear Reactor Regulation, Director 6pp 15589 170
24X Fiche 50-352, 82/09/30, 8210040239

--8210040267 Revision 10 to FSAR
* Philadelphia Electric Co 82/09/30 464pp 15989 183 24X
Fiche 50-352, 82/09/30, 8210040239

8212130341 Forwards Affidavit of Svc re distribution of Revision 13 to FSAR per DQ Eisenhower 810706 ltr
BRADLEY, E J Philadelphia Electric Co 82/12/10 DENTON, H R
Office of Nuclear Reactor Regulation, Director 3pp 16389 282
24X Fiche 50-352, 82/12/10, 8212130341

8212210491 Forwards Amend 43 to license application (filed in PDR Category A), consisting of Revision B to environ rept (filed in PDR Category C) & Revision 14 to FSAR (filed in PDR Category K) Certificate of Svc encl
BRADLEY, E J Philadelphia Electric Co 82/12/17 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 16486 048 24X
Fiche 50-352, 82/12/17, 8212210491

--8212210499 Revision 14 to FSAR
* Philadelphia Electric Co 82/12/31 151pp 16486 056 24X
Fiche 50-352, 82/12/17, 8212210491

G Inspection reports, IE Bulletins & correspondence

8208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BHR Plants" Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc
112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240

DOCKETED ITEMS

B208190245 IE Info Notice B2-42, "Defects Observed in Panasonic Model B01 & Model B02 Thermoluminescent Dosimeters " Svc list encl
 CG88, L I Division of Fuel Facilities, Materials & Safeguards
 B2/11/05 Consolidated Edison Co. of New York, Inc 110pp
 14372 142 24X Fiche 50-000, B2/11/05, B208190245

B208190251 IE Info Notice B2-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl
 JORDAN, E L Division of Engineering & Quality Assurance B2/11/18
 Consolidated Edison Co. of New York, Inc 109pp 16411 199 24X
 Fiche 50-000, B2/11/18, B208190251

B212070264 Forwards IE Insp Rept 50-352/B2-13 on B21004-1114 & notice of violation
 STAROSTECKI, R Division of Project & Resident Programs B2/11/23
 KENFER, J S Philadelphia Electric Co 2pp 16339 141 24X
 Fiche 50-352, B2/11/23, B212070264

--B212070265 Notice of violation from insp on B21004-1114
 * Division of Project & Resident Programs B2/11/23 1p.
 16339 143 24X Fiche 50-352, B2/11/23, B212070264

--B212070269 IE Insp Rept 50-352/B2-13 on B21004-1114 Noncompliance noted design Drawing Q88-102-H1 revised on B20930 w/o incorporating Field Change Requests H-11 559F & H-11 939F
 CHAUDHARY, S K ; GRAY, E H ; MCCABE, E C Division of Project & Resident Programs B2/11/17 6pp 16339 144 24X
 Fiche 50-352, B2/11/23, B212070264

B208190256 IE Info Notice B2-46, "Defective & Obsolete Combination Padlocks " Svc list encl
 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement B2/11/26 Consolidated Edison Co. of New York, Inc 127pp 16411 065 24X Fiche 50-000, B2/11/26, B208190256

B208190257 IE Info Notice B2-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl
 CG88, L I Division of Fuel Facilities, Materials & Safeguards
 B2/11/30 Consolidated Edison Co. of New York, Inc 356pp
 16387 028 24X Fiche 50-000, B2/11/30, B208190257

B208190259 IE Bulletin B2-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl
 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement B2/12/03 Consolidated Edison Co. of New York, Inc 113pp 16411 317 24X Fiche 50-000, B2/12/03, B208190259

B208190261 IE Info Notice B2-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl
 JORDAN, E L Division of Engineering & Quality Assurance B2/12/03
 Consolidated Edison Co. of New York, Inc 110pp 16462 064 24X
 Fiche 50-000, B2/12/03, B208190261

B208190267 IE Info Notice B2-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement B2/12/16 Consolidated Edison Co. of New York, Inc 127pp 16628 191 24X Fiche 50-000, B2/12/16, B208190267

B208190268 IE Info Notice B2-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27 " Svc list encl
 JORDAN, E L Division of Engineering & Quality Assurance B2/12/20
 Consolidated Edison Co. of New York, Inc 108pp 16628 293 24X
 Fiche 50-000, B2/12/20, B208190268

R. Periodic operating reports & related correspondence

B212290276 Revises B20921 ltr re const completion date, per NRC B10811 request for quarterly updates Const & engineering efforts support earlier const & fuel load date of Aug 1984
 BRADLEY, E J Philadelphia Electric Co B2/12/27 EISENHUT, D O.
 Division of Licensing 2pp 16581 064 24X Fiche 50-352, B2/12/27, B212290276

S. Reportable occurrences, LERs & related correspondence

B212280363 Interim deficiency rept re inadequate pressure transducers/transmitters mounted on post-LOCA hydrogen recombiners Initially reported on B21119 Final rept will be submitted by B30211 Also reported per Part 21
 MANN, S F Niagara Mohawk Power Corp B2/12/14 STAROSTECKI, R.
 Division of Project & Resident Programs 2pp 16560.058 24X
 Fiche 50-000, B2/12/14, B212280363

--B212280373 Part 21 rept re inadequate pressure transducers/transmitters mounted on post-LOCA hydrogen recombiners Transducers should be replaced w/nuclear rated transducers Engineering field bulletin to be issued by B21029
 EMPEY, D C Rockwell International Corp B2/10/21 COLLINS, J
 Region 4, Office of Director 2pp 16560 060 24X
 Fiche 50-000, B2/12/14, B212280363

T. Hearing transcripts on non-antitrust matters

B212080496 Transcript of B20818 public meeting in Pottstown, PA re environ review Pp 1-132 Supporting documentation encl
 * NRC - No Detailed Affiliation Given B2/08/18 275pp
 16333 035 24X Fiche 50-352, B2/08/18, B212080496

DOCKET 50-353 LIMERICK GENERATING STATION, UNIT 2

A. Application/construction stage documents & correspondence

B210040239 Forwards Amend 39 to application for OL (filed in PDR in Category A)
 BRADLEY, E J Philadelphia Electric Co B2/09/30 DENTON, H R
 Office of Nuclear Reactor Regulation, Director 6pp 15589 170
 24X Fiche 50-352, B2/09/30, B210040239

--B210040253 Amend 39 to application for OL, consisting of Revision 10 to FSAR, proprietary & nonproprietary Revision 1 to design assessment rept & Revision 6 to environ rept Certificate of Env encl Proprietary design rept withheld (ref 10CFR2 790)
 BOYER, V S Philadelphia Electric Co B2/09/28 7pp 15589 174
 24X Fiche 50-352, B2/09/30, B210040239

--B210040272 Revision 1 to nonproprietary design assessment rept
 * Philadelphia Electric Co B2/09/30 228pp 15590 286 24X
 Fiche 50-352, B2/09/30, B210040239

B212060097 Forwards request for addl auxilliary sys info re Revision 10 to FSAR Response should be provided within 7 days
 SCHWENCER, A Licensing Branch 2 B2/11/17 BAUER, E O
 Philadelphia Electric Co 4pp 16323 016 24X
 Fiche 50-352, B2/11/17, B212060097

B212060118 Forwards request for addl info as result of concerns raised during hearing session on Point Pleasant Diversion Project
 SCHWENCER, A Licensing Branch 2 B2/11/18 BAUER, E O
 Philadelphia Electric Co 4pp 16323 007 24X
 Fiche 50-352, B2/11/18, B212060118

B212060510 Notification of B21217 meeting w/util at Limerick Info Ctr to discuss mgt structure & technical resources audit
 ABELSON, H Licensing Branch 2 B2/11/23 SCHWENCER, A Licensing
 Branch 2 4pp 16344 016 24X Fiche 50-352, B2/11/23, B212060510

B212080015 Notification of cancellation of B21217 meeting w/util at site to discuss plant mgt structure & technical resources audit Meeting will be rescheduled
 ABELSON, H Licensing Branch 2 B2/11/23 SCHWENCER, A Licensing
 Branch 2 4pp 16367 173 24X Fiche 50-352, B2/11/23, B212080015

B212010470 Confirms B21214-17 mgt structure & technical resources audit Agenda encl
 SCHWENCER, A Licensing Branch 2 B2/11/24 BAUER, E O
 Philadelphia Electric Co 5pp 16270 215 24X
 Fiche 50-352, B2/11/24, B212010470

B212010513 Forwards E0&0 draft technical evaluation rept, "Control of Heavy Loads at Nuclear Power Plants, Limerick Generating Station Units 1 & 2," for comment
 SCHWENCER, A Licensing Branch 2 B2/11/24 BAUER, E O
 Philadelphia Electric Co 3pp 16260 168 24X
 Fiche 50-352, B2/11/24, B212010513

--B212010519 "Control of Heavy Loads at Nuclear Power Plants, Limerick Generating Station Units 1 & 2"
 MARINOAS, M ; STICKLEY, T H E0&0, Inc B2/11/30 NRC - No
 Detailed Affiliation Given 30pp 16268 171 24X
 Fiche 50-352, B2/11/24, B212010513

B212060393 Summary of B20903 meeting w/util, OE, Fauske & Associates, Inc, BNL, NUS, Science Applications, Inc, Commonwealth of PA, Limerick Ecology Action & applicant counsel in Bethesda, MD re PRA
 ABELSON, H Licensing Branch 2 B2/11/29 Licensing Branch 2
 47pp 16323 021 24X Fiche 50-352, B2/11/29, B212060393

B212060398 Summary of B20922 meeting w/util, NUTECH & BNML in Bethesda, MD re present & future corp & plant mgt structure, staffing, training plans & safety review groups
 ABELSON, H Licensing Branch 2 B2/11/29 Licensing Branch 2
 17pp 16322 318 24X Fiche 50-352, B2/11/29, B212060398

B212030122 Forwards Amend 42 to application for OL Amend revises FSAR in response to NRC B20809 ltr Certificate of Svc encl
BRADLEY, E J Philadelphia Electric Co 82/11/30 DENTON, H R
Office of Nuclear Reactor Regulation, Director 5pp 16303 283
24X Fiche 50-352, 82/11/30, B212030122

--B212030132 Amend 42 to application for OL, revising FSAR
BOYER, V S Philadelphia Electric Co 82/11/29 3pp 16303 288
24X Fiche 50-352, 82/11/30, B212030122

B212070493 Notification of B21215 meeting w/util & DNL in Bethesda, MD to discuss questions generated during review of BNL draft reg on PRA Meeting agenda encl
ABELSON, H Licensing Branch 2 82/12/01 SCHWENCER, A Licensing Branch 2 4pp 16351 355 24X Fiche 50-352, 82/12/01, B212070493

B212070025 Forwards agreement w/ARCO Pipeline Co prohibiting shipping propane through ARCO pipeline, per C Ferrell concern from Aug 1982 environ site visit
BRADLEY, E J Philadelphia Electric Co 82/12/03 SCHWENCER, A Licensing Branch 2 5pp 16327 349 24X Fiche 50-352, 82/12/03, B212070025

B212080446 Forwards draft response to NRC B20901 request for addl info to aid E Pedersen audit of util organization
BRADLEY, E J Philadelphia Electric Co 82/12/03 SCHWENCER, A Licensing Branch 2 71pp 16352 180 24X Fiche 50-352, 82/12/03, B212080446

B212160747 Forwards request for addl info re pump house noise Corrected numbers for previously submitted E290 series questions resubmitted Response requested within 7 days of ltr receipt
SCHWENCER, A Licensing Branch 2 82/12/08 BAUER, E O Philadelphia Electric Co 4pp 16466 001 24X Fiche 50-352, 82/12/08, B212160747

B212220541 Requests test case calculation for radiological risk be provided to facilitate review of PRA Case should be calculated w/version of CRAC computer code used in plant PRA
SCHWENCER, A Licensing Branch 2 82/12/13 DAUER, E O Philadelphia Electric Co 3pp 16523 357 24X Fiche 50-352, 82/12/13, B212220541

B212210402 Advises that actual scram valve characteristics will be used in preparing analysis of control rod drive sys hydrodynamic loads Analysis & complete response will be provided by H30315
BRADLEY, E J Philadelphia Electric Co 82/12/16 SCHWENCER, A Licensing Branch 2 2pp 16494 310 24X Fiche 50-352, 82/12/16, B212210402

B212210491 Forwards Amend 43 to license application (filed in PDR Category A)
BRADLEY, E J Philadelphia Electric Co 82/12/17 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 16486 048 24X Fiche 50-352, 82/12/17, B212210491

--B212210495 Amend 43 to license application consisting of Revision B to environ rept & Revision 14 to FSAR
BOYER, V S Philadelphia Electric Co 82/12/15 6pp 16486 050 24X Fiche 50-352, 82/12/17, B212210491

B212220097 Forwards DOI B21206 ltr transmitting Fish & Wildlife Svc correspondence re Point Pleasant diversion Info relates to testimony before ASLB
HODGSON, P Hearing Branch 2 82/12/20 BRENNER, L Atomic Safety and Licensing Board Panel 11pp 16516 105 24X Fiche 50-352, 82/12/20, B212220097

B212270141 Forwards summary of loss of offsite power comments presented at B21215 meeting, compilation of requests for addl info for BNL re PRA review & summary of comments on remaining issues
BOYER, V S Philadelphia Electric Co 82/12/22 EISENHUT, D O Division of Licensing 23pp 16538 312 24X Fiche 50-352, 82/12/22, B212270141

B212280209 Forwards responses to Auxiliary Sys Branch Questions 410 94 through 410 99 re spent fuel storage, transmitted by B21122 ltr Responses will be incorporated in FSAR revision scheduled for Jan 1983
BRADLEY, E J Philadelphia Electric Co 82/12/22 SCHWENCER, A Licensing Branch 2 10pp 16562 110 24X Fiche 50-352, 82/12/22, B212280209

C Utility Environmental Report (ER), amends & correspondence

B210040239 Forwards Revision 6 to environ rept (filed in PDR in Category C)
BRADLEY, E J Philadelphia Electric Co 82/09/30 DENTON, H R Office of Nuclear Reactor Regulation, Director 6pp 15589 170 24X Fiche 50-352, 82/09/30, B210040239

--B210040278 Revision 6 to environ rept
* Philadelphia Electric Co 82/09/30 20pp 15591 154 24X Fiche 50-352, 82/09/30, B210040239

B212100274 Advises that response to Siting Analysis Branch Question E310 10 will be provided via environ rept revision in Feb 1983
BRADLEY, E J Philadelphia Electric Co 82/12/07 SCHWENCER, A Licensing Branch 2 2pp 16376 147 24X Fiche 50-352, 82/12/07, B212100274

B212210491 Forwards Revision B to environ rept (filed in PDR Category C)
BRADLEY, E J Philadelphia Electric Co 82/12/17 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 16486 048 24X Fiche 50-352, 82/12/17, B212210491

--B212210498 Revision B to environ rept
* Philadelphia Electric Co 82/12/31 23pp 16486 207 24X Fiche 50-352, 82/12/17, B212210491

F Security, medical, emergency & fire protection plans

B212070138 Advises that revised fire protection evaluation rept due by Nov 1982, per B20901 commitment, delayed until Jan 1983 Delay due to substantial, unanticipated addl effort required to upgrade rept per NRC B20728 ltr
BRADLEY, E J Philadelphia Electric Co 82/12/03 SCHWENCER, A Licensing Branch 2 2pp 16327 032 24X Fiche 50-352, 82/12/03, B212070138

B212100090 Submits info per B21203 telcon request re emergency operations Facility (EOF) Response to Generic Ltr B1-10 submitted B10320 EOF const will be completed by Sept 1983
KENNER, J S Philadelphia Electric Co 82/12/06 SCHWENCER, A Licensing Branch 2 3pp 16379 240 24X Fiche 50-352, 82/12/06, B212100090

B212210398 Forwards draft FSAR page changes & responses to QA Branch B20713 request for addl info Sixteen overseas drawings encl
Appendix cards available in PDR
BRADLEY, E J Philadelphia Electric Co 82/12/17 SCHWENCER, A Licensing Branch 2 92pp 16489 324 24X Fiche 50-352, 82/12/17, B212210398

B212270144 Forwards response to NRC comments on physical security plan Response withheld (ref 10CFR279 & 10CFR73 21)
BRADLEY, E J Philadelphia Electric Co 82/12/17 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 16538 128 24X Fiche 50-352, 82/12/17, B212270144

D Adjudicatory correspondence

B212020330 Reply findings of fact & conclusions of law in form of initial decision
CONNER, T B Philadelphia Electric Co CONNER, T B Conner & Wetterhahn 82/11/30 21pp 16277 279 24X Fiche 50-352, 82/11/30, B212020330

--B212020339 Reply to Del-Aware B21117 response to ASLB request for info re flows in Schuylkill River Response inaccurate & exceeds scope of ASLB limited inquiry Del-Aware is cluttering record w/erroneous & irrelevant matl w/Certificate of Svc
CONNER, T B Philadelphia Electric Co CONNER, T B Conner & Wetterhahn 82/11/29 10pp 16277 300 24X Fiche 50-352, 82/11/30, B212020330

B212130358 Notifies that B20702 petition on behalf of Del-Aware Unlimited to suspend or revoke CPs has been denied Decision encl
DENTON, H R Office of Nuclear Reactor Regulation, Director 82/12/07 SUGARMAN, R J Sugarmann, R J 3pp 16413 008 24X Fiche 50-352, 82/12/07, B212130358

--B212130359 Director's Decision DD-B2-13 denying Del-Aware Unlimited petition to suspend & revoke CPs No major changes in facts matl to resolution of environ issues presented
DENTON, H R, CASE, E O Office of Nuclear Reactor Regulation, Director 82/12/07 42pp 16413, 011 24X Fiche 50-352, 82/12/07, B212130358

--B212130361 Notice of denial of Del-Aware Unlimited petition to suspend & revoke CPs
CASE, E O Office of Nuclear Reactor Regulation, Director 82/12/07 3pp 16413 054 24X Fiche 50-352, 82/12/07, B212130358

DOCKETED ITEMS

8212140036 Forwards NRR Director 821207 denial of Del-Aware Unlimited request for suspension or revocation of CPs per 10CFR2 202 & 2 204 W/o encl
HODGSON, A P Hearing Branch 2 82/12/10 BRENNER, L, MORRIS, P A, COLE, R F Atomic Safety and Licensing Board Panel 2pp 16409 293
24X Fiche 50-352, 82/12/10, 8212140036

8212160304 Requests encl DOI 821207 ltr to ASLB be served on parties LANE, V M Atomic Safety and Licensing Board Panel 82/12/14 STUCKY, S Docketing & Services Branch 1p 16446 039 24X
Fiche 50-352, 82/12/14, 8212160304

--8212160316 Forwards pages from "Design of Water Intake Structures for Fish Protection," re velocity difference across intake & potential for biofouling even in fresh water
MCCOY, R W Interior, Dept of, Fish & Wildlife Service 82/12/07 BRENNER, L Atomic Safety and Licensing Board Panel 8pp 16446 040 24X Fiche 50-352, 82/12/14, 8212160304

8212200114 Advises that correspondence re Miller & McCoy testimony in DL proceeding sent to ASLB Portions of transcript where Miller & McCoy testimony appears or is discussed encl W/o encl
HODGSON, A P Hearing Branch 2 82/12/17 CONTE, A R Interior, Dept of 1p 16470 184 24X Fiche 50-352, 82/12/17, 8212200114

8212230327 Advises of State court 821216 decision reversing Public Utils Commission 820827 order re Unit 2 Financing Del-Aware Unlimited, Inc preliminary injunction to enjoin work on Point Pleasant Diversion Project denied on 821215
CONNER, T B Conner & Hetterhahn CONNER, T B Philadelphia Electric Co. 82/12/17 BRENNER, L, COLE, R F, MORRIS, P A Atomic Safety and Licensing Board Panel 2pp 16505 136 24X Fiche 50-352, 82/12/17, 8212230327

8212230352 Informal discovery re Friends of the Earth/RL Anthony Contentions V-3a & V-3b admitted by ASLB on 821122
ANTHONY, R L Anthony, R L ANTHONY, R L Friends of the Earth 82/12/17 Atomic Safety and Licensing Board Panel 1p 16511 196 24X Fiche 50-352, 82/12/17, 8212230352

8212230356 Response to ASLB 821122 order re Friends of the Earth proposed contentions on hazards from industrial activities & motion to reconsider admission of Contentions 1, 2, 6, 8 & 9
ANTHONY, R L Anthony, R L ANTHONY, R L Friends of the Earth 82/12/19 Atomic Safety and Licensing Board Panel 3pp 16511 162 24X Fiche 50-352, 82/12/19, 8212230356

8212220097 Forwards DOI 821206 ltr transmitting Fish & Wildlife Svc correspondence re Point Pleasant diversion info relates to testimony before ASLB
HODGSON, A P Hearing Branch 2 82/12/20 BRENNER, L, MORRIS, P A, COLE, R F Atomic Safety and Licensing Board Panel 11pp 16516 105 24X Fiche 50-352, 82/12/20, 8212220097

8212220126 Advises that NRC will not respond to Del-Aware Unlimited 821201 request for leave to respond to applicant reply on flows in Schuylkill River re need for supplemental cooling water for one unit vs two units
HODGSON, A P Hearing Branch 2 82/12/20 BRENNER, L, MORRIS, P A, COLE, R F Atomic Safety and Licensing Board Panel 3pp 16503 026 24X Fiche 50-352, 82/12/20, 8212220126

8212270216 Notice re contract award & const starting date Mergentime, Inc awarded contract on 821215 to construct Point Pleasant intake Non-contention work will begin on 830107 Certificate of Svc & VS Boyer affidavit encl
CONNER, T B Philadelphia Electric Co CONNER, T B Conner & Hetterhahn. 82/12/21. 7pp 16536 196 24X Fiche 50-352, 82/12/21, 8212270216

8212280185 Forwards US District Court for Eastern District of PA 821217 order dismissing Del-Aware, Inc claims under Rivers & Harbors Act for lack of jurisdiction
CONNER, T B Conner & Hetterhahn CONNER, T B Philadelphia Electric Co 82/12/23 BRENNER, L, COLE, R F, MORRIS, P A Atomic Safety and Licensing Board Panel 4pp 16536 142 24X Fiche 50-352, 82/12/23, 8212280185

8212300187 Response in opposition to Friends of the Earth 821219 motion to reconsider ASLB 821122 order ruling on proposed contentions on hazards from industrial activities near site. Instant request clearly too late Certificate of Svc encl.
CONNER, T B Philadelphia Electric Co CONNER, T B Conner & Hetterhahn. 82/12/28 Atomic Safety and Licensing Board Panel 5pp 16597 330. 24X Fiche 50-352, 82/12/28, 8212300187

K Utility Final Safety Analysis Report (FSAR) & amends

8210040239 Forwards Amend 39 to application for OL (filed at PDR in Category A), consisting of Revision 10 to FSAR (Category K), Revision 6 to environ rept (Category C) & Revision 1 to design assessment rept (Category A)
BRADLEY, E J Philadelphia Electric Co 82/09/30 DENTON, H R Office of Nuclear Reactor Regulation, Director 6pp 15589 170 24X Fiche 50-352, 82/09/30, 8210040239

--8210040267 Revision 10 to FSAR
Philadelphia Electric Co 82/09/30 464pp 15589 183 24X
Fiche 50-352, 82/09/30, 8210040239

8212130341 Forwards Affidavit of Svc re distribution of Revision 13 to FSAR per DO Eisenhower 810706 ltr
BRADLEY, E J Philadelphia Electric Co 82/12/10 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 16389 282 24X Fiche 50-352, 82/12/10, 8212130341

8212210491 Forwards Amend 43 to license application (filed in PDR Category A), consisting of Revision 8 to environ rept (filed in PDR Category C) & Revision 14 to FSAR (filed in PDR Category K) Certificate of Svc encl
BRADLEY, E J Philadelphia Electric Co 82/12/17 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 16486 048 24X
Fiche 50-352, 82/12/17, 8212210491

--8212210499 Revision 14 to FSAR
Philadelphia Electric Co 82/12/31 151pp 16486 056 24X
Fiche 50-352, 82/12/17, 8212210491

Q Inspection Reports, IE Bulletins & correspondence

8208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Svc list encl
DEVOUNO, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240

8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000, 82/11/05, 8208190245

8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X
Fiche 50-000, 82/11/18, 8208190251

8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Radilocks " Svc list encl
DEVOUNO, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000, 82/11/26, 8208190256

8208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000, 82/11/30, 8208190257

8208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl
DEVOUNO, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259

8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Societs " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X
Fiche 50-000, 82/12/03, 8208190261

8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
DEVOUNO, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16, 8208190267

8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27 " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 273 24X
Fiche 50-000, 82/12/20, 8208190268

S Reportable occurrences, LERs & related correspondence

8212280363 Interim deficiency rept re inadequate pressure transducers/transmitters mounted on post-LOCA hydrogen recombiners
Initially reported on 821119 Final rept will be submitted by
030211 Also reported per Part 21
MANNING, S F Niagara Mohawk Power Corp 82/12/14 STAROSTECKI, R
Division of Project & Resident Programs 2pp 16560 05B 24X
Fiche 50-000, 82/12/14, 8212280363

--8212280373 Part 21 rept re inadequate pressure transducers/transmitters mounted on post-LOCA hydrogen recombiners Transducers should be replaced w/nuclear rated transducers Engineering field bulletin to be issued by 821029
EMPEY, D C Rockwell International Corp 82/10/21 COLLINS, J
Region 4, Office of Director 2pp 16560 060 24X
Fiche 50-000, 82/12/14, 8212280363

T Hearing transcripts on non-antitrust matters

8212080496 Transcript of 820818 public meeting in Pottstown, PA re environ review Pp 1-132 Supporting documentation encl
* NRC - No Detailed Affiliation Given 82/08/18 275pp
16353 035 24X Fiche 50-352, 82/08/18, 8212080496

DOCKET 50-354 HOPE CREEK NUCLEAR STATION, UNIT 1

A Application/construction stage documents & correspondence

8212300072 Notification of 830104 significant licensee meeting w/util for presentation of QA organizational & functional changes
TRIPP, L E Division of Project & Resident Programs 82/12/21
Division of Project & Resident Programs 2pp 16624 280 24X
Fiche 50-000, 82/12/21, 8212300072

8212270135 Advises that Rept 82-13B, "Hope Creek Generating Station Recirculation Sys Crack Stability/LLB," contains no proprietary info
PARIS, P C Fracture Proof Design Corp 82/12/22 WAGNER, D
Licensing Branch 2 1p 16538 016 24X Fiche 50-354, 82/12/22, 8212270135

C Utility Environmental Report (ER), amends & correspondence

8212010349 Notification of 821202 meeting w/util, Bechtel & Fracture Proof Design Corp in Bethesda, MD to discuss drywell jet impingement barriers & alternatives re OL environ rept
Agenda encl
WAGNER, D Licensing Branch 2 82/11/26 SCHWENCER, A Licensing Branch 2 4pp 16271 329 24X Fiche 50-354, 82/11/26, 8212010349

G Adjudicatory correspondence

8212140186 Request for extension of time until 821224 to file petition for review of ALAB-701 Time necessary due to holidays, sickness & vacations Certificate of Svc encl
JOHNSRUD, J H Environmental Coalition on Nuclear Power 82/12/08
Commissioners 4pp 16403 167 24X Fiche 50-000, 82/12/08, 8212140186

8212140438 Order extending time until 821227 for TH1 & Peach Bottom intervenors to file petition for review of ALAB-701
CHILK, B J Office of the Secretary of the Commission 82/12/13
Environmental Coalition on Nuclear Power 1p 16404 360 24X
Fiche 50-000, 82/12/13, 8212140438

8212210009 Advises that intervenor petition for review of ALAB-701 should be served on NRC when filed
BORDENICK, B M Hearing Branch 3 82/12/16 JOHNSRUD, J
Affiliation Unknown 2pp 16486 005 24X Fiche 50-000, 82/12/16, 8212210009

8212300134 Petition for review of consolidated radon proceedings
Commission should grant financial assistance to intervenors, should reopen record on all issues & remand case for full consideration Certificate of Svc encl
JOHNSRUD, J H Environmental Coalition on Nuclear Power 82/12/27
Commissioners 19pp 16598 112 24X Fiche 50-000, 82/12/27, 8212300134

O. Inspection reports, IE Bulletins & correspondence

8208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co. of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240

8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co. of New York, Inc 110pp 16372 142 24X Fiche 50-000, 82/11/05, 8208190245

8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co. of New York, Inc 107pp 16411 199 24X
Fiche 50-000, 82/11/18, 8208190251

8212020051 Notification of contract execution Task Order 27 to "Technical Assistance to Support NRC IE Personnel in Investigations of Incidents," awarded to Parameter, Inc
WOLLETT, B Research Contracts Branch FIN 0-1302 82/11/18
BLAHA, J Director's Office, Office of Inspection and Enforcement 10FY, R NRC - No Detailed Affiliation Given 1p 16317 091 24X
Fiche 50-354, 82/11/18, 8212020051

--8212020057 Ltr contract issuing Task Order 27 to, "Technical Assistance to Support NRC IE Personnel in Investigations of Incidents " GUSTAVE, R P Research Contracts Branch FIN 0-1302 82/11/10
LOFF, R A Parameter, Inc 4pp 16317 092 24X
Fiche 50-354, 82/11/18, 8212020051

8212020006 Notification of 821207 significant licensee meeting w/util in Hancock Bridge, NJ to discuss BALP
TRIPP, L E Region 1, Office of Director 82/11/19 Region 1, Office of Director 1p 16308 362 24X Fiche 50-354, 82/11/19, 8212020006

8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co. of New York, Inc 127pp 16411 065 24X Fiche 50-000, 82/11/26, 8208190256

8208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co. of New York, Inc 336pp 16387 02B 24X Fiche 50-000, 82/11/30, 8208190257

8212160024 Responds to IE Bulletin 81-02, Suppl 1, "Failure of Gate Type Valves to Close Against Differential Pressure " All vendors, including NSSS supplier confirm that no Westinghouse gate valves used in safety-related applications at facility
MARTIN, T J Public Service Electric & Gas Co. of New Jersey 82/12/01 HAYNES, R C Region 1, Office of Director 3pp 16446 216 24X Fiche 50-354, 82/12/01, 8212160024

8208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co. of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259

8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Baskets " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co. of New York, Inc 110pp 16462 064 24X
Fiche 50-000, 82/12/03, 8208190261

8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co. of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16, 8208190267

8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27 " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co. of New York, Inc 108pp 16628 293 24X
Fiche 50-000, 82/12/20, 8208190268

8212290436 Ack receipt of 821201 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-354/82-12
STAROSTECKI, R Division of Project & Resident Programs 82/12/22
MARTIN, T J Public Service Electric & Gas Co. of New Jersey 1p 16585 197 24X Fiche 50-354, 82/12/22, 8212290436

--8212290444 Responds to NRC 821103 ltr re violations noted in IE Insp Rept 50-354/82-12 Corrective actions Varglass tie wraps replaced w/Tefzel wraps & motor control ctrs cleaned, removing cut Varglass wraps & strands
MARTIN, T J Public Service Electric & Gas Co. of New Jersey 82/12/01 HAYNES, R C Region 1, Office of Director 3pp 16585 198 24X Fiche 50-354, 82/12/22, 8212290436

DOCKETED ITEMS

R Periodic operating reports & related correspondence

B212280067 Advises that const progress approx 58% complete as of Nov 1982 Fuel load date scheduled for Jan 1986
LANDRIEU, P R Public Service Electric & Gas Co of New Jersey
82/12/15 TRIPPL, E Division of Project & Resident Programs 1p
16564 234 24X Fiche 50-354, 82/12/15, B212280067

S Reportable occurrences, LERs & related correspondence

B212080502 Deficiency rept re significant const deficiency underestimated annulus pressurization loads Initially reported on 821028 Independent technical review of design calculations performed
MARTIN, T J Public Service Electric & Gas Co of New Jersey
82/11/29 HAYNES, R C Region 1, Office of Director 2pp
16352 120 24X Fiche 50-354, 82/11/29, B212080502

DOCKET 50-355 HOPE CREEK NUCLEAR STATION, UNIT 2A Application/construction stage documents & correspondence

B212270135 Advises that Rept 82-13B, "Hope Creek Generating Station Recirculation Sys Crack Stability/LLB," contains no proprietary info.
PARIS, P C Fracture Proof Design Corp 82/12/22 WAGNER, D
Licensing Branch 2 1p 16538 016 24X Fiche 50-354, 82/12/22, B212270135

C Utility Environmental Report (ER), amends & correspondence

B212010349 Notification of 821202 meeting w/util, Bechtel & Fracture Proof Design Corp in Bethesda, MD to discuss drywell jet impingement barriers & alternatives re OL environ rept
Agenda encl
WAGNER, D, Licensing Branch 2 82/11/26 SCHWENGER, A Licensing Branch 2 4pp 16271-329 24X Fiche 50-354, 82/11/26, B212010349

Q Adjudicatory correspondence

B212140186 Request for extension of time until 821224 to file petition for review of ALAB-701 Time necessary due to holidays, sickness & vacations Certificate of Bvc encl
JOHNSRUD, J H Environmental Coalition on Nuclear Power 82/12/08 Commissioners 4pp 16403 167 24X Fiche 50-000, 82/12/08, B212140186

B212140438 Order extending time until 821227 for TMI & Peach Bottom intervenors to file petition for review of ALAB-701
CHILK, S J Office of the Secretary of the Commission 82/12/13 Environmental Coalition on Nuclear Power 1p 16404 360 24X Fiche 50-000, 82/12/13, B212140438

B212210009 Advises that intervenor petition for review of ALAB-701 should be served on NRC when filed
BORDENICK, B M Hearing Branch 3 82/12/16 JOHNSRUD, J Affiliation Unknown 2pp 16486 005 24X Fiche 50-000, 82/12/16, B212210009

B212300134 Petition for review of consolidated radon proceedings Commission should grant financial assistance to intervenors, should reopen record on all issues & remand case for full consideration Certificate of Bvc encl.
JOHNSRUD, J H Environmental Coalition on Nuclear Power 82/12/27 Commissioners 18pp 16598, 112 24X Fiche 50-000, 82/12/27, B212300134

G. Inspection reports, IE Bulletins & correspondence

B208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel Recirculation Sys Piping at BWR Plants." Bvc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, B208190240

B208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model B01 & Model B02 Thermoluminescent Dosimeters." Bvc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/09 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000, 82/11/09, B208190245

B208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements" Bvc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X Fiche 50-000, 82/11/18, B208190251

B208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks" Bvc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000, 82/11/26, B208190256

B208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl" Bvc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000, 82/11/30, B208190257

B212160024 Responds to IE Bulletin 81-02, Suppl 1, "Failure of Gate Type Valves to Close Against Differential Pressure" All vendors, including NSSB supplier confirm that no Westinghouse gate valves used in safety-related applications at facility
MARTIN, T J Public Service Electric & Gas Co of New Jersey 82/12/01 HAYNES, R C Region 1, Office of Director 3pp 16446 216 24X Fiche 50-354, 82/12/01, B212160024

B208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies" Bvc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, B208190259

B208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets" Bvc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X Fiche 50-000, 82/12/03, B208190261

B208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring" Bvc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16, B208190267

B208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27" Bvc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X Fiche 50-000, 82/12/20, B208190268

S Reportable occurrences, LERs & related correspondence

B212080502 Deficiency rept re significant const deficiency underestimated annulus pressurization loads Initially reported on 821028 Independent technical review of design calculations performed
MARTIN, T J Public Service Electric & Gas Co of New Jersey 82/11/29 HAYNES, R C Region 1, Office of Director 2pp 16352 120 24X Fiche 50-354, 82/11/29, B212080502

DOCKET 50-356 UNIV OF ILLINOIS LOPRA RESEARCH REACTORQ Inspection reports, IE Bulletins & correspondence

B212140396 Forwards IE Safeguards Insp Repts 50-151/82-01, 50-356/82-02 & 70-0258/82-01 on 821117-19 & notice of violation Insp rept details withheld (ref 10CFR2 790)
MILLER, J R Division of Engineering & Technical Programs 82/12/09 MILEY, G H Illinois, Univ of, Urbana-Champaign 2pp 16404 344 24X Fiche 50-151, 82/12/09, B212140396

--B212140399 Notice of violation from insp on 821117-19
MILLER, J R Division of Engineering & Technical Programs 82/12/09 1p 16404 346 24X Fiche 50-151, 82/12/09, B212140396

--B212140414 IE Safeguards Insp Repts 50-151/82-01, 50-356/82-02 & 70-0258/82-01 on 821117-19 Noncompliance noted failure to include items containing ENM on annual inventory & to submit 742 forms Details withheld (ref 10CFR2 790)
MADEJA, T J, CREED, J R Division of Engineering & Technical Programs 82/12/06 1p 16404 347 24X Fiche 50-151, 82/12/09, B212140396

DOCKET 50-358 WILLIAM H ZIMMER NUCLEAR STATION, UNIT 1A Application/construction stage documents & correspondence

B21230066 Generic Ltr 82-27 to all BWR licensees of operating reactors except LACBWR, Big Rock Point, Dresden 1, Humboldt Bay, applicants for OL & holders of CP re transmittal of NUREG-0763 & NUREG-0783 Bvc list encl W/o stated encl
EISENHUT, D G Division of Licensing 82/11/15 General Public Utilities - OPU Service Corp 22pp 16387 004 24X Fiche 50-000, 82/11/15, B21230066

8212010087 Application to amend CRR-88, extending const completion date to 841231 to permit resolution of quality conformation program deficiencies noted in 810408 immediate action ltr & 811124 notice of violation & to resolve mgt & QA concerns
BORGMANN, E A Cincinnati Gas & Electric Co 82/11/24 DENTON, H R
Office of Nuclear Reactor Regulation, Director 4pp 16260 272
24X Fiche 50-358, 82/11/24, 8212010087

8212010530 Staff requirements memo re Commissioners 821123 affirmation/ discussion & vote in Washington, DC on SECY-82-449 & SECY-82-425 Petition to disqualify NRC atty from Zimmer proceeding denied
CHILK, S J Office of the Secretary of the Commission 82/11/24
Office of the Secretary of the Commission 2pp 16270 268 24X
Fiche 50-358, 82/11/24, 8212010530

8212020004 Summary of 821103 meeting w/ util in Bethesda, MD re environ qualification rept for Class IE equipment NRC requested conditionally qualified equipment be qualified
KINTNER, L L Licensing Branch 1 82/11/24 Licensing Branch 1
App 16317 085 24X Fiche 50-358, 82/11/24, 8212020004

8212030253 Board Notification 82-105 forwards RH Vollmer 820930 memo to BG Eisenhut re alleged design deficiency in ASME Code Class I piping Effects of local pipe wall stresses due to support loads introduced by pipe clamps not evaluated properly
EISENHUT, D G Division of Licensing 82/11/24 PALLADINO, N J
Commissioners 2pp 16316 240 24X Fiche 50-000, 82/11/24, 8212030253

--8212030265 Discusses alleged design deficiency in ASME Code Class I piping Failure to deal w/ pipe support-pipe interface design issue would be serious matter if substantiated Ofc of Investigations will assist in evaluation
VOLLMER, R H Division of Engineering 82/09/30 EISENHUT, D G
Division of Licensing 3pp 16316 247 24X Fiche 50-000, 82/11/24, 8212030265

8212070458 Forwards request for addl info to be submitted to Mechanical Engineering Branch in form of revision to FSAR & to Equipment Qualification Branch in form of revision to 820716 environ qualification rept Response due in 7 days
YOUNGBLOOD, D J Licensing Branch 1 82/11/29 BORGMANN, E A
Cincinnati Gas & Electric Co 5pp 16355 348 24X
Fiche 50-358, 82/11/29, 8212070458

8212020256 Forwards 50 oversize P&ID drawings, per Revision 89 of FSAR, scheduled for submittal on 821203 Drawing revision list encl Aperture cards are available in PDR
RAITHMONI, P J Sargent & Lundy, Inc 82/11/30 DICK, O NRC - No
Detailed Affiliation Given 5pp 16279 133 24X
Fiche 50-358, 82/11/30, 8212020256

8212140335 Responds to 821118 ltr & 821122 revision requesting concurrence prior to performing 16 activities Clarifies activities considered nonsafety-related & others needing approval on case-by-case basis
KEPPLER, J O Region 3, Office of Director 82/11/30 BORGMANN, E A
Cincinnati Gas & Electric Co 3pp 16402 001 24X
Fiche 50-358, 82/11/30, 8212140335

--8212140340 Requests concurrence prior to performance on nonconst items under 821112 show cause order for immediate suspension of essential const
BORGMANN, E A Cincinnati Gas & Electric Co 82/11/18
KEPPLER, J O Region 3, Office of Director 2pp 16402 004 24X
Fiche 50-358, 82/11/30, 8212140335

--8212140342 Requests deletion of Items 9 & 15 from 821118 ltr as items do not constitute physical const as covered by show cause order
BORGMANN, E A Cincinnati Gas & Electric Co 82/11/22
KEPPLER, J O Region 3, Office of Director 2pp 16402 006 24X
Fiche 50-358, 82/11/30, 8212140335

8212090094 Amend 142 to DL application, consisting of Revision 89 to FSAR
BORGMANN, E A Cincinnati Gas & Electric Co 82/12/03 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 16358 001
24X Fiche 50-358, 82/12/03, 8212090094

8212170080 Forwards Certificate of Bvc of Amend 142 to DL application, in form of Revision 89 to FSAR
BORGMANN, E A Cincinnati Gas & Electric Co 82/12/10 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 16453 009
24X Fiche 50-358, 82/12/10, 8212170080

8212270424 Forwards comments on Bechtel 821123 proposal to perform independent review of util mgt required by Commission 821112 Order CL1-82-30
EISENHUT, D G Division of Licensing 82/12/16 KEPPLER, J O
Region 3, Office of Director 3pp 16589 297 24X
Fiche 50-358, 82/12/16, 8212270424

--8212270429 Requests comments on util 821126 request for approval of Bechtel as independent reviewer to fulfill requirements in Commission 821112 show cause order
KEPPLER, J O Region 3, Office of Director 82/12/02
CUNNINGHAM, G H Office of the Executive Legal Director
DENTON, H R Office of Nuclear Reactor Regulation, Director
DEVOUND, R C Director's Office, Office of Inspection and Enforcement 1p 16589 300 24X Fiche 50-358, 82/12/16, 8212270424

--8212270434 Proposes Bechtel as independent reviewer per Commission 821112 show cause order requirements & transmits program for independent review of mgt
DICKHONER, W H Cincinnati Gas & Electric Co 82/11/26
KEPPLER, J O Region 3, Office of Director 4pp 16589 301 24X
Fiche 50-358, 82/12/16, 8212270424

8212290420 Responds to 821012 ltr re position on conduct of self-initiated audit of engineering & const programs Details of audit plan in lieu of self-initiated plan requested
WARRICK, R F Region 3, Office of Director 82/12/27 BORGMANN, E A
Cincinnati Gas & Electric Co 2pp 16585 192 24X
Fiche 50-358, 82/12/27, 8212290420

--8212290425 Informs that INPO self-initiated audit will not be conducted at facility Double insp & in-house audits planned
BORGMANN, E A Cincinnati Gas & Electric Co 82/10/12
KEPPLER, J O Region 3, Office of Director 1p 16585 194 24X
Fiche 50-358, 82/12/27, 8212290420

F Security, medical, emergency & fire protection plans

8212090027 Releases public version of revised emergency plan & revision to "Design Submittal - Emergency Response Facilities"
FELTON, J M Division of Rules and Records 82/12/02, Document Management Branch 1p 16335 197 24X Fiche 50-358, 82/12/02, 8212090027

--8212090028 Forwards public version of Revision 2 to emergency plan & Revision 1 to "Design Submittal - Emergency Response Facilities"
BORGMANN, E A Cincinnati Gas & Electric Co 82/11/19
DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 16385 198 24X Fiche 50-358, 82/12/02, 8212090027

--8212090031 Public version of Revision 2 to emergency plan
* Cincinnati Gas & Electric Co 82/11/30 397pp 16385 202
24X Fiche 50-358, 82/12/02, 8212090027

--8212090034 Public version of Revision 1 to "Design Submittal - Emergency Response Facilities"
* Cincinnati Gas & Electric Co * Columbus & Southern Ohio Electric Co * Dayton Power & Light Co 82/08/31 125pp 16386 239 24X Fiche 50-358, 82/12/02, 8212090027

8212080472 Confirms 821202 telcon to L Kintner re emergency preparedness review Response to Generic Ltr 81-10 sent on 810512 Permanent primary emergency operations facility described
BORGMANN, E A Cincinnati Gas & Electric Co 82/12/03 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 16352 256 24X
Fiche 50-358, 82/12/03, 8212080472

8212080001 Forwards Meteorology & Effluent Treatment Branch request for addl info re gaseous effluent transport to continue DL application review FSAR amend requested by 830601
YOUNGBLOOD, D J Licensing Branch 1 82/12/06 BORGMANN, E A
Cincinnati Gas & Electric Co 4pp 16368 302 24X
Fiche 50-358, 82/12/06, 8212080001

8212210541 Releases public version of Revision 2 to emergency plan & Revision 1 to "Design Submittal - Emergency Response Facilities"
FELTON, J M Division of Rules and Records 82/12/10 Document Management Branch 1p 16502 270 24X Fiche 50-358, 82/12/10, 8212210541

--8212210543 Forwards public version of Revision 2 to emergency plan & Revision 1 to "Design Criteria - Emergency Response Facilities" w/o encl
BORGMANN, E A Cincinnati Gas & Electric Co 82/11/29
DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 16502, 271 24X Fiche 50-358, 82/12/10, 8212210541

8212220306 Discusses layout of communications equipment required in control room, onsite technical support ctr & near-site emergency operations facility
KEPPLER, J O Region 3, Office of Director 82/12/16
Commonwealth Edison Co 3pp 16503 351 24X Fiche 50-000, 82/12/16, 8212220306

DOCKETED ITEMS

G Adjudicatory correspondence

8212010040 Ack receipt of 821103 ltr estimating completion date of FEHA final finding per 44CFR330 Ltr forwarded to ASLB & parties Estimate of interim findings of sufficient finality requested
TRESBY, S A Hearing Branch 1 82/11/30 CASSIDY, B Federal Emergency Management Agency 1p 16260 333 24X
Fiche 50-358, 82/11/30, 8212010040

8212020382 Response supporting Zimmer Area Citizens - Zimmer Area Citizens of KY & City of Mentor, KY 821119 petitions for appointment of consultant to monitor third party audit & for public participation procedures Certificate of Svc encl
DEVINE, T B, BERNABEI, L Miami Valley Power Project 82/11/30 Commissioners 9pp 16278 104 24X Fiche 50-358, 82/11/30, 8212020382

8212070184 Resolution of City of Mentor, KY in support of ZAC/ZACK & City of Mentor 821119 joint intervention petition Public participation necessary ingredient in meaningful attempt to resolve difficulties Certificate of Svc encl
STRASINGER, R J, YOUNG, G Mentor, KY 82/12/02 3pp 16335 259 24X
Fiche 50-358, 82/12/02, 8212070184

8212080288 Answer opposing Zimmer Area Citizens/Zimmer Area Citizens of KY 821119 petition for appointment of consulting firm to review & monitor third-party audit Commission considered same grounds in issuing CLI-82-33 W/Certificate of Svc
WETTERHAHN, M J Cincinnati Gas & Electric Co WETTERHAHN, M J Conner & Wetterhahn 82/12/06 Commissioners 12pp 16354 213 24X Fiche 50-358, 82/12/06, 8212080288

8212090073 Answer consenting to Commission 821112 show cause order & order immediately suspending const Consent should not be taken as admission of truth of factual assertions or conclusions in order Certificate of Svc encl
WETTERHAHN, M J Cincinnati Gas & Electric Co WETTERHAHN, M J Conner & Wetterhahn 82/12/07 7pp 16357 355 24X
Fiche 50-358, 82/12/07, 8212090073

8212090222 Response to applicant brief supporting applicant revised exceptions ASLB erred in determining further proceedings re evacuation of schools in Clermont & Campbell Counties necessary Certificate of Svc encl
BARTH, C A Hearing Branch 1 82/12/08 Atomic Safety and Licensing Appeal Panel 42pp 16363 037 24X Fiche 50-358, 82/12/08, 8212090222

8212140205 Memorandum supporting Zimmer Area Citizens-Zimmer Area Citizens of KY & City of Mentor, KY 821119 petition for appointment of consulting firm to review & monitor third-party audit Certificate of Svc encl
WOLIVER, J D Frankhauser, D D WOLIVER, J D Wolliver, J D 82/12/10 Commissioners 4pp 16408 332 24X Fiche 50-358, 82/12/10, 8212140205

8212150032 Order scheduling 830110 oral argument on applicant appeal from ASLB 820421 initial decision & from 820824 memorandum & order in Bethesda, MD Each side allocated 90 minutes
SHOENAKER, C J Atomic Safety and Licensing Appeal Panel 82/12/13 3pp 16421 243 24X Fiche 50-358, 82/12/13, 8212150032

8212160241 Errata to NRC response to applicant brief supporting applicant exceptions Certificate of Svc encl
BARTH, C A Hearing Branch 1 82/12/15 Atomic Safety and Licensing Appeal Panel 3pp 16446 126 24X Fiche 50-358, 82/12/15, 8212160241

8212200089 Answer opposing Miami Valley Power Project 821130 petition to establish detailed structure for public participation through audit Intervenor fails to demonstrate process necessary to carry out NRC goals Certificate of Svc encl
WETTERHAHN, M J Cincinnati Gas & Electric Co WETTERHAHN, M J Conner & Wetterhahn 82/12/16 Commissioners 7pp 16473 297 24X Fiche 50-358, 82/12/16, 8212200089

8212230367 Notice of oral argument on application for appeal from ASLB 820621 initial decision & 820824 memorandum & order Argument will be heard on 830110 in Bethesda, MD
SHOENAKER, C J Atomic Safety and Licensing Appeal Panel 82/12/21 1p 16511 203 24X Fiche 50-358, 82/12/21, 8212230367

8212280191 Advises that M Sinclair will not respond to applicant 821210 objections to interrogatories prior to completion of NRC investigation of Zimmer Area Citizens of KY issues
BISHOP, L L Harmon & Weiss BISHOP, L L Sinclair, M 82/12/21 BECHHOEFER, C HARBOUR, J, COWAN, F P Atomic Safety and Licensing Board Panel 1p 16562 303 24X Fiche 50-358, 82/12/21, 8212280191

8212300244 Staff requirements memo summarizing 821214 affirmation/discussion & vote in Washington, DC re citizens petition for consulting firm svcs to monitor procedures instituted per show cause order Petition denied
CHILK, S J Office of the Secretary of the Commission 82/12/22 Office of the Secretary of the Commission 1p 16612 334 24X
Fiche 50-358, 82/12/22, 8212300244

8212270241 Order CLI-82-40, denying Zimmer Area Citizens/Zimmer Area Citizens of KY 821119 motion to have util provide svcs of consulting firm to monitor procedures per Order CLI-82-33 & motion for review of independent entity selection
CHILK, S J Office of the Secretary of the Commission 82/12/23 Zimmer Area Citizens - Zimmer Area Citizens of KY 5pp 16537 155 24X Fiche 50-358, 82/12/23, 8212270241

8212280128 Supplemental memorandum in support of Miami Valley Power Project 820820 petition for reconsideration of Commission 820730 order & motion for notification of all future third-party communications Certificate of Svc encl
DEVINE, T B, BERNABEI, L Miami Valley Power Project DEVINE, T B Government Accountability Project 82/12/23 Commissioners 24pp 16564 035 24X Fiche 50-358, 82/12/23, 8212280128

H General correspondence

8212270315 Addl response to FOIA request for tape recordings of interviews w/ F Dils on 810225 & 0604 & any other recordings re facility investigation Forwards Magnaflux Corp tape & disclaimer re Applegate/Alldredge ssde of tape W/o encls
FELTON, J M Division of Rules and Records 82/11/12 HICKEY, J B Shaw, Pittman, Potts & Trowbridge 1p 16555 321 24X
Fiche 50-358, 82/11/16, 8212270315

J Insurance & indemnity information

8212280205 Forwards Endorsement 21 to NELIA Policy NF-249
BUCKLES, J Marsh & McLennan, Inc M & M Nuclear Consultants, Inc Div 82/12/20 SALTZMAN, J Office of State Programs, Director 2pp 16562 287 24X Fiche 50-358, 82/12/20, 8212280205

K Utility Final Safety Analysis Report (FSAR) & amends

8212090094 Amend 142 to OL application, consisting of Revision B9 to FSAR
BORGMANN, E A Cincinnati Gas & Electric Co 82/12/03 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 16398 001 24X Fiche 50-358, 82/12/03, 8212090094

--8212090096 Revision B9 to FSAR
Cincinnati Gas & Electric Co 82/12/31 167pp 16398 003 24X Fiche 50-358, 82/12/03, 8212090094

8212170080 Forwards Certificate of Svc of Amend 142 to OL application, in form of Revision B9 to FSAR
BORGMANN, E A Cincinnati Gas & Electric Co 82/12/10 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 16493 009 24X Fiche 50-358, 82/12/10, 8212170080

G Inspection reports, IE Bulletins & correspondence

8208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel Recirculation Sys Piping at BWR Plants " Svc list encl
DEVOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240

8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list encl
COBB, L J Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000, 82/11/05, 8208190245

8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 179 24X
Fiche 50-000, 82/11/18, 8208190251

8212010089 Application to amend CPR-88, extending const completion date to 841231 to permit resolution of quality confirmation program deficiencies noted in 810408 immediate action ltr & 811124 notice of violation & to resolve mgt & QA concerns
BORGMANN, E A Cincinnati Gas & Electric Co 82/11/24 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 16260 272 24X Fiche 50-358, 82/11/24, 8212010089

8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000, 82/11/26, 8208190256

8208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000, 82/11/30, 8208190257

8212060025 Ack receipt of 820721 & 0816 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 50-358/82-05
WARNICK, R F Region 3, Office of Director 82/11/30 BORGMANN, E A Cincinnati Gas & Electric Co 1p 16313 327 24X Fiche 50-358, 82/11/30, 8212060025

--8212060030 Responds to NRC 820701 ltr re violations noted in IE Insp Rept 50-358/82-05 Corrective actions notification of potentially reportable item forms received prior to violation reviewed & GA procedures revised
BORGMANN, E A Cincinnati Gas & Electric Co 82/07/21 KEPLER, J Q Region 3, Office of Director 2pp 16313 330 24X Fiche 50-358, 82/11/30, 8212060025

--8212060039 Suppl 820721 response to NRC 820701 ltr re violations noted in IE Insp Rept 50-358/82-05 Addl training will be provided for site personnel re reporting requirements of 10CFR50 55(e) Training to be completed by 820730
BORGMANN, E A Cincinnati Gas & Electric Co 82/08/14 KEPLER, J Q Region 3, Office of Director 2pp 16313 332 24X Fiche 50-358, 82/11/30, 8212060025

8208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259

8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X Fiche 50-000, 82/12/03, 8208190261

8212210027 Ack receipt of 820506 ltr supplementing 800506 response to IE Insp Rept 50-358/80-05 All required QC insps & evaluations/dispositions must be completed prior to initiating design document change
NORELIUS, C E Division of Engineering & Technical Programs 82/12/15 BORGMANN, E A Cincinnati Gas & Electric Co 2pp 16486 001 24X Fiche 50-358, 82/12/15, 8212210027

--8212210031 Suppl 800506 ltr responding to violations noted in IE Insp Rept 50-358/80-05 All design document changes will receive R&L Engineering site approval under existing procedures prior to final acceptance
BORGMANN, E A Cincinnati Gas & Electric Co 82/05/06 KEPLER, J Q Region 3, Office of Director 2pp 16486 003 24X Fiche 50-358, 82/12/15, 8212210027

8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16, 8208190267

8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27 " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X Fiche 50-000, 82/12/20, 8208190268

8212280166 Notifies that use of generic nonconformance repts conforms w/820927 commitment to perform 100% review of surveillance & nonconformance repts written by contractor Evaluations of exception correction notices ensure initiation of repts
WARNICK, R F Region 3, Office of Director 82/12/23 BORGMANN, E A Cincinnati Gas & Electric Co 2pp 16563 332 24X Fiche 50-358, 82/12/23, 8212280166

--8212280171 Submits summary of 820902 agreements re document reviews Quality confirmation program personnel should perform review after NJ Kaiser review of action items Quality confirmation personnel will review correction notices
BORGMANN, E A Cincinnati Gas & Electric Co 82/09/29 KEPLER, J Q Region 3, Office of Director 1p 16563 334 24X Fiche 50-358, 82/12/23, 8212280166

8212290341 Ack receipt of 820812 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-358/82-03
WARNICK, R F Region 3, Office of Director 82/12/27 BORGMANN, E A Cincinnati Gas & Electric Co 1p 16586 184 24X Fiche 50-358, 82/12/27, 8212290341

--8212290343 Responds to IE Insp Rept 50-358/82-03 Completion dates for committed actions clarified & supplemental info provided
BORGMANN, E A Cincinnati Gas & Electric Co 82/08/12 KEPLER, J Q Region 3, Office of Director 3pp 16586 185 24X Fiche 50-358, 82/12/27, 8212290341

8212290381 Ack receipt of 820804 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-358/82-01
WARNICK, R F Region 3, Office of Director 82/12/27 BORGMANN, E A Cincinnati Gas & Electric Co 2pp 16585 158 24X Fiche 50-358, 82/12/27, 8212290381

--8212290429 Documents 820721 telcon re response to IE Insp Rept 50-358/82-01 Response will be submitted by 820806 per agreement w/NRC Delay needed due to extensive evaluation required to address Commission concerns
BORGMANN, E A Cincinnati Gas & Electric Co 82/08/02 KEPLER, J Q Region 3, Office of Director 1p 16585 160 24X Fiche 50-358, 82/12/27, 8212290381

--8212290454 Responds to NRC 820624 ltr re violations noted in IE Insp Rept 50-358/82-01 Corrective actions GA job descriptions re-evaluated & qualifications & procedures for cable pulling & wire termination insps revised
BORGMANN, E A Cincinnati Gas & Electric Co 82/08/04 KEPLER, J Q Region 3, Office of Director 16pp 16585 161 24X Fiche 50-358, 82/12/27, 8212290381

R Periodic operating reports & related correspondence

8212170107 Advises that project is 98 27 complete as of 820928 Actual dates & activity status encl
BORGMANN, E A Cincinnati Gas & Electric Co 82/10/26 KEPLER, J Q Region 3, Office of Director 6pp 16450 305 24X Fiche 50-358, 82/10/26, 8212170107

8212170191 Advises that project considered 98 3X complete as of 821026 Actual dates & activity status encl
BORGMANN, E A Cincinnati Gas & Electric Co 82/11/09 KEPLER, J Q Region 3, Office of Director 6pp 16450 178 24X Fiche 50-358, 82/11/09, 8212170191

8212080595 Forwards monthly status rept for Oct 1982
DIRCKS, W J Office of the Executive Director for Operations 82/12/03 PALLADINO, N J Commissioners 1p 16372 259 24X Fiche 50-358, 82/12/03, 8212080595

--8212080597 "Zimmer Monthly Status Rept," Oct 1982
* Region 3, Office of Director 82/10/31 37pp 16372 260 24X Fiche 50-358, 82/12/03, 8212080595

S Reportable occurrences, LERs & related correspondence

8212020367 Interim deficiency rept re failure of fusible links in fire dampers mfg by Air Balance, Inc initially reported on 821029 Engineering evaluation continuing Next rept will be submitted by 830131
BORGMANN, E A Cincinnati Gas & Electric Co 82/11/16 KEPLER, J Q Region 3, Office of Director 2pp 16278 140 24X Fiche 50-358, 82/11/16, 8212020367

8212020225 Interim deficiency rept re discrepancies in dynamic analysis in small bore piping Initially reported on 821026 Audit of simplified dynamic analysis procedures continuing Next rept will be submitted by 830228
BORGMANN, E A Cincinnati Gas & Electric Co 82/11/19 KEPLER, J Q Region 3, Office of Director 2pp 16274 092 24X Fiche 50-358, 82/11/19, 8212020225

8212020257 Interim deficiency rept re seismic clearance Initially reported on 821029 Insp procedure for pipe support installation does not contain proper seismic clearance criteria Walkdown to be performed Next rept due by 830731
BORGMANN, E A Cincinnati Gas & Electric Co 82/11/19 KEPLER, J Q Region 3, Office of Director 2pp 16279 319 24X Fiche 50-358, 82/11/19, 8212020257

8212030111 Interim deficiency rept re OE panel installations Condition not reportable per 10CFR50 55(e) or Part 21 Plant safety not compromised Separation requirements not necessary Final rept expected by 830117
BORGMANN, E A Cincinnati Gas & Electric Co 82/11/19 KEPLER, J Q Region 3, Office of Director 2pp 16303 025 24X Fiche 50-358, 82/11/19, 8212030111

DOCKETED ITEMS

8212020320 Interim deficiency rept re failure to provide procedures for installation of non-Class IE cables in panels Initially reported on 821027 Stop work order issued & procedures will be revised Next rept expected by 830131
BORGMANN, E A Cincinnati Gas & Electric Co 82/11/24 KEPPLER, J O
Region 3, Office of Director 2pp 16279 196 24X
Fiche 50-358, 82/11/24, 8212020320

8212170260 Interim deficiency rept re lack of pipe bend qualifications Initially reported on 821109 HJ Kaiser mechanical const procedure revised to allow requalification of bending operations Final rept by 830131
BORGMANN, E A Cincinnati Gas & Electric Co 82/12/08 KEPPLER, J O
Region 3, Office of Director 2pp 16456 204 24X
Fiche 50-358, 82/12/08, 8212170260

8212270190 Interim deficiency rept re lack of insp records for Nelson studs Investigation re structural adequacy of studs used on installed cable tray supports almost complete Rept detailing plans for verification of support integrity due by 821222
BORGMANN, E A Cincinnati Gas & Electric Co 82/12/15 KEPPLER, J O
Region 3, Office of Director 1p 16539 302 24X
Fiche 50-358, 82/12/15, 8212270190

8212290277 Followup to final deficiency rept re svc water sys mods Due to delay at vendor facility, pump will not be returned to site until 830331
BORGMANN, E A Cincinnati Gas & Electric Co 82/12/20 KEPPLER, J O
Region 3, Office of Director 1p 16581 066 24X
Fiche 50-358, 82/12/20, 8212290277

8212290364 Deficiency rept re M-71 work package control Initially reported on 821126 Condition determined not reportable under 10CFR50.55(a) as communicated in 821220 telcon Addl info available in QA dept.
BORGMANN, E A Cincinnati Gas & Electric Co 82/12/20 KEPPLER, J O
Region 3, Office of Director 1p 16585 164 24X
Fiche 50-358, 82/12/20, 8212290364

8212290397 Interim deficiency rept re potential M-50 masking of rejectable discontinuities in radiographs of weldments by as-welded surface conditions Radiographs will be reviewed for proper quality & interpretation by 830331
BORGMANN, E A Cincinnati Gas & Electric Co 82/12/20 KEPPLER, J O
Region 3, Office of Director 1p 16586 291 24X
Fiche 50-358, 82/12/20, 8212290397

8212290438 Supplemental final deficiency rept re potential overpressurization of RHR sys piping inboard & outboard isolation valves, previously submitted in 820525 1tr Valve will be delivered by 830401 & work completed by 830630
BORGMANN, E A Cincinnati Gas & Electric Co 82/12/20 KEPPLER, J O
Region 3, Office of Director 2pp 16585 177 24X
Fiche 50-358, 82/12/20, 8212290438

8212290467 Final deficiency rept re discrepancies in simplified dynamic analysis of small bore piping const Initially reported on 821026 Corrective actions verified & accepted Final designs found within allowable limits
BORGMANN, E A Cincinnati Gas & Electric Co 82/12/20 KEPPLER, J O
Region 3, Office of Director 2pp 16585 217 24X
Fiche 50-358, 82/12/20, 8212290467

8212290483 Interim deficiency rept re seismic qualification of essential HVAC damper mounting brackets American Farming & Ventilation Co resubmitted modified Sargent & Lundy design drawings. Followup rept will be submitted by 830228
BORGMANN, E A Cincinnati Gas & Electric Co 82/12/20 KEPPLER, J O
Region 3, Office of Director 2pp 16583 253 24X
Fiche 50-358, 82/12/20, 8212290483

8212290342 Interim deficiency rept re lack of insp records for Nelson studs Small base metal defect in embed plate discovered Random studs will receive test loading which will exceed AWS D1.1 requirements, NRC approval for testing anticipated
BORGMANN, E A Cincinnati Gas & Electric Co 82/12/21 KEPPLER, J O
Region 3, Office of Director 2pp 16586 234 24X
Fiche 50-358, 82/12/21, 8212290342

8212290285 Interim deficiency rept re QA program When NRC approval obtained to perform mgt reviews & when const & QA mgt recommendations accepted, definite schedule for quality confirmation program completion will be submitted
BORGMANN, E A Cincinnati Gas & Electric Co 82/12/23 KEPPLER, J O
Region 3, Office of Director 1p 16581 114 24X
Fiche 50-358, 82/12/23, 8212290285

T Hearing transcripts on non-antitrust matters

8212020226 Unofficial transcript of 821123 affirmation/discussion & vote in Washington, DC re SECY-82-425 & SECY-82-449
* Commissioners 82/11/23 8pp 16308 193. 24X
Fiche 50-000, 82/11/23, 8212020226

8212290254 Unofficial transcript of Commission 821216 affirmation/discussion & vote in Washington, DC on SECY-82-474A re independent review of facility Pp 1-9
* Commissioners 82/12/16 10pp 16606 266 24X
Fiche 50-358, 82/12/16, 8212290254

DOCKET 50-361 SAN ONOFRE NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

8212140001 Addl response to FOIA request for five categories of documents re SEP Forwards documents listed in App A No documents located subj to Item 3 of request Review of remaining documents continuing Documents available in PDR
FELTON, J H Division of Rules and Records 82/11/03 GALLO, J
Isham, Lincoln & Beale 2pp 16433 334 24X Fiche 50-000, 82/11/03, 8212140001

--7912190426 Notifies of info required from applicant re independent confirmatory piping analysis
BOSMAH, R J Mechanical Engineering Branch 79/12/06
RUBENSTEIN, L Light Water Reactors Branch 4 2pp 16435 014
24X Fiche 50-000, 82/11/03, 8212140001

--8003310092 Suggests review of existing high resolution seismic profiling to define possible Christianitos-Offshore Deformation Zone USOC to assist
JACKSON, R E Geosciences Branch 80/03/18 KNIGHT, J P
Assistant Director for Engineering 1p 16434 258 24X
Fiche 50-000, 82/11/03, 8212140001

--8005050726 "Vertical Spectra from 1979 Imperial Earthquake"
* Southern California Edison Co 80/03/31 24pp 16435 021
24X Fiche 50-000, 82/11/03, 8212140001

--8007180114 Forwards NRC formal question, requesting that util perform evaluation of estimated earthquake ground motion for Unit 1 based on deterministic modeling & ground motion for Units 2 & 3, based upon empirical evaluation
CARDDONE, A T Geosciences Branch 80/06/11 DAVIS, J California, State of 1p 16434 259 24X Fiche 50-000, 82/11/03, 8212140001

--8007230260 Forwards transcripts of 800520-21 meetings w/licenses re need for addl offshore seismic profiles w/o encl
CARDDONE, A T Geosciences Branch 80/06/04 AMIMOTO, P
California, State of 1p 16435 052 24X Fiche 50-000, 82/11/03, 8212140001

--8010150236 Request for procurement NRR-80-143 to award sole source contract to JE Lucio for "Followon to Simulation of Earthquake Ground Motion for San Onofre Nuclear Generating Station"
VOLLMER, R H Division of Engineering FIN 8-6898-0 80/08/04
7pp 16435 087 24X Fiche 50-000, 82/11/03, 8212140001

--8010150242 Requests for procurement NRR-80-145 to award sole source contract to R Herrmann for "Followon to Simulation of Earthquake Ground Motions for San Onofre Nuclear Generating Station"
VOLLMER, R H Division of Engineering FIN 8-6898-0 80/08/04
7pp 16435 063 24X Fiche 50-000, 82/11/03, 8212140001

--8010150246 Request for procurement NRR-80-144 to award sole source contract to K Aki for "Followon to Simulation of Earthquake Ground Motions for San Onofre Nuclear Generating Station"
VOLLMER, R H Division of Engineering FIN 8-6898-0 80/08/04
7pp 16434 247 24X Fiche 50-000, 82/11/03, 8212140001

F. Security, medical, emergency & fire protection plans

8212210197 Forwards IE Insp Repts 50-361/82-36 & 50-362/82-29 on 821101-05 No noncompliance noted
BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 82/12/02 PAPAY, L T Southern California Edison Co
2pp 16484 317 24X Fiche 50-361, 82/12/02, 8212210197

--8212210204 IE Insp Repts 50-361/82-36 & 50-362/82-29 on 821101-05 No noncompliance noted, Major areas inspected fire protection/prevention program & program implementation
SCOWAN, K M, ZHETZIO, G B Division of Resident, Reactor Project & Engineering Programs 82/12/01 9pp 16484 319 24X
Fiche 50-361, 82/12/02, 8212210197

8212060228 Forwards IE Safeguards Insp Rept 50-361/82-35 on 820907-1103 & notice of violation Encls withheld (ref 10CFR2.790)
NORDEHAU, L R Division of Radiological Safety & Safeguards Program 82/12/03 PAPAY, L T Southern California Edison Co
2pp 16312 178 24X Fiche 50-361, 82/12/03, 8212060228

8212090532 Forwards IE Safeguards Insp Repts 50-206/82-29 & 50-361/82-29 on 821031-1105 & notice of violation Notice of violation & insp rept withheld (ref 10CFR2 790) NORDERHAUG, L R Division of Radiological Safety & Safeguards Program 82/12/06 PAPAY, L T Southern California Edison Co 2pp 16366 106 24X Fiche 50-206, 82/12/06, 8212090532

8212170208 Advises that emergency support facilities are operational Red & green phones will not be operational in emergency operations facility until 830126 BASKIN, K P Southern California Edison Co 82/12/15 KNIGHTON, Q W Licensing Branch 3 2pp 16459 345 24X Fiche 50-361, 82/12/15, 8212170208

G Adjudicatory correspondence

8212070007 Confirms 821203 telcon w/Freeman rescheduling meeting to 821215 CHANDLER, L J Hearing Branch 2 82/12/06 NEBBITT, W Affiliation Unknown 1p 16327 237 24X Fiche 50-361, 82/12/06, 8212070007

8212090199 Confirms 821213 meeting in Houston, TX to discuss possibility of participation in hearing re medical svcs to treat radiological contamination & exposure CHANDLER, L J Hearings Division 82/12/08 COLLINS, V P Affiliation Unknown 1p 16363 356 24X Fiche 50-361, 82/12/08, 8212090199

H General correspondence

8212290007 Final response to FOIA request for SECY-81-600A, SECY-81-622A, SECY-82-23, SECY-82-42, SECY-81-136, SECY-82-137, SECY-82-197A & B, SECY-82-286 & SECY-82-315 SECY-81-622A & SECY-82-197A & B withheld (ref FOIA Exemption 5) FELTON, J M Division of Rules and Records 82/12/03 GRABER, L Affiliation Unknown 2pp 16607 164 24X Fiche 50-361, 82/12/03, 8212290007

J Insurance & indemnity information

8212270171 Forwards Endorsements 89 & 90 to NELIA Policy NF-146, Endorsements 77 & 79 to MAELU Policy NF-79, Endorsement 35 to NELIA Policy NF-282, Endorsement 1 to NELIA Binder ED-B7 & Endorsement 1 to MAELU Binder XB-87 ROCCO, J Southern California Edison Co 82/12/20 DINI, T. Antitrust & Economic analysis Branch (Utility Finance) 19pp 16538 347 24X Fiche 50-206, 82/12/20, 8212270171

P Operating license stage documents & correspondence

8212140001 Addl response to FOIA request for five categories of documents re SEP Forwards documents listed in App A No documents located subj to item 3 of request Review of remaining documents continuing Documents available in PDR FELTON, J M Division of Rules and Records 82/11/03 GALLO, J Isham, Lincoln & Deale 2pp 16433 354 24X Fiche 50-000, 82/11/03, 8212140001

--8203310470 Forwards SEP seismic completion plan to perform review parallel w/license efforts to complete SEP Topic III-6, seismic design considerations for Group II plants JERMANN, R Systematic Evaluation Program Branch 82/03/08 RUSSELL, W T Systematic Evaluation Program Branch 5pp 16434 276 24X Fiche 50-000, 82/11/03, 8212140001

8212030269 Board Notification 82-117 forwards RH Engelken 821108 memo to DO Eisenhut re welding-related allegations made by former Bechtel employee W/o encl NOVAK, T M Assistant Director for Licensing 82/11/17 Atomic Safety and Licensing Appeal Panel 3pp 16316 323 24X Fiche 50-000, 82/11/17, 8212030269

8212030253 Board Notification 82-105 forwards RH Vollmer 820930 memo to DO Eisenhut re alleged design deficiency in ASME Code Class I piping Effects of local pipe wall stresses due to support loads introduced by pipe clamps not evaluated properly EISENHUT, D O Division of Licensing 82/11/24, PALLADINO, N J., GILINSKY, V., AHEARNE, J F Commissioners 2pp 16316 240 24X Fiche 50-000, 82/11/24, 8212030253

--8212030265 Discusses alleged design deficiency in ASME Code Class I piping Failure to deal w/pipes support-pipe interface design issue would be serious matter if substantiated Ofc of Investigations will assist in evaluation VOLLMER, R H Division of Engineering 82/09/30 EISENHUT, D O, Division of Licensing 5pp 16316 247 24X Fiche 50-000, 82/11/24, 8212030253

8212010171 Responds to NRC 821026 ltr re Congressional request for info on steam generator tube integrity Due to recent receipt of OL, operating history does not provide meaningful info DIETCH, R Southern California Edison Co 82/11/29 EISENHUT, D O Division of Licensing 1p 16258 082 24X Fiche 50-361, 82/11/29, 8212010171

8212010319 Staff requirements memo re Commission 821118 affirmation/discussion & vote on SECYs 82-439 & 82-438 CHILK, S J Office of the Secretary of the Commission 82/11/30 DIRCKS, W J Office of the Executive Director for Operations BICKNIT, L Office of the General Counsel 2pp 16271 282 24X Fiche 50-361, 82/11/30, 8212010319

8212020373 Forwards changes to post-accident sampling descriptions per NUREG-0737, Item II B 3 & 821112 meeting Changes will be incorporated in FSAR amend to be submitted late Dec 1982 BASKIN, K P Southern California Edison Co 82/11/30 KNIGHTON, Q W Licensing Branch 3 7pp 16290 318 24X Fiche 50-361, 82/11/30, 8212020373

8212030275 Board Notification 82-117 Forwards RH Engelken 821108 memo to DO Eisenhut re welding-related allegations made by former Bechtel employee W/o encl NOVAK, T M Assistant Director for Licensing 82/11/30 Atomic Safety and Licensing Board Panel 5pp 16316 315 24X Fiche 50-000, 82/11/30, 8212030275

8212030157 Forwards Amend Application 15 to License NPF-10, consisting of Proposed Changes 10 & 21 Changes would increase ESF response time limits for auxiliary feedwater delivery & minimize Tech Spec differences between units DIETCH, R Southern California Edison Co 82/12/01 DENTON, H R. Office of Nuclear Reactor Regulation, Director 1p 16306 309 24X Fiche 50-361, 82/12/01, 8212030157

--8212030168 Amend Application 15 to License NPF-10, revising Tech Specs 3 3 2 (Table 3 3-5) & 4 7 1 2 1 a Proposed changes increase ESF response time limits for auxiliary feedwater delivery DIETCH, R Southern California Edison Co COTTON, G D San Diego Gas & Electric Co HOYT, G W Anaheim, CA 82/12/01 7pp 16306 310 24X Fiche 50-361, 82/12/01, 8212030157

--8212030250 Proposed Tech Spec changes, increasing ESF response time limits for auxiliary feedwater delivery * Southern California Edison Co 82/12/01 96pp 16306 317 24X Fiche 50-361, 82/12/01, 8212030157

8212170381 Notification of 821207 meeting w/util in San Clemente, CA to discuss rapid depressurization & DHR capability & inadequate core cooling instrumentation ROOD, H Licensing Branch 3 82/12/01 KNIGHTON, Q W Licensing Branch 3 5pp 16478 090 24X Fiche 50-361, 82/12/01, 8212170381

8212070190 Forwards proposed Tech Spec changes re turbine overspeed protection Proposed change will be detailed in formal OL amend request to be submitted during w/ of 821220 BASKIN, K P Southern California Edison Co 82/12/03 KNIGHTON, Q W Licensing Branch 3 3pp 16334 354 24X Fiche 50-361, 82/12/03, 8212070190

--8212070193 Proposed Tech Spec Page 3/4 3-75 re turbine overspeed protection * Southern California Edison Co 82/12/03 5pp 16334 357 24X Fiche 50-361, 82/12/03, 8212070190

8212090376 Forwards amend fee for Items 2 & 3 per NRC 821018 ltr re Amends 4, 6 & 7 to License NPF-10 Disagrees w/fees applicable for Item 1(b) re license condition for environ qualification program BASKIN, K P Southern California Edison Co 82/12/03 MILLER, W O License Fee Management Branch 2pp 16365 053 24X Fiche 50-361, 82/12/03, 8212090376

8212090176 Amends util 821028 ltr summarizing status of electrical equipment environ qualification program Review & determination of acceptability of as-installed condition will be completed by 821215 BASKIN, K P Southern California Edison Co 82/12/07 KNIGHTON, Q W Licensing Branch 3 6pp 16339 213 24X Fiche 50-361, 82/12/07, 8212090176

8212090179 Forwards Affidavit of Svc affirming that distribution of Amend 15 to License NPF-10 has been completed MEDFORD, M O Southern California Edison Co 82/12/07 KNIGHTON, Q W Licensing Branch 3 4pp 16359, 207 24X Fiche 50-361, 82/12/07, 8212090179

DOCKETED ITEMS

8212090514 Responds to Generic Ltr 82-16, "Clarification of TMI Action Plan Requirements " Comparison of Tech Specs for both units vs NUREG-0737 requirements encl
BASKIN, K P Southern California Edison Co 82/12/07 KNIGHTON, O W
Licensing Branch 3 12pp 16366 013 24X Fiche 50-361, 82/12/07, 8212090514

8212130161 Forwards Amend 11 to License NPF-10, safety evaluation & notice of issuance & availability Amend changes Tech Spec 3 3 4 specifying at least one operable turbine overspeed protection sys
KNIGHTON, O W Licensing Branch 3 82/12/07 DIETCH, R Southern California Edison Co COTTON, O D, BERNATH, L San Diego Gas & Electric Co 3pp 16396 056 24X Fiche 50-361, 82/12/07, 8212130161

--8212130162 Amend 11 to License NPF-10, changing Tech Spec 3 3 4 specifying at least one operable turbine overspeed protection sys
KNIGHTON, O W Licensing Branch 3 82/12/07 5pp 16396 060 24X Fiche 50-361, 82/12/07, 8212130161

--8212130164 Safety evaluation supporting Amend 11 to License NPF-10 * Office of Nuclear Reactor Regulation, Director 82/12/07 3pp 16396 065 24X Fiche 50-361, 82/12/07, 8212130161

--8212130168 Notice of issuance & availability of Amend 11 to License NPF-10
KNIGHTON, O W Licensing Branch 3 82/12/07 3pp 16396 068 24X Fiche 50-361, 82/12/07, 8212130161

8208190243 Generic Ltr 82-32 to all FWR licensees re potential steam generator-related generic requirements Forwards Science Applications, Inc draft rept re subJ requirements Comments requested within 30 days of ltr Svc list encl
EISENHUT, D O Division of Licensing 82/12/09 Consolidated Edison Co of New York, Inc 27pp 16629 247 24X Fiche 50-000, 82/12/09, 8208190243

8212220061 Requests remittance of Class III fees per 820816 Tech Spec change request re condensate storage tank & 820930 application to allow Mode 2 & 3 operation w/turbine overspeed protection sys inoperable
DIGGS, R M License Fee Management Branch 82/12/10 DIETCH, R Southern California Edison Co 1p 16525 362 24X Fiche 50-361, 82/12/10, 8212220061

8212220434 Board Notifications 82-125 & 82-125A forwards info re flow blockage during natural circulation All concerns re phenomena of natural circulation flow blockage previously identified by NRC & provided to Commission
EISENHUT, D O Division of Licensing 82/12/14 PALLADINO, N J, OILINSKY, V, AHEARNE, J Commissioners 4pp 16523 103 24X Fiche 50-000, 82/12/14, 8212220434

8212220440 Board Notifications 82-125 & 82-125A forwards info re H Etherington evaluation of flow blockage during natural circulation of PHRS Results do not adversely impact present position on reliance on natural circulation
NOVAK, T H Assistant Director for Licensing 82/12/14 Atomic Safety and Licensing Board Panel 5pp 16523 135 24X Fiche 50-000, 82/12/14, 8212220440

8212220461 Board Notification 82-124 forwards RJ Mattson 821123 memo re Semiscale 8-UT-8 test results Phenomena of core level depression & loop seal clearing may be more complex than previously supposed
NOVAK, T H Assistant Director for Licensing 82/12/14 Atomic Safety and Licensing Board Panel 7pp 16523 169 24X Fiche 50-000, 82/12/14, 8212220461

8212220482 Board Notification 82-124 forwards RJ Mattson 821123 memo re Semiscale 8-UT-8 test results Phenomena of core level depression & loop seal clearing may be more complex than previously supposed
EISENHUT, D O Division of Licensing 82/12/14 PALLADINO, N J, OILINSKY, V, AHEARNE, J Commissioners 4pp 16523 199 24X Fiche 50-000, 82/12/14, 8212220482

8212230291 Forwards table of all ESF actuation sys subgroup relays categorized per NRC 821007 request ESF actuation trains not defeated for testing subgroup relays Procedure considered unsafe operating practice
BASKIN, K P Southern California Edison Co 82/12/17 KNIGHTON, O W Licensing Branch 3 26pp 16507 321 24X Fiche 50-361, 82/12/17, 8212230291

8212230260 Provides results of review of Rosemount transmitters & resistance temp detectors tested w/terminal head areas sealed from abnormal environ atmosphere
BASKIN, K P Southern California Edison Co 82/12/21 KNIGHTON, O W Licensing Branch 3 4pp 16508 184 24X Fiche 50-361, 82/12/21, 8212230260

8212230325 Suppls 821230 ltr re proposed change to License NPF-10 Component cooling water sys adequate to simultaneously serve all essential & nonessential loads except shutdown cooling HX Safety analyses not affected by change
BASKIN, K P Southern California Edison Co 82/12/21 KNIGHTON, O W Licensing Branch 3 1p 16507 309 24X Fiche 50-361, 82/12/21, 8212230325

8212230349 Comments on NRC safety evaluation re Amend 8 to License NPF-10 Amend changed date for operability of post-accident sampling sys Plant expected to return to power by early Jan 1983
BASKIN, K P Southern California Edison Co 82/12/21 KNIGHTON, O W Licensing Branch 3 2pp 16511 264 24X Fiche 50-361, 82/12/21, 8212230349

G Inspection reports, IE Bulletins & correspondence

8212290023 FOIA request for documents re EE Kent allegations concerning facilities
COHEN, E M, CARPENTER, T, JACOBSON, J Orange County Alliance for Survival 82/10/27 FELTON, J M Division of Rules and Records 1p 16607 055 24X Fiche 50-206, 82/10/27, 8212290023

8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000, 82/11/05, 8208190245

8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X Fiche 50-000, 82/11/18, 8208190251

8212060154 Forwards IE Insp Rept 50-361/82-32 on 821025-29 No noncompliance noted
BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 82/11/19 PAPAY, L T Southern California Edison Co 2pp 16313 135 24X Fiche 50-361, 82/11/19, 8212060154

--8212060159 IE Insp Rept 50-361/82-32 on 821025-29 No noncompliance noted Major areas inspected audit implementation, training & qualification training program
MENDONCA, M M, KIRSCH, D F Division of Resident, Reactor Project & Engineering Programs 82/11/19 3pp 16313 137 24X Fiche 50-361, 82/11/19, 8212060154

8212060156 Forwards IE Insp Repts 50-206/82-33 & 50-361/82-33 on 821025-28 & notice of violation
BOOK, H E Region 5, Office of Director 82/11/19 PAPAY, L T Southern California Edison Co 4pp 16313 120 24X Fiche 50-206, 82/11/19, 8212060156

--8212060161 Notice of violation from insp on 821025-28 * Region 5, Office of Director 82/11/19 4pp 16313 122 24X Fiche 50-206, 82/11/19, 8212060156

--8212060168 IE Insp Repts 50-206/82-33 & 50-361/82-33 on 821025-28 Noncompliance noted Failure to post notice to workers, described in 10CFR19.11, Paragraph 3
VORAS, O P, WENSLAWSKI, F A, BOOK, H E Division of Radiological Safety & Safeguards Program 82/11/18 9pp 16313 126 24X Fiche 50-206, 82/11/19, 8212060156

8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000, 82/11/26, 8208190256

8208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000, 82/11/30, 8208190257

8212170369 Forwards IE Insp Repts 50-206/82-31, 50-361/82-31 & 50-362/82-27 on 821015-1115 No noncompliance noted
BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 82/11/30 PAPAY, L T Southern California Edison Co 4pp 16435 279 24X Fiche 50-206, 82/11/30, 8212170369

--8212170376 IE Insp Repts 50-206/82-31, 50-361/82-31 & 50-362/82-27 on 821015-1115 No noncompliance noted Major areas inspected allegations re design inadequacies & deficiencies in implementation of welding codes & stds
HERNANDEZ, O, WAGNER, W J, KIRSCH, D F Division of Resident, Reactor Project & Engineering Programs 82/11/30 43pp 16455 283 24X Fiche 50-206, 82/11/30, 8212170369

DOCKETED ITEMS

231

--8212170383 Requests notification if list of items to be submitted by 821103 re welding code requirements not correct
ENGELKEN, R H Region 5, Office of Director 82/10/29 PAPAY, L T
Southern California Edison Co 1p 16455 326 24X
Fiche 50-206, 82/11/30, 8212170369

--8212170384 Responds to NRC 821029 ltr re allegations concerning const quality & welding code requirements
PAPAY, L T Southern California Edison Co 82/11/03
ENGELKEN, R H Region 5, Office of Director 11pp 16455 327
24X Fiche 50-206, 82/11/30, 8212170369

--8212170386 Forwards Bechtel 821029 response to allegations re const quality, per request made at 821103 site meeting
CURRAN, J M Southern California Edison Co 82/11/03 KIRSCH, D F
Region 5, Office of Director 37pp 16455 338 24X
Fiche 50-206, 82/11/30, 8212170369

--8212080291 Transmits reply to 821029 request for technical assistance in evaluating EE Kent Allegation Items 2, 5, 6 & 8 Evaluation concludes allegations unsubstantiated
EISENHUT, D O Division of Licensing 82/11/30 CRENS, J L
Division of Resident, Reactor Project & Engineering Programs 1P
16456 013 24X Fiche 50-206, 82/11/30, 8212170369

--8212190023 Forwards safety evaluation of E Kent allegations re weldments at plants Allegations have no merit & no further action should be taken
JOHNSTON, W V Assistant Director for Materials & Qualifications
Engineering 82/11/17 NOVAK, T M Assistant Director for
Licensing 14pp 16456 014 24X Fiche 50-206, 82/11/30, 8212170369

821210197 Forwards IE Insp Repts 50-361/82-36 & 50-362/82-29 on 821101-05 No noncompliance noted
WISHOP, T W Division of Resident, Reactor Project & Engineering
Programs 82/12/02 PAPAY, L T Southern California Edison Co
2pp 16484 317 24X Fiche 50-361, 82/12/02, 821210197

--821210204 IE Insp Repts 50-361/82-36 & 50-362/82-29 on 821101-05 No noncompliance noted Major areas inspected fire protection/prevention program & program implementation
SCOWEN, K M, ZHETZIG, G B Division of Resident, Reactor Project & Engineering Programs 82/12/01 9pp 16484 319 24X
Fiche 50-361, 82/12/02, 821210197

8208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies" Svc list encl
DEVOUNO, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc
113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259

8208190261 IE Info Notice 82-48, "Failures of Agestat CR 0095 Relay Sockets" Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X
Fiche 50-000, 82/12/03, 8208190261

8212060228 Forwards IE Safeguards Insp Rept 50-361/82-39 on 820907-1103 & notice of violation Encls withheld (ref 10CFR2 790)
NORDEHHAUG, L R Division of Radiological Safety & Safeguards Program 82/12/03 PAPAY, L T Southern California Edison Co 2pp
16312 178 24X Fiche 50-361, 82/12/03, 8212060228

8212170391 Forwards IE Insp Rept 50-361/82-41 on 821110-11 & notice of violation
WISHOP, T W Division of Resident, Reactor Project & Engineering Programs 82/12/03 PAPAY, L T Southern California Edison Co
2pp 16459 168 24X Fiche 50-361, 82/12/03, 8212170391

--8212170394 Notice of violation from insp on 821110-11
YOUNG, T Division of Resident, Reactor Project & Engineering Programs 82/12/03 1p 16459 170 24X Fiche 50-361, 82/12/03, 8212170391

--8212170397 IE Insp Rept 50-361/82-41 on 821110-11 Noncompliance noted failure to maintain open, continuous communication channel w/NRC operations ctr
YOUNG, T, JOHNSON, P H, KIRSCH, D F Division of Resident, Reactor Project & Engineering Programs 82/12/03 8pp 16459 171 24X
Fiche 50-361, 82/12/03, 8212170391

8212290030 Partial response to FOIA request for documents re EE Kent allegations concerning facilities Forwards Documents 1, 2, 4, 7, 10, 15 & 16 listed in App A Remaining documents will be released when Insp rept issued Tapes available in PDR
FELTON, J M Division of Rules and Records 82/12/03 CARPENTER, T
Orange County Alliance for Survival 3pp 16607 056 24X
Fiche 50-206, 82/12/03, 8212290030

--8212290035 Summarizes 821006 telcon w/J O'Dell (LA Times) re EE Kent allegations concerning welding practice at facilities
KIRSCH, D F Division of Resident, Reactor Project & Engineering Programs 82/10/06 Division of Resident, Reactor Project & Engineering Programs 2pp 16607 077 24X Fiche 50-206, 82/12/03, 8212290030

--8212290038 Forwards util/Bechtel QA audit package re EE Kent allegations concerning facilities
CURRAN, J M Southern California Edison Co 82/10/07 KIRSCH, D F
Region 5, Office of Director 48pp 16607 079 24X
Fiche 50-206, 82/12/03, 8212290030

--8212290042 Lists EE Kent concerns re Facilities, per 821022 discussions w/Kent
KIRSCH, D F Division of Resident, Reactor Project & Engineering Programs 82/10/22 CURRAN, J Southern California Edison Co
1p 16607 127 24X Fiche 50-206, 82/12/03, 8212290030

--8212290049 Figure NB-4250-1, "Welding End Transitions - Max Envelope," w/annotation "Example of Approx Slopes Discovered 821025 at San Onofre Nuclear Generating Stations" Charts re welding & pipe support encl
KENT, E E Affiliation Unknown 82/11/12 3pp 16607 129 24X
Fiche 50-206, 82/12/03, 8212290030

8212090532 Forwards IE Safeguards Insp Repts 50-206/82-29 & 50-361/82-29 on 821031-1105 & notice of violation Notice of violation & insp rept withheld (ref 10CFR2 790)
NORDEHHAUG, L R Division of Radiological Safety & Safeguards Program 82/12/06 PAPAY, L T Southern California Edison Co 2pp
16366 106 24X Fiche 50-206, 82/12/06, 8212090532

8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring" Svc list encl
DEVOUNO, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc
127pp 16628 191 24X Fiche 50-000, 82/12/16, 8208190267

8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27" Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X
Fiche 50-000, 82/12/20, 8208190268

R Periodic operating reports & related correspondence

8212290176 Forwards monthly operating rept for Oct 1982
RAY, H B Southern California Edison Co 82/11/15 Division of Data Automation & Management Information 1p 16578 039 24X
Fiche 50-361, 82/11/15, 8212290176

--8212290181 Monthly operating rept for Oct 1982
RYER, J S Southern California Edison Co 82/11/15 5pp
16578 040 24X Fiche 50-361, 82/11/15, 8212290176

B Reportable occurrences, LERs & related correspondence

8212070225 Forwards LER 82-131/03L-0 Detailed event analysis submitted
RAY, H B Southern California Edison Co 82/11/18 ENGELKEN, R H
Region 5, Office of Director 2pp 16329 349 24X
Fiche 50-361, 82/11/18, 8212070225

--8212070231 LER 82-131/03L-0 on 821020, auxiliary feedwater pump 2P-141 declared inoperable Caused by dirt on oil filter preventing valve 2HV4731 from stroking fully open Oil filter replaced & valve tested successfully
RAY, H B Southern California Edison Co 82/11/18 Region 5, Office of Director 1p 16329 351 24X Fiche 50-361, 82/11/18, 8212070225

8212070252 Forwards LER 82-135/03L-0 Detailed event analysis submitted
RAY, H B Southern California Edison Co 82/11/18 ENGELKEN, R H
Region 5, Office of Director 2pp 16339 124 24X
Fiche 50-361, 82/11/18, 8212070252

--8212070259 LER 82-135/03L-0 on 821018, during change from Mode 4 to Mode 3, one train of component cooling water improperly aligned rendering emergency chiller E-335 inoperable Caused by improper documentation Personnel retrained
RAY, H B Southern California Edison Co 82/11/18 Region 5, Office of Director 1p 16339 126 24X Fiche 50-361, 82/11/18, 8212070252

8212070383 Forwards LER 82-128/03L-0 Detailed event analysis submitted
RAY, H B Southern California Edison Co 82/11/18 ENGELKEN, R H
Region 5, Office of Director 2pp 16336 336 24X
Fiche 50-361, 82/11/18, 8212070383

DOCKETED ITEMS

--8212070399 LER 82-128/03L-0 on 821021, while in Mode 2, control element assembly slipped & dropped in excess of 7 inches. Caused by slow operation of grippers. Gripper actuation voltage & duration of application increased. Sys tested successfully.
RAY, H B Southern California Edison Co 82/11/18 Region 5,
Office of Director 1p 16336 33B 24X Fiche 50-361, 82/11/18,
8212070383

8212070281 Forwards LER 82-137/03L-0 Detailed event analysis submitted
RAY, H B Southern California Edison Co 82/11/19 ENGELKEN, R H
Region 5, Office of Director 2pp 16343 191 24X
Fiche 50-361, 82/11/19, 8212070281

--8212070294 LER 82-137/03L-0 on 821020, while in Mode 3, absence of chemical & vol control sys Jetdown flow & decreasing vol control tank level revealed. Caused by sticking relief valve. Investigation ongoing. Revised LER will be provided.
RAY, H B Southern California Edison Co 82/11/19 Region 5,
Office of Director 1p 16343 193 24X Fiche 50-361, 82/11/19,
8212070281

8212070283 Forwards LER 82-133/03L-0 Detailed event analysis submitted
RAY, H B Southern California Edison Co 82/11/19 ENGELKEN, R H
Region 5, Office of Director 2pp 16339 110 24X
Fiche 50-361, 82/11/19, 8212070283

--8212070287 LER 82-133/03L-0 on 821021, during Mode 2, hot leg sample isolation valve 2HV-0509 observed w/ simultaneous open & closed position indication when actually closed. Caused by loose actuator bar on limit switch assembly. Bar tightened.
RAY, H B Southern California Edison Co 82/11/19 Region 5,
Office of Director 1p 16339 112 24X Fiche 50-361, 82/11/19,
8212070283

8212070290 Forwards LER 82-134/03L-0 Detailed event analysis submitted
RAY, H B Southern California Edison Co 82/11/19 ENGELKEN, R H
Region 5, Office of Director 2pp 16339 017 24X
Fiche 50-361, 82/11/19, 8212070290

--8212070293 LER 82-134/03L-0 on 821024, during Mode 1, containment airborne monitor 2RT-7804-1 failed to meet surveillance requirements of Tech Specs. Caused by instrument drift in sample pump flow controller. Controller adjusted.
RAY, H B Southern California Edison Co 82/11/19 Region 5,
Office of Director 1p 16339 019 24X Fiche 50-361, 82/11/19,
8212070290

8212070379 Forwards LER 82-132/03L-0 Detailed event analysis submitted
RAY, H B Southern California Edison Co 82/11/19 ENGELKEN, R H
Region 5, Office of Director 2pp 16336 339 24X
Fiche 50-361, 82/11/19, 8212070379

--8212070388 LER 82-132/03L-0 on 821023, during turbine generator voltage regulator testing, turbine stop valve 20V-2500E failed to close. Caused by faulty electro-hydraulic servo-mechanism which controls valve actuation. Assembly replaced.
RAY, H B Southern California Edison Co 82/11/19 Region 5,
Office of Director 1p 16336 341 24X Fiche 50-361, 82/11/19,
8212070379

8212070406 Forwards LER 82-125/03L-0 Detailed event analysis submitted
RAY, H B Southern California Edison Co 82/11/22 ENGELKEN, R H
Region 5, Office of Director 2pp 16336 344 24X
Fiche 50-361, 82/11/22, 8212070406

--8212070412 LER 82-125/03L-0 on 821001, shutdown cooling sys declared inoperable when pre-existing tube leak in Train A component cooling water sys HX aggravated. Caused by surge tank filled w/solid due to faulty level control switch 2LSN-6498.
RAY, H B Southern California Edison Co 82/11/22 Region 5,
Office of Director 1p 16336 346 24X Fiche 50-361, 82/11/22,
8212070406

8212070324 Forwards LER 82-141/03L-0 Detailed event analysis submitted
RAY, H B Southern California Edison Co 82/11/24 ENGELKEN, R H
Region 5, Office of Director 2pp 16343 139 24X
Fiche 50-361, 82/11/24, 8212070324

--8212070329 LER 82-141/03L-0 on 821027, during Mode 2, condensate storage tank T-120 water fell below Tech Spec limit. Caused by inadequate makeup water control to tank due to misalignment of valves. Engineering evaluation underway.
RAY, H B Southern California Edison Co 82/11/24 Region 5,
Office of Director 1p 16343 161 24X Fiche 50-361, 82/11/24,
8212070324

8212070350 Forwards LER 82-138/01T-0 Detailed event analysis submitted
RAY, H B Southern California Edison Co 82/11/24 ENGELKEN, R H
Region 5, Office of Director 2pp 16337 216 24X
Fiche 50-361, 82/11/24, 8212070350.

--8212070360 LER 82-138/01T-0 on 821109, during momentary loss of power to feedwater control sys, reactor manually tripped & ECCS automatically initiated. Caused by dislodging of power cord. Control cabinets secured w/tie wraps & training updated.
RAY, H B Southern California Edison Co 82/11/24 Region 5,
Office of Director 1p 16337 219 24X Fiche 50-361, 82/11/24,
8212070350

8212070369 Forwards LER 82-140/03L-0 Detailed event analysis submitted
RAY, H B Southern California Edison Co 82/11/24 ENGELKEN, R H
Region 5, Office of Director 2pp 16336 333 24X
Fiche 50-361, 82/11/24, 8212070369

--8212070374 LER 82-140/03L-0 on 821025, mismatch in power indication found between channel B & channels A, C & D indicating circuitry failure associated w/channel B calculation. Caused by gain drifting in linear amplifier. Board replaced.
RAY, H B Southern California Edison Co 82/11/24 Region 5,
Office of Director 1p 16336 335 24X Fiche 50-361, 82/11/24,
8212070369

8212140035 ROs 82-142 & 82-001 on 821124 & 28, CREACUS Train A declared inoperable due to charcoal filter replacement on cooling unit E-418 & emergency chiller E-335 inoperable due to high motor winding temp trip. Cooldown initiated.
RAY, H B Southern California Edison Co 82/11/30 ENGELKEN, R H
Region 5, Office of Director 2pp 16409 291 24X
Fiche 50-361, 82/11/30, 8212140035

8212140265 Forwards LERs 82-094/03L-1 & 82-103/03L-1 Detailed event analyses submitted
RAY, H B Southern California Edison Co 82/11/30 ENGELKEN, R H
Region 5, Office of Director 2pp 16402 115 24X
Fiche 50-361, 82/11/30, 8212140265

--8212140270 LER 82-094/03L-1 on 820808, stroke time for hot leg sample isolation valve 2HV-0517 could not be measured due to simultaneous indication of valve open & closed positions. Caused by loose limit switch. Switch tightened.
RAY, H B Southern California Edison Co 82/11/30 Region 5,
Office of Director 1p 16402 117 24X Fiche 50-361, 82/11/30,
8212140265

--8212140272 LER 82-103/03L-1 on 820825, during ESF subgroup relay testing, hot leg sample isolation valve 2HV-0517 breaker 2BJ-23 tripped on overload while attempting to close valve. Caused by burned out motor on operator. Motor replaced.
RAY, H B Southern California Edison Co 82/11/30 Region 5,
Office of Director 1p 16402 118 24X Fiche 50-361, 82/11/30,
8212140265

8212140398 Forwards LER 82-143/03L-0 Detailed event analysis submitted
RAY, H B Southern California Edison Co 82/12/01 ENGELKEN, R H
Region 5, Office of Director 2pp 16403 360 24X
Fiche 50-361, 82/12/01, 8212140398

--8212140405 LER 82-143/03L-0 on 821101, auxiliary feedwater pump 2P-140 declared inoperable. Caused by introduction of air into electro-hydraulic actuator by low hydraulic oil level condition resulting in slow response of governor valve.
RAY, H B Southern California Edison Co 82/12/01 Region 2,
Office of Director 1p 16403 362 24X Fiche 50-361, 82/12/01,
8212140398

8212170281 PNG-V-82-050 on 821212, reactor tripped due to low DNRR signal. Caused by generation of false rod control element position penalty by protection sys due to improper filtering of fluctuating rod position read switch input signal.
ECKHARDT, J, BISHOP, T W Region 5, Office of Director 82/12/13
1p 16461 182 24X Fiche 50-361, 82/12/13, 8212170281

8212290413 Discusses ESF actuation sys 821217 event & short-term actions taken to reduce probability of recurrence. NRC concurrence w/Unit 2 power operation & continuation of Unit 3 startup test program requested.
DIETCH, R Southern California Edison Co 82/12/28 EISENHUT, D O
Division of Licensing 6pp 16587 093 24X Fiche 50-361, 82/12/28,
8212290413

DOCKET 50-362 SAN ONDRE NUCLEAR STATION, UNIT 3

A Application/construction stage documents & correspondence

8212140001 Addl response to FOIA request for five categories of documents re SEP Forwards documents listed in App A. No documents located subj to Item 3 of request. Review of remaining documents continuing. Documents available in PDR.
FELTON, J M Division of Rules and Records 82/11/03 GALLO, J
Isham, Lincoln & Beale 2pp 16433 354 24X Fiche 50-000, 82/11/03,
8212140001

--7912190426 Notifies of info required from applicant re independent confirmatory piping analysis
GOSNAX, R J Mechanical Engineering Branch 79/12/06
RUBENSTEIN, L Light Water Reactors Branch 4 2pp 16435 014
24X Fiche 50-000, 82/11/03, 8212140001

--8003310092 Suggests review of existing high resolution seismic profiling to define possible Christiansitos-Offshore Deformation Zone USGC to assist
JACKSON, R E Geosciences Branch 80/03/18 KNIGHT, J P
Assistant Director for Engineering 1p 16434 258 24X
Fiche 50-000, 82/11/03, 8212140001

--8005050726 "Vertical Spectra from 1979 Imperial Earthquake"
* Southern California Edison Co 80/03/31 24pp 16435 021
24X Fiche 50-000, 82/11/03, 8212140001

--8007180114 Forwards NRC formal question, requesting that util perform evaluation of estimated earthquake ground motion for Unit 1 based on deterministic modeling & ground motion for Units 2 & 3, based upon empirical evaluation
CARDONE, A T Geosciences Branch 80/06/11 DAVIS, J California, State of 1p 16434 259 24X Fiche 50-000, 82/11/03, 8212140001

--8007230260 Forwards transcripts of 800520-21 meetings w/licensee re need for addl offshore seismic profiles W/o encl
CARDONE, A T Geosciences Branch 80/06/04 AMIMOTO, P California, State of 1p 16435 052 24X Fiche 50-000, 82/11/03, 8212140001

--8010150236 Request for procurement NRR-80-143 to award sole source contract to JE Luco for "Followon to Simulation of Earthquake Ground Motion for San Onofre Nuclear Generating Station"
VOLLNER, R H Division of Engineering FIN B-6898-0 80/08/04 7pp 16435 057 24X Fiche 50-000, 82/11/03, 8212140001

--8010150242 Requests for procurement NRR-80-145 to award sole source contract to R Herrmann for "Followon to Simulation of Earthquake Ground Motions for San Onofre Nuclear Generating Station"
VOLLNER, R H Division of Engineering FIN B-6898-0 80/08/04 7pp 16435 065 24X Fiche 50-000, 82/11/03, 8212140001

--8010150246 Request for procurement NRR-80-144 to award sole source contract to K Aki for "Followon to Simulation of Earthquake Ground Motions for San Onofre Nuclear Generating Station"
VOLLNER, R H Division of Engineering FIN B-6898-0 80/08/04 7pp 16434 247 24X Fiche 50-000, 82/11/03, 8212140001

--8003310670 Forwards SEP seismic completion plan to perform review parallel w/licensee efforts to complete SEP Topic III-6, seismic design considerations, for Group II plants
HERMANN, R Systematic Evaluation Program Branch 82/03/08
RUSSELL, W T Systematic Evaluation Program Branch 5pp 16434 276 24X Fiche 50-000, 82/11/03, 8212140001

B212230291 Forwards table of all ESF actuation sys subgroup relays categorized per NRC 821007 request ESF actuation trains not defeated for testing subgroup relays Procedure considered unsafe operating practice
BASKIN, K P Southern California Edison Co 82/12/17 KNIGHTON, G W Licensing Branch 3 26pp 16507 321 24X Fiche 50-361, 82/12/17, 8212230291

B212230260 Provides results of review of Rosemount transmitters & resistance temp detectors tested w/terminal head areas sealed from abnormal environ atmosphere
BASKIN, K P Southern California Edison Co 82/12/21 KNIGHTON, G W Licensing Branch 3 4pp 16508 184 24X Fiche 50-361, 82/12/21, 8212230260

F Security, medical, emergency & fire protection plans

B212210197 Forwards IE Insp Repts 50-361/82-36 & 50-362/82-29 on 821101-05 No noncompliance noted
BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 82/12/02 PAPAY, L T Southern California Edison Co 2pp 16484 317 24X Fiche 50-361, 82/12/02, 8212210197

--8212210204 IE Insp Repts 50-361/82-36 & 50-362/82-29 on 821101-05 No noncompliance noted Major areas inspected fire protection/prevention program & program implementation
SCOWEN, K M Division of Resident, Reactor Project & Engineering Programs 82/12/01 9pp 16484 319 24X Fiche 50-361, 82/12/02, 8212210197

B212210362 Forwards IE Safeguards Insp Rept 50-362/82-22 on 821005-08 & notice of deviation Rept & notice of deviation withheld (ref 10CFR2 790)
NORDERHAUD, L R Division of Radiological Safety & Safeguards Program 82/12/14 PAPAY, L T Southern California Edison Co 2pp 16495 159 24X Fiche 50-362, 82/12/14, 8212210362

B212170208 Advises that emergency support facilities are operational Red & green phones will not be operational in emergency operations facility until 830126
BASKIN, K P Southern California Edison Co 82/12/15 KNIGHTON, G W Licensing Branch 3 2pp 16459 345 24X Fiche 50-361, 82/12/15, 8212170208

G Adjudicatory correspondence

B212070007 Confirms 821203 telcon w/Freeman rescheduling meeting to 821215
CHANDLER, L J Hearing Branch 2 82/12/06 NESBITT, W Affiliation Unknown 1p 16327 237 24X Fiche 50-361, 82/12/06, 8212070007

B212090199 Confirms 821213 meeting in Houston, TX to discuss possibility of participation in hearing re medical svcs to treat radiological contamination & exposure
CHANDLER, L J Hearings Division 82/12/08 COLLINS, V P Affiliation Unknown 1p 16363 356 24X Fiche 50-361, 82/12/08, 8212090199

H General correspondence

B212290007 Final response to FOIA request for SECY-81-600A, SECY-81-622A, SECY-82-23, SECY-82-42, SECY-81-136, SECY-82-137, SECY-82-197A & B, SECY-82-286 & SECY-82-315 SECY-81-622A & SECY-82-197A & B withheld (ref FOIA Exemption 5)
FELTON, J M Division of Rules and Records 82/12/03 GRABER, L Affiliation Unknown 2pp 16607 164 24X Fiche 50-361, 82/12/03, 8212290007

J Insurance & indemnity information

B212130039 Forwards Amend 17 to Indemnity Agreement D-31, reflecting issuance of License NPF-15, per NRC 821115 request
BASKIN, K P Southern California Edison Co 82/12/17 BALTZMAN, J Assistant Director for State & Licensee Relations 3pp 16389 308 24X Fiche 50-362, 82/12/17, 8212130039

B212270171 Forwards Endorsements 89 & 90 to NELIA Policy NF-146, Endorsements 77 - 79 to MAELU Policy MF-79, Endorsement 35 to NELIA Policy NF-282, Endorsement 1 to NELIA Binder ED-87 & Endorsement 1 to MAELU Binder XB-87
ROCCO, J Southern California Edison Co 82/12/20 DINITZ, I Antitrust & Economic Analysis Branch (Utility Finance) 17pp 16538 347 24X Fiche 50-206, 82/12/20, 8212270171

P Operating license stage documents & correspondence

B212030269 Board Notification 82-117 forwards RH Engelen 821108 memo to DO Eisenhower re welding-related allegations made by former Bechtel employee W/o encl.
NOVAK, T M Assistant Director for Licensing 82/11/17 Atomic Safety and Licensing Appeal Panel 3pp 16316 323 24X Fiche 50-000, 82/11/17, 8212030269

B212010409 Submits daily highlight Fuel load completed 821121
RODD, H Licensing Branch 3 82/11/23 DENTON, H R, CASE, E G, CARTER, J Office of Nuclear Reactor Regulation, Director 1p 16271 077 24X Fiche 50-362, 82/11/23, 8212010409

B212030253 Board Notification 82-105 forwards RH Vollmer 820930 memo to DO Eisenhower re alleged design deficiency in ASME Code Class 1 piping Effects of local pipe wall stresses due to support loads introduced by pipe clamps not evaluated properly
EISENHUT, D G Division of Licensing 82/11/24 PALLADINO, N J, ROBERTS, T F, ABELSTINE, J K Commissioners 2pp 16316 240 24X Fiche 50-000, 82/11/24, 8212030253

--8212030265 Discusses alleged design deficiency in ASME Code Class 1 piping Failure to deal w/pipe support-pipe interface design issue would be serious matter if substantiated Ofc of Investigations will assist in evaluation
VOLLNER, R H Division of Engineering 82/09/30, EISENHUT, D G Division of Licensing 5pp 16316 247 24X Fiche 50-000, 82/11/24, 8212030253

B212010171 Responds to NRC 821026 ltr re Congressional request for info on steam generator tube integrity Due to recent receipt of OLS, operating history does not provide meaningful info
DIETCH, R Southern California Edison Co 82/11/29 EISENHUT, D G Division of Licensing 1p 16258 082 24X Fiche 50-361, 82/11/29, 8212010171

DOCKETED ITEMS

B212010319 Staff requirements memo re Commission B21118 affirmation/discussion & vote on SECYA B2-437 & B2-438
CHILK, S J Office of the Secretary of the Commission 82/11/30
DIRCKS, M J Office of the Executive Director for Operations
BICKHIT, L Office of the General Counsel 2pp 16271 282 24X
Fiche 50-361, 82/11/30, B212010319

B212020373 Forwards changes to post-accident sampling descriptions per NUREG-0737, Item 12 B 3 & B21112 meeting. Changes will be incorporated in FSAR amend to be submitted late Dec 1982
BASKIN, K P Southern California Edison Co 82/11/30 KNIGHTON, G W
Licensing Branch 3 7pp 16290 318 24X Fiche 50-361, 82/11/30, B212020373

B212030275 Board Notification B2-117 forwards RM Engelken B21108 memo to DO Eisenhower re welding-related allegations made by former Reactor employee W/a encl
NOVAK, T M Assistant Director for Licensing 82/11/30 Atomic
Safety and Licensing Board Panel 5pp 16316 315 24X
Fiche 50-000, 82/11/30, B212030275

B212080540 Advises that License NPF-15 amended per B21119 ltr & telcon. Listed footnote should be added to Tech Spec 3 9 B 2 Amend allows removal of cooling trains for up to 1-h per B-h period during performance of core alterations
NOVAK, T M Division of Licensing 82/11/30 DIETCH, R Southern California Edison Co, COTTON, D B, BERNATH, L San Diego Gas & Electric Co 3pp 16370 185 24X Fiche 50-362, 82/11/30, B212080540

B212140482 TECHNICAL SPECIFICATIONS FOR SAN ONOFRE NUCLEAR GENERATING STATION, UNIT NO 3 Docket No 50-362 (Southern California Edison Company)
BRINKMAN, D Office of Nuclear Reactor Regulation, Director
NUREG-0752 82/11/30 454pp 16431 340 24X Fiche 50-362, 82/11/30, B212140482

B212170381 Notification of B21207 meeting w/util in San Clemente, CA to discuss rapid depressurization & DHR capability & inadequate core cooling instrumentation
ROOD, H Licensing Branch 3 82/12/01 KNIGHTON, G W Licensing Branch 3 5pp 16478 090 24X Fiche 50-361, 82/12/01, B212170381

B212090176 Amends util B21028 ltr summarizing status of electrical equipment environ qualification program Review & determination of acceptability of as-installed condition will be completed by B21215
BASKIN, K P Southern California Edison Co 82/12/07 KNIGHTON, G W
Licensing Branch 3 6pp 16359 213 24X Fiche 50-361, 82/12/07, B212090176

B212090514 Responds to Generic Ltr B2-16, "Clarification of TMI Action Plan Requirements " Comparison of Tech Specs for both units vs NUREG-0737 requirements encl
BASKIN, K P Southern California Edison Co 82/12/07 KNIGHTON, G W
Licensing Branch 3 12pp 16366 013 24X Fiche 50-361, 82/12/07, B212090514

B212190263 Generic Ltr B2-32 to all PWR licensees re potential steam generator-related generic requirements Forwards Science Applications, Inc draft rept re subj requirements Comments requested within 30 days of ltr Svc list encl
EISENHUT, D O Division of Licensing 82/12/09 Consolidated
Edison Co of New York, Inc 29pp 16629 247 24X
Fiche 50-000, 82/12/09, B208190263

B212130188 Forwards Amend Application 1 to License NPF-15, consisting of proposed Change NPF-15-2 to Tech Spec 2 9 B 2 to allow shutdown cooling trains to be removed from operation to facilitate fuel movement & core alterations
DIETCH, R Southern California Edison Co 82/12/09 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 16396 120 24X
Fiche 50-362, 82/12/09, B212130188

B212130193 Amend Application 1 to License NPF-15, allowing both shutdown cooling trains to be removed from operation to facilitate fuel movement & core alteration in vicinity of reactor pressure vessel hot legs
DIETCH, R Southern California Edison Co 82/12/09 5pp 16396 121 24X Fiche 50-362, 82/12/09, B212130188

B212130198 Proposed Change NPF-15-2 to Tech Spec 3 9 B 2, allowing both shutdown cooling trains to be removed from operation to facilitate fuel movement & core alteration in vicinity of reactor pressure vessel hot legs
Southern California Edison Co 82/12/09 3pp 16396 126 24X
Fiche 50-362, 82/12/09, B212130188

B21220434 Board Notifications B2-125 & B2-125A Forwards info re flow blockage during natural circulation All concerns re phenomena of natural circulation flow blockage previously identified by NRC & provided to Commission
EISENHUT, D O Division of Licensing 82/12/14 PALLADINO, N J,
ROBERTS, T, ASSELSTINE, J K Commissioners 4pp 16523 103 24X
Fiche 50-000, 82/12/14, B21220434

B212220440 Board Notifications B2-125 & B2-125A forwards info re H Etherington evaluation of flow blockage during natural circulation of PWRs Results do not adversely impact present position on reliance on natural circulation
NOVAK, T M Assistant Director for Licensing 82/12/14 Atomic
Safety and Licensing Board Panel 5pp 16523 135 24X
Fiche 50-000, 82/12/14, B212220440

B212220461 Board Notification B2-124 forwards RJ Mattson B21123 memo re Semiscale S-UT-8 test results Phenomena of core level depression & loop seal clearing may be more complex than previously supposed
NOVAK, T M Assistant Director for Licensing 82/12/14 Atomic
Safety and Licensing Board Panel 7pp 16523 169 24X
Fiche 50-000, 82/12/14, B212220461

B212220482 Board Notification B2-124 forwards RJ Mattson B21123 memo re Semiscale S-UT-8 test results Phenomena of core level depression & loop seal clearing may be more complex than previously supposed
EISENHUT, D O Division of Licensing 82/12/14 PALLADINO, N J,
ROBERTS, T, ASSELSTINE, J K Commissioners 4pp 16523 199 24X
Fiche 50-000, 82/12/14, B212220482

Q Inspection reports, IE Bulletins & correspondence

B212290023 FOIA request for documents re EE Kent allegations concerning facilities
COHEN, E M Orange County Alliance for Survival 82/10/27
FELTON, J M Division of Rules and Records 1p 16607 055 24X
Fiche 50-362, 82/10/27, B212290023

B208190240 IE Bulletin B2-03, Revision 1, "Stress Cracking in Thirk-Wall, Large-Diameter, Stainless Steel Recirculation Sys Piping at BWR Plants " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, B208190240

B208190245 IE Info Notice B2-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000, 82/11/05, B208190245

B208190251 IE Info Notice B2-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X
Fiche 50-000, 82/11/18, B208190251

B212060166 Forwards IE Insp Rept 50-362/B2-24 on B21012-29 No noncompliance noted
BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 82/11/18 PAPAY, L T Southern California Edison Co 2pp 16313 090 24X Fiche 50-362, 82/11/18, B212060166

--B212060170 IE Insp Rept 50-362/B2-24 on B21012-29 No noncompliance noted Major areas inspected preoperational test program, including test procedure verification, evaluation of test results & nonroutine event followup
STEWART, J P, KIRSCH, D F Division of Resident, Reactor Project & Engineering Programs 82/11/17 9pp 16313 092 24X
Fiche 50-362, 82/11/18, B212060166

B208190256 IE Info Notice B2-46, "Defective & Obsolete Combination Padlocks " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000, 82/11/26, B208190256

B212130263 Forwards IE Insp Rept 50-362/B2-30 on B21025-29 No noncompliance noted
BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 82/11/29 PAPAY, L T Southern California Edison Co 2pp 16396 247 24X Fiche 50-362, 82/11/29, B212130263

--B212130265 IE Insp Rept 50-362/B2-30 on B21025-29 No noncompliance noted Major areas inspected const of installed instrumentation, records review of instrumentation & electrical components & onsite design change program
ECKHARDT, J H, KIRSCH, D F Division of Resident, Reactor Project & Engineering Programs 82/11/24 4pp 16396 249 24X
Fiche 50-362, 82/11/29, B212130263

B208190257 IE Info Notice B2-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000, 82/11/30, B208190257

B212170367 Forwards IE Insp Repts 50-206/82-31, 50-361/82-31 & 50-362/82-27 on 821015-1115 No noncompliance noted
 HISHOP, T W Division of Resident, Reactor Project & Engineering Programs 82/11/30 PAPAY, L T Southern California Edison Co 4pp 16455 279 24X Fiche 50-206, 82/11/30, 8212170367

--B212170376 IE Insp Repts 50-206/82-31, 50-361/82-31 & 50-362/82-27 on 821015-1115 No noncompliance noted Major areas inspected allegations re design inadequacies & deficiencies in implementation of welding codes & stds
 HERNANDEZ, G, WAGNER, W J, KIRSCH, D F Division of Resident, Reactor Project & Engineering Programs 82/11/30 43pp 16455 283 24X Fiche 50-206, 82/11/30, 8212170369

--B212170383 Requests notification if list of items to be submitted by 821103 re welding code requirements not correct
 ENGELKEN, R H Region 5, Office of Director 82/10/29 PAPAY, L T Southern California Edison Co 1p 16455 326 24X Fiche 50-206, 82/11/30, 8212170369

--B212170384 Responds to NRC 821029 ltr re allegations concerning const quality & welding code requirements
 PAPAY, L T Southern California Edison Co 82/11/03 ENGELKEN, R H Region 5, Office of Director 11pp 16455 327 24X Fiche 50-206, 82/11/30, 8212170369

--B212170386 Forwards Bechtel 821029 response to allegations re const quality, per request made at 821103 site meeting
 CURRAN, J M Southern California Edison Co 82/11/03 KIRSCH, D F Region 5, Office of Director 37pp 16455 338 24X Fiche 50-206, 82/11/30, 8212170369

--B212093291 Transmits reply to 821029 request for technical assistance in evaluating EE Kent Allegation Items 2, 5, 6 & 8 Evaluation concludes allegations unsubstantiated
 EISENHUT, D O Division of Licensing 82/11/30 CREWS, J L Division of Resident, Reactor Project & Engineering Programs 1p 16455 013 24X Fiche 50-206, 82/11/30, 8212170369

--B21290023 Forwards safety evaluation of E Kent allegations re weldments at plants Allegations have no merit & no further action should be taken
 JOHNSTON, H V Assistant Director for Materials & Qualifications Engineering 82/11/17 NOVAK, T M Assistant Director for Licensing 14pp 16456 014 24X Fiche 50-206, 82/11/30, 8212170369

B212210197 Forwards IE Insp Repts 50-361/82-36 & 50-362/82-29 on 821101-05 No noncompliance noted
 HISHOP, T W Division of Resident, Reactor Project & Engineering Programs 82/12/02 PAPAY, L T Southern California Edison Co 2pp 16484 317 24X Fiche 50-361, 82/12/02, 8212210197

--B212210204 IE Insp Repts 50-361/82-36 & 50-362/82-29 on 821101-05 No noncompliance noted Major areas inspected fire protection/prevention program & program implementation
 SOGHI, K M, ZWETIG, G B Division of Resident, Reactor Project & Engineering Programs 82/12/01 9pp 16484 319 24X Fiche 50-361, 82/12/02, 8212210197

B208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment & Electrical Penetration Assemblies" Svc list encl
 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259

B208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets" Svc list encl
 JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X Fiche 50-000, 82/12/03, 8208190261

B212290030 Partial response to FOIA request for documents re EE Kent allegations concerning facilities Forwards Documents 1, 2, 4, 7, 10, 15 & 16 listed in App A Remaining documents will be released when insp rept issued Tapes available in PDR
 FELTON, J M Division of Rules and Records 82/12/03 CARPENTER, T Orange County Alliance for Survival 3pp 16607 056 24X Fiche 50-362, 82/12/03, 8212290030

--B212290035 Summarizes 821006 telcon w/J O'Dell (LA Times) re EE Kent allegations concerning welding practice at facilities
 KIRSCH, D F Division of Resident, Reactor Project & Engineering Programs 82/10/06 Division of Resident, Reactor Project & Engineering Programs 2pp 16607 077 24X Fiche 50-362, 82/12/03, 8212290030

--B212290038 Forwards util/Bechtel QA audit package re EE Kent allegations concerning facilities
 CURRAN, J M Southern California Edison Co 82/10/07 KIRSCH, D F Region 5, Office of Director 48pp 16607 079 24X Fiche 50-362, 82/12/03, 8212290030

--B212290042 Lists EE Kent concerns re facilities, per 821022 discussions w/Kent
 KIRSCH, D F Division of Resident, Reactor Project & Engineering Programs 82/10/22 CURRAN, J Southern California Edison Co 1p 16607 127 24X Fiche 50-362, 82/12/03, 8212290030

--B212290049 Figure NB-4250-1, "Welding End Transitions - Max Envelope," w/annotation "Example of Approx Slopes Discovered 821025 at San Onofre Nuclear Generating Stations" Charts re welding & pipe support encl
 KENT, E E Affiliation Unknown 82/11/12 3pp 16607 129 24X Fiche 50-362, 82/12/03, 8212290030

B212210362 Forwards IE Safeguards Insp Rept 50-362/82-22 on 821005-08 & notice of deviation Rept & notice of deviation withheld (ref 10CFR2 790)
 NORDERHAUG, L R Division of Radiological Safety & Safeguards Program 82/12/14 PAPAY, L T Southern California Edison Co 2pp 16495 159 24X Fiche 50-362, 82/12/14, 8212210362

B208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring" Svc list encl
 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16, 8208190267

B208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type 1E-27" Svc list encl
 JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X Fiche 50-000, 82/12/20, 8208190268

S Reportable occurrences, LERs & related correspondence

B212060012 Deficiency rept re Stewart-Stevenson governor output voltage erratic behavior causing momentary speed changes of diesel generator 36002 Initially reported on 821021 Evaluation being performed
 CURRAN, J M Southern California Edison Co 82/10/22 ENGELKEN, R H Region 5, Office of Director 1p 16313 326 24X Fiche 50-362, 82/10/22, 8212060012

B212140035 ROs 82-142 & 82-001 on 821124 & 28, CREACUS Train A declared inoperable due to charcoal filter replacement on cooling unit E-418 & emergency chiller E-335 inoperable due to high motor winding temp trip Cool-down initiated
 RAY, H B Southern California Edison Co 82/11/30 ENGELKEN, R H Region 5, Office of Director 2pp 16409 291 24X Fiche 50-361, 82/11/30, 8212140035

B212290413 Discusses ESF actuation sys B21217 event & short-term actions taken to reduce probability of recurrence NRC concurrence w/Unit 2 power operation & continuation of Unit 3 startup test program requested
 DEITCH, R Southern California Edison Co 82/12/28 EISENHUT, D O Division of Licensing 6pp 16587 093 24X Fiche 50-361, 82/12/28, 8212290413

DOCKET 50-364 JOSEPH M FARLEY NUCLEAR PLANT, UNIT 2

F Security, medical, emergency & fire protection plans

B212100070 Submits permanent, backup, interim primary & interim backup emergency operations facilities (EOF) info per 821202 verbal request EOF completed & occupied in Oct 1982
 CLAYTON, F L Alabama Power Co 82/12/03 VARQA, B A Office of Nuclear Reactor Regulation, Director 3pp 16375 359 24X Fiche 50-348, 82/12/03, 8212100070

J Insurance & indemnity information

B212280223 Forwards Endorsement 48 to NELA Policy NF-23B & Endorsement 40 to MAELU Policy NF-93
 DUCK, J R Marsh & McLennan, Inc, M & M Nuclear Consultants, Inc Div 82/12/20 SALTZMAN, J Assistant Director for State & License Relations 3pp 16562 276 24X Fiche 50-348, 82/12/20, 8212280223

B212280348 Forwards Certificates of Insurance N-62 & N-73 for Endorsements 1, 2 & 3 to NELA Policy NF-23B & Certificates of Insurance M-62 & M-73 for Endorsements 1, 2 & 3 to MAELU Policy NF-93
 DUCK, J R Marsh & McLennan, Inc, M & M Nuclear Consultants, Inc Div 82/12/20 SALTZMAN, J Assistant Director for State & License Relations 35pp 16561 146 24X Fiche 50-348, 82/12/20, 8212280348

DOCKETED ITEMS

P Operating license stage documents & correspondence

B212020108 "SER of Pump & Valve Inservice Testing (IST) Program
Submitted by AL Power Co for Joseph M Farley Nuclear Plant,
Unit 2." interim rept
COOK, T L, HUBBLE, W H, ROCKHOLD, H C EQ&O, Inc FIN A-6430
B212020108 82/10/31 HAMMER, C G Division of Engineering 141pp
16309 252 24X Fiche 50-364, 82/10/31, B212020108

B212020130 Informs that info requested in Generic Ltr 82-22 re steam
generator tube integrity, maint, repair & worker exposures
submitted via annual CFR repts & util 820412 ltr
CLAYTON, F L Alabama Power Co 82/11/24 EISENHUT, D G Division
of Licensing 2pp 16272 037 24X Fiche 50-348, 82/11/24,
B212020130

B212080060 Forwards Amend 20 to License NPF-B, safety evaluation &
notice of issuance & availability Amend modifies valve
leakage test criteria
VARQA, S A Operating Reactors Branch 1 82/11/24 CLAYTON, F L
Alabama Power Co 3pp 16367 200 24X Fiche 50-364, 82/11/24,
B212080060

--B212080077 Amend 20 to License NPF-B, modifying valve leakage test
criteria on one-time basis for startup from first refueling
outage only
VARQA, S A Operating Reactors Branch 1 82/11/24 6pp
16367 203 24X Fiche 50-364, 82/11/24, B212080060

--B212080080 Safety evaluation supporting Amend 20 to License NPF-B
* Office of Nuclear Reactor Regulation, Director 82/11/24 3pp
16367 209 24X Fiche 50-364, 82/11/24, B212080060

--B212080083 Notice of issuance & availability of Amend 20 to License
NPF-B
VARQA, S A Operating Reactors Branch 1 82/11/24 2pp
16367 212 24X Fiche 50-364, 82/11/24, B212080060

B212150033 Advises that all portions of post-accident sampling sys,
including containment atmosphere & vent stack ac-powered
solenoids, operational (ref NUREG 0737, Item II B 3) Solenoids
mistakenly installed utilizing dc power
CLAYTON, F L Alabama Power Co 82/11/30 VARQA, S A Office of
Nuclear Reactor Regulation, Director 1p 16421 242 24X
Fiche 50-364, 82/11/30, B212150033

B212160568 Forwards Amend 21 to License NPF-B, safety evaluation &
notice of issuance & availability Amend extends time to
complete mod to safety-related masonry wall
REEVES, E A Operating Reactors Branch 1 82/12/02 CLAYTON, F L
Alabama Power Co 2pp 16466 179 24X Fiche 50-364, 82/12/02,
B212160568

--B212160578 Amend 21 to License NPF-B, extending time scheduled to
complete mod to safety-related masonry wall until second
refueling outage or until NRC accepts energy balance
technique showing no mod needed
VARQA, S A Operating Reactors Branch 1 82/12/02 2pp
16466 181 24X Fiche 50-364, 82/12/02, B212160568

--B212160581 Safety evaluation supporting Amend 21 to License NPF-B
* Office of Nuclear Reactor Regulation, Director 82/12/02 3pp
16466 183 24X Fiche 50-364, 82/12/02, B212160568

--B212160586 Notice of issuance & availability of Amend 21 to License
NPF-B
VARQA, S A Operating Reactors Branch 1 82/12/02 2pp
16466 186 24X Fiche 50-364, 82/12/02, B212160568

B208190263 Generic Ltr 82-32 to all PWR licensees re potential steam
generator-related generic requirements Forwards Science
Applications, Inc draft rept re suby requirements Comments
requested within 30 days of ltr Svc list encl
EISENHUT, D G Division of Licensing 82/12/09 Consolidated
Edison Co of New York, Inc 2pp 16629 247 24X
Fiche 50-000, 82/12/09, B208190263

B212140103 Generic Ltr 82-28 to all licensees of operating
Westinghouse & C-E PWRs (except Arkansas Nuclear One, Unit 2
& San Onofre 2 & 3) re inadequate core cooling
instrumentation sys Svc list encl
EISENHUT, D G Division of Licensing 82/12/10 Yankee Atomic
Electric Co 2pp 16690 035 24X Fiche 50-000, 82/12/10,
B212140103

B212170234 Clarifies B21008 proposed Tech Spec change to delete turbine
valve testing requirements. Proposed change not inconsistent
w/MCAP-1016 conclusions Expedited review requested
Westinghouse draft B21210 ltr encl
CLAYTON, F L Alabama Power Co 82/12/10 VARQA, S A Office of
Nuclear Reactor Regulation, Director 5pp 16459 357 24X
Fiche 50-364, 82/12/10, B212170234.

B212210130 Request for amend to License NPF-B, deleting eight nonsafety-
related snubbers from Tech Spec Table 3 7-4a Safety
evaluation encl
CLAYTON, F L Alabama Power Co 82/12/10 VARQA, S A Office of
Nuclear Reactor Regulation, Director 3pp 16485 078 24X
Fiche 50-364, 82/12/10, B212210130

--B212210132 Proposed Tech Spec Table 3 7-4a, deleting eight nonsafety-
related snubbers
* Alabama Power Co 82/12/10 3pp 16485 081 24X
Fiche 50-364, 82/12/10, B212210130

B212280280 Requests approval by B30701 of B20810 ltr re RCS pressure
isolation valve leak testing, to support planning &
scheduling of next refueling outage
CLAYTON, F L Alabama Power Co 82/12/23 VARQA, S A Office of
Nuclear Reactor Regulation, Director 1p 16561 243 24X
Fiche 50-348, 82/12/23, B212280280

Q Inspection reports, IE Bulletins & correspondence

B208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-
Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping
at BWR Plants " Svc list encl
DEVOUNO, R C Director's Office, Office of Inspection and
Enforcement 82/10/28 Consolidated Edison Co of New York, Inc
112pp 16462 163 24X Fiche 50-000, 82/10/28, B208190240

B208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model
801 & Model 802 Thermoluminescent Dosimeters " Svc list
encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards
82/11/05 Consolidated Edison Co of New York, Inc 110pp
16372 142 24X Fiche 50-000, 82/11/05, B208190245

B212090412 Advises that IE Bulletin 82-01, Revision 1, Suppl 1, review of
radiographs furnished by ITT Grinnell for piping assemblies,
revealed two assemblies w/ altered radiographs on total of
three welds Penetrometer image darkened
CLAYTON, F L Alabama Power Co 82/11/09 O'REILLY, J P Region 2,
Office of Director 2pp 16365 042 24X Fiche 50-348, 82/11/09,
B212090412

B212090435 Confirms B21108 telcon re enforcement conference scheduled
for B21119 in Atlanta, GA Circumstances surrounding
inoperable containment spray sys will be discussed
O'REILLY, J P Region 2, Office of Director 82/11/12
MCDONALD, R P Alabama Power Co 2pp 16363 266 24X
Fiche 50-364, 82/11/12, B212090435

B212090511 Forwards IE Insp Repts 50-348/82-25 & 50-364/82-24 on
B20916-1022 No noncompliance noted
VERRELLI, D M Division of Project & Resident Programs 82/11/17
MCDONALD, R P Alabama Power Co 2pp 16367 014 24X
Fiche 50-348, 82/11/17, B212090511

--B212090519 IE Insp Repts 50-348/82-25 & 50-364/82-24 on B20916-1022 No
noncompliance noted Major areas inspected monthly
surveillance observation, monthly maint observation &
operational safety verification
BRADFORD, W H, CANTRELL, F Division of Project & Resident
Programs 82/11/17 8pp 16367 016 24X Fiche 50-348, 82/11/17,
B212090511

B208190251 IE Info Notice 82-44, "Clarification of Emergency Plan
Exercise Requirements " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18
Consolidated Edison Co of New York, Inc 109pp 16411 199 24X
Fiche 50-000, 82/11/18, B208190251

B208190256 IE Info Notice 82-46, "Defective & Obsolete Combination
Padlocks " Svc list encl
DEVOUNO, R C Director's Office, Office of Inspection and
Enforcement 82/11/26 Consolidated Edison Co of New York, Inc
127pp 16411 065 24X Fiche 50-000, 82/11/26, B208190256

B212090432 Confirms B21123 telcon re B21214 mgt meeting in Birmingham,
AL to review results of first phase of annual appraisal
of regulatory performance Proposed agenda encl
LEWIS, R C Division of Project & Resident Programs 82/11/29
MCDONALD, R P Alabama Power Co 3pp 16364 271 24X
Fiche 50-348, 82/11/29, B212090432

B208190257 IE Info Notice 82-47, "Transportation of Type A Quantities
of Non-Fissile Radioactive Matl " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards
82/11/30 Consolidated Edison Co of New York, Inc 356pp
16387 028 24X Fiche 50-000, 82/11/30, B208190257

8212070336 Submits info per IE Bulletin 82-11, "Masonry Walls," re concrete block wall 2CBW-34 Motor control ctr can be supplied by power feed from Unit 1 within 2-h, if seismic event occurred & power supply lost
CLAYTON, F L Alabama Power Co 82/12/01 VARGA, S A NRC - No Detailed Affiliation Given 1p 16343 204 24X
Fiche 50-364, 82/12/01, 8212070336

8208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259

8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X
Fiche 50-000, 82/12/03, 8208190261

8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16, 8208190267

8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type IIE-27 " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X
Fiche 50-000, 82/12/20, 8208190268

R Periodic operating reports & related correspondence

8212170297 Forwards monthly operating rept for Nov 1982
CLAYTON, F L Alabama Power Co 82/12/13 Office of Management and Program Analysis 1p 16493 215 24X Fiche 50-364, 82/12/13, 8212170297

--8212170302 Monthly operating rept for Nov 1982
HAIRSTON, W G Alabama Power Co 82/12/04 Bpp 16453 216 24X
Fiche 50-364, 82/12/13, 8212170297

S Reportable occurrences, LERs & related correspondence

8212090295 Forwards LER 82-046/03L-0
CLAYTON, F L Alabama Power Co 82/12/01 O'REILLY, J P Region 2, Office of Director 1p 16365 131 24X Fiche 50-364, 82/12/01, 8212090295

--8212090312 LER 82-046/03L-0 on 821028, snubber 2RC-R50A determined to be inoperable when found w/damaged & leaking O-ring Snubber rebuilt, satisfactorily tested & reinstalled No evidence of damage to piping supports or restraints near snubber
HAIRSTON, W G Alabama Power Co 82/12/01 Region 2, Office of Director 1p 16365 132 24X Fiche 50-364, 82/12/01, 8212090295

8212300216 Forwards LERs 82-047/03L-0, 82-048/03L-0, 82-049/03L-0 & 82-050/03L-0
CLAYTON, F L Alabama Power Co 82/12/23 Region 2, Office of Director 1p 16598 107 24X Fiche 50-364, 82/12/23, 8212300216

--8212300223 LER 82-047/03L-0 on 821124, during surveillance test review, air temp monitoring not performed within required time interval Caused by personnel error Requirement (FNP-2-STP-63 O) revised to include performance of air temp monitoring
HAIRSTON, W G Alabama Power Co 82/12/23 Region 2, Office of Director 1p 16598 108 24X Fiche 50-364, 82/12/23, 8212300216

--8212300227 LER 82-048/03L-0 on 821127, source range channel N-32 declared inoperable due to loss of detector voltage Caused by faulty high voltage connector Connector replaced
HAIRSTON, W G Alabama Power Co 82/12/23 Region 2, Office of Director 1p 16598 109 24X Fiche 50-364, 82/12/23, 8212300216

--8212300231 LER 82-049/03L-0 on 821201, containment atmosphere activity monitors R-11 (particulate monitor) & R-12 (gaseous monitor) declared inoperable when vacuum pump tripped due to erroneous high flow signal Caused by faulty high flow relay
HAIRSTON, W G Alabama Power Co 82/12/23 Region 2, Office of Director 1p 16598 110 24X Fiche 50-364, 82/12/23, 8212300216

--8212300236 LER 82-050/03L-0 on 821124, source range channel N32 declared inoperable due to erratic readings Caused by faulty detector on N31 & faulty high voltage power supply cable connector on N32 Detector & cable connector replaced
HAIRSTON, W G Alabama Power Co 82/12/23 Region 2, Office of Director 1p 16598 111 24X Fiche 50-364, 82/12/23, 8212300216

DOCKET 50-366 EDWIN I HATCH NUCLEAR PLANT, UNIT 2

F Security, medical, emergency & fire protection plans

8212150009 Confirms telcon re emergency facility status per Generic Ltr 82-10 Structures complete & habitable Info equipment not completely installed, but facility operable
BECKHAM, J T Georgia Power Co 82/12/08 Office of Nuclear Reactor Regulation, Director 1p 16421 138 24X
Fiche 50-321, 82/12/08, 8212150009

J Insurance & indemnity information

8212280222 Forwards ANI & MAELU secondary financial protection certificates of insurance N-51, N-67, M-51 & M-67
DUCK, J R Marsh & McLennan, Inc J M & M Nuclear Consultants, Inc Div 82/12/20 SALTZMAN, J Assistant Director for State & Licensee Relations 41pp 16562 135 24X Fiche 50-321, 82/12/20, 8212280222

8212280369 Forwards Endorsement 74 to NELIA Policy NF-215 & Endorsement 60 to MAELU Policy MF-78
DUCK, J R Marsh & McLennan, Inc J M & M Nuclear Consultants, Inc Div 82/12/20 SALTZMAN, J Assistant Director for State & Licensee Relations 3pp 16560 067 24X Fiche 50-321, 82/12/20, 8212280369

P Operating license stage documents & correspondence

8212100393 Requests verification that encl acceptance criteria for NUREG-0737, Item II K 3 22, "Automatic Switchover of RCIC Sys Section," satisfied Response requested within 30 days
STOLZ, J F Operating Reactors Branch 4 82/08/04 BECKHAM, J T Georgia Power Co 4pp 16389 220 24X Fiche 50-321, 82/08/04, 8212100393

821230066 Generic Ltr 82-27 to all BWR licensees of operating reactors except LACBWR, Big Rock Point, Dresden 1, Humboldt Bay, applicants for DL & holders of CP re transmittal of NUREG-0763 & NUREG-0783 Svc list encl W/o stated encl
EISENHUT, D O Division of Licensing 82/11/15 General Public Utilities - CPU Service Corp 22pp 16387 004 24X
Fiche 50-000, 82/11/15, 821230066

8212170246 Advises that specific containment & purge valves identified in NRC 821110 ltr are not applicable to facilities Meeting requested to determine status of remaining issue re purging & venting
BECKHAM, J T Georgia Power Co 82/12/13 Office of Nuclear Reactor Regulation, Director 1p 16457 178 24X
Fiche 50-321, 82/12/13, 8212170246

8212290450 Informs of post-implementation review of NUREG-0737, Items II F 1 4, II F 1 9 & II F 1 6 re containment pressure, water level & hydrogen monitors Addl info & guidance for answering questions encl
STOLZ, J F Operating Reactors Branch 4 82/12/17 BECKHAM, J T Georgia Power Co 10pp 16606 074 24X Fiche 50-321, 82/12/17, 8212290450

8212290151 Revises estimated completion date for implementation of NUREG-0737, Item II B 3 to 830401, in response to Generic Ltr 82-05 Interim sampling capabilities per NUREG-0578 provided in 820607 ltr
GUCHAR, L T Georgia Power Co 82/12/20 Office of Nuclear Reactor Regulation, Director 1p 16582 239 24X Fiche 50-321, 82/12/20, 8212290151

Q Inspection reports, IE Bulletins & correspondence

8208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Bys Piping at BWR Plants " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240

8208190243 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list encl
COBB, L I Divisions of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000, 82/11/05, 8208190243

8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X
Fiche 50-000, 82/11/18, 8208190251

DOCKETED ITEMS

8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 055 24X Fiche 50-000, 82/11/26, 8208190256

8208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl
CORB, L J Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000, 82/11/30, 8208190257

8208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259

8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X Fiche 50-000, 82/12/03, 8208190261

8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16, 8208190267

8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27 " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X Fiche 50-000, 82/12/20, 8208190268

8212300189 Advises that NRC has no objection to use of 1980 Edition of ASME Section XI & addenda through Winter 1980 for inservice insp of Category B-H welded supports, in response to 820830 request for relief from 1974 Edition requirements
STOLZ, J F Operating Reactors Branch 4 82/12/20 BECKHAM, J T Georgia Power Co 2pp 16624 034 24X Fiche 50-321, 82/12/20, 8212300189

A Periodic operating reports & related correspondence

8212170353 Forwards monthly operating rpts for Nov 1982
NIX, H C Georgia Power Co 82/12/07 Director's Office, Office of Inspection and Enforcement 1p 16459 191 24X Fiche 50-321, 82/12/07, 8212170353

--8212170359 Monthly operating rpts for Nov 1982
SMITH, A Georgia Power Co 82/12/07 10pp 16459 192 24X Fiche 50-321, 82/12/07, 8212170359

B Reportable occurrences, LERs & related correspondence

8212020292 Forwards LER 82-120/03L-0
NIX, H C Georgia Power Co 82/11/19 O'REILLY, J P Region 2, Office of Director 1p 16279 140 24X Fiche 50-366, 82/11/19, 8212020292

--8212020295 LER 82-120/03L-0 on 821022, barrier adjacent to silicone foam fire barrier in cable spread room found breached Caused by penetration left unsealed after installation of conduit
Maint request initiated Seal repaired on 821102
SUMNER, H L Georgia Power Co 82/11/19 Region 2, Office of Director 1p 16279 141 24X Fiche 50-366, 82/11/19, 8212020292

8212090142 Forwards updated LER 78-059/03X-1
NIX, H C Georgia Power Co 82/11/23 O'REILLY, J P Region 2, Office of Director 1p 16359 172 24X Fiche 50-366, 82/11/23, 8212090142

--8212090149 Updated LER 78-059/03X-1 on 781026, during review of HNP-832 limiting conditions for operation instrument data sheets, 32 instruments exceeded calibr interval Caused by oversight Instruments calibr Personnel counseled re recordkeeping.
TIPPS, S B Georgia Power Co 82/11/23 Region 2, Office of Director 1p 16359 173 24X Fiche 50-366, 82/11/23, 8212090142

8212090247 Forwards LER 82-123/03L-0
NIX, H C Georgia Power Co 82/11/23 O'REILLY, J P Region 2, Office of Director 1p 16361 349 24X Fiche 50-366, 82/11/23, 8212090247

--8212090254 LER 82-123/03L-0 on 821030, during insertion of control rods for reactor shutdown, read switch position indicators for control rods 14-07 & 34-43 found inoperable Caused by component failure Indicators will be repaired
TIPPS, S B Georgia Power Co 82/11/23 Region 2, Office of Director 1p 16361 350 24X Fiche 50-366, 82/11/23, 8212090247

8212090381 Forwards updated LER 80-097/03X-1
NIX, H C Georgia Power Co 82/11/23 O'REILLY, J P Region 2, Office of Director 1p 16365 040 24X Fiche 50-366, 82/11/23, 8212090381

--8212090388 Updated LER 80-097/03X-1 on 800625, while performing HPCI steam line delta P instrument FT&C procedure, flow switch N004 setpoints found to be out of tolerance Caused by setpoint drift Switch calibr, tested & returned to svc
TIPPS, S B Georgia Power Co 82/11/23 Region 2, Office of Director 1p 16365 041 24X Fiche 50-366, 82/11/23, 8212090388

8212090386 Forwards updated LER 80-019/03X-1
NIX, H C Georgia Power Co 82/11/23 O'REILLY, J P Region 2, Office of Director 1p 16364 193 24X Fiche 50-366, 82/11/23, 8212090386

--8212090391 Updated LER 80-019/03X-1 on 800227, erroneous reading on drywell hydrogen dioxide analyzer A recorder disclosed Caused by diaphragm failure in analyzer vacuum pump Diaphragm replaced Analyzer calibr & functionally tested.
TIPPS, S B Georgia Power Co 82/11/23 Region 2, Office of Director 1p 16364 194 24X Fiche 50-366, 82/11/23, 8212090386

8212090121 Forwards LER 82-125/03L-0
NIX, H C Georgia Power Co 82/11/30 O'REILLY, J P Region 2, Office of Director 1p 16357 325 24X Fiche 50-366, 82/11/30, 8212090121

--8212090126 LER 82-125/03L-0 on 821103, w/reactor protection sys (RPS) alternate supply out of svc for maint, RPS supply over voltage relay discovered out of calibr Caused by component failure due to setpoint drift Relay recalibr
TIPPS, S B Georgia Power Co 82/11/30 Region 2, Office of Director 1p 16357 326 24X Fiche 50-366, 82/11/30, 8212090121

8212090329 Forwards updated LER 81-084/03X-1
NIX, H C Georgia Power Co 82/11/30 O'REILLY, J P Region 2, Office of Director 1p 16365 079 24X Fiche 50-366, 82/11/30, 8212090329

--8212090335 Updated LER 81-084/03X-1 on 810903, N005 HPCI steam line delta P switch found to activate at 204.5 inches water Caused by setpoint drift Barton Model 288A switch recalibr, tested & returned to svc
TIPPS, S B Georgia Power Co 82/11/30 Region 2, Office of Director 1p 16365 080 24X Fiche 50-366, 82/11/30, 8212090329

8212090389 Forwards LER 82-124/03L-0
NIX, H C Georgia Power Co 82/11/30 O'REILLY, J P Region 2, Office of Director 1p 16364 249 24X Fiche 50-366, 82/11/30, 8212090389

--8212090399 LER 82-124/03L-0 on 821102, during administrative review, temporary changes made to arm calibr procedure not reviewed & signed within required 14 days Caused by personnel error One dept assigned responsibility for tracking changes
TIPPS, S B Georgia Power Co 82/11/30 Region 2, Office of Director 1p 16364 250 24X Fiche 50-366, 82/11/30, 8212090389

8212090437 Forwards updated LER 80-100/01X-1
NIX, H C Georgia Power Co 82/11/30 O'REILLY, J P Region 2, Office of Director 1p 16364 176 24X Fiche 50-366, 82/11/30, 8212090437

--8212090446 Updated LER 80-100/01X-1 on 800702, during testing, switches N002A - D & N011A - D actuated above Tech Specs limit of plus/minus 2 psig Caused by setpoint drift Switches recalibr, tested & returned to svc
TIPPS, S B Georgia Power Co 82/11/30 Region 2, Office of Director 2pp 16364 177 24X Fiche 50-366, 82/11/30, 8212090437

8212100264 Forwards updated LER 80-141/03X-1
NIX, H C Georgia Power Co 82/11/30 O'REILLY, J P Region 2, Office of Director 1p 16377 050 24X Fiche 50-366, 82/11/30, 8212100264

--8212100279 Updated LER 80-141/03X-1 on 801014, while making power changes from 2,180 to 1,980 MWT, N004 HPCI steam line dp switch found to activate at 198 inches water Caused by setpoint drift Switch recalibr
TIPPS, S B Georgia Power Co 82/11/30 Region 2, Office of Director 1p 16377 051 24X Fiche 50-366, 82/11/30, 8212100264

DOCKETED ITEMS

239

8212100282 Forwards updated LER 80-103/01X-1
NIX,H C Georgia Power Co 82/11/30 O'REILLY, J P Region 2,
Office of Director 1p 16377 146 24X Fiche 50-366, 82/11/30,
8212100282

--8212100286 Updated LER 80-103/01X-1 on 800709, at 97% power, high drywell
pressure switches N010A - D actuated at 2.21, 2.34, 2.27 &
2.47 psig, respectively above Tech Spec limit of plus/minus
2 psig Caused by setpoint drift Switches recalibr & tested
TIPPS, S B Georgia Power Co 82/11/30 Region 2, Office of
Director 2pp 16377 147 24X Fiche 50-366, 82/11/30, 8212100282

8212100311 Forwards updated LER 81-121/03X-1
NIX,H C Georgia Power Co 82/11/30 O'REILLY, J P Region 2,
Office of Director 1p 16376 279 24X Fiche 50-366, 82/11/30,
8212100311

--8212100314 Updated LER 81-121/03X-1 on 811207, at 2,402 MWT, N004 HPCI
steam line dp switch actuated at 207.5 inches below Tech
Spec limit of plus/minus 300% rated flow Caused by setpoint
drift Switch recalibr, tested & returned to svc
TIPPS, S B Georgia Power Co 82/11/30 Region 2, Office of
Director 1p 16376 280 24X Fiche 50-366, 82/11/30, 8212100311

8212140421 Forwards updated LER 80-076/03X-1
NIX,H C Georgia Power Co 82/11/30 O'REILLY, J P Region 2,
Office of Director 1p 16404 197 24X Fiche 50-366, 82/11/30,
8212140421

--8212140429 Updated LER 80-076/03X-1 on 800429, 61 of 137 control rod
drive line hydraulic control unit pressure switches found to
have setpoints greater than Tech Spec limit Caused by
instrument drift Switches recalibr & returned to svc
TIPPS, S B Georgia Power Co 82/11/30 Region 2, Office of
Director 1p 16404 198 24X Fiche 50-366, 82/11/30, 8212140421

8212140433 Forwards updated LER 79-124/03X-1
NIX,H C Georgia Power Co 82/11/30 O'REILLY, J P Region 2,
Office of Director 1p 16404 361 24X Fiche 50-366, 82/11/30,
8212140433

--8212140436 Updated LER 79-124/03X-1 on 791120, vacuum breaker E failed
to open per Tech Specs Caused by stuck valve operator Valve
operator freed & repaired Torus/drywell vacuum breaker E
satisfactorily tested & returned to svc
TIPPS, S B Georgia Power Co 82/11/30 Region 2, Office of
Director 1p 16404 362 24X Fiche 50-366, 82/11/30, 8212140433

8212090190 Forwards updated LER 82-112/01X-2
NIX,H C Georgia Power Co 82/12/02 O'REILLY, J P Region 2,
Office of Director 1p 16361 295 24X Fiche 50-366, 82/12/02,
8212090190

--8212090193 Updated LER 82-112/01X-2 from 821009-1118 inadequacies
discovered in test procedures for automatic initiation logic
of listed plant sys Caused by failure to test relay k/or
continuity of one or more sets of contacts
SUMNER, H L Georgia Power Co 82/12/02 Region 2, Office of
Director 2pp 16361 296 24X Fiche 50-366, 82/12/02, 8212090190

8212170155 Forwards LER 82-126/03L-0
NIX,H C Georgia Power Co 82/12/03 O'REILLY, J P Region 2,
Office of Director 1p 16450 298 24X Fiche 50-366, 82/12/03,
8212170155

--8212170165 LER 82-126/03L-0 on 821105, post-accident high drywell
pressure alarm failed to actuate during quarterly
surveillance test Caused by erroneous wiring of drywell &
torus pressure recorder Wiring error corrected
TIPPS, S B Georgia Power Co 82/12/03 Region 2, Office of
Director 1p 16450 299 24X Fiche 50-366, 82/12/03, 8212170155

8212140115 Forwards updated LER 81-116/03Y-1
NIX,H C Georgia Power Co 82/12/07 O'REILLY, J P Region 2,
Office of Director 1p 16408 245 24X Fiche 50-366, 82/12/07,
8212140115

--8212140123 Updated LER 81-116/03X-1 on 811125, N004 HPCI steam line
differential pressure switch actuated above Tech Spec limits
during performance of steam line instrument FT & C
procedures Caused by setpoint drift Switch recalibr
TIPPS, S B Georgia Power Co 82/12/07 Region 2, Office of
Director 1p 16408 246 24X Fiche 50-366, 82/12/07, 8212140115

8212210446 Forwards LER 82-127/03L-0
NIX,H C Georgia Power Co 82/12/07 O'REILLY, J P Region 2,
Office of Director 1p 16489 194 24X Fiche 50-366, 82/12/07,
8212210446

--8212210452 LER 82-127/03L-0 on 821113, during hydrogen & oxygen analyzer
FT & C procedure, A drywell analyzer found inoperable Caused
by component failure, due to loose connection Connection
repaired & component returned to svc
TIPPS, S B Georgia Power Co 82/12/07 Region 2, Office of
Director 1p 16489 195 24X Fiche 50-366, 82/12/07, 8212210446

8212150090 PND-11-82-134 on 821208, bomb threat received while in final
preparation for full scale emergency drill Security
determined call came from security guard posted at entry
gate to owner controlled area Guard fired & arrested
TILLMAN, A, MCGUIRE, D R Region 2, Office of Director 82/12/07
2pp 16430 189 24X Fiche 50-366, 82/12/07, 8212150090

8212280159 Forwards LER 82-122/03L-0
NIX,H C Georgia Power Co 82/12/16 O'REILLY, J P Region 2,
Office of Director 1p 16556 133 24X Fiche 50-366, 82/12/16,
8212280159

--8212280161 LER 82-122/03L-0 on 821123, during Mode 1 at 2,417 MWT, fire
detector surveillance safety-related areas procedure not
completed by latest possible date (821123) Caused by
personnel oversight Personnel counseled
TIPPS, S B Georgia Power Co 82/12/16 Region 2, Office of
Director 1p 16556 134 24X Fiche 50-366, 82/12/16, 8212280159

8212300058 Forwards updated LER 82-043/03X-1
NIX,H C Georgia Power Co 82/12/16 O'REILLY, J P Region 2,
Office of Director 1p 16598 206 24X Fiche 50-366, 82/12/16,
8212300058

--8212300063 Updated LER 82-043/03X-1 on 820428, w/plant in refueling
outage, delta pressure switch N004 actuated above Tech Spec
limit Caused by setpoint drift Switch recalibr
TIPPS, S B Georgia Power Co 82/12/16 Region 2, Office of
Director 1p 16598 207 24X Fiche 50-366, 82/12/16, 8212300058

8212300284 Forwards updated LER 81-102/03X-1
NIX,H C Georgia Power Co 82/12/16 O'REILLY, J P Region 2,
Office of Director 1p 16594 075 24X Fiche 50-366, 82/12/16,
8212300284

--8212300290 Updated LER 81-102/03X-1 on 811026, P001B primary containment
hydrogen peroxide analyzer declared inoperable due to
erratic operation Caused by worn pump head valve body Pump
repaired & analyzer returned to svc
TIPPS, S B Georgia Power Co 82/12/16 Region 2, Office of
Director 1p 16594 076 24X Fiche 50-366, 82/12/16, 8212300284

8212300285 Forwards updated LER 80-109/03X-1
NIX,H C Georgia Power Co 82/12/16 O'REILLY, J P Region 2,
Office of Director 1p 16595 117 24X Fiche 50-366, 82/12/16,
8212300285

--8212300292 Updated LER 80-109/03X-1 on 800809, during HPCI valve
operability procedure, HPCI suppression chamber suction valve
failed when cycled to check battery ground Caused by motor
winding failure due to humid temp Valve motor repaired
TIPPS, S B Georgia Power Co 82/12/16 Region 2, Office of
Director 1p 16595 118 24X Fiche 50-366, 82/12/16, 8212300285

8212300295 Forwards updated LER 81-115/03X-1
NIX,H C Georgia Power Co 82/12/16 O'REILLY, J P Region 2,
Office of Director 1p 16594 290 24X Fiche 50-366, 82/12/16,
8212300295

--8212300298 Updated LER 81-115/03X-1 on 821123, during performance of
HPCI turbine exhaust diaphragm pressure instrument FT&C
procedure, pressure switch N012A actuated above Tech Spec
limit Caused by setpoint drift Switch recalibr
TIPPS, S B Georgia Power Co 82/12/16 Region 2, Office of
Director 1p 16594 291 24X Fiche 50-366, 82/12/16, 8212300295

8212300323 Forwards updated LER 80-124/03X-1
NIX,H C Georgia Power Co 82/12/16 O'REILLY, J P Region 2,
Office of Director 1p 16594 082 24X Fiche 50-366, 82/12/16,
8212300323

--8212300325 Updated LER 80-124/03X-1 on 800813 & 27, during surveillance
of torus/drywell vacuum breakers, J & I breakers failed to
give proper light indication Caused by air control valves
being out of adjustment Valves adjusted & breakers tested
TIPPS, S B Georgia Power Co 82/12/16 Region 2, Office of
Director 1p 16594 083 24X Fiche 50-366, 82/12/16, 8212300323

8212300340 Forwards updated LER 80-101/03X-1
NIX,H C Georgia Power Co 82/12/16 O'REILLY, J P Region 2,
Office of Director 1p 16594 223 24X Fiche 50-366, 82/12/16,
8212300340

DOCKETED ITEMS

--B212300345 Updated LER 80-101/03X-1 on 800711. HPCI sys failed to manual start due to failure of F006 HPCI injection valve. Caused by motor winding failure due to design problem. Motor replaced. Valve tested & returned to svc. TIFPS, S B Georgia Power Co 80/12/16 Region 2, Office of Director 1p 16594 224 24X Fiche 50-366, 82/12/16, 8212300340

B212300344 Forwards updated LER 80-129/03X-1 NIX, H C Georgia Power Co 82/12/16 O'REILLY, J P Region 2, Office of Director 1p 16594 227 24X Fiche 50-366, 82/12/16, 8212300344

--B212300346 Updated LER 80-129/03X-1 on 800918, torus/drywell vacuum breaker Q failed to open upon actuation of test switch. Caused by air control valve out of adjustment. Valve adjusted & breaker satisfactorily tested & returned to svc on 800929. TIFPS, S B Georgia Power Co 82/12/16 Region 2, Office of Director 1p 16594 228 24X Fiche 50-366, 82/12/16, 8212300344

B212300098 Forwards LER 82-128/03L-0 NIX, H C Georgia Power Co 82/12/21 O'REILLY, J P Region 2, Office of Director 1p 16598 129 24X Fiche 50-366, 82/12/21, 8212300098

--B212300102 LER 82-128/03L-0 on 821125, during power ascension, core max fraction of limiting power density found greater than Tech Spec limit. Caused by control rod movement in low xenon concentration producing higher power. Monitor adjusted. SUMNER, H L Georgia Power Co 82/12/21 Region 2, Office of Director 2pp 16598 130 24X Fiche 50-366, 82/12/21, 8212300098

DOCKET 50-367 BAILLY GENERATING STATION

A Application/construction stage documents & correspondence

B211230066 Generic Ltr 82-27 to all BHR licensees of operating reactors except LACBWR, Big Rock Point, Dresden 1, Humboldt Bay, applicants for QL & holders of CP re transmittal of NUREG-0763 & NUREG-0783 Svc list encl W/o stated encl. EISENHUT, D O Division of Licensing 82/11/15 General Public Utilities - OPU Service Corp 22pp 16387 004 24X Fiche 50-000, 82/11/15, 8211230066

B212160729 Forwards evaluation of util final rept re site restoration, per ASLB 820506 order. Util has restored site per approved restoration plan. SCHWENGER, A Licensing Branch 2 82/12/13 SHORB, E M Northern Indiana Public Service Co 5pp 16466 008 24X Fiche 50-367, 82/12/13, 8212160729

Q Inspection reports, IE Bulletins & correspondence

B212100195 Forwards IE Insp Rept 50-367/82-02 on 821116 No noncompliance noted. KNOP, R C Division of Project & Resident Programs 82/11/24 SHORB, E M Northern Indiana Public Service Co 2pp 16376 200 24X Fiche 50-367, 82/11/24, 8212100195

--B212100200 IE Insp Rept 50-367/82-02 on 821116 No noncompliance noted. Major areas inspected site restoration activities. FELKE, P R, KONKLIN, J E Division of Project & Resident Programs 82/11/24 2pp 16376 202 24X Fiche 50-367, 82/11/24, 8212100195

DOCKET 50-368 ARKANSAS NUCLEAR ONE, UNIT 2

F Security, medical, emergency & fire protection plans

B212070425 Responds to FOIA request for documents re 820809 notice of violation & order imposing civil penalty. Forwards App A documents. App B documents completely withheld & Documents C1-C4 partially withheld (ref FOIA Exemptions 3, 5 & 7). FELTON, J M Division of Rules and Records 82/11/05 MCGARRY, J M DeBoevisse & Liberman 5pp 16355 003 24X Fiche 50-000, 82/11/05, 8212070425

--B212070473 Concludes that all Region 4 licensees in compliance w/820201 deadlines for implementation of prompt notification sys. COLLINS, J T Region 4, Office of Director 82/02/01 GRIMES, B K Division of Emergency Preparedness 2pp 16355 104 24X Fiche 50-000, 82/11/03, 8212070425

B212080074 Releases public version of revised emergency plan procedure. FELTON, J M Division of Rules and Records 82/12/01 Document Management Branch 1p 16367 185 24X Fiche 50-313, 82/12/01, 8212080074

--B212080082 Forwards public version of Revision 4 to Emergency Plan Procedure 1903 30, "Plant Evacuation." Receipt form encl. * Arkansas Power & Light Co 82/11/12 NRC - No Detailed Affiliation Given 1p 16367 186 24X Fiche 50-313, 82/12/01, 8212080074

--B212080085 Public version of Revision 4 to Emergency Plan Procedure 1903 30, "Plant Evacuation." * Arkansas Power & Light Co 82/11/11 3pp 16367 187 24X Fiche 50-313, 82/12/01, 8212080074

B212090311 Forwards emergency operations facility (EOF) summary info, per O Vissing 821203 request & Generic Ltr 82-10 Const of permanent backup EOF completed. MARSHALL, J R Arkansas Power & Light Co 82/12/06 STOLZ, J F Operating Reactors Branch 4 CLARK, R A Operating Reactors Branch 3 2pp 16365 127 24X Fiche 50-313, 82/12/06, 8212090311

B212150272 Releases public version of ack of receipt of licensee ltr transmitting amend to emergency plan. FELTON, J M Division of Rules and Records 82/12/08 Document Management Branch 1p 16446 276 24X Fiche 50-313, 82/12/08, 8212150272

--B212150280 Submits public version of ack of receipt of licensee B20827 ltr transmitting Amend 5 to emergency plan info re compliance w/requirements of 10CFR50.54(t) re annual review & audits of emergency plan requested. SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs 82/11/24 CAVANAUGH, W Arkansas Power & Light Co 2pp 16446 278 24X Fiche 50-313, 82/12/08, 8212150272

--B212150288 Forwards public version of transmittal of Amend 5 to emergency plan, incorporating both State of AR & in-house comments W/o encl. MARSHALL, J R Arkansas Power & Light Co 82/08/27 COLLINS, J Office of Nuclear Regulatory Research, Director DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 16446 280 24X Fiche 50-313, 82/12/08, 8212150272

B212160542 Forwards draft safety evaluations of util requests for exemptions from fire protection of safe shutdown capability & of safe shutdown capability in event of fire. Proposed mode will be reviewed in 1983 Confirmation of 821111 ltr needed. CLARK, R A Operating Reactors Branch 3 STOLZ, J F Operating Reactors Branch 4 82/12/08 CAVANAUGH, W Arkansas Power & Light Co 57pp 16447 125 24X Fiche 50-313, 82/12/08, 8212160542

B212280224 Discusses util 820701 response documenting results of review of fire zones for compliance w/10CFR50.48 & App R Alternate shutdown capability would be provided by cross-feed between Units 1 & 2. Special entry for G valves will not be made. MARSHALL, J R Arkansas Power & Light Co 82/12/10 EISENHUT, D O Division of Licensing 1p 16562 176 24X Fiche 50-313, 82/12/10, 8212280224

B212230132 Releases public version of revised nuclear contingency plan procedure. FELTON, J M Division of Rules and Records 82/12/15, Document Management Branch 1p 16543 279 24X Fiche 50-313, 82/12/15, 8212230132

--B212230165 Forwards public version of Revision 1 to Nuclear Contingency Plan Procedure 9, "Emergency Response Support." MARSHALL, J R Arkansas Power & Light Co 82/12/10 COLLINS, J T Region 4, Office of Director EISENHUT, D O Division of Licensing 1p 16543 280 24X Fiche 50-313, 82/12/15, 8212230132

--B212230172 Public version of Revision 1 to Nuclear Contingency Plan Procedure 9, "Emergency Response Support." * Arkansas Power & Light Co 82/11/15 86pp 16543 282 24X Fiche 50-313, 82/12/15, 8212230132

P Operating license stage documents & correspondence

B212030169 Forwards info re NUREG-0737, Item II B.3, "Post-Accident Sampling Sys," in response to NRC 820701 request. Grab sample sys utilized as backup to online sampling sys. MARSHALL, J R Arkansas Power & Light Co 82/11/24 CLARK, R A Operating Reactors Branch 3 STOLZ, J F Operating Reactors Branch 4 12pp 16306 254 24X Fiche 50-313, 82/11/24, 8212030169

B212060262 Requests extension until 830228 to respond to NRC 820721 request for Tech Spec revision re snubber surveillance. Extension needed to review implications of ANBI/ASME DMA-1982. MARSHALL, J R Arkansas Power & Light Co 82/11/26 STOLZ, J F Operating Reactors Branch 4 CLARK, R A Operating Reactors Branch 3 2pp 16312 272 24X Fiche 50-313, 82/11/26, 8212060262.

8212040333 Requests extension to 830228 for submittal of App I revisions
MARSHALL, J R Arkansas Power & Light Co 82/11/30 STOLZ, J F
Operating Reactors Branch 4 CLARK, R A Operating Reactors Branch
3 2pp 16312 190 24X Fiche 50-313, 82/11/30, 8212060333

8212070284 Forwards summary of analysis of pressurizer safety & relief valve discharge piping, as required by NUREG-0737, Item II D 1 Piping stresses & support loads do not meet code, however, piping & valves will remain operable
MARSHALL, J R Arkansas Power & Light Co 82/11/30 STOLZ, J F
Operating Reactors Branch 4 CLARK, R A Operating Reactors Branch
3 4pp 16343 195 24X Fiche 50-313, 82/11/30, 8212070284

8212210013 Forwards SER on NUREG-0737, Item II A 2 1, "Upgraded Reactor Operator & Senior Reactor Operator Training" & Item II B 4, "Training for Mitigating Core Damage" Items resolved
STOLZ, J F Operating Reactors Branch 4 CLARK, R A Operating Reactors Branch 3 82/12/01 CAVANAUGH, W Arkansas Power & Light Co 8pp 16543 221 24X Fiche 50-313, 82/12/01, 8212210013

8208190263 Generic Ltr 82-32 to all PWR licensees re potential steam generator-related generic requirements Forwards Science Applications, Inc draft rept re subj requirements Comments requested within 30 days of ltr Svc list encl
EISENHUT, D O Division of Licensing 82/12/09 Consolidated Edison Co of New York, Inc 29pp 16629 247 24X Fiche 50-000, 82/12/09, 8208190263

8212170215 Forwards proprietary & nonproprietary slides, "Fuel Shoulder Gap Mod," used at 821006 meeting re fuel shoulder gap problem Affidavit from C-E encl B1ides withheld (ref 10CFR2 790)
MARSHALL, J R Arkansas Power & Light Co 82/12/10 CLARK, R A
Operating Reactors Branch 3 5pp 16456 028 24X Fiche 50-368, 82/12/10, 8212170215

8212210039 Forwards response to 821119 request for info & clarification of 13 remaining open items re inservice test program
MARSHALL, J R Arkansas Power & Light Co 82/12/10 CLARK, R A
Operating Reactors Branch 3 4pp 16490 220 24X Fiche 50-368, 82/12/10, 8212210039

8212270421 Forwards order for mod of licenses requiring installation of inadequate core cooling instrumentation sys conforming w/ NUREG-0737, Item II F 2
EISENHUT, D O Division of Licensing 82/12/10 CAVANAUGH, W
Arkansas Power & Light Co 2pp 16572 330 24X Fiche 50-313, 82/12/10, 8212270421

--8212270427 Order for mod of licenses requiring installation of inadequate core cooling instrumentation sys conforming w/ NUREG-0737, Item II F 2 Checklist for review of sys encl
EISENHUT, D O Division of Licensing 82/12/10 Arkansas Power & Light Co 11pp 16572 332 24X Fiche 50-313, 82/12/10, 8212270421

8212290022 Responds to 821130 ltr requesting extension of response date re App I submittal to 830228 Delay acceptable
CLARK, R A Operating Reactors Branch 3 STOLZ, J F Operating Reactors Branch 4 82/12/14 CAVANAUGH, W Arkansas Power & Light Co 2pp 16607 181 24X Fiche 50-313, 82/12/14, 8212290022

8212280459 Informs of procurement of seismic instrumentation to augment & replace triaxial time-history accelerographs Changes to Tech Specs re new equipment will be submitted & will obviate request for deletion of monthly channel check requirement
MARSHALL, J R Arkansas Power & Light Co 82/12/20 CLARK, R A
Operating Reactors Branch 3 2pp 16556 009 24X Fiche 50-368, 82/12/20, 8212280459

G Inspection reports, IE Bulletins & correspondence

8208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel Recirculation Bypass Piping at BWR Plants," Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240

8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters" Svc list encl
CDBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000, 82/11/05, 8208190245

8212210245 Forwards IE Insp Repts 50-313/82-21 & 50-368/82-18 on 820802-06 No noncompliance noted.
SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs 82/11/05 CAVANAUGH, W Arkansas Power & Light Co 2pp 16483 317 24X Fiche 50-313, 82/11/05, 8212210245

--8212210250 IE Insp Repts 50-313/82-21 & 50-368/82-18 on 820802-06 No noncompliance noted Major areas inspected licensee action on previous insp findings, procedures review qualification & exposure control
BAER, R, WILBORN, L, HOLLEV, W Division of Resident, Reactor Project & Engineering Programs 82/10/28 29pp 16483 319 24X Fiche 50-313, 82/11/05, 8212210245

8212140481 Forwards addl info re IE Bulletin 82-02, clarifying 820929 commitments Results of mail review to determine number of leaks on bolted closures listed
MARSHALL, J R Arkansas Power & Light Co 82/11/08 COLLINS, J T Region 4, Office of Director 5pp 16403 355 24X Fiche 50-313, 82/11/08, 8212140481

8212140334 Responds to IE Bulletin 82-01, Revision 1, Suppl 1, "Alterations of Radiographs of Welds in Piping Subassemblies" Listing of specific welds & action taken encl Actions indicate resolution of discrepancies
MARSHALL, J R Arkansas Power & Light Co 82/11/11 COLLINS, J T Region 4, Office of Director 4pp 16401 284 24X Fiche 50-368, 82/11/11, 8212140334

8212030184 Forwards IE Insp Rept 50-368/82-32 on 821025-29 No noncompliance noted
SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs 82/11/12 CAVANAUGH, W Arkansas Power & Light Co 2pp 16303 214 24X Fiche 50-368, 82/11/12, 8212030184

--8212030192 IE Insp Rept 50-368/82-32 on 821025-29 No noncompliance noted Major areas inspected pipe hangers following licensee rept of numerous svc water sys deficiencies
JOHNKINS, D P Region 4, Office of Director CUMMINS, J E, TOMLINSON, W D Division of Resident, Reactor Project & Engineering Programs 82/11/05 4pp 16303 216 24X Fiche 50-368, 82/11/12, 8212030184

8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements" Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X Fiche 50-000, 82/11/18, 8208190251

8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks" Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000, 82/11/26, 8208190256

8208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl" Svc list encl
CDBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 336pp 16387 028 24X Fiche 50-000, 82/11/30, 8208190257

8208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies" Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259

8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets" Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X Fiche 50-000, 82/12/03, 8208190261

8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring" Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16, 8208190267

8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27" Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X Fiche 50-000, 82/12/20, 8208190268

8212290192 Ack receipt of 821105 ltr informing NRC of steps taken to correct deviation noted in IE Insp Repts 50-313/82-19 & 50-368/82-16
SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs 82/12/23 CAVANAUGH, W Arkansas Power & Light Co 1p 16578 132 24X Fiche 50-313, 82/12/23, 8212290192

--8212290198 Responds to NRC 821007 ltr re deviation noted in IE Insp Repts 50-313/82-19 & 50-368/82-16 Corrective actions environ qualification info submitted in 820729 & 0813 ltrs Commitment tracking sys implemented
MARSHALL, J R Arkansas Power & Light Co 82/11/05 SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs 2pp 16578 133 24X Fiche 50-313, 82/12/23, 8212290192

DOCKETED ITEMS

R Periodic operating reports & related correspondence

8212290168 Forwards suppl to "Annual Environ Monitoring Rept, 1981"
MARSHALL, J R Arkansas Power & Light Co 82/11/12 COLLINS, J T
Region 4, Office of Director 1p 16582 181 24X
Fiche 50-313, 82/11/12, 8212290168

--8212290171 Suppl to "Annual Environ Monitoring Rept, 1981"
* Arkansas Power & Light Co 82/11/12 15pp 16592 182 24X
Fiche 50-313, 82/11/12, 8212290168

8212290234 Forwards monthly operating rept for Oct 1982
MARSHALL, J R Arkansas Power & Light Co 82/11/15 HALLER, N M
Management Information Branch 1p 16582 173 24X
Fiche 50-368, 82/11/15, 8212290234

--8212290236 Monthly operating rept for Oct 1982
BRAMLETT, L S Arkansas Power & Light Co 82/11/15 4pp
16582 174 24X Fiche 50-368, 82/11/15, 8212290234

S Reportable occurrences, LERs & related correspondence

8212030066 Forwards LER 82-033/03L-0
MARSHALL, J R Arkansas Power & Light Co 82/11/18 SEIDLE, W C
Division of Resident, Reactor Project & Engineering Programs 1p
16307 157 24X Fiche 50-368, 82/11/18, 8212030066

--8212030075 LER 82-033/03L-0 on 821018, while in Mode 6, safety injection
check valve 2SI-13C stuck in open position when stroked by
hand Caused by protruding valve disc stud Portion of
protruding disc stud filled off
ROOGER, P Arkansas Power & Light Co 82/11/18 Region 4,
Office of Director 2pp 16307 158 24X Fiche 50-368, 82/11/18,
8212030066

8212100254 PNO-IV-82-044 on 821203, normal phone communication lost due
to local flooding caused by heavy rains & severe weather
Backup radio communications feasible from elevated ground
northwest of Little Rock Addl heavy rain possible
SEIDLE, W C, OAGLIARDO, J E Region 4, Office of Director 82/12/03
2pp 16376 127 24X Fiche 50-313, 82/12/03, 8212100254

8212210027 Forwards LER 82-038/03L-0
MARSHALL, J R Arkansas Power & Light Co 82/12/06 SEIDLE, W C
Division of Resident, Reactor Project & Engineering Programs 1p
16485 361 24X Fiche 50-368, 82/12/06, 8212210027

--8212210028 LER 82-039/03L-0 on 821111, emergency feedwater control valve
2CV-1076-2 found not wired per installation drawings Caused
by installation oversight Circuitry for valve operators
connected to conform to electrical schematic
ROOGER, P Arkansas Power & Light Co 82/12/07 Region 4,
Office of Director 1p 16485 362 24X Fiche 50-368, 82/12/06,
8212210027

8212210117 Forwards LER 82-034/03L-0
MARSHALL, J R Arkansas Power & Light Co 82/12/07 SEIDLE, W C
Division of Resident, Reactor Project & Engineering Programs 1p
16485 125 24X Fiche 50-368, 82/12/07, 8212210117

--8212210120 LER 82-034/03L-0 on 821107, improper level indication
observed on C safety injection tank Caused by water in
safety injection tank saturated w/nitrogen, causing gas
bubbles to develop in transmitter ref legs Legs vented
MOEGGENDER, D Arkansas Power & Light Co 82/12/07 Region 4,
Office of Director 2pp 16485 126 24X Fiche 50-368, 82/12/07,
8212210117

8212210193 Forwards LER 82-037/03L-0
MARSHALL, J R Arkansas Power & Light Co 82/12/07 SEIDLE, W C
Division of Resident, Reactor Project & Engineering Programs 1p
16484 354 24X Fiche 50-368, 82/12/07, 8212210193

--8212210198 LER 82-037/03L-0 on 821110, during low power testing in
Mode 2, breaker to operating charging pump 2P36A tripped
Caused unknown Resistance check of all motor leads &
windings revealed no abnormalities
MOEGGENDER, D Arkansas Power & Light Co 82/12/07 Region 4,
Office of Director 1p 16484 355 24X Fiche 50-368, 82/12/07,
8212210193

8212210257 Forwards LER 82-036/03L-0
MARSHALL, J R Arkansas Power & Light Co 82/12/07 SEIDLE, W C
Division of Resident, Reactor Project & Engineering Programs 1p
16483 299 24X Fiche 50-368, 82/12/07, 8212210257

--8212210260 LER 82-036/03L-0 on 821108, during Mode 3, emergency feedwater
pump 2P-7A isolation valve 2CV-1062-2 failed to close
Caused by changes in operating characteristics due to
contact not being wired
MOEGGENDER, D Arkansas Power & Light Co 82/12/07 Region 4,
Office of Director 1p 16483 300 24X Fiche 50-368, 82/12/07,
8212210257

8212280072 LER 82-042/01T-0 on 821210, power ascension testing revealed
that values of shape annealing matrix for all four CPC
channels improperly loaded into CPCs Caused not stated
Correct matrix loaded within 1 h
LEVINE, J M Arkansas Power & Light Co 82/12/10 COLLINS, J
Region 4, Office of Director 2pp 16565 094 24X
Fiche 50-368, 82/12/10, 8212280072

8212210208 PNO-IV-82-048 on 821211, unit tripped from 97% power due
to dropped control element assembly (CEA) Caused by failure
of upper gripper coil for part length CEA 26
JOHNSON, W D, CALLAN, L J Region 4, Office of Director 82/12/13
1p 16485 031 24X Fiche 50-368, 82/12/13, 8212210208

8212270189 Forwards LER 82-039/03L-0
MARSHALL, J R Arkansas Power & Light Co 82/12/13 SEIDLE, W C
Division of Resident, Reactor Project & Engineering Programs 1p
16337 299 24X Fiche 50-368, 82/12/13, 8212270189

--8212270194 LER 82-039/03L-0 on 821112, degraded fire barrier existed due
to unsealed piping penetrations Caused by personnel error
arising from insufficient instruction on applicable design
change documentation Penetrations sealed
WADE, P B Arkansas Power & Light Co 82/12/13 Region 4,
Office of Director 2pp 16539 300 24X Fiche 50-368, 82/12/13,
8212270189

8212190212 Forwards LER 82-041/03L-0
MARSHALL, J R Arkansas Power & Light Co 82/12/13 SEIDLE, W C
Division of Resident, Reactor Project & Engineering Programs 1p
16578 196 24X Fiche 50-368, 82/12/13, 8212190212

--8212290223 LER 82-041/03L-0 on 821124, isolation valve 2MS-0340 failed
to close & steam leak discovered in emergency feedwater pump
steam supply pressure transmitter 2PT-0340 Caused by
stripped threads due to overtightening of tubing connector
ROOGER, P Arkansas Power & Light Co 82/12/13 Region 4,
Office of Director 2pp 16578 197 24X Fiche 50-368, 82/12/13,
8212290212

8212280142 Forwards revised LER 82-036/03L-1
MARSHALL, J R Arkansas Power & Light Co 82/12/15 SEIDLE, W C
Division of Resident, Reactor Project & Engineering Programs 1p
16563 186 24X Fiche 50-368, 82/12/15, 8212280142

--8212280146 Revised LER 82-036/03L-1 on 821108, during Mode 3, emergency
feedwater pump 2P-7A isolation valve 2CV-1026-2 failed to
close following surveillance testing Caused by change in
operating characteristics due to miswired contact
MOEGGENDER, D Arkansas Power & Light Co 82/12/07 Region 4,
Office of Director 2pp 16563 187 24X Fiche 50-368, 82/12/15,
8212280142

8212300052 Forwards LER 82-044/03L-0
MARSHALL, J R Arkansas Power & Light Co 82/12/21 SEIDLE, W C
Division of Resident, Reactor Project & Engineering Programs 1p
16598 191 24X Fiche 50-368, 82/12/21, 8212300052

--8212300059 LER 82-044/03L-0 on 821206, control power fuse opened on
charging pump 2P-036-C during pump startup while charging
pump A (inoperable due to maint) Possibly caused by fuse
fatigue or dragging contactor Fuse/motor contacts replaced
WADE, P B Arkansas Power & Light Co 82/12/21 Region 4,
Office of Director 1p 16598 192 24X Fiche 50-368, 82/12/21,
8212300052

8212300088 Forwards LER 82-042/01T-0
MARSHALL, J R Arkansas Power & Light Co 82/12/21 SEIDLE, W C
Division of Resident, Reactor Project & Engineering Programs 1p
16599 024 24X Fiche 50-368, 82/12/21, 8212300088

--8212300090 LER 82-042/01T-0 on 821210, shape annealing matrix values for
core protection calculators found improperly loaded Caused
by personnel error due to inadequate labeling of matrix
elements listed by SAM analysis code
ROOGER, P Arkansas Power & Light Co 82/12/21 Region 4,
Office of Director 2pp 16599 030 24X Fiche 50-368, 82/12/21,
8212300088

8212300057 Forwards LER 82-045/03L-0
MARSHALL, J R Arkansas Power & Light Co 82/12/23 SEIDLE, W C
Division of Resident, Reactor Project & Engineering Programs 1p
16598 188 24X Fiche 50-368, 82/12/23, 8212300057

--821230062 LER 82-045/03L-0 on 821129, slow decrease in pressurizer pressure noted w/both proportional & one backup heater banks energized Caused by three open fuses Fuses replaced
MOEGENBERG, D Arkansas Power & Light Co 82/12/23 Region 4,
Office of Director 1p 16398 189 24X Fiche 50-368,82/12/23,
8212300037

8212300182 PNO-IV-82-052 administrative measures taken to preclude potential problem w/single plant protection sys, including caution-tagged cabinets, shift supervisor briefing & operator review of San Onofre incident
JAUDON, J P, CALLAN, L J Region 4, Office of Director 82/12/27
1p 16597 329 24X Fiche 50-368,82/12/27,8212300182

DOCKET 50-369 WILLIAM B MCGUIRE NUCLEAR STATION, UNIT 1

F Security, medical, emergency & fire protection plans

8212130069 Forwards info on emergency offsite facilities (EOF), per R Birkel 821203 request & Generic Ltr 81-10 Const of permanent primary & backup EOF completed
TUCKER, H B Duke Power Co 82/12/03 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 16390 186 24X Fiche 50-000,82/12/03,8212130069

8212090044 Reviews util 820419 & 0727 ltrs re security personnel requalification requirements Annual supervisor observation considered sufficient requalification test
STOLZ, J F Operating Reactors Branch 4 82/12/07 TUCKER, H B Duke Power Co 2pp 16384 244 24X Fiche 50-000,82/12/07,8212090044

8212230067 Releases public version of emergency plan implementing procedures
FELTON, J M Division of Rules and Records 82/12/14 Document Management Branch 1p 16545 246 24X Fiche 50-369,82/12/14,8212230067

--8212230076 Forwards public version of emergency plan implementing procedures, including Procedure HP/D/B/1009/05 re first response evaluation of reactor coolant leak inside containment
TUCKER, H B Duke Power Co 82/12/02 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAH, E O Licensing Branch 4 2pp 16545 247 24X Fiche 50-369,82/12/14,8212230067

--8212230083 Public version of emergency plan implementing procedures, including Procedure HP/D/D/1009/05 re first response evaluation of reactor coolant leak inside containment
MCREE, W D, LEONARD, J R Duke Power Co 82/11/23 84pp 16545 249 24X Fiche 50-369,82/12/14,8212230067

8212230093 Releases public version of revision to crisis mgt plan & revisions to crisis mgt plan implementing procedures
FELTON, J M Division of Rules and Records 82/12/15 Document Management Branch 1p 16542 026 24X Fiche 50-000,82/12/15,8212230093

--8212230108 Forwards public version of Revision 7 to crisis mgt plan & revisions to crisis mgt plan implementing procedures
TUCKER, H B Duke Power Co 82/12/02 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 16542 027 24X Fiche 50-000,82/12/15,8212230093

--8212230124 Public version of Revision 7 to crisis mgt plan One oversize pamphlet encl Aperture card available in PDR
VAUGHN, R E Duke Power Co 82/11/29 9pp 16542 029 24X Fiche 50-000,82/12/15,8212230093

--8212230134 Public version of revised crisis mgt plan implementing procedures, including Procedures 5.3.2 re crisis news group plan & 5.3.11 re McGuire crisis phone directory
VAUGHN, R E Duke Power Co 82/11/29 280pp 16542 038 24X Fiche 50-000,82/12/15,8212230093

P Operating license stage documents & correspondence

8212030002 Forwards "Reactor Containment Bldg Integrated Leak Rate Test, Suppl 2"
TUCKER, H B Duke Power Co 82/11/18 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAH, E O Licensing Branch 4 1p 16304 216 24X Fiche 50-369,82/11/18,8212030002

--8212030003 "Reactor Containment Bldg Integrated Leak Rate Test, Suppl 2"
* Duke Power Co 82/11/18 3pp 16304.217. 24X Fiche 50-369,82/11/18,8212030002

8212060244 Application to amend License NPF-9, revising App A Tech Specs to reduce measurement uncertainty for total RCB flow Tech Spec, justification & safety analysis withheld
(ref 10CFR2 790)
TUCKER, H B Duke Power Co 82/11/23 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAH, E O Licensing Branch 4 3pp 16312 159 24X Fiche 50-369,82/11/23,8212060244

--8212060245 Requests withholding of proprietary matl re RCB total flowrate vs R1 & R2 - four loops in operation (STS), per encl Affidavit AW-76-60
WIESEMANN, R A Westinghouse Electric Corp 82/11/17 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAH, E O Licensing Branch 4 8pp 16312 162 24X Fiche 50-369,82/11/23,8212060244

8212010286 Submits list of outstanding items requiring responses by 821217 to complete review of OL application
ADENSAH, E O Licensing Branch 4 82/11/24 TUCKER, H B Duke Power Co 2pp 16271 254 24X Fiche 50-369,82/11/24,8212010286

8212070341 Forwards responses to NUREG-0737, Item II B 3, "Post-Accident Sampling Sys" w/14 oversize drawings Aperture cards are available in PDR
TUCKER, H B Duke Power Co 82/12/01 DENTON, H R Office of Nuclear Reactor Regulation, Director 32pp 16340 252 24X Fiche 50-269,82/12/01,8212070341

--8212070353 "Operating Procedure for Operation of Post-Accident Liquid Sample Sys"
DEAR, A M, MCCONNELL, T. Duke Power Co 82/05/17 18pp 16340 305 24X Fiche 50-269,82/12/01,8212070341

8212140390 Forwards fee for Class III amend re requests for relief from hydrostatic testing requirements on feedwater sys to steam generators & safety injection sys
TUCKER, H B Duke Power Co 82/12/03 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAH, E O Licensing Branch 4 2pp 16401 032 24X Fiche 50-369,82/12/03,8212140390

8212140103 Generic Ltr 82-28 to all licensees of operating Westinghouse & C-E PWRs (except Arkansas Nuclear One, Unit 2 & San Onofre 2 & 3) re inadequate core cooling instrumentation sys Svc list encl
EISENHUT, D O Division of Licensing 82/12/10 Yankee Atomic Electric Co 27pp 16690 035 24X Fiche 50-000,82/12/10,8212140103

8212150178 Notification of 821216 meeting w/util in Bethesda, MD to discuss independent design verification program
BIRKEL, R A Licensing Branch 4 82/12/10 ADENSAH, E O Licensing Branch 4 3pp 16437 350 24X Fiche 50-369,82/12/10,8212150178

8212160249 Forwards responses to questions re standby shutdown sys per NRC 821203 request
TUCKER, H B Duke Power Co 82/12/14 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAH, E O Licensing Branch 4 16pp 16446 100 24X Fiche 50-369,82/12/14,8212160249

8212170290 Forwards justification for addl 30-day operation of steam generators at 75% power, based on encl results of recent eddy current tests Mod scheduled for mid-Jan 1983
Concurrence requested
TUCKER, H B Duke Power Co 82/12/15 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAH, E O Licensing Branch 4 11pp 16456 166 24X Fiche 50-369,82/12/15,8212170290

8212210419 Forwards Amend 70 to application for OL, consisting of Revision 44 to FSAR
TUCKER, H B Duke Power Co 82/12/15 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAH, E O Licensing Branch 4 2pp 16490 056 24X Fiche 50-370,82/12/15,8212210419

8212290232 Requests exemption from 10CFR50.71(a) requirements re FSAR update initiated within 24 months of 800722 or OL issuance, whichever is later Updated FSAR will be submitted 12 months after issuance of OL for Unit 2
TUCKER, H B Duke Power Co 82/12/22 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAH, E O Licensing Branch 4 1p 16578 079 24X Fiche 50-369,82/12/22,8212290232

Q Inspection Reports, IE Bulletins & correspondence

8208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants." Svc list encl
DEVOUNO, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000,82/10/28,8208190240

DOCKETED ITEMS

8212090373 Forwards IE Insp Repts 50-369/82-38 & 50-370/82-33 on 820918-1020 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 82/11/04
TUCKER, H B Duke Power Co 2pp 16365 057 24X
Fiche 50-369, 82/11/04, 8212090373

--8212090380 IE Insp Repts 50-369/82-38 & 50-370/82-33 on 820918-1020 No noncompliance noted Major areas inspected maint, surveillance, hot functional testing, sys operational safety verification, plant trips, LERS & NUREG-0737 items
HOPKINS, P. BRYANT, J C Division of Project & Resident Programs
82/11/04 9pp 16365 059 24X Fiche 50-369, 82/11/04, 8212090373

8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards
82/11/05 Consolidated Edison Co of New York, Inc 110pp
16372 142 24X Fiche 50-000, 82/11/05, 8208190245

8212090250 Responds to IE Bulletin 82-01, Revision 1, Suppl 1 Total radiographic film review revealed no film alterations & required penetrometer sensitivities were clear
TUCKER, H B Duke Power Co 82/11/10 O'REILLY, J P Region 2, Office of Director 1p 16361 352 24X Fiche 50-369, 82/11/10, 8212090250

8212090401 Ack receipt of IE Insp Repts 50-369/82-36 & 50-370/82-30, No proprietary info
TUCKER, H B Duke Power Co 82/11/12 O'REILLY, J P Region 2, Office of Director 1p 16364 261 24X Fiche 50-369, 82/11/12, 8212090401

8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X
Fiche 50-000, 82/11/18, 8208190251

8212090187 Ack receipt of 821105 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-369/82-35
DANCE, H C Division of Project & Resident Programs 82/11/19
TUCKER, H B Duke Power Co 1p 16361 285 24X
Fiche 50-369, 82/11/19, 8212090187

--8212090192 Responds to NRC 821007 ltr re violations noted in IE Insp Rept 50-369/82-35 Corrective actions addl training given to staff developing exposure folders & random file auditing initiated
TUCKER, H B Duke Power Co 82/11/05 O'REILLY, J P Region 2, Office of Director 2pp 16361 286 24X Fiche 50-369, 82/11/19, 8212090187

--8212090197 Forwards IE Insp Rept 50-369/82-35 on 820913-17 & notice of violation
DANCE, H C Division of Project & Resident Programs 82/10/07
TUCKER, H B Duke Power Co 2pp 16361 288 24X
Fiche 50-369, 82/11/19, 8212090187

--8212090198 Notice of violation from Insp on 820913-17
+ Division of Project & Resident Programs 82/10/07 1p
16361:290 24X Fiche 50-369, 82/11/19, 8212090187

--8212090204 IE Insp Rept 50-369/82-35 on 820913-17 Noncompliance noted wrong exposure credited to individual when record of individual exposure not available
ALBRICHT, R H. BARR, K P Division of Engineering & Technical Programs 82/10/01 4pp 16361 291 24X Fiche 50-369, 82/11/19, 8212090187

8212090339 Ack receipt of IE Insp Repts 50-369/82-34 & 50-370/82-29 No proprietary info
TUCKER, H B Duke Power Co 82/11/19 O'REILLY, J P Region 2, Office of Director 1p 16365 138 24X Fiche 50-369, 82/11/19, 8212090339

8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks." Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000, 82/11/26, 8208190256

8208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards
82/11/30 Consolidated Edison Co of New York, Inc 336pp
16387 028 24X Fiche 50-000, 82/11/30, 8208190257

8208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259

8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X
Fiche 50-000, 82/12/03, 8208190261

8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16, 8208190267

8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27 " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X
Fiche 50-000, 82/12/20, 8208190268

R Periodic operating reports & related correspondence

8212210060 Forwards monthly operating rept for Nov 1982
TUCKER, H B Duke Power Co 82/12/15 Director's Office, Office of Inspection and Enforcement 1p 16492 263 24X
Fiche 50-369, 82/12/15, 8212210060

--8212210065 Monthly operating rept for Nov 1982
REAVIS, J A Duke Power Co 82/12/15 6pp 16492 264 24X
Fiche 50-369, 82/12/15, 8212210060

S Reportable occurrences, LERs & related correspondence

8212140425 Forwards LER 82-074/03L-0 Detailed event analysis encl
TUCKER, H B Duke Power Co 82/11/30 O'REILLY, J P Region 2, Office of Director 4pp 16404 181 24X Fiche 50-369, 82/11/30, 8212140425

--8212140434 LER 82-074/03L-0 on 821014, 19, 25 & 28, various door seals failed on both upper & lower personnel air locks Caused by door out of alignment, seals inflated while door open & surface of seal peeled off Seals replaced
NARDOLCI, P B Duke Power Co 82/11/30 Region 2, Office of Director 1p 16404 185 24X Fiche 50-369, 82/11/30, 8212140425

8212140171 Forwards LER 82-076/03L-0
TUCKER, H B Duke Power Co 82/12/03 O'REILLY, J P Region 2, Office of Director 1p 16409 355 24X Fiche 50-369, 82/12/03, 8212140171

--8212140176 LER 82-076/03L-0 on 821104, while in Mode 1, power supply to main fire pump C lost for approx 2-h & 25 minutes making main fire pumps 2 & 3 inoperable Caused by power loss from broken insulator damaged by lightning Insulator replaced.
NARDOLCI, P B Duke Power Co 82/12/03 Region 2, Office of Director 1p 16409 356, 24X Fiche 50-369, 82/12/03, 8212140171

8212200005 Forwards LER 82-077/03L-0
TUCKER, H B Duke Power Co 82/12/03 O'REILLY, J P Region 2, Office of Director 1p 16474 040 24X Fiche 50-369, 82/12/03, 8212200005

--8212200012 LER 82-077/03L-0 on 821105, eight procedure change cards of each reactor protection sys channel omitted from overlap testing Caused by inadequate procedures Omitted cards calibr & procedural changes approved
NARDOLCI, P B Duke Power Co 82/12/03 Region 2, Office of Director 1p 16474 041 24X Fiche 50-369, 82/12/03, 8212200005

8212210145 Forwards LER 82-078/03L-0
TUCKER, H B Duke Power Co 82/12/08 O'REILLY, J P Region 2, Office of Director 1p 16485 167 24X Fiche 50-369, 82/12/08, 8212210145

--8212210154 LER 82-078/03L-0 on 821108, during draining of RCS, both centrifugal charging pumps inoperable Caused by confusing statement in draining procedure allowing both breakers to be racked out & tagged Procedure revised & personnel counseled
NARDOLCI, P B Duke Power Co 82/12/08 Region 2, Office of Director 1p 16485 168 24X Fiche 50-369, 82/12/08, 8212210145

8212280380 Forwards LER 82-079/03L-0
TUCKER, H B Duke Power Co 82/12/15 O'REILLY, J P Region 2, Office of Director 1p 16560 086 24X Fiche 50-369, 82/12/15, 8212280380

--B212280394 LER 82-079/03L-0 on 821118, centrifugal charging pump 1A declared inoperable when excessive leakage from pump seals noted. Caused by pump shaft slinging water out of seal leakage basin. Drain line cleared & pump returned to svc. HARDDOC1, P B Duke Power Co 82/12/15 Region 2, Office of Director 1p 16560 057 24X Fiche 50-369, 82/12/15, 8212280380

B212300093 Forwards LER 82-080/03L-0
TUCKER, H B Duke Power Co 82/12/22 O'REILLY, J P Region 2, Office of Director 1p 16599 034 24X Fiche 50-369, 82/12/22, 8212300093

--B212300096 LER 82-080/03L-0 on 821122, discrepancies discovered in intermediate range internal picoampere source & LOO current amplifier calibr procedures. Caused by improper procedure options Channels recalibr & procedures revised. HARDDOC1, P B Duke Power Co 82/12/22 Region 2, Office of Director 1p 16599 035 24X Fiche 50-369, 82/12/22, 8212300093

DOCKET 50-370 WILLIAM B MCQUIRE NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

B212010286 Submits list of outstanding items requiring responses by 821217 to complete review of OL application
ADENSAM, E G Licensing Branch 4 82/11/24 TUCKER, H B Duke Power Co 2pp 16271 254 24X Fiche 50-369, 82/11/24, 8212010286

B212070341 Forwards responses to NUREG-0737, Item II B 3, "Post-Accident Sampling Sys" W/14 oversize drawings Aperture cards are available in PDR
TUCKER, H B Duke Power Co 82/12/01 DENTON, H R Office of Nuclear Reactor Regulation, Director 32pp 16340 252 24X Fiche 50-269, 82/12/01, 8212070341

--B212070353 "Operating Procedure for Operation of Post-Accident Liquid Sample Sys"
DEAK, A M, MCCONNELL, T Duke Power Co 82/05/17 18pp 16340 305 24X Fiche 50-269, 82/12/01, 8212070341

B212140390 Forwards fee for Class III amend re requests for relief from hydrostatic testing requirements on feedwater sys to steam generators & safety injection sys
TUCKER, H B Duke Power Co 82/12/03 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 2pp 16401 032 24X Fiche 50-369, 82/12/03, 8212140390

B212150178 Notification of 821216 meeting w/util in Bethesda, MD to discuss independent design verification program
BIRKEL, R A Licensing Branch 4 82/12/10 ADENSAM, E G Licensing Branch 4 3pp 16437 350 24X Fiche 50-369, 82/12/10, 8212150178

B212160249 Forwards responses to questions re standby shutdown sys per NRC 821203 request
TUCKER, H B Duke Power Co 82/12/14 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 16pp 16446 100 24X Fiche 50-369, 82/12/14, 8212160249

B212210419 Forwards Amend 70 to application for OL, consisting of Revision 44 to FSAR
TUCKER, H B Duke Power Co 82/12/15 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 2pp 16490 056 24X Fiche 50-370, 82/12/15, 8212210419

B212290232 Requests exemption from 10CFR50.71(e) requirements re FSAR update initiated within 24 months of 800722 or OL issuance, whichever is later. Updated FSAR will be submitted 12 months after issuance of OL for Unit 2
TUCKER, H B Duke Power Co 82/12/22 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 1p 16578 079 24X Fiche 50-369, 82/12/22, 8212290232

F Security, medical, emergency & fire protection plans

B212130069 Forwards info on emergency offsite facilities (EOF), per R Birkel 821203 request & Generic Ltr 81-10 Const of permanent primary & backup EOF completed
TUCKER, H B Duke Power Co 82/12/03 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 16390 186 24X Fiche 50-000, 82/12/03, 8212130069

B212090044 Reviews util 820419 & 0727 ltrs re security personnel requalification requirements. Annual supervisor observation indicated sufficient requalification test
STOLZ, J F Operating Reactors Branch 4 82/12/07 TUCKER, H B Duke Power Co 2pp 16394 244 24X Fiche 50-000, 82/12/07, 8212090044

B212230067 Releases public version of emergency plan implementing procedures
FELTON, J M Division of Rules and Records 82/12/14 Document Management Branch 1p 16545 246 24X Fiche 50-369, 82/12/14, 8212230067

--B212230076 Forwards public version of emergency plan implementing procedures, including Procedure HP/D/B/1009/05 re first response evaluation of reactor coolant leak inside containment
TUCKER, H B Duke Power Co 82/12/02 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 2pp 16545 247 24X Fiche 50-369, 82/12/14, 8212230067

--B212230083 Public version of emergency plan implementing procedures, including Procedure HP/D/B/1009/05 re first response evaluation of reactor coolant leak inside containment
MCCREE, H B, LEONARD, J R Duke Power Co 82/11/23 84pp 16945 249 24X Fiche 50-369, 82/12/14, 8212230067

B212230093 Releases public version of revision to crisis mgt plan & revisions to crisis mgt plan implementing procedures
FELTON, J M Division of Rules and Records 82/12/15 Document Management Branch 1p 16542 026 24X Fiche 50-000, 82/12/15, 8212230093

--B212230108 Forwards public version of Revision 7 to crisis mgt plan & revisions to crisis mgt plan implementing procedures
TUCKER, H B Duke Power Co 82/12/02 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 16542 027 24X Fiche 50-000, 82/12/15, 8212230093

--B212230124 Public version of Revision 7 to crisis mgt plan One oversize pamphlet encl Aperture card available in PDR
VAUGHN, R E Duke Power Co 82/11/29 9pp 16542 027 24X Fiche 50-000, 82/12/15, 8212230093

--B212230134 Public version of revised crisis mgt plan implementing procedures, including Procedures 5.3.2 re crisis news group plan & 5.3.11 re McGuire crisis phone directory
VAUGHN, R E Duke Power Co 82/11/29 280pp 16542 038 24X Fiche 50-000, 82/12/15, 8212230093

K Utility Final Safety Analysis Report (FSAR) & amends

B212210419 Forwards Amend 70 to application for OL, consisting of Revision 44 to FSAR
TUCKER, H B Duke Power Co 82/12/15 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 2pp 16490 056 24X Fiche 50-370, 82/12/15, 8212210419

--B212210423 Revision 44 to FSAR W/one oversize drawing Aperture card is available in PDR
* Duke Power Co 82/12/15 65pp 16490 058 24X Fiche 50-370, 82/12/15, 8212210419

Q Inspection reports, IE Bulletins & correspondence

B208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants" Svc list encl
DEYDUNO, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240

B212090373 Forwards IE Insp Repts 50-369/82-38 & 50-370/82-33 on 820918-1020 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 82/11/04 TUCKER, H B Duke Power Co 2pp 16365 057 24X Fiche 50-369, 82/11/04, 8212090373

--B212090380 IE Insp Repts 50-269/82-38 & 50-370/82-33 on 820918-1020 No noncompliance noted. Major areas inspected: maint, surveillance, hot functional testing, sys operational safety verification, plant trips, LERs & NUREG-0737 items
HOPIANS, P, BRYANT, J C Division of Project & Resident Programs 82/11/04 9pp 16365 059 24X Fiche 50-369, 82/11/04, 8212090373

B208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model B01 & Model 902 Thermoluminescent Dosimeters" Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372.142 24X Fiche 50-000, 82/11/05, 8208190245

B212090250 Responds to IE Bulletin 82-04, Revision 1, Suppl 1 Total radiographic film review revealed no film alterations & required penetrameter sensitivities were clear
TUCKER, H B Duke Power Co 82/11/10 O'REILLY, J P Region 2, Office of Director 1p 16361 392 24X Fiche 50-369, 82/11/10, 8212090250

DOCKETED ITEMS

B212090401 Ack receipt of IE Insp Repts 50-369/82-36 & 50-370/82-30
No proprietary info
TUCKER, H B Duke Power Co 82/11/12 O'REILLY, J P Region 2,
Office of Director 1p 16364 261 24X Fiche 50-369, 82/11/12,
B212090401

B212090262 Forwards IE Insp Rept 50-370/82-34 on 821101-04 No
noncompliance noted
DANCE, H C Division of Project & Resident Programs 82/11/17
TUCKER, H B Duke Power Co 2pp 16362 332 24X
Fiche 50-370, 82/11/17, B212090262

--B212090271 IE Insp Rept 50-370/82-34 on 821101-04 No noncompliance
noted Major areas inspected preoperational test procedure
review, preoperational test witnessing & preoperational test
results review
THOMAS, H, JAPE, F Division of Engineering & Technical Programs
82/11/15 3pp 16362 334 24X Fiche 50-370, 82/11/17, B212090262

B208190251 IE Info Notice 82-44, "Clarification of Emergency Plan
Exercise Requirements " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18
Consolidated Edison Co of New York, Inc 109pp 16411 199 24X
Fiche 50-000, 82/11/18, B208190251

B212090339 Ack receipt of IE Insp Repts 50-369/82-34 & 50-370/82-29 No
proprietary info
TUCKER, H B Duke Power Co 82/11/19 O'REILLY, J P Region 2,
Office of Director 1p 16365 198 24X Fiche 50-369, 82/11/19,
B212090339

B208190256 IE Info Notice 82-46, "Defective & Obsolete Combination
Padlocks " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and
Enforcement 82/11/24 Consolidated Edison Co of New York, Inc
127pp 16411 065 24X Fiche 50-000, 82/11/26, B208190256

B208190257 IE Info Notice 82-47, "Transportation of Type A Quantities
of Non-Fissile Radioactive Matl " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards
82/11/30 Consolidated Edison Co of New York, Inc 356pp
16387 028 24X Fiche 50-000, 82/11/30, B208190257

B208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment
Electrical Penetration Assemblies " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and
Enforcement 82/12/03 Consolidated Edison Co of New York, Inc
113pp 16411 317 24X Fiche 50-000, 82/12/03, B208190259

B208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay
Sockets " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03
Consolidated Edison Co of New York, Inc 110pp 16462 064 24X
Fiche 50-000, 82/12/03, B208190261

B208190267 IE Info Notice 82-49, "Correction for Sample Conditions for
Air & Gas Monitoring " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and
Enforcement 82/12/16 Consolidated Edison Co of New York, Inc
127pp 16628 191 24X Fiche 50-000, 82/12/16, B208190267

B208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage
Relays Type ITE-27 " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20
Consolidated Edison Co of New York, Inc 108pp 16628 293 24X
Fiche 50-000, 82/12/20, B208190268

DOCKET 50-373 LASALLE COUNTY STATION, UNIT 1

F Security, medical, emergency & fire protection plans

B212060041 Forwards Revision 13 to modified amended security plan
Revision withheld (ref 10CFR73.21)
DELOERGE, L O Commonwealth Edison Co 82/11/29 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 16313 270. 24X
Fiche 50-373, 82/11/29, B212060041

B212090383 Forwards info re emergency operations facilities per
B21122 & 1202 requests info previously submitted by telcon
Request for written response unnecessary burden on licensee
DELOERGE, L O Commonwealth Edison Co 82/12/03 EISENHUT, D O
Division of Licensing 2pp 16365 051 24X Fiche 50-000, 82/12/03,
B212090383

B21230017 Releases public version of Revision 1 to Emergency Plan
Implementing Procedure EQ-2, "Pre-Established Onsite &
Offsite Monitoring Locations (Maps) "
FELTON, J M Division of Rules and Records 82/12/07. Document
Management Branch 1p 16417 062 24X Fiche 50-000, 82/12/07,
B2130017

--B212130028 Forwards public version of Revision 1 to Emergency Plan
Implementing Procedure EQ-2, "Pre-Established Onsite &
Offsite Monitoring Locations (Maps) " Revised table of
contents encl
PAJOWSKI, J Commonwealth Edison Co 82/11/01 DENTON, H R NRC -
No Detailed Affiliation Given 2pp 16417 063 24X
Fiche 50-000, 82/12/07, B212130017

--B212130041 Public version of Revision 1 to Emergency Plan Implementing
Procedure EQ-2, "Pre-Established Onsite & Offsite Monitoring
Locations (Maps) "
PAJOWSKI, J E Commonwealth Edison Co 82/11/29 4pp 16417 065
24X Fiche 50-000, 82/12/07, B212130017

B212130093 Requests exemption from 10CFR50.44 requirements, extending
initial startup test program beyond 6 months following
initial criticality per Tech Specs 3.6.6.2 & 3.10.5 Approval
required by B21220
SCHROEDER, C W Commonwealth Edison Co 82/12/07 SCHWENGER, A
Licensing Branch 2 6pp 16390 176 24X Fiche 50-373, 82/12/07,
B212130093

B212140243 Advises of distribution of revisions to "Generating Station
Emergency Plan " Braidwood annex not prepared
TRAHNT, R Commonwealth Edison Co 82/12/07 DENTON, H R Office
of Nuclear Reactor Regulation, Director 2pp 16409 302 24X
Fiche 50-000, 82/12/07, B212140243

B212220175 Releases public version of revised generating station
emergency plan implementing procedures
FELTON, J M Division of Rules and Records 82/12/10 Document
Management Branch 1p 16529 029 24X Fiche 50-000, 82/12/10,
B212220175

--B212220190 Forwards public version of revised generating station
emergency plan implementing procedures, including Procedures
ED-3 re demand polling of meteorological data & ED-20 re
emergency forecast request
PAJOWSKI, J E Commonwealth Edison Co 82/11/15 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 16529 030
24X Fiche 50-000, 82/12/10, B212220175

--B212220202 Public version of revised generating station emergency plan
implementing procedures, including Procedures ED-3 re demand
polling of meteorological data & ED-20 re emergency
forecast request
LITERSKI, L A Commonwealth Edison Co 82/10/13 48pp
16529 031 24X Fiche 50-000, 82/12/10, B212220175

B212220306 Discusses layout of communications equipment required in
control room, onsite technical support ctr & near-site
emergency operations facility
KEPLER, J O Region 3, Office of Director 82/12/16
Commonwealth Edison Co 3pp 16503 351 24X Fiche 50-000, 82/12/16,
B212220306

B212300167 Releases public version of revised generating station
emergency plan telephone directory
FELTON, J M Division of Rules and Records 82/12/20 Document
Management Branch 1p 16612 215 24X Fiche 50-000, 82/12/20,
B212300167

--B212300179 Forwards public version of revised generating station
emergency plan telephone directory
MOORE, R D Commonwealth Edison Co 82/12/02 DENTON, H R Office
of Nuclear Reactor Regulation, Director 1p 16612 216 24X
Fiche 50-000, 82/12/20, B212300167

--B212300199 Public version of revised generating station emergency
plan telephone directory
GALLE, D P Commonwealth Edison Co 82/11/05 60pp 16612 217
24X Fiche 50-000, 82/12/20, B212300167

H General correspondence

B212200099 Submits petition to revoke DL until main recirculation pumps
& all other parts of RCS are capable of operating at full
power & order investigation & open public hearing into
causes of stuck discharge valve on recirculation pump A
GODD, L E Citizens Against Nuclear Power 82/12/15 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 16470 138
24X Fiche 50-373, 82/12/15, B212200099

B212280176 Notifies of change in mailing address for NRC licensing
matl
WRIGHT, O N Illinois, State of, Dept Nuc Safety (formerly Dept
Public Health) 82/12/20 EISENHUT, D O Division of Licensing
1p 16356 135 24X Fiche 50-000, 82/12/20, B212280176

K Utility Final Safety Analysis Report (FSAR) & amends

8212210463 Forwards Amend 61 to FSAR, updating baseline record & incorporating as-built & as-tested configuration
SCHROEDER, C W Commonwealth Edison Co 82/12/13 DENTON, H R
Office of Nuclear Reactor Regulation, Director 3pp 16486 276
24X Fiche 50-373, 82/12/13, 8212210463

--8212210466 Amend 61 to FSAR
* Commonwealth Edison Co 82/12/31 279pp 16486 279 24X
Fiche 50-373, 82/12/13, 8212210463

8212280341 Forwards affidavit confirming distribution of FSAR, Amend 61
SCHROEDER, C W Commonwealth Edison Co 82/12/23 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 16560 092
24X Fiche 50-373, 82/12/23, 8212280341

P Operating license stage documents & correspondence

821230066 Generic Ltr 82-27 to all BWR licensees of operating reactors
except LACBWR, Big Rock Point, Dresden 1, Humboldt Bay,
applicants for OL & holders of CP re transmittal of
NUREG-0763 & NUREG-0783 Svc list encl W/o stated encl
EISENHUT, D G Division of Licensing 82/11/15 General Public
Utilities - OPU Service Corp 22pp 16387 004 24X
Fiche 50-000, 82/11/15, 821230066

8212080662 Forwards addl matl tests received on 821119 from Region 3
supplementing matl addressed in "Independent HVAC Review
Final Rpt." Oct 1982 Data reviewed by welding & matl
specialists Comments encl
XEPHIA, A J C F Braun & Co 82/11/24 SHELTON, B R
Commonwealth Edison Co 3pp 16372 324 24X Fiche 50-373, 82/11/24,
8212080662

--8212080664 Forwards addl data obtained as part of matl sampling program
re HVAC in addition to data provided on 821007
NORELIUS, C E Region 3, Office of Director 82/11/19
STIEBE, W L C F Braun & Co 11pp 16372 327 24X
Fiche 50-373, 82/11/24, 8212080662

--8212080668 Discusses hardness tests performed to determine whether matl
samples which meet chemical requirements for A36 also meet
tensile requirements Specimens meet specs
SHACK, W J Argonne National Laboratory 82/08/06 LANSBURY, R
Region 3, Office of Director 2pp 16372 338 24X
Fiche 50-373, 82/11/24, 8212080662

--8212080670 Discusses hardness tests performed to determine whether matl
samples met mechanical requirements of appropriate ASTM
spec Nut meets hardness spec Calculated flow stress
consistent w/proof load stress
SHACK, W J Argonne National Laboratory 82/09/22 LANSBURY, R
Region 3, Office of Director 3pp 16372 340 24X
Fiche 50-373, 82/11/24, 8212080662

--8212080673 Discusses hardness tests performed on three bolts (1/2, 3/8,
1/4-inches) & corresponding nuts to find if bolts conform
to appropriate ASTM spec Results of test summarized
Specimens meet required specs
SHACK, W J Argonne National Laboratory 82/10/07 LANSBURY, R
Region 3, Office of Director 3pp 16372 343 24X
Fiche 50-373, 82/11/24, 8212080662

8212060381 Notification of 821201 meeting w/util, CF Braun & Govt
Accountability Project in Bethesda, MD to discuss independent
review of HVAC sys
BOURNIA, A Licensing Branch 2 82/11/26 SCHWENCER, A Licensing
Branch 2 3pp 16323 324 24X Fiche 50-373, 82/11/26, 8212060381

8212020398 Submits recommendations re proposed issuance of full power
OL, based on review of CF Braun & Co 821027 rept & witness
analysis of Zack Co QA breakdown in area of HVAC sys
Weaknesses in rept preclude issuance pending further review
DEVINE, T, GARDE, B P Institute for Policy Studies 82/11/30
DENTON, H R Office of Nuclear Reactor Regulation, Director 20pp
16290 345 24X Fiche 50-373, 82/11/30, 8212020398

8212100361 Authorizes operation of facility above 50% power Safety
evaluation of licensee 821027 independent HVAC review final
rept on Project 6356-N & FR notice encl Measures to correct
discrepancies in rept requested
EISENHUT, D G Division of Licensing 82/12/03 REED, C
Commonwealth Edison Co 5pp 16398 307 24X Fiche 50-373, 82/12/03,
8212100361

--8212100368 Safety evaluation of independent HVAC review final rept on
Project 6356-N HVAC review provides reasonable assurance
that sys acceptable for power operation above 50%
* NRC - No Detailed Affiliation Given 82/12/03, 19pp
16398 312 24X Fiche 50-373, 82/12/03, 8212100361

--8212100372 Notice of authorization of operation above 50% power
SCHWENCER, A Licensing Branch 2 82/12/03 4pp 16398 331 24X
Fiche 50-373, 82/12/03, 8212100361

8212130151 Submits daily highlights rept for 821206 Restriction to 50%
power removed as result of acceptable independent review
findings
BOURNIA, A Licensing Branch 2 82/12/06 DENTON, H R, CASE, D O,
CARTER, J Office of Nuclear Reactor Regulation, Director 1p
16410 316 24X Fiche 50-373, 82/12/06, 8212130151

8212140068 Forwards application for amend to License NPF-11, allowing
plant operation w/one recirculation loop out of svc
SCHROEDER, C W Commonwealth Edison Co 82/12/06 SCHWENCER, A
Licensing Branch 2 2pp 16408 316 24X Fiche 50-373, 82/12/06,
8212140068

--8212140072 Application for amend to License NPF-11, allowing operation
w/one recirculation loop out of svc
* Commonwealth Edison Co 82/12/06 3pp 16408 318 24X
Fiche 50-373, 82/12/06, 8212140068

8212130093 Requests exemption from 10CFR50.44 requirements, extending
initial startup test program beyond 6 months following
initial criticality per Tech Specs 3 & 6.2 & 3.10.5 Approval
required by 821220
SCHROEDER, C W Commonwealth Edison Co 82/12/07 SCHWENCER, A
Licensing Branch 2 6pp 16390 176 24X Fiche 50-373, 82/12/07,
8212130093

8212140402 Responds to 821207 request to specify implementation data of
mod for License Condition 1 C (17) Since current outage
allows for mod installation, 820818 Tech Spec change request
should be approved to be effective as of 821209
SCHROEDER, C W Commonwealth Edison Co 82/12/08 SCHWENCER, A
Licensing Branch 2 2pp 16404 358 24X Fiche 50-373, 82/12/08,
8212140402

8212170013 Forwards Amend 10 to License NPF-11, safety evaluation &
notice of issuance & availability Amend changes Tech Specs
as result of hardware mods to satisfy License Condition
2 C (17)
EISENHUT, D G Division of Licensing 82/12/09 DELGEORGE, L O
Commonwealth Edison Co 2pp 16480 304 24X Fiche 50-373, 82/12/09,
8212170013

--8212170016 Amend 10 to License NPF-11, changing Tech Spec as result of
hardware mods to satisfy License Condition 2 C (17)
EISENHUT, D G Division of Licensing 82/12/09 4pp 16480 306
24X Fiche 50-373, 82/12/09, 8212170013

--8212170030 Safety evaluation supporting Amend 10 to License NPF-11
* Office of Nuclear Reactor Regulation, Director 82/12/09
13pp 16480 310 24X Fiche 50-373, 82/12/09, 8212170013

--8212170034 Notice of issuance & availability of Amend 10 to License
NPF-11
SCHWENCER, A Licensing Branch 2 82/12/09 4pp 16480 323 24X
Fiche 50-373, 82/12/09, 8212170013

8212220212 Forwards Revision 22 to CE-1-A, "QA Program for Nuclear
Generating Stations"
SWARTZ, E D Commonwealth Edison Co 82/12/14 HAASS, W P Quality
Assurance Branch 1p 16518 007 24X Fiche 50-000, 82/12/14,
8212220212

--8212220231 "QA Program for Nuclear Generating Stations," Revision 22
* Commonwealth Edison Co CE-1-A R22 82/11/01 17pp
16518 009 24X Fiche 50-000, 82/12/14, 8212220212

8212280212 Forwards updated schedule for ongoing environ qualification
testing programs, per 810528 commitment
SWARTZ, E D Commonwealth Edison Co 82/12/22 EISENHUT, D G
Division of Licensing 18pp 16556 161 24X Fiche 50-000, 82/12/22,
8212280212

8212280298 Forwards info on 821201 meeting re Govt Accountability
Project repts & discussions of corrective actions for
CF Braun Observation GC-2-53, QA review & Unit 2 HVAC, per NRC
821203 request
REED, C Commonwealth Edison Co 82/12/22 EISENHUT, D G Division
of Licensing 34pp 16561 099 24X Fiche 50-373, 82/12/22,
8212280298

DOCKETED ITEMS

G Inspection reports, IE Bulletins & correspondence

8208190240 IE Bulletin 82-03, Revision J, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240

8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000, 82/11/05, 8208190245

8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X Fiche 50-000, 82/11/18, 8208190251

8212030021 Forwards IE Insp Repts 50-373/82-49 & 50-374/82-15 on 821001-29 No noncompliance noted
STREETEER, J F Division of Project & Resident Programs 82/11/18 REED, C Commonwealth Edison Co 2pp 16304 316 24X Fiche 50-373, 82/11/18, 8212030021

--8212030028 IE Insp Repts 50-373/82-49 & 50-374/82-15 on 821001-29 No noncompliance noted Major areas inspected licensee action on previous insp findings, operational safety verification & monthly surveillance observations
GULDMOND, H, WILLIAMS, D, MADISON, A Division of Project & Resident Programs 82/11/18 12pp 16304 318 24X Fiche 50-373, 82/11/18, 8212030021

8212140326 Forwards final SALP Repts 50-373/82-38 & 50-374/82-08 for Jul 1980-Dec 1981 No response required
KEPPLER, J O Region 3, Office of Director 82/11/23 REED, C Commonwealth Edison Co 3pp 16402 012 24X Fiche 50-373, 82/11/23, 8212140326

--8212140329 SALP Repts 50-373/82-38 & 50-374/82-08 for Jul 1980-Dec 1981 Deficiency noted in conducting tests w/o adequate procedures
* Region 3, Office of Director 82/05/30 39pp 16402 015 24X Fiche 50-373, 82/11/23, 8212140326

8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000, 82/11/26, 8208190256

8208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000, 82/11/30, 8208190257

8212170077 Forwards IE Insp Repts 50-373/82-53 & 50-374/82-21 on 821101-05 & 08 No noncompliance noted
PAFERIELLO, C J Division of Emergency Preparedness & Operational Support 82/12/01 REED, C Commonwealth Edison Co 2pp 16450 354 24X Fiche 50-373, 82/12/01, 8212170077

--8212170079 IE Insp Repts 50-373/82-53 & 50-374/82-21 on 821101-05 & 08 No noncompliance noted Major areas inspected radiological environ protection, including program mgt, QC & implementation
JANUSKA, A O, OESTHANN, M J, SCHUMACHER, M C Division of Emergency Preparedness & Operational Support 82/11/29 8pp 16450 355 24X Fiche 50-373, 82/12/01, 8212170077

3190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 13pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259

8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X Fiche 50-000, 82/12/03, 8208190261

8212140224 Ack receipt of 821202 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-373/82-45
SPESSARD, R L Division of Project & Resident Programs 82/12/09 REED, C Commonwealth Edison Co 1p 16408 339 24X Fiche 50-373, 82/12/09, 8212140224

--8212140231 Responds to NRC 821104 ltr re violations noted in IE Insp Repts 50-373/82-45 & 50-374/82-13 Corrective actions flow controller returned to panel & station procedures revised to include leakage compensation
DELOERDGE, L O Commonwealth Edison Co 82/12/02 KEPPLER, J O Division of Project & Resident Programs 3pp 16408 340 24X Fiche 50-373, 82/12/09, 8212140224

8212140289 Forwards re-evaluation of safety-related concrete masonry walls per IE Bulletin 80-11 Requests NRC review be concluded by June 1983
SCHROEDER, C W Commonwealth Edison Co 82/12/09 SCHWENCER, A Licensing Branch 2 2pp 16402 085 24X Fiche 50-373, 82/12/09, 8212140289

--8212140292 "Re-evaluation of Safety-Related Concrete Masonry Walls at LaSalle County Station "
* Commonwealth Edison Co 82/11/19 11pp 16402 087 24X Fiche 50-373, 82/12/09, 8212140289

8212210104 Ack receipt of 821202 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-373/82-46 & 50-374/82-19
NORELIOUS, C E Division of Engineering & Technical Programs 82/12/13 REED, C Commonwealth Edison Co 1p 16491 042 24X Fiche 50-373, 82/12/13, 8212210104

--8212210108 Responds to NRC 821108 ltr re violations noted in IE Insp Repts 50-373/82-46 & 50-374/82-19 Corrective actions Morrison Const Co SDP PC-2 welding matls control procedure reworked to avoid internal procedure conflict
DELOERDGE, L O Commonwealth Edison Co 82/12/02 KEPPLER, J O Region 3, Office of Director 3pp 16491 043 24X Fiche 50-373, 82/12/13, 8212210104

8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16, 8208190267

8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type IYE-27 " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X Fiche 50-000, 82/12/20, 8208190268

8212270198 Ack receipt of 821105 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-373/82-41 & 50-374/82-09
STREETEER, J F Division of Project & Resident Programs 82/12/20 REED, C Commonwealth Edison Co 1p 16535 151 24X Fiche 50-373, 82/12/20, 8212270198

--8212270223 Responds to NRC 821007 ltr re violations noted in IE Insp Repts 50-373/82-41 & 50-374/82-09 Corrective actions operator trainee functioning directly under unit operator & guidelines for control room trainees drafted
DELOERDGE, L O Commonwealth Edison Co 82/11/05 KEPPLER, J O Region 3, Office of Director 3pp 16535 152 24X Fiche 50-373, 82/12/20, 8212270198

R Periodic operating reports & related correspondence

8212130175 Forwards monthly operating rept for Nov 1982
DIEDERICH, O J Commonwealth Edison Co 82/12/06 Office of Resource Management, Director 1p 16396 072 24X Fiche 50-373, 82/12/06, 8212130175

--8212130177 Monthly operating rept for Nov 1982
ULLRICH, J Commonwealth Edison Co 82/12/06 16pp 16396 073 24X Fiche 50-373, 82/12/06, 8212130175

B Reportable occurrences, LERs & related correspondence

8212020274 Forwards NPDES noncompliance notification
DIEDERICH, O J Commonwealth Edison Co 82/11/23 KEPPLER, J O Region 3, Office of Director 2pp 16288 353 24X Fiche 50-373, 82/11/23, 8212020274

--8212020282 NPDES noncompliance notification on 821029, iron concentrations of 41.3 mg found in regenerated waste solids discharge tank Caused by addition of const wastes from Unit 2 condensate polishing sys Treatment mod initiated
* Commonwealth Edison Co 82/11/12 1p 16288 355 24X Fiche 50-373, 82/11/23, 8212020274

8212020294 Forwards LER 82-138/03L-0
DIEDERICH, O J Commonwealth Edison Co 82/11/23 KEPPLER, J O Region 3, Office of Director 1p 16277 359 24X Fiche 50-373, 82/11/23, 8212020294

DOCKETED ITEMS

249

- 8212020301 LER 82-138/03L-0 on 821026, LITB-1B21-N026A level switch failed to perform design function. Caused by misalignment of micro switch w/actuating device preventing proper operation. Switch realigned.
HOUSTON, R W Commonwealth Edison Co 82/11/22 Region 3, Office of Director 2pp 16277 360 24X Fiche 50-373, 82/11/23, 8212020294
- 8212020305 Forwards LER 82-137/03L-0
DIEDERICH, O J Commonwealth Edison Co 82/11/24 KEPPLER, J O Region 3, Office of Director 1p 16277 270 24X Fiche 50-373, 82/11/24, 8212020305
- 8212020327 LER 82-137/03L-0 on 821026, both reactor recirculation pumps received downshift signal. Pump 1A downshifted, but pump 1B did not pick up in slow speed & drifted to stop, resulting in tripping of pump 1A. Caused by feedwater low flow transient.
HETELAH, J J Commonwealth Edison Co 82/11/24 Region 3, Office of Director 2pp 16277 271 24X Fiche 50-373, 82/11/24, 8212020305
- 8212080400 Forwards LER 82-140/03L-0
DIEDERICH, O J Commonwealth Edison Co 82/11/29 KEPPLER, J O Region 3, Office of Director 1p 16352 273 24X Fiche 50-373, 82/11/29, 8212080400
- 8212080410 LER 82-140/03L-0 on 821030, offgas pretreatment monitor became inoperative. Caused by loss of flow due to water in sample line. Sample line drained. Purge valve installed to allow proper flow.
LUETT, W R Commonwealth Edison Co 82/11/29 Region 3, Office of Director 3pp 16352 274 24X Fiche 50-373, 82/11/29, 8212080400
- 8212080308 Forwards LER 82-142/03L-0
DIEDERICH, O J Commonwealth Edison Co 82/11/30 KEPPLER, J O Region 3, Office of Director 1p 16353 353 24X Fiche 50-373, 82/11/30, 8212080308
- 8212080317 LER 82-142/03L-0 on 821102, radwaste valve DNL067 did not fully close when tripped w/insulated radwaste discharge. hi-hi trip signal. Caused by fouling of valve internals w/foreign matter. Valve cleaned.
ARAND, J Commonwealth Edison Co 82/11/30 Region 3, Office of Director 2pp 16353 354 24X Fiche 50-373, 82/11/30, 8212080308
- 8212080412 Forwards LER 82-139/03L-0
DIEDERICH, O J Commonwealth Edison Co 82/11/30 KEPPLER, J O Region 3, Office of Director 1p 16352 270 24X Fiche 50-373, 82/11/30, 8212080412
- 8212080413 LER 82-139/03L-0 on 821030, Div 11 oxygen channel was reading erratically. Caused by moisture buildup in oxygen sample flowmeter. Moisture removed & instrumentation recalibrated.
DUS, R Commonwealth Edison Co 82/11/30 Region 3, Office of Director 2pp 16352 271 24X Fiche 50-373, 82/11/30, 8212080412
- 8212080508 Forwards LER 82-143/03L-0
DIEDERICH, O J Commonwealth Edison Co 82/11/30 KEPPLER, J O Region 3, Office of Director 1p 16352 069 24X Fiche 50-373, 82/11/30, 8212080508
- 8212080524 LER 82-143/03L-0 on 821102, offgas pretreatment monitor inoperable. Caused by loss of flow due to water in sample line. Sample line drained. Temporary heat trace installed to keep gas at higher temp. Mod M-1-1-82-227 written.
LUETT, W Commonwealth Edison Co 82/11/30 Region 3, Office of Director 2pp 16352 070 24X Fiche 50-373, 82/11/30, 8212080508
- 8212080318 Forwards LER 82-141/03L-0
DIEDERICH, O J Commonwealth Edison Co 82/12/01 KEPPLER, J O Region 3, Office of Director 1p 16353 344 24X Fiche 50-373, 82/12/01, 8212080318
- 8212080332 LER 82-141/03L-0 on 821102, RCIC inbound testable check valve IE51-F066 failed to indicate closed. Cause still under investigation w/vendor. Alternative limit switch configurations being evaluated.
HOUSTON, R W Commonwealth Edison Co 82/12/01 Region 3, Office of Director 2pp 16353 349 24X Fiche 50-373, 82/12/01, 8212080318
- 8212100272 Forwards NPDES noncompliance notification
DIEDERICH, O J Commonwealth Edison Co 82/12/02 KEPPLER, J O Region 3, Office of Director 1p 16377 087 24X Fiche 50-373, 82/12/02, 8212100272
- 8212100275 NPDES noncompliance notification on 821105, temporary hydrogen peroxide sys not injecting hydrogen peroxide. Injection pump repaired.
* Commonwealth Edison Co 82/11/13 2pp 16377 088 24X Fiche 50-373, 82/12/02, 8212100272
- 8212100261 PND-111-82-133 on 821205, during hot shutdown, discharge valve in recirculation loop A could not open beyond 20%. Vendor representative will attempt in-place repairs. Unit placed in cold shutdown.
WALKER, R, GULDEMOND, W, STREETER, J Region 3, Office of Director 82/12/06 1p 16376 146 24X Fiche 50-373, 82/12/06, 8212100261
- 8212140067 Forwards LER 82-144/03L-0
DIEDERICH, O J Commonwealth Edison Co 82/12/06 KEPPLER, J O Region 3, Office of Director 1p 16408 313 24X Fiche 50-373, 82/12/06, 8212140067
- 8212140093 LER 82-144/03L-0 on 821107, Div 1 battery charger declared inoperable due to defective dc output breaker. Battery also out due to prolonged discharge w/specific gravities exceeding min value. Caused by poor connections.
HETELAH, J J Commonwealth Edison Co 82/12/06 Region 3, Office of Director 2pp 16408 314 24X Fiche 50-373, 82/12/06, 8212140067
- 8212140119 Forwards LER 82-145/03L-0
DIEDERICH, O J Commonwealth Edison Co 82/12/06 KEPPLER, J O Region 3, Office of Director 1p 16408 201 24X Fiche 50-373, 82/12/06, 8212140119
- 8212140128 LER 82-145/03L-0 on 821107, chlorine & ammonia detector B alarmed & would not reset. Caused by dirty lens. Lens cleaned & detector returned to svc.
KAY, D L Commonwealth Edison Co 82/12/06 Region 3, Office of Director 2pp 16408 202 24X Fiche 50-373, 82/12/06, 8212140119
- 8212270354 Forwards LER 82-155/03L-0 Detailed event analysis encl
DIEDERICH, O J Commonwealth Edison Co 82/12/06 KEPPLER, J O Region 3, Office of Director 2pp 16530 012 24X Fiche 50-373, 82/12/06, 8212270354
- 8212270356 LER 82-155/03L-0 on 821118, secondary containment violated in reactor bldg at 761-ft elevation due to doors 418 & 285 opening simultaneously. Caused by malfunctioning latch bolt due to electric strike out-of-adjustment at door 285.
KAY, D L Commonwealth Edison Co 82/12/03 Region 3, Office of Director 1p 16530 014 24X Fiche 50-373, 82/12/06, 8212270354
- 8212170159 Forwards LER 82-146/03L-0
DIEDERICH, O J Commonwealth Edison Co 82/12/09 KEPPLER, J O Region 3, Office of Director 1p 16462 030 24X Fiche 50-373, 82/12/09, 8212170159
- 8212170176 LER 82-146/03L-0 on 821111, div 11, ID18-N009C monitor discovered drifting high. Caused by failed Geiger-Mueller tube. Tube replaced.
KAY, D L Commonwealth Edison Co 82/12/10 Region 3, Office of Director 2pp 16462 031 24X Fiche 50-373, 82/12/09, 8212170159
- 8212170184 Forwards LER 82-148/03L-0
DIEDERICH, O J Commonwealth Edison Co 82/12/09 KEPPLER, J O Region 3, Office of Director 1p 16462 061 24X Fiche 50-373, 82/12/09, 8212170184
- 8212170194 LER 82-148/03L-0 on 821112, Div 11 post-LDCA oxygen channel indication drifted down to 4%. Caused by instrument drift, resulting in false indication. Adjustments made to sample flows & calibr performed.
DUS, R Commonwealth Edison Co 82/12/10 Region 3, Office of Director 2pp 16462 062 24X Fiche 50-373, 82/12/09, 8212170184
- 8212170233 Forwards LER 82-147/03L-0
DIEDERICH, O J Commonwealth Edison Co 82/12/09 KEPPLER, J O Region 3, Office of Director 1p 16459 332 24X Fiche 50-373, 82/12/09, 8212170233
- 8212170238 LER 82-147/03L-0 on 821111, offgas B train hydrogen analyzer began operating erratically. Caused by moisture entering sensitive hydrogen sensors in units. Hydrogen sensors removed, dried out & replaced.
HOUSTON, R Commonwealth Edison Co 82/12/10 Region 3, Office of Director 2pp 16459 333 24X Fiche 50-373, 82/12/09, 8212170233
- 8212170123 Forwards LER 82-149/03L-0
DIEDERICH, O J Commonwealth Edison Co 82/12/10 KEPPLER, J O Region 3, Office of Director 1p 16452 349 24X Fiche 50-373, 82/12/10, 8212170123
- 8212170126 LER 82-149/03L-0 on 821112, lake blowdown flow recorder discovered giving incorrect readings. Caused by algae buildup on instrument probe. Probe cleaned & weekly functional test will be performed.
WATFORD, P S Commonwealth Edison Co 82/12/10 Region 3, Office of Director 2pp 16452 350 24X Fiche 50-373, 82/12/10, 8212170123

DOCKETED ITEMS

8212170211 Forwards NPDES noncompliance for Permit IL0048151, per App B, Section 3 2 of License NPF-11
DIEDERICH, O J Commonwealth Edison Co 82/12/10 KEPLER, J G
Region 3, Office of Director 1p 16459 349 24X
Fiche 50-373, 82/12/10, 8212170211

--8212170214 NPDES noncompliance notification on 821112, discharge from low vol waste wastewater treatment facility contained 115.6 mg/l oil & grease Cause not stated Discharge stopped, tank taken out of svc & oil soak bags placed in tank
DIEDERICH, O J Commonwealth Edison Co 82/11/24 2pp
16459 350 24X Fiche 50-373, 82/12/10, 8212170211

8212170244 Forwards LER 82-150/03L-0
DIEDERICH, O J Commonwealth Edison Co 82/12/10 KEPLER, J G
Region 3, Office of Director 1p 16456 201 24X
Fiche 50-373, 82/12/10, 8212170244

--8212170270 LER 82-150/03L-0 on 821111, RCIC flow controller failed to control RCIC sys flow during performance of ATP-14 Caused by loose leads at square root converter 1E51-K401 Leads tightened RCIC sys successfully run
HOUSTON, R W Commonwealth Edison Co 82/12/10 Region 3, Office of Director 2pp 16456 202 24X Fiche 50-373, 82/12/10, 8212170244

8212270140 Forwards LER 82-152/03L-0
DIEDERICH, O J Commonwealth Edison Co 82/12/13 KEPLER, J G
Region 3, Office of Director 1p 16538 131 24X
Fiche 50-373, 82/12/13, 8212270140

--8212270148 LER 82-152/03L-0 on 821115, during performance of LIS-RJ-01, differential pressure indicating switch 1E31-N007A setpoint found out of tolerance in nonconservative direction per Tech Spec 3 3 2 Cause unknown Switch recalibrated
HOUSTON, R W Commonwealth Edison Co 82/12/13 Region 3, Office of Director 2pp 16538 132 24X Fiche 50-373, 82/12/13, 8212270140

8212270162 Forwards NPDES noncompliance rpt for 821116
DIEDERICH, O J Commonwealth Edison Co 82/12/13 KEPLER, J G
Region 3, Office of Director 2pp 16539 007 24X
Fiche 50-373, 82/12/13, 8212270162

--8212270170 NPDES noncompliance rpt on 821116, emulsified oil in equalization tank reduced flocculation & filtration efficiency Cause not stated Plant discharge stopped & all treated water returned to equalization tank
* Commonwealth Edison Co 82/12/13 1p 16939 009 24X
Fiche 50-373, 82/12/13, 8212270162

8212280363 Interim deficiency rpt re inadequate pressure transducers/transmitters mounted on post-LOCA hydrogen recombiners Initially reported on 821119 Final rpt will be submitted by 830211 Also reported per Part 21
MANN, S F Niagara Mohawk Power Corp 82/12/14 STAROSTECKI, R
Division of Project & Resident Programs 2pp 16560 058 24X
Fiche 50-000, 82/12/14, 8212280363

--8212280373 Part 21 rpt re inadequate pressure transducers/transmitters mounted on post-LOCA hydrogen recombiners Transducers should be replaced w/nuclear rated transducers Engineering field bulletin to be issued by 821029
EMPEY, D C Rockwell International Corp 82/10/21 COLLINS, J
Region 4, Office of Director 2pp 16560 060 24X
Fiche 50-000, 82/12/14, 8212280363

8212270175 Forwards LER 82-151/03L-0
DIEDERICH, O J Commonwealth Edison Co 82/12/13 KEPLER, J G
Region 3, Office of Director 1p 16538 020 24X
Fiche 50-373, 82/12/13, 8212270175

--8212270180 LER 82-151/03L-0 on 821117, emergency makeup control room ventilation fan B failed to start Caused by bent outlet damper shaft to B train & broken bearing housing cap Linkage misaligned when installed initially Damper repaired
WITTENBURG, K Commonwealth Edison Co 82/12/15 Region 3, Office of Director 2pp 16538 021 24X Fiche 50-373, 82/12/15, 8212270175

8212280447 Forwards LER 82-153/03L-0
DIEDERICH, O J Commonwealth Edison Co 82/12/16 KEPLER, J G
Region 3, Office of Director 1p 16556 001 24X
Fiche 50-373, 82/12/16, 8212280447

--8212280444 LER 82-153/03L-0 on 821118, steam & water leak discovered on regenerative HX shell side relief line to HX socket weld junction Cause not determined Reactor water cleanup sys isolated w/both HX off
WINTERHOFF, D Commonwealth Edison Co 82/12/15 Region 3, Office of Director 2pp 16556 002 24X Fiche 50-373, 82/12/16, 8212280447

8212280483 Forwards LER 82-156/03L-0
DIEDERICH, O J Commonwealth Edison Co 82/12/16 KEPLER, J G
Region 3, Office of Director 1p 16556 006 24X
Fiche 50-373, 82/12/16, 8212280483

--8212280487 LER 82-156/03L-0 on 821119, while performing STP-23A, reactor coolant conductivity exceeded limit Caused by personnel error Personnel advised that startup test insufficient reason to bypass condensate polishers
WITTENBURG, K Commonwealth Edison Co 82/12/16 Region 3, Office of Director 2pp 16556 007 24X Fiche 50-373, 82/12/16, 8212280483

8212280195 Forwards LER 82-158/03L-0
DIEDERICH, O J Commonwealth Edison Co 82/12/20 KEPLER, J G
Region 3, Office of Director 1p 16556 158 24X
Fiche 50-373, 82/12/20, 8212280195

--8212280215 LER 82-158/03L-0 on 821122, drain valve 1B21-F016 would not seal in close direction Caused by dirty contacts in closing torque switch Torque switch contacts cleaned & settings verified
DUS, R Commonwealth Edison Co 82/12/20 Region 3, Office of Director 2pp 16556 159 24X Fiche 50-373, 82/12/20, 8212280195

8212280229 Forwards LER 82-157/03L-0
DIEDERICH, O J Commonwealth Edison Co 82/12/20 KEPLER, J G
Region 3, Office of Director 1p 16562 273 24X
Fiche 50-373, 82/12/20, 8212280229

--8212280231 LER 82-157/03L-0 on 821121, QA control room HVAC ammonia detector failed Caused by broken paper tape in detector Tape replaced
WATFORD, P S Commonwealth Edison Co 82/12/20 Region 3, Office of Director 2pp 16562 274 24X Fiche 50-373, 82/12/20, 8212280229

DOCKET 50-374 LASALLE COUNTY STATION, UNIT 2

A Application/construction stage documents & correspondence

821230066 Generic Ltr 82-27 to all BWR licensees of operating reactors except LACBWR, Big Rock Point, Dresden 1, Humboldt Bay, applicants for GL & holders of CP re transmittal of NUREG-0763 & NUREG-0783 Svc list encl W/o stated encl EISENHUT, D O Division of Licensing 82/11/15 General Public Utilities - OPU Service Corp 22pp 16387 004 24X
Fiche 50-000, 82/11/15, 821230066

8212060381 Notification of 821201 meeting w/util, CF Braun & Govt Accountability Project in Bethesda, MD to discuss independent review of HVAC sys
BOURNIA, A Licensing Branch 2 82/11/26 SCHWENCER, A Licensing Branch 2 3pp 16323 324 24X Fiche 50-373, 82/11/26, 8212060381

8212280212 Forwards Revision 22 to CE-1-A, "QA Program for Nuclear Generating Stations"
SWARTZ, E D Commonwealth Edison Co 82/12/14 HAASS, W P Quality Assurance Branch 1p 16518 007 24X Fiche 50-000, 82/12/14, 8212280212

--8212280231 "QA Program for Nuclear Generating Stations," Revision 22
* Commonwealth Edison Co CE-1-A R22 82/11/01 17pp
16518 009 24X Fiche 50-000, 82/12/14, 8212280212

8212280212 Forwards updated schedule for ongoing environ qualification testing programs, per 810528 commitment
SWARTZ, E D Commonwealth Edison Co 82/12/22 EISENHUT, D O Division of Licensing 18pp 16556 161 24X Fiche 50-000, 82/12/22, 8212280212

8212280298 Forwards info on 821201 meeting re Govt Accountability Project repts & discussions of corrective actions for CF Braun Observation QC-2-53, QA review & Unit 2 HVAC, per NRC 821203 request
REED, C Commonwealth Edison Co 82/12/22 EISENHUT, D O Division of Licensing 34pp 16561 099 24X Fiche 50-373, 82/12/22, 8212280298

F Security, medical, emergency & fire protection plans

8212060041 Forwards Revision 13 to modified amended security plan revision withheld (ref 10CFR73 21)
DELOERGE, L O Commonwealth Edison Co 82/11/29 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 16313 270 24X
Fiche 50-373, 82/11/29, 8212060041

B212090383 Forwards info re emergency operations facilities per B21122 & 1202 requests info previously submitted by telcon Request for written response unnecessary burden on licensee
DELOEDRGE, L O Commonwealth Edison Co 82/12/03 EISENHUT, D O
Division of Licensing 2pp 16365 051 24X Fiche 50-000, 82/12/03, 8212090383

B212130017 Releases public version of Revision 1 to Emergency Plan Implementing Procedure EQ-2, "Pre-Established Onsite & Offsite Monitoring Locations (Maps) "
FELTON, J M Division of Rules and Records 82/12/07 Document
Management Branch 1p 16417 062 24X Fiche 50-000, 82/12/07, 8212130017

--B212130028 Forwards public version of Revision 1 to Emergency Plan Implementing Procedure EQ-2, "Pre-Established Onsite & Offsite Monitoring Locations (Maps) " Revised table of contents encl
PAJOWSKI, J Commonwealth Edison Co 82/11/01 DENTON, H R NRC --
No Detailed Affiliation Given 2pp 16417 063 24X
Fiche 50-000, 82/12/07, 8212130017

--B212130041 Public version of Revision 1 to Emergency Plan Implementing Procedure EQ-2, "Pre-Established Onsite & Offsite Monitoring Locations (Maps) "
PAJOWSKI, J E Commonwealth Edison Co 82/11/29 App 16417 065
24X Fiche 50-000, 82/12/07, 8212130017

B212140243 Advises of distribution of revisions to "Generating Station Emergency Plan " Braidwood annex not prepared
TRAMER, T R Commonwealth Edison Co 82/12/07 DENTON, H R Office
of Nuclear Reactor Regulation, Director 2pp 16409 302 24X
Fiche 50-000, 82/12/07, 8212140243

B212220175 Releases public version of revised generating station emergency plan implementing procedures
FELTON, J M Division of Rules and Records 82/12/10 Document
Management Branch 1p 16529 029 24X Fiche 50-000, 82/12/10, 8212220175

--B212220190 Forwards public version of revised generating station emergency plan implementing procedures, including Procedures ED-3 re demand polling of meteorological data & ED-20 re emergency forecast request
PAJOWSKI, J E Commonwealth Edison Co 82/11/15 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 16529 030
24X Fiche 50-000, 82/12/10, 8212220175

--B212220202 Public version of revised generating station emergency plan implementing procedures, including Procedures ED-3 re demand polling of meteorological data & ED-20 re emergency forecast request
LITERSKI, L A Commonwealth Edison Co 82/10/13 48pp
16529 031 24X Fiche 50-000, 82/12/10, 8212220175

B212220306 Discusses layout of communications equipment required in control room, onsite technical support ctr & near-site emergency operations facility
KEPPLER, J O Region 3, Office of Director 82/12/16
Commonwealth Edison Co 3pp 16503 351 24X Fiche 50-000, 82/12/16, 8212220306

B212300167 Releases public version of revised generating station emergency plan telephone directory
FELTON, J M Division of Rules and Records 82/12/20 Document
Management Branch 1p 16612 215 24X Fiche 50-000, 82/12/20, 8212300167

- B212300179 Forwards public version of revised generating station emergency plan telephone directory
MOORE, R D Commonwealth Edison Co 82/12/02 DENTON, H R Office
of Nuclear Reactor Regulation, Director 1p 16612 216 24X
Fiche 50-000, 82/12/20, 8212300167

--B212300199 Public version of revised generating station emergency plan telephone directory
GALLE, D P Commonwealth Edison Co 82/11/05 60pp 16612 21/
24X Fiche 50-000, 82/12/20, 8212300167

H General correspondence

B212280176 Notifies of change in mailing address for NRC licensing mail
WRIGHT, O N Illinois, State of, Dept. Nuc. Safety (formerly Dept. Public Health) 82/12/20 EISENHUT, D O Division of Licensing,
1p 16556 135 24X Fiche 50-000, 82/12/20, 8212280176

K Utility Final Safety Analysis Report (FSAR) & amends

B212210463 Forwards Amend 61 to FSAR, updating baseline record & incorporating as-built & as-tested configuration
SCHROEDER, C W Commonwealth Edison Co 82/12/13 DENTON, H R
Office of Nuclear Reactor Regulation, Director 3pp 16486 276
24X Fiche 50-373, 82/12/13, 8212210463

--B212210466 Amend 61 to FSAR
* Commonwealth Edison Co 82/12/31 299pp 16486 279 24X
Fiche 50-373, 82/12/13, 8212210463

B212280341 Forwards affidavit confirming distribution of FSAR, Amend 61
SCHROEDER, C W Commonwealth Edison Co 82/12/23 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 16560 092
24X Fiche 50-373, 82/12/23, 8212280341

G Inspection reports, IE Bulletins & correspondence

B208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel Recirculation Sys Piping at BHR Plants " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc
112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240

B208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model B01 & Model B02 Thermoluminescent Dosimeters " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp
16372 142 24X Fiche 50-000, 82/11/05, 8208190245

B208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X
Fiche 50-000, 82/11/18, 8208190251

B212030021 Forwards IE Insp Repts 50-373/82-49 & 50-374/82-15 on B21001-29 No noncompliance noted
STREETER, J F Division of Project & Resident Programs 82/11/18
REED, C Commonwealth Edison Co 2pp 16304 316 24X
Fiche 50-373, 82/11/18, 8212030021

--B212030028 IE Insp Repts 50-373/82-49 & 50-374/82-15 on B21001-29 No noncompliance noted Major areas inspected licensee action on previous insp findings, operational safety verification & monthly surveillance observations
GULDEMOND, W, WILLIAMS, D, MADISON, A Division of Project & Resident Programs 82/11/18 12pp 16304 318 24X
Fiche 50-373, 82/11/18, 8212030021

B212140326 Forwards final BALP Repts 50-373/82-38 & 50-374/82-08 for Jul 1980-Dec 1981 No response required
KEPPLER, J O Region 3, Office of Director 82/11/23 REED, C
Commonwealth Edison Co 3pp 16402 012 24X Fiche 50-373, 82/11/23, 8212140326

--B212140329 BALP Repts 50-373/82-38 & 50-374/82-08 for Jul 1980-Dec 1981 Deficiency noted in conducting tests w/o adequate procedures
* Region 3, Office of Director 82/05/30 39pp 16402 015 24X
Fiche 50-373, 82/11/23, 8212140326

B208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Radilocks " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc
127pp 16411 065 24X Fiche 50-000, 82/11/26, 8208190256

B208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp
16387 028 24X Fiche 50-000, 82/11/30, 8208190257

B212170077 Forwards IE Insp Repts 50-373/82-53 & 50-374/82-21 on B21101-05 & 08 No noncompliance noted
PAPERIELLO, C J Division of Emergency Preparedness & Operational Support 82/12/01 REED, C Commonwealth Edison Co 2pp
16450 354 24X Fiche 50-373, 82/12/01, 8212170077

--B212170079 IE Insp Repts 50-373/82-53 & 50-374/82-21 on B21101-05 & 08 No noncompliance noted Major areas inspected radiological environ protection, including program mgmt, QC & implementation
JANUSKA, A O, GETHMANN, M J, SCHUMACHER, M C Division of Emergency Preparedness & Operational Support 82/11/29 8pp 16450 356
24X Fiche 50-373, 82/12/01, 8212170077

DOCKETED ITEMS

B208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl
 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, B208190259

B208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl
 JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X Fiche 50-000, 82/12/03, B208190261

B212140224 Ack receipt of B21202 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-373/82-45
 SPESSARD, R L Division of Project & Resident Programs 82/12/09 REED, C Commonwealth Edison Co 1p 16408 339 24X Fiche 50-373, 82/12/09, B212140224

--B212140231 Responds to NRC B21104 ltr re violations noted in IE Insp Repts 50-373/82-45 & 50-374/82-13 Corrective actions flow controller returned to panel & station procedures revised to include leakage compensation
 DELOEORGE, L O Commonwealth Edison Co 82/12/02 KEPLER, J G Division of Project & Resident Programs 3pp 16408 340 24X Fiche 50-373, 82/12/09, B212140224

B212140289 Forwards re-evaluation of safety-related concrete masonry walls per IE Bulletin 80-11 Requests NRC review be concluded by June 1983
 SCHROEDER, C W Commonwealth Edison Co 82/12/09 SCHWENCER, A Licensing Branch 2 2pp 16402 085 24X Fiche 50-373, 82/12/09, B212140239

--B212140292 "Re-evaluation of Safety-Related Concrete Masonry Walls at LaSalle County Station "
 * Commonwealth Edison Co 82/11/19 11pp 16402 087 24X Fiche 50-373, 82/12/09, B212140289

B21210104 Ack receipt of B21202 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-373/82-46 & 50-374/82-19
 NORELIOUS, C E Division of Engineering & Technical Programs 82/12/13 REED, C Commonwealth Edison Co 1p 16491 042 24X Fiche 50-373, 82/12/13, B21210104

--B21210108 Responds to NRC B21108 ltr re violations noted in IE Insp Repts 50-373/82-46 & 50-374/82-19 Corrective actions Morrison Const Co SDP PC-2 welding metal control procedure reworded to avoid internal procedure conflict
 DELOEORGE, L O Commonwealth Edison Co 82/12/02 KEPLER, J G Region 3, Office of Director 3pp 16491 043 24X Fiche 50-373, 82/12/13, B21210104

B208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16, B208190267

B208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27 " Svc list encl
 JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X Fiche 50-000, 82/12/20, B208190268

B212270198 Ack receipt of B21105 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-373/82-41 & 50-374/82-09
 STREETER, J F Division of Project & Resident Programs 82/12/20 REED, C Commonwealth Edison Co 1p 16535 151 24X Fiche 50-373, 82/12/20, B212270198

--B212270223 Responds to NRC B21007 ltr re violations noted in IE Insp Repts 50-373/82-41 & 50-374/82-09 Corrective actions operator trainee functioning directly under unit operator & guidelines for control room trainees drafted
 DELOEORGE, L O Commonwealth Edison Co 82/11/05 KEPLER, J G Region 3, Office of Director 3pp 16535 152 24X Fiche 50-373, 82/12/20, B212270198

B212290337 Forwards addl copies of inservice insp plan in response to NRC request & per requirements of Generic Ltr 82-14 Suggests alternative to requirements contained in ltr
 SCHROEDER, C W Commonwealth Edison Co 82/12/21 SCHWENCER, A Licensing Branch 2 2pp 16589 124 24X Fiche 50-374, 82/12/21, B212290337

S Reportable occurrences, LERs & related correspondence

B212270162 Forwards NPDES noncompliance rept for B21116
 DIEDERICH, G J Commonwealth Edison Co 82/12/13 KEPLER, J G Region 3, Office of Director 2pp 16539 007 24X Fiche 50-373, 82/12/13, B212270162

--B212270170 NPDES noncompliance rept on B21116, emulsified oil in equalization tank reduced flocculation & filtration efficiency Cause not stated Plant discharge stopped & all treated water returned to equalization tank
 * Commonwealth Edison Co 82/12/13 1p 16539 009 24X Fiche 50-373, 82/12/13, B212270162

B212280363 Interim deficiency rept re inadequate pressure transducers/transmitters mounted on post-LOCA hydrogen recombiners Initially reported on B21119 Final rept will be submitted by 830211 Also reported per Part 21
 MANNO, S F Niagara Mohawk Power Corp 82/12/14 STARDSTECK, J R Division of Project & Resident Programs 2pp 16560 098 24X Fiche 50-000, 82/12/14, B212280363

--B212280373 Part 21 rept re inadequate pressure transducers/transmitters mounted on post-LOCA hydrogen recombiners Transducers should be replaced w/nuclear rated transducers Engineering field bulletin to be issued by 821029
 EMPEY, D C Rockwell International Corp 82/10/21 COLLINS, J Region 4, Office of Director 2pp 16360 060 24X Fiche 50-000, 82/12/14, B212280363

DOCKET 50-375 NUCLEAR EXAMINATION REACTOR

W Decommissioning Stage Documents & Correspondence

B212210110 Discusses 800310 application to authorize dismantling of L-85 facility, License R-118 Physical changes in facility have resulted in preparation of revised supporting statement for dismantling facility Statement encl
 REMLEY, M E Rockwell International Corp 82/12/14 THOMAS, C D Standardisation & Special Projects Branch 8pp 16491 033 24X Fiche 50-375, 82/12/14, B212210110

DOCKET 50-382 WATERFORD GENERATING STATION, UNIT 3

A Application/construction stage documents & correspondence

B212090429 Forwards B21102 meeting summary re activities authorized by Licenses NPF-13 & CPPR-13 Meeting beneficial & provided better understanding of issues W/o encl
 O'REILLY, J P Region 2, Office of Director 82/11/15 LEWIS, F W Middle South Utilities, Inc - Middle South Energy, Inc 2pp 16364 274 24X Fiche 50-000, 82/11/15, B212090429

B212270418 Responds to FOIA request for documents re proposed revision &/or update to reactor safety study referred to in NUREG-0784, Chapter 10 as RS 11 & all documents pertaining to reactor cooling methods Forwards documents listed in app
 FELTON, J M Division of Rules and Records 82/11/26 SHOLLY, S C Union of Concerned Scientists 3pp 16549 233 24X Fiche 50-000, 82/11/26, B212270418

--B211050027 Forwards summary of semiscale test results & advises that board notification re test results issued W/o encl
 NOVAK, T M Assistant Director for Licensing 82/09/24 Division of Licensing 1p 16549 278 24X Fiche 50-000, 82/11/26, B212270418

B212100002 Informs of revisions inadvertently excluded from FSAR Amend 29 Info will be incorporated in FSAR Amend 30, currently scheduled for submittal in early Dec 1982
 MAURIN, L V Louisiana Power & Light Co 82/12/07 NOVAK, T M Assistant Director for Licensing 5pp 16377 272 24X Fiche 50-382, 82/12/07, B212100002

B212220440 Board Notifications 82-125 & 82-125A forwards info re H Etherington evaluation of flow blockage during natural circulation of PWRs Results do not adversely impact present position on reliance on natural circulation
 NOVAK, T M Assistant Director for Licensing 82/12/14 Atomic Safety and Licensing Board Panel 5pp 16523 135 24X Fiche 50-000, 82/12/14, B212220440

B212220461 Board Notification 82-124 forwards RJ Mattson B21123 memo re Semiscale S-UT-8 test results Phenomena of core level depression & loop seal clearing may be more complex than previously supposed
 NOVAK, T M Assistant Director for Licensing 82/12/14 Atomic Safety and Licensing Board Panel 7pp 16523 169 24X Fiche 50-000, 82/12/14, B212220461

8212300162 Provides status of commitments re recruiting & upgrading total corporate capability
MAURIN, L V Louisiana Power & Light Co 82/12/17 WILSON, J NRC -
No Detailed Affiliation Given 3pp 16598 020 24X
Fiche 50-382, 82/12/17, 8212300162

8212270160 Confirms 821215 telcon re equipment qualification audit Agreements & commitments documented
MAURIN, L V Louisiana Power & Light Co 82/12/20 NOVAK, T M
Assistant Director for Licensing 2pp 16538 044 24X
Fiche 50-382, 82/12/20, 8212270160

E NRC Safety Evaluation Report (SER), suppl's & correspondence

8212010175 Forwards Suppl 4 to SER w/o encl
KNIGHTON, Q W Licensing Branch 3 82/10/29 MAURIN, L V Louisiana
Power & Light Co 2pp 16290 293 24X Fiche 50-382, 82/10/29,
8212010175

F Security, medical, emergency & fire protection plans

8212010411 Requests addl info re emergency action levels in facility radiological emergency plan Response to encl comments should be provided within 15 days
KNIGHTON, Q W Licensing Branch 3 82/11/19 MAURIN, L V Louisiana
Power & Light Co 8pp 16271 069 24X Fiche 50-382, 82/11/19,
8212010411

8212090203 Confirms 821202 telcon re 820128 response to Generic Ltr B1-10 re permanent backup & interim emergency operations facilities (EOF) Interim EOF approved in NRC 820202 ltr
MAURIN, L V Louisiana Power & Light Co 82/12/03 NOVAK, T M
Assistant Director for Licensing 3pp 16361 333 24X
Fiche 50-382, 82/12/03, 8212090203

8212200121 Forwards GL Madsen 821014 ltr transmitting SALP Rept 50-382/82-20 for Jul 1981 - June 1982 & util 821108 & 16 comments on rept
COLLINS, J T Region 4, Office of Director 82/12/03 MAURIN, L V
Louisiana Power & Light Co 2pp 16470 100 24X
Fiche 50-382, 82/12/03, 8212200121

--8212200126 SALP Rept 50-382/82-20 for Jul 1981 - June 1982 Addl insp effort should be continued until const program completed & throughout preoperational testing phase or until licensee demonstrates improvement in mgt controls in weak areas
CROSSMAN, W A, MADSEN, O L Division of Resident, Reactor Project & Engineering Programs 82/10/13 20pp 16470 104 24X
Fiche 50-382, 82/12/03, 8212200121

--8212200127 Forwards comments on SALP Rept 50-382/82-20 for Jul 1981 - June 1982 Agrees w/NRC findings, conclusions & recommendations Corrective measures in weak areas initiated
MAURIN, L V Louisiana Power & Light Co 82/11/08 MADSEN, O L
Division of Resident, Reactor Project & Engineering Programs 7pp
16470 124 24X Fiche 50-382, 82/12/03, 8212200121

8212150042 Forwards fire protection training program & fire protection program
MAURIN, L V Louisiana Power & Light Co 82/12/09 NOVAK, T M
Assistant Director for Licensing 1p 16425 060 24X
Fiche 50-382, 82/12/09, 8212150042

--8212150047 Fire protection program
* Louisiana Power & Light Co PMD-FE-010 R00 82/05/17 51pp
16425 061 24X Fiche 50-382, 82/12/09, 8212150042

--8212150050 "Program Description for Fire Protection Training"
* Louisiana Power & Light Co 82/02/17 36pp 16425 112 24X
Fiche 50-382, 82/12/09, 8212150042

8212150140 Requests deficiencies noted in 820331 interim findings of offsite emergency preparedness be remedied Future interim & final findings should include FEMA headquarter concurrence
GRIMES, B K Division of Emergency Preparedness 82/06/11
KRIMM, R W Federal Emergency Management Agency 1p 16429 109
24X Fiche 50-382, 82/12/14, 8212150131

8212270013 Releases public version of comments on BNWL/NRC review of emergency action levels
FELTON, J M Division of Rules and Records 82/12/16 Document
Management Branch 1p 16591 290 24X Fiche 50-382, 82/12/16,
8212270013

--8212270015 Forwards public version of BNWL/NRC review of emergency action levels for radiological emergency plan
MAURIN, L V Louisiana Power & Light Co 82/12/10 NOVAK, T M
Assistant Director for Licensing 1p 16551 291 24X
Fiche 50-382, 82/12/16, 8212270013

--8212270017 Public version of comments on BNWL/NRC review of emergency action levels for radiological emergency plan
* Louisiana Power & Light Co 82/12/10 17pp 16551 292 24X
Fiche 50-382, 82/12/16, 8212270013

G Adjudicatory correspondence

8212020355 Response opposing applicant 821112 motion for reconsideration & clarification of certain rulings in ASLB 821103 partial initial decision on conditions for evacuation & ltrs of agreement
GROESCH, G L Joint Intervenor-Waterford 82/11/29 Atomic
Safety and Licensing Board Panel 3pp 16278 015 24X
Fiche 50-382, 82/11/29, 8212020355

8212020374 Memorandum & order denying Joint Intervenor 820612 motion for reconsideration of ASLB 790913 order & 790512 ruling Balance of State of LA 820721 petition to intervene denied in light of Court of Appeals decision, NRDC vs NRC
WOLFE, S J Atomic Safety and Licensing Board Panel 82/11/30
Joint Intervenor-Waterford 7pp 16278 092 24X
Fiche 50-382, 82/11/30, 8212020374

8212020342 Order scheduling 830111-14 evidentiary hearing in New Orleans, LA Record reopened solely to receive evidence on adequacy of applicant revised pre-emergency public info brochure
WOLFE, S J Atomic Safety and Licensing Board Panel 82/12/01 2pp
16279 147 24X Fiche 50-382, 82/12/01, 8212020342

8212060088 Advises that Judge Jordan should be served at address in Pompano Beach, FL during 821218-830131
WOLFE, S J Atomic Safety and Licensing Board Panel 82/12/01
Office of the Executive Legal Director 1p 16314 279 24X
Fiche 50-382, 82/12/01, 8212060088

8212060007 Response supporting applicant 821112 motion for reconsideration or clarification of ASLB 821103 partial initial decision Need to satisfy four conditions to receive low power OL should be clarified Certificate of Svc encl
TURK, S E Hearing Branch 1 82/12/02 Atomic Safety and
Licensing Board Panel 8pp 16313 302 24X Fiche 50-382, 82/12/02,
8212060007

8212080260 Response opposing Joint Intervenor 821130 motion to extend time to file direct testimony & to reschedule hearing on emergency brochure Intervenor fails to explain witness unavailability Certificate of Svc encl
TURK, S E Hearing Branch 1 82/12/07 Atomic Safety and
Licensing Board Panel 6pp 16354 111 24X Fiche 50-382, 82/12/07,
8212080260

8212100098 Memorializes 821012 telcon w/ASLB, applicant, Joint Intervenor, NRC & FEMA re ASLB rulings on applicant 820923 filing & Joint Intervenor 820927 motions Svc list encl
CHURCHILL, B W Shaw, Pittman, Potts & Troubridge CHURCHILL, B W
Louisiana Power & Light Co 82/12/07 WOLFE, S J, FOREMAN, H,
JORDAN, W H Atomic Safety and Licensing Board Panel 5pp
16379 181 24X Fiche 50-382, 82/12/07, 8212100098

8212100100 Answer opposing Joint Intervenor 821130 motion to extend time for filing direct testimony & to reschedule hearing on emergency brochure Joint Intervenor fails to justify untimeliness of motion Certificate of Svc encl
CHURCHILL, B W Louisiana Power & Light Co CHURCHILL, B W Shaw,
Pittman, Potts & Troubridge 82/12/07 Atomic Safety and
Licensing Board Panel 10pp 16379 116 24X Fiche 50-382, 82/12/07,
8212100100

8212150035 Memorandum & order denying Joint Intervenor 821130 motion for indefinite extension of time to file direct testimony & request for rescheduling hearing Intervenor failed to show good cause in support of motion
WOLFE, S J Atomic Safety and Licensing Board Panel 82/12/13
Joint Intervenor-Waterford 6pp 16421 236 24X
Fiche 50-382, 82/12/13, 8212150035

8212150131 Forwards listed correspondence between NRC & FEMA Some documents withheld (ref 10CFR2.790)
TURK, S E Hearing Branch 1 82/12/14 GROESCH, G Affiliation
Unknown 2pp 16429 106 24X Fiche 50-382, 82/12/14, 8212150131

--8212150137 Requests L Jones 820305 ltr to S Turk, NRC exhibit on potassium iodine & transcripts for 820906, 07 & 12
CASSIDY, B P Federal Emergency Management Agency 82/05/14
TURK, S E Hearing Branch 1, 1p 16429 108 24X
Fiche 50-382, 82/12/14, 8212150131

DOCKETED ITEMS

--B212150140 Requests deficiencies noted in B20331 interim findings of offsite emergency preparedness be remedied Future interim & final findings should include FEMA headquarter concurrence
ORIHES, B K Division of Emergency Preparedness 82/06/11
KRIHM, R W Federal Emergency Management Agency 1p 16429 109
24X Fiche 50-382, 82/12/14, 8212150131

--B212150148 Forwards NRC proposed Findings of fact, supporting brief & motion to correct hearing transcript w/o encl
TURK, S E Hearing Branch 1 82/07/16 CASSIDY, B P Federal
Emergency Management Agency 1p 16429 110 24X
Fiche 50-382, 82/12/14, 8212150131

--B212150153 Requests ASLB order requesting further FEMA testimony on public info brochure & final FEMA testimony filed w/ASLB
CASSIDY, B P Federal Emergency Management Agency 82/09/13
TURK, S E Hearing Branch 1 1p 16429 111 24X
Fiche 50-382, 82/12/14, 8212150131

B212160354 Memorandum memorializing 821213 telcon w/applicant, NRC, FEMA & Joint Intervenor's Joint Intervenor's motion to extend time to file direct testimony & reschedule hearing on emergency brochure denied
WOLFE, S J Atomic Safety and Licensing Board Panel 82/12/14 App
16442 337 24X Fiche 50-382, 82/12/14, 8212160354

B212160503 Memorandum & order partially granting applicant 821112 motion for reconsideration or clarification of ASLB 821103 Partial Initial Decision LBP-82-100 Condition 2 re ltrs of agreement w/support parishes modified
WOLFE, S J Atomic Safety and Licensing Board Panel 82/12/14
Louisiana Power & Light Co 8pp 16442 122 24X
Fiche 50-382, 82/12/14, 8212160503

B212160515 Order rejecting Joint Intervenor's 821212 request for full NRC investigation re massive chemical fire at Union Carbide plant & relation to nuclear plant ASLB not authorized to initiate or conduct investigation
WOLFE, S J Atomic Safety and Licensing Board Panel 82/12/15 2pp
16442 117 24X Fiche 50-382, 82/12/15, 8212160515

--B212160521 Notifies of massive chemical fire at Union Carbide plant & requests full NRC investigation re nuclear plant
FONTANA, L Joint Intervenor's-Waterford FONTANA, L Fontana, L
82/12/12 WOLFE, S Atomic Safety and Licensing Board Panel 1p
16442 119 24X Fiche 50-382, 82/12/15, 8212160515

B212230361 Motion for reconsideration of ASLB 821213 memorandum & order due to ill health of E Duncan, 30-day extension requested in which to file direct testimony & commence hearings
ORDESCH, O L Joint Intervenor's-Waterford 82/12/17 Atomic
Safety and Licensing Board Panel 4pp 16531 166 24X
Fiche 50-382, 82/12/17, 8212230361

B212270330 Forwards ASLB 730731 Memorandum & Order ALA0-13B, affirming ASLB decisions to reopen hearing on fuel densification issue & to permit operation during proceeding & reversing determination to reopen on four issues H/svc list
PIZZUTO, C M Shaw, Pittman, Potts & Trowbridge 82/12/21
ORDESCH, O L Joint Intervenor's-Waterford 10pp 16530 174 24X
Fiche 50-382, 82/12/21, 8212270330

B212270184 Order rescheduling hearing since record reopened to receive evidence re adequacy of public info booklet, hearing will be held on 820208-11 in New Orleans, LA
WOLFE, S J Atomic Safety and Licensing Board Panel 82/12/22 2pp
16539 011 24X Fiche 50-382, 82/12/22, 8212270184

B212270247 Memorandum memorializing 821221 conference call w/FEMA, Applicants & Joint Intervenor's
WOLFE, S J Atomic Safety and Licensing Board Panel 82/12/22 4pp
16530 392 24X Fiche 50-382, 82/12/22, 8212270247

B212280182 Exception to ASLB 821103 partial initial decision re Condition 2 Certificate of Svc encl
CHURCHILL, B W Louisiana Power & Light Co CHURCHILL, B W Shaw,
Pittman, Potts & Trowbridge 82/12/24 Atomic Safety and
Licensing Appeal Panel 4pp 16562 181 24X Fiche 50-382, 82/12/24,
8212280182

0 Inspection reports, IE Bulletins & correspondence

B208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and
Enforcement 82/10/28 Consolidated Edison Co of New York, Inc
112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240

B208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model B01 & Model B02 Thermoluminescent Dosimeters " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards
82/11/05 Consolidated Edison Co of New York, Inc 110pp
16372 142 24X Fiche 50-000, 82/11/05, 8208190245

B212070119 Forwards IE Insp Rept 50-382/82-23 on 820716-0915 No noncompliance noted
MADSEN, O L Division of Resident, Reactor Project & Engineering
Programs 82/11/17 MAURIN, L V Louisiana Power & Light Co 2pp
16327 089 24X Fiche 50-382, 82/11/17, 8212070119

--B212070123 IE Insp Rept 50-382/82-23 on 820716-0915 No noncompliance noted Major areas inspected previously identified insp findings, preoperational test procedure review, preoperational test witnessing & site tour
CONSTABLE, O L, CUMMINS, J E, JONES, W B Division of Resident,
Reactor Project & Engineering Programs 82/11/10 10pp
16327 091 24X Fiche 50-382, 82/11/17, 8212070119

B208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18
Consolidated Edison Co of New York, Inc 109pp 16411 199 24X
Fiche 50-000, 82/11/18, 8208190251

B208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Paddocks " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and
Enforcement 82/11/26 Consolidated Edison Co of New York, Inc
127pp 16411 065 24X Fiche 50-000, 82/11/26, 8208190256

B208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards
82/11/30 Consolidated Edison Co of New York, Inc 356pp
16387 028 24X Fiche 50-000, 82/11/30, 8208190257

B208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and
Enforcement 82/12/03 Consolidated Edison Co of New York, Inc
113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259

B208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03
Consolidated Edison Co of New York, Inc 110pp 16462 064 24X
Fiche 50-000, 82/12/03, 8208190261

B212070223 Ack receipt of 821029 ltr in response to violations noted in IE Insp Rept 50-382/82-1B Addl info re craft personnel training & completion of training requested
MADSEN, O L Division of Resident, Reactor Project & Engineering
Programs 82/12/03 MAURIN, L V Louisiana Power & Light Co 2pp
16329 352 24X Fiche 50-382, 82/12/03, 8212070223

--B212070228 Responds to NRC 820930 ltr re violations noted in IE Insp Rept 50-382/82-1B Corrective actions Nonconformance Rept W3-4374 issued reporting lack of approved design & weld insp documentation on mod insp Procedure CP-717 revised
MAURIN, L V Louisiana Power & Light Co 82/10/29 MADSEN, O L
Division of Resident, Reactor Project & Engineering Programs 2pp
16329 354 24X Fiche 50-382, 82/12/03, 8212070223

B212200121 Forwards OL Madsen 821014 ltr transmitting SALP Rept 50-382/82-20 for Jul 1981 - June 1982 & util 821108 & 16 comments on rept
COLLINS, J T Region 4, Office of Director 82/12/03 MAURIN, L V
Louisiana Power & Light Co 2pp 16470 100 24X
Fiche 50-382, 82/12/03, 8212200121

--B212200125 Forwards SALP Rept 50-382/82-20 for Jul 1981 - June 1982 Analyses & evaluation will be discussed in New Orleans, LA on 821020 Comments should be submitted within 20 days from date of meeting
MADSEN, O L Division of Resident, Reactor Project & Engineering
Programs 82/10/14 MAURIN, L V Louisiana Power & Light Co
2pp 16470 102 24X Fiche 50-382, 82/12/03, 8212200121

--B212200126 SALP Rept 50-382/82-20 for Jul 1981 - June 1982 Addl insp effort should be continued until const program completed & throughout preoperational testing phase or until licensee demonstrates improvement in mgt controls in weak areas
CROSSMAN, W A, MADSEN, O L Division of Resident, Reactor Project & Engineering Programs 82/10/13 20pp 16470 104 24X
Fiche 50-382, 82/12/03, 8212200121

--B21200127 Forwards comments on SALP Rept 50-382/82-20 for Jul 1981 - June 1982 Agrees w/NRC findings, conclusions & recommendations Corrective measures in weak areas initiated MAURIN, L V Louisiana Power & Light Co 82/11/08 MADSEN, G L Division of Resident, Reactor Project & Engineering Programs 9pp 16470 124 24X Fiche 50-382, 82/12/03, B21200121

--B21200129 Clarifies B21108 comments on Item g of SALP Rept 50-382/82-20 for Jul 1981 - June 1982 re instrumentation & controls sys MAURIN, L V Louisiana Power & Light Co 82/11/16 MADSEN, G L Division of Resident, Reactor Project & Engineering Programs 2pp 16470 133 24X Fiche 50-382, 82/12/03, B21200121

B21280374 Forwards IE Insp Rept 50-382/82-14 on B20516-0715 Notice of violation transmitted under separate cover MADSEN, G L Division of Resident, Reactor Project & Engineering Programs 82/12/06 MAURIN, L V Louisiana Power & Light Co 2pp 16559 078 24X Fiche 50-382, 82/12/06, B21280374

--B21280378 IE Insp Rept 50-382/82-14 on B20516-0715 Noncompliance noted failure to adequately control quality of safety-related work CONSTATLE, G L, CUMMINS, J E, JONES, W B Division of Resident, Reactor Project & Engineering Programs 82/10/29 17pp 16559 080 24X Fiche 50-382, 82/12/06, B21280374

B21280423 Discusses IE Insp on B20516-0715 & forwards notice of violation & notice of proposed imposition of civil penalty COLLINS, J T Region 4, Office of Director 82/12/06 MAURIN, L V Louisiana Power & Light Co 3pp 16559 028 24X Fiche 50-382, 82/12/06, B21280423

--B21280430 Notice of violation & notice of proposed imposition of civil penalty in amount of \$20,000 Noncompliance noted failure to adequately control activities affecting quality of safety-related work COLLINS, J T Region 4, Office of Director 82/12/06 3pp 16559 031 24X Fiche 50-382, 82/12/06, B21280423

B208190267 IE Info Notice B2-49, "Correction for Sample Conditions for Air & Gas Monitoring" Svc list encl DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 12pp 16628 191 24X Fiche 50-000, 82/12/16, B208190267

B208190268 IE Info Notice B2-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27" Svc list encl JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X Fiche 50-000, 82/12/20, B208190268

B21290245 Discusses augmented inservice insp program being implemented to comply w/requirements of SRP 6 & including Branch Technical Position ASB 3-1 re main steam & feedwater & safety injection piping MAURIN, L V Louisiana Power & Light Co 82/12/22 NOVAK, T M Assistant Director for Licensing 3pp 16582 100 24X Fiche 50-382, 82/12/22, B21290245

5 Reportable occurrences, LERs & related correspondence

B212210066 Fifth interim rept of Significant Const Deficiency 35 re matl properties of JC White Co tube track & welded fittings Corrective action will be completed by B30401 Final rept will be sent by B30508 MAURIN, L V Louisiana Power & Light Co 82/11/15 COLLINS, J T Region 4, Office of Director 2pp 16492 270 24X Fiche 50-382, 82/11/15, B212210066

B212210172 Seventh Interim Significant Const Deficiency Rept 40 re ITE-Gould starter coil failure in containment cooling fans Lab testing of six coils returned to vendor scheduled to be completed by B21210 Final rept will be submitted by B30110 MAURIN, L V Louisiana Power & Light Co 82/11/15 COLLINS, J T Region 4, Office of Director 1p 16484 256 24X Fiche 50-382, 82/11/15, B212210172

B212210281 Final rept of Potential Reportable Deficiency 91 re operator base plate hubs for MSIVs made from alloy matl rather than carbon steel Initially reported on B21019 Safety function of MSIVs not affected Item reportable under 10CFR50.55(e) MAURIN, L V Louisiana Power & Light Co 82/11/15 COLLINS, J T Region 4, Office of Director 2pp 16483 019 24X Fiche 50-382, 82/11/15, B212210281

B212030048 Final rept of Potentially Reportable Deficiency 92 re design of maint hatch shield door seal sys Initially reported on B21019 Condition not reportable under 10CFR50.55(e) because change initiated to upgrade sys to safety-related design MAURIN, L V Louisiana Power & Light Co 82/11/22 COLLINS, J T Region 4, Office of Director 2pp 16304 141 24X Fiche 50-382, 82/11/22, B212030048

B212030036 Interim Significant Const Deficiency Rept 67 re failure of A500 Grade B tube steel to meet chemical/physical properties Initially reported on B21022 Physical property data needed to judge acceptability Next rept by B21219 MAURIN, L V Louisiana Power & Light Co 82/11/23 COLLINS, J T Region 4, Office of Director 3pp 16304 131 24X Fiche 50-382, 82/11/23, B212030036

B212030055 Final deficiency rept re lack of DBA testing for Coating Sys MS-1 & MS-3 in reactor containment bldg Initially reported on B21023 Successful DBA tests conducted on Dimetrate E-2 Condition determined not reportable per 10CFR50.55(e) MAURIN, L V Louisiana Power & Light Co 82/11/23 COLLINS, J T Region 4, Office of Director 2pp 16304 156 24X Fiche 50-382, 82/11/23, B212030055

B212140395 Significant Const Deficiency Rept 50 re possible malfunction in Agastat E7000 series time-delay relays Corrective actions complete Documentation being assembled by contractor for QA review Final rept will be submitted by B30105 MAURIN, L V Louisiana Power & Light Co 82/11/30 COLLINS, J T Region 4, Office of Director 1p 16401 034 24X Fiche 50-382, 82/11/30, B212140395

B212210230 Interim Significant Const Deficiency Rept 49 re Time-Trol, Inc heat trace panel malfunctions Defective modules still being replaced Final rept to be submitted by B30118 MAURIN, L V Louisiana Power & Light Co 82/11/30 COLLINS, J T Region 4, Office of Director 1p 16483 350 24X Fiche 50-382, 82/11/30, B212210230

B212060329 EN-B2-037 on B21206, notice of violation & notice of proposed imposition of civil penalty will be issued to util for violation of OA requirements CRAIG, J, AXELRAD, J NRC - No Detailed Affiliation Given 82/12/01 1p 16312 081 24X Fiche 50-382, 82/12/01, B212060329

B212270130 Final Significant Const Deficiency Rept 42 re Type HMA auxiliary relays mfg from 1976-June 1981 Initially reported on B21207 Corrective actions complete, per GE Svc Advice 721-PSM-166 1 MAURIN, L V Louisiana Power & Light Co 82/12/14 COLLINS, J T Region 4, Office of Director 3pp 16538 146 24X Fiche 50-382, 82/12/14, B212270130

B212270138 Final Significant Const Deficiency Rept 38 re flooding of emergency diesel generator A high & low voltage control & relay panels Damaged relay panels replaced MAURIN, L V Louisiana Power & Light Co 82/12/15 COLLINS, J T Region 4, Office of Director 3pp 16538 134 24X Fiche 50-382, 82/12/15, B212270138

B212270166 Interim deficiency rept re incorrect structural calculations used for holdup & boric acid makeup tanks Const completion date delayed so final rept will not be submitted until B30221 MAURIN, L V Louisiana Power & Light Co 82/12/15 COLLINS, J T Region 4, Office of Director 1p 16538 043 24X Fiche 50-382, 82/12/15, B212270166

B212270257 Final Significant Const Deficiency Rept 44 re LPSI pump suction valves Initially reported on B20810 New 20-inch diameter check valves installed, butterfly valves locked open & 300 lb pressure class rating extended to suction line, MAURIN, L V Louisiana Power & Light Co 82/12/15 COLLINS, J T Region 4, Office of Director 3pp 16530 327 24X Fiche 50-382, 82/12/15, B212270257

B212280169 Final rept of Significant Const Deficiency 52 re bimetallic penetration welds w/o stress relief/post-weld heat treatment on containment penetration assemblies Replacement penetrations w/correct post-weld heat treatment installed MAURIN, L V Louisiana Power & Light Co 82/12/15 COLLINS, J T Region 4, Office of Director 3pp 16563 204 24X Fiche 50-382, 82/12/15, B212280169

B212280203 Final rept of Significant Const Deficiency 34 re Buffalo Forge HVAC fan shrouds w/o capability to contain fan blade missiles Mods to fans completed on B21132 Reported by manufacturer under Part 21 MAURIN, L V Louisiana Power & Light Co 82/12/15 COLLINS, J T Region 4, Office of Director 3pp 16562 104 24X Fiche 50-382, 82/12/15, B212280203

B212280143 Final rept of Significant Const Deficiency 48 re design application of break flanges at elevated temps in RCS, safety injection & chemical & vol control sys Flanges w/matl not meeting ASME Code requirements replaced w/correct matl MAURIN, L V Louisiana Power & Light Co 82/12/17, COLLINS, J T Region 4, Office of Director 2pp, 16563 189 24X Fiche 50-382, 82/12/17, B212280143

DOCKETED ITEMS

B212300198 Potentially Reportable Deficiency 96 re inadequate shoulder gap for Batch C fuel assemblies Initially reported on B21117 Condition determined not reportable Mods to fuel assemblies will be made by C-E prior to shipment MAURIN, L. V. Louisiana Power & Light Co 82/12/20 COLLINS, J. T. Region 4, Office of Director 2pp 16598 027. 24X Fiche 50-382, 82/12/20, B212300198

B212300310 Final Significant Const Deficiency Rept 67 re Failure of AS200 Grade B tube steel to meet chemical/physical Properties Properties within ASME/ASTM code No degradation of safety-related sys occurred MAURIN, L. V. Louisiana Power & Light Co 82/12/20 COLLINS, J. T. Region 4, Office of Director 2pp 16594 216 24X Fiche 50-382, 82/12/20, B212300310

B212300219 Final rept of Significant Const Deficiency 43 re main/ emergency feedwater sys Internals of check valves 2FW-V825A & 2FW-V826B removed & two 6-inch 900 check valves added downstream of each emergency feedwater flow transmitter MAURIN, L. V. Louisiana Power & Light Co 82/12/21 COLLINS, J. T. Region 4, Office of Director 7pp 16597 357 24X Fiche 50-382, 82/12/21, B212300219

B212300288 Final rept of Significant Const Deficiency 41 re unapproved welding Attachment weld removed & rewelded w/approved procedures Two temporary welds removed & base metal repaired & found acceptable MAURIN, L. V. Louisiana Power & Light Co 82/12/21 COLLINS, J. T. Region 4, Office of Director 3pp 16595 128 24X Fiche 50-382, 82/12/21, B212300288

DOCKET 50-387 SUSQUEHANNA STEAM ELECTRIC STATION, UNIT 1

C NRC Safety Evaluation Report (SER), supp & correspondence

B211090019 Updates B20827 response to SER Suppl 3, Section 3 10 2 2 re seismic & dynamic qualification Info completes SER action CURTIS, N. W. Pennsylvania Power & Light Co 82/11/04 SCHWENCER, A. Licensing Branch 2. 2pp 16008 238 24X Fiche 50-387, 82/11/04, B211090019

F Security, medical, emergency & fire protection plans

B212030087 Forwards IE Safeguards Insp Rept 50-387/82-23 on B20916. No noncompliance noted HARTY, T. T. Division of Engineering & Technical Programs 82/11/19 KENYON, B. D. Pennsylvania Power & Light Co 2pp 16304 255 24X Fiche 50-387, 82/11/19, B212030087

--B212030090 IE Safeguards Insp Rept 50-387/82-23 on B20916 No noncompliance noted Major areas inspected licensee actions re excessive alarms Safeguards info deleted (ref 10CFR2 21)

HADDEN, W. J., DUNLAP, J. M., ODDY, A. T. Division of Engineering & Technical Programs 82/11/19 2pp 16304 257 24X Fiche 50-387, 82/11/19, B212030087

B212070151 Forwards IE Insp Repts 50-387/82-32 & 50-388/82-05 on B20908-1019 & notice of violation BYARDSTECK, R. Division of Project & Resident Programs 82/11/23 KENYON, B. D. Pennsylvania Power & Light Co 2pp 16335 318 24X Fiche 50-387, 82/11/23, B212070151

--B212070154 Notice of violation from insp on B20908-1019 Safeguards info deleted (ref 10CFR2 790)
* Division of Project & Resident Programs. 82/11/23 2pp 16335 319 24X Fiche 50-387, 82/11/23, B212070151

--B212070158 IE Insp Repts 50-387/82-32 & 50-388/82-05 on B20908-1019 Noncompliance noted security violation re vehicles in protected areas & requirements for operable fire protection equipment not met Safeguards info deleted (ref 10CFR2 790)
RHODS, G. G., MCCANN, J. F., CHUNG, J. W. Division of Project & Resident Programs 82/11/03 17pp 16335 321 24X Fiche 50-387, 82/11/23, B212070151

B212060140 Provides status of B20916 proposed improvements to security sys Improvement re info retrieval complete Mod re vital area portal hardware unnecessary CURTIS, N. W. Pennsylvania Power & Light Co 82/11/30 SCHWENCER, A. Licensing Branch 2 1p 16313 157. 24X Fiche 50-387, 82/11/30, B212060140

B21220537 Notifies that B21025 amend request for License NPF-14 is consistent w/10CFR50 54(g) & does not decrease effectiveness of physical security plan No fee required SCHWENCER, A. Licensing Branch 2 82/12/16 CURTIS, N. W. Pennsylvania Power & Light Co 2pp 16523 036 24X Fiche 50-387, 82/12/16, B21220537

B212300407 Releases public version of temporary change notices for emergency plan implementing procedures FELTON, J. M. Division of Rules and Records 82/12/22 Document Management Branch 1p 16613 179 24X Fiche 50-387, 82/12/22, B212300407

--B212300408 Forwards public version of temporary change notices for emergency plan implementing procedures, including Procedure EP-IP-034 re pharmacy bldg sample station emergency sampling * Pennsylvania Power & Light Co 82/12/14 DENTON, H. R. NRC - No Detailed Affiliation Given 1p 16613 180 24X Fiche 50-387, 82/12/22, B212300407

--B212300410 Public version of temporary change notices for emergency plan implementing procedures, including Procedure EP-IP-034 re pharmacy bldg sample station emergency sampling RIZZO, J. S. Pennsylvania Power & Light Co 82/12/13 14pp 16613 181 24X Fiche 50-387, 82/12/22, B212300407

K Utility Final Safety Analysis Report (FSAR) & amends

B212210450 Forwards Amend 53 to DL application containing Revision 32 to FSAR CURTIS, N. W. Pennsylvania Power & Light Co 82/12/17 SCHWENCER, A. Licensing Branch 2 11pp 16487 218 24X Fiche 50-387, 82/12/17, B212210450

P Operating license stage documents & correspondence

B212010167 Board Notification B2-114 forwards Teledyne independent design review EISENHUT, D. G. Division of Licensing 82/11/09 PALLADINO, N. J., OLINSKY, V., AHEARNE, J. Commissioners 5pp 16290 244 24X Fiche 50-387, 82/11/09, B212010167

B21230066 Generic Ltr B2-27 to all BWR licensees of operating reactors except LACDWR, Big Rock Point, Dresden 1, Humboldt Bay, applicants for DL & holders of CP re transmittal of NUREG-0763 & NUREG-0783 Svc list encl W/o stated encl EISENHUT, D. G. Division of Licensing 82/11/15 General Public Utilities - OPU Service Corp 22pp 16387 004 24X Fiche 50-000, 82/11/15, B21230066

B212010030 Informs of issuance of full power license amends on B21112 Susquehanna 1 & Summer 1 issued 40-yr license expiring on 220717 & 220321, respectively Susquehanna 1 will operate w/low power limitation & Summer 1 at 50% power PERCH, R. L. Licensing Branch 2 KANE, W. F. Licensing Branch 1 82/11/15 CASE, E., CARTER, J. Office of Nuclear Reactor Regulation, Director EISENHUT, D. Division of Licensing 1p 16271 356 24X Fiche 50-000, 82/11/15, B212010030

B212140494 Forwards containment dome shield bell descriptions, Figures 4 & 5 ROUSE, L. C. Advanced Fuel & Spent Fuel Licensing Branch 82/11/23 Advanced Fuel & Spent Fuel Licensing Branch 3pp 16431 336 24X Fiche 50-387, 82/11/23, B212140494

--B212140497 Advises that shield bell descriptions need no longer be withheld from public disclosure CURTIS, N. W. Pennsylvania Power & Light Co 82/11/11 ROUSE, L. C. Advanced Fuel & Spent Fuel Licensing Branch 1p 16431 339 24X Fiche 50-387, 82/11/23, B212140494

B212030253 Board Notification B2-105 forwards RH Vollmer B20930 memo to DQ Eisenhut re alleged design deficiency in ASME Code Class I piping Effects of local pipe wall stresses due to support loads introduced by pipe clamps not evaluated properly EISENHUT, D. G. Division of Licensing 82/11/24 PALLADINO, N. J., ROBERTS, T. F., ASSELBTINE, J. K. Commissioners 2pp 16316 240 24X Fiche 50-000, 82/11/24, B212030253

--B212030265 Discusses alleged design deficiency in ASME Code Class I piping Failure to dual w/pipe support-pipe interface design issue would be serious matter if substantiated Dfc of Investigations will assist in evaluation VOLLMER, R. H. Division of Engineering 82/09/30 EISENHUT, D. G. Division of Licensing 5pp 16316 247 24X Fiche 50-000, 82/11/24, B212030253

B212060066 Informs of changes to be made to emergency svc water sys in order to resolve single failure concerns Mod changes spray pond bypass valve from normally closed valve to normally open valve CURTIS, N. W. Pennsylvania Power & Light Co 82/12/01 SCHWENCER, A. Licensing Branch 2 1p 16314 321 24X Fiche 50-387, 82/12/01, B212060066

DOCKETED ITEMS

B212090214 Suppls B21110 ltr describing nonconformance w/NUREG-0737, Item II E 4 2, "Containment Isolation Dependability"
Opening logic for isolation valves modified to eliminate ganged-opening in more than one sys
CURTIS, N W Pennsylvania Power & Light Co 82/12/07 SCHWENCER, A
Licensing Branch 2 1p 16362 343 24X Fiche 50-387, 82/12/07,
B212090214

B212160417 Forwards "PA Power & Light Co Susquehanna Steam Electric Station Unit 1 - Review of As-Built Reconciliation on Sample of 400 Pipe Supports & All Phase III (Large Pipe) Anchors"
CURTIS, N W Pennsylvania Power & Light Co 82/12/07 SCHWENCER, A
Licensing Branch 2 1p 16443 001 24X Fiche 50-387, 82/12/07,
B212160417

--B212160419 "PA Power & Light Co Susquehanna Steam Electric Station Unit 1 - Review of As-Built Reconciliation on Sample of 400 Pipe Supports & All Phase III (Large Pipe) Anchors"
SATTAR, D, RHOADES, W J Pennsylvania Power & Light Co 82/11/30
97pp 16443 002 24X Fiche 50-387, 82/12/07, B212160417

B212170271 Application for Amend 15 to License NPF-14, consisting of proposed changes to Tech Specs re administrative controls, special test exemption for oxygen concentration, leakage in RCS & refueling operations
CURTIS, N W Pennsylvania Power & Light Co 82/12/10 SCHWENCER, A
Licensing Branch 2 3pp 16456 177 24X Fiche 50-387, 82/12/10,
B212170271

--B212170272 Proposed Tech Spec changes re administrative controls, special test exemption for oxygen concentration, leakage in RCS & refueling operations
* Pennsylvania Power & Light Co 82/12/10 10pp 16456 180
24X Fiche 50-387, 82/12/10, B212170271

B212160317 Provides justification for interim operation w/currently installed suppression pool temp monitoring sys (SPOTMOS) resistance temp detector device Multiple sensor failures disabling SPOTMOS unlikely to occur during normal operation
CURTIS, N W Pennsylvania Power & Light Co 82/12/13 SCHWENCER, A
Licensing Branch 2 3pp 16442 083 24X Fiche 50-387, 82/12/13,
B212160317

B212220552 Forwards Amend 6 to License NPF-14, safety evaluation & notice of issuance & availability Amend changes surveillance requirements for vacuum breakers, establishes min discharge pressure for LPCI pump & changes ECCS actuation values
SCHWENCER, A Licensing Branch 2 82/12/16 CURTIS, N W
Pennsylvania Power & Light Co 3pp 16523 309 24X
Fiche 50-387, 82/12/16, B212220552

--B212220554 Amend 6 to License NPF-14, changing surveillance requirements for vacuum breakers, establishing min discharge pressure for LPCI pump, changing ECCS actuation instrument setpoint values & applicability of safety relief valves
SCHWENCER, A Licensing Branch 2 82/12/16 28pp 16523 312
24X Fiche 50-387, 82/12/16, B212220552

--B212220556 Safety evaluation supporting Amend 6 to License NPF-14
* Office of Nuclear Reactor Regulation, Director 82/12/16 4pp
16523 340 24X Fiche 50-387, 82/12/16, B212220552

--B212220557 Notice of issuance & availability of Amend 6 to License NPF-14
PERCH, R L Licensing Branch 2 82/12/16 3pp 16523 344 24X
Fiche 50-387, 82/12/16, B212220552

B212270272 Provides complete description delineating interim gas line flow restrictions to 39m3 per second & procedures addressing sys configuration changes, per License Condition 2 C (13)
CURTIS, N W Pennsylvania Power & Light Co 82/12/21 SCHWENCER, A
Licensing Branch 2 2pp 16530, 324 24X Fiche 50-387, 82/12/21,
B212270272

B212280446 Advises that util response to questions re evaluation of hydrodynamic loads on control rod drive piping delayed until end of Second Quarter 1983, due to delay in receiving BWR owners group input
CURTIS, N W Pennsylvania Power & Light Co 82/12/22, SCHWENCER, A
Licensing Branch 2 1p 16556 022 24X Fiche 50-387, 82/12/22,
B212280446

B212280347 Forwards revised "Mark II Primary Containment Vacuum Relief Valve Test Program Phase 4"
CURTIS, N W Pennsylvania Power & Light Co 82/12/23 SCHWENCER, A
Licensing Branch 2 2pp 16561 043 24X Fiche, 50-387, 82/12/23,
B212280347

--B212280354 Revision 1 to "Mark II Primary Containment Vacuum Relief Valve Test Program Phase 4"
WILLIAMSON, O O, TESKE, M E, BILANIN, A J Continuum Dynamics, Inc
82-4 R01 82/09/30 6pp, 16561 045 24X Fiche 50-387, 82/12/23,
B212280347

0 Inspection Reports, IE Bulletins & correspondence

B208190240 IE Bulletin B2-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel Recirculation Sys Piping at BWR Plants" Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc.
112pp 16462 163 24X Fiche 50-000, 82/10/28, B208190240

B208190245 IE Info Notice B2-42, "Defects Observed in Panasonic Model 801 & Model B02 Thermoluminescent Dosimeters" Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards
82/11/05 Consolidated Edison Co of New York, Inc 110pp
16372 142 24X Fiche 50-000, 82/11/05, B208190245

B208190251 IE Info Notice B2-44, "Clarification of Emergency Plan Exercise Requirements" Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18,
Consolidated Edison Co of New York, Inc 109pp 16411 197 24X
Fiche 50-000, 82/11/18, B208190251

B212030087 Forwards IE Safeguards Insp Rpt 50-387/82-23 on B20816 No noncompliance noted
MARTIN, T T Division of Engineering & Technical Programs 82/11/19
KENYON, B D Pennsylvania Power & Light Co 2pp 16304 255 24X
Fiche 50-387, 82/11/19, B212030087

--B212030090 IE Safeguards Insp Rpt 50-387/82-23 on B20816 No noncompliance noted Major areas inspected licensee actions re excessive alarms Safeguards info deleted (ref 10CFR73 21)
MADDEN, W J, DUNLAP, J M, QODY, A T Division of Engineering & Technical Programs 82/11/19 2pp 16304 257 24X
Fiche 50-387, 82/11/19, B212030087

B212070151 Forwards IE Insp Rpts 50-387/82-32 & 50-388/82-05 on B20908-1019 & notice of violation
STAROSTECKI, R Division of Project & Resident Programs 82/11/23
KENYON, B D Pennsylvania Power & Light Co 2pp 16335 318 24X
Fiche 50-387, 82/11/23, B212070151

--B212070154 Notice of violation from Insp on B20908-1019 Safeguards 1 deleted (ref 10CFR2 790)
* Division of Project & Resident Programs 82/11/23 2pp
16335 319 24X Fiche 50-387, 82/11/23, B212070151

--B212070158 IE Insp Rpts 50-387/82-32 & 50-388/82-05 on B20908-1019 Noncompliance noted security violation re vehicles in protected area & requirements for operable fire protection equipment not met Safeguards info deleted (ref 10CFR2 790)
RHOADS, G G, MCCANN, J F, CHUNG, J W Division of Project & Resident Programs 82/11/03 17pp 16335 321 24X
Fiche 50-387, 82/11/23, B212070151

B208190256 IE Info Notice B2-46, "Defective & Obsolete Combination Radilocks" Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc
127pp 16411 065 24X Fiche 50-000, 82/11/26, B208190256

B212100059 Forwards IE Insp Rpt 50-387/82-41 on B21105-10, No noncompliance noted
MARTIN, T T Division of Engineering & Technical Programs 82/11/2
KENYON, B D Pennsylvania Power & Light Co 2pp 16377 149 24X
Fiche 50-387, 82/11/26, B212100059

--B212100064 IE Insp Rpt 50-387/82-41 on B21105-10 No noncompliance noted Major area inspected status of outstanding items concerning pipe hangers & restraints
NARROW, L, DURR, J P Division of Engineering & Technical Program
82/11/24 4pp 16377 151 24X Fiche 50-387, 82/11/26, B212100064

B208190257 IE Info Notice B2-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl" Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards
82/11/30 Consolidated Edison Co of New York, Inc 356pp
16397 028 24X Fiche 50-000, 82/11/30, B208190257

B212030093 Ack receipt of B21119 ltr informing NRC of steps taken to correct violations noted in IE Insp Rpt 50-387/82-39
MARTIN, T T Division of Engineering & Technical Programs 82/11/3
KENYON, B D Pennsylvania Power & Light Co 1p 16304 250. 24X
Fiche 50-387, 82/11/30, B212030093

--B212030096 Responds to NRC B21019 ltr re violations noted in IE Insp Rpt 50-387/82-39 Corrective actions Temporary Change
B2-2232 issued requiring section heads to identify computer points & functions used for Tech Spec
KENYON, B D Pennsylvania Power & Light Co. 82/11/19 MARTIN, T,
Division of Engineering & Technical Programs 4pp 16304 251
24X Fiche 50-387, 82/11/30, B212030093

DOCKETED ITEMS

8208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies" Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259

8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets" Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X Fiche 50-000, 82/12/03, 8208190261

8212290463 Forwards IE Insp Repts 50-387/82-40 & 50-388/82-12 on 821020-1201 & notice of violation
STARDSTECKI, R Division of Project & Resident Programs 82/12/14 KENYON, B D Pennsylvania Power & Light Co 2pp 16585 138 24X Fiche 50-387, 82/12/14, 8212290463

--8212290463 Notice of violation from insp on 821020-1201
* Division of Project & Resident Programs 82/12/19 1p. 16585 140 24X Fiche 50-387, 82/12/14, 8212290463

--8212290468 IE Insp Repts 50-387/82-40 & 50-388/82-12 on 821020-1201 Noncompliance noted failure to keep record of average suppression chamber water temp during RCIC sys testing
RHODES, D O, MCCANN, J F, CHUNG, J H Division of Project & Resident Programs 82/12/10 17pp 16585 141 24X Fiche 50-387, 82/12/14, 8212290468

8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring" Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16, 8208190267

8212220400 Ack receipt of 821203 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-387/82-34
MARTIN, T T Division of Engineering & Technical Programs 82/12/16 KENYON, B D Pennsylvania Power & Light Co 1p 16503 232 24X Fiche 50-387, 82/12/16, 8212220400

--8212220405 Responds to NRC 821103 ltr re violations noted in IE Insp Rept 50-387/82-34 Corrective actions procedures revised to clarify & implement insp program for prefabricated hanger components Affidavit encl
KAUFFMAN, J T Pennsylvania Power & Light Co 82/12/03 MARTIN, T T Division of Engineering & Technical Programs 5pp 16503 233 24X Fiche 50-387, 82/12/16, 8212220400

8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27" Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X Fiche 50-000, 82/12/20, 8208190268

R Periodic operating reports & related correspondence

8212290115 Forwards monthly operating rept for Oct 1982
KENYON, B D Pennsylvania Power & Light Co 82/11/11 Management Information Branch 1p 16582 245 24X Fiche 50-387, 82/11/11, 8212290115

--8212290117 Monthly operating rept for Oct 1982
KUCZYNSKI, L A Pennsylvania Power & Light Co 82/11/03 4pp 16582 246 24X Fiche 50-387, 82/11/11, 8212290115

S Reportable occurrences, LERs & related correspondence

8212030041 Forwards revised LER 82-026/01T-1
KEISER, H W Pennsylvania Power & Light Co 82/11/19 HAYNES, R C Region 1, Office of Director 1p. 16304 138 24X Fiche 50-387, 82/11/19, 8212030041

--8212030047 Revised LER 82-026/01T-1 on 820717, review revealed certain cables discussed in Deficiency Rept 80-00-28 not flexed or grounded prior to fuel load. Caused by failure to maintain control over FDDR KRI-607 during turnover of const
MITCHELL, D O Pennsylvania Power & Light Co 82/11/19 Region 1, Office of Director 2pp 16304 139 24X Fiche 50-387, 82/11/19, 8212030041

8212030173 Forwards LER 82-043/03L-0
KEISER, H W Pennsylvania Power & Light Co 82/11/24 HAYNES, R C Region 1, Office of Director 1p 16303 278 24X Fiche 50-387, 82/11/24, 8212030173.

--8212030179 LER 82-043/03L-0 on 821025, essential svc water pump failed to start. Cause could not be determined or reproduced Svc pump tested 5 times w/o recurrence of failure
MITCHELL, D O Pennsylvania Power & Light Co 82/11/24 Region 1, Office of Director 1p 16303 279 24X Fiche 50-387, 82/11/24, 8212030173

8212080295 Forwards LER 82-046/03L-0
KEISER, H W Pennsylvania Power & Light Co 82/11/29 HAYNES, R C Region 1, Office of Director 1p 16353 360 24X Fiche 50-387, 82/11/29, 8212080295

--8212080303 LER 82-046/03L-0 on 821031, OA reviewer determined five safety-related snubbers installed had not been determined operable by performing necessary surveillance Caused by oversights in turnover process List of snubbers verified
MITCHELL, D O Pennsylvania Power & Light Co 82/11/29 Region 1, Office of Director 1p 16353 361 24X Fiche 50-387, 82/11/29, 8212080295

8212080320 Forwards LER 82-044/03L-0
KEISER, H W Pennsylvania Power & Light Co 82/11/29 HAYNES, R C Region 1, Office of Director 1p 16353 342 24X Fiche 50-387, 82/11/29, 8212080320

--8212080328 LER 82-044/03L-0 on 821030, during startup test program, determined that excess flow check valve returned to svc after maint w/o surveillance Caused by personnel error
MITCHELL, D O Pennsylvania Power & Light Co 82/11/29 Region 1, Office of Director 1p 16353 343 24X Fiche 50-387, 82/11/29, 8212080320

8212080333 Forwards LER 82-047/03L-0
KEISER, H W Pennsylvania Power & Light Co 82/11/29 HAYNES, R C Region 1, Office of Director 1p 16353 333 24X Fiche 50-387, 82/11/29, 8212080333

--8212080342 LER 82-047/03L-0 on 821027, during performance of diesel generator monthly operability test, diesel generator tripped on high vibration Caused by defective vibration switch & pressure regulator components repaired
KUCZYNSKI, L A Pennsylvania Power & Light Co 82/11/29 Region 1, Office of Director 1p 16353 334 24X Fiche 50-387, 82/11/29, 8212080333

8212080362 Forwards LER 82-042/01T-0
KEISER, H W Pennsylvania Power & Light Co 82/11/30 HAYNES, R C Region 1, Office of Director 1p 16352 291 24X Fiche 50-387, 82/11/30, 8212080362

--8212080372 LER 82-042/01T-0 on 821116, review of response to internal incident rept revealed that grab samples not taken at required frequency while RHR svc water sys monitor out of svc Caused by personnel error
KUCZYNSKI, L A Pennsylvania Power & Light Co 82/11/30 Region 1, Office of Director 1p 16352 292 24X Fiche 50-387, 82/11/30, 8212080362

8212080369 Forwards LER 82-043/01T-0
KEISER, H W Pennsylvania Power & Light Co 82/11/30 HAYNES, R C Region 1, Office of Director 1p 16353 314 24X Fiche 50-387, 82/11/30, 8212080369

--8212080378 LER 82-043/01T-0 on 821116, engineering review revealed failure of single component could defeat overload detection & protection devices for containment penetration carrying power cables for reactor recirculation pumps
KUCZYNSKI, L A Pennsylvania Power & Light Co 82/11/30 Region 1, Office of Director 2pp 16353 315 24X Fiche 50-387, 82/11/30, 8212080369

8212080382 Forwards LER 82-048/03L-0
KEISER, H W Pennsylvania Power & Light Co 82/12/01 HAYNES, R C Region 1, Office of Director 1p 16352 321 24X Fiche 50-387, 82/12/01, 8212080382

--8212080386 LER 82-048/03L-0 on 821101, control rod position indication full-out position switch inoperable for one rod Caused by failed subcomponent on printed circuit board Board replaced
MITCHELL, D O Pennsylvania Power & Light Co 82/12/01 Region 1, Office of Director 1p 16352 322 24X Fiche 50-387, 82/12/01, 8212080382

8212140182 Forwards LER 82-002/01T-1
KEISER, H W Pennsylvania Power & Light Co 82/12/01 HAYNES, R C Region 1, Office of Director 1p 16410 211 24X Fiche 50-387, 82/12/01, 8212140182

--B212140189 LER 82-002/01T-1 on 820721, review of pipe clamp anchors determined that Detail 600 anchors would not support axial loads as designed. Caused by faulty documentation which allowed incorrect installation of anchors. Anchors reworked. MITCHELL, D G Pennsylvania Power & Light Co 82/12/01 Region 1, Office of Director 2pp 16410 212 24X Fiche 50-387, 82/12/01, 8212140182

B212140135 Forwards LER 82-049/03L-0
KEISER, H W Pennsylvania Power & Light Co 82/12/03 HAYNES, R C
Region 1, Office of Director 1p 16408 171 24X
Fiche 50-387, 82/12/03, 8212140135

--B212140138 LER 82-049/03L-0 on 821103, HPCI sys inoperable when input voltage to static inverter exceeded setpoint & tripped off inverter during startup test program. Caused by exceeding trip setpoint. Inverter reworked & setpoint raised. MITCHELL, D G Pennsylvania Power & Light Co 82/12/03 Region 1, Office of Director 1p 16408 172 24X Fiche 50-387, 82/12/03, 8212140135

B212140258 Forwards LER 82-050/03L-0
KEISER, H W Pennsylvania Power & Light Co 82/12/03 HAYNES, R C
Region 1, Office of Director 1p 16401 330 24X
Fiche 50-387, 82/12/03, 8212140258

--B212140261 LER 82-050/03L-0 on 821103, diesel generator D failed to run during performance of surveillance test. Caused by frequency sensitive relay voltage regulator repositioned until nonfrequency sensitive relay installed. MITCHELL, D G Pennsylvania Power & Light Co 82/12/03 Region 1, Office of Director 1p 16401 331 24X Fiche 50-387, 82/12/03, 8212140258

B212140268 Forwards revised LER 82-031/03L-1
KEISER, H W Pennsylvania Power & Light Co 82/12/03 HAYNES, R C
Region 1, Office of Director 1p 16401 004 24X
Fiche 50-387, 82/12/03, 8212140268

--B212140325 Revised LER 82-031/03L-1 on 821002, 1105, 07, 08 & 09, zone III of secondary containment showed indication of failure to maintain required vacuum. Caused by wind turbulence. External atmospheric sensor moved. MITCHELL, D G Pennsylvania Power & Light Co 82/12/03 Region 1, Office of Director 1p 16401 005 24X Fiche 50-387, 82/12/03, 8212140268

B212210236 Forwards LER 82-05L/03L-0
KEISER, H W Pennsylvania Power & Light Co 82/12/07 HAYNES, R C
Region 1, Office of Director 1p 16484 232 24X
Fiche 50-387, 82/12/07, 8212210236

--B212210241 LER 82-051/03L-0 on 821107, during startup testing of RCIC sys, controller functioning but could not be transferred to automatic mode. Caused by controller not being tuned at rated conditions. Controller calibr & testing completed. MITCHELL, D G Pennsylvania Power & Light Co 82/12/07 Region 1, Office of Director 1p 16484 233 24X Fiche 50-387, 82/12/07, 8212210236

B212210343 Forwards LER 82-052/03L-0
KEISER, H W Pennsylvania Power & Light Co 82/12/07 HAYNES, R C
Region 1, Office of Director 1p 16497 001 24X
Fiche 50-387, 82/12/07, 8212210343

--B212210347 LER 82-052/03L-0 on 821107, during startup testing, pressure instrumentation indicated Zone 1 of secondary containment not maintained at required vacuum. Caused by high wind condition. Zone III sensor separated & moved. MITCHELL, D G Pennsylvania Power & Light Co 82/12/07 Region 1, Office of Director 1p 16497 003 24X Fiche 50-387, 82/12/07, 8212210343

B212210052 Forwards LER 82-053/03L-0
KEISER, H W Pennsylvania Power & Light Co 82/12/10 HAYNES, R C
Region 1, Office of Director 1p 16492 234 24X
Fiche 50-387, 82/12/10, 8212210052

--B212210057 LER 82-053/03L-0 on 821111, during startup testing program, control structure heating & ventilation sys chlorine detector determined inoperable. Caused by clogged wick in chlorine detector. Equipment repaired. MITCHELL, D G Pennsylvania Power & Light Co 82/12/10 Region 1, Office of Director 2pp 16492 235 24X Fiche 50-387, 82/12/10, 8212210052

B212280403 Forwards LER 82-055/03L-0
KEISER, H W Pennsylvania Power & Light Co 82/12/14 HAYNES, R C
Region 1, Office of Director 1p 16560 050 24X
Fiche 50-387, 82/12/14, 8212280403

--B212280417 LER 82-055/03L-0 on 821114, during startup testing, rod worth minimizer declared inoperable & removed from svc after locking up several times during rod movement. Caused by defective reed switch. Indication mechanism replaced. MITCHELL, D G Pennsylvania Power & Light Co 82/12/14 Region 1, Office of Director 1p 16560 051 24X Fiche 50-387, 82/12/14, 8212280403

B212280465 Forwards LER 82-054/03L-0
KEISER, H W Pennsylvania Power & Light Co 82/12/14 HAYNES, R C
Region 1, Office of Director 1p 16556 026 24X
Fiche 50-387, 82/12/14, 8212280465

--B212280468 LER 82-054/03L-0 on 821115, due to drywell chiller tripping, drywell temp exceeded 135 F. Caused by strainer blockage. Strainer removed & design change to replace present strainer initiated. MITCHELL, D G Pennsylvania Power & Light Co 82/12/14 Region 1, Office of Director 2pp 16556 027 24X Fiche 50-387, 82/12/14, 8212280465

B212280490 Final deficiency rept re failure to meet single failure criterion for medium voltage penetration. Initially reported on 821117. Redundant Class IE overcurrent protection will be provided for assemblies. Also reported per Part 21. CURTIS, N W Pennsylvania Power & Light Co 82/12/15 HAYNES, R C
Region 1, Office of Director 4pp 16556 138 24X
Fiche 50-387, 82/12/15, 8212280490

B212290441 Forwards LER 82-057/03L-0
KEISER, H W Pennsylvania Power & Light Co 82/12/20 HAYNES, R C
Region 1, Office of Director 1p 16585 219 24X
Fiche 50-387, 82/12/20, 8212290441

--B212290446 LER 82-057/03L-0 on 821120, during startup testing program, RCIC declared inoperable after ramp generator failed. Cause undetermined. Generator board inspected, cleaned & functionally checked. No problems identified. MITCHELL, D G Pennsylvania Power & Light Co 82/12/20 Region 1, Office of Director 1p 16585 220 24X Fiche 50-387, 82/12/20, 8212290441

X Onsite Storage of Low Level Waste

B212290494 Advises that affidavit re 820923 application for byproduct mat'l license for low level radioactive waste storage must contain reason for withholding info from public disclosure per 10CFR2 790
ROUSE, L C Advanced Fuel & Spent Fuel Licensing Branch 82/10/27
CURTIS, N W Pennsylvania Power & Light Co 2pp 16603 181 24X
Fiche 50-387, 82/10/27, 8212290494

DOCKET 50-388 SUSQUEHANNA STEAM ELECTRIC STATION, UNIT 2

A Application/construction stage documents & correspondence

B21230066 Generic Ltr 82-27 to all BWR licensees of operating reactors except LACBWR, Big Rock Point, Dresden 1, Humboldt Bay, applicants for DL & holders of CP re transmittal of NUREG-0763 & NUREG-0783 Svc list encl W/o stated encl EISENHUT, D G Division of Licensing 82/11/15 General Public Utilities - CPU Service Corp 2pp 16387 004 24X
Fiche 50-000, 82/11/15, 821230066

B212140494 Forwards containment dome shield bell descriptions, Figures 4 & 5
ROUSE, L C Advanced Fuel & Spent Fuel Licensing Branch 82/11/23
Advanced Fuel & Spent Fuel Licensing Branch 3pp 16431 336 24X
Fiche 50-387, 82/11/23, 8212140494

--B212140497 Advises that shield bell descriptions need no longer be withheld from public disclosure
CURTIS, N W Pennsylvania Power & Light Co 82/11/11 ROUSE, L C
Advanced Fuel & Spent Fuel Licensing Branch 1p 16431 339 24X
Fiche 50-387, 82/11/23, 8212140494

B212030293 Board Notification 82-105 forwards RH Vollmer 820930 memo to DO Eisenhower re alleged design deficiency in ASME Code Class I piping. Effects of local pipe wall stresses due to support loads introduced by pipe clamps not evaluated properly. EISENHUT, D G Division of Licensing 82/11/24 FALLADINO, N J
Commissioners 2pp 16316 240 24X Fiche 50-000, 82/11/24, 8212030293

--B212030265 Discusses alleged design deficiency in ASME Code Class I piping. Failure to deal w/pipe support-pipe interface design issue would be serious matter if substantiated. Ofc of Investigations will assist in evaluation.
VOLLMER, R H Division of Engineering 82/09/30 EISENHUT, D G
Division of Licensing 5pp 16316 247 24X Fiche 50-000, 82/11/24, 8212030265

DOCKETED ITEMS

8212060066 Informs of changes to be made to emergency svc water sys in order to resolve single failure concerns Mod changes spray pond bypass Valve from normally closed valve to normally open valve
CURTIS, N W Pennsylvania Power & Light Co 82/12/01 SCHWENCER, A
Licensing Branch 2 1p 16314 321 24X Fiche 50-387, 82/12/01, 8212060066

8212210310 Provides justification for unnecessary documentation of Unit 2 seismic qualification review team & environ qualification audit Few equipment differences exist between Units 1 & 2
CURTIS, N W Pennsylvania Power & Light Co 82/12/17 SCHWENCER, A
Licensing Branch 2 2pp 16496 320 24X Fiche 50-388, 82/12/17, 8212210310

8212210450 Forwards Amend 53 to DL application containing Revision 32 to FSAR
CURTIS, N W Pennsylvania Power & Light Co 82/12/17 SCHWENCER, A
Licensing Branch 2 11pp 16487 218 24X Fiche 50-387, 82/12/17, 8212210450

8212280446 Advises that util response to questions re evaluation of hydrodynamic loads on control rod drive piping delayed until end of Second Quarter 1983, due to delay in receiving DWR owners group input
CURTIS, N W Pennsylvania Power & Light Co 82/12/22 SCHWENCER, A
Licensing Branch 2 1p 16556 022 24X Fiche 50-387, 82/12/22, 8212280446

8212280347 Forwards revised "Mark II Primary Containment Vacuum Relief Valve Test Program Phase 4"
CURTIS, N W Pennsylvania Power & Light Co 82/12/23 SCHWENCER, A
Licensing Branch 2 2pp 16561 043 24X Fiche 50-387, 82/12/23, 8212280347

--8212280354 Revision 1 to "Mark II Primary Containment Vacuum Relief Valve Test Program Phase 4"
WILLIAMSON, G O, TESKE, M E, DILANIN, A J Continuum Dynamics, Inc
82-4 R01 82/09/30 6pp 16561 045 24X Fiche 50-387, 82/12/23, 8212280347

F Security, medical, emergency & fire protection plans

8212070151 Forwards IE Insp Repts 50-387/82-32 & 50-388/82-05 on 820908-1019 & notice of violation
STAROSTECKI, R Division of Project & Resident Programs 82/11/23
KENYON, B D Pennsylvania Power & Light Co 2pp 16335 318 24X
Fiche 50-387, 82/11/23, 8212070151

--8212070154 Notice of violation from insp on 820908-1019 Safeguards info deleted (ref 10CFR2 790)
* Division of Project & Resident Programs 82/11/23 2pp
16335 319 24X Fiche 50-387, 82/11/23, 8212070151

--8212070158 IE Insp Repts 50-387/82-32 & 50-388/82-05 on 820908-1019 Noncompliance noted security violation re vehicles in protected area & requirements for operable fire protection equipment not met Safeguards info deleted (ref 10CFR2 790)
RHODAS, O O, MCCABE, E C Division of Project & Resident Programs 82/11/03 17pp 16338 321 24X Fiche 50-387, 82/11/23, 8212070151

8212300407 Releases public version of temporary change notices for emergency plan implementing procedures
FELTON, J M Division of Rules and Records 82/12/22 Document
Management Branch 1p 16613 179 24X Fiche 50-387, 82/12/22, 8212300407

--8212300408 Forwards public version of temporary change notices for emergency plan implementing procedures, including Procedure EP-IP-034 re pharmacy bldg sample station emergency sampling
* Pennsylvania Power & Light Co 82/12/14 DENTON, H R NRC - No
Detailed Affiliation Given 1p 16613 180 24X
Fiche 50-387, 82/12/22, 8212300407

--8212300410 Public version of temporary change notices for emergency plan implementing procedures, including Procedure EP-IP-034 re pharmacy bldg sample station emergency sampling
RIZZIO, J S Pennsylvania Power & Light Co 82/12/13 14pp
16613 181 24X Fiche 50-387, 82/12/22, 8212300407

G Inspection reports, IE Bulletins & correspondence

8208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc
112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240

8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp
16372 142 24X Fiche 50-000, 82/11/05, 8208190245

8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/10 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X
Fiche 50-000, 82/11/10, 8208190251

8212070151 Forwards IE Insp Repts 50-387/82-32 & 50-388/82-05 on 820908-1019 & notice of violation
STAROSTECKI, R Division of Project & Resident Programs 82/11/23
KENYON, B D Pennsylvania Power & Light Co 2pp 16335 318 24X
Fiche 50-387, 82/11/23, 8212070151

--8212070154 Notice of violation from insp on 820908-1019 Safeguards info deleted (ref 10CFR2 790)
* Division of Project & Resident Programs 82/11/23 2pp
16335 319 24X Fiche 50-387, 82/11/23, 8212070151

--8212070158 IE Insp Repts 50-387/82-32 & 50-388/82-05 on 820908-1019 Noncompliance noted security violation re vehicles in protected area & requirements for operable fire protection equipment not met Safeguards info deleted (ref 10CFR2 790)
RHODAS, O O, MCCANN, J F, CHUNG, J W Division of Project & Resident Programs 82/11/03 17pp 16335 321 24X
Fiche 50-387, 82/11/23, 8212070151

8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Radiolocks " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc
127pp 16411 065 24X Fiche 50-000, 82/11/26, 8208190256

8208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp
16387 028 24X Fiche 50-000, 82/11/30, 8208190257

8208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc
113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259

8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X
Fiche 50-000, 82/12/03, 8208190261

8212290463 Forwards IE Insp Repts 50-387/82-40 & 50-388/82-12 on 821020-1201 & notice of violation
STAROSTECKI, R Division of Project & Resident Programs 82/12/14
KENYON, B D Pennsylvania Power & Light Co 2pp 16385 138 24X
Fiche 50-387, 82/12/14, 8212290463

--8212290468 IE Insp Repts 50-387/82-40 & 50-388/82-12 on 821020-1201 Noncompliance noted failure to keep record of average suppression chamber water temp during RCTC sys testing
RHODAS, O O, MCCANN, J F, CHUNG, J W Division of Project & Resident Programs 82/12/10 17pp 16385 141 24X
Fiche 50-387, 82/12/14, 8212290463

8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc
127pp 16428 191 24X Fiche 50-000, 82/12/16, 8208190267

8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27 " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X
Fiche 50-000, 82/12/20, 8208190268

H Reportable occurrences, LERs & related correspondence

8212280323 Final deficiency rept re nonconformance of Bechtel field welding initially reported on 821115 Training sessions conducted re welding QC requirements & Procedures FP-0-24 & FP-W-1 will be revised Also reported per Part 21
CURTIS, N W Pennsylvania Power & Light Co 82/12/15 HAYNEB, R C
Region 1, Office of Director 7pp 16562 077 24X
Fiche 50-388, 82/12/15, 8212280323

DOCKETED ITEMS

B212280346 Interim deficiency rept re design verification of max permissible lengths of wire in low voltage power & control circuits Caused by Bechtel failure to follow procedures Final rept by B30415 Also reportable per Part 21
CURTIS, N W Pennsylvania Power & Light Co 82/12/15 HAYNES, R C
Region 1, Office of Director 3pp 16561 038 24X
Fiche 50-389, 82/12/15, 8212280346

B212280400 Final deficiency rept re failure to meet single failure criterion for medium voltage penetration Initially reported on 821117 Redundant Class 1E overcurrent protection will be provided for assemblies Also reported per Part 21
CURTIS, N W Pennsylvania Power & Light Co 82/12/15 HAYNES, R C
Region 1, Office of Director 4pp 16556 138 24X
Fiche 50-387, 82/12/15, 8212280400

X Onsite Storage of Low Level Waste

B212290494 Advises that affidavit re 820923 application for byproduct mail license for low level radwaste storage must contain reason for withholding info from public disclosure per 10CFR2.750
ROUSE, L C Advanced Fuel & Spent Fuel Licensing Branch 82/10/27
CURTIS, N W Pennsylvania Power & Light Co 2pp 16605 181 24X
Fiche 50-387, 82/10/27, 8212290494

DOCKET 50-389 ST LUCIE PLANT, UNIT 2

A Application/construction stage documents & correspondence

B212010439 Summary of 820831-0903 instrument & control site audit
NERSES, V Licensing Branch 3 82/11/18 Licensing Branch 3
5pp 16267 280 24X Fiche 50-389, 82/11/18, 8212010439

B212090002 Notification of 821130 meeting w/util in Bethesda, MD to discuss status of plant const completion
NERSES, V Licensing Branch 3 82/11/22 KNIGHTON, G W Licensing Branch 3 3pp 16384 231 24X Fiche 50-389, 82/11/22, 8212090002

B212100260 Notices of Engineering Verification Program Review Committee 821215 meeting in Bethesda, MD to discuss resolution of remaining discrepancies from design review phase & review mail to be included in final design rept
CHRISTIAN, D L Florida Power & Light Co 82/12/07 EISENHUT, D O
Division of Licensing 2pp 16376 044 24X Fiche 50-389, 82/12/07, 8212100260

B212150129 Forwards resubmittal of "Mechanized Preservice Exam of Selected Components of St Lucie Plant, Unit 2" Attachment updates 821110 submittal which had missing pages
UHRIO, R E Florida Power & Light Co 82/12/07 EISENHUT, D O
Division of Licensing 1p 16423 004 24X Fiche 50-389, 82/12/07, 8212150129

--B212150134 Resubmittal of "Mechanized Preservice Exam of Selected Components of St Lucie Plant, Unit 2"
* Southwest Research Institute 82/07/31 234pp 16423 005
24X Fiche 50-389, 82/12/07, 8212150129

B212220153 Summary of 821130 meeting w/util in Bethesda, MD re status of plant const implementation schedule for fire protection hardware items not approved NRC will suggest submittal date for results of independent design review
NERSES, V Licensing Branch 3 82/12/08 Licensing Branch 3
4pp 16525 382 24X Fiche 50-389, 82/12/08, 8212220153

B212140373 Forwards revision to 821008 ltr re post-accident sampling sys Completion date will be changed from "Prior to Exceeding 5% Power" to "Prior to Initial Criticality"
UHRIO, R E Florida Power & Light Co 82/12/09 EISENHUT, D O
Division of Licensing 2pp 16401 006 24X Fiche 50-389, 82/12/09, 8212140373

B212140461 Forwards response to request for analysis of limited small feedwater line break w/assumption of single failure & availability of offsite power, to verify that sys pressures will not exceed 120% of design pressure
UHRIO, R E Florida Power & Light Co 82/12/09 EISENHUT, D O
Division of Licensing 24pp 16404 023 24X Fiche 50-389, 82/12/09, 8212140461

B212170269 Forwards responses to issues raised in Environ Qualification Branch review of program All safety-related equipment will be qualified per NUREG-0589 by first refueling
UHRIO, R E Florida Power & Light Co 82/12/09 EISENHUT, D O
Division of Licensing 314pp 16486 213 24X Fiche 50-389, 82/12/09, 8212170269

B212220200 Provides status of inadequate core cooling instrumentation package per THM Item 11 F 2 Sys will be fully operational by mid 1983 Mods to sys will be included in next revision to FSAR
UHRIO, R E Florida Power & Light Co 82/12/14 EISENHUT, D O
Division of Licensing 1p 16503 048 24X Fiche 50-389, 82/12/14, 8212220200

B212280333 Forwards minutes of 821209 meeting w/util & C-E task force managers in New York, NY re engineering verification program Results of onsite verification phases of program discussed
BLODGETT, T H Ebasco Services, Inc (subs of Enserch Corp)
82/12/22 EISENHUT, D O Division of Licensing 2pp 16560 090
24X Fiche 50-389, 82/12/22, 8212280333

B212280405 Forwards minutes of engineering verification program review committee 821215 final meeting in Bethesda, MD Task force disbanded as of 821217
BLODGETT, T H Ebasco Services, Inc (subs of Enserch Corp)
82/12/22 EISENHUT, D O Division of Licensing 2pp 16560 040
24X Fiche 50-389, 82/12/22, 8212280405

E NRC Safety Evaluation Report (SER), supp's & correspondence

B212090211 Forwards 1E Insp Rept 50-389/82-54 on 821101-05 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 82/11/19
UHRIO, R E Florida Power & Light Co 2pp 16361 336 24X
Fiche 50-389, 82/11/19, 8212090211

--B212090213 1E Insp Rept 50-389/82-54 on 821101-05 No noncompliance noted Major areas inspected preoperational test program implementation & SER confirmatory items
TAYLOR, P , KRUG, H , JAFFE, F Division of Engineering & Technical Programs 82/11/18 4pp 16361 338 24X Fiche 50-389, 82/11/19, 8212090211

B212210101 Forwards addl info re small feedwater line break analysis Info needed to close confirmatory issue addressed in Section 15 10 2 of SER
UHRIO, R E Florida Power & Light Co 82/12/14 EISENHUT, D O
Division of Licensing 19pp 16491 061 24X Fiche 50-389, 82/12/14, 8212210101

B212290265 Advises that satisfactory reactor protection sys power supply testing has been completed for ultra isolation transformers, per SER Suppl 1, Section 7 2 5 Acceptance criteria met
UHRIO, R E Florida Power & Light Co 82/12/22 EISENHUT, D O
Division of Licensing 2pp 16582 035 24X Fiche 50-389, 82/12/22, 8212290265

F Security, medical, emergency & fire protection plans

B212090268 Forwards 1E Insp Rept 50-389/82-47 on 821004-08 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 82/10/26
UHRIO, R E Florida Power & Light Co 2pp 16362 307 24X
Fiche 50-389, 82/10/26, 8212090268

--B212090275 1E Insp Rept 50-389/82-47 on 821004-08 No noncompliance noted Major areas inspected fire protection
MILLER, W H , CONLON, T E Division of Engineering & Technical Programs 82/10/22 5pp 16362 309 24X Fiche 50-389, 82/10/26, 8212090268

B212170408 Notification of 821214 meeting w/util in Bethesda, MD to review remaining licensing action re fire protection
NERSES, V Licensing Branch 3 82/12/07 KNIGHTON, G W Licensing Branch 3 3pp 16478 152 24X Fiche 50-389, 82/12/07, 8212170408

B212220153 Summary of 821130 meeting w/util in Bethesda, MD re status of plant const implementation schedule for fire protection hardware items not approved NRC will suggest submittal date for results of independent design review
NERSES, V Licensing Branch 3 82/12/08 Licensing Branch 3, 4pp 16525 382 24X Fiche 50-389, 82/12/08, 8212220153

J Insurance & indemnity information

B212300294 Forwards Endorsements 1, 2 & 3 to NELIA Certificate N-89 & MAELU Certificate M-39
DUCK, J R Marsh & McLennan, Inc , M & M Nuclear Consultants, Inc Div
82/12/27 SALTZMAN, J Assistant Director for State & License Relations 19pp 16594 271 24X Fiche 50-389, 82/12/27, 8212300294,

DOCKETED ITEMS

M Antitrust correspondence

8212010046 Informs that addl antitrust advice received from atty general No antitrust hearing necessary on proposed amend to CP per 821025 ltr
TOALSTON, A L Antitrust & Economic analysis Branch (Utility Finance) 82/11/16 UDALL, M K House of Rep, Interior & Insular Affairs 1p 16271 345 24X Fiche 50-389, 82/11/16, 8212010046

--8212010053 Advises that info submitted for antitrust review provides no basis to conclude that participation by util would create situation inconsistent w/antitrust laws No antitrust hearing necessary
BAXTER, W F Justice, Dept of 82/10/25 CUNNINGHAM, G H Office of the Executive Legal Director 1p 16271 346 24X Fiche 50-389, 82/11/16, 8212010046

8212010288 Ack receipt of encl assistant atty general 821025 ltr providing addl antitrust advice, per Atomic Energy Act of 1954, Section 105c No antitrust hearing necessary for proposed CP amend
TOALSTON, A L Antitrust & Economic analysis Branch (Utility Finance) 82/11/16 SIMPSON, A Senate, Environment & Public Works 1p 16271 268 24X Fiche 50-389, 82/11/16, 8212010288

--8212010290 Comments on proposed CP amend to allow util to become co-owner of facility No antitrust hearing necessary for proposed amend
BAXTER, W F Justice, Dept of, Attorney General's Office 82/10/25 CUNNINGHAM, G H Office of the Executive Legal Director 1p 16271 269 24X Fiche 50-389, 82/11/16, 8212010288

8212010299 Ack receipt of encl assistant atty general 821025 ltr providing addl antitrust advice, per Atomic Energy Act of 1954, Section 105c No antitrust hearing necessary for proposed CP amend
TOALSTON, A L Antitrust & Economic analysis Branch (Utility Finance) 82/11/16 OTTINGER, R L House of Rep, Energy & Commerce 1p 16271 277 24X Fiche 50-389, 82/11/16, 8212010299

8212010292 Forwards assistant atty general 821025 ltr providing addl antitrust advice, per Atomic Energy Act of 1954, Section 105c
TOALSTON, A L Antitrust & Economic analysis Branch (Utility Finance) 82/11/19 UHRIG, R E Florida Power & Light Co 1p 16271 270 24X Fiche 50-389, 82/11/19, 8212010292

Q Inspection reports, IE Bulletins & correspondence

8212090268 Forwards IE Insp Rept 50-389/82-47 on 821004-08 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 82/10/26 UHRIG, R E Florida Power & Light Co 2pp 16362 307 24X Fiche 50-389, 82/10/26, 8212090268

--8212090275 IE Insp Rept 50-389/82-47 on 821004-08 No noncompliance noted Major areas inspected fire protection
MILLER, W H, CONLON, T E Division of Engineering & Technical Programs 82/10/22 5pp 16362 309 24X Fiche 50-389, 82/10/26, 8212090268

8208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel Recirculation Sys Piping at BWR Plants " Svc list encl
BEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc. 112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240

8212090302 Forwards IE Insp Repts 50-335/82-35 & 50-389/82-50 on 821019-22 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 82/11/02 UHRIG, R E Florida Power & Light Co 2pp 16365 171 24X Fiche 50-335, 82/11/02, 8212090302

--8212090308 IE Insp Repts 50-335/82-35 & 50-389/82-50 on 821019-22 No noncompliance noted Major areas inspected IE Circular 81-08, previous insp findings & quality records for foundations
LEHAHAN, J J, CONLON, T E Division of Engineering & Technical Programs 82/11/01 4pp 16365 173 24X Fiche 50-335, 82/11/02, 8212090302

8212090331 Forwards IE Insp Rept 50-389/82-52 on 821019-22 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 82/11/02 UHRIG, R E Florida Power & Light Co 2pp 16365 091 24X Fiche 50-389, 82/11/02, 8212090331

--8212090336 IE Insp Rept 50-389/82-52 on 821019-22 No noncompliance noted Major areas inspected previous enforcement matters, reactor vessel installation, safety-related components, RCPB piping, safety-related piping & inspector followup items
KLEINSORGE, W P, BLAKE, J J Division of Engineering & Technical Programs 82/11/01 9pp 16365 093 24X Fiche 50-389, 82/11/02, 8212090331

8212090531 Forwards IE Insp Repts 50-335/82-32 & 50-389/82-44 on 820911-1010 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 82/11/02 UHRIG, R E Florida Power & Light Co 2pp 16367 001 24X Fiche 50-335, 82/11/02, 8212090531

--8212090537 IE Insp Repts 50-335/82-32 & 50-389/82-44 on 820911-1010 No noncompliance noted Major areas inspected maint & surveillance observation, operational safety verification, bulletins, circulars, info notices & preoperational testing
ELROD, S A, BIBB, H E, JULIAN, C A Division of Project & Resident Programs 82/11/02, 11pp 16367 003 24X Fiche 50-335, 82/11/02, 8212090531

8212090353 Forwards IE Insp Rept 50-389/82-51 on 821018-22 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 82/11/03 UHRIG, R E Florida Power & Light Co 2pp 16365 072 24X Fiche 50-389, 82/11/03, 8212090353

--8212090360 IE Insp Rept 50-389/82-51 on 821018-22 No noncompliance noted Major areas inspected preoperational test procedure review, witnessing & implementation, hot functional test witnessing & inspector followup items
TAYLOR, P A, JAPE, F Division of Engineering & Technical Programs 82/11/01 4pp 16365 074 24X Fiche 50-389, 82/11/03, 8212090353

8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model B01 & Model B02 Thermoluminescent Dosimeters " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000, 82/11/05, 8208190245

8212090404 Forwards IE Insp Rept 50-389/82-58 on 821025-29 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 82/11/09 UHRIG, R E Florida Power & Light Co 2pp 16365 001 24X Fiche 50-389, 82/11/09, 8212090404

--8212090411 IE Insp Rept 50-389/82-58 on 821025-29 No noncompliance noted Major areas inspected preoperational test procedure review & witnessing thermal expansion testing performed during initial plant startup
WHITENER, H L, JAPE, F Division of Engineering & Technical Programs 82/11/08 5pp 16365 003 24X Fiche 50-389, 82/11/09, 8212090404

8212090553 Ack receipt of 821103 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-335/82-29 & 50-389/82-39
DANCE, H C Division of Project & Resident Programs 82/11/17 UHRIG, R E Florida Power & Light Co 1p 16367 038 24X Fiche 50-335, 82/11/17, 8212090553

--8212090559 Responds to NRC 821005 ltr re violations noted in IE Insp Repts 50-335/82-29 & 50-389/82-39 Corrective actions clearance orders corrected & personnel re instructed re need to designate "locked open" or "locked closed" on orders
UHRIG, R E Florida Power & Light Co 82/11/03 O'REILLY, J P Region 2, Office of Director 2pp 16367 039 24X Fiche 50-335, 82/11/17, 8212090553

--8212090561 Forwards IE Insp Repts 50-335/82-29 & 50-389/82-29 on 820811-0910 & notice of violation
DANCE, H C Division of Project & Resident Programs 82/10/08 UHRIG, R E Florida Power & Light Co 2pp 16367 041 24X Fiche 50-335, 82/11/17, 8212090553

--8212090564 IE Insp Repts 50-335/82-29 & 50-389/82-39 on 820811-0910 Noncompliance noted failure to implement procedure for locking safety-related valves in required position
ELROD, S A, BIBB, H E, JULIAN, C A Division of Project & Resident Programs 82/10/04, 13pp 16367 044 24X Fiche 50-335, 82/11/17, 8212090553

8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X Fiche 50-000, 82/11/18, 8208190251

8212070211 Forwards IE Insp Rept 50-389/82-54 on 821101-05 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 82/11/19
UHRIG, R E Florida Power & Light Co 2pp 16361 336 24X
Fiche 50-389, 82/11/19, 8212070211

--8212070213 IE Insp Rept 50-389/82-54 on 821101-05 No noncompliance noted Major areas inspected preoperational test program implementation & SER confirmatory items
TAYLOR, P, KRUG, H, JAPE, F Division of Engineering & Technical Programs 82/11/18 4pp 16361 338 24X Fiche 50-389, 82/11/19, 8212070211

8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000, 82/11/26, 8208190256

8208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16397 028 24X Fiche 50-000, 82/11/30, 8208190257

8208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259

8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X Fiche 50-000, 82/12/03, 8208190261

8212150129 Forwards resubmittal of "Mechanized Preservice Exam of Selected Components of St Lucie Plant, Unit 2 " Attachment updates 821110 submittal which had missing pages
UHRIG, R E Florida Power & Light Co 82/12/07 EISENHUT, D O Division of Licensing 1p 16423 004 24X Fiche 50-389, 82/12/07, 8212150129

--8212150134 Resubmittal of "Mechanized Preservice Exam of Selected Components of St Lucie Plant, Unit 2 "
* Southwest Research Institute 82/07/31 234pp 16423 005 24X Fiche 50-389, 82/12/07, 8212150129

8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16, 8208190267

8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27 " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628-293 24X Fiche 50-000, 82/12/20, 8208190268

R Periodic operating reports & related correspondence

8212170243 Forwards Joint Ebasco & C-E Task Force engineering verification program status summary for 2-wk period, 821122-1204
BLONDOTT, T H Ebasco Services, Inc (subs of Enserch Corp) 82/12/09 EISENHUT, D O Division of Licensing 5pp 16461:292 24X Fiche 50-389, 82/12/09, 8212170243

8212280187 Forwards Joint Ebasco & C-E task force engineering verification program weekly status summary for 821213-17, BLONDOTT, T H Ebasco Services, Inc (subs of Enserch Corp) 82/12/21 EISENHUT, D O Division of Licensing 5pp 16562:256 24X Fiche 50-389, 82/12/21, 8212280187

S Reportable occurrences, LERs & related correspondence

8212030216 Interim deficiency rept re fan bolts on diesel generators 2A & 2B Initially reported on 820210 Addl mods needed to fully correct problem Final rept will be submitted by 830120
UHRIG, R E Florida Power & Light Co 82/11/24 O'REILLY, J P Region 2, Office of Director 1p 16306 295 24X Fiche 50-389, 82/11/24, 8212030216

8212070215 Interim deficiency rept re failure of reactor shutdown cooling bypass valves to respond to command signals Initially reported on 820630 Review continuing Next rept will be submitted by 830115
UHRIG, R E Florida Power & Light Co 82/11/29 O'REILLY, J P Region 2, Office of Director 1p 16329 359 24X Fiche 50-389, 82/11/29, 8212070215

8212090200 Suppl to 810724 final deficiency rept re local control switches supplied by Gould Rundel Re-evaluation of switch protruberance indicated deficiency only in 8B-6 switches
UHRIG, R E Florida Power & Light Co 82/12/01 O'REILLY, J P Region 2, Office of Director 1p 16362 360 24X Fiche 50-389, 82/12/01, 8212090200

8212150074 Final Deficiency Rept 82-021 re incorrect reactor protective sys low flow input signals Initially reported on 821013 Wiring diagram & polarity of input signal cables corrected Deficiency not reportable per 10CFR50.55(e)
UHRIG, R E Florida Power & Light Co 82/12/09 O'REILLY, J P Region 2, Office of Director 2pp 16431 013 24X Fiche 50-389, 82/12/09, 8212150074

8212150098 Final Deficiency Rept 82-024 re defective masonry walls Initially reported on 821110 During insp of as-built masonry walls, 31 contained less than required amount of rebar due to design misinterpretation Walls will be modified
UHRIG, R E Florida Power & Light Co 82/12/09 O'REILLY, J P Region 2, Office of Director 2pp 16425 242 24X Fiche 50-389, 82/12/09, 8212150098

8212210348 Interim deficiency rept re insulation on Conax ring tongue connectors Initially reported on 821110 Investigation continuing Final rept will be submitted by 821228
UHRIG, R E Florida Power & Light Co 82/12/10 O'REILLY, J P Region 2, Office of Director 1p 16496 362 24X Fiche 50-389, 82/12/10, 8212210348

8212210354 Interim deficiency rept re micro-switch PTK selector switches Initially reported on 821110 Review continuing final rept will be submitted by 830110
UHRIG, R E Florida Power & Light Co 82/12/10 O'REILLY, J P Region 2, Office of Director 1p 16489 175 24X Fiche 50-389, 82/12/10, 8212210354

8212300252 Interim deficiency rept re lack of documentation on Class 1 & II bolts & nuts Initially reported on 821013 Final rept will be submitted by 830126
UHRIG, R E Florida Power & Light Co 82/12/20 O'REILLY, J P Region 2, Office of Director 1p 16595 234 24X Fiche 50-389, 82/12/20, 8212300252

U Congressional/Executive Correspondence

8212010046 Informs that addl antitrust advice received from atty general No antitrust hearing necessary on proposed amend to CP per 821025 ltr
TOALSTON, A L Antitrust & Economic analysis Branch (Utility Finance) 82/11/16 UDALL, M K House of Rep, Interior & Insular Affairs 1p 16271 345 24X Fiche 50-389, 82/11/16, 8212010046

DOCKET 50-390 WATTS BAR NUCLEAR PLANT, UNIT 1

A Application/construction stage documents & correspondence

8212010117 Notifies that no requests received from public for hearing on extension of const completion dates
KENYON, T J Licensing Branch 4 82/11/19 NOVAK, T M Assistant Director for Licensing 1p 16290 230 24X Fiche 50-390, 82/11/19, 8212010117

--8212010122 Notifies of extension of const completion dates to 840301 & 850801 for Units 1 & 2, respectively Order & safety evaluation encl
ADENHAM, E O Licensing Branch 4. 82/11/19 PARRIS, H O Tennessee Valley Authority 1p 16290 231 24X Fiche 50-390, 82/11/19, 8212010117

--8212010126 Order extending const completion dates for Units 1 & 2 to 840301 & 850801, respectively.
EISENHUT, D O Division of Licensing. 82/11/19 Tennessee Valley Authority 2pp 16290 232 24X Fiche 50-390, 82/11/19, 8212010117

--8212010129 Safety evaluation supporting request for extension of CPPR-91 & CPPR-92 to 840301 & 850801, respectively Extension acceptable
* Division of Licensing 82/11/19 5pp 16290 234 24X Fiche 50-390, 82/11/19, 8212010117

DOCKETED ITEMS

8212060081 Submits revised milestone schedules of prompt notification sys for design, const & field testing finish & inservice testing State of TN assumes sys on 830701
MILLS, L M Tennessee Valley Authority 82/11/30 ADENSAH, E
Licensing Branch 4 1p 16316 107 24X Fiche 50-390, 82/11/30, 8212060081

8212070291 Responds to action items resulting from NRC 820922 geotechnical audit of plant Util action complete w/exception of analysis of axial stresses on buried pipe which will be provided by 830305
MILLS, L M Tennessee Valley Authority 82/11/30 ADENSAH, E
Licensing Branch 4 44pp 16339 020 24X Fiche 50-390, 82/11/30, 8212070291

8212070072 Requests addl info re 820514 submittal on Branch Technical Position CSB 4-4, "Containment Purging During Normal Plant Operation" Info needed by 830115
ADENSAH, E G Licensing Branch 4 82/12/01 PARRIS, H G Tennessee Valley Authority 3pp 16356 274 24X Fiche 50-390, 82/12/01, 8212070072

8212070186 Forwards addl info to resolve concerns listed in NRC 820923 ltr re Apr 1982 seismic qualification review team audit
MILLS, L M Tennessee Valley Authority 82/12/01 ADENSAH, E
Licensing Branch 4 127pp 16335 131 24X Fiche 50-390, 82/12/01, 8212070186

8212270287 Forwards "Liquefaction Evaluation of Essential Raw Cooling Water Pipeline Route Task 9," per LM Mills 821116 ltr
KAHMER, D S Tennessee Valley Authority 82/12/09 ADENSAH, E
Licensing Branch 4 1p 16565 145 24X Fiche 50-390, 82/12/09, 8212270287

--8212270290 "Liquefaction Evaluation of Essential Raw Cooling Water Pipeline Route Task 9" w/seven oversize figures Aperture cards are available in PDR
Woodward-Clyde Consultants, Inc 82/11/30 79pp 16565 146 24X Fiche 50-390, 82/12/09, 8212270287

8212270262 Provides info to facilitate NRC use of computer card deck containing time histories of four artificial earthquakes used for facility
MILLS, L M Tennessee Valley Authority 82/12/20 ADENSAH, E
Licensing Branch 4 2pp 16530 330 24X Fiche 50-390, 82/12/20, 8212270262

8212270355 Forwards status rept on proposed mods to model D steam generators to reduce flow-induced vibration & tube wear problems Rept specifying final resolution of issue will be provided in Jan 1983
MILLS, L M Tennessee Valley Authority 82/12/20 ADENSAH, E
Licensing Branch 4 2pp 16530 044 24X Fiche 50-390, 82/12/20, 8212270355

E NRC Safety Evaluation Report (SER), suppl's & correspondence

8212060070 Forwards response to SER open item 13 re quality classification of diesel generator auxiliary sys piping & components
MILLS, L M Tennessee Valley Authority 82/11/29 ADENSAH, E
Licensing Branch 4 3pp 16314 296 24X Fiche 50-390, 82/11/29, 8212060070

8212210451 Forwards response to 820419 request for addl info. Questions 40 127 & 40 128 re diesel generators Info to resolve SER Open item 14 re diesel generator operation w/o secondary coolant & expansion tank location also encl
MILLS, L M Tennessee Valley Authority 82/12/14 ADENSAH, E
Licensing Branch 4 11pp 16489 181 24X Fiche 50-390, 82/12/14, 8212210451

F Security, medical, emergency & fire protection plans

8212100046 Responds to R Heron 811202 telcon request re emergency operations facility (EOF) Response to Generic Ltr 81-10 on 810602 describes util plans to utilize central emergency response ctr Project-specific details to be provided
KAHMER, D S Tennessee Valley Authority 82/12/06 ADENSAH, E
Licensing Branch 4 1p 16379 071 24X Fiche 50-000, 82/12/06, 8212100046

J Insurance & indemnity information

8212020269 Submits info re const & warehouse values located offsite as result of revised site descriptions under ANI/MAELU nuclear liability insurance facility form policies
DUCK, J R Marsh & McLennan, Inc, M & M Nuclear Consultants, Inc Div 82/11/18 HAINES, H L American Nuclear Insurers 1p 16288:356, 24X Fiche 50-000, 82/11/18, 8212020269

G Inspection reports, IE Bulletins & correspondence

8208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants" Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240

8212090400 Forwards IE Insp Repts 50-390/82-36 & 50-391/82-33 on 821012-15 No noncompliance noted
VERRELLI, D M Division of Project & Resident Programs 82/11/01 PARRIS, H G Tennessee Valley Authority 2pp 16364 256 24X Fiche 50-390, 82/11/01, 8212090400

--8212090407 IE Insp Repts 50-390/82-36 & 50-391/82-33 on 821012-15 No noncompliance noted Major areas inspected electrical cables & terminations, licensee identified items & independent insp
GIBSON, T D, CONLON, T E Division of Engineering & Technical Programs 82/10/29 3pp 16364 258 24X Fiche 50-390, 82/11/01, 8212090400

8212090497 Forwards IE Insp Repts 50-390/82-37 & 50-391/82-34 on 820923-1019 No noncompliance noted
VERRELLI, D M Division of Project & Resident Programs 82/11/03 PARRIS, H G Tennessee Valley Authority 2pp 16365 335 24X Fiche 50-390, 82/11/03, 8212090497

--8212090504 IE Insp Repts 50-390/82-37 & 50-391/82-34 on 820923-1019 No noncompliance noted Major areas inspected licensee action on previous insp findings, independent insp effort, followup on licensee identified items & worker allegations
HEATHERLY, T L, GUICK, D R Division of Project & Resident Programs 82/11/03 7pp 16365 337 24X Fiche 50-390, 82/11/03, 8212090497

8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model B01 & Model B02 Thermoluminescent Dosimeters" Svc list encl
CORR, L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000, 82/11/05, 8208190245

8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements" Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X Fiche 50-000, 82/11/18, 8208190251

8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks" Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000, 82/11/26, 8208190256

8212090334 Ack receipt of 821118 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-390/81-26 & 50-391/81-24
VERRELLI, D M Division of Project & Resident Programs 82/11/29 PARRIS, H G Tennessee Valley Authority 1p 16365 087 24X Fiche 50-390, 82/11/29, 8212090334

--8212090347 Submits supplemental response to NRC 811223 ltr re violations noted in IE Insp Repts 50-390/81-26 & 50-391/81-24 Corrective actions assessment of cleanliness of HVAC sys should be completed by 830201
MILLS, L M Tennessee Valley Authority 82/11/18 O'REILLY, J P Region 2, Office of Director 1p 16365 090 24X Fiche 50-390, 82/11/29, 8212090334

8208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl" Svc list encl
CORR, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000, 82/11/30, 8208190257

8208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies" Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259

8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets" Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X Fiche 50-000, 82/12/03, 8208190261

DOCKETED ITEMS

265

8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16, 8208190267

8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27 " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X Fiche 50-000, 82/12/20, 8208190268

R Periodic operating reports & related correspondence

8212030071 Forwards central emergency control ctr meteorological data availability statistics for Apr-Sept 1982
MILLS, L M Tennessee Valley Authority 82/11/30 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 16304 210 24X Fiche 50-000, 82/11/30, 8212030071

S Reportable occurrences, LERs & related correspondence

8212020298 First combined interim deficiency rept re nonconformance in alternately analyzed piping program Util proceeding w/100% reverification of alternate Analyses Next rept will be submitted by 830426
MILLS, L M Tennessee Valley Authority 82/11/24 O'REILLY, J P Region 2, Office of Director 3pp 16277 354 24X Fiche 50-390, 82/11/24, 8212020298

8212020368 Final deficiency rept re unterminated cables associated w/control room isolation function of control bldg ventilation sys Initially reported on 820901 Cables terminated & inspected per as-constructed drawings
MILLS, L M Tennessee Valley Authority 82/11/24 O'REILLY, J P Region 2, Office of Director 3pp 16278 142 24X Fiche 50-390, 82/11/24, 8212020368

8212030001 First interim deficiency rept re easily bent heat collecting fins & corroding sprinkler heads in fire suppression sys Initially reported on 821026 Proposed disposition to replace Star Model GE sprinkler heads under review
MILLS, L M Tennessee Valley Authority 82/11/29 O'REILLY, J P Region 2, Office of Director 2pp 16304 212 24X Fiche 50-000, 82/11/29, 8212030001

8212070058 Second interim deficiency rept re attachment of conduit & piping supports to cable tray supports Initially reported on 820607 Sampling program still being conducted Next rept expected by 830223
MILLS, L M Tennessee Valley Authority 82/11/29 O'REILLY, J P Region 2, Office of Director 1p 16327 335 24X Fiche 50-390, 82/11/29, 8212070058

8212070142 Sixth interim deficiency rept re diesel generator room exhaust fan mod Initially reported on 810831 Design mod in progress to provide structural stiffeners to reduce lateral vibration of fans Next rept will be submitted by 830225
MILLS, L M Tennessee Valley Authority 82/11/29 O'REILLY, J P Region 2, Office of Director 1p 16327 073 24X Fiche 50-390, 82/11/29, 8212070142

8212070267 Final deficiency rept re unauthorized conduit & cable rework Initially reported on 821015 Procedure WBNP-GCI-1 07 revised to clarify requirements when immediate documentation required for rework
MILLS, L M Tennessee Valley Authority 82/11/29 O'REILLY, J P Region 2, Office of Director 2pp 16339 071 24X Fiche 50-390, 82/11/29, 8212070267

8212090140 Third interim deficiency rept re incorrect seismic displacements & response spectra use Initially reported on 820430 Problems reanalyzed to determine final effect on piping & nozzle No other displacement errors occurred
MILLS, L M Tennessee Valley Authority 82/11/30 O'REILLY, J P Region 2, Office of Director 2pp 16359 246 24X Fiche 50-390, 82/11/30, 8212090140

8212090165 First interim deficiency rept re control of non-GA hex nuts Initially reported on 821021 Unqualified hex nuts used to install some hangers on safety-related upper head injection sys Investigation continuing
MILLS, L M Tennessee Valley Authority 82/11/30 O'REILLY, J P Region 2, Office of Director 2pp 16359 244 24X Fiche 50-390, 82/11/30, 8212090165

8212090170 First interim deficiency rept re curtain-type fire dampers failing to close against normal operating air flow Initially reported on 821025 Std Spec MED-SS-10 3 revised to include stainless negator closer springs
MILLS, L M Tennessee Valley Authority 82/11/30 O'REILLY, J P Region 2, Office of Director 2pp 16359 232 24X Fiche 50-390, 82/11/30, 8212090170

8212090341 Fourth interim rept re containment spray miniflow valve design error Initially reported on 820305 Possible breakdown in Westinghouse QA diagram being reviewed Also reportable per Part 21 Next rept expected by 830502
MILLS, L M Tennessee Valley Authority 82/12/01 O'REILLY, J P Region 2, Office of Director 2pp 16366 338 24X Fiche 50-390, 82/12/01, 8212090341

8212090054 Fourth interim deficiency rept re excessive movement of containment penetration bellows Initially reported on 811204 Problem being reanalyzed incorporating correct operating temps Next rept to be submitted on 830520
MILLS, L M Tennessee Valley Authority 82/12/02 O'REILLY, J P Region 2, Office of Director 2pp 16357 346 24X Fiche 50-390, 82/12/02, 8212090054

8212090150 Tenth interim deficiency rept re improper design of steel containment penetration assemblies Initially reported on 801219 All affected piping evaluated & reanalyzed Piping can withstand extra pressures Next rept expected by 830318
MILLS, L M Tennessee Valley Authority 82/12/03 O'REILLY, J P Region 2, Office of Director 2pp 16359 119 24X Fiche 50-390, 82/12/03, 8212090150

8212100270 Fifth interim deficiency rept re lack of Div of Engineering design sys to ensure QA procedures issued before work begins Initially reported on 811020 Final rept will not be submitted until decision made on deferral of projects
MILLS, L M Tennessee Valley Authority 82/12/06 O'REILLY, J P Region 2, Office of Director 1p 16377 136 24X Fiche 50-000, 82/12/06, 8212100270

8212140087 Fifth interim deficiency rept re incorrect thermal range analysis Initially reported on 821022 Upon closure of Engineering Change Notice 3210, support mod will be evaluated Next rept expected by 830527
MILLS, L M Tennessee Valley Authority 82/12/06 O'REILLY, J P Region 2, Office of Director 1p 16408 255 24X Fiche 50-390, 82/12/06, 8212140087

8212140141 First interim deficiency rept re Henry Pratt pneumatic butterfly valve actuator yoke failure Initially reported on 821109 Valves will be modified on site Next rept due 830607 Also reportable per Part 21
MILLS, L M Tennessee Valley Authority 82/12/07 O'REILLY, J P Region 2, Office of Director 3pp 16408 166 24X Fiche 50-000, 82/12/07, 8212140141

8212140164 Second interim deficiency rept re heat loss from Power Bys diesels Initially reported on 820729 Evaluation of heat load test results underway to determine needed changes Next rept due by 830322 Also reportable per Part 21
MILLS, L M Tennessee Valley Authority 82/12/07 O'REILLY, J P Region 2, Office of Director 2pp 16409 344 24X Fiche 50-390, 82/12/07, 8212140164

8212140376 Final deficiency rept re anchor bolts not installed in accordance w/spacing specs. Initially reported on 810331 Condition could not have adversely affected safe operation of plant Condition not reportable under 10CFR50.55(e)
MILLS, L M Tennessee Valley Authority 82/12/07 O'REILLY, J P Region 2, Office of Director 2pp 16403 157 24X Fiche 50-390, 82/12/07, 8212140376

8212150136 Second interim deficiency rept re inadequate QA program for masonry block work Initially reported on 820902 Areas where mortar did not meet min compressive strength requirements acceptable Next rept due by 830225
MILLS, L M Tennessee Valley Authority 82/12/09 O'REILLY, J P Region 2, Office of Director 2pp 16425 238 24X Fiche 50-390, 82/12/09, 8212150136

8212200001 Third interim deficiency rept re generic deficiency in design review Initially reported on 811215 No addl info available until action team 821215 rept Next rept will be submitted by 830420
MILLS, L M Tennessee Valley Authority 82/12/13 O'REILLY, J P Region 2, Office of Director 1p 16473 362 24X Fiche 50-000, 82/12/13, 8212200001

8212200017 Fifth interim deficiency rept re design review process interface coordination activity Initially reported on 810717 Corrective action to be based on action team rept to be issued approx 821215 Next rept expected by 830422
MILLS, L M Tennessee Valley Authority 82/12/13 O'REILLY, J P Region 2, Office of Director 2pp 16473 085 24X Fiche 50-000, 82/12/13, 8212200017

8212210356 Fourth interim deficiency rept re design of HVAC penetrations in containment Initially reported on 811224 Penetrations determined to be overstressed will be supported by hangers or stiffened Next rept expected by 830325
MILLS, L M Tennessee Valley Authority 82/12/13 O'REILLY, J P Region 2, Office of Director 1p 16493 171 24X Fiche 50-390, 82/12/13, 8212210356

DOCKETED ITEMS

8212210445 Second final deficiency rept re improper weld attachment of shear lugs initially reported on 801030 New Hanger installation procedure implemented Remaining corrective action on welds will be completed by 830301
MILLS, L M Tennessee Valley Authority 82/12/13 O'REILLY, J P
Region 2, Office of Director 3pp 16489 197 24X
Fiche 50-390, 82/12/13, 8212210445

8212210026 Fourth interim deficiency rept re potentially overstressed embedded plates Initially reported on 820412 Multiple supports attached to plates w/o design review of plate capacity Preliminary const spec issued Next rept by 830404
MILLS, L M Tennessee Valley Authority 82/12/14 O'REILLY, J P
Region 2, Office of Director 3pp 16485 260 24X
Fiche 50-000, 82/12/14, 8212210026

8212210217 Second interim deficiency rept re incorrect supports in analysis of 3-inch chemical & vol control sys line Initially reported on 820505 in-line isolation valves reanalyzed Next rept expected by 830520
MILLS, L M Tennessee Valley Authority 82/12/15 O'REILLY, J P
Region 2, Office of Director 3pp 16485 014 24X
Fiche 50-390, 82/12/15, 8212210217

8212210431 Fourth interim deficiency rept re resolution of unanticipated vibratory loading concerns Initially reported on 820120 Const activities for Yellow Creek & Hartsville deferred Next rept will be sent by 830322
MILLS, L M Tennessee Valley Authority 82/12/15 O'REILLY, J P
Region 2, Office of Director 3pp 16489 168 24X
Fiche 50-000, 82/12/15, 8212210431

8212220485 Second interim deficiency rept re solid state protection sys test procedures Initially reported on 820831 Westinghouse proposal for procedural change rejected Util will implement own change Also reportable per Part 21
MILLS, L M Tennessee Valley Authority 82/12/16 O'REILLY, J P
Region 2, Office of Director 3pp 16504 015 24X
Fiche 50-390, 82/12/16, 8212220485

8212220426 Seventh interim deficiency rept re rerouting of high pressure fire protection piping Initially reported on 810130 Increasing pipe head diameter to next largest size would eliminate deficiency Next rept due by 830622
MILLS, L M Tennessee Valley Authority 82/12/17 O'REILLY, J P
Region 2, Office of Director 3pp 16503 287 24X
Fiche 50-390, 82/12/17, 8212220426

8212280355 Second interim deficiency rept re unistrut clamps loaded in more than one direction for seismic supports Initially reported on 820708 Investigation continuing Next rept will be provided by 830211
MILLS, L M Tennessee Valley Authority 82/12/21 O'REILLY, J P
Region 2, Office of Director 3pp 16560 100 24X
Fiche 50-390, 82/12/21, 8212280355

DOCKET 50-391 WATTS BAR NUCLEAR PLANT, UNIT 2

A Application/construction stage documents & correspondence

8212010117 Notifies that no requests received from public for hearing on extension of const completion dates
KENYON, T J Licensing Branch 4 82/11/19 NOVAK, T M Assistant
Director for Licensing 1p 16290 230 24X Fiche 50-390, 82/11/19, 8212010117

--8212010122 Notifies of extension of const completion dates to 840301 & 850801 for Units 1 & 2, respectively Order & safety evaluation encl
ADENSAM, E O Licensing Branch 4 82/11/19 PARRIS, H O
Tennessee Valley Authority 1p 16290 231 24X
Fiche 50-390, 82/11/19, 8212010117

--8212010126 Order extending const completion dates for Units 1 & 2 to 840301 & 850801, respectively
EISENHUT, D O Division of Licensing 82/11/19 Tennessee
Valley Authority 2pp 16290 232 24X Fiche 50-390, 82/11/19, 8212010117

--8212010129 Safety evaluation supporting request for extension of CPPR-91 & CPPR-92 to 840301 & 850801, respectively Extension acceptable
* Division of Licensing 82/11/19 5pp 16290 234 24X
Fiche 50-390, 82/11/19, 8212010117

8212060081 Submits revised milestone schedules of prompt notification sys for design, const & field testing finish & inservice testing State of TN assumes sys on 830701
MILLS, L M Tennessee Valley Authority 82/11/30 ADENSAM, E
Licensing Branch 4 1p 16316 107 24X Fiche 50-390, 82/11/30, 8212060081

8212070291 Responds to action items resulting from NRC 820922 geotechnical audit of plant Util action complete w/exception of analysis of axial stresses on buried pipe which will be provided by 830305
MILLS, L M Tennessee Valley Authority 82/11/30 ADENSAM, E
Licensing Branch 4 44pp 16339 020 24X Fiche 50-390, 82/11/30, 8212070291

8212070072 Requests addl info re 820514 submittal on Branch Technical Position CSB 4-4, "Containment Purging During Normal Plant Operation" Info needed by 830115
ADENSAM, E O Licensing Branch 4 82/12/01 PARRIS, H O Tennessee
Valley Authority 3pp 16356 274 24X Fiche 50-390, 82/12/01, 8212070072

8212070186 Forwards addl info to resolve concerns listed in NRC 820923 ltr re Apr 1982 seismic qualification review team audit
MILLS, L M Tennessee Valley Authority 82/12/01 ADENSAM, E
Licensing Branch 4 127pp 16335 131 24X Fiche 50-390, 82/12/01, 8212070186

8212270287 Forwards "Liquefaction Evaluation of Essential Raw Cooling Water Pipelining Route Task 9," per LM Mills 821116 ltr
KAMMER, D S Tennessee Valley Authority 82/12/09 ADENSAM, E
Licensing Branch 4 1p 16565 145 24X Fiche 50-390, 82/12/09, 8212270287

--8212270290 "Liquefaction Evaluation of Essential Raw Cooling Water Pipelining Route Task 9" w/seven oversize figures Aperture cards are available in PDR
* Woodward-Clyde Consultants, Inc 82/11/30 79pp 16565 146 24X Fiche 50-390, 82/12/09, 8212270287

8212270262 Provides info to facilitate NRC use of computer card deck containing time histories of four artificial earthquakes used for facility
MILLS, L M Tennessee Valley Authority 82/12/20 ADENSAM, E
Licensing Branch 4 2pp 16530 330 24X Fiche 50-390, 82/12/20, 8212270262

8212270355 Forwards status rept on proposed mods to model D steam generators to reduce flow-induced vibration & tube wear problems Rept specifying final resolution of issue will be provided in Jan 1983
MILLS, L M Tennessee Valley Authority 82/12/20 ADENSAM, E
Licensing Branch 4 2pp 16530 044 24X Fiche 50-390, 82/12/20, 8212270355

E NRC Safety Evaluation Report (SER), supp & correspondence

8212060070 Forwards response to SER open item 13 re quality classification of diesel generator auxiliary sys piping & components
MILLS, L M Tennessee Valley Authority 82/11/29 ADENSAM, E
Licensing Branch 4 3pp 16314 296 24X Fiche 50-390, 82/11/29, 8212060070

8212210451 Forwards response to 820419 request for addl info, Questions 40 127 & 40 128, re diesel generators info to resolve SER Open item 14 re diesel generator operation w/o secondary coolant & expansion tank location also encl
MILLS, L M Tennessee Valley Authority 82/12/14 ADENSAM, E
Licensing Branch 4 11pp 16489 181 24X Fiche 50-390, 82/12/14, 8212210451

F Security, medical, emergency & fire protection plans

8212100046 Responds to R Heron 811202 telcon request re emergency operations facility (EOF) Response to Generic Ltr 81-10 on 810602 describes util plans to utilize central emergency response ctr Project-specific details to be provided
KAMMER, D S Tennessee Valley Authority 82/12/06 ADENSAM, E
Licensing Branch 4 1p 16379 071 24X Fiche 50-000, 82/12/06, 8212100046

J Insurance & indemnity information

8212020269 Submits info re const & warehouse values located offsite as result of revised site descriptions under ANI/MAELU nuclear liability insurance facility form policies
DUCK, J R Marsh & McLennan, Inc, M & M Nuclear Consultants, Inc Div
82/11/18 HAINES, H L American Nuclear Insurers 1p 16288 356 24X Fiche 50-000, 82/11/18, 8212020269

Q Inspection reports, IE Bulletins & correspondence

8208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BHR Plants " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240

8212090400 Forwards IE Insp Repts 50-390/82-36 & 50-391/82-33 on 821012-15 No noncompliance noted
VERRELLI, D M Division of Project & Resident Programs 82/11/01
PARRIS, H Q Tennessee Valley Authority 2pp 16364 256 24X Fiche 50-390, 82/11/01, 8212090400

--8212090407 IE Insp Repts 50-390/82-36 & 50-391/82-33 on 821012-15 No noncompliance noted Major areas inspected electrical cables & terminations, licensee identified items & independent insp
GIBBONS, T D, CONLON, T E Division of Engineering & Technical Programs 82/10/29 3pp 16364 258 24X Fiche 50-390, 82/11/01, 8212090400

8212090497 Forwards IE Insp Repts 50-390/82-37 & 50-391/82-34 on 820923-1019 No noncompliance noted
VERRELLI, D M Division of Project & Resident Programs 82/11/03
PARRIS, H Q Tennessee Valley Authority 2pp 16365 335 24X Fiche 50-390, 82/11/03, 8212090497

--8212090504 IE Insp Repts 50-390/82-37 & 50-391/82-34 on 820923-1019 No noncompliance noted Major areas inspected licensee action on previous insp findings, independent insp effort, followup on licensee identified items & worker allegations
HEATHERLY, T L, QUICK, D R Division of Project & Resident Programs 82/11/03 7pp 16365 337 24X Fiche 50-390, 82/11/03, 8212090497

8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000, 82/11/05, 8208190245

8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X Fiche 50-000, 82/11/18, 8208190251

8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 045 24X Fiche 50-000, 82/11/26, 8208190256

8212090334 Ack receipt of 821118 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-390/81-26 & 50-391/81-24
VERRELLI, D M Division of Project & Resident Programs 82/11/29
PARRIS, H Q Tennessee Valley Authority 1p 16365 089 24X Fiche 50-390, 82/11/29, 8212090334

--8212090347 Submits supplemental response to NRC 811223 ltr re violations noted in IE Insp Repts 50-390/81-26 & 50-391/81-24 Corrective actions assessment of cleanliness of HVAC sys should be completed by 830201
MILLS, L M Tennessee Valley Authority 82/11/18 O'REILLY, J P Region 2, Office of Director 1p 16365 090 24X Fiche 50-390, 82/11/29, 8212090334

8208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000, 82/11/30, 8208190257

8208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259

8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X Fiche 50-000, 82/12/03, 8208190261

8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16, 8208190267

8212210360 Forwards "ASME Section XI Preservice Insp Program Technical Instruction T1-50B," Revision 3
MILLS, L M Tennessee Valley Authority 82/12/16 ADENBAM, E Licensing Branch 4 1p 16495 172 24X Fiche 50-391, 82/12/16, 8212210360

--8212210363 Surveillance Instruction T1-50B, "ASME Section XI Preservice Insp Program," Revision 3
DETULLIO, D, SWALLOW, J M Tennessee Valley Authority 82/11/03 126pp 16495 173 24X Fiche 50-391, 82/12/16, 8212210360

8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27 " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X Fiche 50-000, 82/12/20, 8208190268

R Periodic operating reports & related correspondence

8212030071 Forwards central emergency control ctr meteorological data availability statistics for Apr-Sept 1982
MILLS, L M Tennessee Valley Authority 82/11/30 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 16304 210 24X Fiche 50-000, 82/11/30, 8212030071

S Reportable occurrences, LERs & related correspondence

8212020278 First combined interim deficiency rept re nonconformance in alternately analyzed piping program Util proceeding w/100% reverification of alternate analyses Next rept will be submitted by 830426
MILLS, L M Tennessee Valley Authority 82/11/24 O'REILLY, J P Region 2, Office of Director 3pp 16277 354 24X Fiche 50-390, 82/11/24, 8212020278

8212020368 Final deficiency rept re unterminated cables associated w/control room isolation function of control bldg ventilation sys Initially reported on 820901 Cables terminated & inspected per as-constructed drawings
MILLS, L M Tennessee Valley Authority 82/11/24 O'REILLY, J P Region 2, Office of Director 3pp 16278 142 24X Fiche 50-390, 82/11/24, 8212020368

8212030001 First interim deficiency rept re easily bent heat collecting fins & corroding sprinkler heads in fire suppression sys Initially reported on 821026 Proposed disposition to replace Star Model OE sprinkler heads under review
MILLS, L M Tennessee Valley Authority 82/11/29 O'REILLY, J P Region 2, Office of Director 2pp 16304 212 24X Fiche 50-000, 82/11/29, 8212030001

8212070058 Second interim deficiency rept re attachment of conduit & piping supports to cable tray supports Initially reported on 820607 Sampling program still being conducted Next rept expected by 830223
MILLS, L M Tennessee Valley Authority 82/11/29 O'REILLY, J P Region 2, Office of Director 1p 16327 355 24X Fiche 50-390, 82/11/29, 8212070058

8212070142 Sixth interim deficiency rept re diesel generator room exhaust fan mod Initially reported on 810831 Design mod in progress to provide structural stiffeners to reduce lateral vibration of fans Next rept will be submitted by 830225
MILLS, L M Tennessee Valley Authority 82/11/29 O'REILLY, J P Region 2, Office of Director 1p 16327 073 24X Fiche 50-390, 82/11/29, 8212070142

8212090160 Third interim deficiency rept re incorrect seismic displacements & response spectra use Initially reported on 820430 Problems reanalyzed to determine final effect on piping & nozzle No other displacement errors occurred
MILLS, L M Tennessee Valley Authority 82/11/30 O'REILLY, J P Region 2, Office of Director 2pp 16359 246 24X Fiche 50-390, 82/11/30, 8212090160

8212090170 First interim deficiency rept re curtain-type fire dampers failing to close against normal operating air flow Initially reported on 821025 Std Spec MEB-88-10 3 revised to include stainless negator closer springs
MILLS, L M Tennessee Valley Authority 82/11/30 O'REILLY, J P Region 2, Office of Director 2pp 16359 232 24X Fiche 50-390, 82/11/30, 8212090170

8212090541 Fourth interim rept re containment spray miniflow valve design error Initially reported on 820303 Possible breakdown in Westinghouse QA diagram being reviewed Also reportable per Part 21 Next rept expected by 830502
MILLS,L M Tennessee Valley Authority 82/12/01 O'REILLY, J P
Region 2, Office of Director 2pp 16366 338 24X
Fiche 50-390, 82/12/01, 8212090541

8212090054 Fourth interim deficiency rept re excessive movement of containment penetration bellows Initially reported on 811004 Problem being reanalyzed incorporating correct operating temps Next rept to be submitted on 830520
MILLS,L M Tennessee Valley Authority 82/12/02 O'REILLY, J P
Region 2, Office of Director 2pp 16357 346 24X
Fiche 50-390, 82/12/02, 8212090054

8212090190 Tenth interim deficiency rept re improper design of steel containment penetration assemblies Initially reported on 801219 All affected piping evaluated & reanalyzed Piping can withstand extra pressures Next rept expected by 830318
MILLS,L M Tennessee Valley Authority 82/12/03 O'REILLY, J P
Region 2, Office of Director 2pp 16359 119 24X
Fiche 50-390, 82/12/03, 8212090190

8212100270 Fifth interim deficiency rept re lack of Div of Engineering design sys to ensure QA procedures issued before work begins Initially reported on 811020 Final rept will not be submitted until decision made on deferral of projects
MILLS,L M Tennessee Valley Authority 82/12/04 O'REILLY, J P
Region 2, Office of Director 1p 16377 136 24X
Fiche 50-000, 82/12/05, 8212100270

8212140087 Fifth interim deficiency rept re incorrect thermal range analysis Initially reported on 821022 Upon closure of Engineering Change Notice 3210, support mod will be evaluated Next rept expected by 830527
MILLS,L M Tennessee Valley Authority 82/12/06 O'REILLY, J P
Region 2, Office of Director 1p 16408 255 24X
Fiche 50-390, 82/12/06, 8212140087

8212140141 First interim deficiency rept re Henry Pratt pneumatic butterfly valve actuator yoke failure Initially reported on 821109 Valves will be modified on site Next rept due 830607 Also reportable per Part 21
MILLS,L M Tennessee Valley Authority 82/12/07 O'REILLY, J P
Region 2, Office of Director 3pp 16408 166 24X
Fiche 50-000, 82/12/07, 8212140141

8212140164 Second interim deficiency rept re heat loss from Power Sys diesel Initially reported on 820729 Evaluation of heat load test results underway to determine needed changes Next rept due by 830322 Also reportable per Part 21
MILLS,L M Tennessee Valley Authority 82/12/07 O'REILLY, J P
Region 2, Office of Director 2pp 16409 344 24X
Fiche 50-390, 82/12/07, 8212140164

8212140376 Final deficiency rept re anchor bolts not installed in accordance w/spacing specs Initially reported on 810331 Condition could not have adversely affected safe operation of plant Condition not reportable under 10CFR50 55(e)
MILLS,L M Tennessee Valley Authority 82/12/07 O'REILLY, J P
Region 2, Office of Director 2pp 16403 197 24X
Fiche 50-390, 82/12/07, 8212140376

8212150136 Second interim deficiency rept re inadequate QA program for masonry block work Initially reported on 820902 Areas where mortar did not meet min compressive strength requirements acceptable Next rept due by 830223
MILLS,L M Tennessee Valley Authority 82/12/09 O'REILLY, J P
Region 2, Office of Director 2pp 16425 239 24X
Fiche 50-390, 82/12/09, 8212150136

8212200001 Third interim deficiency rept re generic deficiency in design review Initially reported on 812115 No addl info available until action team 821215 rept Next rept will be submitted by 830420
MILLS,L M Tennessee Valley Authority 82/12/13 O'REILLY, J P
Region 2, Office of Director 1p 16473 362 24X
Fiche 50-000, 82/12/13, 8212200001

8212200017 Fifth interim deficiency rept re design review process interface coordination activity Initially reported on 810717 Corrective action to be based on action team rept to be issued approx 821215 Next rept expected by 830422
MILLS,L M Tennessee Valley Authority 82/12/13 O'REILLY, J P
Region 2, Office of Director 2pp 16473 085 24X
Fiche 50-000, 82/12/13, 8212200017

8212210356 Fourth interim deficiency rept re design of HVAC penetrations in containment Initially reported on 811224 Penetrations determined to be overstressed will be supported by hangers or stiffened Next rept expected by 830325
MILLS,L M Tennessee Valley Authority 82/12/13 O'REILLY, J P
Region 2, Office of Director 1p 16495 171 24X
Fiche 50-390, 82/12/13, 8212210356

8212210445 Second final deficiency rept re improper weld attachment of shear lugs Initially reported on 801030 New hanger installation procedure implemented Remaining corrective action on welds will be completed by 830131
MILLS,L M Tennessee Valley Authority 82/12/13 O'REILLY, J P
Region 2, Office of Director 2pp 16489 197 24X
Fiche 50-390, 82/12/13, 8212210445

8212210026 Fourth interim deficiency rept re potentially overstressed embedded plates Initially reported on 820412 Multiple supports attached to plates w/o design review of plate capacity Preliminary const spec issued Next rept by 830404
MILLS,L M Tennessee Valley Authority 82/12/14 O'REILLY, J P
Region 2, Office of Director 2pp 16485 260 24X
Fiche 50-000, 82/12/14, 8212210026

8212210217 Second interim deficiency rept re incorrect supports in analysis of 3-inch chemical & vol control sys line Initially reported on 820503 In-line isolation valves reanalyzed Next rept expected by 830520
MILLS,L M Tennessee Valley Authority 82/12/15 O'REILLY, J P
Region 2, Office of Director 2pp 16485 014 24X
Fiche 50-390, 82/12/15, 8212210217

8212210431 Fourth interim deficiency rept re resolution of unanticipated vibratory loading concerns Initially reported on 820120 Const activities for Yellow Creek & Hartsville deferred Next rept will be sent by 830322
MILLS,L M Tennessee Valley Authority 82/12/15 O'REILLY, J P
Region 2, Office of Director 2pp 16489 168 24X
Fiche 50-000, 82/12/15, 8212210431

8212220485 Second interim deficiency rept re solid state protection sys test procedures Initially reported on 820831 Westinghouse proposal for procedural change rejected Util will implement own change Also reportable per Part 21
MILLS,L M Tennessee Valley Authority 82/12/16 O'REILLY, J P
Region 2, Office of Director 3pp 16504 015 24X
Fiche 50-390, 82/12/16, 8212220485

8212220426 Seventh interim deficiency rept re rerouting of high pressure fire protection piping Initially reported on 810130 Increasing pipe head diameter to next largest size would eliminate deficiency Next rept due by 830622
MILLS,L M Tennessee Valley Authority 82/12/17 O'REILLY, J P
Region 2, Office of Director 2pp 16503 287 24X
Fiche 50-390, 82/12/17, 8212220426

8212280355 Second interim deficiency rept re unistrut clamps loaded in more than one direction for seismic supports Initially reported on 820708 Investigation continuing Next rept will be provided by 830211
MILLS,L M Tennessee Valley Authority 82/12/21 O'REILLY, J P
Region 2, Office of Director 2pp 16560 100 24X
Fiche 50-390, 82/12/21, 8212280355

DOCKET 50-395 VIRGIL C SUMMER NUCLEAR STATION, UNIT 1

E NRC Safety Evaluation Report (SER), supp's & correspondence

8211170238 Forwards NRC briefing package for meeting w/Commission on full power operation Matters raised in Commissioner Ahearne 821103 memo to be discussed
DIRCKS,W J Office of the Executive Director for Operations
82/11/05 FALLADING,N J Commissioners 2pp 16155 292 24X
Fiche 50-395, 82/11/05, 8211170238

8212070448 Forwards NUREG-0717, Suppl 5 to SER Copy also sent to LPDR w/o encl
YOUNG,LODD,B J Licensing Branch 1 82/11/29 DIXON,O W South Carolina Electric & Gas Co 3pp 16355 321 24X
Fiche 50-395, 82/11/29, 8212070448

F Security, medical, emergency & fire protection plans

8212090398 Forwards RC Lewis 820825 ltr & SALP rept for Sept 1980-Mar 1982
O'REILLY, J P Region 2, Office of Director 82/11/08 DIXON,O W South Carolina Electric & Gas Co 2pp 16363 268 24X
Fiche 50-395, 82/11/08, 8212090398

--8212090444 Forwards SALP rept for Sept 1980-Mar 1982 Meeting scheduled for 820831 to discuss results Comments re fire protection program & settlement of svc water pumphouse & piping deficiencies should be submitted within 20 days of meeting
LEWIS,R C Division of Project & Resident Programs 82/08/25 DIXON,O W South Carolina Electric & Gas Co 2pp 16363 270 24X
Fiche 50-395, 82/11/08, 8212090398

--B212090454 SALP rept for Sept 1980-Mar 1982 Addl attention warranted in areas of fire protection program evaluation & settlement of svc water pumphouse & piping
* Region 2, Office of Director 82/08/25 14pp 16363-272 24X
Fiche 50-395, 82/11/08, 8212090398

B212020340 Advises that util does not wish to participate in BNL exercise in response to Generic Ltr 82-25, "Integrated IAEA Exercise for Physical Inventory of LWRs"
DIXON, D W South Carolina Electric & Gas Co 82/11/29 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 16277 269
24X Fiche 50-395, 82/11/29, 8212020340

B212100292 Forwards Amend 8 to physical security plan Amend withheld (ref 10CFR2 790)
DIXON, D W South Carolina Electric & Gas Co 82/11/29 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 16376 272
24X Fiche 50-395, 82/11/29, 8212100292

B212100094 Forwards Amend 6 to License NPF-12, safety evaluation & notice of issuance & availability Amend provides for independent review of emergency plan & implementing procedures once every 12 months
YOUNGBLOOD, B J Licensing Branch 1 82/11/30 DIXON, D W South Carolina Electric & Gas Co 3pp 16399 009 24X
Fiche 50-395, 82/11/30, 8212100094

--B212100101 Amend 6 to License NPF-12, providing for independent review of emergency plan & implementing procedures at least once every 12 months per 10CFR50 54(b) Tech Spec changes encl
YOUNGBLOOD, B J Licensing Branch 1 82/11/30 4pp 16399 012
24X Fiche 50-395, 82/11/30, 8212100094

--B212100106 Safety evaluation supporting Amend 6 to License NPF-12
* Office of Nuclear Reactor Regulation, Director 82/11/30 3pp
16399 017 24X Fiche 50-395, 82/11/30, 8212100094

--B212100110 Notice of issuance & availability of Amend 6 to License NPF-12
YOUNGBLOOD, B J Licensing Branch 1 82/11/30 3pp 16399 020
24X Fiche 50-395, 82/11/30, 8212100094

B212070181 Suppl to B21008 application for amend to License NPF-12 re fire protection info mistakenly omitted from original application
DIXON, D W South Carolina Electric & Gas Co 82/12/01 DENTON, H R
Office of Nuclear Reactor Regulation, Director 12pp 16335 263
24X Fiche 50-395, 82/12/01, 8212070181

B212070018 Ack receipt of 821119 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Rept 50-395/82-53
LEWIS, R C Division of Project & Resident Programs 82/12/02
DIXON, D W South Carolina Electric & Gas Co 1p 16327 342 24X
Fiche 50-395, 82/12/02, 8212070018

--B212070026 Forwards response to NRC 821021 ltr re violations noted in IE Safeguards Insp Rept 50-395/82-53 Response withheld
DIXON, D W South Carolina Electric & Gas Co 82/11/19
O'REILLY, J P Region 2, Office of Director 2pp 16327 343 24X
Fiche 50-395, 82/12/02, 8212070018

--B212070030 Forwards IE Safeguards Insp Rept 50-395/82-53 on 820920 & notice of violation Details & notice of violation withheld (ref 10CFR73 21)
LEWIS, R C Division of Project & Resident Programs 82/10/21
DIXON, D W South Carolina Electric & Gas Co 2pp 16327 346
24X Fiche 50-395, 82/12/02, 8212070018

--B212070034 IE Safeguards Insp Rept 50-395/82-53 on 820920 Noncompliance noted failure to follow escort procedures Details withheld (ref 10CFR73 21)
SKOLDS, J L, MCQUIRE, D R Division of Engineering & Technical Programs 82/10/20 1p 16327 348 24X Fiche 50-395, 82/12/02, 8212070018

B212070128 Provides info re emergency operations facility per NRC request facility is served by separate ventilation sys w/HEPA filters
DIXON, D W South Carolina Electric & Gas Co 82/12/03 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 16327, 085
24X Fiche 50-395, 82/12/03, 8212070128

B212160322 Forwards corrected Pages 1 & 2 of table of contents to Amend 8 of physical security plan
DIXON, D W South Carolina Electric & Gas Co 82/12/13 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 16442 319
24X Fiche 50-395, 82/12/13, 8212160322

--B212160329 Corrected Pages 1 & 2 of table of contents of Amend 8 of physical security plan
* South Carolina Electric & Gas Co 82/12/13 2pp 16442 320
24X Fiche 50-395, 82/12/13, 8212160322

G Adjudicatory correspondence

B211150416 Order rendering ASLB 820720 & 0804 decisions immediately effective Order does not authorize issuance of full power OL since order does not deal w/uncontested issues considered separately by NRC & Commissioners
CHILK, S J Office of the Secretary of the Commission 82/11/10
2pp 16060 283 24X Fiche 50-395, 82/11/10, 8211150416

P Operating license stage documents & correspondence

B212020076 "SER, Inservice Testing Program, VC Summer Nuclear Station," interim rept
HUBBLE, W H, ROCKHOLD, H C EG&G, Inc FIN A-6430 8212020076
82/10/31 HAMMER, G O Division of Engineering 73pp 16309 001
24X Fiche 50-395, 82/10/31, 8212020076

B211170238 Forwards NRC briefing package for meeting w/Commission on full power operation matters raised in Commissioner Ahern's B21103 memo to be discussed
DIRCKS, W J Office of the Executive Director for Operations 82/11/05
PALLADINO, N J Commissioners 2pp 16155 292 24X
Fiche 50-395, 82/11/05, 8211170238

B212090398 Forwards RC Lewis 820825 ltr & SALP rept for Sept 1980-Mar 1982
O'REILLY, J P Region 2, Office of Director 82/11/08 DIXON, D W
South Carolina Electric & Gas Co 2pp 16363 268 24X
Fiche 50-395, 82/11/08, 8212090398

--B212090444 Forwards SALP rept for Sept 1980-Mar 1982 Meeting scheduled for 820831 to discuss results Comments re fire protection program & settlement of svc water pumphouse & piping deficiencies should be submitted within 20 days of meeting
LEWIS, R C Division of Project & Resident Programs 82/08/25
DIXON, D W South Carolina Electric & Gas Co 2pp 16363 270
24X Fiche 50-395, 82/11/08, 8212090398

--B212090454 SALP rept for Sept 1980-Mar 1982 Addl attention warranted in areas of fire protection program evaluation & settlement of svc water pumphouse & piping
* Region 2, Office of Director 82/08/25 14pp 16363 272 24X
Fiche 50-395, 82/11/08, 8212090398

B212010030 Informs of issuance of full power license amends on B21112 Susquehanna 1 & Summer 1 issued 40-yr license expiring on 220717 & 220321, respectively Susquehanna 1 will operate w/low power limitation & Summer 1 at 50% power
PERCH, R L Licensing Branch 2 KANE, W F Licensing Branch 1
82/11/15 CASE, E, CARTER, J Office of Nuclear Reactor Regulation, Director EISENHUT, D Division of Licensing 1p 16271 356 24X
Fiche 50-000, 82/11/15, 8212010030

B212010526 Staff requirements memo re Commission B21112 discussion/possible vote in Washington, DC on full power OL Operation above 5% approved
CHILK, S J Office of the Secretary of the Commission 82/11/26
DIRCKS, W J Office of the Executive Director for Operations 2pp 16270 266 24X Fiche 50-395, 82/11/26, 8212010526

B212270418 Responds to FOIA request for documents re proposed revision &/or update to reactor safety study referred to in NUREG-0784, Chapter 10 as RS 11 & all documents pertaining to reactor cooling methods. Forwards documents listed in app
FELTON, J M Division of Rules and Records 82/11/26 SHOLLY, S C
Union of Concerned Scientists 3pp 16549 233 24X
Fiche 50-000, 82/11/26, 8212270418

--B211050027 Forwards summary of semiscale test results & advises that board notification re test results issued w/o encl
NOUAK, F M Assistant Director for Licensing 82/09/24
Division of Licensing, 1p 16549 278 24X Fiche 50-000, 82/11/26, 8212270418

B212100094 Forwards Amend 6 to License NPF-12, safety evaluation & notice of issuance & availability Amend provides for independent review of emergency plan & implementing procedures once every 12 months
YOUNGBLOOD, B J Licensing Branch 1 82/11/30 DIXON, D W South Carolina Electric & Gas Co 3pp 16399 009 24X
Fiche 50-395, 82/11/30, 8212100094

--B212100101 Amend 6 to License NPF-12, providing for independent review of emergency plan & implementing procedures at least once every 12 months per 10CFR50 54(b) Tech Spec changes encl
YOUNGBLOOD, B J Licensing Branch 1 82/11/30 4pp 16399 012
24X Fiche 50-395, 82/11/30, 8212100094

DOCKETED ITEMS

--B212100106 Safety evaluation supporting Amend 6 to License NPF-12
 * Office of Nuclear Reactor Regulation, Director 82/11/30 3pp
 16399 017 24X Fiche 50-395,82/11/30,8212100094

--B212100110 Notice of issuance & availability of Amend 6 to License NPF-12
 YOUNGBL000,B J Licensing Branch 1 82/11/30 3pp 16399 020
 24X Fiche 50-395,82/11/30,8212100094

B212070181 Suppl to B21008 application for amend to License NPF-12 re fire protection info mistakenly omitted from original application
 DIXON,D W South Carolina Electric & Gas Co 82/12/01 DENTON,H R
 Office of Nuclear Reactor Regulation, Director 12pp 16335 263
 24X Fiche 50-395,82/12/01,8212070181

B212290067 Forwards Amend 7 to License NPF-12, safety evaluation & notice of issuance & availability Amend provides for range of hydrogen & oxygen content in std gas samples in channel calibr
 YOUNGBL000,B J Licensing Branch 1 82/12/06 DIXON,D W South Carolina Electric & Gas Co 3pp 16606 347 24X
 Fiche 50-395,82/12/06,8212290067

--B212290071 Amend 7 to License NPF-12, providing for range of hydrogen & oxygen in std gas samples used in hydrogen & oxygen monitor channel calibr
 YOUNGBL000,B J Licensing Branch 1 82/12/06 5pp 16606 350
 24X Fiche 50-395,82/12/06,8212290067

--B212290076 Safety evaluation supporting Amend 7 to License NPF-12
 * Office of Nuclear Reactor Regulation, Director 82/12/06 2pp
 16606 355 24X Fiche 50-395,82/12/06,8212290067

--B212290081 Notice of issuance & availability of Amend 7 to License NPF-12
 YOUNGBL000,B J Licensing Branch 1 82/12/06 3pp 16606 357
 24X Fiche 50-395,82/12/06,8212290067

B212140103 Generic Ltr 82-28 to all licensees of operating Westinghouse & C-E PHRs (except Arkansas Nuclear One, Unit 2 & San Onofre 2 & 3) re inadequate core cooling instrumentation sys Svc list encl
 EISENHUT,D G Division of Licensing 82/12/10 Yankee Atomic Electric Co 27pp 16690 035 24X Fiche 50-000,82/12/10,8212140103

B212170257 Provides addl info on Operating License Condition 2 3 (14) re operations at 50% power Util intends to implement program addressed in Westinghouse rept on interim power evaluation
 DIXON,D W South Carolina Electric & Gas Co 82/12/14 DENTON,H R
 Office of Nuclear Reactor Regulation, Director 2pp 16457 173
 24X Fiche 50-395,82/12/14,8212170257

B212220440 Board Notifications 82-125 & B2-125A Forwards info re H Etherington evaluation of flow blockage during natural circulation of PHRs Results do not adversely impact present position on reliance on natural circulation
 NOVAK,T M Assistant Director for Licensing 82/12/14 Atomic
 Safety and Licensing Board Panel 5pp 16523 135 24X
 Fiche 50-000,82/12/14,8212220440

B212220461 Board Notification 82-124 forwards RJ Mattson 821123 memo re Semiscale S-UT-8 test results Phenomena of core level depression & loop seal clearing may be more complex than previously supposed
 NOVAK,T M Assistant Director for Licensing 82/12/14 Atomic
 Safety and Licensing Board Panel 7pp 16523 169 24X
 Fiche 50-000,82/12/14,8212220461

B212230288 Application to amend License NPF-12, revising Tech Spec Figure 3 2-3 & Table 3 B-1 to add containment penetration conductor overcurrent protective device for steam cleaning machine permanent power source
 DIXON,D W South Carolina Electric & Gas Co 82/12/17 DENTON,H R
 Office of Nuclear Reactor Regulation, Director 3pp 16507 347
 24X Fiche 50-395,82/12/17,8212230288

--B212230294 Proposed Tech Spec Figure 3 2-3 & Table 3 B-1 re RCS floorate & containment penetration conductor overcurrent protective device test setpoint criteria, respectively
 * South Carolina Electric & Gas Co 82/12/17 2pp 16507 350
 24X Fiche 50-395,82/12/17,8212230288

Q Inspection reports, IE Bulletins & correspondence

B208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Svc list encl
 DEYUNO,R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000,82/10/28,8208190240

B212090392 Notices that info necessary to close IE Bulletin 79-14, "Seismic Analysis of As-Built Safety-Related Piping Sys," & to resolve issue re criteria for overlapping computer analyzed piping math models will be provided by B30128
 DIXON,D W South Carolina Electric & Gas Co 82/11/04 O'REILLY,J P Region 2, Office of Director 2pp 16364 347 24X
 Fiche 50-395,82/11/04,8212090392

B208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list encl
 COBB,L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000,82/11/05,8208190245

B212090398 Forwards RC Lewis 820825 ltr & SALP rept for Sept 1980-Mar 1982
 O'REILLY,J P Region 2, Office of Director 82/11/08 DIXON,D W South Carolina Electric & Gas Co 2pp 16363 268 24X
 Fiche 50-395,82/11/08,8212090398

--B212070444 Forwards SALP rept for Sept 1980-Mar 1982 Meeting scheduled for 820831 to discuss results Comments re fire protection program & settlement of svc water pumphouse & piping deficiencies should be submitted within 20 days of meeting
 LEWIS,R C Division of Project & Resident Programs 82/08/28 DIXON,D W South Carolina Electric & Gas Co 2pp 16363 270 24X
 Fiche 50-395,82/11/08,8212090398

--B212090454 SALP rept for Sept 1980-Mar 1982 Addl attention warranted in areas of fire protection program evaluation & settlement of svc water pumphouse & piping
 * Region 2, Office of Director 82/08/28 14pp 16363 272 24X
 Fiche 50-395,82/11/08,8212090398

B212090406 Confirms that requirements constraining power below 5% have been completed & util may proceed above 5% power in accordance w/OL
 O'REILLY,J P Region 2, Office of Director 82/11/10 DIXON,D W South Carolina Electric & Gas Co 1p 16364 175 24X
 Fiche 50-395,82/11/10,8212090406

B208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl
 JORDAN,E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X
 Fiche 50-000,82/11/18,8208190251

B208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list encl
 DEYUNO,R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 045 24X Fiche 50-000,82/11/26,8208190256

B212090509 Ack receipt of 821118 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-395/82-49
 DANCE,H C Division of Project & Resident Programs 82/11/29 DIXON,D W South Carolina Electric & Gas Co 1p 16367 024 24X
 Fiche 50-395,82/11/29,8212090509

--B212090516 Responds to NRC 821019 ltr re violations noted in IE Insp Rept 50-395/82-49 Corrective actions operator logs revised to include svc water pond level requirements & clarifications made to Tech Spec surveillance requirements
 DIXON,D W South Carolina Electric & Gas Co 82/11/18 O'REILLY,J P Region 2, Office of Director 4pp 16367 025 24X
 Fiche 50-395,82/11/29,8212090509

--B212090530 Forwards IE Insp Rept 50-395/82-49 on 820901-30 & notice of violation
 DANCE,H C Division of Project & Resident Programs 82/10/19 DIXON,D W South Carolina Electric & Gas Co 2pp 16367 029 24X
 Fiche 50-395,82/11/29,8212090509

--B212090534 Notice of violation from insp on 820901-30
 * Division of Project & Resident Programs 82/10/19 1p 16367 031 24X
 Fiche 50-395,82/11/29,8212090509

--B212090545 IE Insp Rept 50-395/82-49 on 820901-30 Noncompliance noted failure to follow procedures & failure to perform required surveillance for svc water pond level verification
SKOLDS, J L, BROWNLEE, V L Division of Project & Resident Programs 82/10/19 6pp 16367 032 24X Fiche 50-395, 82/11/29, 8212090509

B208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl" Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16367 028 24X Fiche 50-000, 82/11/30, 8208190257

B212070018 Act receipt of 821119 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Rept 50-395/82-53
LEWIS, R C Division of Project & Resident Programs 82/12/02
DIXON, D W South Carolina Electric & Gas Co 1p 16327 342 24X Fiche 50-395, 82/12/02, 8212070018

--B212070026 Forwards response to NRC 821021 ltr re violations noted in IE Safeguards Insp Rept 50-395/82-53 Response withheld
DIXON, D W South Carolina Electric & Gas Co 82/11/19
O'REILLY, J P Region 2, Office of Director 2pp 16327 343 24X Fiche 50-395, 82/12/02, 8212070018

--B212070030 Forwards IE Safeguards Insp Rept 50-395/82-53 on 820920 & notice of violation Details & notice of violation withheld (ref 10CFR73.21)
LEWIS, R C Division of Project & Resident Programs 82/10/21
DIXON, D W South Carolina Electric & Gas Co 2pp 16327 346 24X Fiche 50-395, 82/12/02, 8212070018

--B212070034 IE Safeguards Insp Rept 50-395/82-53 on 820920 Noncompliance noted failure to follow escort procedures Details withheld (ref 10CFR73.21)
SKOLDS, J L, MCQUIRE, D R Division of Engineering & Technical Programs 82/10/20 1p 16327 348 24X Fiche 50-395, 82/12/02, 8212070018

B208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies" Svc list encl
MEYDUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259

B208190261 IE Info Notice 82-48, "Failures of Agastat CR 0075 Relay Buckets" Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X Fiche 50-000, 82/12/03, 8208190261

B208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring" Svc list encl
MEYDUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16, 8208190267

B208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27" Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X Fiche 50-000, 82/12/20, 8208190268

S Reportable occurrences, LERs & related correspondence

B212030108 RO on 821110, during Mode 2 operation, radiation monitor RM-019C (main steam line C monitor) declared inoperable due to erratic indications Caused by moisture accumulation Monitor will be changed prior to 830101
DIXON, D W South Carolina Electric & Gas Co 82/11/23
O'REILLY, J P Region 2, Office of Director 2pp 16303 099 24X Fiche 50-395, 82/11/23, 8212030108

B212030188 Forwards LER 82-029/03L-0 Detailed event analysis encl
DIXON, D W South Carolina Electric & Gas Co 82/11/23
O'REILLY, J P Region 2, Office of Director 2pp 16306 266 24X Fiche 50-395, 82/11/23, 8212030188

--B212030199 LER 82-029/03L-0 on 821025, during zero power testing, isolation amplifier resistor input on power range channel NI-44 found out of calibr tolerance Caused by instrument drift Channel removed from svc & calibr
MCKINNEY, C J South Carolina Electric & Gas Co 82/11/23 Region 2, Office of Director 1p 16306 268 24X Fiche 50-395, 82/11/23, 8212030188

B212030089 Interim deficiency rept re safety hazard concerning undetectable failure which could exist in on-line circuits of solid state protection sys Westinghouse finalizing design mod package Final rept expected by 830201
DIXON, D W South Carolina Electric & Gas Co 82/11/24
O'REILLY, J P Region 2, Office of Director 2pp 16304 101 24X Fiche 50-395, 82/11/24, 8212030089

B212030133 Forwards LER 82-030/03L-0 Detailed event analysis encl
DIXON, D W South Carolina Electric & Gas Co 82/11/24
O'REILLY, J P Region 2, Office of Director 2pp 16306 098 24X Fiche 50-395, 82/11/24, 8212030133

--B212030139 LER 82-030/03L-0 on 821028, in Mode 2, svc water booster pump discharge check valve XVC-3138B found stuck in closed position Valve disassembled, inspected, lubricated, reassembled & tested satisfactorily
FIELDS, H C South Carolina Electric & Gas Co 82/11/24 Region 2, Office of Director 1p 16306 100 24X Fiche 50-395, 82/11/24, 8212030133

B212030164 Forwards LER 82-031/03L-0 Detailed event analysis encl
DIXON, D W South Carolina Electric & Gas Co 82/11/24
O'REILLY, J P Region 2, Office of Director 2pp 16307 080 24X Fiche 50-395, 82/11/24, 8212030164

--B212030171 LER 82-031/03L-0 on 821030, w/plant in Mode 4, source range channel NI-32 failed low Caused by loose connection on dry bulb voltage attenuator connector Connection repaired & channel operable by 821101
MCKINNEY, C J South Carolina Electric & Gas Co 82/11/24 Region 2, Office of Director 1p 16307 082 24X Fiche 50-395, 82/11/24, 8212030164

B212030186 Forwards LER 82-032/03L-0 Detailed event analysis encl
DIXON, D W South Carolina Electric & Gas Co 82/11/24
O'REILLY, J P Region 2, Office of Director 2pp 16303 211 24X Fiche 50-395, 82/11/24, 8212030186

--B212030202 LER 82-032/03L-0 on 821029, auxiliary operator discovered nuclear shutdown monitor tank damaged Caused by distorted diaphragm blocking tank overflow & vent paths Diaphragm removed & tank repaired
KODIN, A R South Carolina Electric & Gas Co 82/11/24 Region 2, Office of Director 1p 16303 213 24X Fiche 50-395, 82/11/24, 8212030186

B212030060 Forwards LER 82-033/03L-0 Detailed event analysis encl
DIXON, D W South Carolina Electric & Gas Co 82/11/29
O'REILLY, J P Region 2, Office of Director 2pp 16304 187 24X Fiche 50-395, 82/11/29, 8212030060

--B212030064 LER 82-033/03L-0 on 821031, during water pump test, speed switch XES-2003A failed in midposition during fast to slow speed transfer, rendering svc water train A inoperable Caused by bad relay contact on speed switch Relay repaired
MCKINNEY, C J South Carolina Electric & Gas Co 82/11/29 Region 2, Office of Director 1p 16304 189 24X Fiche 50-395, 82/11/29, 8212030060

B212090422 Forwards LER 82-034/03L-0 Detailed event analysis encl
DIXON, D W South Carolina Electric & Gas Co 82/12/01
O'REILLY, J P Region 2, Office of Director 2pp 16364 253 24X Fiche 50-395, 82/12/01, 8212090422

--B212090438 LER 82-034/03L-0 on 821103, during Mode 4, radiation monitor RM-019C (main steam line C monitor) failed to high radiation alarm setpoint Caused by moisture penetration of cable connectors between detector & preamp Detector replaced
FIELDS, H C South Carolina Electric & Gas Co 82/12/01 Region 2, Office of Director 1p 16364 255 24X Fiche 50-395, 82/12/01, 8212090422

B212090243 Forwards LER 82-036/03L-0 Detailed event analysis encl
DIXON, D W South Carolina Electric & Gas Co 82/12/02
O'REILLY, J P Region 2, Office of Director 2pp 16361 353 24X Fiche 50-395, 82/12/02, 8212090243

--B212090253 LER 82-036/03L-0 on 821103, plant entered Mode 3 w/control room evacuation panel pressurizer relief tank level indicator LI-470A inoperable Caused by level transmitter being out of calibr Transmitter calibr
FIELDS, H C South Carolina Electric & Gas Co 82/12/02 Region 2, Office of Director 1p 16361 355 24X Fiche 50-395, 82/12/02, 8212090243

B212090449 Forwards LER 82-035/03L-0 Detailed event analysis encl
DIXON, D W South Carolina Electric & Gas Co 82/12/02
O'REILLY, J P Region 2, Office of Director 2pp 16363 249 24X Fiche 50-395, 82/12/02, 8212090449

--8212090460 LER 82-035/03L-0 on 821103, plant entered Mode 3 w/ boric acid tank B level instrument LT-163A inoperable Caused by instrument out of calibr due to zero shift on transmitter instrument recalibrate
KODON, A R South Carolina Electric & Gas Co 82/12/02 Region 2, Office of Director 1p 16363 251 24X Fiche 50-395, 82/12/02, 8212090449

8212090366 Forwards LER 82-037/03L-0 Detailed event analysis encl
DIXON, D W South Carolina Electric & Gas Co 82/12/03
O'REILLY, J P Region 2, Office of Director 2pp 16365 068 24X
Fiche 50-395, 82/12/03, 8212090366

--8212090372 LER 82-037/03L-0 on 821104, steam generator blowdown radiation monitor (RM-L3) & steam generator blowdown discharge radiation monitor (RM-L10) taken out of svl Caused by insufficient sample flow Sys aligned for RM-L10
HARRIS, A B South Carolina Electric & Gas Co 82/12/03 Region 2, Office of Director 1p 16365 070 24X Fiche 50-395, 82/12/03, 8212090366

8212150077 Forwards LER 82-038/03L-0 Detailed event analysis encl
DIXON, D W South Carolina Electric & Gas Co 82/12/08
O'REILLY, J P Region 2, Office of Director 2pp 16427 342 24X
Fiche 50-395, 82/12/08, 8212150077

--8212150081 LER 82-038/03L-0 on 821114, main control board indication for steam generator A steam flow (FT-474) failed to indicate sys flow Caused by indicator needle sticking to lower stop Channel calibr performed
MCKINNEY, C J South Carolina Electric & Gas Co 82/12/08 Region 2, Office of Director 1p 16427 344 24X
Fiche 50-395, 82/12/08, 8212150077

8212150089 Forwards LER 82-040/03L-0 Detailed event analysis encl
DIXON, D W South Carolina Electric & Gas Co 82/12/08
O'REILLY, J P Region 2, Office of Director 3pp 16431 027 24X
Fiche 50-395, 82/12/08, 8212150089

--8212150091 LER 82-040/03L-0 on 821108, Tech Spec 3.3.2 had not been complied w/ due to improper interpretation Caused by personnel error Ltr issued delineating correct interpretation of Tech Spec
KODON, A R South Carolina Electric & Gas Co 82/12/08 Region 2, Office of Director 1p 16431 030 24X Fiche 50-395, 82/12/08, 8212150089

8212150097 Forwards LER 82-039/03L-0 Detailed event analysis encl
DIXON, D W South Carolina Electric & Gas Co 82/12/08
O'REILLY, J P Region 2, Office of Director 2pp 16430 349 24X
Fiche 50-395, 82/12/08, 8212150097

--8212150100 LER 82-039/03L-0 on 821108, steam generator steam flow transmitter (FT-476) power supply found defective Caused by failure on transmitter power supply (FGV-476) Channel placed in tripped condition Circuit board replaced & tested
MCKINNEY, C J South Carolina Electric & Gas Co 82/12/08 Region 2, Office of Director 1p 16430 351 24X
Fiche 50-395, 82/12/08, 8212150097

8212150117 Forwards LER 82-041/03L-0 Detailed event analysis encl
DIXON, D W South Carolina Electric & Gas Co 82/12/09
O'REILLY, J P Region 2, Office of Director 2pp 16427 348 24X
Fiche 50-395, 82/12/09, 8212150117

--8212150122 LER 82-041/03L-0 on 821109, during Mode 2, radiation monitor RM-A1 (control room isolation) failed surveillance Test Procedure 360 032 Caused by instrument drift Monitor calibr & returned to svc.
KODON, A R South Carolina Electric & Gas Co 82/12/09 Region 2, Office of Director 1p 16427 350 24X Fiche 50-395, 82/12/09, 8212150117

8212170287 Forwards LER 82-042/03L-0 Detailed event analysis encl
DIXON, D W South Carolina Electric & Gas Co 82/12/10
O'REILLY, J P Region 2, Office of Director 2pp 16453 212 24X
Fiche 50-395, 82/12/10, 8212170287

--8212170291 LER 82-042/03L-0 on 821110, RCS temp average decreased when control rods inserted Caused by simultaneous rod insertion & main steam dumping Control rods withdrawn & steam dump isolated to recover temp average
FIELDS, H C South Carolina Electric & Gas Co 82/12/10 Region 2, Office of Director 1p 16453 214 24X Fiche 50-395, 82/12/10, 8212170287

8212210341 Final Part 21 rept re possible thermostatic valve malfunction fail-safe to "Full Cooling Position" Initially reported on 820525 All corrective actions completed
MORIARTY, J M Colt Industries, Inc 82/12/10 KEPLER, J O Region 3, Office of Director 1p 16496 334 24X Fiche 50-395, 82/12/10, 8212210341

8212200110 Forwards LER 82-043/03L-0 Detailed event analysis encl
DIXON, D W South Carolina Electric & Gas Co 82/12/13
O'REILLY, J P Region 2, Office of Director 2pp 16470 149 24X
Fiche 50-395, 82/12/13, 8212200110

--8212200115 LER 82-043/03L-0 on 821113, nuclear instrumentation power range channel (N42) low-range trip setpoint found set at 50% instead of 25% of rated thermal power Caused by personnel error Low-range trip setpoint reset
MCKINNEY, C J South Carolina Electric & Gas Co 82/12/13 Region 2, Office of Director 1p 16470 151 24X
Fiche 50-395, 82/12/13, 8212200110

8212220376 Forwards LER 82-047/03L-0 Detailed event analysis encl
DIXON, D W South Carolina Electric & Gas Co 82/12/16
O'REILLY, J P Region 2, Office of Director 2pp 16517 264 24X
Fiche 50-395, 82/12/16, 8212220376

--8212220384 LER 82-047/03L-0 on 821118, operations personnel failed to document Tavg on 30-minute basis greater than 551 degrees w/Tavg-Tref deviation alarm not reset Caused by failure of operator to recognize surveillance requirements
MCKINNEY, C J South Carolina Electric & Gas Co 82/12/16 Region 2, Office of Director 1p 16517 266 24X
Fiche 50-395, 82/12/16, 8212220376

8212220411 Forwards LER 82-046/03L-0 Detailed event analysis encl
DIXON, D W South Carolina Electric & Gas Co 82/12/16
O'REILLY, J P Region 2, Office of Director 3pp 16503 248 24X
Fiche 50-395, 82/12/16, 8212220411

--8212220414 LER 82-046/03L-0 on 821117, main control board indication for steam generator feedwater flow read zero Caused by personnel leaving equalizing valves on transmitters open Valves closed & personnel indoctrinated
MCKINNEY, C J South Carolina Electric & Gas Co 82/12/16 Region 2, Office of Director 1p 16503 251 24X
Fiche 50-395, 82/12/16, 8212220411

8212220428 Forwards LER 82-045/03L-0 Detailed event analysis encl
DIXON, D W South Carolina Electric & Gas Co 82/12/16
O'REILLY, J P Region 2, Office of Director 2pp 16503 289 24X
Fiche 50-395, 82/12/16, 8212220428

--8212220462 LER 82-045/03L-0 on 821116, plant entered Mode 1 w/o performing surveillance Test Procedure 134 001 re shutdown margin calculation per Tech Specs Caused by personnel oversight Tech Specs reviewed Surveillance program revised
FIELDS, H C South Carolina Electric & Gas Co 82/12/16 Region 2, Office of Director 1p 16503 291 24X Fiche 50-395, 82/12/16, 8212220428

8212220498 Forwards LER 82-044/01T-0 Detailed event analysis encl
DIXON, D W South Carolina Electric & Gas Co 82/12/16
O'REILLY, J P Region 2, Office of Director 4pp 16503 259 24X
Fiche 50-395, 82/12/16, 8212220498

--8212220500 LER 82-044/01T-0 on 821202, surveillance test performed on 821005 for RHR pump A signed off approved when acceptance criteria not met Caused by personnel error due to lack of experience
KODON, A R South Carolina Electric & Gas Co 82/12/16 Region 2, Office of Director 1p 16503 263 24X Fiche 50-395, 82/12/16, 8212220498

8212220328 Forwards LER 82-049/03L-0 Detailed event analysis encl
DIXON, D W South Carolina Electric & Gas Co 82/12/17
O'REILLY, J P Region 2, Office of Director 3pp 16517 177 24X
Fiche 50-395, 82/12/17, 8212220328

--8212220337 LER 82-049/03L-0 on 821118, Surveillance Requirement 4.7.9.1 (e) not performed on fire suppression water sys Caused by fire protection group being unaware of Mode 4 restriction Personnel counseled & tracking program updated
MCKINNEY, C J South Carolina Electric & Gas Co 82/12/17 Region 2, Office of Director 1p 16517 180 24X
Fiche 50-395, 82/12/17, 8212220328

8212300035 Forwards LER 82-050/03L-0
DIXON, D W South Carolina Electric & Gas Co 82/12/21
O'REILLY, J P Region 2, Office of Director 3pp 16598 198 24X
Fiche 50-395, 82/12/21, 8212300035

--8212300042 LER 82-050/03L-0 on 821207, fire watch patrol not executed for Zone FF for 4 h while smoke detectors inoperable Caused by breakdown in communications & absenteeism Personnel dismissed
* South Carolina Electric & Gas Co 82/12/21 Region 2, Office of Director 1p 16598 201 24X Fiche 50-395, 82/12/21, 8212300035

7 Hearing transcripts on non-antitrust matters

B21180122 Unofficial transcript of B21112 public discussion/possible vote on full power QL in Washington, DC Pg 1-90
* Commissioners 82/11/12 94pp 16154 141 24X
Fiche 50-395, 82/11/12, B211180122

DOCKET 50-396 UNIV OF VIRGINIA CAVALIER REACTOR

D Inspection reports, IE Bulletins & correspondence

B208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants" Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, B208190240

DOCKET 50-397 WPPSS NUCLEAR PROJECT, UNIT 2

A Application/construction stage documents & correspondence

B210270013 Forwards Revision 1 to "Plant Verification Rept," dtd Oct 1982
BOUCHEY, O D Washington Public Power Supply System 82/10/22
DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 15817 012 24X Fiche 50-397, 82/10/22, B210270013

--B210270016 Forwards Revision 1 to "Plant Verification Rept," dtd Oct 1982
GLASSCOCK, R D Washington Public Power Supply System 82/10/22
ENGELKEN, R H Region 5, Office of Director 1p 15817 014 24X
Fiche 50-397, 82/10/22, B210270013

--B210270018 Revision 1 to "Plant Verification Rept," dtd Oct 1982
TIMMINS, D C, MATLOCK, R G, SHEN, P K Washington Public Power Supply System 82/06/30 437pp 15817 015 24X
Fiche 50-397, 82/10/22, B210270013

B211230066 Generic Ltr 82-27 to all BWR licensees of operating reactors except LACBWR, Big Rock Point, Dresden 1, Humboldt Bay, applicants for DL & holders of CP re transmittal of NUREG-0743 & NUREG-0783 Svc list encl w/o stated encl
EISENHUT, D G Division of Licensing 82/11/15 General Public Utilities - CPU Service Corp 22pp 16387 004 24X
Fiche 50-000, 82/11/15, B211230066

B212030260 Summary of B21110 meeting w/util in Bethesda, MD re review of GA program in light of deficiencies disclosed at other projects Viewgraphs encl
AULUCK, R Licensing Branch 2 82/11/30 Licensing Branch 2 83pp 16317 231 24X Fiche 50-397, 82/11/30, B212030260

B212200047 Forwards one oversize design elementary diagram showing relaying scheme used to implement commitment to provide second level undervoltage protection for div I & II EGF buses Aperture card is available in PDR
BOUCHEY, O D Washington Public Power Supply System 82/12/08
SCHWENCER, A Licensing Branch 2 1p 16470 185 24X
Fiche 50-397, 82/12/08, B212200047

B212200074 Forwards summary info re containment vessel out-of-roundness issue raised during litigation following termination of Contract 206 per R Auluck request Out-of-roundness will have no detrimental effect on structural capacity
BOUCHEY, O D Washington Public Power Supply System 82/12/08
SCHWENCER, A Licensing Branch 2 5pp 16470 025 24X
Fiche 50-397, 82/12/08, B212200074

B212170173 Responds to NRC Question O10 046 re pipe break in BWR scram sys (NUREG-0803) Response to Questions O10 067 - O10 074 will be submitted under separate cover during Dec 1982
BOUCHEY, O D Washington Public Power Supply System 82/12/09
SCHWENCER, A Licensing Branch 2 13pp 16450 124 24X
Fiche 50-397, 82/12/09, B212170173

B212170175 Responds to telephone request for info re analytical models used to predict forcing functions & response of drywell-to-wetwell vacuum breakers Final rept to be provided following completion of vacuum breaker mod
BOUCHEY, O D Washington Public Power Supply System 82/12/09
SCHWENCER, A Licensing Branch 2 1p 16462 060 24X
Fiche 50-397, 82/12/09, B212170175

B212170374 Forwards marked-up revision to FSAR Section 8.3.1.4 reflecting analysis justification for coil-to-contact relay isolation between redundant Class IE circuits & Revision 0 to "Electrical Separation Practices"
BOUCHEY, O D Washington Public Power Supply System 82/12/09
SCHWENCER, A Licensing Branch 2 3pp 16453 226 24X
Fiche 50-397, 82/12/09, B212170374

--B212170379 Revision 0 to "Electrical Separation Practices"
BRASTAD, O W, MALLANDA, J J Washington Public Power Supply System 82/12/03 51pp 16453 229 24X Fiche 50-397, 82/12/09, B212170374

B212220355 Forwards request for addl info re review of safety-related equipment Responses needed by B30107
SCHWENCER, A Licensing Branch 2 82/12/09 FERGUSON, R L Washington Public Power Supply System 4pp 16523 244 24X
Fiche 50-397, 82/12/09, B212220355

B212270159 Forwards revised organization & staffing announcement for operational QA program description, per B21215 telcon info will be included in FSAR revision to be filed early in 1983
BOUCHEY, O D Washington Public Power Supply System 82/12/16
HAASB, W P Quality Assurance Branch 8pp 16538 046 24X
Fiche 50-397, 82/12/16, B212270159

B212230363 Trap rept of Commissioners Gilsinsky & Abbott B21202 site visit Agenda & viewgraphs encl
ABBOTT, E C Commissioners 82/12/17 Commissioners 26pp 16511 170 24X Fiche 50-397, 82/12/17, B212230363

B212290241 Responds to NRC B20809 request for addl info on fuel corrosion measures Factors attributed to corrosion fuel failures include fuel duty, cladding matl & reactor water environ
BOUCHEY, O D Washington Public Power Supply System 82/12/23
SCHWENCER, A Licensing Branch 2 2pp 16382 043 24X
Fiche 50-397, 82/12/23, B212290241

E NRC Safety Evaluation Report (SER), supp's & correspondence

B212010024 Advises that recommendations re application for DL per B21013 ltr will be addressed in SER supplement to be issued in Dec 1982
GOODWIN, E F Office of Nuclear Reactor Regulation, Director 82/11/12 FRALEY, R ACRS - Advisory Committee on Reactor Safeguards 3pp 16290 239 24X Fiche 50-397, 82/11/12, B212010024

B212200083 Forwards sweepnet stress calculation per SER, NUREG-0892, Confirmatory Issue 6 & B20930 telcon
BOUCHEY, O D Washington Public Power Supply System 82/12/08
SCHWENCER, A Licensing Branch 2 8pp 16470 041 24X
Fiche 50-397, 82/12/08, B212200083

B212170138 Forwards responses to NRC Questions O10 067 through O10 074 re internally generated missiles, per B21209 commitment Responses close out Outstanding Issue 2 in SER, NUREG-0892
BOUCHEY, O D Washington Public Power Supply System 82/12/09
SCHWENCER, A Licensing Branch 2 9pp 16452 006 24X
Fiche 50-397, 82/12/09, B212170138

F Security, medical, emergency & fire protection plans

B212100256 Forwards util B00616 & 1212 & B10320 & 0408 ltrs re emergency response facilities (ERF) in response to Generic Ltr B1-10, per NRC request Util does not plan to provide backup ERF Requested info provided
BOUCHEY, O D Washington Public Power Supply System 82/12/03
DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 16376 149 24X Fiche 50-397, 82/12/03, B212100256

B212290505 Notification of B30105 meeting w/util in Bethesda, MD to discuss request for limited exemption re prompt notification sys
AULUCK, R Licensing Branch 2 82/12/23 SCHWENCER, A Licensing Branch 2 3pp 16593 346 24X Fiche 50-397, 82/12/23, B212290505

G Adjudicatory correspondence

B212020350 Order scheduling B30119-20 prehearing conference in Richland, WA to discuss standing of parties, specific issues to be considered at evidentiary hearing, scheduling & possible consolidation
GROSSMAN, H Atomic Safety and Licensing Board Panel 82/11/30 4pp 16278 001 24X Fiche 50-397, 82/11/30, B212020350

DOCKETED ITEMS

8212140418 Motion for delay of 830119 & 20 prehearing conference
Schedule burdensome due to two major holiday periods Four
days of preparation lost Certificate of Svc encl
DELLI, K Coalition for Safe Power 82/12/09 Atomic Safety and
Licensing Board Panel 3pp 16403 312 24X Fiche 50-397, 82/12/09,
8212140418

8212200104 Order rescheduling 830119 & 20 prehearing conferences for
830106-27 Coalition for Safe Power allowed to file suppis to
requests for hearing no later than 15 days before
conference
GROSSMAN, H Atomic Safety and Licensing Board Panel 82/12/15
2pp 16470 089 24X Fiche 50-397, 82/12/15, 8212200104

8212230314 Requests supplemental pleadings be served on applicant
counsel in Washington, DC per ASLB 821215 order Pleadings
expected by 830111 Pleadings served to util in Richland, WA
do not constitute svc in proceeding
REYNOLDS, N S Debevoise & Liberman REYNOLDS, N S Washington
Public Power Supply System 82/12/20 ROSSOLIE, E Coalition for
Safe Power 1p 16507 027 24X Fiche 50-397, 82/12/20, 8212230314

8212270326 Response supporting Coalition for Safe Power 821209 motion
for 1-wk delay of prehearing conference scheduled for
830119-20 Applicant does not concede that basis for request
constitutes good cause Certificate of Svc encl
REYNOLDS, N S Washington Public Power Supply System REYNOLDS, N S
Debevoise & Liberman 82/12/22 Atomic Safety and Licensing Board
Panel 6pp 16530 190 24X Fiche 50-397, 82/12/22, 8212270326

8212280277 Forwards responses to petitioner motion for delay of 830119
& 22 prehearing conference, for inclusion in records Related
correspondence W/o encl
REYNOLDS, N S Debevoise & Liberman REYNOLDS, N S Washington
Public Power Supply System 82/12/22 GROSSMAN, H Atomic Safety
and Licensing Board Panel 1p 16561 311 24X
Fiche 50-397, 82/12/22, 8212280277

8212280145 Notice of appearance in proceeding Certificate of Svc encl
PATON, H D Hearing Branch 2 82/12/27 2pp 16563 122 24X
Fiche 50-397, 82/12/27, 8212280145

H General correspondence

8212170314 Notifies that RL Ferguson, managing director of util, resigned
on 821129, effective 830601, due to health reasons
DOUCHEY, O D Washington Public Power Supply System 82/12/08
DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp
16456 158 24X Fiche 50-397, 82/12/08, 8212170314

K Utility Final Safety Analysis Report (FSAR) & amends

8212290180 Forwards App J to FSAR, "Shielding Evaluation Rept"
DOUCHEY, O D Washington Public Power Supply System 82/11/23
SCHWENCER, A Licensing Branch 2 2pp 16580 096 24X
Fiche 50-397, 82/11/23, 8212290180

--8212290185 App J to FSAR, "Shielding Evaluation Rept"
Washington Public Power Supply System 82/09/30 310pp
16580 096 24X Fiche 50-397, 82/11/23, 8212290180

D Advisory Committee on Reactor Safeguards reports & correspondence

8211100488 Summarizes ACRS 270th meeting on 821007-08 in Washington, DC
to review full-power OL for WPPSS Unit 2 & small break LOCA
for B&W plants
SHEKHON, P ACRS - Advisory Committee on Reactor Safeguards
82/10/19 PALLADINO, N J Commissioners 2pp 16441 090 24X
Fiche 50-397, 82/10/19, 8211100488

8212010024 Advises that recommendations re application for OL per
821013 ltr will be addressed in SER supplement to be issued
in Dec 1982
GOODWIN, E F Office of Nuclear Reactor Regulation, Director
82/11/12 FRALEY, R ACRS - Advisory Committee on Reactor
Safeguards 3pp 16290 239 24X Fiche 50-397, 82/11/12, 8212010024

G Inspection reports, IE Bulletins & correspondence

8208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-
Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping
at BHR Plants" Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and
Enforcement 82/10/28 Consolidated Edison Co of New York, Inc
112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240

8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic P33
801 & Model 802 Thermoluminescent Dosimeters" Svc list
encl
COBB, L J Division of Fuel Facilities, Materials & Safeguards
82/11/05 Consolidated Edison Co of New York, Inc 110pp
16372 142 24X Fiche 50-000, 82/11/05, 8208190245

8212040021 Advises that IE Bulletin 82-01, Suppl 1 re IYT Grinnell
supplied matls, is not applicable to facility
MATLOCK, R G Washington Public Power Supply System 82/11/12
ENGELKEN, R H Region 5, Office of Director 1p 16313 325 24X
Fiche 50-397, 82/11/12, 8212040021

8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan
Exercise Requirements" Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/12
Consolidated Edison Co of New York, Inc 109pp 16411 199 24X
Fiche 50-000, 82/11/12, 8208190251

8212060205 Forwards IE Insp Rept 50-397/82-24 on 821001-31 No
noncompliance noted
STERNBERG, D M Division of Resident, Reactor Project & Engineering
Programs 82/11/22 MATLOCK, R G Washington Public Power Supply
System 2pp 16312 241 24X Fiche 50-397, 82/11/22, 8212060205

--8212060208 IE Insp Rept 50-397/82-24 on 821001-31 No noncompliance
noted. Major areas inspected mechanical contractor records
review program & corrective activities, work reverification
program activities, RCP piping & as-built configuration
TOTH, A D, FELL, R A, DODDS, R T Division of Resident, Reactor
Project & Engineering Programs 82/11/19 16pp 16312 243 24X
Fiche 50-397, 82/11/22, 8212060205

8212030107 Forwards revised schedule for responding to Questions
031 135 - 031 138 re IE Bulletins 79-27 & 80-06 & IE Info
Notice 79-22
DOUCHEY, O D Washington Public Power Supply System 82/11/23
SCHWENCER, A Licensing Branch 2 62pp 16303 037 24X
Fiche 50-397, 82/11/23, 8212030107

8212220213 Forwards IE Insp Rept 50-397/82-19 on 820913-1008 No
noncompliance noted
STERNBERG, D M Division of Resident, Reactor Project & Engineering
Programs 82/11/24 MATLOCK, R G Washington Public Power Supply
System 2pp 16503 335 24X Fiche 50-397, 82/11/24, 8212220213

--8212220218 IE Insp Rept 50-397/82-19 on 820913-1008 No noncompliance
noted. Major areas inspected welding QC program, radiograph
reverification program, items reported by 10CFR50 55(e)
notification & safety-related piping sys. sizes & matls
KERCH, H W, HARRIS, R H, DURR, J P Region 1, Office of Director
82/11/04 8pp 16503 337 24X Fiche 50-397, 82/11/24, 8212220213

8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination
Padlocks" Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and
Enforcement 82/11/26 Consolidated Edison Co of New York, Inc
127pp 16411 065 24X Fiche 50-000, 82/11/26, 8208190256

8208190257 IE Info Notice 82-47, "Transportation of Type A Quantities
of Non-Fissile Radioactive Matl" Svc list encl
COBB, L J Division of Fuel Facilities, Materials & Safeguards
82/11/30 Consolidated Edison Co of New York, Inc 356pp
16387 028 24X Fiche 50-000, 82/11/30, 8208190257

8212280443 Confirms 821123 telephone request for extension until
821203 to provide response to IE Insp Rept 50-397/82-21
MATLOCK, R G Washington Public Power Supply System 82/12/02
ENGELKEN, R H Region 5, Office of Director 1p 16556 037 24X
Fiche 50-397, 82/12/02, 8212280443

8208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment
Electrical Penetration Assemblies" Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and
Enforcement 82/12/03 Consolidated Edison Co of New York, Inc
113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259

8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay
Sockets" Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03
Consolidated Edison Co of New York, Inc 110pp 16462 064 24X
Fiche 50-000, 82/12/03, 8208190261

8212210416 Forwards IE Insp Rept 50-397/82-26 on 821101-05 No
noncompliance noted
STERNBERG, D M Division of Resident, Reactor Project & Engineering
Programs 82/12/08 MATLOCK, R G Washington Public Power Supply
System 2pp 16493 078 24X Fiche 50-397, 82/12/08, 8212210416

--B212210427 IE Insp Rept 50-397/82-26 on B21101-05 No noncompliance noted Major areas inspected preoperational test procedure program, followup of open items, IE bulletin/circular followup & independent insp
WILLET, D J, DODDS, R T Division of Resident, Reactor Project & Engineering Programs 82/12/08 3pp 16493 082 24X
Fiche 50-397, 82/12/08, B212210416

B212170088 Forwards SALP rept for Jul 1981-Jul 1982
ENGELKEN, R H Region 5, Office of Director 82/12/10
FERGUSON, R L Washington Public Power Supply System 3pp
16450 322 24X Fiche 50-397, 82/12/10, B212170088

--B212170091 SALP rept for Jul 1981-Jul 1982 Weaknesses noted design & installation of electrical sys & implementation of corrective actions in const deficiency repts
a Region 5, Office of Director 82/12/10 21pp 16450 325 24X
Fiche 50-397, 82/12/10, B212170088

--B212170100 Responds to B21027 SALP rept Corrective actions task force established to revisit electrical separation & follow up surveillances on const deficiency repts incorporated into project QA
FERGUSON, R L Washington Public Power Supply System 82/11/23
STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 3pp 16450 346 24X Fiche 50-397, 82/12/10, B212170088

--B212170103 Notifies of weaknesses in specific areas identified in SALP rept Meeting scheduled for B21103 to discuss assessment
STERNBERG, D M Region 5, Office of Director 82/10/27
MATLOCK, R G Washington Public Power Supply System 1p
16450 351 24X Fiche 50-397, 82/12/10, B212170088

B212280023 Notifies that generic qualification tests of Raychem Flamtrol cables no longer applicable for all cables Certain Raychem-Flamtrol cables react adversely to space charges occurring during radiation crosslinking
JORDAN, E L Division of Engineering & Quality Assurance 82/12/10
FERGUSON, R Washington Public Power Supply System 4pp 16593 120
24X Fiche 50-397, 82/12/10, B212280023

B2108190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
HAYGUNS, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16, B208190267

B2108190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27 " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X
Fiche 50-000, 82/12/20, B208190268

B212300308 Ack receipt of B21202 ltr informing NRC of steps taken to correct violations & deviations noted in IE Insp Rept 50-397/82-21
STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 82/12/23 MATLOCK, R G Washington Public Power Supply System 1p 16594 292 24X Fiche 50-397, 82/12/23, B212300308

--B212300318 Responds to NRC B21025 ltr re violations & deviations noted in IE Insp Rept 50-397/82-21 Corrective actions electrical separation project engineering directives reviewed to identify cables affected by 6-inch separation requirements
CARLISLE, C S Washington Public Power Supply System 82/12/02
STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 15pp 16594 293 24X Fiche 50-397, 82/12/23, B212300308

9 Reportable occurrences, LERs & related correspondence

B212060179 Interim deficiency rept re voltage drop due to excessive cable length Initially reported on B20603 Control power transformer output increased Voltage no longer impeded & long cable used Next rept expected by 830222
MATLOCK, R G Washington Public Power Supply System 82/11/23
ENGELKEN, R H Region 5, Office of Director 2pp 16313 076 24X
Fiche 50-397, 82/11/23, B212060179

B212060289 Interim deficiency rept re controls for remote shutdown panel & pump discharge switch Initially reported on B20819 & B2020, respectively Switches & valves will be relocated Next rept will be submitted on 830228
MATLOCK, R G Washington Public Power Supply System 82/11/23
ENGELKEN, R H Region 5, Office of Director 4pp 16312 066 24X
Fiche 50-397, 82/11/23, B212060289

B212210386 Deficiency rept re Johnson Controls design issue Eight of 132 small bore lines did not meet min design criteria following thermal effects application
MATLOCK, R G Washington Public Power Supply System 82/12/02
ENGELKEN, R H Region 5, Office of Director 2pp 16493 361 24X
Fiche 50-397, 82/12/02, B212210386

DOCKET 50-400 SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 1

A Application/construction stage documents & correspondence

B212130181 Forwards revised "Human Factors Design Evaluation Rept for Shearon Harris Unit 1 Control Room "
MCUFFIE, M A Carolina Power & Light Co 82/12/07 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 16397 336 24X
Fiche 50-400, 82/12/07, B212130181

--B212130185 Revised "Human Factors Design Evaluation Rept for Shearon Harris Unit 1 Control Room "
TALLEY, W T, HAHER, J, FABRY, J Essex Corp 82/09/16 165pp
16397 337 24X Fiche 50-400, 82/12/07, B212130181

C Utility Environmental Report (ER), amends & correspondence

B21210422 Forwards Amend 5 to environ rept
MCUFFIE, M A Carolina Power & Light Co 82/12/15 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 16494 001
24X Fiche 50-400, 82/12/15, B212210422

--B212210424 Amend 5 to environ rept
a Carolina Power & Light Co 82/12/15 270pp 16494 003 24X
Fiche 50-400, 82/12/15, B212210422

B212280112 Forwards revised distribution list reflecting title, address & name changes for distribution of Amend 5 to environ rept
Distribution made within 10 days after issuance of amend Affidavit encl
ZIMMERMAN, S R Carolina Power & Light Co 82/12/23 EISENHUT, D G
Division of Licensing 3pp 16564 183 24X Fiche 50-400, 82/12/23, B212280112

D NRC Draft/Final Environmental Statements, supp's & correspondence

B212160036 Forwards addl info requested by NRC B21120 ltr re vol reduction sys info addresses all items necessary for DES input Remaining info will be submitted as available
MCUFFIE, M A Carolina Power & Light Co 82/12/13 DENTON, H R
Office of Nuclear Reactor Regulation, Director 9pp 16446 207
24X Fiche 50-400, 82/12/13, B212160036

E NRC Safety Evaluation Report (SER), supp's & correspondence

B212080558 Forwards request for addl info re response to vol reduction sys for draft SER Response required by B21210 to complete safety review on schedule
KNIGHTON, O W Licensing Branch 3 82/11/26 UTLEY, E E Carolina Power & Light Co 3pp 16368 395 24X Fiche 50-400, 82/11/26, B212080558

G Adjudicatory correspondence

B212020336 Order directing NRC & util to answer questions on document copies & cost to enable ASLB to rule on intervenor requests to reconsider order re svc of documents
KELLEY, J L Atomic Safety and Licensing Board Panel 82/12/01
Office of the Executive Legal Director 2pp 16277 149 24X
Fiche 50-400, 82/12/01, B212020336

B212100099 Advises that name will be added to applicant svc list for future filings Listed documents encl Svc list only encl
BAXTER, T A Shaw, Pittman, Potts & Trowbridge BAXTER, T A
Carolina Power & Light Co 82/12/07 LOTCHIN, P Affiliation
Unknown 3pp 16379 185 24X Fiche 50-400, 82/12/07, B212100099

B212170073 Forwards Generic Ltr B2-14 setting forth schedule of number of copies of documents required to be submitted to NRC, in response to ASLB B21201 inquiry
BARTH, C A Hearing Branch 1 82/12/14 KELLEY, J L, BRIGHT, O D, CARPENTER, J H Atomic Safety and Licensing Board Panel 1p
16452 326 24X Fiche 50-400, 82/12/14, B212170073

B212230366 Response to ASLB B21201 order seeking info on document copies & costs re serving documents on intervenors
Certificate of Svc encl Related correspondence
JONES, R E, FLYNN, S F Carolina Power & Light Co 82/12/15
Atomic Safety and Licensing Board Panel 6pp 16511 197 24X
Fiche 50-400, 82/12/15, B212230366

B212210222 Motion for codification of admitted contentions Request made for convenience of all parties & ASLB & in fairness to applicants who bear burden of proof re each contention admitted for litigation Certificate of Svc encl
O'NEILL, J H Carolina Power & Light Co O'NEILL, J H Shaw, Pittman, Potts & Trowbridge 82/12/17
Atomic Safety and Licensing Board Panel 78pp 16484 101 24X Fiche 50-400, 82/12/17, B212210222

DOCKETED ITEMS

8212270222 Forwards Chapters 8 & 11 of environ rept, through Amend 5 Chapters cover benefits & costs & provide analysis of savings for utilizing plants from 1986 - 1995 Svc list encl
BAXTER, T A Shaw, Pittman, Potts & Trowbridge BAXTER, T A
Carolina Power & Light Co 82/12/21 KELLEY, J L, BRIGHT, C D,
CARPENTER, J H Atomic Safety and Licensing Board Panel 19pp
16535 097 24X Fiche 50-400, 82/12/21, 8212270222

0 Inspection reports, IE Bulletins & correspondence

8212090183 Forwards IE Insp Repts 50-400/82-33 & 50-401/82-33 on 821004-05 No noncompliance noted
VERRELLI, D M Division of Project & Resident Programs 82/10/26
UTLEY, E E Carolina Power & Light Co 2pp 16359 191 24X
Fiche 50-400, 82/10/26, 8212090183

--8212090186 IE Insp Repts 50-400/82-33 & 50-401/82-33 on 821004-05 No noncompliance noted Major areas inspected safety-related piping for Unit 2
COLEY, J L, BLAKE, J J Division of Engineering & Technical Programs 82/10/21 4pp 16359 193 24X Fiche 50-400, 82/10/26, 8212090183

8212090348 Forwards IE Insp Repts 50-400/82-34 & 50-401/82-34 on 821012-15 No noncompliance noted
VERRELLI, D M Division of Project & Resident Programs 82/10/27
UTLEY, E E Carolina Power & Light Co 2pp 16365 081 24X
Fiche 50-400, 82/10/27, 8212090348

--8212090355 IE Insp Repts 50-400/82-34 & 50-401/82-34 on 821012-15 No noncompliance noted Major areas inspected electrical components & sys work & work activities, quality records & followup on previous insp item
HERRIWEATHER, N, CONLON, T E Division of Engineering & Technical Programs 82/10/22 3pp 16365 083 24X Fiche 50-400, 82/10/27, 8212090348

8208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at 8HR Plants " Svc list encl
DEVOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462-163 24X Fiche 50-000, 82/10/28, 8208190240

8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000, 82/11/05, 8208190245

8212090229 Ack receipt of 821027 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-400/82-31
VERRELLI, D M Division of Project & Resident Programs 82/11/10
UTLEY, E E Carolina Power & Light Co 1p 16363 079 24X
Fiche 50-400, 82/11/10, 8212090229

--8212090237 Responds to NRC 820928 ltr re violations noted in IE Insp Rept 50-400/82-31 Corrective actions maint logs initiated for warehouse & walkdown of storage areas performed
PARSONS, R M Carolina Power & Light Co 82/10/27 O'REILLY, J P Region 2, Office of Director 3pp 16363 080 24X
Fiche 50-400, 82/11/10, 8212090229

--8212090244 Forwards IE Insp Repts 50-400/82-31 & 50-401/82-31 on 820907-10 & notice of violation
VERRELLI, D M Division of Project & Resident Programs 82/09/28
JONES, J A Carolina Power & Light Co 2pp 16363 083 24X
Fiche 50-400, 82/11/10, 8212090229

--8212090249 Notice of violation from insp on 820907-10
* Division of Project & Resident Programs 82/09/28 1p
16363 085 24X Fiche 50-400, 82/11/10, 8212090229

--8212090256 IE Insp Repts 50-400/82-31 & 50-401/82-31 on 820907-10 Noncompliance noted failed to follow storage procedures for electrical penetrations
HUNT, M D Division of Project & Resident Programs, CONLON, T E Division of Engineering & Technical Programs 82/09/21 4pp 16363-086 24X Fiche 50-400, 82/11/10, 8212090229

8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc. 109pp 16411-199 24X
Fiche 50-000, 82/11/18, 8208190251

8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list encl
DEVOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 069 24X Fiche 50-000, 82/11/26, 8208190256

8208190257 IE Info Notice 82-47, "Transportation of Type A Containers of Non-Fissile Radioactive Matl " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000, 82/11/30, 8208190257

8208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl
DEVOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259

8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0075 Pumps, Sockets " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/30 Consolidated Edison Co of New York, Inc 110pp 16462 144 24X Fiche 50-000, 82/12/03, 8208190261

8208190267 IE Info Notice 82-49, "Correction for Sample Conditions of Air & Gas Monitoring " Svc list encl
DEVOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16428 191 24X Fiche 50-000, 82/12/16, 8208190267

8208190268 IE Info Notice 82-50, "Mod of Solid State AC Under-Station Relays Type ITE-27 " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 108pp 16428 293 24X Fiche 50-000, 82/12/20, 8208190268

5 Reportable occurrences, LERs & related correspondence

8212070043 Interim deficiency rept re bolted connections w/excessively gaps & ASTM A325 nuts on ASTM A490 bolts initially reported on 820618 Bolt-nut combination acceptable & nonreportable Each gap being evaluated individually Next rept by 830415
PARSONS, R M Carolina Power & Light Co 82/11/30 O'REILLY, J P Region 2, Office of Director 2pp 16329 347 24X
Fiche 50-400, 82/11/30, 8212070043

8212070305 Interim deficiency rept re defective welding in auxiliary relay cabinets supplied by Sys Control Corp Initially reported on 821101 Vendor evaluating Next rept will be submitted by 830204 Also reportable per Part 21
PARSONS, R M Carolina Power & Light Co 82/11/30 O'REILLY, J P Region 2, Office of Director 1p 16343 158 24X
Fiche 50-400, 82/11/30, 8212070305

8212170328 Third interim deficiency rept re failure of seismic Category 1 pressure gauges supplied by Dresser Industries Initially reported on 810923 Gauges placed on QA hold pending test results Also reportable per 10CFR21
PARSONS, R M Carolina Power & Light Co 82/12/09 O'REILLY, J P Region 2, Office of Director 4pp 16456 115 24X
Fiche 50-400, 82/12/09, 8212170328

8212170183 Interim deficiency rept re 480-volt switchgear design of secondary disconnects. Initially reported on 821102 Disconnects in breaker cradle will be replaced Final rept expected 830131 Also reportable per Part 21
PARSONS, R M Carolina Power & Light Co 82/12/10 O'REILLY, J P Region 2, Office of Director 4pp 16450 184 24X
Fiche 50-400, 82/12/10, 8212170183

8212220345 Deficiency rept re welding deficiencies in chemical & vol control sys pump supports Initially reported on 821129 Item determined not reportable per 10CFR50 55(e) & 10CFR21
CHIANG, N J Carolina Power & Light Co 82/12/14 O'REILLY, J P Region 2, Office of Director 1p 16517 152 24X
Fiche 50-400, 82/12/14, 8212220345

8212220432 Supplemental deficiency rept requesting extension to 831112 to submit 10CFR50 55(e) & 10CFR21 repts re shop welding defects on seismic Class I cable trays
PARSONS, R M Carolina Power & Light Co 82/12/14 O'REILLY, J P Region 2, Office of Director 1p 16503 316 24X
Fiche 50-400, 82/12/14, 8212220432

8212300326 Interim deficiency rept re welding deficiencies in reactor coolant pump motor frame Initially reported on 821202 Westinghouse evaluation continuing Next rept will be submitted by 830311
PARSONS, R M Carolina Power & Light Co 82/12/23 O'REILLY, J P Region 2, Office of Director 1p 16594 266 24X
Fiche 50-400, 82/12/23, 8212300326

DOCKET 50-401 SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 2

C Utility Environmental Report (ER), amends & correspondence

B212210422 Forwards Amend 5 to environ rept
MC DUFFIE, M A Carolina Power & Light Co 82/12/15 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 16494 001
24X Fiche 50-400, 82/12/15, B212210422

--B212210424 Amend 5 to environ rept
* Carolina Power & Light Co 82/12/15 270pp 16494 003 24X
Fiche 50-400, 82/12/15, B212210422

B212280112 Forwards revised distribution list reflecting title, address
& name changes for distribution of Amend 5 to environ rept
Distribution made within 10 days after issuance of amend
Affidavit encl
ZIMMERMAN, S R Carolina Power & Light Co 82/12/23 EISENHUT, D G
Division of Licensing 3pp 16564 183 24X Fiche 50-400, 82/12/23,
B212280112

D NRC Draft/Final Environmental Statements, supplis & correspondence

B212160036 Forwards addl info requested by NRC B21120 ltr re vol
reduction sys info addresses all items necessary for DEB
input Remaining info will be submitted as available
MC DUFFIE, M A Carolina Power & Light Co 82/12/13 DENTON, H R
Office of Nuclear Reactor Regulation, Director 9pp 16446 207
24X Fiche 50-400, 82/12/13, B212160036

E NRC Safety Evaluation Report (SER), supplis & correspondence

B212080558 Forwards request for addl info re response to vol reduction
sys for draft SER Response required by B21210 to complete
safety review on schedule
KNIGHTON, G W Licensing Branch 3 82/11/24 UTLEY, E E Carolina
Power & Light Co 5pp 16368 355 24X Fiche 50-400, 82/11/24,
B212080558

G Adjudicatory correspondence

B212020336 Order directing NRC & util to answer questions on document
copies & cost to enable ASLB to rule on intervenor requests
to reconsider order re svc of documents
KELLEY, J L Atomic Safety and Licensing Board Panel 82/12/01
Office of the Executive Legal Director 2pp 16279 149 24X
Fiche 50-400, 82/12/01, B212020336

B212100099 Advises that name will be added to applicant svc list for
future filings Lstsd documents encl Svc list only encl
BAXTER, T A Shaw, Pittman, Potts & Trowbridge BAXTER, T A
Carolina Power & Light Co 82/12/07 LOTCHIN, P Affiliation
Unknown 3pp 16379 186 24X Fiche 50-400, 82/12/07, B212100099,

B212170073 Forwards Generic Ltr B2-14 setting forth schedule of number
of copies of documents required to be submitted to NRC, in
response to ASLB B21201 inquiry
BARTH, C A Hearing Branch 1 82/12/14 KELLEY, J L, BRIGHT, G D,
CARPENTER, J H Atomic Safety and Licensing Board Panel 1p
16452 326 24X Fiche 50-400, 82/12/14, B212170073

B212230366 Response to ASLB B21201 order seeking info on document
copies & costs re serving documents on intervenors
Certificate of Svr encl Related correspondence
JONES, R E, FLYNN, S F Carolina Power & Light Co 82/12/15
Atomic Safety and Licensing Board Panel 6pp 16511 197 24X
Fiche 50-400, 82/12/15, B212230366

B212210222 Motion for codification of admitted contentions Request made
for convenience of all parties & ASLB & in fairness to
applicants who bear burden of proof re each contention
admitted for litigation Certificate of Svc encl
D'NEILL, J H Carolina Power & Light Co D'NEILL, J H Shaw,
Pittman, Potts & Trowbridge 82/12/17 Atomic Safety and
Licensing Board Panel 78pp 16484 101 24X Fiche 50-400, 82/12/17,
B212210222

B212270222 Forwards Chapters 8 & 11 of environ rept, through Amend 5
Chapters cover benefits & costs & provide analysis of
savings for utilizing plants from 1986 - 1995 Svc list encl
BAXTER, T A Shaw, Pittman, Potts & Trowbridge BAXTER, T A
Carolina Power & Light Co 82/12/21 KELLEY, J L, BRIGHT, G D,
CARPENTER, J H Atomic Safety and Licensing Board Panel 19pp
16353 097 24X Fiche 50-400, 82/12/21, B212270222

G Inspection Reports, IE Bulletins & correspondence

B212090183 Forwards IE Insp Repts 50-400/82-33 & 50-401/82-33 on
B21004-05 No noncompliance noted
VERRELLI, D M Division of Project & Resident Programs 82/10/26
UTLEY, E E Carolina Power & Light Co 2pp 16359 191 24X
Fiche 50-400, 82/10/26, B212090183

--B212090186 IE Insp Repts 50-400/82-33 & 50-401/82-33 on B21004-05 No
noncompliance noted Major areas inspected safety-related
piping for Unit 2
COLEY, J L, BLAKE, J J Division of Engineering & Technical
Programs 82/10/21 4pp 16359 193 24X Fiche 50-400, 82/10/26,
B212090183

B212090348 Forwards IE Insp Repts 50-400/82-34 & 50-401/82-34 on
B21012-15 No noncompliance noted
VERRELLI, D M Division of Project & Resident Programs 82/10/27
UTLEY, E E Carolina Power & Light Co 2pp 16363 081 24X
Fiche 50-400, 82/10/27, B212090348

--B212090355 IE Insp Repts 50-400/82-34 & 50-401/82-34 on B21012-15 No
noncompliance noted Major areas inspected electrical
components & sys work & work activities, quality records &
followup on previous insp item
MERRIWEATHER, N, CONLON, T E Division of Engineering & Technical
Programs 82/10/22 3pp 16365 083 24X Fiche 50-400, 82/10/27,
B212090348

B208190240 IE Bulletin B2-03, Revision 1, "Stress Cracking in Thick-
Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping
at BHR Plants " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and
Enforcement 82/10/28 Consolidated Edison Co. of New York, Inc
112pp 16462 163 24X Fiche 50-000, 82/10/28, B208190240

B208190245 IE Info Notice B2-42, "Defects Observed in Panasonic Model
B01 & Model B02 Thermoluminescent Dosimeters " Svc list
encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards
82/11/05 Consolidated Edison Co. of New York, Inc 110pp
16372 142 24X Fiche 50-000, 82/11/05, B208190245

B212090229 Ack receipt of B21027 ltr informing NRC of steps taken to
correct violations noted in IE Insp Rept 50-400/82-31
VERRELLI, D M Division of Project & Resident Programs 82/11/10
UTLEY, E E Carolina Power & Light Co 1p 16363 079 24X
Fiche 50-400, 82/11/10, B212090229

--B212090244 Forwards IE Insp Repts 50-400/82-31 & 50-401/82-31 on
B20907-10 & notice of violation
VERRELLI, D M Division of Project & Resident Programs 82/09/28
JONES, J A Carolina Power & Light Co 2pp 16363 083 24X
Fiche 50-400, 82/11/10, B212090229

--B212090249 Notice of violation from Insp on B20907-10
* Division of Project & Resident Programs 82/09/28 1p
16363 085 24X Fiche 50-400, 82/11/10, B212090229

--B212090256 IE Insp Repts 50-400/82-31 & 50-401/82-31 on B20907-10
Noncompliance noted Failed to follow storage procedures for
electrical penetrations
HUNT, M D Division of Project & Resident Programs CONLON, T E
Division of Engineering & Technical Programs 82/09/21 4pp
16363 086 24X Fiche 50-400, 82/11/10, B212090229

B208190251 IE Info Notice B2-44, "Clarification of Emergency Plan
Exercise Requirements " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18
Consolidated Edison Co. of New York, Inc 109pp 16411 199 24X
Fiche 50-000, 82/11/18, B208190251

B208190256 IE Info Notice B2-46, "Defective & Obsolete Combination
Padlocks " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and
Enforcement 82/11/26 Consolidated Edison Co. of New York, Inc
127pp 16411 065 24X Fiche 50-000, 82/11/26, B208190256.

B208190257 IE Info Notice B2-47, "Transportation of Type A Quantities
of Non-Fissile Radioactive Matl " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards,
82/11/30 Consolidated Edison Co. of New York, Inc 356pp
16387 028 24X Fiche 50-000, 82/11/30, B208190257

B208190259 IE Bulletin B2-04, "Deficiencies in Primary Containment
Electrical Penetration Assemblies " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and
Enforcement 82/12/03 Consolidated Edison Co. of New York, Inc
113pp 16411 317 24X Fiche 50-000, 82/12/03, B208190259

DOCKETED ITEMS

8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03
Consolidated Edison Co of New York, Inc 110pp 16462 064 24X
Fiche 50-000, 82/12/03, 8208190261

8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
DEYOUNG, R C Director's Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16, 8208190267

8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27 " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20
Consolidated Edison Co of New York, Inc 108pp 16628 293 24X
Fiche 50-000, 82/12/20, 8208190268

S Reportable occurrences, LERs & related correspondence

8212070043 Interim deficiency rept re bolted connections w/excessive gaps & ASTM A325 nuts on ASTM A490 bolts Initially reported on 820618 Bolt-nut combination acceptable & nonreportable Each gap being evaluated individually Next rept by 830415
PARSONS, R M Carolina Power & Light Co 82/11/30 O'REILLY, J P Region 2, Office of Director 2pp, 16329 347 24X
Fiche 50-400, 82/11/30, 8212070043

8212070305 Interim deficiency rept re defective welding in auxiliary relay cabinets supplied by Sys Control Corp Initially reported on 821101 Vendor evaluating Next rept will be submitted by 830204, Also reportable per Part 21
PARSONS, R M Carolina Power & Light Co 82/11/30 O'REILLY, J P Region 2, Office of Director 1p 16343 158 24X
Fiche 50-400, 82/11/30, 8212070305

8212170183 Interim deficiency rept re 480-volt switchgear design of secondary disconnects Initially reported on 821102 Disconnects in breaker cradle will be replaced Final rept expected 830131 Also reportable per Part 21
PARSONS, R M Carolina Power & Light Co 82/12/10 O'REILLY, J P Region 2, Office of Director 4pp 16450 184 24X
Fiche 50-400, 82/12/10, 8212170183

8212220345 Deficiency rept re welding deficiencies in chemical & vol control sys pump supports Initially reported on 821129 Item determined not reportable per 10CFR50.55(e) & 10CFR21.
CHIANG, H J Carolina Power & Light Co 82/12/14 O'REILLY, J P Region 2, Office of Director 1p 16517 152 24X
Fiche 50-400, 82/12/14, 8212220345

8212220432 Supplemental deficiency rept requesting extension to 831002 to submit 10CFR50.55(e) & 10CFR21 repts re shop welding defects on seismic Class 1 cable trays
PARSONS, R M Carolina Power & Light Co 82/12/14 O'REILLY, J P Region 2, Office of Director 1p 16503 316 24X
Fiche 50-400, 82/12/14, 8212220432

8212300326 Interim deficiency rept re welding deficiencies in reactor coolant pump motor frame Initially reported on 821202 Westinghouse evaluation continuing Next rept will be submitted by 830311
PARSONS, R M Carolina Power & Light Co 82/12/23 O'REILLY, J P Region 2, Office of Director 1p 16594 266 24X
Fiche 50-400, 82/12/23, 8212300326

DOCKET 50-404 NORTH ANNA POWER STATION, UNIT 3

Q Inspection reports, IE Bulletins & correspondence

8212090305 Provides final rept on resolution of issues re IE Bulletins 79-28, "Possible Malfunction of NAMCO Model EA180 Limit Switches at Elevated Temps" & 80-23, "Failures of Solenoid Valves Mfg by Valcor Engineering Corp."
SPENCER, W C Virginia Electric & Power Co 82/11/01 O'REILLY, J P Region 2, Office of Director 2pp 16345 133 24X
Fiche 50-404, 82/11/01, 8212090305

DOCKET 50-409 LA CROSSE BOILING WATER REACTOR

F Security, medical, emergency & fire protection plans

8212060249 Forwards IE Insp Rept 50-409/82-06 on 820510-14 & notice of violation
KEPPLER, J O Region 3, Office of Director 82/11/16 LINDER, F W Dairyland Power Cooperative 3pp 16312 288 24X
Fiche 50-409, 82/11/16, 8212060249

--8212060250 Notice of violation from insp on 820510-14
KEPPLER, J O Region 3, Office of Director 82/11/16 3pp 16312 291 24X Fiche 50-409, 82/11/16, 8212060249

--8212060252 IE Insp Rept 50-409/82-06 on 820510-14 Noncompliance noted inadequate shift staff augmentation capability & inadequate meteorological measurements procedures
PAGLIARD, J A, ORANT, W B, AXELSON, W L Division of Emergency Preparedness & Operational Support 82/11/10 16pp 16312 294 24X Fiche 50-409, 82/11/16, 8212060249

8212150015 Forwards IE Emergency Plan Safety Evaluation Rept 50-409/82-15 during Nov 1982 No noncompliance noted
HIND, J A Division of Emergency Preparedness & Operational Support 82/11/23 LINDER, F W Dairyland Power Cooperative 2pp 16421 181 24X Fiche 50-409, 82/11/23, 8212150015

--8212150019 IE Emergency Plan Safety Evaluation Rept 50-409/82-15 during Nov 1982 No noncompliance noted Major areas inspected 820703 site emergency plan
PAGLIARD, J A, AXELSON, W L, PAPERIELLO, C J Division of Emergency Preparedness & Operational Support 82/11/18 31pp 16421 183 24X Fiche 50-409, 82/11/23, 8212150015

8212070152 Forwards supplemental info re emergency offsite facility (EOF), per R Dudley 821202 telcon request EOF considered both interim & permanent facility
LINDER, F Dairyland Power Cooperative 82/12/02 CRUTCHFIELD, D Operating Reactors Branch 5 5pp 16326 224 24X
Fiche 50-409, 82/12/02, 8212070152

8212080169 Forwards Amend 30 to License DPR-45 & notice of issuance Amend revises requirement to maintain guard training & qualification plan to be implemented within 60 days of approval & qualification of all security personnel
CRUTCHFIELD, D Operating Reactors Branch 5 82/12/06 LINDER, F Dairyland Power Cooperative 4pp 16354 075 24X
Fiche 50-409, 82/12/06, 8212080169

--8212080174 Amend 30 to License DPR-45, including requirement to maintain guard training & qualification plan to be implemented within 60 days of issuance & requiring security personnel to be qualified within 2 yrs of approval
CRUTCHFIELD, D Operating Reactors Branch 5 82/12/06 3pp 16354 080 24X Fiche 50-409, 82/12/06, 8212080169

--8212080178 Notice of issuance & availability of Amend 30 to License DPR-45
* Operating Reactors Branch 5 82/12/06 2pp 16354 083 24X
Fiche 50-409, 82/12/06, 8212080169

8212220315 Releases public version of radiological emergency response plan implementing procedure
FELTON, J M Division of Rules and Records 82/12/10 Document Management Branch 1p 16523 248 24X Fiche 50-409, 82/12/10, 8212220315

--8212220323 Forwards public version of Issue 0 to Radiological Emergency Response Plan Implementing Procedure EPP-18, "Operation of Technical Support Ctr/Emergency Offsite Facility Data Acquisition Sys"
LINDER, F Dairyland Power Cooperative 82/11/29 CRUTCHFIELD, D Operating Reactors Branch 5 1p 16523 249 24X
Fiche 50-409, 82/12/10, 8212220315

--8212220331 Public version of Issue 0 to Radiological Emergency Response Plan Implementing Procedure EPP-18, "Operation of Technical Support Ctr/Emergency Offsite Facility Data Acquisition Sys."
* Dairyland Power Cooperative 82/11/17 4pp 16523 251 24X
Fiche 50-409, 82/12/10, 8212220315

8212210216 Forwards Amend 31 to License DPR-45, safety evaluation & notice of issuance & availability Amend approves revisions to physical security plan & safeguards contingency plan Encs withheld (ref 10CFR73.21)
CRUTCHFIELD, D Operating Reactors Branch 5 82/12/14 LINDER, F Dairyland Power Cooperative 5pp 16485 009 24X
Fiche 50-409, 82/12/14, 8212210216

8212220306 Discusses layout of communications equipment required in control room, onsite technical support ctr & near-site emergency operations facility
KEPPLER, J O Region 3, Office of Director 82/12/16 Commonwealth Edison Co 3pp 16503 351 24X Fiche 50-000, 82/12/16, 8212220306

DOCKETED ITEMS

2

P Operating license stage documents & correspondence

8212020086 "SEP Topic VII-3, Electrical, Instrumentation & Control Features of Sys Required for Safe Shutdown LACBWR," Interim rept
HAROLDSON, R O, FARMER, F G EO&G, Inc FIN A-6425 8212020086
82/10/31 SCHOLL, R F Office of Nuclear Reactor Regulation,
Director 17pp 16309 063 24X Fiche 50-409, 82/10/31, 8212020086

8212140001 Addl response to FOIA request for five categories of documents re SEP Forwards documents listed in App A No documents located suby to Item 3 of request Review of remaining documents continuing Documents available in PDR
FELTON, J M Division of Rules and Records 82/11/03 GALLIG, J
Jham, Lincoln & Beale 2pp 16433 354 24X Fiche 50-000, 82/11/03, 8212140001

--7907180391 Submits results of numerical values for spectral ordinates for facility
WIGHT, L H TERA Corp 79/07/11 REITER, L Geosciences Branch
7pp 16436 291 24X Fiche 50-000, 82/11/03, 8212140001

--7908090435 Forwards individual plant summaries re seismic capability & recommended interim actions Older SEP plants have less inherent margins to withstand lateral dynamic loads
DAVIS, D K Systematic Evaluation Program Branch (Pre 791030)
79/06/18 VOLLMER, R H Assistant Director for Systematic Evaluation Program (Pre 791030) 5pp 16434 321 24X
Fiche 50-000, 82/11/03, 8212140001

--8002200975 Notifies that review & performance of audit calculations to be continued per contract & preliminary review work to be completed at LaCrosse Code used for reanalysis of piping sys requires benchmarking per code verification program
SILVER, L C Assistant Director for Engineering Programs 79/10/30
EISENHUT, D O Division of Operating Reactors 1p 16435 111 24X Fiche 50-000, 82/11/03, 8212140001

--8003310489 Requests approval of proposed show cause order re seismic design changes Risk-benefit evaluation entirely appropriate for decisions
MALSCH, M O Office of the Executive Legal Director 80/02/19
AHEARNE, J F, GILINSKY, V, KENNEDY, R T Commissioners 2pp 16434 268 24X Fiche 50-000, 82/11/03, 8212140001

--8009170164 Advises that util 800804 rept, "Seismic & Structural Analysis of LACBWR & Genoa 3 Stacks," indicates that stack rests directly on foundation soil Info conflict w/740111 rept Factual determination should be obtained from util
LEAR, O E Hydrologic & Geotechnical Engineering Branch 80/09/08
CRUTCHFIELD, D Operating Reactors Branch 5 1p 16434 267 24X
Fiche 50-000, 82/11/03, 8212140001

--8203310670 Forwards SEP seismic completion plan to perform review parallel w/ license efforts to complete SEP Topic III-6, seismic design considerations, for Group II plants
HERMANN, R Systematic Evaluation Program Branch 82/03/08
RUSSELL, W T Systematic Evaluation Program Branch 5pp 16434 276 24X Fiche 50-000, 82/11/03, 8212140001

- 8212140149 Discusses SEP site-specific spectra project Project in final stages Comments from Peer Review Group & all other comments should be received by 791130 Listing of references re site-specific spectra (SEP Topic III-6) encl
LEVIN, H A Systematic Evaluation Program Branch 79/11/13
EISENHUT, D O Division of Operating Reactors 4pp 16436 300 24X Fiche 50-000, 82/11/03, 8212140001

8212020328 Forwards final SER for SEP Hydrology Topics II-3 A, II-3 B, II-3 B 1 & II-3 C Development of emergency plans & Tech Specs for site flooding & low water level required to complement emergency svc water supply sys
CRUTCHFIELD, D Operating Reactors Branch 5 82/11/12 LINDER, F
Dairyland Power Cooperative 24pp 16278 185 24X
Fiche 50-409, 82/11/12, 8212020328

--8209290122 "Hydrological Considerations (SEP, II-3A, B, B 1, C) Dairyland Power Cooperative, LACBWR," technical evaluation rept
SCHERRER, J S Franklin Institute/Franklin Research Center
NRC-03-79-118 TER-C5257-427 82/09/27 STALEY, O NRC - No Detailed Affiliation Given 50pp 16278 208 24X
Fiche 50-409, 82/11/12, 8212020328

8212080228 Forwards "1982 Evaluation of LACBWR" for review
TAYLOR, J Dairyland Power Cooperative 82/11/22 KEPPLER, J O
Region 3, Office of Director 1p 16354 137 24X
Fiche 50-409, 82/11/22, 8212080228

--8212080250 "1982 Evaluation of LACBWR "
* Institute of Nuclear Power Operations 82/10/31 35pp
16354 138 24X Fiche 50-409, 82/11/22, 8212080228

8212030024 Submits addl info re draft technical evaluation rept for control of heavy loads, per 821116 telcon Diagram of load paths handled by reactor bldg crane encl
LINDER, F Dairyland Power Cooperative 82/11/24 CRUTCHFIELD, D
Operating Reactors Branch 5 4pp 16304 330 24X
Fiche 50-409, 82/11/24, 8212030024

8212020245 Forwards final evaluation of SEP Topic III-4 A, "Tornado Missiles " Sys & components inadequately protected from tornado missiles
CRUTCHFIELD, D Operating Reactors Branch 5 82/11/29 LINDER, F
Dairyland Power Cooperative 16pp 16274 073 24X
Fiche 50-409, 82/11/29, 8212020245

8212070110 Submits addl info on post-accident containment radiation dose, per 821201 telcon Electrical equipment requiring environ qualification located in containment bldg reviewed for beta radiation sensitivity
LINDER, F Dairyland Power Cooperative 82/12/02 CRUTCHFIELD, D
Operating Reactors Branch 5 1p 16327 362 24X
Fiche 50-409, 82/12/02, 8212070110

8212080169 Forwards Amend 30 to License DPR-45 & notice of issuance Amend revises requirement to maintain guard training & qualification plan to be implemented within 60 days of approval & qualification of all security personnel
CRUTCHFIELD, D Operating Reactors Branch 5 82/12/06 LINDER, F
Dairyland Power Cooperative 4pp 16354 075 24X
Fiche 50-409, 82/12/06, 8212080169

--8212080174 Amend 30 to License DPR-45, including requirement to maintain guard training & qualification plan to be implemented within 60 days of issuance & requiring security personnel to be qualified within 2 yrs of approval
CRUTCHFIELD, D Operating Reactors Branch 5 82/12/06 3pp 16354 080 24X Fiche 50-409, 82/12/06, 8212080169

--8212080178 Notice of issuance & availability of Amend 30 to License DPR-45
* Operating Reactors Branch 5 82/12/06 2pp 16354 083 24X
Fiche 50-409, 82/12/06, 8212080169

8212150115 Forwards draft evaluation of SEP Topic III-7 B re design codes, design criteria & load combinations Review should be conducted to determine applicability of codes & ability of structures to resist increased loads
CRUTCHFIELD, D Operating Reactors Branch 5 82/12/09 LINDER, F
Dairyland Power Cooperative 11pp 16429 114 24X
Fiche 50-409, 82/12/09, 8212150115

--8209230258 "Design Codes, Design Criteria, & Loading Combinations (SEP, III-7B), LaCrosse (Genoa) Nuclear Generating Station," technical evaluation rept
STILHELL, T C Franklin Institute/Franklin Research Center
NRC-03-79-118 TER-C5257-325 82/09/20 PERBINKO, D NRC - No Detailed Affiliation Given 246pp 16429 125 24X
Fiche 50-409, 82/12/09, 8212150115

8212150154 Forwards SER of SEP Topic VI-4, "Containment Isolation Sys Four deviations from review guidelines identified Evaluation will be basic input to integrated safety assessment
CRUTCHFIELD, D Operating Reactors Branch 5 82/12/09 LINDER, F
Dairyland Power Cooperative 25pp 16423-242 24X
Fiche 50-409, 82/12/09, 8212150154

8212170204 Advises of plans to modify waste disposal bldg, due to need for greater flexibility in agent resin handling, FES, NUREG-0191, Section 3 & 4 should be revised to reflect mod.
LINDER, F Dairyland Power Cooperative 82/12/10 CRUTCHFIELD, D
Operating Reactors Branch 5 2pp 16459 321 24X
Fiche 50-409, 82/12/10, 8212170204

8212150039 Forwards evaluation of SEP Topic III-3 A, "Effects of High Water Levels on Structures " Containment bldg will remain undamaged by design basis flood concurrent w/3-ft high wave
CRUTCHFIELD, D Operating Reactors Branch 5 82/12/13 LINDER, F
Dairyland Power Cooperative 5pp 16421 325 24X
Fiche 50-409, 82/12/13, 8212150039

8212210216 Forwards Amend 31 to License DPR-45, safety evaluation & notice of issuance & availability Amend approves revisions to physical security plan & safeguards contingency plan Encls withheld (ref 10CFR73.21)
CRUTCHFIELD, D Operating Reactors Branch 5 82/12/14 LINDER, F
Dairyland Power Cooperative 5pp 16485 009 24X
Fiche 50-409, 82/12/14, 8212210216

DOCKETED ITEMS

8212280059 Forwards Revision 1 to "Seismic & Stress Analysis of LACBWR HPCS Discharge Line Piping Sys." Rept discusses discrepancies identified in RD 82-05 & noted between as-analyzed & as-built conditions of piping sys. LINDER, F. Dairyland Power Cooperative 82/12/16 CRUTCHFIELD, D. Operating Reactors Branch 5 12pp 16562 323 24X Fiche 50-409, 82/12/16, 8212280059

--8212280061 "Seismic & Stress Analysis of LACBWR HPCS Discharge Line Piping Sys." Revision 1 DBLIOADD, A., HUSAIN, I. Nuclear Energy Service, Inc. NEB 81A0091 R01 77/05/10 138pp 16562 335 24X Fiche 50-409, 82/12/16, 8212280059

8212280434 Board Notification 82-123 forwards USOS open file rept on "Probabilistic Estimates of Max Acceleration & Velocity in Rock in Contiguous US." MIRAGLIA, F. J. Assistant Director for Safety Assessment 82/12/17 Atomic Safety and Licensing Board Panel 5pp 16592 001 24X Fiche 50-409, 82/12/17, 8212280434

--8212280438 Open File Rept 82-1033, "Probabilistic Estimates of Max Acceleration & Velocity in Rock in Contiguous US." ALGERMISSEN, B., PERKINS, D. M., THENHAUS, P. C. Interior, Dept. of, Geological Survey 82-1033 82/12/31 113pp 16592 006 24X Fiche 50-409, 82/12/17, 8212280434

8212290320 Forwards SER & nonproprietary & proprietary versions of "Review of Licensee Resolution of Outstanding Issues From NRC Equipment Environ Qualification SERs (F-11, B-60)." Proprietary version withheld (ref 10CFR2 790) CRUTCHFIELD, D. Operating Reactors Branch 5 82/12/21 LINDER, F. Dairyland Power Cooperative. 3pp 16585 232 24X Fiche 50-409, 82/12/21, 8212290320

--8212290323 SER supporting util environ qualification of safety-related electrical equipment. * Office of Nuclear Reactor Regulation, Director 82/12/21 5pp 16585 235 24X Fiche 50-409, 82/12/21, 8212290320

--8207010410 "Review of Licensee Resolution of Outstanding Issues From NRC Equipment Environ Qualification SERs (F-11, B-60)," technical evaluation rept CRANE, C. J. Franklin Institute/Franklin Research Center NRC-03-79-118 TER-05257-464 82/06/25 LEIN, B. NRC - No Detailed Affiliation Given 268pp 16586 001 24X Fiche 50-409, 82/12/21, 8212290320

Q Inspection reports, IE Bulletins & correspondence

8208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants." Svc list encl DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co. of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240

8212060051 Forwards IE Insp Rept 50-409/82-17 on 821004-15 & notice of violation PAPERIELLO, C. J. Division of Emergency Preparedness & Operational Support 82/11/01 LINDER, F. W. Dairyland Power Cooperative 2pp 16314 080, 24X Fiche 50-409, 82/11/01, 8212060051

--8212060055 Notice of violation from insp on 821004-15 PAPERIELLO, C. J. Division of Emergency Preparedness & Operational Support 82/11/01 1p 16314 082 24X Fiche 50-409, 82/11/01, 8212060051

--8212060062 IE Insp Rept 50-409/82-17 on 821004-15 Noncompliance noted failure to perform monthly strontium analysis of liquid waste water composite NICHOLSON, N. A., LYNCH, J. L., SCHUMACHER, M. C. Division of Emergency Preparedness & Operational Support. 82/10/28 11pp 16314 083 24X Fiche 50-409, 82/11/01, 8212060051

8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters." Svc list encl COBB, L. I. Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co. of New York, Inc 110pp 16372 142 24X Fiche 50-000, 82/11/05, 8208190245

8212060249 Forwards IE Insp Rept 50-409/82-06 on 820510-14 & notice of violation KEFFLER, J. O. Region 3, Office of Director. 82/11/16 LINDER, F. W. Dairyland Power Cooperative 3pp 16312 288 24X Fiche 50-409, 82/11/16, 8212060249.

--8212060250 Notice of violation from insp on 820510-14 KEFFLER, J. O. Region 3, Office of Director. 82/11/16 3pp 16312 291 24X Fiche 50-409, 82/11/16, 8212060249.

--8212060252 IE Insp Rept 50-409/82-06 on 820510-14 Noncompliance noted inadequate shift staff augmentation capability & inadequate meteorological measurements procedures PAPERIELLO, C. J., GRANT, W. B., AXELSON, W. L. Division of Emergency Preparedness & Operational Support 82/11/10 16pp 16312 294 24X Fiche 50-409, 82/11/16, 8212060249

8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements." Svc list encl JORDAN, E. L. Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co. of New York, Inc 109pp 16411 199 24X Fiche 50-000, 82/11/18, 8208190251

8212150015 Forwards IE Emergency Plan Safety Evaluation Rept 50-409/82-15 during Nov 1982 No noncompliance noted HIND, J. A. Division of Emergency Preparedness & Operational Support 82/11/23 LINDER, F. W. Dairyland Power Cooperative 2pp 16421 181 24X Fiche 50-409, 82/11/23, 8212150015

--8212150019 IE Emergency Plan Safety Evaluation Rept 50-409/82-15 during Nov 1982 No noncompliance noted Major areas inspected 820903 site emergency plan PAPERIELLO, C. J., AXELSON, W. L., PAPERIELLO, C. J. Division of Emergency Preparedness & Operational Support 82/11/18 31pp 16421 182 24X Fiche 50-409, 82/11/23, 8212150015

8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Radiolocks." Svc list encl DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co. of New York, Inc 127pp 16411 065 24X Fiche 50-000, 82/11/26, 8208190256

8208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl." Svc list encl COBB, L. I. Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co. of New York, Inc 356pp 16387 028 24X Fiche 50-000, 82/11/30, 8208190257

8208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies." Svc list encl DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co. of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259

8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets." Svc list encl JORDAN, E. L. Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co. of New York, Inc 110pp 16462 064 24X Fiche 50-000, 82/12/03, 8208190261

8212090433 Ack receipt of 821115 ltr providing info on NUREG-0737, Test Action Item 11 F 1.1 re SPINQ equipment as requested in IE Insp Rept 50-409/82-14 PAUL, R. A. Region 3, Office of Director 82/12/03, SHAFFER, P. W. Dairyland Power Cooperative 1p 16364 278 24X Fiche 50-409, 82/12/03, 8212090433

--8212090440 Forwards info on NUREG-0737, Item 11 F 1.1 re SPINQ equipment as requested in IE Insp Rept 50-409/82-14 SPINQ-3 moved to stack shack replacing SPINQ-4 as normal operations stack particulate I-131 & noble gas monitor SHAFFER, P. W. Dairyland Power Cooperative 82/11/15 PAUL, R. Region 3, Office of Director 68pp 16364 279 24X Fiche 50-409, 82/12/03, 8212090433

8212140410 Ack receipt of 821124 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-409/82-17 PAPERIELLO, C. J. Division of Emergency Preparedness & Operational Support 82/12/08 LINDER, F. W. Dairyland Power Cooperative 1p 16404 330 24X Fiche 50-409, 82/12/08, 8212140410

--8212140417 Responds to NRC 821101 ltr re violations noted in IE Insp Rept 50-409/82-17 Corrective actions gravimetric strontium separation & analytical procedure replaced w/less complicated ion-exchange/gravimetric procedure LINDER, F. W. Dairyland Power Cooperative 82/11/24 PAPERIELLO, C. J. Division of Emergency Preparedness & Operational Support 5pp 16404 331 24X Fiche 50-409, 82/12/08, 8212140410

8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring." Svc list encl DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co. of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16, 8208190267

8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type 17E-27." Svc list encl JORDAN, E. L. Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co. of New York, Inc 108pp 16628 293 24X Fiche 50-000, 82/12/20, 8208190268

B212280091 Ack receipt of B21118 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-409/B2-16
MILLER, J R Division of Engineering & Technical Programs 82/12/20
LINDER, F W Dairyland Power Cooperative 2pp 16564 231 24X
Fiche 50-409, 82/12/20, B212280091

--B212280095 Forwards response to NRC B21026 ltr re violations noted in IE Insp Rept 50-409/B2-16 Response withheld (ref 10CFR73.21)
LINDER, F Dairyland Power Cooperative 82/11/18 MILLER, J R
Division of Engineering & Technical Programs 1p 16564 233 24X
Fiche 50-409, 82/12/20, B212280091

R Periodic operating reports & related correspondence

B212290220 Forwards monthly operating rept for Oct 1982
LINDER, F Dairyland Power Cooperative 82/11/10 Management
Information Branch 1p 16578 080 24X Fiche 50-409, 82/11/10, B212290220

--B212290222 Monthly operating rept for Oct 1982
GADDON, G R Dairyland Power Cooperative 82/11/10 Bpp
16578 081 24X Fiche 50-409, 82/11/10, B212290220

S Reportable occurrences, LERs & related correspondence

B212280253 Forwards LER B2-020/03L-0 Detailed event analysis submitted
LINDER, F Dairyland Power Cooperative 82/12/16 KEPPLER, J O
Region 3, Office of Director 1p 16561 181 24X
Fiche 50-409, 82/12/16, B212280253

--B212280256 LER B2-020/03L-0 on B21119 & 20, vacuum pump which maintains isokinetic flow rate to stack activity monitors tripped
Caused by overheating Air blower set up to cool motor
ODDAMAN, L S Dairyland Power Cooperative 82/12/16 Region 3,
Office of Director 2pp 16561 182 24X Fiche 50-409, 82/12/16, B212280253

DOCKET 50-410 NINE MILE POINT NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

B211230066 Generic Ltr B2-27 to all BWR licensees of operating reactors except LACBWR, Big Rock Point, Dresden 1, Humboldt Bay, applicants for OL & holders of CP re transmittal of NUREG-0763 & NUREG-0783 Svc list encl W/o stated encl
EISENHUT, D G Division of Licensing 82/11/15 General Public
Utilities - OPU Service Corp 22pp 16387 004 24X
Fiche 50-000, 82/11/15, B211230066

B212100207 Clarifies position on implementation of NF-2130 re bulk mat'l certification Policy will be documented in PSAR amend
WISE, D P Niagara Mohawk Power Corp 82/12/06 SCHWENCER, A
Licensing Branch 2 1p 16376 215 24X Fiche 50-410, 82/12/06, B212100207

G Inspection reports, IE Bulletins & correspondence

B208190240 IE Bulletin B2-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel Recirculation Sys Piping at BWR Plants " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, B208190240

B208190245 IE Info Notice B2-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list encl
CORB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000, 82/11/05, B208190245

B208190251 IE Info Notice B2-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X Fiche 50-000, 82/11/18, B208190251

B208190256 IE Info Notice B2-46, "Defective & Obsolete Combination Padlocks " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000, 82/11/26, B208190256

B212140490 Forwards IE Insp Rept 50-410/B2-12 on B21012-1112 & notice of violation
STAROSTECKI, R Division of Project & Resident Programs 82/11/29
KHODE, G K Niagara Mohawk Power Corp 2pp 16404 001 24X
Fiche 50-410, 82/11/29, B212140490

--B212140492 Notice of violation from insp on B21012-1112
* Division of Project & Resident Programs 82/11/29 1p
16404 003 24X Fiche 50-410, 82/11/29, B212140490

--B212140495 IE Insp Rept 50-410/B2-12 on B21012-1112 Noncompliance noted failure to submit planner package for safety-related piping to QC documentation supervisor for review & approval
SCHULZ, R D, KISTER, H B Division of Project & Resident Programs 82/11/20 Bpp 16404 004 24X Fiche 50-410, 82/11/29, B212140490

B208190257 IE Info Notice B2-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Mat'l " Svc list encl
CORB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000, 82/11/30, B208190257

B208190259 IE Bulletin B2-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, B208190259

B208190261 IE Info Notice B2-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X Fiche 50-000, 82/12/03, B208190261

B212150227 Notification of B21220 meeting w/util in Syracuse, NY to discuss BALP
KISTER, H Division of Project & Resident Programs 82/12/09
Division of Project & Resident Programs 2pp 16446 361 24X
Fiche 50-410, 82/12/09, B212150227

B208190267 IE Info Notice B2-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16, B208190267

B208190268 IE Info Notice B2-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27 " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X Fiche 50-000, 82/12/20, B208190268

S Reportable occurrences, LERs & related correspondence

B212030166 Interim deficiency rept re ITT Grinnell Category II planner for Category I work Initially reported on B21026 Evaluation of effects of flooding due to failure in progress Final rept expected by B30114
MANNO, S F Niagara Mohawk Power Corp 82/11/24 STAROSTECKI, R
Division of Project & Resident Programs 2pp 16306 103 24X
Fiche 50-410, 82/11/24, B212030166

B212140093 Interim deficiency rept re issuance of planners by ITT Grinnell w/o prior approval by S&W Initially reported on B21101 Work restarted as planners released by S&W Final rept will be submitted by B30131
MANNO, S F Niagara Mohawk Power Corp 82/12/01 STAROSTECKI, R
Division of Project & Resident Programs 2pp 16408 271 24X
Fiche 50-410, 82/12/01, B212140093

B212140372 Interim deficiency rept re enhancement of ITT Grinnell weld radiographs per IE Bulletin B2-01, Revision 1, Suppl 1 Initially reported on B21108 Review of Grinnell site radiographs in progress Final rept expected by B30131
MANNO, S F Niagara Mohawk Power Corp 82/12/06 STAROSTECKI, R
Division of Project & Resident Programs 2pp 16401 154 24X
Fiche 50-410, 82/12/06, B212140372

B212280363 Interim deficiency rept re inadequate pressure transducers/transmitters mounted on post-LOCA hydrogen recombiners Initially reported on B21119 Final rept will be submitted by B30211 Also reported per Part 21
MANNO, S F Niagara Mohawk Power Corp 82/12/14 STAROSTECKI, R
Division of Project & Resident Programs 2pp 16560 058 24X
Fiche 50-000, 82/12/14, B212280363

DOCKETED ITEMS

--B212280373 Part 21 rept re inadequate pressure transducers/transmitters mounted on post-LCCA hydrogen recombiners Transducers should be replaced w/nuclear rated transducers Engineering field bulletin to be issued by B21029
EMPEY, D C Rockwell International Corp B2/10/21 COLLINS, J
Region 4, Office of Director, 2pp 16560 060 24X
Fiche 50-000, B2/12/14, B212280363

DOCKET 50-412 BEAVER VALLEY POWER STATION, UNIT 2

A Application/construction stage documents & correspondence

B212170410 Notification of B21208 meeting w/util in Bethesda, MD to inform applicant of project manager assignment in Licensing Branch 3 to facility
LAZOL, L Licensing Branch 3 B2/12/06 KNIIGHTON, O W Licensing Branch 3 3pp 16478 155 24X Fiche 50-412, B2/12/06, B212170410

B212220403 Forwards amend to application for OL, consisting of general info required by environ rept, FSAR & 10CFR50 & 51
WOOLEVER, E J Duquesne Light Co B2/12/15 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 16504 291 24X
Fiche 50-412, B2/12/15, B212220403

--B212220404 Amend to application for OL, consisting of general info required by environ rept, FSAR & 10CFR50 & 51
WOOLEVER, E J Duquesne Light Co B2/12/15 30pp 16504 293 24X Fiche 50-412, B2/12/15, B212220403

M Antitrust correspondence

B212220283 Forwards info for OL antitrust review per Generic Ltr B2-14 Encl submittal addresses questions in Reg Guide 9.3 as applicable to all facility owners for period since CP antitrust review
WOOLEVER, E J Duquesne Light Co B2/12/15 DENTON, H R Office of Nuclear Reactor Regulation, Director 128pp 16516 117 24X
Fiche 50-412, B2/12/15, B212220283

Q Inspection reports, IE Bulletins & correspondence

B208190240 IE Bulletin B2-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement B2/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, B2/10/28, B208190240

B208190245 IE Info Notice B2-42, "Defects Observed in Panasonic Model B01 & Model B02 Thermoluminescent Dosimeters " Svc list encl
COBB, L J Division of Fuel Facilities, Materials & Safeguards B2/11/05 Consolidated Edison Co. of New York, Inc 110pp 16372 142 24X Fiche 50-000, B2/11/05, B208190245

B208190251 IE Info Notice B2-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance B2/11/18 Consolidated Edison Co of New York, Inc. 109pp 16411 199 24X
Fiche 50-000, B2/11/18, B208190251

B212060189 Forwards IE Insp Rept 50-412/B2-13 on B21004-1102 No noncompliance noted
STAROSTECKI, R Division of Project & Resident Programs B2/11/22 WOOLEVER, E J Duquesne Light Co 2pp 16313 066 24X
Fiche 50-412, B2/11/22, B212060189

--B212060192 IE Insp Rept 50-412/B2-13 on B21004-1102, No noncompliance noted Major areas inspected welding activities, nondestructive exams, piping support installation procedure review, site tours & unresolved items
WALTON, G, TRIPP, L Division of Project & Resident Programs B2/11/19 4pp. 16313 068 24X Fiche 50-412, B2/11/22, B212060189

B208190256 IE Info Notice B2-46, "Defective & Obsolete Combination Padlocks " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement B2/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000, B2/11/26, B208190256

B208190257 IE Info Notice B2-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl
COBB, L J Division of Fuel Facilities, Materials & Safeguards B2/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000, B2/11/30, B208190257

B208190259 IE Bulletin B2-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement B2/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, B2/12/03, B208190259

B208190261 IE Info Notice B2-48, "Failures of Agastat CR 0075 Relay Sockets " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance B2/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X
Fiche 50-000, B2/12/03, B208190261

B212140424 Ack receipt of B21020 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-412/B2-09
STAROSTECKI, R Division of Project & Resident Programs B2/12/07 WOOLEVER, E J Duquesne Light Co 2pp 16404 013 24X
Fiche 50-412, B2/12/07, B212140424

--B212140427 Responds to NRC B20914 ltr re violations noted in IE Insp Rept 50-412/B2-09 Corrective actions engineering evaluation of condition of affected seating will be performed & ESHC cards will be issued for valves requiring maint
WOOLEVER, E J Duquesne Light Co B2/10/20 STAROSTECKI, R Division of Project & Resident Programs 3pp 16404 015 24X
Fiche 50-412, B2/12/07, B212140424

B208190267 IE Info Notice B2-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement B2/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, B2/12/16, B208190267

B208190268 IE Info Notice B2-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27 " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance B2/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X
Fiche 50-000, B2/12/20, B208190268

S Reportable occurrences, LERs & related correspondence

B212140043 PND-I-B2-078 on B21206, security guard caught w/marijuana cigarette & fired Resident inspector informed on B21208
No police charges filed
WALTON, G, LAZARUS, W Region 1, Office of Director B2/12/09 1p 16408 278 24X Fiche 50-412, B2/12/09, B212140043

DOCKET 50-413 CATAWBA NUCLEAR STATION, UNIT 1

A Application/construction stage documents & correspondence

B212030080 Forwards info demonstrating compliance w/10CFR20.50 & 100 regulations, in response to B21027 request
TUCKER, H B Duke Power Co B2/11/30 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAH, E G Licensing Branch 4 33pp 16304 261 24X Fiche 50-413, B2/11/30, B212030080

B212030049 Forwards responses & revised responses to FSAR open items
TUCKER, H B Duke Power Co B2/12/01 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAH, E G Licensing Branch 4 82pp 16305 082 24X Fiche 50-413, B2/12/01, B212030049

B212130257 Forwards summary of B21103-04 meeting w/Mechanical Engineering Branch & BNWL in Charlotte, NC to discuss open items from previous meetings W/ eight oversize drawings
Aperture cards are available in PDR
TUCKER, H B Duke Power Co B2/12/06 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAH, E G Licensing Branch 4 59pp 16411 011 24X Fiche 50-413, B2/12/06, B212130257

B212140263 Forwards Westinghouse proprietary & nonproprietary versions of response to NRC request for addl info re improved thermal design procedures
TUCKER, H B Duke Power Co B2/12/08 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAH, E G Licensing Branch 4 2pp 16406 092 24X Fiche 50-413, B2/12/08, B212140263

--B212140312 Affidavit of RA Wiesemann re Westinghouse proprietary info in util submittal on improved thermal design procedures
WIESEMAN, R A Westinghouse Electric Corp B2/12/02 7pp 16406 099 24X Fiche 50-413, B2/12/08, B212140263

--B212140318 Submits response to NRC request for addl info on improved thermal design procedures Nonproprietary version encl
Proprietary version withheld
TWOOOD, F J Westinghouse Electric Corp B2/12/03 CANADY, R S Duke Power Co 51pp 16406 102 24X Fiche 50-413, B2/12/08, B212140263

8212140267 Requests Westinghouse proprietary matl in util submittal re improved thermal design procedures be withheld (ref 10CFR2 790) Affidavit encl
WIEBEMANN, R A Westinghouse Electric Corp 82/12/02 DENTON, H R
Office of Nuclear Reactor Regulation, Director ADENSAH, E O
Licensing Branch 4 1p 16406 094 24X Fiche 50-413, 82/12/08,
8212140267

8212160044 Forwards summary of 821116-18 meetings w/Westinghouse & NRC in Bethesda, MD re open items from previous meetings
List of attendees encl
TUCKER, H B Duke Power Co 82/12/08 DENTON, H R Office of
Nuclear Reactor Regulation, Director ADENSAH, E O Licensing Branch
4 11pp 16446 077 24X Fiche 50-413, 82/12/08, 8212160044

8212150232 Notification of 821214 meeting w/util in Bethesda, MD to discuss resolution of Reactor Sys Branch open items & concerns
JABBOUR, K N Licensing Branch 4 82/12/09 ADENSAH, E O Licensing
Branch 4 3pp 16446 356 24X Fiche 50-413, 82/12/09, 8212150232

8212220015 Notification of 821215 meeting w/util & Westinghouse in Bethesda, MD to discuss resolution of Containment Sys Branch open items
JABBOUR, K N Licensing Branch 4 82/12/09 ADENSAH, E O Licensing
Branch 4 3pp 16329 097 24X Fiche 50-413, 82/12/09, 8212220015

8212290354 Forwards response to question re diesel generator operation during adverse environ conditions, per 821013 request Based on past 30 yrs of weather data, lowest recorded outside temp was -5 F
TUCKER, H B Duke Power Co 82/12/09 DENTON, H R Office of
Nuclear Reactor Regulation, Director ADENSAH, E O Licensing Branch
4 9pp 16586 168 24X Fiche 50-413, 82/12/09, 8212290354

8212160345 Forwards responses or revised responses to open items of listed technical review branches to facilitate completion of FSAR review Responses to be included in FSAR, Revision 7
TUCKER, H B Duke Power Co 82/12/10 DENTON, H R Office of
Nuclear Reactor Regulation, Director ADENSAH, E O Licensing Branch
4 43pp 16442 040 24X Fiche 50-413, 82/12/10, 8212160345

8212170422 Notification of 821213 meeting w/util in Bethesda, MD to discuss resolution of Reactor Sys Branch open items re safety valve sizing analyses
JABBOUR, K N Licensing Branch 4 82/12/10 ADENSAH, E O Licensing
Branch 4 20pp 16478 114 24X Fiche 50-413, 82/12/10, 8212170422

8212270261 Transmits responses to open items of listed technical review branches to complete FSAR review Responses will be included in FSAR Revision 7 4/23 oversize drawings Aperture cards are available in PDR Three drawings illegible
TUCKER, H B Duke Power Co 82/12/15 DENTON, H R Office of
Nuclear Reactor Regulation, Director ADENSAH, E O Licensing Branch
4 84pp 16533 316 24X Fiche 50-413, 82/12/15, 8212270261

8212220227 Forwards response to 821220 generic ltr re NUREG-0612, "Control of Heavy Loads," Section 2.2 for spent fuel pool areas & Section 2.4 for auxiliary bldgs Ice condenser bridge crane design specs listed
TUCKER, H B Duke Power Co 82/12/16 DENTON, H R Office of
Nuclear Reactor Regulation, Director ADENSAH, E O Licensing Branch
4 81pp 16518 332 24X Fiche 50-413, 82/12/16, 8212220227

D NRC Draft/Final Environmental Statements, suppl's & correspondence

8212220093 Requests mgt review & comment on FEB scheduled for issuance on 830105 Comments & changes must be forwarded by noon on 821217 to allow time for final approval
ADENSAH, E O Licensing Branch 4 82/12/13 LEAR, G E Hydrologic & Geotechnical Engineering Branch BALLARD, R L Environmental Engineering Branch TOALBTON, A Antitrust & Economic analysis Branch (Utility Finance) 2pp 16526 346 24X
Fiche 50-413, 82/12/13, 8212220093

E NRC Safety Evaluation Report (SER), suppl's & correspondence

8212030317 Forwards, for review & comment, Reactor Sys Branch preliminary draft SER input Transmittal provides for identification & resolution of add'l analysis, missing info, clarifications or other work necessary to resolve outstanding issues
NOVAK, T M Assistant Director for Licensing 82/11/30 TUCKER, H
Duke Power Co 46pp 16316 169 24X Fiche 50-413, 82/11/30,
8212030317

F Security, medical, emergency & fire protection plans

8212130069 Forwards info on emergency offsite facilities (EOF), per R Birkel 821203 request & Generic Ltr 81-10 Const of permanent primary & backup EOF completed
TUCKER, H B Duke Power Co 82/12/03 DENTON, H R Office of
Nuclear Reactor Regulation, Director 2pp 16390 186 24X
Fiche 50-000, 82/12/03, 8212130069

8212230093 Releases public version of revision to crisis mgt plan & revisions to crisis mgt plan implementing procedures
FELTON, J M Division of Rules and Records 82/12/15 Document
Management Branch 1p 16542 026 24X Fiche 50-000, 82/12/15,
8212230093

--8212230108 Forwards public version of Revision 7 to crisis mgt plan & revisions to crisis mgt plan implementing procedures
TUCKER, H B Duke Power Co 82/12/02 DENTON, H R Office of
Nuclear Reactor Regulation, Director 2pp 16542 027 24X
Fiche 50-000, 82/12/15, 8212230093

--8212230124 Public version of Revision 7 to crisis mgt plan One oversize pamphlet encl Aperture card available in PDR
VAUGHN, R E Duke Power Co 82/11/29 9pp 16542 029 24X
Fiche 50-000, 82/12/15, 8212230093

--8212230134 Public version of revised crisis mgt plan implementing procedures, including Procedures 5.3.2 re crisis news group plan & 5.3.11 re McGuire crisis phone directory
VAUGHN, R E Duke Power Co 82/11/29 280pp 16542 038 24X
Fiche 50-000, 82/12/15, 8212230093

G Adjudicatory correspondence

8212060135 Memorandum & order reflecting decisions made following 821007-08 second prehearing conference in Charlotte, NC
Impact of ALAB-687 on contentions determined & add'l contentions re DES considered
KELLEY, J L Atomic Safety and Licensing Board Panel 82/12/01
29pp 16314 040 24X Fiche 50-413, 82/12/01, 8212060135

8212060243 Order extending time until 821210 for Commission to act to review ALAB-687
CHILK, S J Office of the Secretary of the Commission 82/12/03
Commissioners 1p 16312 236 24X Fiche 50-413, 82/12/03,
8212060243

8212070178 Interrogatories & requests to produce re Carolina Environ Study Group Contention 18/Palmetto Alliance Contention 44
Certificate of Svc encl Related correspondence
* Duke Power Co 82/12/03 Carolina Environmental Study Group
15pp 16334 299 24X Fiche 50-413, 82/12/03, 8212070178

8212100096 Response supporting NRC 821122 motion for sanctions against Palmetto Alliance for failure to comply w/ASLB ordered discovery, or alternatively, for dismissal of Alliance Contentions 8.16 & 17 Certificate of Svc encl
CARR, A V Duke Power Co 82/12/07 Atomic Safety and Licensing
Board Panel 49pp 16379 191 24X Fiche 50-413, 82/12/07,
8212100096

8212130362 Requests review of encl ASLB 821201 memorandum & order, containing add'l info re ASLB views on what NRC comments should address Updates may be necessary
ADENSAH, E O Licensing Branch 4 82/12/08 LEAR, G E Hydrologic & Geotechnical Engineering Branch BALLARD, R L Environmental Engineering Branch TOALBTON, A Antitrust & Economic analysis Branch (Utility Finance) 2pp 16412 183 24X
Fiche 50-413, 82/12/08, 8212130362

8212130230 Motion for resumption of discovery as listed Several discovery matters remain outstanding Certificate of Svc encl Related correspondence
MCGARRY, J M Duke Power Co MCGARRY, J M Debevoise & Liberman
82/12/09 Atomic Safety and Licensing Board Panel 5pp
16396 264 24X Fiche 50-413, 82/12/09, 8212130230

8212130214 Order extending time until 821217 for Commission to act to review ALAB-687
CHILK, S J Office of the Secretary of the Commission 82/12/10
Commissioners 1p 16390 116 24X Fiche 50-413, 82/12/10,
8212130214

8212150127 Statement of position on applicability of Table 6-4 to transshipment of spent fuel from Oconee & McGuire to Catauba Environ Impact of spent fuel transportation properly considered in OL hearings W/Certificate of Svc
JOHNSON, O E Hearing Branch 4 82/12/13 18pp 16430 320 24X
Fiche 50-413, 82/12/13, 8212150127

DOCKETED ITEMS

8212160261 Position on consideration of Oconee & McGuire spent fuel transportation issues in proceeding Environ effects of transporting fuel to Catawba should not be litigated in instant proceeding Certificate of Svc encl
MCGARRY, J M Duke Power Co MCGARRY, J M Debevoise & Liberman.
82/12/13 22pp 16446 173 24X Fiche 50-413, 82/12/13, 8212160261

8212150124 Forwards NRC first set of interrogatories & document production requests to replace lost copy Confirms stipulation reached in 821213 telcon that responses will be provided by 821228
JOHNSON, G E Hearing Branch 4 82/12/14 PRESLER, H
Charlotte-Mecklenburg Environmental Coalition 1p 16430 310 24X
Fiche 50-413, 82/12/14, 8212150124

8212160235 Motion for protective order re listed Palmetto Alliance third set of interrogatories Interrogatories seek info which is irrelevant, requires compilation of mats not readily available or is protected by work product doctrine
JOHNSON, G E Hearing Branch 4 82/12/15 Atomic Safety and Licensing Board Panel 9pp 16443-101 24X Fiche 50-413, 82/12/15, 8212160235

--8212160240 Response to third set of interrogatories & requests to produce re Palmetto Alliance Contentions 16 & 44 Prof qualifications & Certificate of Svc encl
JOHNSON, G E Hearing Branch 4 82/12/15 Palmetto Alliance
163pp 16443 110 24X Fiche 50-413, 82/12/15, 8212160235

8212160256 Third set of interrogatories & document production requests Certificate of Svc encl
JOHNSON, G E Hearing Branch 4 82/12/15 Palmetto Alliance
10pp 16445 163 24X Fiche 50-413, 82/12/15, 8212160256

8212160303 Second set of interrogatories & document production requests Certificate of Svc encl
JOHNSON, G E Hearing Branch 4 82/12/15 Carolina Environmental Study Group 10pp 16442-322 24X Fiche 50-413, 82/12/15, 8212160303

8212170180 Forwards RO Gonzales affidavit & second page of JJ Buzy statement of prof qualifications, inadvertently omitted from NRC 821215 responses to Palmetto Alliance third set of interrogatories & requests to produce
JOHNSON, G E Hearing Branch 4 82/12/16 GUILD, R Guild, R 4pp
16430 188 24X Fiche 50-413, 82/12/16, 8212170180

8212170186 Motion to compel full responses to NRC first set of interrogatories & document production requests to Palmetto Alliance on Contention 7 Intervenor must answer contentions on factual & legal bases Certificate of Svc encl.
JOHNSON, G E Hearing Branch 4 82/12/16 Atomic Safety and Licensing Board Panel 10pp 16450 168 24X Fiche 50-413, 82/12/16, 8212170186

8212210242 Order extending time until 821223 for Commission to act to review ALAB-687
CHILK, S J Office of the Secretary of the Commission 82/12/17
Commissioners 1p 16484 080 24X Fiche 50-413, 82/12/17, 8212210242

8212210317 Advises that NRC does not intend to file answer to until 821209 motion re discovery NRC already answered Palmetto Alliance Contention 44 & filed motion to compel answers to NRC interrogatories on Palmetto Contention 7
JOHNSON, G E Hearing Branch 4 82/12/20 KELLEY, J L, FOBT, R F, CALLIHAN, D
Atomic Safety and Licensing Board Panel. 1p 16496 290 24X Fiche 50-413, 82/12/20, 8212210317

8212220232 Motion to compel Prairie Alliance answers to Util interrogatories re Palmetto Alliance Contentions 6 & 7 or alternatively, to dismiss contentions Alliance fails to satisfy Commission rules & regulations
MCGARRY, J M Duke Power Co MCGARRY, J M Debevoise & Liberman
82/12/20 Atomic Safety and Licensing Board Panel 32pp
16518 234 24X Fiche 50-413, 82/12/20, 8212220232

--8212220239 Response opposing Palmetto Alliance motion for protective order from applicant discovery Alliance motion impermissibly vague & fails to demonstrate applicability of atty/client privilege or work product doctrine W/Certificate of Svc
MCGARRY, J M Duke Power Co MCGARRY, J M Debevoise & Liberman
82/12/20 Atomic Safety and Licensing Board Panel 14pp
16518; 266 24X Fiche 50-413, 82/12/20, 8212220232

8212270244 Motion to compel Palmetto Alliance to respond further to interrogatories re Alliance Contentions 6 & 7 Discovery of bases for contentions permitted Contention 7 should be dismissed
MCGARRY, J M Duke Power Co. MCGARRY, J M Debevoise & Liberman.
82/12/20 Atomic Safety and Licensing Board Panel 32pp
16537 166 24X Fiche 50-413, 82/12/20, 8212270244

8212270321 Response opposing Palmetto Alliance 820428 motion for protective order re Contentions 6 & 7 Alliance has not demonstrated applicability of atty-client or work product privileges
MCGARRY, J M Duke Power Co MCGARRY, J M Debevoise & Liberman
82/12/20 Atomic Safety and Licensing Board Panel 12pp
16530 266 24X Fiche 50-413, 82/12/20, 8212270321

8212280132 Objections to ASLB 821201 order & motion for reconsideration or for certification Contentions 18 re emergency diesel generator operation & 17 re carbicula infestation effect on cooling sys should be admitted Certificate of Svc encl
GUILD, R Palmetto Alliance GUILD, R Carolina Environmental Study Group GUILD, R Guild, R 82/12/20 Atomic Safety and Licensing Board Panel 8pp 16563 212 24X Fiche 50-413, 82/12/20, 8212280132

8212280138 Comments on transshipment of spent fuel from Oconee & McGuire for storage at Catawba Table 8-4 inapplicable Contentions DES 10 & DES 19 should be admitted
GUILD, R Palmetto Alliance GUILD, R Carolina Environmental Study Group GUILD, R Guild, R 82/12/20 Atomic Safety and Licensing Board Panel 5pp 16563 207 24X Fiche 50-413, 82/12/20, 8212280138

8212270226 Memorandum & order ruling on various disputes Palmetto Alliance waived all claims to privilege & thus must answer interrogatories Alliance 820830 motion for protective order & NRC motion for sanctions denied
KELLY, J L Atomic Safety and Licensing Board Panel 82/12/22
Palmetto Alliance 93pp 16535 004 24X Fiche 50-413, 82/12/22, 8212270226

8212270251 Order establishing Commission review of ASLB Decision ALAB-687 Commission will review issues re Atomic Energy Act, Section 189a & definition of good cause for late filing Briefs due in 30 days & reply briefs in 30
CHILK, S J Office of the Secretary of the Commission 82/12/23
3pp 16530 055 24X Fiche 50-413, 82/12/23, 8212270251

8212280174 Requests complete copy of Palmetto Alliance & Carolina Environ Study Group objections to ASLB 821201 order & motion for reconsideration or certification
CARR, A V Duke Power Co 82/12/23 GUILD, R Guild, R RILEY, J L
Affiliation Unknown 1p 16563 141 24X Fiche 50-413, 82/12/23, 8212280174

8212290002 Requests complete copy of Palmetto Alliance & Carolina Environ Study Group 821220 objections to ASLB 821201 order & motion for reconsideration or certification
JOHNSON, G E Hearing Branch 4 82/12/27 GUILD, R Palmetto Alliance GUILD, R Guild, R 1p 16582 240 24X
Fiche 50-413, 82/12/27, 8212290002

8212300010 Serves Commission 821223 order & underlying decision ALAB-687 W/o encl
STUCKY, S W Docketing & Services Branch 82/12/28 Natural Resources Defense Council 1p 16598 261 24X
Fiche 50-413, 82/12/28, 8212300010

Q Inspection reports, IE Bulletins & correspondence

8208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc.
112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240

8212090482 Ack receipt of IE Insp Repts 50-413/82-24 & 50-414/82-22 No proprietary info
TUCKER, H B Duke Power Co 82/10/28 O'REILLY, J P Region 2, Office of Director 1p 16363 286 24X Fiche 50-413, 82/10/28, 8212090482

8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model B01 & Model B02 Thermoluminescent Dosimeters " Svc list encl
COBB, L J Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp
16372-142 24X Fiche 50-000, 82/11/05, 8208190245

8212090233 Advises that no piping subassemblies exist within scope of IE Bulletin 82-01, Revision 1, Suppl 1, in response to 820818 transmittal
TUCKER, H B Duke Power Co 82/11/05 O'REILLY, J P Region 2, Office of Director 1p 16361 348 24X Fiche 50-413, 82/11/05, 8212090233

8212090442 Ack receipt of IE Insp Repts 50-413/82-25 & 50-414/82-23 No proprietary info
TUCKER, H B Duke Power Co 82/11/11 O'REILLY, J P Region 2, Office of Director 1p 16364 252 24X Fiche 50-413, 82/11/11, 8212090442

8212090459 Forwards IE Insp Repts 50-413/82-28 & 50-414/82-26 on 821026-29 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 82/11/15
TUCKER, H B Duke Power Co 2pp 16363 357 24X
Fiche 50-413, 82/11/15, 8212090459

--8212090465 IE Insp Repts 50-413/82-28 & 50-414/82-26 on 821026-29 No noncompliance noted Major areas inspected instrumentation components & sys work activities, QC records, instrumentation cables & action on previous insp matters
QIBBONS, T B , CONLON, T E Division of Engineering & Technical Programs 82/11/10 4pp 16363 359 24X Fiche 50-413, 82/11/15, 8212090459

8212090522 Ack receipt of IE Insp Repts 50-413/82-26 & 50-414/82-24 No proprietary info
TUCKER, H B Duke Power Co 82/11/17 O'REILLY, J P Region 2, Office of Director 1p 16366 362 24X Fiche 50-413, 82/11/17, 8212090522

8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X
Fiche 50-000, 82/11/18, 8208190251

8212090232 Ack receipt of 821027 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-413/82-21 & 50-414/82-19
LEWIS, R C Division of Project & Resident Programs 82/11/18
TUCKER, H B Duke Power Co 1p 16362 314 24X
Fiche 50-413, 82/11/18, 8212090232

--8212090239 Responds to NRC 820930 ltr re violations noted in IE Insp Repts 50-413/82-21 & 50-414/82-19 Corrective actions defective base metal indication in Class B weld repaired Clearance criteria added to Design Drawing ICS-A-20 4
TUCKER, H B Duke Power Co 82/10/29 O'REILLY, J P Region 2, Office of Director 4pp 16362 315 24X Fiche 50-413, 82/11/18, 8212090232

--8212090246 Forwards IE Insp Repts 50-413/82-21 & 50-414/82-19 on 820726-0825 & notice of violation
LEWIS, R C Division of Project & Resident Programs 82/09/30
TUCKER, H B Duke Power Co 2pp 16362 319 24X
Fiche 50-413, 82/11/18, 8212090232

--8212090251 Notice of violation from insp on 820726-0825
* Division of Project & Resident Programs 82/09/30 3pp
16362 321 24X Fiche 50-413, 82/11/18, 8212090232

--8212090261 IE Insp Repts 50-413/82-21 & 50-414/82-19 on 820726-0825 Noncompliance noted failure to evaluate rejectable defect identified by radiography adequately & failure to include qualitative acceptance criteria in drawings
VANDORRN, P K , BRYANT, J C Division of Project & Resident Programs 82/09/29 8pp 16362 324 24X Fiche 50-413, 82/11/18, 8212090232

8212090317 Forwards IE Insp Repts 50-413/82-27 & 50-414/82-25 on 821026-29 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 82/11/19
TUCKER, H B Duke Power Co 2pp 16365 105 24X
Fiche 50-413, 82/11/19, 8212090317

--8212090324 IE Insp Repts 50-413/82-27 & 50-414/82-25 on 821026-29 No noncompliance noted Major areas inspected const progress, reactor vessel internals & licensee action on previous enforcement matters
ECONOMOS, N , BLAKE, J J Division of Engineering & Technical Programs 82/11/12 6pp 16365 107 24X Fiche 50-413, 82/11/19, 8212090317

8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000, 82/11/26, 8208190256

8208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16367 029 24X Fiche 50-000, 82/11/30, 8208190257

8208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259

8208190261 IE Info Notice 82-46, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X
Fiche 50-000, 82/12/03, 8208190261

8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16, 8208190267

8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27 " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X
Fiche 50-000, 82/12/20, 8208190268

S Reportable occurrences, LERs & related correspondence

8212170256 Interim Significant Deficiency Rept SD 413-414/82-23 re violation of approved const procedures for mixing & placing SikaTop 122 during drill hole repair Initially reported on 821108 Test program initiated Final rpt due by 830506
TUCKER, H B Duke Power Co 82/12/08 O'REILLY, J P Region 2, Office of Director 3pp 16457 170 24X Fiche 50-413, 82/12/08, 8212170256

8212150086 PNO-11-82-135 on 821209, contractor employee arrested & charged w/blackmail, including extortion & threat to kill, injure or intimidate Arrest followed 3 day investigation as result of bomb threats on 821206, 07 & 08
MOORE, D E , BRYANT, J C Region 2, Office of Director 82/12/09 2pp 16431 024 24X Fiche 50-413, 82/12/09, 8212150086

8212210231 Significant Deficiency Rept SD 413-414/82-24 re ITT Barton Class IE transmitters exhibiting thermal non-repeatability Initially reported on 821112 Problem eliminated by addition of insulating spacers between potentiometers & brackets
TUCKER, H B Duke Power Co 82/12/10 O'REILLY, J P Region 2, Office of Director 6pp 16483 351 24X Fiche 50-413, 82/12/10, 8212210231

DOCKET 50-414 CATAWBA NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

8212030080 Forwards info demonstrating compliance w/10CFR20, 50 & 100 regulations, in response to 821027 request
TUCKER, H B Duke Power Co 82/11/30 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENBAM, E O Licensing Branch 4 33pp 16304 261 24X Fiche 50-413, 82/11/30, 8212030080

8212030049 Forwards responses & revised responses to FSAR open items
TUCKER, H B Duke Power Co 82/12/01 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENBAM, E O Licensing Branch 4 82pp 16305 082 24X Fiche 50-413, 82/12/01, 8212030049

8212130257 Forwards summary of 821103-04 meeting w/Mechanical Engineering Branch & BNWL in Charlotte, NC to discuss open items from previous meetings w/eight oversize drawings Aperture cards are available in PDR
TUCKER, H B Duke Power Co 82/12/04 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENBAM, E O Licensing Branch 4 55pp 16411 011 24X Fiche 50-413, 82/12/04, 8212130257

8212140263 Forwards Westinghouse proprietary & nonproprietary versions of response to NRC request for addl info re improved thermal design procedures
TUCKER, H B Duke Power Co 82/12/08 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENBAM, E O Licensing Branch 4 2pp 16406 092 24X Fiche 50-413, 82/12/08, 8212140263

--8212140312 Affidavit of RA Wiesemann re Westinghouse proprietary info in util submittal on improved thermal design procedures
WIESEMAN, R A Westinghouse Electric Corp 82/12/02 7pp 16406 095 24X Fiche 50-413, 82/12/08, 8212140263

--8212140318 Submits response to NRC request for addl info on improved thermal design procedures Nonproprietary version encl Proprietary version withheld
WIDOMOOD, F J Westinghouse Electric Corp 82/12/03 CANADY, K B Duke Power Co 51pp 16406 102 24X Fiche 50-413, 82/12/08, 8212140263

DOCKETED ITEMS

8212140267 Requests Westinghouse proprietary matl in util submittal re improved thermal design procedures be withheld (ref 10CFR2.790) Affidavit encl
WIEGEMANN, R A Westinghouse Electric Corp 82/12/02 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 1p 16406 094 24X Fiche 50-413, 82/12/08, 8212140267

8212160044 Forwards summary of 821116-18 meetings w/Westinghouse & NRC in Bethesda, MD re open items from previous meetings
List of attendees encl
TUCKER, H B Duke Power Co 82/12/08 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 11pp 16446 077 24X Fiche 50-413, 82/12/08, 8212160044

8212150232 Notification of 821214 meeting w/util in Bethesda, MD to discuss resolution of Reactor Sys Branch open items & concerns
JABBOUR, K N Licensing Branch 4 82/12/09 ADENSAM, E G Licensing Branch 4 3pp 16446 356 24X Fiche 50-413, 82/12/09, 8212150232

8212220015 Notification of 821215 meeting w/util & Westinghouse in Bethesda, MD to discuss resolution of Containment Sys Branch open items
JABBOUR, K N Licensing Branch 4 82/12/09 ADENSAM, E G Licensing Branch 4 3pp 16529 097 24X Fiche 50-413, 82/12/09, 8212220015

8212290354 Forwards response to question re diesel generator operation during adverse environ conditions, per 821013 request based on past 30 yrs of weather data, lowest recorded outside temp was -5 F
TUCKER, H B Duke Power Co 82/12/09 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 9pp 16586 168 24X Fiche 50-413, 82/12/09, 8212290354

8212160345 Forwards responses or revised responses to open items of listed technical review branches to facilitate completion of FSAR review Responses to be included in FSAR, Revision 7
TUCKER, H B Duke Power Co 82/12/10 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 43pp 16442 040 24X Fiche 50-413, 82/12/10, 8212160345

8212170422 Notification of 821213 meeting w/util in Bethesda, MD to discuss resolution of Reactor Sys Branch open items re safety valve sizing analyses
JABBOUR, K N Licensing Branch 4 82/12/10 ADENSAM, E G Licensing Branch 4 20pp 16478 114 24X Fiche 50-413, 82/12/10, 8212170422

8212270261 Transmits responses to open items of listed technical review branches to complete FSAR review Responses will be included in FSAR Revision 7 W/23 oversize drawings Aperture cards are available in PDR Three drawings illegible
TUCKER, H B Duke Power Co 82/12/15 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 84pp 16533 316 24X Fiche 50-413, 82/12/15, 8212270261

8212220227 Forwards response to 821220 generic ltr re NUREG-0612, "Control of Heavy Loads," Section 2.2 for spent fuel pool areas & Section 2.4 for auxiliary bldgs Ice condenser bridge crane design specs listed
TUCKER, H B Duke Power Co 82/12/16 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 81pp 16518 332 24X Fiche 50-413, 82/12/16, 8212220227

D NRC Draft/Final Environmental Statements, suppl's & correspondence

8212220093 Requests mgt review & comment on FEB scheduled for issuance on 830105 Comments & changes must be forwarded by noon on 821217 to allow time for final approval
ADENSAM, E G Licensing Branch 4 82/12/13 LEAR, G E Hydrologic & Geotechnical Engineering Branch BALLARD, R L Environmental Engineering Branch TOALSTON, A Antitrust & Economic analysis Branch (Utility Finance) 2pp 16526 346 24X Fiche 50-413, 82/12/13, 8212220093

E NRC Safety Evaluation Report (SER), suppl's & correspondence

8212030317 Forwards, for review & comment, Reactor Sys Branch preliminary draft SER input Transmittal provides for identification & resolution of addl analysis, missing info, clarifications or other work necessary to resolve outstanding issues
NOVAK, T M Assistant Director for Licensing 82/11/30, TUCKER, H B Duke Power Co 46pp 16316 169 24X Fiche 50-413, 82/11/30, 8212030317

F Security, medical, emergency & fire protection plans

8212130069 Forwards info on emergency offsite facilities (EOF), per R Birkel 821203 request & Generic Ltr 81-10 Const of permanent primary & backup EOF completed
TUCKER, H B Duke Power Co 82/12/03 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 16390 186 24X Fiche 50-000, 82/12/03, 8212130069

8212230093 Releases public version of revision to crisis mgt plan & revisions to crisis mgt plan implementing procedures
FELTON, J M Division of Rules and Records 82/12/15 Document Management Branch 1p 16542 026 24X Fiche 50-000, 82/12/15, 8212230093

--8212230108 Forwards public version of Revision 7 to crisis mgt plan & revisions to crisis mgt plan implementing procedures
TUCKER, H B Duke Power Co 82/12/02 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 16542 027 24X Fiche 50-000, 82/12/15, 8212230093

--8212230124 Public version of Revision 7 to crisis mgt plan One oversize pamphlet encl Aperture card available in PDR
VAUGHN, R E Duke Power Co 82/11/29 9pp 16542 029 24X Fiche 50-000, 82/12/15, 8212230093

--8212230134 Public version of revised crisis mgt plan implementing procedures, including Procedures 5.3.2 re crisis news group plan & 5.3.11 re McGuire crisis phone directory
VAUGHN, R E Duke Power Co 82/11/29 280pp 16542 038 24X Fiche 50-000, 82/12/15, 8212230093

G Adjudicatory correspondence

8212060135 Memorandum & order reflecting decisions made following 821007-08 second prehearing conference in Charlotte, NC Impact of ALAB-687 on contentions determined & addl contentions re DES considered
KELLEY, J L Atomic Safety and Licensing Board Panel 82/12/01 27pp 16314 040 24X Fiche 50-413, 82/12/01, 8212060135

8212060243 Order extending time until 821210 for Commission to act to review ALAB-687
CHILK, S J Office of the Secretary of the Commission 82/12/03 Commissioners 1p 16312 236 24X Fiche 50-413, 82/12/03, 8212060243

8212070178 Interrogatories & requests to produce re Carolina Environ Study Group Contention 18/Palmetto Alliance Contention 44 Certificate of Svc encl Related correspondence
* Duke Power Co 82/12/03 Carolina Environmental Study Group 15pp 16334 299 24X Fiche 50-413, 82/12/03, 8212070178

8212100096 Response supporting NRC 821122 motion for sanctions against Palmetto Alliance for failure to comply w/ASLB ordered discovery, or alternatively, for dismissal of Alliance Contentions 8, 16 & 17 Certificate of Svc encl
CARR, A V Duke Power Co 82/12/07 Atomic Safety and Licensing Board Panel 49pp 16379 191 24X Fiche 50-413, 82/12/07, 8212100096

8212130362 Requests review of encl ASLB 821201 memorandum & order, containing addl info re ASLB views on what NRC comments should address Updates may be necessary
ADENSAM, E G Licensing Branch 4 82/12/08 LEAR, G E Hydrologic & Geotechnical Engineering Branch BALLARD, R L Environmental Engineering Branch TOALSTON, A Antitrust & Economic analysis Branch (Utility Finance) 2pp 16412 183 24X Fiche 50-413, 82/12/08, 8212130362

8212130230 Motion for resumption of discovery as listed Several discovery matters remain outstanding Certificate of Svc encl Related correspondence
MCGARRY, J M Duke Power Co MCGARRY, J M Debevoise & Liberman 82/12/09 Atomic Safety and Licensing Board Panel 5pp 16396 264 24X Fiche 50-413, 82/12/09, 8212130230

8212130214 Order extending time until 821217 for Commission to act to review ALAB-687.
CHILK, S J Office of the Secretary of the Commission 82/12/10 Commissioners 1p 16390 116 24X Fiche 50-413, 82/12/10, 8212130214

8212150127 Statement of position on applicability of Table B-4 to transshipment of spent fuel from Oconee & McGuire to Catawba Environ impact of spent fuel transportation properly considered in OL hearings w/Certificate of Svc.
JOHNSON, G E Hearing Branch 4 82/12/13 18pp 16430 320 24X Fiche 50-413, 82/12/13, 8212150127

8212160261 Position on consideration of Oconee & McGuire spent fuel transportation issues in proceeding Environ effects of transporting fuel to Catawba should not be litigated in instant proceeding Certificate of Svc encl
MCGARRY, J M Duke Power Co MCGARRY, J M Debevoise & Liberman
82/12/13 22pp 16446 173 24X Fiche 50-413, 82/12/13, 8212160261

8212150124 Forwards NRC first set of interrogatories & document production requests, to replace lost copy Confirms stipulation reached in 821213 telcon that responses will be provided by 821228
JOHNSON, O E Hearing Branch 4 82/12/14 PRESLER, H
Charlotte-Mecklenburg Environmental Coalition 1p 16430 310 24X
Fiche 50-413, 82/12/14, 8212150124

0212160235 Motion for protective order re listed Palmetto Alliance third set of interrogatories Interrogatories seek info which is irrelevant, requires compilation of mats not readily available or is protected by work product doctrine
JOHNSON, O E Hearing Branch 4 82/12/15 Atomic Safety and Licensing Board Panel 9pp 16443 101 24X Fiche 50-413, 82/12/15, 8212160235

--8212160240 Response to third set of interrogatories & requests to produce re Palmetto Alliance Contentions 16 & 44 Prof qualifications & Certificate of Svc encl
JOHNSON, O E Hearing Branch 4 82/12/15 Palmetto Alliance
163pp 16443 110 24X Fiche 50-413, 82/12/15, 8212160235

8212160256 Third set of interrogatories & document production requests Certificate of Svc encl
JOHNSON, O E Hearing Branch 4 82/12/15 Palmetto Alliance
10pp 16446 163 24X Fiche 50-413, 82/12/15, 8212160256

8212160303 Second set of interrogatories & document production requests Certificate of Svc encl
JOHNSON, O E Hearing Branch 4 82/12/15 Carolina Environmental Study Group 10pp 16442 322 24X Fiche 50-413, 82/12/15, 8212160303

8212170180 Forwards RO Gonzales affidavit & second page of JJ Buty statement of prof qualifications, inadvertently omitted from NRC 821215 responses to Palmetto Alliance third set of interrogatories & requests to produce
JOHNSON, O E Hearing Branch 4 82/12/16 GUILD, R Guild, R 4pp
16450 188 24X Fiche 50-413, 82/12/16, 8212170180

8212170186 Motion to compel full responses to NRC first set of interrogatories & document production requests to Palmetto Alliance on Contention 7 Intervenor must answer contentions on factual & legal bases Certificate of Svc encl
JOHNSON, O E Hearing Branch 4 82/12/16 Atomic Safety and Licensing Board Panel 10pp 16450 168 24X Fiche 50-413, 82/12/16, 8212170186

0212210242 Order extending time until 821223 for Commission to act to review ALAB-687
CHILK, S J Office of the Secretary of the Commission 82/12/17 Commissioners 1p 16484 080 24X Fiche 50-413, 82/12/17, 8212210242

8212210317 Advises that NRC does not intend to file answer to util 821209 motion re discovery NRC already answered Palmetto Alliance Contention 44 & filed motion to compel answers to NRC interrogatories on Palmetto Contention 7
JOHNSON, O E Hearing Branch 4 82/12/20 KELLEY, J L, FOSTER, R F,
CALLIHAN, D Atomic Safety and Licensing Board Panel 1p
16496 290 24X Fiche 50-413, 82/12/20, 8212210317

8212220232 Motion to compel Prairie Alliance answers to util interrogatories re Palmetto Alliance Contentions 6 & 7 or alternatively, to dismiss contentions Alliance fails to satisfy Commission rules & regulations
MCGARRY, J M Duke Power Co MCGARRY, J M Debevoise & Liberman
82/12/20 Atomic Safety and Licensing Board Panel 32pp
16518 234 24X Fiche 50-413, 82/12/20, 8212220232

--8212220239 Response opposing Palmetto Alliance motion for protective order from applicant discovery Alliance motion impermissibly vague & fails to demonstrate applicability of atty/client privilege or work product doctrine W/Certificate of Svc
MCGARRY, J M Duke Power Co MCGARRY, J M Debevoise & Liberman
82/12/20 Atomic Safety and Licensing Board Panel 14pp
16518 266 24X Fiche 50-413, 82/12/20, 8212220232

8212270244 Motion to compel Palmetto Alliance to respond further to interrogatories re Alliance Contentions 6 & 7 Discovery of bases for contentions permitted Contention 7 should be dismissed
MCGARRY, J M Duke Power Co MCGARRY, J M Debevoise & Liberman
82/12/20 Atomic Safety and Licensing Board Panel 32pp
16537 166 24X Fiche 50-413, 82/12/20, 8212270244

8212270321 Response opposing Palmetto Alliance 820428 motion for protective order re Contentions 6 & 7 Alliance has not demonstrated applicability of atty-client or work product privileges
MCGARRY, J M Duke Power Co MCGARRY, J M Debevoise & Liberman
82/12/20 Atomic Safety and Licensing Board Panel 12pp
16530 266 24X Fiche 50-413, 82/12/20, 8212270321

8212280132 Objections to ASLB 821201 order & motion for reconsideration or for certification Contentions 18 re emergency diesel generator operation & 17 re corbicula infestation effect on cooling sys should be admitted Certificate of Svc encl
GUILD, R Palmetto Alliance GUILD, R Carolina Environmental Study Group GUILD, R Guild, R 82/12/20 Atomic Safety and Licensing Board Panel 8pp 16563 212 24X Fiche 50-413, 82/12/20, 8212280132

8212280138 Comments on transshipment of spent fuel from Oconee & McGuire for storage at Catawba Table S-4 inapplicable Contentions DES 10 & DES 19 should be admitted
GUILD, R Palmetto Alliance GUILD, R Carolina Environmental Study Group GUILD, R Guild, R 82/12/20 Atomic Safety and Licensing Board Panel 8pp 16563 207 24X Fiche 50-413, 82/12/20, 8212280138

8212270226 Memorandum & order ruling on various disputes Palmetto Alliance waived all claims to privilege & thus must answer interrogatories Alliance 820530 motion for protective order & NRC motion for sanctions denied
KELLY, J L Atomic Safety and Licensing Board Panel 82/12/22 Palmetto Alliance 93pp 16535 004 24X Fiche 50-413, 82/12/22, 8212270226

8212270251 Order establishing Commission review of ASLB Decision ALAB-687 Commission will review issues re Atomic Energy Act, Section 187a & definition of good cause for late filing briefs due in 30 days & reply briefs in 50
CHILK, S J Office of the Secretary of the Commission 82/12/23 3pp 16530 055 24X Fiche 50-413, 82/12/23, 8212270251

8212280174 Requests complete copy of Palmetto Alliance & Carolina Environ Study Group objections to ASLB 821201 order & motion for reconsideration or certification
CARR, A V Duke Power Co 82/12/23 GUILD, R Guild, R RILEY, J L Affiliation Unknown 1p 16563 141 24X Fiche 50-413, 82/12/23, 8212280174

8212290002 Requests complete copy of Palmetto Alliance & Carolina Environ Study Group 821220 objections to ASLB 821201 order & motion for reconsideration or certification
JOHNSON, O E Hearing Branch 4 82/12/27 GUILD, R Palmetto Alliance GUILD, R Guild, R 1p 16582 240 24X Fiche 50-413, 82/12/27, 8212290002

8212300010 Serves Commission 821223 order & underlying decision ALAB-687 W/o encl
STUCKY, S W Docketing & Services Branch 82/12/28 Natural Resources Defense Council 1p 16598 261 24X Fiche 50-413, 82/12/28, 8212300010

Q Inspection reports, IE Bulletins & correspondence

8208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc
112pp 14462 163 24X Fiche 50-000, 82/10/28, 8208190240

8212090482 Ack receipt of IE Insp Repts 50-413/82-24 & 50-414/82-22 No proprietary info
TUCKER, H B Duke Power Co 82/10/28 O'REILLY, J P Region 2, Office of Director 1p 16363 286 24X Fiche 50-413, 82/10/28, 8212090482

8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/08 Consolidated Edison Co of New York, Inc 110pp
16372 142 24X Fiche 50-000, 82/11/08, 8208190245

8212090233 Advises that no piping subassemblies exist within scope of IE Bulletin 82-01, Revision 1, Suppl 1, in response to 820818 transmittal
TUCKER, H B Duke Power Co 82/11/05 O'REILLY, J P Region 2, Office of Director 1p 16361 348 24X Fiche 50-413, 82/11/05, 8212090233

8212090442 Ack receipt of IE Insp Repts 50-413/82-25 & 50-414/82-23 No proprietary info
TUCKER, H B Duke Power Co 82/11/11 O'REILLY, J P Region 2, Office of Director 1p 16364 252 24X Fiche 50-413, 82/11/11, 8212090442

DOCKETED ITEMS

B212090459 Forwards IE Insp Repts 50-413/82-28 & 50-414/82-26 on B21026-29 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 82/11/15
TUCKER, H B Duke Power Co 2pp 16363 357 24X
Fiche 50-413, 82/11/15, B212090459

--B212090465 IE Insp Repts 50-413/82-28 & 50-414/82-26 on B21026-29 No noncompliance noted Major areas inspected instrumentation components & sys work activities, QC records, instrumentation cables & action on previous insp matters
GIBBONS, T D, CONLON, T E Division of Engineering & Technical Programs 82/11/10 4pp 16363 359 24X Fiche 50-413, 82/11/15, B212090459

B212090522 Ack receipt of IE Insp Repts 50-413/82-26 & 50-414/82-24 No proprietary info
TUCKER, H B Duke Power Co 82/11/17 O'REILLY, J P Region 2, Office of Director 1p 16366 362 24X Fiche 50-413, 82/11/17, B212090522

B208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X
Fiche 50-000, 82/11/18, B208190251

B212090232 Ack receipt of B21029 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-413/82-21 & 50-414/82-19
LEWIS, R C Division of Project & Resident Programs 82/11/18
TUCKER, H B Duke Power Co 1p 16362 314 24X
Fiche 50-413, 82/11/18, B212090232

--B212090239 Responds to NRC B20930 ltr re violations noted in IE Insp Repts 50-413/82-21 & 50-414/82-19 Corrective actions defective base metal indication in Class B weld repaired Clearance criteria added to Design Drawing ICS-A-20.4
TUCKER, H B Duke Power Co 82/10/29 O'REILLY, J P, Region 2, Office of Director 4pp 16362 315 24X Fiche 50-413, 82/11/18, B212090232

--B212090246 Forwards IE Insp Repts 50-413/82-21 & 50-414/82-19 on B20726-0825 & notice of violation
LEWIS, R C Division of Project & Resident Programs 82/09/30
TUCKER, H B Duke Power Co 2pp 16362 319 24X
Fiche 50-413, 82/11/18, B212090232

--B212090251 Notice of violation from insp on B20726-0825
Division of Project & Resident Programs 82/09/30 3pp
16362 321 24X Fiche 50-413, 82/11/18, B212090232

--B212090261 IE Insp Repts 50-413/82-21 & 50-414/82-19 on B20726-0825 Noncompliance noted Failure to evaluate rejectable defect identified by radiography adequately & failure to include qualitative acceptance criteria in drawings
VANDORP, P K, BRYANT, J C Division of Project & Resident Programs 82/09/29 5pp 16362 324 24X Fiche 50-413, 82/11/18, B212090232

B212090317 Forwards IE Insp Repts 50-413/82-27 & 50-414/82-25 on B21026-29 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 82/11/19
TUCKER, H B Duke Power Co 2pp 16365 105 24X
Fiche 50-413, 82/11/19, B212090317

--B212090324 IE Insp Repts 50-413/82-27 & 50-414/82-25 on B21026-29 No noncompliance noted Major areas inspected const progress, reactor vessel internals & licensee action on previous enforcement matters
ECONOMOS, N, BLAKE, J J Division of Engineering & Technical Programs 82/11/12 6pp 16365 107 24X Fiche 50-413, 82/11/19, B212090317

B208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks." Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000, 82/11/26, B208190256

B208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000, 82/11/30, B208190257

B212090259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, B208190259

B208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X
Fiche 50-000, 82/12/03, B208190261

B208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16, B208190267

B208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27 " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X
Fiche 50-000, 82/12/20, B208190268

B Reportable occurrences, LERs & related correspondence

B212090079 Significant Deficiency Rept SD 414/81-30 re Sweeno 8-inch Schedule 40 min-wall violation Initially reported on 811231 As-found condition of pipe satisfies design requirements & will be installed
TUCKER, H B Duke Power Co 82/11/29 O'REILLY, J P, Region 2, Office of Director 3pp 16357 332 24X Fiche 50-414, 82/11/29, B212090079

B212090323 Interim Significant Deficiency Rept SD 414/82-16 re large arc strike on body of Borg-Warner gate valve Initially reported on B20803 Valve replaced Investigation of deficient valve underway Next rept will be submitted by B30701
TUCKER, H B Duke Power Co 82/12/01 O'REILLY, J P, Region 2, Office of Director 2pp 16365 125 24X Fiche 50-414, 82/12/01, B212090323

B212170256 Interim Significant Deficiency Rept SD 413-414/82-23 re violation of approved const procedures for mixing & placing Bitatop 122 during drill hole repair Initially reported on B21108 Test program initiated Final rept due by B30506
TUCKER, H B Duke Power Co 82/12/08 O'REILLY, J P, Region 2, Office of Director 3pp 16457 170 24X Fiche 50-413, 82/12/08, B212170256

B212150086 PNO-11-82-135 on B21209, contractor employee arrested & charged w/blackmail, including extortion & threat to kill, injure or intimidate Arrest followed 2 day investigation as result of bomb threats on B21206, 07 & 08
MOORE, D E, BRYANT, J C Region 2, Office of Director 82/12/09 2pp 16431 024 24X Fiche 50-413, 82/12/09, B212150086

B21210231 Significant Deficiency Rept SD 413-414/82-24 re ITT Darton Class IE transmitters exhibiting thermal non-repeatability Initially reported on B21112 Problem eliminated by addition of insulating spacers between potentiometers & brackets
TUCKER, H B Duke Power Co 82/12/10 O'REILLY, J P, Region 2, Office of Director 6pp 16483 351 24X Fiche 50-413, 82/12/10, B21210231

DOCKET 50-416 GRAND OULF NUCLEAR STATION, UNIT 1

F Security, medical, emergency & fire protection plans

B212010176 Discusses util compliance w/Reg Guide 1.97 Final response to Reg Guide 1.97 at present time would not be in keeping w/intent of SECY-82-111 for integrated emergency response capability review
DALE, L F Mississippi Power & Light Co 82/11/29 DENTON, H R Office of Nuclear Reactor Regulation, Director 7pp 16288 102 24X Fiche 50-416, 82/11/29, B212010176

B212090436 Confirms B21124 arrangements re B21202 enforcement conference in Atlanta, GA to discuss circumstances concerning security violation & to discuss resolution of outstanding items
O'REILLY, J P Region 2, Office of Director 82/12/01, STAMPEL, N L Mississippi Power & Light Co 2pp 16364 269 24X
Fiche 50-416, 82/12/01, B212090436

B212290207 Submits supplemental info on emergency preparedness at facilities State of LA revised radiological emergency preparedness plan will be submitted in Feb 1983, due to delays at state level
THOMAS, L M Federal Emergency Management Agency 82/12/17 DIRCKS, W Office of the Executive Director for Operations 1p 16578 202 24X Fiche 50-416, 82/12/17, B212290207

8212270235 Forwards addl info re adequacy of onsite communication sys. per 821115 telcon Communication sys testing during startup phase will provide confidence that use of two-way radios is restricted, as required
DALE, L F Mississippi Power & Light Co 82/12/22 DENTON, H R
Office of Nuclear Reactor Regulation, Director 13pp 16536 253
24X Fiche 50-416, 82/12/22, 8212270235

G Adjudicatory correspondence

8212100113 Decision ALAB-704, affirming ASLB 821020 decision denying State of LA 820721 petition to intervene subj to final outcome of judicial proceedings before US Supreme Court in NRC vs NRCDC
6HOEMAKER, C J Atomic Safety and Licensing Appeal Panel 82/12/08
13pp 16375 346 24X Fiche 50-416, 82/12/08, 8212100113

P Operating license stage documents & correspondence

821230066 Generic Ltr 82-27 to all BWR licensees of operating reactors except LACBHR, Big Rock Point, Dresden I, Humboldt Bay, applicants for OL & holders of CP re transmittal of NUREG-0763 & NUREG-0783 Svc list encl 1/0 stated encl
EISENHUT, D G Division of Licensing 82/11/15 General Public
Utilities - OPU Service Corp 22pp 16387 004 24X
Fiche 50-000, 82/11/15, 821230066

8212090429 Forwards 821102 meeting summary re activities authorized by Licenses NPF-13 & CFP-13 Meeting beneficial & provided better understanding of issues w/o encl
O'REILLY, J P Region 2, Office of Director 82/11/15 LEWIS, F W
Middle South Utilities, Inc - Middle South Energy, Inc 2pp
16364 274 24X Fiche 50-000, 82/11/15, 8212090429

8212060379 Forwards enhanced copy of approved offsite dose calculation manual
SCHWENCER, A Licensing Branch 2 82/11/16 MCGAUGHY, J P
Mississippi Power & Light Co 2pp 16323 068 24X
Fiche 50-416, 82/11/16, 8212060379

--8212060385 Revised offsite dose calculation manual
* Applied Physical Technology, Inc 82/01/12 75pp 16323 070
24X Fiche 50-416, 82/11/16, 8212060379

8212010027 Notifies that process control program approved per 82042/
ltr Future changes should be handled as described in 10CFR50.71 for revisions to FSAR re replacement pages, change indicators & certification
SCHWENCER, A Licensing Branch 2 82/11/19 MCGAUGHY, J P
Mississippi Power & Light Co 2pp 16271 357 24X
Fiche 50-416, 82/11/19, 8212010027

8212010176 Discusses util compliance w/Reg Guide 1.97 Final response to Reg Guide 1.97 at present time would not be in keeping w/intent of SECY-82-111 for integrated emergency response capability review
DALE, L F Mississippi Power & Light Co 82/11/29 DENTON, H R
Office of Nuclear Reactor Regulation, Director 7pp 16258 102
24X Fiche 50-416, 82/11/29, 8212010176

8212070274 Forwards balance of info to close Humphrey containment concerns, including "Evaluation Rept on Modified SOLA-VDF Code" & "Survey of Tests & Analyses on Effectiveness of RHR Sys in Pool-Cooling Mode" & proprietary Figures 18 - 25
DALE, L F Mississippi Power & Light Co 82/12/03 DENTON, H R
Office of Nuclear Reactor Regulation, Director 42pp 16340 128
24X Fiche 50-416, 82/12/03, 8212070274

--8212070276 "Evaluation Rept on Modified SOLA-VDF Code"
HIRT, C W, SICILIAN, J M Flow Science, Inc 82/10/18 11pp
16340 190 24X Fiche 50-416, 82/12/03, 8212070274

--8212070278 Revision A to "Survey of Tests & Analyses on Effectiveness of RHR Sys in Pool-Cooling Mode"
* Quadrex Corp QUAD-1-82-245 REV A 82/11/30 51pp
16340 201 24X Fiche 50-416, 82/12/03, 8212070274

8212170278 Comments on BWR06-8260, "NUREG-0737, Item II K 3 18, Mod of Automatic Depressurization Sys Logic " Option 4, providing bypass timer delay, will assure adequate core cooling during worst case conditions
DALE, L F Mississippi Power & Light Co 82/12/14 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 16461 152
24X Fiche 50-416, 82/12/14, 8212170278

8212230252 Discusses util responses to recently discussed unresolved NRC concerns re automatic depressurization sys air sys
DALE, L F Mississippi Power & Light Co 82/12/20 DENTON, H R
Office of Nuclear Reactor Regulation, Director 4pp 16511 063
24X Fiche 50-416, 82/12/20, 8212230252

8212300184 Forwards Amend 5 to License NPF-13, safety evaluation & notice of issuance & availability Amend changes schedule for completion of open items & corrective actions for environ qualification of safety-related electrical equipment
SCHWENCER, A Licensing Branch 2 82/12/20 MCGAUGHY, J P
Mississippi Power & Light Co 4pp 16613 056 24X
Fiche 50-416, 82/12/20, 8212300184

--8212300188 Amend 5 to License NPF-13, changing schedule for completion of corrective actions for safety-related electrical equipment to end of first refueling outage
EISENHUT, D G Division of Licensing 82/12/20 7pp 16613 060
24X Fiche 50-416, 82/12/20, 8212300184

--8212300194 Safety evaluation supporting Amend 5 to License NPF-13
* Office of Nuclear Reactor Regulation, Director 82/12/20 3pp
16613 067 24X Fiche 50-416, 82/12/20, 8212300184

--8212300203 Notice of issuance & availability of Amend 5 to License NPF-13
BDURNIA, A, SCHWENCER, A Licensing Branch 2 82/12/20 3pp
16613 070 24X Fiche 50-416, 82/12/20, 8212300184

8212270147 Application for amend to License NPF-13, adding provision to License Condition Item 2 C(42)h re installing protective sleeves on bottom entry in-core assemblies & revising License Condition 2 C(42)i re startup source replacement
MCGAUGHY, J P Mississippi Power & Light Co 82/12/22 DENTON, H R
Office of Nuclear Reactor Regulation, Director 3pp 16538 060
24X Fiche 50-416, 82/12/22, 8212270147

--8212270153 Proposed changes to Tech Specs re installing protective sleeves on bottom entry in-core assemblies & reducing sleeves on bottom entry in-core assemblies
* Mississippi Power & Light Co 82/12/22 4pp 16538 063 24X
Fiche 50-416, 82/12/22, 8212270147

8212270154 Submits updated qualification status & justification for interim operation of NSSS equipment not meeting SGRT criteria, originally submitted 820405
DALE, L F Mississippi Power & Light Co 82/12/22 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 16538 343
24X Fiche 50-416, 82/12/22, 8212270154

G Inspection reports, IE Bulletins & correspondence

8208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Svc list encl
DEVOUNO, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc
112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240

8212090414 Approves issuance of SALP Repts 50-416/82-45 & 50-417/82-11 for Jul 1980-June 1981 Mgt attentive to matters of nuclear safety Weaknesses in Unit 1 preoperational testing & training programs noted
O'REILLY, J P Region 2, Office of Director 82/11/01
STAMPLEY, N L Mississippi Power & Light Co 2pp 16365 013 24X
Fiche 50-416, 82/11/01, 8212090414

--8212090421 Forwards SALP Repts 50-416/82-45 & 50-417/82-11 for Jul 1980-June 1981 Comments requested within 20 days
LEWIS, R C Division of Project & Resident Programs 82/07/22
STAMPLEY, N L Mississippi Power & Light Co 2pp 16365 014 24X
Fiche 50-416, 82/11/01, 8212090414

--8212090427 SALP Repts 50-416/82-45 & 50-417/82-11 for Jul 1980-June 1981 Weaknesses in Unit 1 preoperational testing & training programs noted
* Region 2, Office of Director 82/07/22 15pp 16365 017 24X
Fiche 50-416, 82/11/01, 8212090414

8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp
16372 142 24X Fiche 50-000, 82/11/05, 8208190245

8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X
Fiche 50-000, 82/11/18, 8208190251

8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list encl
DEVOUNO, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000, 82/11/26, 8208190256

DOCKETED ITEMS

8208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl." Svc list encl
 COBB, L I Division of Fuel Facilities, Materials & Safeguards
 82/11/30 Consolidated Edison Co. of New York, Inc 356pp
 16387 028 24X Fiche 50-000, 82/11/30, 8208190257

8212090282 Ack receipt of 820927 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-416/82-58
 LEWIS, R C Division of Project & Resident Programs 82/12/01
 STAMPLEY, N L Mississippi Power & Light Co 1p 16365 243 24X
 Fiche 50-416, 82/12/01, 8212090282

--8212090290 Responds to NRC 820827 ltr re violation noted in IE Insp Rept 50-416/82-58-02 Corrective actions 10CFR50.59 safety evaluation of Chem-Nuclear solidification sys performed & personnel instructed to perform evaluation prior to mod
 MCGAUGHY, J P Mississippi Power & Light Co 82/09/27
 O'REILLY, J P Region 2, Office of Director 2pp 16365 244 24X
 Fiche 50-416, 82/12/01, 8212090282

--8212090303 Responds to NRC 820827 ltr re violations noted in IE Insp Rept 50-416/82-58 Violation denied as stated Caused by misinterpretation of plant administrative Procedure
 01-8-08-5, "Radiological Surveys & Surveillance"
 MCGAUGHY, J P Mississippi Power & Light Co 82/09/27
 O'REILLY, J P Region 2, Office of Director 2pp 16365 246 24X
 Fiche 50-416, 82/12/01, 8212090282

--8212090310 Responds to NRC 820827 ltr re violations noted in IE Insp Rept 50-416/82-58 Corrective actions 10CFR50.59 evaluation required prior to mod of radwaste solidification sys will be performed & procedures revised
 MCGAUGHY, J P Mississippi Power & Light Co 82/09/27
 O'REILLY, J P Region 2, Office of Director 2pp 16365 248 24X
 Fiche 50-416, 82/12/01, 8212090282

--8212090316 Forwards IE Insp Rept 50-416/82-58 on 820802-06 & notice of violation
 LEWIS, R C Division of Project & Resident Programs 82/08/27
 STAMPLEY, N L Mississippi Power & Light Co 2pp 16365 250 24X
 Fiche 50-416, 82/12/01, 8212090282

--8212090320 Notice of violation from insp on 820802-06
 * Region 2, Office of Director 82/08/27 2pp 16365 252 24X
 Fiche 50-416, 82/12/01, 8212090282

--8212090332 IE Insp Rept 50-416/82-58 on 820802-06 Noncompliance noted failure to review Chem-Nuclear solidification sys prior to use, safety evaluation not written on alterations to radwaste sys & surveys not performed in restricted areas
 COLLINGS, T R, BARR, K P Division of Engineering & Technical Programs 82/08/30 6pp 16365 254 24X Fiche 50-416, 82/12/01, 8212090282

8212090436 Confirms 821124 arrangements re 821202 enforcement conference in Atlanta, GA to discuss circumstances concerning security violation & to discuss resolution of outstanding items
 O'REILLY, J P Region 2, Office of Director 82/12/01
 STAMPLEY, N L Mississippi Power & Light Co 2pp 16364 269 24X
 Fiche 50-416, 82/12/01, 8212090436

8208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies" Svc list encl
 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co. of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259

8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Buckets" Svc list encl
 JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co. of New York, Inc 110pp 16462 064 24X
 Fiche 50-000, 82/12/03, 8208190261

8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring" Svc list encl
 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co. of New York, Inc 127pp 16428 191 24X Fiche 50-000, 82/12/16, 8208190267

8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27" Svc list encl
 JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co. of New York, Inc 108pp 16428 293 24X
 Fiche 50-000, 82/12/20, 8208190268

--8212200106 Monthly operating rept for Nov 1982
 RICHARDSON, J D Mississippi Power & Light Co 82/12/15 8pp
 16470 081 24X Fiche 50-416, 82/12/15, 8212200103

S Reportable occurrences, LERs & related correspondence

8212020033 Forwards updated LER 82-081/99X-1
 MCGAUGHY, J P Mississippi Power & Light Co 82/11/22
 O'REILLY, J P Region 2, Office of Director 1p 16272 054 24X
 Fiche 50-416, 82/11/22, 8212020033

--8212020037 Updated LER 82-081/99X-1 on 820916, during preoperational test, local instrument check revealed discrepancies in containment ventilation monitoring sys effluent flourate monitor indications Caused by clogged manifold
 BYRD, R Mississippi Power & Light Co 82/11/22 Region 2, Office of Director 2pp 16272 055 24X Fiche 50-416, 82/11/22, 8212020033

8212020050 Forwards LER 82-108/99L-0
 MCGAUGHY, J P Mississippi Power & Light Co 82/11/24
 O'REILLY, J P Region 2, Office of Director 1p 16272 060 24X
 Fiche 50-416, 82/11/24, 8212020050

--8212020061 LER 82-108/99L-0 on 821027, discovered surveillance requirements for some fire detection instruments not met & no documentation existed to indicate that heat detectors listed in Table 3.3.7.9-1 tested Cause not stated
 FREEMAN, M S Mississippi Power & Light Co 82/11/24 Region 2, Office of Director 2pp 16272 061 24X Fiche 50-416, 82/11/24, 8212020050

8212020058 Forwards updated LER 82-103/01X-1
 MCGAUGHY, J P Mississippi Power & Light Co 82/11/24
 O'REILLY, J P Region 2, Office of Director 1p 16272 063 24X
 Fiche 50-416, 82/11/24, 8212020058

--8212020065 Updated LER 82-103/01X-1 on 821022, failure to demonstrate operability of remaining ac power sources discovered during review of documentation declaring HPCS, Div III diesel generator inoperable Caused by personnel error
 ALBERT, J Mississippi Power & Light Co 82/11/24 Region 2, Office of Director 2pp 16272 064 24X Fiche 50-416, 82/11/24, 8212020058

8212020138 Forwards LER 82-105/01T-0
 MCGAUGHY, J P Mississippi Power & Light Co 82/11/24
 O'REILLY, J P Region 2, Office of Director 1p 16274 161 24X
 Fiche 50-416, 82/11/24, 8212020138

--8212020144 LER 82-105/01T-0 on 821110, design review revealed turbine trip condition in FSAR analysis less conservative than that caused by circulating water pump trip Caused by failure to account for 3-s steam bypass operation after turbine trip
 BYRD, R Mississippi Power & Light Co 82/11/24 Region 2, Office of Director 1p 16274 162 24X Fiche 50-416, 82/11/24, 8212020138

8212090078 Forwards LER 82-109/03L-0
 MCGAUGHY, J P Mississippi Power & Light Co 82/12/01
 O'REILLY, J P Region 2, Office of Director 1p 16357 330 24X
 Fiche 50-416, 82/12/01, 8212090078

--8212090081 LER 82-109/03L-0 on 821102, diesel generator air start receiver pressure discovered less than required 175 psig Caused by open circuit breaker Breaker closed
 ROHRER, M V Mississippi Power & Light Co 82/12/01 Region 2, Office of Director 1p 16357 331 24X Fiche 50-416, 82/12/01, 8212090078

8212090110 Forwards LER 82-128/03L-0
 MCGAUGHY, J P Mississippi Power & Light Co 82/12/01
 O'REILLY, J P Region 2, Office of Director 1p 16357 301 24X
 Fiche 50-416, 82/12/01, 8212090110

--8212090113 LER 82-128/03L-0 on 821102, standby diesel generator 12 placed in maint mode while diesel generator 11 also down for maint Caused by need to perform regular maint Generator 11 repaired & returned to svc on 821118
 FREEMAN, M S Mississippi Power & Light Co 82/12/01 Region 2, Office of Director 1p 16357 302 24X Fiche 50-416, 82/12/01, 8212090110

8212090131 Forwards LER 82-127/03L-0
 MCGAUGHY, J P Mississippi Power & Light Co 82/12/01
 O'REILLY, J P Region 2, Office of Director 1p 16359 179 24X
 Fiche 50-416, 82/12/01, 8212090131

R Periodic operating reports & related correspondence

8212200103 Forwards monthly operating rept for Nov 1982
 MCGAUGHY, J P Mississippi Power & Light Co 82/12/15 DEYOUNG, R C
 Director's Office, Office of Inspection and Enforcement 2pp
 16470 079 24X Fiche 50-416, 82/12/15, 8212200103

--8212090136 LER 82-127/03L-0 on 821102, during cold shutdown, shutdown cooling loop B of RHR sys declared inoperable in order to perform work on butterfly valve. Caused by valve being installed backward due to const error. Work completed 821124. ROHRER, M V Mississippi Power & Light Co 82/12/01 Region 2, Office of Director 1p 16359 180 24X Fiche 50-416, 82/12/01, 8212090131

8212090177 Forwards LER 82-123/99X-0 on 821102, cabinet IH13P700 A, B, D & E, IH13P735A & B & IH13P714A & B fire barrier penetrations in control bldg at 166 ft, broken for planned maint. Hourly fire watch established. Updated rept to be submitted by 830202. FLOYD, J M Mississippi Power & Light Co 82/12/01 Region 2, Office of Director 1p 16359 212 24X Fiche 50-416, 82/12/01, 8212090177

8212090326 Forwards LER 82-126/99L-0 on 821102, several fire dams & penetration seals broken while replacing shorted cable running from control room to computer room. Fire dams restored. Work still progressing on penetration seals. Update by 830202. FREEMAN, M S Mississippi Power & Light Co 82/12/01 Region 2, Office of Director 1p 16365 114 24X Fiche 50-416, 82/12/01, 8212090326

8212090074 Forwards LER 82-119/03L-0 on 821104, smoke detectors in zone covering auxiliary bldg east corridor annunciator. Caused by dust accumulation. Detectors cleaned & program instituted to clean detectors periodically. FLOYD, J M Mississippi Power & Light Co 82/12/02 Region 2, Office of Director 1p 16357 362 24X Fiche 50-416, 82/12/02, 8212090074

--8212090075 LER 82-119/03L-0 on 821104, smoke detectors in zone covering auxiliary bldg east corridor annunciator. Caused by dust accumulation. Detectors cleaned & program instituted to clean detectors periodically. FLOYD, J M Mississippi Power & Light Co 82/12/02 Region 2, Office of Director 1p 16357 363 24X Fiche 50-416, 82/12/02, 8212090074

8212090151 Forwards LER 82-118/03L-0 on 821104, smoke detectors in piping penetration, RHR C pump & LPCS rooms of auxiliary bldg annunciator w/o presence of smoke or fumes. Caused by accumulation of dust on detectors. FLOYD, J M Mississippi Power & Light Co 82/12/02 Region 2, Office of Director 1p 16359 117 24X Fiche 50-416, 82/12/02, 8212090151

--8212090158 LER 82-118/03L-0 on 821104, smoke detectors in piping penetration, RHR C pump & LPCS rooms of auxiliary bldg annunciator w/o presence of smoke or fumes. Caused by accumulation of dust on detectors. FLOYD, J M Mississippi Power & Light Co 82/12/02 Region 2, Office of Director 1p 16359 118 24X Fiche 50-416, 82/12/02, 8212090151

8212090159 Forwards LER 82-112/03L-0 on 821105, smoke detector in east switchgear & piping penetration rooms of auxiliary bldg, elevation 119 ft, alarmed & would not reset. Caused by dust in detector. Detector cleaned & returned to svc on 821108. FREEMAN, M S Mississippi Power & Light Co 82/12/02 Region 2, Office of Director 1p 16359 101 24X Fiche 50-416, 82/12/02, 8212090159

8212090191 Forwards LER 82-110/03L-0 on 821105, auxiliary bldg east corridor area smoke detectors at 119 ft alarmed & did not reset. Caused by accumulation of dust. Ionization smoke detector cleaned & returned to svc. Periodic detector cleaning initiated. ROHRER, M V Mississippi Power & Light Co 82/12/02 Region 2, Office of Director 1p 16361 298 24X Fiche 50-416, 82/12/02, 8212090191

--8212090195 LER 82-110/03L-0 on 821105, auxiliary bldg east corridor area smoke detectors at 119 ft alarmed & did not reset. Caused by accumulation of dust. Ionization smoke detector cleaned & returned to svc. Periodic detector cleaning initiated. ROHRER, M V Mississippi Power & Light Co 82/12/02 Region 2, Office of Director 1p 16361 299 24X Fiche 50-416, 82/12/02, 8212090191

8212100297 Forwards LER 82-114/03L-0 on 821108, smoke detector in zone covering control bldg, elevation 166 ft & 177 ft, alarmed & would not reset. Caused by damage to detector due to installation work in area. Detector replaced & tested satisfactorily. FREEMAN, M S Mississippi Power & Light Co 82/12/07 Region 2, Office of Director 1p 16376 219 24X Fiche 50-416, 82/12/07, 8212100297

8212100306 LER 82-114/03L-0 on 821108, smoke detector in zone covering control bldg, elevation 166 ft & 177 ft, alarmed & would not reset. Caused by damage to detector due to installation work in area. Detector replaced & tested satisfactorily. FREEMAN, M S Mississippi Power & Light Co 82/12/07 Region 2, Office of Director 1p 16376 220 24X Fiche 50-416, 82/12/07, 8212100297

8212170137 Forwards LER 82-120/99X-0 on 821105, during shutdown, fire door 1A106 opened to drain standby svc water loop B by allowing passage of hose to channel water from flush & drain of loop. Door will be restored. Final rept expected by 830212. FLOYD, J M Mississippi Power & Light Co 82/12/13 Region 2, Office of Director 1p 16450 274 24X Fiche 50-416, 82/12/13, 8212170137

8212170146 LER 82-120/99X-0 on 821105, during shutdown, fire door 1A106 opened to drain standby svc water loop B by allowing passage of hose to channel water from flush & drain of loop. Door will be restored. Final rept expected by 830212. FLOYD, J M Mississippi Power & Light Co 82/12/13 Region 2, Office of Director 1p 16450 275 24X Fiche 50-416, 82/12/13, 8212170137

8212170209 Forwards LER 82-130/03L-0 on 821112, shutdown cooling loops A & B of RHR sys simultaneously inoperative. Caused by need to bring down loop A to perform surveillance tests & add water to reactor vessel. Surveillance performed. FREEMAN, M S Mississippi Power & Light Co 82/12/13 Region 2, Office of Director 1p 16459 347 24X Fiche 50-416, 82/12/13, 8212170209

--8212170213 LER 82-130/03L-0 on 821112, shutdown cooling loops A & B of RHR sys simultaneously inoperative. Caused by need to bring down loop A to perform surveillance tests & add water to reactor vessel. Surveillance performed. FREEMAN, M S Mississippi Power & Light Co 82/12/13 Region 2, Office of Director 1p 16459 348 24X Fiche 50-416, 82/12/13, 8212170209

8212170222 Forwards LER 82-122/99X-0 on 821104, during shutdown, cover to HVAC chase on elevation 148 ft in control bldg lower cable spreading room found removed. Cause unknown. Cover reinstalled. Investigation continuing. FLOYD, J M Mississippi Power & Light Co 82/12/13 Region 2, Office of Director 1p 16459 320 24X Fiche 50-416, 82/12/13, 8212170222

--8212170227 LER 82-122/99X-0 on 821104, during shutdown, cover to HVAC chase on elevation 148 ft in control bldg lower cable spreading room found removed. Cause unknown. Cover reinstalled. Investigation continuing. FLOYD, J M Mississippi Power & Light Co 82/12/13 Region 2, Office of Director 1p 16459 320 24X Fiche 50-416, 82/12/13, 8212170222

8212170263 Forwards LER 82-125/03L-0 on 821113, 200 gallons of potentially contaminated plant svc water drained to storm drains. Effluent not sampled prior to release. Caused by personnel error. Personnel instructed. ROHRER, M V Mississippi Power & Light Co 82/12/13 Region 2, Office of Director 1p 16456 212 24X Fiche 50-416, 82/12/13, 8212170263

--8212170277 LER 82-125/03L-0 on 821113, 200 gallons of potentially contaminated plant svc water drained to storm drains. Effluent not sampled prior to release. Caused by personnel error. Personnel instructed. ROHRER, M V Mississippi Power & Light Co 82/12/13 Region 2, Office of Director 1p 16456 212 24X Fiche 50-416, 82/12/13, 8212170263

8212170313 Forwards LER 82-129/03L-0 on 821113, 14 & 15, smoke detectors in auxiliary bldg new & spent fuel pool, east corridor, northeast corridor equipment & steam tunnel root areas annunciator & would not reset. Caused by dust in detectors. ROHRER, M V Mississippi Power & Light Co 82/12/13 Region 2, Office of Director 2pp 16456 154 24X Fiche 50-416, 82/12/13, 8212170313

--8212170327 LER 82-129/03L-0 on 821113, 14 & 15, smoke detectors in auxiliary bldg new & spent fuel pool, east corridor, northeast corridor equipment & steam tunnel root areas annunciator & would not reset. Caused by dust in detectors. ROHRER, M V Mississippi Power & Light Co 82/12/13 Region 2, Office of Director 2pp 16456 154 24X Fiche 50-416, 82/12/13, 8212170313

8212170334 Forwards LER 82-095/99X-0 on 821106, three fire rated doors in auxiliary bldg blocked open due to painting suppression pool. Caused by need to route sandblasting hoses from outside bldg into suppression pool. Hourly fire watch established. FREEMAN, M S Mississippi Power & Light Co 82/12/13 Region 2, Office of Director 1p 16456 160 24X Fiche 50-416, 82/12/13, 8212170334

--8212170339 LER 82-095/99X-0 on 821106, three fire rated doors in auxiliary bldg blocked open due to painting suppression pool. Caused by need to route sandblasting hoses from outside bldg into suppression pool. Hourly fire watch established. FREEMAN, M S Mississippi Power & Light Co 82/12/13 Region 2, Office of Director 1p 16456 161 24X Fiche 50-416, 82/12/13, 8212170334

8212210155 Forwards LER 82-063/99X-1 on 821106, three fire rated doors in auxiliary bldg blocked open due to painting suppression pool. Caused by need to route sandblasting hoses from outside bldg into suppression pool. Hourly fire watch established. FREEMAN, M S Mississippi Power & Light Co 82/12/14 Region 2, Office of Director 1p 16484 241 24X Fiche 50-416, 82/12/14, 8212210155

DOCKETED ITEMS

- B212210182 LER 82-063/99X-1 on 820902, during shutdown, several fire-rated cable penetration seals were broken on field termination cabinets in control room to allow routing of add'l cable. Seals repaired following maint activities.
ALBERT, J M Mississippi Power & Light Co 82/12/14 Region 2,
Office of Director 1p 16484 242 24X Fiche 50-416, 82/12/14,
8212210155
- B212210179 Forwards LER 82-132/01T-0
MCGAUGHY, J P Mississippi Power & Light Co 82/12/14
O'REILLY, J P Region 2, Office of Director 1p 16484 339 24X
Fiche 50-416, 82/12/14, 8212210179
- B212210192 LER 82-132/01T-0 on 821130 & 1202, several fire-rated electrical penetrations found open. Penetration openings authorized by maint work orders w/o notifying control room. Instructions issued to responsible persons.
FREEHAN, B Mississippi Power & Light Co 82/12/14 Region 2,
Office of Director 2pp 16484 340 24X Fiche 50-416, 82/12/14,
8212210179
- B212210191 Forwards LER 82-011/99X-1
MCGAUGHY, J P Mississippi Power & Light Co 82/12/14
O'REILLY, J P Region 2, Office of Director 1p 16485 016 24X
Fiche 50-416, 82/12/14, 8212210191
- B212210205 LER 82-011/99X-1 on 820722, during functional testing of diesel generator 12, generator tripped due to high water jacket temp. Caused by elevated cooling water temps due to isolated cooling water outlet valve. Design change made.
ROHRER, M V Mississippi Power & Light Co 82/12/14 Region 2,
Office of Director 2pp 16485 017 24X Fiche 50-416, 82/12/14,
8212210191
- B212210367 Forwards Interim LER 82-027/99X-1
MCGAUGHY, J P Mississippi Power & Light Co 82/12/14
O'REILLY, J P Region 2, Office of Director 1p 16494 273 24X
Fiche 50-416, 82/12/14, 8212210367
- B212210371 Interim LER 82-027/99X-1 on 820727, during special insp, seal AV-8D discovered not installed in spare HVAC penetration to containment exhaust filter train room. Threaded conduit plug installed. Design change requested.
ROHRER, M V Mississippi Power & Light Co 82/12/14 Region 2,
Office of Director 1p 16494 274 24X Fiche 50-416, 82/12/14,
8212210367
- B212210212 Forwards LER 82-021/99X-1
MCGAUGHY, J P Mississippi Power & Light Co 82/12/15
O'REILLY, J P Region 2, Office of Director 1p 16483 359 24X
Fiche 50-416, 82/12/15, 8212210212
- B212210227 LER 82-021/99X-1 on 820720, limiting condition for operation entered due to quarterly test of radioactive liquid effluent monitoring sys not being performed by 820720. Caused by inadequate sys design. Design change implemented.
ROHRER, M V Mississippi Power & Light Co 82/12/15 Region 2,
Office of Director 1p 16483 360 24X Fiche 50-416, 82/12/15,
8212210212
- B212210375 Interim Deficiency Rept 4 re corroded terminal boards on transmitters. Initially reported on 820421. Corrosion attributed to moisture. Final rept expected by 830128.
MCGAUGHY, J P Mississippi Power & Light Co 82/12/15
O'REILLY, J P Region 2, Office of Director 2pp 16494 314 24X
Fiche 50-416, 82/12/15, 8212210375
- B212280080 Forwards Interim LER 82-031/99X-1
MCGAUGHY, J P Mississippi Power & Light Co 82/12/15
O'REILLY, J P Region 2, Office of Director 1p 16564 236 24X
Fiche 50-416, 82/12/15, 8212280080
- B212280081 Interim LER 82-031/99X-1 on 820722, HVAC penetration seal CV-190 found not installed during insp. Caused by const oversight. Maint work order released to install seal & hourly fire watch established until task completed.
ROHRER, M V Mississippi Power & Light Co 82/12/15 Region 2,
Office of Director 1p 16564 237 24X Fiche 50-416, 82/12/15,
8212280080
- B212280377 Final Deficiency Rept PRD-82/33 re excessive length of capacitors in standby diesel generator air start valve assembly potentially resulting in valve failure. Initially reported on 820623. Deficiency not reportable per Part 21.
MCGAUGHY, J P Mississippi Power & Light Co 82/12/15
O'REILLY, J P Region 2, Office of Director 5pp 16259 006 24X
Fiche 50-416, 82/12/15, 8212280377
- B212280056 Forwards LER 82-140/99X-0
MCGAUGHY, J P Mississippi Power & Light Co 82/12/16,
O'REILLY, J P Region 2, Office of Director 1p 16565 141 24X
Fiche 50-416, 82/12/16, 8212280056
- B212280057 LER 82-140/99X-0 on 821112, during shutdown, fire door 1A21J (entrance to valve room 1A220) blocked open for hose which supported local leak rate testing. Fire watch in effect. Fire door secured upon test completion.
FLOYD, J M Mississippi Power & Light Co 82/12/16 Region 2,
Office of Director 1p 16565 142 24X Fiche 50-416, 82/12/16,
8212280056
- B212280150 Forwards Interim LER 82-138/99X-0
MCGAUGHY, J P Mississippi Power & Light Co 82/12/16
O'REILLY, J P Region 2, Office of Director 1p 16563 113 24X
Fiche 50-416, 82/12/16, 8212280150
- B212280154 Interim LER 82-138/99X-0 on 821112, during shutdown, several duct covers could not be installed due to cables extending through ducts. Caused by faulty design. Document Engineering evaluation underway.
AMBROSINO, R A Mississippi Power & Light Co 82/12/16 Region 2,
Office of Director 1p 16563 114 24X Fiche 50-416, 82/12/16,
8212280150
- B212280177 Forwards LER 82-139/03L-0
MCGAUGHY, J P Mississippi Power & Light Co 82/12/16
O'REILLY, J P Region 2, Office of Director 1p 16562 179 24X
Fiche 50-416, 82/12/16, 8212280177
- B212280183 LER 82-139/03L-0 on 821118, smoke detector in control cabinet room alarmed & would not reset. No smoke or fumes present in area. Caused by defective detector. Fire watch established & detector replaced.
ROHRER, M V Mississippi Power & Light Co 82/12/16 Region 2,
Office of Director 1p 16562 180 24X Fiche 50-416, 82/12/16,
8212280177
- B212280241 Forwards LER 82-137/03L-0
MCGAUGHY, J P Mississippi Power & Light Co 82/12/16
O'REILLY, J P Region 2, Office of Director 1p 16561 205 24X
Fiche 50-416, 82/12/16, 8212280241
- B212280245 LER 82-137/03L-0 on 821117, fire rated doors GC503 & DC501 blocked open by hoses being used in sealing of control room penetrations during shutdown. Caused by planned maint activities. Hourly fire watch established.
AMBROSINO, R A Mississippi Power & Light Co 82/12/16 Region 2,
Office of Director 1p 16561 206 24X Fiche 50-416, 82/12/16,
8212280241
- B212280386 Forwards LER 82-142/99X-0
MCGAUGHY, J P Mississippi Power & Light Co 82/12/16
O'REILLY, J P Region 2, Office of Director 1p 16558 360 24X
Fiche 50-416, 82/12/16, 8212280386
- B212280389 LER 82-142/99X-0 on 821118, during shutdown, fire barriers broken in control room to allow cable rerouting per approved maint work order. Fire watch established. Fire barriers resealed following completion of work.
FLOYD, J M Mississippi Power & Light Co 82/12/16 Region 2,
Office of Director 1p 16558 361 24X Fiche 50-416, 82/12/16,
8212280386
- B212280458 Forwards LER 82-141/99X-0
MCGAUGHY, J P Mississippi Power & Light Co 82/12/16
O'REILLY, J P Region 2, Office of Director 1p 16556 020 24X
Fiche 50-416, 82/12/16, 8212280458
- B212280463 LER 82-141/99X-0 on 821112, fire doors 1A30B & 1A316 blocked open to route hoses to sandblasting operations in suppression pool. Caused by planned maint activity. Upon work completion doors will be restored.
BYRD, R Mississippi Power & Light Co 82/12/16 Region 2,
Office of Director 1p 16556 021 24X Fiche 50-416, 82/12/16,
8212280458
- B212280466 Forwards LER 82-135/99X-0
MCGAUGHY, J P Mississippi Power & Light Co 82/12/16
O'REILLY, J P Region 2, Office of Director 1p 16556 018 24X
Fiche 50-416, 82/12/16, 8212280466
- B212280475 LER 82-135/99X-0 on 821105, smoke detectors in auxiliary bldg steam tunnel covered to prevent fumes from causing erroneous alarms. Caused by paint fumes from planned maint activity. Fire watch established until 821208.
AMBROSINO, R A Mississippi Power & Light Co 82/12/16 Region 2,
Office of Director 1p 16556 019 24X Fiche 50-416, 82/12/16,
8212280466
- B212280402 Forwards LER 82-133/03L-0
MCGAUGHY, J P Mississippi Power & Light Co 82/12/17
O'REILLY, J P Region 2, Office of Director 1p 16560 053 24X
Fiche 50-416, 82/12/17, 8212280402

DOCKETED ITEMS

20

--8212280412 LER 82-133/03L-0 during 821027-29,RHR & LPCS rendered inoperable when suppression pool drained to allow painting of carbon steel components Limiting conditions for operation entered Painting completed & pool filled 821204
AM3ROSGIND,R A Mississippi Power & Light Co 82/12/17 Region 2, Office of Director 2pp 16560 054 24X Fiche 50-416, 82/12/17,8212280402

8212280194 Forwards LER 82-123/99X-1
MCOAUGHY, J P Mississippi Power & Light Co 82/12/20
O'REILLY, J P Region 2, Office of Director 1p 16562 294 24X
Fiche 50-416, 82/12/20, 8212280194

--8212280198 LER 82-123/99X-1 on 821102, fire barrier penetrations to cabinets in control bldg broken to complete planned maint activity Fire watch established Penetrations resealed Limiting conditions for operation cleared
FLOYD, J M Mississippi Power & Light Co 82/12/20 Region 2, Office of Director 1p 16562 295 24X Fiche 50-416, 82/12/20, 8212280194

8212280308 Forwards LER 82-134/03L-0
MCOAUGHY, J P Mississippi Power & Light Co 82/12/20
O'REILLY, J P Region 2, Office of Director 1p 16561 133 24X
Fiche 50-416, 82/12/20, 8212280308

--8212280311 LER 82-134/03L-0 on 821201, during cold shutdown, RHR loop A shut down to allow flush of RHR loop B piping Caused by need to maintain RHR loop B for return to operation RHR loop A returned to svc
ROHRER, M V Mississippi Power & Light Co 82/12/20 Region 2, Office of Director 1p 16561 134 24X Fiche 50-416, 82/12/20, 8212280308

8212280312 Forwards LER 82-048/99X-0
MCOAUGHY, J P Mississippi Power & Light Co 82/12/20
O'REILLY, J P Region 2, Office of Director 1p 16561 361 24X
Fiche 50-416, 82/12/20, 8212280312

--8212280314 LER 82-048/99X-0 on 820812, discovered unsealed fire barrier between two control room cabinets Caused by const oversight Fire barrier sealed by maint work order on 820919
ROHRER, M V Mississippi Power & Light Co 82/12/20 Region 2, Office of Director 1p 16561 362 24X Fiche 50-416, 82/12/20, 8212280312

8212280327 Forwards LER 82-107/03X-1
MCOAUGHY, J P Mississippi Power & Light Co 82/12/20
O'REILLY, J P Region 2, Office of Director 1p 16561 064 24X
Fiche 50-416, 82/12/20, 8212280327

--8212280336 LER 82-107/03X-1 on 821014, when entering Mode 3, requirements of Tech Spec 3.6.5 c not satisfied Caused by inoperable drywell post-LOCA vacuum breaker position indicators Indicators replaced Tech Specs amended
ALBERT, J M Mississippi Power & Light Co 82/12/20 Region 2, Office of Director 1p 16561 065 24X Fiche 50-416, 82/12/20, 8212280327

8212280344 Forwards LER 82-033/99X-1
MCOAUGHY, J P Mississippi Power & Light Co 82/12/20
O'REILLY, J P Region 2, Office of Director 1p 16561 035 24X
Fiche 50-416, 82/12/20, 8212280344

--8212280352 LER 82-033/99X-1 on 820814, HPCS diesel generator 13 started on low reactor vessel level indication & tripped on overspeed Caused by faulty tachometer relay Dynalco relay replaced & sys restored on 820818
BYRD, R Mississippi Power & Light Co 82/12/20 Region 2, Office of Director 2pp 16561 036 24X Fiche 50-416, 82/12/20, 8212280344

8212300039 Forwards LER 82-144/03L-0
MCOAUGHY, J P Mississippi Power & Light Co 82/12/22
O'REILLY, J P Region 2, Office of Director 1p 16598 196 24X
Fiche 50-416, 82/12/22, 8212300039

--8212300047 LER 82-146/03L-0 on 821124, drywell to containment differential pressure not verified within proper frequency during hot shutdown Caused by inadequate procedure Procedure revised
ROHRER, M V Mississippi Power & Light Co 82/12/22 Region 2, Office of Director 1p 16598 197 24X Fiche 50-416, 82/12/22, 8212300039

8212300084 Forwards LER 82-143/03L-0.
MCOAUGHY, J P Mississippi Power & Light Co 82/12/22
O'REILLY, J P Region 2, Office of Director 1p 16599 027 24X
Fiche 50-416, 82/12/22, 8212300084

--8212300087 LER 82-143/03L-0 on 821201, seismic switch alarmed & would not reset No seismic event had occurred Caused by instrument cover touching cover bracket resulting in spurious alarms when personnel walked across floor Cover repositioned
ROHRER, M V Mississippi Power & Light Co 82/12/22 Region 2, Office of Director 1p 16599 028 24X Fiche 50-416, 82/12/22, 8212300084

8212300114 Forwards LER 82-144/03L-0
MCOAUGHY, J P Mississippi Power & Light Co 82/12/22
O'REILLY, J P Region 2, Office of Director 1p 16598 231 24X
Fiche 50-416, 82/12/22, 8212300114

--8212300119 LER 82-144/03L-0 on 821125, fire detection zones 2-7 & 2-B alarmed w/no fire or smoke present Cause undetermined Smoke detectors N531G & N707B reset
BYRD, R Mississippi Power & Light Co 82/12/22 Region 2, Office of Director 1p 16598 232 24X Fiche 50-416, 82/12/22, 8212300114

8212300186 Forwards LER 82-145/03L-0
MCOAUGHY, J P Mississippi Power & Light Co 82/12/22
O'REILLY, J P Region 2, Office of Director 1p 16598 029 24X
Fiche 50-416, 82/12/22, 8212300186

--8212300200 LER 82-145/03L-0 on 821127, meteorological monitoring sys removed from svc for approx 7.5 h to perform work as required by Design Change Package 82-457 Caused by planned maint outage Change implemented
BYRD, R Mississippi Power & Light Co 82/12/22 Region 2, Office of Director 1p 16598 030 24X Fiche 50-416, 82/12/22, 8212300186

8212300222 Forwards LER 82-153/99T-0
MCOAUGHY, J P Mississippi Power & Light Co 82/12/23
O'REILLY, J P Region 2, Office of Director 1p 16598 034 24X
Fiche 50-416, 82/12/23, 8212300222

--8212300228 LER 82-153/99T-0 on 821207, during daily channel check, channel A wind direction sensor at elevation 162 ft gave erroneous indication Caused by defective sensor Sensor replaced & channel returned to svc
ROHRER, M V Mississippi Power & Light Co 82/12/23 Region 2, Office of Director 1p 16598 035 24X Fiche 50-416, 82/12/23, 8212300222

DOCKET 50-417 GRAND OULF NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

8212300066 Generic Ltr 82-27 to all BWR licensees of operating reactors except LACBWR, Big Rock Point, Dresden 1, Humboldt Bay, applicants for OL & holders of CP re transmittal of NUREG-0763 & NUREG-0783 Svc list encl W/o stated encl EISENHUT, D O Division of Licensing 82/11/15 General Public Utilities - OPU Service Corp 22pp 16387 004 24X
Fiche 50-000, 82/11/15, 8212300066

8212070274 Forwards balance of info to close Humphrey containment concerns, including "Evaluation Rpt on Modified BOLA-VDF Code" & "Survey of Tests & Analyses on Effectiveness of RHR Sys in Pool-Cooling Mode" & proprietary Figures 18 - 25
DALE, L F Mississippi Power & Light Co 82/12/03 DENTON, H R Office of Nuclear Reactor Regulation, Director 62pp 16340 128 24X Fiche 50-416, 82/12/03, 8212070274

--8212070276 "Evaluation Rpt on Modified BOLA-VDF Code"
HIRT, C W, SICILIAN, J M Flow Science, Inc 82/10/18 11pp 16340 190 24X Fiche 50-416, 82/12/03, 8212070274

--8212070278 Revision A to "Survey of Tests & Analyses on Effectiveness of RHR Sys in Pool-Cooling Mode"
* Quadrex Corp QUAD-1-B2-245 REV A 82/11/30 51pp 16340 201 24X Fiche 50-416, 82/12/03, 8212070274

8212170278 Comments on BWR00-8260, "NUREG-0737, Item II K 3 18, Mod of Automatic Depressurization Sys Logic" Option 4, providing bypass timer delay, will assure adequate core cooling during worst case conditions
DALE, L F Mississippi Power & Light Co 82/12/14 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 16461 152 24X Fiche 50-416, 82/12/14, 8212170278

8212230252 Discusses util responses to recently discussed unresolved NRC concerns re automatic depressurization sys air sys.
DALE, L F Mississippi Power & Light Co 82/12/20 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 16511 063 24X Fiche 50-416, 82/12/20, 8212230252

DOCKETED ITEMS

B212270154 Submits updated qualification status & justification for interim operation of NSSS equipment not meeting SGRT criteria, originally submitted B20403
DALE, L F Mississippi Power & Light Co 82/12/22 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 16538 343
24X Fiche 50-416, 82/12/22, B212270154

F Security, medical, emergency & fire protection plans

B212290207 Submits supplemental info on emergency preparedness at Facilities State of LA revised radiological emergency preparedness plan will be submitted in Feb 1983, due to delays at state level
THOMAS, L M Federal Emergency Management Agency 82/12/17
DIRCKAS, H Office of the Executive Director for Operations 1p
16578 202 24X Fiche 50-416, 82/12/17, B212290207

B212270235 Forwards addl info re adequacy of onsite communication sys, per B21115 telcon Communication sys testing during startup phase will provide confidence that use of two-way radios is restricted, as required
DALE, L F Mississippi Power & Light Co 82/12/22 DENTON, H R
Office of Nuclear Reactor Regulation, Director 13pp 16536 253
24X Fiche 50-416, 82/12/22, B212270235

G Adjudicatory correspondence

B212100113 Decision ALAB-704, affirming ASLB B21020 decision denying State of LA B20721 petition to intervene subj to final outcome of judicial proceedings before US Supreme Court in NRC vs NRCDC
SHOENMAKER, C J Atomic Safety and Licensing Appeal Panel 82/12/08
13pp 16375 346 24X Fiche 50-416, 82/12/08, B212100113

H Inspection reports, IE Bulletins & correspondence

B208190240 IE Bulletin B2-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Svc list encl
DEVOUNO, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc
112pp 16462 163 24X Fiche 50-000, 82/10/28, B208190240

B212090357 Forwards IE Insp Rept 50-417/82-16 on B21012-15 No noncompliance noted
VERRELLI, D M Division of Project & Resident Programs 82/10/28
STAMPLEY, N L Mississippi Power & Light Co 2pp 16365 152 24X
Fiche 50-417, 82/10/28, B212090357

--B212090364 IE Insp Rept 50-417/82-16 on B21012-15 No noncompliance noted Major areas inspected structural concrete
HARRIS, J R, CONLON, T E Division of Engineering & Technical Programs 82/10/26 3pp 16365 154 24X Fiche 50-417, 82/10/28, B212090367

B212070414 Approves issuance of SALP Repts 50-416/82-45 & 50-417/82-11 for Jul 1980-June 1981 Mgt attentive to matters of nuclear safety Weaknesses in Unit 1 preoperational testing & training programs noted
O'REILLY, J P Region 2, Office of Director 82/11/01
STAMPLEY, N L Mississippi Power & Light Co 2pp 16365 013. 24X
Fiche 50-416, 82/11/01, B212090414

--B212090421 Forwards SALP Repts 50-416/82-45 & 50-417/82-11 for Jul 1980-June 1981 Comments requested within 20 days
LEWIS, R C Division of Project & Resident Programs 82/07/22
STAMPLEY, N L Mississippi Power & Light Co 2pp 16365 014 24X
Fiche 50-416, 82/11/01, B212090414

--B212090427 SALP Repts 50-416/82-45 & 50-417/82-11 for Jul 1980-June 1981 Weaknesses in Unit 1 preoperational testing & training programs noted
* Region 2, Office of Director 82/07/22 15pp 16365 017 24X
Fiche 50-416, 82/11/01, B212090414

B208190245 IE Info Notice B2-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/05
Consolidated Edison Co of New York, Inc. 110pp
16372:142 24X Fiche 50-000, 82/11/05, B208190245.

B208190251 IE Info Notice B2-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18
Consolidated Edison Co of New York, Inc 109pp 16411 199 24X
Fiche 50-000, 82/11/18, B208190251

B208190256 IE Info Notice B2-46, "Defective & Obsolete Combination Padlocks " Svc list encl
DEVOUNO, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc
127pp 16411 065 24X Fiche 50-000, 82/11/26, B208190256

B208190257 IE Info Notice B2-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp
16387 028 24X Fiche 50-000, 82/11/30, B208190257

B208190259 IE Bulletin B2-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl
DEVOUNO, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc
113pp 16411 317 24X Fiche 50-000, 82/12/03, B208190259

B208190261 IE Info Notice B2-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X
Fiche 50-000, 82/12/03, B208190261

B208190267 IE Info Notice B2-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
DEVOUNO, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc
127pp 16628 191 24X Fiche 50-000, 82/12/16, B208190267

B208190268 IE Info Notice B2-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27 " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X
Fiche 50-000, 82/12/20, B208190268

I Reportable occurrences, LERs & related correspondence

B212280377 Final Deficiency Rept PRD-B2/33 re excessive length of cap screws in standby diesel generator air start valve assembly potentially resulting in valve failure Initially reported on B20623 Deficiency not reportable per Part 21
MCCORMACK, J P Mississippi Power & Light Co 82/12/15
O'REILLY, J P Region 2, Office of Director 5pp 16559 006 24X
Fiche 50-416, 82/12/15, B212280377

DOCKET 50-423 MILLSTONE NUCLEAR POWER STATION, UNIT 3

A Application/construction stage documents & correspondence

B212290061 Requests lists of reviewers from each branch who will be assigned to plant QL applications & list of SRP sections for which reviewers will be performing safety reviews
YOUNGBLOOD, B J Licensing Branch 82/12/09 THOMAS, C
Standardization & Special Projects Branch EVANS, L J Fuel Facility
Safeguards Licensing Branch MCCORMACK, J P Power Reactor Safeguards
Licensing Branch 2pp 16606 360 24X Fiche 50-000, 82/12/09, B212290061

B212300092 Responds to B21209 memo requesting identification of reviewers & associated SRP sections for forthcoming QL reviews EW McPeak & FD Anderson chosen to review Sections 13 & 16 & 10, respectively
THOMAS, C D Standardization & Special Projects Branch 82/12/23
YOUNGBLOOD, B J Licensing Branch 1p 16624 263 24X
Fiche 50-000, 82/12/23, B212300092

C Utility Environmental Report (ER), amends & correspondence

B212300023 Notifies that environ rept acceptable DES input should be completed within 2 months of receipt of PRA
YOUNGBLOOD, B J Licensing Branch 1 82/12/22 HULMAN, L O
Accident Evaluation Branch 1p 16624 282 24X
Fiche 50-423, 82/12/22, B212300023

D NRC Draft/Final Environmental Statements, suppls & correspondence

B212300023 Notifies that environ rept acceptable DES input should be completed within 2 months of receipt of PRA
YOUNGBLOOD, B J Licensing Branch 1 82/12/22 HULMAN, L O
Accident Evaluation Branch 1p 16624 282 24X
Fiche 50-423, 82/12/22, B212300023

F Security, medical, emergency & fire protection plans

B212210355 Forwards revision to physical security plan Revision withheld (ref 10CFR2 790)
COUNSIL, W G , CAQUETTA, J P Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL, W G Northeast Utilities 82/12/09
BENTON, H R Office of Nuclear Reactor Regulation, Director 1p
16489 176 24X Fiche 50-000, 82/12/09, 8212210355

G Inspection reports, IE Bulletins & correspondence

8208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel Recirculation Sys Piping at BWR Plants " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240

8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model B01 & Model B02 Thermoluminescent Dosimeters " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000, 82/11/05, 8208190245

8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X Fiche 50-000, 82/11/18, 8208190251

8212060187 Forwards IE Insp Rept 50-423/82-13 on 821018-22 No noncompliance noted
MARTIN, T T Division of Engineering & Technical Programs 82/11/22 COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 16311 050 24X Fiche 50-423, 82/11/22, 8212060187

--8212060190 IE Insp Rept 50-423/82-13 on 821018-22 No noncompliance noted Major areas inspected matl receipt insp of electrical components, cable & cable tray installation & GC insp of electrical work
RICHARDS, S , BETTENHAUSEN, L Division of Engineering & Technical Programs 82/11/17 4pp 16311 092 24X Fiche 50-423, 82/11/22, 8212060187

8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000, 82/11/26, 8208190256

8212140322 Forwards IE Insp Rept 50-423/82-12 on 820918-30 & 1001-23 No noncompliance noted
STAROSTECKI, R Division of Project & Resident Programs 82/11/29 COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 16401 273 24X Fiche 50-423, 82/11/29, 8212140322

--8212140337 IE Insp Rept 50-423/82-12 on 820918-30 & 1001-23 No noncompliance noted Major areas inspected Followup of previous insp findings, plant tours, electrical cable pulling & installation of reactor vessel internals
MATTIA, J C , ELSASSER, T Division of Project & Resident Programs 82/11/23 7pp 16401 275 24X Fiche 50-423, 82/11/29, 8212140322

8208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000, 82/11/30, 8208190257

8208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259

8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X Fiche 50-000, 82/12/03, 8208190261

8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16, 8208190267

8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27 " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X Fiche 50-000, 82/12/20, 8208190268

S Reportable occurrences, LERs & related correspondence

8212080541 Interim deficiency rept re failure of motor pinion gear shear keys in Limitorque Model B80 (SD-25) motor operated valves Initially reported on 820804 Vendor info inconclusive Evaluation continuing
COUNSIL, W G , CAQUETTA, J P Northeast Nuclear Energy Co (subs of Northeast Utilities) CAQUETTA, J P Northeast Utilities 82/11/24 HAYNES, R C Region 1, Office of Director 2pp 16392 038 24X Fiche 50-423, 82/11/24, 8212080541

8212160470 Interim deficiency rept re cracks related to embedments in containment crane wall (SD-29) Initially reported on 821105 Investigation continuing Update will be provided by 820215
COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL, W G Northeast Utilities 82/12/07 HAYNES, R C Region 1, Office of Director 1p 16442 112 24X Fiche 50-423, 82/12/07, 8212160470

DOCKET 50-424 ALVIN W VOOTLE NUCLEAR PLANT, UNIT 1

A Application/construction stage documents & correspondence

8212280356 Advises that submittal of QA organizational change in Chapter 17 of PSAR will be delayed until Feb or Mar 1983, to allow for inclusion of addl info on refinements to QA program
DUTTON, D E Georgia Power Co 82/12/21 EISENHUT, D O Division of Licensing 1p 16360 099 24X Fiche 50-424, 82/12/21, 8212280356

Q Inspection reports, IE Bulletins & correspondence

8208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel Recirculation Sys Piping at BWR Plants " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240

8212090248 Forwards IE Insp Repts 50-424/82-25 & 50-425/82-25 on 821018-20 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 82/11/02 KELLY, R J Georgia Power Co 2pp 16363 350 24X Fiche 50-424, 82/11/02, 8212090248

--8212090258 IE Insp Repts 50-424/82-25 & 50-425/82-25 on 821018-20 No noncompliance noted Major areas inspected diesel generator storage, observation of cable tray support installation, QA audits & QA/GC procedures
HUNT, M D , CONLON, T E Division of Engineering & Technical Programs 82/10/29 4pp 16363 352 24X Fiche 50-424, 82/11/02, 8212090248

8212090227 Forwards IE Insp Repts 50-424/82-24 & 50-425/82-24 on 820911-1010 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 82/11/03 KELLY, R J Georgia Power Co 2pp 16361 300 24X Fiche 50-424, 82/11/03, 8212090227

--8212090245 IE Insp Repts 50-424/82-24 & 50-425/82-24 on 820911-1010 No noncompliance noted Major areas inspected primary containment, auxiliary bldg, control bldg, fuel handling bldg, steam generator mods & pipe spool & control panel insp
SANDERS, W F , BROWNLEE, V L Division of Project & Resident Programs 82/11/01 6pp 16361 302 24X Fiche 50-424, 82/11/03, 8212090227

8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model B01 & Model B02 Thermoluminescent Dosimeters " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000, 82/11/05, 8208190245

8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance, 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X Fiche 50-000, 82/11/18, 8208190251

8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411, 065 24X Fiche 50-000, 82/11/26, 8208190256

DOCKETED ITEMS

8208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards
82/11/30 Consolidated Edison Co of New York, Inc 356pp
16387 028 24X Fiche 50-000, 82/11/30, 8208190257

8208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259

8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X Fiche 50-000, 82/12/03, 8208190261

8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16428 191 24X Fiche 50-000, 82/12/16, 8208190267

8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27 " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X Fiche 50-000, 82/12/20, 8208190268

DOCKET 50-425 ALVIN W VOOTLE NUCLEAR PLANT, UNIT 2

A Application/construction stage documents & correspondence

8212280356 Advises that submittal of QA organizational change in Chapter 17 of PSAR will be delayed until Feb or Mar 1983, to allow for inclusion of addl info on refinements to QA program
DUTTON, D E Georgia Power Co 82/12/21 EISENHUT, D O Division of Licensing 1p 16560 099 24X Fiche 50-424, 82/12/21, 8212280356

Q Inspection reports, IE Bulletins & correspondence

8208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240

8212090248 Forwards IE Insp Repts 50-424/82-25 & 50-425/82-25 on 821018-20 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 82/11/02 KELLY, R J Georgia Power Co 2pp 16363 390 24X Fiche 50-424, 82/11/02, 8212090248

--8212090258 IE Insp Repts 50-424/82-25 & 50-425/82-25 on 821018-20 No noncompliance noted Major areas inspected, diesel generator storage, observation of cable tray support installation, QA audits & QA/QC procedures
HUNT, M D, CONLON, T E Division of Engineering & Technical Programs 82/10/29 4pp 16363 352 24X Fiche 50-424, 82/11/02, 8212090248

8212090227 Forwards IE Insp Repts 50-424/82-24 & 50-425/82-24 on 820911-1010 No noncompliance noted.
DANCE, H C Division of Project & Resident Programs 82/11/03 KELLY, R J Georgia Power Co 2pp 16361 300 24X Fiche 50-424, 82/11/03, 8212090227

--8212090245 IE Insp Repts 50-424/82-24 & 50-425/82-24 on 820911-1010 No noncompliance noted Major areas inspected primary containment, auxiliary bldg, control bldg, fuel handling bldg, steam generator mods & pipe spool & control panel insp
SANDERS, W F, BROWNLEE, V L Division of Project & Resident Programs 82/11/01 6pp 16361 302 24X Fiche 50-424, 82/11/03, 8212090227

8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model B01 & Model B02 Thermoluminescent Dosimeters " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/03 Consolidated Edison Co of New York, Inc 110pp 16372:142 24X Fiche 50-000, 82/11/03, 8208190245

8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co. of New York, Inc 109pp 16411 199 24X Fiche 50-000, 82/11/18, 8208190251

8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000, 82/11/26, 8208190256

8208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000, 82/11/30, 8208190257

8208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259

8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X Fiche 50-000, 82/12/03, 8208190261

8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16, 8208190267

8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27 " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X Fiche 50-000, 82/12/20, 8208190268

DOCKET STN-50-437 FLOATING NUCLEAR PLANT

A Application/construction stage documents & correspondence

8212270418 Responds to FOIA request for documents re proposed revision &/or update to reactor safety study referred to in NUREG-0784, Chapter 10 as RS 11 & all documents pertaining to reactor cooling methods Forwards documents listed in app
FELTON, J M Division of Rules and Records 82/11/26 SHOLLY, S C Union of Concerned Scientists 3pp 16549 233 24X Fiche 50-000, 82/11/26, 8212270418

--8211050027 Forwards summary of semiscale test results & advises that board notification re test results issued w/o encl
NOVAK, T M Assistant Director for Licensing 82/09/24 Division of Licensing 1p 16549 278 24X Fiche 50-000, 82/11/26, 8212270418

8212220440 Board Notifications 82-125 & 82-125A forwards info re H Etherington evaluation of flow blockage during natural circulation of PWRs Results do not adversely impact present position on reliance on natural circulation
NOVAK, T M Assistant Director for Licensing 82/12/14 Atomic Safety and Licensing Board Panel 5pp 16523 135 24X Fiche 50-000, 82/12/14, 8212220440

8212220441 Board Notification 82-124 forwards RJ Mattson 821123 memo re Semiscale S-UT-8 test results Phenomena of core level depression & loop seal clearing may be more complex than previously supposed
NOVAK, T M Assistant Director for Licensing 82/12/14 Atomic Safety and Licensing Board Panel 7pp 16523 169 24X Fiche 50-000, 82/12/14, 8212220441

8212270481 Notifies that manufacturing license for Offshore Power Sys will be issued on 821217
DIRCHS, W J Office of the Executive Director for Operations 82/12/15 PALLADINO, N J, GILINSKY, V, AHEARNE, J Commissioners 1p 16548 362 24X Fiche 50-437, 82/12/15, 8212270481

8212270423 Forwards Manufacturing License ML-1 for production of up to eight floating nuclear plants & FR notice of issuance
EISENHUT, D O Division of Licensing 82/12/17 THOMAS, R A Offshore Power Systems (subs of Westinghouse Electric Corp) 2pp 16571 293 24X Fiche 50-437, 82/12/17, 8212270423

--8212270425 Manufacturing License ML-1 for production of up to eight floating nuclear plants
EISENHUT, D O Division of Licensing 82/09/30 13pp 16571 295 24X Fiche 50-437, 82/12/17, 8212270423

--8212270426 Notice of issuance of Manufacturing License ML-1
ADENBAM, E O Licensing Branch 4 82/12/17 4pp 16571 309 24X Fiche 50-437, 82/12/17, 8212270423

G Adjudicatory correspondence

B212070168 Memorandum & Order CL1-82-37, finding that immediate effectiveness review does not apply to mfg licenses Mfg license can become effective before becoming final
Commissioners Gilinsky & Ahearne separate views encl
CHILK, S J Office of the Secretary of the Commission 82/12/06
12pp 16335 299 24X Fiche 50-000, 82/12/06, B212070168

G Inspection reports, IE Bulletins & correspondence

B208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc
112pp 16462 163 24X Fiche 50-000, 82/10/28, B208190240

B208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model B01 & Model B02 Thermoluminescent Dosimeters " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp
16372 142 24X Fiche 50-000, 82/11/05, B208190245

B208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X
Fiche 50-000, 82/11/18, B208190251

B208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc
127pp 16411 065 24X Fiche 50-000, 82/11/26, B208190256

B208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp
16387 028 24X Fiche 50-000, 82/11/30, B208190257

B208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc
113pp 16411 317 24X Fiche 50-000, 82/12/03, B208190259

B208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X
Fiche 50-000, 82/12/03, B208190261

B208190267 IE Info Notice 82-49, "Correction For Sample Conditions for Air & Gas Monitoring " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc
127pp 16628 191 24X Fiche 50-000, 82/12/16, B208190267

B208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27 " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20, Consolidated Edison Co of New York, Inc 108pp 16628 293 24X
Fiche 50-000, 82/12/20, B208190268

I Hearing transcripts on non-antitrust matters

B212020226 Unofficial transcript of B21123 affirmation/discussion & vote in Washington, DC re SECY-82-425 & SECY-82-449
* Commissioners 82/11/23 Spp 16308 193 24X
Fiche 50-000, 82/11/23, B212020226

DOCKET 50-438 BELLEFONTE NUCLEAR PLANT, UNIT 1

F Security, medical, emergency & fire protection plans

B212100046 Responds to R Heron 811202 telcon request re emergency operations facility (EOF) Response to Generic Ltr 81-10 on 810602 describes util plans to utilize central emergency response ctr Project-specific details to be provided
KAMMER, D S Tennessee Valley Authority 82/12/06 ADENSA, E
Licensing Branch 4 1p 16379 071 24X Fiche 50-000, 82/12/06, B212100046

J Insurance & indemnity information

B212020269 Submits info re const & warehouse values located offsite as result of revised site descriptions under ANI/MAELU nuclear liability insurance facility form policies
DUCK, J R Marsh & McLennan, Inc, M & M Nuclear Consultants, Inc Div 82/11/18 HAINES, H L American Nuclear Insurers 1p 16288 356
24X Fiche 50-000, 82/11/18, B212020269

B212300300 Forwards Endorsement 16 to NELIA Policy NF-258
DUCK, J R Marsh & McLennan, Inc, M & M Nuclear Consultants, Inc Div 82/12/27 SALTZMAN, J Assistant Director for State & Licensee Relations 2pp 16594 195 24X Fiche 50-438, 82/12/27, B212300300

K Utility Final Safety Analysis Report (FSAR) & amends

B212280437 Forwards affidavit of LM Mills certifying svc of Amend 23 to FSAR on 821221
MILLS, L M Tennessee Valley Authority 82/12/22 ADENSA, E
Licensing Branch 4 1p 16356 059 24X Fiche 50-438, 82/12/22, B212280437

G Inspection reports, IE Bulletins & correspondence

B208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc
112pp 16462 163 24X Fiche 50-000, 82/10/28, B208190240

B208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model B01 & Model B02 Thermoluminescent Dosimeters " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp
16372 142 24X Fiche 50-000, 82/11/05, B208190245

B212090528 Forwards IE Insp Repts 50-438/82-29 & 50-439/82-29 on B21026-29 No noncompliance noted
VERRELLI, D M Division of Project & Resident Programs 82/11/12
PARRIS, H Q Tennessee Valley Authority 2pp 16366 303 24X
Fiche 50-438, 82/11/12, B212090528

--B212090536 IE Insp Repts 50-438/82-29 & 50-439/82-29 on B21026-29 No noncompliance noted Major areas inspected licensee action on previous enforcement matters, RCPB pipe welds, safety-related pipe support & restraint sys & IE Bulletins 79-02 & 79-14
GIRARD, E H, LIU, W C, BLAKE, J J Division of Engineering & Technical Programs 82/11/10 10pp 16366 305 24X
Fiche 50-438, 82/11/12, B212090528

B208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X
Fiche 50-000, 82/11/18, B208190251

B208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc
127pp 16411 065 24X Fiche 50-000, 82/11/26, B208190256

B208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp
16387 028 24X Fiche 50-000, 82/11/30, B208190257

B208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc
113pp 16411 317 24X Fiche 50-000, 82/12/03, B208190259

B208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X
Fiche 50-000, 82/12/03, B208190261

B208190267 IE Info Notice 82-49, "Correction For Sample Conditions for Air & Gas Monitoring " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc
127pp 16628 191 24X Fiche 50-000, 82/12/16, B208190267

DOCKETED ITEMS

8208190268 IE Info Notsce 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27 " Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance 82/12/20
Consolidated Edison Co. of New York, Inc 108pp 16628 293 24X
Fiche 50-000, 82/12/20, 8208190268

S Reportable occurrences, LERs & related correspondence

8212020107 Seventh interim deficiency rept re old grease pumped on motor winding of reactor bldg cooling fans Initially reported on 810128 Tubing removed & grease relief holes plugged Next rept by 830223 Also reportable per Part 21
MILLS, L. M. Tennessee Valley Authority 82/11/23 O'REILLY, J. P
Region 2, Office of Director 2pp 16272 029 24X
Fiche 50-438, 82/11/23, 8212020107

8212020139 Final deficiency rept re water in rock anchor tendon head protective grease cans Initially reported on 790523 Ground water will not prevent prestressing sys from performing intended functions Components tested for corrosion
MILLS, L. M. Tennessee Valley Authority 82/11/23 O'REILLY, J. P
Region 2, Office of Director 2pp 16274 164 24X
Fiche 50-438, 82/11/23, 8212020139

8212020137 First interim deficiency rept re unqualified flux hose connections Initially reported on 821027 Package of all info re flux hose assembled for reanalysis Next rept expected by 830430
MILLS, L. M. Tennessee Valley Authority 82/11/24 O'REILLY, J. P
Region 2, Office of Director 2pp 16274 159 24X
Fiche 50-438, 82/11/24, 8212020137

8212020149 First interim deficiency rept re failure to analyze isometrics & load tables Initially reported on 821026 Analysis check errors subsequently identified Deficiency will be addressed when errors resolved Next rept by 830322
MILLS, L. M. Tennessee Valley Authority 82/11/24 O'REILLY, J. P
Region 2, Office of Director 2pp 16274 157 24X
Fiche 50-438, 82/11/24, 8212020149

8212020162 First interim deficiency rept re failure to review diagrams properly Initially reported on 821027 Review of revisions to functional control logic diagrams continuing Next rept will be submitted by 830722
MILLS, L. M. Tennessee Valley Authority 82/11/24 O'REILLY, J. P
Region 2, Office of Director 2pp 16274 174 24X
Fiche 50-438, 82/11/24, 8212020162

8212030001 First interim deficiency rept re easily bent heat collecting fins & corroding sprinkler heads in fire suppression sys Initially reported on 821026 Proposed disposition to replace Star Model GE sprinkler heads under review
MILLS, L. M. Tennessee Valley Authority 82/11/29 O'REILLY, J. P
Region 2, Office of Director 2pp 16304 212 24X
Fiche 50-000, 82/11/29, 8212030001

8212030072 Fourth interim deficiency rept re chiller unit piping components mfg by Dunham-Bush improperly welded Initially reported on 820111 Next rept expected by 830620 Also reportable per Part 21
MILLS, L. M. Tennessee Valley Authority 82/11/29 O'REILLY, J. P
Region 2, Office of Director 2pp 16304 214 24X
Fiche 50-438, 82/11/29, 8212030072

8212030152 Second interim deficiency rept re design problems w/B&W steam generators Initially reported on 820830 Addition of external header investigated Next rept expected by 830131 Also reportable per Part 21
MILLS, L. M. Tennessee Valley Authority 82/11/29 O'REILLY, J. P
Region 2, Office of Director 2pp 16303 305 24X
Fiche 50-438, 82/11/29, 8212030152

8212090163 Final deficiency rept re steam pressure regulator malfunction verification requirements Initially reported on 810519 DNR requirements met No evidence found that deficiency exists
MILLS, L. M. Tennessee Valley Authority 82/12/03 O'REILLY, J. P
Region 2, Office of Director 2pp 16359 096 24X
Fiche 50-438, 82/12/03, 8212090163

8212100270 Fifth interim deficiency rept re lack of Div of Engineering design sys to ensure QA procedures issued before work begins Initially reported on 811020 Final rept will not be submitted until decision made on deferral of projects
MILLS, L. M. Tennessee Valley Authority 82/12/06 O'REILLY, J. P
Region 2, Office of Director 1p 16377 136 24X
Fiche 50-000, 82/12/06, 8212100270

8212140047 Seventh interim deficiency rept re miscategorization of main feedwater & containment isolation valves Initially reported on 810106 Atwood & Morrill seismic & stress rept re swing check valves qualification approved Next rept by 830331
MILLS, L. M. Tennessee Valley Authority 82/12/06 O'REILLY, J. P
Region 2, Office of Director 2pp 16408 279 24X
Fiche 50-438, 82/12/06, 8212140047

8212140415 Final deficiency rept re conduit loading on annulus framing in reactor bldg Initially reported on 820802 No corrective action necessary Subj nonconformance determined not reportable per 10CFR50.55(e)
MILLS, L. M. Tennessee Valley Authority 82/12/06 O'REILLY, J. P
Region 2, Office of Director 2pp 16403 318 24X
Fiche 50-438, 82/12/06, 8212140415

8212150079 Revised final deficiency rept re pipe hanger documentation error Initially reported on 810128 Const informed by 810601 memo that final approval by div of engineering design manager must be received before installation of hangers
MILLS, L. M. Tennessee Valley Authority 82/12/08 O'REILLY, J. P
Region 2, Office of Director 2pp 16431 019 24X
Fiche 50-438, 82/12/08, 8212150079

8212170157 Fourth interim deficiency rept re improper use of foam plastic installation on stainless steel pipe Initially reported on 820203 Instruction memo re insulation types & drawings revised Next rept expected by 830321
MILLS, L. M. Tennessee Valley Authority 82/12/10 O'REILLY, J. P
Region 2, Office of Director 2pp 16462 026 24X
Fiche 50-438, 82/12/10, 8212170157

8212170160 Second revised final deficiency rept re Johnson Machine Works welds on revolving platform trucks Initially reported on 811106 Also reportable per Part 21 New welding magnetic particle or dye penetrant tested & training initiated
MILLS, L. M. Tennessee Valley Authority 82/12/10 O'REILLY, J. P
Region 2, Office of Director 3pp 16462 023 24X
Fiche 50-438, 82/12/10, 8212170160

8212170221 Supplemental deficiency rept re unacceptable replacement for component cooling water pump shaft Initially reported on 820301 Completion of corrective actions expected by 830201 Also reportable per Part 21
MILLS, L. M. Tennessee Valley Authority 82/12/10 O'REILLY, J. P
Region 2, Office of Director 1p 16459 336 24X
Fiche 50-438, 82/12/10, 8212170221

8212200001 Third interim deficiency rept re generic deficiency in design review Initially reported on 811219 No addl info available until action team 821215 rept Next rept will be submitted by 830420
MILLS, L. M. Tennessee Valley Authority 82/12/13 O'REILLY, J. P
Region 2, Office of Director 1p 16473 362 24X
Fiche 50-000, 82/12/13, 8212200001

8212200017 Fifth interim deficiency rept re design review process interface coordination activity Initially reported on 810717 Corrective action to be based on action team rept to be issued approx 821215 Next rept expected by 830422
MILLS, L. M. Tennessee Valley Authority 82/12/13 O'REILLY, J. P
Region 2, Office of Director 2pp 16473 085 24X
Fiche 50-000, 82/12/13, 8212200017

8212210256 Fifth interim deficiency rept re potential stress corrosion cracking in RCS supports & restraints for bolt torques Initially reported on 810824 Util program to survey RCS matl properties continuing Also reported per Part 21
MILLS, L. M. Tennessee Valley Authority 82/12/13 O'REILLY, J. P
Region 2, Office of Director 2pp 16483 301 24X
Fiche 50-438, 82/12/13, 8212210256

8212210026 Fourth interim deficiency rept re potentially overstressed embedded plates Initially reported on 820412 Multiple supports attached to plates w/o design review of plate capacity Preliminary const spec issued Next rept by 830404
MILLS, L. M. Tennessee Valley Authority 82/12/14 O'REILLY, J. P
Region 2, Office of Director 2pp 16485 260 24X
Fiche 50-000, 82/12/14, 8212210026

8212210122 Fourth interim deficiency rept re omissions to auxiliary feedwater pump drawings Initially reported on 820225 Auxiliary feedwater pump vents, drains & turbine cooling water piping incorporated into drawings Next rept by 830409
MILLS, L. M. Tennessee Valley Authority 82/12/14 O'REILLY, J. P
Region 2, Office of Director 2pp 16485 128 24X
Fiche 50-438, 82/12/14, 8212210122

8212210364 Third interim deficiency rept re valves mfg by Target Rock Valve Co & YARWAY Corp not qualified as active components Initially reported on 820412 Qualifying documentation expected by 830201 Next rept expected by 830330
MILLS, L. M. Tennessee Valley Authority 82/12/14 O'REILLY, J. P
Region 2, Office of Director 2pp 16493 096 24X
Fiche 50-438, 82/12/14, 8212210364

B212210431 Fourth interim deficiency rept re resolution of anticipated vibratory loading concerns Initially reported on B20120 Const activities for Yellow Creek & Hartsville deferred Next rept will be sent by B30322
MILLS, L. M. Tennessee Valley Authority 82/12/15 O'REILLY, J. P
Region 2, Office of Director 2pp 16489 168 24X
Fiche 50-000, 82/12/15, B212210431

B212280358 First interim deficiency rept re substitution of grouted anchors for wedge bolts w/o ensuring adequate shear load capacities Initially reported on B21117 TVA will evaluate deficiency Next rept will be submitted by B30328
MILLS, L. M. Tennessee Valley Authority 82/12/15 O'REILLY, J. P
Region 2, Office of Director 3pp 16558 357 24X
Fiche 50-438, 82/12/15, B212280358

B212300006 Final deficiency rept re allowable stresses for pipe support design Initially reported on B11207 Nonconformance not reportable per 10CFR50.55(e) because condition not nonconforming or adverse to safe operation
MILLS, L. M. Tennessee Valley Authority 82/12/16 O'REILLY, J. P
Region 2, Office of Director 8pp 16598 136 24X
Fiche 50-438, 82/12/16, B212300006

B212220419 First interim deficiency rept re improper use of alternate analysis eibolets Initially reported on B21118 Piping w/eibolets qualified by alternate criteria identified & evaluated Next rept due by B30323
MILLS, L. M. Tennessee Valley Authority 82/12/17 O'REILLY, J. P
Region 2, Office of Director 2pp 16503 272 24X
Fiche 50-438, 82/12/17, B212220419

B212280064 Second interim deficiency rept re shielded power cable bend radius Initially reported on B20806 Cable samples will be tested for worst case bend installation Next rept will be submitted by B30722
MILLS, L. M. Tennessee Valley Authority 82/12/20 O'REILLY, J. P
Region 2, Office of Director 2pp 16565 137 24X
Fiche 50-438, 82/12/20, B212280064

B212280305 Final Deficiency Repts 50-438/82-58 & 50-439/82-52 re nonconforming reactor bldg door weld by Johnson Machine Works Initially reported on B20816 Reactor bldg equipment hatch doors to be reworked Also reported per Part 21
MILLS, L. M. Tennessee Valley Authority 82/12/20 O'REILLY, J. P
Region 2, Office of Director 3pp 16562 055 24X
Fiche 50-438, 82/12/20, B212280305

B212280328 Third interim deficiency rept re B&W design of RCS supports & restraints Initially reported on B20618 B&W recommended disposition reviewed & comments returned for evaluation Next rept will be submitted by B30620
MILLS, L. M. Tennessee Valley Authority 82/12/20 O'REILLY, J. P
Region 2, Office of Director 2pp 16561 062 24X
Fiche 50-438, 82/12/20, B212280328

B212280100 Fourth interim deficiency rept re small globe valves in auxiliary feedwater sys exceeding weight & length limitations Initially reported on B20222 Valves replaced on Unit 1 Unit 2 drawings revised Next rept due by B30415
MILLS, L. M. Tennessee Valley Authority 82/12/21 O'REILLY, J. P
Region 2, Office of Director 2pp 16564 219 24X
Fiche 50-438, 82/12/21, B212280100

B212280210 Supplemental deficiency rept re GE relays Initially reported on B10513 Addl relay coils needed for replacement in intake pumping station Completion expected by B30430 Also reportable under Part 21
MILLS, L. M. Tennessee Valley Authority 82/12/21 O'REILLY, J. P
Region 2, Office of Director 1p 16562 286 24X
Fiche 50-438, 82/12/21, B212280210

B212280340 Second interim deficiency rept re steam generator support bolts mfg by Lakeside Bridge & Steel Initially reported on B20723 Applicant awaiting results of bolt testing & evaluation Next rept will be submitted by B30331
MILLS, L. M. Tennessee Valley Authority 82/12/21 O'REILLY, J. P
Region 2, Office of Director 2pp 16560 097 24X
Fiche 50-438, 82/12/21, B212280340

DOCKET 50-439 BELLEFONTE NUCLEAR PLANT, UNIT 2

F. Security, medical, emergency & fire protection plans

B212100046 Responds to R Heron B11202 telcon request re emergency operations facility (EOF) Response to Generic Ltr B1-10 on B10602 describes util plans to utilize central emergency response ctr Project-specific details to be provided
KAHMER, D. S. Tennessee Valley Authority 82/12/06 ADENSAM, E
Licensing Branch 4 1p 16379 071 24X Fiche 50-000, 82/12/06, B212100046

J Insurance & indemnity information

B212020269 Submits info re const & warehouse values located offsite as result of revised site descriptions under ANI/HAELU nuclear liability insurance facility form policies
DUCK, J. R. Marsh & McLennan, Inc. H & M Nuclear Consultants, Inc. Div
B2/11/18 HAINES, H. C. American Nuclear Insurers 1p 16288 356
24X Fiche 50-000, 82/11/18, B212020269

B212300300 Forwards Endorsement 16 to NELIA Policy NF-258
DUCK, J. R. Marsh & McLennan, Inc. H & M Nuclear Consultants, Inc. Div
B2/12/27 SALTZMAN, J. Assistant Director for State & License Relations 2pp 16594 195 24X Fiche 50-438, 82/12/27, B212300300

K Utility Final Safety Analysis Report (FSAR) & amends

B212280437 Forwards affidavit of LM Mills certifying svc of Amend 23 to FSAR on B21221
MILLS, L. M. Tennessee Valley Authority 82/12/22 ADENSAM, E
Licensing Branch 4 1p 16556 059 24X Fiche 50-438, 82/12/22, B212280437

L Inspection reports, IE Bulletins & correspondence

B208190240 IE Bulletin B2-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Svc list encl
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co. of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, B208190240

B208190245 IE Info Notice B2-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list encl
COBB, L. I. Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co. of New York, Inc 110pp 16372 142 24X Fiche 50-000, 82/11/05, B208190245

B212090528 Forwards IE Insp Repts 50-438/82-29 & 50-439/82-29 on B21026-29 No noncompliance noted
VERRELLI, D. M. Division of Project & Resident Programs 82/11/12 PARRIS, H. O. Tennessee Valley Authority 2pp 16366 303 24X
Fiche 50-438, 82/11/12, B212090528

--B212090536 IE Insp Repts 50-438/82-29 & 50-439/82-29 on B21026-29 No noncompliance noted Major areas inspected licensee action on previous enforcement matters, RCPB pipe welds, safety-related pipe support & restraint sys & IE Bulletins 79-02 & 79-14
OIRARD, E. H., LIU, W. C., BLAKE, J. J. Division of Engineering & Technical Programs 82/11/10 10pp 16366 305 24X
Fiche 50-438, 82/11/12, B212090528

B208190251 IE Info Notice B2-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co. of New York, Inc. 107pp 16411 199 24X
Fiche 50-000, 82/11/18, B208190251

B208190256 IE Info Notice B2-46, "Defective & Obsolete Combination Radiolocks " Svc list encl
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co. of New York, Inc 127pp 16411 065 24X Fiche 50-000, 82/11/26, B208190256

B208190257 IE Info Notice B2-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl
COBB, L. I. Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co. of New York, Inc 356pp 16387 028 24X Fiche 50-000, 82/11/30, B208190257

B208190259 IE Bulletin B2-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co. of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, B208190259

B208190261 IE Info Notice B2-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co. of New York, Inc 110pp 16462 064 24X
Fiche 50-000, 82/12/03, B208190261

B208190267 IE Info Notice B2-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co. of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16, B208190267

DOCKETED ITEMS

8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relay Type ITE-27" Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance 82/12/20
Consolidated Edison Co of New York, Inc 108pp 16628 273 24X
Fiche 50-000, 82/12/20, 8208190268

9 Reportable occurrences, LERs & related correspondence

8212020107 Seventh interim deficiency rept re old grease pumped on motor winding of reactor bldg cooling fans Initially reported on 810128 Tubing removed & grease relief holes plugged Next rept by 830223 Also reportable per Part 21 MILLS, L M Tennessee Valley Authority 82/11/23 O'REILLY, J P Region 2, Office of Director 3pp 16272 029 24X
Fiche 50-438, 82/11/23, 8212020107

8212020139 Final deficiency rept re water in rock anchor tendon head protective grease cans Initially reported on 790523 Ground water will not prevent prestressing sys from performing intended functions Components tested for corrosion MILLS, L M Tennessee Valley Authority 82/11/23 O'REILLY, J P Region 2, Office of Director 3pp 16274 164 24X
Fiche 50-438, 82/11/23, 8212020139

8212020137 First interim deficiency rept re unqualified flux hose connections Initially reported on 821027 Package of all info re flux hose assembled for reanalysis Next rept expected by 830430 MILLS, L M Tennessee Valley Authority 82/11/24 O'REILLY, J P Region 2, Office of Director 2pp 16274 159 24X
Fiche 50-438, 82/11/24, 8212020137

8212020149 First interim deficiency rept re failure to analyze isometrics & load tables Initially reported on 821026 Analysis check errors subsequently identified Deficiency will be addressed when errors resolved Next rept by 830322 MILLS, L M Tennessee Valley Authority 82/11/24 O'REILLY, J P Region 2, Office of Director 2pp 16274 157 24X
Fiche 50-438, 82/11/24, 8212020149

8212020162 First interim deficiency rept re failure to review diagrams properly Initially reported on 821027 Review of revisions to functional control logic diagrams continuing Next rept will be submitted by 830722 MILLS, L M Tennessee Valley Authority 82/11/24 O'REILLY, J P Region 2, Office of Director 2pp 16274 174 24X
Fiche 50-438, 82/11/24, 8212020162

8212030001 First interim deficiency rept re easily bent heat collecting fins & corroding sprinkler heads in fire suppression sys Initially reported on 821026 Proposed disposition to replace Star Model QE sprinkler heads under review MILLS, L M Tennessee Valley Authority 82/11/29 O'REILLY, J P Region 2, Office of Director 2pp 16304 212 24X
Fiche 50-000, 82/11/29, 8212030001

8212030072 Fourth interim deficiency rept re chiller unit piping components nfg by Dunham-Bush improperly welded Initially reported on 820111 Next rept expected by 830620 Also reportable per Part 21 MILLS, L M Tennessee Valley Authority 82/11/29 O'REILLY, J P Region 2, Office of Director 2pp 16304 214 24X
Fiche 50-438, 82/11/29, 8212030072

8212030152 Second interim deficiency rept re design problems w/R&M steam generators Initially reported on 820830 Addition of external header investigated Next rept expected by 830131 Also reportable per Part 21 MILLS, L M Tennessee Valley Authority 82/11/29 O'REILLY, J P Region 2, Office of Director 2pp 16303 305 24X
Fiche 50-438, 82/11/29, 8212030152

8212090163 Final deficiency rept re steam pressure regulator malfunction Verification requirements Initially reported on 810519 DNBR requirements met No evidence found that deficiency exists. MILLS, L M Tennessee Valley Authority 82/12/03 O'REILLY, J P Region 2, Office of Director 2pp 16397 096 24X
Fiche 50-438, 82/12/03, 8212090163

8212100270 Fifth interim deficiency rept re lack of Div of Engineering design sys to ensure QA procedures issued before work begins Initially reported on 81020 Final rept will not be submitted until decision made on deferral of projects MILLS, L M Tennessee Valley Authority 82/12/06 O'REILLY, J P Region 2, Office of Director 1p 16377.136 24X
Fiche 50-000, 82/12/06, 8212100270

8212140047 Seventh interim deficiency rept re miscategorization of main feedwater & containment isolation valves Initially reported on 810106 Atwood & Morrill seismic & stress rept re swing check valves qualification approved Next rept by 830331 MILLS, L M Tennessee Valley Authority 82/12/06 O'REILLY, J P Region 2, Office of Director 2pp 16408 279 24X
Fiche 50-438, 82/12/06, 8212140047

8212140415 Final deficiency rept re conduit loading on annulus framing in reactor bldg Initially reported on 820802 No corrective action necessary Buby nonconformance determined not reportable per 10CFR50.55(e) MILLS, L M Tennessee Valley Authority 82/12/06 O'REILLY, J P Region 2, Office of Director 2pp 16403 318 24X
Fiche 50-438, 82/12/06, 8212140415

8212140371 Second interim deficiency rept re faulty I-T-E relays in auxiliary power distribution sys by Brown Dover Electric Initially reported on 820528 Vendor rept pending Next rept expected by 830924 Also reportable under Part 21 MILLS, L M Tennessee Valley Authority 82/12/07 O'REILLY, J P Region 2, Office of Director 2pp 16401 149 24X
Fiche 50-438, 82/12/07, 8212140371

8212150079 Revised final deficiency rept re pipe hanger documentation error Initially reported on 810128 Const informed by 810601 memo that final approval by div of engineering design manager must be received before installation of hangers MILLS, L M Tennessee Valley Authority 82/12/08 O'REILLY, J P Region 2, Office of Director 2pp 16431 019 24X
Fiche 50-438, 82/12/08, 8212150079

8212170157 Fourth interim deficiency rept re improper use of foam plastic installation on stainless steel pipe Initially reported on 820203 Instruction memo re insulation types & drawings revised Next rept expected by 830321 MILLS, L M Tennessee Valley Authority 82/12/10 O'REILLY, J P Region 2, Office of Director 2pp 16462 026 24X
Fiche 50-438, 82/12/10, 8212170157

8212170160 Second revised final deficiency rept re Johnson Machine Works welds on revolving platform trucks Initially reported on 811006 Also reportable per Part 21 New welding magnetic particle or dye penetrant tested & training initiated MILLS, L M Tennessee Valley Authority 82/12/10 O'REILLY, J P Region 2, Office of Director 3pp 16462 023 24X
Fiche 50-438, 82/12/10, 8212170160

8212200001 Third interim deficiency rept re generic deficiency in design review Initially reported on 811215 No addl info available until action team 821215 rept Next rept will be submitted by 830420 MILLS, L M Tennessee Valley Authority 82/12/13 O'REILLY, J P Region 2, Office of Director 1p 16473 362 24X
Fiche 50-000, 82/12/13, 8212200001

8212200017 Fifth interim deficiency rept re design review process interface coordination activity Initially reported on 810717 Corrective action to be based on action team rept to be issued approx 821215 Next rept expected by 830422 MILLS, L M Tennessee Valley Authority 82/12/13 O'REILLY, J P Region 2, Office of Director 2pp 16473 085 24X
Fiche 50-000, 82/12/13, 8212200017

8212210256 Fifth interim deficiency rept re potential stress corrosion cracking in RCS supports & restraints for bolt torques Initially reported on 810824 Util program to survey RCS metal properties continuing Also reported per Part 21 MILLS, L M Tennessee Valley Authority 82/12/13 O'REILLY, J P Region 2, Office of Director 2pp 16483 301 24X
Fiche 50-438, 82/12/13, 8212210256

8212210026 Fourth interim deficiency rept re potentially overstressed embedded plates Initially reported on 820412 Multiple supports attached to plates w/o design review of plate capacity Preliminary const spec issued Next rept by 830404 MILLS, L M Tennessee Valley Authority 82/12/14 O'REILLY, J P Region 2, Office of Director 2pp 16485 260 24X
Fiche 50-000, 82/12/14, 8212210026

8212210122 Fourth interim deficiency rept re omissions to auxiliary feedwater pump drawings Initially reported on 820225 Auxiliary feedwater pump vents, drains & turbine cooling water piping incorporated into drawings Next rept by 830409 MILLS, L M Tennessee Valley Authority 82/12/14 O'REILLY, J P Region 2, Office of Director 2pp 16485 128 24X
Fiche 50-438, 82/12/14, 8212210122

8212210364 Third interim deficiency rept re valves mfg by Target Rock Valve Co & YARWAY Corp not qualified as active components Initially reported on 820412 Qualifying documentation expected by 830201 Next rept expected by 830330 MILLS, L M Tennessee Valley Authority 82/12/14 O'REILLY, J P Region 2, Office of Director 2pp 16493 096 24X
Fiche 50-438, 82/12/14, 8212210364

8212210431 Fourth interim deficiency rept re resolution of unanticipated vibratory loading concerns Initially reported on 820120 Const activities for Yellow Creek & Hartsville deferred Next rept will be sent by 830322
MILLS, L. M. Tennessee Valley Authority 82/12/15 O'REILLY, J. P.
Region 2, Office of Director 2pp 16489 168 24X
Fiche 50-000, 82/12/15, 8212210431

8212280358 First interim deficiency rept re substitution of grouted anchors for wedge bolts w/o ensuring adequate shear load capacities Initially reported on 821117 TVA will evaluate deficiency Next rept will be submitted by 830328
MILLS, L. M. Tennessee Valley Authority 82/12/15 O'REILLY, J. P.
Region 2, Office of Director 3pp 16558 357 24X
Fiche 50-438, 82/12/15, 8212280358

8212300006 Final deficiency rept re allowable stresses for pipe support design Initially reported on 811207 Nonconformance not reportable per 10CFR50.55(e) because condition not nonconforming or adverse to safe operation
MILLS, L. M. Tennessee Valley Authority 82/12/16 O'REILLY, J. P.
Region 2, Office of Director 8pp 16598 136 24X
Fiche 50-438, 82/12/16, 8212300006

8212220419 First interim deficiency rept re improper use of alternate analysis elbows Initially reported on 821118 Piping w/elbows qualified by alternate criteria identified & evaluated Next rept due by 830323
MILLS, L. M. Tennessee Valley Authority 82/12/17 O'REILLY, J. P.
Region 2, Office of Director 2pp 16503 272 24X
Fiche 50-438, 82/12/17, 8212220419

8212280064 Second interim deficiency rept re shielded power cable bend radius Initially reported on 820806 Cable samples will be tested for worst case bend installation Next rept will be submitted by 830722
MILLS, L. M. Tennessee Valley Authority 82/12/20 O'REILLY, J. P.
Region 2, Office of Director 2pp 16565 137 24X
Fiche 50-438, 82/12/20, 8212280064

8212280305 Final Deficiency Repts 50-438/82-58 & 50-439/82-52 re nonconforming reactor bldg door weld by Johnson Machine Works Initially reported on 820816 Reactor bldg equipment hatch doors to be reworked Also reported per Part 21
MILLS, L. M. Tennessee Valley Authority 82/12/20 O'REILLY, J. P.
Region 2, Office of Director 3pp 16562 055 24X
Fiche 50-438, 82/12/20, 8212280305

8212280328 Third interim deficiency rept re B&W design of RCS supports & restraints Initially reported on 820618 B&W recommended disposition reviewed & comments returned for evaluation Next rept will be submitted by 830620
MILLS, L. M. Tennessee Valley Authority 82/12/20 O'REILLY, J. P.
Region 2, Office of Director 2pp 16561 062 24X
Fiche 50-438, 82/12/20, 8212280328

8212280100 Fourth interim deficiency rept re small globe valves in auxiliary feedwater sys exceeding weight & length limitations Initially reported on 820222 Valves replaced on Unit 1 Unit 2 drawings revised Next rept due by 830415
MILLS, L. M. Tennessee Valley Authority 82/12/21 O'REILLY, J. P.
Region 2, Office of Director 2pp 16564 219 24X
Fiche 50-438, 82/12/21, 8212280100

8212280210 Supplemental deficiency rept re OE relays initially reported on 810513 Addl relay coils needed for replacement in intake pumping station Completion expected by 830430 Also reportable under Part 21
MILLS, L. M. Tennessee Valley Authority 82/12/21 O'REILLY, J. P.
Region 2, Office of Director 1p 16562 286 24X
Fiche 50-438, 82/12/21, 8212280210

8212280340 Second interim deficiency rept re steam generator support bolts mfg by Lakeside Bridge & Steel Initially reported on 820723 Applicant awaiting results of bolt testing & evaluation Next rept will be submitted by 830331
MILLS, L. M. Tennessee Valley Authority 82/12/21 O'REILLY, J. P.
Region 2, Office of Director 2pp 16560 097 24X
Fiche 50-438, 82/12/21, 8212280340

DOCKET 50-440 FERRY NUCLEAR POWER PLANT, UNIT 1

A Application/construction stage documents & correspondence

8212290031 FOIA request for five categories of documents
HIATT, S. L. Ohio Citizens for Responsible Energy 82/11/04
FELTON, J. M. Division of Rules and Records 1p 16607 132 24X
Fiche 50-440, 82/11/04, 8212290031

8212060484 Forwards "Human Factors Engineering Control Room In-Progress Audit" Requests schedule for NRC final control room design audit, including close-out of TMI Action Plan Item I D 1 & I I K 3 27 prior to licensing
SCHWENCER, A. Licensing Branch 2 82/11/12 DAVIDSON, D. R.
Cleveland Electric Illuminating Co 2pp 16343 248 24X
Fiche 50-440, 82/11/12, 8212060484

--821110457 "Audit Rept Human Factors Engineering Control Room In Progress Audit"
MOORE, J. W. Lawrence Livermore Laboratory 82/10/26 51pp
16343 250 24X Fiche 50-440, 82/11/12, 8212060484

8212300066 Generic Ltr 82-27 to all BWR licensees of operating reactors except LACBWR, Big Rock Point, Dresden 1, Humboldt Bay, applicants for OL & holders of CP re transmittal of NUREG-0763 & NUREG-0783 Svc 1st encl W/o stated encl EISENHUT, D. G. Division of Licensing 82/11/15 General Public Utilities - OPU Service Corp 22pp 16387 004 24X
Fiche 50-000, 82/11/15, 8212300066

8212070451 Ack receipt of 821116 memo to A Schwencer clarifying procedure for controlling document transmittals Superseded transmittals will be returned as requested Future transmittals should be addressed to BJ Youngblood
STEFANO, J. J. Licensing Branch 1 82/11/29 KINKADE, J. Cleveland Electric Illuminating Co 1p 16355 324 24X Fiche 50-440, 82/11/29, 8212070451

8212070466 Forwards requests for addl info to be furnished prior to site audit for seismic & dynamic equipment qualification reviews Scheduled time period for audit also requested
YOUNGBLOOD, B. J. Licensing Branch 1 82/11/30 DAVIDSON, D. R.
Cleveland Electric Illuminating Co 28pp 16354 244 24X
Fiche 50-440, 82/11/30, 8212070466

8212080021 Memorializes 821124 telcon w/util & Gilbert Associates re safety relief valve hydrodynamic loads test
STEFANO, J. J. Licensing Branch 1 82/11/30 YOUNGBLOOD, B. J.
Licensing Branch 1 2pp 16367 167 24X Fiche 50-440, 82/11/30, 8212080021

8212080115 Summary of 821122 meeting w/util, Gilbert Associates & Nuclear Technology in Bethesda, MD re util proposal for not performing safety relief valve hydrodynamic load discharge tests
STEFANO, J. J. Licensing Branch 1 82/11/30 YOUNGBLOOD, B. J.
Licensing Branch 1 4pp 16368 291 24X Fiche 50-440, 82/11/30, 8212080115

8212070237 Amplifies justifications provided in 820721 application for amend of CFP-148 & CFP-149 to extend const completion dates Reduced demand, increased regulations & high interest rates delayed need for capacity supplied by facilities
EDELHMAN, M. R. Cleveland Electric Illuminating Co 82/12/01
YOUNGBLOOD, B. J. Licensing Branch 1 2pp 16329 311 24X
Fiche 50-440, 82/12/01, 8212070237

8212290036 Responds to FOIA request for five categories of documents Forwards documents listed in App A Review of documents re Item 1 continuing
FELTON, J. M. Division of Rules and Records 82/12/02 HIATT, S. L.
Ohio Citizens for Responsible Energy 2pp 16607 133 24X
Fiche 50-440, 82/12/02, 8212290036

8212230385 Discusses JJ Stefano 821130 meeting rept summarizing discussions re need to conduct safety relief valve hydrodynamic load tests Potential thermal gradient stresses of concern Questions encl for response formulating concern
YOUNGBLOOD, B. J. Licensing Branch 1 82/12/14 EDELHMAN, M. R.
Cleveland Electric Illuminating Co 3pp 16540 242 24X
Fiche 50-440, 82/12/14, 8212230385

8212300077 Notification of 830111-13 meetings w/util in Lake County, OH to assess status of const & completion schedules
STEFANO, J. J. Licensing Branch 1 82/12/15 YOUNGBLOOD, B. J.
Licensing Branch 1 3pp 16624 275 24X Fiche 50-440, 82/12/15, 8212300077

8212280255 Responds to NRC 821019 Questions 260 10-260 13 requesting addl info & clarification of Table 3 2 1 in FSAR Amend B & 9 re GA
EDELHMAN, M. R. Cleveland Electric Illuminating Co 82/12/21
YOUNGBLOOD, B. J. Licensing Branch 1 7pp 16561 297 24X
Fiche 50-440, 82/12/21, 8212280255

D NRC Draft/Final Environmental Statements, suppl & correspondence

8212210435 Advises that EIS & EIA reviewed by all interested state agencies No concerns stated
BRACHMAN, J. Y. Ohio, State of 82/10/27 SCHWENCER, A. Licensing Branch 2 1p 16489 177 24X Fiche 50-440, 82/10/27, 8212210435

DOCKETED ITEMS

E NRC Safety Evaluation Report (SER), supp's & correspondence

8212010377 Summarizes findings on SER Outstanding Issues 15 & 16 re fire protection & Confirmatory Issue 36 re documentation or test of 3-h fire resistance of gypsum board walls
SCHWENGER, A Licensing Branch 2 82/11/26 DAVIDSON, D R Cleveland Electric Illuminating Co 3pp 16271 094 24X Fiche 50-440, 82/11/26, 8212010377

8212070460 Requests that util formally endorse DWR owners group proposal to modify automatic depressurization sys initiation to allow NRC to complete generic review of TMI item
II K 3 18 Info needed to resolve SER Confirmatory Issue 7
YOUNGBLOOD, B J Licensing Branch 1 82/11/30 DAVIDSON, D R Cleveland Electric Illuminating Co 2pp 16355 319 24X Fiche 50-440, 82/11/30, 8212070460

8212070397 Responds to SER Outstanding Issue 10 re continuous containment purge & Confirmatory Issue 20 re subcompartment pressure analysis FSAR will be revised w/ resolution of issues
EDELMAN, M R Cleveland Electric Illuminating Co 82/12/02 YOUNGBLOOD, B J Licensing Branch 1 5pp 16336 328 24X Fiche 50-440, 82/12/02, 8212070397

8212270002 Notification of 821214 meeting w/ applicants & QA Intl in Bethesda, MD to discuss unresolved containment issues cited in SER (NUREG-0887)
STEFANO, J J Licensing Branch 1 82/12/09 YOUNGBLOOD, B J Licensing Branch 1 3pp 16551 287 24X Fiche 50-440, 82/12/09, 8212270002

8212290189 Responds to SER Confirmatory Issue 44 re radiation & shielding design of inclined fuel transfer sys tubes Info in Amend 10 to FSAR should resolve issue
EDELMAN, M R Cleveland Electric Illuminating Co 82/12/21 YOUNGBLOOD, B J Licensing Branch 1 1p 16578 195 24X Fiche 50-440, 82/12/21, 8212290189

8212290305 Forwards response to NRC 820708 ltr. Question 640 2, re SER Outstanding Issue 21, Section 13 5 2 2 on reanalysis of transients & accidents & development of emergency operating procedures Submittal supp's 821116 response
EDELMAN, M R Cleveland Electric Illuminating Co 82/12/21 YOUNGBLOOD, B J Licensing Branch 1 2pp 16588 016 24X Fiche 50-440, 82/12/21, 8212290305

8212290325 Forwards response to SER Confirmatory Issues 41 & 42 re design for noble gas effluent monitors & design for sampling & analysis of plant effluents, per NUREG-0737, Items II F 1 & II F 1 2, respectively
EDELMAN, M R Cleveland Electric Illuminating Co 82/12/21 YOUNGBLOOD, B J Licensing Branch 1 4pp 16589 158 24X Fiche 50-440, 82/12/21, 8212290325

8212290481 Forwards final draft of SER Suppl 2 for release approval Suppl to be issued by 830103 Written approval should be provided by 821229 to meet issue date Urges suppl be reviewed to ensure evaluation inputs not altered w/o encl
NOVAK, T M Assistant Director for Licensing 82/12/21 JOHNSTON, W V Assistant Director for Materials & Qualifications Engineering KNIGHT, J P Assistant Director for Components & Structures Engineering HOUSTON, R W Assistant Director for Radiation Protection 2pp 16593 344 24X Fiche 50-440, 82/12/21, 8212290481

F Security, medical, emergency & fire protection plans

8212010377 Summarizes findings on SER Outstanding Issues 15 & 16 re fire protection & Confirmatory Issue 36 re documentation or test of 3-h fire resistance of gypsum board walls
SCHWENGER, A Licensing Branch 2 82/11/26 DAVIDSON, D R Cleveland Electric Illuminating Co 3pp 16271 094 24X Fiche 50-440, 82/11/26, 8212010377

8212220306 Discusses layout of communications equipment required in control room on-site technical support ctr & near-site emergency operations facility
KEPPLER, J O Region 3, Office of Director 82/12/16 Commonwealth Edison Co 3pp 16503 351 24X Fiche 50-000, 82/12/16, 8212220306

G Adjudicatory correspondence

8212010208 Memorializes 821123 telcon w/ ASLB, OH Citizens for Responsible Energy, Sunflower Alliance, NRC & util re discovery & scheduling matters Svc list encl Related correspondence
SILBERG, J E Shaw, Pittman, Potts & Trowbridge SILBERG, J E Cleveland Electric Illuminating Co 82/11/29 BLOCH, P B, KLINE, J R, SHON, F J Atomic Safety and Licensing Board Panel 4pp 16258 003 24X Fiche 50-440, 82/11/29, 8212010208

8212010212 Updated response to OH Citizens for Responsible Energy
820928 Interrogatory 4-2 Svc list encl Related correspondence
SILBERG, J E Cleveland Electric Illuminating Co SILBERG, J E Shaw, Pittman, Potts & Trowbridge 82/11/29 Ohio Citizens for Responsible Energy 2pp 16258 007 24X Fiche 50-440, 82/11/29, 8212010212

8212060108 Resubmission of sixth set of interrogatories & motion requesting presiding officer to require NRC answers Certificate of Svc encl Related correspondence
HIATT, S L Ohio Citizens for Responsible Energy 82/11/30 Office of the Executive Legal Director 7pp 16314 022 24X Fiche 50-440, 82/11/30, 8212060108

8212030181 Motion for deadline for particularization of Issue 9 by OH Citizens for Responsible Energy & for filing motions for summary disposition of Issue 9 ASLB 820712 memorandum & order failed to establish date Certificate of Svc encl
CUTCHIN, J M Hearing Branch 4 82/12/01 Atomic Safety and Licensing Board Panel 4pp 16303 224 24X Fiche 50-440, 82/12/01, 8212030181

8212080264 Requests to make limited appearance statement at DL hearings
SCHAEFER, K Affiliation Unknown 82/12/01 NRC - No Detailed Affiliation Given 1p 16354 110 24X Fiche 50-440, 82/12/01, 8212080264

8212090495 Brief opposing NRC motion for summary disposition of Issue 3 re inadequate QA program Serious problems still exist Proof of Svc encl Related correspondence
WILT, D D Cleveland Electric Illuminating Co WILT, D D Sunflower Alliance 82/12/02 Atomic Safety and Licensing Board Panel 50pp 16363 288 24X Fiche 50-440, 82/12/02, 8212090495

8212070196 Response in opposition to applicant 821118 motion for directed certification of ASLB 821029 memorandum & order re late-filed Contentions 21-26 Applicant second attempt as deficient as first Certificate of Svc encl
HIATT, S L Ohio Citizens for Responsible Energy 82/12/03 Atomic Safety and Licensing Appeal Panel 10pp 16335 001 24X Fiche 50-440, 82/12/03, 8212070196

8212070199 Response in support of NRC 821109 motion for summary disposition of Issue 5 Discovery on issue incomplete Request for site tour withdrawn Certificate of Svc encl Related correspondence
HIATT, S L Ohio Citizens for Responsible Energy 82/12/03 Atomic Safety and Licensing Board Panel 2pp 16334 352 24X Fiche 50-440, 82/12/03, 8212070199

8212070203 Response in opposition to NRC 821112 motion for summary disposition of Issue 7 NRC has not met burden of proof Certificate of Svc encl Related correspondence
HIATT, S L Ohio Citizens for Responsible Energy 82/12/03 Atomic Safety and Licensing Board Panel 7pp 16334 341 24X Fiche 50-440, 82/12/03, 8212070203

8212070358 Answer supporting NRC 821029 motion for summary disposition of Issue 3 Applicant mgt reacted properly to NRC Feb 1978 findings Applicant overall QA program has not been called into question since Feb 1978 Related correspondence
SILBERG, J E Cleveland Electric Illuminating Co SILBERG, J E Shaw, Pittman, Potts & Trowbridge 82/12/03 Atomic Safety and Licensing Board Panel 8pp 16337 143 24X Fiche 50-440, 82/12/03, 8212070358

--8212070365 Affidavit of MR Edelman & RL Farrell supporting NRC 821029 motion for summary disposition of Issue 3 re inadequate QA program Const completed by Feb 1978 acceptable & QA program effective, Certificate of Svc encl
EDELMAN, M R, FARRELL, R L Cleveland Electric Illuminating Co 82/11/30 65pp 16337 151 24X Fiche 50-440, 82/12/03, 8212070365

8212100120 Requests to make limited appearance statement at DL hearings
LIEBERMAN, A. Affiliation Unknown 82/12/03 Commissioners 1p 16376 014 24X Fiche 50-440, 82/12/03, 8212100120

8212130241 Answer supporting NRC 821109 motion for summary disposition of Issue 5 Break in piping of steam discharge vol would not cause unrecoverable LOCA Related correspondence
SILBERG, J Cleveland Electric Illuminating Co SILBERG, J Shaw, Pittman, Potts & Trowbridge 82/12/03 Atomic Safety and Licensing Board Panel 2pp 16396 199 24X Fiche 50-440, 82/12/03, 8212130241

DOCKETED ITEMS

30

- B212130246 Affidavit of MA Ross supporting NRC B21109 motion for summary disposition of Issue 5 Postulated scram discharge vol piping rupture does not present threat to long-term core cooling capability Certificate of Svc encl
ROSS, M A Cleveland Electric Illuminating Co ROSS, M A General Electric Co 82/12/01 15pp 16396 201 24X Fiche 50-440, 82/12/03, 8212130241
- B212070155 Motion for reconsideration of ASLB B20303 Memorandum & Order LBP-B2-15, admitting Issue 8 Issue inadmissible ab initio & not particularized as ASLB required Certification of Svc encl
CUTCHIN, J M Hearing Branch 4 82/12/06 Atomic Safety and Licensing Board Panel 9pp 16326 229 24X Fiche 50-440, 82/12/06, 8212070155
- B212080293 Forwards MA Ross signed original affidavit supporting NRC motion for summary disposition of Issue 5
SILBERG, J E Shaw, Pittman, Potts & Trowbridge SILBERG, J E Cleveland Electric Illuminating Co 82/12/06 Docketing & Services Branch 2pp 16354 225 24X Fiche 50-440, 82/12/06, 8212080293
- B212080301 Affidavit of MA Ross supporting NRC B21109 motion for summary disposition of Issue 5 Postulated scram discharge vol rupture does not present threat to long-term core cooling capability postulated in NUREG-0785
ROSS, M A NRC - No Detailed Affiliation Given ROSS, M A General Electric Co 82/12/01 13pp 16354 227 24X Fiche 50-440, 82/12/06, 8212080293
- B212090196 Answer supporting NRC B21112 motion for summary disposition of Issue 7 Util provided for early warning of asiatic clam establishment in area Plant monitoring sys will detect any clam infestation
SILBERG, J E Cleveland Electric Illuminating Co 82/12/07 Atomic Safety and Licensing Board Panel 4pp 16363 004 24X Fiche 50-440, 82/12/07, 8212090196
- B212090201 Affidavit of RS Nugent supporting NRC B21112 motion for summary disposition of Issue 7 Likelihood of asiatic clams establishing in Lake Erie is low but util will monitor for clams Prof qualifications encl
NUGENT, R S Cleveland Electric Illuminating Co NUGENT, R S NUS Corp 82/12/03 12pp 16363 008 24X Fiche 50-440, 82/12/07, 8212090196
- B212090206 Affidavit of RA Pender & RL Scherman supporting NRC B21112 motion for summary disposition of Issue 7 Util committed to plant monitoring program to detect asiatic clams Prof qualifications & Certificate of Svc encl
PENDER, R A , SCHERMAN, R L Cleveland Electric Illuminating Co 82/12/03 17pp 16363 020 24X Fiche 50-440, 82/12/07, 8212090196
- B212130218 Requests to make limited appearance statement at OL hearings
JONES, R Affiliation Unknown 82/12/07 Atomic Safety and Licensing Board Panel 1p 16390 117 24X Fiche 50-440, 82/12/07, 8212130218
- B212090228 Response supporting util B21118 motion for directed certification of portion of ASLB B21029 memorandum & order admitting three late-filed contentions ASLB improperly found good cause for admitting issues Certificate of Svc encl
CUTCHIN, J M Hearing Branch 4 WOODHEAD, C P Hearing Branch 1 82/12/08 Atomic Safety and Licensing Appeal Panel 13pp 16361 308 24X Fiche 50-440, 82/12/08, 8212090228
- B212100108 Memorandum & order denying Sunflower Alliance B21110 motion for order requiring NRC to answer third set of interrogatories Sunflower failed to demonstrate relevance of unanswered discovery requests to admitted contention
BLOCH, P B , KLINE, J R , SHON, F J Atomic Safety and Licensing Board Panel 82/12/08 Sunflower Alliance 3pp 16373 350 24X Fiche 50-440, 82/12/08, 8212100108
- B212130249 Memorandum listing interpretations of OH Citizens for Responsible Energy interrogatories on Issue B, stated by ASLB during B21209 telcon
BLOCH, P B Atomic Safety and Licensing Board Panel 82/12/10 1p 16389:314 24X Fiche 50-440, 82/12/10, 8212130249
- B212140445 Forwards RA Pender & RL Scherman original affidavit supporting NRC motion for summary disposition of Issue 7 Svc list encl
SILBERG, J E Shaw, Pittman, Potts & Trowbridge SILBERG, J E Cleveland Electric Illuminating Co 82/12/10 Docketing & Services Branch 2pp 16405 011 24X Fiche 50-440, 82/12/10, 8212140445
- B212140465 Requests to make limited appearance statement at OL hearings
BARTH, K P Affiliation Unknown 82/12/10 Docketing & Services Branch 1p 16404 349 24X Fiche 50-440, 82/12/10, 8212140465
- B212150041 Memorandum & order denying NRC B21206 motion for reconsideration of admission of Issue 8 re hydrogen control NRC motion untimely & is dismissed on merits
BLOCH, P B , KLINE, J R , SHON, F J Atomic Safety and Licensing Board Panel 82/12/13 Office of the Executive Legal Director 3pp 16421 248 24X Fiche 50-440, 82/12/13, 8212150041
- B212150118 Forwards notes from B21209 telcon involving ASLB applicants, NRC, Sunflower Alliance & OH Citizens for Responsible Energy re three pending motions
CUTCHIN, J M Hearing Branch 4 82/12/13 BLOCH, P B , SHON, F J , KLINE, J R Atomic Safety and Licensing Board Panel 5pp 16425 244 24X Fiche 50-440, 82/12/13, 8212150118
- B212160247 Answers to eighth set of interrogatories Certificate of Svc encl
SILBERG, J E Cleveland Electric Illuminating Co SILBERG, J E Shaw, Pittman, Potts & Trowbridge 82/12/13 Ohio Citizens for Responsible Energy 8pp 16446 195 24X Fiche 50-440, 82/12/13, 8212160247
- B212160251 Answers to second set of interrogatories, Numbers 20, 28 & 31 Certificate of Svc encl
SILBERG, J E Cleveland Electric Illuminating Co SILBERG, J E Shaw, Pittman, Potts & Trowbridge 82/12/13 Sunflower Alliance 9pp 16446 154 24X Fiche 50-440, 82/12/13, 8212160251
- B212200105 Notice of appearance in proceeding Certificate of Svc encl
SWIGER, M A Cleveland Electric Illuminating Co SWIGER, M A Shaw, Pittman, Potts & Trowbridge 82/12/14 3pp 16470 091 24X Fiche 50-440, 82/12/14, 8212200105
- B212230267 Informs of withdrawal of Interrogatories b - 6 of sixth set of interrogatories Info provided via FOIA procedures Related correspondence
HIATT, S L Ohio Citizens for Responsible Energy 82/12/14 BLOCH, P B Atomic Safety and Licensing Board Panel 1p 16507 352 24X Fiche 50-440, 82/12/14, 8212230267
- B212230319 Eighth discovery progress rept Certificate of Svc encl Related correspondence
HIATT, S L Ohio Citizens for Responsible Energy 82/12/14 3pp 16507 028 24X Fiche 50-440, 82/12/14, 8212230319
- B212230345 Motion in opposition to NRC B21105 motion for summary disposition of Issue 4 Genuine issues of matl fact still to be heard Certificate of Svc encl Related correspondence
HIATT, S L Ohio Citizens for Responsible Energy 82/12/14 Atomic Safety and Licensing Board Panel 9pp 16505 176 24X Fiche 50-440, 82/12/14, 8212230345
- B212230368 Response to NRC B21122 motion for summary disposition of Issue 12 FES should be amended to reflect existence of NUREG/CR-2591 Certificate of Svc encl Related correspondence
HIATT, S L Ohio Citizens for Responsible Energy 82/12/14 Atomic Safety and Licensing Board Panel 3pp 16511 204 24X Fiche 50-440, 82/12/14, 8212230368
- B212200061 Answer supporting NRC B21105 motion for summary disposition of Issue 4 Thirty-degree sector steam test not specifically required by App K GE performed test for simulated BWR/6 core Distribution of core spray flow not safety issue
SILBERG, J E Cleveland Electric Illuminating Co SILBERG, J E Shaw, Pittman, Potts & Trowbridge 82/12/15 Atomic Safety and Licensing Board Panel 3pp 16473 315 24X Fiche 50-440, 82/12/15, 8212200061
- B212200072 Affidavit of WA Sutherland supporting NRC B21105 motion for summary disposition of Issue 4 App K does not require full-scale 30-degree sector steam test Certificate of Svc encl
SUTHERLAND, W A Cleveland Electric Illuminating Co SUTHERLAND, W A General Electric Co 82/12/15 24pp 16473 310 24X Fiche 50-440, 82/12/15, 8212200061
- B212200093 Memorandum & Order ALAB-706, denying applicant B21027 motion for directed certification of LBP-B2-9B, admitting OH Citizens for Responsible Energy three late-filed contentions ASLB intercession not yet warranted
TOMPKINS, B A Atomic Safety and Licensing Appeal Panel 82/12/15 Cleveland Electric Illuminating Co 8pp 16474 292 24X Fiche 50-440, 82/12/15, 8212200093
- B212220260 Requests to make limited appearance statement at OL hearings
LONG, B M Affiliation Unknown 82/12/15 Docketing & Services Branch 1p 16518 329 24X Fiche 50-440, 82/12/15, 8212220260

DOCKETED ITEMS

8212210321 Answer supporting NRC 821122 motion for summary disposition of Issues 11 & 12 Sunflower Alliance withdrew Issue 11 on 821110 No genuine issue of matl fact remains for Issue 12 Certificate of Svc encl
SILBERG, J E Cleveland Electric Illuminating Co 82/12/16
Shaw, Pittman, Potts & Trowbridge 82/12/16 Atomic Safety and Licensing Board Panel 5pp 16496 311 24X Fiche 50-440, 82/12/16, 8212210321

8212210345 Forwards signed original affidavits of KA Matheny & RA Stratman re applicant 821213 answers to interrogatories & WA Sutherland re support of NRC motion for summary disposition of Issue 4
SILBERG, J E Shaw, Pittman, Potts & Trowbridge 82/12/17
Cleveland Electric Illuminating Co 82/12/17 Docketing & Services Branch 3pp 16496 337 24X Fiche 50-440, 82/12/17, 8212210345

8212220339 Requests to make limited appearance statement at DL hearings
DAVIS, H M Affiliation Unknown 82/12/17 Docketing & Services Branch 1p 16517 151, 24X Fiche 50-440, 82/12/17, 8212220339

8212210318 Answer opposing OH Citizens for Responsible Energy 821130 motion for order requiring NRC to answer sixth set of interrogatories Certificate of Svc encl
CUTCHIN, J M Hearing Branch 4 82/12/20 Atomic Safety and Licensing Board Panel 37pp 16496-253 24X Fiche 50-440, 82/12/20, 8212210318

8212280319 Forwards SL Hiatt affidavit supporting Sunflower Alliance opposition to NRC motion for summary disposition of Issue 3
WILT, D D Wilt, D D WILT, D D Sunflower Alliance 82/12/20
BLOCH, P B, SHON, F J, KLINE, J R Atomic Safety and Licensing Board Panel 1p 16556 146 24X Fiche 50-440, 82/12/20, 8212280319

--8212280324 Affidavit of SL Hiatt re exam of facility quarterly QA assessments & trend analysis repts
HIATT, S L Ohio Citizens for Responsible Energy 82/12/14 11pp 16556 147 24X Fiche 50-440, 82/12/20, 8212280319

8212230339 Suppls applicant response to Sunflower Alliance Interrogatory 2 re standby liquid control sys initiation Svc list encl Related correspondence
GLASSPIGEL, H Shaw, Pittman, Potts & Trowbridge 82/12/21
HIATT, S L Ohio Citizens for Responsible Energy 3pp 16505 159 24X Fiche 50-440, 82/12/21, 8212230339

8212230351 Order granting NRC motions for summary disposition of QA, Corbucula & scram discharge vol contentions except for genuine issues of fact specified
BLOCH, P B KLINE, J R, SHON, F J Atomic Safety and Licensing Board Panel 82/12/22 Office of the Executive Legal Director 17pp 16517 133 24X Fiche 50-440, 82/12/22, 8212230351

8212300054 Requests to make limited appearance statement at DL hearing
WOODSIDE, P Affiliation Unknown 82/12/22 NRC - No Detailed Affiliation Given 1p 16598 190 24X Fiche 50-440, 82/12/22, 8212300054

8212280192 Notice of ASLB reconstitution PB Bloch, chairman & JR Kline & GD Bright, members.
COITER, B P Atomic Safety and Licensing Board Panel 82/12/23 2pp 16562 304 24X Fiche 50-440, 82/12/23, 8212280192

8212300018 Memorandum & order directing NRC to respond as listed to OH Citizens for Responsible Energy interrogatories on Issue 8 re hydrogen generation
BLOCH, P B, BRIGHT, G D Atomic Safety and Licensing Board Panel 82/12/23 Office of the Executive Legal Director 10pp 16598 208 24X Fiche 50-440, 82/12/23, 8212300018

8212300051 Requests to make limited appearance statement at DL hearing
FRITZ, E J Affiliation Unknown 82/12/24 Docketing & Services Branch 1p 16598 193 24X Fiche 50-440, 82/12/24, 8212300051

8212300013 Updates applicant 820924 response to Interrogatory 3-4 of OH Citizens for Responsible Energy 820830 third set of interrogatories Svc list encl Related correspondence
SWIGER, M A Shaw, Pittman, Potts & Trowbridge 82/12/27 HIATT, S L Ohio Citizens for Responsible Energy 3pp 16598-224 24X Fiche 50-440, 82/12/27, 8212300013

H General correspondence

8212070015 Submits mgt changes effective 821201 DR Davidson to become senior vice president & MR Edelman to become vice president, nuclear group & staff contact for correspondence
DAVIDSON, D R Cleveland Electric Illuminating Co 82/12/02
YOUNGBLOD, B J Licensing Branch 1p 16327 243 24X Fiche 50-440, 82/12/02, 8212070015

8212200051 Requests that USGS evaluate risk of catastrophic explosion of propane leak from underground storage wells into Morton Salt Mine FSAR & FE8 deny possibility of event
BIMBER, R M Affiliation Unknown 82/12/14 STEFANO, J J NRC - No Detailed Affiliation Given 2pp 16470 006 24X Fiche 50-440, 82/12/14, 8212200051

--8212200058 Trip rept of 730912 site safety visit re specific features associated w/proposed site
Atomic Energy Commission 73/12/13 Atomic Energy Commission 3pp 16470 008 24X Fiche 50-440, 82/12/14, 8212200051

K Utility Final Safety Analysis Report (FSAR) & amends

8212020098 Amend 10 to FSAR W/629 oversize drawings Aperture cards are available in PDR
Cleveland Electric Illuminating Co 82/11/29 420pp 16274 179 24X Fiche 50-440, 82/11/23, 8212020098

M Antitrust correspondence

8212150012 Requests NRC review of Cleveland Electric Illuminating Co 821119 filing w/FERC for increase in rates for firm power svc Also requests NRC consideration of petition to intervene in matter
PANDY, J Cleveland, OH 82/12/02 TOLSTON, A Antitrust & Economic Analysis Branch (Utility Finance) 37pp 16421 139 24X Fiche 50-000, 82/12/02, 8212150012

8212220075 Forwards NRC 790625 ltr to util transmitting 790625 order requiring util to file transmission svc tariff at FERC per 81108 telcon
VOGLER, B H Hearing Branch 2 82/12/09 DAVIS, P Arnold & Porter 1p 16516 094 24X Fiche 50-440, 82/12/09, 8212220075

Q Inspection reports, IE Bulletins & correspondence

8208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BHR Plants " Svc list encl
DEVOUNO, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240

8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000, 82/11/05, 8208190245

8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X Fiche 50-000, 82/11/18, 8208190251

8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Radiolocks " Svc list encl
DEVOUNO, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000, 82/11/26, 8208190256

8208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000, 82/11/30, 8208190257

8212080019 Forwards NRR input to SALP rept for Oct 1981-Sept 1982 Overall rating of Category I given for licensee performance
STEFANO, J J Licensing Branch 1 82/11/30 EISENHUT, D O Division of Licensing 2pp 16367 169 24X Fiche 50-440, 82/11/30, 8212080019

8208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl
DEVOUNO, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259

B208190261 IE Info Notice B2-48, "Failures of Agastat CR 0095 Relay
Sockets " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03
Consolidated Edison Co of New York, Inc 110pp 16462 064 24X
Fiche 50-000, 82/12/03, B208190261

B212290412 Forwards IE Insp Repts 50-440/B2-16 & 50-441/B2-15 on
B20801-1031 No noncompliance noted
KNDP, R C Division of Project & Resident Programs 82/12/15
EDELMAN, M R Cleveland Electric Illuminating Co 2pp 16384 311
24X Fiche 50-440, 82/12/15, B212290412

--B212290417 IE Insp Repts 50-440/B2-16 & 50-441/B2-15 on B20801-1031 No
noncompliance noted Major areas inspected containment dome
installation, shield bldg dome concrete placement, refueling
bridge rail concrete placement & general housekeeping
GILDER, M L, KONKLIN, J E Division of Project & Resident
Programs 82/12/14 4pp 16384 313 24X Fiche 50-440, 82/12/15,
B212290412

B208190267 IE Info Notice B2-49, "Correction for Sample Conditions for
Air & Gas Monitoring " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and
Enforcement 82/12/16 Consolidated Edison Co of New York, Inc
127pp 16628 191 24X Fiche 50-000, 82/12/16, B208190267

B208190268 IE Info Notice B2-50, "Mod of Solid State AC Undervoltage
Relays Type ITE-27 " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20
Consolidated Edison Co of New York, Inc 108pp 16628 293 24X
Fiche 50-000, 82/12/20, B208190268

S Reportable occurrences, LERs & related correspondence

B212020296 Interim deficiency rept re contact leads on HMA relays
supplied by GE initially reported on B20917 Deficiency not
reportable based on design function of relay C61A-K2 Rept
for Unit 2 HMA relays will be submitted by B31031
DAVIDSON, D R Cleveland Electric Illuminating Co 82/11/24
KEPPLER, J O Region 3, Office of Director 2pp 16277 357 24X
Fiche 50-440, 82/11/24, B212020296

B212020395 Revised B20315 final deficiency rept re cladding fissures
adjacent to weld seams in stainless steel suppression pools
Items 2 & 3 of proposed corrective action deleted Placement
of annulus concrete in pool region will reduce stress level
DAVIDSON, D R Cleveland Electric Illuminating Co 82/11/24
KEPPLER, J O Region 3, Office of Director 2pp 16278 298 24X
Fiche 50-440, 82/11/24, B212020395

B212170153 Supplemental final deficiency rept re biological concrete
shield walls Unit 1 repairs will not be completed until
B30501 due to changes in const scheduling Unit 2 repairs on
schedule
EDELMAN, M R Cleveland Electric Illuminating Co 82/12/10
KEPPLER, J O Region 3, Office of Director 1p 16450 225 24X
Fiche 50-440, 82/12/10, B212170153

B212170241 Revised final deficiency rept re defective Bettis Model T3
series actuation yokes on Henry Pratt Co valves Due to delay
in receipt of replacement parts & const scheduling, required
mods not yet completed
EDELMAN, M R Cleveland Electric Illuminating Co 82/12/10
KEPPLER, J O Region 3, Office of Director 1p 16459 336 24X
Fiche 50-440, 82/12/10, B212170241

B212210370 Final deficiency rept re dowel counterbore in link rod in
standby diesel engine initially reported on B01008 Link rod
inspected Deficiency determined not reportable per
10CFR50.55(e)
EDELMAN, M R Cleveland Electric Illuminating Co 82/12/10
KEPPLER, J O Region 3, Office of Director 1p 16493 360 24X
Fiche 50-440, 82/12/10, B212210370

B212280291 Final deficiency rept re potential defect in starting air
sys check valve mfg by Transamerica Delaval initially
reported on B11218 Check valve disc assembly will be
replaced by B30701
EDELMAN, M R Cleveland Electric Illuminating Co 82/12/15
KEPPLER, J O Region 3, Office of Director 2pp 16560 102 24X
Fiche 50-440, 82/12/15, B212280291

DOCKET 50-441 PERRY NUCLEAR POWER PLANT, UNIT 2

A Application/construction stage documents & correspondence

B212290031 FOIA request for five categories of documents
HIATT, B L Ohio Citizens for Responsible Energy 82/11/04
FELTON, J M Division of Rules and Records 1p 16607 132 24X
Fiche 50-440, 82/11/04, B212290031

B212060484 Forwards "Human Factors Engineering Control Room In-Progress
Audit " Requests schedule for NRC final control room design
audit, including close-out of TMI Action Plan Item I D 1 &
I I K 3 27 prior to licensing
SCHWENCER, A Licensing Branch 2 82/11/12 DAVIDSON, D R
Cleveland Electric Illuminating Co 2pp 16343 248 24X
Fiche 50-440, 82/11/12, B212060484

B212300066 Generic Ltr B2-27 to all BWR licensees of operating reactors
except LACBWR, Big Rock Point, Dresden 1, Humboldt Bay,
applicants for DL & holders of CP re transmittal of
NUREG-0763 & NUREG-0783 Svc list encl W/o stated encl
EISENHUT, D G, Division of Licensing 82/11/15 General Public
Utilities - OPU Service Corp 22pp 16387 004 24X
Fiche 50-000, 82/11/15, B212300066

B212070451 Ack receipt of B21116 memo to A Schwencer clarifying
procedure for controlling document transmittals Superseded
transmittals will be returned as requested Future
transmittals should be addressed to BJ Youngblood
STEFANO, J J Licensing Branch 1 82/11/29 KINKADE, J Cleveland
Electric Illuminating Co 1p 16355 324 24X Fiche 50-440,
82/11/29, B212070451

B212070466 Forwards requests for addl info to be furnished prior to
site audit for seismic & dynamic equipment qualification
reviews Scheduled time period for audit also requested
YOUNGBLOOD, B J Licensing Branch 1 82/11/30 DAVIDSON, D R
Cleveland Electric Illuminating Co 28pp 16354 244 24X
Fiche 50-440, 82/11/30, B212070466

B212080021 Memorializes B21124 telcon w/util & Gilbert Associates re
safety relief valve hydrodynamic loads test
STEFANO, J J Licensing Branch 1 82/11/30 YOUNGBLOOD, B J
Licensing Branch 1 2pp 16367 167 24X Fiche 50-440, 82/11/30,
B212080021

B212080115 Summary of B21122 meeting w/util, Gilbert Associates &
Nuclear Technology in Bethesda, MD re util proposal for not
performing safety relief valve hydrodynamic load discharge
tests
STEFANO, J J Licensing Branch 1 82/11/30 YOUNGBLOOD, B J
Licensing Branch 1 4pp 16368 291 24X Fiche 50-440, 82/11/30,
B212080115

B212070237 Amplifies justifications provided in B20721 application for
amend of CPPR-14B & CPPR-147 to extend const completion
dates Reduced demand, increased regulations & high interest
rates delayed need for capacity supplied by facilities
EDELMAN, M R Cleveland Electric Illuminating Co 82/12/01
YOUNGBLOOD, B J Licensing Branch 1 2pp 16329 311 24X
Fiche 50-440, 82/12/01, B212070237

B212290036 Responds to FOIA request for five categories of documents
forwards documents listed in App A Review of documents re
item 1 continuing
FELTON, J M Division of Rules and Records 82/12/02 HIATT, B L
Ohio Citizens for Responsible Energy 2pp 16607 133 24X
Fiche 50-440, 82/12/02, B212290036

B212230038 Discusses JJ Stefano B21130 meeting rept summarizing
discussions re need to conduct safety relief valve
hydrodynamic load tests Potential thermal gradient stresses
of concern Questions encl for response formulating concern
YOUNGBLOOD, B J Licensing Branch 1 82/12/14 EDELMAN, M R
Cleveland Electric Illuminating Co 3pp 16540 242 24X
Fiche 50-440, 82/12/14, B212230038

B212300077 Notification of B20111-13 meetings w/util in Lake County, OH
to assess status of const & completion schedules
STEFANO, J J Licensing Branch 1 82/12/15 YOUNGBLOOD, B J
Licensing Branch 1 5pp 16624 275 24X Fiche 50-440, 82/12/15,
B212300077

B212280255 Responds to NRC B21019 Questions 260 10-260 13 requesting
addl info & clarification of Table 3 2 1 in FBAR Amend
B & 9 re GA
EDELMAN, M R Cleveland Electric Illuminating Co 82/12/21
YOUNGBLOOD, B J Licensing Branch 1 7pp 16561 297 24X
Fiche 50-440, 82/12/21, B212280255

D NRC Draft/Final Environmental Statements, suppl's & correspondence

B212210435 Advises that EIS & EIA reviewed by all interested state
agencies No concerns stated
BRACHMAN, J Y Ohio, State of 82/10/27 SCHWENCER, A Licensing
Branch 2 1p 16489 177 24X Fiche 50-440, 82/10/27, B212210435

DOCKETED ITEMS

E NRC Safety Evaluation Report (SER), supply & correspondence

B212010377 Summarizes findings on SER Outstanding Issues 15 & 16 re fire protection & Confirmatory Issue 36 re documentation or test of 3-h fire resistance of gypsum board walls
SCHWENGER, A Licensing Branch 2 82/11/26 DAVIDSON, D R
Cleveland Electric Illuminating Co 3pp 16271 094 24X
Fiche 50-440, 82/11/26, 8212010377

B212070460 Requests that util formally endorse EWR owners group proposal to modify automatic depressurization sys initiation to allow NRC to complete generic review of TMI Item
II K 3 18 Info needed to resolve SER Confirmatory Issue 7
YOUNGBLOOD, B J Licensing Branch 1 82/11/30 DAVIDSON, D R
Cleveland Electric Illuminating Co 2pp 16355 319 24X
Fiche 50-440, 82/11/30, 8212070460

B212070397 Responds to SER Outstanding Issue 10 re continuous containment purge & Confirmatory Issue 20 re subcompartment pressure analysis FSAR will be revised w/ resolution of issues
EDELMAN, M R Cleveland Electric Illuminating Co 82/12/02
YOUNGBLOOD, B J Licensing Branch 1 5pp 16336 028 24X
Fiche 50-440, 82/12/02, 8212070397

B212270002 Notification of B21214 meeting w/ applicants & QA intl in Bethesda, MD to discuss unresolved containment issues cited in SER (NUREG-0887)
STEFANO, J J Licensing Branch 1 82/12/09 YOUNGBLOOD, B
Licensing Branch 1 3pp 16551 287 24X Fiche 50-440, 82/12/09, 8212270002

B212290189 Responds to SER Confirmatory Issue 44 re radiation & shielding design of inclined fuel transfer sys tubes Info in Amend 10 to FSAR should resolve issue
EDELMAN, M R Cleveland Electric Illuminating Co 82/12/21
YOUNGBLOOD, B J Licensing Branch 1 1p 16578 195 24X
Fiche 50-440, 82/12/21, 8212290189

B212290305 Forwards response to NRC B20908 ltr, Question 640 2 re SER Outstanding Issue 21, Section 13 5 2 2 on reanalysis of transients & accidents & development of emergency operating procedures Submittal suppl 821116 response
EDELMAN, M R Cleveland Electric Illuminating Co 82/12/21
YOUNGBLOOD, B J Licensing Branch 1 2pp 16588 016 24X
Fiche 50-440, 82/12/21, 8212290305

B212290325 Forwards response to SER Confirmatory Issues 41 & 42 re design for noble gas effluent monitors & design for sampling & analysis of plant effluents, per NUREG-0737, Items II F 1 1 & II F 1 2, respectively
EDELMAN, M R Cleveland Electric Illuminating Co 82/12/21
YOUNGBLOOD, B J Licensing Branch 1 4pp 16597 198 24X
Fiche 50-440, 82/12/21, 8212290325

B212290481 Forwards final draft of SER Suppl 2 for release approval
Suppl to be issued by B30103 Written approval should be provided by B21229 to meet issue date Urges suppl be reviewed to ensure evaluation inputs not altered w/o encl
JOHNSTON, W V Assistant Director for Licensing 82/12/21
KNIGHT, J P Assistant Director for Components & Structures Engineering
HOUSTON, R W Assistant Director for Radiation Protection 2pp 16593 344 24X Fiche 50-440, 82/12/21, 8212290481

F Security, medical, emergency & fire protection plans

B212010377 Summarizes findings on SER Outstanding Issues 15 & 16 re fire protection & Confirmatory Issue 36 re documentation or test of 3-h fire resistance of gypsum board walls
SCHWENGER, A Licensing Branch 2 82/11/26 DAVIDSON, D R
Cleveland Electric Illuminating Co 3pp 16271 094 24X
Fiche 50-440, 82/11/26, 8212010377

B212220306 Discusses layout of communications equipment required in control room, onsite technical support ctr & near-site emergency operations facility
KEPPLER, J O Region 3, Office of Director 82/12/16
Commonwealth Edison Co 3pp 16503 351 24X Fiche 50-000, 82/12/16, 8212220306

G Adjudicatory correspondence

B212010208 Memorializes B21123 telcon w/ ASLB, OH Citizens for Responsible Energy, Sunflower Alliance, NRC & util re discovery & scheduling matters Svc list encl Related correspondence
SILBERO, J E Shaw, Pittman, Potts & Trowbridge SILBERO, J E
Cleveland Electric Illuminating Co 82/11/29 BLOCH, P D,
KLINE, J R, SHON, F J Atomic Safety and Licensing Board Panel 4pp
16258 003 24X Fiche 50-440, 82/11/29, 8212010208

B212010212 Updated response to OH Citizens for Responsible Energy
B20928 Interrogatory 4-2 Svc list encl Related correspondence
SILBERO, J E Cleveland Electric Illuminating Co SILBERO, J E
Shaw, Pittman, Potts & Trowbridge 82/11/29 Ohio Citizens for
Responsible Energy 2pp 16258 007 24X Fiche 50-440, 82/11/29, 8212010212

B212060108 Resubmission of sixth set of interrogatories & motion requesting presiding officer to require NRC answers
Certificate of Svc encl Related correspondence
HIATT, S L Ohio Citizens for Responsible Energy 82/11/30
Office of the Executive Legal Director 9pp 16314 022 24X
Fiche 50-440, 82/11/30, 8212060108

B212030181 Motion for deadline for particularization of Issue 9 by OH Citizens for Responsible Energy & for filing motions for summary disposition of Issue 9 ASLB 820712 memorandum & order failed to establish date Certificate of Svc encl
CUTCHIN, J M Hearing Branch 4 82/12/01 Atomic Safety and
Licensing Board Panel 4pp 16303 224 24X Fiche 50-440, 82/12/01, 8212030181

B212080264 Requests to make limited appearance statement at OL hearings
SCHAEFER, K Affiliation Unknown 82/12/01 NRC - No Detailed
Affiliation Given 1p 16354 110 24X Fiche 50-440, 82/12/01, 8212080264

B212090495 Brief opposing NRC motion for summary disposition of Issue 3 re inadequate QA program Serious problems still exist
Proof of Svc encl Related correspondence
WILTR, D D Cleveland Electric Illuminating Co WILTR, D D Sunflower
Alliance 82/12/02 Atomic Safety and Licensing Board Panel
50pp 16363 288 24X Fiche 50-440, 82/12/02, 8212090495

B212070196 Response in opposition to applicant B21118 motion for directed certification of ASLB 821027 memorandum & order re late-filed Contentions 21-26 Applicant second attempt as deficient as first Certificate of Svc encl
HIATT, S L Ohio Citizens for Responsible Energy 82/12/03
Atomic Safety and Licensing Appeal Panel 10pp 16339 001 24X
Fiche 50-440, 82/12/03, 8212070196

B212070199 Response in support of NRC B21109 motion for summary disposition of Issue 5 Discovery on issue incomplete Request for site tour withdrawn Certificate of Svc encl Related correspondence
HIATT, S L Ohio Citizens for Responsible Energy 82/12/03
Atomic Safety and Licensing Board Panel 2pp 16334 352 24X
Fiche 50-440, 82/12/03, 8212070199

B212070203 Response in opposition to NRC B21112 motion for summary disposition of Issue 7 NRC has not met burden of proof
Certificate of Svc encl Related correspondence
HIATT, S L Ohio Citizens for Responsible Energy 82/12/03
Atomic Safety and Licensing Board Panel 9pp 16334 341 24X
Fiche 50-440, 82/12/03, 8212070203

B212070358 Answer supporting NRC B21029 motion for summary disposition of Issue 3 Applicant mgt reacted properly to NRC Feb 1978 findings Applicant overall QA program has not been called into question since Feb 1978 Related correspondence
SILBERO, J E Cleveland Electric Illuminating Co SILBERO, J E
Shaw, Pittman, Potts & Trowbridge 82/12/03, Atomic Safety and
Licensing Board Panel 8pp 16337 143 24X Fiche 50-440, 82/12/03, 8212070358

--B212070365 Affidavit of MR Edelman & RL Farrell supporting NRC B21029 motion for summary disposition of Issue 3 re inadequate QA program Const completed by Feb 1978 acceptable & QA program effective Certificate of Svc encl
EDELMAN, M R, FARRELL, R L Cleveland Electric Illuminating Co
82/11/30 45pp 16337 151 24X Fiche 50-440, 82/12/03, 8212070365

B212100120 Requests to make limited appearance statement at OL hearings
LIEBERMAN, A Affiliation Unknown 82/12/03 Commissioners 1p
16376 014 24X Fiche 50-440, 82/12/03, 8212100120

B212130241 Answer supporting NRC B21109 motion for summary disposition of Issue 5 Break in piping of scram discharge val would not cause unrecoverable LOCA Related correspondence
SILBERO, J Cleveland Electric Illuminating Co, SILBERO, J, Shaw,
Pittman, Potts & Trowbridge 82/12/03 Atomic Safety and
Licensing Board Panel 2pp 16396 199 24X Fiche 50-440, 82/12/03, 8212130241

--B212130246 Affidavit of MA Ross supporting NRC B21109 motion for summary disposition of Issue 5 Postulated scram discharge vol piping rupture does not present threat to long-term core cooling capability Certificate of Svc encl
ROSS, M A Cleveland Electric Illuminating Co ROSS, M A General Electric Co 82/12/01 13pp 16396 201 24X
Fiche 50-440, 82/12/03, B212130241

B212070155 Motion for reconsideration of ASLB B20303 Memorandum & Order LBP-B2-15, admitting Issue B issue inadmissible ab initio & not particularized as ASLB required Certification of Svc encl
CUTCHIN, J M Hearing Branch 4 82/12/06 Atomic Safety and Licensing Board Panel 9pp 16326 229 24X Fiche 50-440, 82/12/06, B212070155

B212080293 Forwards MA Ross signed original affidavit supporting NRC motion for summary disposition of Issue 5
SILBERG, J E Shaw, Pittman, Potts & Trowbridge SILBERG, J E Cleveland Electric Illuminating Co 82/12/06 Docketing & Services Branch 2pp 16354 225 24X Fiche 50-440, 82/12/06, B212080293

--B212080301 Affidavit of MA Ross supporting NRC B21109 motion for summary disposition of Issue 5 Postulated scram discharge vol rupture does not present threat to long-term core cooling capability postulated in NUREG-0785
ROSS, M A NRC - No Detailed Affiliation Given ROSS, M A General Electric Co 82/12/01 13pp 16354 227 24X
Fiche 50-440, 82/12/06, B212080293

B212090196 Answer supporting NRC B21112 motion for summary disposition of Issue 7 Util provided for early warning of asiatic clam establishment in area Plant monitoring sys will detect any clam infestation
SILBERG, J E Cleveland Electric Illuminating Co 82/12/07 Atomic Safety and Licensing Board Panel 4pp 16363 004 24X
Fiche 50-440, 82/12/07, B212090196

--B212090201 Affidavit of RS Nugent supporting NRC B21112 motion for summary disposition of Issue 7 Likelihood of asiatic clams establishing in Lake Erie is low but util will monitor for clams Prof qualifications encl
NUGENT, R S Cleveland Electric Illuminating Co NUGENT, R S NUB Corp 82/12/03 12pp 16363 008 24X Fiche 50-440, 82/12/07, B212090196

--B212090206 Affidavit of RA Pender & RL Scherman supporting NRC B21112 motion for summary disposition of Issue 7 Util committed to plant monitoring program to detect asiatic clams Prof qualifications & Certificate of Svc encl
PENDER, R A, SCHERMAN, R L Cleveland Electric Illuminating Co 82/12/03 17pp 16363 020 24X Fiche 50-440, 82/12/07, B212090196

B212130218 Requests to make limited appearance statement at OL hearings
JONES, R Affiliation Unknown 82/12/07 Atomic Safety and Licensing Board Panel 1p 16390 117 24X Fiche 50-440, 82/12/07, B212130218

B212090228 Response supporting util B21118 motion for directed certification of portion of ASLB B21029 memorandum & order admitting three late-filed contentions ASLB improperly found good cause for admitting issues Certificate of Svc encl
CUTCHIN, J M Hearing Branch 4 WOODHEAD, C P, Hearing Branch 1 82/12/08 Atomic Safety and Licensing Appeal Panel 13pp 16361 308 24X Fiche 50-440, 82/12/08, B212090228

B212100108 Memorandum & order denying Sunflower Alliance B21110 motion for order requiring NRC to answer third set of interrogatories Sunflower failed to demonstrate relevance of unanswered discovery requests to admitted contention
BLOCH, P B, KLINE, J R, SHON, F J Atomic Safety and Licensing Board Panel 82/12/08 Sunflower Alliance 3pp 16373 350 24X
Fiche 50-440, 82/12/08, B212100108

B212130249 Memorandum listing interpretations of OH Citizens for Responsible Energy interrogatories on Issue B, stated by ASLB during B21209 telcon
BLOCH, P B Atomic Safety and Licensing Board Panel 82/12/10 1p 16389 314 24X Fiche 50-440, 82/12/10, B212130249

B212140445 Forwards RA Pender & RL Scherman original affidavit supporting NRC motion for summary disposition of Issue 7 Svc list encl
SILBERG, J E Shaw, Pittman, Potts & Trowbridge SILBERG, J E Cleveland Electric Illuminating Co 82/12/10 Docketing & Services Branch 2pp 16408 011 24X Fiche 50-440, 82/12/10, B212140445

B212140445 Requests to make limited appearance statement at OL hearings
BARTH, K P, Affiliation Unknown 82/12/10 Docketing & Services Branch 1p 16404 349 24X Fiche 50-440, 82/12/10, B212140445

B212150041 Memorandum & order denying NRC B21206 motion for reconsideration of admission of Issue B re hydrogen control NRC motion untimely & is dismissed on merits
BLOCH, P B, KLINE, J R, SHON, F J Atomic Safety and Licensing Board Panel 82/12/13 Office of the Executive Legal Director 3pp 16421 248 24X Fiche 50-440, 82/12/13, B212150041

B212150118 Forwards notes from B21209 telcon involving ASLB applicants, NRC, Sunflower Alliance & OH Citizens for Responsible Energy re three pending motions
CUTCHIN, J M Hearing Branch 4 82/12/13 BLOCH, P B, SHON, F J, KLINE, J R Atomic Safety and Licensing Board Panel 9pp 16425 244 24X Fiche 50-440, 82/12/13, B212150118

B212160247 Answers to eighth set of interrogatories Certificate of Svc encl
SILBERG, J E Cleveland Electric Illuminating Co SILBERG, J E Shaw, Pittman, Potts & Trowbridge 82/12/13 Ohio Citizens for Responsible Energy 8pp 16446 195 24X Fiche 50-440, 82/12/13, B212160247

B212160251 Answers to second set of interrogatories, Numbers 20, 28 & 31 Certificate of Svc encl
SILBERG, J E Cleveland Electric Illuminating Co SILBERG, J E Shaw, Pittman, Potts & Trowbridge 82/12/13 Sunflower Alliance 9pp 16446 154 24X Fiche 50-440, 82/12/13, B212160251

B212200105 Notice of appearance in proceeding Certificate of Svc encl
SWIGER, M A Cleveland Electric Illuminating Co SWIGER, M A Shaw, Pittman, Potts & Trowbridge 82/12/14 3pp 16470 091 24X
Fiche 50-440, 82/12/14, B212200105

B212230267 Informs of withdrawal of Interrogatories & - B of sixth set of interrogatories Info provided via FOIA procedures
Related correspondence
HIATT, S L Ohio Citizens for Responsible Energy 82/12/14
BLOCH, P B Atomic Safety and Licensing Board Panel 1p 16507 352 24X Fiche 50-440, 82/12/14, B212230267

B212230319 Eighth discovery progress rept Certificate of Svc encl
Related correspondence
HIATT, S L Ohio Citizens for Responsible Energy 82/12/14 3pp 16507 028 24X Fiche 50-440, 82/12/14, B212230319

B212230345 Motion in opposition to NRC B21105 motion for summary disposition of Issue 4 Genuine issues of matl fact still to be heard Certificate of Svc encl Related correspondence
HIATT, S L Ohio Citizens for Responsible Energy 82/12/14 Atomic Safety and Licensing Board Panel 9pp 16505 176 24X
Fiche 50-440, 82/12/14, B212230345

B212230368 Response to NRC B21122 motion for summary disposition of Issue 12 FES should be amended to reflect existence of NUREG/CR-2591 Certificate of Svc encl Related correspondence
HIATT, S L Ohio Citizens for Responsible Energy 82/12/14 Atomic Safety and Licensing Board Panel 3pp 16511 204 24X
Fiche 50-440, 82/12/14, B212230368

B212200061 Answer supporting NRC B21105 motion for summary disposition of Issue 4 Thirty-degree sector steam test not specifically required by App K GE performed test for simulated DHR/4 core Distribution of core spray flow not safety issue
SILBERG, J E Cleveland Electric Illuminating Co SILBERG, J E Shaw, Pittman, Potts & Trowbridge 82/12/15 Atomic Safety and Licensing Board Panel 3pp 16473 315 24X Fiche 50-440, 82/12/15, B212200061

--B212200072 Affidavit of WA Sutherland supporting NRC B21105 motion for summary disposition of Issue 4 App K does not require full-scale 30-degree sector steam test Certificate of Svc encl
SUTHERLAND, W A Cleveland Electric Illuminating Co SUTHERLAND, W A General Electric Co 82/12/15 24pp 16473 310 24X Fiche 50-440, 82/12/15, B212200061

B212200093 Memorandum & Order ALAB-706, denying applicant B21029 motion for directed certification of LBP-B2-9B, admitting OH Citizens for Responsible Energy three late-filed contentions ASLB intercession not yet warranted
TOMPKINS, B A Atomic Safety and Licensing Appeal Panel 82/12/15 Cleveland Electric Illuminating Co 8pp 16474 292 24X
Fiche 50-440, 82/12/15, B212200093

B212220260 Requests to make limited appearance statement at OL hearings
LOMO, B M Affiliation Unknown 82/12/15 Docketing & Services Branch 1p 16518 329 24X Fiche 50-440, 82/12/15, B212220260

DOCKETED ITEMS

8212210321 Answer supporting NRC 821222 motion for summary disposition of Issues 11 & 12 Sunflower Alliance withdrew Issue 11 on 821110 No genuine issue of matl fact remains for Issue 12 Certificate of Svc encl
SILBERG, J E Cleveland Electric Illuminating Co 82/12/16 Atomic Safety and Licensing Board Panel 5pp 16496 311 24X Fiche 50-440, 82/12/16, 8212210321

8212210345 Forwards signed original affidavits of KA Matheny & KA Stratman re applicant 821213 answers to interrogatories & KA Sutherland re support of NRC motion for summary disposition of Issue 4
SILBERG, J E Shaw, Pittman, Potts & Trowbridge 82/12/17 Docketing & Services Branch 3pp 16496 337 24X Fiche 50-440, 82/12/17, 8212210345

8212220339 Requests to make limited appearance statement at OL hearings
DAVIS, H M Affiliation Unknown 82/12/17 Docketing & Services Branch 1p 16517 131 24X Fiche 50-440, 82/12/17, 8212220339

8212210318 Answer opposing OH Citizens for Responsible Energy 821130 motion for order requiring NRC to answer sixth set of interrogatories Certificate of Svc encl
CUTCHIN, J M Hearing Branch 4 82/12/20 Atomic Safety and Licensing Board Panel 37pp 16496 253 24X Fiche 50-440, 82/12/20, 8212210318

8212280319 Forwards SL Hyatt affidavit supporting Sunflower Alliance opposition to NRC motion for summary disposition of Issue 3
WILT, D D Wilt, D D WILT, D D Sunflower Alliance 82/12/20 BLOCH, P B, SHON, F J, KLINE, J R Atomic Safety and Licensing Board Panel 1p 16556 146 24X Fiche 50-440, 82/12/20, 8212280319

- 8212280324 Affidavit of SL Hyatt re exam of facility quarterly QA assessments & trend analysis repts
HYATT, S L Ohio Citizens for Responsible Energy 82/12/14 11pp 16556 147 24X Fiche 50-440, 82/12/20, 8212280319

8212230339 Suppl's applicant response to Sunflower Alliance Interrogatory 2 re standby liquid control sys initiation Svc list encl Related correspondence
GLASSPIEREL, H Shaw, Pittman, Potts & Trowbridge 82/12/21 HYATT, S L Ohio Citizens for Responsible Energy 3pp 16505 154 24X Fiche 50-440, 82/12/21, 8212230339

8212230351 Order granting NRC motions for summary disposition of GA, Corbicular & scam discharge vol contentions except for genuine issues of fact specified
BLOCH, P B, KLINE, J R, SHON, F J Atomic Safety and Licensing Board Panel 82/12/22 Office of the Executive Legal Director 17pp 16517 133 24X Fiche 50-440, 82/12/22, 8212230351

8212300054 Requests to make limited appearance statement at OL hearing
WOODSIDE, P Affiliation Unknown 82/12/22 NRC - No Detailed Affiliation Given 1p 16598 190 24X Fiche 50-440, 82/12/22, 8212300054

8212280192 Notice of ASLO reconstitution PD Bloch, chairman & JR Kline & CO Bright, members
COTTER, B P Atomic Safety and Licensing Board Panel 82/12/23 2pp 16562 304 24X Fiche 50-440, 82/12/23, 8212280192

8212300018 Memorandum & order directing NRC to respond as listed to OH Citizens for Responsible Energy Interrogatories on Issue 8 re hydrogen generation
BLOCH, P B, BRIGHT, O O Atomic Safety and Licensing Board Panel 82/12/23 Office of the Executive Legal Director 10pp 16598 208 24X Fiche 50-440, 82/12/23, 8212300018

8212300051 Requests to make limited appearance statement at OL hearing
FRITZ, E J Affiliation Unknown 82/12/24 Docketing & Services Branch 1p 16598 193 24X Fiche 50-440, 82/12/24, 8212300051

8212300013 Updates applicant 820924 response to Interrogatory 3-4 of OH Citizens for Responsible Energy 820830 third set of interrogatories Svc list encl Related correspondence
SWIGER, M A Shaw, Pittman, Potts & Trowbridge, SWIGER, M A Cleveland Electric Illuminating Co 82/12/27 HYATT, S L Ohio Citizens for Responsible Energy 3pp 16598 224 24X Fiche 50-440, 82/12/27, 8212300013

H General correspondence

8212070015 Submits mgt changes effective 821201 DR Davidson to become senior vice president & MR Edelman to become vice president, nuclear group & staff contact for correspondence
DAVIDSON, D R Cleveland Electric Illuminating Co 82/12/02 YOUNGBLOOD, B J Licensing Branch 1 1p 16327 243 24X Fiche 50-440, 82/12/02, 8212070015

8212200051 Requests that USOS evaluate risk of catastrophic explosion of propane leak from underground storage wells into Morton Salt Mine FSAR & FES deny possibility of event
HIMBER, R M Affiliation Unknown 82/12/14 STEFANO, J J NRI - No Detailed Affiliation Given 2pp 16470 006 24X Fiche 50-440, 82/12/14, 8212200051

- 8212200058 Trip rept of 730912 site safety visit re specific features associated w/proposed site
* Atomic Energy Commission 73/12/13 Atomic Energy Commission 3pp 16470 008 24X Fiche 50-440, 82/12/14, 8212200051

K Utility Final Safety Analysis Report (FSAR) & amends

8212020098 Amend 10 to FSAR W/629 oversize drawings Aperture cards are available in PDR
* Cleveland Electric Illuminating Co 82/11/29 420pp 162/4 177 24X Fiche 50-440, 82/11/23, 8212020091

N Antitrust correspondence

8212150012 Requests NRC review of Cleveland Electric Illuminating Co 821119 filing w/NERC for increase in rates for firm power svc Also requests NRC consideration of petition to intervene in matter
PANDY, J Cleveland, OH 82/12/02 TOALSTON, A Antitrust & Economic Analysis Branch (Utility Finance) 37pp 16421 139 24X Fiche 50-000, 82/12/02, 8212150012

8212220075 Forwards NRC 790625 ltr to util transmitting 790625 order requiring util to file transmission svc tariff at FERC, per 011208 telcon
VOGLER, B H Hearing Branch 2 82/12/09 DAVIS, P Arnold & Porter 1p 16516 094 24X Fiche 50-440, 82/12/09, 8212220075

O Inspection reports, IE Bulletins & correspondence

8208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Bys Piping at BWR Plants " Svc list encl
DEVOUNO, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240

8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000, 82/11/05, 8208190245

8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18, Consolidated Edison Co of New York, Inc 109pp 16411 199 24X Fiche 50-000, 82/11/18, 8208190251

8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list encl
DEVOUNO, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000, 82/11/26, 8208190256

8208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30, Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000, 82/11/30, 8208190257

8212080019 Forwards NRR input to BALP rept for Oct 1981-Sept 1982 Overall rating of Category I given for licensee performance.
STEFANO, J J Licensing Branch 1 82/11/30 EISENHUT, D O Division of Licensing 2pp 16367 169 24X Fiche 50-440, 82/11/30, 8212080019

8208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl
DEVOUNO, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259

DOCKETED ITEMS

30

B208190261 IE Info Notice B2-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03
Consolidated Edison Co of New York, Inc 110pp 16462 064 24X
Fiche 50-000, 82/12/03, B208190261

B212290412 Forwards IE Insp Repts 50-440/B2-16 & 50-441/B2-15 on 820801-1031 No noncompliance noted
KNOP, R C Division of Project & Resident Programs 82/12/15
EDFELMAN, M R Cleveland Electric Illuminating Co 2pp 16584 311
24X Fiche 50-440, 82/12/15, B212290412

--B212290417 IE Insp Repts 50-440/B2-16 & 50-441/B2-15 on 820801-1031 No noncompliance noted Major areas inspected containment dome installation, shield bldg dome concrete placement, refueling bridge rail concrete placement & general housekeeping
GILDER, M L, KONKLIN, J E Division of Project & Resident Programs 82/12/14 4pp 16584 313 24X Fiche 50-440, 82/12/15, B212290412

B208190267 IE Info Notice B2-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16, B208190267

B208190268 IE Info Notice B2-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27 " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X
Fiche 50-000, 82/12/20, B208190268

S Reportable occurrences, LERs & related correspondence

B212020395 Revised B20315 final deficiency rept re cladding fissures adjacent to weld seams in stainless steel suppression pools Items 2 & 3 of proposed corrective action deleted Placement of annulus concrete in pool region will reduce stress level
DAVIDSON, D R Cleveland Electric Illuminating Co 82/11/24
KEPPLER, J O Region 3, Office of Director 2pp 16278 258 24X
Fiche 50-440, 82/11/24, B212020395

B212170153 Supplemental final deficiency rept re biological concrete shield walls Unit 1 repairs will not be completed until 830501 due to changes in const scheduling Unit 2 repairs on schedule
EDFELMAN, M R Cleveland Electric Illuminating Co 82/12/10
KEPPLER, J O Region 3, Office of Director 1p 16450 225 24X
Fiche 50-440, 82/12/10, B212170153

B212170241 Revised final deficiency rept re defective Bettis Model Y3 series actuation yokes on Henry Pratt Co valves Due to delay in receipt of replacement parts & const scheduling, required mods not yet completed
EDFELMAN, M R Cleveland Electric Illuminating Co 82/12/10
KEPPLER, J O Region 3, Office of Director 1p 16459 336 24X
Fiche 50-440, 82/12/10, B212170241

B212210370 Final deficiency rept re dowel counterbore in link rod in standby diesel engine Initially reported on 801008 Link rod inspected Deficiency determined not reportable per JOCFR50 55(e)
EDFELMAN, M R Cleveland Electric Illuminating Co 82/12/10
KEPPLER, J O Region 3, Office of Director 1p 16493 360 24X
Fiche 50-440, 82/12/10, B212210370

B212280291 Final deficiency rept re potential defect in starting air sys check valve mfg by Transamerica Delaval Initially reported on 811218 Check valve disc assembly will be replaced by 830701
EDFELMAN, M R Cleveland Electric Illuminating Co 82/12/15
KEPPLER, J O Region 3, Office of Director 2pp 16560 102 24X
Fiche 50-440, 82/12/15, B212280291

DOCKET 50-443 SEABROOK NUCLEAR STATION, UNIT 1

A Application/construction stage documents & correspondence

B212100102 FOIA request for nine categories of documents re QA program at facilities
KINDER, E T New Hampshire, State of 82/10/27 Division of Rules and Records 3pp 16388 094 24X Fiche 50-443, 82/10/27, B212100102

B212100105 Responds to FOIA request for nine categories of documents re QA program at facilities Forwards safety evaluation & excerpt from FSAR & Suppl 3 to SER dtd 750314
FELTON, J M Division of Rules and Records 82/11/18 KINDER, E T New Hampshire, State of 1p 16388 097 24X Fiche 50-443, 82/11/18, B212100105

--B212100109 Excerpt from FSAR re QA program corrective actions for design & const
* Yankee Atomic Electric Co 82/11/18 2pp 16388 098 24X
Fiche 50-443, 82/11/18, B212100109

--B212103112 Safety evaluation supporting approval of QA program contained in PSAR Chapter 17 Approval contingent upon applicant's resolution of outstanding issues re supervision of QA activities during design & const phases
* Atomic Energy Commission, Directorate of Licensing 74/08/14 20pp 16388 100 24X Fiche 50-443, 82/11/18, B212100105

B212020286 Responds to open items re independent safety engineering group charter (SRP 13 4 3, Licensee Qualification Branch)
Revised FSAR Section 13 4 3 & Tech Spec 6 2 3 forwarded
DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 82/11/23 KNIGHTON, G W Licensing Branch 3 4pp 16279 142 24X Fiche 50-443, 82/11/23, B212020286

--B212020316 Revised Tech Spec 6 2 3 re independent safety engineering group function, composition, responsibilities & authority
* Yankee Atomic Electric Co * Public Service Co of New Hampshire 82/11/23 1p 16279 146 24X Fiche 50-443, 82/11/23, B212020286

B212080545 Forwards "Control of Heavy Loads at Nuclear Power Plants, Seabrook Units 1 & 2," draft technical evaluation rept, per until 820924 ltr Comments requested by B21216 Conference call will be arranged to discuss resolution of open items
KNIGHTON, G W Licensing Branch 3 82/11/23 TALLMAN, H C Public Service Co of New Hampshire 2pp 16370 157 24X
Fiche 50-443, 82/11/23, B212080545

--B212080551 "Control of Heavy Loads at Nuclear Power Plants, Seabrook Units 1 & 2," draft technical evaluation rept
JENSEN, S A, STICKLEY, T H E&O, Inc 82/11/30 NRC - No Detailed Affiliation Given 26pp 16370 159 24X
Fiche 50-443, 82/11/23, B212080545

B212020029 Forwards responses to Containment Sys Branch SRP open items re containment purge sys Response will be included in OL application, Amend 4B
DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 82/11/26 KNIGHTON, G W Licensing Branch 3 4pp 16272 050 24X Fiche 50-443, 82/11/26, B212020029

B212020334 Forwards "Tests of Anchorages to Determine Effects of Prying," final rept, revising B20930 response to Mechanical Engineering Branch B20618 Request for Addl Info 210 704SRP 3 9) Rept will be included in Amend 4B to OL application
DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 82/11/26 KNIGHTON, G W Licensing Branch 3 2pp 16279 231 24X Fiche 50-443, 82/11/26, B212020334

--B212020338 "Tests of Anchorages to Determine Effects of Prying," fin rept
BURDETTE, E O Tennessee, Univ of 82/08/31 86pp 16279 233 24X Fiche 50-443, 82/11/26, B212020334

B212030194 Summarizes caseload forecast panel B21116-17 plant tour & meeting w/HRC re status of const Picture of bridge B over ductwork SF-6 will be submitted by B21215 Supporting documentation & attendance list encl
DEVINCENTIS, J Public Service Co of New Hampshire 82/11/29 KNIGHTON, G W Licensing Branch 3 4pp 16304 044 24X
Fiche 50-443, 82/11/29, B212030194

B212060075 Summarizes Effluent Treatment Sys & Radiological Assessment Branch Open Items 11 5 2, 11 5-1, 12 3 2, 12 5 2 1 & 12 3 4, per B21014 & 0917 meetings
DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 82/11/29 KNIGHTON, G W Licensing Branch 3 12pp 16316 055 24X Fiche 50-443, 82/11/29, B212060075

B212060056 Forwards second revision to Reactor Sys Branch B20212 request for addl info re containment sump design & effect on long-term cooling Following LOCA Response will be included in Amend 4B to OL application Svc list encl
DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 82/11/30 KNIGHTON, G W Licensing Branch 3 6pp 16314 014 24X Fiche 50-443, 82/11/30, B212060056

B212060094 Forwards revised response to Chemical Engineering Branch B20212 request for addl info re NUREG-0737, Item 11 B 3, "Post-Accident Sampling Sys " Info will be provided in OL application, Amend 4B
DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 82/12/01 KNIGHTON, G W Licensing Branch 3 22pp 16315 001 24X Fiche 50-443, 82/12/01, B212060094

DOCKETED ITEMS

8212060151 Forwards three photographs of SF6 ductwork & bridges per L Wheeler request during 821116-17 site tour
DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 82/12/01 KNIGHTON, G W Licensing Branch 3 5pp 16313 140 24X Fiche 50-443, 82/12/01, 8212060151

8212070100 Provides revised schedule for completion of facilities Fuel load scheduled for Sept 1984 for Unit 1 & Dec 1984 for Unit 2 Commercial operation should begin in Dec 1984 for Unit 1 & Mar 1987 for Unit 2 Press release encl
DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 82/12/02 KNIGHTON, G W Licensing Branch 3 5pp 16327 272 24X Fiche 50-443, 82/12/02, 8212070100

8212080224 Submits responses to Chemical Engineering Branch open items Addl info on secondary water chemistry requested to complete review
DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 82/12/02 KNIGHTON, G W Licensing Branch 3 15pp 16354 092 24X Fiche 50-443, 82/12/02, 8212080224

8212080190 Forwards info omitted from 820930 response to Mechanical Engineering Branch 820618 request for addl info re tees or branch connections in Class 1 piping
DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 82/12/03 KNIGHTON, G W Licensing Branch 3 4pp 16354 056 24X Fiche 50-443, 82/12/03, 8212080190

8212080207 Agrees to modify Tech Spec surveillance requirements for emergency feedwater sys
DEVINCENTIS, J Public Service Co of New Hampshire 82/12/03 KNIGHTON, G W Licensing Branch 3 2pp 16354-005 24X Fiche 50-443, 82/12/03, 8212080207

8212080560 Notification of contract execution, Mod 2 to "Follow on Review of Seabrook Nuclear Station, Units 1 & 2" Contractor Fugro, Inc
SILVUS, R H Technical Assistance Contracts Branch FIN B-682/ 82/12/03 DEBENTON, H R Office of Nuclear Reactor Regulation, Director JACKSON, R E NRC - No Detailed Affiliation Given 1p 16368 353 24X Fiche 50-443, 82/12/03, 8212080560

--8212080568 Mod 2, deobligating funds, to "Follow on Review of Seabrook Nuclear Station, Units 1 & 2"
MADSEN, B H Fugro, Inc GUSTAVE, R P Technical Assistance Contracts Branch FIN B-682/ 82/12/03 1p 16368 354 24X Fiche 50-443, 82/12/03, 8212080568

8212090498 Forwards supplemental response to Reactor Sys Branch 820212 & 0426 Requests for Addl info 440 89 & 440 127 re locked rotor event info will be included in OL application, Amend 4B
DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 82/12/07 KNIGHTON, G W Licensing Branch 3 3pp 16365 332 24X Fiche 50-443, 82/12/07, 8212090498

8212140235 Forwards revision to FSAR in response to open item identified by D Powers of Containment Sys Branch Revision to be included in OL application, Amend 4B
DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 82/12/08 KNIGHTON, G W Licensing Branch 3 3pp 16408 352 24X Fiche 50-443, 82/12/08, 8212140235

8212270279 Forwards "Test Rept on Emergency Spray Sys Testing Using Transco Thermo-Wrap," in response to NRC 821203 request for addl info re RCS thermal insulation Transco insulation almost identical to Owens-Corning insulation
DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 82/12/08 KNIGHTON, G W Licensing Branch 3 2pp 16530 284 24X Fiche 50-443, 82/12/08, 8212270279

--8212270281 "Test Repts on Emergency Spray Sys Testing Using Transco Thermo-Wrap"
* Transco, Inc TTR-28N 82/07/27 3pp 16530 286 24X Fiche 50-443, 82/12/08, 8212270279

--8212270286 "Transco Flexible Thermo-Wrap Blanket Type Insulation"
* Transco, Inc 82/05/04 5pp 16530 289 24X Fiche 50-443, 82/12/08, 8212270279

--8212270289 Topical rept evaluation of OCF-1, "Nuclear Containment Insulation Sys" Rept acceptable.
* NRC - No Detailed Affiliation Given 82/12/08 13pp 16530 297 24X Fiche 50-443, 82/12/08, 8212270279

8212270188 Responds to Core Performance Branch open items in safety review re cladding collapse, ECCS calculations & conformance w/App A of SRP Section 4.2
DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 82/12/20 KNIGHTON, G W Licensing Branch 3 9pp 16539 290 24X Fiche 50-443, 82/12/20, 8212270188

8212270146 Forwards draft revised FSAR Section 17.2, "QA During Operations Phase," in response to QA Branch request Section will be included in Amend 43 of OL application
DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 82/12/21 KNIGHTON, G W Operating Reactors Branch 3 61pp 16538 067 24X Fiche 50-443, 82/12/21, 8212270146

8212270270 Informs that FSAR Section 4.2.2.3 a re rod cluster assembly revised per SRP 4.2 Encl revised page will be included in Amend 48 to OL application
DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 82/12/21 KNIGHTON, G W Licensing Branch 3 2pp 16530 311 24X Fiche 50-443, 82/12/21, 8212270270

D NRC Draft/Final Environmental Statements, supplis & correspondence

8212060068 Submits supplemental info re use of steel H-frame structures along Newington transmission line right-of-way per FES Installation of H-frames w/less bulk reduces visual impact & minimizes environ impact
DEVINCENTIS, J Public Service Co of New Hampshire 82/12/01 KNIGHTON, G W Licensing Branch 3 5pp 16316 079 24X Fiche 50-443, 82/12/01, 8212060068

E. NRC Safety Evaluation Report (SER), supplis & correspondence

8212010375 Summary of 821019-1029 meetings w/util re open items in safety review & safety requirements remaining to be met prior to SER issuance
WHEELER, L Licensing Branch 3 82/11/08 Licensing Branch 3 2pp 16267 170 24X Fiche 50-443, 82/11/08, 8212010375

--8211040225 Notification of 821019-1130 meetings w/util in Bethesda, MD to discuss remaining open items in safety review
WHEELER, L Licensing Branch 3 82/10/14 KERRIGAN, J D Licensing Branch 3 2pp 16267 172 24X Fiche 50-443, 82/11/08, 8212010375

8212100105 Responds to FOIA request for nine categories of documents re QA program at Facilities Forwards safety evaluation & excerpt from FSAR & Suppl 3 to SER dtd 750314
FELTON, J M Division of Rules and Records 82/11/18 KINDER, E T New Hampshire, State of 1p 16388 097 24X Fiche 50-443, 82/11/18, 8212100105

--8212100114 Suppl 3 to SER supporting approval of QA program contained in FSAR Chapter 17 Resolution of outstanding issues re review & approval of contractor QA procedures & manuals verified in 741106 insp rept
* Atomic Energy Commission, Directorate of Licensing 75/03/14 3pp 16388 120 24X Fiche 50-443, 82/11/18, 8212100105

8212060059 Submits addl design changes to emergency feedwater sys per SER Startup feedwater pump circuit breaker installed in alternate electrical supply cubicle on emergency electrical bus E5 Changes will be incorporated into FSAR revision
DEVINCENTIS, J Public Service Co of New Hampshire 82/11/30 KNIGHTON, G W Licensing Branch 3 3pp 16314 077 24X Fiche 50-443, 82/11/30, 8212060059

F Security, medical, emergency & fire protection plans

8212080163 Forwards summary info on primary & alternate emergency operations facilities per L Wheeler request
DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 82/12/03 KNIGHTON, G W Licensing Branch 3 3pp 16354 085 24X Fiche 50-443, 82/12/03, 8212080163

G Adjudicatory correspondence

8212010385 Forwards response to Seacoast Anti-Pollution League first set of interrogatories & request for production of documents
PERLIS, R O Hearing Branch 3, 82/11/23 BACKUS, R A Backus, R A 1p 16271 087 24X Fiche 50-443, 82/11/23, 8212010385

--8212010389 Responds to Seacoast Anti-Pollution League first set of interrogatories & request for production of documents
* Commissioners 82/11/23 Seacoast Anti-Pollution League 3pp 16271 088 24X Fiche 50-443, 82/11/23, 8212010385

--8212010396 Affidavit of MC Thadani re NRC response to Seacoast Anti-Pollution League first set of interrogatories & request for production of documents
THADANI, M C Division of Licensing 82/11/23 1p 16271 091 24X Fiche 50-443, 82/11/23, 8212010385

B212020323 Forwards NRC response to State of NH first set of interrogatories & request for production of documents
 PERLIS, R G Hearing Branch 3 82/11/30 KINDER, E T New Hampshire, State of 1p 16279 164 24X Fiche 50-443, 82/11/30, 8212020323

--B212020326 Response to first set of interrogatories & request for production of documents
 PERLIS, R G, LESSY, R P Hearing Branch 3 82/11/30 New Hampshire, State of 29pp 16279 165 24X Fiche 50-443, 82/11/30, 8212020323

B212070242 Request for clarification of ASLB B20913 memorandum & order re resubmission of contentions on offsite emergency planning Time for resubmission unclear Certificate of Svc encl
 SHOTWELL, J A Massachusetts, State of 82/11/30 Atomic Safety and Licensing Board Panel 6pp 16329 292 24X Fiche 50-443, 82/11/30, 8212070242

B212030163 Advises that NRC will take no position on State of NH 821115 motion to compel until answers to first set of interrogatories
 PERLIS, R G Hearing Branch 3 82/12/01 HOYT, H, LUEBKE, E A, HARBOUR, J Atomic Safety and Licensing Board Panel 2pp 16306 013 24X Fiche 50-443, 82/12/01, 8212030163

B212060020 Confirms 821201 telcon from Judge Hoyt Parties invited to B21210 tour w/Judge Prehearing conference scheduled for B30111 to be rescheduled Availability of FEMA representative at next prehearing conference uncertain
 LESSY, R P Hearing Branch 3 82/12/02 HOYT, H, LUEBKE, E A, HARBOUR, J Atomic Safety and Licensing Board Panel 2pp 16313 298 24X Fiche 50-443, 82/12/02, 8212060020

B212140212 Interrogatories & request for production of documents Certificate of Svc encl Related correspondence
 DIGNAN, T G, QAD, R K Public Service Co of New Hampshire
 DIGNAN, T G Ropes & Gray 82/12/08 Coastal Chamber of Commerce of New Hampshire 110pp 16406 153 24X Fiche 50-443, 82/12/08, 8212140212

B212140217 Interrogatories & request for production of documents Certificate of Svc encl Related correspondence
 DIGNAN, T G, QAD, R K Public Service Co of New Hampshire
 DIGNAN, T G Ropes & Gray 82/12/08 Seacoast Anti-Pollution League 108pp 16406 307 24X Fiche 50-443, 82/12/08, 8212140217

B212140430 Interrogatories & request for production of documents Certificate of Svc encl Related correspondence
 DIGNAN, T G, QAD, R K Public Service Co of New Hampshire
 DIGNAN, T G Ropes & Gray 82/12/08 New Hampshire, State of 110pp 16405 031 24X Fiche 50-443, 82/12/08, 8212140430

B212140441 Interrogatories & request for production of documents Certificate of Svc encl Related correspondence
 DIGNAN, T G, QAD, R K Public Service Co of New Hampshire
 DIGNAN, T G Ropes & Gray 82/12/08 New England Coalition on Nuclear Pollution 11pp 16404 063 24X Fiche 50-443, 82/12/08, 8212140441

B212140227 Motion to file responsive pleading re State of NH motion to compel answers to first set of interrogatories to until Certificate of Svc encl Related correspondence
 KINDER, E T New Hampshire, State of 82/12/09 Atomic Safety and Licensing Board Panel 3pp 16408 343 24X Fiche 50-443, 82/12/09, 8212140227

B212140234 Withdrawal of motion to compel answers to interrogatories & response to applicant answer Interrogatories 9, 6, 9, 16 & 10, 2 withdrawn Util should answer 9, 1, 9, B & 10, 1 & SAPL 3, 7, 3, 10 & 3, 11 w/Certificate of Svc Related correspondence
 KINDER, E T New Hampshire, State of 82/12/09 Atomic Safety and Licensing Board Panel 6pp 16408 345 24X Fiche 50-443, 82/12/09, 8212140234

B212140426 Motion for continuance of discovery deadline to B30601 Continuance fair in light of rescheduling of projected fuel loading dates Previous deadline burdensome & would impede litigation of intervenor contention Related correspondence
 BACKUS, R A Seacoast Anti-Pollution League BACKUS, R A Backus, R A 82/12/09 Atomic Safety and Licensing Board Panel 2pp 16404 174 24X Fiche 50-443, 82/12/09, 8212140426

--B212140437 Advises of results of const scheduling study Study indicates 10-month slippage, changing projected fuel loading dates for Unit 1 to Sept 1984 & Unit 2 to Dec 1985 Svc list encl.
 DIGNAN, T G Ropes & Gray DIGNAN, T G Public Service Co of New Hampshire 82/11/30 HOYT, H, LUEBKE, E A, HARBOUR, J Atomic Safety and Licensing Board Panel 2pp 16404 176 24X Fiche 50-443, 82/12/09, 8212140437

B212160281 Motion to extend time until B30315 for discovery on admitted contentions Present schedule does not allow sufficient time to complete requests Certificate of Svc encl Related correspondence
 KINDER, E T, BISBEE, O D New Hampshire, State of 82/12/13 Atomic Safety and Licensing Board Panel 6pp 16446 058 24X Fiche 50-443, 82/12/13, 8212160281

B212160321 Responses to interrogatories & requests for document production Svc list encl Related correspondence
 DOUGHTY, J Seacoast Anti-Pollution League 82/12/13 Office of the Executive Legal Director 5pp 16442 332 24X Fiche 50-443, 82/12/13, 8212160321

B212200039 Forwards motion for extension of time for discovery & LL Bishop notice of appearance
 CURRAN, D Harman & Weiss CURRAN, D New England Coalition on Nuclear Pollution 82/12/15 HOYT, H F, LUEBKE, E A, HARBOUR, J Atomic Safety and Licensing Board Panel 1p 16474 255 24X Fiche 50-443, 82/12/15, 8212200039

--B212200049 Motion for extension of time for discovery until B30315 Sheer vol of matl to be processed to prepare or answer interrogatories on large number of complex technical issues makes compliance impossible Certificate of Svc encl
 CURRAN, D, BISBEE, O D New England Coalition on Nuclear Pollution CURRAN, D Harman & Weiss 82/12/15 Atomic Safety and Licensing Board Panel 8pp 16474 255 24X Fiche 50-443, 82/12/15, 8212200049

B212220255 Amended answer to State of NH Interrogatory 9 B Certificate of Svc encl
 DIGNAN, T G, QAD, R K Public Service Co of New Hampshire
 DIGNAN, T G Ropes & Gray 82/12/15 New Hampshire, State of 4pp 16518 001 24X Fiche 50-443, 82/12/15, 8212220255

B212230346 Second set of interrogatories & request for production of documents Certificate of Svc encl Related correspondence
 KINDER, E T, BISBEE, O D New Hampshire, State of 82/12/15 Office of the Executive Legal Director 14pp 16505 162 24X Fiche 50-443, 82/12/15, 8212230346

B212230348 Second set of interrogatories & request for production of documents Certificate of Svc encl Related correspondence
 KINDER, E T, BISBEE, O D New Hampshire, State of 82/12/15 Public Service Co of New Hampshire 24pp 16511 240 24X Fiche 50-443, 82/12/15, 8212230348

B212200079 Motion for continuance of B21215 deadline for discovery until B30601 Burden of short discovery period & re-election campaign precluded submittal of documents in timely manner Svc list encl
 HOLLINGSWORTH, B Coastal Chamber of Commerce of New Hampshire 82/12/16 Atomic Safety and Licensing Board Panel 3pp 16474 306 24X Fiche 50-443, 82/12/16, 8212200079

B212210228 Answers to second set of interrogatories & request for production of documents on Contentions I A 2, I B 1, I B 2 & I C & motion for protective order Certificate of Svc encl
 DIGNAN, T G, QAD, R K Public Service Co of New Hampshire
 DIGNAN, T G Ropes & Gray 82/12/16 New England Coalition on Nuclear Pollution 71pp 16484 001 24X Fiche 50-443, 82/12/16, 8212210228

B212230334 Second set of interrogatories & request for production of documents Svc list encl Related correspondence
 BACKUS, R A Seacoast Anti-Pollution League BACKUS, R A Backus, R A 82/12/16 Office of the Executive Legal Director 3pp 16505 128 24X Fiche 50-443, 82/12/16, 8212230334

B212230203 Order admitting Towns of Brentwood & Hampton, NH as interested municipalities List of admitted contentions encl
 HOYT, H F Atomic Safety and Licensing Board Panel 82/12/20 Brentwood, NH 10pp 16510 270 24X Fiche 50-443, 82/12/20, 8212230203

B212270208 Memorandum & order ruling on State of NH 821115 motion to compel applicants to answer first set of interrogatories. Applicants must identify persons w/supervisory capacity for control room design & installation
 HOYT, H F Atomic Safety and Licensing Board Panel 82/12/22 Public Service Co. of New Hampshire 6pp 16534 356 24X Fiche 50-443, 82/12/22, 8212270208

B212280017 Advises that NRC will not take position re applicant B21217 motion for protective order for New England Coalition on Nuclear Pollution Interrogatory & Dispute is between applicant & intervenor
 PERLIS, R G Hearing Branch 3, 82/12/23 HOYT, H, LUEBKE, E A, HARBOUR, J Atomic Safety and Licensing Board Panel 1p 16564 288 24X Fiche 50-443, 82/12/23, 8212280017

DOCKETED ITEMS

B212290290 Response to first set of interrogatories & request for documents on Contactions I A 2, I V, I B 1-3, I C, I D, I F, I G, I I & I L - I I N Affidavits & Certificate of Svc encl
 LESSY, R P Hearings Division 82/12/28 New England Coalition on Nuclear Pollution 100pp 16381 115 24X Fiche 50-443, 82/12/28, 8212290290

M Antitrust correspondence

G212080527 Forwards notice of receipt of antitrust info w/recent application for DL Notice to be published in FR, Electric Light & Power, Public Utils Fortnightly & Rural Electrification, trade journals
 KNIGHTON, G W Licensing Branch 3 82/11/29 TALLMAN, H C Public Service Co of New Hampshire 2pp 16370 191 24X Fiche 50-443, 82/11/29, 8212080527

--B212080532 Notice of receipt of antitrust info Request for re-evaluation & addl info must be received by 830107
 KNIGHTON, G W Licensing Branch 3 82/11/29 2pp 16370 193 24X Fiche 50-443, 82/11/29, 8212080527

Q Inspection reports, IE Bulletins & correspondence

B208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Svc list encl
 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 143 24X Fiche 50-000, 82/10/28, 8208190240

B208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list encl
 LOBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000, 82/11/05, 8208190245

B208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl
 JORDAN, E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X Fiche 50-000, 82/11/18, 8208190251

B208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list encl
 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000, 82/11/26, 8208190256

B208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl
 COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000, 82/11/30, 8208190257

B208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl
 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259

B208190261 IE Info Notice 82-48, "Failures of Agastat CR 6095 Relay Sockets " Svc list encl
 JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X Fiche 50-000, 82/12/03, 8208190261

B212080321 Ack receipt of 821117 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-443/82-10 & 50-444/82-10
 STAROSTECKI, R Division of Project & Resident Programs 82/12/03 TALLMAN, H C Public Service Co of New Hampshire 1p 16353 337 24X Fiche 50-443, 82/12/03, 8212080321

--B212080329 Responds to NRC 821020 ltr re violations noted in IE Insp Repts 50-443/82-10 & 50-444/82-10 Corrective actions technical procedure issued to resolve clearance problems & drawing revised to indicate required bolt & nut matl
 DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 82/11/17 STAROSTECKI, R Division of Project & Resident Programs 4pp 16353 338 24X Fiche 50-443, 82/12/03, 8212080321

B212210270 Forwards IE Insp Repts 50-443/82-13 & 50-444/82-11 on 821001-1105 & notice of violation
 STAROSTECKI, R Division of Project & Resident Programs 82/12/06 TALLMAN, H C Public Service Co of New Hampshire 2pp 16483 035 24X Fiche 50-443, 82/12/06, 8212210270

--B212210275 Notice of violation from insp on 821001-1105
 * Division of Project & Resident Programs 82/12/06 1p 16483 037 24X Fiche 50-443, 82/12/06, 8212210270

--B212210282 IE Insp Repts 50-443/82-13 & 50-444/82-11 on 821001-1105 Noncompliance noted failure to conduct & document insp of pipe support Kwik-bolting activities per procedural hold-point requirements
 CERNE, A C, GRAMM, H A, GALLO, R M Division of Project & Resident Programs 82/11/17 9pp 16483 038 24X Fiche 50-443, 82/12/06, 8212210270

B208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16, 8208190267

B208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27 " Svc list encl
 JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X Fiche 50-000, 82/12/20, 8208190268

S Reportable occurrences, LERs & related correspondence

B212060079 PNO-I-82-075 on 821201, util announced 10-month delay & new commercial operation dates for Unit 1 (821231) & Unit 2 (870331) projected Total cost revised by 44% Caused by increased design & engineering complexity
 KELLY, E, GALLO, R, GREENMAN, E Region 1, Office of Director 82/12/01 2pp 16314 342 24X Fiche 50-443, 82/12/01, 8212060079

B212210287 Final deficiency rept re seat leakage in ASCO solenoid valves mounted on Posi-Seal Intl butterfly valves Initially reported on 821103 Posi-Seal Intl supplied relubrication kits to correct problem
 DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 82/12/08 STAROSTECKI, R Division of Project & Resident Programs 3pp 16497 039 24X Fiche 50-443, 82/12/08, 8212210287

B212210273 Interim deficiency rept re adequacy of tornado missile shield protection on north & west walls of fuel storage bldg Initially reported on 821110 Engineering evaluation results will be reported by 830401
 DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 82/12/14 STAROSTECKI, R Division of Project & Resident Programs 2pp 16483 233 24X Fiche 50-443, 82/12/14, 8212210273

B212210449 Interim deficiency rept re potential for pipe & component overstress due to exceeding pipe pulling limits during welding fit-up Initially reported on 821110 Nonconformance rept dispositioned to rework complete Next rept by 830715
 DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 82/12/14 STAROSTECKI, R Division of Project & Resident Programs 3pp 16489 178 24X Fiche 50-443, 82/12/14, 8212210449

DOCKET 50-444 SEABROOK NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

B212100102 FOIA request for nine categories of documents re GA program at facilities.
 KINDER, E T New Hampshire, State of 82/10/27 Division of Rules and Records 3pp 16388 094 24X Fiche 50-443, 82/10/27, 8212100102

B212100105 Responds to FOIA request for nine categories of documents re GA program at facilities Forwards safety evaluation & excerpt from FSAR & Suppl 3 to SER dtd 750314
 FELTON, J M Division of Rules and Records 82/11/18 KINDER, E T New Hampshire, State of 1p 16388 097 24X Fiche 50-443, 82/11/18, 8212100105

--B212100109 Excerpt from FSAR re GA program corrective actions for design & const
 * Yankee Atomic Electric Co 82/11/18 2pp 16388 098 24X Fiche 50-443, 82/11/18, 8212100105

--B212100112 Safety evaluation supporting approval of GA program contained in FSAR Chapter 17 Approval contingent upon applicant resolution of outstanding issues re supervision of GA activities during design & const phases
 * Atomic Energy Commission, Directorate of Licensing 74/08/14 20pp 16388 100 24X Fiche 50-443, 82/11/18, 8212100105

8212020286 Responds to open items re independent safety engineering group charter (SRP 13 4 3, License Qualification Branch) Revised FSAR Section 13 4 3 & Tech Spec 6 2 3 forwarded DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 82/11/23 KNIGHTON, G W Licensing Branch 3 4pp 16279 142 24X Fiche 50-443, 82/11/23, 8212020286

--8212020316 Revised Tech Spec 6 2 3 re independent safety engineering group function, composition, responsibilities & authority * Yankee Atomic Electric Co * Public Service Co of New Hampshire 82/11/23 1p 16279 146 24X Fiche 50-443, 82/11/23, 8212020286

8212080545 Forwards "Control of Heavy Loads at Nuclear Power Plants, Seabrook Units 1 & 2," draft technical evaluation rept, per util 820924 ltr Comments requested by 821216 Conference call will be arranged to discuss resolution of open items KNIGHTON, G W Licensing Branch 3 82/11/23 TALLMAN, W C Public Service Co of New Hampshire 2pp 16370 197 24X Fiche 50-443, 82/11/23, 8212080545

--8212080551 "Control of Heavy Loads at Nuclear Power Plants, Seabrook Units 1 & 2," draft technical evaluation rept JENSEN, B A, STICKLEY, T H EQ&O, Inc 82/11/30 NRC - No Detailed Affiliation Given 26pp 16370.159 24X Fiche 50-443, 82/11/23, 8212080545

8212020029 Forwards responses to Containment Sys Branch SRP open items re containment purge sys Response will be included in OL application, Amend 48 DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 82/11/26 KNIGHTON, G W Licensing Branch 3 4pp 16272 050 24X Fiche 50-443, 82/11/26, 8212020029

8212020334 Forwards "Tests of Anchorages to Determine Effects of Prying," final rept, revising 820930 response to Mechanical Engineering Branch 820618 Request for Addl Info 210 70 (SRP 3 9) Rept will be included in Amend 48 to OL application DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 82/11/26 KNIGHTON, G W Licensing Branch 3 2pp 16279 231 24X Fiche 50-443, 82/11/26, 8212020334

--8212020338 "Tests of Anchorages to Determine Effects of Prying," final rept BURDETTE, E G Tennessee, Univ of 82/08/31 84pp 16279 233 24X Fiche 50-443, 82/11/26, 8212020334

8212030194 Summarizes caseload forecast panel 821116-17 plant tour & meeting w/NRC re status of const Picture of bridge B over ductwork BF-6 will be submitted by 821215 Supporting documentation & attendance list encl DEVINCENTIS, J Public Service Co of New Hampshire 82/11/29 KNIGHTON, G W Licensing Branch 3 4pp 16304 044 24X Fiche 50-443, 82/11/29, 8212030194

8212060075 Summarizes Effluent Treatment Sys & Radiological Assessment Branch Open Items 11 5 2, 11 5-1, 12 3 2, 12 5 2 1 & 12 3 4, per 821014 & 0917 meetings DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 82/11/29 KNIGHTON, G W Licensing Branch 3 12pp 16316 055 24X Fiche 50-443, 82/11/29, 8212060075

8212060056 Forwards second revision to Reactor Sys Branch 820212 request for addl info re containment sump design & effect on long-term cooling following LOCA Response will be included in Amend 48 to OL application Bvc list encl DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 82/11/30 KNIGHTON, G W Licensing Branch 3 6pp 16314 014 24X Fiche 50-443, 82/11/30, 8212060056

8212060094 Forwards revised response to Chemical Engineering Branch 820212 request for addl info re NUREG-0737, Item II B 3, "Post-Accident Sampling Sys" Info will be provided in OL application, Amend 48 DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 82/12/01 KNIGHTON, G W Licensing Branch 3 22pp 16315 001 24X Fiche 50-443, 82/12/01, 8212060094

8212060151 Forwards three photographs of SF6 ductwork & bridges per L Wheeler request during 821116-17 site tour DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 82/12/01 KNIGHTON, G W Licensing Branch 3 5pp 16313 140 24X Fiche 50-443, 82/12/01, 8212060151

8212070100 Provides revised schedule for completion of facilities Fuel load scheduled for Sept 1984 for Unit 1 & Dec 1984 for Unit 2 Commercial operation should begin in Dec 1986 for Unit 1 & Mar 1987 for Unit 2 Press release encl DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 82/12/02 KNIGHTON, G W Licensing Branch 3 5pp 16327 272, 24X Fiche 50-443, 82/12/02, 8212070100

8212080224 Submits responses to Chemical Engineering Branch open items Addl info on secondary water chemistry requested to complete review DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 82/12/02 KNIGHTON, G W Licensing Branch 3 13pp 16354 092 24X Fiche 50-443, 82/12/02, 8212080224

8212080190 Forwards info omitted from 820930 response to Mechanical Engineering Branch 820618 request for addl info re tees or branch connections in Class 1 piping DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 82/12/03 KNIGHTON, G W Licensing Branch 3 4pp 16354 056 24X Fiche 50-443, 82/12/03, 8212080190

8212080207 Agrees to modify Tech Spec surveillance requirements for emergency feedwater sys DEVINCENTIS, J Public Service Co of New Hampshire 82/12/03 KNIGHTON, G W Licensing Branch 3 2pp 16354 005 24X Fiche 50-443, 82/12/03, 8212080207

8212080560 Notification of contract execution, Mod 2 to "Follow on Review of Seabrook Nuclear Station, Units 1 & 2" Contractor Fugro, Inc SILVIER, R M Technical Assistance Contracts Branch FIN D-6827 82/12/03 DENTON, H R Office of Nuclear Reactor Regulation, Director JACKSON, R E NRC - No Detailed Affiliation Given 1p 16368 353 24X Fiche 50-443, 82/12/03, 8212080560

--8212080568 Mod 2, deobligating funds, to "Follow on Review of Seabrook Nuclear Station, Units 1 & 2" MADSEN, S H Fugro, Inc GUSTAVE, R P Technical Assistance Contracts Branch FIN D-6827 82/12/03 1p 16368 354 24X Fiche 50-443, 82/12/03, 8212080560

8212090498 Forwards supplemental response to Reactor Sys Branch 820912 & 0426 Requests for Addl Info 440 89 & 440 127 re locked rotor event Info will be included in OL application, Amend 48 DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 82/12/07 KNIGHTON, G W Licensing Branch 3 3pp 16365 332 24X Fiche 50-443, 82/12/07, 8212090498

8212140235 Forwards revision to FSAR in response to open item identified by D Powers of Containment Sys Branch Revision to be included in OL application, Amend 48 DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 82/12/08 KNIGHTON, G W Licensing Branch 3 3pp 16408 352 24X Fiche 50-443, 82/12/08, 8212140235

8212270279 Forwards "Test Rept on Emergency Spray Sys Testing Using Transco Thermo-Wrap," in response to NRC 821203 request for addl info re RCS thermal insulation Transco insulation almost identical to Owens-Corning insulation DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 82/12/08 KNIGHTON, G W Licensing Branch 3 2pp 16530 284, 24X Fiche 50-443, 82/12/08, 8212270279

--8212270281 "Test Repts on Emergency Spray Sys Testing Using Transco Thermo-Wrap" * Transco, Inc TTR-25N 82/07/27 3pp 16530 286 24X Fiche 50-443, 82/12/08, 8212270279

--8212270286 "Transco Flexible Thermo-Wrap Blanket Type Insulation" * Transco, Inc 82/05/04 3pp 16530 289 24X Fiche 50-443, 82/12/08, 8212270279

8212270188 Responds to Core Performance Branch open items in safety review re cladding collapse, ECCS calculations & conformance w/App A of SRP Section 4 2 DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 82/12/20 KNIGHTON, G W Licensing Branch 3 9pp 16539 290 24X Fiche 50-443, 82/12/20, 8212270188

8212270146 Forwards draft revised FSAR Section 17 2, "QA During Operations Phase," in response to QA Branch request Section will be included in Amend 43 of OL application DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 82/12/21, KNIGHTON, G W Operating Reactors Branch 3 61pp 16538 067 24X Fiche 50-443, 82/12/21, 8212270146

8212270270 Informs that FSAR Section 4 2 2 3 a re rod cluster assembly revised per SRP 4 2 Encl revised page will be included in Amend 48 to OL application DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 82/12/21 KNIGHTON, G W Licensing Branch 3 2pp 16530 311 24X Fiche 50-443, 82/12/21, 8212270270

D NRC Draft/Final Environmental Statements, supplis & correspondence

B21206006B Submits supplemental info re use of steel H-frame structures along Newington transmission line right-of-way per FEB Installation of H-Frames w/less bulk reduces visual impact & minimizes environ impact
DEVINCENIS, J Public Service Co of New Hampshire, B2/12/01
KNIGHTON, Q W Licensing Branch 3 5pp 16316 079 24X
Fiche 50-443, B2/12/01, B21206006B

E. NRC Safety Evaluation Report (SER), supplis & correspondence

B212010375 Summary of B21019-1029 meetings w/util re open items in safety review & safety requirements remaining to be met prior to SER issuance
WHEELER, L L Licensing Branch 3 B2/11/08 Licensing Branch 3
5pp 16267 170 24X Fiche 50-443, B2/11/08, B212010375

--B211040225 Notification of B21019-1130 meetings w/util in Bethesda, MD to discuss remaining open items in safety review
WHEELER, L L Licensing Branch 3 B2/10/14 KERRIGAN, J D
Licensing Branch 3 2pp 16267 172 24X Fiche 50-443, B2/11/08, B212010375

B212100105 Responds to FOIA request for nine categories of documents re QA program at facilities Forwards safety evaluation & excerpt from FSAR & Suppl 3 to SER dtd 750314
FELTON, J M Division of Rules and Records B2/11/18 KINDER, E T
New Hampshire, State of 1p 16388 097 24X Fiche 50-443, B2/11/18, B212100105

--B212100114 Suppl 3 to SER supporting approval of QA program contained in FSAR Chapter 17 Resolution of outstanding issues re review & approval of contractor QA procedures & manuals verified in 741104 insp rept
* Atomic Energy Commission, Directorate of Licensing 75/03/14
3pp 16388 120 24X Fiche 50-443, B2/11/18, B212100105

B212060059 Submits addl design changes to emergency feedwater sys per SER Startup feedwater pump circuit breaker installed in alternate electrical supply cubicle on emergency electrical bus E5 Changes will be incorporated into FSAR revision
DEVINCENIS, J Public Service Co of New Hampshire B2/11/30
KNIGHTON, Q W Licensing Branch 3 3pp 16314 077 24X
Fiche 50-443, B2/11/30, B212060059

F Security, medical, emergency & fire protection plans

B212080163 Forwards summary info on primary & alternate emergency operations facilities per L Wheeler request
DEVINCENIS, J Yankee Atomic Electric Co DEVINCENIS, J Public Service Co of New Hampshire B2/12/03 KNIGHTON, Q W Licensing Branch 3 3pp 16354 085 24X Fiche 50-443, B2/12/03, B212080163

G Adjudicatory correspondence

B212010385 Forwards response to Seacoast Anti-Pollution League first set of interrogatories & request for production of documents
PERLIS, R O Hearing Branch 3 B2/11/23 BACKUS, R A Backus, R A
1p 16271 087 24X Fiche 50-443, B2/11/23, B212010385

--B212010389 Responds to Seacoast Anti-Pollution League first set of interrogatories & request for production of documents
* Commissioners, B2/11/23 Seacoast Anti-Pollution League
3pp 16271 088 24X Fiche 50-443, B2/11/23, B212010385

--B212010396 Affidavit of MC Thadani re NRC response to Seacoast Anti-Pollution League first set of interrogatories & request for production of documents
THADANI, M C Division of Licensing B2/11/23 1p 16271 091
24X Fiche 50-443, B2/11/23, B212010385

B212020323 Forwards NRC response to State of NH first set of interrogatories & request for production of documents.
PERLIS, R O Hearing Branch 3 B2/11/30 KINDER, E T New Hampshire, State of 1p 16279 164 24X Fiche 50-443, B2/11/30, B212020323

--B212020326 Response to first set of interrogatories & request for production of documents
PERLIS, R O, LESSBY, R P Hearing Branch 3 B2/11/30 New Hampshire, State of 27pp 16279 165 24X Fiche 50-443, B2/11/30, B212020323

B212070242 Request for clarification of ASLB B20913 memorandum & order re submission of contentions on offsite emergency planning time for resubmission unclear Certificate of Svc encl
SHOTWELL, J A Massachusetts, State of B2/11/30 Atomic Safety and Licensing Board Panel 6pp 16329 292 24X
Fiche 50-443, B2/11/30, B212070242

B212030163 Advises that NRC will take no position on State of NH B21115 motion to compel util answers to first set of interrogatories
PERLIS, R O Hearing Branch 3 B2/12/01 HOYT, H, LUEBKE, E A, HARBOUR, J Atomic Safety and Licensing Board Panel 2pp 16306 013 24X Fiche 50-443, B2/12/01, B212030163

B212060020 Confirms B21201 telcon from Judge Hoyt Parties invited to B21210 tour w/Judge Prehearing conference scheduled for B30111 to be rescheduled Availability of FEMA representative at next prehearing conference uncertain
LESSBY, R P Hearing Branch 3 B2/12/02 HOYT, H, LUEBKE, E A, HARBOUR, J Atomic Safety and Licensing Board Panel 2pp 16313 298 24X Fiche 50-443, B2/12/02, B212060020

B212140212 Interrogatories & request for production of documents Certificate of Svc encl Related correspondence
DIGMAN, T O, QAD, R K Public Service Co of New Hampshire
DIGMAN, T O Ropes & Gray B2/12/08 Coastal Chamber of Commerce of New Hampshire 110pp 16406 153 24X Fiche 50-443, B2/12/08, B212140212

B212140217 Interrogatories & request for production of documents Certificate of Svc encl Related correspondence
DIGMAN, T O, QAD, R K Public Service Co of New Hampshire
DIGMAN, T O Ropes & Gray B2/12/08 Seacoast Anti-Pollution League 108pp 16406 307 24X Fiche 50-443, B2/12/08, B212140217

B212140430 Interrogatories & request for production of documents Certificate of Svc encl Related correspondence
DIGMAN, T O, QAD, R K Public Service Co of New Hampshire
DIGMAN, T O Ropes & Gray B2/12/08 New Hampshire, State of 110pp 16405 031 24X Fiche 50-443, B2/12/08, B212140430

B212140441 Interrogatories & request for production of documents Certificate of Svc encl Related correspondence
DIGMAN, T O, QAD, R K Public Service Co of New Hampshire
DIGMAN, T O Ropes & Gray B2/12/08 New England Coalition on Nuclear Pollution 11pp 16404 063 24X Fiche 50-443, B2/12/08, B212140441

B212140227 Motion to file responsive pleading re State of NH motion to compel answers to first set of interrogatories to util Certificate of Svc encl Related correspondence
KINDER, E T New Hampshire, State of B2/12/09 Atomic Safety and Licensing Board Panel 3pp 16408 343 24X Fiche 50-443, B2/12/09, B212140227

B212140234 Withdrawal of motion to compel answers to interrogatories & response to applicant answer Interrogatories 9, 6, 9, 16 & 10 2 withdrawn Util should answer 9, 1, 9 & 10 1 & 8, 13, 7, 3, 10 & 3 11 W/Certificate of Svc Related correspondence
KINDER, E T New Hampshire, State of B2/12/09 Atomic Safety and Licensing Board Panel 6pp 16408 346 24X Fiche 50-443, B2/12/09, B212140234

B212140426 Motion for continuance of discovery deadline to B30601 Continuance fair in light of rescheduling of projected fuel loading dates Previous deadline burdensome & would impede litigation of intervenor contention Related correspondence
BACKUS, R A Seacoast Anti-Pollution League BACKUS, R A Backus, R A B2/12/09 Atomic Safety and Licensing Board Panel 2pp 16404 174 24X Fiche 50-443, B2/12/09, B212140426

--B212140437 Advises of results of const scheduling study Study indicates 10-month slippage, changing projected fuel loading dates for Unit 1 to Sept 1984 & Unit 2 to Dec 1986 Svc list encl
DIGMAN, T O Ropes & Gray DIGMAN, T O Public Service Co of New Hampshire B2/11/30 HOYT, H, LUEBKE, E A, HARBOUR, J Atomic Safety and Licensing Board Panel 2pp 16404 176 24X
Fiche 50-443, B2/12/09, B212140426

B212160281 Motion to extend time until B30315 for discovery on admitted contentions Present schedule does not allow sufficient time to complete requests Certificate of Svc encl Related correspondence
KINDER, E T, BISBEE, O D New Hampshire, State of B2/12/13 Atomic Safety and Licensing Board Panel 6pp 16446 058 24X
Fiche 50-443, B2/12/13, B212160281

B212160321 Responses to interrogatories & requests for document production Svc list encl Related correspondence
DOUGHERTY, J Seacoast Anti-Pollution League B2/12/13 Office of the Executive Legal Director 5pp 16442 332 24X
Fiche 50-443, B2/12/13, B212160321

B212200039 Forwards motion for extension of time for discovery & LL Bishop notice of appearance
CURRAN, D Harmon & Weiss CURRAN, D New England Coalition on Nuclear Pollution 82/12/15 HOYT, H F, LUEBKE, E A, HARBOUR, J Atomic Safety and Licensing Board Panel 1p 16474 255 24X Fiche 50-443, 82/12/15, 8212200039

--8212200049 Motion for extension of time for discovery until 830315
Sheer vol of matl to be processed to prepare or answer interrogatories on large number of complex technical issues makes compliance impossible Certificate of Svc encl
CURRAN, D, BISHOP, L L New England Coalition on Nuclear Pollution CURRAN, D Harmon & Weiss 82/12/15 Atomic Safety and Licensing Board Panel 8pp 16474 255 24X Fiche 50-443, 82/12/15, 8212200039

B212220255 Amended answer to State of NH Interrogatory 9 & Certificate of Svc encl
BIGNAN, T O, QAD, R K Public Service Co of New Hampshire BIGNAN, T O Ropes & Gray 82/12/15 New Hampshire, State of 4pp 16518 001 24X Fiche 50-443, 82/12/15, 8212220255

B212230346 Second set of interrogatories & request for production of documents Certificate of Svc encl Related correspondence
KINDER, E T, BISHOP, D New Hampshire, State of 82/12/15 Office of the Executive Legal Director 14pp 16505 162 24X Fiche 50-443, 82/12/15, 8212230346

B212230348 Second set of interrogatories & request for production of documents Certificate of Svc encl Related correspondence
KINDER, E T, BISHOP, D New Hampshire, State of 82/12/15 Public Service Co of New Hampshire 24pp 16511 240 24X Fiche 50-443, 82/12/15, 8212230348

B212200079 Motion for continuance of 821215 deadline for discovery until 830601 Burden of short discovery period & re-election campaign precluded submittal of documents in timely manner
Svc list encl
HOLLINGWORTH, B Coastal Chamber of Commerce of New Hampshire 82/12/16 Atomic Safety and Licensing Board Panel 3pp 16474 306 24X Fiche 50-443, 82/12/16, 8212200079

B212210228 Answers to second set of interrogatories & request for production of documents on Contentions I A 2, I B 1, I B 2 & I C & motion for protective order Certificate of Svc encl
BIGNAN, T O, QAD, R K Public Service Co of New Hampshire BIGNAN, T O Ropes & Gray 82/12/16 New England Coalition on Nuclear Pollution 7pp 16484 001 24X Fiche 50-443, 82/12/16, 8212210228

B212230334 Second set of interrogatories & request for production of documents Svc list encl Related correspondence
BACKUS, R A Seacoast Anti-Pollution League BACKUS, R A Backus, R A 82/12/16 Office of the Executive Legal Director 3pp 16505 128 24X Fiche 50-443, 82/12/16, 8212230334

B212230203 Order admitting Towns of Brentwood & Hampton, NH as interested municipalities List of admitted contentions
encl
HOYT, H F Atomic Safety and Licensing Board Panel 82/12/20 Brentwood, NH 10pp 16510 270 24X Fiche 50-443, 82/12/20, 8212230203

B212270208 Memorandum & order ruling on State of NH 821115 motion to compel applicants to answer first set of interrogatories
Applicants must identify persons w/supervisory capacity for control room design & installation
HOYT, H F Atomic Safety and Licensing Board Panel 82/12/22 Public Service Co of New Hampshire 6pp 16534 356 24X Fiche 50-443, 82/12/22, 8212270208

B212280017 Advises that NRC will not take position re applicant 821217 motion for protective order for New England Coalition on Nuclear Pollution Interrogatory 6 Dispute is between applicant & intervenor
PERLIS, R O Hearing Branch 3 82/12/23 HOYT, H, LUEBKE, E A, HARBOUR, J Atomic Safety and Licensing Board Panel 1p 16564 288 24X Fiche 50-443, 82/12/23, 8212280017

B212270270 Response to first set of interrogatories & request for documents on Contentions I A 2, I V, II, B 1-5, II C, II D, II F, II G, II I & II L - II N Affidavits & Certificate of Svc encl
LESSY, R P Hearings Division 82/12/28 New England Coalition on Nuclear Pollution 100pp 16581 115 24X Fiche 50-443, 82/12/28, 8212270270

M Antitrust correspondence

B212080527 Forwards notice of receipt of antitrust info w/recent application for OL Notice to be published in FR, Electric Light & Power, Public Utils Forthrightly & Rural Electrification, trade journals
KNIGHTON, O W Licensing Branch 3 82/11/29 TALLMAN, W C Public Service Co of New Hampshire 2pp 16370 191 24X Fiche 50-443, 82/11/29, 8212080527

--8212080532 Notice of receipt of antitrust info Requests for re-evaluation & addl info must be received by 830107
KNIGHTON, O W Licensing Branch 3 82/11/29 2pp 16370 193 24X Fiche 50-443, 82/11/29, 8212080527

G Inspection reports, IE Bulletins & correspondence

B208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 14662 163 24X Fiche 50-000, 82/10/28, 8208190240

B208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000, 82/11/05, 8208190245

B208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 107pp 16411 199 24X Fiche 50-000, 82/11/18, 8208190251

B208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000, 82/11/26, 8208190256

B208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000, 82/11/30, 8208190257

B208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259

B208190261 IE Info Notice 82-48, "Failures of Agestat CR 0095 Relay Sockets " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X Fiche 50-000, 82/12/03, 8208190261

B212080321 Ack receipt of 821117 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-443/82-10 & 50-444/82-10
STAROSTECKI, R Division of Project & Resident Programs, 82/12/03 TALLMAN, W C Public Service Co of New Hampshire 1p 16553 337 24X Fiche 50-443, 82/12/03, 8212080321

--8212080329 Responds to NRC 821020 ltr re violations noted in IE Insp Repts 50-443/82-10 & 50-444/82-10 Corrective actions technical procedure issued to resolve clearance problems & drawing revised to indicate required bolt & nut matl
DEVINCENTIS, J Yankee Atomic Electric Co, DEVINCENTIS, J Public Service Co of New Hampshire 82/11/17 STAROSTECKI, R Division of Project & Resident Programs 4pp 16353 338 24X Fiche 50-443, 82/12/03, 8212080321

B212210270 Forwards IE Insp Repts 50-443/82-13 & 50-444/82-11 on 821001-1105 & notice of violation
STAROSTECKI, R Division of Project & Resident Programs 82/12/06, TALLMAN, W C Public Service Co of New Hampshire 2pp 16483 035 24X Fiche 50-443, 82/12/06, 8212210270

--8212210282 IE Insp Repts 50-443/82-13 & 50-444/82-11 on 821001-1105 Noncompliance noted failure to conduct & document insp of pipe support kwik-bolting activities per procedural hold-point requirements
CERNE, A C, GRAHAM, R A, GALLO, R M Division of Project & Resident Programs 82/11/17, 9pp 16483 038 24X Fiche 50-443, 82/12/06, 8212210270

DOCKETED ITEMS

B208190267 IE Info Notice B2-49, "Correction for Sample Conditions for Air & Gas Monitoring" Svc list encl
 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc
 127pp 16628 191 24X Fiche 50-000, 82/12/16, B208190267

B208190268 IE Info Notice B2-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27" Svc list encl
 JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 273 24X
 Fiche 50-000, 82/12/20, B208190268

S Reportable occurrences, LERs & related correspondence

B212060079 PNO-I-82-075 on B21201, util announced 10-month delay & new commercial operation dates for Unit 1 (B21231) & Unit 2 (B20331) projected. Total cost revised by 44% Caused by increased design & engineering complexity
 KELLY, E, GALLLO, R, GREENMAN, E Region 1, Office of Director 82/12/01 2pp 16314.342 24X Fiche: 50-443, 82/12/01, B212060079

B212210287 Final deficiency rept re seat leakage in ASCO solenoid valves mounted on Posi-Seal Intl butterfly valves Initially reported on B21103 Posi-Seal Intl supplied relubrication kits to correct problem
 DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 82/12/08 STARGSTECKI, R Division of Project & Resident Programs 3pp 16497 039 24X
 Fiche 50-443, 82/12/08, B212210287

B212210273 Interim deficiency rept re adequacy of tornado missile shield protection on north & west walls of fuel storage bldg Initially reported on B21110 Engineering evaluation results will be reported by B20401.
 DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 82/12/14 STARGSTECKI, R Division of Project & Resident Programs 2pp 16483 233 24X
 Fiche 50-443, 82/12/14, B212210273

B212210449 Interim deficiency rept re potential for pipe & component overstress due to exceeding pipe pulling limits during welding fit-up Initially reported on B21110 Nonconformance rept dispositioned to rework complete. Next rept by B30715
 DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 82/12/14 STARGSTECKI, R Division of Project & Resident Programs 3pp 16489 178 24X
 Fiche 50-443, 82/12/14, B212210449

CKET 50-445 COMANCHE PEAK STEAM ELECTRIC STA., UNIT 1

Application/construction stage documents & correspondence

B21270418 Responds to FOIA request for documents re proposed revision &/or update to reactor safety study referred to in NUREG-0784; Chapter 10 as RB II & all documents pertaining to reactor cooling methods. Forwards documents listed in app
 FELTON, J M Division of Rules and Records 82/11/26 SHOLLY, S C Union of Concerned Scientists 3pp 16549 233 24X
 Fiche 50-000, 82/11/26, B21270418

B211050027 Forwards summary of semiscale test results & advises that board notification re test results issued. W/o encl
 NOVAK, T M Assistant Director for Licensing 82/09/24 Division of Licensing 1p 16349 278 24X Fiche 50-000, 82/11/26, B21270418

B2080106 Notification of B21216 meeting w/util in Bethesda, MD to discuss util plans for independent design verification program
 IURMELL, S B Licensing Branch 1, 82/12/01 YOUNGBLOOD, B J Licensing Branch 1 3pp 16368 297 24X Fiche 50-445, 82/12/01, B212080106

B2160428 Forwards proposed process control program establishing boundary conditions for operation of ATCOR radwaste solidification sys
 LEMENTS, B R Texas Utilities Generating Co 82/12/09 DENTON, H R Office of Nuclear Reactor Regulation, Director 14pp 16442 132 24X Fiche 50-445, 82/12/09, B212160428

B220440 Board Notifications B2-125 & B2-125A: forwards info re Etherington evaluation of flow blockage during natural circulation of PWRs Results do not adversely impact present position on reliance on natural circulation
 NOVAK, T M Assistant Director for Licensing 82/12/14 Atomic Safety and Licensing Board Panel 5pp 16523 135 24X
 Fiche 50-000, 82/12/14, B21220440

B212220461 Board Notification B2-124 forwards RJ Mattson B21123 memo re Semiscale S-UT-B test results Phenomena of core level depression & loop seal clearing may be more complex than previously supposed
 NOVAK, T M Assistant Director for Licensing 82/12/14 Atomic Safety and Licensing Board Panel 7pp 16523 169 24X
 Fiche 50-000, 82/12/14, B212220461

E NRC Safety Evaluation Report (SER), supplis & correspondence

B212170337 Forwards "Human Factors Control Room Design Review of Comanche Peak Steam Electric Station," to resolve SER (NUREG-0797) open issue
 GARY, R J Texas Utilities Generating Co 82/12/15 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 16460 001 24X
 Fiche 50-445, 82/12/15, B212170337

--B212170342 "Human Factors Control Room Design Review of Comanche Peak Steam Electric Station"
 GARY, R J Texas Utilities Generating Co 82/12/31 510pp 16460 002 24X Fiche 50-445, 82/12/15, B212170337

F Security, medical, emergency & fire protection plans

B212070403 Responds to B21202 request re Generic Ltr B1-10, "Emergency Operations Facility Survey" Emergency operations facility const completed Aug 1982 Protection factor upgraded Equipment will be installed prior to fuel load
 SCHMIDT, H C Texas Utilities Services, Inc 82/12/03 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 16335 343 24X
 Fiche 50-445, 82/12/03, B212070403

B212140298 Forwards Revision 2 to security training & qualification plan Revision withheld (ref 10CFR73.21)
 GARY, R J Texas Utilities Generating Co 82/12/06 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 16402 080 24X Fiche 50-445, 82/12/06, B212140298

G Adjudicatory correspondence

B212090095 Order advising that record will not be closed at present time due to unresolved issues & incomplete analyses Parties directed to file provisional proposed findings on all issues covered in record Admitted intervenor exhibits listed
 MILLER, M E Atomic Safety and Licensing Board Panel 82/12/07 6pp 16337 313 24X Fiche 50-445, 82/12/07, B212090095

B212140409 Motion for reconsideration of B21207 order establishing schedule for simultaneous filing of proposed findings of fact Applicants bear ultimate burden of proof in proceeding & should be allowed time to respond to proposed findings
 REYNOLDS, N S, HORIN, W A Texas Utilities Generating Co REYNOLDS, N S Debevoise & Liberman 82/12/10 Atomic Safety and Licensing Board Panel 4pp 16403 329 24X Fiche 50-445, 82/12/10, B212140409

B212230182 Motion to suppl exhibits accepted by B21202 order Encl exhibits constitute new & significant info which should be in record Certificate of Svc encl
 ELLIS, J Citizens Association for Sound Energy 82/12/14 Atomic Safety and Licensing Board Panel 50pp 16510 319 24X
 Fiche 50-445, 82/12/14, B212230182

B212230195 Motion for reconsideration of ASLB B21207 order directing simultaneous filing of proposed findings of fact Since fuel load not expected until Dec 1983, deadline for Walsh/Daigle allegation findings may be extended W/Certificate of Svc
 ELLIS, J Citizens Association for Sound Energy 82/12/14 Atomic Safety and Licensing Board Panel 9pp 16311 021 24X
 Fiche 50-445, 82/12/14, B212230195

B212230353 Reconsideration of B21207 order, extending deadline until B30223 to file provisional proposed findings of fact
 MILLER, M E Atomic Safety and Licensing Board Panel 82/12/21 Texas Utilities Generating Co 4pp 16517 129 24X
 Fiche 50-445, 82/12/21, B212230353

B212300009 Brief in opposition to NRC exceptions to ASLB B20930 order denying reconsideration of orders to produce info Affidavit & Certificate of Svc encl
 ELLIS, J Citizens Association for Sound Energy 82/12/21 Atomic Safety and Licensing Appeal Panel 175pp 16599 036 24X
 Fiche 50-445, 82/12/21, B212300009

B212300045 Affidavit of J Ellis, attesting to truth of statements in Citizens Assoc for Sound Energy brief in opposition to NRC exceptions to ASLB order denying reconsideration of B20930 order
 ELLIS, J Citizens Association for Sound Energy 82/12/21 2pp 16598 194 24X Fiche 50-445, 82/12/21, B212300045

- 8212270317 Forwards MP Osborne affidavit confirming that value of DNDR remains above limiting value of 1.30 w/o w/o boron injection tank
REYNOLDS, N S Debevoise & Liberman REYNOLDS, N S Texas Utilities Generating Co 82/12/22 MILLER, M E, MCCOLLUM, K A, COLE, R Atomic Safety and Licensing Board Panel 2pp 16530 278 24X Fiche 50-445, 82/12/22, 8212270317
- 8212270320 Affidavit of MP Osborne confirming that value of DNDR remains above 1.30 limit for pertinent steam line break analyses w/o boron injection tank
OSBORNE, M P Texas Utilities Generating Co 82/11/29 1p 16530 280 24X Fiche 50-445, 82/12/22, 8212270317
- 8212270332 Brief in response to NRC B21008 exceptions to ASLB B20930 order denying reconsideration of ASLB B20804 order to show cause ASLB review required to decide if party to proceeding was prejudiced w/ Certificate of Svc
REYNOLDS, N S Texas Utilities Generating Co REYNOLDS, N S Debevoise & Liberman 82/12/22 Atomic Safety and Licensing Appeal Panel 21pp 16530 016 24X Fiche 50-445, 82/12/22, 8212270332
- 8212280273 Response in opposition to Citizens Assoc for Sound Energy (CASE) B21214 motion to suppl exhibits info to be presented in applicant brief should be considered in disposing of CASE instant motion Certificate of Svc encl
REYNOLDS, N S, HORIN, W A Texas Utilities Generating Co REYNOLDS, N S Debevoise & Liberman 82/12/23 Atomic Safety and Licensing Board Panel 11pp 16561 232 24X Fiche 50-445, 82/12/23, 8212280273
- 8212300016 Notices that oral argument on issues raised by NRC appeal from ASLB B20930 order denying NRC motion for reconsideration of B20804 order will be held on B30119 in Bethesda, MD
SHOEMAKER, C J Atomic Safety and Licensing Appeal Panel 82/12/27 TURK, S E Office of the Executive Legal Director ELLIS, J Citizens Association for Sound Energy REYNOLDS, N S Debevoise & Liberman 1p 16598 309 24X Fiche 50-445, 82/12/27, 8212300016
- Utility Final Safety Analysis Report (FSAR) & amendments
- 8212130301 Forwards tabled revisions to FSAR, Amend 36
MARSHALL, J S Texas Utilities Services, Inc 82/12/10 BURWELL, S B Division of Licensing 7pp 16389 333 24X Fiche 50-445, 82/12/10, 8212130301
- 8212150166 Forwards Amend 36 to FSAR
GARY, R J Texas Utilities Generating Co 82/12/10 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 16428 001 24X Fiche 50-445, 82/12/10, 8212150166
- 8212150171 Amend 36 to FSAR
Texas Utilities Generating Co 82/12/10 88pp 16429 001 24X Fiche 50-445, 82/12/10, 8212150166
- 8212210391 Forwards Amend 37 to FSAR
GARY, R J Texas Utilities Generating Co 82/12/17 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 16494 330 24X Fiche 50-445, 82/12/17, 8212210391
- 8212210394 Amend 37 to FSAR
Texas Utilities Generating Co 82/12/17 187pp 16494 332 24X Fiche 50-445, 82/12/17, 8212210391
- Inspection reports, IE Bulletins & correspondence
- 8208190240 IE Bulletin B2-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants" Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 12pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240
- 8212010354 Board Notification B2-116 forwards matl re welds in main control panel at sites Licensee has not provided info necessary to resolve item identified in IE Insp Rept 50-445/82-19
NOVAK, T M Assistant Director for Licensing 82/11/04 Atomic Safety and Licensing Board Panel 4pp 16271 206 24X Fiche 50-445, 82/11/04, 8212010354
- 8208190245 IE Info Notice B2-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters" Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards, Consolidated Edison Co of New York, Inc 82/11/05 110pp 16372 142 24X Fiche 50-000, 82/11/05, 8208190245
- 8212030151 Forwards IE Insp Rept 50-445/82-22 on B21019-20 No noncompliance noted
MADSEN, O L Division of Resident, Reactor Project & Engineering Programs 82/11/10 GARY, R J Texas Utilities Generating Co 2pp 16303 299 24X Fiche 50-445, 82/11/10, 8212030151
- 8212030156 IE Insp Rept 50-445/82-22 on B21019-20 No noncompliance noted Major areas inspected const activities
TOHLINSON, D P, STEWART, R C, ROBERTS, M J Region 4, Office of Director 82/11/02 4pp 16303 301 24X Fiche 50-445, 82/11/10, 8212030151
- 8212280329 Responds to IE Bulletin B2-01, Revision 1, Suppl 1, "Alteration of Radiographs of Welds in Piping Subassemblies" All but six welds will meet applicable code requirements
GARY, R J Texas Utilities Generating Co 82/11/17 COLLINS, J T Region 4, Office of Director 2pp 16560 104 24X Fiche 50-445, 82/11/17, 8212280329
- 8208190251 IE Info Notice B2-44, "Clarification of Emergency Plan Exercise Requirements" Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411, 199 24X Fiche 50-000, 82/11/18, 8208190251
- 8208190256 IE Info Notice B2-46, "Defective & Obsolete Combination Padlocks" Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000, 82/11/26, 8208190256
- 8208190257 IE Info Notice B2-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl" Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000, 82/11/30, 8208190257
- 8208190259 IE Bulletin B2-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies" Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259
- 8208190261 IE Info Notice B2-4B, "Failures of Agastat CR 0095 Relay Sockets" Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X Fiche 50-000, 82/12/03, 8208190261
- 8212140157 Advises that IE Insp Rept 50-445/82-14 on 820803-30 issued on 821108 supersedes insp rept issued on 820929, due to addl info reported re structural welding performed by NPB Industries
MADSEN, O L Division of Resident, Reactor Project & Engineering Programs 82/12/09 GARY, R J Texas Utilities Generating Co 2pp 16409 346 24X Fiche 50-445, 82/12/09, 8212140157
- 8208190267 IE Info Notice B2-49, "Correction for Sample Conditions for Air & Gas Monitoring" Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16, 8208190267
- 8208190268 IE Info Notice B2-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27" Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance, Consolidated Edison Co of New York, Inc 108pp, 16628 293 24X Fiche 50-000, 82/12/20, 8208190268
- 8212300121 Forwards QA Program Insp Repts 99900784/B2-01 & 99900781/B2-01, which impact work at facility, per 821208 SALP meeting Insp repts of NPB1 & ITT Grinnell will follow WFO encls
COLLINS, J T Region 4, Office of Director 82/12/27 CLEMENTS, B R Texas Utilities Generating Co 1p 16598 233 24X Fiche 50-445, 82/12/27, 8212300121
- DOCKET 50-446 CONACHE PEAK STEAM ELECTRIC STA, UNIT 2
- A Application/construction stage documents & correspondence
- 8212270418 Responds to FOIA request for documents re proposed revision &/or update to reactor safety study referred to in NUREG-0784, Chapter 10 as RB II & all documents pertaining to reactor cooling methods Forwards documents listed in app.
FELTON, J M Division of Rules and Records 82/11/26 BRIDLEY, B C Union of Concerned Scientists 3pp 16549:233 24X Fiche 50-000, 82/11/26, 8212270418

DOCKETED ITEMS

--8211050027 Forwards summary of semiscale test results & advises that board notification re test results issued w/o encl
NOVAK, T M Assistant Director for Licensing 82/09/24
Division of Licensing 1p 16549 278 24X Fiche 50-000, 82/11/26,
8212270418

8212080106 Notification of 821216 meeting w/util in Bethesda, MD to discuss util plans for independent design verification program
BURNELL, S B Licensing Branch 1 82/12/01 YOUNGBLOOD, B J
Licensing Branch I 3pp 16368 299 24X Fiche 50-445, 82/12/01,
8212080106

8212160428 Forwards proposed process control program establishing boundary conditions for operation of ATCOR radwaste solidification sys
CLEMENTS, B R Texas Utilities Generating Co 82/12/09 DENTON, H R
Office of Nuclear Reactor Regulation, Director 14pp 16442 132
24X Fiche 50-445, 82/12/09, 8212160428

821220440 Board Notifications 82-125 & 82-125A forwards info re H Etherington evaluation of flow blockage during natural circulation of PHRs Results do not adversely impact present position on reliance on natural circulation
NOVAK, T M Assistant Director for Licensing 82/12/14 Atomic
Safety and Licensing Board Panel 5pp 16523 135 24X
Fiche 50-000, 82/12/14, 821220440

821220461 Board Notification 82-124 forwards RJ Mattson 82123 memo re Semiscale S-UT-B test results Phenomena of core level depression & loop seal clearing may be more complex than previously supposed
NOVAK, T M Assistant Director for Licensing 82/12/14 Atomic
Safety and Licensing Board Panel 7pp 16523 169 24X
Fiche 50-000, 82/12/14, 821220461

E NRC Safety Evaluation Report (SER), suppl's & correspondence

8212170337 Forwards "Human Factors Control Room Design Review of Comanche Peak Steam Electric Station," to resolve SER (NUREG-0797) open issue
GARY, R J Texas Utilities Generating Co 82/12/15 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 16460 001 24X
Fiche 50-445, 82/12/15, 8212170337

--8212170342 "Human Factors Control Room Design Review of Comanche Peak Steam Electric Station"
GARY, R J Texas Utilities Generating Co 82/12/31 510pp
16460 002 24X Fiche 50-445, 82/12/15, 8212170337

F Security, medical, emergency & fire protection plans

8212070403 Responds to 821202 request re Generic Ltr 81-10, "Emergency Operations Facility Survey" Emergency operations facility completed Aug 1982 Protection factor upgraded Equipment will be installed prior to fuel load
SCHMIDT, H C Texas Utilities Services, Inc 82/12/03 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 16336 343 24X
Fiche 50-445, 82/12/03, 8212070403

8212140298 Forwards Revision 2 to security training & qualification plan Revision withheld (ref. 10CFR73.21)
GARY, R J Texas Utilities Generating Co 82/12/06 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 16402 080
24X Fiche 50-445, 82/12/06, 8212140298

G Adjudicatory correspondence

8212090095 Order advising that record will not be closed at present time due to unresolved issues & incomplete analyses Parties directed to file provisional proposed findings on all issues covered in record Admitted Intervenor exhibits listed
MILLER, M E Atomic Safety and Licensing Board Panel 82/12/07
4pp 16357 313 24X Fiche 50-445, 82/12/07, 8212090095

8212140409 Motion for reconsideration of 821207 order establishing schedule for simultaneous filing of proposed findings of fact Applicants bear ultimate burden of proof in proceeding & should be allowed time to respond to proposed findings
REYNOLDS, N S, HORIN, W A Texas Utilities Generating Co
REYNOLDS, N S Debevoise & Liberman 82/12/10 Atomic Safety and Licensing Board Panel 4pp 16403 329 24X Fiche 50-445, 82/12/10,
8212140409

8212230182 Motion to suppl exhibits accepted by 821202 order Encl exhibits constitute new & significant info which should be in record Certificate of BvC encl
ELLIS, J Citizens Association for Sound Energy 82/12/14 Atomic
Safety and Licensing Board Panel 50pp 16510 319 24X
Fiche 50-445, 82/12/14, 8212230182

8212230195 Motion for reconsideration of ASLB 821207 order directing simultaneous filing of proposed findings of fact Since fuel load not expected until Dec 1983, deadline for Walsh/Doyle allegation findings may be extended W/Certificate of BvC
ELLIS, J Citizens Association for Sound Energy 82/12/14 Atomic
Safety and Licensing Board Panel 7pp 16511 021 24X
Fiche 50-445, 82/12/14, 8212230195

8212230353 Reconsideration of 821207 order, extending deadline until 830225 to file provisional proposed findings of fact
MILLER, M E Atomic Safety and Licensing Board Panel 82/12/21
Texas Utilities Generating Co 4pp 16517 129 24X
Fiche 50-445, 82/12/21, 8212230353

8212300009 Brief in opposition to NRC exceptions to ASLB 820930 order denying reconsideration of orders to produce info Affidavit & Certificate of BvC encl
ELLIS, J Citizens Association for Sound Energy 82/12/21 Atomic
Safety and Licensing Board Panel 175pp 16599 036 24X
Fiche 50-445, 82/12/21, 8212300009

8212300045 Affidavit of J Ellis, attesting to truth of statements in Citizens Assoc for Sound Energy brief in opposition to NRC exceptions to ASLB order denying reconsideration of 820930 order
ELLIS, J Citizens Association for Sound Energy 82/12/21 2pp
16598 194 24X Fiche 50-445, 82/12/21, 8212300045

8212270317 Forwards MP Osborne affidavit confirming that value of DNBR remains above limiting value of 1.30 w/o w/o boron injection tank
REYNOLDS, N S Debevoise & Liberman REYNOLDS, N S Texas Utilities
Generating Co 82/12/22 MILLER, M E, MCCOLLOM, K A, COLE, R
Atomic Safety and Licensing Board Panel 2pp 16530 278 24X
Fiche 50-445, 82/12/22, 8212270317

--8212270320 Affidavit of MP Osborne confirming that value of DNBR remains above 1.30 limit for pertinent steam line break analyses w/o boron injection tank
OSBORNE, M P Texas Utilities Generating Co 82/11/29 1p
16530 280 24X Fiche 50-445, 82/12/22, 8212270317

8212270332 Brief in response to NRC 821008 exceptions to ASLB 820930 order denying reconsideration of ASLB 820804 order to show cause ASLB review required to decide if party to proceeding was prejudiced W/Certificate of BvC
REYNOLDS, N S Texas Utilities Generating Co REYNOLDS, N S
Debevoise & Liberman 82/12/22 Atomic Safety and Licensing
Appeal Panel 21pp 16530 016 24X Fiche 50-445, 82/12/22,
8212270332

8212280273 Response in opposition to Citizens Assoc for Sound Energy (CASE) 821214 motion to suppl exhibits Info to be presented in applicant brief should be considered in disposing of CASE instant motion Certificate of BvC encl
REYNOLDS, N S, HORIN, W A Texas Utilities Generating Co
REYNOLDS, N S Debevoise & Liberman 82/12/23 Atomic Safety and
Licensing Board Panel 11pp 16561 232 24X Fiche 50-445, 82/12/23,
8212280273

8212300016 Notifies that oral argument on issues raised by NRC appeal from ASLB 820930 order denying NRC motion for reconsideration of 820804 order will be held on 830119 in Bethesda, MD
SHOENAKER, C J Atomic Safety and Licensing Appeal Panel 82/12/27
YURK, S E Office of the Executive Legal Director ELLIS, J
Citizens Association for Sound Energy REYNOLDS, N S Debevoise &
Liberman 1p 16598 309 24X Fiche 50-445, 82/12/27, 8212300016

K Utility Final Safety Analysis Report (FSAR) & amends

8212130301 Forwards tabled revisions to FSAR, Amend 36
MARSHALL, J S Texas Utilities Services, Inc 82/12/10
BURNELL, S B Division of Licensing 7pp 16389 333 24X
Fiche 50-445, 82/12/10, 8212130301

8212150166 Forwards Amend 36 to FSAR
GARY, R J Texas Utilities Generating Co 82/12/10 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 16428 001
24X Fiche 50-445, 82/12/10, 8212150166

--8212150171 Amend 36 to FSAR
* Texas Utilities Generating Co 82/12/10 88pp 16429 001
24X Fiche 50-445, 82/12/10, 8212150166

8212210391 Forwards Amend 37 to FSAR,
GARY, R J Texas Utilities Generating Co 82/12/17 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 16494 330
24X Fiche 50-445, 82/12/17, 8212210391

--8212210394 Amend 37 to FSAR
 * Texas Utilities Generating Co 82/12/17 187pp 14494 332
 24X Fiche 50-445,82/12/17,8212210391

Q Inspection reports, IE Bulletins & correspondence

8208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BHR Plants " Svc list encl
 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 14462 163 24X Fiche 50-000, 82/10/28, 8208190240

8212010354 Board Notification 82-116 forwards matl re welds in main control panel at sites Licensee has not provided info necessary to resolve item identified in IE Insp Rept 50-445/82-19
 NOVAK, T M Assistant Director for Licensing 82/11/04 Atomic Safety and Licensing Board Panel App 16271 206 24X Fiche 50-445, 82/11/04, 8212010354

8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list encl
 COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000, 82/11/05, 8208190245

8212280329 Responds to IE Bulletin 82-01, Revision 1, Suppl 1, "Alteration of Radiographs of Welds in Piping Subassemblies," All but six welds will meet applicable code requirements
 GARY, R J Texas Utilities Generating Co 82/11/17 COLLINS, J T Region 4, Office of Director 2pp 16560 104 24X Fiche 50-445, 82/11/17, 8212280329

8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl
 JORDAN, E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X Fiche 50-000, 82/11/18, 8208190251

8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list encl
 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000, 82/11/26, 8208190256

8208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl
 COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000, 82/11/30, 8208190257

8208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl
 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259

8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl
 JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462.064 24X Fiche: 50-000, 82/12/03, 8208190261

8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement, 82/12/16 Consolidated Edison Co of New York, Inc 127pp. 16628.191 24X Fiche 50-000, 82/12/16, 8208190267

8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27 " Svc list encl
 JORDAN, E L Division of Engineering & Quality Assurance, 82/12/20 Consolidated Edison Co. of New York, Inc 108pp 16628.293 24X Fiche: 50-000, 82/12/20, 8208190268

8212300121 Forwards QA Program Insp Repts 99900784/82-01 & 99900741/82-01, which impact work at facility, per 821208 SALP meeting Insp repts of NPBI & ITT Grinnell will follow W/o encls
 COLLINS, J T Region 4, Office of Director, 82/12/27 CLEMENTS, D R Texas Utilities Generating Co 1p. 16598 233 24X Fiche 50-445, 82/12/27, 8212300121.

S Reportable occurrences, LERs & related correspondence

8212280267 Interim deficiency rept re linear indications in diesel generator auxiliary skid Initially reported on 820709 Completion of evaluation expected by 840113
 GARY, R J Texas Utilities Generating Co 82/12/16 MADSEN, O L Division of Resident, Reactor Project & Engineering Programs 1p 16561 310 24X Fiche 50-446, 82/12/16, 8212280267

DOCKET STN-50-447 GESSAR-238

A Application/construction stage documents & correspondence

8212150203 Notification of 821213 meeting w/GE in Bethesda, MD to discuss GESSAR-II soil structure interaction
 SCALETTI, D C Standardization & Special Projects Branch 82/12/10 THOMAS, C O Standardization & Special Projects Branch 3pp 16437 347 24X Fiche 50-447, 82/12/10, 8212150203

8212150209 Notification of 821216 meeting w/GE in Bethesda, MD to propose BHR/6 Mark III GESSAR-II seismic event analysis
 SCALETTI, D C Standardization & Special Projects Branch 82/12/10 THOMAS, C O Standardization & Special Projects Branch 3pp 16447 065 24X Fiche 50-447, 82/12/10, 8212150209

8212280510 Notification of location change for 821216 meeting w/GE in Bethesda, MD to propose BHR/6 Mark III GESSAR-II seismic event analysis
 SCALETTI, D C Standardization & Special Projects Branch 82/12/10 THOMAS, C O Standardization & Special Projects Branch 1p 16590 113 24X Fiche 50-447, 82/12/10, 8212280510

8212200041 Summarizes 821214 meeting discussions between NRC & GE re status of GESSAR-II final design approval (FDA) review
 GIFFORD, L S General Electric Co 82/12/15 THOMAS, C Standardization & Special Projects Branch 2pp 16474 264 24X Fiche 50-447, 82/12/15, 8212200041

8212230328 Forwards final draft responses to Radiation Assessment Branch, Effluent Treatment Sys Branch, Auxiliary Sys Branch & Power Sys Branch 820825 info request
 SHERWOOD, O O General Electric Co 82/12/17 EISENHUT, D O Division of Licensing 179pp 16505 193 24X Fiche 50-447, 82/12/17, 8212230328

8212290119 Forwards final draft responses to Commission 821005 info request re GESSAR-II Instrumentation & Control Sys Branch responses will be provided following GE/NRC meeting in Jan 1983
 SHERWOOD, O O General Electric Co 82/12/22 EISENHUT, D O Division of Licensing 169pp 16582 250 24X Fiche 50-447, 82/12/22, 8212290119

8212300196 Requests addl info re review of severe accident portion of GE application for final design approval Responses to encl questions should be provided by 830201
 MIRAOLTA, F J Assistant Director for Safety Assessment 82/12/23 SHERWOOD, O O General Electric Co 27pp 16612 302 24X Fiche 50-447, 82/12/23, 8212300196

D Utility Preliminary Safety Analysis Report, amends

8212130172 Forwards proprietary Amend 10 to GESSAR II re enhanced level instrumentation Amend withheld (ref 10CFR2 790)
 SHERWOOD, O O General Electric Co 82/11/23 EISENHUT, D O Division of Licensing 2pp 16390 114 24X Fiche 50-447, 82/11/23, 8212130172

8212140348 Forwards proprietary portion of Amend 11 to GESSAR-II re PRA Affidavit for withholding only encl
 SHERWOOD, O O General Electric Co 82/12/03 EISENHUT, D O Division of Licensing 8pp 16403 159 24X Fiche 50-447, 82/12/03, 8212140348

8212140449 Forwards nonproprietary Amend 11 to GESSAR II, revising App 15D, Section 3, "PRA of BHR/6 Std Plant " Proprietary version only encl & withheld (ref 10CFR2 790)
 SHERWOOD, O O General Electric Co 82/12/03 EISENHUT, D O Division of Licensing 2pp 16403 212 24X Fiche 50-447, 82/12/03, 8212140449

E NRC Safety Evaluation Report (SER), suppl's & correspondence

8212230301 Forwards response to Mechanical Engineering Branch draft SER questions Remaining responses will be completed by 830114 Amend scheduled for Jan 1983 will formalize responses requiring changes to facility
 SHERWOOD, O O General Electric Co 82/12/17 EISENHUT, D O Division of Licensing 144pp 16508 001 24X Fiche, 50-447, 82/12/17, 8212230301

DOCKETED ITEMS

DOCKET BTN-50-454 BYRON STATION, UNIT 1

A Application/construction stage documents & correspondence

B211290530 Application to amend applications for OL, consisting of Amend 40 to FBAR
 TRAMM, T R Commonwealth Edison Co 82/11/19 DENTON, H R Office
 of Nuclear Reactor Regulation, Director 3pp 16227 348 24X
 Fiche 50-000, 82/11/19, 8211290530

B212070177 Requests withholding of proprietary Westinghouse info inadvertently encl in revisions to App C of FBAR in 820818 & 0902 ltrs re turbine missiles
 TRAMM, T R Commonwealth Edison Co 82/11/29 DENTON, H R Office
 of Nuclear Reactor Regulation, Director 2pp 16329 169 24X
 Fiche 50-000, 82/11/29, 8212070177

--B212070187 Affidavit re Westinghouse application for withholding proprietary info encl in App C to FBAR in TR Tramm 820818 & 0902 ltrs to NRC concerning turbine missiles
 COLLIER, A R Westinghouse Electric Corp 82/11/08 8pp
 16329 171 24X Fiche 50-000, 82/11/29, 8212070177

--B212070198 Forwards nonproprietary version of revised FBAR re protection against possible turbine missiles
 TRAMM, T R Commonwealth Edison Co 82/09/02 DENTON, H R Office
 of Nuclear Reactor Regulation, Director 35pp 16329 179 24X
 Fiche 50-000, 82/11/29, 8212070177

--B212070207 Forwards nonproprietary version of revisions to FBAR re protection against possible turbine missiles
 TRAMM, T R Commonwealth Edison Co 82/08/18 DENTON, H R Office
 of Nuclear Reactor Regulation, Director 70pp 16329 214 24X
 Fiche 50-000, 82/11/29, 8212070177

B212220212 Forwards Revision 22 to CE-1-A, "QA Program for Nuclear Generating Stations"
 SWARTZ, E D Commonwealth Edison Co 82/12/14 HAASS, W P Quality Assurance Branch 1p 16518 007 24X Fiche 50-000, 82/12/14, 8212220212

--B212220231 "QA Program for Nuclear Generating Stations," Revision 22
 * Commonwealth Edison Co CE-1-A R22 82/11/01 17pp
 16518 009 24X Fiche 50-000, 82/12/14, 8212220212

B212280212 Forwards updated schedule for ongoing environ qualification testing programs, per B10328 commitment
 SWARTZ, E D Commonwealth Edison Co 82/12/22 EISENHUT, D O Division of Licensing 18pp 16556 161 24X Fiche 50-000, 82/12/22, 8212280212

E NRC Safety Evaluation Report (SER), suppl & correspondence

B212070249 Clarifies seismic qualification program & pump valve operability program evaluated in SER & reviewed in audit during wk of 820913
 TRAMM, T R Commonwealth Edison Co 82/12/02 DENTON, H R Office
 of Nuclear Reactor Regulation, Director 5pp 16329 323 24X
 Fiche 50-000, 82/12/02, 8212070249

B212300019 Forwards draft SER Suppl 2 for comments & approval. Response expected by 821223 w/o encl
 NOVAK, T M Division of Licensing 82/12/21 ERNST, M Division of Systems Integration (post 811005), JOHNSTON, W Assistant Director for Materials & Qualifications Engineering RUBENSTEIN, L Assistant Director for Core & Plant Systems 2pp 16624 286 24X
 Fiche 50-454, 82/12/21, 8212300019

F Security, medical, emergency & fire protection plans

B212080120 Notification of cancellation of 821207 meeting w/util in Bethesda, MD to discuss fire protection program, specifically, emergency communications sys & sprinklers in cable spreading room
 ULSHAN, L Licensing Branch 1 82/11/10 YOUNGBLOOM, B J Licensing Branch 1 3pp 16368 288 24X Fiche 50-454, 82/11/10, 8212080120

B212080494 Forwards SALP Repts 50-454/82-13 & 50-455/82-09 for Jul 1980-Dec 1981, per IE 820518 mgt meeting. Overall regulatory performance satisfactory although specific areas need to be strengthened
 KEPLER, J O Region 3, Office of Director 82/12/02 REED, C Commonwealth Edison Co 3pp 16352 122 24X Fiche 50-454, 82/12/02, 8212080494

--B212080503 SALP Repts 50-454/82-13 & 50-455/82-09 for Jul 1980-Dec 1981 Procedure control & implementation of QA program require improvements
 * Region 3, Office of Director 82/05/31 27pp 16352 125 24X
 Fiche 50-454, 82/12/02, 8212080494.

B212090383 Forwards info re emergency operations facilities per B21122 & 1202 requests info previously submitted by telcon Request for written response unnecessary burden on licensee
 DELGEORE, L O Commonwealth Edison Co 82/12/03 EISENHUT, D O Division of Licensing 2pp 16365 051 24X Fiche 50-000, 82/12/03, 8212090383

B212130017 Releases public version of Revision 1 to Emergency Plan Implementing Procedure EQ-2, "Pre-Established Onsite & Offsite Monitoring Locations (Maps)"
 FELTON, J M Division of Rules and Records 82/12/07 Document Management Branch 1p 16417 062 24X Fiche 50-000, 82/12/07, 8212130017

--B212130028 Forwards public version of Revision 1 to Emergency Plan Implementing Procedure EQ-2, "Pre-Established Onsite & Offsite Monitoring Locations (Maps)" Revised table of contents encl
 PAJOWSKI, J Commonwealth Edison Co 82/11/01 DENTON, H R NRC - No Detailed Affiliation Given 2pp 16417 063 24X
 Fiche 50-000, 82/12/07, 8212130017

--B212130041 Public version of Revision 1 to Emergency Plan Implementing Procedure EQ-2, "Pre-Established Onsite & Offsite Monitoring Locations (Maps)"
 PAJOWSKI, J E Commonwealth Edison Co 82/11/29 4pp 16417 065 24X Fiche 50-000, 82/12/07, 8212130017

B212140243 Advises of distribution of revisions to "Generating Station Emergency Plan" Braidwood annex not prepared
 TRAMM, T R Commonwealth Edison Co 82/12/07 DENTON, H R Office
 of Nuclear Reactor Regulation, Director 2pp 16409 302 24X
 Fiche 50-000, 82/12/07, 8212140243

B212220306 Discusses layout of communications equipment required in control room, onsite technical support ctr & near-site emergency operations facility
 KEPLER, J O Region 3, Office of Director 82/12/16 Commonwealth Edison Co 3pp 16503 351 24X Fiche 50-000, 82/12/16, 8212220306

B212300167 Releases public version of revised generating station emergency plan telephone directory
 FELTON, J M Division of Rules and Records 82/12/20 Document Management Branch 1p 16612 215 24X Fiche 50-000, 82/12/20, 8212300167

--B212300179 Forwards public version of revised generating station emergency plan telephone directory
 MOORE, R D Commonwealth Edison Co 82/12/02 DENTON, H R Office
 of Nuclear Reactor Regulation, Director 1p 16612 216 24X
 Fiche 50-000, 82/12/20, 8212300167

--B212300199 Public version of revised generating station emergency plan telephone directory
 GALLE, D P Commonwealth Edison Co 82/11/05 60pp 16612 217 24X Fiche 50-000, 82/12/20, 8212300167

B212290247 Forwards corrected Pages 1-5 & 4-2 of Revision 7 to security plan Pages withheld (ref 10CFR73.21)
 DELGEORE, L O Commonwealth Edison Co 82/12/22 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 16592 111 24X
 Fiche 50-454, 82/12/22, 8212290247

G Adjudicatory correspondence

B212060010 Response opposing Rockford League of Women Voters B21112 motion to require NRC answers to Rockford B21022 interrogatories. Answers unnecessary for proper decision
 Certificate of Svc encl
 GOLDBERG, S C Hearing Branch 4 82/12/02 Atomic Safety and Licensing Board Panel 12pp 16313 313 24X Fiche 50-454, 82/12/02, 8212060010

B212070157 Forwards revised Page 3 of NRC B21202 response to Rockford League of Women Voters motion to require interrogatory answers
 GOLDBERG, S C Hearing Branch 4 82/12/06 SMITH, I W, COLE, R F, CALLIHAN, A D Atomic Safety and Licensing Board Panel 1p 16335 316 24X Fiche 50-454, 82/12/06, 8212070157

--B212070161 Revised Page 3 to NRC B21202 response to Rockford League of Women Voters motion to require interrogatory answers
 Citation corrected
 * Office of the Executive Legal Director 82/12/06 Atomic Safety and Licensing Board Panel 1p 16335 317 24X
 Fiche 50-454, 82/12/06, 8212070157

Q12080235 Motion for entry of order approving B21206 stipulation re litigation of contentions
GOLDBERG, S Hearing Branch 4 BIEWALSKI, A Commonwealth Edison Co
* League of Women Voters of Rockford, IL 82/12/06 Atomic
Safety and Licensing Board Panel 1p 16354 127 24X
Fiche 50-454, 82/12/06, B212080235

--B212080245 Stipulation re litigation of contentions Contentions 28, 32, 34, 41, 47, 53, 54, 61, 63, 71 & 77 withdrawn Contentions 8, 19, 22, 39, 42, 62, 106, 108, 109, 112 & portions of 111 will be litigated
GOLDBERG, S Hearing Branch 4 BIEWALSKI, A Commonwealth Edison Co
* League of Women Voters of Rockford, IL 82/12/06 9pp
16354 128 24X Fiche 50-454, 82/12/06, B212080235

B212090231 Response opposing DeKalb Area Alliance for Responsible Energy/Sinnissippi Alliance for Environ B21118 motion to direct NRC to commence special insp ASLB lacks authority to supervise regional investigation, or dictate pace
GOLDBERG, S C Hearing Branch 4 82/12/08 Atomic Safety and Licensing Board Panel 3pp 16361 322 24X Fiche 50-454, 82/12/08, B212090231

--B212090236 Affidavit of DW Hayes providing status of Region 3 special insp on allegations re GA/QC Certificate of Svc encl
HAYES, D W Division of Project & Resident Programs 82/12/07 8pp 16361 325 24X Fiche 50-454, 82/12/08, B212090231

B212200102 Memorandum & order denying DeKalb Area Alliance for Responsible Energy/Sinnissippi Alliance for Environ B21118 motion to direct NRC to commence special investigation into allegations on GA/QC ASLB lacks requisite authority
SMITH, I W Atomic Safety and Licensing Board Panel 82/12/16 DeKalb Area Alliance for Responsible Energy 1p 16470 148 24X Fiche 50-454, 82/12/16, B212200102

B212200107 Memorandum & order approving joint party B21206 stipulation on procedural problems, w/one listed revision
COLE, R F, SMITH, I W Atomic Safety and Licensing Board Panel 82/12/16 2pp 16470 094 24X Fiche 50-454, 82/12/16, B212200107

B212200113 Supplemental response to Rockford League of Women Voters proposed interrogatories to NRC Certificate of Svc encl
RAMSON, R J Hearing Branch 4 82/12/17 League of Women Voters of Rockford, IL 12pp 16470 164 24X Fiche 50-454, 82/12/17, B212200113

B21220188 Answers to NRC second set of interrogatories re Contention 1A Certificate of Svc encl Related correspondence
MORRISON, P League of Women Voters of Rockford, IL 82/12/22 Office of the Executive Legal Director 5pp 16562 268 24X Fiche 50-454, 82/12/22, B21220188

H General correspondence

B21220176 Notices of change in mailing address for NRC licensing matl
WRIGHT, G N Illinois, State of, Dept Nuc Safety (formerly Dept Public Health) 82/12/20 EISENHUT, D O Division of Licensing 1p 16556 135 24X Fiche 50-000, 82/12/20, B21220176

K Utility Final Safety Analysis Report (FSAR) & amends

B211290530 Application to amend applications for OL, consisting of Amend 40 to FSAR
TRAHM, T R Commonwealth Edison Co 82/11/19 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 16227 348 24X Fiche 50-000, 82/11/19, B211290530

--B211290559 Amend 40 to FSAR
* Commonwealth Edison Co 82/11/30 234pp 16227 351 24X Fiche 50-000, 82/11/19, B211290530

G12280306 Forwards Affidavit of Svc re distribution of FSAR Amend 40 per RS Boyd 781020 ltr to C Reed
TRAHM, T R Commonwealth Edison Co 82/12/17 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 16561 095 24X Fiche 50-000, 82/12/17, B212280306

Q Inspection reports, IE Bulletins & correspondence

B208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, B208190240

B208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/09 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000, 82/11/09, B208190245

B208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 179 24X Fiche 50-000, 82/11/18, B208190251

B212100296 Forwards IE Insp Repts 50-454/82-22 & 50-455/82-16 on 820901-1031 & notice of violation
SPESSARD, R L Division of Project & Resident Programs 82/11/23 REED, C Commonwealth Edison Co 2pp 16376 281 24X Fiche 50-454, 82/11/23, B212100296

--B212100302 Notice of violation from insp on 820901-1031
SPESSARD, R L Division of Project & Resident Programs 82/11/23 5pp 16376 283 24X Fiche 50-454, 82/11/23, B212100296

--B212100308 IE Insp Repts 50-454/82-22 & 50-455/82-16 on 820901-1031 Noncompliance noted installation of wireplate incomplete, failure to determine impact of deficiency on testing & care of safety equipment & QC insps not performed
FORNEY, W L, CONNAUGHTON, K, HAYES, D W Division of Project & Resident Programs 82/11/19 11pp 16376 288 24X Fiche 50-454, 82/11/23, B212100296

B208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411.065 24X Fiche 50-000, 82/11/26, B208190256

B208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000, 82/11/30, B208190257

B212080494 Forwards SALP Repts 50-454/82-13 & 50-455/82-09 for Jul 1980-Dec 1981, per IE 820518 mtg meeting Overall regulatory performance satisfactory although specific areas need to be strengthened
KEPPLER, J O Region 3, Office of Director 82/12/02 REED, C Commonwealth Edison Co 3pp 16392 122 24X Fiche 50-454, 82/12/02, B212080494

--B212080503 SALP Repts 50-454/82-13 & 50-455/82-09 for Jul 1980-Dec 1981 Procedure control & implementation of GA program require improvements
* Region 3, Office of Director 82/05/31 27pp 16392 125 24X Fiche 50-454, 82/12/02, B212080494

B212170106 Forwards IE Insp Rept 50-454/82-21 on B21006-29 No noncompliance noted
LITTLE, W S Division of Engineering & Technical Programs 82/12/02 REED, C Commonwealth Edison Co 2pp 16450 311 24X Fiche 50-454, 82/12/02, B212170106

--B212170118 IE Insp Rept 50-454/82-21 on B21006-29 No noncompliance noted Major areas inspected preoperational testing & test results evaluation, previous open items & test program implementation
RING, M A, JACKIN, I N Region 3, Office of Director 82/11/24 6pp 16450.313 24X Fiche 50-454, 82/12/02, B212170106

B208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317. 24X Fiche 50-000, 82/12/03, B208190259

B208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Buckets " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064. 24X Fiche 50-000, 82/12/03, B208190261

B212100324 Ack receipt of B21018 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-454/82-12
NORRIS, C E Division of Engineering & Technical Programs 82/12/07 REED, C, Commonwealth Edison Co 2pp 16377 070. 24X Fiche 50-454, 82/12/07, B212100324

DOCKETED ITEMS

--B212100330 Responds to NRC B20910 ltr re violations noted in IE Insp Rept 50-454/82-12 Corrective actions administrative procedures revised to include use of new form for communicating test problems.
DELOEORGE, L O Commonwealth Edison Co 82/10/18 KEPLER, J O Region 3, Office of Director 5pp 16377 092 24X
Fiche 50-454, 82/12/07, B212100334

B208190267 IE Info Notice B2-49, "Correction for Sample Conditions for Air & Gas Monitoring." Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16428 191 24X Fiche 50-000, 82/12/16, B208190267

B208190268 IE Info Notice B2-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27." Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16428 293 24X
Fiche 50-000, 82/12/20, B208190268

B212280433 Ack receipt of B21105 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-454/82-05 & 50-455/82-04
NORELIUS, C E Division of Engineering & Technical Programs 82/12/21 REED, C Commonwealth Edison Co 2pp 16556 061 24X
Fiche 50-454, 82/12/21, B212280433

--B212280448 Suppls B20817 & 0922 responses to NRC B20624 ltr re violations noted in IE Insp Repts 50-454/82-05 & 50-455/82-04 Corrective actions training/qualification records of QC inspectors will be reviewed
STIEDE, W L Commonwealth Edison Co 82/11/05 KEPLER, J O Region 3, Office of Director 3pp 16556 063 24X
Fiche 50-454, 82/12/21, B212280433

S Reportable occurrences, LERs & related correspondence

B212020329 Interim Deficiency Rept B2-08 re unavailable insp records for high strength bolt connections of structural steel bolting initially reported B21021 Reinsp planned final rept expected by B30115
TRAMM, T R Commonwealth Edison Co 82/11/24 KEPLER, J O Region 3, Office of Director 2pp 16277 277 24X Fiche 50-454, 82/11/24, B212020329

B212170192 Interim deficiency rept re failure of several dc cables in underground duct initially reported on B20916 Circuits utilizing faulted cables rerouted so that cables can be pulled for insp final rept will be provided by B30401
TRAMM, T R Commonwealth Edison Co 82/12/06 KEPLER, J O Region 3, Office of Director 2pp 16450 006 24X Fiche 50-454, 82/12/06, B212170192

DOCKET STN-50-455 BYRON STATION, UNIT 2

A Application/construction stage documents & correspondence

B211290530 Application to amend applications for OL, consisting of Amend 40 to FSAR
TRAMM, T R Commonwealth Edison Co 82/11/19 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 16227 348 24X
Fiche 50-000, 82/11/19, B211290530

B212070177 Requests withholding of proprietary Westinghouse info inadvertently encl in revisions to App C of FSAR in B20818 & 0902 ltrs re turbine missiles.
TRAMM, T R Commonwealth Edison Co 82/11/29 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 16329 169 24X
Fiche 50-000, 82/11/29, B212070177.

--B212070187 Affidavit re Westinghouse application for withholding proprietary info encl in App C to FSAR in TR Tramm B20818 & 0902 ltr to NRC concerning turbine missiles
COLLIER, A R Westinghouse Electric Corp. 82/11/08 8pp 16329 171 24X Fiche 50-000, 82/11/29, B212070177.

--B212070198 Forwards nonproprietary version of revised FSAR re protection against possible turbine missiles
TRAMM, T R Commonwealth Edison Co 82/09/02, DENTON, H R Office of Nuclear Reactor Regulation, Director 35pp, 16329 179 24X
Fiche 50-000, 82/11/29, B212070177.

--B212070207 Forwards nonproprietary version of revisions to FSAR re protection against possible turbine missiles
TRAMM, T R Commonwealth Edison Co 82/08/18, DENTON, H R Office of Nuclear Reactor Regulation, Director 70pp 16329 214 24X
Fiche 50-000, 82/11/29, B212070177.

B212220212 Forwards Revision 22 to CE-1-A, "QA Program for Nuclear Generating Stations."
SWARTZ, E D Commonwealth Edison Co 82/12/14 HAASB, W P Quality Assurance Branch 1p 16318 007 24X Fiche 50-000, 82/12/14, B212220212

--B212220231 "QA Program for Nuclear Generating Stations," Revision 22 * Commonwealth Edison Co CE-1-A R22 82/11/01 17pp 16318 009 24X Fiche 50-000, 82/12/14, B212220212

B212280212 Forwards updated schedule for ongoing environ qualification testing programs per B10528 commitment
SWARTZ, E D Commonwealth Edison Co 82/12/22 EISENHUT, D O Division of Licensing 18pp 16356 161 24X Fiche 50-000, 82/12/22, B212280212

E NRC Safety Evaluation Report (SER), suppls & correspondence

B212070249 Clarifies seismic qualification program & pump valve operability program evaluated in SER & reviewed in audit during wk of B20913
TRAMM, T R Commonwealth Edison Co 82/12/02 DENTON, H R Office of Nuclear Reactor Regulation, Director 5pp 16329 323 24X
Fiche 50-000, 82/12/02, B212070249

B212300019 Forwards draft SER Suppl 2 for comments & approval Response expected by B21223 W/o encl
NOVAK, T M Division of Licensing 82/12/21 ERNST, M Division of Systems Integration (post B11003) JOHNSTON, W Assistant Director for Materials & Qualifications Engineering RUBENSTEIN, L Assistant Director for Core & Plant Systems 2pp 16624 286 24X
Fiche 50-454, 82/12/21, B212300019

F Security, medical, emergency & fire protection plans

B212080120 Notification of cancellation of B21207 meeting w/util in Bethesda, MD to discuss fire protection program specifically, emergency communications sys & sprinklers in cable spreading room
OLSHAN, L Licensing Branch 1 82/11/10 YOUNGBLOOD, D J Licensing Branch 1 3pp 16368 288 24X Fiche 50-454, 82/11/10, B212080120

B212080494 Forwards BALP Repts 50-454/82-13 & 50-455/82-09 for Jul 1980-Dec 1981, per IE B20318 mgt meeting Overall regulatory performance satisfactory although specific areas need to be strengthened
KEPLER, J O Region 3, Office of Director 82/12/02 REED, C Commonwealth Edison Co 3pp 16352 122 24X Fiche 50-454, 82/12/02, B212080494

--B212080503 BALP Repts 50-454/82-13 & 50-455/82-09 for Jul 1980-Dec 1981 Procedure control & implementation of QA program require improvements
* Region 3, Office of Director 82/05/31 27pp 16352 125 24X
Fiche 50-454, 82/12/02, B212080494

B212090383 Forwards info re emergency operations facilities per B21122 & 1202 requests info previously submitted by telcon Request for written response unnecessary burden on licensee
DELOEORGE, L O Commonwealth Edison Co 82/12/03 EISENHUT, D O Division of Licensing 2pp 16365 051 24X Fiche 50-000, 82/12/03, B212090383

B212130017 Releases public version of Revision 1 to Emergency Plan Implementing Procedure EQ-2, "Pre-Established Onsite & Offsite Monitoring Locations (Maps)"
FELTON, J M Division of Rules and Records 82/12/07 Document Management Branch 1p, 16417 062 24X Fiche 50-000, 82/12/07, B212130017

--B212130028 Forwards public version of Revision 1 to Emergency Plan Implementing Procedure EQ-2, "Pre-Established Onsite & Offsite Monitoring Locations (Maps)" Revised table of contents encl
PAJOWSKI, J E Commonwealth Edison Co 82/11/01 DENTON, H R NRC - No Detailed Affiliation Given 2pp 16417 063 24X
Fiche 50-000, 82/12/07, B212130017

--B212130041 Public version of Revision 1 to Emergency Plan Implementing Procedure EQ-2, "Pre-Established Onsite & Offsite Monitoring Locations (Maps)"
PAJOWSKI, J E Commonwealth Edison Co 82/11/29 4pp 16417 065 24X Fiche 50-000, 82/12/07, B212130017

B212140243 Advises of distribution of revisions to "Generating Station Emergency Plan." Braidwood annex not prepared
TRAMM, T R Commonwealth Edison Co 82/12/07 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 16409 302 24X
Fiche 50-000, 82/12/07, B212140243

821220306 Discusses layout of communications equipment required in control room, onsite technical support ctr & near-site emergency operations facility
KEPPLER, J G Region 3, Office of Director 82/12/16
Commonwealth Edison Co 3pp 16503 351 24X Fiche 50-000, 82/12/16, 821220306

8212300167 Releases public version of revised generating station emergency plan telephone directory
FELTON, J M Division of Rules and Records 82/12/20 Document Management Branch 1p 16612 215 24X Fiche 50-000, 82/12/20, 8212300167

--8212300179 Forwards public version of revised generating station emergency plan telephone directory
MOORE, R D Commonwealth Edison Co 82/12/02 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 16612 216 24X Fiche 50-000, 82/12/20, 8212300167

--8212300197 Public version of revised generating station emergency plan telephone directory
GALLE, D P Commonwealth Edison Co 82/11/03 60pp 16612 217 24X Fiche 50-000, 82/12/20, 8212300167

8212290247 Forwards corrected Pages 1-5 & 4-2 of Revision 7 to security plan Pages withheld (ref 10CRF73 21)
DELGEORGE, L O Commonwealth Edison Co 82/12/22 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 16582 111 24X Fiche 50-454, 82/12/22, 8212290247

4 Adjudicatory correspondence

8212060010 Response opposing Rockford League of Women Voters 821112 motion to require NRC answers to Rockford 821022 interrogatories. Answers unnecessary for proper decision Certificate of Svc encl
GOLDBERG, S C Hearing Branch 4 82/12/02 Atomic Safety and Licensing Board Panel 12pp 16313 313 24X Fiche 50-454, 82/12/02, 8212060010

8212070157 Forwards revised Page 3 of NRC 821202 response to Rockford League of Women Voters motion to require interrogatory answers
GOLDBERG, S C Hearing Branch 4 82/12/06 SMITH, I W, COLE, R F, CALLIHAN, A D Atomic Safety and Licensing Board Panel 1p 16335 316 24X Fiche 50-454, 82/12/06, 8212070157

--8212070161 Revised Page 3 to NRC 821202 response to Rockford League of Women Voters motion to require interrogatory answers
Citation corrected
* Office of the Executive Legal Director 82/12/06 Atomic Safety and Licensing Board Panel 1p 16335 317 24X Fiche 50-454, 82/12/06, 8212070157

8212080235 Motion for entry of order approving 821206 stipulation re litigation of contentions
GOLDBERG, S C Hearing Branch 4 BIEHALSKI, A Commonwealth Edison Co * League of Women Voters of Rockford, IL 82/12/06 Atomic Safety and Licensing Board Panel 1p 16354 127 24X Fiche 50-454, 82/12/06, 8212080235

--8212080245 Stipulation re litigation of contentions Contentions 28, 32, 34, 41, 47, 53, 54, 61, 63, 71 & 77 withdrawn Contentions 8, 19, 22, 39, 42, 62, 106, 108, 109, 112 & portions of 111 will be litigated
GOLDBERG, S C Hearing Branch 4 BIEHALSKI, A Commonwealth Edison Co * League of Women Voters of Rockford, IL 82/12/06 9pp 16354 128 24X Fiche 50-454, 82/12/06, 8212080235

8212090231 Response opposing Dekalb Area Alliance for Responsible Energy/Sinnissippi Alliance for Environ 821118 motion to direct NRC to commence special insp ASLB lacks authority to supervise regional investigation, or dictate pace
GOLDBERG, S C Hearing Branch 4 82/12/08 Atomic Safety and Licensing Board Panel 3pp 16361 322 24X Fiche 50-454, 82/12/08, 8212090231

--8212090236 Affidavit of DW Hayes providing status of Region 3 special insp on allegations re QA/QC Certificate of Svc encl
HAYES, D W Division of Project & Resident Programs 82/12/07 8pp 16361 325 24X Fiche 50-454, 82/12/08, 8212090231

8212200102 Memorandum & order denying Dekalb Area Alliance for Responsible Energy/Sinnissippi Alliance for Environ 821118 motion to direct NRC to commence special investigation into allegations on QA/QC ASLB lacks requisite authority
SMITH, I W Atomic Safety and Licensing Board Panel 82/12/16 Dekalb Area Alliance for Responsible Energy 1p 16470 148 24X Fiche 50-454, 82/12/16, 8212200102

8212200107 Memorandum & order approving joint party 821206 stipulation on procedural problems, w/one listed revision
COLE, R F, SMITH, I W Atomic Safety and Licensing Board Panel 82/12/16 2pp 16470 094 24X Fiche 50-454, 82/12/16, 8212200107

8212200113 Supplemental response to Rockford League of Women Voters proposed interrogatories to NRC Certificate of Svc encl
RAMSON, R J Hearing Branch 4 82/12/17 League of Women Voters of Rockford, IL 12pp 16470 164 24X Fiche 50-454, 82/12/17, 8212200113

8212280188 Answers to NRC second set of interrogatories re Contention 1A Certificate of Svc encl Related correspondence
MORRISON, P League of Women Voters of Rockford, IL 82/12/22 Office of the Executive Legal Director 3pp 16562 268 24X Fiche 50-454, 82/12/22, 8212280188

H General correspondence

8212280176 Notices of change in mailing address for NRC licensing mail
WRIGHT, O N Illinois, State of, Dept Nuc Safety (formerly Dept Public Health), 82/12/20 EISENHUT, D O Division of Licensing 1p 16556 135 24X Fiche 50-000, 82/12/20, 8212280176

K Utility Final Safety Analysis Report (FSAR) & amends

8212290530 Application to amend applications for DL, consisting of Amend 40 to FSAR
TRAMM, T R Commonwealth Edison Co 82/11/19 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 16227 348 24X Fiche 50-000, 82/11/19, 8212290530

--8212290559 Amend 40 to FSAR
* Commonwealth Edison Co 82/11/30 234pp 16227 351 24X Fiche 50-000, 82/11/19, 8212290530

8212280306 Forwards Affidavit of Svc re distribution of FSAR Amend 40 per RS Boyd 781020 ltr to C Reed
TRAMM, T R Commonwealth Edison Co 82/12/17 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 16561 095 24X Fiche 50-000, 82/12/17, 8212280306

Q Inspection reports, IE Bulletins & correspondence

8208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Svc list encl
DEVOUNO, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240

8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000, 82/11/05, 8208190245

8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X Fiche 50-000, 82/11/18, 8208190251

8212100296 Forwards IE Insp Repts 50-454/82-22 & 50-455/82-16 on 820901-1031 & notice of violation
SPESSARD, R L Division of Project & Resident Programs 82/11/23 REED, C Commonwealth Edison Co 2pp 16376 281 24X Fiche 50-454, 82/11/23, 8212100296

--8212100302 Notice of violation from insp on 820901-1031
SPESSARD, R L Division of Project & Resident Programs 82/11/23 5pp 16376, 283 24X Fiche 50-454, 82/11/23, 8212100296

--8212100308 IE Insp Repts 50-454/82-22 & 50-455/82-16 on 820901-1031 Noncompliance noted: installation of wireplate incomplete, failure to determine impact of deficiency on testing & care of safety equipment & QC insps not performed
FORNEY, W L, CONNAUGHTON, K, HAYES, D W Division of Project & Resident Programs 82/11/19 11pp 16376 288 24X Fiche 50-454, 82/11/23, 8212100296

8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list encl
DEVOUNO, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000, 82/11/26, 8208190256

DOCKETED ITEMS

8208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl." Svc list encl
 QDBB, L I Division of Fuel Facilities, Materials & Safeguards
 82/11/30 Consolidated Edison Co. of New York, Inc 356pp
 16387 028 24X Fiche 50-000, 82/11/30, 8208190257

8212080494 Forwards SALP Repts 50-454/82-13 & 50-455/82-09 for Jul 1980-Dec 1981, per IE 820518 mgt meeting Overall regulatory performance satisfactory although specific areas need to be strengthened
 KEPLER, J O Region 3, Office of Director 82/12/02 REED, C
 Commonwealth Edison Co 3pp 16352 122 24X Fiche 50-454, 82/12/02, 8212080494

--8212080503 SALP Repts 50-454/82-13 & 50-455/82-09 for Jul 1980-Dec 1981 Procedure control & implementation of QA program require improvements
 * Region 3, Office of Director 82/05/31 27pp 16352 125 24X
 Fiche 50-454, 82/12/02, 8212080494

8208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies." Svc list encl
 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co. of New York, Inc
 113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259

8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Buckets." Svc list encl
 JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co. of New York, Inc 110pp 16462 064 24X
 Fiche 50-000, 82/12/03, 8208190261

8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring." Svc list encl
 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co. of New York, Inc
 127pp 16628 191 24X Fiche 50-000, 82/12/16, 8208190267

8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITC-27." Svc list encl
 JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co. of New York, Inc 108pp 16628 293 24X
 Fiche 50-000, 82/12/20, 8208190268

8212280433 Ack receipt of 821105 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-454/82-05 & 50-455/82-04
 NORELUS, C E Division of Engineering & Technical Programs 82/12/21 REED, C Commonwealth Edison Co 2pp 16556 061 24X
 Fiche 50-454, 82/12/21, 8212280433

--8212280448 Suppls 820817 & 0922 responses to NRC 820624 ltr re violations noted in IE Insp Repts 50-454/82-05 & 50-455/82-04 Corrective actions training/qualification records of QC inspectors will be reviewed
 STIEDE, W L Commonwealth Edison Co 82/11/05 KEPLER, J O
 Region 3, Office of Director 3pp 16556 063 24X
 Fiche 50-454, 82/12/21, 8212280433

B Reportable occurrences, LERs & related correspondence

8212020329 Interim Deficiency Rept 82-08 re unavailable insp records for high strength bolt connections of structural steel bolting Initially reported 821021 Reinsp planned Final rept expected by 830115
 TRAMM, T R Commonwealth Edison Co 82/11/24 KEPLER, J O Region 3, Office of Director 2pp 16277 277 24X Fiche 50-454, 82/11/24, 8212020329

8212170192 Interim deficiency rept re failure of several dc cables in underground duct Initially reported on 820916 Circuits utilizing faulted cables rerouted so that cables can be pulled for insp Final rept will be provided by 830401
 TRAMM, T R Commonwealth Edison Co 82/12/06 KEPLER, J O Region 3, Office of Director 2pp 16450 006 24X Fiche 50-454, 82/12/06, 8212170192

DOCKET STN-50-456 BRAIDWOOD STATION, UNIT 1

A Application/construction stage documents & correspondence

8212010014 Forwards order extending const completion dates for CPPR-132 from 821101 to 870430 & CPPR-133 from 831101 to 880430, in response to 820930 ltr Safety evaluation also encl
 EISENHUT, D O Division of Licensing 82/11/15 DELGEOERGE, L O
 Commonwealth Edison Co 2pp 16290 208 24X Fiche 50-456, 82/11/15, 8212010014

--8212010017 Order extending const completion date for CPPR-132 from 821101 to 870430 & CPPR-133 from 831101 to 880430
 EISENHUT, D O Division of Licensing 82/11/15 Commonwealth Edison Co 3pp 16290 210 24X Fiche 50-456, 82/11/15, 8212010014

--8212010020 Safety evaluation supporting extension of const completion dates for CPPR-132 & CPPR-133 to 870430 & 880430, respectively
 OLSHAN, L, YOUNGBLOOD, B J Licensing Branch 1 82/11/08 4pp
 16290 213 24X Fiche 50-456, 82/11/15, 8212010014

821290530 Application to amend applications for OL, consisting of Amend 40 to FSAR
 TRAMM, T R Commonwealth Edison Co 82/11/19 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 16227 348 24X
 Fiche 50-000, 82/11/19, 821290530

8212070177 Requests withholding of proprietary Westinghouse info inadvertently encl in revisions to App C of FSAR in 820818 & 0902 ltrs re turbine missiles
 TRAMM, T R Commonwealth Edison Co 82/11/29 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 16329 169 24X
 Fiche 50-000, 82/11/29, 8212070177

--8212070187 Affidavit re Westinghouse application for withholding proprietary info encl in App C to FSAR in TR Tramm 820818 & 0902 ltrs to NRC concerning turbine missiles
 COLLIER, A R Westinghouse Electric Corp 82/11/08 8pp
 16329 171 24X Fiche 50-000, 82/11/29, 8212070177

--8212070198 Forwards nonproprietary version of revised FSAR re protection against possible turbine missiles
 TRAMM, T R Commonwealth Edison Co 82/09/02 DENTON, H R Office of Nuclear Reactor Regulation, Director 35pp 16629 179 24X
 Fiche 50-000, 82/11/29, 8212070177

--8212070207 Forwards nonproprietary version of revisions to FSAR re protection against possible turbine missiles
 TRAMM, T R Commonwealth Edison Co 82/08/18 DENTON, H R Office of Nuclear Reactor Regulation, Director 70pp 16329 214 24X
 Fiche 50-000, 82/11/29, 8212070177

8212220212 Forwards Revision 22 to CE-1-A, "QA Program for Nuclear Generating Stations"
 SWARTZ, E D Commonwealth Edison Co 82/12/14 HAASS, W P Quality Assurance Branch 1p 16518 007 24X Fiche 50-000, 82/12/14, 8212220212

--8212220231 "QA Program for Nuclear Generating Stations," Revision 2
 * Commonwealth Edison Co CE-1-A R22 82/11/01 17pp
 16518 009 24X Fiche 50-000, 82/12/14, 8212220212

8212280212 Forwards updated schedule for ongoing environ qualification testing programs, per 810528 commitment
 SWARTZ, E D Commonwealth Edison Co 82/12/22 EISENHUT, D O
 Division of Licensing 18pp 16556 161 24X Fiche 50-000, 82/12/22, 8212280212

E NRC Safety Evaluation Report (SER), suppls & correspondence

8212070249 Clarifies seismic qualification program & pump valve operability program evaluated in SER & reviewed in audit during wk of 820913
 TRAMM, T R Commonwealth Edison Co 82/12/02 DENTON, H R Office of Nuclear Reactor Regulation, Director 5pp 16329 323 24X
 Fiche 50-000, 82/12/02, 8212070249

F Security, medical, emergency & fire protection plans

8212090383 Forwards info re emergency operations facilities per 821122 & 1202 requests, info previously submitted by telcon Request for written response unnecessary burden on licensee
 DELGEOERGE, L O Commonwealth Edison Co 82/12/03 EISENHUT, D O
 Division of Licensing 2pp 16363 051 24X Fiche 50-000, 82/12/03, 8212090383

8212130017 Releases public version of Revision 1 to Emergency Plan Implementing Procedure EQ-2, "Pre-Established Onsite & Offsite Monitoring Locations (Maps)"
 FELTON, J M Division of Rules and Records 82/12/07 Document Management Branch 1p 16417 062 24X Fiche 50-000, 82/12/07, 8212130017

--8212130028 Forwards public version of Revision 1 to Emergency Plan Implementing Procedure EQ-2, "Pre-Established Onsite & Offsite Monitoring Locations (Maps)" Revised table of contents encl
 PAJCHSKI, J Commonwealth Edison Co 82/11/01 DENTON, H R NRC - No Detailed Affiliation Given 2pp 16417 063 24X
 Fiche: 50-000, 82/12/07, 8212130017

--B212130041 Public version of Revision 1 to Emergency Plan Implementing Procedure EQ-2, "Pre-Established Onsite & Offsite Monitoring Locations (Maps)"
PAJQWSKI, J E Commonwealth Edison Co 82/11/29 4pp 16417 065
24X Fiche 50-000, 82/12/07, 8212130017

B212140243 Advises of distribution of revisions to "Generating Station Emergency Plan " Braidwood annex not prepared
TRAHM, T R Commonwealth Edison Co 82/12/07 DENTON, H R Office
of Nuclear Reactor Regulation, Director 2pp 16409 302 24X
Fiche 50-000, 82/12/07, 8212140243

B21220306 Discusses layout of communications equipment required in central room, onsite technical support ctr & near-site emergency operations facility
KEPPLER, J O Region 3, Office of Director 82/12/16
Commonwealth Edison Co 3pp 16503 351 24X Fiche 50-000, 82/12/16, 821220306

H General correspondence

B212280176 Notifies of change in mailing address for NRC licensing mail
WRIGHT, Q N Illinois, State of, Dept Nuc Safety (formerly Dept Public Health) 82/12/20 EISENHUT, D O Division of Licensing
1p 16556 135. 24X Fiche 50-000, 82/12/20, 8212280176

K Utility Final Safety Analysis Report (FSAR) & amends

B211290530 Application to amend applications for DL, consisting of Amend 40 to FSAR
TRAHM, T R Commonwealth Edison Co 82/11/19 DENTON, H R Office
of Nuclear Reactor Regulation, Director 3pp 16227 348 24X
Fiche 50-000, 82/11/19, 8211290530

--B211290559 Amend 40 to FSAR
* Commonwealth Edison Co 82/11/30 234pp 16227 351. 24X
Fiche 50-000, 82/11/19, 8211290530

B212280306 Forwards Affidavit of Svc re distribution of FSAR Amend 40 per RS Boyd 781020 ltr to C Reed
TRAHM, T R Commonwealth Edison Co 82/12/17 DENTON, H R Office
of Nuclear Reactor Regulation, Director 2pp 16561 095 24X
Fiche 50-000, 82/12/17, 8212280306

G Inspection reports, IE Bulletins & correspondence

B2108190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Svc list encl
BEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc
112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240

B208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp
16372 142 24X Fiche 50-000, 82/11/05, 8208190245

B2108190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X
Fiche 50-000, 82/11/18, 8208190251

B208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list encl
BEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc.
127pp 16411 065 24X Fiche 50-000, 82/11/26, 8208190256

B2108190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/20 Consolidated Edison Co of New York, Inc. 356pp
16387 028 24X Fiche 50-000, 82/11/30, 8208190257

B2108190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl
BEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc.
113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259

B2108190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16442 064 24X
Fiche 50-000, 82/12/03, 8208190261.

B212270275 Forwards IE Insp Rept 50-456/82-06 on 82102-22 & 26-27 & notice of violation
NORELIUS, C E Division of Engineering & Technical Programs 82/12/10 REED, C Commonwealth Edison Co 2pp 16530 069 24X
Fiche 50-456, 82/12/10, 8212270275

--B212270308 Notice of violation from insp on 821021-22 & 26-27
NORELIUS, C E Division of Engineering & Technical Programs 82/12/10 3pp 16530 071 24X Fiche 50-456, 82/12/10, 8212270275

--B212270318 IE Insp Rept 50-456/82-06 on 821021-22 & 26-27 Noncompliance noted failure to translate design criterion into Tech Specs, power cable insp not adequately performed & nonconforming components not controlled or identified
MENDEZ, R, NAIDUK, K, WILLIAMS, C C Region 3, Office of Director 82/12/03 9pp 16530 076 24X Fiche 50-456, 82/12/10, 8212270275

B208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
BEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc
127pp 16628 191 24X Fiche 50-000, 82/12/16, 8208190267.

B208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27 " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X
Fiche 50-000, 82/12/20, 8208190268

DOCKET SYN-50-457 BRAIDWOOD STATION, UNIT 2

A Application/construction stage documents & correspondence

B212010014 Forwards order extending const completion dates for CPPR-132 from 821101 to 870430 & CPPR-133 from 831101 to 880430, in response to 820930 ltr Safety evaluation also encl
EISENHUT, D O Division of Licensing 82/11/15 DELGEOERGE, L O Commonwealth Edison Co 2pp 16290 208 24X Fiche 50-456, 82/11/15, 8212010014

--B212010017 Order extending const completion date for CPPR-132 from 821101 to 870430 & CPPR-133 from 831101 to 880430
EISENHUT, D O Division of Licensing 82/11/15 Commonwealth Edison Co 3pp 16290 210 24X Fiche 50-456, 82/11/15, 8212010014

--B212010020 Safety evaluation supporting extension of const completion dates for CPPR-132 & CPPR-133 to 870430 & 880430, respectively
OLSHAN, L, YOUNGBLOOD, B J Licensing Branch 1, 82/11/08 4pp
16290 213 24X Fiche 50-456, 82/11/15, 8212010014

B21290530 Application to amend applications for DL, consisting of Amend 40 to FSAR
TRAHM, T R Commonwealth Edison Co 82/11/19 DENTON, H R Office
of Nuclear Reactor Regulation, Director 3pp 16227 348 24X
Fiche 50-000, 82/11/19, 8211290530.

B212070177 Requests withholding of proprietary Westinghouse info inadvertently encl in revisions to App C of FSAR in 820818 & 0902 ltrs re turbine missiles
TRAHM, T R Commonwealth Edison Co 82/11/29 DENTON, H R Office
of Nuclear Reactor Regulation, Director 2pp 16329 169 24X
Fiche 50-000, 82/11/29, 8212070177

--B212070187 Affidavit re Westinghouse application for withholding proprietary info encl in App C to FSAR & in TR Tramm 820818 & 0902 ltrs to NRC concerning turbine missiles
COLLIER, A R Westinghouse Electric Corp 82/11/08 8pp
16329 171 24X Fiche 50-000, 82/11/29, 8212070177

--B212070198 Forwards nonproprietary version of revised FSAR re protection against possible turbine missiles.
TRAHM, T R Commonwealth Edison Co 82/09/02 DENTON, H R Office
of Nuclear Reactor Regulation, Director. 35pp 16329 179 24X
Fiche 50-000, 82/11/29, 8212070177.

--B212070207 Forwards nonproprietary version of revisions to FSAR re protection against possible turbine missiles.
TRAHM, T R Commonwealth Edison Co 82/08/18 DENTON, H R Office
of Nuclear Reactor Regulation, Director. 70pp. 16329 214. 24X
Fiche 50-000, 82/11/29, 8212070177

B212220212 Forwards Revision 22 to CE-I-A, "QA Program for Nuclear Generating Stations "
SWARTZ, E D Commonwealth Edison Co 82/12/14 HAASB, W P Quality Assurance Branch 1p. 16518 007 24X Fiche 50-000, 82/12/14, 8212220212

DOCKETED ITEMS

--B212220231 "QA Program for Nuclear Generating Stations," Revision 22
* Commonwealth Edison Co CE-1-A R22 82/11/01 17pp
16518 009 24X Fiche 50-000, 82/12/14, B212220212

B212280212 Forwards updated schedule for ongoing environ qualification
testing programs, per B10528 commitment
SHARTZ, E D Commonwealth Edison Co 82/12/22 EISENHUT, D O
Division of Licensing 18pp 16556 161 24X Fiche 50-000, 82/12/22,
B212280212

E NRC Safety Evaluation Report (SER), suppl & correspondence

B212070249 Clarifies seismic qualification program & pump valve
operability program evaluated in SER & reviewed in audit
during wk of B20913
TRAMM, T R Commonwealth Edison Co 82/12/02 DENTON, H R Office
of Nuclear Reactor Regulation, Director 5pp 16327 323 24X
Fiche 50-000, 82/12/02, B212070249

F Security, medical, emergency & fire protection plans

B212090383 Forwards info re emergency operations facilities per
B21122 & 1202 requests info previously submitted by telcon.
Request for written response unnecessary burden on licensee
DELGEORGE, L O Commonwealth Edison Co 82/12/03 EISENHUT, D O
Division of Licensing 2pp 16565 051 24X Fiche 50-000, 82/12/03,
B212090383

B212130017 Releases public version of Revision 1 to Emergency Plan
Implementing Procedure EQ-2, "Pre-Established Onsite &
Offsite Monitoring Locations (Maps)"
FELTON, J M Division of Rules and Records 82/12/07 Document
Management Branch 1p 16417 062 24X Fiche 50-000, 82/12/07,
B212130017

--B212130028 Forwards public version of Revision 1 to Emergency Plan
Implementing Procedure EQ-2, "Pre-Established Onsite &
Offsite Monitoring Locations (Maps)" Revised table of
contents encl
PAJOWSKI, J Commonwealth Edison Co 82/11/01 DENTON, H R NRC -
No Detailed Affiliation Given 2pp 16417 063 24X
Fiche 50-000, 82/12/07, B212130017

--B212130041 Public version of Revision 1 to Emergency Plan Implementing
Procedure EQ-2, "Pre-Established Onsite & Offsite Monitoring
Locations (Maps)"
PAJOWSKI, J E Commonwealth Edison Co 82/11/29 4pp 16417 065
24X Fiche 50-000, 82/12/07, B212130017

B212140243 Advises of distribution of revisions to "Generating Station
Emergency Plan" Braidwood annex not prepared
TRAMM, T R Commonwealth Edison Co 82/12/07 DENTON, H R Office
of Nuclear Reactor Regulation, Director 2pp 16409 302 24X
Fiche 50-000, 82/12/07, B212140243

B212220306 Discusses layout of communications equipment required in
control room, onsite technical support ctr & near-site
emergency operations facility
KEPPLER, J O Region 3, Office of Director 82/12/16,
Commonwealth Edison Co 3pp 16503 351 24X Fiche 50-000, 82/12/16,
B212220306

H General correspondence

B212280176 Notifies of change in mailing address for NRC licensing
matl
WRIGHT, O N Illinois, State of, Dept Nuc Safety (formerly Dept
Public Health) 82/12/20 EISENHUT, D O Division of Licensing
1p 16556 135 24X Fiche 50-000, 82/12/20, B212280176

K Utility Final Safety Analysis Report (FSAR) & amends

B211290530 Application to amend applications for OL, consisting of Amend
40 to FSAR
TRAMM, T R Commonwealth Edison Co 82/11/19 DENTON, H R Office
of Nuclear Reactor Regulation, Director 3pp 16227 348 24X
Fiche 50-000, 82/11/19, B211290530

--B211290559 Amend 40 to FSAR
* Commonwealth Edison Co 82/11/30 234pp 16227 351 24X
Fiche 50-000, 82/11/19, B211290530

B212280306 Forwards Affidavit of Svc re distribution of FSAR Amend 40
per RS Boyd 781020 ltr to C Reed
TRAMM, T R Commonwealth Edison Co 82/12/17 DENTON, H R Office
of Nuclear Reactor Regulation, Director 2pp 16561 095 24X
Fiche 50-000, 82/12/17, B212280306

G Inspection reports, IE Bulletins & correspondence

B208190240 IE Bulletin B2-03, Revision 1, "Stress Cracking in Thick-
Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping
at BWR Plants" Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and
Enforcement 82/10/28 Consolidated Edison Co of New York, Inc
112pp 14662 163 24X Fiche 50-000, 82/10/28, B208190240

B208190245 IE Info Notice B2-42, "Defects Observed in Panasonic Model
801 & Model 802 Thermoluminescent Dosimeters" Svc list
encl
COBB, L J Division of Fuel Facilities, Materials & Safeguards
82/11/05 Consolidated Edison Co of New York, Inc 110pp
16372 142 24X Fiche 50-000, 82/11/05, B208190245

B208190251 IE Info Notice B2-44, "Clarification of Emergency Plan
Exercise Requirements" Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18
Consolidated Edison Co of New York, Inc 107pp 16411 199 24X
Fiche 50-000, 82/11/18, B208190251

B208190256 IE Info Notice B2-46, "Defective & Obsolete Combination
Padlocks" Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and
Enforcement 82/11/26 Consolidated Edison Co of New York, Inc
127pp 16411 065 24X Fiche 50-000, 82/11/26, B208190256

B208190257 IE Info Notice B2-47, "Transportation of Type A Quantities
of Non-Fissile Radioactive Matl" Svc list encl
COBB, L J Division of Fuel Facilities, Materials & Safeguards
82/11/30 Consolidated Edison Co of New York, Inc 356pp
16387 028 24X Fiche 50-000, 82/11/30, B208190257

B208190259 IE Bulletin B2-04, "Deficiencies in Primary Containment
Electrical Penetration Assemblies" Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and
Enforcement 82/12/03 Consolidated Edison Co of New York, Inc
113pp 16411 317 24X Fiche 50-000, 82/12/03, B208190259

B208190261 IE Info Notice B2-48, "Failures of Agastat CR 0095 Relay
Sockets" Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03
Consolidated Edison Co of New York, Inc 110pp 16462 064 24X
Fiche 50-000, 82/12/03, B208190261

B208190267 IE Info Notice B2-49, "Correction for Sample Conditions for
Air & Gas Monitoring" Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and
Enforcement 82/12/16 Consolidated Edison Co of New York, Inc
127pp 16628 191 24X Fiche 50-000, 82/12/16, B208190267

B208190268 IE Info Notice B2-50, "Mod of Solid State AC Undervoltage
Relays Type ITE-27" Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20
Consolidated Edison Co of New York, Inc 108pp 16628 293 24X
Fiche 50-000, 82/12/20, B208190268

DOCKET 50-458 RIVER BEND STATION, UNIT 1

A Application/construction stage documents & correspondence

B21230066 Generic Ltr B2-27 to all BWR licensees of operating reactors
except LACBWR, Big Rock Point, Dresden 1, Humboldt Bay,
applicants for OL & holders of CP re transmittal of
NUREG-0763 & NUREG-0763 Svc list encl H/o stated encl
EISENHUT, D O Division of Licensing 82/11/15 General Public
Utilities - OPU Service Corp 22pp 16387 004 24X
Fiche 50-000, 82/11/15, B21230066

B212220274 Forwards action plan addressing addl containment issues
raised in NRC B20623 & 0723 ltrs. Util will summarize
responses to containment issue approx 30 days after end of
owners group program. Cross ref of containment issues encl.
BOOKER, J E Gulf States Utilities Co 82/12/09 SCHWENCER, A
Licensing Branch 2 59pp 16517 294 24X Fiche 50-458, 82/12/09,
B212220274

B212220049 Forwards clarification of NRC criteria re remote shutdown
station designs, per util B20813 position on remote shutdown
capability H/o encl
SCHWENCER, A Licensing Branch 2 82/12/13 CAHILL, W J Gulf
States Utilities Co 2pp 16526 353, 24X Fiche 50-458, 82/12/13,
B212220049

F Security, medical, emergency & fire protection plans

8212270491 Requests addl info re emergency plan. Revised plan should be submitted within 60 days of receipt of ltr List of required info & comments encl
SCHWENGER, A Licensing Branch 2 82/12/16 CAHILL, W J Gulf States Utilities Co 27pp 16551 016 24X Fiche 50-458, 82/12/16, 8212270491

G Adjudicatory correspondence

8212100117 Motion for extension of time until 840115 to file contentions. Util requested extension of CP until 851231 so that schedule for OL hearing will probably slip. GER will not be issued until 831202 Certificate of Svc encl
LINDSEY, I D Louisiana, State of 82/12/02 Commissioners App 16376 015 24X Fiche 50-458, 82/12/02, 8212100117

8212230192 Contentions of State of LA Certificate of Svc encl
LINDSEY, I D Louisiana, State of 82/12/15 Atomic Safety and Licensing Board Panel 8pp 16511 112 24X Fiche 50-458, 82/12/15, 8212230192

8212210261 Response in opposition to State of LA 821202 motion for extension of time within which to file contentions. Thirteen-month delay would significantly interfere w/ timely completion of hearing Certificate of Svc encl
CONNER, T B, WETTERHAHN, M J Gulf States Utilities Co CONNER, T B Conner & Wetterhahn 82/12/17 Atomic Safety and Licensing Board Panel 8pp 16483 258 24X Fiche 50-458, 82/12/17, 8212210261

8212230215 Order granting State of LA 821202 motion for extension of time for filing contentions. Contentions must be filed by 830315, answers by 830415 & responses by 830503. Prehearing conference will be held on 830524
COTTER, B F Atomic Safety and Licensing Board Panel 82/12/21 Louisiana, State of 2pp 16511 047 24X Fiche 50-458, 82/12/21, 8212230215

8212230315 Forwards order, granting in part & denying in part, motion for extension of 13 months to file contentions. Order reconstituting ASLB by appointment of GA Linenberger also encl W/O encl
COTTER, B F Atomic Safety and Licensing Board Panel 82/12/21 LINDSEY, I D Justice, Dept of 1p 16511 125 24X Fiche 50-458, 82/12/21, 8212230315

G Inspection reports, IE Bulletins & correspondence

8208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants." Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc. 112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240

8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model B01 & Model B02 Thermoluminescent Dosimeters." Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000, 82/11/05, 8208190245

8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements." Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X Fiche 50-000, 82/11/18, 8208190251

8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks." Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411:065 24X Fiche 50-000, 82/11/26, 8208190256

8208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Mat'l." Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000, 82/11/30, 8208190257

8212200076 Forwards IE Insp Rept 50-458/82-14 on 821001-31 No noncompliance noted
MADSEN, O L Division of Resident, Reactor Project & Engineering Programs 82/12/01 CAHILL, W J Gulf States Utilities Co 2pp 16470 030 24X Fiche 50-458, 82/12/01, 8212200076

--8212200086 IE Insp Rept 50-458/82-14 on 821001-31 No noncompliance noted. Major areas inspected followup of previous insp findings, licensee identified const deficiencies, safety-related pipe welding & reactor coolant pipe welding
BROWN, R L, CROSSMAN, W A Division of Resident, Reactor Project & Engineering Programs 82/12/01 6pp 16470 032 24X Fiche 50-458, 82/12/01, 8212200076

8212100236 Ack receipt of 820809 & 1101 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 50-458/82-03
MADSEN, O L Division of Resident, Reactor Project & Engineering Programs 82/12/02 CAHILL, W J Gulf States Utilities Co 1p 16376 064 24X Fiche 50-458, 82/12/02, 8212100236

--8212100239 Responds to NRC 820708 & 0929 ltrs re violations noted in IE Insp Rept 50-458/82-03. Corrective actions pipe supports designed per ASME code requirements
BOOKER, J E Gulf States Utilities Co 82/11/01 COLLINS, J T Region 4, Office of Director 2pp 16376 065 24X Fiche 50-458, 82/12/02, 8212100236

8208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies." Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259

8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets." Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X Fiche 50-000, 82/12/03, 8208190261

8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring." Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16, 8208190267

8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27." Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X Fiche 50-000, 82/12/20, 8208190268

B Reportable occurrences, LERs & related correspondence

8212100033 Interim deficiency rept re cracked, spalled & chipped concrete around main steam & other penetrations through drywell wall to steam tunnel. Initially reported on 820806. Investigation continuing. Next rept will be issued by 830127
BOOKER, J E Gulf States Utilities Co 82/12/03 COLLINS, J T Region 4, Office of Director 1p 16379 035 24X Fiche 50-458, 82/12/03, 8212100033

8212210176 Interim deficiency rept re violation of requirements for min spacing between drills in anchors & adjacent embedment plates. Initially reported on 821109. Investigation re reporting criteria continuing. Next rept expected by 830127
BOOKER, J E Gulf States Utilities Co 82/12/09 COLLINS, J T Region 4, Office of Director 1p 16484 249 24X Fiche 50-458, 82/12/09, 8212210176

8212210136 Final Deficiency Rept DR-68 re application of non-specified preservative (Tectyl 506) on high pressure core spray diesel engine pistons & valve mechanisms. Initially reported on 821122. All Tectyl 506 to be removed
BOOKER, J E Gulf States Utilities Co 82/12/10 COLLINS, J T Region 4, Office of Director 2pp 16485 144 24X Fiche 50-458, 82/12/10, 8212210136

8212270183 Interim deficiency rept re installation & insp of undersized fillet weld. Initially reported on 821118. Investigation not completed. Next rept expected by 830329
BOOKER, J E Gulf States Utilities Co 82/12/15 COLLINS, J T Region 4, Office of Director 1p 16534 362 24X Fiche 50-458, 82/12/15, 8212270183

8212270236 Interim Deficiency Rept DR-72 re improper installation, testing & insp of concrete drilled in expansion-type anchors. Initially reported on 820830. Investigation complete. Final rept to be submitted by 830228
BOOKER, J E Gulf States Utilities Co 82/12/15 COLLINS, J T Region 4, Office of Director 1p 16530 356 24X Fiche 50-458, 82/12/15, 8212270236

8212280196 Interim Deficiency Rept DR-79 re failure to follow weld procedures on field weld. Initially reported on 821123. Investigation continuing. Next rept expected by 830228.
BOOKER, J E Gulf States Utilities Co 82/12/17 COLLINS, J T Region 4, Office of Director 1p 16562 090 24X Fiche 50-458, 82/12/17, 8212280196

DOCKETED ITEMS

B212280252 Interim Deficiency Rept DR-80 re Transamerica Delaval piston skirt castings installed in emergency diesel generator engines Initially reported on B21124 Evaluation cannot proceed until const around bldg complete Next rept B20530
BOOKER, J E Gulf States Utilities Co B2/12/17 COLLINS, J T
Region 4, Office of Director 1p 16561 270 24X
Fiche 50-458, B2/12/17, B212280252

DOCKET 50-459 RIVER BEND STATION, UNIT 2

A Application/construction stage documents & correspondence

B211230066 Generic Ltr B2-27 to all BWR licensees of operating reactors except LACBWR, Big Rock Point, Dresden 1, Humboldt Bay, applicants for DL & holders of CP re transmittal of NUREG-0763 & NUREG-0783 Svc list encl W/o stated encl
EIGENHUT, D O Division of Licensing B2/11/15 General Public Utilities - OPU Service Corp 22pp 16387 004 24X
Fiche 50-000, B2/11/15, B211230066

B212220274 Forwards action plan addressing addl containment issues raised in NRC B20623 & 0723 ltr Util will summarize responses to containment issue approx 30 days after end of owners group program Cross ref of containment issues encl
BOOKER, J E Gulf States Utilities Co B2/12/09 SCHWENCER, A
Licensing Branch 2 59pp 16517 294 24X Fiche 50-458, B2/12/09, B212220274

B212220049 Forwards clarification of NRC criteria re remote shutdown station designs, per util B20813 position on remote shutdown capability W/o encl
SCHWENCER, A Licensing Branch 2 B2/12/13 CAHILL, W J Gulf States Utilities Co 2pp, 16526 353 24X Fiche 50-458, B2/12/13, B212220049

F. Security, medical, emergency & fire protection plans

B212270491 Requests addl info re emergency plan Revised plan should be submitted within 40 days of receipt of ltr List of required info & comments encl
SCHWENCER, A Licensing Branch 2 B2/12/16 CAHILL, W J Gulf States Utilities Co 27pp 16551 016 24X Fiche 50-458, B2/12/16, B212270491

G Adjudicatory correspondence

B212100117 Motion for extension of time until B40115 to file contentions Util requested extension of CP until B51231 so that schedule for DL hearing will probably slip SER will not be issued until B31202 Certificate of Svc encl
LINDSEY, I D Louisiana, State of B2/12/02 Commissioners 4pp 16376 015 24X Fiche 50-458, B2/12/02, B212100117

B212230192 Contentions of State of LA Certificate of Svc encl
LINDSEY, I D Louisiana, State of. B2/12/15 Atomic Safety and Licensing Board Panel. Bpp 16511 112 24X Fiche 50-458, B2/12/15, B212230192

B212210261 Response in opposition to State of LA B21202 motion for extension of time within which to file contentions. Thirteen-month delay would significantly interfere w/timely completion of hearing Certificate of Svc encl
CONNER, T O, WETTERHAHN, M J Gulf States Utilities Co CONNER, T O Conner & Wetterhahn B2/12/17 Atomic Safety and Licensing Board Panel Bpp. 16483 298 24X Fiche 50-458, B2/12/17, B212210261

B212230215 Order granting State of LA B21202 motion for extension of time for filing contentions. Contentions must be filed by B30315, answers by B30415 & responses by B30503 Prehearing conference will be held on B30524
COTTER, B P Atomic Safety and Licensing Board Panel. B2/12/21 Louisiana, State of 2pp 16511 047 24X Fiche 50-458, B2/12/21, B212230215

B212230315 Forwards order granting in part & denying in part motion for extension of 13 months to file contentions Order reconstituting ABLB by appointment of GA Linenberger also encl W/o encl
COTTER, B P Atomic Safety and Licensing Board Panel B2/12/21 LINDSEY, I D Justice, Dept of 1p 16511 125 24X
Fiche 50-458, B2/12/21, B212230315

H Inspection reports, IE Bulletins & correspondence

B208190240 IE Bulletin B2-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel Recirculation Sys Piping at BWR Plants " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement. B2/10/28. Consolidated Edison Co. of New York, Inc 112pp 16462 163 24X Fiche 50-000, B2/10/28, B208190240

B208190245 IE Info Notice B2-42, "Defects Observed in Panasonic Model B01 & Model B02 Thermoluminescent Dosimeters " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards B2/11/09 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000, B2/11/09, B208190245

B208190251 IE Info Notice B2-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance B2/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X
Fiche 50-000, B2/11/18, B208190251

B208190256 IE Info Notice B2-46, "Defective & Obsolete Combination Padlocks " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement B2/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000, B2/11/26, B208190256

B208190257 IE Info Notice B2-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards B2/11/30. Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000, B2/11/30, B208190257

B208190259 IE Bulletin B2-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement B2/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, B2/12/03, B208190259

B208190261 IE Info Notice B2-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance B2/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X
Fiche 50-000, B2/12/03, B208190261

B208190267 IE Info Notice B2-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement B2/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, B2/12/16, B208190267

B208190268 IE Info Notice B2-50, "Mod of Solid State AC Undervoltage Relays Type 17E-27 " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance B2/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X
Fiche 50-000, B2/12/20, B208190268

S Reportable occurrences, LERs & related correspondence

B212210136 Final Deficiency Rept DR-68 re application of non-specified preservative (Tectyl 506) on high pressure core spray diesel engine pistons & valve mechanisms Initially reported on B21122 All Tectyl 506 to be removed
BOOKER, J E Gulf States Utilities Co B2/12/10 COLLINS, J T Region 4, Office of Director 2pp 16485 144 24X
Fiche 50-458, B2/12/10, B212210136

DOCKET 50-460 WPPSS NUCLEAR PROJECT, UNIT 1

A Application/construction stage documents & correspondence

B212230363 Trip rept of Commissioners Gilinsky & Abbott B21202 site visit Agenda & viewgraphs encl
ABBOTT, E C Commissioners B2/12/17 Commissioners 26pp 16511 170 24X Fiche 50-397, B2/12/17, B212230363

B212280440 Requests that Topical Repts BAW-10092P, Revision 3 & BAW-10154P be considered as part of DL application for Unit 1 so that work on TMI Action Item II K 3 30 can commence
BOUCHEY, O D Washington Public Power Supply System B2/12/21 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 16556 057 24X Fiche 50-460, B2/12/21, B212280440

E NRC Safety Evaluation Report (SER), supp & correspondence

B212060341 Forwards request for addl info needed to complete review & prepare SER input
NOVAK, T M Assistant Director for Licensing B2/11/26, FERGUSON, R L Washington Public Power Supply System 18pp 16323 327 24X Fiche 50-460, B2/11/26, B212060341

F Security, medical, emergency & fare protection plans

8212100236 Forwards util 800616 & 1212 & 810320 & 0408 ltrs re emergency response facilities (ERF) in response to Generic Ltr 81-10, per NRC request Util does not plan to provide backup ERF Requested info provided
BOUCHEY, O D Washington Public Power Supply System 82/12/03
DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp
1637a 149 24X Fiche 50-397, 82/12/03, 8212100236

G Adjudicatory correspondence

8212020344 Order scheduling 830119-20 prehearing conference in Richland, WA to discuss standing of parties, specific issues to be considered at evidentiary hearing, scheduling & possible consolidation
GROSSMAN, H Atomic Safety and Licensing Board Panel 82/11/30
4pp 16277 265 24X Fiche 50-460, 82/11/30, 8212020344

8212020360 Order scheduling 830119-20 special prehearing conference in Richland, WA re standing of parties, specific issues to be considered at evidentiary hearing & further scheduling
GROSSMAN, H Atomic Safety and Licensing Board Panel 82/12/01
4pp 16278 018 24X Fiche 50-460, 82/12/01, 8212020360

8212080272 Ack receipt of 821110 ltr requesting intervention as interested state to make limited appearance statement
Statement allowable w/o intervening Intervention requests will be considered at prehearing conference
GROSSMAN, H Atomic Safety and Licensing Board Panel 82/12/06
LEWIS, N D Washington, State of 1p 16354 210 24X
Fiche 50-460, 82/12/06, 8212080272

8212140418 Motion for delay of 830119 & 20 prehearing conference Schedule burdensome due to two major holiday periods Four days of preparation lost Certificate of Svc encl
BELL, N Coalition for Safe Power 82/12/09 Atomic Safety and Licensing Board Panel 3pp 16403 312 24X Fiche 50-397, 82/12/09, 8212140418

8212200104 Order rescheduling 830119 & 20 prehearing conferences for 830106-27 Coalition for Safe Power allowed to file supps to requests for hearing no later than 15 days before conference
GROSSMAN, H Atomic Safety and Licensing Board Panel 82/12/15
2pp 16470 089 24X Fiche 50-397, 82/12/15, 8212200104

8212230314 Requests supplemental pleadings be served on applicant counsel in Washington, DC per ASLB 821215 order Pleadings expected by 830111 Pleadings served to util in Richland, WA do not constitute svc in proceeding
REYNOLDS, N S Debevoise & Liberman REYNOLDS, N S Washington Public Power Supply System 82/12/20 ROSOLIE, E Coalition for Safe Power 1p 16507 027 24X Fiche 50-397, 82/12/20, 8212230314

8212270329 Response supporting Coalition for Safe Power 821209 motion for 1-wk delay of prehearing conference scheduled for 830119-20 Applicant does not concede that basis for request constitutes good cause Certificate of Svc encl
REYNOLDS, N S Washington Public Power Supply System REYNOLDS, N S Debevoise & Liberman 82/12/22 Atomic Safety and Licensing Board Panel 6pp 16530 184 24X Fiche 50-460, 82/12/22, 8212270329

8212280277 Forwards responses to petitioner motion for delay of 830119 & 22 prehearing conference, for inclusion in records Related correspondence w/o encl
REYNOLDS, N S Debevoise & Liberman REYNOLDS, N S Washington Public Power Supply System 82/12/22 GROSSMAN, H Atomic Safety and Licensing Board Panel 1p 16561 311 24X
Fiche 50-397, 82/12/22, 8212280277

8212280294 Response in opposition to Coalition for Safe Power 821209 motion for delay of 830119 & 20 prehearing conference Allegations set forth do not constitute good cause for extension Certificate of Svc encl
REYNOLDS, N S Washington Public Power Supply System REYNOLDS, N S Debevoise & Liberman 82/12/22 Atomic Safety and Licensing Board Panel 6pp 16562 001 24X Fiche 50-460, 82/12/22, 8212280294

H General correspondence

8212170314 Notifies that RL Ferguson, managing director of util, resigned on 821129, effective 830601, due to health reasons
BOUCHEY, O D Washington Public Power Supply System 82/12/08
DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp
16456 158 24X Fiche 50-397, 82/12/08, 8212170314

I Inspection reports, IE Bulletins & correspondence

8208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240

8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp
16372 142 24X Fiche 50-000, 82/11/05, 8208190245

8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X
Fiche 50-000, 82/11/18, 8208190251

8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000, 82/11/26, 8208190256

8208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp
16387 028 24X Fiche 50-000, 82/11/30, 8208190257

8208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259

8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X
Fiche 50-000, 82/12/03, 8208190261

8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring." Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16, 8208190267

8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27 " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X
Fiche 50-000, 82/12/20, 8208190268

S Reportable occurrences, LERs & related correspondence

8212210251 Interim deficiency rept re potentially defective switch on OE electrically operated low voltage circuit breaker types AKR30 & AKR50 mfg before May 1980 Initially reported on 821115 Breakers will be corrected by Apr 1983
ROOT, R W Washington Public Power Supply System 82/12/06
STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 2pp 16483 309 24X Fiche 50-460, 82/12/06, 8212210251

8212280428 Interim deficiency rept re rusting & pitting condition detected in noncorrosion resistant surfaces of reactor vessel flange stud holes Initially reported on 821115 Final rept will be submitted following B&W evaluation
ROOT, R W Washington Public Power Supply System 82/12/14
STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 2pp 16597 023 24X Fiche 50-460, 82/12/14, 8212280428

DOCKET 50-461 CLINTON POWER STATION, UNIT 1

A Application/construction stage documents & correspondence

8212280125 Advises of project mgt reorganization to provide supplemental staff
GERSTNER, W C Iowa Electric Light & Power Co 82/10/06
KEPLER, J G Region 3, Office of Director 2pp 16564:071 24X
Fiche 50-461, 82/10/06, 8212280125

DOCKETED ITEMS

8211230066 Generic Ltr 82-27 to all BWR licensees of operating reactors except LACBWR, Big Rock Point, Dresden 1, Humboldt Bay, applicants for OL & holders of CP re transmittal of NUREG-0763 & NUREG-0783 Svc list encl W/o stated encl EISENHUT, D G Division of Licensing 82/11/15 General Public Utilities - OPU Service Corp 22pp 16387 004 24X Fiche 50-000, 82/11/15, 8211230066

8212060144 Notifies of intended action to complete prerequisite re identification of type of discontinuity on weld map Detailed plan for disposition of drywell refueling bellows will be available by 830101 HALL, D P Illinois Power Co 82/11/23 KEPLER, J O Region 3, Office of Director 2pp 16313 159 24X Fiche 50-461, 82/11/23, 8212060144

8212020142 Forwards request for addl info justifying acceptance criteria for piping vibration preoperational test procedures Proposed criteria in FGAR Amend 20 not acceptable THOMAS, C O Standardization & Special Projects Branch 82/11/24 MULLER, O E Illinois Power Co 3pp 16308 291 24X Fiche 50-461, 82/11/24, 8212020142

8212020396 Summary of 821026 meeting w/Util & Sargent & Lundy re use of ASME code for containment & drywell structures Design spec adequate Const acceptability should be confirmed by independent insp of records Supporting documentation encl WILLIAMS, J H Licensing Branch 2 82/11/24 SCHWENCER, A Licensing Branch 2 40pp 16308 132 24X Fiche 50-461, 82/11/24, 8212020396

8212060105 Forwards proprietary response for Action Plan Issue 14, corresponding to Humphrey Issue 4 3 re suppression pool thermal stratification GE affidavit supporting proprietary classification encl Response withheld (ref 10CFR2 790) MULLER, O E Illinois Power Co 82/11/24 THOMAS, C O Standardization & Special Projects Branch 4pp 16315 023 24X Fiche 50-461, 82/11/24, 8212060105

8212020088 Advises that immediate review of containment purge issue commenced, in response to NRC 821112 ltr GERSTNER, W C Illinois Power Co 82/11/30 THOMAS, C O Standardization & Special Projects Branch 2pp 16272 021 24X Fiche 50-461, 82/11/30, 8212020088

8212060320 Ack receipt of 821123 ltr concerning action to be taken re defect on weld map & location of ultrasonic analysis All other prerequisites satisfied Plan will be reviewed by 830103 KEPLER, J O Region 3, Office of Director 82/12/02 GERSTNER, W C Illinois Power Co 1p 16312 078 24X Fiche 50-461, 82/12/02, 8212060320

8212280101 Forwards procurement recovery plan, indicating method by which util will correct inadequacies identified in 820318 stop work action Procedures implementing plan will be available for insp Review & concurrence requested HALL, D P Illinois Power Co 82/12/03 KEPLER, J P Region 3, Office of Director 19pp 16556 098 24X Fiche 50-461, 82/12/03, 8212280101

8212170303 Submits followup on containment vent & purge sys, per 821130 ltr Design changes to existing containment purge sys to implement Grand Gulf type configuration should begin immediately, per 821130 ltr MULLER, O E Illinois Power Co 82/12/13 SCHWENCER, A Licensing Branch 2 1p 16453 205 24X Fiche 50-461, 82/12/13, 8212170303

8212220233 Forwards seismic & dynamic qualification summary & status for balance of plant & NSSS mechanical equipment important to safety, in response to 820604 & 1211 requests Tables 3 10-1 & 3 10-2 will be incorporated into FGAR amend MULLER, O E Illinois Power Co 82/12/15 SCHWENCER, A Licensing Branch 2 506pp 16519 031 24X Fiche 50-461, 82/12/15, 8212220233

8212210313 Forwards listing of revised full-size P&IDs, identified in FGAR Table 1 7-2 Drawings will be sent under separate cover MULLER, O E Illinois Power Co 82/12/20 SCHWENCER, A Licensing Branch 2 7pp 16497 127 24X Fiche 50-461, 82/12/20, 8212210313

8212280108 Comments on proposed improvement program/master mgt plan Interim planning & scheduling sys covering items defined in 820901 confirmatory action ltr required prior to lifting stop work actions. SPESBARD, R L Division of Project & Resident Programs 82/12/20 GERSTNER, W C Illinois Power Co 3pp 16564 188 24X Fiche 50-461, 82/12/20, 8212280108

8212280235 Forwards info re tube bundle assembly & single stage moisture separator reheater One oversize drawing encl Aperture card is available in PDR. MULLER, O E Illinois Power Co 82/12/20 ABELSON, H Licensing Branch 2 3pp 16556 068 24X Fiche 50-461, 82/12/20, 8212280235

E NRC Safety Evaluation Report (SER), suppl's & correspondence

8212070125 Provides justification for use of 8% bypass leakage fraction, closing out SER Outstanding Issue 10(e) Draft Tech Specs & FSAR Chapter 15 will be revised to reflect new calculated post-accident doses MULLER, O E Illinois Power Co 82/11/30 THOMAS, C O Standardization & Special Projects Branch 2pp 16327 087 24X Fiche 50-461, 82/11/30, 8212070125

8212070200 Advises of masonry blockwall test program to determine modules of rupture of concrete block masonry walls to resolve SER Confirmatory Issue 7 (3 B 3) NRC welcome to witness testing on 821220 & 21 at Const Technology Labs MULLER, O E Illinois Power Co 82/12/02 THOMAS, C O Standardization & Special Projects Branch 2pp 16334 350 24X Fiche 50-461, 82/12/02, 8212070200

8212170330 Forwards "Control Sys Failure Review & Evaluation Program," final rept re outstanding Issues 14 & 15 of SER, NUREG-0835 Outstanding Issue 14 addressed for operating reactors per IE Bulletin 79-27 MULLER, O E Illinois Power Co 82/12/09 SCHWENCER, A Licensing Branch 2 2pp 16458 070 24X Fiche 50-461, 82/12/09, 8212170330

--8212170335 "Control Sys Failure Review & Evaluation Program," final rept v Quadrex Corp QUAD-1-82-244 82/11/12 454pp 16458 072 24X Fiche 50-461, 82/12/09, 8212170335.

8212290179 Submits info re SER Outstanding Issue 6 (Section 3 9 2), "Steady State Vibration Acceptance Criteria for Balance-of-Plant Piping" Proposed stress levels acceptable for steady-state vibration MULLER, O E Illinois Power Co 82/12/10 SCHWENCER, A Licensing Branch 2 2pp 16578 036 24X Fiche 50-461, 82/12/10, 8212290179

F Security, medical, emergency & fire protection plans

8212080014 Notifies of acceptance of security plan & training & qualification plan submitted in 820827 & 0930 ltrs Encl to ltrs withheld (ref 10CFR73 21) SCHWENCER, A Licensing Branch 2 82/12/01 MULLER, O E Illinois Power Co 2pp 16367 177 24X Fiche 50-461, 82/12/01, 8212080014

8212070229 Confirms info re status of emergency operations facility, per 821203 request More detailed info available in FGAR App 13 B, emergency plan, Section 10 MULLER, O E Illinois Power Co 82/12/03 SCHWENCER, A Licensing Branch 2 2pp 16329 321 24X Fiche 50-461, 82/12/03, 8212070229

8212220306 Discusses layout of communications equipment required in control room, onsite technical support ctr & near-site emergency operations facility KEPLER, J O Region 3, Office of Director 82/12/16 Commonwealth Edison Co 3pp 16503 351 24X Fiche 50-000, 82/12/16, 8212220306

G Adjudicatory correspondence

8212270322 Marked-up petition for leave to intervene & request for hearing Certificate of Svc encl SAMELSON, A Prairie Alliance 81/03/30 Atomic Safety and Licensing Board Panel 36pp 16530 230 24X Fiche 50-461, 81/03/30, 8212270322

8212220119 Advises of corrected address for J Foy, spokesperson for Prairie Alliance GODDARD, R J Hearing Branch 3 82/12/17 CLARK, H K, PARIS, D H, FERQUSSON, G A Atomic Safety and Licensing Board Panel 1p 16503 025 24X Fiche 50-461, 82/12/17, 8212220119

H General correspondence

8212280176 Notifies of change in mailing address for NRC licensing mail WRIGHT, G N Illinois, State of, Dept Nuc Safety (formerly Dept Public Health) 82/12/20 EISENHUT, D G Division of Licensing 1p 16556 135 24X Fiche 50-000, 82/12/20, 8212280176

I Inspection reports, IE Bulletins & correspondence

8208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants" Svc list encl DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240

8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model B01 & Model 802 Thermoluminescent Dosimeters " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards
82/11/05 Consolidated Edison Co of New York, Inc 110pp
16372 142 24X Fiche 50-000, 82/11/05, 8208190245

8212280360 Responds to NRC 821006 confirmatory action ltr re util overinsp program Util terminated all new overinsp work on 821005 No further insps will be performed until proper overinsp program developed
HALL, D P Illinois Power Co 82/11/08 SPESSARD, R L Division of Project & Resident Programs 3pp 16560 074 24X
Fiche 50-461, 82/11/08, 8212280360

8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18
Consolidated Edison Co of New York, Inc 107pp 16411 199 24X
Fiche 50-000, 82/11/18, 8208190251

8212080561 Forwards IE Insp Rept 50-461/82-14 on 820801-0930 & notice of violation
KNOP, R C Division of Project & Resident Programs 82/11/22
GERSTNER, W C Illinois Power Co 2pp 16392 042 24X
Fiche 50-461, 82/11/22, 8212080561

--8212080567 Notice of violation from insp on 820801-0930
KNOP, R C Division of Project & Resident Programs 82/11/22 1p
16352 044 24X Fiche 50-461, 82/11/22, 8212080561

--8212080573 IE Insp Rept 50-461/82-14 on 820801-0930 Noncompliance noted radwaste reprocessing w/o recirculation, chemical test & dump evolution performed w/o applicable procedures
LIVERMORE, H H Division of Project & Resident Programs
HAYES, D W Region 3, Office of Director 82/11/22 7pp
16392 045 24X Fiche 50-461, 82/11/22, 8212080561

8212060093 Requests approval of encl description of proposed Phase 2A-2 of insp of structural steel, insp of remainder of uninspected fixed connections & reinsp of expansion connections in containment deficiency rept filed w/o encl
HALL, D P Illinois Power Co 82/11/23 KEPLER, J O Region 3, Office of Director 2pp 16316 121 24X Fiche 50-461, 82/11/23, 8212060093

8212100329 Forwards IE Insp Rept 50-461/82-18 on 820927-30 & 1005-08 & notice of violation
NORELIUS, C E Division of Engineering & Technical Programs
82/11/23 GERSTNER, W C Illinois Power Co 2pp 16377 031 24X
Fiche 50-461, 82/11/23, 8212100329

--8212100333 Notice of violation from insp on 820927-30 & 1005-08
NORELIUS, C E Division of Engineering & Technical Programs
82/11/23 3pp 16377 033 24X Fiche 50-461, 82/11/23, 8212100329

--8212100339 IE Insp Rept 50-461/82-18 on 820927-30 & 1005-08 Noncompliance noted failure to update QA manual & failure to follow procedures for qualification of QC personnel
HASSE, R A, KISH, J N, PESCHEL, J M Region 3, Office of Director 82/11/16 12pp 16377 036 24X Fiche 50-461, 82/11/23, 8212100329

8212100226 Forwards IE Insp Rept 50-461/82-19 on 821001-1101 & notice of violation
KNOP, R C Division of Project & Resident Programs 82/11/24
GERSTNER, W C Illinois Power Co 2pp 16376 096 24X
Fiche 50-461, 82/11/24, 8212100226

--8212100230 Notice of violation from insp on 821001-1101.
KNOP, R C Division of Project & Resident Programs 82/11/24 1p
16376 098 24X Fiche 50-461, 82/11/24, 8212100226

--8212100240 IE Insp Rept 50-461/82-19 on 821001-1101 Noncompliance noted containment gas control boundary structure pressure test performed w/o approved procedure.
LIVERMORE, H H, HAYES, D W Division of Project & Resident Programs 82/11/24 6pp 16376 099 24X Fiche 50-461, 82/11/24, 8212100226

8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000, 82/11/26, 8208190256

8208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp
16387 028 24X Fiche 50-000, 82/11/30, 8208190257

8212280485 Forwards minutes of 821026 meeting w/util & Sargent & Lundy re use of ASME Code requiring insp by ASME authorized inspector
BAER, R L Engineering & Technical Support Branch 82/12/01
KNOP, R C Division of Project & Resident Programs 3pp 16592 247 24X Fiche 50-461, 82/12/01, 8212280485

--8212280489 Forwards draft FSAR revisions for Section 3 B re ASME Code required insp to be discussed at 821026 meeting
LAUNI, C H Sargent & Lundy, Inc 82/10/21 WILLIAMS, H
Standardization & Special Projects Branch 32pp 16592 253 24X
Fiche 50-461, 82/12/01, 8212280485

8212080366 Confirms 821118 meeting & 821119 telcon w/util & NRC concurrence in partial release of work addressed in 820901 confirmatory action ltr re Stop Work Action 016 Release limited to 467 electrical conduits
SPESSARD, R L Division of Project & Resident Programs 82/12/02
GERSTNER, W C Illinois Power Co 1p 16353 320 24X
Fiche 50-461, 82/12/02, 8212080366

8208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259

8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03
Consolidated Edison Co of New York, Inc 110pp 16462 064 24X
Fiche 50-000, 82/12/03, 8208190261

8212090472 Confirms 821118 telcon discussing util 821115 ltr & 820901 & 1006 confirmatory action ltr re plans for overinsp & record verification concurs w/plans
SPESSARD, R L Division of Project & Resident Programs 82/12/03
GERSTNER, W C Illinois Power Co 2pp 16363 345 24X
Fiche 50-461, 82/12/03, 8212090472

8212170330 Forwards "Control Sys Failure Review & Evaluation Program," final rept re outstanding issues 14 & 15 of SER, NUREG-0835
Outstanding Issue 14 addressed for operating reactors per IE Bulletin 79-27
MULLER, O E Illinois Power Co 82/12/09 SCHWENCER, A Licensing Branch 2 2pp 16458 070 24X Fiche 50-461, 82/12/09, 8212170330

--8212170335 "Control Sys Failure Review & Evaluation Program," final rept
* Quadrex Corp QUAD-1-82-244 82/11/12 454pp 16458 072 24X Fiche 50-461, 82/12/09, 8212170330

8212280375 Forwards IE Mgt Meeting Rept 50-461/82-23 on 821122 No noncompliance noted
KEPLER, J O Region 3, Office of Director 82/12/10 GERSTNER, W C Illinois Power Co 2pp 16560 052 24X Fiche 50-461, 82/12/10, 8212280375

--8212280381 IE Mgt Meeting Rept 50-461/82-23 on 821122 No noncompliance noted. Major areas discussed master mgt plan improvement program
KEPLER, J O Region 3, Office of Director KNOP, R C, HAYES, D W Division of Project & Resident Programs 82/12/08 3pp 16560:064 24X Fiche 50-461, 82/12/10, 8212280375

8212210413 Confirms 821209 discussion between A Budnick & DW Hayes, extending response date re items of noncompliance noted in IE Insp Rept 50-461/82-18 to 830107 due to postal delays
NORELIUS, C E Division of Engineering & Technical Programs 82/12/13 GERSTNER, W C Illinois Power Co 1p 16493 085 24X
Fiche 50-461, 82/12/13, 8212210413

8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring." Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16, 8208190267

8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27 " Svc list encl.
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X
Fiche 50-000, 82/12/20, 8208190268

DOCKETED ITEMS

S Reportable occurrences, LERs & related correspondence

B212020333 Interim Deficiency Rept B2-11 re incorrect identification of base metal & weld procedures on piping hanger travelers initially reported on B21020 Review of add'l travelers continues Final rpt expected in approx 60 days
HALL, D P Illinois Power Co B2/11/19 KEPLER, J O Region 3, Office of Director 4pp 16279.156 24X Fiche 50-461, B2/11/19, B212020333

B212020324 Interim Deficiency Rept B2-12 re overwelding at connection between sway strut type pipe eyelet & threaded rod on affected male rod extension piece initially reported on B21021 Insp checklist revised on B21108 to include binding
HALL, D P Illinois Power Co B2/11/20 KEPLER, J O Region 3, Office of Director 4pp 16277.273 24X Fiche 50-461, B2/11/20, B212020324

B212140057 Interim deficiency report re instrument data sheets initially reported on B20902 Instrument data sheet books collected & reissued as controlled copies Investigation continuing Final rpt will be filed in 90 days
HALL, D P Illinois Power Co B2/12/04 KEPLER, J O Region 3, Office of Director 4pp 16408.302 24X Fiche 50-461, B2/12/04, B212140057

T Hearing transcripts on non-antitrust matters

B212220051 Forwards JY Lee testimony & ME Wangler testimony & affidavit re Clinton Contention V on effects of routine low level radioactivity to be released from plant
PATTERSON, H F Hearing Branch 3 B2/12/17 FOY, J Prairie Alliance 3pp 16516.049 24X Fiche 50-461, B2/12/17, B212220051

--B212220066 Testimony of JY Lee re Contention I(a) on methods used to calculate atmospheric effluents Estimates used to calculate routine effluent releases not conservative Prof qualifications encl
LEE, J Y Effluent Treatment Systems Branch B2/12/17 4pp 16516.052 24X Fiche 50-461, B2/12/17, B212220066

--B212220070 Testimony of ME Wangler re Prairie Alliance Contention I(b) on effects of low level radiation, incremental risk to public health & safety from exposure to radiation from plant operation is small
WANGLER, M E Radiological Assessment Branch B2/12/17 4pp 16516.056 24X Fiche 50-461, B2/12/17, B212220070

--B212220073 Affidavit of ME Wangler re Contention V(b) on effects of low level radiation incremental risk to public health & safety from exposure to radiation released in normal plant operation is small
WANGLER, M E Radiological Assessment Branch B2/12/16 34pp 16516.060 24X Fiche 50-461, B2/12/17, B212220073

DOCKET 50-462 CLINTON POWER STATION, UNIT 2A Application/construction stage documents & correspondence

B211230066 Generic Ltr B2-27 to all BWR licensees of operating reactors except LACBWR, Big Rock Point, Dresden 1, Humboldt Bay, applicants for DL & holders of CP re transmittal of NUREG-0763 & NUREG-0783 Svc list encl W/o stated encl
EISENHUT, D O Division of Licensing B2/11/15 General Public Utilities - CPU Service Corp 22pp 16397.004 24X Fiche 50-000, B2/11/15, B211230066

F Security, medical, emergency & fire protection plans

B212220306 Discusses layout of communications equipment required in control room, onsite technical support ctr & near-site emergency operations facility
KEPLER, J O Region 3, Office of Director B2/12/16 Commonwealth Edison Co 3pp 16503.331 24X Fiche 50-000, B2/12/16, B212220306

G Adjudicatory correspondence

B212270322 Marked-up petition for leave to intervene & request for hearing, Certificate of Svc encl
SAHELSON, A Prairie Alliance B1/03/30 Atomic Safety and Licensing Board Panel 36pp 16530.230 24X Fiche 50-461, B1/03/30, B212270322

G Inspection reports, IE Bulletins & correspondence

B208190240 IE Bulletin B2-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement B2/10/28 Consolidated Edison Co of New York, Inc 112pp 16462.163 24X Fiche 50-000, B2/10/28, B208190240

B208190245 IE Info Notice B2-42, "Defects Observed in Panasonic Model B01 & Model U02 Thermoluminescent Dosimeters " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards B2/11/05 Consolidated Edison Co of New York, Inc 110pp 16372.142 24X Fiche 50-000, B2/11/05, B208190245

B208190251 IE Info Notice B2-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance B2/11/18 Consolidated Edison Co of New York, Inc 109pp 16411.199 24X Fiche 50-000, B2/11/18, B208190251

B208190256 IE Info Notice B2-46, "Defective & Obsolete Combination Padlocks " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement B2/11/26 Consolidated Edison Co of New York, Inc 127pp 16411.065 24X Fiche 50-000, B2/11/26, B208190256

B208190257 IE Info Notice B2-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards B2/11/30 Consolidated Edison Co of New York, Inc 356pp 16387.028 24X Fiche 50-000, B2/11/30, B208190257

B212280485 Forwards minutes of B21026 meeting w/util & Lundy re use of ASME Code requiring insp by ASME authorized inspector
BAER, R L Engineering & Technical Support Branch B2/12/01 KNOP, R C Division of Project & Resident Programs 3pp 16592.247 24X Fiche 50-461, B2/12/01, B212280485

B208190259 IE Bulletin B2-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement B2/12/03 Consolidated Edison Co of New York, Inc 113pp 16411.317 24X Fiche 50-000, B2/12/03, B208190259

B208190261 IE Info Notice B2-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance B2/12/03 Consolidated Edison Co of New York, Inc 110pp 16462.064 24X Fiche 50-000, B2/12/03, B208190261

B208190267 IE Info Notice B2-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement B2/12/16 Consolidated Edison Co of New York, Inc 127pp 16628.191 24X Fiche 50-000, B2/12/16, B208190267

B208190268 IE Info Notice B2-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27 " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance B2/12/20 Consolidated Edison Co of New York, Inc 108pp 16628.293 24X Fiche 50-000, B2/12/20, B208190268

DOCKET 50-466 ALLENS CREEK NUCLEAR STATION, UNIT 1G Inspection reports, IE Bulletins & correspondence

B208190240 IE Bulletin B2-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement B2/10/28 Consolidated Edison Co of New York, Inc 112pp 16462.163 24X Fiche 50-000, B2/10/28, B208190240

B208190245 IE Info Notice B2-42, "Defects Observed in Panasonic Model B01 & Model B02 Thermoluminescent Dosimeters " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards B2/11/05 Consolidated Edison Co of New York, Inc 110pp 16372.142 24X Fiche 50-000, B2/11/05, B208190245

B208190251 IE Info Notice B2-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance B2/11/18 Consolidated Edison Co of New York, Inc 109pp 16411.199 24X Fiche 50-000, B2/11/18, B208190251

8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Radiocis " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000, 82/11/26, 8208190256

8208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl
COBB, L J Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000, 82/11/30, 8208190257

8208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259

8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X Fiche 50-000, 82/12/03, 8208190261

8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16, 8208190267

8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27 " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X Fiche 50-000, 82/12/20, 8208190268

DOCKET STN-50-482 WOLF CREEK GENERATING STATION

A Application/construction stage documents & correspondence

8212140001 Addl response to FOIA request for five categories of documents re SEP Forwards documents listed in App A No documents located subj to Item 3 of request Review of remaining documents continuing Documents available in PDR
FELTON, J M Division of Rules and Records 82/11/03 GALLO, J Ishaq, Lincoln & Beale 2pp 16433 354 24X Fiche 50-000, 82/11/03, 8212140001

--8001280032 Forwards NRC Response to WH Ward request that NRC partially suspended CP SSE is adequately conservative Recommends that petition be denied
JACKSON, R E Geosciences Branch 80/01/04 PARR, O D Light Water Reactors Branch 3 7pp 16436 339 24X Fiche 50-000, 82/11/03, 8212140001

8212020005 Notification of 821214 meeting w/utls & SNUPPS in Bethesda, MD to discuss equipment qualification
EDISON, O E Licensing Branch 1 82/11/22 YOUNGBLOOD, B J Licensing Branch 1 4pp 16310 358 24X Fiche 50-000, 82/11/22, 8212020005

8212030127 Forwards application for amend to CPPR-147, extending const completion date to 860701
KOEESTER, O L Kansas Gas & Electric Co 82/11/24 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 16306 018 24X Fiche 50-482, 82/11/24, 8212030127

--8212030135 Application for amend to CPPR-147, extending const completion date to 860701
KOEESTER, O L Kansas Gas & Electric Co 82/11/24 2pp 16306 019 24X Fiche 50-482, 82/11/24, 8212030127

8212170288 Forwards Tech Spec revising visual exam, visual exam acceptance criteria & functional testing of snubbers
PETRICK, N A Standardized Nuclear Unit Power Plant System 82/12/15 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 16456 119 24X Fiche 50-000, 82/12/15, 8212170288

--8212170293 Proposed Tech Spec revising visual exam, visual exam acceptance criteria & functional testing of snubbers
* Standardized Nuclear Unit Power Plant System 82/12/15 Bpp 16456 120 24X Fiche 50-000, 82/12/15, 8212170288

8212280236 Forwards Revision 5 to QA programs for design & const
PETRICK, N A Standardized Nuclear Unit Power Plant System 82/12/22 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 16562 185 24X Fiche 50-000, 82/12/22, 8212280236

--8212280240 Revision 5 to QA programs for design & const
* Standardized Nuclear Unit Power Plant System 82/12/22 7pp 16562 186 24X Fiche 50-000, 82/12/22, 8212280236

C Utility Environmental Report (ER), amends & correspondence

8212270187 Forwards Revision 4 to environ rept - OL stage, deleting Chapters 1, 9, 11 & portion of Chapter 8, updating meteorology data in Chapters 2 & 6 & revising meteorological concentration analysis in Chapter 5 Certificate of Svc encl
KOEESTER, O L Kansas Gas & Electric Co 82/12/07 DENTON, H R Office of Nuclear Reactor Regulation, Director 7pp 16539 022 24X Fiche 50-482, 82/12/07, 8212270187

--8212270193 Revision 4 to environ rept - OL stage
* Kansas Gas & Electric Co 82/11/30 26pp 16539 029 24X Fiche 50-482, 82/12/07, 8212270187

F Security, medical, emergency & fire protection plans

8212070222 Advises of status of emergency operations facility activities Full operation expected after equipment delivery, installation & testing
KOEESTER, O L Kansas Gas & Electric Co 82/12/03 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 16336 318 24X Fiche 50-482, 82/12/03, 8212070222

8212270022 Forwards requests for addl info for review of Revision 9 to emergency plan Plan should be revised to reflect resolution of comments
YOUNGBLOOD, B J Licensing Branch 1 82/12/06 KOEESTER, O L Kansas Gas & Electric Co 19pp 16551 317 24X Fiche 50-482, 82/12/06, 8212270022

H General correspondence

8212170324 Notifies that util mgt organization was further revised on 821126 Nuclear activities responsibilities not affected
FSAR will be revised to reflect revision W/o encl announcement
KOEESTER, O L Kansas Gas & Electric Co 82/12/10 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 16453 190 24X Fiche 50-482, 82/12/10, 8212170324

I Advisory Committee on Reactor Safeguards reports & correspondence

8212010502 Summary of 265th ACRS meeting on 820506-08 in Washington, DC re Olinda restart safety evaluation, Wolf Creek OL review, Palisades SEP review, emergency response capability of plants & safety-related equipment qualification program
* ACRS - Advisory Committee on Reactor Safeguards 82/11/26 ACRS - Advisory Committee on Reactor Safeguards 605pp 16294 131 24X Fiche 50-000, 82/11/26, 8212010502

Q Inspection reports, IE Bulletins & correspondence

8208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BHR Plants." Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240

8212030109 Forwards IE Insp Rept 50-482/82-14 during Sept 1982 No noncompliance noted
SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs 82/11/02 KOEESTER, O L Kansas Gas & Electric Co 2pp 16303 029 24X Fiche 50-482, 82/11/02, 8212030109

--8212030115 IE Insp Rept 80-482/82-14 during Sept 1982, No noncompliance noted Major areas inspected followup on previous insp finding, observation of installation activities for RCPS piping & other piping sys
VANDEL, T E, JOHNSON, W D Division of Resident, Reactor Project & Engineering Programs 82/10/27 6pp 16303 031 24X Fiche 50-482, 82/11/02, 8212030109

8212030046 Forwards IE Insp Rept 50-482/82-15 on 821004-08, No noncompliance noted
SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs 82/11/03 KOEESTER, O L Kansas Gas & Electric Co 2pp 16307 150 24X Fiche 50-482, 82/11/03, 8212030046

--8212030058 IE Insp Rept 50-482/82-15 on 821004-08, No noncompliance noted Major areas inspected site tour, observation of work, review of records for welding & nondestructive exam of safety-related piping.
OILBERT, L D., JOHNSON, W D., HUNNICUTT, D M Division of Resident, Reactor Project & Engineering Programs 82/11/02 9pp 16307 152 24X Fiche 50-482, 82/11/03, 8212030046

DOCKETED ITEMS

8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards
82/11/05 Consolidated Edison Co of New York, Inc 110pp
16372 142 24X Fiche 50-000, 82/11/05, 8208190245

8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18
Consolidated Edison Co of New York, Inc 107pp 16411 179 24X
Fiche 50-000, 82/11/18, 8208190251

8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc
127pp 16411 065 24X Fiche 50-000, 82/11/26, 8208190256

8208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards
82/11/30 Consolidated Edison Co of New York, Inc 356pp.
16387 028 24X Fiche 50-000, 82/11/30, 8208190257

8208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc
113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259

8208190261 IE Info Notice 82-48, "Failures of Agestat CR 0095 Relay Sockets " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03
Consolidated Edison Co of New York, Inc 110pp 16462 064 24X
Fiche 50-000, 82/12/03, 8208190261

8212170288 Forwards Tech Spec revising visual exam, visual exam acceptance criteria & functional testing of snubbers
PETRICK, N A Standardized Nuclear Unit Power Plant System
82/12/15 DENTON, H R Office of Nuclear Reactor Regulation,
Director 1p 16456 119 24X Fiche 50-000, 82/12/15, 8212170288

--8212170293 Proposed Tech Spec revising visual exam, visual exam acceptance criteria & functional testing of snubbers
* Standardized Nuclear Unit Power Plant System 82/12/15 8pp
16456 120 24X Fiche 50-000, 82/12/15, 8212170293

8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc
127pp 16428 191 24X Fiche 50-000, 82/12/16, 8208190267

8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27 " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20
Consolidated Edison Co of New York, Inc. 108pp 16428 293 24X
Fiche 50-000, 82/12/20, 8208190268

B Reportable occurrences, LERs & related correspondence

8212210115 Final deficiency rept re malfunction in 4E IE 480-volt AKR 30/50 breakers Initially reported on 821108 Replacement spring lever will have ear on end to preclude breaker failures Also reported per Part 21
KOESTER, O L Kansas Gas & Electric Co 82/12/09 6EIDLE, W C
Division of Resident, Reactor Project & Engineering Programs 2pp
16485 123 24X Fiche 50-482, 82/12/09, 8212210115

8212280338 Interim deficiency rept re inadequate matl control for special scope items Initially reported on 820514 Numerous matl items identified prior to beginning analysis of installed special scope items. Next rept expected by 830601
KOESTER, O L Kansas Gas & Electric Co 82/12/13 SIEDLE, W C
Division of Resident, Reactor Project & Engineering Programs 1p
16561 052 24X Fiche 50-482, 82/12/13, 8212280338

8212290249 PNO-IV-82-051 on 821222, loose parts found in secondary side of steam generators B & C during insg inside surfaces of steam generators also found covered within layer of grit-type matl. No immediate safety concern identified
JOHNSON, W D, SCHUM, W S Region 4, Office of Director 82/12/24
1p 16582:180 24X Fiche: 50-482, 82/12/24, 8212290249

DOCKET STN-50-483 CALLAWAY PLANT, UNIT 1

A Application/construction stage documents & correspondence

8212020005 Notification of 821214 meeting w/utls & SNUPPS in Bethesda, MD to discuss equipment qualification
EDISON, O E Licensing Branch 1 82/11/22 YOUNGBLOOD, B J
Licensing Branch 1 4pp 16310 358 24X Fiche 50-000, 82/11/22, 8212020005

8212270418 Responds to FOIA request for documents re proposed revision &/or update to reactor safety study referred to in NUREG-0784, Chapter 10 as RS II & all documents pertaining to reactor cooling methods Forwards documents listed in app
FELTON, J M Division of Rules and Records 82/11/26 SHOLLY, S C
Union of Concerned Scientists 3pp 16549 233 24X
Fiche 50-000, 82/11/26, 8212270418

--8211050027 Forwards summary of semiscale test results & advises that board notification re test results issued w/o encl
NOVAK, T M Assistant Director for Licensing 82/09/24
Division of Licensing 1p 16549 278 24X Fiche 50-000, 82/11/26, 8212270418

8212220440 Board Notifications 82-125 & 82-125A forwards info re H Etherington evaluation of flow blockage during natural circulation of PHRs Results do not adversely impact present position on reliance on natural circulation
NOVAK, T M Assistant Director for Licensing 82/12/14 Atomic
Safety and Licensing Board Panel 5pp 16523 135 24X
Fiche 50-000, 82/12/14, 8212220440

8212220461 Board Notification 82-124 forwards RJ Mattson 821123 memo re Semiscale 8-UT-8 test results Phenomena of core level depression & loop seal clearing may be more complex than previously supposed
NOVAK, T M Assistant Director for Licensing 82/12/14 Atomic
Safety and Licensing Board Panel 7pp 16523 169 24X
Fiche 50-000, 82/12/14, 8212220461

8212170288 Forwards Tech Spec revising visual exam, visual exam acceptance criteria & functional testing of snubbers
PETRICK, N A Standardized Nuclear Unit Power Plant System
82/12/15 DENTON, H R Office of Nuclear Reactor Regulation,
Director 1p 16456 119 24X Fiche 50-000, 82/12/15, 8212170288

--8212170293 Proposed Tech Spec revising visual exam, visual exam acceptance criteria & functional testing of snubbers
* Standardized Nuclear Unit Power Plant System 82/12/15 8pp
16456 120 24X Fiche 50-000, 82/12/15, 8212170288

8212280236 Forwards Revision 5 to QA programs for design & const
PETRICK, N A Standardized Nuclear Unit Power Plant System
82/12/22 DENTON, H R Office of Nuclear Reactor Regulation,
Director 1p 16562 185 24X Fiche 50-000, 82/12/22, 8212280236

--8212280240 Revision 5 to QA programs for design & const
* Standardized Nuclear Unit Power Plant System 82/12/22 9pp
16562 186 24X Fiche 50-000, 82/12/22, 8212280236

F Security, medical, emergency & fire protection plans

8212080256 Forwards info re emergency operations facility for NRC survey
SCHNELL, D F Union Electric Co 82/12/03 DENTON, H R Office of
Nuclear Reactor Regulation, Director 4pp 16384 179 24X
Fiche 50-483, 82/12/03, 8212080256

8212280426 Forwards 821027 rept in response to NRC request for finding & determination on adequacy of offsite plans & preparedness for plant insufficient factual basis available to render finding & determination
KRIMM, R W Federal Emergency Management Agency 82/12/15
GRIMES, B Division of Emergency Preparedness 3pp 16559 025 24X
Fiche 50-483, 82/12/15, 8212280426

8212220306 Discusses layout of communications equipment required in control room, onsite technical support ctr & near-site emergency operations facility
KEPPLER, J G Region 3, Office of Director 82/12/14
Commonwealth Edison Co 3pp 16503 351 24X Fiche 50-000, 82/12/16, 8212220306

G Adjudicatory correspondence

B212090093 Memorandum & order ruling on contentions Contentions 1,2,4 through 10, 13 & 14 & portions of 3 & 15 admitted
Contention 12 denied Addl info on Contention 11 required
BRIGHT, G O, KLINE, J R, GLEASON, J P Atomic Safety and Licensing Board Panel 82/12/07 Reqd, J G 6pp 16357 168 24X
Fiche 50-483, 82/12/07, B212090093

B212130197 Memorandum & order granting applicant motion to compel JO Reqd to answer listed portions of util B21020 interrogatories
KLINE, J R, GLEASON, J P Atomic Safety and Licensing Board Panel 82/12/09 Union Electric Co 3pp 16396 174 24X
Fiche 50-483, 82/12/09, B212130197

B212150026 Partial initial decision ruling on GA program & const defects No serious safety, environ or common defense & security matters exist All GA matters in controversy resolved in favor of authorizing facility operation
BRIGHT, G O, KLINE, J R, GLEASON, J P Atomic Safety and Licensing Board Panel 82/12/13 121pp 16421 009 24X
Fiche 50-483, 82/12/13, B212150026

B212210274 Answers to interrogatories per ASLB B21213 order Certificate of Svc encl
REED, J G Reqd, J G 82/12/13 Union Electric Co 8pp 16483 223 24X Fiche 50-483, 82/12/13, B212210274

B212280179 Motion for enlargement of time until B20131 to file exceptions to ASLB B21214 partial initial decision Delay needed since decision is extensive & counsel is involved w/ litigation in federal courts Certificate of Svc encl
CHACKES, K M Joint Intervenor-Callaway CHACKES, K M Chackes & Moore 82/12/23 Atomic Safety and Licensing Appeal Panel 3pp 16562 314 24X Fiche 50-483, 82/12/23, B212280179

B212300226 Calls attention to errors on witness list (App I) to B21213 partial initial decision BC Tye & JV Laux erroneously identified as employees of Bechtel Svc list encl
BAXTER, T A Shaw, Pittman, Potts & Trowbridge BAXTER, T A Union Electric Co 82/12/28 GLEASON, J P, BRIGHT, G O, KLINE, J R Atomic Safety and Licensing Board Panel 3pp 16598 001 24X
Fiche 50-483, 82/12/28, B212300226

J Insurance & indemnity information

B212280334 Forwards Endorsement 11 to NELIA Policy NF-264
NADEL, M Marsh & McLennan, Inc, M & M Nuclear Consultants, Inc Div 82/12/20 SALTZMAN, J Assistant Director for State & License Relations 2pp 16561 144 24X Fiche 50-483, 82/12/20, B212280334

Q Inspection reports, IE Bulletins & correspondence

B208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel Recirculation Sys Piping at BHR Plants " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, B208190240

B208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model B01 & Model B02 Thermoluminescent Dosimeters " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000, 82/11/05, B208190245

B212010049 Forwards NRR input for SALP for B11001-B21001 No comments received on draft SALP input
YOUNGBLOOD, B J Licensing Branch 1 82/11/17 EISENHUT, D O Division of Licensing 3pp 16271 333 24X Fiche 50-483, 82/11/17, B212010049

B208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X
Fiche 50-000, 82/11/18, B208190251

B208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000, 82/11/26, B208190256

B212100234 Forwards IE Insp Rept 50-483/82-15 on B21001-31 & notice of violation
SPESSARD, R L Division of Project & Resident Programs 82/11/26 SCHNELL, D F Union Electric Co 2pp 16376 192 24X
Fiche 50-483, 82/11/26, B212100234

--B212100238 Notice of violation from insp on B21001-31
SPESSARD, R L Division of Project & Resident Programs 82/11/26 1p 16376 194 24X Fiche 50-483, 82/11/26, B212100234

--B212100242 IE Insp Rept 50-483/82-15 on B21001-31 Noncompliance noted inadequate design of Class IE conduit supports
NEISLER, J H, KONKLIN, J E Region 3, Office of Director 82/11/26 5pp 16376 195 24X Fiche 50-483, 82/11/26, B212100234

B208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000, 82/11/30, B208190257

B208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, B208190259

B208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X
Fiche 50-000, 82/12/03, B208190261

B212170205 Forwards IE Insp Rept 50-483/82-16 on B21026-29 No noncompliance noted
LITTLE, H S Division of Engineering & Technical Programs 82/12/03 SCHNELL, D F Union Electric Co 2pp 16459 218 24X
Fiche 50-483, 82/12/03, B212170205

--B212170286 IE Insp Rept 50-483/82-16 on B21026-29 No noncompliance noted Major areas inspected items identified during previous insps
LOVE, R S, WILLIAMS, C C Division of Engineering & Technical Programs 82/12/01 5pp 16459 220 24X Fiche 50-483, 82/12/03, B212170205

B212170288 Forwards Tech Spec revising visual exam, visual exam acceptance criteria & functional testing of snubbers
PETRICK, M A Standardized Nuclear Unit Power Plant System 82/12/15 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 16456 119 24X Fiche 50-000, 82/12/15, B212170288

--B212170293 Proposed Tech Spec revising visual exam, visual exam acceptance criteria & functional testing of snubbers
Standardized Nuclear Unit Power Plant System 82/12/15 8pp 16456 120 24X Fiche 50-000, 82/12/15, B212170288

B208190267 IE Info Notice 82-49, "Correction For Sample Conditions for Air & Gas Monitoring " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16, B208190267

B208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27 " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X
Fiche 50-000, 82/12/20, B208190268

S Reportable occurrences, LERs & related correspondence

B212020259 Final deficiency rept re level on closing spring interlock of GE IE 480-volt AKR breakers overtraveling armature linkage pin Initially reported on B21105 GE will replace levers Also reportable per Part 21
SCHNELL, D F Union Electric Co 82/11/19 KEPPLER, J O Region 3, Office of Director 1p 16279 354 24X Fiche 50-483, 82/11/19, B212020259

T Hearing transcripts on non-antitrust matters

B212270204 Memorandum & order making encl transcript corrections to evidentiary record of proceeding
GLEASON, J P Atomic Safety and Licensing Board Panel 82/12/22 16pp 16534 338 24X Fiche 50-483, 82/12/22, B212270204

DOCKETED ITEMS

DOCKET STN-50-485 STERLING POWER NUCLEAR PROJECT, UNIT 1

Q Inspection reports, IE Bulletins & correspondence

8208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BHR Plants " Svc list encl
 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240

8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list encl
 COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000, 82/11/05, 8208190245

8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl
 JORDAN, E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X Fiche 50-000, 82/11/18, 8208190251

8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list encl
 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000, 82/11/26, 8208190256

8208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl
 COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000, 82/11/30, 8208190257

8208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl
 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259

8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl
 JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X Fiche 50-000, 82/12/03, 8208190261

8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16, 8208190267

8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27 " Svc list encl
 JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X Fiche 50-000, 82/12/20, 8208190268

DOCKET STN-50-486 CALLAWAY PLANT, UNIT 2

F Security, medical, emergency & fire protection plans

8212280426 Forwards 821027 rept in response to NRC request for finding & determination on adequacy of offsite plans & preparedness for plant insufficient factual basis available to render finding & determination
 KRIMM, R W Federal Emergency Management Agency 82/12/15
 GRIMES, D Division of Emergency Preparedness 3pp 16389 025 24X Fiche 50-483, 82/12/15, 8212280426

8212280306 Discusses layout of communications equipment required in control room, onsite technical support ctr & near-site emergency operations facility
 KEPPLER, J G Region 3, Office of Director 82/12/16
 Commonwealth Edison Co 3pp 16803 351 24X Fiche 50-000, 82/12/16, 8212280306

DOCKET STN-50-488 PERKINS NUCLEAR STATION, UNIT 1

Q Inspection reports, IE Bulletins & correspondence

8208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BHR Plants " Svc list encl
 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240

8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list encl
 COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000, 82/11/05, 8208190245

8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl
 JORDAN, E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X Fiche 50-000, 82/11/18, 8208190251

8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list encl
 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000, 82/11/26, 8208190256

8208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl
 COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000, 82/11/30, 8208190257

8208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl
 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259

8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl
 JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X Fiche 50-000, 82/12/03, 8208190261

8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16, 8208190267

8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27 " Svc list encl
 JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X Fiche 50-000, 82/12/20, 8208190268

DOCKET STN-50-489 PERKINS NUCLEAR STATION, UNIT 2

Q Inspection reports, IE Bulletins & correspondence

8208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BHR Plants " Svc list encl
 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240

8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list encl
 COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000, 82/11/05, 8208190245

8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl
 JORDAN, E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X Fiche 50-000, 82/11/18, 8208190251

8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list encl
 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000, 82/11/26, 8208190256

8208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl
 COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000, 82/11/30, 8208190257

8208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl
 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259

8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay
Sockets " Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance 82/12/03
Consolidated Edison Co. of New York, Inc 110pp 16462 064 24X
Fiche 50-000, 82/12/03, 8208190261

8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for
Air & Gas Monitoring " Svc list encl
DEYOUNG, R. C. Director's Office, Office of Inspection and
Enforcement 82/12/16 Consolidated Edison Co. of New York, Inc
127pp 16628 191 24X Fiche 50-000, 82/12/16, 8208190267

8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage
Relays Type ITE-27 " Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance 82/12/20
Consolidated Edison Co. of New York, Inc 108pp 16628 293 24X
Fiche 50-000, 82/12/20, 8208190268

DOCKET STN-50-490 PERKINS NUCLEAR STATION, UNIT 3

G Inspection reports, IE Bulletins & correspondence

8208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-
Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping
at BWR Plants " Svc list encl
DEYOUNG, R. C. Director's Office, Office of Inspection and
Enforcement 82/10/28 Consolidated Edison Co. of New York, Inc
112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240

8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model
801 & Model 802 Thermoluminescent Dosimeters " Svc list
encl
COBB, L. I. Division of Fuel Facilities, Materials & Safeguards
82/11/05 Consolidated Edison Co. of New York, Inc 110pp
16372 142 24X Fiche 50-000, 82/11/05, 8208190245

8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan
Exercise Requirements " Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance 82/11/18
Consolidated Edison Co. of New York, Inc 109pp 16411 199 24X
Fiche 50-000, 82/11/18, 8208190251

8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination
Padlocks " Svc list encl
DEYOUNG, R. C. Director's Office, Office of Inspection and
Enforcement 82/11/26 Consolidated Edison Co. of New York, Inc
127pp 16411 065 24X Fiche 50-000, 82/11/26, 8208190256

8208190257 IE Info Notice 82-47, "Transportation of Type A Quantities
of Non-Fissile Radioactive Matl " Svc list encl
COBB, L. I. Division of Fuel Facilities, Materials & Safeguards
82/11/30 Consolidated Edison Co. of New York, Inc 356pp
16387 028 24X Fiche 50-000, 82/11/30, 8208190257

8208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment
Electrical Penetration Assemblies " Svc list encl
DEYOUNG, R. C. Director's Office, Office of Inspection and
Enforcement 82/12/03 Consolidated Edison Co. of New York, Inc
113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259

8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay
Sockets " Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance 82/12/03
Consolidated Edison Co. of New York, Inc 110pp 16462 064 24X
Fiche 50-000, 82/12/03, 8208190261

8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for
Air & Gas Monitoring " Svc list encl
DEYOUNG, R. C. Director's Office, Office of Inspection and
Enforcement 82/12/16 Consolidated Edison Co. of New York, Inc
127pp 16628 191 24X Fiche 50-000, 82/12/16, 8208190267

8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage
Relays Type ITE-27 " Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance 82/12/20
Consolidated Edison Co. of New York, Inc 108pp 16628 293 24X
Fiche 50-000, 82/12/20, 8208190268

DOCKET STN-50-491 CHEROKEE NUCLEAR STATION, UNIT 1

G Inspection reports, IE Bulletins & correspondence

8208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-
Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping
at BWR Plants " Svc list encl
DEYOUNG, R. C. Director's Office, Office of Inspection and
Enforcement 82/10/28 Consolidated Edison Co. of New York, Inc
112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240

8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model
801 & Model 802 Thermoluminescent Dosimeters " Svc list
encl
COBB, L. I. Division of Fuel Facilities, Materials & Safeguards
82/11/05 Consolidated Edison Co. of New York, Inc 110pp
16372 142 24X Fiche 50-000, 82/11/05, 8208190245

8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan
Exercise Requirements " Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance 82/11/18
Consolidated Edison Co. of New York, Inc 109pp 16411 199 24X
Fiche 50-000, 82/11/18, 8208190251

8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination
Padlocks " Svc list encl
DEYOUNG, R. C. Director's Office, Office of Inspection and
Enforcement 82/11/26 Consolidated Edison Co. of New York, Inc
127pp 16411 065 24X Fiche 50-000, 82/11/26, 8208190256

8208190257 IE Info Notice 82-47, "Transportation of Type A Quantities
of Non-Fissile Radioactive Matl " Svc list encl
COBB, L. I. Division of Fuel Facilities, Materials & Safeguards
82/11/30 Consolidated Edison Co. of New York, Inc 356pp
16387 028 24X Fiche 50-000, 82/11/30, 8208190257

8208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment
Electrical Penetration Assemblies " Svc list encl
DEYOUNG, R. C. Director's Office, Office of Inspection and
Enforcement 82/12/03 Consolidated Edison Co. of New York, Inc
113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259

8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay
Sockets " Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance 82/12/03
Consolidated Edison Co. of New York, Inc 110pp 16462 064 24X
Fiche 50-000, 82/12/03, 8208190261

8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for
Air & Gas Monitoring " Svc list encl
DEYOUNG, R. C. Director's Office, Office of Inspection and
Enforcement 82/12/16 Consolidated Edison Co. of New York, Inc
127pp 16628 191 24X Fiche 50-000, 82/12/16, 8208190267

8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage
Relays Type ITE-27 " Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance 82/12/20
Consolidated Edison Co. of New York, Inc 108pp 16628 293 24X
Fiche 50-000, 82/12/20, 8208190268

DOCKET STN-50-492 CHEROKEE NUCLEAR STATION, UNIT 2

G Inspection reports, IE Bulletins & correspondence

8208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-
Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping
at BWR Plants " Svc list encl
DEYOUNG, R. C. Director's Office, Office of Inspection and
Enforcement 82/10/28 Consolidated Edison Co. of New York, Inc
112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240

8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model
801 & Model 802 Thermoluminescent Dosimeters " Svc list
encl
COBB, L. I. Division of Fuel Facilities, Materials & Safeguards
82/11/05 Consolidated Edison Co. of New York, Inc 110pp
16372 142 24X Fiche 50-000, 82/11/05, 8208190245

8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan
Exercise Requirements " Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance 82/11/18
Consolidated Edison Co. of New York, Inc 109pp 16411 199 24X
Fiche 50-000, 82/11/18, 8208190251

8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination
Padlocks " Svc list encl
DEYOUNG, R. C. Director's Office, Office of Inspection and
Enforcement 82/11/26 Consolidated Edison Co. of New York, Inc
127pp 16411 065 24X Fiche 50-000, 82/11/26, 8208190256

8208190257 IE Info Notice 82-47, "Transportation of Type A Quantities
of Non-Fissile Radioactive Matl " Svc list encl
COBB, L. I. Division of Fuel Facilities, Materials & Safeguards
82/11/30 Consolidated Edison Co. of New York, Inc 356pp
16387 028 24X Fiche 50-000, 82/11/30, 8208190257

8208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment
Electrical Penetration Assemblies " Svc list encl
DEYOUNG, R. C. Director's Office, Office of Inspection and
Enforcement 82/12/03 Consolidated Edison Co. of New York, Inc
113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259

DOCKETED ITEMS

B208190261 IE Info Notice B2-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03
Consolidated Edison Co of New York, Inc 110pp 16462 064 24X
Fiche 50-000, 82/12/03, B208190261

B208190267 IE Info Notice B2-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16, B208190267

B208190268 IE Info Notice B2-50, "Mod of Solid State AC Undervoltage Relays Type 17E-27 " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X
Fiche 50-000, 82/12/20, B208190268

DOCKET STN-50-493 CHEROKEE NUCLEAR STATION, UNIT 3

G Inspection reports, IE Bulletins & correspondence

B208190240 IE Bulletin B2-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel Recirculation Sys Piping at BWR Plants " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, B208190240

B208190245 IE Info Notice B2-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000, 82/11/05, B208190245

B208190251 IE Info Notice B2-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X
Fiche 50-000, 82/11/18, B208190251

B208190256 IE Info Notice B2-46, "Defective & Obsolete Combination Radios " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000, 82/11/26, B208190256

B208190257 IE Info Notice B2-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000, 82/11/30, B208190257

B208190259 IE Bulletin B2-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, B208190259

B208190261 IE Info Notice B2-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X
Fiche 50-000, 82/12/03, B208190261

B208190267 IE Info Notice B2-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16, B208190267

B208190268 IE Info Notice B2-50, "Mod of Solid State AC Undervoltage Relays Type 17E-27 " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X
Fiche 50-000, 82/12/20, B208190268

DOCKET STN-50-498 SOUTH TEXAS PROJECT, UNIT 1

A Application/construction stage documents & correspondence

B212020254 Forwards FSAR effective page listing, through Amend 26
WISENBURG, M R Houston Lighting & Power Co 82/11/09 NOVAK, T H Assistant Director for Licensing 73pp 16288 257 24X
Fiche 50-498, 82/11/09, B212020254

B21230066 Generic Ltr B2-27 to all BWR licensees of operating reactors except LACBWR, Big Rock Point, Dresden 1, Humboldt Bay, applicants for OL & holders of CP re transmittal of NUREG-0763 & NUREG-0763 Svc list encl w/o stated encl
EISENHUT, D O Division of Licensing 82/11/15 General Public Utilities - OPU Service Corp 22pp 16387 004 24X
Fiche 50-000, 82/11/15, B21230066

B212010414 Notification of B21207 meeting w/util & Bechtel in Bethesda, MD to discuss Bechtel review & assessment of Brown & Root soil structure interaction analysis
SCHIERLING, H Licensing Branch 3 82/11/18 KNIGHTON, G W Licensing Branch 3 3pp 16267 339 24X Fiche 50-498, 82/11/18, B212010414

B212010443 Summary of B21005 meeting w/util, Bechtel, Westinghouse & Torrey Pines in Houston, TX re control room design review program plan
SELLS, D Licensing Branch 3 82/11/18 Licensing Branch 3 71pp 16267 209 24X Fiche 50-498, 82/11/18, B212010443

B212170450 Notification of B21215 meeting w/util in Houston, TX & B21216 site visit to discuss status of project, including const activities
SCHIERLING, H Licensing Branch 3 82/12/07 KNIGHTON, G W Licensing Branch 3 3pp 16478 158 24X Fiche 50-498, 82/12/07, B212170450

B212220440 Board Notifications B2-125 & B2-125A forwards info re H Etherington evaluation of flow blockage during natural circulation of PWRs Results do not adversely impact present position on reliance on natural circulation
NOVAK, T H Assistant Director for Licensing 82/12/14 Atomic Safety and Licensing Board Panel 5pp 16523 135 24X
Fiche 50-000, 82/12/14, B212220440

B212220461 Board Notification B2-124 forwards RJ Mattson B21123 memo re Semicale S-UT-B test results Phenomena of core level depression & loop seal clearing may be more complex than previously supposed
NOVAK, T H Assistant Director for Licensing 82/12/14 Atomic Safety and Licensing Board Panel 7pp 16523 169 24X
Fiche 50-000, 82/12/14, B212220461

B212170120 Forwards Amend B to application for OLs, SEC info, financial statements & annual financial repts
GOLDBERG, J H Houston Lighting & Power Co 82/12/15 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 16451 001 24X
Fiche 50-498, 82/12/15, B212170120

--B212170124 Amend B to application for OLs,
GOLDBERG, J H Houston Lighting & Power Co 82/12/15 34pp 16451 002 24X Fiche 50-498, 82/12/15, B212170120

--B212170128 Annual Financial Rept, yr ending B20131
BIDDES, G SPRUCE, J K San Antonio City Public Service Board 82/12/15 24pp 16451 135 24X Fiche 50-498, 82/12/15, B212170120

--B212170131 Annual Financial Rept 1981 SEC info encl
BORCHERT, T H Central Power & Light 82/03/01 125pp 16451 158 24X Fiche 50-498, 82/12/15, B212170120

--B212170133 Annual Financial Rept 1981
JORDAN, D D Houston Industries, Inc 82/03/22 52pp 16451 283 24X Fiche 50-498, 82/12/15, B212170120

C Utility Environmental Report (ER), amends & correspondence

B212140381 Forwards Amend 6 to environ rept Amend describes high voltage dc terminal facility to be located onsite
GOLDBERG, J H Houston Lighting & Power Co 82/12/10 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 16401 248 24X Fiche 50-498, 82/12/10, B212140381

--B212140383 Amend 6 to environ rept
GOLDBERG, J H Houston Lighting & Power Co 82/12/10 21pp 16401 250 24X Fiche 50-498, 82/12/10, B212140381

G Adjudicatory correspondence

B212060083 Comments on plant tour & general licensing process & warns that Commissioner concern for fairness, legality & truth is not shared by remainder of NRC
SINKIN, L Affiliation Unknown 82/11/20, ASSELSTINE, J K Commissioners 3pp 16314 322 24X Fiche 50-498, 82/11/20, B212060083

8212100125 Motion to reopen record to take evidence on TX Public Util Commission rulings finding mismanagement of plant TX Commission special expertise should be heard Issue relevant to NRC hearings Certificate of Svc encl
BINKIN, L. Citizens Concerned About Nuclear Power, Inc 82/12/06
Atomic Safety and Licensing Board Panel 13pp 16376 029 24X
Fiche 50-498, 82/12/06, 8212100125

8212280279 Advises, per DL Lex testimony, that util & Bechtel executed contract providing for performance of AE & const mgt svcs Certificate of Svc encl Related correspondence
NEWMAN, J R Lowenstein, Newman, Reis, Axelrad & Toll NEWMAN, J R
Houston Lighting & Power Co 82/12/21 BECHHOEFER, C, LAMB, J C
HILL, E E Atomic Safety and Licensing Board Panel 3pp 16561 225
24X Fiche 50-498, 82/12/21, 8212280279

8212280282 Response in opposition to Citizens Concerned About Nuclear Power 821206 motion to reopen record Receipt of evidence would involve ASLB in nonpertinent ratemaking matters Certificate of Svc encl
NEWMAN, J R Houston Lighting & Power Co NEWMAN, J R
Lowenstein, Newman, Reis, Axelrad & Toll 82/12/21 Atomic Safety and Licensing Board Panel 8pp 16561 217 24X
Fiche 50-498, 82/12/21, 8212280282

8212290003 Response in opposition to Citizens Concerned About Nuclear Power 821206 motion to reopen Phase I record Nexus between TX Public Util Commission findings on util financial ability & issue of util competence not shown w/Certificate of Svc
OUTIERRE, J M Hearing Branch 3 82/12/27 Atomic Safety and Licensing Board Panel 8pp 16583 240 24X Fiche 50-498, 82/12/27, 8212290003

I Financial information

8212170120 Forwards Amend 8 to application for OLS, BEC info, financial statements & annual financial repts
QOLDBERG, J H Houston Lighting & Power Co 82/12/15 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 16451 001 24X
Fiche 50-498, 82/12/15, 8212170120

--8212170128 Annual Financial Rept, yr ending 820131
B1408, O SPRUCE, J K San Antonio City Public Service Board
82/12/15 24pp 16491 133 24X Fiche 50-498, 82/12/15, 8212170120

--8212170131 Annual Financial Rept 1981 BEC info encl
BORCHERT, M L Central Power & Light 82/03/01 123pp
16451 158 24X Fiche 50-498, 82/12/15, 8212170120

--8212170133 Annual Financial Rept 1981
JORDAN, D D Houston Industries, Inc 82/03/22 52pp 16451 283
24X Fiche 50-498, 82/12/15, 8212170120

K Utility Final Safety Analysis Report (FSAR) & amends

8212070262 Forwards Amend 27 to FSAR, incorporating organizational changes, QA revisions, Tech Spec deletions, revised responses to NRC questions & miscellaneous FSAR text revisions & editorial changes
QOLDBERG, J H Houston Lighting & Power Co 82/11/29 DENTON, H R
Office of Nuclear Reactor Regulation, Director 4pp 16339 159
24X Fiche 50-498, 82/11/29, 8212070262

--8212070263 Amend 27 to FSAR
* Houston Lighting & Power Co 82/11/29 325pp 16339:163 24X
Fiche 50-498, 82/11/29, 8212070262

8212090377 Forwards Amend 28 to FSAR, describing high voltage direct current (HVDC) terminal facility to be located at site Info re removal of personnel from HVDC facility will be included in emergency plan FSAR Chapter 8 will be updated
QOLDBERG, J H Houston Lighting & Power Co 82/12/06 DENTON, H R
Office of Nuclear Reactor Regulation, Director 4pp 16364 195
24X Fiche 50-498, 82/12/06, 8212090377

--8212090382 Amend 28 to FSAR
* Houston Lighting & Power Co 82/12/06 42pp 16364:199 24X
Fiche 50-498, 82/12/06, 8212090377

Q. Inspection reports, IE Bulletins & correspondence

8208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462:163 24X Fiche 50-000, 82/10/28, 8208190240.

8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000, 82/11/05, 8208190245

8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X
Fiche 50-000, 82/11/18, 8208190251

8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000, 82/11/26, 8208190256

8208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 336pp 16387 028 24X Fiche 50-000, 82/11/30, 8208190257

8208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259

8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X
Fiche 50-000, 82/12/03, 8208190261

8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16, 8208190267

8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27 " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X
Fiche 50-000, 82/12/20, 8208190268

B Reportable occurrences, LERs & related correspondence

8212030100 Eighth interim deficiency rept re breakdown in quality program-procurement cycle of purchased matls Initially reported on 800613, Bechtel assessment continuing Next rept will be submitted by 830403
OPREA, O W Houston Lighting & Power Co 82/11/19 COLLINS, J T
Region 4, Office of Director 4pp 16304 243 24X
Fiche 50-498, 82/11/19, 8212030100

8212270172 Suppl to final deficiency rept re structural steel beam to column connection design Initially reported on 800924 Bechtel method of analysis & design in final phase summarized
OPREA, O W Houston Lighting & Power Co 82/12/16 COLLINS, J T
Region 4, Office of Director 10pp 16538 023 24X
Fiche 50-498, 82/12/16, 8212270172

8212290202 Sixth interim deficiency rept re computer verification program Initially reported on 810508 Bechtel method for reviewing Brown & Root, Inc computer calculations established & results discussed Next rept expected by 830512
OPREA, O W Houston Lighting & Power Co 82/12/22 COLLINS, J T
Region 4, Office of Director 4pp 16578 048 24X
Fiche 50-498, 82/12/22, 8212290202

DOCKET BYN-50-499 SOUTH TEXAS PROJECT, UNIT 2

A Application/construction stage documents & correspondence

8212020254 Forwards FSAR effective page listing, through Amend 26
WISNEBRO, H R Houston Lighting & Power Co 82/11/09 NOVAK, T H
Assistant Director for Licensing, 73pp 16288 257 24X
Fiche 50-498, 82/11/09, 8212020254

821230066 Generic Ltr 82-27 to all BWR licensees of operating reactors except LACBWR, Big Rock Point, Dresden 1, Humboldt Bay, applicants for OL & holders of CP re transmittal of NUREG-0763 & NUREG-0783 Svc list encl w/o stated encl
EISENHUT, D O Division of Licensing, 82/11/15 General Public Utilities - CPU Service Corp 22pp 16387 004 24X
Fiche 50-000, 82/11/15, 821230066

DOCKETED ITEMS

B212010414 Notification of B21207 meeting w/util & Bechtel in Bethesda, MD to discuss Bechtel review & assessment of Brown & Root soil structure interaction analysis
SCHIERLING, H Licensing Branch 3 82/11/18 KNIGHTON, G W
Licensing Branch 3 3pp 16267 359 24X Fiche 50-498, 82/11/18, B212010414

B212010443 Summary of B21005 meeting w/util, Bechtel, Westinghouse & Torrey Pines in Houston, TX re control room design review program plan
SELLS, D Licensing Branch 3 82/11/18 Licensing Branch 3
71pp 16267 209 24X Fiche 50-498, 82/11/18, B212010443

B212170450 Notification of B21215 meeting w/util in Houston, TX & B21216 site visit to discuss status of project, including const activities
SCHIERLING, H Licensing Branch 3 82/12/07 KNIGHTON, G W
Licensing Branch 3 3pp 16478 158 24X Fiche 50-498, 82/12/07, B212170450

B21220440 Board Notifications B2-125 & B2-125A forwards info re H Etherington evaluation of flow blockage during natural circulation of PWRs Results do not adversely impact present position on reliance on natural circulation
NOVAK, T M Assistant Director for Licensing 82/12/14 Atomic Safety and Licensing Board Panel 8pp 16523 135 24X Fiche 50-000, 82/12/14, B21220440

B21220461 Board Notification B2-124 forwards RJ Mattson B21123 memo re Semicale S-UT-B test results Phenomena of core level depression & loop seal clearing may be more complex than previously supposed
NOVAK, T M Assistant Director for Licensing 82/12/14 Atomic Safety and Licensing Board Panel 7pp 16523 169 24X Fiche 50-000, 82/12/14, B21220461

B212170120 Forwards Amend B to application for DLs, SEC info, financial statements & annual financial repts
GOLDBERG, J H Houston Lighting & Power Co 82/12/15 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 16451 001 24X Fiche 50-498, 82/12/15, B212170120

--B212170124 Amend B to application for DLs
GOLDBERG, J H Houston Lighting & Power Co 82/12/15 34pp 16451 002 24X Fiche 50-498, 82/12/15, B212170120

C Utility Environmental Report (ER), amends & correspondence

B212140381 Forwards Amend 6 to environ rept Amend describes high voltage dc terminal facility to be located onsite
GOLDBERG, J H Houston Lighting & Power Co 82/12/10 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 16401 248 24X Fiche 50-498, 82/12/10, B212140381

--B212140383 Amend 6 to environ rept
GOLDBERG, J H Houston Lighting & Power Co 82/12/10 21pp 16401 250 24X Fiche 50-498, 82/12/10, B212140381

G Adjudicatory correspondence

B212060083 Comments on plant tour & general licensing process & warns that Commissioner concern for fairness, legality & truth is not shared by remainder of NRC
STINKIN, L Affiliation Unknown 82/11/20 ASSELSTINE, J K Commissioners 3pp 16314 322 24X Fiche 50-498, 82/11/20, B212060083

B212100123 Motion to reopen record to take evidence on TX Public Util Commission rulings finding mismanagement of plant TX
Commission special expertise should be heard Issue relevant to NRC hearings Certificate of Svc encl
STINKIN, L Citizens Concerned About Nuclear Power, Inc 82/12/06 Atomic Safety and Licensing Board Panel 13pp 16376 029 24X Fiche 50-498, 82/12/06, B212100123

B212280279 Adviser per BL Lex testimony, that util & Bechtel executed contract providing for performance of AE & const mgt svcs Certificate of Svc encl Related correspondence
NEWMAN, J R Lowenstein, Newman, Reis, Axelrad & Toll NEWMAN, J R Houston Lighting & Power Co 82/12/21 BECHHOEFER, C, LANB, J C, HILL, E E Atomic Safety and Licensing Board Panel 3pp 16561 225 24X Fiche 50-498, 82/12/21, B212280279

B212280282 Response in opposition to Citizens Concerned About Nuclear Power B21206 motion to reopen record Receipt of evidence would involve ASLB in nonpertinent ratemaking matters Certificate of Svc encl
NEWMAN, J R Houston Lighting & Power Co NEWMAN, J R Lowenstein, Newman, Reis, Axelrad & Toll 82/12/21 Atomic Safety and Licensing Board Panel 8pp 16561 217 24X Fiche 50-498, 82/12/21, B212280282

B212290003 Response in opposition to Citizens Concerned About Nuclear Power B21206 motion to reopen Phase I record Nexus between TX Public Util Commission findings on util financial ability & issue of util competence not shown W/Certificate of Svc
OUTIERREZ, J M Hearing Branch 3 82/12/27 Atomic Safety and Licensing Board Panel 8pp 16583 240 24X Fiche 50-498, 82/12/27, B212290003

I Financial information

B212170120 Forwards Amend B to application for DLs, SEC info, financial statements & annual financial repts
GOLDBERG, J H Houston Lighting & Power Co 82/12/15 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 16451 001 24X Fiche 50-498, 82/12/15, B212170120

--B212170128 Annual Financial Rept, yr ending B20131
BIGGS, G, SPRUCE, J K San Antonio City Public Service Board 82/12/15 24pp 16451 135 24X Fiche 50-498, 82/12/15, B212170120

--B212170131 Annual Financial Rept 1981 SEC info encl
BORCHELT, M L Central Power & Light 82/03/01 125pp 16451 158 24X Fiche 50-498, 82/12/15, B212170120

--B212170133 Annual Financial Rept 1981
JORDAN, D D Houston Industries, Inc 82/03/22 52pp 16451 283 24X Fiche 50-498, 82/12/15, B212170120

K Utility Final Safety Analysis Report (FSAR) & amends

B212070262 Forwards Amend 27 to FSAR, incorporating organizational changes, DA revisions, Tech Spec deletions, revised responses to NRC questions & miscellaneous FSAR text revisions & editorial changes
GOLDBERG, J H Houston Lighting & Power Co 82/11/29 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 16339 159 24X Fiche 50-498, 82/11/29, B212070262

--B212070263 Amend 27 to FSAR
Houston Lighting & Power Co 82/11/29 325pp 16339 163 24X Fiche 50-498, 82/11/29, B212070262

B212090377 Forwards Amend 28 to FSAR, describing high voltage direct current (HVDC) terminal facility to be located at site Info re removal of personnel from HVDC facility will be included in emergency plan FSAR Chapter B will be updated
GOLDBERG, J H Houston Lighting & Power Co 82/12/06 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 16364 195 24X Fiche 50-498, 82/12/06, B212090377

--B212090382 Amend 28 to FSAR
Houston Lighting & Power Co 82/12/06 42pp 16364 199 24X Fiche 50-498, 82/12/06, B212090377

G Inspection reports, IE Bulletins & correspondence

B208190240 IE Bulletin B2-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at DWR Plants " Svc list encl
DEVOUNO, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, B208190240

B208190245 IE Info Notice B2-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000, 82/11/05, B208190245

B208190251 IE Info Notice B2-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X Fiche 50-000, 82/11/18, B208190251

B208190256 IE Info Notice B2-46, "Defective & Obsolete Combination Padlocks " Svc list encl
DEVOUNO, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000, 82/11/26, B208190256

B208190257 IE Info Notice B2-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000, 82/11/30, B208190257

DOCKETED ITEMS

341

B708190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259

8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0075 Relay Sockets " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X Fiche 50-000, 82/12/03, 8208190261

8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16, 8208190267

B708190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type IYE-27 " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X Fiche 50-000, 82/12/20, 8208190268

S Reportable occurrences, LERs & related correspondence

B712030100 Eighth interim deficiency rept re breakdown in quality program-procurement cycle of purchased matls Initially reported on 800613 Bechtel assessment continuing Next rept will be submitted by 830603
OPREA, G W Houston Lighting & Power Co 82/11/19 COLLINS, J T Region 4, Office of Director 4pp 16304 243 24X Fiche 50-498, 82/11/19, 8212030100

B212270172 Suppl to final deficiency rept re structural steel beam to column connection design Initially reported on 800924 Bechtel method of analysis & design in final phase summarized
OPREA, G W Houston Lighting & Power Co 82/12/16 COLLINS, J T Region 4, Office of Director 10pp 16338 023 24X Fiche 50-498, 82/12/16, 8212270172

G712290202 Sixth interim deficiency rept re computer verification program Initially reported on 810508 Bechtel method for reviewing Brown & Root, Inc computer calculations established & results discussed Next rept expected by 830812
OPREA, G W Houston Lighting & Power Co 82/12/22 COLLINS, J T Region 4, Office of Director 4pp 16578 048 24X Fiche 50-498, 82/12/22, 8212290202

DOCKET STN-50-508 WPPSS NUCLEAR PROJECT, UNIT 3

A Application/construction stage documents & correspondence

B712130244 Notification of 821207 meeting w/util in Bethesda, MD to discuss shift of responsibility as project manager from D Wheeler to A Vietti
VIETTI, A Licensing Branch 3 82/11/29 KNIGHTON, G W Licensing Branch 3 3pp 16410 335 24X Fiche 50-508, 82/11/29, 8212130244

8212150021 Forwards marked-up FSAR pages transmitted as supplemental info re conformance w/ERP (NUREG-0800) Changes will be incorporated into subsequent FSAR amend
DOUCHEY, G D Washington Public Power Supply System 82/11/30 KNIGHTON, G W Licensing Branch 3 13pp 16421 218 24X Fiche 50-508, 82/11/30, 8212150021

G712150029 Forwards responses to 820820 acceptance review questions re OL application, scheduled for NRC review in Nov Marked-up FSAR pages included where changes became necessary due to responses
DOUCHEY, G D Washington Public Power Supply System 82/11/30 KNIGHTON, G W Licensing Branch 3 22pp, 16421, 254 24X Fiche 50-508, 82/11/30, 8212150029

B712230208 Forwards Category 1 tank enclosure structure figures in response to acceptance review questions
DOUCHEY, G D Washington Public Power Supply System 82/12/21 KNIGHTON, G W Licensing Branch 3 32pp, 16510 280 24X Fiche 50-508, 82/12/21, 8212230208

C Utility Environmental Report (ER), amends & correspondence

B712220011 Forwards Sitting Analysis Branch request for info re regional socioeconomic impacts per environ rept Responses expected no later than 830211
KNIGHTON, G W Licensing Branch 3 82/12/06 FERGUSON, R L Washington Public Power Supply System 3pp 16529 100 24X Fiche 50-508, 82/12/06, 8212220011

B712140194 Forwards Amend 1 to environ rept Distribution list encl
DOUCHEY, G D Washington Public Power Supply System 82/12/09 KNIGHTON, G W Licensing Branch 3 3pp 16407 055 24X Fiche 50-508, 82/12/09, 8212140194

--8212140201 Amend 1 to environ rept
* Washington Public Power Supply System 82/12/31 177pp 16407 059 24X Fiche 50-508, 82/12/09, 8212140194

F Security, medical, emergency & fire protection plans

B712070131 Forwards Revision 1 to physical security plan Revision withheld (ref 10CFR73.21)
DOUCHEY, G D Washington Public Power Supply System 82/12/01 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 16327 030 24X Fiche 50-508, 82/12/01, 8212070131

8212100256 Forwards util B00616 & 1212 & B10320 & 0408 ltrs re emergency response facilities (ERF) in response to Generic Ltr B1-10, per NRC request Util does not plan to provide backup ERF Requested info provided
DOUCHEY, G D Washington Public Power Supply System 82/12/03 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 16376 149 24X Fiche 50-397, 82/12/03, 8212100256

H General correspondence

B712170314 Notifies that RL Ferguson, managing director of util, resigned on 821129, effective 830601, due to health reasons
DOUCHEY, G D Washington Public Power Supply System 82/12/08 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 16456 158 24X Fiche 50-397, 82/12/08, 8212170314

K Utility Final Safety Analysis Report (FSAR) & amends

B712130033 Forwards Amend 2 to FSAR Amend contains supplemental info re conformance w/ERP (NUREG-0800) & responses to NRC Aug 1982 acceptance review questions
DOUCHEY, G D Washington Public Power Supply System 82/11/30 KNIGHTON, G W Licensing Branch 3 2pp 16393 157 24X Fiche 50-508, 82/11/30, 8212130033

--8212130036 Amend 2 to FSAR
* Washington Public Power Supply System 82/11/30 977pp 16393 159 24X Fiche 50-508, 82/11/30, 8212130033

Q Inspection reports, IE Bulletins & correspondence

8208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240

B708190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list encl
CDBR, L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372, 142 24X Fiche 50-000, 82/11/05, 8208190245

B712060260 Forwards IE Insp Rept 50-508/82-19 on 821001-31 & notice of violation
STERNBERG, D H Division of Resident, Reactor Project & Engineering Programs 82/11/15, LEDDICH, R S Washington Public Power Supply System 2pp 16312 150 24X Fiche 50-508, 82/11/15, 8212060260

--8212060264 Notice of violation from insp on 821001-31
DODDS, R T Division of Resident, Reactor Project & Engineering Programs 82/11/15 1p 16312 152 24X Fiche 50-508, 82/11/15, 8212060260

--8212060274 IE Insp Rept 50-508/82-19 on 821001-31 Noncompliance noted tension ring welds of left-in-place dome form work made by unqualified weld procedure
ALBERT, W G, DODDS, R T, Division of Resident, Reactor Project & Engineering Programs 82/11/12 6pp 16312, 153, 24X Fiche 50-508, 82/11/13, 8212060260

B708190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 179 24X Fiche 50-000, 82/11/18, 8208190251

DOCKETED ITEMS

8208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl
C088,L 1 Division of Fuel Facilities, Materials & Safeguards
82/11/30 Consolidated Edison Co. of New York, Inc 356pp
14987 028 24X Fiche 50-000,82/11/30,8208190257

8212170354 Forwards IE Insp Rept 50-508/82-20 on 821004-08 & 1101-03 & notice of violation
STERNBERG,D M. Division of Resident, Reactor Project & Engineering Programs 82/12/02 LEDDICK,R S Washington Public Power Supply System 2pp 14559 179 24X Fiche 50-508,82/12/02,8212170354

--8212170361 Notice of violation from insp on 821004-08 & 1101-03
DODDS,R T Division of Resident, Reactor Project & Engineering Programs 82/12/02 3pp 14459 181 24X Fiche 50-508,82/12/02,8212170354

--8212170370 IE Insp Rept 50-508/82-20 on 821004-08 & 1101-03
Noncompliance noted failure to perform design verification of onsite design changes per Ebasco Procedure E-76 & failure to conduct calculations per Ebasco Procedure E-30
HAIST,D D, DODDS,R T Division of Resident, Reactor Project & Engineering Programs 82/11/30 7pp 14459 184 24X Fiche 50-508,82/12/02,8212170354

8212210189 Forwards IE Mgt Meeting Rept 50-508/82-21 on 821104
ENGELKEN,R H Region 5, Office of Director 82/12/02 LEDDICK,R S Washington Public Power Supply System 1p 14484 332 24X Fiche 50-508,82/12/02,8212210189

--8212210195 IE Mgt Meeting Rept 50-508/82-21 on 821104 Major areas discussed results of 820802-04 & 30-0903 insp,including onsite design change control & NRC actions to be taken
FAULKENBERRY,B, DODDS,R T, ALBERT,W G Division of Resident, Reactor Project & Engineering Programs 82/12/02 3pp 14484 333 24X Fiche 50-508,82/12/02,8212210189

8208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl
DEYOUNG,R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co. of New York, Inc 113pp 14411 317 24X Fiche 50-000,82/12/03,8208190259

8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl
JORDAN,E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co. of New York, Inc 110pp. 14462 044 24X Fiche 50-000,82/12/03,8208190261

8212280121 Responds to NRC 821115 ltr re violations noted in IE Insp Rept 50-508/82-19 Corrective actions Ebasco evaluating matter to determine whether problem was isolated occurrence
Rept of corrective actions will be submitted by 830315
LEDDICK,R S Washington Public Power Supply System 82/12/15
STERNBERG,D M Division of Resident, Reactor Project & Engineering Programs 1p 14554 180 24X Fiche 50-508,82/12/15,8212280121

8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
DEYOUNG,R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co. of New York, Inc 127pp, 14428 191 24X Fiche 50-000,82/12/16,8208190267

8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27 " Svc list encl
JORDAN,E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co. of New York, Inc. 108pp 14428 293. 24X Fiche 50-000,82/12/20,8208190268

8212280299 Forwards IE Mgt Meeting Rept 50-508/82-24 on 821209 No noncompliance noted
CREWS,J L Division of Resident, Reactor Project & Engineering Programs 82/12/22 LEDDICK,R S Washington Public Power Supply System 1p 14561 133 24X Fiche 50-508,82/12/22,8212280299

--8212280301 IE Mgt Meeting Rept 50-508/82-24 on 821209 No noncompliance noted Major areas discussed site design change control & licensee involvement & actions taken to tighten site change control process
CREWS,J L, STERNBERG,D M, DODDS,R T Division of Resident, Reactor Project & Engineering Programs 82/12/21 2pp 14561 136 24X Fiche 50-508,82/12/22,8212280299

8212300070 Ack receipt of 821202 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-508/82-04
STERNBERG,D M Division of Resident, Reactor Project & Engineering Programs 82/12/23 LEDDICK,R S Washington Public Power Supply System 1p 14599 018. 24X Fiche 50-508,82/12/23,8212300070

--8212300075 Responds to NRC 820413 ltr re violations noted in IE Insp Rept 50-508/82-04 Corrective actions Ebasco reviewed all Chicago Bridge & Iron Class D structures & determined that failure would not affect components
LEDDICK,R S Washington Public Power Supply System 82/12/02
STERNBERG,D M Region 5, Office of Director 8pp 14599 019 24X Fiche 50-508,82/12/23,8212300070

8212300268 Ack receipt of 821210 ltr informing NRC of status of noncompliance item noted in IE Insp Repts 50-508/82-04 & 50-509/82-03
STERNBERG,D M Division of Resident, Reactor Project & Engineering Programs 82/12/23 LEDDICK,R S Washington Public Power Supply System 1p 14595 253 24X Fiche 50-508,82/12/23,8212300268

--8212300274 Suppls 820528 response to NRC 820426 ltr re violations noted in IE Insp Repts 50-508/82-06 & 50-509/82-03 New compliance data re absence of specific preventive maint control for shutdown cooling HX will be submitted by 830315
LEDDICK,R S Washington Public Power Supply System 82/12/10
STERNBERG,D M Division of Resident, Reactor Project & Engineering Programs 1p 14595 254 24X Fiche 50-508,82/12/23,8212300268

8212300320 Ack receipt of 821210 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-508/82-16
STERNBERG,D M Division of Resident, Reactor Project & Engineering Programs 82/12/23 LEDDICK,R S Washington Public Power Supply System 1p 14594 077 24X Fiche 50-508,82/12/23,8212300320

--8212300324 Responds to NRC 821022 ltr re violations noted in IE Insp Rept 50-508/82-16 Corrective actions resident engineering instruction will be issued,all concrete blocks in seismic zones will be examined & prism tests will continue
LEDDICK,R S Washington Public Power Supply System 82/12/10
STERNBERG,D M Division of Resident, Reactor Project & Engineering Programs 4pp 14594 078 24X Fiche 50-508,82/12/23,8212300320

DOCKET STN-50-509 WPPSS NUCLEAR PROJECT, UNIT 5

Q Inspection reports, IE Bulletins & correspondence

8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list encl
DEYOUNG,R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co. of New York, Inc 127pp 14411 065 24X Fiche 50-000,82/11/26,8208190256

8212300070 Ack receipt of 821202 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-508/82-04
STERNBERG,D M Division of Resident, Reactor Project & Engineering Programs 82/12/23 LEDDICK,R S Washington Public Power Supply System 1p 14599 018 24X Fiche 50-508,82/12/23,8212300070

8212300268 Ack receipt of 821210 ltr informing NRC of status of noncompliance item noted in IE Insp Repts 50-508/82-04 & 50-509/82-03
STERNBERG,D M Division of Resident, Reactor Project & Engineering Programs 82/12/23 LEDDICK,R S Washington Public Power Supply System 1p 14595 253 24X Fiche 50-508,82/12/23,8212300268

--8212300274 Suppls 820528 response to NRC 820426 ltr re violations noted in IE Insp Repts 50-508/82-06 & 50-509/82-03 New compliance data re absence of specific preventive maint control for shutdown cooling HX will be submitted by 830315
LEDDICK,R S Washington Public Power Supply System 82/12/10
STERNBERG,D M Division of Resident, Reactor Project & Engineering Programs 1p 14595 254 24X Fiche 50-508,82/12/23,8212300268

DOCKET 50-513 WPPSS NUCLEAR PROJECT, UNIT 4

A Application/construction stage documents & correspondence

8212230343 Trip rept of Commissioners Gilinsky & Abbott 821202 site visit Agenda & viewgraphs encl
ABBOTT,E C Commissioners 82/12/17 Commissioners 26pp 14511 170 24X Fiche 50-397,82/12/17,8212230343

S Reportable occurrences, LERs & related correspondence

8212210251 Interim deficiency rept re potentially defective switch on GE electrically operated low voltage circuit breaker types AKR30 & AKR50 mfg before May 1980 initially reported on 821115.Breakers will be corrected by Apr 1983
ROOT,R W Washington Public Power Supply System 82/12/06
STERNBERG,D M Division of Resident, Reactor Project & Engineering Programs 2pp 14483,309 24X Fiche 50-440,82/12/06,8212210251

DOCKET 50-514 PEBBLE SPRINGS NUCLEAR PLANT, UNIT 1

G Adjudicatory correspondence

B212060002 Response to applicant B21112 motion to withdraw application for CPs & for termination of proceeding NRC does not oppose motion Certificate of Svc encl
 QODDARD, R J Hearing Branch 3 82/12/02 Atomic Safety and Licensing Board Panel 3pp 16313 310 24X Fiche 50-514, B2/12/02, B212060002

Q Inspection reports, IE Bulletins & correspondence

B208190240 IE Bulletin B2-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Svc list encl
 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 14662 163 24X Fiche 50-000, B2/10/28, B208190240

B208190245 IE Info Notice B2-42, "Defects Observed in Panasonic Model B01 & Model B02 Thermoluminescent Dosimeters " Svc list encl
 COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000, B2/11/05, B208190245

B208190251 IE Info Notice B2-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl
 JORDAN, E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X Fiche 50-000, B2/11/18, B208190251

B208190256 IE Info Notice B2-46, "Defective & Obsolete Combination Padlocks " Svc list encl
 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000, B2/11/26, B208190256

B208190257 IE Info Notice B2-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl
 COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000, B2/11/30, B208190257

B208190259 IE Bulletin B2-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl
 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, B2/12/03, B208190259

B208190261 IE Info Notice B2-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl
 JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X Fiche 50-000, B2/12/03, B208190261

B208190267 IE Info Notice B2-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, B2/12/16, B208190267

B208190268 IE Info Notice B2-50, "Mod of Solid State AC Undervoltage Relays Type 17E-27 " Svc list encl
 JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X Fiche 50-000, B2/12/20, B208190268

DOCKET 50-515 PEBBLE SPRINGS NUCLEAR PLANT, UNIT 2

G Adjudicatory correspondence

B212060002 Response to applicant B21112 motion to withdraw application for CPs & for termination of proceeding NRC does not oppose motion Certificate of Svc encl
 QODDARD, R J Hearing Branch 3 82/12/02 Atomic Safety and Licensing Board Panel 3pp 16313 310 24X Fiche 50-514, B2/12/02, B212060002

Q Inspection reports, IE Bulletins & correspondence

B208190240 IE Bulletin B2-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Svc list encl
 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 14662 163 24X Fiche 50-000, B2/10/28, B208190240

B208190245 IE Info Notice B2-42, "Defects Observed in Panasonic Model B01 & Model B02 Thermoluminescent Dosimeters " Svc list encl
 COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000, B2/11/05, B208190245

B208190251 IE Info Notice B2-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl
 JORDAN, E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X Fiche 50-000, B2/11/18, B208190251

B208190256 IE Info Notice B2-46, "Defective & Obsolete Combination Padlocks " Svc list encl
 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000, B2/11/26, B208190256

B208190257 IE Info Notice B2-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl
 COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000, B2/11/30, B208190257

B208190259 IE Bulletin B2-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl
 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, B2/12/03, B208190259

B208190261 IE Info Notice B2-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl
 JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X Fiche 50-000, B2/12/03, B208190261

B208190267 IE Info Notice B2-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, B2/12/16, B208190267

B208190268 IE Info Notice B2-50, "Mod of Solid State AC Undervoltage Relays Type 17E-27 " Svc list encl
 JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X Fiche 50-000, B2/12/20, B208190268

DOCKET 50-518 HARTSVILLE NUCLEAR PLANT, UNIT 1

A Application/construction stage documents & correspondence

B211230066 Generic Ltr B2-27 to all BWR licensees of operating reactors except LACBWR, Big Rock Point, Dresden 1, Humboldt Bay, applicants for OL & holders of CP re transmittal of NUREG-0763 & NUREG-0763 Svc list encl W/o stated encl
 EISENHUT, D G Division of Licensing 82/11/15 General Public Utilities - OPU Service Corp 22pp 16387 004 24X Fiche 50-000, B2/11/15, B211230066

B212090055 Forwards "Socioeconomic Monitoring & Mitigation Rept," & "Const Employee Monitoring Errata Rept "
 MILLS, L M Tennessee Valley Authority 82/11/30 EISENHUT, D G Division of Licensing 1p 16366 027 24X Fiche 50-518, B2/11/30, B212090055

--B212090056 "Socioeconomic Monitoring & Mitigation Rept "
 * Tennessee Valley Authority HNP SHR-12 82/10/31 11pp 16366 028 24X Fiche 50-518, B2/11/30, B212090055

--B212090058 "Const Employee Monitoring Errata Rept "
 * Tennessee Valley Authority 82/10/31 66pp 16366 039 24X Fiche 50-518, B2/11/30, B212090055

Q Inspection reports, IE Bulletins & correspondence

B208190240 IE Bulletin B2-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Svc list encl
 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 14662 163 24X Fiche 50-000, B2/10/28, B208190240

B208190245 IE Info Notice B2-42, "Defects Observed in Panasonic Model B01 & Model B02 Thermoluminescent Dosimeters " Svc list encl
 COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000, B2/11/05, B208190245

DOCKETED ITEMS

8208190231 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18
Consolidated Edison Co of New York, Inc 109pp 16411 199 24X
Fiche 50-000, 82/11/18, 8208190231

8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co. of New York, Inc 127pp 16411 065 24X Fiche 50-000, 82/11/26, 8208190256

8208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl
CORB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000, 82/11/30, 8208190257

8208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259

8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X
Fiche 50-000, 82/12/03, 8208190261

8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16, 8208190267

8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27 " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X
Fiche 50-000, 82/12/20, 8208190268

S Reportable occurrences, LERs & related correspondence

8212100270 Fifth interim deficiency rept re lack of Div of Engineering design sys to ensure QA procedures issued before work begins Initially reported on 8/10/20 Final rept will not be submitted until decision made on deferral of projects
MILLS, L M Tennessee Valley Authority 82/12/06 O'REILLY, J P Region 2, Office of Director 1p 16377 136 24X
Fiche 50-000, 82/12/06, 8212100270

8212140141 First interim deficiency rept re Henry Pratt pneumatic butterfly valve actuator yoke failure Initially reported on 8/21/09 Valves will be modified on site Next rept due 8/30/09
Also reportable per Part 21
MILLS, L M Tennessee Valley Authority 82/12/07 O'REILLY, J P Region 2, Office of Director 3pp 16408 166 24X
Fiche 50-000, 82/12/07, 8212140141

8212200001 Third interim deficiency rept re generic deficiency in design review Initially reported on 8/12/13 No addl info available until action team 8/21/15 rept Next rept will be submitted by 8/30/20
MILLS, L M Tennessee Valley Authority 82/12/13 O'REILLY, J P Region 2, Office of Director 1p 16473 362 24X
Fiche 50-000, 82/12/13, 8212200001

8212200017 Fifth interim deficiency rept re design review process interface coordination activity Initially reported on 8/10/17 Corrective action to be based on action team rept to be issued approx 8/21/15 Next rept expected by 8/30/22
MILLS, L M Tennessee Valley Authority 82/12/13 O'REILLY, J P Region 2, Office of Director 2pp 16473 085 24X
Fiche 50-000, 82/12/13, 8212200017

8212200052 Final deficiency rept re Atlas QA documentation on auxiliary & fuel bldg structural steel Initially reported on 8/11/13 QA hold placed on suspect items until further testing performed Also reportable under Part 21
MILLS, L M Tennessee Valley Authority 82/12/13 O'REILLY, J P Region 2, Office of Director 4pp 16470 011 24X
Fiche 50-000, 82/12/13, 8212200052

8212210431 Fourth interim deficiency rept re resolution of unanticipated vibratory loading concerns Initially reported on 8/20/20 Const activities for Yellow Creek & Hartsville deferred Next rept will be sent by 8/30/22
MILLS, L M Tennessee Valley Authority 82/12/15 O'REILLY, J P Region 2, Office of Director 2pp 16489 168 24X
Fiche 50-000, 82/12/15, 8212210431

DOCKET STN-50-519 HARTSVILLE NUCLEAR PLANT, UNIT 2

A Application/construction stage documents & correspondence

8211230066 Generic Ltr 82-27 to all BWR licensees of operating reactors except LACBWR, Big Rock Point, Dresden 1, Humboldt Bay, applicants for DL & holders of CP re transmittal of NUREG-0763 & NUREG-0783 Svc list encl N/A stated encl
EISENHUT, D G Division of Licensing 82/11/15 General Public Utilities - OPU Service Corp 22pp 16387 004 24X
Fiche 50-000, 82/11/15, 8211230066

B Inspection reports, IE Bulletins & correspondence

8208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall Large-Diameter Stainless Steel Recirculation Sys Piping at BWR Plants " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240

8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list encl
CORB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000, 82/11/05, 8208190245

8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X
Fiche 50-000, 82/11/18, 8208190251

8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000, 82/11/26, 8208190256

8208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl
CORB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000, 82/11/30, 8208190257

8208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259

8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X
Fiche 50-000, 82/12/03, 8208190261

8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16, 8208190267

8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27 " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X
Fiche 50-000, 82/12/20, 8208190268

B Reportable occurrences, LERs & related correspondence

8212140141 First interim deficiency rept re Henry Pratt pneumatic butterfly valve actuator yoke failure Initially reported on 8/21/09 Valves will be modified on site Next rept due 8/30/09
Also reportable per Part 21
MILLS, L M Tennessee Valley Authority 82/12/07 O'REILLY, J P Region 2, Office of Director 3pp 16408 166 24X
Fiche 50-000, 82/12/07, 8212140141

DOCKETED ITEMS

34

DOCKET STN-50-520 HARTSVILLE NUCLEAR PLANT, UNIT 3

A Application/construction stage documents & correspondence

821230066 Generic Ltr 82-27 to all BWR licensees of operating reactors except LACBWR, Big Rock Point, Dresden 1, Humboldt Bay, applicants for OL & holders of CP re transmittal of NUREG-0763 & NUREG-0783 Svc list encl w/o stated encl EISENHUT, D O Division of Licensing 82/11/15 General Public Utilities - OPU Service Corp 22pp 16387 004 24X Fiche 50-000, 82/11/15, 821230066

821209055 Forwards "Socioeconomic Monitoring & Mitigation Rept." & "Const Employee Monitoring Errata Rept " MILLS, L M Tennessee Valley Authority 82/11/30 EISENHUT, D O Division of Licensing 1p 16366 027 24X Fiche 50-518, 82/11/30, 821209055

--821209056 "Socioeconomic Monitoring & Mitigation Rept " * Tennessee Valley Authority HNP S/W-12 82/10/31 11pp 16366 028 24X Fiche 50-518, 82/11/30, 821209055

--821209058 "Const Employee Monitoring Errata Rept " * Tennessee Valley Authority 82/10/31 66pp 16366 039 24X Fiche 50-518, 82/11/30, 821209055

G Inspection reports, IE Bulletins & correspondence

8208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Svc list encl DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240

8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list encl COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000, 82/11/05, 8208190245

8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl JORDAN, E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X Fiche 50-000, 82/11/18, 8208190251

8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list encl DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000, 82/11/26, 8208190256

8208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000, 82/11/30, 8208190257

8208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259

8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X Fiche 50-000, 82/12/03, 8208190261

8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16, 8208190267

8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27 " Svc list encl JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X Fiche 50-000, 82/12/20, 8208190268

B Reportable occurrences, LERs & related correspondence

8212100270 Fifth interim deficiency rept re lack of Div of Engineering design sys to ensure QA procedures issued before work begins Initially reported on 811020 Final rept will not be submitted until decision made on deferral of projects MILLS, L M Tennessee Valley Authority 82/12/06 O'REILLY, J P Region 2, Office of Director 1p 16377 136 24X Fiche 50-000, 82/12/06, 8212100270

8212200001 Third interim deficiency rept re generic deficiency in design review Initially reported on 811215 No addl info available until action team 821215 rept Next rept will be submitted by 830420 MILLS, L M Tennessee Valley Authority 82/12/13 O'REILLY, J P Region 2, Office of Director 1p 16473 362 24X Fiche 50-000, 82/12/13, 8212200001

8212200017 Fifth interim deficiency rept re design review process interface coordination activity Initially reported on 810717 Corrective action to be based on action team rept to be issued approx 821215 Next rept expected by 830422 MILLS, L M Tennessee Valley Authority 82/12/13 O'REILLY, J P Region 2, Office of Director 2pp 16473 085 24X Fiche 50-000, 82/12/13, 8212200017

8212200052 Final deficiency rept re Atlas QA documentation on auxiliary & fuel bldg structural steel Initially reported on 811113 QA hold placed on suspect items until further testing performed Also reportable under Part 21 MILLS, L M Tennessee Valley Authority 82/12/13 O'REILLY, J P Region 2, Office of Director 4pp 16470 011 24X Fiche 50-518, 82/12/13, 8212200052

8212210431 Fourth interim deficiency rept re resolution of unanticipated vibratory loading concerns Initially reported on 820120 Const activities for Yellow Creek & Hartsville deferred Next rept will be sent by 830322 MILLS, L M Tennessee Valley Authority 82/12/15 O'REILLY, J P Region 2, Office of Director 2pp 16489 168 24X Fiche 50-000, 82/12/15, 8212210431

DOCKET STN-50-521 HARTSVILLE NUCLEAR PLANT, UNIT 4

A Application/construction stage documents & correspondence

821230066 Generic Ltr 82-27 to all BWR licensees of operating reactors except LACBWR, Big Rock Point, Dresden 1, Humboldt Bay, applicants for OL & holders of CP re transmittal of NUREG-0763 & NUREG-0783 Svc list encl w/o stated encl EISENHUT, D O Division of Licensing 82/11/15 General Public Utilities - OPU Service Corp 22pp 16387 004 24X Fiche 50-000, 82/11/15, 821230066

G Inspection reports, IE Bulletins & correspondence

8208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Svc list encl DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240

8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list encl COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000, 82/11/05, 8208190245

8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl JORDAN, E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411, 199 24X Fiche 50-000, 82/11/18, 8208190251

8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list encl DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000, 82/11/26, 8208190256

8208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000, 82/11/30, 8208190257

DOCKETED ITEMS

8208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259

8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0075 Relay Sockets " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X Fiche 50-000, 82/12/03, 8208190261

8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16428 191 24X Fiche 50-000, 82/12/16, 8208190267

8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27 " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X Fiche 50-000, 82/12/20, 8208190268

DOCKET 50-522 SKAGIT NUCLEAR POWER PROJECT, UNIT 1

A Application/construction stage documents & correspondence

821230066 Generic Ltr 82-27 to all BWR licensees of operating reactors except LACBHR, Big Rock Point, Dresden 1, Humboldt Bay, applicants for OL & holders of CP re transmittal of NUREG-0743 & NUREG-0783 Svc list encl w/o stated encl
EISENHUT, D O Division of Licensing 82/11/15 General Public Utilities - OPU Service Corp 22pp 16397 004 24X Fiche 50-000, 82/11/15, 821230066

8212140419 Forwards suppl to 820222 response to request for info re Unresolved Safety Issue A-39 concerning safety relief valve pool dynamic loads, per NUREG-0802, NUREG-0783 & NUREG-0743
MYERS, R V Puget Sound Power & Light Co 82/12/08 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 16404 186 24X Fiche 50-522, 82/12/08, 8212140419

B Utility Preliminary Safety Analysis Report, amends

8210190729 Forwards final draft of Amend 28 to PSAR, consisting of responses to NRC Questions 231, 5, 231, 14 & 231 15, revisions to PSAR Section 2.5 & Apps 2K & 2R w/25 oversize figures
Aperture cards are available in PDR
SPANSENBERG, F Northwest Energy Services Co 82/10/15 ADENSA, E Licensing Branch 4 20pp 15751 035 24X Fiche 50-522, 82/10/15, 8210190729

G Adjudicatory correspondence

8212010038 Brief opposing admission of Yakima Indian Nation reworded proposed Contention 10 Nation special relationship w/US does not exempt Nation from Commission rules & regulations
Specificity requirements not met Certificate of Svc encl
DEWEY, L S Hearing Branch 3 82/11/30 Atomic Safety and Licensing Board Panel 7pp 16260 334 24X Fiche 50-522, 82/11/30, 8212010038

8212020376 Memorandum & order granting NRDC motion for amend to Contention 3 as adopted in ASLB 821102 memorandum & order
WOLF, J F Atomic Safety and Licensing Board Panel 82/11/30 Natural Resources Defense Council 2pp 16278 090 24X Fiche 50-522, 82/11/30, 8212020376

8212020379 Memorandum & order granting NRDC 821122 motion to substitute NRDC for Coalition for Safe Power as lead party for Contention 3
WOLF, J F Atomic Safety and Licensing Board Panel 82/11/30 Natural Resources Defense Council 2pp 16278 102 24X Fiche 50-522, 82/11/30, 8212020379

8212070172 Request for production of documents & interrogatories, per 10CFR2 740(h) & 10CFR2 741 Certificate of Svc encl Related correspondence
THATCHER, T L National Wildlife Federation THATCHER, T L Oregon Environmental Council 82/12/01 Portland General Electric Co 10pp 16334 331 24X Fiche 50-522, 82/12/01, 8212070172

8212070239 Brief re admissibility of Yakima Indian Nation Proposed Contention 10 Clarification needed on procedural rule of Commission & scope of contention Certificate of Svc encl
THOMSEN, F T Puget Sound Power & Light Co THOMSEN, F T Perkins, Cole, Stone, Olsen & Williams 82/12/01 Atomic Safety and Licensing Board Panel 13pp, 16329, 298 24X Fiche 50-522, 82/12/01, 8212070239

8212100116 Advises that time for Commission to act to review ALAB-700 has expired Commission declined review Decision became final agency action on 821208
CHILK, S J Office of the Secretary of the Commission 82/12/09 Office of the Executive Legal Director 1p 16376 019 24X Fiche 50-522, 82/12/09, 8212100116

8212140333 Certifies svc of brief on admissibility of reworded proposed Contention 10, motion for reconsideration of ASLB 821029 memorandum & order, R Jim affidavit & notice of counsel law firm change on 821210
HOVIS, J B Yakima Indian Nation HOVIS, J B Hovis, Cockrill, Weaver & Bjur 82/12/10 4pp 16402 008 24X Fiche 50-522, 82/12/10, 8212140333

8212140345 Brief supporting admissibility of Yakima Indian Nation reworded proposed Contention 10 Attempt to terminate reserved rights of Yakima Indian Nation violates Fifth amend Land cannot be taken by inverse condemnation
HOVIS, J B Yakima Indian Nation HOVIS, J B Hovis, Cockrill, Weaver & Bjur 82/12/10 Atomic Safety and Licensing Board Panel 9pp 16401 010 24X Fiche 50-522, 82/12/10, 8212140345

8212140354 Motion for reconsideration of ASLB 821029 memorandum & order re Yakima Indian Nation Contentions 7, 8 & 9 Nation right to enjoy reservation peacefully given by 1855 treaty should be protected by ASLB
HOVIS, J B Yakima Indian Nation HOVIS, J B Hovis, Cockrill, Weaver & Bjur 82/12/10 Atomic Safety and Licensing Board Panel 3pp 16401 035 24X Fiche 50-522, 82/12/10, 8212140354

8212140386 Notice of counsel new law firm affiliation, as of 820901
HOVIS, J B Yakima Indian Nation HOVIS, J B Hovis, Cockrill, Weaver & Bjur 82/12/10 1p 16401 305 24X Fiche 50-522, 82/12/10, 8212140386

8212140455 Affidavit of R Jim supporting Yakima Indian Nation brief on admissibility of Nation reworded proposed Contention 10 & motion for reconsideration Nation has right to pasture horses & gather roots even though US holds title to land
JIM, R Yakima Indian Nation 82/12/10 3pp 16403 154 24X Fiche 50-522, 82/12/10, 8212140455

8212160267 Motion to clarify & amend Contentions 7 & 8 Contentions should be reorganized to facilitate coordinated evidentiary presentations for environ matters ASLB set out as Contentions 4, 7 & 8 Certificate of Svc encl
THATCHER, T L National Wildlife Federation WAPATO, S T Columbia River Inter-Tribal Fish Commission BELL, N Coalition for Safe Power 82/12/13 Atomic Safety and Licensing Appeal Panel 10pp 16446 048 24X Fiche 50-522, 82/12/13, 8212160267

8212270225 Response to 821201 discovery requests Certificate of Svc encl
THOMSEN, F T Puget Sound Power & Light Co THOMSEN, F T Perkins, Cole, Stone, Olsen & Williams 82/12/20 National Wildlife Federation 16pp 16536 237 24X Fiche 50-522, 82/12/20, 8212270225

8212280289 Response supporting intervenor 821213 motion to clarify & amend Contentions 7 & 8 Quantification of environ impacts not practicable due to subjective nature Certificate of Svc encl
FRANTZ, S P Puget Sound Power & Light Co FRANTZ, S P Lowenstein, Newman, Reis, Axelrad & Toll 82/12/23 Atomic Safety and Licensing Board Panel 11pp 16361 075 24X Fiche 50-522, 82/12/23, 8212280289

G Inspection reports, IE Bulletins & correspondence

8208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel Recirculation Sys Piping at BWR Plants " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240

8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model B01 & Model B02 Thermoluminescent Dosimeters " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000, 82/11/05, 8208190245

8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X Fiche 50-000, 82/11/18, 8208190251

8208190254 IE Info Notice 82-46, "Defective & Obsolete Combination
Hedlocks " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and
Enforcement 82/11/26 Consolidated Edison Co of New York, Inc
127pp 16411 065 24X Fiche 50-000, 82/11/26, 8208190254

8208190257 IE Info Notice 82-47, "Transportation of Type A Quantities
of Non-Fissile Radioactive Matl " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards
82/11/30 Consolidated Edison Co of New York, Inc 356pp
16387 028 24X Fiche 50-000, 82/11/30, 8208190257

8208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment
Electrical Penetration Assemblies " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and
Enforcement 82/12/03 Consolidated Edison Co of New York, Inc
113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259

8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay
Sockets " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03
Consolidated Edison Co of New York, Inc 110pp 16462 064 24X
Fiche 50-000, 82/12/03, 8208190261

8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for
Air & Gas Monitoring " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and
Enforcement 82/12/16 Consolidated Edison Co of New York, Inc
127pp 16628 191 24X Fiche 50-000, 82/12/16, 8208190267

8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage
Relays Type ITE-27 " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20
Consolidated Edison Co of New York, Inc 108pp 16628 293 24X
Fiche 50-000, 82/12/20, 8208190268

1 Hearing transcripts on non-antitrust matters

8212070334 Transcript of 821202 prehearing conference in Olympia, WA
(p 78-175
* Atomic Safety and Licensing Board Panel 82/12/02 102pp
16337 306 24X Fiche 50-522, 82/12/02, 8212070334

DOCKET 50-523 SKAQIT NUCLEAR POWER PROJECT, UNIT 2

A Application/construction stage documents & correspondence

8211230066 Generic Ltr 82-27 to all BWR licensees of operating reactors
except LACBWR, Big Rock Point, Dresden 1, Humboldt Bay,
applicants for OL & holders of CP re transmittal of
NUREG-0763 & NUREG-0783 Svc list encl W/o stated encl
EISENHUT, D O Division of Licensing 82/11/15 General Public
Utilities - GPU Service Corp 22pp 16387 004 24X
Fiche 50-000, 82/11/15, 8211230066

8212140419 Forwards suppl to 820222 response to request for info re
Unresolved Safety Issue A-39 concerning safety relief valve
pool dynamic loads, per NUREG-0802, NUREG-0783 & NUREG-0763
MYERS, R V Puget Sound Power & Light Co 82/12/08 DENTON, H R
Office of Nuclear Reactor Regulation, Director 4pp 16404 186
24X Fiche 50-522, 82/12/08, 8212140419

B Utility Preliminary Safety Analysis Report, amends

8210190729 Forwards final draft of Amend 28 to PSAR, consisting of
responses to NRC Questions 231.5, 231.14 & 231.15; revisions
to PSAR Section 2.5 & Apps 2K & 2R w/25 oversize figures
Aperture cards are available in PDR
SPANGENBERG, F Northwest Energy Services Co 82/10/15 ADENBAM, E
Licensing Branch 4 201pp 15751 035 24X Fiche 50-522, 82/10/15,
8210190729

G Adjudicatory correspondence

8212010038 Brief opposing admission of Yakima Indian Nation reworded
proposed Contention 10 Nation special relationship w/US does
not exempt Nation from Commission rules & regulations
Specificity requirements not met Certificate of Svc encl
BENEY, L B Hearing Branch 3 82/11/30 Atomic Safety and
Licensing Board Panel 7pp 16260 334 24X Fiche 50-522, 82/11/30,
8212010038

8212020376 Memorandum & order granting NRDC motion for amend to
Contention 3 as adopted in ASLB 821102 memorandum & order
WOLF, J F Atomic Safety and Licensing Board Panel 82/11/30
Natural Resources Defense Council 2pp 16278 090 24X
Fiche 50-522, 82/11/30, 8212020376

8212020379 Memorandum & order granting NRDC 821122 motion to substitute
NRDC for Coalition for Safe Power as lead party for
Contention 3
WOLF, J F Atomic Safety and Licensing Board Panel 82/11/30
Natural Resources Defense Council 2pp 16278 102 24X
Fiche 50-522, 82/11/30, 8212020379

8212070172 Request for production of documents & interrogatories, per
10CFR2 740(b) & 10CFR2 741 Certificate of Svc encl Related
correspondence
THATCHER, T L National Wildlife Federation THATCHER, T L Oregon
Environmental Council 82/12/01 Portland General Electric Co
10pp 16334 331 24X Fiche 50-522, 82/12/01, 8212070172

8212070239 Brief re admissibility of Yakima Indian Nation Proposed
Contention 10 Clarification needed on procedural rule of
Commission & scope of contention Certificate of Svc encl
THOMSEN, F T Puget Sound Power & Light Co THOMSEN, F T Perkins,
Cole, Stone, Olson & Williams 82/12/01 Atomic Safety and
Licensing Board Panel 13pp 16329 298 24X Fiche 50-522, 82/12/01,
8212070239

8212100116 Advises that time for Commission to act to review ALAB-700
has expired Commission declined review Decision became final
agency action on 821208
CHILK, S J Office of the Secretary of the Commission 82/12/09
Office of the Executive Legal Director 1p 16376 019 24X
Fiche 50-522, 82/12/09, 8212100116

8212140333 Certifies svc of brief on admissibility of reworded
proposed Contention 10, motion for reconsideration of ASLB
821029 memorandum & order, R Jim affidavit & notice of
counsel law firm change on 821210
HOVIS, J B Yakima Indian Nation HOVIS, J B Hovis, Cockrill,
Weaver & Bjur 82/12/10 4pp 16402 008 24X
Fiche 50-522, 82/12/10, 8212140333

8212140345 Brief supporting admissibility of Yakima Indian Nation
reworded proposed Contention 10 Attempt to terminate
reserved rights of Yakima Indian Nation violates fifth
amend Land cannot be taken by inverse condemnation
HOVIS, J B Yakima Indian Nation HOVIS, J B Hovis, Cockrill,
Weaver & Bjur 82/12/10 Atomic Safety and Licensing Board Panel
9pp 16401 010 24X Fiche 50-522, 82/12/10, 8212140345

8212140354 Motion for reconsideration of ASLB 821029 memorandum & order
re Yakima Indian Nation Contentions 7, 8 & 9 Nation right to
enjoy reservation peacefully given by 1855 treaty should be
protected by ASLB
HOVIS, J B Yakima Indian Nation HOVIS, J B Hovis, Cockrill,
Weaver & Bjur 82/12/10 Atomic Safety and Licensing Board Panel
3pp 16401 035 24X Fiche 50-522, 82/12/10, 8212140354

8212140386 Notice of counsel new law firm affiliation, as of 820901
HOVIS, J B Yakima Indian Nation HOVIS, J B Hovis, Cockrill,
Weaver & Bjur 82/12/10 1p 16401 305 24X Fiche 50-522,
82/12/10, 8212140386

8212140455 Affidavit of R Jim supporting Yakima Indian Nation brief on
admissibility of Nation reworded proposed Contention 10 &
motion for reconsideration Nation has right to pasture
horses & gather roots even though US holds title to land
JIM, R Yakima Indian Nation 82/12/10 3pp 16403 154 24X
Fiche 50-522, 82/12/10, 8212140455

8212160267 Motion to clarify & amend Contentions 7 & 8 Contentions
should be reorganized to facilitate coordinated evidentiary
presentations for environ matters ASLB set out as
Contentions 4, 7 & 8 Certificate of Svc encl
THATCHER, T L National Wildlife Federation WAPATO, S T Columbia
River Inter-Tribal Fish Commission BELL, N Coalition for Safe
Power 82/12/13 Atomic Safety and Licensing Appeal Panel 10pp
16446 048 24X Fiche 50-522, 82/12/13, 8212160267

8212270225 Response to 821201 discovery requests Certificate of Svc
encl
THOMSEN, F T Puget Sound Power & Light Co THOMSEN, F T Perkins,
Cole, Stone, Olson & Williams 82/12/20 National Wildlife
Federation 16pp 16536 237 24X Fiche 50-522, 82/12/20, 8212270225

8212280289 Response supporting intervenor 821213 motion to clarify &
amend Contentions 7 & 8 Quantification of environ impacts
not practicable due to subjective nature Certificate of Svc
encl
FRANTZ, S P Puget Sound Power & Light Co FRANTZ, S P
Lowenstein, Neuman, Reis, Axelrad & Toll 82/12/23 Atomic Safety
and Licensing Board Panel 11pp 16561 075 24X
Fiche 50-522, 82/12/23, 8212280289

DOCKETED ITEMS

G Inspection reports, IE Bulletins & correspondence

B208190240 IE Bulletin B2-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BHR Plants." Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 14462-163 24X Fiche 50-000, 82/10/28, B208190240

B208190245 IE Info Notice B2-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000, 82/11/05, B208190245

B208190251 IE Info Notice B2-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X Fiche 50-000, 82/11/18, B208190251

B208190256 IE Info Notice B2-46, "Defective & Obsolete Combination Radiacks " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000, 82/11/26, B208190256

B208190257 IE Info Notice B2-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000, 82/11/30, B208190257

B208190259 IE Bulletin B2-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, B208190259

B208190261 IE Info Notice B2-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X Fiche 50-000, 82/12/03, B208190261

B208190267 IE Info Notice B2-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16, B208190267

B208190268 IE Info Notice B2-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27 " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X Fiche 50-000, 82/12/20, B208190268

T Hearing transcripts on non-antitrust matters

B212070334 Transcript of B21202 prehearing conference in Olympia, WA Pp 78-175.
* Atomic Safety and Licensing Board Panel 82/12/02 102pp 16337 306 24X Fiche 50-528, 82/12/02, B212070334

DOCKET STN-50-528 PALO VERDE NUCLEAR STATION, UNIT 1

A Application/construction stage documents & correspondence

B212010448 Summary of B21020 meeting w/util, C-E & Bechtel in Bethesda, MD re pipe whip restraints
LICITRA, E A Licensing Branch 3 82/11/18 Licensing Branch 3 5pp 16270 226 24X Fiche 50-528, 82/11/18, B212010448

B211290135 Forwards "Independent QA Evaluation of Palo Verde Nuclear Generating Station Units 1, 2 & 3," Vol 1, "Executive Summary," Vol 2, "Program Results" & Vol 3, "Potential Finding Repts "
TURLLEY, K L Arizona Public Service Co 82/11/19 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 16298-001 24X Fiche 50-528, 82/11/19, B211290135

--B211290142 Forwards, under separate cover, "Independent QA Evaluation of Palo Verde Nuclear Generating Station Units 1, 2 & 3," Vols 1, 2 & 3 No reason seen to prohibit issuance of full power OL for Units 1, 2 & 3
SIMON, W A Torrey Pines Technology 82/11/19, DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 16298-003, 24X Fiche 50-528, 82/11/19, B211290135

--B211290148 "Independent QA Evaluation of Palo Verde Nuclear Generating Station Units 1, 2 & 3," Vol 1, "Executive Summary "
* Torrey Pines Technology 82/10/31 27pp 16298 004 24X Fiche 50-528, 82/11/19, B211290135

--B211290150 "Independent QA Evaluation of Palo Verde Nuclear Generating Station Units 1, 2 & 3," Vol 2, "Program Results "
* Torrey Pines Technology 82/10/31 163pp 16298 192 24X Fiche 50-528, 82/11/19, B211290135

--B211290155 "Independent QA Evaluation of Palo Verde Nuclear Generating Station Units 1, 2 & 3," Vol 3, "Potential Finding Repts," Books 1 & 2
* Torrey Pines Technology 82/10/31 1406pp 16298 355 24X Fiche 50-528, 82/11/19, B211290135

B212080564 Requests addl info re probability study of tornado missile damage to UHS (spray pond) to complete review of PRA open item Response should be provided by B21215 W/o stated encl
KNIGHTON, O W Licensing Branch 3 82/11/23 VAN BRUNT, E E Arizona Public Service Co 1p 16368 352 24X Fiche 50-528, 82/11/23, B212080564

B212130405 Responds to B21028 request to authorize use of ASME Code Cases N-338 & N-339 in component const Code Case N-338 conditionally acceptable subj to indicated conditions Code Case N-339 approved for general use
KNIGHTON, O W Licensing Branch 3 82/11/23 VAN BRUNT, E E Arizona Public Service Co 2pp 16412 100 24X Fiche 50-528, 82/11/23, B212130405

B212270418 Responds to FOIA request for documents re proposed revision &/or update to reactor safety study referred to in NUREG-0784, Chapter 10 as RS II & all documents pertaining to reactor cooling methods Forwards documents listed in app
FELTON, J M Division of Rules and Records 82/11/26 GHOLLY, S C Union of Concerned Scientists 3pp 16549 233 24X Fiche 50-000, 82/11/26, B212270418

--B211050027 Forwards summary of semiscale test results & advises that board notification re test results issued W/o encl
NOVAK, T M Assistant Director for Licensing 82/09/24 Division of Licensing 1p 16549 278 24X Fiche 50-000, 82/11/26, B212270418

B212080666 Notification of B21208 meeting w/util, SANL, C-E & Burns & Roe in Maricopa County, AZ to discuss shutdown heat removal sys design for CESSAR Sys 80 plant
LICITRA, E A Licensing Branch 3 82/12/01 KNIGHTON, O W Licensing Branch 3 3pp 16379 243 24X Fiche 50-528, 82/12/01, B212080666

B212220063 Summary of B21117 meeting w/util & Bechtel in Bethesda, MD re natural circulation testing & training per TMI Action Item J O I
LICITRA, E A Licensing Branch 3 82/12/01 Licensing Branch 3 5pp 16526 348 24X Fiche 50-528, 82/12/01, B212220063

B212070109 Forwards comments on draft environ protection plan NRC should accept other federal agency findings w/o further review
VAN BRUNT, E E Arizona Public Service Co 82/12/02 NOVAK, T M Assistant Director for Licensing 4pp 16327 291 24X Fiche 50-528, 82/12/02, B212070109

B212080179 Forwards Amend 5 to CPPR-141, CPPR-142 & CPPR-143, safety evaluation & notice of issuance & availability Amend deletes M-B-R Public Power Agency as co-owner
EISENHUT, D O Division of Licensing 82/12/06 VAN BRUNT, E E Arizona Public Service Co 4pp 16354 061 24X Fiche 50-528, 82/12/06, B212080179

--B212080188 Amend 5 to CPPR-141, CPPR-142 & CPPR-143, deleting M-B-R Public Power Agency as co-owner
EISENHUT, D O Division of Licensing 82/12/06 6pp 16354 065 24X Fiche 50-528, 82/12/06, B212080179

--B212080195 Safety evaluation supporting Amend 5 to CPPR-141, CPPR-142 & CPPR-143
* Office of Nuclear Reactor Regulation, Director 82/12/06 2pp 16354 071 24X Fiche 50-528, 82/12/06, B212080179

--B212080204 Notice of issuance & availability of Amend 5 to CPPR-141, CPPR-142 & CPPR-143
KNIGHTON, O W Licensing Branch 3 82/12/06 2pp 16354 073 24X Fiche 50-528, 82/12/06, B212080179

8212290473 Trip rept of 821103-04 site visit by Instrument & Control Sys Branch re physical arrangement & installation of instrumentation & control electrical equipment in accordance w/design criteria Control cabling acceptable
LICITRA, E A Licensing Branch 3 82/12/13 Licensing Branch 3
10pp 16606 048 24X Fiche 50-528, 82/12/13, 8212290473

8212220440 Board Notifications 82-125 & 82-125A forwards info re H Etherington evaluation of flow blockage during natural circulation of PWRs Results do not adversely impact present position on reliance on natural circulation
NOVAK, T M Assistant Director for Licensing 82/12/14 Atomic Safety and Licensing Board Panel 5pp 16523 135 24X
Fiche 50-000, 82/12/14, 8212220440

8212220461 Board Notification 82-124 forwards RJ Mattson 821123 memo re Semiscale S-UT-8 test results Phenomena of core level depression & loop seal clearing may be more complex than previously supposed
NOVAK, T M Assistant Director for Licensing 82/12/14 Atomic Safety and Licensing Board Panel 7pp 16523 169 24X
Fiche 50-000, 82/12/14, 8212220461

8212270129 Forwards change to FSAR Section 1.8 adding fission chamber detectors & sealed sources to exception taken to Reg Guide 1.38 Change will be included in upcoming FSAR amend
VAN BRUNT, E E Arizona Public Service Co 82/12/21 NOVAK, T M Assistant Director for Licensing 3pp 16538 149 24X
Fiche 50-528, 82/12/21, 8212270129

E NRC Safety Evaluation Report (SER), supp's & correspondence

8212210107 Discusses confirmatory issue re motor operators powered from vital sources, per SER (NUREG-0897) Plant design modified to include motor operators on appropriate valves
VAN BRUNT, E E Arizona Public Service Co 82/10/28 NOVAK, T M Assistant Director for Licensing 2pp 16491 049 24X
Fiche 50-528, 82/10/28, 8212210107

8212030031 Forwards schedule for submitting requested info & remaining outstanding & confirmatory issues discussed in Suppl 3 to SER, per NRC 820927 ltr
VAN BRUNT, E E Arizona Public Service Co 82/11/29 NOVAK, T M Assistant Director for Licensing 6pp 16305 076 24X
Fiche 50-528, 82/11/29, 8212030031

8212130292 Advises that all piping components in essential ASME Code Class 1, 2 & 3 piping sys designed to Levels C & D svc limits evaluated against emergency & faulted conditions imposed by screening criteria All criteria met
VAN BRUNT, E E Arizona Public Service Co 82/12/09 NOVAK, T M Assistant Director for Licensing 6pp 16390 062 24X
Fiche 50-528, 82/12/09, 8212130292

F Security, medical, emergency & fire protection plans

8212080157 Forwards response to 821202 telephone request re emergency operations facility Conceptual design for upgraded emergency response facilities under NRC review
VAN BRUNT, E E Arizona Public Service Co 82/12/06 NOVAK, T M Assistant Director for Licensing 4pp 16354 088 24X
Fiche 50-528, 82/12/06, 8212080157

G Adjudicatory correspondence

8212010202 Requests consideration of West Valley Agricultural Protection Council, Inc supplemental memorandum supporting Council petition to intervene Brief includes useful analysis
BERLIN, K Affiliation Unknown 82/11/29 LAZO, R M, CALLIHAN, D, COLE, R F Atomic Safety and Licensing Board Panel 1p 16258 053 24X Fiche 50-528, 82/11/29, 8212010202

8212060095 Requests West Valley Agricultural Protection Council, Inc 821018 supplemental memorandum supporting petition to intervene be stricken from record if not stricken, Joint Applicants answer should be allowed
CRAWFORD, V A Sneli & Winer CRAWFORD, V A Joint Applicants-Palo Verde 82/11/29 LAZO, R M, CALLIHAN, D, COLE, R F Atomic Safety and Licensing Board Panel 2pp 16316 073 24X
Fiche 50-528, 82/11/29, 8212060095

8212220118 Forwards Torrey Pines Technology 820714 ltr & revision to Torrey Pines QA/QC plan
DEWEY, L B Hearing Branch 3 82/12/09 BERNABEI, L Harmon & Weiss, BERNABEI, L Hourihan, P 3pp 16503 022 24X
Fiche 50-528, 82/12/09, 8212220118

X Utility Final Safety Analysis Report (FSAR) & amends

8212070328 Forwards Amend 10 to FSAR
VAN BRUNT, E E Arizona Public Service Co 82/12/06 Office of Nuclear Reactor Regulation, Director 2pp 16345 047 24X
Fiche 50-528, 82/12/06, 8212070328

--8212070331 Amend 10 to FSAR Two oversize drawings encl Aperture cards are available in PDR
* Arizona Public Service Co 82/12/31 318pp 16345 049 24X
Fiche 50-528, 82/12/06, 8212070328

8212210075 Forwards Proof of Svc for Amend 10 to FSAR
VAN BRUNT, E E Arizona Public Service Co 82/12/15 Office of Nuclear Reactor Regulation, Director 3pp 16485 252 24X
Fiche 50-528, 82/12/15, 8212210075

M Antitrust correspondence

8212080179 Forwards Amend 5 to CPPR-141, CPPR-142 & CPPR-143, safety evaluation & notice of issuance & availability Amend deletes M-B-R Public Power Agency as co-owner
EISENHUT, D O Division of Licensing 82/12/06 VAN BRUNT, E E Arizona Public Service Co 4pp 16354 061 24X
Fiche 50-528, 82/12/06, 8212080179

--8212080188 Amend 5 to CPPR-141, CPPR-142 & CPPR-143, deleting M-B-R Public Power Agency as co-owner
EISENHUT, D O Division of Licensing 82/12/06 6pp 16354 065 24X Fiche 50-528, 82/12/06, 8212080179

--8212080195 Safety evaluation supporting Amend 5 to CPPR-141, CPPR-142 & CPPR-143
* Office of Nuclear Reactor Regulation, Director 82/12/06 2pp 16354 071 24X Fiche 50-528, 82/12/06, 8212080179

--8212080204 Notice of issuance & availability of Amend 5 to CPPR-141, CPPR-142 & CPPR-143
KNIGHTON, O W Licensing Branch 3 82/12/06 2pp 16354 073 24X Fiche 50-528, 82/12/06, 8212080179

Q Inspection reports, IE Bulletins & correspondence

8208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BHR Plants " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240

8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000, 82/11/05, 8208190245

8212060143 Requests extension to respond to items of noncompliance in IE Insp Repts 50-528/82-25, 50-529/82-09 & 50-530/82-10 Rept will be submitted by 821119
VAN BRUNT, E E Arizona Public Service Co 82/11/10 STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 1p 16314 069 24X Fiche 50-528, 82/11/10, 8212060143

8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X
Fiche 50-000, 82/11/18, 8208190251

8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc. 127pp 16411 065 24X Fiche 50-000, 82/11/26, 8208190256

8212130207 Forwards IE Insp Rept 50-528/82-30 on 821018-1119 & notice of violation
STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs, 82/11/29 ANDOGNINI, O C Arizona Public Service Co 2pp 16397 005 24X Fiche 50-528, 82/11/29, 8212130207

--8212130209 Notice of violation from insp on 821018-1119
YOUNG, T Division of Resident, Reactor Project & Engineering Programs 82/11/29 1p 16397 007 24X Fiche 50-528, 82/11/29, 8212130207

DOCKETED ITEMS

--B212130215 IE Insp Rept 50-528/82-30 on B21018-1119 Noncompliance noted unplanned introduction of water into steam generator 1 did not meet chemical specs
FIORELLI, D. J. JOHNSTON, D. YOUNG, T. Division of Resident, Reactor Project & Engineering Programs 82/11/29 7pp 16397 008 24X
Fiche 50-528, 82/11/29, B212130207

B208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl
COBB, L. I. Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co. of New York, Inc 356pp
16387 028 24X Fiche 50-000, 82/11/30, B208190257

B212210203 Forwards IE Insp Repts 50-528/82-29, 50-529/82-12 & 50-530/82-13 on B21004-08 No noncompliance noted
STERNBERG, D. M. Division of Resident, Reactor Project & Engineering Programs 82/11/30 VAN BRUNT, E. E. Arizona Public Service Co 2pp 16485 022 24X Fiche 50-528, 82/11/30, B212210203

--B212210211 IE Insp Repts 50-528/82-29, 50-529/82-12 & 50-530/82-13 on B21004-08 No noncompliance noted Major areas inspected
licensee action on previous insp findings, electrical cable installation & containment structural steel welding
ECKHARDT, J. H., D'ANGELO, A., YOUNG, T. Division of Resident, Reactor Project & Engineering Programs 82/11/29 7pp 16485 024 24X
Fiche 50-528, 82/11/30, B212210203

B208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl
DEVOUNG, R. C. Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co. of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, B208190259

B208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co. of New York, Inc 110pp 16462 064 24X
Fiche 50-000, 82/12/03, B208190261

B212090546 Ack receipt of B21122 ltr informing NRC of steps taken to correct violations noted in IE insp on B20834-0903
STERNBERG, D. M. Division of Resident, Reactor Project & Engineering Programs 82/12/03 VAN BRUNT, E. E. Arizona Public Service Co 1p 16366 344 24X Fiche 50-528, 82/12/03, B212090546

--B212090552 Responds to NRC B21008 ltr re violations noted in IE insp on B20830-0903 Corrective actions as-built weld pattern reconciled against weld pattern of Comp Customline Corp
VAN BRUNT, E. E. Arizona Public Service Co 82/11/22 STERNBERG, D. M. Division of Resident, Reactor Project & Engineering Programs 6pp 16366 345 24X Fiche 50-528, 82/12/03, B212090546

B208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
DEVOUNG, R. C. Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co. of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16, B208190267

B208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27 " Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co. of New York, Inc 108pp 16628 293 24X
Fiche 50-000, 82/12/20, B208190268

B Reportable occurrences, LERs & related correspondence

B212060229 Interim deficiency rept re Bechtel supplier document register errors which may allow outdated C-E procedures to be used for instrument calibr Initially reported on B20421
Final rept delayed until B21209 due to evaluation
VAN BRUNT, E. E. Arizona Public Service Co 82/11/22 STERNBERG, D. M. Division of Resident, Reactor Project & Engineering Programs 2pp 16312 231 24X Fiche 50-528, 82/11/22, B212060229

B212060240 Interim deficiency rept re instrument ac circuit breakers left set below trip range after testing Initially reported on B20806 Extension requested to submit final rept until B21229 due to extensive investigation & evaluation
VAN BRUNT, E. E. Arizona Public Service Co 82/11/22 STERNBERG, D. M. Division of Resident, Reactor Project & Engineering Programs 2pp 16312 237 24X Fiche 50-528, 82/11/22, B212060240

B212060275 Final Deficiency Rept DER 82-58 re Cooper Energy Svcs diesel generator high voltage cubicles w/o seismically qualified design. Initially reported on B21021 Anchorage will be provided on all four sides Also reportable under Part 21
VAN BRUNT, E. E. Arizona Public Service Co 82/11/22 STERNBERG, D. M. Division of Resident, Reactor Project & Engineering Programs 3pp 16312, 139, 24X Fiche 50-528, 82/11/22, B212060275

B212060283 Final Deficiency Rept DER 82-59 re Cooper Energy Svcs diesel generator crankcase sumps internal coating flaking off into lube oil Initially reported on B21021 Condition not reportable since flaking will not affect lube oil sys
VAN BRUNT, E. E. Arizona Public Service Co 82/11/22 STERNBERG, D. M. Division of Resident, Reactor Project & Engineering Programs 3pp 16312 074 24X Fiche 50-528, 82/11/22, B212060283

B212130267 Interim Deficiency Rept DER 82-61 re reactor coolant pumps diffuser-ring cap screws which may fail & damage pump Cap screw matl heat treatment will be changed so that matl will not be susceptible to cracking
VAN BRUNT, E. E. Arizona Public Service Co 82/11/22 STERNBERG, D. M. Division of Resident, Reactor Project & Engineering Programs 3pp 16390 159 24X Fiche 50-528, 82/11/22, B212130267

B212130320 Interim deficiency rept re failure of EBF actuation sys dc power supply ground detectors supplied by C-E to meet preoperational test requirements Initially reported on B21021 Evaluation continuing Final rept expected by B30209
VAN BRUNT, E. E. Arizona Public Service Co 82/11/22 STERNBERG, D. M. Division of Resident, Reactor Project & Engineering Programs 3pp 16389 329 24X Fiche 50-528, 82/11/22, B212130320

B212130216 Interim Deficiency Rept DER 82-63 re design calculation error in refueling water tank Initially reported on B21026 Bechtel performing independent detailed analysis Final rept expected by B30210
VAN BRUNT, E. E. Arizona Public Service Co 82/11/24 STERNBERG, D. M. Division of Resident, Reactor Project & Engineering Programs 3pp 16390 120 24X Fiche 50-528, 82/11/24, B212130216

B212210077 Interim Deficiency Rept DER 81-14 re A-354 anchor bolt failures Initially reported on B10529 Final rept including Teladyne & Battelle repts will be submitted by B30131 Delay due to extensive evaluations
VAN BRUNT, E. E. Arizona Public Service Co 82/11/29 STERNBERG, D. M. Division of Resident, Reactor Project & Engineering Programs 2pp 16485 248 24X Fiche 50-528, 82/11/29, B212210077

B212210036 Deficiency Evaluation Rept 82-64 re installation of dissimilar metal socket welds, restricted by Revision 10 of PM-204, due to delay in receipt of revised drawings
Deficiency not reportable per 10CFR50.55(e)
VAN BRUNT, E. E. Arizona Public Service Co 82/11/29 STERNBERG, D. M. Division of Resident, Reactor Project & Engineering Programs 2pp 16493 018 24X Fiche 50-528, 82/11/29, B212210036

B212210237 Interim Deficiency Rept DER 82-51 re Pullman-Kellogg pipe lining failure in ERCW sys Initially reported on B20910
Final rept will be submitted by B30208
VAN BRUNT, E. E. Arizona Public Service Co 82/12/01 STERNBERG, D. M. Division of Resident, Reactor Project & Engineering Programs 2pp 16483 348 24X Fiche 50-528, 82/12/01, B212210237

B212210077 Final Deficiency Rept DER 48 re Dragon Valve Co instrument line check valves seized open by welding heat Movable internal poppet for excess flow check valve redesigned by vendor to preclude binding from welding valve in place
VAN BRUNT, E. E. Arizona Public Service Co 82/12/07 STERNBERG, D. M. Division of Resident, Reactor Project & Engineering Programs 3pp 16491 083 24X Fiche 50-528, 82/12/07, B212210077

B212210225 Final Deficiency Rept DER 82-44 re Gould-Brown Boveri load ctrs w/ improperly crimped AMP termination lugs Initially reported on B20813 All terminations utilizing AMP crimp type lugs will be inspected for compliance
VAN BRUNT, E. E. Arizona Public Service Co 82/12/07 STERNBERG, D. M. Division of Resident, Reactor Project & Engineering Programs 4pp 16484 227 24X Fiche 50-528, 82/12/07, B212210225

B212260148 Final Deficiency Rept DER 82-17 re C-E documents for instrument calibr not updated in Bechtel supplier document register Initially reported on B20421 Condition not reportable under 10CFR50.55(e)
VAN BRUNT, E. E. Arizona Public Service Co 82/12/09 STERNBERG, D. M. Division of Resident, Reactor Project & Engineering Programs 4pp 16363 115 24X Fiche 50-528, 82/12/09, B212260148

B212260227 Interim Deficiency Rept 82-68 re underground cables to startup transformers Initially reported on B21126 Cables may not be adequately sized for worst case site soil temp & thermal resistivity conditions Next rept due by B30222
VAN BRUNT, E. E. Arizona Public Service Co 82/12/13 STERNBERG, D. M. Division of Resident, Reactor Project & Engineering Programs 3pp 16562 261 24X Fiche 50-528, 82/12/13, B212260227

DOCKET STN-50-529 PALO VERDE NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

8212010448 Summary of 821020 meeting w/util, C-E & Bechtel in Bethesda, MD re pipe whip restraints
LICITRA, E A Licensing Branch 3 82/11/18 Licensing Branch 3
5pp 16270 226 24X Fiche 50-528, 82/11/18, 8212010448

8211290135 Forwards "Independent QA Evaluation of Palo Verde Nuclear Generating Station Units 1, 2 & 3," Vol 1, "Executive Summary," Vol 2, "Program Results" & Vol 3, "Potential Finding Repts"
TURLEY, K L Arizona Public Service Co 82/11/19 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 16298 001
24X Fiche 50-528, 82/11/19, 8211290135

--8211290142 Forwards, under separate cover, "Independent QA Evaluation of Palo Verde Nuclear Generating Station Units 1, 2 & 3," Vols 1, 2 & 3 No reason seen to prohibit issuance of full power OL for Units 1, 2 & 3
SIMON, W A Torrey Pines Technology 82/11/19 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 16298 003
24X Fiche 50-528, 82/11/19, 8211290135

--8211290148 "Independent QA Evaluation of Palo Verde Nuclear Generating Station Units 1, 2 & 3," Vol 1, "Executive Summary"
* Torrey Pines Technology QA-C16924 V01 82/10/31 27pp
16298 004 24X Fiche 50-528, 82/11/19, 8211290135

--8211290150 "Independent QA Evaluation of Palo Verde Nuclear Generating Station Units 1, 2 & 3," Vol 2, "Program Results"
* Torrey Pines Technology QA-C16924 V02 82/10/31 163pp
16298 192 24X Fiche 50-528, 82/11/19, 8211290135

--8211290155 "Independent QA Evaluation of Palo Verde Nuclear Generating Station Units 1, 2 & 3," Vol 3, "Potential Finding Repts," Books 1 & 2
* Torrey Pines Technology QA-C16924 V03 82/10/31 1406pp
16298 355 24X Fiche 50-528, 82/11/19, 8211290135

8212080564 Requests addl info re probability study of tornado missile damage to UHS (spray pond) to complete review of PRA open item Response should be provided by 821215 W/o stated encl
KNIGHTON, O W Licensing Branch 3 82/11/23 VAN BRUNT, E E
Arizona Public Service Co 1p 16368 332 24X
Fiche 50-528, 82/11/23, 8212080564

8212130405 Responds to 821028 request to authorize use of ASME Code Cases N-338 & N-339 in component const Code Case N-338 conditionally acceptable sub; to indicated conditions Code Case N-339 approved for general use
KNIGHTON, O W Licensing Branch 3 82/11/23 VAN BRUNT, E E
Arizona Public Service Co 2pp 16412 100 24X
Fiche 50-528, 82/11/23, 8212130405

8212270418 Responds to FOIA request for documents re proposed revision &/or update to reactor safety study referred to in NUREG-0784, Chapter 10 as RS II & all documents pertaining to reactor cooling methods Forwards documents listed in app
FELTON, J M Division of Rules and Records 82/11/26 SHOLLY, S C
Union of Concerned Scientists 3pp 16549 233 24X
Fiche 50-000, 82/11/26, 8212270418

--8211050027 Forwards summary of semiscale test results & advises that board notification re test results issued W/o encl
NOVAK, T M Assistant Director for Licensing 82/09/24
Division of Licensing 1p 16549 278 24X Fiche 50-000, 82/11/26, 8212270418

8212080666 Notification of 821208 meeting w/util, SANL, C-E & Burns & Roe in Maricopa County, AZ to discuss shutdown heat removal sys design for CESSAR Sys 80 plant.
LICITRA, E A Licensing Branch 3 82/12/01 KNIGHTON, O W
Licensing Branch 3 3pp 16379 243 24X Fiche 50-528, 82/12/01, 8212080666

8212220063 Summary of 821117 meeting w/util & Bechtel in Bethesda, MD re natural circulation testing & training per THI Action Item
J O I
LICITRA, E A Licensing Branch 3 82/12/01 Licensing Branch 3
5pp 16526 348 24X Fiche 50-528, 82/12/01, 8212220063

8212070109 Forwards comments on draft environ protection plan. NRC should accept other federal agency findings w/o further review
VAN BRUNT, E E Arizona Public Service Co 82/12/02 NOVAK, T M
Assistant Director for Licensing 4pp 16327:291 24X
Fiche 50-528, 82/12/02, 8212070109

8212080179 Forwards Amend 5 to CPPR-141, CPPR-142 & CPPR-143, safety evaluation & notice of issuance & availability Amend deletes H-S-R Public Power Agency as co-owner
EISENHUT, D O Division of Licensing 82/12/06 VAN BRUNT, E E
Arizona Public Service Co 4pp 16354 061 24X
Fiche 50-528, 82/12/06, 8212080179

--8212080189 Amend 5 to CPPR-141, CPPR-142 & CPPR-143, deleting H-S-R Public Power Agency as co-owner
EISENHUT, D O Division of Licensing 82/12/06 6pp 16354 065
24X Fiche 50-528, 82/12/06, 8212080179

--8212080195 Safety evaluation supporting Amend 5 to CPPR-141, CPPR-142 & CPPR-143
* Office of Nuclear Reactor Regulation, Director 82/12/06 2pp
16354 071 24X Fiche 50-528, 82/12/06, 8212080179

--8212080204 Notice of issuance & availability of Amend 5 to CPPR-141, CPPR-142 & CPPR-143
KNIGHTON, O W Licensing Branch 3 82/12/06 2pp 16354 073
24X Fiche 50-528, 82/12/06, 8212080179

8212290473 Trip rept of 821103-04 site visit by Instrument & Control Sys Branch re physical arrangement & installation of instrumentation & control electrical equipment in accordance w/design criteria. Control cabling acceptable
LICITRA, E A Licensing Branch 3 82/12/13 Licensing Branch 3
10pp 16606 048 24X Fiche 50-528, 82/12/13, 8212290473

8212220440 Board Notifications 82-125 & 82-125A forwards info re H Etherington evaluation of flow blockage during natural circulation of PHRs Results do not adversely impact present position on reliance on natural circulation
NOVAK, T M Assistant Director for Licensing 82/12/14 Atomic
Safety and Licensing Board Panel 5pp 16523 135 24X
Fiche 50-000, 82/12/14, 8212220440

8212220461 Board Notification 82-124 forwards RJ Mattson 821123 memo re Semiscale B-UT-B test results Phenomena of core level depression & loop seal clearing may be more complex than previously supposed
NOVAK, T M Assistant Director for Licensing 82/12/14 Atomic
Safety and Licensing Board Panel 7pp 16523 169 24X
Fiche 50-000, 82/12/14, 8212220461

8212270129 Forwards change to FSAR Section 1.8, adding fission chamber detectors & sealed sources to exception taken to Reg Guide 1.38 Change will be included in upcoming FSAR amend
VAN BRUNT, E E Arizona Public Service Co 82/12/21 NOVAK, T M
Assistant Director for Licensing 3pp 16538 149 24X
Fiche 50-528, 82/12/21, 8212270129

E NRC Safety Evaluation Report (SER), supp's & correspondence

8212210107 Discusses confirmatory issue re motor operators powered from vital sources, per BER (NUREG-0857) Plant design modified to include motor operators on appropriate valves
VAN BRUNT, E E Arizona Public Service Co 82/10/28 NOVAK, T M
Assistant Director for Licensing 2pp 16491 049 24X
Fiche 50-528, 82/10/28, 8212210107

8212030031 Forwards schedule for submitting requested info & remaining outstanding & confirmatory issues discussed in Suppl 3 to SER, per NRC 820929 ltr
VAN BRUNT, E E Arizona Public Service Co 82/11/29 NOVAK, T M
Assistant Director for Licensing 6pp 16305 076 24X
Fiche 50-528, 82/11/29, 8212030031

8212130292 Advises that all piping components in essential ASME Code Class 1, 2 & 3 piping sys designed to Levels C & D svc limits evaluated against emergency & faulted conditions imposed by screening criteria All criteria met
VAN BRUNT, E E Arizona Public Service Co 82/12/09 NOVAK, T M
Assistant Director for Licensing 6pp 16390 062 24X
Fiche 50-528, 82/12/09, 8212130292

F Security, medical, emergency & fire protection plans

8212080157 Forwards response to 821202 telephone request re emergency operations facility Conceptual design for upgraded emergency response facilities under NRC review
VAN BRUNT, E E Arizona Public Service Co 82/12/06 NOVAK, T M
Assistant Director for Licensing 4pp 16354 088 24X
Fiche 50-528, 82/12/06, 8212080157

DOCKETED ITEMS

Q Adjudicatory correspondence

8212010202 Requests consideration of West Valley Agricultural Protection Council, Inc supplemental memorandum supporting Council petition to intervene Brief includes useful analysis
BERLIN, K Affiliation Unknown 82/11/29 LAZO, R M, CALLIHAN, D, COLE, R F Atomic Safety and Licensing Board Panel 1p 16258 053 24X Fiche 50-528, 82/11/29, 8212010202

8212060093 Requests West Valley Agricultural Protection Council, Inc 821018 supplemental memorandum supporting petition to intervene be stricken from record if not stricken. Joint Applicants answer should be allowed
CRAWFORD, V A Snell & Wilmer CRAWFORD, V A Joint Applicants-Palo Verde 82/11/29 LAZO, R M, CALLIHAN, D, COLE, R F Atomic Safety and Licensing Board Panel. 2pp. 16316 073 24X Fiche 50-528, 82/11/29, 8212060093

8212220118 Forwards Torrey Pines Technology 820714 ltr & revision to Torrey Pines QA/QC plan
DEWEY, L S Hearing Branch 3 82/12/09 BERNABEI, L Harmon & Weiss BERNABEI, L Hourihan, P 3pp 16503 022 24X Fiche 50-528, 82/12/09, 8212220118

K Utility Final Safety Analysis Report (FSAR) & amends

8212070328 Forwards Amend 10 to FSAR
VAN BRUNT, E E Arizona Public Service Co 82/12/06 Office of Nuclear Reactor Regulation, Director 2pp 16345 047 24X Fiche 50-528, 82/12/06, 8212070328.

--8212070331 Amend 10 to FSAR Two oversize drawings encl Aperture cards are available in FDR
* Arizona Public Service Co 82/12/31 318pp 16345 049 24X Fiche 50-528, 82/12/06, 8212070328

8212210075 Forwards Proof of Svc for Amend 10 to FSAR
VAN BRUNT, E E Arizona Public Service Co 82/12/15, Office of Nuclear Reactor Regulation, Director 3pp. 16485 252 24X Fiche 50-528, 82/12/15, 8212210075

M Antitrust correspondence

8212080179 Forwards Amend 5 to CFPB-141, CFPB-142 & CFPB-143, safety evaluation & notice of issuance & availability Amend deletes M-S-R Public Power Agency as co-owner
EISENHUT, D O Division of Licensing, 82/12/06 VAN BRUNT, E E Arizona Public Service Co 4pp. 16334 061 24X Fiche 50-528, 82/12/06, 8212080179

--8212080189 Amend 5 to CFPB-141, CFPB-142 & CFPB-143, deleting M-S-R Public Power Agency as co-owner
EISENHUT, D O Division of Licensing, 82/12/06 6pp. 16334 065 24X Fiche 50-528, 82/12/06, 8212080179

--8212080195 Safety evaluation supporting Amend 5 to CFPB-141, CFPB-142 & CFPB-143
* Office of Nuclear Reactor Regulation, Director, 82/12/06 2pp 16334 071 24X Fiche 50-528, 82/12/06, 8212080179

--8212080204 Notice of issuance & availability of Amend 5 to CFPB-141, CFPB-142 & CFPB-143
KNIGHTON, G H Licensing Branch 3 82/12/06 2pp 16354 073 24X Fiche 50-528, 82/12/06, 8212080179

Q Inspection reports, IE Bulletins & correspondence

8208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel Recirculation Sys Piping at BWR Plants " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240

8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142. 24X Fiche 50-000, 82/11/05, 8208190245

8212060143 Requests extension to respond to items of noncompliance in IE Insp Repts 50-528/82-25, 50-529/82-07 & 50-530/82-10 Rept will be submitted by 821119.
VAN BRUNT, E E Arizona Public Service Co 82/11/10 STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 1p 16314:067 24X Fiche 50-528, 82/11/10, 8212060143.

8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 107pp 16411 197 24X Fiche 50-000, 82/11/18, 8208190251

8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000, 82/11/26, 8208190256

8208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000, 82/11/30, 8208190257

8212210203 Forwards IE Insp Repts 50-528/82-29, 50-529/82-12 & 50-530/82-13 on 821004-08 No noncompliance noted
STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 82/11/30 VAN BRUNT, E E Arizona Public Service Co 2pp 16485 022 24X Fiche 50-528, 82/11/30, 8212210203

--8212210211 IE Insp Repts 50-528/82-29, 50-529/82-12 & 50-530/82-13 on 821004-08 No noncompliance noted Major areas inspected licensee action on previous insp findings, electrical cable installation & containment structural steel welding
ECKHARDT, J H, D'ANGELO, A, YOUNG, T Division of Resident, Reactor Project & Engineering Programs 82/11/29 7pp 16485 024 24X Fiche 50-528, 82/11/30, 8212210203

8208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259

8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X Fiche 50-000, 82/12/03, 8208190261

8212090346 Ack receipt of 821122 ltr informing NRC of steps taken to correct violations noted in IE insp on 820834-0903
STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 82/12/03 VAN BRUNT, E E Arizona Public Service Co 1p 16366 344 24X Fiche 50-528, 82/12/03, 8212090346

--8212090352 Response to NRC 821008 ltr re violations noted in IE insp on 820830-0903 Corrective actions as-built weld pattern reconciled against weld pattern of Consig Customline Corp
VAN BRUNT, E E Arizona Public Service Co 82/11/22 STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 4pp 16366 345 24X Fiche 50-528, 82/12/03, 8212090346

8208190267 IE Info Notice 82-49, "Correction for Sample Conditions For Air & Gas Monitoring " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16, 8208190267

8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27 " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X Fiche 50-000, 82/12/20, 8208190268

S Reportable occurrences, LERs & related correspondence

8212060275 Final Deficiency Rept DER 82-58 re Cooper Energy Svcs diesel generator high voltage cubicles w/o seismically qualified design Initially reported on 821021 Anchorage will be provided on all four sides Also reportable under Part 21
VAN BRUNT, E E Arizona Public Service Co 82/11/22 STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 3pp 16312 139 24X Fiche 50-528, 82/11/22, 8212060275

8212130267 Interim Deficiency Rept DER-82-61 re reactor coolant pumps diffuser-ring cap screws which may fail & damage pump Cap screw matl heat treatment will be changed so that matl will not be susceptible to cracking
VAN BRUNT, E E Arizona Public Service Co 82/11/22 STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 3pp 16390 158 24X Fiche 50-528, 82/11/22, 8212130267

DOCKETED ITEMS

353

8212130216 Interim Deficiency Rept DER 82-63 re design calculation error in refueling water tank Initially reported on 821026 Bechtel performing independent detailed analysis Final rept expected by 830210
VAN BRUNT, E E Arizona Public Service Co 82/11/24 STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 3pp 16390 120 24X Fiche 50-528, 82/11/24, 8212130216

821210077 Interim Deficiency Rept DER 81-14 re A-354 anchor bolt failures Initially reported on 810529 Final rept including Teledyne & Battelle repts will be submitted by 830131 Delay due to extensive evaluations
VAN BRUNT, E E Arizona Public Service Co 82/11/29 STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 2pp 16485 248 24X Fiche 50-528, 82/11/29, 821210077

821210086 Deficiency Evaluation Rept 82-64 re installation of dissimilar metal socket welds, restricted by Revision 10 of PM-204, due to delay in receipt of revised drawings
VAN BRUNT, E E Arizona Public Service Co 82/11/29 STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 2pp 16493 018 24X Fiche 50-528, 82/11/29, 821210086

821210225 Final Deficiency Rept DER 82-44 re Gould-Brown Boveri load city w/improperly crimped AMP termination lugs Initially reported on 820813 All terminations utilizing AMP crimp type lugs will be inspected for compliance
VAN BRUNT, E E Arizona Public Service Co 82/12/07 STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 4pp 16484 227 24X Fiche 50-528, 82/12/07, 821210225

821220027 Interim Deficiency Rept 82-68 re underground cables to startup transformers Initially reported on 821126 Cables may not be adequately sized for worst case site soil temp & thermal resistivity conditions Next rept due by 830222
VAN BRUNT, E E Arizona Public Service Co 82/12/13 STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 3pp 16562 261 24X Fiche 50-528, 82/12/13, 821220027

8212200407 Interim Deficiency Rept DER 82-43 re Compis main control panels w/improperly crimped termination lugs Initially reported on 820813 Due to extensive evaluation, next rept will be submitted until 830207
VAN BRUNT, E E Arizona Public Service Co 82/12/13 STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 2pp 16559 039 24X Fiche 50-529, 82/12/13, 8212200407

DOCKET STN-50-530 PALO VERDE NUCLEAR STATION, UNIT 3

A Application/construction stage documents & correspondence

8212010448 Summary of 821020 meeting w/util, C-E & Bechtel in Bethesda, MD re pipe whip restraints
LICITRA, E A Licensing Branch 3 82/11/18 Licensing Branch 3 3pp 16270 226 24X Fiche 50-528, 82/11/18, 8212010448

82121290135 Forwards "Independent QA Evaluation of Palo Verde Nuclear Generating Station Units 1, 2 & 3," Vol 1, "Executive Summary," Vol 2, "Program Results" & Vol 3, "Potential Finding Repts"
TURLEY, K L Arizona Public Service Co 82/11/19 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 16298 001 24X Fiche 50-528, 82/11/19, 82121290135

--82121290142 Forwards, under separate cover, "Independent QA Evaluation of Palo Verde Nuclear Generating Station Units 1, 2 & 3," Vols 1, 2 & 3 No reason seen to prohibit issuance of full power DL for Units 1, 2 & 3
STIMON, W A Torrey Pines Technology 82/11/19 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 16298 003 24X Fiche 50-528, 82/11/19, 82121290135

--82121290148 "Independent QA Evaluation of Palo Verde Nuclear Generating Station Units 1, 2 & 3," Vol 1, "Executive Summary"
* Torrey Pines Technology QA-C16924 V01 82/10/31 27pp 16298 004 24X Fiche 50-528, 82/11/19, 82121290135

--82121290150 "Independent QA Evaluation of Palo Verde Nuclear Generating Station Units 1, 2 & 3," Vol 2, "Program Results"
* Torrey Pines Technology QA-C16924 V02 82/10/31 163pp 16298 172 24X Fiche 50-528, 82/11/19, 82121290135

--82121290155 "Independent QA Evaluation of Palo Verde Nuclear Generating Station Units 1, 2 & 3," Vol 3, "Potential Finding Repts," Books 1 & 2
* Torrey Pines Technology QA-C16924 V03 82/10/31 1406pp 16298:355 24X Fiche 50-528, 82/11/19, 82121290135

8212080564 Requests addl info re probability study of tornado missile damage to UHS (spray pond) to complete review of PRA open item Response should be provided by 821213 W/o stated encl
KNIGHTON, O W Licensing Branch 3 82/11/23 VAN BRUNT, E E Arizona Public Service Co 1p 16368 352 24X Fiche 50-528, 82/11/23, 8212080564

8212130405 Responds to 821028 request to authorize use of ASME Code Cases N-338 & N-339 in component const Code Case N-338 conditionally acceptable suby to indicated conditions Code Case N-339 approved for general use
KNIGHTON, O W Licensing Branch 3 82/11/23 VAN BRUNT, E E Arizona Public Service Co 2pp 16412 100 24X Fiche 50-528, 82/11/23, 8212130405

8212270418 Responds to FOIA request for documents re proposed revision &/or update to reactor safety study referred to in NUREG-0784, Chapter 10 as RB II & all documents pertaining to reactor cooling methods Forwards documents listed in app
FELTON, J M Division of Rules and Records 82/11/26 BHOLLY, S C Union of Concerned Scientists 3pp 16549 233 24X Fiche 50-000, 82/11/26, 8212270418

--8211050027 Forwards summary of semiscale test results & advises that board notification re test results issued W/O encl
NOVAK, T M Assistant Director for Licensing 82/09/24 Division of Licensing 1p 16599 278 24X Fiche 50-000, 82/11/26, 8212270418

8212080666 Notification of 821208 meeting w/util, BANL, C-E & Burns & Roe in Maricopa County, AZ to discuss shutdown heat removal sys design for CESSAR Sys 80 plant
LICITRA, E A Licensing Branch 3 82/12/01 KNIGHTON, O W Licensing Branch 3 3pp 16379 243 24X Fiche 50-528, 82/12/01, 8212080666

8212220063 Summary of 821117 meeting w/util & Bechtel in Bethesda, MD re natural circulation testing & training per TMI Action Item 1 O 1
LICITRA, E A Licensing Branch 3 82/12/01 Licensing Branch 3, 5pp 16526 348 24X Fiche 50-528, 82/12/01, 8212220063

8212070109 Forwards comments on draft environ protection plan NRC should accept other federal agency findings w/o further review
VAN BRUNT, E E Arizona Public Service Co 82/12/02 NOVAK, T M Assistant Director for Licensing 4pp 16327 291 24X Fiche 50-528, 82/12/02, 8212070109

8212080179 Forwards Amend 5 to CPPR-141, CPPR-142 & CPPR-143, safety evaluation & notice of issuance & availability Amend deletes M-B-R Public Power Agency as co-owner
EISENHUT, D O Division of Licensing 82/12/06 VAN BRUNT, E E Arizona Public Service Co 4pp 16354 061 24X Fiche 50-528, 82/12/06, 8212080179

--8212080188 Amend 5 to CPPR-141, CPPR-142 & CPPR-143, deleting M-B-R Public Power Agency as co-owner.
EISENHUT, D O Division of Licensing 82/12/06 6pp 16354 066 24X Fiche 50-528, 82/12/06, 8212080179

--8212080195 Safety evaluation supporting Amend 5 to CPPR-141, CPPR-142 & CPPR-143
* Office of Nuclear Reactor Regulation, Director 82/12/06 2pp 16354 071 24X Fiche 50-528, 82/12/06, 8212080179

--8212080204 Notice of issuance & availability of Amend 5 to CPPR-141, CPPR-142 & CPPR-143
KNIGHTON, O W Licensing Branch 3 82/12/06 2pp 16354 073 24X Fiche 50-528, 82/12/06, 8212080179

8212240473 Trip rept of 821103-04 site visit by Instrument & Control Sys Branch re physical arrangement & installation of instrumentation & control electrical equipment in accordance w/design criteria Control cabling acceptable
LICITRA, E A Licensing Branch 3 82/12/13 Licensing Branch 3 10pp 16606 048 24X Fiche 50-528, 82/12/13, 8212240473

8212220440 Board Notifications 82-125 & 82-125A forwards info re H Etherington evaluation of flow blockage during natural circulation of PWRs Results do not adversely impact present position on reliance on natural circulation
NOVAK, T M Assistant Director for Licensing 82/12/14 Atomic Safety and Licensing Board Panel, 5pp 16523 135 24X Fiche 50-000, 82/12/14, 8212220440

8212220461 Board Notification 82-124 forwards RJ Mattson 821123 memo re Semiscale S-UT-8 test results, Phenomena of core level depression & loop seal clearing may be more complex than previously supposed
NOVAK, T M Assistant Director for Licensing, 82/12/14 Atomic Safety and Licensing Board Panel 7pp 16523 169 24X Fiche 50-000, 82/12/14, 8212220461

DOCKETED ITEMS

8212270129 Forwards change to FSAR Section 1 B, adding fission chamber detectors & sealed sources to exception taken to Reg Guide 1.3B Change will be included in upcoming FSAR amend
VAN BRUNT, E E Arizona Public Service Co 82/12/21 NOVAK, T M
Assistant Director for Licensing 3pp 16538 149 24X
Fiche 50-528, 82/12/21, 8212270129

E NRC Safety Evaluation Report (SER), suppis & correspondence

8212210107 Discusses confirmatory issue re motor operators powered from vital sources, per SER (NUREG-0857) Plant design modified to include motor operators on appropriate valves
VAN BRUNT, E E Arizona Public Service Co 82/10/28 NOVAK, T M
Assistant Director for Licensing 2pp 16491.049 24X
Fiche 50-528, 82/10/28, 8212210107

8212030031 Forwards schedule for submitting requested info & remaining outstanding & confirmatory issues discussed in Suppl 3 to SER, per NRC 820929 ltr
VAN BRUNT, E E Arizona Public Service Co 82/11/29 NOVAK, T M
Assistant Director for Licensing 6pp 16305 076 24X
Fiche 50-528, 82/11/29, 8212030031

8212130292 Advises that all piping components in essential ASME Code Class 1, 2 & 3 piping are designed to Levels C & D svc limits evaluated against emergency & faulted conditions imposed by screening criteria All criteria met
VAN BRUNT, E E Arizona Public Service Co 82/12/09 NOVAK, T M
Assistant Director for Licensing 6pp 16390-062 24X
Fiche 50-528, 82/12/09, 8212130292

F Security, medical, emergency & fire protection plans

8212080157 Forwards response to 821202 telephone request re emergency operations facility Conceptual design for upgraded emergency response facilities under NRC review.
VAN BRUNT, E E Arizona Public Service Co 82/12/06 NOVAK, T M
Assistant Director for Licensing 4pp 16354 088 24X
Fiche 50-528, 82/12/06, 8212080157

G Adjudicatory correspondence

8212010202 Requests consideration of West Valley Agricultural Protection Council, Inc supplemental memorandum supporting Council petition to intervene Brief includes useful analysis
BERLIN, K Affiliation Unknown 82/11/29 LAZO, R M, CALLIHAN, D, COLE, R F Atomic Safety and Licensing Board Panel 1p 16258 053 24X
Fiche 50-528, 82/11/29, 8212010202

8212060095 Requests West Valley Agricultural Protection Council, Inc 821018 supplemental memorandum supporting petition to intervene be stricken from record If not stricken, Joint Applicants answer should be allowed
CRAWFORD, V A Shell & Wilmer CRAWFORD, V A Joint Applicants-Palo Verde 82/11/29 LAZO, R M, CALLIHAN, D, COLE, R F Atomic Safety and Licensing Board Panel 2pp 16316 073 24X
Fiche 50-528, 82/11/29, 8212060095

8212220118 Forwards Torrey Pines Technology 820714 ltr & revision to Torrey Pines QA/QC plan
DEWEY, L S Hearing Branch 3 82/12/09 BERNABEI, L Harmon & Weiss BERNABEI, L Hourihan, P 3pp 16503 022 24X
Fiche 50-528, 82/12/09, 8212220118

I Utility Final Safety Analysis Report (FSAR) & amends

8212070328 Forwards Amend 10 to FSAR
VAN BRUNT, E E Arizona Public Service Co 82/12/06 Office of Nuclear Reactor Regulation, Director 2pp 16345 047 24X
Fiche 50-528, 82/12/06, 8212070328

-8212070331 Amend 10 to FSAR Two oversize drawings encl Aperture cards are available in PDR
* Arizona Public Service Co 82/12/31 318pp 16345 049 24X
Fiche 50-528, 82/12/06, 8212070328

821210075 Forwards Proof of Svc for Amend 10 to FSAR
VAN BRUNT, E E Arizona Public Service Co 82/12/15 Office of Nuclear Reactor Regulation, Director 3pp 16485 252 24X
Fiche: 50-528, 82/12/13, 821210075

Antitrust correspondence

8212080179 Forwards Amend 5 to CPPR-141, CPPR-142 & CPPR-143, safety evaluation & notice of issuance & availability Amend deletes M-S-R Public Power Agency as co-owner
EISENHUT, D O Division of Licensing 82/12/06 VAN BRUNT, E E Arizona Public Service Co 4pp 16354, 061 24X
Fiche 50-528, 82/12/06, 8212080179

--8212080188 Amend 5 to CPPR-141, CPPR-142 & CPPR-143, deleting M-S-R Public Power Agency as co-owner
EISENHUT, D O Division of Licensing 82/12/06 6pp 16354 065 24X
Fiche 50-528, 82/12/06, 8212080179

--8212080195 Safety evaluation supporting Amend 5 to CPPR-141, CPPR-142 & CPPR-143
* Office of Nuclear Reactor Regulation, Director 82/12/06 2pp 16354 071 24X
Fiche 50-528, 82/12/06, 8212080179

--8212080204 Notice of issuance & availability of Amend 5 to CPPR-141, CPPR-142 & CPPR-143
KNIGHTON, O H Licensing Branch 3 82/12/06 2pp 16354 073 24X
Fiche 50-528, 82/12/06, 8212080179

J Inspection reports, IE Bulletins & correspondence

8208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X
Fiche 50-000, 82/10/28, 8208190240

8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X
Fiche 50-000, 82/11/05, 8208190245

8212060143 Requests extension to respond to items of noncompliance in IE Insp Repts 50-528/82-25, 50-529/82-09 & 50-530/82-10 Rept will be submitted by 821119
VAN BRUNT, E E Arizona Public Service Co 82/11/10 STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 1p 16314 069 24X
Fiche 50-528, 82/11/10, 8212060143

8208190231 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/10 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X
Fiche 50-000, 82/11/10, 8208190231

8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X
Fiche 50-000, 82/11/26, 8208190256

8208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X
Fiche 50-000, 82/11/30, 8208190257

8212210203 Forwards IE Insp Repts 50-528/82-29, 50-529/82-12 & 50-530/82-13 on 821004-08 No noncompliance noted
STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 82/11/30 VAN BRUNT, E E Arizona Public Service Co 2pp 16485 022 24X
Fiche 50-528, 82/11/30, 8212210203

--8212210211 IE Insp Repts 50-528/82-29, 50-529/82-12 & 50-530/82-13 on 821004-08 No noncompliance noted Major areas inspected license action on previous insp findings, electrical cable installation & containment structural steel welding
ECKHARDT, J H, D'ANGELO, A, YOUNG, T Division of Resident, Reactor Project & Engineering Programs 82/11/29 7pp 16485 024 24X
Fiche: 50-528, 82/11/30, 8212210203

8208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X
Fiche 50-000, 82/12/03, 8208190259

8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X
Fiche: 50-000, 82/12/03, 8208190261

8212090346 Ack receipt of 821122 ltr informing NRC of steps taken to correct violations noted in IE insp on 820834-0903
STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 82/12/03 VAN BRUNT, E E Arizona Public Service Co 1p 16366 344 24X
Fiche 50-528, 82/12/03, 8212090346

-8212090352 Responds to NRC 821008 ltr re violations noted in IE insp on 820830-0903 Corrective actions as-built weld pattern reconciled against weld pattern of Comsip Customline Corp
VAN BRUNT, E E Arizona Public Service Co 82/11/22
STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 3pp 16366 345 24X Fiche 50-528, 82/12/03, 8212090546

8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16, 8208190267

8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type 1TE-27 " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X Fiche 50-000, 82/12/20, 8208190268

9 Reportable occurrences, LERs & related correspondence

8212060082 Final deficiency rept re Pullman 24-inch pipe spools w/ internal surface indications violating min wall thickness Initially reported on 820831 Visual exam performed Deficiency determined not reportable per 10CFR50 55(e)
VAN BRUNT, E E Arizona Public Service Co 82/11/19 STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 4pp 16316 069 24X Fiche 50-530, 82/11/19, 8212060082

8212060275 Final Deficiency Rept DER 82-58 re Cooper Energy Svcs diesel generator high voltage cubicles w/o Seismically qualified design Initially reported on 821021 Anchorage will be provided on all four sides Also reportable under Part 21
VAN BRUNT, E E Arizona Public Service Co 82/11/22 STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 3pp 16312 139 24X Fiche 50-528, 82/11/22, 8212060275

8212130259 Final deficiency rept re nonconforming matl certification for diesel generator piston Initially reported on 820930 Nonconformance Rept MO-1445 issued to control & document piston replacement prior to unit startup
VAN BRUNT, E E Arizona Public Service Co 82/11/22 STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 3pp 16396 244 24X Fiche 50-530, 82/11/22, 8212130259

8212130267 Interim Deficiency Rept DER-82-61 re reactor coolant pumps diffuser-ring cap screws which may fail & damage pump Cap screw matl heat treatment will be changed so that matl will not be susceptible to cracking
VAN BRUNT, E E Arizona Public Service Co 82/11/22 STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 3pp 16390 158 24X Fiche 50-528, 82/11/22, 8212130267

8212130309 Final deficiency rept re improperly crimped termination lugs in control bldg switchgear supplied by GE Initially reported on 820802 Connectors not meeting vendor specs will be corrected Also reported per Part 21
VAN BRUNT, E E Arizona Public Service Co 82/11/23 STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 3pp 16387 340 24X Fiche 50-530, 82/11/23, 8212130309

8212130216 Interim Deficiency Rept DER 82-63 re design calculation error in refueling water tank Initially reported on 821026 Bechtel performing independent detailed analysis Final rept expected by 830210
VAN BRUNT, E E Arizona Public Service Co 82/11/24 STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 3pp 16390 120 24X Fiche 50-528, 82/11/24, 8212130216

8212210077 Interim Deficiency Rept DER 81-14 re A-354 anchor bolt failures Initially reported on 810529 Final rept including Teledyne & Battelle repts will be submitted by 830131 Delay due to extensive evaluations
VAN BRUNT, E E Arizona Public Service Co 82/11/29 STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 2pp 16485 248 24X Fiche 50-528, 82/11/29, 8212210077

8212210086 Deficiency Evaluation Rept 82-64 re installation of dissimilar metal socket welds, restricted by Revision 10 of PM-204, due to delay in receipt of revised drawings Deficiency not reportable per 10CFR50 55(e)
VAN BRUNT, E E Arizona Public Service Co 82/11/29 STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 2pp 16493 018 24X Fiche 50-528, 82/11/29, 8212210086

8212210225 Final Deficiency Rept DER 82-44 re Gould-Brown Boveri load ctrs w/ improperly crimped AMP termination lugs Initially reported on 820813 All terminations utilizing AMP crimp type lugs will be inspected for compliance
VAN BRUNT, E E Arizona Public Service Co 82/12/07 STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 4pp 16484 227 24X Fiche 50-528, 82/12/07, 8212210225

8212280227 Interim Deficiency Rept 82-68 re underground cables to startup transformers Initially reported on 821126 Cables may not be adequately sized for worst case site soil temp & thermal resistivity conditions Next rept due by 830222
VAN BRUNT, E E Arizona Public Service Co 82/12/13 STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 3pp 16562 261 24X Fiche 50-528, 82/12/13, 8212280227

DOCKET 50-537 CLINCH RIVER BREEDER REACTOR

A Application/construction stage documents & correspondence

8212230253 Forwards radiological dose calculations used in assessing potential impact of CRBR accidents on Oak Ridge Gaseous Diffusion Plant & Y-12 Plant operation
LONGENECKER, J Energy, Dept of, Clinch River Breeder Reactor Plant 82/10/28 CHECK, P S Clinch River Breeder Reactor Program Office 5pp 16511 049 24X Fiche 50-537, 82/10/28, 8212230253

8212270484 Notification of contract execution "Casework-CRBR," awarded to BBA
FLEETOR, C Technical Assistance Contracts Branch FIN B-8601 82/11/05 CHECK, P S Clinch River Breeder Reactor Program Office MORRIS, B NRC - No Detailed Affiliation Given 1p 16549 360 24X Fiche 50-537, 82/11/05, 8212270484

--8212270501 Contract "Casework-CRBR," awarded to BBA
* Engineering & Economics Research, Inc * Small Business Administration HAGAN, T F Division of Contracts FIN B-8601 82/11/05 2pp 16549 361 24X Fiche 50-537, 82/11/05, 8212270484

8212060395 Supplemental response to 820906 FOIA request for eight categories of documents Forwards documents listed in App A for Items 4 & 5 No other documents subj to request located
FELTON, J M Division of Rules and Records 82/11/08 AUDIN, L Affiliation Unknown 2pp 16322 342 24X Fiche 50-320, 82/11/08, 8212060395

--8212060403 Items of interest re CRBR fuel cycle environ review, spent fuel reprocessing & TMI-2 waste mgt task force for wk ending 820709
* Office of Nuclear Material Safety & Safeguards, Director 82/07/09 1p 16322 345 24X Fiche 50-000, 82/11/08, 8212060395

8212230262 Summarizes 821108 meeting re CRBR plant steam supply sys component degradation monitoring Viewgraphs encl
LONGENECKER, J Energy, Dept of, Clinch River Breeder Reactor Plant 82/11/09 CHECK, P S Clinch River Breeder Reactor Program Office 11pp 16508 189 24X Fiche 50-537, 82/11/09, 8212230262

8212010161 Forwards summary of 820915 meeting w/NRC in Bethesda, MD re thermal margin beyond design basis Meeting agenda, viewgraphs & attendance list encl
LONGENECKER, J Energy, Dept of, Clinch River Breeder Reactor Plant 82/11/12 CHECK, P S Clinch River Breeder Reactor Program Office 140pp 16259 253 24X Fiche 50-537, 82/11/12, 8212010161

8212030323 "SSC Development, Validation & Application & CRBR Balance of Plant Modeling," monthly highlights for Oct 1982
GUPPY, J O Brookhaven National Laboratory FIN A-3015 8212030323 82/11/12 CURTIS, R T Severe Accident Assessment Branch 7pp 16316 329 24X Fiche 50-537, 82/11/12, 8212030323

8212010146 Forwards addl info for items identified in DOE 820904 ltr re summary for Mechanical Engineering Branch/CRBR 820908-09 meeting
LONGENECKER, J Energy, Dept of, Clinch River Breeder Reactor Plant 82/11/23 CHECK, P S Clinch River Breeder Reactor Program Office 27pp 16260 239 24X Fiche 50-537, 82/11/23, 8212010146

8212130157 A SIMULANT-MATERIAL EXPERIMENTAL INVESTIGATION OF FLOW DYNAMICS IN THE CRBR UPPER CORE STRUCTURE
WILHELM, D, STARKOVICH, V S, CHAPYAK, E J Los Alamos Scientific Laboratory FIN A-7235 NUREG/CR-2866 82/11/30 Division of Accident Evaluation 82pp 16415 284 24X Fiche 50-537, 82/11/30, 8212130157

8212020262 Summarizes 821123 meeting w/NRC, Burns & Roe, GE & Westinghouse re resolution of equipment qualification items
LONGENECKER, J Energy, Dept of 82/12/01 CHECK, P S Clinch River Breeder Reactor Program Office 5pp 16279 347 24X Fiche 50-537, 82/12/01, 8212020262

8212020303 Forwards update to PSAR Section 6.2 re open containment Update responds to Item 6 of action items from 821018 containment sys meeting Remaining PSAR amends will be submitted in early Dec
LONGENECKER, J Energy, Dept of, Clinch River Breeder Reactor Plant 82/12/01 CHECK, P S Clinch River Breeder Reactor Program Office 7pp 16278 166 24X Fiche 50-537, 82/12/01, 8212020303

DOCKETED ITEMS

8212080127 Notification of 821216 meeting w/applicants & DOE in Bethesda, MD to discuss shutdown heat removal sys
STARK, R M Clinch River Breeder Reactor Program Office 82/12/02
CHECK, P S Clinch River Breeder Reactor Program Office 3pp
16368 285 24X Fiche 50-537, 82/12/02, 8212080127

8212080143 Notification of 821208-09 meetings w/applicants & DOE in Bethesda, MD to discuss structural engineering review items
STARK, R M Clinch River Breeder Reactor Program Office 82/12/02
CHECK, P S Clinch River Breeder Reactor Program Office 3pp
16367 359 24X Fiche 50-537, 82/12/02, 8212080143

8212070226 Forwards revised responses to NRC 430 Series questions
Revisions incorporate mods re electric power & mechanical sys PSAR Sections 8.3.1.2.14 & 8.3.1.4 revised Responses will be incorporated into PSAR, Amend 74
LONGENECKER, J Energy, Dept of, Clinch River Breeder Reactor Plant 82/12/06 CHECK, P S Clinch River Breeder Reactor Program Office 320pp
16335 338 24X Fiche 50-537, 82/12/06, 8212070226

8212070243 Forwards addl info requested during 820921-22 & 1118-19 instrumentation working meetings Amended PSAR pages will be incorporated into future PSAR revision
LONGENECKER, J Energy, Dept of, Clinch River Breeder Reactor Plant 82/12/06 CHECK, P S Clinch River Breeder Reactor Program Office 77pp
16333 214 24X Fiche 50-537, 82/12/06, 8212070243

8212070311 Discusses reactor design (Chapter 4) open items raised at 821225-26 working meeting & forwards addl info documenting NRC issues & project resolutions
LONGENECKER, J Energy, Dept of, Clinch River Breeder Reactor Plant 82/12/06 CHECK, P S Clinch River Breeder Reactor Program Office 13pp
16343 168 24X Fiche 50-537, 82/12/06, 8212070311

8212160200 Documents commitments made at 821202-03 meeting w/Westinghouse, ORNL & Burns & Roe re CRBR control room design Draft revisions to App H, Item I D 1 encl
LONGENECKER, J Energy, Dept of, Clinch River Breeder Reactor Plant 82/12/06 CHECK, P S Clinch River Breeder Reactor Program Office 7pp
16446 116 24X Fiche 50-537, 82/12/06, 8212160200

8212140374 Forwards info on thermal margins beyond design base, per 820918 meeting between NRC & CRBR project mgt
LONGENECKER, J Energy, Dept of, Clinch River Breeder Reactor Plant 82/12/07 CHECK, P S Clinch River Breeder Reactor Program Office 2pp
16401 156 24X Fiche 50-537, 82/12/07, 8212140374

--8212140380 "Aerosol Release From Sodium-Concrete Reactions" Prototype hydrogen filter preliminary test results encl
MULLESTEIN, L. D. COLBURN, R. P. Hanford Engineering Development Laboratory 82/10/31 23pp 16401 158 24X
Fiche 50-537, 82/12/07, 8212140374

--8212140388 "Hydrogen Distribution in Breeder Reactor Containments," summary rept Miscellaneous updates to CRBRP-3, Vol 2 info on containment cleanup sys & revised response to Question C8760 144 on axisymmetric distribution of temps encl
BLOND, G R Hanford Engineering Development Laboratory 82/10/31 67pp 16401 181 24X Fiche 50-537, 82/12/07, 8212140374

8212170190 Forwards marked-up revision to CRBRP-3, Vol 1, "Structural Margin Beyond Design Base," in response to Question C8760 162
LONGENECKER, J Energy, Dept of, Clinch River Breeder Reactor Plant 82/12/13 CHECK, P S Clinch River Breeder Reactor Program Office 5pp
16450 001 24X Fiche 50-537, 82/12/13, 8212170190

8212220160 Summary of 820915 meeting w/Sandia in Bethesda, MD re details on venting of reactor cavity, operability of containment vent/purge & cleanup sys & open issues from 820817 meeting
STARK, R M Clinch River Breeder Reactor Program Office 82/12/13
Clinch River Breeder Reactor Program Office 3pp 16525 347 24X
Fiche 50-537, 82/12/13, 8212220160

8212150054 Summarizes Mechanical Engineering Branch/CRBR Project 821122-23 meeting Matrix indicating resolution status &/or addl info for items identified in 820904 1tr & PSAR pages documenting resolution of items encl
LONGENECKER, J Energy, Dept of, Clinch River Breeder Reactor Plant 82/12/14 CHECK, P S Clinch River Breeder Reactor Program Office 315pp
16426 241 24X Fiche 50-537, 82/12/14, 8212150054

8212150133 Forwards addl info requested during 820921, 22 & 1118 & 19 meetings re instrumentation & control (PSAR Chapter 7) Encl amended PSAR pages will be incorporated into future PSAR revision
LONGENECKER, J Energy, Dept of, 82/12/14, CHECK, P S Clinch River Breeder Reactor Program Office MAUCH, J L Instrumentation & Control Systems Branch 33pp 16422 333 24X Fiche 50-537, 82/12/14, 8212150133

8212200077 Forwards addl clarification re training program per PSAR/ SRP, Section 13.2 Mod will be incorporated into future amend
LONGENECKER, J Energy, Dept of, Clinch River Breeder Reactor Plant 82/12/17 CHECK, P S Clinch River Breeder Reactor Program Office 3pp
16470 038 24X Fiche 50-537, 82/12/17, 8212200077

8212210045 Summarizes 821216 meeting w/NRC, BNL, ANL, Westinghouse, EG&G & Barthold & Assoc re shutdown heat removal Viewgraphs encl
LONGENECKER, J Energy, Dept of, Clinch River Breeder Reactor Plant 82/12/20 CHECK, P S Clinch River Breeder Reactor Program Office 40pp
16490 227 24X Fiche 50-537, 82/12/20, 8212210045

8212210050 Forwards responses to NRC comments & amended sections of PSAR Chapter 9, "Plant Auxiliary Sys," per 821215 meeting w/NRC Info will be incorporated into Amend 75 of PSAR, scheduled for Jan 1983
LONGENECKER, J Energy, Dept of, Clinch River Breeder Reactor Plant 82/12/20 CHECK, P S Clinch River Breeder Reactor Program Office 101pp
16490 267 24X Fiche 50-537, 82/12/20, 8212210050

8212210055 Forwards addl info requested at 820921 & 22 & 1118 & 19 working meetings on PSAR Chapter 7, "Instrumentation" & info inadvertently omitted from 821206 submittal Info will be incorporated into future PSAR revision
LONGENECKER, J Energy, Dept of, Clinch River Breeder Reactor Plant 82/12/20 CHECK, P S Clinch River Breeder Reactor Program Office 11pp
16492 237 24X Fiche 50-537, 82/12/20, 8212210055

8212230007 Summarizes 821220 environ qualification meeting w/Burns & Roe, Westinghouse, NRC & GE Agreements, commitments & viewgraphs encl
LONGENECKER, J Energy, Dept of, Clinch River Breeder Reactor Plant 82/12/21 CHECK, P S Clinch River Breeder Reactor Program Office 38pp
16511 067 24X Fiche 50-537, 82/12/21, 8212230007

8212230237 Forwards responses to action items generated at 821208 meeting w/NRC re filter efficiency for venturi scrubber & plugging of vent pipes behind liners during DBA & thermal margin beyond design base conditions
LONGENECKER, J Energy, Dept of, Clinch River Breeder Reactor Plant 82/12/21 CHECK, P S Clinch River Breeder Reactor Program Office 6pp
16511 054 24X Fiche 50-537, 82/12/21, 8212230237

8212230263 Summarizes 821220 reliability program meeting Viewgraphs encl
LONGENECKER, J Energy, Dept of, Clinch River Breeder Reactor Plant 82/12/21 CHECK, P S Clinch River Breeder Reactor Program Office 25pp
16508 213 24X Fiche 50-537, 82/12/21, 8212230263

8212230300 Forwards analysis of structural margin beyond design base loads on reactor vessel support ledge, in response to 821209 request
LONGENECKER, J Energy, Dept of, Clinch River Breeder Reactor Plant 82/12/21 CHECK, P S Clinch River Breeder Reactor Program Office 13pp
16508 286 24X Fiche 50-537, 82/12/21, 8212230300

8212230321 Forwards addl info re secondary control rod sys, per 821015 1tr re meeting summary for reactor mechanical shutdown sys
821014 working meeting
LONGENECKER, J Energy, Dept of, Clinch River Breeder Reactor Plant 82/12/21 CHECK, P S Clinch River Breeder Reactor Program Office 20pp
16507 031 24X Fiche 50-537, 82/12/21, 8212230321

8212270231 Forwards response to NRC 821012 request for addl info re intermediate heat transport sys tee overtemp problem
LONGENECKER, J Energy, Dept of, Clinch River Breeder Reactor Plant 82/12/22 CHECK, P S Clinch River Breeder Reactor Program Office 5pp
16537 207 24X Fiche 50-537, 82/12/22, 8212270231

8212270302 Forwards response to request for addl info re DOE 821214 1tr summarizing Mechanical Engineering Branch & CRBR 821122-24 meeting Encl info will be incorporated into Amend 75 to PSAR
LONGENECKER, J Energy, Dept of, Clinch River Breeder Reactor Plant 82/12/22 CHECK, P S Clinch River Breeder Reactor Program Office 33pp
16530 128 24X Fiche 50-537, 82/12/22, 8212270302

8212270185 Forwards addl info re PSAR Chapter 4, "Reactor" Chapter 4.3, Item 1 e & Chapter 4.4, Item 1 d will be incorporated in Amend 75 to PSAR scheduled for submittal Jan 1983
LONGENECKER, J Energy, Dept of, Clinch River Breeder Reactor Plant 82/12/23 CHECK, P S Clinch River Breeder Reactor Program Office 9pp
16539 013 24X Fiche 50-537, 82/12/23, 8212270185

8212270229 Forwards addl info requested at 821118-19 meetings re instrumentation (Chapter 7) Amended PSAR pages will be incorporated into Amend 75 of PSAR to be submitted in Jan 1983
LONGENECKER, J Energy, Dept of, Clinch River Breeder Reactor Plant 82/12/23 CHECK, P S Clinch River Breeder Reactor Program Office 8pp
16537 212, 24X Fiche 50-537, 82/12/23, 8212270229

B212270248 Forwards addl info requested at B20921 meeting on energetics analysis
LONGENECKER, J Energy, Dept of, Clinch River Breeder Reactor Plant
B2/12/23 CHECK, P S Clinch River Breeder Reactor Program Office
10pp 16534 038 24X Fiche 50-537, B2/12/23, B212270248

--B212270250 "Assessment of Unprotected Loss of Flow Accident at End of Cycle-4 in CRBR Heterogeneous Core Design"
CAHALAN, J E, DUNN, F E, GRUBER, E E Argonne National Laboratory
B2/12/31 87pp 16534 048 24X Fiche 50-537, B2/12/23, B212270248

--B212270254 "Freezing of Driver Fuel Upon Entry to Inner Blanket"
EPSTEIN, M Fauske & Associates, Inc B2/12/23 4pp 16534 136
24X Fiche 50-537, B2/12/23, B212270248

--B212270260 "Results of Reactor Matl Fuel Dispersal Tests GAP-3 & GAP-4"
SPENCER, B W, VETTER, D L, WESEL, R Argonne National Laboratory
B2/12/23 36pp 16534 140 24X Fiche 50-537, B2/12/23, B212270248

B212300215 Forwards addl info re plant procedures per agreement
Response will be incorporated into PSAR Amend 75, scheduled for submittal in Jan 1983
LONGENECKER, J Energy, Dept of, Clinch River Breeder Reactor Plant
B2/12/28 CHECK, P S Clinch River Breeder Reactor Program Office
3pp 16598 047 24X Fiche 50-537, B2/12/28, B212300215

B212300253 Forwards addl info re seismic qualification discussed in PSAR Section 3.10 & revision to Question 270.10 per B212123 request
LONGENECKER, J Energy, Dept of, Clinch River Breeder Reactor Plant
B2/12/28 CHECK, P S Clinch River Breeder Reactor Program Office
6pp 16595 228 24X Fiche 50-537, B2/12/28, B212300253

B212300299 Forwards updated responses to Questions 412.1, 2 & 4 re project technical resources, training & utilization of industry experience Updated PSAR Pages H-7 & B encl
Responses & questions will be incorporated in PSAR amend
LONGENECKER, J Energy, Dept of, Clinch River Breeder Reactor Plant
B2/12/28 CHECK, P S Clinch River Breeder Reactor Program Office
111pp 16594 084 24X Fiche 50-537, B2/12/28, B212300299

B212300343 Forwards illustration of margin in plant protection sys setpoints demonstrating application of instrument channel uncertainties, per NRC request
LONGENECKER, J Energy, Dept of, Clinch River Breeder Reactor Plant
B2/12/28 CHECK, P S Clinch River Breeder Reactor Program Office
2pp 16594 225 24X Fiche 50-537, B2/12/28, B212300343

B212300248 Application to amend application for CP, consisting of Amend 74 to PSAR Amend revises responses to NRC Questions CS430.1 through 104
LONGENECKER, J Energy, Dept of, Clinch River Breeder Reactor Plant
B2/12/30 CHECK, P S Clinch River Breeder Reactor Program Office
App 16595 284 24X Fiche 50-537, B2/12/30, B212300248

B Utility Preliminary Safety Analysis Report, amends

B212150177 Forwards JR Ellwanger affidavit certifying distribution of PSAR Amend 73 to listed govt agencies & officials on B21130
LONGENECKER, J Energy, Dept of, Clinch River Breeder Reactor Plant
B2/12/07 DENTON, H Office of Nuclear Reactor Regulation, Director
2pp 16430 158 24X Fiche 50-537, B2/12/07, B212150177

B212300248 Application to amend application for CP, consisting of Amend 74 to PSAR Amend revises responses to NRC Questions CS430.1 through 104
LONGENECKER, J Energy, Dept of, Clinch River Breeder Reactor Plant
B2/12/30 CHECK, P S Clinch River Breeder Reactor Program Office
App 16595 284 24X Fiche 50-537, B2/12/30, B212300248

--B212300249 Amend 74 to PSAR
* Energy, Dept of, Clinch River Breeder Reactor Plant B2/12/31
715pp 16595 288 24X Fiche 50-537, B2/12/30, B212300248

D NRC Draft/Final Environmental Statements, suppl & correspondence

B212080201 Offers no comments on Suppl 1 to FES for facility
NEEL, A W East Tennessee Development District B2/11/18
CHECK, P S Clinch River Breeder Reactor Program Office 1p
16353 362 24X Fiche 50-537, B2/11/18, B212080201

F Security, medical, emergency & fire protection plans

B212010011 Forwards Draft B to "CRBR Fire Hazard Analysis Rept," for NRC assessment of intended coverage for plant Addl work will be required at FSAR stage to completely define & describe procedures & techniques
LONGENECKER, J Energy, Dept of, Clinch River Breeder Reactor Plant
B2/11/30 CHECK, P S Clinch River Breeder Reactor Program Office
1p 16261 009 24X Fiche 50-537, B2/11/30, B212010011

--B212010015 "CRBR Fire Hazard Analysis Rept," Draft B
HONO, C Burns & Roe Co ES-26NS-10-004 DRF B B2/11/01 666pp
16261 010 24X Fiche 50-537, B2/11/30, B212010011

B212270294 Forwards responses to requests for addl info re emergency planning, including location of plant emergency personnel & plant data transmission & control room locations Encl info will be included in Amend 75 to PSAR
LONGENECKER, J Energy, Dept of, Clinch River Breeder Reactor Plant
B2/12/22 CHECK, P S Clinch River Breeder Reactor Program Office
7pp 16530 001 24X Fiche 50-537, B2/12/22, B212270294

G Adjudicatory correspondence

B212060113 Notification of pending litigation Cases include petition for review & application for stay of Commission B20817 order, EPA & NRC CRBR Project Ofc agreement issue & LMFBR program statement Certificate of Svc encl
EDGAR, O L Project Management Corp BERGHOLZ, W E Energy, Dept of B2/12/03 17pp 16316 085 24X Fiche 50-537, B2/12/03, B212060113

B212080257 Suggestions for procedures & scheduling re Court of Appeals, DC Circuit, B21202 remand of applicant exemption requests to Commission Certificate of Svc encl
GREENBERG, E V, FINAMORE, B A Natural Resources Defense Council
GREENBERG, E V Sierra Club B2/12/07 9pp 16354 117 24X Fiche 50-537, B2/12/07, B212080257

B212150123 Forwards chart illustrating proposed witness schedule for contentions to be addressed on B21213-17 during concluding phase of LMA evidentiary hearings
SWANSON, D T Hearing Branch 1 B2/12/07 MILLER, M, HAND, C H, LINENBERGER, Q Atomic Safety and Licensing Board Panel 2pp 16425 240 24X Fiche 50-537, B2/12/07, B212150123

B212090082 Notification of pending litigation Court of Appeals, DC Circuit, remanded case re exemption to allow site preparation activities to Commission to reconsider 10CFR50.12 availability W/Certificate of Svc
EDGAR, O L Project Management Corp BERGHOLZ, W E Energy, Dept of B2/12/08 11pp 16357 335 24X Fiche 50-537, B2/12/08, B212090082

B212130205 Order establishing procedures for reconsidering whether exigent circumstances exist warranting grant of applicant request for exemption Order issued per Court of Appeals, DC Circuit remand of record re exemption request
CHILK, S J Office of the Secretary of the Commission B2/12/10 6pp 16396 193 24X Fiche 50-537, B2/12/10, B212130205

B212200015 Brief in response to Commission B21210 order, Commission should reaffirm B20817 decision Section 50.12 procedures appropriately invoked due to compelling or extraordinary circumstances present Certificate of Svc encl
EDGAR, O L Project Management Corp SILVERSTROM, L Energy, Dept of B2/12/15 27pp 16473 035 24X Fiche 50-537, B2/12/15, B212200015

B21210326 Forwards corrected Page 3 to Commission B21210 order.
STUCKY, B W Docketing & Services Branch B2/12/17 Office of the Executive Legal Director 1p 16496 244 24X Fiche 50-537, B2/12/17, B21210326

--B212210328 Corrected Page 3 to Commission B21210 order
* Commissioners B2/12/17 1p 16496 245 24X
Fiche 50-537, B2/12/17, B212210328

B212230200 Brief in response to Commission B21210 order establishing procedure for reconsideration of existence of exigent circumstances warranting licensing relief under 10CFR50.12
No such circumstances exist Certificate of Svc encl
GREENBERG, E V, FINAMORE, B A Natural Resources Defense Council
GREENBERG, E V Sierra Club B2/12/21 Commissioners 33pp
16510 237 24X Fiche 50-537, B2/12/21, B212230200

DOCKETED ITEMS

8212270245 Advises that "Conference Rept on Continuing Resolution for FY83," published in 821220 Congressional Record Language cited in NRDC & Sierra Club 821221 brief appears on Page H10636
GREENBERG, E V Galloway & Greenberg 82/12/23 PALLADINO, N J, GILINSKY, V, ROBERTS, T M Commissioners 6pp 16537 160 24X Fiche 50-537, 82/12/23, 8212270245

8212300011 Reply in opposition to intervenor response to Commission 821210 order Circumstances surrounding CRBR clearly warrant relief under 10CFR50.12 Order eliminates 9-month delay Commission order should be affirmed
EDGAR, G L Project Management Corp SILVERSTROM, L Energy, Dept of 82/12/28 Atomic Safety and Licensing Board Panel 16pp 16598 262 24X Fiche 50-537, 82/12/28, 8212300011

O Inspection reports, IE Bulletins & correspondence

8208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BHR Plants " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240

8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model B01 & Model B02 Thermoluminescent Dosimeters " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000, 82/11/05, 8208190245

8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X Fiche 50-000, 82/11/18, 8208190251

8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000, 82/11/26, 8208190256

8208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000, 82/11/30, 8208190257

8212080148 Notification of 821208 meeting w/applicants & DOE in Bethesda, MD to discuss inservice insp review items
STARK, R M Clinch River Breeder Reactor Program Office 82/12/02 CHECK, P S Clinch River Breeder Reactor Program Office 3pp 16367 273 24X Fiche 50-537, 82/12/02, 8212080148

8208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259

8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X Fiche 50-000, 82/12/03, 8208190261

8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16, 8208190267

8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27 " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X Fiche 50-000, 82/12/20, 8208190268

T. Hearing transcripts on non-antitrust matters

8212030005 Transcript of ACRS Working Group on Structures & Matls for CRBR 821201 meeting in Bethesda, MD Pp 1-214 Supporting documentation encl
* ACRS - Advisory Committee on Reactor Safeguards 82/12/01 390pp 16307 160 24X Fiche 50-537, 82/12/01, 8212030005

8212170083 Transcript of 821213 hearing in Oak Ridge, TN Pp 4, 947-5, 283
* Atomic Safety and Licensing Board Panel 82/12/13 311pp 16452 015 24X Fiche 50-537, 82/12/13, 8212170083

8212200066 Transcript of 821214 hearing in Oak Ridge, TN Pp 5, 254-5, 704
* Atomic Safety and Licensing Board Panel 82/12/14 449pp 16474 312 24X Fiche 50-537, 82/12/14, 8212200066

8212210099 Transcript of 821216 hearing in Oak Ridge, TN Pp 6, 141-6, 634 Supporting documentation encl
* Atomic Safety and Licensing Board Panel 82/12/16 493pp 16491 086 24X Fiche 50-537, 82/12/16, 8212210099

8212210094 Transcript of 821217 hearing in Oak Ridge, TN Pp 6, 635-6, 731
* Atomic Safety and Licensing Board Panel 82/12/17 97pp 16492 278 24X Fiche 50-537, 82/12/17, 8212210094

DOCKET BTN-50-546 MARBLE HILL NUCLEAR STATION, UNIT 1

A Application/construction stage documents & correspondence

8212080121 Submits daily highlight for 821126 Util submitted CL application Acceptance review will begin upon receipt of appropriate portions of application Fuel loading of Unit 1 scheduled for June 1986 & Dec 1987 for Unit 2
DODLITTLE, E L Licensing Branch 1 82/11/26 CASE, E, CARTER, J Office of Nuclear Reactor Regulation, Director EISENHUT, D Division of Licensing 1p 16367 362 24X Fiche 50-546, 82/11/26, 8212080121

8212080114 Requests assistance in performing CL acceptance review Results of review should be received by 830114 Requests for addl info should be forwarded to T Novak or BJ Youngblood
YOUNGBLOOD, B J Licensing Branch 1 82/11/30 JACKSON, R E Sciences Branch LEAR, G E Hydrologic & Geotechnical Engineering Branch BALLARD, R L Environmental Engineering Branch 1p 16368 295 24X Fiche 50-546, 82/11/30, 8212080114

8212290061 Requests lists of reviewers from each branch who will be assigned to plant CL applications & list of SRP sections for which reviewers will be performing safety reviews
YOUNGBLOOD, B J Licensing Branch 1 82/12/09 THOMAS, C Standardization & Special Projects Branch EVANS, L J Fuel Facility Safeguards Licensing Branch MCCORMACK, G W Power Reactor Safeguards Licensing Branch 2pp 16606 360 24X Fiche 50-000, 82/12/09, 8212290061

8212300092 Responds to 821209 memo requesting identification of reviewers & associated SRP sections for forthcoming CL reviews EW McPeck & FD Anderson chosen to review Sections 13 & 16 O, respectively
THOMAS, C Standardization & Special Projects Branch 82/12/23 YOUNGBLOOD, B J Licensing Branch 1 1p 16624 263 24X Fiche 50-000, 82/12/23, 8212300092

F Security, medical, emergency & fire protection plans

8212080630 Releases public version of acceptance review copy of emergency plan
FELTON, J M Division of Rules and Records 82/12/02 Document Management Branch 1p 16380 001 24X Fiche 50-546, 82/12/02, 8212080630

8212080633 Forwards public version of acceptance review copy of emergency plan
SHIELDS, S W Public Service Co of Indiana, Inc 82/11/23 DEWITT, H R Office of Nuclear Reactor Regulation, Director, 3pp 16380 002 24X Fiche 50-546, 82/12/02, 8212080633

8212080637 Public version of acceptance review copy of emergency plan
* Public Service Co of Indiana, Inc, 82/10/31 210pp 16380 005 24X Fiche 50-546, 82/12/02, 8212080637

8212220306 Discusses layout of communications equipment required in control room, onsite technical support ctr & near-site emergency operations facility
KEPPLER, J G Region 3, Office of Director 82/12/16 Commonwealth Edison Co 3pp 16503 351 24X Fiche 50-000, 82/12/16, 8212220306

8212290498 Requests acceptance review of fire protection rept submitted w/CL application Results requested by 830114 Addl info required for detailed review should be described in request format & submitted to T Novak or BJ Youngblood
YOUNGBLOOD, B J Licensing Branch 1 82/12/16 BENARROYA, V Chemical Engineering Branch 1p 16605 165 24X Fiche 50-546, 82/12/16, 8212290498

8212290502 Requests acceptance review of emergency plan submitted w/DL application by 830114 Addl info required for detailed review should be described in request format & submitted to T Novak or BJ Youngblood
YOUNGBLOOD, B J Licensing Branch 1 82/12/16 PAGANO, F O EP Licensing Branch 1p 16605 164 24X Fiche 50-546, 82/12/16, 8212290502

8212290112 Informa of plans to begin const an emergency operations facility & joint public info ctr Review of adequacy of protection factors & contingencies requested by 830215
SHIELDS, S W Public Service Co of Indiana, Inc 82/12/21
BENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 16582 243 24X Fiche 50-546, 82/12/21, 8212290112

G Adjudicatory correspondence

8212300086 Notifies that copies of NRC correspondence to applicant will no longer be sent unless requested Documents available at IPDR
YOUNGBLOOD, B J Licensing Branch 1 82/12/22 FREY, D O Audubon Society 2pp 16624 264 24X Fiche 50-546, 82/12/22, 8212300086

G Inspection reports, IE Bulletins & correspondence

8208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240

8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000, 82/11/05, 8208190245

8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X Fiche 50-000, 82/11/18, 8208190251

8212080398 Forwards IE Insp Repts 50-546/82-14 & 50-547/82-14 on 820801-1008 & notice of violation
KNOP, R C Division of Project & Resident Programs 82/11/22
SHIELDS, S W Public Service Co of Indiana, Inc 2pp 16352 293 24X Fiche 50-546, 82/11/22, 8212080398

--8212080402 Notice of violation from insp on 820801-1008
KNOP, R C Division of Project & Resident Programs 82/11/22 1p 16352 293 24X Fiche 50-546, 82/11/22, 8212080398

- 8212080407 IE Insp Repts 50-546/82-14 & 50-547/82-14 on 820801-1008 Noncompliance noted failure to implement preservation program for mats & equipment
HARRISON, J J, KONKLIN, J E Division of Project & Resident Programs 82/11/22 11pp 16352 296 24X Fiche 50-546, 82/11/22, 8212080398

8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000, 82/11/26, 8208190256

8208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000, 82/11/30, 8208190257

8208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259

8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X Fiche 50-000, 82/12/03, 8208190261

8212290406 Forwards IE Insp Repts 50-546/82-19 & 50-547/82-19 on 821201-03 No noncompliance noted
KNOP, R C Division of Project & Resident Programs 82/12/14
SHIELDS, S W Public Service Co of Indiana, Inc 2pp 16587 102 24X Fiche 50-546, 82/12/14, 8212290406

--8212290414 IE Insp Repts 50-546/82-19 & 50-547/82-19 on 821201-03 No noncompliance noted Major areas inspected site tour & discussions w/licensee staff
PELKE, P R, KONKLIN, J E Division of Project & Resident Programs 82/12/13 2pp 16587 104 24X Fiche 50-546, 82/12/14, 8212290406

8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16, 8208190267

8212280304 Advises that onsite radiograph sets of piping subassemblies supplied by ITT-Grinnell reviewed, in response to IE Bulletin 82-01, Revision 1, Suppl 1 Two subassemblies rejected Results of investigation will be provided by 830201
SHIELDS, S W Public Service Co of Indiana, Inc 82/12/16
KEPPLER, J O Region 3, Office of Director 2pp 16561 097 24X Fiche 50-546, 82/12/16, 8212280304

8212280321 Responds to IE Bulletin 82-04 Bunker-Ramo electrical penetrations not planned for use in safety-related sys
SHIELDS, S W Public Service Co of Indiana, Inc 82/12/16
KEPPLER, J O Region 3, Office of Director 2pp 16561 066 24X Fiche 50-546, 82/12/16, 8212280321

8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27 " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X Fiche 50-000, 82/12/20, 8208190268

S Reportable occurrences, LERs & related correspondence

8212100181 Final deficiency rept re conduit & cable tray hanger insp repts Initially reported on 820721 Commonwealth-Lord Joint Venture revised insp procedures to clarify documentation requirements
SHIELDS, S W Public Service Co of Indiana, Inc 82/12/03
KEPPLER, J O Region 3, Office of Director 2pp 16373 353 24X Fiche 50-546, 82/12/03, 8212100181

8212170329 Interim deficiency rept re operation of centrifugal charging pumps during high energy line rupture Initially reported on 800509 Westinghouse evaluating util alternative proposal for equipment mod Next rept will be provided by 830429
SHIELDS, S W Public Service Co of Indiana, Inc 82/12/09
KEPPLER, J O Region 3, Office of Director 2pp 16456 164 24X Fiche 50-546, 82/12/09, 8212170329

8212280157 Interim deficiency rept re design of Robertshaw Controls Co thermostatic valves installed in Coll Industries diesel generators Initially reported on 820602 Procedure to inspect & modify valves being developed Also reported per Part 21
SHIELDS, S W Public Service Co of Indiana, Inc 82/12/17
KEPPLER, J O Region 3, Office of Director 2pp 16556 096 24X Fiche 50-546, 82/12/17, 8212280157

8212280462 Interim deficiency rept re procedural changes requiring spec/design changes be contractually imposed on suppliers & contractors Initially reported on 821208 Special process procedure issued Next rept expected by 830930
SHIELDS, S W Public Service Co of Indiana, Inc 82/12/17
KEPPLER, J O Region 3, Office of Director 2pp 16556 029 24X Fiche 50-546, 82/12/17, 8212280462

8212280272 Interim deficiency rept re approval of disposition of contractor nonconformance rept w/o design subcontractor review of equipment Initially reported on 820811 Action to redispotion rept taken Next rept expected by 830218
SHIELDS, S W Public Service Co of Indiana, Inc 82/12/20
KEPPLER, J O Region 3, Office of Director 2pp 16556 136 24X Fiche 50-546, 82/12/20, 8212280272

DOCKET STN-50-547 MARBLE HILL NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

8212080121 Submits daily highlight for 821126 Util submitted DL application Acceptance review will begin upon receipt of appropriate portions of application Fuel loading of Unit 1 scheduled for June 1986 & Dec 1987 for Unit 2
DOOLITTLE, E L Licensing Branch 1 82/11/26 CASE, E, CARTER, J Office of Nuclear Reactor Regulation, Director EISENHUT, D Division of Licensing 1p 16367 362 24X Fiche 50-546, 82/11/26, 8212080121

DOCKETED ITEMS

8212080114 Requests assistance in performing OL acceptance review Results of review should be received by 830114 Requests for addl info should be forwarded to T Novak or BJ Youngblood YOUNGBLOOD, B J Licensing Branch 1 82/11/30 JACKSON, R E Geosciences Branch LEAR, G E Hydrologic & Geotechnical Engineering Branch BALLARD, R L Environmental Engineering Branch 1p 16368 295 24X Fiche 50-546, 82/11/30, 8212080114

8212290061 Requests lists of reviewers from each branch who will be assigned to plant OL applications & list of SRP sections for which reviewers will be performing safety reviews YOUNGBLOOD, B J Licensing Branch 1 82/12/09 THOMAS, C Standardization & Special Projects Branch EVANS, L J Fuel Facility Safeguards Licensing Branch MCCORKLE, G W Power Reactor Safeguards Licensing Branch 2pp 16606 360 24X Fiche 50-000, 82/12/09, 8212290061

8212300092 Responds to 821209 memo requesting identification of reviewers & associated SRP sections for forthcoming OL reviews EW McPeak & FO Anderson chosen to review Sections 13 & 16 O, respectively THOMAS, C O Standardization & Special Projects Branch 82/12/23 YOUNGBLOOD, B J Licensing Branch 1 1p 16624 263 24X Fiche 50-000, 82/12/23, 8212300092

F Security, medical, emergency & fire protection plans

8212080630 Releases public version of acceptance review copy of emergency plan FELTON, J M Division of Rules and Records 82/12/02 Document Management Branch 1p 16380 001 24X Fiche 50-546, 82/12/02, 8212080630

--8212080633 Forwards public version of acceptance review copy of emergency plan SHIELDS, S W Public Service Co of Indiana, Inc 82/11/23 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 16380 002 24X Fiche 50-546, 82/12/02, 8212080630

--8212080637 Public version of acceptance review copy of emergency plan * Public Service Co of Indiana, Inc 82/10/31 210pp 16380 005 24X Fiche 50-546, 82/12/02, 8212080630

8212280306 Discusses layout of communications equipment required in control room, onsite technical support ctr & near-site emergency operations facility KEPLER, J O Region 3, Office of Director 82/12/16 Commonwealth Edison Co 3pp. 16503 351 24X Fiche 50-000, 82/12/16, 8212280306

8212290498 Requests acceptance review of fire protection rept submitted w/OL application Results requested by 830114 Addl info required for detailed review should be described in request format & submitted to T Novak or BJ Youngblood YOUNGBLOOD, B J Licensing Branch 1 82/12/16 BENARDYA, V Chemical Engineering Branch 1p 16605 165 24X Fiche 50-546, 82/12/16, 8212290498

8212290502 Requests acceptance review of emergency plan submitted w/OL application by 830114 Addl info required for detailed review should be described in request format & submitted to T Novak or BJ Youngblood YOUNGBLOOD, B J Licensing Branch 1 82/12/16 PAQUAND, F O EP Licensing Branch 1p. 16605 164 24X Fiche 50-546, 82/12/16, 8212290502

8212290112 Informs of plans to begin const on emergency operations facility & joint public info ctr Review of adequacy of protection factors & contingencies requested by 830215 SHIELDS, S W Public Service Co of Indiana, Inc 82/12/21 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 16582 243 24X Fiche 50-546, 82/12/21, 8212290112

G Adjudicatory correspondence

8212300086 Notifies that copies of NRC correspondence to applicant will no longer be sent unless requested Documents available at IPR YOUNGBLOOD, B J Licensing Branch 1 82/12/22 FREY, D G Audubon Society 2pp 16624 264 24X Fiche 50-546, 82/12/22, 8212300086

H Inspection reports, IE Bulletins & correspondence

8208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel Recirculation Sys Piping at BWR Plants " Svc list encl DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240

8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list encl COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000, 82/11/05, 8208190245

8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl JORDAN, E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X Fiche 50-000, 82/11/18, 8208190251

8212080398 Forwards IE Insp Repts 50-546/82-14 & 50-547/82-14 on 820801-1008 & notice of violation KNOP, R C Division of Project & Resident Programs 82/11/22 SHIELDS, S W Public Service Co of Indiana, Inc 2pp 16352 293 24X Fiche 50-546, 82/11/22, 8212080398

--8212080402 Notice of violation from insp on 820801-1008 KNOP, R C Division of Project & Resident Programs 82/11/22 1p 16352 295 24X Fiche 50-546, 82/11/22, 8212080398

--8212080407 IE Insp Repts 50-546/82-14 & 50-547/82-14 on 820801-1008 Noncompliance noted failure to implement preservation program for mats & equipment HARRISON, J J, KONKLIN, J E Division of Project & Resident Programs 82/11/22 11pp 16352 296 24X Fiche 50-546, 82/11/22, 8212080398

8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list encl DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000, 82/11/26, 8208190256

8208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000, 82/11/30, 8208190257

8208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259

8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0075 Relay Sockets " Svc list encl JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X Fiche 50-000, 82/12/03, 8208190261

8212290406 Forwards IE Insp Repts 50-546/82-19 & 50-547/82-19 on 821201-03 No noncompliance noted KNOP, R C Division of Project & Resident Programs 82/12/14 SHIELDS, S W Public Service Co of Indiana, Inc 2pp 16587 10P 24X Fiche 50-546, 82/12/14, 8212290406

--8212290414 IE Insp Repts 50-546/82-19 & 50-547/82-19 on 821201-03 No noncompliance noted Major areas inspected site tour & discussions w/licenses staff PELKE, P R, KONKLIN, J E Division of Project & Resident Programs 82/12/13 2pp 16587 104 24X Fiche 50-546, 82/12/14, 8212290406

8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16, 8208190267

8212280304 Advises that onsite radiograph sets of piping subassemblies supplied by ITT-Grinnell reviewed in response to IE Bulletin 82-01, Revision 1, Suppl 1 Two subassemblies rejected Results of investigation will be provided by 830201 SHIELDS, S W Public Service Co of Indiana, Inc 82/12/16 KEPLER, J O Region 3, Office of Director 2pp 16561 097 24X Fiche 50-546, 82/12/16, 8212280304

8212280321 Responds to IE Bulletin 82-04 Bunker-Ramo electrical penetrations not planned for use in safety-related sys SHIELDS, S W Public Service Co of Indiana, Inc 82/12/16 KEPLER, J O Region 3, Office of Director 2pp 16561 066 24X Fiche 50-546, 82/12/16, 8212280321

8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type 1E-27 " Svc list encl JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X Fiche 50-000, 82/12/20, 8208190268

5 Reportable occurrences, LERs & related correspondence

B212100181 Final deficiency rept re conduit & cable tray hanger insp
repts initially reported on 820721 Commonwealth-Lord
Joint Venture revised insp procedures to clarify
documentation requirements
SHIELDS, S W Public Service Co of Indiana, Inc 82/12/03 24X
KEPPLER, J G Region 3, Office of Director 2pp 16373 353
Fiche 50-546, 82/12/03, 8212100181

B212170329 Interim deficiency rept re operation of centrifugal charging
pumps during high energy line rupture Initially reported on
800509 Westinghouse evaluating util alternative proposal for
equipment mod Next rept will be provided by 830429
SHIELDS, S W Public Service Co of Indiana, Inc 82/12/09 24X
KEPPLER, J G Region 3, Office of Director 2pp 16456 164
Fiche 50-546, 82/12/09, 8212170329

GP12280157 Interim deficiency rept re design of Robertshaw Controls Co
thermostatic valves installed in Colt Industries diesel
generators Initially reported on 820602 Procedure to inspect
& modify valves being developed Also reported per Part 21
SHIELDS, S W Public Service Co of Indiana, Inc 82/12/17 24X
KEPPLER, J G Region 3, Office of Director 2pp 16556 096
Fiche 50-546, 82/12/17, 8212280157

8212280462 Interim deficiency rept re procedural changes requiring
spec/design changes be contractually imposed on suppliers &
contractors Initially reported on 821208 Special process
procedure issued Next rept expected by 830930
SHIELDS, S W Public Service Co of Indiana, Inc 82/12/17 24X
KEPPLER, J G Region 3, Office of Director 2pp 16556 029
Fiche 50-546, 82/12/17, 8212280462

8212280272 Interim deficiency rept re approval of disposition of
contractor nonconformance rept w/o design subcontractor
review of equipment Initially reported on 820811 Action to
redispotion rept taken Next rept expected by 830218
SHIELDS, S W Public Service Co of Indiana, Inc 82/12/20 24X
KEPPLER, J G Region 3, Office of Director 2pp 16556 136
Fiche 50-546, 82/12/20, 8212280272

DOCKET STN-50-553 PHIPPS BEND NUCLEAR STATION, UNIT 1

A Application/construction stage documents & correspondence

B211230066 Generic Ltr 82-27 to all BWR licensees of operating reactors
except LACBWR, Big Rock Point, Dresden 1, Humboldt Bay,
applicants for OL & holders of CP re transmittal of
NUREG-0763 & NUREG-0783 Svc list encl W/o stated encl
EISENHUT, D G Division of Licensing 82/11/15 General Public
Utilities - OPU Service Corp 22pp 16387 004 24X
Fiche 50-000, 82/11/15, 8211230066

G Inspection reports, IE Bulletins & correspondence

B208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-
Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping
at BWR Plants " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and
Enforcement 82/10/28 Consolidated Edison Co of New York, Inc
112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240

B208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model
801 & Model 802 Thermoluminescent Dosimeters " Svc list
encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards
82/11/05 Consolidated Edison Co of New York, Inc 110pp
16372 142 24X Fiche 50-000, 82/11/05, 8208190245

B208190251 IE Info Notice 82-44, "Clarification of Emergency Plan
Exercise Requirements " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18
Consolidated Edison Co of New York, Inc 109pp 16411 199 24X
Fiche 50-000, 82/11/18, 8208190251

B208190256 IE Info Notice 82-46, "Defective & Obsolete Combination
Padlocks " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and
Enforcement 82/11/26 Consolidated Edison Co of New York, Inc
127pp 16411 065 24X Fiche 50-000, 82/11/26, 8208190256

B208190257 IE Info Notice 82-47, "Transportation of Type A Quantities
of Non-Fissile Radioactive Matl " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards
82/11/30 Consolidated Edison Co of New York, Inc 356pp
16387 028 24X Fiche 50-000, 82/11/30, 8208190257

B208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment
Electrical Penetration Assemblies " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and
Enforcement 82/12/03 Consolidated Edison Co of New York, Inc
113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259

B208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay
Sockets " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03
Consolidated Edison Co of New York, Inc 110pp 16462 064 24X
Fiche 50-000, 82/12/03, 8208190261

B208190267 IE Info Notice 82-49, "Correction for Sample Conditions for
Air & Gas Monitoring " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and
Enforcement 82/12/16 Consolidated Edison Co of New York, Inc
127pp 16628 191 24X Fiche 50-000, 82/12/16, 8208190267

B208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage
Relays Type ITE-27 " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20
Consolidated Edison Co of New York, Inc 108pp 16628 293 24X
Fiche 50-000, 82/12/20, 8208190268

DOCKET STN-50-554 PHIPPS BEND NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

B211230066 Generic Ltr 82-27 to all BWR licensees of operating reactors
except LACBWR, Big Rock Point, Dresden 1, Humboldt Bay,
applicants for OL & holders of CP re transmittal of
NUREG-0763 & NUREG-0783 Svc list encl W/o stated encl
EISENHUT, D G Division of Licensing 82/11/15 General Public
Utilities - OPU Service Corp 22pp 16387 004 24X
Fiche 50-000, 82/11/15, 8211230066

G Inspection reports, IE Bulletins & correspondence

B208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-
Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping
at BWR Plants " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and
Enforcement 82/10/28 Consolidated Edison Co of New York, Inc
112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240

B208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model
801 & Model 802 Thermoluminescent Dosimeters " Svc list
encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards
82/11/05 Consolidated Edison Co of New York, Inc 110pp
16372 142 24X Fiche 50-000, 82/11/05, 8208190245

B208190251 IE Info Notice 82-44, "Clarification of Emergency Plan
Exercise Requirements " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18
Consolidated Edison Co of New York, Inc 109pp 16411 199 24X
Fiche 50-000, 82/11/18, 8208190251

B208190256 IE Info Notice 82-46, "Defective & Obsolete Combination
Padlocks " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and
Enforcement 82/11/26 Consolidated Edison Co of New York, Inc
127pp 16411 065 24X Fiche 50-000, 82/11/26, 8208190256

B208190257 IE Info Notice 82-47, "Transportation of Type A Quantities
of Non-Fissile Radioactive Matl " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards
82/11/30 Consolidated Edison Co of New York, Inc 356pp
16387 028 24X Fiche 50-000, 82/11/30, 8208190257

B208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment
Electrical Penetration Assemblies " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and
Enforcement 82/12/03 Consolidated Edison Co of New York, Inc
113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259

B208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay
Sockets " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03
Consolidated Edison Co of New York, Inc 110pp 16462 064 24X
Fiche 50-000, 82/12/03, 8208190261

B208190267 IE Info Notice 82-49, "Correction for Sample Conditions for
Air & Gas Monitoring " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and
Enforcement 82/12/16 Consolidated Edison Co of New York, Inc
127pp 16628 191 24X Fiche 50-000, 82/12/16, 8208190267

DOCKETED ITEMS

B208190268 IE Info Notice B2-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27 " Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance 82/12/20
Consolidated Edison Co. of New York, Inc 108pp 16628 293 24X
Fiche 50-000, 82/12/20, B208190268

DOCKET STN-50-556 BLACK FOX STATION, UNIT 1

A Application/construction stage documents & correspondence

B211230066 Generic Ltr B2-27 to all BWR licensees of operating reactors except LACBWR, Big Rock Point, Dresden 1, Humboldt Bay, applicants for OL & holders of CP re transmittal of NUREG-0763 & NUREG-0783 Svc list encl W/o stated encl
EISENHUT, D. G. Division of Licensing 82/11/15 General Public
Utilities - OPU Service Corp 22pp 16387 004 24X
Fiche 50-000, 82/11/15, B211230066

G Inspection reports, IE Bulletins & correspondence

B208190240 IE Bulletin B2-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Svc list encl
DEVOUNO, R. C. Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co. of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, B208190240

B208190245 IE Info Notice B2-42, "Defects Observed in Panasonic Model B01 & Model B02 Thermoluminescent Dosimeters " Svc list encl
COBB, L. I. Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co. of New York, Inc 110pp 16372 142 24X Fiche 50-000, 82/11/05, B208190245

B208190251 IE Info Notice B2-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co. of New York, Inc 109pp 16411 199 24X
Fiche 50-000, 82/11/18, B208190251

B208190256 IE Info Notice B2-46, "Defective & Obsolete Combination Padlocks " Svc list encl
DEVOUNO, R. C. Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co. of New York, Inc 127pp 16411 065 24X Fiche 50-000, 82/11/26, B208190256

B208190257 IE Info Notice B2-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl
COBB, L. I. Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co. of New York, Inc 356pp 16387 028 24X Fiche 50-000, 82/11/30, B208190257

B208190259 IE Bulletin B2-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl
DEVOUNO, R. C. Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co. of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, B208190259

B208190261 IE Info Notice B2-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co. of New York, Inc 110pp 16462 064 24X
Fiche 50-000, 82/12/03, B208190261

B208190267 IE Info Notice B2-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
DEVOUNO, R. C. Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co. of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16, B208190267

B208190268 IE Info Notice B2-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27 " Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co. of New York, Inc 108pp 16628 293 24X
Fiche 50-000, 82/12/20, B208190268

DOCKET STN-50-557 BLACK FOX STATION, UNIT 2

A Application/construction stage documents & correspondence

B211230066 Generic Ltr B2-27 to all BWR licensees of operating reactors except LACBWR, Big Rock Point, Dresden 1, Humboldt Bay, applicants for OL & holders of CP re transmittal of NUREG-0763 & NUREG-0783 Svc list encl W/o stated encl
EISENHUT, D. G. Division of Licensing 82/11/15 General Public
Utilities - OPU Service Corp 22pp 16387 004 24X
Fiche 50-000, 82/11/15, B211230066

G Inspection reports, IE Bulletins & correspondence

B208190240 IE Bulletin B2-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Svc list encl
DEVOUNO, R. C. Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co. of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, B208190240

B208190245 IE Info Notice B2-42, "Defects Observed in Panasonic Model B01 & Model B02 Thermoluminescent Dosimeters " Svc list encl
COBB, L. I. Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co. of New York, Inc 110pp 16372 142 24X Fiche 50-000, 82/11/05, B208190245

B208190251 IE Info Notice B2-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co. of New York, Inc 109pp 16411 199 24X
Fiche 50-000, 82/11/18, B208190251

B208190256 IE Info Notice B2-46, "Defective & Obsolete Combination Padlocks " Svc list encl
DEVOUNO, R. C. Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co. of New York, Inc 127pp 16411 065 24X Fiche 50-000, 82/11/26, B208190256

B208190257 IE Info Notice B2-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl
COBB, L. I. Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co. of New York, Inc 356pp 16387 028 24X Fiche 50-000, 82/11/30, B208190257

B208190259 IE Bulletin B2-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl
DEVOUNO, R. C. Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co. of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, B208190259

B208190261 IE Info Notice B2-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co. of New York, Inc 110pp 16462 064 24X
Fiche 50-000, 82/12/03, B208190261

B208190267 IE Info Notice B2-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
DEVOUNO, R. C. Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co. of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16, B208190267

B208190268 IE Info Notice B2-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27 " Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co. of New York, Inc 108pp 16628 293 24X
Fiche 50-000, 82/12/20, B208190268

DOCKET STN-50-546 YELLOW CREEK NUCLEAR PLANT, UNIT 1

G Inspection reports, IE Bulletins & correspondence

B208190240 IE Bulletin B2-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Svc list encl
DEVOUNO, R. C. Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co. of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, B208190240

B208190245 IE Info Notice B2-42, "Defects Observed in Panasonic Model B01 & Model B02 Thermoluminescent Dosimeters " Svc list encl
COBB, L. I. Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co. of New York, Inc 110pp 16372 142 24X Fiche 50-000, 82/11/05, B208190245

B208190251 IE Info Notice B2-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co. of New York, Inc 109pp 16411 199 24X
Fiche 50-000, 82/11/18, B208190251

B208190256 IE Info Notice B2-46, "Defective & Obsolete Combination Padlocks " Svc list encl
DEVOUNO, R. C. Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co. of New York, Inc 127pp 16411 065 24X Fiche 50-000, 82/11/26, B208190256

B208190257 IE Info Notice B2-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards
B2/11/30 Consolidated Edison Co. of New York, Inc 356pp
16387 028 24X Fiche 50-000, B2/11/30, B208190257

B208190259 IE Bulletin B2-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co. of New York, Inc 113pp 16411 317 24X Fiche 50-000, B2/12/03, B208190259

B208190261 IE Info Notice B2-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co. of New York, Inc 110pp 16462 064 24X Fiche 50-000, B2/12/03, B208190261

B208190267 IE Info Notice B2-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co. of New York, Inc 127pp 16628 191 24X Fiche 50-000, B2/12/16, B208190267

B208190268 IE Info Notice B2-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27 " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co. of New York, Inc 108pp 16628 293 24X Fiche 50-000, B2/12/20, B208190268

5 Reportable occurrences, LERs & related correspondence

B212100270 Fifth interim deficiency rept re lack of Div of Engineering design sys to ensure QA procedures issued before work begins Initially reported on B11020 Final rept will not be submitted until decision made on deferral of projects
MILLS, L M Tennessee Valley Authority 82/12/06 O'REILLY, J P Region 2, Office of Director 1p 16377 136 24X Fiche 50-000, B2/12/06, B212100270

B212200001 Third interim deficiency rept re generic deficiency in design review Initially reported on B11215 No addl info available until action team B21215 rept Next rept will be submitted by B30420
MILLS, L M Tennessee Valley Authority 82/12/13 O'REILLY, J P Region 2, Office of Director 1p 16473 362 24X Fiche 50-000, B2/12/13, B212200001

B212200017 Fifth interim deficiency rept re design review process interface coordination activity Initially reported on B10717 Corrective action to be based on action team rept to be issued approx B21215 Next rept expected by B30422
MILLS, L M Tennessee Valley Authority 82/12/13 O'REILLY, J P Region 2, Office of Director 2pp 16473 085 24X Fiche 50-000, B2/12/13, B212200017

B212210431 Fourth interim deficiency rept re resolution of unanticipated vibratory loading concerns Initially reported on B20120 Const activities for Yellow Creek & Hartsville deferred Next rept will be sent by B30322
MILLS, L M Tennessee Valley Authority 82/12/15 O'REILLY, J P Region 2, Office of Director 2pp 16489 168 24X Fiche 50-000, B2/12/15, B212210431

DOCKET STN-50-567 YELLOW CREEK NUCLEAR PLANT, UNIT 2

0 Inspection reports, IE Bulletins & correspondence

B208190240 IE Bulletin B2-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co. of New York, Inc 112pp 16462 163 24X Fiche 50-000, B2/10/28, B208190240

B208190245 IE Info Notice B2-42, "Defects Observed in Panasonic Model 901 & Model 802 Thermoluminescent Dosimeters " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co. of New York, Inc 110pp 16372 142 24X Fiche 50-000, B2/11/05, B208190245

B208190251 IE Info Notice B2-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co. of New York, Inc 107pp 16411 179 24X Fiche 50-000, B2/11/18, B208190251

B208190254 IE Info Notice B2-46, "Defective & Obsolete Combination Padlocks " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co. of New York, Inc 127pp 16411 065 24X Fiche 50-000, B2/11/26, B208190254

B208190257 IE Info Notice B2-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co. of New York, Inc 356pp 16387 028 24X Fiche 50-000, B2/11/30, B208190257

B208190259 IE Bulletin B2-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co. of New York, Inc 113pp 16411 317 24X Fiche 50-000, B2/12/03, B208190259

B208190261 IE Info Notice B2-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co. of New York, Inc 110pp 16462 064 24X Fiche 50-000, B2/12/03, B208190261

B208190267 IE Info Notice B2-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co. of New York, Inc 127pp 16628 191 24X Fiche 50-000, B2/12/16, B208190267

B208190268 IE Info Notice B2-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27 " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co. of New York, Inc 108pp 16628 293 24X Fiche 50-000, B2/12/20, B208190268

5 Reportable occurrences, LERs & related correspondence

B212210431 Fourth interim deficiency rept re resolution of unanticipated vibratory loading concerns Initially reported on B20120 Const activities for Yellow Creek & Hartsville deferred Next rept will be sent by B30322
MILLS, L M Tennessee Valley Authority 82/12/15 O'REILLY, J P Region 2, Office of Director 2pp 16489 168 24X Fiche 50-000, B2/12/15, B212210431

B212100270 Fifth interim deficiency rept re lack of Div of Engineering design sys to ensure QA procedures issued before work begins Initially reported on B11020 Final rept will not be submitted until decision made on deferral of projects
MILLS, L M Tennessee Valley Authority 82/12/06 O'REILLY, J P Region 2, Office of Director 1p 16377 136 24X Fiche 50-000, B2/12/06, B212100270

B212200001 Third interim deficiency rept re generic deficiency in design review Initially reported on B11215 No addl info available until action team B21215 rept Next rept will be submitted by B30420
MILLS, L M Tennessee Valley Authority 82/12/13 O'REILLY, J P Region 2, Office of Director 1p 16473 362 24X Fiche 50-000, B2/12/13, B212200001

B212200017 Fifth interim deficiency rept re design review process interface coordination activity Initially reported on B10717 Corrective action to be based on action team rept to be issued approx B21215 Next rept expected by B30422
MILLS, L M Tennessee Valley Authority 82/12/13 O'REILLY, J P Region 2, Office of Director 2pp 16473 085 24X Fiche 50-000, B2/12/13, B212200017

DOMESTIC LICENSING OF SPECIAL NUCLEAR MATERIAL

DOCKET 70-0025 ROCKWELL INTERNATIONAL CORP., CANDOR PARK, CA

B212210240 Forwards IE Safeguards Insp Rept 70-0025/B2-10 on B21018-20 & 1101-05 No noncompliance noted
NORDERHAUS, L R Division of Radiological Safety & Safeguards Program 82/12/14 FIELER, F W Rockwell International Corp 2pp 16483 014

--B212210246 IE Safeguards Insp Rept 70-0025/B2-10 on B21018-20 & 1101-05 No noncompliance noted Major areas inspected physical inventory & inventory verification & independent safeguards insp effort Details withheld (ref 10CFR2 790)
NELSON, G B, WIEDER, A V, BROCK, B L Division of Radiological Safety & Safeguards Program 82/12/13 1p 16483 016

DOCKETED ITEMS

B212290058 Requests review & recommendations for action on licensee request for withholding group organizational info & resumes from renewal application for License SNM-21 W/a encl
KETZLACH, N Uranium Fuel Licensing Branch 82/12/14 ABRAMS, N E Operations & Administrative Division 2pp 16607 051

B212300234 Forwards IE Enforcement Conference Rept 70-0025/82-11 on 821122
SPENCER, O S Division of Radiological Safety & Safeguards Program 82/12/22 REMLEY, M E Rockwell International Corp 1p 16595 280

--B212300240 IE Enforcement Conference Rept 70-0025/82-11 on 821122 Major areas discussed reported radiation overexposures, NRC enforcement options & concerns & licensee mgt responsibilities
JOHNSON, A D, THOMAS, R D, BOOK, H E Division of Radiological Safety & Safeguards Program 82/12/21 3pp 16595 281

DOCKET 70-0027 BABCOCK & WILCOX CO, LYNCHBURG, VA

B212130062 Ack receipt of 821025 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-0027/82-22
GIBSON, A F Division of Engineering & Technical Programs 82/11/09 ECKERT, J P Babcock & Wilcox Co 1p 16390 168

--B212130067 Responds to NRC 821004 ltr re violations noted in IE Insp Rept 70-0027/82-22 Corrective actions employee instructed in transfer documentation procedures Procedures will be reviewed by all personnel
ECKERT, J P Babcock & Wilcox Co 82/10/25 GIBSON, A F Division of Engineering & Technical Programs 2pp 16390 169

--B212130071 Forwards IE Insp Rept 70-0027/82-22 on 820913-17 & notice of violation Rept & notice of violation withheld (ref 10CFR2 790)
GIBSON, A F Division of Engineering & Technical Programs 82/10/04 ECKERT, J P Babcock & Wilcox Co 2pp 16390 171

B212270406 Proposes extension until 830131 to respond to request for addl info in support of renewal of License SNM-42 Delay due to plant shutdowns for Thanksgiving & Christmas holidays
KELLY, J W Babcock & Wilcox Co 82/11/16 KETZLACH, N Division of Fuel Cycle & Material Safety 1p 16572 356

B212270537 Requests exception to 10CFR70.51 (e)(3)(i) allowing performance of Nov/Dec 1982 inventory to begin on 830107 Handling of inventory described in 810922 request Administrative amend fee encl
KELLY, J W Babcock & Wilcox Co 82/11/16 EVANS, L J Fuel Facility Safeguards Licensing Branch 3pp 16346 358

B212090430 Forwards IE Insp Rept 70-0027/82-27 on 821101-03 No noncompliance noted
GIBSON, A F Division of Engineering & Technical Programs 82/11/19 ECKERT, J P Babcock & Wilcox Co 2pp 16364 354

--B212090439 IE Insp Rept 70-0027/82-27 on 821101-03 No noncompliance noted Major areas inspected internal & external exposure control program & procedures
WRAV, J R, BARR, K P Division of Engineering & Technical Programs 82/11/17 5pp 16364 356

B212080045 Issues Amend 18 to License SNM-42, authorizing production scale fabrication of box type research reactor fuel elements
PAGE, R G Uranium Fuel Licensing Branch 82/11/26 KELLY, J W Babcock & Wilcox Co 1p 16367 138

--B212080049 SER supporting B&W 820903 application to amend License SNM-42, authorizing production scale fabrication of box type research reactor fuel elements
KETZLACH, N Uranium Fuel Licensing Branch 82/11/26 13pp 16367 139

DOCKET 70-0033 TEXAS INSTRUMENTS, INC, ATTLEBORO, MA

B212270024 Forwards application for Amend 1 to License SNM-23, authorizing termination of license
SHERMAN, F L, SCHENSPFIER, R Texas Instruments, Inc 82/11/02 PAGE, R G Uranium Fuel Licensing Branch 2pp 16551 086

--B212270030 Application for Amend 1 to License SNM-23, authorizing termination of license W/one oversize figure Aperture card is available in PDR
ODETZ, H, CHURCHILL, R, SHERMAN, F L Texas Instruments, Inc 82/11/01 48pp 16591 090

DOCKET 70-0036 COMBUSTION ENGINEERING, INC, WINDSOR, CT

B212010369 Forwards negative declaration & EIA supporting renewal of License SNM-33
PAGE, R G Uranium Fuel Licensing Branch 82/11/24 LICHTENBERGER Combustion Engineering, Inc 1p 16271 113

--B212010372 Negative declaration re renewal of License SNM-33
PAGE, R G Uranium Fuel Licensing Branch 82/11/23 1p 16271 114

--B212010374 EIA supporting renewal of License SNM-33
* Division of Fuel Cycle & Material Safety 82/11/30 74pp 16271 115

B212300078 Trip rept of 821208-09 visit to C-E in Hematite, MD re license renewal application
BIDINGER, G H Uranium Fuel Licensing Branch 82/12/16 CROW, H F Uranium Fuel Licensing Branch 1p 16624 274

DOCKET 70-0135 BABCOCK & WILCOX CO, APOLLO, PA

B212220436 Forwards IE Safeguards Insp Rept 70-0135/82-09 on 821115-19 No noncompliance noted
MARTIN, T T Division of Engineering & Technical Programs 82/12/17 COLEMAN, W L Babcock & Wilcox Co 2pp 66533 093

--B212220437 IE Safeguards Insp Rept 70-0135/82-09 on 821115-19 No noncompliance noted Major areas inspected organization, operations, measurements, internal control & mgt
WOLTER, E, ZIBULSKY, H, GODY, A T Division of Engineering & Technical Programs 82/12/13 3pp 16503 328

DOCKET 70-0143 NUCLEAR FUEL SERVICES, INC, ERWIN, TN

B208290112 FOIA request for repts re inventory differences at NFS plant in Erwin, TN & correspondence between NRC & NFS concerning fuel inventory differences from 1979 to present
BARLETT, D L Philadelphia Inquirer 82/09/15 FELTON, J M Division of Rules and Records 1p 16566 084

B212080006 Addl response to FOIA request for seven categories of info re NFS, Erwin, TN facility Forwards App A documents denoted w/asterisk
FELTON, J M Division of Rules and Records 82/10/25 WEISS, E R Harmon & Weiss 36pp 16369 001

--B212080018 Forwards preprint of "Use of Process Monitoring Data for Enhancement of Matl Control at High Enrichment U Fabrication Facility," classified confidential-restricted data Official NUREG rept will be submitted within next few wks W/a encl
SMITH, C N Material Control Licensing Branch 79/10/04 HENSLEY, K D Nuclear Fuel Services, Inc (subs of Getty Oil Co) 1p 16369 037

--B212080089 Discusses 791030 NFS, Erwin meeting concerning results of FBI investigation Rept of investigation dtd 791015 not yet received by NRC
HOWARD, E M Division of Safeguards Inspections 79/11/01 STELLO, V Office of Inspection & Enforcement, Office of the Director 1p 16370 132

--B212080093 Submits proposed agenda for Commission 791106 briefing on NFS
HOWARD, E M Division of Safeguards Inspections 79/11/01 STELLO, V Office of Inspection & Enforcement, Office of the Director 1p 16370 133

--B212080099 Recommends proposed license conditions for NFS be adopted All items on inventory should be remeasured regardless of period generated, except matl shipped offsite & independently verified by receiver
STELLO, V Office of Inspection & Enforcement, Office of the Director 79/11/05 BURNETT, R F Division of Safeguards 1p 16370 134

--B212080105 Comments on proposed license conditions for NFS & mad of NFS order to allow limited processing New matls balance period should not be considered as starting 791004 physical inventory
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/11/01 BURNETT, R F Division of Safeguards 3pp 16370 135

- B212080113 Discusses 791105 meeting w/NFS re license conditions
Safeguards requirements, including matl control & physical
security, will be upgraded
BLAYLOCK, J Division of Safeguards Inspections 79/11/06
CHAPELL, D R Division of Safeguards Inspections 1p 16370 13B
- B212080117 Discusses Commission 791106 briefing re NFS status FBI
investigation uncovered no evidence of illegal employee
activity Cause for inventory difference not identified
BLAYLOCK, J Division of Safeguards Inspections 79/11/08
CHAPELL, D R Division of Safeguards Inspections 14pp
16370 139
- B212080129 Advises of B10103 or 0104 informal briefing for
congressional aides from Oversight Committee in
Washington, DC on status of NFS Erwin Briefing requested by
Acting Chairman Ahearn in view of recent media interest
HOWARD, E M Division of Safeguards Inspections 79/12/28
STELLO, V Office of Inspection & Enforcement, Office of the
Director 1p 16370 153
- B212080139 Supplemental PNS-II-79-102E on 790924, followup of areas
outside protected area identified by aerial measurements sys
found not to exceed limits for unrestricted use
CORRYELL, G P Region 2, Office of Director 79/09/25 1p
16370 154
- B212080149 Supplemental PNS-II-79-102K on 791102, initial reinventory
efforts resulted in partial reconciliation of 790917
difference Unresolved inventory difference in excess of
regulatory limits for continued operation remains
LEE, T D Region 2, Atlanta, Office of the Director 79/11/02
1p 16370 155
- B212080154 Documents telcon w/F Gillespie, Region 2 re ongoing NFS
events NRC will issue press release to head off publicity
Region 2 will prepare briefing for Commission 791106 meeting
on NFS Semifinished fuel will not be processed
BLAYLOCK, J Division of Safeguards Inspections 77/11/06
CHAPELL, D R Division of Safeguards Inspections 1p 16370 156
- B212160072 Forwards Revision 2 to safeguards contingency plan Revision
withheld
MANSER, W C Nuclear Fuel Services, Inc (subs of Getty Oil Co)
82/11/05 EVANS, L J Fuel Facility Safeguards Licensing Branch
1p 16447 252
- B212160420 Forwards request for amend to License SNM-124 Administrative
amend fee encl Amend withheld (ref 10CFR2 790)
HENLEY, K D Nuclear Fuel Services, Inc (subs of Getty Oil Co)
82/11/09 EVANS, L J Fuel Facility Safeguards Licensing Branch
1p 16447 191
- B212090260 Ack receipt of IE Insp Rept 70-0143/82-26 No proprietary
info
MANSER, W C Nuclear Fuel Services, Inc (subs of Getty Oil Co)
82/11/10 GIBSON, A F Division of Engineering & Technical Programs
1p 16363 245
- B212160429 Ack receipt of IE Insp Rept 70-0143/82-36 No proprietary
info
MANSER, W C Nuclear Fuel Services, Inc (subs of Getty Oil Co)
82/11/10 GIBSON, A F Division of Engineering & Technical Programs
1p 16447 188
- B212090469 Ack receipt of IE Insp Rept 70-0143/82-38 on B21013 No
proprietary info
MANSER, W C Nuclear Fuel Services, Inc (subs of Getty Oil Co)
82/11/11 GIBSON, A F Division of Engineering & Technical Programs
1p 16363 246
- B212090507 Forwards IE Insp Rept 70-0143/82-42 on B21025-29 No
noncompliance noted
GIBSON, A F Division of Engineering & Technical Programs 82/11/12
MANSER, W C Nuclear Fuel Services, Inc (subs of Getty Oil Co)
2pp 16366 332
- B212090517 IE Insp Rept 70-0143/82-42 on B21025-29 No noncompliance
noted Major areas inspected external & internal radiation
exposure, contamination control, audits & insps & ALARA rept
KAHLE, J B, BARR, K P Division of Engineering & Technical
Programs 82/11/09 6pp 16366.354
- B212090533 Forwards IE Safeguards Insp Rept 70-0143/82-43 on B21004-29
No noncompliance noted
GIBSON, A F Division of Engineering & Technical Programs 82/11/12
MANSER, W C Nuclear Fuel Services, Inc (subs of Getty Oil Co)
2pp 16366 331
- B212090539 IE Safeguards Insp Rept 70-0143/82-43 on B21004-29 No
noncompliance noted Major areas inspected facility
operation, criticality safety, radiation/envirom/physical
protection & SNM control & accounting
LEE, T D, MCALPINE, E J Division of Engineering & Technical
Programs 82/11/10 5pp 16366 333
- B212100111 Responds to FOIA request for seven categories of info re
NFS, Erwin TN Forwards documents listed in App A Documents
listed in App B withheld (ref FOIA Exemptions 3 & 5)
FELTON, J M Division of Rules and Records 82/11/12 WEISS, E R
Harmon & Weiss App 16368 157
- B212100121 Forwards addl comments on proposed license conditions for
NFS-Erwin re emergency preparedness
GRIMES, B K Division of Emergency Preparedness 82/03/23
PAOE, R O Uranium Fuel Licensing Branch 1p 16388 164
- B212100128 Ack receipt of B20225 concerns re timeliness of alerting &
notifying nearby residents in event of certain type of
emergency at NFS, Inc Emergency planning license conditions
for NFS discussed
TROJANDZSKI, R Region 2, Office of Director 82/03/12
GRAHAM, J A Tennessee, State of 2pp 16388 165
- B212090385 Ack receipt of B21008 ltr expressing concerns re health
physics program at NFS Facility safely operated, based upon
previous insp findings Mods being made to improve
security & radiological controls
O'REILLY, J P Region 2, Office of Director 82/11/17 HOBLEY, M H
Tennessee, State of 1p 16364 242
- B212090393 Discusses unfavorable impressions of NFS facility Facility
appears to operate in manner warranting shutdown Review of
license activities requested
HOBLEY, M H Tennessee, State of 82/10/08 O'REILLY, J P Region,
2, Office of Director 2pp 16364 243
- B212150293 Forwards "Daily Summary of Stack Monitoring, Oct 1982 "
MANSER, W C Nuclear Fuel Services, Inc (subs of Getty Oil Co)
82/11/17 O'REILLY, J P Region 2, Office of Director 1p
16437 353
- B212150298 "Daily Summary of Stack Monitoring, Oct 1982 "
* Nuclear Fuel Services, Inc (subs of Getty Oil Co) 82/11/17
App 16437 354
- B212090402 Forwards IE Safeguards Insp Rept 70-0143/82-40 on B21104-13
No noncompliance noted
GIBSON, A F Division of Engineering & Technical Programs 82/11/26
MANSER, W C Nuclear Fuel Services, Inc (subs of Getty Oil Co)
2pp 16365 037
- B212090413 IE Safeguards Insp Rept 70-0143/82-40 on B21104-13
No noncompliance noted Major areas inspected MCBSR06-B
MBA-5 inprocess measurements & MCBS213-B MBA-5 physical
inventory verification Details withheld (ref 10CFR2 790)
CLAY, E L, MCALPINE, E J Division of Engineering & Technical
Programs 82/11/24 1p 16365 039
- B212090408 Forwards IE Safeguards Insp Rept 70-0143/82-46 on B21102-05
No noncompliance noted
GIBSON, A F Division of Engineering & Technical Programs 82/11/30
MANSER, W C Nuclear Fuel Services, Inc (subs of Getty Oil Co)
2pp 16365 048.
- B212090416 IE Safeguards Insp Rept 70-0143/82-46 on B21102-05 No
noncompliance noted Major areas inspected measurements,
measurement control program & followup on previously
identified items Details withheld (ref 10CFR2 790)
BATES, J W, SABADOS, J W, MCALPINE, E J Division of Engineering &
Technical Programs 82/11/30 1p 16365 050
- B212220527 Informs of interim organizational change affecting License
SNM-124, Section 200 Administrative manager position vacant
Safety & decommissioning manager directly responsible to
general manager All other positions unchanged.
DEKER, R L Nuclear Fuel Services, Inc (subs of Getty Oil Co)
82/11/30 PAOE, R O Uranium Fuel Licensing Branch 2pp
16522 352
- B212130189 Responds to NRC B21103 notice of violation contained in IE
Insp Rept 70-0143/82-37 Corrective actions radiological
contingency plan will be revised to clarify definition of
explosion.
MANSER, W C Nuclear Fuel Services, Inc (subs of Getty Oil Co)
82/12/01 GIBSON, A F Division of Engineering & Technical Programs
2pp 16410 358

DOCKETED ITEMS

8212270078 Addl response to FOIA request for repts & correspondence re inventory differences at NFS plant in Erwin, TN Documents completely & partially withheld (ref FOIA Exemptions 3 & 4)
FELTON, J M Division of Rules and Records 82/12/03 BARLETT, D L Philadelphia Inquirer. 5pp 16566 085

--8212270112 "Technical Assessment of Inventory Differences at NFS," Jan 1978 - Mar 1980
* Region 2, Atlanta, Safeguards Branch 80/05/27 33pp 16566 097

--8212270116 Forwards outline & description of NFS insp program to verify matl balance emphasizing measured discards Summary rept detailing further actions will be prepared following insp
O'REILLY, J P Region 2, Atlanta, Office of the Director 77/06/07 HOWARD, E M Division of Safeguards Inspections 5pp 16566 130

--8212270124 Forwards final rept re 790920 preliminary draft, "Summary Rept of High Enriched Hexfluoride Leak, 790807"
MANSER, W C Nuclear Fuel Services, Inc (subs of Getty Oil Co) 77/10/29 GILLESPIE, F P Region 2, Atlanta, Safeguards Branch 13pp 16566 175

--8212270128 Forwards Fuel Facility & Matls Safety Branch input for Safeguards Branch assessment re NFS inventory differences
GIBSON, A F Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/05/20 GILLESPIE, F P Region 2, Atlanta, Safeguards Branch 3pp 16566 212

8212150088 PNO-11-82-133 on 821013, physical inventory resulted in inventory difference of gain exceeding calculated limit of error Investigation conducted for probable cause
MCALPINE, E J Region 2, Office of Director 82/12/08 1p 16431 026

8212100011 Requests Commission review suggested questions for relevancy & materiality & allow NRC & other parties to respond in writing in lieu of oral session Adequate record can be developed w/written questions Certificate of Svc encl
FONNER, R L Regulations Division. 82/12/09 6pp 16379 154

8212270544 Provides results of determinations on spiked urine sample received from RESL per 821006 ltr request Average of results is 399 DPM U per liter
MANSER, W C Nuclear Fuel Services, Inc (subs of Getty Oil Co) 82/12/09 MONTGOMERY, D Region 2, Office of Director 2pp 16546 344

8212150138 Forwards IE Safeguards Insp Rept 70-0143/82-44 on 821115-19 No noncompliance noted
GIBSON, A F Division of Engineering & Technical Programs 82/12/13 MANSER, W C Nuclear Fuel Services, Inc (subs of Getty Oil Co) 2pp 16423 239

--8212150143 IE Safeguards Insp Rept 70-0143/82-44 on 821115-19 No noncompliance noted Major areas inspected security plan & implementing procedures, records & repts & physical barriers-protected areas Details withheld (ref 10CFR73 21)
TILLMAN, A, MCQUIRE, D R Division of Engineering & Technical Programs 82/12/10 1p. 16423 241

8212200021 Response to NRC 821209 request to answer questions in writing Opposes NRC proposal to cancel oral session All parties should answer questions in writing & propose followup questions Certificate of Svc encl
WEISS, E R Natural Resources Defense Council WEISS, E R Harmon & Weiss 82/12/15 8pp 16473 087

8212210253 Comments on proposed NRDC questions re hypothetical programmatic alternatives to continued operation of plant, in preparation for proceeding on matter Certificate of Svc encl
LEIKEN, L Energy, Dept of 82/12/20 6pp 16483 303

8212270238 Comments on proposed NRDC questions Seventeen questions beyond scope of proceeding Questions 31 - 34 & 37 relate to safeguards & security Certificate of Svc encl
LEIKEN, L Energy, Dept of 82/12/20 6pp 16530 058

8212202024 Advises that Div of Security completed security review of questions filed by NRDC on 821109 for Commission oral hearing Matl contains no classified info
STUCKY, S W Docketing & Services Branch 82/12/21 Office of the Executive Legal Director 1p. 16517 267.

--8212202048 Classified inserts to NRDC proposed questions to Commission Div of Security determined that matl contains no classified info. Certificate of Svc encl
WEISS, E R Natural Resources Defense Council WEISS, E R Harmon & Weiss 82/11/10. 12pp 16517 268.

8212230344 Order suspending schedule set forth in 821001 order for oral session
CHILK, S J Office of the Secretary of the Commission 82/12/21 1p 16505 131

8212300239 Transcript of Commission 821221 meeting in Washington, DC re plans for hearing to modify NFS Erwin, TN license Pp 1-72
* Commissioners 82/12/21 75pp 16612 335

8212280270 Request to comment on scope of proceeding NRDC entitled to rebut NRC arguments that NRDC questions beyond proper scope of proceeding Suggested response date is 830110 Certificate of Svc encl
WEISS, E R Natural Resources Defense Council WEISS, E R Harmon & Weiss 82/12/27 Commissioners 5pp 16561 244

DOCKET 70-0146 SPENCER CHEMICAL CO , KANSAS CITY, MO

8212280009 Addl response to FOIA request for six categories of documents re Spencer Chemical Co Forwards documents listed in App A
FELTON, J M Division of Rules and Records 82/11/29 BARNES, C Affiliation Unknown 2pp 16390 141

--8212280016 Requests that rept on levels of fixed & removable U contamination, including radiation levels existing on applicable bldgs, equipment & property, be submitted prior to termination of License SNM-154
MUSBAUMER, D A Atomic Energy Commission 64/01/06 GREENLEE, N A Spencer Chemical Co 1p 16590 148

--8212280019 Forwards license 640302 ltr specifying results of residual contamination survey Closeout insp requested to permit termination of License SNM-154
MUSBAUMER, D A Atomic Energy Commission 64/04/07 DUBINSKI, L Atomic Energy Commission 1p 16590 151

--8212280022 Trip rept of 640430 visit to Jayhawk Works site located 22 miles south of Pittsburgh, KS, to conduct closeout insp of License SNM-154, in response to TW Brackett 640413 request
WALKER, D I Atomic Energy Commission 64/05/20 DUBINSKI, L Atomic Energy Commission 5pp 16590 152

--8212280024 Recommends that License SNM-154, covering activities performed at Jayhawk Works plant near Pittsburgh, KS, be terminated
LAFIELD, R L Atomic Energy Commission 64/12/28 Atomic Energy Commission 1p 16590 158

--8212280026 Outlines soil sample procedures & results of 811009 contamination survey of Jayhawk burn site under License SNM-154 No significant difference noted in geiger counter readings on matls or water Field sample diagram encl
PURCELL, L D Spencer Chemical Co 81/10/14 SCOTT, L M Spencer Chemical Co 4pp 16590 159

--8212280030 Forwards results of 810810 radiation survey of advanced matls plant/bldg & pressure vessel test lab, in response to 820512 request No detectable amounts of natural U or thorium found at either bldg site
MCCORMACK, O M Gulf Oil Corp 82/06/04 CAIN, C L Region 4, Office of Director 3pp 16590 163

DOCKET 70-0258 ILLINOIS, UNIV OF, URBANA, IL

8212140396 Forwards IE Safeguards Insp Repts 50-151/82-01, 50-356/82-02 & 70-0258/82-01 on 821117-19 & notice of violation Insp rept details withheld (ref 10CFR2 790)
MILLER, J R Division of Engineering & Technical Programs 82/12/09 MILEY, G H Illinois, Univ of, Urbana-Champaign 2pp 16404 344 24X Fiche 50-151, 82/12/09, 8212140396

--8212140399 Notice of violation from insp on 821117-19
MILLER, J R Division of Engineering & Technical Programs 82/12/09 1p 16404 346 24X Fiche 50-151, 82/12/09, 8212140396.

--8212140414 IE Safeguards Insp Repts 50-151/82-01, 50-356/82-02 & 70-0258/82-01 on 821117-19 Noncompliance noted failure to include items containing SNM on annual inventory & to submit 742 forms Details withheld (ref 10CFR2 790)
MADEJA, T J, CREED, J R Division of Engineering & Technical Programs 82/12/06 1p 16404 347 24X Fiche 50-151, 82/12/09, 8212140396

DOCKET 70-0340 SPENCER CHEMICAL CO , KANSAS CITY, MO

B21280009 Addl response to FOIA request for six categories of documents re Spencer Chemical Co Forwards documents listed in App A
FELTON, J M Division of Rules and Records 82/11/29 BARNES, C
Affiliation Unknown 2pp 16590 141

--B21280012 Requests correspondence re Spencer Chemical Co be sent to listed address
COBB, G W Kerr-McGee Corp 62/09/06 JOHNSON, L Atomic Energy
Commission 1p 16590 144

DOCKET 70-0371 UNC NAVAL PRODUCTS, INC , UNCASVILLE, CT

B212010338 Requests addl info re B20224 application for renewal of License SNM-368 Info should be submitted in 60 days to continue review
CROW, W T Uranium Fuel Licensing Branch 82/11/19 KIRK, W F
United Nuclear Corp 6pp 16271 318

B212010497 Advises that info requested in NRC B11216 ltr re Amend 16 on environ sampling for nonradioactive matls & de minimis U release concentrations must be provided within 30 days
Failure constitutes basis for denial per 10CFR2 108
PAGE, R G Uranium Fuel Licensing Branch 82/11/24 KIRK, W F
United Nuclear Corp 1p 16270 209

B212150266 Lists priority items in B21014 & 26 license change submittals
KIRK, W F United Nuclear Corp 82/11/24 PAGE, R G Uranium Fuel
Licensing Branch 1p 16446 283

B212270541 Discusses request for amend to eliminate non-radiological environ monitoring from NRC license control for License SNM-368 Licensee also subj to CT Dept of Environ Protection regulation for facility effluent & discharge control
KIRK, W F United Nuclear Corp 82/12/01 PAGE, R G Fuel Process
& Fab Branch (Pre 790727) 3pp 16546 353

DOCKET 70-0687 UNION CARBIDE CORP , TUXEDO, NY

B212160245 Forwards revised fundamental nuclear matls control plan in accordance w/10CFR70 32 Revision incorporates organizational changes & implementation of U-235 recovery in waste form SNM not affected W/o encl
MCDOVERN, J J Union Carbide Corp 82/11/04 JACKSON, R L Office
of Nuclear Material Safety & Safeguards, Director 1p 16447 202

B212070173 Forwards response to B21104 request for addl info & addl Tech Spec changes re renewal to License R-81
VOTH, M H Union Carbide Corp 82/11/22 THOMAS, C D
Standardization & Special Projects Branch 14pp 16337 001 24X
Fiche 50-054, 82/11/22, B212070173

B212160331 Requests technical assistance in reviewing seismic info from encl Union Carbide Corp environ submittal Info supports application for renewal of SNM license W/o encl
ROUSE, L C Advanced Fuel & Spent Fuel Licensing Branch 82/11/23
JACKSON, R E Geosciences Branch 1p 16447 201

B212210376 Forwards IE Insp Rept 70-0687/82-07 on B21102-05 & notice of violation
MARTIN, T T Division of Engineering & Technical Programs 82/12/06
MCDOVERN, J J Union Carbide Corp 2pp 16494 316

--B212210379 Notice of violation from insp on B21102-05
* Division of Engineering & Technical Programs 82/12/06 1p.
16494 318

--B212210390 IE Insp Rept 70-0687/82-02 on B21102-05 Noncompliance noted failure to maintain stored U solution in doubly sealed container & post new waste storage facility w/"caution radioactive matl" sign
ROTH, J , GDDY, A T Division of Engineering & Technical Programs
82/11/30 9pp 16494 319

DOCKET 70-0698 WESTINGHOUSE ELECTRIC CORP, PITTSBURGH, PA

B212080654 Advises that License SNM-770 renewed for 5 yrs, expiring 871031 Renewal issued following preparation of EIA Negative declaration approved per 10CFR51 FR notice issued 821026
License SNM-770 & SER forwarded
PAGE, R G Uranium Fuel Licensing Branch 82/11/30 NARDI, A J
Westinghouse Electric Corp 1p 16379 310

--B212080671 License SNM-770 for Westinghouse, authorizing use of all byproduct matl, SNM & source matls (U, depleted U & thorium) in forms & amounts listed, per 810529 revised application & 810807 & B20427 suppl
PAGE, R G Division of Fuel Cycle & Material Safety 82/11/30
4pp 16379 311

--B212080695 SER supporting renewal of License SNM-770 per 810529 application & 810807 & B20427 suppl subj to listed conditions
KETZLACH, N , SOONG, A Division of Fuel Cycle & Material Safety
82/10/31 29pp 16379-319

DOCKET 70-0734 QA TECHNOLOGIES, INC , SAN DIEGO, CA

B212010503 Advises of issuance of Amend 5 to License SNM-696, changing corporate ownership & name to QA Technologies, Inc
PAGE, R G Uranium Fuel Licensing Branch 82/11/26 MOHRY, W R QA
Technologies, Inc /General Atomic Co 1p 16308 326

--B212020081 Safety evaluation supporting Amend 15 to License SNM-696
KETZLACH, N , CROW, W T Uranium Fuel Licensing Branch 82/11/26
2pp 16308 327

B212300207 Forwards IE Insp Rept 70-0734/82-09 on B21018-22 & notice of violation
SPENCER, O S Division of Radiological Safety & Safeguards Program
82/12/08 PARKER, J W QA Technologies, Inc /General Atomic Co
2pp 16597 338

--B212300210 Notice of violation from insp on B21018-22
THOMAS, R D Region 5, Office of Director 82/12/08 1p
16597 340

--B212300213 IE Insp Rept 70-0734/82-09 on B21018-22 Noncompliance noted licensee B20309 waste shipment to Chem-Nuclear Sys SC burial site arrived w/total of 11 holes in two boxes
BROCK, B L , ZURAKOWSKI, P R , THOMAS, R D Division of Radiological
Safety & Safeguards Program 82/12/08 12pp 16597 341

DOCKET 70-0754 GENERAL ELECTRIC CO , PLEASANTON, CA

B212280276 Requests delay to respond to B21021, 1112 & 19 memoranda & orders, due to inaccessability of documents needed for complete response Partial response to GE B21123 requests provided
TURK, J Affiliation Unknown 82/12/20 FRYE, J H , LINENBERGER, O ,
FOREMAN, H Atomic Safety and Licensing Board Panel 2pp
16561 230 24X Fiche 50-070, 82/12/20, B212280276

B212300022 Grants J Turk petition for extension until 830105 to respond to ASLB B21119 memorandum & order Other petitioners & intervenors granted same extension NRC response due by 830117
FRYE, J H Atomic Safety and Licensing Board Panel 82/12/27
TURK, J Affiliation Unknown 1p 16598 310 24X
Fiche 50-070, 82/12/27, B212300022

DOCKET 70-0820 UNITED NUCLEAR CORP , WOOD RIVER JCT , RI

B212290351 Forwards IE Safeguards Insp Rept 70-0820/82-11 on B21101-05 No noncompliance noted
MARTIN, T T Division of Engineering & Technical Programs 82/12/15
AMY, G O United Nuclear Corp 2pp 16586 240

--B212290352 IE Safeguards Insp Rept 70-0820/82-11 on B21101-05 No noncompliance noted Major areas inspected, holdup measurements for decommissioning
ZIBULSKY, H , WOLTER, E , DELLA RATTIA, A Region 1, Office of
Director. 82/12/13 2pp 16586 242

B212270252 Ack receipt of B20225 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-0820/81-10
Severity Level V re discharges into storage tank appropriate & will remain as cited
MARTIN, T T Division of Engineering & Technical Programs 82/12/21
AMY, G O United Nuclear Corp 2pp. 16530 319

--B212270256 Responds to NRC B20208 ltr re violations noted in IE Insp Rept 70-0820/81-10 Corrective actions liquid sample from storage tank analyzed for nitrate & fluoride ions Severity Level V categorization disputed
GREGG, R J United Nuclear Corp 82/02/25 MARTIN, T T Division
of Engineering & Technical Programs 3pp 16530 321

DOCKETED ITEMS

DOCKET 70-0824 BABCOCK & WILCOX CO , LYNCHBURG, VA

8212090292 Forwards IE Insp Rept 70-0824/82-09 on 821018-19 No noncompliance noted
 OIBSON, A F Division of Engineering & Technical Programs 82/11/02
 ENGELDER, T C Babcock & Wilcox Co 2pp 16361 336

--8212090265 IE Insp Rept 70-0824/82-09 on 821018-19. No noncompliance noted Major areas inspected info notices, safety committees, procedure control, maint, facility changes & mods, operations & criticality safety
 TROUP, G L, MCALPINE, E J Division of Engineering & Technical Programs 82/11/01 4pp 16361 338

8212090292 Forwards IE Insp Rept 70-0824/82-08 on 821020 No noncompliance noted
 OIBSON, A F Division of Engineering & Technical Programs 82/11/16
 ENGELDER, T C Babcock & Wilcox Co 2pp 16365 177

--8212090294 IE Insp Rept 70-0824/82-08 on 821020 No noncompliance noted Major areas inspected emergency preparedness
 MARSTON, R R, JENKINS, G R Region 2, Office of Director 82/11/15 5pp 16365 179

8212090477 Ack receipt of 821104 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 70-0824/82-07
 OIBSON, A F Division of Engineering & Technical Programs 82/11/22
 ENGELDER, T C Babcock & Wilcox Co 1p 16365 309

--8212090489 Responds to NRC 821019 ltr re violation noted in IE Insp Rept 70-0824/82-07 Corrective actions, segmented gamma scan operator instructed in need for data recording & retention. Procedure for waste scanning will be revised by 821215
 ENGELDER, T C Babcock & Wilcox Co 82/11/04 OIBSON, A F Division of Engineering & Technical Programs 2pp 16365 310

--8212090499 Forwards IE Insp Rept 70-0824/82-07 on 820928-30 & notice of violation Rept & notice of violation withheld (ref 10CFR2 790)
 OIBSON, A F Division of Engineering & Technical Programs 82/10/19 ENGELDER, T C Babcock & Wilcox Co 2pp. 16365-312

DOCKET 70-1100 COMBUSTION ENGINEERING, INC , WINDSOR, CT

8212160004 Requests extension from 821030 to 821115 to submit matl balance summary for period ending 820930 Request necessary due to heavy production schedule & generation of accompanying documentation
 BOWIE, T B Combustion Engineering, Inc 82/10/26 JACKSON, R NRC
 - No Detailed Affiliation Given. 2pp 16447:283

8212030029 Forwards IE Insp Rept 70-1100/82-09 on 820929-1001 No noncompliance noted.
 MARTIN, T Y Division of Engineering & Technical Programs 82/11/19
 LICHTENBERGER Combustion Engineering, Inc. 2pp 16305 054

--8212030032 IE Insp Rept 70-1100/82-09 on 820929-1001 No noncompliance noted. Major areas inspected radiation protection program, termination repts, source leak tests, bioassay, dosimetry, surveys & training
 CLEMONS, P, GREENHAM, E Region 1, Office of Director. 82/11/12 5pp 16305:056

8212290360 Forwards IE Safeguards Insp Rept 70-1100/82-10 on 821018-22 No noncompliance noted
 MARTIN, T Y Division of Engineering & Technical Programs. 82/12/14
 LICHTENBERGER Combustion Engineering, Inc 2pp 16586:256

--8212290363 IE Safeguards Insp Rept 70-1100/82-10 on 821018-22 No noncompliance noted Major areas inspected measurement & statistical controls, internal control & inventory verification
 ZIBULSKY, H, GODY, A T Region 1, Office of Director 82/12/09 3pp 16586 258.

DOCKET 70-1113 GENERAL ELECTRIC CO , WILMINGTON, NC

8212090264 Forwards IE Safeguards Insp Rept 70-1113/82-22 on 821018-22 No noncompliance noted
 OIBSON, A F Division of Engineering & Technical Programs 82/11/04
 LONG, J A General Electric Co 2pp. 16361 282

--8212090270 IE Safeguards Insp Rept 70-1113/82-22 on 821018-22 No noncompliance noted Major areas inspected statistical controls associated w/nuclear matl accountability measurements Details withheld (ref 10CFR2 790)
 JONES, D W, MCALPINE, E J Division of Engineering & Technical Programs 82/11/04 1p 16361 284

8212160423 Forwards revisions to fundamental nuclear matl control plan Encls withheld (ref 10CFR2 790)
 VAUGHAN, C M General Electric Co 82/11/18 EVANS, L J Fuel Facility Safeguards Licensing Branch 1p 16447 190

8212160378 Comments on review of draft license conditions re groundwater monitoring outlined in 821008 ltr Conditions acceptable w/ listed deletions
 WAKILD, C North Carolina, State of 82/11/24 CROW, W T Uranium Fuel Licensing Branch 1p 16447 199

8212230085 Forwards revised page from 820331 amend application for License SNM-1097 to increase plant capacity Revision reflects use of new equipment which will provide timely operational support
 VAUGHAN, C M General Electric Co 82/12/07 CROW, W T Uranium Fuel Licensing Branch 1p 16544 265

--8212230103 Revised page for 820331 amend application to License SNM-1097, reflecting new equipment to provide timely operational support
 VAUGHAN, C M General Electric Co 82/12/07 CROW, W T Uranium Fuel Licensing Branch 1p 16544 266

DOCKET 70-1143 WESTINGHOUSE ELECTRIC CORP , PITTSBURGH, PA

8212150262 Forwards final survey results for weld pit in Pu fuels development lab Pit meets unqualified release criteria & should be released for unrestricted use Pit will be backfilled & opening sealed
 NARDI, A J Westinghouse Electric Corp 82/11/09 ROUSE, L C Advanced Fuel & Spent Fuel Licensing Branch 8pp 16446 284

8212220124 Forwards Revision 14 to application for amend to License SNM-1120, revising Page 2 5-3 re meteorological tower maint requirements
 NARDI, A J Westinghouse Electric Corp 82/11/09 ROUSE, L C Division of Fuel Cycle & Material Safety 2pp 16525 356

--8212220134 Revision 14 to application for amend to License SNM-1120, revising Page 2 5-3 re meteorological tower maint requirements
 Westinghouse Electric Corp 82/11/30 4pp 16525 358

8212170014 Forwards Amend B to License SNM-1120, revised license pages & SER Amend revises requirements for maintaining meteorological tower
 ROUSE, L C Advanced Fuel & Spent Fuel Licensing Branch 82/12/07
 NARDI, A J Westinghouse Electric Corp 1p 16480 327

--8212170017 Amend B to Westinghouse License SNM-1120, revising requirements for maintaining meteorological tower
 ROUSE, L C Division of Fuel Cycle & Material Safety 82/12/07 3pp 16480 328

--8212170020 SER supporting proposed Amend B to License SNM-1120, revising requirements for maintaining meteorological tower
 KRATZKE, R T Advanced Fuel & Spent Fuel Licensing Branch 82/12/07 2pp 16480 331

8212230330 Forwards IE Insp Rept 70-1143/82-05 on 821018-22 & notice of violation
 MARTIN, T Y Division of Engineering & Technical Programs 82/12/08
 JACOBI, W M Westinghouse Electric Corp 2pp 16505 138

--8212230333 Notice of violation from insp on 821018-22
 Division of Engineering & Technical Programs 82/12/08 1p 16505 140

--8212230335 IE Insp Rept 70-1143/82-05 on 821018-22 Noncompliance noted Failure to maintain records of training for two individuals from Jan 1978-821020
 ROTH, J, GODY, A T Division of Engineering & Technical Programs 82/11/15 16pp 16505 141

8212230136 Advises that weld pit in Pu fuels development lab meets unqualified release criteria Westinghouse may proceed to backfill pit & seal opening
 ROUSE, L C Advanced Fuel & Spent Fuel Licensing Branch 82/12/13
 NARDI, A J Westinghouse Electric Corp 1p 16544 259

--B212230141 Safety evaluation supporting release of weld pit in Pu fuels development lab for unrestricted use
KRATZKE, R T , ROUSE, L C Advanced Fuel & Spent Fuel Licensing Branch 82/12/13 2pp 16544 260

DOCKET 70-1151 WESTINGHOUSE ELECTRIC CORP , PITTSBURGH, PA

B212090428 Forwards IE Safeguards Insp Rept 70-1151/82-21 on B21028-1102 No noncompliance noted
GIBSON, A F Division of Engineering & Technical Programs 82/11/17
D'AMORE, M Westinghouse Electric Corp 2pp 16363 347

--B212090445 IE Safeguards Insp Rept 70-1151/82-21 on B21028-1102 No noncompliance noted Major areas inspected physical inventory observation Details withheld (ref 10CFR2 790)
TODD, G A , LANFORD, J B , MCALPINE, E J Division of Engineering & Technical Programs 82/11/17 1p 16363 349

B212090547 Forwards IE Insp Rept 70-1151/82-20 on B21101-05 No noncompliance noted
GIBSON, A F Division of Engineering & Technical Programs 82/11/17
D'AMORE, M Westinghouse Electric Corp 2pp 16366 325

--B212090555 IE Insp Rept 70-1151/82-20 on B21101-05 No noncompliance noted Major areas inspected onsite emergency preparedness & offsite state & local support for licensee emergency organization
HUFFMAN, G N , JENKINS, G R Region 2, Office of Director 82/11/16 4pp 16366 327

B212020209 Trip rept of B21103-04 visit to Columbia facility to discuss pending amend application & to observe facilities & equipment to be used in bulk handling
BIDINGER, G H Uranium Fuel Licensing Branch 82/11/19 CROW, W T Uranium Fuel Licensing Branch 1p 16302 337

G212150340 Forwards addl info re B20326 application to amend License SNM-1107, consisting of Revision 13a, per NRC B21102 request
NARDI, A J Westinghouse Electric Corp 82/11/19 PAGE, R O Uranium Fuel Licensing Branch 18pp 16446 246

G212150238 Forwards "Columbia Plant ALARA Rept, Jan-June, 1982," in support of application for renewal of License SNM-1107
REITLER, E K Westinghouse Electric Corp 82/11/22 BIDINGER, G H Uranium Fuel Licensing Branch 1p 16446 302

--B212150244 "Columbia Plant ALARA Rept Jan-June, 1982 "
REITLER, E K , SANDERS, C F , GOODWIN, W L Westinghouse Electric Corp 82/08/20 80pp 16446 303

B212090269 Forwards IE Safeguards Insp Rept 70-1151/82-23 on B21115-18 No noncompliance noted
GIBSON, A F Division of Engineering & Technical Programs 82/12/01
D'AMORE, M Westinghouse Electric Corp 2pp 16365 286

--B212090278 IE Safeguards Insp Rept 70-1151/82-23 on B21115-18 No noncompliance noted Major areas inspected measurements, measurement control program & followup of previously identified items Details withheld (ref 10CFR73 21)
BATES, J W , MCALPINE, E J Division of Engineering & Technical Programs 82/12/01 1p 16365 288

DOCKET 70-1193 KERR-MCGEE NUCLEAR CORP , OKLAHOMA CITY, OK

B212280013 Forwards check covering fee for administrative changes requested in B21015 ltr re license renewal
SHELLEY, W J Kerr-McGee Corp 82/10/18 WEISS, D License Fee Management Branch 2pp 16593 110

--B212280018 Notifies that OJ Sinke will be assuming OM France function as nuclear criticality inspector Depressed U industry led to discharge of OM France Changes will be reflected in updated standby license
SHELLEY, W J Kerr-McGee Corp 82/10/13 ROUSE, L C Advanced Fuel & Spent Fuel Licensing Branch 2pp 16593 112

DOCKET 70-1201 BABCOCK & WILCOX CO , LYNCHBURG, VA

B212090333 Forwards IE Insp Rept 70-1201/82-18 on B21020-22 No noncompliance noted
GIBSON, A F Division of Engineering & Technical Programs 82/11/02
ALTO, R A Babcock & Wilcox Co 2pp 16364 001.

--B212090340 IE Insp Rept 70-1201/82-18 on B21020-22 No noncompliance noted Major areas inspected organization, procedures, safety committees, training, maintenance, facility changes & mods, criticality safety, operations & info notices
ROUP, G L , MCALPINE, E J Division of Engineering & Technical Programs 82/11/01 6pp 16364 003

B212090263 Forwards IE Insp Rept 70-1201/82-16 on B21021-22 No noncompliance noted
GIBSON, A F Division of Engineering & Technical Programs 82/11/16
ALTO, R A Babcock & Wilcox Co 2pp 16362 337

--B212090274 IE Insp Rept 70-1201/82-16 on B21021-22 No noncompliance noted Major areas inspected emergency preparedness
MARSTON, R R , JENKINS, G R Division of Engineering & Technical Programs 82/11/15 4pp 16362 339

G212230025 Forwards revised pages to B10227 license renewal application per agreement reached at B21129 meeting
FORD, J T Babcock & Wilcox Co 82/12/06 PAGE, R O Uranium Fuel Licensing Branch 2pp 16344 269

--B212230031 Revised Pages 6, 8, 10-13 & 7B to B10227 renewal Application for License SNM-1168
* Babcock & Wilcox Co 82/12/06 7pp 16544 271

DOCKET 70-1237 EXXON NUCLEAR CO , INC , RICHLAND, WA

B212150276 Revision 7 to application for renewal of License SNM-1227, changing "quarterly" to "monthly" on Page 3 4B
* Exxon Nuclear Co, Inc (subs of Exxon Corp) 82/11/17 5pp, 16446 270

DOCKET 70-1308 GENERAL ELECTRIC CO , SAN JOSE, CA

B212130148 Notification of B21116 meeting w/GE in Silver Spring, MD to discuss potential changes, tests & experiments re thermal & dosimetry measurements involving Riddiford, Eggers & Assoc dry spent fuel cask
ROBERTS, J P Advanced Fuel & Spent Fuel Licensing Branch 82/11/18
ROUSE, L C Advanced Fuel & Spent Fuel Licensing Branch 2pp 16410, 285

DOCKET 70-1334 AVCO EVERETT RESEARCH LABORATORY, INC , EVERETT, MA

B212100178 Issues Amend 7 to License SNM-1308 in response to B20913 application Amend incorporates encl guidelines as Condition 14 of license
PAGE, R O Uranium Fuel Licensing Branch 82/12/02 SCHLIER, R E Avco Everett Research Laboratory, Inc 1p 16398 358

--B212100180 Safety evaluation supporting issuance of Amend 7 to License SNM-1308 Amend incorporates encl guidelines as Condition 14 of license
SOONO, A L , CROW, W T Uranium Fuel Licensing Branch 82/12/02 2pp 16398 359

DOCKET 70-1359 IRT CORP. , SAN DIEGO, CA

B212090068 Forwards IE Safeguards Insp Rept 70-1359/82-03 on B21021-22 No noncompliance noted
NORDERHAUG, L R Division of Radiological Safety & Safeguards Program 82/12/06 HERTZ, R L IRT Corp 2pp 16359 090

--B212090071 IE Safeguards Insp Rept 70-1359/82-03 on B21021-22 No noncompliance noted Major areas inspected implementation of nuclear matl control & accounting procedures, facility organization & operation, shipping & receiving & storage
WIEDER, A V , NELSON, G B , NORDERHAUG, L R Division of Radiological Safety & Safeguards Program 82/12/06 4pp 16359 092

DOCKET 70-1430 MT. SINAI HOSP MEDICAL CENTER, CHICAGO, IL

B212150040 Forwards IE Safeguards Insp Repts 50-112/82-02 & 70-1430/82-02 on B21023-29 No noncompliance noted
MADSEN, G L Division of Resident, Reactor Project & Engineering Programs 82/12/09 UPTEGROVE, W R Oklahoma Univ of 2pp 16421 322 24X Fiche 50-112, 82/12/09, B212150040

DOCKETED ITEMS

--B212150049 IE Safeguards Insp Repts 50-112/82-02 & 70-1430/82-02 on 821025-29 No noncompliance noted Major areas inspected nuclear mat'l control & accountability, including facility organization & operation Details withheld (ref 10CFR2 790) CALDWELL, R A. KELLY, J A Division of Resident Reactor Project & Engineering Programs 82/11/30 1p 16421 324 24X Fiche 50-112,82/12/09,8212150040

DOCKET 70-1621 DUGUESNE LIGHT CO., PITTSBURGH, PA

B212270173 Forwards Endorsement 60 to NELIA Policy NF-226 & Endorsement 52 to MAELU Policy MF-87 BARNETT, J E Conover & Associates, Inc Insurance 82/12/20 DINI72, I Antitrust & Economic analysis Branch (Utility Finance) 3pp 16539 004

B212280254 Forwards Endorsements 1,2 & 3 to NELIA & MAELU Certificates N-58 & M-58, respectively BARNETT, J E Conover & Associates, Inc Insurance 82/12/22 DINI72, I Antitrust & Economic analysis Branch (Utility Finance) 19pp 16561 278

DOCKET 70-2487 ST CLARE'S HOSP., DENVER, NJ

B212140303 Notices of expiration of License SNM-1708, per 820812 telcon Statement explaining method of disposal of mat'l & repts for individuals engaged in activities under expired license requested MARTIN, T T Division of Engineering & Technical Programs 82/11/30 COUREY, K M St Claire's Hosp Denver, NJ 2pp 16402 078

DOCKET 70-2792 LOWER DUCKS HOSP., BRISTOL, PA

B212030016 Act receipt of B21027 ltr providing policy/procedure for controlling nuclear pacemakers KINNEHAN, J D Division of Engineering & Technical Programs 82/11/24 THOMAS, C J Lowell General Hosp Lowell, MA 1p 16304 238

--B212030020 Forwards policy/procedure for controlling nuclear pacemakers THOMAS, C J Lowell General Hosp Lowell, MA 82/10/27 DAVIS, J Region I, Office of Director 4pp 16304 239

DOCKET 70-2872 RS HOLDING, INC., CLEVELAND, OH

B212100245 Discusses IE Insp of Licenses SNM-1826, 34-18233-01 & 34-18156-01 on 820621-25 & forwards notice of violation SRENIANSKI, D J Division of Engineering & Technical Programs 82/12/02 KEMPE, R A Rauter-Stokes, Inc 2pp 16376 111

--B212100249 Notice of violation from insp on 820621-25 Noncompliance noted film badges issued which did not monitor for fast neutrons SRENIANSKI, D J Division of Engineering & Technical Programs 82/12/02 1p 16376 113

DOCKET 70-2895 SPECTRO-CHEM LABORATORIES, INC., FRANKLIN LAKES, NJ

B212140251 Discusses IE Insp Rept 70-2895/82-01 on 820826 & forwards notice of violation MARTIN, T T Division of Engineering & Technical Programs 82/11/30 VAN DIEN, E I Spectro-Chem Laboratories, Inc 2pp 16409 324

--B212140248 Notice of violation from insp on 820826 Noncompliance noted failure to check urine for U semiannually & to perform surveys w/survey meter 810407-820712 Division of Engineering & Technical Programs 82/11/30 1p 16409 326

DOCKET 70-2926 DETROIT EDISON CO., DETROIT, MI

B212130424 Forwards revised application for license to receive, possess, repackage for shipment, transfer & store SNM License should be issued before 830225 to allow receipt of unirradiated fuel onsite to support 830613 fuel load TAUBER, H Detroit Edison Co 82/11/09 DAVIS, J Office of Nuclear Material Safety & Safeguards, Director 1p 16413 057

--B212130427 Revised application for license to receive, possess, repackage for shipment, transfer & store SNM Request license be issued before 830225 to allow receipt of unirradiated fuel onsite to support 830613 fuel load TAUBER, H Detroit Edison Co 82/10/31 24pp 16413 058

DOCKET 70-2928 TENNESSEE VALLEY AUTHORITY

B212170004 Advises of issuance of Amend 1 to License SNM-1873, extending expiration date to 830531 SER encl PAOE, R Q Uranium Fuel Licensing Branch 82/12/08 MILLS, L M Tennessee Valley Authority 1p 16478 001

--B212170011 SER supporting Amend 1 to License SNM-1873, extending expiration date to 830531 BIDINGER, O H, CROW, W T Uranium Fuel Licensing Branch 82/12/08 1p 16478 002

DOCKET 70-2941 TENNESSEE VALLEY AUTHORITY, CHATTANOOGA, TN

B212270026 Advises of issuance of Amend 1 to License SNM-1883, extending expiration date to 840531 SER encl PAOE, R Q Uranium Fuel Licensing Branch 82/12/16 MILLS, L M Tennessee Valley Authority 1p 16551 342

--B212270029 SER supporting issuance of Amend 1 to License SNM-1883 CROW, W T Uranium Fuel Licensing Branch 82/12/16, 1p 16551 343

DOCKET 70-2949 ARIZONA PUBLIC SERVICE CO., PHOENIX, AZ

B212130146 Transmits Amend 3 to physical security plan in support of License SNM-887 Amend withheld (ref 10CFR2 790 & 10CFR9 5) Ex-core detectors from C-E expected on site by 821201 ANDONINI, O C Arizona Public Service Co 82/11/12 Office of Nuclear Material Safety & Safeguards, Director 1p 16410 287

DOCKET 70-2955 EDLOW INTERNATIONAL CO., WASHINGTON, DC

B211090496 Requests that Reporting Identification Symbol XKB be used for all mat'l stored at St Louis, IL site Symbol would apply to Licenses SMC-1377 & SNM-1903 mat'l SHAW, A Edlow International Co 82/10/12 PAOE, R Q Uranium Recovery Licensing Branch 1p 16021 001

DOCKET 70-2957 FLORIDA POWER & LIGHT CO., MIAMI, FL

B212150204 Application for Amend 1 to License SNM-1902, amending License Condition 11 to remove potentially unnecessary constraint in initial fuel assembly unloading UHRIO, R E Florida Power & Light Co 82/11/17 PAOE, R Q Uranium Fuel Licensing Branch 1p 16447 068

B212130285 Advises of issuance of Amend 1 to License SNM-1902, modifying Condition 11 re control of fuel assemblies PAOE, R Q Uranium Fuel Licensing Branch 82/12/03 UHRIO, R E Florida Power & Light Co 1p 16418 241

--B212130287 Safety evaluation supporting Amend 1 to License SNM-1902 SERINI, B L, CROW, W T Uranium Fuel Licensing Branch 82/12/03 2pp 16418 242

DOCKET 70-2960 KANSAS GAS & ELECTRIC CO., WICHITA, KS

B212100187 Forwards request for addl info to complete initial safety review of application for receipt & storage of fresh fuel assemblies, fission chambers & fission counter SERINI, B L Uranium Fuel Licensing Branch 82/12/02 KOESTER, O L Kansas Gas & Electric Co 3pp 16399 023

DOCKET 70-2964 CONSUMERS POWER CO., JACKSON, MI

B212080007 Forwards request for addl info re review of 820622 application to receive, inspect, possess, store & transfer fresh fuel assemblies KILLINGER, M H Uranium Fuel Licensing Branch 82/11/26 COOK, J W Consumers Power Co 3pp 16367 182

8212230112 Forwards revised security plan for new irradiated fuel assemblies Info withheld (ref 10CFR73 21)
COOK, J W Consumers Power Co 82/11/29 DAVIS, J O Office of Nuclear Material Safety & Safeguards, Director 3pp 16544 262

DOCKET 70-2965 CONSUMERS POWER CO, JACKSON, MI

8212080007 Forwards request for addl info re review of 820622 application to receive, inspect, possess, store & transfer fresh fuel assemblies
KILLINGER, M H Uranium Fuel Licensing Branch 82/11/26 COOK, J W Consumers Power Co 3pp 16367 182

8212230112 Forwards revised security plan for new irradiated fuel assemblies Info withheld (ref 10CFR73 21)
COOK, J W Consumers Power Co 82/11/29 DAVIS, J O Office of Nuclear Material Safety & Safeguards, Director 3pp 16544 262

DOCKET 70-2968 CLEVELAND ELECTRIC ILLUMINATING CO, CLEVELAND, OH

8212060493 Requests ack of receipt of matl license application & supplied 820830 & 0930, respectively
KILLINGER, M H Uranium Fuel Licensing Branch 82/11/30 STEFANO, J Office of Nuclear Reactor Regulation, Director CUTCHIN, J Hearing Branch 4 1p 16348 014

PACKAGING OF RADIOACTIVE MATERIAL FOR TRANSPORT AND TRANSPORTATION OF RADIOACTIVE MATERIAL UNDER CERTAIN CONDITIONS

DOCKET 71-0170 GENERAL ELECTRIC CO

8212160020 Forwards QA program approval for Radioactive Matl Package 0170, Revision 2
MACDONALD, C E Transportation Branch 82/11/30 CUNNINGHAM, G E General Electric Co 1p 16447 274

--8212160023 QA program approval for Radioactive Matl Package 0170, Revision 2
MACDONALD, C E Transportation Branch 82/11/30 1p 16447 275

DOCKET 71-0206 PRYOR FOUNDRY, INC

8212100057 Forwards QA program approval for Radioactive Matl Package 0206, Revision 1
MACDONALD, C E Transportation Branch 82/11/30 GILBREATH, J H Pryor Foundry Inc 1p 16398 335

--8212100062 QA program approval for Radioactive Matl Package 0206, Revision 1
MACDONALD, C E Transportation Branch 82/10/20 1p 16398 336

DOCKET 71-0370 AMERSHAM CORP

8212100066 Forwards QA program approval for Radioactive Matl Package 0370, Revision 0
MACDONALD, C E Transportation Branch 82/11/30 BAOSY, L A Amersham Corp 1p 16399 039

--8212100069 QA program approval for Radioactive Matl Package 0370, Revision 0
MACDONALD, C E Transportation Branch 82/11/30 1p 16399 040

DOCKET 71-0394 NUCLEAR SOURCES & SERVICES, INC

8212130222 Forwards portions of revised QC manual for review
GALLAGHER, R D, Nuclear Sources & Services, Inc 82/11/22 MACDONALD, C E Transportation Branch 29pp 16414 059

DOCKET 71-0454 ATOMIC ENERGY OF CANADA, LTD

8212160134 Forwards Revision 1 to QA program for design, testing & fabrication of radioactive matl transport packages per 820712 request Current designation is AECL-CP Document 5.01-AA 02, Revision 1
RIDDOUT, E F Canada 82/11/12 MACDONALD, C E Transportation Branch 4pp 16449 023

--8212160148 Revision 1 to QA program for design, testing & fabrication of radioactive matl transport packages
RIDDOUT, E F, BROWN, M Canada 82/11/10 26pp 16449 027

8212130068 Forwards QA program approval for Radioactive Matl Package 0454, Revision 1
MACDONALD, C E Transportation Branch 82/11/30 RIDDOUT, E F Atomic Energy of Canada, Ltd 1p 16417 233

--8212130074 QA program approval for Radioactive Matl Package 0454, Revision 1
MACDONALD, C E Transportation Branch 82/11/30 1p 16417 254

DOCKET 71-0474 NAVY, DEPT OF

8212230156 Requests QA program approval for Certificate of Compliance 0474 be modified to allow shipment of radioactive matl & exchange old cesium source radiac calibrator for new type
PERRY, J M Navy, Dept of 82/12/09 GORDON, L NRC - No Detailed Affiliation Given 1p 16544 039

DOCKET 71-0483 FAIRCHILD HESTON SYSTEMS, INC

8212100037 Responds to 820929 request for approval of QA program
Schlumberger, Inc must approve program
MACDONALD, C E Transportation Branch 82/12/03 PRATT, T E Fairchild Heston Systems, Inc. 1p 16399 344

DOCKET 71-0484 NEBRASKA PUBLIC POWER DISTRICT

8212160433 Requests concurrence that QA program approval in 791207 ltr meets 10CFR71 51(d) requirements to issue general license to deliver licensed matl to carrier for transport.
PILANT, J M Nebraska Public Power District 82/11/30 MACDONALD, C E Transportation Branch 1p 16447 187

8212230036 Forwards QA program approval for Radioactive Matl Package 0484, Revision 0
MACDONALD, C E Transportation Branch 82/12/10 PILANT, J M Nebraska Public Power District 1p 16545 348

--8212230039 QA program approval for Radioactive Matl Package 0484, Revision 0
MACDONALD, C E Transportation Branch 82/12/10 1p 16545 349

DOCKET 71-0486 INTEC INSPECTION, INC

8212160026 Forwards QA program approval for Radioactive Matl Package 0486, Revision 0
MACDONALD, C E Transportation Branch 82/11/18 BAKER, T Intec Inspection, Inc 1p 16447-272

--8212160028 QA program approval for Radioactive Matl Package 0486, Revision 0
MACDONALD, C E Transportation Branch 82/11/18 1p 16447 273

DOCKET 71-0487 ARMY, DEPT OF

8212220531 Forwards QA program approval for Radioactive Matl Package 0487, Revision 0
MACDONALD, C E Transportation Branch 82/12/09 TARAS, J N Army, Dept of, White Sands Missile Range. 1p 16522 330

--8212220538 QA program approval for Radioactive Matl Package 0487, Revision 0
MACDONALD, C E Transportation Branch 82/12/09 1p 16522 351

DOCKET 71-0488 RAMSEY CONSTRUCTION & FABRICATING CO, INC

8212210501 Forwards QA program for industrial radiography
STALLINS, J E Ramsey Engineering Company 82/11/03 MACDONALD, C E NRC - No Detailed Affiliation Given 1p 16502 356

--8212210504 QA program for industrial radiography
* Ramsey Engineering Company. 82/11/03, 3pp 16502, 357

8212220518 Forwards QA program approval for Radioactive Matl Package 0488, Revision 0
MACDONALD, C E Transportation Branch 82/12/09 STALLINS, J E Ramsey Construction & Fabrication Co, Inc 1p 16523 025

--8212220526 QA program approval for Radioactive Matl Package 0488, Revision 0
MACDONALD, C E Transportation Branch 82/12/09 1p 16523 026

DOCKETED ITEMS

DOCKET 71-0489 SACRAMENTO MUNICIPAL UTILITY DISTRICT

B212160009 Ack receipt of B21019 ltr of confirmation of registration for Cask CNS 14-195-M requesting info re QA program Since Rancho Seco plant GL granted QA program already approved MILLER, R Sacramento Municipal Utility District 82/11/18 MACDONALD, C E Transportation Branch 1p 16447 282

B212160177 Forwards QA program approval for Radioactive Matl Package 0489, Revision 0 MACDONALD, C E Transportation Branch 82/12/03 MILLER, R Sacramento Municipal Utility District 1p 16447 204

--B212160185 QA program approval for Radioactive Matl Package 0489, Revision 0 MACDONALD, C E Transportation Branch 82/12/03 1p 16447-205

DOCKET 71-0490 INSPECTION SERVICES CORP

B212270018 Forwards QA program for shipping radioisotopes BROTTON, O C Inspection Services Corp 82/12/07 MACDONALD, C E Transportation Branch 1p 16551 043

--B212270027 QA program for shipping radioisotopes. BROTTON, O C Inspection Services Corp. 82/12/07 3pp 16551 044

DOCKET 71-4909 MODEL GE 21PF-1, GENERAL ELECTRIC CO

B212140513 Forwards Revision 1 to Certificate of Compliance 4909 for Model GE-21PF-1 MACDONALD, C E Transportation Branch 82/11/19 VAUGHAN, C M General Electric Co 1p 16431 323

--B212140517 Certificate of Compliance 4909, Revision 1, for Model GE-21PF-1 Approval record encl MACDONALD, C E Transportation Branch 82/11/19 3pp 16431 324

B212130195 Requests registration of DDE, Union Carbide Corp & of Goodyear Atomic Corp as users of Model DR-3 HEISEKEL, M M Energy, Dept of 82/11/30 MACDONALD, C E Transportation Branch 2pp 16410 338

B212160727 Notification of registration as user of Model GE-21PF-1 in response to B21130 request MACDONALD, C E Transportation Branch 82/12/09 FORD, C L Union Carbide Corp 1p 16466 022

B212160733 Notification of registration as user of Model GE 21PF-1 in response to B21130 request MACDONALD, C E Transportation Branch 82/12/09 TAYLOR, J C Union Carbide Corp 1p 16466 007

B212160738 Notification of registration as user of Model GE 21PF-1 in response to B21130 request MACDONALD, C E Transportation Branch 82/12/09. BLALOCK, L Energy, Dept of 1p 16466 006

B212220041 Notification of registration as user of Model GE 21PF-1 in response to B21130 request MACDONALD, C E Transportation Branch 82/12/09 SIMPSON, W R Goodyear Atomic Corp 1p 16527 004

DOCKET 71-5086 MODEL UNC-2600, UNITED NUCLEAR CORP

B212160426 Requests registration as user of Model UNC-2600 KELLY, J W Babcock & Wilcox Co. 82/11/13 MACDONALD, C E Transportation Branch 1p 16447 189

B212170001 Notification of registration as user of Model UNC-2600 in response to B21113 request MACDONALD, C E Transportation Branch 82/12/07. KELLY, J W Babcock & Wilcox Co 1p 16502 238

DOCKET 71-5461 MODEL ORNL TRU, ENERGY, DEPT OF

B212160755 Notification of registration as user of Models ORNL TRU & ORNL TRU CALIF in response to B21015 request MACDONALD, C E Transportation Branch 82/12/09 GADDIS, C K Energy, Dept of 1p 16465 355

DOCKET 71-5469 MODEL HNPFF SPENT FUEL SHIPPING CASK, ENERGY, DEPT OF

B212220036 Forwards request for addl info to complete review of Model HNPFF spent fuel shipping casks per 780802 ltr Response within 30 days of receipt of ltr requested MACDONALD, C E Transportation Branch 82/12/09 PRICHARD, R P Energy, Dept of 3pp 16529 079

DOCKET 71-5740 MODEL ORNL TRU CALIF, ENERGY, DEPT OF

B212160755 Notification of registration as user of Models ORNL TRU & ORNL TRU CALIF in response to B21015 request MACDONALD, C E Transportation Branch 82/12/09 GADDIS, C K Energy, Dept of 1p 16465 355

DOCKET 71-5796 MODEL 181375, 181361, ADVANCED MEDICAL SYSTEMS, INC

B212160043 Application for revision of Certificate of Compliance 5796, modifying Model 181375 overpack shipping container bolt lug position & head tiedown sys Revised pages & drawings encl IRWIN, H R Advanced Medical Systems, Inc 82/11/01 MACDONALD, C L Transportation Branch 26pp 16447 285

--B212160050 Requests payment of minor amend fee for B21101 application for revision of Certificate of Compliance 5796 JACKSON, O License Fee Management Branch 82/11/10 IRWIN, H R Advanced Medical Systems, Inc 1p 16447 311

DOCKET 71-5814 MODEL NRBK-41, -42 & -43, ENERGY, DEPT OF

B212160086 Requests registration as user of NRBK-41 shipping container OLSEN, A F Babcock & Wilcox Co 82/11/17 Transportation Branch 1p 16447 251

B212230132 Advises that amend to Certificate of Compliance 5814 must be requested to include general license provision MACDONALD, C E Transportation Branch 82/12/15 OLSEN, A F Babcock & Wilcox Co 1p 16544 344

DOCKET 71-5907 MODEL ORNL IN PILE CAPSULE, ENERGY, DEPT OF

B212140509 Forwards request for addl info re 780731 application for approval of Model ORNL in-pile capsule MACDONALD, C E Transportation Branch 82/12/03 PRICHARD, R P Energy, Dept of 4pp 16431 327

DOCKET 71-5939 MODEL GE-1500, GENERAL ELECTRIC CO

B212150274 Requests registration as user of Model GE 1500 for transport of radioactive matl while involved in beneficial uses of nuclear byproducts program PIERCE, J D Sandia Laboratories 82/11/05 MACDONALD, C E Transportation Branch 1p 16446 275

B212160743 Notification of registration as user of Model GE-1500 in response to B21103 request MACDONALD, C E Transportation Branch 82/12/09 PIERCE, J D Sandia Laboratories 1p 16466 005

DOCKET 71-5942 MODEL GE-700, GENERAL ELECTRIC CO

B212130010 Notification of registration as user of Models GE-200 & GE-700 in response to B21026 request MACDONALD, C E Transportation Branch 82/11/18 ANSELMO, A A EG&G, Inc 1p 16417 069

DOCKET 71-5957 MODEL BMI-1, BATTELLE COLUMBUS LABORATORY

B212210529 Application for Revision 9 to Certificate of Compliance 5957, revising SAR pages re basket integrity BURIAN, R J Battelle Memorial Institute, Pacific Northwest Laboratory 82/11/23 MACDONALD, C E Transportation Branch. 3pp 16502 313

B212150212 Forwards replacement Page 1 & corrected replacement page schedule to B21123 application for Amend D to Certificate of Compliance 5957 BURIAN, R J Battelle Memorial Institute, Columbus Laboratories. 82/11/24 MACDONALD, C E Transportation Branch 1p 16447 059

--B21215021B Replacement Page 1 & corrected replacement page schedule to B21123 application for Amend D to Certificate of Compliance 5957
 * Battelle Memorial Institute, Columbus Laboratories 82/11/24
 3pp 16447 060

B212280010 Notices of future use of Model BM1-1
 FIEDLER, P B General Public Utilities - GPU Service Corp 82/12/01
 Division of Fuel Cycle & Material Safety 1p 16593 109

DOCKET 71-5971 MODEL GE-200, GENERAL ELECTRIC CO

B212130010 Notification of registration as user of Models GE-200 & GE-700 in response to B21026 request
 MACDONALD, C E Transportation Branch 82/11/18 ANGELMO, A A
 EQ&G, Inc 1p 16417 069

DOCKET 71-6003 MODEL M-130, ENERGY, DEPT OF

B21216003B Forwards Revision 2 to Certificate of Compliance 6003 for Model M-130
 MACDONALD, C E Transportation Branch 82/11/19 ENGEL, W P
 Energy, Dept of 1p 16447 259

--B212160041 Certificate of Compliance 6003, Revision 2, for Model M-130
 Approval record encl
 MACDONALD, C E Transportation Branch 82/11/19 7pp 16447 260

DOCKET 71-6144 MODEL B-2, U S ECOLOGY

B212270479 Requests registration as user of Models B-2 & GE-1600
 AYRES, J AWC, Inc 82/12/07 MACDONALD, C E Transportation
 Branch 1p 16551 055

DOCKET 71-6347 MODEL FSV-3, GENERAL ATOMIC CO

B21213003B Notification of registration as user of Model FSV-3 in response to B21105 request
 MACDONALD, C E Transportation Branch 82/11/22 COONEY, M J
 Philadelphia Electric Co 1p 16417 050

DOCKET 71-6495 MODEL PADUCAH DEMONSTRATION CASK, ENERGY

B212130122 Forwards safety summary rept for Certificate of Compliance 6495 Model Paducah demonstration cask & certificate of compliance
 PRICHARD, R P Energy, Dept of 82/11/17 MACDONALD, C E
 Transportation Branch 1p 16418 021

--B212130129 Certificate of Compliance 6495, Revision 0, for Model Paducah demonstration cask
 DUVAL, P A Energy, Dept of 82/04/05 8pp 16418 022

--B212130138 "Safety Summary Rept, Paducah Demonstration Cask (Packaging of Radioactive & Fissile Matls)"
 * Rockwell International Corp DPBU 71-124-4 82/02/28 147pp
 16416 006

DOCKET 71-6974 MODEL HN-200, HITTMAN NUCLEAR & DEVELOPMENT CORP

B212150222 Requests registration as user of Model HN-200
 GRAVES, R H Connecticut Yankee Atomic Power Co 82/11/12
 MACDONALD, C E Transportation Branch 1p 16446 399

B212160750 Notification of registration as user of Models HN-200 & HN-100 Series 3 in response to B21112 request
 MACDONALD, C E Transportation Branch 82/12/09 GRAVES, R H
 Connecticut Yankee Atomic Power Co 1p 16465 356

DOCKET 71-6601 MODEL CNS B-120, CHEM-NUCLEAR SYSTEMS, INC

B212130136 Notification of registration as user of Model CNS B-120 in response to B21022 request
 MACDONALD, C E Transportation Branch 82/11/18 WILLIAMSON, E D
 Knolls Atomic Power Laboratory 1p 16417 149

DOCKET 71-6717 MODEL 6717-B, QAMMA INDUSTRIES

B212130098 Notification of registration as user of Models 6717B, 20, 20A, 50, 50A, 100, 100A, 200, 200A & C-B, in response to B21007 request
 MACDONALD, C E Transportation Branch 82/11/18 BROTTON, O C
 Inspection Services Corp 1p 16417 255

B212100420 Notification of registration as user of Model 6717-B in response to B20923 request
 MACDONALD, C E Transportation Branch 82/11/23 CLARK, R L Clerk
 Inspection Service, Inc 1p 16389 060

B212160169 Notification of registration as user of Model 6717-B in response to B20927 request
 MACDONALD, C E Transportation Branch 82/11/30 BAKER, T
 International Technical Service 1p 16447 203

B212230001 Requests registration as user of Model 6717-B
 GORNES, J W Dayton Power & Light Co 82/12/10 MACDONALD, C E
 Transportation Branch 1p 16344 348

DOCKET 71-9001 MODEL IF-300, GENERAL ELECTRIC CO

B212150216 Suppl to application to amend Certificate of Compliance 9001, Revision 14, reinstating use of Model GE IF-300 for BWR fuel shipment, in response to B21029 request for addl info
 DAMSON, D M General Electric Uranium Management Corp 82/11/22
 MACDONALD, C E Transportation Branch 33pp 16447 026

B212140472 Requests registration as user of Model IF-300
 PILANT, J M Nebraska Public Power District 82/11/30
 MACDONALD, C E Transportation Branch 1p 16431 318

B212230018 Notification of registration as user of Model IF-300 in response to B21120 request
 MACDONALD, C E Transportation Branch 82/12/10 PILANT, J M
 Nebraska Public Power District 1p 16544 362

DOCKET 71-9006 MODEL 500-BU, AUTOMATION INDUSTRIES, INC

B212160012 Forwards Revision 3 to Certificate of Compliance 9006 for Model 500-BU
 MACDONALD, C E Transportation Branch 82/11/23 SANTORO, M P SRL,
 Autometrix 3pp 16447 276

--B212160016 Certificate of Compliance 9006, Revision 3, for Model 500-BU
 Approval record encl
 MACDONALD, C E Transportation Branch 82/11/23 3pp 16447 279

B212160361 Requests registration as user of Models 650 & 500-BU
 CASH, A Yuba Heat Transfer Corp 82/12/03 Transportation
 Branch 1p 16447 200

DOCKET 71-9010 MODEL NLI-1/2, NL INDUSTRIES, INC

B212130001 Notification of registration as user of Model NLI-1/2 in response to B21018 request
 MACDONALD, C E Transportation Branch 82/11/18 LENTINE, F G
 Commonwealth Edison Co 1p 16417 071

DOCKET 71-9015 MODEL TN-B, -BL, NO USERS

B212270069 Application for revision of Certificate of Compliance 9015 to delete initial fuel pin pressure at 100 F from B10707
 Revision 3 as content condition, to allow transport of PWR fuel w/higher initial pressures of helium
 GOLDMANN, K Transnuclear, Inc 82/12/03 MACDONALD, C E
 Transportation Branch 2pp 16553 129

--B212270071 Revision 0 to "TN-B & TN-9 SAR, Second Addendum for TN-B & TN-BL Packagings"
 * Transnuclear, Inc E-350B R00 82/12/03 16pp 16553 131

DOCKET 71-9032 MODEL 650, TECHNICAL OPERATIONS, INC

B212130116 Notification of registration as user of Models 650, 660 & 660E in response to B21029 request
 MACDONALD, C E Transportation Branch 82/11/18 GILBREATH, J H
 Pryor Foundry Inc. 1p 16417 151

DOCKETED ITEMS

8212160361 Requests registration as user of Models 650 & 800-SU
CASH, A Yuba Heat Transfer Corp 82/12/03 Transportation
Branch 1p 16447 200

DOCKET 71-9033 MODEL 660 & 660E, TECHNICAL OPERATIONS, INC

8212130116 Notification of registration as user of Models 650, 660 &
660E in response to 821029 request
MACDONALD, C E Transportation Branch 82/11/18. OILBREATH, J H
Pryor Foundry Inc 1p 16417 151

DOCKET 71-9044 MODEL GE-1600, GENERAL ELECTRIC CO

8212270479 Requests registration as user of Models B-2 & GE-1600
AYRES, J AWC, Inc 82/12/07 MACDONALD, C E Transportation
Branch 1p 16551 055

DOCKET 71-9073 MODEL OH-142, NUCLEAR PACKAGING, INC

8212270408 Application for renewal of Certificate of Compliance 9073
For Model OH-142
SIMCHUK, J D Nuclear Packaging, Inc. 82/10/20 MACDONALD, C E
Transportation Branch. 205pp 16572 125

8212270485 Requests addl info re 821020 consolidated application for
renewal of Certificate of Compliance 9073 For Model OH-142
Info should be submitted within 60 days
MACDONALD, C E Transportation Branch 82/12/16 SIMCHUK, J D
Nuclear Packaging, Inc 2pp. 16548 360

DOCKET 71-9079 MODEL HN-100, SERIES 2 & 2A, HITTMAN NUCLEAR

8212270377 Application for renewal of Certificate of Compliance 9079,
incorporating listed changes to SAR Renewal fee encl
SIMCHUK, J D. Nuclear Packaging, Inc 82/11/29. MACDONALD, C E.
Transportation Branch 2pp 16573 293

--8212270382 "Consolidated SAR for NUPAC 140-2 & Casts to 10CFR71 Type A
& Low Specific Activity Packaging Requirements"
* Nuclear Packaging, Inc 82/11/29 53pp 16573 295

8212160748 Advises that 821129 application for renewal of Certificate
of Compliance 9079 satisfies condition for timely renewal
Certificate will not expire until final determination made
by NRC
MACDONALD, C E Transportation Branch 82/12/09 SIMCHUK, J D
Nuclear Packaging, Inc. 3pp 16465 360

DOCKET 71-9081 MODEL CNS-1600, CHEM-NUCLEAR SYSTEMS, INC.

8212150202 Forwards response to 820917 ltr re Model CNS1 1-13C Review
& certification requested Revised pages to SAR encl
POPPEL, K Chem-Nuclear Systems, Inc 82/11/15 MACDONALD, C E
Transportation Branch 9pp 16447 049

--8212150206 "SAR for Model CNS 1-13C Package to 10CFR71 Type B
Packaging Requirements," Revision 1, Vol 1
* Chem-Nuclear Systems, Inc 82/11/15 48pp 16447 078

8212100425 Notification of registration as user of Model CNS-1600 in
response to 821026 request
MACDONALD, C E Transportation Branch 82/11/30 AUSTON, M A
Babcock & Wilcox Co 1p 16389.097

DOCKET 71-9086 MODEL HN-100, SERIES 1, HITTMAN NUCLEAR & DEV. CORP

8212140505 Forwards request for addl info re 820723 application for
renewal of Certificate of Compliance 9086 for Model HN-100,
Series 1
MACDONALD, C E Transportation Branch 82/11/29 MALLORY, C W
Hittman Nuclear & Development Corp (subs Hittman Corp) 2pp
16431 331

DOCKET 71-9089 MODEL HN-100B, HITTMAN NUCLEAR & DEVELOP. CORP.

8212130004 Notification of registration as user of Models HN-100B &
HN-100 Series 3 in response to 821015 request.
MACDONALD, C E. Transportation Branch 82/11/30 KENYON, B D.
Pennsylvania Power & Light Co 1p. 16417 070

DOCKET 71-9094 MODEL CNS 14-195-H, CHEM-NUCLEAR SYSTEMS, INC

8212130141 Notification of registration as user of Model CNS 14-195-H
in response to 821013 request
MACDONALD, C E Transportation Branch 82/11/18 LUNDVALL, A E
Baltimore Gas & Electric Co 1p 16410 357

DOCKET 71-9096 MODEL CNS 21-300, CHEM-NUCLEAR SYSTEMS, INC

8212230037 Requests registration as user of Model CNS 21-300
SMEDIRA, C Neutron Products, Inc 82/12/09 MACDONALD, C E
Transportation Branch 1p 16544 268

DOCKET 71-9099 MODEL ATR, EXXON NUCLEAR IDAHO CO

8212160032 Forwards Revision 2 to Certificate of Compliance 9099 for
Model ATR
MACDONALD, C E Transportation Branch 82/11/23 WILLIAMS, C F
Energy, Dept of 2pp 16447 267

--8212160035 Certificate of Compliance 9099, Revision 2, for Model ATR
Approval record encl
MACDONALD, C E Transportation Branch 82/11/23 3pp 16447 269

DOCKET 71-9111 MODEL CNS 6-B0-2, CHEM-NUCLEAR SYSTEMS, INC

8212130107 Notification of registration as user of Model CNS0-B0-2
in response to 821026 request
MACDONALD, C E Transportation Branch 82/11/18 MATHIS, C J
Boston Edison Co 1p 16417 256

DOCKET 71-9126 MODEL 20, 20A, 50, 50A, GAMMA INDUSTRIES

8212130098 Notification of registration as user of Models 671B, 20,
20A, 50, 50A, 100, 100A, 200, 200A & C-B, in response to 821007
request
MACDONALD, C E Transportation Branch 82/11/18 BROTTON, G C
Inspection Services Corp 1p 16417 255

DOCKET 71-9127 MODEL 100, 100A, 200, 200A, GAMMA INDUSTRIES

8212130098 Notification of registration as user of Models 671B, 20,
20A, 50, 50A, 100, 100A, 200, 200A & C-B, in response to 821007
request
MACDONALD, C E Transportation Branch 82/11/18 BROTTON, G C
Inspection Services Corp 1p 16417 255

DOCKET 71-9128 MODEL C-B, GAMMA INDUSTRIES

8212130098 Notification of registration as user of Models 671B, 20,
20A, 50, 50A, 100, 100A, 200, 200A & C-B, in response to 821007
request
MACDONALD, C E Transportation Branch 82/11/18 BROTTON, G C
Inspection Services Corp 1p 16417 255

DOCKET 71-9132 MODEL T-3, ENERGY, DEPT OF

8212160437 Forwards revision to SAR for Certificate of Compliance 9132,
Model T-3
FRICHARD, R P Energy, Dept of 82/11/30 MACDONALD, C E
Transportation Branch 1p 16447; 183

--8212160438 Forwards Page 7-5, revision to Model T-3 SAR
* Energy, Dept of 82/11/10 MACDONALD, C E Transportation
Branch 3pp 16447 184

8212170005 Forwards Revision 4 to Certificate of Compliance 9132 for
Model T-3
MACDONALD, C E Transportation Branch. 82/12/09 PETERSON, J M
Energy, Dept of 2pp 16480 288

--8212170010 Certificate of Compliance 9132, Revision 4, for Model T-3,
MACDONALD, C E Transportation Branch 82/12/09 5pp 16480 290

DOCKET 71-9150 MODEL PAT-2, ENERGY, DEPT OF

8212140502 Confirms that no action will be taken on 820818 request for mod to Certificate of Compliance 9150 for Model PAT-2 Meeting to discuss scope & content of revised application will be held on 030113 in Silver Spring, MD
MACDONALD, C E Transportation Branch 82/11/30 CAUDLE, R E Energy, Dept of 3pp 16431 333

DOCKET 71-9151 MODEL HN-100, SERIES 3, HITTMAN NUCLEAR & DEV CORP

8212150270 Requests registration as user of Model HN-100, Series 3 FIEDLER, P B General Public Utilities - GPU Service Corp 82/11/10 Division of Fuel Cycle & Material Safety 1p 16446 282

8212140407 Forwards revised amend request to Certificate of Compliance 9151 re Model HN-100 Series 3
POFFE, L K Chem-Nuclear Systems, Inc 82/11/16 MACDONALD, C E Transportation Branch 1p 16447 192

--8212160418 Revised amend to Certificate of Compliance 9151, "Optional Configuration Request," re Model HN-100 Series 3
* Chem-Nuclear Systems, Inc 82/11/16 5pp 16447 193

8212150282 Advises that response to 821018 request for info will be submitted by 821130 Application revised per 821112 meeting, to continue operation at package weight specified in Certificate of Compliance 9079
MALLORY, C W Hittman Nuclear & Development Corp (subs Hittman Corp.) 82/11/17 MACDONALD, C Transportation Branch 1p 16437 361

8212130134 Notification of registration as user of Model HN-100 Series 3 in response to 821103 request
MACDONALD, C E Transportation Branch 82/11/18 GARRITY, J H Maine Yankee Atomic Power Co 1p 16417 190

8212130142 Notification of registration as user of Model HN-100 Series 3 in response to 821103 request
MACDONALD, C E Transportation Branch 82/11/18 HUNTER, R B Indiana & Michigan Power Co 1p 16418 006

8212130055 Forwards addl info requested by NRC 821018 ltr re 820715 application for certification of HN-100 Series 2 casks as HNDC HN-100 Series 3A casks
MALLORY, C W Hittman Corp 82/11/23 MACDONALD, C Transportation Branch 8pp 16418 030

--8212130061 "Addendum to BAR for HN-100 Series 3A Redwaste Shipping Cask"
* Hittman Corp STD-R-02-004 82/11/23 86pp 16418 038

8212290088 Advises that encl 820812 application for amend of Certificate of Compliance 9151 & two oversize drawings marked "proprietary" should be placed in PDR
MACDONALD, C E Transportation Branch 82/11/24 SCOTT, S Document Management Branch 1p 16606 279

8212130004 Notification of registration as user of Models HN-100S & HN-100 Series 3 in response to 821015 request
MACDONALD, C E Transportation Branch 82/11/30 KENYON, B D Pennsylvania Power & Light Co 1p 16417 070

8212170002 Notification of registration as user of Model HN-100 Series 3 in response to 821110 request
MACDONALD, C E Transportation Branch 82/12/07 FIEDLER, P B General Public Utilities - GPU Service Corp 1p 16480 333

8212160750 Notification of registration as user of Models HN-200 & HN-100 Series 3 in response to 821112 request
MACDONALD, C E Transportation Branch 82/12/09 GRAVES, R H Connecticut Yankee Atomic Power Co 1p 16465 356

8212160760 Notification of registration as user of Model HN-100 Series 3 in response to 821012 request
MACDONALD, C E Transportation Branch 82/12/09 SELLERS, D Maine Yankee Atomic Power Co 1p 16465 394

DOCKET 71-9156 MODEL IR-50, INDUSTRIAL NUCLEAR CO

8212130089 Notification of registration as user of Models IR-100 & IR-50 in response to 821012 request
MACDONALD, C E Transportation Branch 82/11/18 RICHARDSON, H D Nuclear System 1p 16416 005

8212130082 Notification of registration as user of Models IR-100 & IR-50 in response to 821012 request
MACDONALD, C E Transportation Branch 82/11/22 Nuclear System 1p 16417 252

DOCKET 71-9157 MODEL IR-100, INDUSTRIAL NUCLEAR CO

8212130089 Notification of registration as user of Models IR-100 & IR-50 in response to 821012 request
MACDONALD, C E Transportation Branch 82/11/18 RICHARDSON, H D Nuclear System 1p 16416 005

8212130082 Notification of registration as user of Models IR-100 & IR-50 in response to 821012 request
MACDONALD, C E Transportation Branch 82/11/22 Nuclear System 1p 16417 252

DOCKET 71-9167 MODEL TYPE B, AMERSHAM CORP

8212150230 Advises that responses to NRC 821029 inquiries & revised pages to application will be provided by 821203
BAOBY, L A Amersham Corp 82/11/23 MACDONALD, C Transportation Branch, 1p 16446 360

DOCKET 71-9852 MODEL DT-14, ENERGY, DEPT OF

8212280020 Forwards Revision O to Certificate of Compliance 9852 for Model DT-14
MACDONALD, C E Transportation Branch 82/12/20 PRICHARD, R P Energy, Dept of 1p 16593 114

--8212280021 Certificate of Compliance 9852, Revision O, for Model DT-14
MACDONALD, C E Transportation Branch 82/12/20 5pp 16593 115

LICENSING OF INDEPENDENT SPENT FUEL STORAGE

DOCKET 72-0001 MORRIS OPERATIONS, GENERAL ELECTRIC CO

8212130148 Notification of 821116 meeting w/9E in Silver Spring, MD to discuss potential changes, tests & experiments re thermal & dosimetry measurements involving Ridhalgh, Eggers & Assoc dry spent fuel cask
ROBERTS, J P Advanced Fuel & Spent Fuel Licensing Branch 82/11/18 ROUSE, L C Advanced Fuel & Spent Fuel Licensing Branch 2pp 16410 285

DOCKET 72-0002 VIRGINIA ELECTRIC & POWER CO

8212220170 Advises that application for dry cask IBSI docketed on 821015 Application evaluated for completeness & acceptability Details of cask must be provided to NH Division before licensing action can be completed
ROUSE, L C Advanced Fuel & Spent Fuel Licensing Branch 82/12/03 LEABURG, R H Virginia Electric & Power Co 2pp 16523 361 24X Fiche 50-280, 82/12/03, 8212220170

8212220005 Forwards notice of consideration of matl license for storage of spent fuel transmitted to OFC of FR for publication
ROUSE, L C Advanced Fuel & Spent Fuel Licensing Branch 82/12/06 LEABURG, R H Virginia Electric & Power Co 2pp 16529 144 24X Fiche 50-280, 82/12/06, 8212220005

--8212220007 Notice of consideration of matl license for storage of spent fuel
ROUSE, L C Advanced Fuel & Spent Fuel Licensing Branch 82/12/03 4pp 16529 146 24X Fiche 50-280, 82/12/06, 8212220005

8212230147 Notice of correction of typographical error in 821209 FR notice re consideration of matl license for storage of spent fuel
ROUSE, L C Advanced Fuel & Spent Fuel Licensing Branch 82/12/10 2pp 16544 056 24X Fiche 50-280, 82/12/10, 8212230147

NONDOCKETED ITEMS

10CFR COMMISSION MEETING RECORDS

8212010078 Unofficial transcript of Commission 821119 meeting in Washington, DC re briefing on hydrogen control program
Pp 1-83 Viewgraphs encl
* Commissioners 82/11/19 110pp 16290 001

8212010518 Staff requirements memo re Commission 821122 briefing in Washington, DC on draft rept on legislative reform Ref to "Meaning of Adequate Protection to Public Health & Safety" requested
CHILK, S J Office of the Secretary of the Commission 8211122A
82/11/24. TOURTELLOTTE Regulatory Reform Task Force BICKWIT, L
Office of the General Counsel 1p 16270 263

8212010522 Staff requirements memo re Commission 821118 meeting w/DQE, EPA & Natl Academy of Sciences in Washington, DC on proposed technical rule for disposal of high level radwaste in geological repositories, SECY-82-427
CHILK, S J Office of the Secretary of the Commission 821118B
82/11/24 DIRCKS, W J Office of the Executive Director for Operations 2pp 16270 264

8212010530 Staff requirements memo re Commissioners 821123 affirmation/discussion & vote in Washington, DC on SECY-82-449 & SECY-82-425 Petition to disqualify NRC atty from Zimmer proceeding denied
CHILK, S J Office of the Secretary of the Commission ALAB-686
82/11/24 Office of the Secretary of the Commission 2pp
16270 268

8212020008 Addl response to FOIA request for documents re final rule on environ qualification Forwards App A Documents 12, 23, 28, 35, 41, 43, 53, 65, 66, 70 & 73. Document 65 listed incorrectly info completely & partially withheld (ref FOIA Exemption 5)
FELTON, J M Division of Rules and Records, 82/11/08 CURRAN, D
Harmon & Weiss 7pp 16297 112

--8212020067 Discusses Commission 820601 briefing on proposed final rule re environ qualification of electrical equipment
CHILK, S J Office of the Secretary of the Commission 82/06/10
Office of the Secretary of the Commission, 1p 16297 291

8212020223 Unofficial transcript of 821119 public meeting in Washington, DC re NRC actions w/respect to recent USGS position Pp 1-49
* Commissioners 82/11/19 53pp 16308 201

8212030277 Unofficial transcript of 821201 briefing in Washington, DC on pressurized thermal shock Pp 1-86 Viewgraphs encl
* Commissioners 82/12/01 135pp 16317 096

8212100035 Unofficial transcript of 821207 public meeting in Washington, DC re briefing of Regulatory Reform Task Force Pp 1-100
* Commissioners 82/12/07 104pp 16399 238

8212130407 Unofficial transcript of Commission 821209 meeting in Washington, DC re discussion/possible vote on pressurized thermal shock actions Pp 1-71.
* Commissioners 82/12/09 72pp 16413 160

8212220003 Staff requirements memo re 821119 briefing on USGS clarification of seismic issues No requests made or requirements placed on staff
CHILK, S J Office of the Secretary of the Commission 821119C
82/11/24 Office of the Secretary of the Commission 1p
16529-150

8212230393 Unofficial transcript of Commission 821214 meeting in Washington, DC re briefing on human factors program plan Pp 1-11 Viewgraphs encl.
* Commissioners. 82/12/14 146pp 16544 113

8212270030 Staff requirements memo re 821122 open discussion of draft policy & planning guidance for FY83 Revised document requested for 821207 meeting
CHILK, S J Office of the Secretary of the Commission 821122B
82/11/24 ZERBE, J E Office of Policy Evaluations 1p 16551 349

8212270562 Unofficial transcript of Regulatory Reform Task Force 821220 briefing in Washington, DC re legislative proposals Pp 1-88
* Commissioners 82/12/20 92pp 16550 234

8212290294 Unofficial transcript of Commission 821216 briefing by Ad Hoc Committee on Regulatory Reform in Washington, DC Pp 1-106. Supporting documentation encl
* Commissioners 82/12/16 142pp 16606 107

8212300131 Staff requirements memo re briefing on human factors program plan outlined in SECY-82-462 Addl meeting should be scheduled to complete NRR briefing & allow Ofc of Policy Evaluation to comment
CHILK, S J Office of the Secretary of the Commission 821214
82/12/23 DIRCKS, W J Office of the Executive Director for Operations 1p 16624 185

8212300157 Staff requirements memo re status of 821104 staff requirements memo on installation of inadequate core cooling instrumentation sys (SECY-82-407) & 821215 daily staff notes info provided on 821220
CHILK, S J Office of the Secretary of the Commission 821216D
82/12/22 Office of the Secretary of the Commission 1p
16624 181

ACRS ADVISORY COMMITTEE ON REACTOR SAFEGUARDS

8208290027 Comments on draft rept on pressurized thermal shock, w/ special attention to Sections 4.5.9 & 10 Conclusions are conservative
GALL, W R Gall, W R GALL, W R ACRS - Advisory Committee on Reactor Safeguards 82/09/28 BENDER, M ACRS - Advisory Committee on Reactor Safeguards 2pp 16267 328

8208290028 Comments on B&W primary sys & steam generator modeling for accident analysis re ECCS Subcommittee 820928 meeting
Verification of vendor models using integral facility recommended Semiscale facility will supply sufficient data
CATTON, I ACRS - Advisory Committee on Reactor Safeguards 82/09/30 BDEHNERT, P NRC - No Detailed Affiliation Given 1p
16267 327

8208290029 Comments on "Integrated Human Factors Program Plan" Agrees w/remarks found in project status rept Program elements reasonably titled Needs & reasons must be stated in plan
CATTON, I California, Univ of Los Angeles CATTON, I ACRS - Advisory Committee on Reactor Safeguards 82/09/20 FISCHER, D ACRS - Advisory Committee on Reactor Safeguards 5pp 16267 322

8208290030 Comments on ACRS Subcommittee on Human Factors 820907 meeting re integrated human factors program plan
KEYSERLING, W. ACRS - Advisory Committee on Reactor Safeguards 82/09/13 WARD, D ACRS - Advisory Committee on Reactor Safeguards 3pp. 16267 330

8208290032 Discusses ACRS 820930 meeting re pressurized thermal shock Appropriate framework needed to establish real margins & limits "PWR Downcomer Fluid Temp Transients Due to High Pressure Injection at Stagnated Loop Flow," encl
THEOFANOUS, T O Purdue Univ. THEOFANOUS, T O ACRS - Advisory Committee on Reactor Safeguards 82/10/04 IGNE, E ACRS - Advisory Committee on Reactor Safeguards 2pp 16267 174

--8212010428 "PWR Downcomer Fluid Temp Transients Due to High Pressure Injection at Stagnated Loop Flow," presented at 820914-15 joint NRC/ANS meeting in Bethesda, MD
THEOFANOUS, T O, NOURBAKHSH, H P Purdue Univ 82/09/15 31pp
16267 178

NONDOCKETED ITEMS

B212010362 Summary of ACRS Subcommittee on Safety Research Program B20811 meeting in Washington, DC re Format & content of proposed long-range research plan Viewgraphs encl
* ACRS - Advisory Committee on Reactor Safeguards 82/10/02
ACRS - Advisory Committee on Reactor Safeguards 18pp 16271 188

B212010365 Summary of ACRS ECCS Subcommittee B20928 meeting w/B&W owners group in Washington, DC re modeling of small break LOCA for B&W plants, reactor coolant pump trip status, results of recent semiscale tests & status of MDD-5 proposal
* ACRS - Advisory Committee on Reactor Safeguards 82/10/08
ACRS - Advisory Committee on Reactor Safeguards 12pp 16271 101

B212020041 Summary of ACRS Subcommittee on Regulatory Activities B20908 meeting in Washington, DC re proposed Revision 1 to Reg Guide 1.145, "Atmospheric Dispersion Models for Potential Accident Consequence Assessments at Nuclear Power Plants"
* ACRS - Advisory Committee on Reactor Safeguards 82/10/07
ACRS - Advisory Committee on Reactor Safeguards 12pp 16310 346

B212020046 Summary of ACRS Subcommittee on Transportation of Radioactive Materials B20824 meeting in Washington, DC re adequacy of activities of Transportation Certification Branch of NRC
* ACRS - Advisory Committee on Reactor Safeguards 82/10/07
ACRS - Advisory Committee on Reactor Safeguards 10pp 16317 063

B212020048 Explores & quantifies some fundamentals of problem re flow blockage by steam during natural circulation in PWRs
ETHERINGTON, M. H. ACRS - Advisory Committee on Reactor Safeguards 82/09/07
SHEWMON, P. O. ACRS - Advisory Committee on Reactor Safeguards 13pp 16317 050

B212020406 Submits comments from 271st ACRS meeting on B21104-05 re NRC integrated human factors program plan Redrafted plan improved & responsive to concerns expressed in R Fraley B20914 memo
SHEWMON, P. ACRS - Advisory Committee on Reactor Safeguards 82/11/09
DIRCKS, W. J. Office of the Executive Director for Operations 2pp 16297 349

B212030280 Discusses options available to ATWS subcommittee for establishment of ATWS rule
EPLER, E. P. Epler, E. P. EPLER, E. P. ACRS - Advisory Committee on Reactor Safeguards 82/10/21
ACRS - Advisory Committee on Reactor Safeguards 5pp 16317 359

B212060153 Summary of 263rd ACRS meeting on B20304-06 in Washington, DC
* ACRS - Advisory Committee on Reactor Safeguards 82/03/06
ACRS - Advisory Committee on Reactor Safeguards 434pp 16324 001

B212060162 Transcript of ACRS Subcommittee on Metal Components B21202 public meeting in Washington, DC Summary of EPRI work on improved stainless steel pipe & pressure vessel insp & viewgraphs encl
* ACRS - Advisory Committee on Reactor Safeguards 82/12/02
388pp 16315 027

B212060328 Discusses primary sys failure mechanism during high pressure transient
CATTON, I. ACRS - Advisory Committee on Reactor Safeguards 82/10/25
SHEWMON, P., KERR, W. ACRS - Advisory Committee on Reactor Safeguards 1p 16323 350

B212060325 Discusses util group ATWS proposal for ATWS subcommittee
EPLER, E. P. Epler, E. P. EPLER, E. P. ACRS - Advisory Committee on Reactor Safeguards 82/10/23
KERR, W. ACRS - Advisory Committee on Reactor Safeguards 6pp 16322 347

B212060399 Comments on ACRS Subcommittee on ATWS B21022 meeting PRA discussions not convincing Data on scram failure poor Existence of inoperable state of scram sys may not be evident until tested or need arises for operation
DITTO, S. J. Ditto, S. J. 82/10/26
BOEHMERT, P. ACRS - Advisory Committee on Reactor Safeguards 3pp 16322 337

B212060514 Comments on ACRS ATWS Subcommittee B21022 meeting PRA & util group value impact analysis make positive contribution toward resolution of ATWS issue
LEE, J. C. Michigan, Univ. of LEE, J. C. ACRS - Advisory Committee on Reactor Safeguards 82/10/26
BOEHMERT, P. A. ACRS - Advisory Committee on Reactor Safeguards 3pp 16344 013

B212070431 Comments on ACRS ATWS Subcommittee B21022 meeting ATWS issue should be closed within reasonable period of time at least expense possible
MUELLER, C. J. Argonne National Laboratory MUELLER, C. J. ACRS - Advisory Committee on Reactor Safeguards 82/10/25
KERR, W., BOEHMERT, P. ACRS - Advisory Committee on Reactor Safeguards 4pp 16355-332

B212070438 Discusses design margins of Class 1E electrical sys above SSE for plants under SEP & near-term OLS Analysis should be conducted to determine whether non-Class 1E loads should be automatically disconnected
LIPINSKI, W. C. Argonne National Laboratory LIPINSKI, W. C. ACRS - Advisory Committee on Reactor Safeguards 82/10/15
OKRENT, D. ACRS - Advisory Committee on Reactor Safeguards 3pp 16355 337

B212070440 Summary of B20914-15 joint NRC/ANS meeting in Bethesda, MD re basic thermal hydraulic mechanisms in LWR analysis
CATTON, I. ACRS - Advisory Committee on Reactor Safeguards 82/10/25
BOEHMERT, P. ACRS - Advisory Committee on Reactor Safeguards 5pp 16355 340

B212090076 Transcript of ACRS Subcommittee on Regulatory Policy & Procedures B21207 meeting in Washington, DC Pp 1-144 Supporting documentation encl
* ACRS - Advisory Committee on Reactor Safeguards 82/12/07
167pp 16357 001

B212100001 Transcript of ACRS Subcommittee on Generic Items B21208 meeting in Washington, DC re prioritization of generic safety issues Pp 1-79
* ACRS - Advisory Committee on Reactor Safeguards 82/12/08
117pp 16377 153

B212100017 Transcript of ACRS Subcommittee on Safety Research Program B21208 meeting in Washington, DC Pp 1-239 Viewgraphs encl
* ACRS - Advisory Committee on Reactor Safeguards 82/12/08
330pp 16373 001

B212100018 Transcript of ACRS Subcommittee on Advanced Reactors B21208 meeting in Washington, DC Pp 1-104
* ACRS - Advisory Committee on Reactor Safeguards 82/12/08
123pp 16375 042

B212100022 Transcript of ACRS Subcommittee on ECCS B21202 meeting in San Jose, CA Pp 1-246 Supporting documentation encl
* ACRS - Advisory Committee on Reactor Safeguards 82/12/02
401pp 16374 001

B212130040 Transcript of 272nd ACRS general meeting on B21209 in Washington, DC Pp 1-285 Supporting documentation encl
* ACRS - Advisory Committee on Reactor Safeguards 82/12/09
499pp 16392 018

B212130045 Transcript of ACRS Subcommittee on ECCS B21203 meeting in San Jose, CA Pp 247-414 Viewgraphs encl
* ACRS - Advisory Committee on Reactor Safeguards 82/12/03
319pp 16390 205

B212130043 Transcript of 272nd ACRS general meeting on B21210 in Washington, DC Pp 286-592 Supporting documentation encl
* ACRS - Advisory Committee on Reactor Safeguards 82/12/10
511pp 16423 269

B212210277 Transcript of ACRS Subcommittees on Reliability & Probabilistic Assessment & Extreme External Phenomena B21215 meeting in Washington, DC Pp 1-94 Supporting documentation encl
* ACRS - Advisory Committee on Reactor Safeguards 82/12/15
176pp 16483 047

B212230284 Transcript of ACRS Subcommittee on Class 7 Accidents B21221 meeting in Washington, DC Pp 1-250 Viewgraphs encl
* ACRS - Advisory Committee on Reactor Safeguards 82/12/21
340pp 16508 299

B212280429 Transcript of ACRS Subcommittee on Electrical Sys B21222 meeting in Washington, DC Pp 1-202 Viewgraphs encl
* ACRS - Advisory Committee on Reactor Safeguards 82/12/22
284pp 16559 097

COMMISSION NRC COMMISSIONERS

B212060470 Responds to B21004 1tr re draft "NRC Staff Evaluation of Pressurized Thermal Shock," & draft ORNL rept, "Pressure Vessel Thermal Shock at US PWRs: Events & Precursors, 1963-Mid-1981." Comments will be considered
PALLADINO, N. J. Commissioners 82/11/23
MARKEY, E. J. House of Rep 3pp 16343 301

--B209150008 Expresses disappointment at failure to inform of NRC draft evaluation & ORNL precursor rept re nuclear reactor pressure vessel thermal shock Concerned w/degree reactor vessels of operating PWRs have become vulnerable to cracking
MARKEY, E. J. House of Rep, Interior & Insular Affairs 82/10/04
PALLADINO, N. Commissioners 4pp 16343 304

B212070090 Responds to B20813 ltr re policies & practices for conduct of investigation, specifically solicitation of public comments prior to policy adoption. Most policies & procedures inappropriate for public comment.
PALLADINO, N J Commissioners 82/11/23 CHARNOFF, G , HICKEY, J P Shaw, Pittman, Potts & Trowbridge 1p 16354 310

--B212070096 Requests public comments solicited for proposed policies of investigations.
CHARNOFF, G , HICKEY, J P Shaw, Pittman, Potts & Trowbridge 82/08/13 PALLADINO, N J Commissioners 7pp 16354 311

B212070342 Informs of redirection of LOFT program. Sufficient financial support available for DOE to proceed w/formation of intl LOFT consortium. Forwards NRC/DOE interagency agreement on LOFT program responsibility.
PALLADINO, N J Commissioners 82/11/22 BEVILL, T House of Rep , Appropriations 1p 16356 247

--B212070351 Informs of redirection of LOFT program. Sufficient financial support available for DOE to proceed w/formation of intl LOFT consortium. Forwards NRC/DOE interagency agreement on LOFT program responsibility.
PALLADINO, N J Commissioners 82/11/22 UDALL, M House of Rep , Interior & Insular Affairs 1p 16356 248

--B212070359 Informs of redirection of LOFT program. Sufficient financial support available for DOE to proceed w/formation of intl LOFT consortium. Forwards NRC/DOE interagency agreement on LOFT program responsibility.
PALLADINO, N J Commissioners 82/11/22 SIMPSON, A Senate, Environment & Public Works 1p 16356 249

--B212070368 Informs of redirection of LOFT program. Sufficient financial support available for DOE to proceed w/formation of intl LOFT consortium. Forwards NRC/DOE interagency agreement on LOFT program responsibility.
PALLADINO, N J Commissioners 82/11/22 HATFIELD, M O Senate, Appropriations 1p 16356 250

--B212070372 Informs of redirection of LOFT program. Sufficient financial support available for DOE to proceed w/formation of intl LOFT consortium. Forwards NRC/DOE interagency agreement on LOFT program responsibility.
PALLADINO, N J Commissioners 82/11/22 OTTINGER, R L House of Rep , Energy & Commerce 1p 16356 251

--B212070378 Interagency agreement re LOFT program responsibility between NRC & DOE. Responsibilities & obligations of parties for operation of LOFT facility delineated.
DIRCKS, W J Office of the Executive Director for Operations BREWER, S T Energy, Dept of 82/11/22 2pp 16356 252

B212070385 Informs that B21020 meeting to discuss QA & to provide informal feedback on initiatives being implemented helpful. Initiative in providing comments commendable & appreciated.
PALLADINO, N J Commissioners 82/11/22 JACKSON, J P Management Analysis Co 1p 16355 255

--B208290147 Forwards comments re specific implementation of QA organization for NRC per Dircks B20820 memo to Commissioners.
JACKSON, J P Management Analysis Co 82/09/21 PALLADINO, N J Commissioners 7pp 16355 256

B212080005 Forwards FR notice of proposed rule recommending 5-yr reporting period to replace annual reporting for licensees distributing radioactive consumer products.
PALLADINO, N J Commissioners 82/11/23 COELHO, T House of Rep 1p 16368 306

--B212080009 Notice of proposed rule modifying reporting requirements for licensees distributing consumer products w/small quantities of radioactive matl.
HOYLE, J C Office of the Secretary of the Commission 82/11/17 15pp 16368 307

B212080023 Forwards rept of nondisclosure of safeguards info for quarter ending B20930 w/o encl.
PALLADINO, N J Commissioners 82/11/19 O'NEILL, T P House of Rep , Speaker of the House, 1p 16367 155

--B212080025 Forwards rept of nondisclosure of safeguards info for quarter ending B20930.
PALLADINO, N J Commissioners 82/11/19 BUSH, O H W Senate, President of the Senate 8pp 16367 156

B212130334 Weekly info rept for wk ending 821203.
REHM, T A Office of the Executive Director for Operations 82/12/09 44pp 16412 318

B212160634 Responds to RE Dickenson B21007 request for info re NRC involvement in archeological data recovery & survey activities for FY81-82. List of 1981-82 archeological activities & titles of survey reports encl.
DENTON, H R Office of Nuclear Reactor Regulation, Director 82/12/08 ATEN, L Interior, Dept of, National Park Service 9pp 16466 023

--B212160643 Forwards questionnaires per annual rept to Congress on scope, effectiveness, cost & results of Federal archeological survey & data recovery program. Return requested by B21130.
DICKENSON, R E Interior, Dept of, National Park Service 82/10/07 PALLADINO, N J Commissioners 5pp 16466 032

B212220512 Weekly info rept for wk ending 821210.
REHM, T A Office of the Executive Director for Operations 82/12/16 32pp 16523 053

B212220555 Discusses M Holt B21122 ltr to R Ansdan re LERs from nuclear power plants. All LERs from nuclear power plants made public. None withheld or classified. LERs containing security-related info are public w/proprietary info deleted.
DIRCKS, W J Office of the Executive Director for Operations 82/12/14 COHEN, W S Senate 2pp 16523 030

--B212220558 Requests info in response to encl constituent M Holt B21122 ltr re LERs filed w/NRC.
ANSDEN, R L Senate 82/11/23 DIRCKS, W J Office of the Executive Director for Operations 3pp 16523 032

B212290521 Weekly info rept for wk ending 821217.
REHM, T A Office of the Executive Director for Operations 82/12/27 38pp 16605 114

CONTRACT NRC CONTRACTS AND MODIFICATIONS

B212010381 Notification of contract execution, Mod 1 to "Maint & Operation of Local Public Document Rooms (LPDRs) " Contractor Univ of Toledo William Carlsson Library.
LITTLE, M Administrative Contracts Branch NRC-10-82-410 82/11/23 FELTON, J M Division of Rules and Records SOUNDER, J NRC - No Detailed Affiliation Given 1p 16271 092

--B212010383 Mod 1, adding govt-furnished microfiche filing cabinet, to "Maint & Operation of Local Public Document Rooms (LPDRs) " * Toledo, Univ of REBELLO, J E Division of Contracts NRC-10-82-410 82/11/23 1p 16271 093

B212010388 Notification of contract execution, Mod 2 to "Maint & Operation of Local Public Document Rooms (LPDRs) " Contractor QA Dow Memorial Library, Midland MI.
LITTLE, M Administrative Contracts Branch NRC-10-81-691 82/11/23 FELTON, J M Division of Rules and Records SOUNDER, J NRC - No Detailed Affiliation Given 1p 16271 085

--B212010391 Mod 2, adding four-drawer ltr-size cabinet, to "Maint & Operation of Local Public Document Rooms (LPDRs) " * Midland County, MI REBELLO, J E Division of Contracts NRC-10-81-691 82/11/23 1p 16271 086

B212010395 Notification of contract execution, Mod 2 to "Maint & Operation of Local Public Document Rooms (LPDRs) " Contractor Minneapolis, MN Public Library & Info Ctr.
LITTLE, M Administrative Contracts Branch NRC-10-81-696 82/11/23 FELTON, J M Division of Rules and Records SOUNDER, J NRC - No Detailed Affiliation Given 1p 16271 083

--B212010398 Mod 2, adding four-drawer ltr-size cabinet, to "Maint & Operation of Local Public Document Rooms (LPDRs) " SHANNON, Z Minneapolis, MN REBELLO, J E Division of Contracts NRC-10-81-696 82/11/23 1p 16271 084

B212010403 Notification of contract execution, Mod 2 to "Maint & Operation of Local Public Document Rooms (LPDRs) " Contractor Crystal River, FL Public Library.
LITTLE, M Administrative Contracts Branch NRC-10-81-694 82/11/23 FELTON, J M Division of Rules and Records SOUNDER, J NRC - No Detailed Affiliation Given 1p 16271 078

--B212010406 Mod 2, adding four-drawer ltr-size cabinet, to "Maint & Operation of Local Public Document Rooms (LPDRs) " * Crystal River, FL REBELLO, J E Division of Contracts NRC-10-81-694 82/11/23 1p 16271 079

B212010419 Notification of contract execution, Mod 2 to "Maint & Operation of Local Public Document Rooms (LPDRs) " Contractor AR Tech Univ Library.
LITTLE, M Administrative Contracts Branch NRC-10-81-405 82/11/23 FELTON, J M Division of Rules and Records SOUNDER, J NRC - No Detailed Affiliation Given 1p 16267 339

NONDOCKETED ITEMS

--B212010423 Mod 2, adding govt-furnished microfiche cabinet, to "Maint & Operation of Local Public Document Rooms (LPDRs) " * Arkansas Tech Univ REBELLO, J E Division of Contracts NRC-10-81-409 82/11/23 1p 16267 340

B212010425 Notification of contract execution, Mod 2 to "Maint & Operation of Local Public Document Rooms (LPDRs) " Contractor Morris, IL Public Library LITTLE, M Division of Contracts NRC-10-81-407 82/11/23 FELTON, J M Division of Rules and Records SQUDER, J NRC - No Detailed Affiliation Given 1p 16267 337

--B212010430 Mod 2, adding govt-furnished microfiche cabinet, to "Maint & Operation of Local Public Document Rooms (LPDRs) " * Morris, IL REBELLO, J E Division of Contracts NRC-10-81-407 82/11/23 1p 16267 338

B212010432 Notification of contract execution, Mod 2 to "Maint & Operation of Local Public Document Rooms (LPDRs) " Contractor Oconee County, SC Library LITTLE, M Administrative Contracts Branch NRC-10-81-381 82/11/23 FELTON, J M Division of Rules and Records SQUDER, J NRC - No Detailed Affiliation Given 1p 16267 333

--B212010434 Mod 2, adding govt-furnished microfiche cabinet, to "Maint & Operation of Local Public Document Rooms (LPDRs) " * Oconee County, SC REBELLO, J E Division of Contracts NRC-10-81-381 82/11/23 1p 16267 334

B212010433 Notification of contract execution, Mod 1 to "Maint & Operation of Local Public Document Rooms (LPDRs) " Contractor Charlevoix, MI Public Library LITTLE, M Purchasing Section NRC-10-82-699 82/11/23 FELTON, J M Division of Rules and Records SQUDER, J NRC - No Detailed Affiliation Given 1p 16267 335

--B212010438 Mod 1, adding govt-furnished microfiche filing cabinet, to "Maint & Operation of Local Public Document Rooms (LPDRs) " * Charlevoix, MI REBELLO, J E Division of Contracts NRC-10-82-699 82/11/23 1p 16267 336

B212020189 Notification of contract execution, Mod 6 to "In-Process Control of SNM " Contractor Science Applications, Inc FIELDS, J A Technical Assistance Contracts Branch NRC-02-81-040 82/10/29 DAVIS, J G Office of Nuclear Material Safety & Safeguards, Director MENDELSON, B NRC - No Detailed Affiliation Given 1p 16308 259

--B212020194 Mod 6, modifying due date for submittal of revised interim rept. to "In-Process Control of SNM " HAGAN, T F Science Applications, Inc MCDONALD, R J Division of Contracts NRC-02-81-040 82/10/29 1p 16308 260

B212020387 Notification of contract execution, Mod 6 to "Cyprus Mines Corp, Hansen Project Mill Tailings Evaluation " Contractor FC Hart Assoc, Inc MCLEAREN, T Technical Assistance Contracts Branch FIN B-6927 NRC-02-79-056 82/11/24 DAVIS, J G Office of Nuclear Material Safety & Safeguards, Director 1p 16297 360

--B212020390 Mod 6, incorporating indirect rate & adding addl funds, to "Cyprus Mines Corp, Hansen Project Mill Tailings Evaluation " * Fred C Hart Associates, Inc HAGAN, T F Division of Contracts FIN B-6927 NRC-02-79-056 82/11/24 2pp 16297 361

B212020402 Notification of contract execution, Mod 1 to "Site Security Evaluation Model Test " Contractor TRW, Inc MCLEAREN, T Technical Assistance Contracts Branch FIN B-6391-B NRC-02-78-050 82/11/24 DAVIS, J G Office of Nuclear Material Safety & Safeguards, Director 1p 16297 354

--B212020404 Mod 1, incorporating final indirect rates & deobligating unliquidated balance of funds, to "Site Security Evaluation Model Test " HERBERT, J P TRW, Inc HAGAN, T F Technical Assistance Contracts Branch FIN B-6391-B NRC-02-78-050 82/11/24 1p 16297 355

B212030236 Notification of contract execution, Mod 7 to "Integrated Geophysical & Geological Study of Tectonic Framework of 38th Parallel Lineament in Vicinity of Intersection " Contractor Purdue Research Foundation SILVER, R M Technical Assistance Contracts Branch FIN B-5971 NRC-04-76-323 82/11/30 BATSON, W Office of Nuclear Regulatory Research, Director STEUER, N NRC - No Detailed Affiliation Given 1p 16317 346

--B212030243 Ltr Contract NRC-04-76-323, Mod 7, deobligating funds, to "Integrated Geophysical & Geological Study of Tectonic Framework of 38th Parallel Lineament in Vicinity " Accepted by RA Greenkorn on 821104 GUSTAVE, R P Technical Assistance Contracts Branch FIN B-5971 NRC-04-76-323 82/10/26 DAVIS, R L Purdue Research Foundation 1p 16317 347

B212030246 Notification of contract execution, Mod 4 to "Study to Develop Integrated Sys Concepts for Safeguards " Contractor General Research Corp SILVER, R M Research Contracts Branch FIN B-5716 NRC-04-76-331 82/11/30 BATSON, W Office of Nuclear Regulatory Research, Director BERGREN, J NRC - No Detailed Affiliation Given 1p 16316 344

--B212030266 Mod 4, deobligating funds, to "Study to Develop Integrated Sys Concepts for Safeguards " VAN HORN, H P General Research Corp GUSTAVE, R P Research Contracts Branch FIN B-5716 NRC-04-76-331 82/11/30 1p 16316 345

B212060114 Notification of grant execution, Mod 1 to "Fundamental Problems in Modeling BWR Containment Sys Flows " Grantee MIT MCDERMOTT, D Research Contracts Branch FIN G-1025 NRC-0-04-81-028 82/11/30 BATSON, W, LEE, T Office of Nuclear Regulatory Research, Director 1p 16323 011

--B212060120 Mod 1, extending period of performance to 821230 at no cost, to "Fundamental Problems in Modeling BWR Containment Sys Flows " DUMMER, G H Massachusetts Institute of Technology MORTON, K V Research Contracts Branch G-1025 NRC-G-04-81-028 82/11/30 1p 16323 012

B212060297 Notification of contract execution, Mod 8 to "Technical Assistance in Support of NRC Reactor Licensing Actions Program 2 " Contractor Science Applications, Inc FLYNN, M J Technical Assistance Contracts Branch FIN B-B609 NRC-03-82-096 82/11/12 EISENHUT, D G Division of Licensing JOHNSON, B NRC - No Detailed Affiliation Given 1p 16323 359

--B212060304 Mod 8, providing incremental funding, to "Technical Assistance in Support of NRC Reactor Licensing Actions Program 2 " Science Applications, Inc HAGAN, T F Division of Contracts FIN B-B609 NRC-03-82-096 82/11/12 2pp 16323 360

B212060405 Notification of contract execution, Mod 3 to "Ad Hoc Committee for Review of Nuclear Reactor Licensing Reform Proposals " Contractor G Charnoff LITTLE, M Administrative Contracts Branch FIN B-8179 NRC-18-82-481 82/11/17 ROTHCHILD, T Office of the General Counsel 1p 16322 316

--B212060413 Mod 3, providing for miscellaneous expenses, extending period of performance to 830410 & increasing monetary value, to "Ad Hoc Committee for Review of Nuclear Reactor Licensing Reform Proposals " Charnoff, G Charnoff, G REBELLO, J E Division of Contracts FIN B-8179 NRC-18-82-481 82/11/17 1p 16322 317

B212060502 Notification of contract execution, Mod 2 to "Economic Impact of Nuclear Energy Ctrs " Contractor Univ of PA MCLEAREN, T Technical Assistance Contracts Branch NRC-02-75-155 82/09/07 DAVIS, J G Office of Nuclear Material Safety & Safeguards, Director 1p 16348 012

--B212060505 Ltr contract, Mod 2, deobligating unliquidated balance, to "Economic Impact of Nuclear Energy Ctrs " HAGAN, T F Technical Assistance Contracts Branch NRC-02-75-155 82/09/02 KELLEY, D E Pennsylvania, Univ of 1p 16348 013

B212070424 Notification of contract execution "Cobalt Teletherapy Calibr Course," awarded to MD Anderson Hosp HOYLE, A Administrative Contracts Branch, FIN B-5090 NRC-06-83-267 82/11/17 KERR, G W Office of State Programs, Director DOLLINO, L A NRC - No Detailed Affiliation Given 1p 16356 254

--B212070429 Contract "Cobalt Teletherapy Calibr Course," awarded to MD Anderson Hosp GILLEY, E R M D Anderson Hosp, Houston, TX * Division of Contracts FIN B-5090 NRC-06-83-267 82/11/17 4pp 16356 255

B212070450 Notification of contract execution, Mod 1 to "Microfiche Verification & Retrofit " Contractor SBA Subcontractor Labat-Anderson, Inc PAGE, M Administrative Contracts Branch NRC-10-82-425 82/11/29 DEGAH, W J Division of Technical Information & Document Control STOCZLAS, J, SCOTT, S NRC - No Detailed Affiliation Given 1p 16355 345

- B212070453 Mod 1, issuing assignment of claim, to "Microfiche Verification & Retrofit"
* Labat-Anderson, Inc * Small Business Administration
SMITH, P A Division of Contracts NRC-10-82-425 82/11/29 2pp
16355 346
- B212080022 Notification of contract execution, Mod 2 to "Evaluation of Power Reactor Fuel Rod Analysis Capabilities"
Contractor Nuclear Associates Intl
GUSTAVE, R Research Contracts Branch FIN B-7479 NRC-04-81-201
82/11/26 DATSON, W, SCOTT, H Office of Nuclear Regulatory Research, Director 1p 16367 105
- B212080024 Mod 2, adding FY83 incremental funding, to "Evaluation of Power Reactor Fuel Rod Analysis Capabilities"
* Nuclear Associates International GUSTAVE, R P Research Contracts Branch FIN B-7474 NRC-04-81-201 82/11/26 1p
16367 166
- B212080090 Notification of contract execution, Mod 6 to "Newspaper Clipping Svc" Contractor Press Intelligence, Inc
GILDENHORN Division of Contracts NRC-10-81-357 82/11/10
SPRINGIER, M L Office of Administration CONYNGHAM, M NRC - No Detailed Affiliation Given 1p 16367 356
- B212080103 Mod 6, extending period of performance to B21107, to "Newspaper Clipping Svc"
JONES, J M Press Intelligence, Inc SMITH, P A Division of Contracts NRC-10-81-357 82/11/10 2pp 16367 357
- B212080572 Notification of contract execution, Mod 2 to "Ad Hoc Committee for Review of Nuclear Reactor Licensing Reform Proposals" Contractor OH State Univ, College of Engineering
LITTLE, M Administrative Contracts Branch FIN B-8179
NRC-18-82-481-0 82/12/03 ROTHSCHELD, T Office of the General Counsel 1p 16368 335
- B212080577 Mod 2, extending period of performance to B30410 & increasing total funds, to "Ad Hoc Committee for Review of Nuclear Reactor Licensing Reform Proposals"
REDMOND, R F Ohio State Univ REBELLO, J E Division of Contracts FIN B-8179 NRC-18-82-481-0 82/12/03 1p
16368 336
- B212080580 Notification of contract execution, Mod 1 to "Keypunch & Verification Svcs" Contractor Info Sys & Networks Corp
PERLMAN, J Administrative Contracts Branch NRC-25-82-318
82/12/02 TROUTMAN, C Division of Automatic Data Processing Support OLIVER, D NRC - No Detailed Affiliation Given 1p
16368 330
- B212080583 Mod 1, adding Task 7, to "Keypunch & Verification Svcs"
MALKANI, R Information Systems & Network Corp HILL, D Small Business Administration SMITH, P A Division of Contracts
NRC-25-82-318 82/12/02 2pp 16368 331
- G212100124 Notification of grant execution, Mod 2 to "Partial Support of Committee on Seismology" Grantee Natl Academy of Sciences
MCDERMOTT, D Research Contracts Branch FIN G-1028
NRC-G-04-81-023 82/12/03 BATSOK, W Office of Nuclear Regulatory Research, Director MURPHY, A NRC - No Detailed Affiliation Given
1p 16398 361
- B212100133 Mod 2, extending grant period to B30930, increasing funding & incorporating B20723 renewal proposal, to "Partial Support of Committee on Seismology"
SMITH, P M National Academy of Sciences MORTON, K V Research Contracts Branch FIN G-1028 NRC-G-04-81-023 82/12/03 1p
16398 362
- B212100154 Notification of contract execution, Mod 1 to "Fuel Cycle Project Review" Contractor Science Applications, Inc
WOLLETT, S Research Contracts Branch FIN B-6694 NRC-04-80-178
82/11/29 FOREHAND, W Office of Nuclear Regulatory Research, Director ENG, C. NRC - No Detailed Affiliation Given 1p
16398 340
- B212100162 Mod 1, changing completion date from B21130 to B30115, to "Fuel Cycle Project Review"
BRAINARD, F Science Applications, Inc GUSTAVE, R P Division of Contracts FIN B-6694 NRC-04-80-178 82/11/29 1p
16398 341
- B212100167 Notification of contract execution, Mod 1 to "Lab Studies Dynamic Response of Prototypical Piping Sys" Contractor
ANCO Engineers, Inc & EPRI
BATESON, L Technical Assistance Contracts Branch FIN B-8907
NRC-04-82-025 82/11/29 FOREHAND, W Office of Nuclear Regulatory Research, Director O'BRIEN, J G NRC - No Detailed Affiliation Given 1p 16398 337
- B212100172 Ltr Contract NRC-04-82-025, Mod 1, extending period of performance to B21118, to "Lab Studies Dynamic Response of Prototypical Piping Sys"
MORTON, K V Division of Contracts FIN B-8907 NRC-04-82-025
82/11/29 HOWARD, O E ANCO Engineers, Inc RYKONEN, B B Electric Power Research Institute 2pp 16398 338
- B212130155 Notification of contract execution, Mod 5 to "Site Suitability Assessments Based on Seepage & Groundwater Conditions Associated w/U Recovery Operations" Contractor
Williams-Robinette & Assoc
FIELDS, J A Technical Assistance Contracts Branch NRC-0-2-81-039
82/12/01 DAVIS, J Office of Nuclear Material Safety & Safeguards, Director 1p 16410 283
- B212130160 Mod 5, changing NRC technical representative under Article XII, to "Site Suitability Assessments Based on Seepage & Groundwater Conditions Associated w/U Recovery Operations"
* Williams-Robinette & Associates, Inc GUSTAVE, R P Technical Assistance Contracts Branch NRC-02-81-039 82/12/01 1p
16410 284
- B212130178 Notification of contract execution, Mod 7 to "Review of Tailings Mgt" Contractor CO State Univ
FIELDS, J A Technical Assistance Contracts Branch NRC-02-80-082
82/11/03 DAVIS, J Office of Nuclear Material Safety & Safeguards, Director FLEMING, T NRC - No Detailed Affiliation Given 1p 16410 360
- B212130182 Mod 7, extending draft & final evaluations due date to B30630, to "Review of Tailings Mgt"
BROWN, J F Colorado State Univ HAQAN, T F Division of Contracts NRC-02-80-82 82/11/03 1p 16410 361
- B212130364 Contract "Word Processing Svcs," awarded to Press Intelligence, Inc
* Press Intelligence, Inc MATTIA, M J Division of Contracts
NRC-10-83-298 82/11/08 2pp 16412 161
- B212160593 Notification of contract execution, Mod 2 to "Licensing Assistance/Geotechnical & Hydrological Evaluations"
Contractor Shannon & Wilson, Inc
FIELDS, J A Technical Assistance Contracts Branch
NRC-02-80-033-06 82/12/03 DAVIS, J Office of Nuclear Material Safety & Safeguards, Director GARCIA, P NRC - No Detailed Affiliation Given 1p 16466 037
- B212160608 Mod 2, changing controller address & incorporating revised manual chapter, to "Licensing Assistance/Geotechnical & Hydrological/Evaluations"
MILLER, R P Shannon & Wilson, Inc HAQAN, T F Division of Contracts NRC-02-80-033-06 82/12/03 1p 16466.038
- B212170398 Notification of contract execution, Mod 24 to "Review & Evaluation of Approx 500 Pending Operating Reactors Licensing Actions" Contractor Franklin Inst
FLYNN, M J Technical Assistance Contracts Branch FIN B-6590
NRC-03-79-118 82/11/23 EISENHUT, D Division of Licensing BAJWA, S NRC - No Detailed Affiliation Given 1p 16478 146
- B212170401 Mod 24, obligating funds, incorporating award fee earned from Jan-June 1982 & substituting key personnel, to "Review & Evaluation of Approx 500 Pending Operating Reactors Licensing Actions"
* Franklin Institute/Franklin Research Center HAQAN, T F Division of Contracts FIN B-6590 NRC-03-79-118 82/11/23 4pp 16478 147
- B212170402 Notifies NRC of resignation of AA Gonzalez as assistant project manager for contract Proposes TA Shook to assume responsibility
ASHTON, A M Franklin Institute/Franklin Research Center
NRC-03-79-118 82/10/28 HAQAN, T Technical Assistance Contracts Branch 1p 16478 151
- B21220018 Notification of contract execution, Mod 7 to "Technical Assistance in Support of NRC Reactor Licensing Action Program 2" Contractor Franklin Inst
FLYNN, M J Technical Assistance Contracts Branch FIN B-6891
NRC-03-81-130 82/11/22 EISENHUT, D G Division of Licensing BAJWA, S NRC - No Detailed Affiliation Given 1p 16529 093
- B21220024 Mod 7, increasing funds, to "Technical Assistance in Support of NRC Reactor Licensing Action Program 2"
* Franklin Institute/Franklin Research Center HAQAN, T F Division of Contracts FIN B-6891 NRC-03-81-130 82/11/22 2pp 16529 094

NONDOCKETED ITEMS

- 8212220019 Notification of contract execution, Mod 2 to "Availability of Medical Treatment to Minimize Early Fatalities Post-Severe Reactor Accidents " Contractor SBA Subcontractor Andrus Research Corp
FLEENOR, C M Technical Assistance Contracts Branch NRC-03-82-128
82/11/03 MATTHEW, R J Division of Systems Integration (post
B11005) CHU, A NRC - No Detailed Affiliation Given 1p
16529 091
- 8212220027 Mod 2, substituting project officer, to "Availability of Medical Treatment to Minimize Early Fatalities Post-Severe Reactor Accidents "
* Small Business Administration * Andrus Research Corp
HAGAN, T F Division of Contracts NRC-03-82-128 82/11/03 1p
16529 092
- 8212220025 Notification of contract execution, Mod 2 to "Matl Balance Capability of Process Similar to NFS, Erwin, TN " Contractor NUSAC, Inc
GILDENHORN, A J Administrative Contracts Branch FIN B-1314
82/12/07 ZERBE, J E , CNO, C Office of Policy Evaluations 1p 16529 082
- 8212220034 Mod 2, adding addl work, extending period of performance through 821231 & increasing funding, to "Matl Balance Capability of Process Similar to NFS, Erwin, TN "
PEVENSTEIN, J E NUSAC, Inc SMITH, P A Division of Contracts FIN B-1314 NRC-19-82-491 82/12/07 2pp 16529 083
- 8212220522 Notification of contract execution, Mod 12 to "Study of Seismicity & Tectonics in New England " Contractor Boston College
JACOBBS, A Research Contracts Branch FIN A-4056 NRC-04-74-238
82/12/07 BASTON, W Office of Nuclear Regulatory Research, Director MURPHY, A NRC - No Detailed Affiliation Given 1p
16522 357
- 8212220528 Mod 12, extending period of performance to 831031 w/addl workscope & funds, to "Study of Seismicity & Tectonics in New England "
SMITH, J R Boston College GUSTAVE, R P Division of Contracts FIN A-4056 NRC-04-74-238 82/12/07 5pp 16522 358
- 8212220524 Notification of contract execution, Mod 8 to "Regional Tectonics & Seismicity of KS " Contractor Univ of KS
JACOBBS, A Research Contracts Branch FIN B-6172 NRC-04-77-017
82/12/14 BASTON, W Office of Nuclear Regulatory Research, Director MURPHY, A NRC - No Detailed Affiliation Given 1p
16522 354
- 8212220535 Mod 8, extending period of performance for 3 months, to "Regional Tectonics & Seismicity of KS "
HORNWITZ, F D Kansas, Univ of GUSTAVE, R P Division of Contracts FIN B-6172 NRC-04-77-017 82/12/14 2pp
16522 355
- 8212220536 Notification of contract execution, Mod 2 to "Support in Geotechnical Engineering for Nonreactor Facilities " Contractor Army Corp of Engineers
BILVIE, R M Research Contracts Branch FIN B-6846 NRC-03-80-125
82/12/09 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 16522 348
- 8212220542 Mod 2, deobligating funds, to "Support in Geotechnical Engineering for Nonreactor Facilities "
KAVANAUGH, P F Army, Dept of, Corps of Engineers GUSTAVE, R P Division of Contracts FIN B-6846 NRC-03-80-125 82/12/09 1p
16522 349
- 8212220549 Notification of contract execution, Mod 2 to "Environ Surveillance for Measuring Concentrations of Radioactivity & Radiation Levels in Environ of Commission Licensed Activities " Contractor State of GA
BILVIE, R M Research Contracts Branch FIN B-5203 NRC-05-79-252
82/12/15 COHEN, L Training & Administration Staff COHEN, L NRC - No Detailed Affiliation Given 1p 16523 349
- 8212220553 Mod 2, deobligating funds, to "Environ Surveillance for Measuring Concentrations of Radioactivity & Radiation Levels in Environ of Commission Licensed Activities Located Within State of GA & Selected by Commission "
LEDBETTER, J, L Georgia, State of, GUSTAVE, R, P Division of Contracts FIN B-5203 NRC-05-79-252 82/12/15 1p 16523 350
- 8212230044 Notification of contract execution, Mod 5 to "Fuel Cycle Licensing " Contractor, Duke Univ
BILVIE, R M Technical Assistance Contracts Branch FIN A-9005
AT(40-1)-4399 82/12/15 DAVIS, J G Office of Nuclear Material Safety & Safeguards, Director 1p 16544 346
- 8212230051 Mod 5, deobligating & obligating funds, to "Fuel Cycle Licensing "
SHUHATE, D R Duke Univ GUSTAVE, R P Division of Contracts FIN A-9005 AT(40-1)-4399 82/12/15 1p 16544 347
- 8212270048 Responds to FOIA request for documents re extensions issued in Nov & Dec 1981 & proposed extensions to "Stenographic Reporting Svcs," awarded to Alderson Reporting Co, Inc
Forwards documents listed in App A
FELTON, J M Division of Rules and Records FIN B-1311
NRC-17-80-448-0 82/11/19 GALLD, J Isham, Lincoln & Beale 3pp
16566 046
- 8212270052 Request for procurement action 80-SEC-448, executing Mod 8 to "Stenographic Reporting Svcs " Mod obligates addl funds
CHILK, S J Office of the Secretary of the Commission FIN B-1311
NRC-17-80-448-0 82/01/18 2pp 16566 049
- 8212270055 Forwards unexecuted Mod 8 to "Stenographic Reporting Svcs," extending period of performance to 820318 & obligating addl funds
Approval requested
LEBO, C D Administrative Contracts Branch FIN B-1311
NRC-17-80-448-0 82/02/01 SHARP, R A Alderson Reporting 2pp
16566 051
- 8212270059 Forwards Mod 8 to "Stenographic Reporting Svcs," extending period of performance to 820318 & obligating addl funds
LEBO, C D Division of Contracts FIN B-1311 NRC-17-80-448-0
82/02/08 SHARP, R A Alderson Reporting 1p 16566 053
- 8212270065 Mod 8, extending period of performance to 820318 & increasing funds obligated to "Stenographic Reporting Svcs " Findings & determination etc.
SHARP, R A Alderson Reporting LEBO, C D Division of Contracts FIN B-1311 NRC-17-80-448-0 82/02/02 2pp 16566 054
- 8212270080 Notification of contract execution, Mod 8 to "Stenographic Reporting Svcs " Contractor Alderson Reporting Co, Inc
PADE, M Administrative Contracts Branch FIN B-1311
NRC-17-80-448-0 82/02/02 CHILK, S J, SULLIVAN, P Office of the Secretary of the Commission MCNAMARA, A Atomic Safety and Licensing Board Panel 1p 16566 056
- 8212270084 Request for procurement action 80-SEC-448, executing Mod 9 to "Stenographic Reporting Svcs " Mod extends period of performance to 820501 & obligates addl funds
MOYLE, J C Office of the Secretary of the Commission FIN B-1311
NRC-17-80-448-0 82/02/23 2pp 16566 057
- 8212270088 Forwards unexecuted Mod 9, extending period of performance to 820501 & obligating addl funds to "Stenographic Reporting Svcs " Approval requested
LEBO, C D Division of Contracts FIN B-1311 NRC-17-80-448-0
82/03/05 SHARP, R A Alderson Reporting 2pp 16566 059
- 8212270091 Forwards Mod 9, extending period of performance to 820501 & obligating addl funds to "Stenographic Reporting Svcs " Contractor Alderson Reporting Co, Inc
LEBO, C D Division of Contracts FIN B-1311 NRC-17-80-448-0
82/03/15 SHARP, R A Alderson Reporting 1p 16566 063
- 8212270095 Request for procurement action 80-SEC-448, executing Mod 10 to "Stenographic Reporting Svcs " Mod extends period of performance to 820806 & obligates addl funds
MOYLE, J C Office of the Secretary of the Commission FIN B-1311
NRC-17-80-448-0 82/05/04 2pp 16566 065
- 8212270107 Forwards unexecuted Mod 10, extending period of performance to 820806 & increasing funds obligated to "Stenographic Reporting Svcs " Approval requested
SMITH, P A Administrative Contracts Branch FIN B-1311
NRC-17-80-448-0 82/05/28 SHARP, R A Alderson Reporting 2pp
16566 070
- 8212270110 Forwards Mod 10, extending period of performance to 820806 & increasing funds obligated to "Stenographic Reporting Svcs " SMITH, P A Administrative Contracts Branch FIN B-1311
NRC-17-80-448-0 82/06/11 Alderson Reporting 1p 16566 072
- 8212270114 Request for procurement action 80-SEC-448, executing Mod 11 to "Stenographic Reporting Svcs " Mod extends period of performance to 821115 & obligates addl funds
CHILK, S J Office of the Secretary of the Commission FIN B-1311
NRC-17-80-448-0 82/07/16 2pp 16566 075
- 8212270123 Forwards unexecuted Mod 11, extending period of performance to 821115 & increasing funds obligated to "Stenographic Reporting Svcs " Approval requested
SMITH, P A Administrative Contracts Branch FIN B-1311
NRC-17-80-448-0 82/08/09 SHARP, R A Alderson Reporting 2pp
16566 079

- B212270127 Forwards Mod 11, extending period of performance to B21115 & increasing funds obligated to "Stenographic Reporting Svcs " SMITH, P A Administrative Contracts Branch FIN B-1311 NRC-17-80-448-0 82/08/20 Alderson Reporting 1p 16566 081
- B212270131 Mod 11, extending period of performance to B21115 & increasing funds obligated to "Stenographic Reporting Svcs " SHARP, R A Alderson Reporting SMITH, P A Division of Contracts FIN B-1311 NRC-17-80-448-0 82/08/20 1p 16566 082
- B212270133 Notification of contract execution, Mod 11 to "Stenographic Reporting Svcs " Contractor Alderson Reporting Co, Inc PAGE, M Administrative Contracts Branch FIN B-1311 NRC-17-80-448-0 82/08/20 CHILK, S J, SULLIVAN, P Office of the Secretary of the Commission MCNAMARA, A Atomic Safety and Licensing Board Panel 1p 16566 083
- B212270410 Notification of contract execution, Mod 5 to "Geotechnical Engineering Review of SEP Plants " Contractor US Army Corps of Engineers FIELDS, J A Technical Assistance Contracts Branch NRC-03-81-127 82/11/16 VOLLNER, R H, HELLER, L Division of Engineering 1p 16555 358
- B212270412 Mod 5, extending period of performance to B31231, to "Geotechnical Engineering Review of SEP Plants " KAVANAUGH, P F Army, Dept of, Corps of Engineers HAGAN, T F Division of Contracts NRC-03-81-122 82/11/16 2pp 16555 359
- B212270415 Notification of contract execution, Mod 1 to "Fire Protection Review & Evaluation " Contractor Rolp Jensen & Assoc, Inc FIELDS, J A Technical Assistance Contracts Branch NRC-03-82-093-01 82/11/23 VOLLNER, R H, FERGUSON, R Division of Engineering 1p 16555 361
- B212270417 Mod 1, changing address for controller ofc & revising manual chapter to "Fire Protection Review & Evaluation " WEBB, W A Rolp Jensen & Associates, Inc HAGAN, T F Division of Contracts NRC-03-82-093-01 82/11/23 1p 16555 362
- B212270419 Notification of contract execution, Mod 9 to "Technical Assistance in Support of NRC Reactor Licensing Actions Program 2 " Contractor Science Applications, Inc FLYNN, M J Technical Assistance Contracts Branch FIN B-8609 NRC-03-82-096 82/11/30 EISENHUT, D O, SILVER, H Division of Licensing 1p 16566 033
- B212270422 Mod 9, providing incremental funding to "Technical Assistance in Support of NRC Reactor Licensing Actions Program 2 " Science Applications, Inc GUSTAVE, R P Division of Contracts FIN B-8609 NRC-03-82-096 82/11/30 2pp 16566 034
- B212270446 Notification of contract execution, Mod 4 to "Review & Critique of Pu Package Certification " Contractor Natl Academy of Sciences SILVIS, R M Technical Assistance Contracts Branch FIN B-148/-7 NRC-02-77-004 82/12/20 DAVIS, J O, NUSSBAUMER, D Office of Nuclear Material Safety & Safeguards, Director 1p 16568 348
- B212270447 Mod 4, deobligating funds to "Review & Critique of Pu Package Certification " SMITH, P National Academy of Sciences GUSTAVE, R P Division of Contracts FIN B-1487-7 NRC-02-77-004 82/12/20 1p 16568 349
- B212270470 Notification of contract execution "Press Clipping Svc," awarded to Press Intelligence, Inc DORSEY, M J, BAZIN, J Administrative Contracts Branch NRC-10-83-249 82/11/08 BESAW, W J Division of Technical Information & Document Control 1p 16566 359
- B212270496 Notification of contract execution, Mod 1 to "Reproduction of Copies Re Stanislaus Nuclear Project Unit 1, NRC Docket P-564-A " Contractor Spiegel & McDiarmid & Northern CA Power Agency SMITH, P A Division of Contracts NRC-10-79-391 82/12/17 SPRINGER, M, WOOD, R Office of Administration 1p 16548 358
- B212270502 Mod 1, deobligating funds to "Reproduction of Copies Re Stanislaus Nuclear Project, Unit 1, NRC Docket P-564-A " Northern California Power Agency, California, State of, TRAUGER, T C Spiegel & McDiarmid SMITH, P A Division of Contracts NRC-10-79-391 82/12/17 1p 16548 359
- B212270503 Notification of contract execution, Mod 2 to "Electrical & Instrumentation Technology & Codes Course " Contractor GE GUSTAVE, R P Technical Assistance Contracts Branch FIN B-1258 NRC-05-81-261 82/12/16 BLAHA, J L Director's Office, Office of Inspection and Enforcement THAYER, C W NRC - No Detailed Affiliation Given 1p 16548 355
- B212270506 Mod 2, authorizing revision of course text, to "Electrical & Instrumentation Technology & Codes Course " CALK, J C General Electric Co MORTON, K V Division of Contracts FIN B-1258 NRC-05-81-261 82/12/16 2pp 16548 356
- B212270509 Notification of contract execution, Mod 2 to "Synergistic Effects of Low Level Radiation " Contractor M Goldman SMITH, P A Contract Policy Branch FIN B-8049 NRC-03-82-114 82/12/17 DENTON, H Office of Nuclear Reactor Regulation, Director CONDEL, F NRC - No Detailed Affiliation Given 1p 16548 353
- B212270513 Mod 2, deobligating funds for close out, to "Synergistic Effects of Low Level Radiation " GOLDMAN, M Goldman, M SMITH, P A Division of Contracts FIN B-8049 NRC-03-82-114 82/12/17 1p 16548 354
- B212270510 Notification of contract execution, Mod 5 to "Card-Entry Access Control Sys " Contractor Racial Vikonics, Inc GOLDMAN, M Goldman, M SMITH, P A Division of Contracts FIN B-8049 NRC-03-82-114 82/12/17 1p 16548 354
- B212270516 Mod 5, clarifying acceptance test requirements & extending period of performance due to govt delay to B34131, to "Card-Entry Access Control Sys " Racial Vikonics, Inc SMITH, P A Division of Contracts NRC-10-82-399 82/12/07 2pp 16548 351
- B212270518 Notification of contract execution, Mod 2 to "Long-Term Performance of Matls Used for High Level Waste Packaging " Contractor BNWL SILVIS, R M Technical Assistance Contracts Branch FIN B-6764 NRC-04-82-015 82/12/17 BATSON, W Office of Nuclear Regulatory Research, Director KIM, K NRC - No Detailed Affiliation Given 1p 16546 361
- B212270521 Mod 2, granting incremental funding, to "Long-Term Performance of Matl Used for High Level Waste Packaging " Battelle Memorial Institute, Columbus Laboratories GUSTAVE, R P Division of Contracts FIN B-6764 NRC-04-82-015 82/12/17 1p 16546 362
- B212270527 Notification of contract execution, Mod 3 to "Licensing Assistance/Tailings Mgt Program Technical Evaluation " Contractor FC Hart Assoc, Inc FIELDS, J A Technical Assistance Contracts Branch NRC-02-79-031-04 82/11/03 DAVIS, J O Office of Nuclear Material Safety & Safeguards, Director ROSSBACH, L NRC - No Detailed Affiliation Given 1p 16551 004
- B212270530 Mod 3, extending period of performance to B20630 to "Licensing Assistance/Tailings Mgt Program Technical Evaluation " STASCO, W H Fred C Hart Associates, Inc HAGAN, T F Division of Contracts NRC-02-79-031-04 82/11/03 1p 16551 005
- B212270539 Notification of contract execution, Mod 4 to "Analysis of Safeguards Needs for Transport of High Level Waste " Contractor BNWL FIELDS, J A Technical Assistance Contracts Branch FIN B-6990-3 NRC-02-81-030 82/11/29 DAVIS, J Office of Nuclear Material Safety & Safeguards, Director SAWYER, C NRC - No Detailed Affiliation Given 1p 16546 356
- B212270543 Mod 4, obligating funds to "Analysis of Safeguards Needs for Transport of High Level Waste " Battelle Memorial Institute, Columbus Laboratories HAGAN, T F Division of Contracts FIN B-6990-3 NRC-02-81-030 82/11/29 1p 16546 357
- B212270555 Notification of contract execution, Mod 8 to "In-Process of SNM " Contractor Science Applications, Inc FIELDS, J A Technical Assistance Contracts Branch FIN B-7313-3 NRC-02-81-040 82/11/29 DAVIS, J Office of Nuclear Material Safety & Safeguards, Director MENDELSON, B NRC - No Detailed Affiliation Given 1p 16546 340
- B212270556 Mod 8, obligating funds to "In-Process Control of SNM " Science Applications, Inc HAGAN, T F Division of Contracts FIN B-7313-3 NRC-02-81-040 82/11/29 1p 16546 341
- B212270558 Notification of contract execution, Mod 1 to "Economic Consulting Svcs in Connection w/ Stanislaus Nuclear Unit, Antitrust Hearing Docket P-564-A " Contractor PM Outmann SILVIS, R M Technical Assistance Contracts Branch FIN B-6521 NRC-03-81-120 82/12/21 DENTON, H R Office of Nuclear Reactor Regulation, Director TOALSTON, A NRC - No Detailed Affiliation Given 1p 16546 338

NONDOCKETED ITEMS

--B212270560 Mod 1, deobligating funds to "Economic Consulting Svcs in Connection w/ Stanislaus Nuclear Unit, Antitrust Hearing
Docket P-364-A "
GUTHMAN, P M Outmann, P M GUSTAVE, R P Technical Assistance
Contracts Branch FIN B-6521 NRC-03-B1-120 82/12/21 1p
16546 339

B212280043 Notification of contract execution, Mod 13 to "Stenographic Reporting Svcs " Contractor Alderson Reporting Co, Inc
PAQUE, M Administrative Contracts Branch FIN B-1311
NRC-17-80-448 82/12/15 CHILK, S J Office of the Secretary of the Commission 1p 14593 006

--B212280044 Mod 13, extending period of performance, to "Stenographic Reporting Svcs "
* Alderson Reporting SMITH, P A Division of Contracts FIN
B-1311 NRC-17-80-448 82/12/15 1p 16593 007

B212280047 Notification of contract execution, Mod 8 to "Kinetics of Chlorine-Ammonia in Sea Water " Contractor Univ of NC
SILVIS, R M Research Contracts Branch FIN B-6248 NRC-04-77-119
82/12/15 BATSON, W Office of Nuclear Regulatory Research,
Director REED, P NRC - No Detailed Affiliation Given 1p
16590 361

--B212280049 Ltr contract, Mod 8, deobligating funds, to "Kinetics of Chlorine-Ammonia in Sea Water "
GUSTAVE, R P Division of Contracts FIN B-6248 NRC-04-77-119
82/11/09 CROOK, P North Carolina, Univ of 1p 16590 362

B212280445 Notification of contract execution, Mod 3 to "Transparent Armor Testing " Contractor US Army
FIELDS, J A Technical Assistance Contracts Branch NRC-02-81-029
82/11/03 DAVIS, J Office of Nuclear Material Safety &
Safeguards, Director QUINN, E NRC - No Detailed Affiliation Given
1p 16590 350

--B212280455 Mod 3, modifying period of performance until 821231 &
changing project officer, to "Transparent Armor Testing "
RICHARDS, J F Army, Dept of HAGAN, T F Division of Contracts
NRC-02-81-029 82/11/03 1p 16590 351

B212280469 Notification of contract execution, Mod 7 to "Technical Assistance for EIS on 10CFR61 " Contractor Dames & Moore
FIELDS, J A Technical Assistance Contracts Branch FIN B-7318-J
NRC-02-81-049 82/11/15 DAVIS, J Office of Nuclear Material
Safety & Safeguards, Director ROLES, G NRC - No Detailed
Affiliation Given 1p 16590 346

--B212280478 Mod 7, modifying statement of work extending period of
performance to 830630, obligating funds & modifying key
personnel, to "Technical Assistance for EIS on 10CFR61
OZTUHALI, O I Dames & Moore MATTIA, M J Division of Contracts
FIN B-7318-3 NRC-02-81-049 82/11/15 3pp 16590 347

B212280486 Notification of contract execution, Mod 6 to "Technical Assistance in Repository Design " Contractor Golder Assoc.
Inc
FIELDS, J A Technical Assistance Contracts Branch NRC-02-81-03/
82/11/15 DAVIS, J Office of Nuclear Material Safety &
Safeguards, Director HARTUNG, L NRC - No Detailed Affiliation
Given 1p 16590 355

--B212280491 Mod 6, modifying statement of work & extending period of
performance to 830715, to "Technical Assistance in Repository
Design "
ROWE, J W Golder Associates MATTIA, M J Division of Contracts
NRC-02-81-037 82/11/15 2pp 16590 356

B212290053 Notification of contract execution, Mod 7 to "Buckling Behavior of Steel Containment Shells " Contractor Lockheed
Missiles & Space Co, Inc
FIELDS, J A Technical Assistance Contracts Branch NRC-03-80-103/
82/09/21 HANAUER, S Division of Safety Technology SCHAUER, F
NRC - No Detailed Affiliation Given 1p 16607 053

--B212290056 Mod 7, extending period of performance to 820930, to
"Buckling Behavior of Steel Containment Shells "
SNEAD, K H Lockheed Missiles & Space Co (subs Lockheed Aircraft
Corp) HAGAN, T F Division of Contracts NRC-03-80-103
82/09/21 1p 16607 054

B212290266 Notification of contract execution, Mod 2 to "Evaluation of
NRC Executive Development & Mgt Program " Contractor Project
Assoc, Inc
SMITH, P Division of Contracts NRC-10-81-356 82/12/16
SPRING, M Office of Administration ALLER, R NRC - No Detailed
Affiliation Given 1p 16406 262

--B212290273 Mod 2, deobligating funds for close out, to "Evaluation of
NRC Executive Development & Mgt Program "
CONVERSANE, E Project Associates SMITH, P A Division of
Contracts NRC-10-81-356 82/12/16 1p 16606 263

B212300117 Notification of contract execution, Mod 3 to "Presentation of
OE BWR Nuclear Engineering Courses " Contractor OE
JACOBUS, A Research Contracts Branch FIN B-1232 NRC-05-80-265
82/12/21 BLAHA, J Program Support Branch FOX, E NRC - No
Detailed Affiliation Given 1p 16624 247

--B212300123 Mod 3, adding 3-month extension to 820927 at no addl cost, to
"Presentation of OE BWR Nuclear Engineering Courses "
PIERCE, R L General Electric Co GUSTAVE, R P Division of
Contracts FIN B-1232 NRC-05-80-265 82/12/21 1p 16624 249

B212300127 Notification of contract execution, Mod 7 to "Graphics/
Photographic Svcs " Contractor Robert Charles Moles & Assoc
PERLMAN, J Administrative Contracts Branch FIN B-1297
NRC-05-81-257 82/12/20 BLAHA, J L Program Support Branch
THAYER, C NRC - No Detailed Affiliation Given 1p 16624 250

--B212300132 Mod 7, adding incremental funding, to "Graphics/Photographic
Svcs "
* Robert Charles Moles & Associates SMITH, P A Division of
Contracts FIN B-1297 NRC-05-81-257 82/12/20 1p 16624 251

B212300170 Notification of contract execution, Mod 2 to "Major
Earthquakes on East Side of New Madrid Earthquake Zone "
Contractor Vanderbilt Univ
SILVIS, R M Technical Assistance Contracts Branch FIN B-807B
NRC-04-81-195 82/12/17 BATSON, W Office of Nuclear Regulatory
Research, Director MURPHY, A NRC - No Detailed Affiliation Given
1p 16613 073

--B212300192 Mod 2, providing incremental funding, to "Major Earthquakes
on East Side of New Madrid Earthquake Zone "
* Vanderbilt Univ GUSTAVE, R P Division of Contracts FIN
B-807B NRC-04-81-195 82/12/17 1p 16613 074

FOIA FREEDOM OF INFORMATION ACT REQUESTS AND RELEASES

B207180049 FOIA request for contract & any proposals, best & final
offers, technical & cost questions & answers & related mods
submitted by Parameter Inc under Request for Proposal
RS-01E-82-249
DAVID, L T Franklin Institute/Franklin Research Center 82/08/19
FELTON, J M Division of Rules and Records 1p 16289 204

B208290092 FOIA request for SECY-81-600A, SECY-81-622A, SECY-82-23,
SECY-82-42, SECY-82-136, SECY-82-137, SECY-82-197A,
SECY-82-197B, SECY-82-286 & SECY-82-315
GRABER, L Affiliation Unknown 82/09/08 Division of Rules and
Records 1p 16384 294

B208290104 FOIA request for eight listed documents
CONNOR, L Doc-Search Associates 82/09/14 Division of Rules and
Records 1p 16388 227

B208290121 FOIA request for documents & records prepared by Energy, Inc
re NRC rulemaking on ATWS
REVELEY, T W, CHRISTMAN, J N, EARLEY, A F Hutton & Williams FIN
A-1228 82/09/22 Office of Administration 3pp 16400 009

B209150054 FOIA request for listed documents referenced in SECY-82-111,
Page 24
GRABER, L Affiliation Unknown 82/09/30 Division of Rules and
Records 1p 16400 353

B209150055 FOIA request for SECY-82-255
GRABER, L Affiliation Unknown 82/10/04 Division of Rules and
Records 1p 16593 331

B209150071 FOIA request for documents setting forth policy re
issuances of NRC press releases in connection w/enforcement
& licensing activities & coverage of licensing & other
hearings by media
HARTMAN, S L Debevoise & Liberman 82/10/13 FELTON, J M Division
of Rules and Records 1p 16289 001

B212010012 Responds to FOIA request for contract & any proposals, best &
final offers, technical & cost questions & answers & related
mods submitted by Parameter, Inc under Request for Proposal
RS-01E-82-249
FELTON, J M Division of Rules and Records 82/11/08 DAVID, L T
Franklin Institute/Franklin Research Center 1p 16289 205

- 8212010016 Technical proposal in response to NRC Request for Proposal RS-01E-82-249, "Technical Assistance to Support NRC-IE Personnel in Investigation of Incidents" LOFY, R A Parameter, Inc 82/04/02 65pp 16289 206
- 8212010021 Submits suppl to 820402 proposal re NRC RFP RS-01E-82-249, "Technical Assistance to Support NRC-IE Personnel in Investigation of Incidents," per NRC 820615 request LOFY, R A Parameter, Inc 82/06/21 MORTON, K V Research Contracts Branch 7pp 16289 273
- 8212010029 Responds to FOIA request for documents setting forth policy re issuances of NRC press releases in connection w/ enforcement & licensing activities Forwards documents listed on app Documents also available in PDR FELTON, J M Division of Rules and Records 82/11/01 HARTMAN, S Debevoise & Liberman 3pp 16289 002
- 8008260700 Advises that present 2-day period between licensee & NRC announcement of proposed civil penalties should be changed to sys where NRC announces action as soon as licensee is notified FOUCHARD, J J Office of Public Affairs 80/05/30 STELLO, V Office of Inspection & Enforcement, Office of the Director 1p 16289 014
- 8212010051 10CFR2 re NRC policy & procedure for enforcement actions * NRC - No Detailed Affiliation Given 82/03/09 9pp 16289 005
- 8212010058 Discusses implementation of camera policy at hearings No significant problems identified in cases where cameras were allowed ABRAHAM, K Region 1, Philadelphia, Office of the Director 78/10/06 FOUCHARD, J J Office of Public Affairs 2pp 16289 017
- 8212010067 Forwards draft papers re camera coverage of licensing hearings Draft "Consent Calendar" recommends that Commission permanently formalize policy of permitting camera coverage of licensing hearings w/ listed conditions INGRAM, F L Office of Public Affairs 78/10/05 ROSENTHAL, A Atomic Safety and Licensing Appeal Panel YORE, J R Atomic Safety and Licensing Board Panel KELLEY, J Office of the General Counsel 14pp 16289 019
- 8212010070 Informs that F Ballard, Commissioner of Dept of Bldg & Grounds for Onondaga County has no objections to use of cameras in public safety bldg Draft public announcement of oral argument will be sent shortly INGRAM, F L Office of Public Affairs 78/03/10 ROSENTHAL, A Atomic Safety and Licensing Appeal Panel 1p 16289 033
- 8212010077 Informs that E Owens has no objections to use of cameras in Courthouse 3 of Richland County Courthouse providing no interference w/ judicial proceedings for both adjoining courtrooms evident INGRAM, F L Office of Public Affairs 78/03/07 SMITH, I Atomic Safety and Licensing Board Panel 1p 16289 034
- 8212010080 Informs that Region 5 public affairs officer J Hanchett has confirmed, w/ appropriate officials, that Commission trial camera policy may be implemented re NRC proceedings held in US Customs House in San Francisco, CA INGRAM, F L Office of Public Affairs 78/03/02 LUTON, E Atomic Safety and Licensing Board Panel 1p 16289 035
- 8212010091 Informs that Commission will permit, on trial basis, camera coverage of proceedings before ASLB & ASLAB under certain conditions FOUCHARD, J J Office of Public Affairs 78/02/01 SIZEMORE, H M Seattle Times 1p 16289 037
- 8212010096 Denies request to photograph proceedings of ASLB 770511 hearing. Use of cameras during actual proceeding has been prohibited Commission considers cameras to be source of distraction CHILK, S J Office of the Secretary of the Commission 77/05/09 SIZEMORE, H M Seattle Times 1p 16289 038
- 8212010099 Expresses disappointment re denial of request to permit photographs to record ASLB 770511 proceedings in Seattle, WA SIZEMORE, H M Seattle Times 77/05/13 CHILK, S J Office of the Secretary of the Commission 1p 16289 039
- 8212010102 Informs that Commission will permit, on trial basis, camera coverage of proceedings before ASLB & ASLAB under certain conditions FOUCHARD, J J Office of Public Affairs 78/02/01 COGAN, P KING Television, Seattle, WA 1p 16289 040
- 8212010105 Denies request to photograph proceedings of ASLB 770511 hearing. Use of cameras during actual proceeding has been prohibited because Commission considers cameras to be source of distraction CHILK, S J Office of the Secretary of the Commission 77/05/09 COGAN, P KING Television, Seattle, WA 1p 16289 041
- 8212010108 Informs that Commission will permit, on trial basis, camera coverage of proceedings before ASLB & ASLAB under certain conditions FOUCHARD, J J Office of Public Affairs 78/02/01 VRIESMAN, W R Radio Television News Directors Association 1p 16289 042
- 8212010112 Responds to 770831 ltr re use of news cameras at ASLB public hearings in Tulsa, OK Commission adherence to policy allowing cameras in hearing rooms only before & after each session was pursued during facility proceedings HENDRIE, J M Commissioners 77/09/30 VRIESMAN, W R Radio Television News Directors Association 1p 16289 043
- 8212010119 Protests Commission refusal to conduct official business while news cameras are present at facility hearings in Tulsa, OK Action considered discriminatory VRIESMAN, W R Radio Television News Directors Association 77/08/31 HENDRIE, J M Commissioners 1p 16289 044
- 8212010123 Advises that Judge Devitt has drafted ltr re clarification of Rule 7d as to whether rule prohibits use of cameras under any circumstances or whether policy might be applicable to NRC proceedings held in court facilities Draft ltr encl FOUCHARD, J J Office of Public Affairs 78/01/31 NELSON, J Office of the General Counsel 2pp 16289 045
- 8212010139 Advises that 14 of 25 federal agencies surveyed have partially implemented Recommendation 72-1 re adoption of regulations encouraging broadcast coverage of proceedings involving issues of public interest YORE, J R Atomic Safety and Licensing Board Panel 77/10/03 FOUCHARD, J J Office of Public Affairs 2pp 16289 047
- 8212010141 Recommends that retention or existing policy re use of cameras during adjudicatory hearings Legal challenge to Commission authority to bar cameras would be unsuccessful fwi, if any, federal courts permit use of cameras ROSENTHAL, A S Atomic Safety and Licensing Appeal Panel 77/09/22 FOUCHARD, J J Office of Public Affairs 3pp 16289 049
- 8212010143 SECY-77-374 Obtains Commission guidance re policy concerning use of cameras during licensing hearings FOUCHARD, J J Office of Public Affairs 77/11/11 13pp 16289 052
- 8212010149 Advises of changes in draft Commission paper on camera policy Recommendation section added based upon position indicated Upon receipt of addl comments, paper will be forwarded to Commission for consideration FOUCHARD, J J Office of Public Affairs 77/11/19 ROSENTHAL, A S Atomic Safety and Licensing Appeal Panel YORE, J R Atomic Safety and Licensing Board Panel NELSON, J Office of the General Counsel 10pp 16289 065
- 8212010157 Recommends Ofc of Public Affairs propose to Commission change of procedure & practice that would open limited appearance portion of hearing to coverage by visual media & already established print media & radio coverage ABRAHAM, K Office of Public Affairs 77/05/11 HARRIS, J J Office of Public Affairs 2pp 16289 075
- 8212010159 Forwards memo from C Wisner re camera coverage at A4LB hearings INGRAM, F L Office of Public Affairs 78/07/13 YORE, J Atomic Safety and Licensing Board Panel 1p 16289 077
- 8212010162 Discusses difficulties encountered in camera policy at 780629-30 hearings WISNER, C E Region 4, Dallas, Office of the Director 78/07/07 INGRAM, F Office of Public Affairs 2pp 16289 078
- 8212010168 Comments on NRC trial policy re use of cameras during licensing proceedings New policy is working well HANCHETT, J O Office of Public Affairs 78/06/13 INTERRANTE, J KFRC Radio, San Francisco, CA 1p 16289 080
- 8212010174 Concurs w/ Commission decision to make proceedings of licensing boards open to cameras Requests rpt on how sys is working INTERRANTE, J KFRC Radio, San Francisco, CA 78/06/05 HANCHETT, J NRC - No Detailed Affiliation Given 1p 16289 081

NONDOCKETED ITEMS

- B212010177 Informs that L. Enert of GSA has no objection to use of cameras in US Post Ofc & Federal Bldg in Peoria, IL
INGRAM, F Office of Public Affairs 78/04/07 GDDDHQPE, A Atomic Safety and Licensing Board Panel 1p 16289 082
- B212010180 Informs that Carey has no objection to use of cameras in Auxiliary Courtroom of US Court of Appeals in Everett McKinley Dirksen Bldg Use of Commission trial policy in connection w/facility remand proceeding proposed
INGRAM, F Office of Public Affairs 78/04/11 MILLER, M Atomic Safety and Licensing Board Panel 1p 16289 083
- B212010187 Informs that ASLD requested guidance from Commission re television coverage of portions of Midland proceedings involving discussion of past culpable conduct of individuals Commission should set forth position in matter
KELLEY, J L Office of the General Counsel 78/03/31 HENDRIC, J, GILINSKY, V, KENNEDY, R Commissioners 3pp 16289 084
- B212010196 Informs that Judge KilKenny ofc has no objections to use of cameras during Pebble Springs 780411 prehearing conference in Portland OR Ltr From J Hanchett to A Goodwin encl
INGRAM, F L Office of Public Affairs 78/03/28 YORE, J Atomic Safety and Licensing Board Panel 1p 16289 087
- B212010201 Informs that Judge KilKenny ofc has no objection to use of cameras during Trojan 780417 prehearing conference in Portland, OR
INGRAM, F L Office of Public Affairs 78/03/28 WOLFE, S Atomic Safety and Licensing Board Panel 1p 16289 088
- B212010209 Confirms understanding from previous conversation that television or still cameras may be used by representatives of news media in courtroom during NRC licensing proceeding Press release explaining new Commission policy encl
HANCHETT, J G Office of Public Affairs 78/03/22 GDDDHIN, A U S Court of Appeals 9th Circuit 1p 16289 089
- B212010218 Informs that S Hanchett confirmed that Commission trial camera policy may be implemented in connection w/Pebble Beach evidentiary hearing to be held in Seattle, WA
INGRAM, F Office of Public Affairs 78/03/02 JENSCH, S Atomic Safety and Licensing Board Panel 1p 16289 091
- B212010226 Informs that K Abraham confirmed that Commission trial camera policy may be implemented in all rooms below sixth floor of Middlesex Superior Courthouse in East Cambridge, MA Trial procedures will be in effect for Pilgrim 2 hearing
INGRAM, F Office of Public Affairs 78/03/02 COUFAL, F Atomic Safety and Licensing Board Panel 1p 16289 092
- B212010230 Forwards first cut at Commission paper on camera policy Comments needed as soon as possible Other federal agencies will be checked to determine current camera policy & info will be added to paper
FOUCHARD, J J Office of Public Affairs 77/09/21 YORE, J R Atomic Safety and Licensing Board Panel ROSENTHAL, A S Atomic Safety and Licensing Appeal Panel KELLEY, J L Office of the General Counsel 8pp 16289 093
- B212010235 Informs that cameras will not be permitted in Courtroom 4 of Morris County Courthouse in Morristown, NJ in connection w/ evidentiary hearing re Radiation Technology, Inc Cameras banned from all courtrooms in state
INGRAM, F Office of Public Affairs 78/03/30 JENSCH, S Atomic Safety and Licensing Board Panel 1p 16289 101
- B212010238 Order convening 780503 evidentiary hearing in Morristown, NJ re Radiation Technology, Inc
JENSCH, S W Commissioners 78/03/28 1p 16289 102
- B212010244 Discusses Commission policy on camera coverage of quasi-judicial licensing hearings NRC follows policy of federal courts & regulatory agencies prohibiting camera coverage of hearings while in session
HARRIS, J A Office of Public Affairs 75/10/22 KETTENRING, M WSM-TV, Nashville, TN 1p 16289 103
- B212010249 Requests comments re alternatives open to Commission re camera policy at NRC licensing hearings Alternatives re adherence to present policy of permitting cameras to be used in hearing room before & after sessions discussed
HARRIS, J A Office of Public Affairs 75/04/17 SHAPER, H K Office of the General Counsel GDDDRICH, N H Atomic Safety and Licensing Board Panel 1p 16289 104
- B212010314 FOIA request for SECY-82-303 & SECY-82-318
GRABER, L Affiliation Unknown 82/10/28 Division of Rules and Records 1p 16271 183
- B212010348 Responds to FOIA SECY-82-303 & SECY-82-318 Documents withheld (ref FOIA Exemption 5) App A documents available at PDR
FELTON, J M Division of Rules and Records 82/11/19 GRABER, L Affiliation Unknown 4pp 16271 184
- B212010440 FOIA request for list of all refs cited in reviews of 71 plants under Assignment 13 of contract w/Franklin Research Ctr
WIEBEMANN, R A Westinghouse Electric Corp NS-RAN-82-426 82/10/20 FELTON, J M Division of Rules and Records 1p 16268 201
- B212010446 Responds to FOIA request for list of all refs cited in reviews of 71 plants under Assignment 13 of contract w/Franklin Research Ctr
FELTON, J M Division of Rules and Records NRC-03-B1-118 82/10/26 WIEBEMANN, R A Westinghouse Electric Corp 1p 16268 202
- B212010451 List of all refs cited in reviews of 71 plants under Assignment 13 of NRC Contract 03-B1-118
* Franklin Institute/Franklin Research Center NRC-03-B1-118 82/09/27 714pp 16268 203
- B212020008 Addl response to FOIA request for documents re final rule on environ qualification Forwards App A Documents 12,23,28,35, 41,45,53,65,66,70 & 73 Document 65 listed incorrectly Info completely & partially withheld (ref FOIA Exemption 5)
FELTON, J M Division of Rules and Records 82/11/08 CURRAN, D Harmon & Weiss 7pp 16297 112
- B202180082 Responds to B11214 memo re SECY-B1-304 & B1-603 Draft version of USI A-46 Task Action Plan currently under review w/expected issue date of Mar 1982 Responses of SGRT case-by-case audits listed types of shortcomings
DIRCKS, W J Office of the Executive Director for Operations 82/01/29 AHEARNE, J F Commissioners 1p 16297 175
- B204130511 Requests info re status of 18 plants being considered for continued operation, per SECY-82-91 on environ qualification of electric equipment
AHEARNE, J Commissioners 82/03/15 Office of the Executive Director for Operations 1p 16297 179
- B206220059 Draft Commission paper providing final rule on environ qualification of safety-related electric equipment for nuclear power plants w/o encl
DIRCKS, W J Office of the Executive Director for Operations 82/06/09 3pp 16297 180
- B212020012 Requests that rule be developed to establish criteria & schedules associated w/enviro qualification of Class IE electrical equipment & to address seismic qualification
CHILK, S J Office of the Secretary of the Commission COMNP-B1-1 81/10/20 DIRCKS, W J Office of the Executive Director for Operations 1p 16297 194
- B212020016 Approves proposed rulemaking, "Environ Qualification of Electric Equipment for Nuclear Power Plants"
ROBERTS, T H Commissioners 81/11/30 CHILK, S J Office of the Secretary of the Commission 1p 16297 195
- B212020019 Advises that Commission requested to approve proposed rule to clarify & strengthen criteria for environ qualification of electrical equipment
CHILK, S J Office of the Secretary of the Commission 82/01/06 Office of the Secretary of the Commission 1p 16297 196
- B212020023 Approves proposed rulemaking, "Environ Qualification of Electric Equipment for Nuclear Power Plants" Date for final environ qualification should be end of first refueling outage after Mar 1982
GILINSKY, V Commissioners 81/12/17 CHILK, S J Office of the Secretary of the Commission 1p 16297 197
- B212020056 Notifies of Commission request for draft "Immediately Effective" rule extending 820610 deadline for qualification of electrical equipment Draft should offer choice between extension for specific period & extension w/deadline
CHILK, S J Office of the Secretary of the Commission 82/06/10 DIRCKS, W J Office of the Executive Director for Operations 1p 16297 270
- B212020067 Discusses Commission B20601 briefing on proposed final rule re environ qualification of electrical equipment
CHILK, S J Office of the Secretary of the Commission 82/06/10 Office of the Secretary of the Commission 1p 16297 291

- B212020075 Discusses revisions to final rule, "Environ Qualification of Safety-Related Electric Equipment for Nuclear Power Plants " Revisions re title, specific sections & coding qualification requirements for replacement parts recommended
CHILK, S J Office of the Secretary of the Commission 82/06/25
DIRCKS, W J Office of the Executive Director for Operations 2pp
16297 292
- B212020080 Offers no comments re Commission paper, "Environ Qualification of Electric Equipment Important to Safety for Nuclear Plants "
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/07/12
AGGARWAL, S K Electrical Engineering Branch 1p 16297 294
- B212060410 FOIA request for computer printouts &/or floppy discs re Broad Licensed (02110), Institutional Licensed (02120) & Private Practice Facilities (02200)
SAVINI, R J LIXI, Inc 82/10/22 VACCA, P Uranium Fuel Licensing Branch 1p 16346 007
- B212060415 Responds to FOIA request for computer printouts &/or floppy discs re Broad Licensed (02110), Institutional Licensed (02120) & Private Practice Facilities (02200) Forwards printouts w/o encls
FELTON, J M Division of Rules and Records 82/11/08 SAVINI, R J LIXI, Inc 1p 16346 008
- B212060420 FOIA request for certified copy of IE Bulletin B1-01, "Surveillance of Mechanical Snubbers," for presentation in litigation
WISHNER, J A Sauli, Ewing, Remick & Saul IEB-B1-01 82/11/03
ROBINSON, L Division of Rules and Records 1p 16346 009
- B212060424 Responds to FOIA request for certified copy of IE Bulletin B1-01, "Surveillance of Mechanical Snubbers," for presentation in litigation Forwards certification
FELTON, J M Division of Rules and Records IEB-B1-01 82/11/12
WISHNER, J A Sauli, Ewing, Remick & Saul 1p 16346 010
- B212060427 Certifies IE Bulletin B1-01, "Surveillance of Mechanical Snubbers "
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement CHILK, S J Office of the Secretary of the Commission IEB-B1-01 82/11/10 1p 16346 011
- B212060433 FOIA request for documents re NRC facsimile network, resident inspector site locations & Facsimile Network Monthly Traffic Vol (Representative) for June 1982
BARTON, C Washington Management Group, Inc 82/10/21 NRC - No Detailed Affiliation Given 1p 16346 019
- B212060440 Responds to FOIA request for documents re NRC facsimile network, resident inspector site locations & Facsimile Network Monthly Traffic Vol (Representative) for June 1982 Forwards document
FELTON, J M Division of Rules and Records 82/11/10 BARTON, C Washington Management Group, Inc 1p 16346 020
- B212060445 "NRC Facsimile Network, NRC Resident Inspector Site Locations & NRC Facsimile Network Monthly Traffic Vol (Representative), June 1982 "
* NRC - No Detailed Affiliation Given 82/11/10 3pp
16346 021
- B212060450 FOIA request for documents re NRC investigation of Nuclear Pharmacy, Inc
EMSHWILLER, J R Wall Street Journal 82/10/26 Division of Rules and Records 1p 16346 024
- B212060453 Responds to FOIA request for documents re NRC investigation of Nuclear Pharmacy, Inc Ofc of Inspector & Auditor will make records available per B21119 telcon during wk of 821122
FELTON, J M Division of Rules and Records 82/11/12 EMSHWILLER, J Wall Street Journal 1p 16346 025
- B212070404 FOIA request for statement of work for contract "Explore Effects on Export Trade," awarded to JF Coates, Inc
STEGER, W A Consad Research Corp 82/11/02 Division of Contracts 1p 16356 195
- B212070408 Responds to FOIA request for statement of work for contract "Explore Effects on Export Trade," awarded to JF Coates, Inc No records subj to request located
FELTON, J M Division of Rules and Records 82/11/12 STEGER, W A Consad Research Corp 1p 16356 196
- B212070414 Responds to FOIA request for all records on embrittlement, thermal shock, corrosion & cracking of reactor pressure vessel at facility Records available at PDR
FELTON, J M Division of Rules and Records 82/11/05 QUIGO, C Pollution & Environmental Problems, Inc 4pp 16356 002
- B212070425 Responds to FOIA request for documents re B20809 notice of violation & order imposing civil penalty Forwards App A documents App B documents completely withheld & Documents C1-C4 partially withheld (ref FOIA Exemptions 3, 5 & 7)
FELTON, J M Division of Rules and Records 82/11/05 MCQUARRY, J M Debevoise & Liberman 5pp 16355 003 24X Fiche 50-000, 82/11/05, B212070425
- B212080006 Addl response to FOIA request for seven categories of info re NFB, Erwin, TN facility Forwards App A documents denoted w/asterisk
FELTON, J M Division of Rules and Records 82/10/25 WEISS, E R Harmon & Weiss 36pp 16369 001
- B212080008 Forwards final versions of "Safeguards Upgrade Schedule" & "Working Group Responsibilities "
EVANS, L J Requirements Analysis Branch 77/01/24 JONES, R, MICHAELS, T Office of Standards Development, Director FONNER, R Office of the Executive Legal Director 16pp 16369 258
- B212080010 Forwards general comments on safeguards rule upgrade
CHAMBERS, D S Office of Inspection & Enforcement, Office of the Director 77/02/16 EVANS, L J Requirements Analysis Branch 2pp 16369 274
- B212080011 Comments on 770210 draft of upgraded rules Implication of min essential sys specs unclear
HATTER, B J NRC - No Detailed Affiliation Given 77/02/16
EVANS, L J Requirements Analysis Branch 1p 16369 276
- B212080013 Comments on 770210 memo re status rept of upgrade rule activity
ARSENAULT, F J Division of Safeguards, Fuel Cycle & Environmental Research 77/02/16 EVANS, L J Requirements Analysis Branch 12pp 16369 277
- B212080017 Forwards comments in response to 771220 memo re issues on upgrade rule
GUHIN, M A Assistant Director for Export/Import & International Safeguards 78/01/23 EVANS, L J Requirements Analysis Branch 118pp 16369 289
- B212080027 Forwards paper which develops underlying ideas of containment & use in Basic Capability 4 Paper builds upon 770131 & 0204 papers & presents different approach from 770216 submittal
SPIRO, H J TRW, Inc 77/02/17 EVANS, L J Requirements Analysis Branch 4pp 16370 047
- B212080028 Forwards "Evaluation of Smith-Greenberg Impinger Method for Sampling Soluble Airborne U in Environ " Recommends discontinuing air sampling in environ using method Details of evaluation available for review during subsequent insps
HANSER, W C Nuclear Fuel Services, Inc (subs of Getty Oil Co) 81/06/30 O'REILLY, J P Region 2, Atlanta, Office of the Director (81/03/01) 1p 16369 042
- B212080030 Forwards recommendations for 10CFR73 app re QA for safeguards sys
SPIRO, H J TRW, Inc 77/03/01 EVANS, L J Requirements Analysis Branch 15pp 16370 051
- B212080032 "Evaluation of Smith-Greenberg Impinger Method for Sampling Soluble Airborne U in Environ "
* Nuclear Fuel Services, Inc (subs of Getty Oil Co) 81/06/30 7pp 16369 043
- B212080041 Discusses subcommittee rept on consistency issues arising from comparison of proposed safeguards upgrade rule (73 50) & proposed 73.55
KUNIHIRD, D M Requirements Analysis Branch MILLER, J J Program Support Branch 77/02/16 EVANS, L J Requirements Analysis Branch 6pp 16370 066
- B212080044 Forwards option paper addressing Basic Capability 4 Paper builds upon 770131 & 0204 option papers
BODDE, D L TRW, Inc 77/02/16 EVANS, L J Requirements Analysis Branch 6pp 16370 072
- B212080051 Comments on safeguards upgrade rule Licensees & NRC should develop methods of testing, achievement & maint of functional capabilities
THAYER, T NRC - No Detailed Affiliation Given 77/02/02
EVANS, B NRC - No Detailed Affiliation Given 2pp 16370 078
- B212080056 Discusses characteristics of performance-oriented rule & methods of development
ERICKSON, B. NRC - No Detailed Affiliation Given 77/02/02
EVANS, B NRC - No Detailed Affiliation Given 14pp 16370 080

NONDOCKETED ITEMS

- B212080059 Comments on matl transmitted by 770317 memo re basic capability regulatory provisions & comparison of basic capabilities w/basic essential elements Five capability narratives encl
CHAMBERS, D S Division of Safeguards Inspections 77/03/24
EVANS, L J Requirements Analysis Branch 8pp 16369 035
- B212080061 Forwards drafts of revised basic capability regulatory provisions, basic capability overview, units up, disaggregation of basic capability charts & cross-ref comparison of basic capabilities w/basic essential elements
EVANS, L J Requirements Analysis Branch 77/03/17 NRC - No Detailed Affiliation Given 21pp 16369 064
- B212080065 Forwards comments re interdependence of basic capabilities per 770118 meeting Redundant, independent, mixed mode sys essential due to magnitude of downside risk of safeguards sys w/loopholes
SPIRO, H J TRW, Inc 77/01/21 EVANS, L J NRC - No Detailed Affiliation Given 5pp 16370 094
- B212080066 Forwards drafts of narratives for three basic capabilities for protecting SNM in-transit Drafts are follow-on to 770309 discussions of basic capabilities paper Comments needed by 770317
EVANS, L J Requirements Analysis Branch 77/03/15 NRC - No Detailed Affiliation Given 8pp 16369 084
- B212080070 Forwards comments on structure of basic capabilities per 770112 meeting & subsequent telcons Term "containment" should be broadly defined to include all safeguards-related conditions
BOODE, D L TRW, Inc 77/01/18 POLTERAK, A S NRC - No Detailed Affiliation Given 13pp 16370 099
- B212080076 Comments on issues resulting from public comments re proposed upgrade rule, "Responsibility for Nuclear Security" Intervenor will be influenced by original Congressional intent re NRC safeguards program
BRIGHTSEN, R A Division of Safeguards 77/11/15 BURNETT, R F Division of Safeguards 9pp 16370 112
- B212080079 Comments on Capabilities 1 & 3 of "Basic Capabilities Needed to Protect SNM While in Transit" Discussion of detection sys under Capability 1 inappropriate since detection sys discussed under cargo security of Capability 2
ELLIOTT, J M Program Support Branch 77/03/17 EVANS, L J Requirements Analysis Branch 1p 16369 098
- B212080081 Forwards expanded chart showing applicability of interim & companion rules to MOX fuel cycle & RD&D activities Chart raises important issues re scope of interim rule & definition of Category III Pu
BOODE, D L TRW, Inc 76/04/09 EVANS, L J Division of Safeguards 7pp 16370 121
- B212080084 Comments on draft interim companion rules Consistent ref to SSNM should be made throughout document Use of term "performance criteria" confusing
THAYER, T C NRC - No Detailed Affiliation Given 76/09/14
POWERS, J A NRC - No Detailed Affiliation Given 4pp 16370 128
- B212080088 Discusses 791030 NFS, Erwin meeting concerning results of FBI investigation Rept of investigation dtd 791015 not yet received by NRC
HOWARD, E M Division of Safeguards Inspections 79/11/01
STELLO, V Office of Inspection & Enforcement, Office of the Director 1p 16370 132
- B212080092 Comments on "Basic Capabilities Needed to Protect SNM While in Transit" Capability 2 should allow air & sea transport where escort vehicles not normally used
MICHAELS, T B Materials Protect Standards Branch 77/03/17
EVANS, L J Requirements Analysis Branch 2pp 16369 099
- B212080095 Discusses language for other than performance & sys spec requirements per 770308 memo
KUFFHRO, D M Requirements Analysis Branch 77/03/11 EVANS, L J Requirements Analysis Branch 9pp 16369 101
- B212080099 Recommends proposed license conditions for NFS be adopted All items on inventory should be remeasured regardless of period generated, except matl shipped offsite & independently verified by receiver
STELLO, V Office of Inspection & Enforcement, Office of the Director 79/11/05 BURNETT, R F Division of Safeguards 1p 16370 134
- B212080101 Forwards draft of basic Capability 5 narrative Comments requested by 770314
EVANS, L J Requirements Analysis Branch 77/03/08 CHAMBERS, D S Office of Inspection & Enforcement, Office of the Director
JONES, R, MICHAELS, T Office of Standards Development, Director 4pp 16369 111
- B212080104 Comments on "Basic In-Transit Protection Capabilities" Second capability should be called cargo security instead of physical protection
JONES, R J Materials Protect Standards Branch 77/03/04
EVANS, L S Requirements Analysis Branch 1p 16369 131
- B212080109 Comments on narrative of fifth basic capability per 770301 memo Sections redundant & contain misplaced subfunction statements
JONES, R J Materials Protect Standards Branch 77/03/04
EVANS, L J Requirements Analysis Branch 9pp 16369 132
- B212080111 Forwards revised list identifying basic elements essential for safeguards sys to be effective against design Basis threat
JONES, R J Materials Protect Standards Branch 77/03/08
EVANS, L J Requirements Analysis Branch 4pp 16369 141
- B212080113 Discusses 791105 meeting w/NFS re license conditions Safeguards requirements, including matl control & physical security, will be upgraded
BLAYLOCK, J Division of Safeguards Inspections 79/11/06
CHAPELL, D R Division of Safeguards Inspections 1p 16370 148
- B212080116 Forwards draft "Basic Capabilities for Transportation & Narrative for Basic Capability 4," for comment Comments should relate to whether capabilities would provide coverage of all essential functions
EVANS, L J Requirements Analysis Branch 77/02/24 CHAMBERS, D S Office of Inspection & Enforcement, Office of the Director
JONES, R, MICHAELS, T Office of Standards Development, Director 23pp 16369 145
- B212080117 Discusses Commission 791106 briefing re NFS status FBI investigation uncovered no evidence of illegal employee activity Cause for inventory difference not identified
BLAYLOCK, J Division of Safeguards Inspections 79/11/08
CHAPELL, D R Division of Safeguards Inspections 14pp 16370 139
- B212080126 Discusses basic capabilities for transportation protection of SNM Basic capabilities needed to assure effective response to attempt to steal matl & assure against sabotage
JONES, R J Materials Protect Standards Branch 77/02/24
EVANS, L Requirements Analysis Branch 2pp 16369 168
- B212080129 Advises of B10103 or D104 informal briefing for congressional aides from Oversight Committee in Washington, DC on status of NFS Erwin Briefing requested by Acting Chairman Ahearns in view of recent media interest
HOWARD, E M Division of Safeguards Inspections 79/12/28
STELLO, V Office of Inspection & Enforcement, Office of the Director 1p 16370 153
- B212080133 Requests comments on encl draft "Basic Capabilities for Transportation"
EVANS, L J Requirements Analysis Branch 77/02/16 CHAMBERS, D S Office of Inspection & Enforcement, Office of the Director
JONES, R, MICHAELS, T Office of Standards Development, Director 9pp 16369 170
- B212080137 Comments on 770210 memo to upgrade working group entitled "Status Rept - Upgrade Rule Activity"
ELLIOTT, J M Program Support Branch 77/02/16 EVANS, L J Requirements Analysis Branch 2pp 16369 179
- B212080139 Supplemental PNS-IJ-79-102E on 790924, followup of areas outside protected area identified by aerial measurements sys found not to exceed limits for unrestricted use
CORVELL, G P, TOBIN, W J Region 2, Office of Director 79/09/75 1p 16370 154
- B212080142 Recommends editorial changes for basic capability narratives
ERICSSON, B NRC - No Detailed Affiliation Given 77/02/17
EVANS, B NRC - No Detailed Affiliation Given 1p 16369 181
- B212080146 Comments on draft capability narratives & min essential requirements Basic capability narratives appear complete if coverage assumed in two basic capabilities not presented
JONES, R J Materials Protect Standards Branch 77/02/15
EVANS, L Division of Safeguards 20pp 16369 182

- B212080149 Supplemental PNS-11-79-102K on 791102, initial reinventory efforts resulted in partial reconciliation of 790917 difference Unresolved inventory difference in excess of regulatory limits for continued operation remains
LEE, T D, GILLESPIE, F P Region 2, Atlanta, Office of the Director 79/11/02 1p 16370 155
- B212080161 Forwards status of upgrade rule activity Work proceeding to develop alternative approaches to implementing upgrade
Examples of drafts useful for developing third option re performance requirements encl
EVANS, L J Requirements Analysis Branch 77/02/10 CHAMBERS, D Office of Inspection & Enforcement, Office of the Director JONES, R, MICHAELS, T Office of Standards Development, Director 24pp 16369 202
- B212080167 Requests comments on safeguards upgrade rule structure & first performance capability narrative drafts by 770201
EVANS, L J Requirements Analysis Branch 77/01/26 JONES, R, MICHAELS, T Office of Standards Development, Director FONNER, R Office of the Executive Legal Director 13pp 16369 237
- B212080008 Forwards final versions of "Safeguards Upgrade Schedule" & "Working Group Responsibilities"
EVANS, L J Requirements Analysis Branch 77/01/24 JONES, R, MICHAELS, T Office of Standards Development, Director FONNER, R Office of the Executive Legal Director 16pp 16369 258
- B212080010 Forwards general comments on safeguards rule upgrade
CHAMBERS, D S Office of Inspection & Enforcement, Office of the Director 77/02/16 EVANS, L J Requirements Analysis Branch 2pp 16369 274
- B2120801011 Comments on 770210 draft of upgraded rules Implication of min essential sys specs unclear
HATYER, B J NRC - No Detailed Affiliation Given 77/02/16 EVANS, L J Requirements Analysis Branch 1p 16369 276
- B212080013 Comments on 770210 memo re status rept of upgrade rule activity
ARSENIAULT, F J Division of Safeguards, Fuel Cycle & Environmental Research 77/02/16 EVANS, L J Requirements Analysis Branch 12pp 16369 277
- B212080017 Forwards comments in response to 771220 memo re issues on upgrade rule
GUHILL, M A Assistant Director for Export/Import & International Safeguards 78/01/23 EVANS, L J Requirements Analysis Branch 118pp 16369 289
- B212080027 Forwards paper which develops underlying ideas of containment & use in Basic Capability 4 Paper builds upon 770131 & 0204 papers & presents different approach from 770216 submittal
SPIRO, H J TRW, Inc 77/02/17 EVANS, L J Requirements Analysis Branch 4pp 16370 047
- B212080028 Forwards "Evaluation of Smith-Greenberg Impinger Method for Sampling Soluble Airborne U in Environ" Recommends discontinuing air sampling in environ using method Details of evaluation available for review during subsequent inps
MANSSER, H C Nuclear Fuel Services, Inc (subs of Getty Oil Co) 81/06/30 O'REILLY, J P Region 2, Atlanta, Office of the Director (81/03/01) 1p 16369 042
- B212080030 Forwards recommendations for 10CFR73 app re QA for safeguards sys
SPIRO, H J TRW, Inc 77/03/01 EVANS, L J Requirements Analysis Branch 15pp 16370 051
- B212080032 "Evaluation of Smith-Greenberg Impinger Method for Sampling Soluble Airborne U in Environ"
* Nuclear Fuel Services, Inc (subs of Getty Oil Co) 81/06/30 7pp 16369 043
- B212080041 Discusses subcommittee rept on consistency issues arising from comparison of proposed safeguards upgrade rule (73 50) & proposed 73 55
KUNIHIRO, D M Requirements Analysis Branch MILLER, J J Program Support Branch 77/02/16 EVANS, L J Requirements Analysis Branch 8pp 16370 066
- B212080044 Forwards option paper addressing Basic Capability 4 Paper builds upon 770131 & 0204 option papers
BODDE, D L TRW, Inc 77/02/16 EVANS, L J Requirements Analysis Branch 6pp 16370 072
- B212080051 Comments on safeguards upgrade rule licenses & NRC should develop methods of testing, achievement & maint of functional capabilities
THAYER, T NRC - No Detailed Affiliation Given 77/02/02 EVANS, B NRC - No Detailed Affiliation Given 2pp 16370 078
- B212080056 Discusses characteristics of performance-oriented rule & methods of development
ERICKSON, B NRC - No Detailed Affiliation Given 77/02/02 EVANS, B NRC - No Detailed Affiliation Given 14pp 16370 080
- B212080058 Comments on matl transmitted by 770317 memo re basic capability regulatory provisions & comparison of basic capabilities w/basic essential elements Five capability narratives encl
CHAMBERS, D S Division of Safeguards Inspections 77/03/24 EVANS, L J Requirements Analysis Branch 8pp 16369 055
- B212080061 Forwards drafts of revised basic capability regulatory provisions, basic capability overview writeup, disaggregation of basic capability charts & cross-ref comparison of basic capabilities w/basic essential elements
EVANS, L J Requirements Analysis Branch 77/03/17 NRC - No Detailed Affiliation Given 21pp 16369 064
- B212080065 Forwards comments re interdependence of basic capabilities per 770118 meeting Redundant, independent, mixed mode sys essential due to magnitude of downside risk of safeguards sys w/loopholes
SPIRO, H J TRW, Inc 77/01/21 EVANS, L J NRC - No Detailed Affiliation Given 5pp 16370 094
- B212080066 Forwards drafts of narratives for three basic capabilities for protecting SNM in-transit Drafts are follow-on to 770309 discussions of basic capabilities paper Comments needed by 770317
EVANS, L J Requirements Analysis Branch 77/03/15 NRC - No Detailed Affiliation Given 8pp 16369 084
- B212080070 Forwards comments on structure of basic capabilities per 770112 meeting & subsequent telcons Term "containment" should be broadly defined to include all safeguards-related conditions
BODDE, D L TRW, Inc 77/01/18 POLTERAK, A S NRC - No Detailed Affiliation Given 13pp 16370 099
- B212080076 Comments on issues resulting from public comments re proposed upgrade rule, "Responsibility for Nuclear Security" Intervenor's will be influenced by original Congressional intent re NRC safeguards program
BRIGHTSEN, R A Division of Safeguards 77/11/15 BURNETT, R F Division of Safeguards 9pp 16370 112
- B212080079 Comments on Capabilities 1 & 3 of "Basic Capabilities Needed to Protect SNM While in Transit" Discussion of detection sys under Capability 1 inappropriate since detection sys discussed under cargo security of Capability 2
ELLIOTT, J M Program Support Branch 77/03/17 EVANS, L J Requirements Analysis Branch 1p 16369 098
- B212080081 Forwards expanded chart showing applicability of interim & companion rules to MOX fuel cycle & RD&D activities Chart raises important issues re scope of interim rule & definition of Category III Pu
BODDE, D L TRW, Inc 76/04/09 EVANS, L J Division of Safeguards 7pp 16370 121
- B212080084 Comments on draft interim companion rules Consistent ref to SSNM should be made throughout document Use of term "performance criteria" confusing
THAYER, T C NRC - No Detailed Affiliation Given 76/09/14 POWERS, J A NRC - No Detailed Affiliation Given 4pp 16370 128
- B212080092 Comments on "Basic Capabilities Needed to Protect SNM While in Transit" Capability 2 should allow air & sea transport where escort vehicles not normally used
MICHAELS, T S Materials Protect Standards Branch 77/03/17 EVANS, L J Requirements Analysis Branch 2pp 16369 099
- B212080095 Discusses language for other than performance & sys spec requirements per 770308 memo
KUNIHIRO, D M Requirements Analysis Branch 77/03/11 EVANS, L J Requirements Analysis Branch 9pp 16369 101
- B212080101 Forwards draft of basic Capability 5 narrative Comments requested by 770314
EVANS, L J Requirements Analysis Branch 77/03/08 CHAMBERS, D Office of Inspection & Enforcement, Office of the Director JONES, R, MICHAELS, T Office of Standards Development, Director 4pp 16369 111
- B212080104 Comments on "Basic In-Transit Protection Capabilities" Second capability should be called cargo security instead of physical protection
JONES, R J Materials Protect Standards Branch 77/03/04 EVANS, L S Requirements Analysis Branch 1p 16369 131

NONDOCKETED ITEMS

- B212080107 Comments on narrative of fifth basic capability per 770302 memo Sections redundant & contain misplaced subfunction statements
JONES, R J Materials Protect Standards Branch 77/03/04
EVANS, L J Requirements Analysis Branch 9pp 16369 132
- B212080111 Forwards revised list identifying basic elements essential for safeguards sys to be effective against design basis threat
JONES, R J Materials Protect Standards Branch 77/03/08
EVANS, L J Requirements Analysis Branch 4pp 16369 141
- B212080116 Forwards draft "Basic Capabilities for Transportation & Narrative for Basic Capability 4," for comment Comments should relate to whether capabilities would provide coverage of all essential functions
EVANS, L J Requirements Analysis Branch 77/02/24 CHAMBERS, O
Office of Inspection & Enforcement, Office of the Director
JONES, R J, MICHAELS, T Office of Standards Development, Director 23pp 16369 145
- B212080126 Discusses basic capabilities for transportation protection of SNM Basic capabilities needed to assure effective response to attempt to steal matl & assure against sabotage
JONES, R J Materials Protect Standards Branch 77/02/24
EVANS, L J Requirements Analysis Branch 2pp 16369 168
- B212080133 Requests comments on encl draft "Basic Capabilities for Transportation"
EVANS, L J Requirements Analysis Branch 77/02/16 CHAMBERS, O
Office of Inspection & Enforcement, Office of the Director
JONES, R J, MICHAELS, T Office of Standards Development, Director 9pp 16369 170
- B212080137 Comments on 770210 memo to upgrade working group entitled "Status Rept - Upgrade Rule Activity"
ELLIGTT, J M Program Support Branch 77/02/16 EVANS, L J
Requirements Analysis Branch 2pp 16369 179
- B212080139 Supplemental PNS-II-79-102E on 790924, followup of areas outside protected area identified by aerial measurements sys found not to exceed limits for unrestricted use
CORVELL, O P, TOBIN, W J Region 2, Office of the Director 79/09/29
1p 16370 134
- B212080142 Recommends editorial changes for basic capability narratives
ERICKSON, B NRC - No Detailed Affiliation Given 77/02/17
EVANS, B NRC - No Detailed Affiliation Given 1p 16369 181
- B212080146 Comments on draft capability narratives & min essential requirements Basic capability narratives appear complete if coverage assumed in two basic capabilities not presented
JONES, R J Materials Protect Standards Branch 77/02/15
EVANS, L J Division of Safeguards 20pp 16369 182
- B212080149 Supplemental PNS-II-79-102K on 791102, initial reinventory results resulted in partial reconciliation of 790917 difference Unresolved inventory difference in excess of regulatory limits for continued operation remains
LEE, T D, GILLESPIE, F P Region 2, Atlanta, Office of the Director 79/11/02 1p 16370 155
- B212080161 Forwards status of upgrade rule activity Work proceeding to develop alternative approaches to implementing upgrade Examples of drafts useful for developing third option re performance requirements encl
EVANS, L J Requirements Analysis Branch 77/02/10 CHAMBERS, O
Office of Inspection & Enforcement, Office of the Director
JONES, R J, MICHAELS, T Office of Standards Development, Director 24pp 16369 202
- B212080167 Requests comments on safeguards upgrade rule structure & first performance capability narrative drafts by 770201
EVANS, L J Requirements Analysis Branch 77/01/26 JONES, R J
MICHAELS, T Office of Standards Development, Director FONNER, R
Office of the Executive Legal Director 13pp 16369 237
- B212090048 Responds to FOIA request for SECYs Forwards SECY-82-23, SECY-82-42, SECY-82-136, SECY-82-137, SECY-82-286 & SECY-82-315, SECY-81-600A available in PDR Review of SECY-81-622A, SECY-82-197A & SECY-82-197B continuing
FELTON, J M Division of Rules and Records 82/10/20 GRABER, L
Affiliation Unknown 1p 16384 295
- B202010383 SECY-82-023
Requests Commission approval of denial of petition that licensee be held responsible for emergency planning & response to transportation on accidents involving radioactive matl. Draft FR notices, proposed rule & ltrs encl
DIRCKS, W J Office of the Executive Director for Operations 82/01/18, 88pp 16384 301
- B203090677 SECY-82-042
Requests approval of proposed amend to existing Section 274b agreement w/State of TX Proposed agreement, proposed FR notice, staff analysis of comments, proposed press release & proposed ltr to governor encl
DIRCKS, W J Office of the Executive Director for Operations 82/02/01 30pp 16385 029
- B204160262 SECY-82-137
Recommends that Commission approve AD recommendation re major deficiencies in mgt controls at nuclear power plant Draft FR notice encl
DIRCKS, W J Office of the Executive Director for Operations 82/03/30 9pp 16385 080
- B204160270 SECY-82-136
Seeks Commission approval of AD determination re blockage of coolant flow to safety-related sys & components Draft FR notice encl
DIRCKS, W J Office of the Executive Director for Operations 82/03/30 19pp 16385 060
- B209280513 SECY-82-315
Requests Commission approve publication of for comment NUREG-0906, "Guidance for Implementation of 10CFR50.34(g)" Section requires applicants to evaluate differences from SRP
DIRCKS, W J Office of the Executive Director for Operations 82/07/26 16pp 16385 166
- B212090052 Advises that Commission has approved B20429 request to withdraw SECY-82-23 pending resolution of NY City/NY State lawsuit against DDT on highway routing & proposed rider on DDT FYB2 authorization bill being considered in Congress
CHILK, S J Office of the Secretary of the Commission 82/05/27
DIRCKS, W J Office of the Executive Director for Operations 16384 296
- B212090065 Advises that Commission has approved proposed amend to existing Section 274b Agreement w/TX Ofc of State Programs informed of action by telephone on 820226 Agreement should be forwarded for signature of Chairman Palladino by 820312
CHILK, S J Office of the Secretary of the Commission 82-042
82/02/26 DIRCKS, W J Office of the Executive Director for Operations 1p 16385 028
- B212090209 Advises that Commission has approved proposed AD recommendation re blockage of coolant flow to safety-related sys & component & FR notice FR notice should be forwarded to Ofc of Secretary for publication by 820511
CHILK, S J Office of the Secretary of the Commission 82/04/27
DIRCKS, W J Office of the Executive Director for Operations 1p 16385 059
- B212090210 Advises that Commission has approved modified proposed AD recommendation re major deficiencies in mgt FR notice should be prepared & forwarded for publication
CHILK, S J Office of the Secretary of the Commission 82/06/04
DIRCKS, W J Office of the Executive Director for Operations 1p 16385 079
- B212090224 SECY-82-286
Recommends that Commission approve publication of proposed rulemaking re staffing at nuclear power plants
DIRCKS, W J Office of the Executive Director for Operations 82/07/02 72pp 16385 093
- B212090230 Advises that Commission has approved recommendation that NUREG-0906, "Guidance for Implementation of 10CFR50.34(g)," be published for comment in FR & sent to appropriate Congressional committees, reactor licensees & applicants
CHILK, S J Office of the Secretary of the Commission 82/08/24
DIRCKS, W J Office of the Executive Director for Operations 1p 16385 165
- B212100049 FOIA request for listing of existing major contracts, excluding grants & small procurements or purchase orders administered by NRC Listing should include outlined info
CHAMBLEE, J A Affiliation Unknown 82/11/07 Division of Rules and Records 1p 16400 214
- B212100051 Responds to FOIA request for listing of existing major contracts, excluding grants & small procurements or purchase orders administered by NRC Forwards computer listing dtd 821112 Document also available in PDR
FELTON, J M Division of Rules and Records 82/11/18 CHAMBLEE, J A
Affiliation Unknown 1p 16400 215
- B212100055 Sequential listing of existing major contracts, excluding grants & small procurements or purchase orders administered by NRC
* NRC - No Detailed Affiliation Given 82/11/12 96pp 16400 216

- 8212100053 Responds to FOIA request for eight listed documents
Forwards documents listed in app Items 5, 6 & 8 available in
PDR
FELTON, J M Division of Rules and Records 82/11/09 CONNOR, L
Doc-Search Associates 2pp 16388 228
- 8001110507 Task Action Plan A-43 "Containment Emergency Sump
Performance "
* Division of Reactor Safety Research 79/09/17 13pp
16388 250
- 8001230275 Task action plan A-44 "Station Blackout "
* TMI-2 Unresolved Safety Issues Task Force 80/01/31 7pp
16388 263
- 8102200777 Forwards approved Task Action Plan A-43, "Containment
Emergency Sump Performance " Completion date scheduled for
Sept 1983
SHAD, L Division of Reactor Safety Research 81/01/16
DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp
16388 230
- 8102200784 Task Action Plan A-43 "Containment Emergency Sump
Performance "
* Division of Reactor Safety Research 81/01/16 13pp
16388 232
- 8206070020 Forwards task action plan for Unresolved Safety Issue (USI)
A-47, "Safety Implications of Control Sys" for concurrence
prior to final approval Projected completion date for draft
NUREG for public comment is Jan 1984
HANAUER, S H Division of Safety Technology 82/05/19
EISENHUT, D O Division of Licensing 25pp 16389 010
- 8206070028 Forwards task action plan for Unresolved Safety Issue (USI)
A-47, "Safety Implications of Control Sys", for concurrence
prior to final approval Projected completion date for draft
NUREG for public comment is Jan 1984
HANAUER, S H Division of Systems Integration (post 811005)
82/05/19 GOLLER, K R Division of Facility Operations 25pp
16389 012
- 8206220070 Advises that encl Revision 1 to Task Action Plan A-45,
"Shutdown Decay Heat Removal Requirements," reviewed &
approved by Div of Safety Technology Draft NUREG w/proposed
recommendations can be available by Nov 1984
HANAUER, S H Division of Safety Technology 82/06/02
DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp
16388 264
- 8206220072 Revision 1 to Task Action Plan A-45, "Shutdown Decay Heat
Removal Requirements "
MARCHESE, A R Generic Issues Branch 82/06/02 49pp 16388 286
- 8207120252 Forwards approved task action plan for Unresolved Safety
Issue A-46 to develop guidelines & acceptance criteria for
seismic & dynamic qualifications of mechanical & electrical
equipment
HANAUER, S H Division of Safety Technology 82/05/19
DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp
16389 037
- 8212100179 Task Action Plan A-46 "Seismic Qualification of Equipment
in Operating Plants "
* Division of Safety Technology 82/05/19 13pp 16389 039
- G/12100084 Responds to FOIA request for documents & records prepared by
Energy, Inc re NRC rulemaking on ATWS Forwards documents
listed in App A
FELTON, J M Division of Rules and Records 82/11/01 EARLEY, A F
Huntan & Williams 2pp 16400 012
- 8212100086 Draft "Preliminary Evaluation of Comments of Util Group on
ATWS "
* Energy Incorporated 82/09/03 NRC - No Detailed Affiliation
Given 63pp 16400 014
- 8212100089 "Evaluation of Comments of Util Group on ATWS "
* Energy Incorporated 82/10/31 NRC - No Detailed Affiliation
Given 63pp 16400 083
- 8212100111 Responds to FOIA request for seven categories of info re
NFS, Erwin, TN Forwards documents listed in App A Documents
listed in App B withheld (ref FOIA Exemptions 3 & 5)
FELTON, J M Division of Rules and Records 82/11/12 WEISS, E R
Harmon & Weiss 4pp 16388 157
- 8212100121 Forwards addl comments on proposed license conditions for
NFS-Erwin re emergency preparedness
GRIMES, B K Division of Emergency Preparedness 82/03/23
PAGE, R O Uranium Fuel Licensing Branch 1p 16388 164
- 8212100128 Act receipt of 820225 concerns re timeliness of alerting &
notifying nearby residents in event of certain type of
emergency at NFS, Inc Emergency planning license conditions
for NFS discussed
TROJANOWSKI, R Region 2, Office of Director 82/03/12
GRAHAM, J A Tennessee, State of 2pp 16388 165
- 8212100138 Concurs w/final amend to 10CFR70 & 73, "Strengthened
Physical Protection Requirements for Fuel Cycle Facilities &
Transportation Involving Formula Quantities of Strategic
SNM " Executive Branch comments to be forwarded
SHEA, J R Office of International Programs, Director 79/01/25
GOLLER, K K Division of Siting, Health & Safeguards Standards
1p 16388 167
- 8212100142 Responds to G McCorkle 780117 comments re upgrade rule re
transport protection requirements Unarmored vehicle escort,
tactical needs & transportation points discussed
NULSEN, B Requirements Analysis Branch 78/01/27 EVANS, L J
Requirements Analysis Branch 2pp 16388 168
- 8212100147 Comments on Sandia rept per Nulsen 780117 memo re upgrade
rule re transport protection requirements Rept does not
consider possible actions by insider in collusion
w/adversary force
MCCORKLE, O W Physical Security Licensing Branch 78/01/23
EVANS, L J Requirements Analysis Branch 1p 16388 170
- 8212100155 Submits recommendation to change physical protection upgrade
rule requirements to nine armed guards & two armored vehicle
escorts for in-transit physical protection
NULSEN, C K NRC - No Detailed Affiliation Given 78/01/17
EVANS, L J Requirements Analysis Branch 3pp 16388 171
- 8212100158 "Convoy Security Upgrades "
* Sandia Laboratories 78/01/17 NRC - No Detailed Affiliation
Given 11pp 16388 174
- 8212100164 Forwards response to request for development of regulatory
changes to safeguards upgrade rule to provide protection
against internal threats Requirements developed in response
to S Chilk 780426 memo re 780420 briefing to Commission
JONES, R J Materials Protect Standards Branch 78/05/05
MCCORKLE, O Physical Security Licensing Branch 4pp 16388 185
- 8212100168 Discusses incorporation of NRC comments into upgrade rule
guidance documents Outline for allocation of outstanding
tasks encl
EVANS, L J Requirements Analysis Branch 79/01/10 JONES, R J
Safeguards Standards Branch 2pp 16388 191
- 8212100185 Forwards draft cover memo for final version of major issues
& NRC positions re physical protection Draft issues for
policy decision encl
EVANS, L J Requirements Analysis Branch 77/12/29 JONES, R
Materials Protect Standards Branch 12pp 16388 194
- 8212100189 Forwards preliminary recommended upgrade rule changes &
considerations for inclusion in paper to Commission
EVANS, L J Requirements Analysis Branch 78/01/11 JONES, R
Materials Protect Standards Branch 20pp 16388 206
- 8212100138 Concurs w/final amend to 10CFR70 & 73, "Strengthened
Physical Protection Requirements for Fuel Cycle Facilities &
Transportation Involving Formula Quantities of Strategic
SNM " Executive Branch comments to be forwarded
SHEA, J R Office of International Programs, Director 79/01/25
GOLLER, K K Division of Siting, Health & Safeguards Standards
1p 16388 167
- 8212100142 Responds to G McCorkle 780117 comments re upgrade rule re
transport protection requirements Unarmored vehicle escort,
tactical needs & transportation points discussed
NULSEN, B Requirements Analysis Branch 78/01/27 EVANS, L J
Requirements Analysis Branch 2pp 16388 168
- 8212100147 Comments on Sandia rept per Nulsen 780117 memo re upgrade
rule re transport protection requirements Rept does not
consider possible actions by insider in collusion
w/adversary force
MCCORKLE, O W Physical Security Licensing Branch 78/01/23
EVANS, L J Requirements Analysis Branch 1p 16388 170
- 8212100155 Submits recommendation to change physical protection upgrade
rule requirements to nine armed guards & two armored vehicle
escorts for in-transit physical protection
NULSEN, C K NRC - No Detailed Affiliation Given 78/01/17
EVANS, L J Requirements Analysis Branch 3pp 16388 171
- 8212100158 "Convoy Security Upgrades "
* Sandia Laboratories 78/01/17 NRC - No Detailed Affiliation
Given 11pp 16388 174

NONDOCKETED ITEMS

- B212100164 Forwards response to request for development of regulatory changes to safeguards upgrade rule to provide protection against internal threats Requirements developed in response to S Chik 780426 memo re 780420 briefing to Commission JONES, R J Materials Protect Standards Branch 78/05/05 MCCORKLE, Q Physical Security Licensing Branch 6pp 16388 185
- B212100168 Discusses incorporation of NRC comments into upgrade rule guidance documents Outline for allocation of outstanding tasks encl
EVANS, L J Requirements Analysis Branch 79/01/10 JONES, R J Safeguards Standards Branch 2pp 16388 191
- B212100185 Forwards draft cover memo for final version of major issues & NRC positions re physical protection Draft issues for policy decision encl
EVANS, L J Requirements Analysis Branch 77/12/29 JONES, R Materials Protect Standards Branch 12pp 16388 194
- B212100189 Forwards preliminary recommended upgrade rule changes & considerations for inclusion in paper to Commission
EVANS, L J Requirements Analysis Branch 78/01/11 JONES, R Materials Protect Standards Branch 20pp 16388 206
- B212100358 FOIA request for listing of total quantities of microcomputers & word processing equipment either rented or purchased in FY82
GROSS, M E Xerox Corp 82/10/25 Division of Rules and Records 1p 16400 350
- B212100362 Responds to FOIA request for listing of total quantities of microcomputers & word processing equipment either rented or purchased in FY82 Listing encl
FELTON, J M Division of Rules and Records 82/11/18 GROSS, M E Xerox Corp 1p 16400 351
- B212100369 "FY82 Equipment Acquisitions - Word Processors & Microcomputers"
* NRC - No Detailed Affiliation Given 82/11/18 1p 16400 352
- B212100371 FOIA request for documents re fuel & shipment of fuel to Savannah River in State of SC
LOWENTHAL, N Sierra Club 82/10/27 Division of Rules and Records 1p 16400 348
- B212100374 Responds to FOIA request for documents re fuel & shipment of fuel to Savannah River in State of SC Documents not located Info may be available from DOE
FELTON, J M Division of Rules and Records 82/11/16 LOWENTHAL, N Sierra Club 1p 16400 349
- B212100378 FOIA request for identity of plants for which ASLB has assigned ME Miller, KA McCollom & RF Cole & listing of FOIA requests released on named individuals
LODGE, B Dallas Morning News 82/10/18 Office of Public Affairs 1p 16400 331
- B212100381 Responds to FOIA request for identity of plants for which ASLB has assigned ME Miller, KA McCollom & RF Cole & listing of FOIA requests released on named individuals Forwards requested info
FELTON, J M Division of Rules and Records 82/11/16 LODGE, W Dallas Morning News 1p 16400 332
- B212100383 Listing of plants on which ME Miller, KA McCollom & RF Cole have served
* NRC - No Detailed Affiliation Given 82/11/16 3pp 16400 333
- B212100387 Responds to FOIA requests for seven categories of documents re facility Document 1 listed in app withheld (ref Exemption 3) Forwards Document 2 & portions of Document 1 Documents available in PDR
FELTON, J M Division of Rules and Records 82/11/15 WEISS, E R Harmon & Weiss 3pp 16400 312
- B212100395 Responds to FOIA request for documents re implementation of employee protection provisions in Section 210 of Energy Reorganization Act of 1974 Memorandum of understanding between NRC & Dept of Labor encl
FELTON, J M Division of Rules and Records 82/11/15 MARCOUX, W C LeBoeuf, Lamb, Leiby & MacRae 1p 16400 325
- B212100398 Memorandum of understanding between NRC & Dept of Labor re implementation of employee protection provisions in Section 210 of Energy Reorganization Act of 1974
DIRCKS, W J Office of the Executive Director for Operations OTTER, W M Labor, Dept of 82/10/25 4pp 16400 326
- B212100404 FOIA request for SECY-77-539 re conversion of provisional OLs to full-term licenses
GRABER, L Affiliation Unknown 82/11/01 Division of Rules and Records 1p 16400 323
- B212100408 Responds to FOIA request for SECY-77-539 re conversion of provisional OLs to full-term licenses Document available in PDR
FELTON, J M Division of Rules and Records 82/11/15 GRABER, L Affiliation Unknown 1p 16400 324
- B212100412 Responds to FOIA request for two documents referenced in SECY-82-111, Page 24 Forwards documents listed in App A Documents available in PDR
FELTON, J M Division of Rules and Records 82/11/15 GRABER, L Affiliation Unknown 2pp 16400 334
- B103120528 Expresses concern w/SECY-81-19 re emergency response facilities Issuance of paper indicative of increasingly confusing structure of NRC legal requirements Features that implement current regulation should be issued in reg guide
MALSCH, M Q Office of the General Counsel 81/01/30 ANEARN, L J Commissioners 3pp 16400 360
- B10310251 Notifies that NRC should proceed w/issuance of NUREG-0137, Item III A 12 re emergency operations facility Commission does not have preference for either Option 2 or Option 4 referenced in NRC B0112 response to B01030 meeting
CHILK, S J Office of the Secretary of the Commission COMJA-80-37 81/01/21 DIRCKS, W J Office of the Executive Director for Operations 3pp 16400 356
- B104100175 Advises of Commission approval of proposed NUREG-0646 sub j to modifications to reflect decisions in B10121 memo, more explicit seismic qualification discussion indication that NUREG provides general guidance only
CHILK, S J Office of the Secretary of the Commission 81/01/19 DIRCKS, W J Office of the Executive Director for Operations 1p 16400 359
- B212140001 Addl response to FOIA request for five categories of documents re SEP Forwards documents listed in App A No documents located sub j to Item 3 of request Review of remaining documents continuing Documents available in PDR
FELTON, J M Division of Rules and Records 82/11/03 GALL, J Lham, Lincoln & Deale 2pp 16433 354 24X Fiche 50-000, 82/11/03, B212140001
- B005070778 Forwards input to SEP Topics III-6 & III-11, consisting of NUREG/CR-0891, "Seismic Review for SEP" & EGG-CA-8065, "Summary of Piping Calculations Performed for SEP" Repts should be transmitted to licensee NUREG only encl
CRUTCHFIELD, D Systematic Evaluation Program Branch 80/04/14 ZIEHANN, D L Systematic Evaluation Program Branch 2pp 16435 183 24X Fiche 50-000, 82/11/03, B212140001
- B009050320 Submits proposal for seismic review of selected plants for SEP Provides detailed breakdown of \$810,000 cost estimate Lab personnel & facilities available per DOE Contract W-7405-ENG-48 w/Univ of CA
SHEPARD, J C Lawrence Livermore Laboratory FIN A-0233-7 80/08/22 DENTON, H R Office of Nuclear Reactor Regulation, Director 6pp 16435 072
- B009180414 Discusses B00604 presentations before ACRS Subcommittee on Extreme External Phenomena re status of SEP site spectra project & initial recommendations
CRUTCHFIELD, D Systematic Evaluation Program Branch 80/06/06 LAING, G C Plant Systems Branch (Pre 791030) 1p 16436 249
- B101080118 Trip rept of B0117-19 site visit to observe site-specific features re SEP structural, electrical & sys topic review Related info encl
MICHAELS, T S Technical Support Branch 80/12/17 RUSSELL, W T Technical Support Branch 17pp 16436 120 24X Fiche 50-000, 82/11/03, B212140001
- B104230080 Advises that structural elements & review areas noted need not be considered part of NRC-03-77-118 Section 3 B of SRP defines structures to be considered
PERBINKO, D Systematic Evaluation Program Branch NRC-03-77-118 B1/04/14 STILLWELL Franklin Institute/Franklin Research Center 2pp 16434 274
- B105110512 Forwards two consultant repts & list of open items re SEP Topics III-6 re seismic design consideration & III-11 re component integrity w/o consultant repts
CRUTCHFIELD, D Operating Reactors Branch 5 L805-81-03-048 B1/03/20 FINFROCK, I R Public Service Electric & Gas Co of New Jersey 3pp 16434 261 24X Fiche 50-000, 82/11/03, B212140001.

- B109210340 Discusses factors impinging on finalization of site-specific spectra program Results of second questionnaire, reduction of spectra at rock sites & Vol I, executive summary, needed from LLL & TERA before start of final review
JACKSON, R E Geosciences Branch 81/02/03 KNIGHT, J P Assistant Director for Components & Structures Engineering 2pp 16437 281
- B109230665 Requests audit review of Geosciences Branch seismic reanalysis program for finalization of site-specific spectra by Feb 1981
LAINAS, O C Assistant Director for Safety Assessment 81/01/28 KNIGHT, J P Assistant Director for Components & Structures Engineering 1p 16436 298
- B201180567 Forwards Mechanical Engineering Branch review of SEP Topic III-5 B, "High Energy Line Break Outside Containment" High energy line break analysis of auxiliary feedwater sys to be included in licensee response to NUREG-0737 Item II E 1 I
KNIGHT, J P Assistant Director for Components & Structures Engineering IEB-79-14 81/12/24 LAINAS, O C Assistant Director for Safety Assessment 10pp 16436 067. 24X Fiche 80-000, 82/11/03, B212140001
- B202180460 Forwards Revision 1 to evaluation rept on SEP Topic VI-4, "Containment Isolation Sys." for facility Rept considers util comments received in 810810 & 820104 ltrs Conclusions of original rept remain unchanged
SPEIS, T P Assistant Director for Reactor Safety 82/01/27 LAINAS, O C Assistant Director for Safety Assessment 43pp 16436 078 24X Fiche 50-000, 82/11/03, B212140001
- B203010313 Monthly Mgt Ltr 7, Jan 1982 re systematic evaluation program
NELSON, T A, SMITH, P D Lawrence Livermore Laboratory FIN A-0436 SM-82-31 82/02/12 EISENHUT, D O Division of Licensing 5pp 16434 312
- B204010021 Forwards evaluation for SEP Topic VI-4, "Containment Isolation Sys." Outstanding items include insufficient isolation provisions in test, vent & drain lines & no isolation or leak detection provisions on ECCS subsystem
SPEIS, T P Assistant Director for Reactor Safety 82/03/24 LAINAS, O C Assistant Director for Safety Assessment 34pp 16434 329 24X Fiche 50-000, 82/11/03, B212140001
- B205040451 "SEP," Monthly Mgt Ltr 9 for Mar 1982
NELSON, T A, SMITH, P D Lawrence Livermore Laboratory FIN A-0436 SM 82-112/0298M 82/04/28 EISENHUT, D O Division of Licensing 4pp 16434 291
- B205240413 "Review of Seismic-Related Topics of Selected Operating Plants for SEP," Monthly Mgt Ltr 10 for Apr 1982
LO, T Y, SMITH, P D Lawrence Livermore Laboratory FIN A-0436 SM 82-135/0298M 82/05/17 EISENHUT, D O Division of Licensing 4pp 16434 295
- B205270590 Forwards std order for DDE work, "Review of Seismic-Related Topics of Selected Operating Plants for SEP," w/ revised statement of work, reflecting mods suggested in DDE B20322 ltr
EISENHUT, D O Division of Licensing FIN A-0436 82/04/26 LAORONE, J B Energy, Dept of 3pp 16434 281
- B206290144 "SEP," Monthly Mgt Ltr 11 for May 1982
LO, T Y, SMITH, P D Lawrence Livermore Laboratory FIN A-0436 SM 82-168/0298M 82/06/17 EISENHUT, D O Division of Licensing 4pp 16434 317
- B207280369 Lists recommendations re guidelines for seismic evaluation criteria for SEP Group II plants
BOSNAK, R J Mechanical Engineering Branch 82/07/15 CRUTCHFIELD, D Operating Reactors Branch 5 1p 16434 299
- B208030436 "Technical Assistance for SEP," Monthly Mgt Ltr 12 for June 1982
LO, T Y, SMITH, P D Lawrence Livermore Laboratory, FIN A-0436 SM 82-200/0298M 82/07/23 EISENHUT, D O Division of Licensing 4pp 16434 308
- B212140015 Computer printout listing SEP documents
* Planning Research Corp 82/09/02 210pp 16433 358
- B212140022 Computer printout listing documents re SEP Topic III-6
* Planning Research Corp 82/09/01 32pp 16434 208
- B212140161 Requests participation in review of probability & statistics aspects of listed consultant repts on seismic hazard analysis
EISENHUT, D O Division of Operating Reactors 79/10/17 HALLER, N M Office of Management and Program Analysis. ROWSONE, F Probabilistic Analysis Branch (Pre 791030) 2pp 16436 304.
- B212160080 Addl response to FOIA request for records re receipt, processing, storage or removal of source matl at Canonsburg, PA, Vitro Mfg Co & Vitro Rare Metals Co Forwards documents listed in App A Remaining info under review
FELTON, J M Division of Rules and Records 82/09/30 BLACK, A E Buchanan, Ingersoll, Rodewald, Kyle & Buerger 7pp 16447 312
- B212160090 Forwards 610512 & 29 & 630715 ltrs from Vitro Corp of America to AEC & 610526 & 630814 ltrs from AEC to Vitro Ltrs re Vitro recent license amend will be forwarded to PA State Health Dept W/o encls
NUSBAUMER, D A Atomic Energy Commission 35293 63/11/08 DENNIS, J M Affiliation Unknown 1p 16448 246
- B212160094 Draft "Radiological Survey Plan-Vitro Corp of America Canonsburg, PA." Phase I
* Vitro Engineering Co 82/09/30 5pp 16447 323
- B212160103 PNO-77-008 draft press release re radiation detected near premises of former AEC contractor/licensee in Canonsburg, PA forwarded Site will be surveyed by ERDA, starting 770112 W/o encl Related info encl
SMITH, G H, ROY, G W, THOMPSON, D Director's Office, Office of Inspection and Enforcement 77/01/11 22pp 16447 328
- B212160160 Advises that ID Analysis Branch has been contacted & has agreed to analyze samples for U-Th-230 & Ra-226 Samples w/identifying descriptions or number should be forwarded to CW 9111
ROEDER, J Atomic Energy Commission TT 218 63/10/15 KIRKMAN, R H Atomic Energy Commission 1p 16448 273
- B212160323 Application for source matl license for possession of 4,374 572 tons of Port Hope residues containing 32,193 lbs of U-308 stockpiled at Canonsburg PA
GENTILE, A B Vitro Engineering Co 60/02/10 1p 16448 064
- B212160343 Forwards License R-129 & licensee 560808 ltr to Div of Licensing & Regulation, per 630314 telcon
ROEDER, J R Atomic Energy Commission 63/03/14 JOHNSTON, W D Atomic Energy Commission 1p 16448 318
- B212160370 Confirms 650615 telcon re burial of U bearing residues at facility Removal of U residues not begun but state has given permission Effort may not be completed until Sept. 1985
BROCKETT, T W Atomic Energy Commission 65/06/15 KIRKMAN, R W, WALKER, D I, SMITH, R W Atomic Energy Commission 1p 16448 073
- B212160372 Source Matl License RI-177 for Vitro Corp of America, authorizing use of 45,000 lbs containing residues through import from Canada
JOHNSON, L Atomic Energy Commission 56/04/27 1p 16448 321
- B212160380 Application for source matl license to import 22-1/2 tons milling byproduct residual matl from Canada Moisture gross weight is 50% Matl contains 0.5% U-308
LITTEL, E O Vitro Engineering Co 56/04/26 Atomic Energy Commission 2pp 16448 322
- B212160386 Source Matl License RI-168 for Vitro Corp of America, authorizing use of 100,000 lbs of U containing residues through import from Canada
JOHNSON, L Atomic Energy Commission 55/11/15 1p 16448 324
- B212160388 Discusses burial of U bearing residues at Canonsburg, PA by Vitro Corp of America State must issue permit Region 1 will make closeout check survey
DUBINSKI, L Atomic Energy Commission 65/03/10 KIRKMAN, R W, WALKER, D I, SMITH, R W Atomic Energy Commission 1p 16448 074
- B212160391 Application for source matl license to import one carload milling byproduct residue matl from Canada Wet matl has max weight of 100,000 lbs
LITTEL, E O Vitro Engineering Co 55/11/14 JOHNSON, L Atomic Energy Commission 2pp 16448 325
- B212160477 Discusses capabilities of Ionics, Inc to perform analytical analyses Tailing results varied by factors up to 470 times higher than analyses performed on duplicate samples analyzed
ROEDER, J R Atomic Energy Commission 64/02/12 DUBINSKI, L Atomic Energy Commission 1p 16448 166
- B212160493 Informs that insp of Licenses C-4269, C-4625 & R-179 was scheduled before learning facility was closed down Radioactive matl in rear yard Arrangements for insp can be scheduled through CD Brennan
EPSTEIN, E Atomic Energy Commission 61/02/09 KLEVIN, P B Atomic Energy Commission 2pp 16449 005

NONDOCKETED ITEMS

- B212160500 Submits info re disposal of source matl under Licenses R-179, C-4269 & C-4625 Thorium oxide covered under License C-4269 transferred to Atlantic Research Corp in Alexandria, VA
RCSBINS, E B Vitro Engineering Co 61/01/30 EPSTEIN, E Atomic Energy Commission 3pp 16449 007
- B212160541 Application for source matl license to receive 300 lbs thorium-bearing residues containing 13 lbs thorium from Natl Lead Co Matl consists of six types to be used for lab tests
LITTEL, E O Vitro Engineering Co 57/09/03 DOULOS, N Atomic Energy Commission 1p 16449 016
- B212160592 Advises that repts re disposition of source matl under Licenses R-179, C-4269 & C-4625 will be made to RC Cole, who had cognizance of plants while matl received under Commission licenses
LITTEL, E O Vitro Engineering Co 61/01/13 EPSTEIN, E Atomic Energy Commission 1p 16449 021
- B212230142 Addl response to FOIA request for documents re Stepan Chemical Co in Maywood, NJ Forwards draft "Backup for AEC-592 " Info partially withheld (ref FOIA Exemption 6)
FELTON, J M Division of Rules and Records 82/11/10 VAN DYKEN, G Affiliation Unknown 1p 16540 341
- B212230150 Draft "Backup for AEC-592 " Info partially withheld (ref FOIA Exemption 6)
SHOPEN, N M Atomic Energy Commission 67/11/06 11pp 16540 342
- B212230159 FOIA request for SECY-82-322, "Review of Director's Decision on 2 206 Petition (PSC of NH)" & S Chalk 820816 memo to L Bickwit
FICKETT, K Energy Research Group, Inc 82/10/13 Office of the Secretary of the Commission 1p 16540 313
- B212230166 Responds to FOIA request for SECY-82-322, "Review of Director's Decision 2 206 Petition (PSC of NH)" & S Chalk memo to L Bickwit Forwards requested documents
FELTON, J M Division of Rules and Records 82/11/04 GOLDSMITH, M W Energy Research Group, Inc 1p 16540 314
- B209010092 SECY-82-322
Recommends that Commission not review 820706 Director's decision denying Seacoast Anti-Pollution League 820205 request for order to show cause why CP should not be suspended or revoked due to lack of financial qualification
MALESCH, M O Office of the General Counsel 82/07/30 4pp 16540 315
- B212230176 Advises that NRC has unanimously decided that no review of Director's Decision 2 206 petition (PSC of NH) needed Ofc of General Counsel notified on 820816
CHILK, S J Office of the Secretary of the Commission 82/08/16 BICKWIT, L Office of the General Counsel 1p 16540 340
- B212270023 Responds to FOIA request for SECY-82-295 Forwards document Document also available in PDR
FELTON, J M Division of Rules and Records 82/11/23 GRABER, L Affiliation Unknown 1p 16553 332
- B212270034 FOIA request for documents re FOIA Request 82-308
SEPAR, S Hutton & Williams 82/11/16 Division of Rules and Records 3pp 16553 161
- B212270036 Responds to FOIA request for documents re FOIA Request 82-308 Documents available in PDR
FELTON, J M Division of Rules and Records 82/11/23 SEPAR, S Hutton & Williams 1p 16553 164
- B212270045 FOIA request for documents re extensions issued in Nov & Dec 1981 & proposed extensions to "Stenographic Reporting Svcs," awarded to Alderson Reporting Co, Inc Response requested within 10 days
GALLO, J Isham, Lincoln & Beale FIN B-1311 NRC-17-80-448-0 82/11/02 FELTON, J Division of Rules and Records 2pp 16566 044
- B212270048 Responds to FOIA request for documents re extensions issued in Nov & Dec 1981 & proposed extensions to "Stenographic Reporting Svcs," awarded to Alderson Reporting Co, Inc Forwards documents listed in App A
FELTON, J M Division of Rules and Records FIN B-1311 NRC-17-80-448-0 82/11/19 GALLO, J Isham, Lincoln & Beale 3pp 16566 046
- B212270052 Request for procurement action 80-SEC-448, executing Mod B to "Stenographic Reporting Svcs " Mod obligates addl funds
CHILK, S J Office of the Secretary of the Commission FIN B-1311 NRC-17-80-448-0 82/01/18 2pp 16566 049
- B212270055 Forwards unexecuted Mod B to "Stenographic Reporting Svcs," extending period of performance to 820318 & obligating addl funds Approval requested
LEBO, C D Administrative Contracts Branch FIN B-1311 NRC-17-80-448-0 82/02/01 SHARP, R A Alderson Reporting 2pp 16566 051
- B212270059 Forwards Mod B to "Stenographic Reporting Svcs," extending period of performance to 820318 & obligating addl funds
LEBO, C D Division of Contracts FIN B-1311 NRC-17-80-448-0 82/02/08 SHARP, R A Alderson Reporting 1p 16566 053
- B212270065 Mod B, extending period of performance to 820318 & increasing funds obligated to "Stenographic Reporting Svcs " Findings & determination encl
SHARP, R A Alderson Reporting LEBO, C D Division of Contracts FIN B-1311 NRC-17-80-448-0 82/02/02 2pp 16566 054
- B212270080 Notification of contract execution, Mod B to "Stenographic Reporting Svcs " Contractor Alderson Reporting Co, Inc PAGE, H Administrative Contracts Branch FIN B-1311 NRC-17-80-448-0 82/02/02 CHILK, S J, SULLIVAN, P Office of the Secretary of the Commission MCNAMARA, A Atomic Safety and Licensing Board Panel 1p 16566 056
- B212270084 Request for procurement action 80-SEC-448, executing Mod 9 to "Stenographic Reporting Svcs " Mod extends period of performance to 820501 & obligates addl funds
HOYLE, J C Office of the Secretary of the Commission FIN B-1311 NRC-17-80-448-0 82/02/23 2pp 16566 057
- B212270088 Forwards unexecuted Mod 9, extending period of performance to 820501 & obligating addl funds to "Stenographic Reporting Svcs " Approval requested
LEBO, C D Division of Contracts FIN B-1311 NRC-17-80-448-0 82/03/05 SHARP, R A Alderson Reporting 2pp 16566 059
- B212270091 Forwards Mod 9, extending period of performance to 820501 & obligating addl funds to "Stenographic Reporting Svcs " Contractor Alderson Reporting Co, Inc
LEBO, C D Division of Contracts FIN B-1311 NRC-17-80-448-0 82/03/15 SHARP, R A Alderson Reporting 1p 16566 063
- B212270095 Request for procurement action 80-SEC-448, executing Mod 10 to "Stenographic Reporting Svcs " Mod extends period of performance to 820806 & obligates addl funds
HOYLE, J C Office of the Secretary of the Commission FIN B-1311 NRC-17-80-448-0 82/05/04 2pp 16566 065
- B212270099 Informs that funded request for procurement action should be submitted for continuation of svcs pending award of follow-on contract for stenographic reporting svcs
PAGE, H Administrative Contracts Branch 82/05/12 SULLIVAN, P Administrative & Logistical Support Branch 1p 16566 067
- B212270107 Forwards unexecuted Mod 10, extending period of performance to 820806 & increasing funds obligated to "Stenographic Reporting Svcs " Approval requested
SMITH, P A Administrative Contracts Branch FIN B-1311 NRC-17-80-448-0 82/05/28 SHARP, R A Alderson Reporting 2pp 16566 070
- B212270110 Forwards Mod 10, extending period of performance to 820806 & increasing funds obligated to "Stenographic Reporting Svcs " SMITH, P A Administrative Contracts Branch FIN B-1311 NRC-17-80-448-0 82/06/11 Alderson Reporting 1p 16566 073
- B212270114 Request for procurement action 80-SEC-448, executing Mod 11 to "Stenographic Reporting Svcs " Mod extends period of performance to 821115 & obligates addl funds
CHILK, S J Office of the Secretary of the Commission, FIN B-1311 NRC-17-80-448-0 82/07/16 2pp 16566 075
- B212270123 Forwards unexecuted Mod 11, extending period of performance to 821115 & increasing funds obligated to "Stenographic Reporting Svcs " Approval requested
SMITH, P A Administrative Contracts Branch FIN B-1311 NRC-17-80-448-0 82/08/09 SHARP, R A Alderson Reporting 2pp 16566 079
- B212270127 Forwards Mod 11, extending period of performance to 821115 & increasing funds obligated to "Stenographic Reporting Svcs " SMITH, P A Administrative Contracts Branch FIN B-1311 NRC-17-80-448-0 82/08/20 Alderson Reporting 1p 16566 081
- B212270131 Mod 11, extending period of performance to 821115 & increasing funds obligated to "Stenographic Reporting Svcs " SHARP, R A Alderson Reporting SMITH, P A Division of Contracts FIN B-1311 NRC-17-80-448-0 82/08/20 1p 16566 082

--B212270133 Notification of contract execution, Mod 11 to "Stenographic Reporting Svcs." Contractor Alderson Reporting Co, Inc
PAGE, M Administrative Contracts Branch FIN 8-1311
NRC-17-80-448-0 82/08/20 CHILK, S J, SULLIVAN, P Office of the
Secretary of the Commission MCNAMARA, A Atomic Safety and
Licensing Board Panel 1p 16566 083

B212270078 Addl response to FOIA request for repts & correspondence re
inventory differences at NPS plant in Erwin, TN Documents
completely & partially withheld (ref FOIA Exemptions 3 & 4)
FELTON, J M Division of Rules and Records 82/12/03 BARLETT, D L
Philadelphia Inquirer 5pp 16566 085

B212270306 Responds to FOIA request for all records re operation
(during last 30 days) & final disposition of all breeder-
type nuclear reactors No documents found subj to request
FELTON, J M Division of Rules and Records 82/11/26 ROSE, M S
Affiliation Unknown 1p 16555 317

B212270311 FOIA request for all records pertaining to operation
(during last 30 days) & final disposition of all breeder-
type nuclear power reactors
ROSE, M Affiliation Unknown 82/11/01 Office of Administration
1p 16555 320

B212270328 Addl response to FOIA request for documents re IAEA
safeguards Forwards App A Documents 1, 9 & 10 Remaining
documents in Apps A & B completely & partially withheld
(ref FOIA Exemptions 1 & 5)
FELTON, J M Division of Rules and Records 82/11/15
GREENBERG, E V Galloway & Greenberg App 16555 329

--B212270333 Advises that info supplied by State Dept does not clarify
nature or significance of delay incurred in completing
facility attachments for Swedish reactors info partially
withheld (ref FOIA Exemptions 1 & 5)
SHERR, T B Material Transfer Safeguards Licensing Branch
82/02/01 DEVINE, J B Assistant Director for Export/Import &
International Safeguards 1p 16555 336

--B212270336 Forwards marked-up analysis consisting of detailed comments
on draft Korean safeguards analysis Addl info addressing
significance of effective implementation of IAEA safeguards
should be included
PETERSON, M R Assistant Director for Export/Import & International
Safeguards 82/06/22 SHERR, T B Material Transfer Safeguards
Licensing Branch 1p 16555 337

B212270414 FOIA request for documents re proposed revision &/or update
to reactor safety study referred to in NUREG-0784, Chapter 10
as RS II & all documents pertaining to discussion of reactor
cooling method
SHOLLY, S C Union of Concerned Scientists 82/11/04 FELTON, J M
Division of Rules and Records 1p 16549 232

B212270418 Responds to FOIA request for documents re proposed revision
&/or update to reactor safety study referred to in
NUREG-0784, Chapter 10 as RS II & all documents pertaining to
reactor cooling methods Forwards documents listed in app
FELTON, J M Division of Rules and Records 82/11/26 SHOLLY, S C
Union of Concerned Scientists 3pp 16549 233 24X
File 50-000, 82/11/26, B212270418

--B212270438 Comments on NUREG-0739, "Approach to Quantitative Safety
Goals for Nuclear Power Plants" Info provided by D Okrent &
M Griesmeyer to AIF relevant to AIF questions
FRALEY, R F ACRS - Advisory Committee on Reactor Safeguards
81/09/15 REMICK, F J Interoffice Steering Group on Development
of a Safety Goal 1p 16549 236

--B212270442 Forwards "Discussion of Some Comments on NUREG-0739," in
response to AIF Committee on Reactor Licensing & Safety
B10326 comments
GRIEBMEYER, J M, OKRENT, D ACRS - Advisory Committee on Reactor
Safeguards 81/09/11 GIBBS, C Atomic Industrial Forum 1p
16549 237

--B212270445 "Discussion of Some Comments on NUREG-0739"
GRIEBMEYER, J M, OKRENT, D ACRS - Advisory Committee on Reactor
Safeguards OKRENT, D California, Univ of, Los Angeles
81/09/30 23pp 16549 238

--B212270448 Forwards N Palladino response to Question 7 re alternate
DHR sys Feed & bleed considered legitimate DHR method
FRALEY, R F ACRS - Advisory Committee on Reactor Safeguards
81/08/13 WARD, D A ACRS - Advisory Committee on Reactor
Safeguards 1p 16549 250

--B212270453 Forwards M Carbon questions re natural circulation & feed &
bleed heat removal sys to be addressed during ACRS
subcommittee 800326 meeting Tentative meeting schedule encl
BATES, A ACRS - Advisory Committee on Reactor Safeguards
80/03/21 TONG, L S, JOHNSTON, W, JOHNSON, C NRC - No Detailed
Affiliation Given 5pp 16549 258

--B212270457 Forwards M Bender concerns re potential interaction of feed
& bleed method of DHR w/other methods Issues warrant
consideration w/o encl
FRALEY, R F ACRS - Advisory Committee on Reactor Safeguards
80/03/20 CARBON, M W ACRS - Advisory Committee on Reactor
Safeguards 1p 16549 263

--B212270461 Discusses feed & bleed heat removal process in B&W & L-E
plants
BATES, A ACRS - Advisory Committee on Reactor Safeguards
80/03/06 CARBON, M, EBERSOLE, J, PLESSET, M NRC - No Detailed
Affiliation Given 2pp 16549 264

--B212270471 Expresses concerns re clarity of NUREG-0626 concerning
features of relief valves & disadvantages & advantages of
pilot operated valves & bleed & feed effect on core cooling
by natural circulation
BENDER, M ACRS - Advisory Committee on Reactor Safeguards
80/03/04 FRALEY, R F ACRS - Advisory Committee on Reactor
Safeguards 1p 16549 274

B212280033 FOIA request for SECY-B1-366 & SECY-B1-366A re proposed
amend to 10CFR2 & 50 concerning significant hazards
considerations
GRABER, L Affiliation Unknown 82/10/20 Division of Rules and
Records 1p 16590 173

B212280039 Responds to FOIA request for SECY-B1-366 & SECY-B1-366A re
proposed amend to 10CFR2 & 50 concerning significant hazards
considerations Documents withheld (ref FOIA Exemption 5)
FELTON, J M Division of Rules and Records 82/11/29 GRABER, L
Affiliation Unknown 2pp 16590 174

B212280506 Appeals denial of FOIA request for documents on behalf of
UCB re environ qualification of electrical equipment
CURRAN, D, BISHOP, L L Harmon & Weiss 82/11/02 DIRCKS, W J
Office of the Executive Director for Operations 3pp 16593 033

B212280509 Responds to appeal re denial of FOIA request for documents
re environ qualification of electrical equipment Appeal
denied Document withheld (ref FOIA Exemption 5)
DIRCKS, W J Office of the Executive Director for Operations
82/12/08 CURRAN, D Harmon & Weiss 2pp 16593 036

B212280511 FOIA request for documents re NRC investigations & repts
into burning of radwastes by Dow Chemical Co
BERG, P Institute for Policy Studies 82/11/12 FELTON, J M
Division of Rules and Records 1p 16593 023

B212280512 Responds to FOIA request for documents re NRC investigations
& repts into burning of radwastes by Dow Chemical Co
Forwards WJ Dircks 820910 ltr State of MI regulations for
incineration do not relate to NRC licensing authority
FELTON, J M Division of Rules and Records 82/12/07 BERG, P
Institute for Policy Studies 2pp 16593 024

--B212280515 Provides info re emission controls placed on NRC licensed
incinerators & NRC authority to license incinerators w/o
public input or state knowledge Dow Chemical Co incinerator
not major licensing action & does not warrant notification
DIRCKS, W J Office of the Executive Director for Operations
82/09/10 RIEGLE, D W Senate 2pp 16593 026

B212280520 Final response to FOIA request for documents re proposed
version &/or update to reactor safety study referenced in
NUREG-0784, Chapter 10 as RS II & documents re reactor
cooling method. No addl documents located
FELTON, J M Division of Rules and Records 82/12/07 SHOLLY, S C
Union of Concerned Scientists 1p 16593 028

B212290007 Final response to FOIA request for SECY-B1-600A,
SECY-B1-622A, SECY-B2-23, SECY-B2-42, SECY-B1-136, SECY-B2-137,
SECY-B2-197A & B, SECY-B2-286 & SECY-B2-315 SECY-B1-622A &
SECY-B2-197A & B withheld (ref FOIA Exemption 5)
FELTON, J M Division of Rules and Records 82/12/03 GRABER, L
Affiliation Unknown 2pp 16607 164

B212290014 FOIA request for SECY-B2-39A, B2-197, B2-197A & B2-197B
GRABER, L Affiliation Unknown 82/11/05 Division of Rules and
Records 1p 16607 169

NONDOCKETED ITEMS

B212290018 Forwards "Comparison of 1/13 Scale Mark II Containment Multivent Pool Swell Data W/Analytical Methods." Mark II containment program rept W/o encl
SOBOM,L J General Electric Co JFN 365-77 77/09/23 PARR,D D
Light Water Reactors Branch 3 1p 16607 050

B212290019 Responds to FOIA request for SECY-82-39A,82-197,82-197A & 82-197B SECY-82-39A available in PDR,SECY-82-197A & 82-197B previously addressed in response to FOIA Request 82-424 NRC review of SECY-82-197 incomplete
FELTON,J M Division of Rules and Records 82/12/13 GRADER,L
Affiliation Unknown 1p 16607 170

B212290036 Responds to FOIA request for five categories of documents Forwards documents listed in App A Review of documents re Item 1 continuing
FELTON,J M Division of Rules and Records 82/12/02 HIATT,S L
Ohio Citizens for Responsible Energy 2pp 16607 133

--B212290039 SECY-82-275
Informs Commission of public comments received on NRC, JM Hendrie & util group proposed ATWS rules & current status of rulemaking effort
DIRCKS,W J Office of the Executive Director for Operations 82/06/28 18pp 16607 140

B212290049 RD 76-12 on 760909, low pressure alarm occurred on safety injection accumulator C, resulting in pressure reduction. Caused by partially open HCV 1936 & body to bonnet leaks on HCV 1898 & 1549 Valves repaired & accumulator repressurized
STALLINGS,C M Virginia Electric & Power Co 266 76/10/01
MOSELEY,N C Region 2, Atlanta, Office of the Director 5pp 16607 263 24X Fiche 50-000,82/11/30,8212290060

--B212290075 RD 76-13 on 760916, normal boric acid makeup to vol control tank could not be accomplished due to plugging of chemical & vol control sys line 1-inch-CH-84-152 Cause unknown Line will be inspected for indications of solidification
STALLINGS,C M Virginia Electric & Power Co 292 76/10/20
MOSELEY,N C Region 2, Atlanta, Office of the Director 5pp 16607 267 24X Fiche 50-000,82/11/30,8212290060

--B212290078 IE Insp Repts 50-250/75-08 & 50-251/75-08 on 750527-30 Noncompliance noted failure to use latest approved procedure in performance of surveillance test
HARDIN,A K, SEIDLE,W C Region 2, Atlanta, Office of the Director IE8-75-05 75/06/24 18pp 16607 338 24X Fiche 50-000,82/11/30,8212290060

--B212290080 RD 76-07 on 760913, monthly average of gaseous & airborne particulate wastes for previous 12 months found greater than Tech Spec limit Caused by interpretational changes in Tech Spec Section 3 II B New limit approved
STALLINGS,C M Virginia Electric & Power Co 258 76/09/24
MOSELEY,N C Region 2, Atlanta, Office of the Director 5pp 16607-273 24X Fiche 50-000,82/11/30,8212290060

--B212290085 RD 76-05 on 760915, pressurizer level fell below 45% level setpoint, resulting in decreases of pressurizer pressure & vol control tank level Caused by leaking tube in steam generator A Cause of tube failure will be evaluated
STALLINGS,C M Virginia Electric & Power Co 264 76/09/29
MOSELEY,N C Region 2, Atlanta, Office of the Director 5pp 16607 278 24X Fiche 50-000,82/11/30,8212290060

--B212290109 IE Insp Repts 50-250/75-16 & 50-251/75-16 on 751105-21 Noncompliance noted failure to submit Unit 4 inservice insp rept to NRC within 90 days
HARDIN,A K Region 2, Atlanta, Reactor Operations Nuclear Support Branch BERATAN,L L Region 2, Atlanta, Reactor Construction & Engineering Support Branch 50-251/75-16 75/12/05 17pp 16607 287 24X Fiche 50-000,82/11/30,8212290060

--B212290114 IE Insp Repts 50-250/75-07 & 50-251/75-07 on 750512-14 Deviation observed one tray of control cables in Unit 3 control rod drive room & cable trays exiting auxiliary bldg did not have fire stops installed
HARDIN,A K Region 2, Atlanta, Office of the Director IE8-75-04A 75/05/27 9pp 16607 360 24X Fiche 50-000,82/11/30,8212290060

--B212290137 IE Insp Repts 50-250/75-17 & 50-251/75-17 on 751209-12 & 16-17 Noncompliance noted high radiation area improperly barricaded & licensed operator requalification program not fully performed per Administrative Procedure 0301
HARDIN,A K, DANCE,H C, JENKINS,G R Region 2, Atlanta, Reactor Operations Nuclear Support Branch 50-251/75-17 76/01/12 18pp 16607 313 24X Fiche 50-000,82/11/30,8212290060

--B212290138 IE Insp Rept 50-261/75-15 on 751124-25 No noncompliance noted Major areas inspected inservice insp results & procedures & eddy current insp of steam generator tubes
PARKER,R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch BLAKE,J J, BERATAN,L L Region 2, Atlanta, Reactor Construction & Engineering Support Branch 75/12/19 6pp 16608 010 24X Fiche 50-000,82/11/30,8212290060

--B212290165 IE Insp Rept 50-261/75-14 on 751104-19 Noncompliances noted failure to follow procedures for radiation surveys/maint of instrument records & surveillance testing procedures did not provide for recording "as-found" & "as-left" calibr data
PARKER,R C, DANCE,H C Region 2, Atlanta, Reactor Operations Nuclear Support Branch TROUP,O L Region 2, Atlanta, Fuel Facility & Materials Safety Branch 75/12/16 17pp 16608 024 24X Fiche 50-000,82/11/30,8212290060

--B212290184 IE Insp Repts 50-280/76-14 & 50-281/76-14 on 760915-17 Noncompliance noted failure to follow log book entry & review & initial requirements specified in Administrative Procedure 29
SINKULE,M V Region 2, Atlanta, Reactor Operations Nuclear Support Branch JENKINS,G R, TROUP,O L Region 2, Atlanta, Fuel Facility & Materials Safety Branch 50-281/76-14 76/10/19 13pp 16608 048 24X Fiche 50-000,82/11/30,8212290060

GEN TEC IS GENERIC TECHNICAL ISSUES

B208290027 Comments on draft rept on pressurized thermal shock, w/ special attention to Sections 4,5,9 & 10 Conclusions are conservative
GALL,H R Gall,H R GALL,W R ACRS - Advisory Committee on Reactor Safeguards 82/09/28 BENDER,M ACRS - Advisory Committee on Reactor Safeguards 2pp 16267 328

B208290032 Discusses ACRS 820930 meeting re pressurized thermal shock Appropriate framework needed to establish real margins & limits "PWR Downcomer Fluid Temp Transients Due to High Pressure Injection at Stagnated Loop Flow," encl
THEOFANOUS,T O Purdue Univ THEOFANOUS,T O ACRS - Advisory Committee on Reactor Safeguards 82/10/04 IGNE,E ACRS - Advisory Committee on Reactor Safeguards 2pp 16267 176

B212030277 Unofficial transcript of 821201 briefing in Washington, DC on pressurized thermal shock Pp 1-86 Viewgraphs encl
* Commissioners 82/12/01 135pp 16317 096

B212060470 Responds to B21004 ltr re draft "NRC Staff Evaluation of Pressurized Thermal Shock," & draft DRNL rept, "Pressure Vessel Thermal Shock at US PWRs Events & Precursors, 1963-1980-1981" Comments will be considered
PALLADINO,N J Commissioners 82/11/23 MARKEY,E J House of Rep 3pp 16343 301

--B20915000B Expresses disappointment at failure to inform of NRC draft evaluation & DRNL precursor rept re nuclear reactor pressure vessel thermal shock Concerned w/damage reactor vessels of operating PWRs have become vulnerable to cracking
MARKEY,E J House of Rep, Interior & Insular Affairs 82/10/04 PALLADINO,N Commissioners 4pp 16343 304

B212070414 Responds to FOIA request for all records on embrittlement, thermal shock, corrosion & cracking of reactor pressure vessel at facility Records available at PDR
FELTON,J M Division of Rules and Records 82/11/05 GUI00,C Pollution & Environmental Problems, Inc 4pp 16356 002

B212090141 Notification of CROR 821124 meeting re Unresolved Safety Issue A-43 concerning containment emergency sump performance & proposed Reg Guide 1 97 Agenda summary info & proposed NUREG encl
STELLO,V Committee to Review Generic Requirements 82/11/12 EISENHUT,D G Division of Licensing BERNARD,R M Office of Nuclear Regulatory Research, Director HELTEMER,C J Director's Office 122pp 16361 029

--B21120169 Forwards CROR package for Unresolved Safety Issue A-43, "Containment Emergency Sump Performance" Issue not as significant as previously postulated CROR review of proposed actions requested
DENTON,H R Office of Nuclear Reactor Regulation, Director 82/10/27 STELLO,V Regional Operations & Generic Requirements 200pp 16361 151

B212130407 Unofficial transcript of Commission 821209 meeting in Washington, DC re discussion/possible vote on pressurized thermal shock actions Pp 1-71
* Commissioners 82/12/09 72pp 16413 160

8212140001 Addl response to FOIA request for five categories of documents re SEP Forward documents listed in App A No documents located suby to item 3 of request Review of remaining documents continuing Documents available in PDR FELTON, J M Division of Rules and Records 82/11/03 QALLD, J Itham, Lincoln & Beale 2pp 16433 354 24X Fiche 50-000, 82/11/03, 8212140001

--8104230080 Advises that structural elements & review areas noted need not be considered part of NRC-03-79-118 Section 3 B of BRP defines structures to be considered PERKINS, D Systematic Evaluation Program Branch NRC-03-79-118 81/04/14 BTILWELL Franklin Institute/Franklin Research Center 2pp 16434 274

8212150326 Submits status rept re plant reviews of NUREG-0612, "Control of Heavy Loads at Nuclear Power Plants-Resolution of TAP A-36 " Div of Sys Integration considering making resolution of A-36 condition for OLs due to lack of util incentive DICK, G F Licensing Branch 1 82/11/29 YOUNGBLOOD, B J Licensing Branch 1 3pp 16446 234

--8212150333 Forwards status rept on NUREG-0612, "Control of Heavy Loads at Nuclear Power Plants" to help expedite project managers submittal of outstanding Phase I & II info CLEMENSON, F Auxiliary Systems Branch 82/10/08 KIPER, K Licensing Branch 2 REGUA, G Operating Reactors Branch 1 9pp 16446 237

8212290062 Summary of CROR Meeting 26 on 821124 re Unresolved Safety Issue A-43, "Containment Emergency Bump Performance" & revision to Reg Guide 1 97 STELLD, V Regional Operations & Generic Requirements 82/12/10 DIRCKS, W J Office of the Executive Director for Operations 5pp 16607 001

I&E INSPECTION AND ENFORCEMENT

8208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Svc list encl DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240

8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list encl COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000, 82/11/05, 8208190245

8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl JORDAN, E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X Fiche 50-000, 82/11/18, 8208190251

8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list encl DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000, 82/11/26, 8208190256

8208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 336pp 16387 028 24X Fiche 50-000, 82/11/30, 8208190257

8208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259

8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X Fiche 50-000, 82/12/03, 8208190261

8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16, 8208190267

8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27 " Svc list encl JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X Fiche 50-000, 82/12/20, 8208190268

8212060079 PNO-I-82-075 on 821201, util announced 10-month delay & new commercial operation dates for Unit 1 (821231) & Unit 2 (870331) projected Total cost revised by 44% Caused by increased design & engineering complexity KELLY, E Region 1, Office of Director 82/12/01 2pp 16314 342

8212060112 PNO-III-82-130 on 821130, all safety-related welding on HVAC stopped after licensee determined QA program for welder certification & procedure qualification inadequate Photon Testing removed from list of approved vendors GARDNER, R Region 3, Office of Director 82/12/01 1p 16316 102

8212060132 PNO-V-82-048 on 821126, Kawai Island, HI suffered loss of all electrical power & phone svc as result of hurricane Iwa US Navy nuclear submarine sent to island to provide electrical power THOMAS, R D Region 5, Office of Director 82/11/26 1p 16316 084

8212060305 PNO-I-82-077 on 821201, contractor employee intentionally poisoned lunch & placed in refrigerator Employee notified licensee of actions upon discovering lunch missing Warning announced on page sys No known harm occurred ARCHITZEL Region 1, Office of Director 82/12/01 1p 16313 111

8212080006 Addl response to FOIA request for seven categories of info re NFB, Erwin, TN facility Forwards App A documents denoted w/asterisk FELTON, J M Division of Rules and Records 82/10/25 WEISS, E R Harmon & Weiss 36pp 16367 001

--8212080139 Supplemental PNS-II-79-102E on 790924, followup of areas outside protected area identified by aerial measurements sys found not to exceed limits for unrestricted use CORVELL, G P, TOBIN, W J Region 2, Office of Director 79/09/25 1p 16370 154

--8212080149 Supplemental PNS-II-79-102K on 791102, initial reinventory efforts resulted in partial reconciliation of 790917 difference Unresolved inventory difference in excess of regulatory limits for continued operation remains LEE, T D, QILLESPIE, F P Region 2, Atlanta, Office of the Director 79/11/02 1p 16370 155

8212080514 PNO-IV-82-046 on 821206, during transfer to offshore platform, radiography camera dropped 15 ft from crane to deck platform discharging 9 Ci Co-60 source Personnel evacuated Caused by improperly securing device to crane DODA, R J Region 4, Office of Director 82/12/06 1p 16352 263

8212100150 PNO-III-82-134 on 821206, briefcase containing radiopharm from Pharmatopes, Inc stolen from car in Detroit, MI Radiopharm consisted of 30 mCi Tc-99m Significant exposure unlikely due to labeling & short half-life of matl SREINAWSKI, D J, MULLAUER, J R Region 3, Office of Director 82/12/06 1p 16376 043

8212100254 PNO-IV-82-044 on 821203, normal phone communication lost due to local flooding caused by heavy rains & severe weather Backup radio communications feasible from elevated ground northwest of Little Rock Addl heavy rain possible SEIDLE, W C Region 4, Office of Director 82/12/03 2pp 16376 127

8212140519 EN-82-038 on 821215 notice of violation & proposed imposition of civil penalty will be issued to Orion Chemical Co re receipt & use of source matl greater than 100CFR40 22 regulation permits FLOCKE, E, AXELRAD, J Director's Office, Office of Inspection and Enforcement 82/12/10 1p 16403 211

8212150086 PNO-II-82-135 on 821209, contractor employee arrested & charged w/blackmail, including extortion & threat to kill, injure or intimidate Arrest followed 3 day investigation as result of bomb threats on 821206, 07 & 08 MOORE, D E Region 2, Office of Director 82/12/09 2pp 16431 024

8212150090 PNO-II-82-134 on 821208, bomb threat received while in final preparation for full scale emergency drill Security determined call came from security guard posted at entry gate to owner controlled area Guard fired & arrested TILLMAN, A Region 2, Office of Director 82/12/09 2pp 16430 189

NONDOCKETED ITEMS

BP12160080 Addl response to FOIA request for records re receipt, processing, storage or removal of source matl at Canonsburg, PA. Vitro Mfg Co & Vitro Rare Metals Co Forwards documents listed in App A Remaining info under review
 FELTON, J M Division of Rules and Records 82/09/30 BLACK, A E Buchanan, Ingersoll, Rodewald, Kyle & Buerger 7pp 16447 312

--8212160103 PNO-77-008 draft press release re radiation detected near premises of former AEC contractor/licensee in Canonsburg, PA forwarded Site will be surveyed by ERDA, starting 770112 W/o encl Related info encl
 SMITH, G H, ROY, O W, THOMPSON, D Director's Office, Office of Inspection and Enforcement 77/01/11 22pp 16447 328

BP12170090 EN-82-040 on 821216, notice of violation & proposed imposition of civil penalty to be issued to licensee Action based on failure to ensure that licensed radioactive matl stored in unrestricted area secured against removal
 BROCKETT, T, AXELRAD, J Director's Office, Office of Inspection and Enforcement EA-82-40 82/12/13 1p 16450 321

BP12200069 PNA-82-010 on 821212, 0 5 Ci Cs-137 sealed source in container lost during shipment between Houma, LA & Cameron, LA Source not found Media interest anticipated
 DODA, R J Region 4, Office of Director 82/12/13 1p 16474 322

BP12210161 PNA-82-010A on 821213, lost well logging source recovered near Houma, LA NRC considering appropriate enforcement action
 * Region 4, Office of Director 82/12/16 1p 16483 361

MISC PUBLIC DOCUMENT ROOM MISCELLANEOUS

BP11120486 Ack receipt of "Near-Term OL Plant Technical Design Verification Program " Three-phase program outlined in rept contains concepts consistent w/independent QA design Const verification programs underway
 EISENHUT, D G Division of Licensing 82/10/21 NOONAN, V S ED, Nuclear, Inc 3pp 16043 106

--8211120491 Forwards proprietary "Near-Term OL Plant Technical Design Verification Program " Comments appreciated Rept withheld (ref 10CFR2 790)
 NOONAN, V S ED, Nuclear, Inc GA2-089 82/09/14 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 16043 109

BP12010436 Forwards review of geology & seismology of BIC prototype reactor plant in response to 820525 request for comments on geologic hazards, including capable faults, landslide or ground collapse present at site
 DENTON, H R Office of Nuclear Reactor Regulation, Director 82/11/09 MCKEE, K R Energy, Dept of 16pp 16267 285

BP12020185 Provides info clarifying USGS position re recurrence of 1886 Charleston, SC earthquake USGS now concludes that earthquakes should not be ruled out until deterministic & probabilistic evaluations of seismic hazard are performed
 DIRCKS, W J Office of the Executive Director for Operations 82/11/19 Commissioners 6pp 16308 267

--8212020193 Clarifies position re 1886 Charleston earthquake Studies reveal earthquake potential along eastern seaboard Deterministic & probabilistic evaluations of seismic hazard should be performed for individual sites
 DEVINE, J F Interior, Dept of, Geological Survey 82/11/18 JACKSON, R E Geosciences Branch 1p 16308 273

BP12060052 Authorizes regional administrators to perform certain operator licensing functions NRR will retain functions delegated to regions
 DIRCKS, W J Office of the Executive Director for Operations DENTON, H R Office of Nuclear Reactor Regulation, Director 82/11/22 O'REILLY, J P Region 2, Office of Director KEPLER, J G Region 3, Office of Director 2pp 16343 215

--8212060058 Forwards Procedure 0128-82-03, "Delegation & Assessment to Region 2 & 3 of Certain Operator Licensing Functions "
 DENTON, H R Office of Nuclear Reactor Regulation, Director 82/11/22 O'REILLY, J P Region 2, Office of Director KEPLER, J G Region 3, Office of Director 1p 16343 217

--8212060064 Procedure 0128-82-03, "Delegation & Assignment to Region 2 & 3 of Certain Operator Licensing Functions "
 DENTON, H R Office of Nuclear Reactor Regulation, Director 82/11/22 3pp 16343 218

8212060209 Forwards IE Security Insp Rept 0-82-70 on 820609 No noncompliance noted
 MARTIN, T T Division of Engineering & Technical Programs 82/11/22 COCHRAN, T B Natural Resources Defense Council 2pp 16313 175

--8212060212 IE Security Insp Rept 0-82-70 on 820609 No noncompliance noted Major areas inspected physical barriers, personnel identification & control, protective alarms, protective personnel & classified document control
 BAILEY, R J, GODY, A T Division of Engineering & Technical Programs 82/11/02 3pp 16313 177

8212080659 "Human Factor in Nuclear Power Plant Safety Progress Since TMI," published in "Progress in Nuclear Energy," Vol 10, Pages 299-347
 HANAUER, S H Affiliation Unknown 81/02/09 50pp 16379 246

8212100217 Summarizes Nuclear Util Action Committee on Emergency Response Capabilities 821021 meeting w/NRC re implementation of SECY-82-111 provisions Committee charter & summary of ongoing activities encl
 GEORGE, R L, BLANCH, P Alabama Power Co 82/12/03 EISENHUT, D G Division of Licensing 12pp 16376 081

8212270253 Responds to 800521 ltr re Research Info Ltr 83 on steam generator integrity Research info ltrs are brief ltrs to staffs presenting findings by Ofc of Research contractors, not review of all developments
 SHAD, L C Assistant Director for General Reactor Safety Research 80/06/02 SHEWMON, P O Affiliation Unknown 2pp 16555 317

8212270432 Forwards regulatory analysis guidelines to replace revised guidelines for value impact analyses
 DIRCKS, W J Office of the Executive Director for Operations 82/12/13 NRC - No Detailed Affiliation Given 2pp 16571 338

--8212270439 "Regulatory Analysis Guidelines of NRC "
 * Office of the Executive Director for Operations 82/12/13 22pp 16571 340

NUREQ NUREQ REPORTS AND RELATED CORRESPONDENCE

8002260162 RIL-076
 Research Info Ltr 76 summarizes info re use of post-irradiation heat treatment to recover preirradiation properties of commercial nuclear power plant reactor vessels for continued safe operation
 LEVINE, S Office of Nuclear Regulatory Research, Director 79/12/28 DENTON, H R Office of Nuclear Reactor Regulation, Director MINOUE, R B Office of Standards Development, Director 4pp 16565 224

8005270762 RIL-085
 Research Info Ltr 85 discusses NUREQ/CR-1014, "Integrated Geophysical & Geological Study of Tectonic Framework of 39th Parallel Lineament in Vicinity of Intersection w/Extension of New Madrid Fault Zone - Annual Progress Rept FY79 "
 BUDNITZ, R J Office of Nuclear Regulatory Research, Director 80/03/24 DENTON, H R Office of Nuclear Reactor Regulation, Director MINOUE, R B Office of Standards Development, Director 7pp 16565 352

8005281047 RIL-071
 Research Info Ltr 71 submits NUREQ/CR-0876, "Regional Tectonics & Seismicity of East NE, Annual Rept, June 1977-May 1978 "
 LEVINE, S Office of Nuclear Regulatory Research, Director 79/11/19 DENTON, H R Office of Nuclear Reactor Regulation, Director 5pp 16565 228

811130045 RIL-124
 Research Info Ltr 124 transmits results of research relevant to display & utilization of control room alarm & annunciator sys RIL is part of TMI Action Plan I D. 4 a(1) & based on NUREQ/CR-2147 W/o encl
 MINOUE, R B Office of Nuclear Regulatory Research, Director RIL-124 81/10/20 DENTON, H R Office of Nuclear Reactor Regulation, Director STELL, V Director's Office, Office of Inspection and Enforcement 4pp 16566 029

8212010026 Comments on NUREQ/CR-2815 re natl reliability evaluation program procedures guide
 UHRIG, R E Florida Power & Light Co L-82-519 82/11/29 EL-BASSIONI, A NRC - No Detailed Affiliation Given 3pp 16260 269

8212010052 NUREQ-0936 VOL N03
 NRC REGULATORY AGENDA Quarterly Report, July-September 17, 1982
 * Division of Rules and Records 82/10/31 199pp, Available at NRC \$7 00 16291 083

- 8212010115 NUREG/CR-2765
A MATHEMATICAL MODEL FOR RADON DIFFUSION IN EARTHEN MATERIALS
NIELSON, K. K., ROGERS, V. C. Rogers Engineering Co., Inc. * Battelle Memorial Institute, Pacific Northwest Laboratory FIN 8-2269
PNL-4301 82/10/31 Division of Health, Siting & Environment
49pp Available at NRC \$4 75 16291 031
- 8212010138 NUREG-0485 V04 N10
SYSTEMATIC EVALUATION PROGRAM STATUS SUMMARY REPORT Data As of October 31, 1982 (Beige Book)
* Office of Resource Management, Director 82/11/30 97pp
16293 139
- 8212010144 NUREG/CR-2566
BWR REFILL-REFLOOD PROGRAM TASK 4 4-CCFL/REFILL SYSTEM EFFECTS TESTS (30 SECTOR) EVALUATION OF PARALLEL CHANNEL PHENOMENA
FINDLAY, J. A. General Electric Co. FIN A-5877 EPRI NP-2373
82/11/30 Division of Accident Evaluation 79pp 16291 282
- 8212010327 SECY-82-462
Recommends approval of NRC integrated human factors program plan. Plan represents systematic & comprehensive approach for addressing human factors concerns important to safety in FV83-B5
DIRCKS, W. J. Office of the Executive Director for Operations
82/11/19 68pp 16522 053
- 8212010514 Forwards "Preliminary Site Stabilization & Closure Plan for Uarmwell Low Level Radwaste Disposal Facility" & NUREG/CR-2478, Vol. 1, per meeting in Natural Bridge State Park, KY re Maxey Flats low level waste facility w/o encl
PENNAFILL, R. A. Low Level Waste Licensing Branch WM 409 18
82/11/04 PAGE, R. Kentucky, State of 1p 16270 262
- 8212020200 Forwards Revision 1 to CEN-152, "C-E Emergency Procedure Guidelines Vols 1 & 2," in response to DG Eisenhower
801031 ltr & NUREG-0737, Item I C 1 Guidelines intended to supersede & replace guidelines in CEN-128
WELLS, R. W. C-E Operating Plants Owners Group WELLS, R. W. Northport Utilities RMW-82-67 82/11/22 EISENHUT, D. G. Division of Licensing 2pp 16272 066
- 8212020212 CEN-152 R01
Revision 1 to CEN-152, "Emergency Procedure Guidelines"
* C-E Operating Plants Owners Group 82/11/30 723pp
16272 070
- 8212060429 NUREG/CR-2364 V01
PROJECTION MODELS FOR HEALTH EFFECTS ASSESSMENT IN POPULATIONS EXPOSED TO RADIOACTIVE AND NONRADIOACTIVE POLLUTANTS Vol 1-Introduction to The SPAHR Demographic Model For Health Risk
COLLINS, J. J., LUNDY, R. T., GRAHN, D. Argonne National Laboratory FIN A-2059
ANL-81-59 82/11/30 Division of Health, Siting & Environment 92pp 16347 124
- 8212060441 NUREG/CR-2364 V02
PROJECTION MODELS FOR HEALTH EFFECTS ASSESSMENT IN POPULATIONS EXPOSED TO RADIOACTIVE AND NONRADIOACTIVE POLLUTANTS Vol 2-SPAHR Introductory Guide
COLLINS, J. J., LUNDY, R. T. Argonne National Laboratory FIN A-2059
ANL-81-59 82/11/30 Division of Health, Siting & Environment 42pp 16346 026
- 8212060447 NUREG/CR-2364 V03
PROJECTION MODELS FOR HEALTH EFFECTS ASSESSMENT IN POPULATIONS EXPOSED TO RADIOACTIVE AND NONRADIOACTIVE POLLUTANTS Vol 3-SPAHR Interactive Package Guide
COLLINS, J. J. Argonne National Laboratory FIN A-2059 ANL-81-59
82/11/30 Division of Health, Siting & Environment 40pp
16346 068
- 8212060451 NUREG/CR-2364 V04
PROJECTION MODELS FOR HEALTH EFFECTS ASSESSMENT IN POPULATIONS EXPOSED TO RADIOACTIVE AND NONRADIOACTIVE POLLUTANTS Vol 4-SPAHR User's Guide
COLLINS, J. J., LUNDY, R. T. Argonne National Laboratory FIN A-2059
ANL-81-59 82/11/30 Division of Health, Siting & Environment 61pp 16346 196
- 8212060455 NUREG/CR-2364 V05
PROJECTION MODELS FOR HEALTH EFFECTS ASSESSMENT IN POPULATIONS EXPOSED TO RADIOACTIVE AND NONRADIOACTIVE POLLUTANTS Vol 5-SPAHR Programmer's Guide
COLLINS, J. J., LUNDY, R. T. Argonne National Laboratory FIN A-2059
ANL-81-59 82/11/30 Division of Health, Siting & Environment 81pp 16346 278
- 8212060458 NUREG/CR-3040
SELECTED REVIEW OF FOREIGN SAFETY RESEARCH FOR NUCLEAR POWER PLANTS
STEVENSON, J. D., THOMAS, F. A. Stevenson & Associates FIN 8-6769
82/11/30 Division of Engineering Technology 123pp Available at NRC \$6 00 16347 001
- 8212060460 NUREG/CR-2811
DEVELOPMENT OF TECHNIQUES FOR FABRICATION OF FILM PROBE SENSOR ASSEMBLY
MOORHEAD, A. J. Oak Ridge National Laboratory FIN B-0413
ORNL-5895 82/11/30 Division of Engineering Technology 40pp
16347 327
- 8212060465 NUREG/CR-2753
ANALYSIS OF A DOUBLE-ENDED COLD-LEG BREAK SIMULATION--THTF TEST 3 05 5B
CRADDICK, W. O., PEVEY, R. E. Oak Ridge National Laboratory ORNL-5846
82/10/31 Division of Accident Evaluation 116pp 16347 216
- 8212060468 NUREG/CR-2960
EXPERIMENT DATA REPORT FOR SEMISCALE MOD-2A STEAM LINE BREAK EXPERIMENTS (TESTS 8-SF-4 AND 8-SF-5)
LARSON, R. A. EG&O, Inc. FIN A-6038 EQG-2224 82/11/30 Office of Nuclear Regulatory Research, Director 68pp 16348 224
- 8212060480 NUREG/CR-2807
TEMPERATURE ESTIMATES FROM ZIRCALOY OXIDATION KINETICS AND MICROSTRUCTURES
OLSEN, C. B. EG&O, Inc. FIN A-6053 EQG-2207 82/11/30 Division of Accident Evaluation 53pp 16344 310
- 8212060486 NUREG/CR-2932 V01
EQUIPMENT QUALIFICATION RESEARCH TEST OF ELECTRIC CABLE WITH FACTORY SPLICES AND INSULATION REWORK TEST NO 2, REPORT NO 1
MINOR, E. E., FURGAL, D. T. Sandia Laboratories FIN A-1355
SAND81-2027 82/10/31 Division of Engineering Technology 77pp
16344 128
- 8212070425 Responds to FOIA request for documents re 820809 notice of violation & order imposing civil penalty Forwards App A documents App B documents completely withheld & Documents C1-C4 partially withheld (ref FOIA Exemptions 3.5 & 7)
FELTON, J. M. Division of Rules and Records 82/11/05 MCQUARRY, J. M. Debevoise & Liberman 5pp 16355 003 24X Fiche 50-000.82/11/05, 8212070425
- 8212080626 Requests participation in 820318 peer review meeting to discuss ORNL draft rept, "Interim Source Term Assumptions for Emergency Planning & Equipment Qualification." Draft rept forwarded first wk of Mar 1982 for review & comment
MULHAHL, G. Accident Evaluation Branch 82/03/02 CASTLEMAN, W. Colorado, Univ. of 1p 16379 354
- 8212080678 "TMI Action Item Plan Tracking Sys," Oct 1982 issue
* Office of Resource Management, Director 82/10/01 161pp
16370 202
- 8212090048 Responds to FOIA request for SECYs Forwards SECY-82-23, SECY-82-42, SECY-82-136, SECY-82-137, SECY-82-286 & SECY-82-315 SECY-81-600A available in PDR Review of SECY-81-622A, SECY-82-197A & SECY-82-197B continuing
FELTON, J. M. Division of Rules and Records 82/10/20 GRABER, L. Affiliation Unknown 1p 16384 295
- 8209280513 SECY-82-315
Requests Commission approve publication of for comment NUREG-0706, "Guidance for Implementation of 10CFR50 34(g)"
Section requires applicants to evaluate differences from SRP
DIRCKS, W. J. Office of the Executive Director for Operations
82/07/26 16pp 16385 166
- 8212090141 Notification of CRGR 821124 meeting re Unresolved Safety Issue A-43 concerning containment emergency sump performance & proposed Reg Guide 1.97 Agenda summary info & proposed NUREG encl
STELLO, V. Committee to Review Generic Requirements 82/11/12 EISENHUT, D. G. Division of Licensing JORDAN, E. L. Director's Office, Office of Inspection and Enforcement CUNNINGHAM, R. E. Office of Nuclear Material Safety & Safeguards, Director 122pp
16361 029
- 8211120169 Forwards CRGR package for Unresolved Safety Issue A-43, "Containment Emergency Sump Performance." Issue not as significant as previously postulated CRGR review of proposed actions requested
DENTON, H. R. Office of Nuclear Reactor Regulation, Director
82/10/27 STELLO, V. Regional Operations & Generic Requirements 200pp 16361 151

NONDOCKETED ITEMS

- 8212100308 Transcript of 821101 press conference in Bethesda, MD re NUREG/CR-2239 on site meteorologic data Pp 1-32
* Office of Public Affairs 82/11/01 34pp 16388 123
- 8212130080 Extends invitation to participate in peer review of rept, "Interim Source Term Assumptions for Emergency Planning & Equipment Qualifications." Comments requested for 820318 meeting to be held in Bethesda, MD
HULMAN, L G. Accident Evaluation Branch 82/03/02 BENJAMIN, A S Sandia Laboratories 1p 16417 049
- 8212130058 NUREG/CR-2643
A REVIEW OF SELECTED METHODS FOR PROTECTION AGAINST SABOTAGE BY AN INSIDER
GOLDMAN, L A., LOBNER, P R. Science Applications, Inc. + Sandia Laboratories FIN A-1210 SAND82-7036 82/10/31 Division of Facility Operations 150pp 16416 198
- 8212130108 NUREG/CR-2942
CRT DISPLAY EVALUATION THE MULTIDIMENSIONAL RATING OF CRT GENERATED DISPLAYS
GERTMAN, D I., BLACKMAN, H S., BANKS, W W. EG&G, Inc. FIN A-6308 EGO-2220 82/11/30 Office of Nuclear Regulatory Research, Director 43pp 16415 209
- 8212130110 NUREG/CR-2899
ANALYSIS OF A PROPOSED ONE THOUSAND DOLLAR PER MAN-REM COST EFFECTIVENESS CRITERION
STRIP, D R. Sandia Laboratories FIN A-1334 SAND82-1870 82/11/30 Division of Risk Analysis 12pp 16417 155
- 8212130113 NUREG/CR-2170
AN ASSESSMENT OF FUEL FOAMING POTENTIAL DURING CORE MELTDOWN ACCIDENTS
CRONENBERG, A W., CROUCHER, P W., MACDONALD, P E. EG&G, Inc. EGO-2191 82/11/30 Office of Nuclear Regulatory Research, Director 61pp 16417 169
- 8212130118 NUREG/CR-2864
IDENTIFICATION OF SAFETY RELATED EQUIPMENT FOR ANALYSIS AND TESTING IN THE HYDROGEN BURN SURVIVAL PROGRAM
DANDINI, V J. Sandia Laboratories FIN A-1270 SAND82-1684 82/11/30 Division of Accident Evaluation 26pp 16417 225
- 8212130123 NUREG/CR-2720
ANALYSIS OF PERFORMANCE OF WESTINGHOUSE REACTOR VESSEL LEVEL INDICATING SYSTEM FOR TESTS AT SEMISCALE
HARDY, J E., MILLER, O N. Oak Ridge National Laboratory FIN B-0401 ORNL/TM-8336 82/11/30 Office of Nuclear Regulatory Research, Director 61pp 16410 220
- 8212130135 NUREG/CR-2697
URANIUM OXIDE AND SODIUM OXIDE AEROSOL EXPERIMENTS NSRP MIXED-OXIDE TESTS 303-307, DATA RECORD REPORT
ADAMS, R E., KRESS, T S., TOBIAS, M L. Oak Ridge National Laboratory FIN D-0121 ORNL/TM-8325 82/11/30 Office of Nuclear Regulatory Research, Director 108pp 16417 298
- 8212130140 NUREG/BR-0051 V04 N4
POWER REACTOR EVENTS May-June 1982
MASSARO, S A. Director's Office 82/11/30 30pp 16415 250
- 8212130143 NUREG/CR-2774 V02
PHYSICS OF REACTOR SAFETY April-June 1982
* Argonne National Laboratory FIN A-2015 ANL-82-24 82/11/30 Division of Accident Evaluation 43pp 16415 164
- 8212130147 NUREG/CR-2918
SOIL-STRUCTURE INTERACTION ANALYSIS OF A 5 KG HDR EXPLOSIVE TEST
KOT, C A., SRINIVASAN, M G., VAUGHAN, D K. Argonne National Laboratory FIN A-2217 ANL-82-53 82/11/30 Division of Engineering Technology 118pp 16419 044
- 8212130152 NUREG/CR-2930
EXPERIMENT DATA REPORT FOR LOFT ANTICIPATED TRANSIENT EXPERIMENT SERIES L6-B
JARRRELL, D B., DIVINE, J M., MCXENNA, K J. EG&G, Inc. FIN A-6043 EGO-2217 82/11/30 Office of Nuclear Regulatory Research, Director 278pp 16414 088
- 8212130217 Forwards "FOAM2 - Computer Program to Calculate Core Swell Level & Mass Flow Rate During Small Break LOCA," in response to NUREG-0565 & NUREG-0737, Item II K 3 30.
TAYLOR, J H. Babcock & Wilcox Co. 82/12/01 BERGOREN, J S. Standardization & Special Projects Branch 1p. 16398 142
- 8212130233 Provides info per 821201 telcon re submittal of App I to "B&W Small Break LOCA ECCS Evaluation Model." App I will be submitted under NUREG-0737, Item II K 3 31.
TAYLOR, J H. Babcock & Wilcox Co. 82/12/03 SHERON, B. Reactor Systems Branch 1p 16397 016
- 8212130283 NUREG/CR-2296
A FIRST STUDY OF AEROSOLS PRODUCED BY NEUTRONIC HEATING OF FRESH URANIUM DIOXIDE FUEL UNDER CORE-DISRUPTIVE ACCIDENT CONDITIONS
ELRICK, R M. Sandia Laboratories FIN A-1218 SAND81-1788 82/11/30 Division of Accident Evaluation 84pp 16418 127
- 8212140001 Add1 response to FOIA request for five categories of documents re SEP Forwards documents listed in App A No documents located subj to Item 3 of request Review of remaining documents continuing Documents available in PDR
FELTON, J M. Division of Rules and Records 82/11/03 GALLO, J. Isham, Lincoln & Beale 2pp 16433 354 24X Fiche 50-000, 82/11/03, 8212140001
- 8202180460 Forwards Revision 1 to evaluation rept on SEP Topic VI-4, "Containment Isolation Sys." for facility Rept considers util comments received in 810810 & 820104 ltrs. Conclusions of original rept remain unchanged
SPEIS, T P. Assistant Director for Reactor Safety 82/01/27 LAIHAS, G. Assistant Director for Safety Assessment 43pp 16435 078 24X Fiche 50-000, 82/11/03, 8212140001
- 8204010021 Forwards evaluation for SEP Topic VI-4, "Containment Isolation Sys." Outstanding items include insufficient isolation provisions in test vent & drain lines & no isolation or leak detection provisions on ECCS subsystem
SPEIS, T P. Assistant Director for Reactor Safety 82/03/24 LAIHAS, G. Assistant Director for Safety Assessment 34pp 16434 329 24X Fiche 50-000, 82/11/03, 8212140001
- 8212140412 Responds to Generic Ltr 82-20 re guidance for implementation of SRP (NUREG-0800) rule. Substantive changes to SRP should be subj to reasonable period of public comment prior to implementation
OLSDORF, C. Baltimore Gas & Electric Co. OL-82-20 82/12/09 PURPLE, R A. Division of Licensing 2pp 16403 320
- 8212140464 NUREG/CR-2974
TRANSFER COEFFICIENTS FOR ASSESSING THE DOSE FROM RADIONUCLIDES IN MEAT AND EGGS
NO-Y C., COLSHER, C S., THOMPSON, S E. Lawrence Livermore Laboratory FIN A-0417 UCID-19464 82/11/30 Division of Systems Integration (post 811005) 116pp Available at NRC \$5 50 16420 251
- 8212140471 NUREG-0327 R03
OWNERS OF NUCLEAR POWER PLANTS PERCENTAGE OWNERSHIP OF COMMERCIAL NUCLEAR POWER PLANTS BY UTILITY COMPANIES
WOOD, R S. Office of State Programs, Director 82/11/30 39pp Available at NRC \$4 50 16418 285
- 8212140475 NUREG-0540 V04 N06
TITLE LIST OF DOCUMENTS MADE PUBLICLY AVAILABLE June 1-30, 1982
* Division of Technical Information & Document Control 82/11/30 610pp 16419 001
- 8212140476 NUREG-0773
THE DEVELOPMENT OF SEVERE REACTOR ACCIDENT SOURCE TERMS 1957 - 1981
BLOND, R., TAYLOR, M., MAROULIES, T. Office of Nuclear Regulatory Research, Director 82/11/30 116pp Available at NRC \$5 50 16431 202
- 8212140485 NUREG/CR-2823
A REVIEW OF THE IMPACT OF COPPER RELEASED INTO MARINE AND ESTUARINE ENVIRONMENTS
HARRISON, F L. Lawrence Livermore Laboratory FIN A-0119 UCRL-83042 82/11/30 Office of Nuclear Regulatory Research, Director 127pp Available at NRC \$4 00 16431 031
- 8212150326 Submits status rept re plant reviews of NUREG-0612, "Control of Heavy Loads at Nuclear Power Plants-Resolution of TAP A-36." Div of Sys Integration considering making resolution of A-36 condition for OLs due to lack of util incentive
DICK, G F. Licensing Branch 1 82/11/29 YOUNGBLOOD, B J. Licensing Branch 1 3pp 16446 234
- 8212150333 Forwards status rept on NUREG-0612, "Control of Heavy Loads at Nuclear Power Plants" to help expedite project managers submittal of outstanding Phase I & II info
CLEIMENSON, F. Auxiliary Systems Branch 82/10/08 KIPER, K. Licensing Branch 2 REGUA, G. Operating Reactors Branch 1 9pp 16446 237
- 8212160762 NUREG/CR-2134
BWR REFILL-REFLOOD PROGRAM, TASK 4 7-CONSTITUTIVE CORRELATIONS FOR SHEAR AND HEAT TRANSFER FOR THE BWR VERSION OF TRAC
ANDERSON, J O H., CHU, K K. General Electric Co. FIN B-5877 EPRI NP-1582 82/11/30 Office of Nuclear Regulatory Research, Director 95pp 16464 190

GP12160773 NUREG/CR-2975
SOIL-TO-PLANT CONCENTRATION FACTORS FOR RADIOLOGICAL
ASSESSMENTS
NG, Y C, COLSHER, C S, THOMPSON, S E Lawrence Livermore Laboratory
FIN A-0417 UCID-19463 82/11/30 Division of Systems
Integration (post B11005) 140pp 16464 286

GP12160780 NUREG-0748 V02 N10
OPERATING REACTORS LICENSING ACTIONS SUMMARY Data As Of
October 31, 1982 (Orange Book)
* Management Information Branch 82/11/30 286pp 16465 066

GP12170163 Forwards review of draft NUREG/CR-2815, "Nat'l Reliability
Evaluation Program Procedures Guide " Comment period
extension granted on 821117 Statements re containment
performance conflict w/backfitting rules
SCHERER, A E Combustion Engineering, Inc LD-82-097 82/12/13
EL-BASSIONI, A Reliability & Risk Assessment Branch 6pp
16459 225

GP12170206 Computer listing of status of generic issues as of B20901,
(NUREG-0660)
* NRC - No Detailed Affiliation Given 82/09/01 141pp
16479 001

GP12200029 Comments on proposed rule 10CFR50 re guidance for
implementation of SRP rule Supports rule
GIBSON, L S Consumers Power Co 47FR47019 004 82/12/09
Docketing & Services Branch 1p 16473 350

GP12200036 Package of two comments on proposed rule 10CFR50 re
proposed guidance for implementation of SRP rule
WEBSTER, G L Kansas Gas & Electric Co BOUCHEY, G D Washington
Public Power Supply System 47FR47019 82/12/10 Docketing &
Services Branch 3pp 16474 001

GP12200045 Comments on proposed rule 10CFR50 re proposed guidance
for implementation of SRP rule, NUREG-0906 Rule imposes
requirements for performance of excessive analysis &
evaluation efforts when relation to SRP not clear
BRADSHAW, R B Stone & Webster Engineering Corp 47FR47019 005
82/12/10 Docketing & Services Branch 2pp 16470 001

GP12210533 Forwards requests for addl info to complete review of
WCAP-10079 (P), "NOTRUMP A Nodal Transient Small Break &
General Network Code," & WCAP-10094 (P) "Westinghouse
Small Break ECCS Evaluation Model "
THOMAS, C O Standardization & Special Projects Branch 82/12/03
KAHE, E P Westinghouse Electric Corp 2pp 16502 288

--GP1221053B Round 1 questions re Reactor Sys Branch review of
WCAP-10054, "Westinghouse Small Break ECCS Evaluation Model
Using NOTRUMP Code," & WCAP-10079, "NOTRUMP Nodal Transient
Small Break & General Network Code "
* Reactor Systems Branch 82/12/03 23pp 16502 290

GP12220143 NUREG-0871 V01 N04
SUMMARY INFORMATION REPORT July 1 - September 30, 1982
(Brown Book)
* Management Information Branch 82/11/30 52pp 16527 102

GP12220162 NUREG/CR-2650
ALLOWABLE SHIPMENT FREQUENCIES FOR THE TRANSPORT OF TOXIC
CASES NEAR NUCLEAR POWER PLANTS
BENNETT, D E, HEATH, D C Sandia Laboratories FIN A-1214
SANDB2-0774 82/11/30 Division of Risk Analysis 37pp
16527 065

GP12220172 NUREG/CP-0033 V02
PROCEEDINGS OF THE WORKSHOP ON CONTAINMENT INTEGRITY June
7-9, 1982
BEDRELL, W A Sandia Laboratories SANDB2-1659 82/11/30 Office
of Nuclear Regulatory Research, Director 370pp 16528 019

GP12220193 NUREG/CR-3004
EVALUATION OF EXPERIENCES IN LONG-TERM RADON AND RADON
DAUGHTER MEASUREMENTS
YOUNG, J A, JACKSON, P O, THOMAS, V W Battelle Memorial Institute,
Pacific Northwest Laboratory FIN B-2370 PNL-4509 82/12/31
Division of Accident Evaluation 43pp Available at NRC \$4 75
16527 019

GP12220204 NUREG/CR-2723
ESTIMATES OF THE FINANCIAL CONSEQUENCES OF NUCLEAR POWER
REACTOR ACCIDENTS
STRIP, D R Sandia Laboratories FIN A-1334 SANDB2-1110
82/11/30 Division of Risk Analysis 180pp 16527 156

8212220228 NUREG/CR-2832
BIOLOGICAL CHARACTERIZATION OF RADIATION EXPOSURE AND DOSE
ESTIMATES FOR INHALED URANIUM MILLING EFFLUENTS Annual
Progress Report, April 1981-March 1982
EIDSON, A F Lovelace Biomed & Environmental Research Institute FIN
A-1222 LMF-97 82/12/31 Division of Health, Siting &
Environment 58pp Available at NRC \$4 75 16526 001

8212220238 NUREG/CR-3055
REVIEW AND EVALUATION OF PALEOHYDROLOGIC METHODOLOGIES
FOLEY, M G, ZIMMERMAN, D A, DUESBURG, J M Battelle Memorial
Institute, Pacific Northwest Laboratory FIN B-2220 PNL-4346
82/12/31 Division of Waste Management 94pp Available at NRC
\$5 50 16526 038

8212220249 NUREG/CR-2995
CANADIAN SEISMIC AGREEMENT Annual Report (1 July 1981-30
June 1982)
LYANS, J A, WETMILLER, R J, ANDERSON, F Canadian Commercial Corp
FIN B-6275 82/11/30 Division of Health, Siting & Environment
32pp Available at NRC \$4 50 16526 152

8212220265 NUREG/CR-2926
LOCA SIMULATION IN NRU PROGRAM Data Report For Thermal-
Hydraulic Experiment 2 (TH-2)
MOHR, C L, HESSON, O M, KING, L L Battelle Memorial Institute,
Pacific Northwest Laboratory FIN B-2277 PNL-4164 82/11/30
Division of Accident Evaluation 158pp Available at NRC \$6 50
16526 188

8212220282 NUREG/CR-2958
CONCEPT 4/MOD 3, A MULTICOMPARTMENT CONTAINMENT SYSTEMS
ANALYSIS PROGRAM
CHENG, T C, METCALFE, L J, HARTMAN, J E EQ&G, Inc FIN A-6439
EGO-2159 82/12/31 Division of Systems Integration (post
B11005) 213pp 16525 053

8212220291 NUREG/CR-2927
NUCLEAR POWER PLANT ELECTRICAL CABLE DAMAGEABILITY
EXPERIMENTS
LUKERS, L A Sandia Laboratories FIN A-1010-2 SANDB2-0236
82/11/30 Division of Engineering Technology 44pp 16523 264

8212220341 NUREG/CR-2875
COMPARISON OF RADON DIFFUSION COEFFICIENTS MEASURED BY
TRANSIENT-DIFFUSION AND STEADY-STATE LABORATORY METHODS
NIELSEN, K K, RICH, P C, ROGERS, V C Rogers Engineering Co, Inc
FIN B-2269 PNL-4370 82/11/30 Waste Management Branch 42pp
Available at NRC \$4 75 16525 009

8212220509 NUREG/CR-2423
MATHEMATICAL SIMULATION OF SEDIMENT AND RADIONUCLIDE
TRANSPORT IN ESTUARIES
UNTEH, Y, TRENT, D S Battelle Memorial Institute, Pacific Northwest
Laboratory FIN B-2271 PNL-4107 82/11/30 Division of Health,
Siting & Environment 81pp Available at NRC \$5 00 16525 266

8212220513 NUREG/CP-0033 V01
PROCEEDINGS OF THE WORKSHOP ON CONTAINMENT INTEGRITY June
7-9, 1982
BEDRELL, W A Sandia Laboratories SANDB2-1659 82/11/30 Office
of Nuclear Regulatory Research, Director 368pp, 16524 001

8212230073 Notification of commencement of 30-day review of FES re
licensing requirements for land disposal of radwaste
* Oregon, State of 82/11/22 1p 16544 338

8212230081 Forwards "Licensing Requirements for Land Disposal of
Radwaste," FES Comments due in 3 wks W/o encl
GATCH, F B Maryland, State of 82/11/24 NRC - No Detailed
Affiliation Given 1p 16544 326

8212230092 Advises of commencement of review of "Licensing Requirements
for Land Disposal of Radwaste," FES
DAVISON, A Illinois, State of 82 11 22 60 82/12/06 NRC - No
Detailed Affiliation Given 1p 16544 324

8212230388 Responds to 821026 request for info on low level waste
disposal & 10CFR61 NUREG-0782, "DEB for 10CFR61," will be
Forwarded
SCARANO, R A Low Level Waste Licensing Branch WMLL 411 4
82/11/17 FERRARA, W R Massachusetts Institute of Technology 1p
16540 239

8212270033 NUREG/CR-2601 V01
TECHNOLOGY, SAFETY AND COSTS OF DECOMMISSIONING REFERENCE
LIGHT WATER REACTORS FOLLOWING POSTULATED ACCIDENTS Main
Report
MURPHY, E S, HOLTER, O M Battelle Memorial Institute, Pacific
Northwest Laboratory FIN B-1171 PNL-4247 82/11/30 461pp,
16569 001

NONDOCKETED ITEMS

- 8212270068 NUREQ-0540 V04 N07
TITLE LIST OF DOCUMENTS MADE PUBLICLY AVAILABLE July 1-31, 1982
* Division of Technical Information & Document Control 82/11/30
980pp 16567 001
- 8212270145 NUREQ/CR-2978
EXPERIMENT DATA REPORT FOR LOFT ANTICIPATED TRANSIENT WITHOUT SCRAM EXPERIMENT 19-4
BATT, D L., DIVINE, J M., MCKERNIA, K J. EG&G, Inc FIN A-6043
EQG-2227 82/11/30 Office of Nuclear Regulatory Research, Director 87pp 16550 001
- 8212270156 NUREQ/CR-2865
HYDROGEN COMBUSTION IN AQUEOUS FOAMS
BAER, M R., GRIFFITHS, S K., SHEPHERD, J E Sandia Laboratories FIN A-1336 SAND82-0717 82/11/30 Division of Engineering Technology 78pp 16553 249
- 8212270165 NUREQ/CR-1935
QUANTITATIVE FAULT TREE ANALYSIS USING THE SET EVALUATION PROGRAM (SEP)
OLMANN, M D Sandia Laboratories FIN A-1241 SAND80-2712 82/11/30 Division of Risk Analysis 50pp 16553 267
- 8212270174 NUREQ-0580 VII N11
REGULATORY LICENSING STATUS SUMMARY REPORT Data as of November 30, 1982 (Blue Book)
* Management Information Branch 82/12/31 70pp 16551 203
- 8212270181 NUREQ-0918
PREVENTION AND MITIGATION OF STEAM GENERATOR WATER HAMMER EVENTS IN PWR PLANTS
ANDERSON, N R., HAN, J T Division of Safety Technology 82/11/30 37pp Available at NRC \$4 50 16551 162
- 8212270221 NUREQ/CR-3020
SELECTED REVIEW OF REGULATORY STANDARDS AND LICENSING ISSUES FOR NUCLEAR POWER PLANTS
STEVENSON, J D., THOMAS, F A Stevenson & Associates FIN B-6769 82/11/30 Division of Engineering Technology 488pp 16552 001
- 8212270232 NUREQ/CR-2601 V02
TECHNOLOGY, SAFETY AND COSTS OF DECOMMISSIONING REFERENCE LIGHT WATER REACTORS FOLLOWING POSTULATED ACCIDENTS
Appendices
MURPHY, E S., HOLTER, G M Battelle Memorial Institute, Pacific Northwest Laboratory FIN B-1171 PNL-4247 82/11/30 Division of Engineering Technology 626pp 16554 001
- 8212270243 NUREQ-0606 V04 N04
UNRESOLVED SAFETY ISSUES SUMMARY Data As Of November 19, 1982 (Aqua Book)
* Office of Resource Management, Director 82/12/01 50pp 16550 186
- 8212270414 FOIA request for documents re proposed revision &/or update to reactor safety study referred to in NUREQ-0784, Chapter 10 as RS II & all documents pertaining to discussion of reactor cooling method
SHOLLY, S C Union of Concerned Scientists 82/11/04 FELTON, J H Division of Rules and Records 1p 16549 232
- 8212270418 Responds to FOIA request for documents re proposed revision &/or update to reactor safety study referred to in NUREQ-0784, Chapter 10 as RS II & all documents pertaining to reactor cooling methods Forwards documents listed in app
FELTON, J H Division of Rules and Records 82/11/26 SHOLLY, S C Union of Concerned Scientists 3pp 16549 233 24X
Fiche 50-000, 82/11/26, 8212270418
- 8212270471 Expresses concerns re clarity of NUREQ-0626 concerning features of relief valves & disadvantages & advantages of pilot operated valves & bleed & feed effect on core cooling by natural circulation
BENDER, M ACRS - Advisory Committee on Reactor Safeguards 80/03/04 FRALEY, R F ACRS - Advisory Committee on Reactor Safeguards 1p 16549 274
- 8212270438 Comments on NUREQ-0739, "Approach to Quantitative Safety Goals for Nuclear Power Plants" Info provided by D Okrent & M Griesmeyer to AIF relevant to AIF questions
FRALEY, R F ACRS - Advisory Committee on Reactor Safeguards 81/09/15 REMICK, F J Interoffice Steering Group on Development of a Safety Goal 1p 16549 236
- 8212270442 Forwards "Discussion of Some Comments on NUREQ-0739," in response to AIF Committee on Reactor Licensing & Safety 810326 comments
GRIESMEYER, J M., OKRENT, D ACRS - Advisory Committee on Reactor Safeguards 81/09/11 OIBBS, C Atomic Industrial Forum 1p 16549, 237
- 8212270449 "Discussion of Some Comments on NUREQ-0739"
GRIESMEYER, J M., OKRENT, D ACRS - Advisory Committee on Reactor Safeguards OKRENT, D California, Univ of, Los Angeles 81/09/30 23pp 16549 238
- 8212270420 NUREQ/CR-3077
HAARM-3 CODE VERIFICATION PROCEDURE
GIESEKE, J A., LEE, K W., JORDAN, H Battelle Memorial Institute, Columbus Laboratories FIN A-4063 BML-2030 82/11/30 Office of Nuclear Regulatory Research, Director 61pp Available at NRC \$4 75 16572 001
- 8212270435 NUREQ/CR-2641
THE IN-PLANT RELIABILITY DATA BASE FOR NUCLEAR POWER PLANT COMPONENTS Data Collection And Methodology Report
DRAOD, J P., BORKOWSKI, R J., PIKE, D H Oak Ridge National Laboratory FIN B-0445 ORNL/TM-8271 82/11/30 Division of Risk Analysis 93pp 16571 089
- 8212270441 NUREQ/CR-2900
PREDICTED RATES OF FORMATION OF IODINE HYDROLYSIS SPECIES AT PH LEVELS, CONCENTRATIONS, AND TEMPERATURES ANTICIPATED IN LWR ACCIDENTS
BELL, J T., LIETZKE, M H., PALMER, D A Oak Ridge National Laboratory FIN B-0453 ORNL-5876 82/11/30 Office of Nuclear Regulatory Research, Director 70pp 16571 021
- 8212270443 NUREQ/BR-0025 V08N11
INFORMATION REPORT ON STATE LEGISLATION
KERR, D W Office of State Programs, Director 82/12/31 NRC - N. Detailed Affiliation Given 19pp 16566 339
- 8212270449 NUREQ/CR-2716 V02
REACTOR SAFETY RESEARCH PROGRAMS Quarterly Report, April - June 1982
EDLER, S K Battelle Memorial Institute, Pacific Northwest Laboratory FIN B-2101 PNL-4275-2 82/11/30 Office of Nuclear Regulatory Research, Director 70pp Available at NRC \$5 00 16556 229
- 8212270454 NUREQ/CR-2961
EXPERIMENT DATA REPORT FOR SEMISCALE MOD-2A PRIMARY FEED AND BLEED EXPERIMENT SERIES (TESTS S-SR-1 AND S-SR-2)
FOODALL, S P EG&G, Inc FIN A-6038 EQG-2225 82/11/30 Office of Nuclear Regulatory Research, Director 64pp 16572 060
- 8212270456 NUREQ/CR-2894
CONSOLIDATION THEORY AND ITS APPLICABILITY TO THE DEWATERING AND COVERING OF URANIN MILL TAILINGS
GATES, T E Battelle Memorial Institute, Pacific Northwest Laboratory FIN B-2370 PNL-4402 82/11/30 Office of Nuclear Regulatory Research, Director 48pp Available at NRC \$4 75 16566 294
- 8212270459 NUREQ-0713 V03
OCCUPATIONAL RADIATION EXPOSURE AT COMMERCIAL NUCLEAR POWER REACTORS - 1981
BROOKS, B O Management Information Branch 82/11/30 118pp Available at NRC \$ 50 16568 221
- 8212270468 NUREQ/CR-2970 V01
MATERIALS SCIENCE DIVISION LIGHT-WATER REACTOR SAFETY RESEARCH PROGRAM Quarterly Progress Report
* Argonne National Laboratory FIN A-2016 ANL-82-41 82/11/30 Division of Accident Evaluation 131pp 16570 102
- 8212270487 NUREQ/CR-2768
LITERATURE REVIEW OF MODELS FOR ESTIMATING SOIL EROSION AND DEPOSITION FROM WIND STRESSES ON URANIUM MILL TAILINGS COVERS
BANDER, T J Battelle Memorial Institute, Pacific Northwest Laboratory FIN B-2370 PNL-4302 82/11/30 Division of Health, Siting & Environment 29pp Available at NRC \$4 50 16548 278
- 8212270492 NUREQ/CR-2797
EVALUATION OF EVENTS INVOLVING SERVICE WATER SYSTEMS IN NUCLEAR POWER PLANTS
HARTED, J A Oak Ridge National Laboratory FIN B-0755 ORNL/NSIC-207 82/11/30 Division of Safety Technology 69pp Available at NRC \$5 00 16548 164
- 8212270499 NUREQ/CR-2948
SIGNIFICANCE OF NICKEL AND COPPER CONTENT TO RADIATION SENSITIVITY AND POSTIRRADIATION HEAT TREATMENT RECOVERY OF REACTOR VESSEL STEELS
HAWTHORNE, J R ENSA, Inc FIN B-8133 MEA-2006 82/11/30 NRC - No Detailed Affiliation Given 26pp 16548 137
- 8212270505 NUREQ-0020 V06 N07
LICENSED OPERATING REACTORS STATUS SUMMARY REPORT Data As of June 1982 (Grey Book)
* Management Information Branch 82/11/30 376pp, 16547 001

8212270512 NUREG/CR-2845
DIGN AN INTERACTIVE GRID GENERATING PROGRAM
FOOTE, H. P., RICE, W. A., KINCAID, C. T. Battelle Memorial Institute,
Pacific Northwest Laboratory FIN 8-2272 PNL-4343 82/11/30
Division of Health, Siting & Environment 61pp Available at NRC
\$5 00 1654B 079

8212270520 NUREG/CR-2982
BUOYANCY, TRANSPORT, AND HEAD LOSS OF FIBROUS REACTOR
INSULATION
BROCARD, D. N. Alden Research Laboratory SAND82-7205 82/11/30
Division of Safety Technology 59pp 1654B 017

8212270559 NUREG/CR-2917
REVIEW OF GROUND-WATER FLOW AND TRANSPORT MODELS IN THE
UNSATURATED ZONE
OSTER, C. A. Battelle Memorial Institute, Pacific Northwest
Laboratory FIN 8-2220 PNL-4427 82/11/30 Division of Waste
Management 175pp 16546 042

8212270561 NUREG/CR-1522
COOLING WATER CHLORINATION THE KINETICS OF CHLORINE, BROMINE
AND AMMONIA REACTION IN SEA WATER
JOHNSON, J. D., INMAN, G. W., TROFE, T. W. North Carolina Univ. of FIN
8-6248 82/11/30 Division of Health, Siting & Environment
121pp 16546 217

8212280520 Final response to FOIA request for documents re proposed
version 4/or update to reactor safety study referenced in
NUREG-0784, Chapter 10 as RS II & documents re reactor
cooling method No addl documents located
FELTON, J. M. Division of Rules and Records 82/12/07 BULLY, S. C
Union of Concerned Scientists 1p 16593 028

8212280535 Advises that FES on 10CFR61, "Licensing Requirements for
Land Disposal of Radwaste," received Status of review will
be provided in 22 days
* Mississippi, State of MSB21123-004 82/12/06 NRC - No
Detailed Affiliation Given 1p 16593 052

8212280542 Certifies state clearinghouse received FES on 10CFR61
Commenting agencies will review responses to comments on
DES
ROBERTS, T. California, State of B1112007 82/11/22 SMITH, R. D
Low Level Waste Licensing Branch 1p 16593 048

8212280543 Advises that FES on 10CFR61 received & assigned 30-day
review period Appropriate review agencies will comment
directly to NRC
BUTKO, K. J. New Jersey, State of NJB2-771 82/11/23 Office of
Nuclear Material Safety & Safeguards, Director 1p 16593 022

8212290188 Forwards CEN-227, "Summary Rpt on Operability of
Pressurized Safety Valves in C-E Designed Plants," in
response to NUREG-0737, Item II D 1 W/o encl
WELLS, R. W. C-E Operating Plants Owners Group WELLS, R. W. Northeast
Utilities RWB-82-70 82/12/20 BERNARD, H. Standardization &
Special Projects Branch 2pp 16578 055

ORG CORRESPONDENCE WITH OTHER ORGANIZATIONS

8208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-
Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping
at BHR Plants " Svc list encl
DEYOUNG, R. C. Director's Office, Office of Inspection and
Enforcement 82/10/28 Consolidated Edison Co. of New York, Inc
112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240

8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model
801 & Model 802 Thermoluminescent Dosimeters " Svc list
encl
COBB, L. I. Division of Fuel Facilities, Materials & Safeguards
82/11/05 Consolidated Edison Co. of New York, Inc 110pp
16372 142 24X Fiche 50-000, 82/11/05, 8208190245

8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan
Exercise Requirements " Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance 82/11/18
Consolidated Edison Co. of New York, Inc 109pp 16411 199 24X
Fiche 50-000, 82/11/18, 8208190251

8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination
Padlocks " Svc list encl
DEYOUNG, R. C. Director's Office, Office of Inspection and
Enforcement 82/11/26 Consolidated Edison Co. of New York, Inc
127pp 16411 065 24X Fiche 50-000, 82/11/26, 8208190256

8208190257 IE Info Notice 82-47, "Transportation of Type A Quantities
of Non-Fissile Radioactive Matl " Svc list encl
COBB, L. I. Division of Fuel Facilities, Materials & Safeguards
82/11/30 Consolidated Edison Co. of New York, Inc 356pp
16387 028 24X Fiche 50-000, 82/11/30, 8208190257

8208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment
Electrical Penetration Assemblies " Svc list encl
DEYOUNG, R. C. Director's Office, Office of Inspection and
Enforcement 82/12/03 Consolidated Edison Co. of New York, Inc
113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259

8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay
Sockets " Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance 82/12/03
Consolidated Edison Co. of New York, Inc 110pp 16462 064 24X
Fiche 50-000, 82/12/03, 8208190261

8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for
Air & Gas Monitoring " Svc list encl
DEYOUNG, R. C. Director's Office, Office of Inspection and
Enforcement 82/12/16 Consolidated Edison Co. of New York, Inc
127pp 16628 191 24X Fiche 50-000, 82/12/16, 8208190267

8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage
Relays Type ITE-27 " Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance 82/12/20
Consolidated Edison Co. of New York, Inc 108pp 16628 293 24X
Fiche 50-000, 82/12/20, 8208190268

8212010213 Responds to approval request for info collection re notices,
instructions & rpt to workers concerning insps, 10CFR19
Request approved through B51130 under OMB Number 3150-0044,
per Paperwork Reduction Act
SCURRY, N. Office of Management & Budget OMB 3150-0044 82/11/24
SCOTT, S. Document Management Branch 2pp 16271 256

8212010219 Responds to approval request for info collection re IE
bulletin, "Deficiencies in Primary Containment Electrical
Penetration Assemblies." Request approved through B51130
under OMB Number 3150-0094, per Paperwork Reduction Act
SCURRY, N. Office of Management & Budget OMB 3150-0094 82/11/19
SCOTT, S. Document Management Branch 2pp 16271 258

8212010241 Responds to approval request for info collection re 10CFR70
concerning domestic licensing of SNM Request approved
through B31231 under OMB Number 3150-0009, per Paperwork
Reduction Act
SCURRY, N. Office of Management & Budget OMB 3150-0009 82/11/19
SCOTT, S. Document Management Branch 2pp 16271 260

8212010247 Responds to approval request for info collection re 10CFR30
concerning domestic licensing of byproduct matl Request
approved through B21231 under OMB Number 3150-0017, per
Paperwork Reduction Act
SCURRY, N. Office of Management & Budget OMB 3150-0017 82/11/19
SCOTT, S. Document Management Branch 2pp 16271 262

8212010253 Responds to approval request for info collection re 10CFR40
concerning domestic licensing of source matl Request
approved through B30831 under OMB Number 3150-0020, per
Paperwork Reduction Act
SCURRY, N. Office of Management & Budget OMB 3150-0020 82/11/19
SCOTT, S. Document Management Branch 2pp 16271 264

8212010256 Responds to approval request for info collection re 10CFR50
concerning domestic licensing of production & utilization
facilities Request approved through B50430 under OMB Number
3150-0011, per Paperwork Reduction Act
SCURRY, N. Office of Management & Budget OMB 3150-0011 82/11/19
SCOTT, S. Document Management Branch 2pp 16271 266

8212020380 Comments on proposed topic definitions & associated cost
estimate for SEP, Phase III Review of need for program in
light of analysis of SEP Phase II & changes made through
regulatory initiatives since Nov 1977 encouraged
CAONETTA, J. P. Atomic Industrial Forum 82/10/19 EISENHUT, D. G
Division of Licensing, 6Bpp 16278: 022

8212070342 Informs of redirection of LOFT program Sufficient financial
support available for DOE to proceed w/formation of intl
LOFT consortium Forwards NRC/DOE interagency agreement on
LOFT program responsibility
PALLADINO, N. J. Commissioners, 82/11/22 BEVILL, T. House of Rep,
Appropriations, 1p 16356: 247

--8212070351 Informs of redirection of LOFT program Sufficient financial
support available for DOE to proceed w/formation of intl
LOFT consortium Forwards NRC/DOE interagency agreement on
LOFT program responsibility
PALLADINO, N. J. Commissioners, 82/11/22 UDALL, M. House of Rep,
Interior & Insular Affairs 1p 16356: 248

NONDOCKETED ITEMS

--B212070359 Informs of redirection of LOFT program Sufficient financial support available for DOE to proceed w/formation of intl LOFT consortium Forwards NRC/DOE interagency agreement on LOFT program responsibility
PALLADINO, N J Commissioners 82/11/22 SIMPSON, A Senate, Environment & Public Works 1p 16356 249

--B212070368 Informs of redirection of LOFT program Sufficient financial support available for DOE to proceed w/formation of intl LOFT consortium Forwards NRC/DOE interagency agreement on LOFT program responsibility
PALLADINO, N J Commissioners 82/11/22 HATFIELD, M O Senate, Appropriations 1p 16356 250

--B212070372 Informs of redirection of LOFT program Sufficient financial support available for DOE to proceed w/formation of intl LOFT consortium Forwards NRC/DOE interagency agreement on LOFT program responsibility
PALLADINO, N J Commissioners 82/11/22 OTTINGER, R L House of Rep, Energy & Commerce 1p 16356 251

--B212070378 Interagency agreement re LOFT program responsibility between NRC & DOE Responsibilities & obligations of parties for operation of LOFT facility delineated
DIRCKS, W J Office of the Executive Director for Operations
BREWER, S T Energy, Dept of 82/11/22 2pp 16356 252

B212080227 IAEA-CN-42/253

"Regulatory Perspective of Role of Const in Revitalizing US Nuclear Industry"
STELLO, V Regional Operations & Generic Requirements 82/12/02 11pp 16367 124

B212210497 Forwards request for OMB review & supporting statement re proposed rule to 10CFR50.54(x) concerning fitness for duty
NORRY, P O Office of Administration 82/12/15 SCURRY, N Office of Management & Budget 2pp 16539 347

B212210505 Forwards requests for OMB review & supporting statement re extension of OMB clearances for NRC Forms 212, "Qualifications Investigation (Professional)" & 212A "Qualifications Investigation (Secretarial/Clerical)"
NORRY, P O Office of Administration 82/12/15 SCURRY, N Office of Management & Budget 1p 16543 001

PR PROPOSED RULE

B211160094 Forwards draft notice of proposed rulemaking 10CFR170 re proposed revision of license fee schedules
NORRY, P O Office of Administration 82/11/02 STOCKMAN, D A Office of Management & Budget 64pp 16102, 230

B212020118 Comments on proposed rule 10CFR34 re third party certification of industrial radiographers Opposes rule if certification allowed only by party outside of Navy Rule not opposed if permitted by Navy party independent of users
HENDRIX, O W Navy, Dept of, Naval Facilities Eng Command 47FR17132 091 82/11/19 Docketing & Services Branch 4pp 16272 043

B212020125 Comments on proposed rule 10CFR50 which would require licensees to compare & evaluate facility against so-called SRP acceptance criteria & justify any deviations Opposes rule
PARKYN, J D Affiliation Unknown 47FR47019 001 82/11/19 Docketing & Services Branch 1p 16272 039

B212020134 Comments on proposed rule 10CFR50, "Applicability of License Conditions & Tech Specs in Emergency" Supports rule
SANDRY, W A Professional Reactor Operator Society 47FR35996 034 82/11/19 Docketing & Services Branch 3pp 16272 033

B212020154 Comments on proposed rules 10CFR30.40 & 70 re licensee responsibility for nuclear matls & procedures for termination of specific licenses
BODDEN, O Western Nuclear, Inc (subs of Phelps Dodge Corp) 47FR47400 002 82/11/16 Docketing & Services Branch 2pp 16274 172

B212020166 Comments on proposed rule 10CFR20 re performance testing for personnel dosimetry
* National Council on Radiation Protection & Measurements 45FR18023 074 82/11/26. NRC - No Detailed Affiliation Given 38pp. 16274 109

B212020182 Comments on proposed rules 10CFR30.40 & 70 re licensee responsibility for nuclear matls & procedures for termination of specific licenses Rule should be revised to reflect activities covered by OL issued under Part 50
CLAYTON, F L Alabama Power Co 47FR47400 001 82/11/05 Docketing & Services Branch 2pp 16274 094

B212020238 Comments on proposed rule 10CFR2 re immediate effectiveness rule for CPs Opposes rule
EDDLEMAN, W Affiliation Unknown 47FR47260 004 82/11/19 NRC - No Detailed Affiliation Given 2pp 16274 155

B212020242 Comments on proposed rule 10CFR2 re immediate effectiveness rule Supports rule Rule should be reinstated w/applicability to const stage & OL stage proceedings
BRADBURY, R B Stone & Webster Engineering Corp 47FR47260 001 82/11/17 Docketing & Services Branch 2pp 16274 147

B212020251 Package of four comments supporting proposed rule 10CFR20 re personnel dosimetry processing accreditation program
MOUNT, D K North Dakota, State of
RUTLEDGE, B O Georgia, State of
Dept of Human Resources WONG, G C California, State of 47FR20493 82/11/29 PALLADINO, N J Commissioners 4pp 16279 355

B212020359 Comments on proposed rule 10CFR2 re Commission review procedures for power reactor CPs hearings Supports rule
HEARNEY, J J Edison Electric Institute 47FR47260 007 82/11/24 CHILK, S J Docketing & Services Branch 1p 16288 358

B212020363 Comments on proposed rule 10CFR2 re immediate effectiveness rule for CP hearings Opposes rule
* Union of Concerned Scientists 47FR47260 006 82/11/24 Office of the Secretary of the Commission 8pp 16278 122

B212020366 Comments on proposed rule 10CFR2 re immediate effectiveness rule re review of ASLB CP decisions Opposes rule
DOUGHTY, J Seacoast Anti-Pollution League 47FR47260 005 82/11/22 CHILK, S J Office of the Secretary of the Commission 2pp 16278 138

B212020372 Comments on proposed rule 10CFR2 re review procedures for CPs & LNAS Supports rule
SCHERER, A E Combustion Engineering, Inc 47FR47260 002 82/11/19 Docketing & Services Branch 1p 16278 120

B212020375 Comments on proposed rule 10CFR2 re immediate effectiveness rule for power reactor CPs Supports rule
PARKYN, J D Affiliation Unknown 47FR47260 009 82/11/19 Office of the Secretary of the Commission 1p 16288 357

B212020378 Comments on proposed rule 10CFR2 re immediate effectiveness rule of ASLB decisions in CP hearings Opposes rule
DOHERTY, D F Gulf Coast Environmental Defense Foundation, Inc 47FR47260 008 82/10/23 Office of the Secretary of the Commission 3pp. 16278 099

B212020383 Comments on proposed rule 10CFR2 re immediate effectiveness rule for CP hearings Opposes rule
READ, D F North Carolina, Univ of 47FR47260 003 82/11/17 Docketing & Services Branch 1p 16278, 119

B212080575 Notices of Commission proposal to amend regulations in 10CFR170, revising fees charged for facilities & matls insp & review of applications for permits, licenses, amends, renewals, topical repts & special projects
NORRY, P Office of Administration 82/11/03 UDALL, M K House of Rep, Interior & Insular Affairs 2pp 16368 333

B212080578 Notices of Commission proposal to amend regulations in 10CFR170, revising fees charged for facilities & matls insp & review of applications for permits, licenses, amends, renewals, topical repts & special projects
NORRY, P Office of Administration 82/11/03 MOFFETT, T House of Rep, Government Operations 2pp 16368 328

B212080585 Notices of Commission proposal to amend regulations in 10CFR170, revising fees charged for facilities & matls insp & review of applications for permits, licenses, amends, renewals, topical repts & special projects
NORRY, P Office of Administration 82/11/03 SIMPSON, A House of Rep, Environment & Public Works 2pp 16368 326

B212080594 Discusses Commission proposal to amend regulations in 10CFR170, revising fees charged for facilities, matls insp, review of applications for permits, licenses, amends, renewals, topical repts & special projects
NORRY, P O Office of Administration 82/11/03 OTTINGER, R L House of Rep, Energy & Commerce 2pp 16368 283

NONDOCKETED ITEMS

40

8212160008 Ack receipt of 821005 comments on proposed rule 10CFR60, "Technical Criteria for Disposal of High Level Radwaste in Geologic Repositories." Concerns & recommendations will be considered prior to issuance of final technical criteria. DIRCKS, W J Office of the Executive Director for Operations 46FR35280 090 82/10/21 MUNTZING, L M American Nuclear Society 1p 16446 146

8212160216 Comments on proposed rule 10CFR50 re applicability of license conditions & Tech Specs in emergency situations Supports rule COUNCIL, W O Connecticut Yankee Atomic Power Co COUNCIL, W O Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNCIL, W O Northeast Utilities 47FR35996 035 82/11/24 Docketing & Services Branch 2pp 16446 129

8212160394 Package of two comments supporting proposed rule 10CFR20 re accreditation of personnel dosimetry svcs GERUSKY, T M Pennsylvania, State of WARREN, D M, HOWARD, B N Utah, State of 45FR20493 82/12/06 PALLADINO, N J Commissioners 6pp 16442 284

8212160422 Comments on proposed rule 10CFR20 re accreditation of personnel dosimetry svcs Supports rule HAZLE, A J Colorado, State of 45FR20493 074 82/11/16 PALLADINO, N J Commissioners 1p 16442 146

8212160431 Comments on proposed rule 10CFR2 re immediate effectiveness of licensing boards decisions Recommends Commission adopt full reinstatement of original rule for all licensing actions CONAN, B Z Atomic Industrial Forum 47FR47260 011 82/11/29 Docketing & Services Branch 2pp 16442 130

8212160434 Comments on proposed rule 10CFR2 re immediate effectiveness of licensing boards decisions No change to proposed rule recommended MARRACK, D Affiliation Unknown 47FR47260 010 82/11/22 PALLADINO, N J Commissioners 1p 16442 086

8212160518 Comments on proposed rule 10CFR32 re change of record submission requirements from annual to 5-yr plan Recommends reporting requirements be eliminated COHEN, C B Rado Watch Co, Inc 47FR52719 002 82/11/29 Docketing & Services Branch 1p 16442 116

8212160524 Comments on proposed rule 10CFR32 re change of record submission requirements from annual base to 5-yr plan Supports rule LESLIE, W G Northern Telecom 47FR52719 004 82/12/03 Office of the Secretary of the Commission 1p 16442 115

8212160530 Comments on proposed rule 10CFR32 re change of record submission requirements from annual to 5-yr plan Supports rule COLE, D Unitek Co (subs of Ecodyne Corp) 47FR52719 003 82/11/30 Docketing & Services Branch 1p 16442 114

8212160532 Comments on proposed rule 10CFR32 re modified record keeping & transfer reporting requirements Opposes rule Requests licensing of small users be terminated BIEGRIST, W Olycine-Sales & Service 47FR52719 001 82/11/29 Docketing & Services Branch 1p 16442 113

8212160538 Comments on proposed rule 10CFR32 re change of record submission requirements from annual to 5-yr plan Opposes rule HEIDER, H J Talley Industries, Inc 47FR52719 005 82/12/03 Docketing & Services Branch 1p 16442 111

8212200003 Comments on proposed rule 10CFR2 re issuance of CP or LWA based on limited NRC review of ASLB decision Supports rule BOUCHEY, G D Washington Public Power Supply System 47FR47260 012 82/12/07 Docketing & Services Branch 1p 16474 039

8212200010 Comments on proposed rule 10CFR2 specifically authorizing issuance of notice of violation to nonlicensees Commission should provide list of situations where NRC has statutory authority over nonlicensees REYNOLDS, N S Debevoise & Liberman 47FR51402 002 82/12/13 CHILK, S J Office of the Secretary of the Commission 3pp 16473 092

8212200016 Comments on proposed rule 10CFR32 re degree of public exposure to radiation from byproduct matl Opposes rule ENGELMANN, J H Miles Laboratories, Inc 47FR52719 006 82/12/09 Docketing & Services Branch 3pp 16473 082

8212200023 Comments on proposed rule 10CFR2 specifically authorizing issuance of notices of violations to nonlicensees Rule should be revised to specifically exclude util employees from rule LEMPGES, T E Niagara Mohawk Power Corp 47FR51402 002 82/12/10 CHILK, S J Office of the Secretary of the Commission 2pp 16473 348

8212200029 Comments on proposed rule 10CFR50 re guidance for implementation of SRP rule Supports rule QIBSON, L S Consumers Power Co 47FR47019 004 82/12/09 Docketing & Services Branch 1p 16473 350

8212200036 Package of two comments on proposed rule 10CFR50 re proposed guidance for implementation of SRP rule KOESTER, O L Kansas Gas & Electric Co BOUCHEY, G D Washington Public Power Supply System 47FR47019 82/12/10 Docketing & Services Branch 3pp 16474 001

8212200045 Comments on proposed rule 10CFR50 re proposed guidance for implementation of SRP rule, NUREG-0906 Rule imposes requirements for performance of excessive analysis & evaluation efforts when relation to SRP not clear BRADBURY, R B Stone & Webster Engineering Corp 47FR47019 005 82/12/10 Docketing & Services Branch 2pp 16470 001

8212200046 Comments on proposed rule 10CFR170 re revisions of license fee schedules Reconsideration urged to assure that schedule of fees be announced only after mgmt controls in place BERNATH, L San Diego Gas & Electric Co 47FR52454 001 82/12/09 Docketing & Services Branch 2pp 16470 004

8212200053 Comments on proposed rule 10CFR170 re revisions of license fee schedules Opposes rule Charges should be made on actual cost basis DIEZ, G R Isomedix, Inc (Subs of Massfield Enterprises, Inc) 47FR52494 002 82/12/09 Docketing & Services Branch 1p 16470 015

8212200073 Comments on proposed rules 10CFR30, 40 & 70 re licensee responsibility for nuclear matl & procedures for termination of specific licenses BOUCHEY, G D Washington Public Power Supply System 47FR47400 003 82/12/07 Docketing & Services Branch 1p 16474 309

8212230073 Notification of commencement of 30-day review of FES re licensing requirements for land disposal of radwaste * Oregon, State of 82/11/22 1p 16544 338

8212230081 Forwards "Licensing Requirements for Land Disposal of Radwaste," FES Comments due in 3 wks W/o encl GATCH, F B Maryland, State of 82/11/24 NRC - No Detailed Affiliation Given 1p 16544 326

8212230092 Advises of commencement of review of "Licensing Requirements for Land Disposal of Radwaste," FES DAVISON, A Illinois, State of 82 11 22 60 82/12/06 NRC - No Detailed Affiliation Given 1p 16544 324

8212280535 Advises that FES on 10CFR61, "Licensing Requirements for Land Disposal of Radwaste," received Status of review will be provided in 22 days * Mississippi, State of MS821123-004 82/12/06 NRC - No Detailed Affiliation Given 1p 16593 052

8212280542 Certifies state clearinghouse received FES on 10CFR61 Commenting agencies will review responses to comments on DES ROBERTS, T California, State of 81122007 82/11/22 SMITH, R D Low Level Waste Licensing Branch 1p 16593 048

8212280543 Advises that FES on 10CFR61 received & assigned 30-day review period Appropriate review agencies will comment directly to NRC BUTKO, K J New Jersey, State of NJ82-771 82/11/23 Office of Nuclear Material Safety & Safeguards, Director 1p 16593 022

PRM PETITION FOR RULEMAKING

82122020243 Comments on petition for rulemaking PRM-34-3 re maintaining record of radiographic survey Supports petition VINCENT, R E Chicago Bridge & Iron Co 47FR52722 82/09/27 Docketing & Services Branch 2pp 16274 102

82122020247 Notice of receipt of petition for rulemaking PRM-40-24 re Union Carbide Corp re disposition of tailing or waste from U milling operations CHILK, S J Office of the Secretary of the Commission 47FR53889 82/11/23 12pp 16279:321

NONDOCKETED ITEMS

8212020265 Comments on petition for rulemaking PRM-50-35 re public intervention if emergency plans not adequate Supports petition
TAYLOR, T Affiliation Unknown 47FR51889 034 82/11/27
CHILK, S J Office of the Secretary of the Commission 1p 16279 352

8212020269 Comments on petition for rulemaking PRM-50-35 re amend of emergency planning rule Supports petition
FLACK, O Flack, O 47FR51889 033 82/11/19 CHILK, S J Office of the Secretary of the Commission 1p 16279 359

8212020277 Package of two comments supporting petition for rulemaking PRM-50-35 re adjudicatory hearings on emergency planning issues prior to full power operation
KLINE, C, HANNON, B, CURRAN, J Affiliation Unknown 47FR51889 82/11/22 CHILK, S J Office of the Secretary of the Commission 5pp 16268 245

8212020279 Forwards petition for rulemaking PRM-40-24 re disposition of tailings & waste from U milling operations
DUDNICK, C L Union Carbide Corp 47FR53887 82/09/29 CHILK, S Docketing & Services Branch 2pp 16275 239

--8212020288 Petition for rulemaking PRM-40-24 re disposition of tailings & waste from U milling operations
DUDNICK, C L Union Carbide Corp 47FR53887 82/09/29 386pp 16275 240

8212020389 Comments on petition for rulemaking PRM-50-35 re UCS amend to 10CFR50.47 to ensure rights of intervenors Supports rule
DAVIS, J R Affiliation Unknown 47FR51889 032 82/11/22 CHILK, S J Office of the Secretary of the Commission 1p 16278 121

8212140209 Comments on petition for rulemaking PRM-50-34 re testing of evacuation plans once every 5 yrs Opposes rule
Evacuation plans should be tested more often
EDDLEMAN, W Affiliation Unknown 47FR50918 001 82/12/01 CHILK, S J Office of the Secretary of the Commission 1p 16446 153

8212200057 Comments on petition for rulemaking PRM-50-35 re right of public to litigate contested emergency planning issues prior to issuance of full power OL Opposes petition
STEWART, A E Lake County, OH 47FR51889 033 82/12/10 CHILK, S J Office of the Secretary of the Commission 1p 16474 253

8212200060 Comments on petition for rulemaking PRM-34-3 re radiation surveys for radiographic exposure devices Supports petition
DUPLISBEY, J F Catalytic, Inc (subs of Air Products & Chemicals, Inc) 47FR52722 001 82/12/08 Docketing & Services Branch 1p 16473 314

PROJ PROJECTS - PREDOCKET LICENSING

8212130435 Requests written confirmation that proprietary info in QNS, "Topical SAR for Castor Cask Type ISFSI (Dry Storage)," has been destroyed
ROBERTS, J P Advanced Fuel & Spent Fuel Licensing Branch 82/11/18 REISENNEAVER, D Chemical Engineering Branch 1p 16413 159

8212130438 Describes actions taken to destroy proprietary info in "Topical SAR for Castor Cask Type ISFSI (Dry Storage)," per Gesellschaft Fuer Nuclear Svc request
ROBERTS, J P Advanced Fuel & Spent Fuel Licensing Branch 82/11/18 Advanced Fuel & Spent Fuel Licensing Branch 1p 16413.056

8212140501 Forwards CENPD-270, "Dry Storage Cask for ISFSI"
SCHERER, A E Combustion Engineering, Inc LD-82-088 82/11/11 ROUSE, L C Advanced Fuel & Spent Fuel Licensing Branch 1p 16431 158

--8212140510 CENPD-270
"Dry Storage Cask for ISFSI"
Combustion Engineering, Inc 82/10/31 41pp 16431 159

8212210817 Summary of 811215 meeting w/Gesellschaft Fuer Nuclear Svc in Silver Spring, MD re submission of dry spent fuel storage cask design topical regt. Addl drop testing of Castor IC cask scheduled for Feb 1982.
ROBERTS, J P Advanced Fuel & Spent Fuel Licensing Branch 81/12/16 ROUSE, L C Advanced Fuel & Spent Fuel Licensing Branch 3pp 16502 344

8212220511 Forwards rept re 820923-24 monitoring visit to site to become fully acquainted w/site activities & personnel Future monitoring visits will cover specific aspects in greater depth
CLARK, A T Advanced Fuel & Spent Fuel Licensing Branch 82/12/20 HANNON, W A Energy, Dept of 7pp 16523 090

8212270473 Responds to 821129 request for review of C-E rept, "Dry Storage Cask for ISFSI" Casks conform w/GA program
CENPD-210-A, Revision 3 Program reviewed in 1977 & accepted
HAASS, W P Quality Assurance Branch 21665 82/12/08 ROUSE, L L Advanced Fuel & Spent Fuel Licensing Branch 1p 16566 360

8212270496 Notification of contract execution, Mod 1 to "Reproduction of Copies Re Stanislaus Nuclear Project Unit 1, NRC Docket P-564-A" Contractor Speigel & McDiarmid & Northern CA Power Agency
SMITH, P A Division of Contracts NRC-10-79-391 82/12/17 SPRINGER, M, WOOD, R Office of Administration 1p 16548 358

--8212270502 Mod 1, deobligating funds to, "Reproduction of Copies Re Stanislaus Nuclear Project, Unit 1, NRC Docket P-564-A"
Northern California Power Agency, California, State of, TRAUER, T C Spiegel & McDiarmid SMITH, P A Division of Contracts NRC-10-79-391 82/12/17 1p 16548 359

8212270558 Notification of contract execution, Mod 1 to "Economic Consulting Svcs in Connection w/Stanislaus Nuclear Unit, Antitrust Hearing Docket P-564-A" Contractor PM Gutmann SILVIR, S R M Technical Assistance Contracts Branch FIN B-6521 NRC-03-81-120 82/12/21 DENTON, H R Office of Nuclear Reactor Regulation, Director DOLSTON, A NRC - No Detailed Affiliation Given 1p 16546 338

--8212270560 Mod 1, deobligating funds to "Economic Consulting Svcs in Connection w/Stanislaus Nuclear Unit, Antitrust Hearing Docket P-564-A"
GUTHAIN, P M Gutmann, P M GUSTAVE, R P Technical Assistance Contracts Branch FIN B-6521 NRC-03-81-120 82/12/21 1p 16546 339

PT21 NONCOMPLIANCE REPORTS AND RELATED CORRESPONDENCE

8212010002 Forwards McGraw Edison Part 21 rept re defective valve components Defective valves are limited to facilities in Regions 3 & 4
MARTIN, T T Division of Engineering & Technical Programs 82/11/05 SPESARD, R Division of Project & Resident Programs GAGLIARDO, J Division of Resident, Reactor Project & Engineering Programs 2pp 16261 006

8212010085 Part 21 rept re changes incorporated into computer program, ADLPIPE Sample 1tr to client encl
HOCHFELDER, E Wylly Co PT21 82-730-000 82/11/03 COLLINS, J T Region 4, Office of Director 10pp 16260 307

8212010154 Part 21 rept re verification of gap distances between bottom of guide tube & upper core plate in failed guide tube support pins Investigation reaffirms 820927 position that no safety concern exists
RAHE, E P Westinghouse Electric Corp PT21 82-737-000 82/11/11 JORDAN, E L Division of Engineering & Quality Assurance 2pp 16258 079

8212010224 Part 21 rept re deficiency concerning pipe stress & support loads exceeding allowable limits Initially reported on 820817, Piping sys structure redesigned
SARSTEN, O E United Engineers & Constructors, Inc (subs of Raytheon Co) PT21 82-735-000 82/10/21 Director's Office, Office of Inspection and Enforcement 18pp 16258 012

8212280362 Part 21 rept re C Sumrall allegations concerning Rockwell main steam isolation valves used in nuclear power plants Investigation confirmed no evidence of reportable defect
DUFFEY, D W Rockwell International Corp 82/12/17 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 7pp 16560 078

GA999 QUALITY ASSURANCE INSPECTIONS

8212070032 Forwards GA Program Insp Rept 99900300/B2-01 on 820823-2/ No noncompliance noted
POTAPOV, U, Division of Vendor & Technical Programs 82/11/08 MORTARTY, J Colt Industries, Inc 2pp 16333 197

NONDOCKETED ITEMS

407

- B212070034 GA Program Insp Rept 99900300/82-01 on 820823-27 No noncompliance noted Major areas inspected previous insp findings,mfg process control,procurement document control & nonconformances & corrective actions
OLLER,R E , BARNES,I Division of Vendor & Technical Programs 82/10/25 15pp 16333 199
- B212070116 Forwards GA Program Insp Rept 99900794/82-01 on 821004-05 & notice of nonconformance
POTAPOVS,U Division of Vendor & Technical Programs 82/11/16
EGGERS,P E Ridihalgh, Eggers & Associates 2pp 16329 330
- B212070117 Notice of nonconformance from insp on 821004-05
* Division of Vendor & Technical Programs 82/11/16 2pp 16329 332
- B212070122 GA Program Insp Rept 99900794/82-01 on 821004-05
Noncompliance noted design control procedure not fully implemented & review,check,reevaluation & verification process for REA 2023 design not fully planned & structured
MCNEILL,W M , BARNES,I Division of Vendor & Technical Programs 82/11/08 7pp 16329 334
- B212070156 Forwards GA Program Insp Rept 99900369/82-01 on 821012-14 & notice of violation & notice of nonconformance
POTAPOVS,U Division of Vendor & Technical Programs 82/11/15
EHRHARD,E R Automatic Switch Co 3pp 16333 184
- B212070159 Notice of violation from insp on 821012-14
* Division of Vendor & Technical Programs 82/11/15 1p 16333 187
- B212070162 Notice of nonconformance from insp on 821012-14
* Division of Vendor & Technical Programs 82/11/15 2pp 16333 189
- B212070169 GA Program Insp Rept 99900369/82-01 on 821012-14
Noncompliance noted revisions to production planning & control dept Procedure PP 468 implemented in fabrication process w/o notifying or forwarding to QC
SUTTON,J W , BARNES,I Division of Vendor & Technical Programs 82/11/15 7pp 16333 190
- B212070301 Forwards GA Program Insp Rept 99900902/82-09 on 820816-21
No noncompliance noted
POTAPOVS,U Division of Vendor & Technical Programs 82/11/10
HOLBROOK,W W Wyle Laboratories 2pp 16343 181
- B212070304 GA Program Insp Rept 99900902/82-09 on 820816-21 No noncompliance noted Major areas inspected review of Terry turbine test spec & Wyle test plan & procedures & witnessing of turbine dynamic testing
HUBBARD,O T , PHILLIPS,H S Region 4, Office of Director 82/11/09 8pp 16343 183
- B212070416 Forwards GA Program Insp Rept 99900317/82-01 on 820920-24 & notices of nonconformance & violation
POTAPOVS,U Division of Vendor & Technical Programs 82/11/12
STOLBA,F B Cooper Industries, Inc 3pp 16336 298
- B212070418 Notice of violation from insp on 820920-24
* Division of Vendor & Technical Programs 82/11/12 1p 16336 301
- B212070422 Notice of nonconformance from insp on 820920-24
* Division of Vendor & Technical Programs 82/11/12 3pp 16336 302
- B212070434 GA Program Insp Rept 99900317/82-01 on 820920-24
Noncompliance noted disintegration of lube oil strainer basket mesh not reported & signatures,clock number & dates not entered for completed operations
FOSTER,W E , BARNES,I Region 4, Office of Director 82/11/02 13pp 16336 305
- B212100003 Ack receipt of 821108 ltr informing NRC of steps taken to correct nonconformance noted in GA Program Insp Rept 99900003/82-02
POTAPOVS,U Division of Vendor & Technical Programs 82/10/26
LONG,J A General Electric Co 1p 16373 358
- B212100005 Responds to NRC 821012 ltr re nonconformance noted in GA Program Insp Rept 99900003/82-02 Corrective actions engineering change request issued requesting anhydrous ammonia requirement in nitrate spec be revised
LONG,J A General Electric Co. 82/11/08. POTAPOVS,U Division of Vendor & Technical Programs 3pp 16373 359
- B212210091 Forwards GA Program Insp Rept 99900088/82-01 on 821018-22, notice of nonconformance & notice of violation
POTAPOVS,U Division of Vendor & Technical Programs 82/12/02.
OFF,H H Harnischfeger Corp 2pp 16492 221
- B212210096 Notice of violation from insp on 821018-22
* Division of Vendor & Technical Programs 82/12/02 1p 16492 223
- B212210098 Notice of nonconformance from insp on 821018-22
* Region 4, Office of Director 82/12/02 2pp 16492 224
- B212210105 GA Program Insp Rept 99900088/82-01 on 821018-22
Noncompliance noted procedures did not exist for two types of hardness testing equipment & equipment exceeded calibr due date
CONWAY,J T , BARNES,I Division of Vendor & Technical Programs 82/11/19 8pp 16492 226
- B212210135 Forwards GA Program Insp Rept 99900282/82-01 on 821018-20
No noncompliance noted
POTAPOVS,U Division of Vendor & Technical Programs 82/12/02
SEWELL,D M ITT Grinnell (subs of ITT) 2pp 16485 175
- B212210141 GA Program Insp Rept 99900282/82-01 on 821018-20 No noncompliance noted Major areas inspected spec of incorrect weld insp requirements on hanger drawings & previous findings
ELLERSHAU,L E , BARNES,I Division of Vendor & Technical Programs 82/11/26 9pp 16485 177
- B212210218 Forwards GA Program Insp Rept 99900519/82-03 on 821004-08
No noncompliance noted
POTAPOVS,U Division of Vendor & Technical Programs 82/12/03
KONES,J M Rechtel Corp 2pp. 16484 081
- B212210223 GA Program Insp Rept 99900519/82-03 on 821004-08 No noncompliance noted Major areas inspected GA program re audits & four 10CFR50 55(e) Part 21 repts
COSTELLO,J R , HALE,C J Division of Vendor & Technical Programs 82/11/30 18pp 16484 083
- B212210353 Forwards GA Program Insp Rept 99900346/82-01 on 820830-0903 & notice of nonconformance
POTAPOVS,U Division of Vendor & Technical Programs 82/11/18
FRANCOIS,E I Velan Valve Co 2pp 16495 299
- B212210357 Notice of nonconformance from insp on 820830-0903
* Division of Vendor & Technical Programs 82/11/18 2pp 16495 301
- B212210366 GA Program Insp Rept 99900346/82-01 on 820830-0903
Noncompliance noted absence of inspector stamp & data for verification of transfer of marking on operation & routing sheets for PO P3-5500-W assembly
CONWAY,J T , BARNES,I Division of Vendor & Technical Programs 82/11/04 8pp 16495 303
- B212270199 Forwards GA Program Insp Rept 99900743/82-01 on 821006 & 07 & notice of nonconformance
POTAPOVS,U Division of Vendor & Technical Programs 82/12/02
DUVALL,D D Brown Boveri Corp (subs Brown Boveri & Co , Ltd) 2pp 16535 135
- B212270206 Notice of nonconformance from insp on 821006 & 07
* Division of Vendor & Technical Programs 82/12/02 3pp 16535 137
- B212270213 GA Program Insp Rept 99900743/82-01 on 821006 & 07
Noncompliance noted data not entered in data sheets to indicate change to 48-volt dc control power & recorded voltage value did not satisfy min requirement
FOSTER,W E , BARNES,I Division of Vendor & Technical Programs 82/11/23 11pp 16535 140.
- B212280396 Ack receipt of 821122 ltr informing NRC of steps taken to correct nonconformance noted in GA Program Insp Rept 99900400/82-03
POTAPOVS,U Division of Vendor & Technical Programs 82/12/21
QUILBERT,D E Babcock & Wilcox Co 1p 16559 034
- B212280401 Responds to NRC 821005 ltr re nonconformance noted in GA Program Insp Rept 99900400/82-03 Corrective actions notification of POWERTRAIN code error distributed to operational analysis unit per Exhibit C of NPG-0903-13
QUILBERT,D E Babcock & Wilcox Co 82/11/22 POTAPOVS,U Division of Vendor & Technical Programs 4pp 16559 035

NONDOCKETED ITEMS

821230027 Forwards QA Program Insp Rept 99900365/B2-01 on 821020-22 & notice of nonconformance
 POTAPPOVS, U Division of Vendor & Technical Programs 82/12/08
 HEARS, L N Van Huffel Tube Corp 2pp 16598 178

--821230029 Notice of nonconformance from insp on 821020-22
 * Division of Vendor & Technical Programs 82/12/08 2pp
 16598 180

--821230032 QA Program Insp Rept 99900365/B2-01 on 821020-22
 Noncompliance noted gas flow meter encrusted w/dirt & oil
 preventing welders from reading gas flow rate
 ELLERSHAU, L E, BARNES, I Division of Vendor & Technical Programs
 82/11/30 6pp 16598 182

8212300212 Forwards QA Program Insp Rept 99900912/B2-01 on 820830-31 & notice of violation
 POTAPPOVS, U Division of Vendor & Technical Programs 82/12/10
 COWOREY, R S Acton Environ Testing Corp 2pp 16598 039

--8212300214 Notice of violation from insp on 820830-31
 * Division of Vendor & Technical Programs 82/12/10 1p
 16598 041

--8212300218 QA Program Insp Rept 99900912/B2-01 on 820830-31
 Noncompliance noted failure to specify provisions of 10CFR21
 in each procurement document for basic component issued on
 or after 780106
 AQEE, J R, PHILLIPS, H S Division of Vendor & Technical Programs
 82/12/07 5pp 16598 042

8212300254 Forwards QA Program Insp Rept 99900795/B2-01 on 821006-08,
 notice of nonconformance & notice of violation
 POTAPPOVS, U Division of Vendor & Technical Programs 82/12/08
 LOTT, J E E L Manufacturing Peebles, Inc 3pp 16595 211

--8212300258 Notices of violation & nonconformance from insp on
 821006-08
 * Division of Vendor & Technical Programs 82/12/08 4pp
 16595 214.

--8212300263 QA Program Insp Rept 99900795/B2-01 on 821006-08
 Noncompliance noted failure to adopt procedures to inform of
 component defects, to establish measures to assure integrity
 of subvendor mfg operations & to perform insp steps
 MCNEILL, W H, SAKOWSKI, P, BARNES, I, Division of Vendor &
 Technical Programs 82/11/26 10pp 16595 218

8212300276 Forwards QA Program Insp Rept 99900276/B2-01 on 820830-0903
 & notice of nonconformance
 POTAPPOVS, U Division of Vendor & Technical Programs 82/12/08
 CASSIDY, R F Solidstate Controls, Inc 2pp 16595 195

--8212300278 Notice of nonconformance from insp on 820830-0903
 * Division of Vendor & Technical Programs 82/12/08 2pp
 16595 197

--8212300280 QA Program Insp Rept 99900276/B2-01 on 820830-0903
 Nonconformance noted failure to maintain records to assure
 compliance w/10CFR21 procedure & failure to submit review
 packages to QA manager
 PARKER, L B, BARNES, I, Division of Vendor & Technical Programs,
 82/11/30 7pp 16595 199

8212300301 Forwards QA Program Insp Rept 99900903/B2-01 on
 820831-0901 & 1025-26 & notice of nonconformance
 POTAPPOVS, U Division of Vendor & Technical Programs 82/12/08
 RUSSELL, J Georgia Institute of Technology 2pp 16594 197

--8212300302 Notice of nonconformance from insp on 820831-0901 & 1025-26
 * Division of Vendor & Technical Programs 82/12/08 1p
 16594 199.

--8212300303 QA Program Insp Rept 99900903/B2-01 on 820831-0901 &
 1025-26 Noncompliance noted QA program not established or
 implemented
 SMITH, A L, PHILLIPS, H S Division of Vendor & Technical Programs
 82/11/30 7pp 16594 200.

REGGD REGULATORY GUIDES

8212020131 Comments on draft Reg Guide OP 722-4, "Qualifications For
 Radiation Safety Officer in Large-Scale Non-Fuel-Cycle
 Radionuclide Program" Supports reg guide
 WECST, W F California, Univ of, Los Angeles 82/11/09 BELL, J M
 Office of Nuclear Regulatory Research, Director 1p 16272 036

8212020173 Advises that comments on draft Reg Guide HF 408-4, "Training
 & Certification of ISFSI Operators," should be considered as
 personal comments, not Bechtel position
 HELLB, B J Bechtel Corp 82/11/18 Docketing & Services Branch
 1p 16274 106.

8212030229 Requests comments on requirements of Reg Guide 1 97 for
 reactor coolant temp indication Requirements not met by
 Westinghouse design Summary of NRC views encl
 EISENHUT, D O Division of Licensing 1805-82-11-072 82/11/18
 KINGSLEY, O D Westinghouse Operating Plants Owners Group
 KINGSLEY, O D Alabama Power Co 5pp 16316 350

8212090141 Notification of CROR 821124 meeting re Unresolved Safety
 Issue A-43 concerning containment emergency sump performance
 & proposed Reg Guide 1 97 Agenda summary info & proposed
 NUREG encl
 STELLD, V Committee to Review Generic Requirements 82/11/12
 EISENHUT, D O Division of Licensing JORDAN, E L Director's
 Office, Office of Inspection and Enforcement CUNNINGHAM, R E
 Office of Nuclear Material Safety & Safeguards, Director 122pp
 16361 029

--8211120212 Forwards proposed Revision 3 to Reg Guide 1 97,
 "Instrumentation for Light Water Cooled Nuclear Power Plants
 to Assess Plant & Environ Conditions During & Following
 Accident," regulatory analysis & CROR summary
 MINOQUE, R B Office of Nuclear Regulatory Research, Director
 82/11/04 STELLD, V Committee to Review Generic Requirements
 43pp 16361 245

8212290062 Summary of CROR Meeting 26 on 821124 re Unresolved Safety
 Issue A-43, "Containment Emergency Sump Performance" &
 revision to Reg Guide 1 97
 STELLD, V Regional Operations & Generic Requirements 82/12/10
 DIRCKS, W J Office of the Executive Director for Operations 5pp
 16607 001

RES RESEARCH AND TECHNICAL ASSISTANCE REPORTS

7811070329 RIL-038

Research Info Ltr 38 re results of initial series of ACPR
 experiments on prompt-burst energetics w/fresh oxide fuel
 W/o encl NUREG/CR-0367
 LEVINE, S Office of Nuclear Regulatory Research, Director
 78/10/13 DENTON, H R Office of Nuclear Reactor Regulation,
 6pp 16565 218

8002260162 RIL-076

Research Info Ltr 76 summarizes info re use of post-
 irradiation heat treatment to recover preirradiation
 properties of commercial nuclear power plant reactor vessels
 for continued safe operation
 LEVINE, S Office of Nuclear Regulatory Research, Director
 79/12/28 DENTON, H R Office of Nuclear Reactor Regulation,
 Director MINOQUE, R B Office of Standards Development, Director
 4pp 16865 224

8003280100 RIL-079

Research Info Ltr 79 transmits evaluation of seismic
 qualification tests for nuclear power plant equipment
 LEVINE, S Office of Nuclear Regulatory Research, Director
 79/12/28 DENTON, H R Office of Nuclear Reactor Regulation,
 Director 4pp 16565 233

8005270762 RIL-085

Research Info Ltr 85 discusses NUREG/CR-1014, "Integrated
 Geophysical & Geological Study of Tectonic Framework of 38th
 Parallel Lineament in Vicinity of Intersection w/Extension
 of New Madrid Fault Zone - Annual Progress Rept FY79"
 BUONITZ, R J Office of Nuclear Regulatory Research, Director
 80/03/24 DENTON, H R Office of Nuclear Reactor Regulation,
 Director MINOQUE, R B Office of Standards Development, Director
 7pp 16565 352

8005270829 RIL-081

Research Info Ltr 81 summarizes results & analysis of Fuel
 Disruption-1 series of in-reactor experiments on swelling &
 disruption of irradiated fuel under conditions of
 unprotected (nonscram) loss of flow accident in LMFBR
 BUONITZ, R J Office of Nuclear Regulatory Research, Director
 80/03/27 DENTON, H R Office of Nuclear Reactor Regulation,
 Director 10pp 16565 339

8005281047 RIL-071

Research Info Ltr 71 submits NUREG/CR-0876, "Regional
 Tectonics & Seismicity of East NE, Annual Rept, June 1977-
 May 1978"
 LEVINE, S Office of Nuclear Regulatory Research, Director
 79/11/19 DENTON, H R Office of Nuclear Reactor Regulation,
 Director 5pp 16565 228

NONDOCKETED ITEMS

409

8006020271 RIL-087

Research Info Ltr 87 transmits results of completed research to develop modeling capability for independent assessment of need for power estimates for util svc areas
MINDOUE, R B Office of Nuclear Regulatory Research, Director
80/04/04 DENTON, H R Office of Nuclear Reactor Regulation, Director 5pp 16566 001

8103250465 RIL-106

Research Info Ltr 106 forwards results of completed research on characterizing effects on atmospheric dispersion from bldg wakes around large reactor complex located on flat terrain
MINDOUE, R B Office of Nuclear Regulatory Research, Director
80/11/28 DENTON, H R Office of Nuclear Reactor Regulation, Director SMITH, R G Office of Standards Development, Director 4pp 16565 359

8104170498 RIL-119

Research Info Ltr 119 discusses development of best-estimate Component Code K-FIX (3D, FLX)
MINDOUE, R B Office of Nuclear Regulatory Research, Director
81/04/14 DENTON, H R Office of Nuclear Reactor Regulation, Director 17pp 16566 012

8104170664 RIL-118

Research Info Ltr 118 discusses variation of resonance component of Doppler coefficient w/depletion.
MINDOUE, R B Office of Nuclear Regulatory Research, Director
81/04/14 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 16566 006

8109280378 RIL-125

Research Info Ltr 125 reviews TRAC-PD2 Code, "Advanced Best Estimate Computer Program for PWR LOCA Analysis"
MINDOUE, R B Office of Nuclear Regulatory Research, Director
81/09/11 DENTON, H R Office of Nuclear Reactor Regulation, Director 10pp 16565 265

--8109280383 Speech entitled "TRAC-PD2 Development Assessment Summary,"

presented at B10114 ACRS Emergency Core Cooling subcommittee meeting
VIGIL, J C Los Alamos Scientific Laboratory 81/01/14 32pp 16565 273

811130045 RIL-124

Research Info Ltr 124 transmits results of research relevant to display & utilization of control room alarm & annunciator sys RIL is part of TMI Action Plan I D 4 a(1) & based on NUREG/OR-2147 H/o enc)
MINDOUE, R B Office of Nuclear Regulatory Research, Director
RIL-124 81/10/20 DENTON, H R Office of Nuclear Reactor Regulation, Director STELLQ, V Director's Office, Office of Inspection and Enforcement 4pp 16566 029

8001150075 RIL-127

Research Info Ltr 127 transmits results of investigation of heat transfer & hydraulics during BWR large-break LOCA
MINDOUE, R B Office of Nuclear Regulatory Research, Director FIN
B-3014 81/12/04 DENTON, H R Office of Nuclear Reactor Regulation, Director 11pp 16565 256

8201180563 RIL-128

Research Info Ltr 128 forwarding "PWR Lower Plenum Refill Research Results" Updates & extends results in Research Info Ltr 57, "Small-Scale Emergency Core Cooling Bypass Research Results" No addl bypass work planned
MINDOUE, R B Office of Nuclear Regulatory Research, Director FIN
A-404B RIL-128 81/12/08 DENTON, H R Office of Nuclear Reactor Regulation, Director 11pp 16565 245

8201220290 RIL-126

Research Info Ltr 126 transmits result of initial testing & analysis of BWR small-break LOCA simulations in two-loop test apparatus
MINDOUE, R B Office of Nuclear Regulatory Research, Director
81/12/04 DENTON, H R Office of Nuclear Reactor Regulation, Director 9pp 16565 309

--8201120155 Speech entitled "Analysis of TLTA Small Break Tests & Comparisons to RELAP4/MOD6 Calculations," presented at

ANS Specialist Conference on Small Breaks in LWRs B10825-27 meeting in Monterey, CA
BECKNER, W D NRC - No Detailed Affiliation Given DALLMAN, R J EG&G, Inc 81/08/27 19pp 16565 318

8202260367 RIL-129

Research Info Ltr 129 transmits results of project "Thorium in Human Tissues" Recommends adaption of ICRP 30 methodology for internally deposited thorium
MINDOUE, R B Office of Nuclear Regulatory Research, Director FIN
B-5756 82/02/05 DAVIS, J O Office of Nuclear Material Safety & Safeguards, Director 6pp 16565 236

8207200458 RIL-131

Research Info Ltr 131 responding to user need ltr NRR-78-2 re significance of impingement & entrainment impacts on Hudson River white perch
MINDOUE, R B Office of Nuclear Regulatory Research, Director
82/06/29 DENTON, H R Office of Nuclear Reactor Regulation, Director 7pp 16565 239

8212010109 "Review of Recent Research Sponsored by DDE That Impacts on

Findings of ICRP30," revision
FELICETTI, B A New Mexico, Univ of RUNKLE, O E Raytheon Corp
FIN A-1165 SAND82-7079 82/09/30 Division of Waste Management 44pp 16290 123

8212010469 "Technical Assistance For Regulatory Development Simplified

Repository Analysis in Hypothetical Bedded Salt Formation"
PEPPING, R E, CHU, M S Sandia Laboratories TIEN, P Science Applications, Inc FIN A-1165 SAND82-0976 82/12/01 NRC - No Detailed Affiliation Given 72pp 16268 088

8212010474 "Quick Look at LERs of Batteries & Battery Chargers at US

Commercial Nuclear Power Plants, Jan 1976-Dec 1981"
BROWN, S R, TROJANSKY, E O & G, Inc FIN A-6276 EQQ-EA-6074
82/10/31 RODDINSON, R C Division of Risk Analysis 141pp 16296 228

8212010475 "Technical Assistance for Regulatory Development

Radionuclide Concentrations for Basalt & Bedded Salt Repositories"
PEPPING, R E Sandia Laboratories FIN A-1165 SAND82-1275
82/09/31 NRC - No Detailed Affiliation Given 71pp 16270 290

8212010478 "Definition of Scenarios & Evaluation of Methods for

Analyzing Source Terms of Major Accidents Involving U Hexafluoride at NRC-Licensed Fuel Cycle Facilities," monthly progress rept for Oct 1982
BIMON-TOV, M Union Carbide Corp FIN D-0495 82/11/16
HERNSTEIN, S Transportation & Materials Risk Branch 3pp 16270 252

8212010481 "Technical Assistance for Regulatory Development Simplified

Repository Analysis in Ref Tuff Site"
SIEGEL, M D, CHU, M S Sandia Laboratories 82/12/01 NRC - No Detailed Affiliation Given 86pp 16268 001

8212010483 "Acoustic Emission/Flow Relationships for Inservice

Monitoring of Nuclear Pressure Vessels," monthly progress rept for Oct 1982
HUTTON, P H, KURTZ, R J Battelle Memorial Institute, Pacific Northwest Laboratory FIN D-2088 82/11/17 MUSCARA, J Materials Engineering Branch 21pp 16270 231

8212010486 "ORNL Projects for NRC Ofc of Nuclear Regulatory Research,"

monthly highlights rept for Sept 1982
LOTTS, A L, BAYLOR, V B, HOMAN, F J Oak Ridge National Laboratory
82/10/28 Office of Nuclear Regulatory Research, Director 103pp 16297 009

8212010487 "Monthly Rept Representing Research Portion of Water Reactor

Research Dept & Thermal Fuels Behavior Program," technical assistance rept
DEARIEN, J A Idaho National Engineering Laboratory 82/09/30 NRC - No Detailed Affiliation Given 212pp 16296 016

8212020010 "Identification of Crevice Corrosion in Titanium Alloy,

TiCode-12 in Simulated Rock Salt Brine at 150 C," interim rept
AHN, T M, LEE, B S, BOO, P Brookhaven National Laboratory
BNL-NUREG-32107 82/09/30 MCNEIL, M B Office of Nuclear Regulatory Research, Director 21pp 16308 341

8212020100 "US Std Problem B Final Comparison Rept," interim rept

DOBBER, C A EG&G, Inc FIN A-6047 EQQ-NTAP-6068 82/10/31
ODAN, F Office of Nuclear Regulatory Research, Director 48pp 16309 139

8212020104 "US Std Problem 10 Final Comparison Rept," interim rept

DOBBER, C A EG&G, Inc FIN A-6047 EQQ-NTAP-6069 82/10/31
ODAN, F Office of Nuclear Regulatory Research, Director 65pp 16309 187

8212020126 "Acceleration Data in Suppression Pool Area From Kuosheng

Safety Relief Valve Tests," interim rept
MILLER, B K, YUAN, C Y EG&G, Inc FIN A-6415 EQQ-EA-6025
82/10/31 BAOCHU, G NRC - No Detailed Affiliation Given 70pp 16310 276

NONDOCKETED ITEMS

B212030239 "Independent Code Assessment at BNL in FY82," prepared for Tenth Water Reactor Safety Research Info meeting on 821012-15
SAHA, P , ROHAT01, U S , JO, J H Brookhaven National Laboratory
BNL-NUREG-32101 82/10/12 NRC - No Detailed Affiliation Given
24pp 16317 001

B212030323 "SSC Development, Validation & Application & CRBR Balance of Plant Modeling," monthly highlights for Oct 1982
GUPPY, J G Brookhaven National Laboratory FIN A-3041 82/11/12
CURTIS, R T Severe Accident Assessment Branch 7pp 16316 329

B212060005 "HTR Safety Program," monthly highlights ltr for Oct 1982
SASTRE, C Brookhaven National Laboratory FIN A-3016 82/11/18
FOULDS, R Office of Nuclear Regulatory Research, Director 4pp
16325 337

B212060119 "LWR Code Assessment & Application," monthly highlight ltr for Oct 1982
SAHA, P Brookhaven National Laboratory FIN A-3215 82/10/31
QDAR, F Analytical Models Branch 6pp 16323-001

B212060128 "LWR Plant Analyzer Project," monthly highlights ltr for Oct 1982
WULFF, W Brookhaven National Laboratory FIN A-3227 82/10/31
SHOTKIN, L M Office of Nuclear Regulatory Research, Director 4pp
16322 360

B212070400 "Thermal Hydraulic LMFBR & LWR Safety Experiments," monthly highlight ltr for Oct 1982
QINSBERG, T , GREENE, G A Brookhaven National Laboratory FIN A-3024 82/10/31
CURTIS, R T Severe Accident Assessment Branch 4pp 16356 191.

B212070471 "Postulated Safety Relief Valve Line Break in Wetwell Airspace of Mark I & II Containments-Risk Assessment," informal rept
ECONOMOS, C , LEHNER, J , RANLEY, J Brookhaven National Laboratory
FIN A-3385 BNL-NUREG-31940 82/10/31 SU, T H Office of Nuclear Reactor Regulation, Director 52pp 16395 265

B212080262 "Stress Corrosion Cracking of PWR Steam Generator Tubing," monthly highlights for Oct 1982
VAN ROOYEN, D Brookhaven National Laboratory 82/10/31 NRC - No Detailed Affiliation Given 4pp 16370 195

B212080305 "Post-Test RELAP5 Simulations of Bemiscale Mod-2A Feedwater Line Break Tests B-SF-1.2 & 3C," interim rept
STREIT, J E , NORTH, P , JOHNSON, G W EG&O, Inc FIN A-6038
EGO-SEMI-6062 82/10/31 LANDRY, R R Office of Nuclear Regulatory Research, Director 82pp 16368 001

B212080510 "R5FORCE Program to Compute Fluid Induced Forces Using Hydrodynamic Output From RELAP5 Code," interim rept
WATKINS, J C EG&O, Inc FIN A-6356 EGO-EA-5920 82/10/31
RICHARDSON, J E Division of Risk Analysis 105pp 16368 085

B212080516 "Evaluation of Thermal-Hydraulic & Radiological Effects of Removing or Bypassing LOFT Steam Generator & Pump Simulators for Experiment L2-6," interim rept
DENHIE, P N , CONNOR, J E , GRI, A H EG&O, Inc FIN A-6048
EGO-LOFT-6084 82/10/31 NRC - No Detailed Affiliation Given 50pp 16368 190

B212080520 "RELAP5/MOD1 Quick Ref Manual," interim rept
HALL, D G , JOHNSON, E C EG&O, Inc FIN A-6330 EGO-CDD-6027
82/10/31 CHEN, Y Office of Nuclear Regulatory Research, Director 42pp 16368 240

B212160549 "Rept of Foreign Travel of MF Osborne," foreign trip rept
OSBORNE, M F Oak Ridge National Laboratory FIN B-0127
ORNL/FTR-1429 82/11/17 SILBERBERG, M Accident Evaluation Branch 22pp 16466 214

B212160558 "BMFT/NRC Core Melt Info Exchange Meeting, Karlsruhe, KfK," foreign trip rept
PARKER, G W Oak Ridge National Laboratory FIN B-0127
ORNL/FTR-1426 82/11/10 SILBERBERG, M Accident Evaluation Branch, 14pp 16466 200

B212160564 "Rept of Foreign Travel of RP Wichner," foreign trip rept
WICHNER, R P Oak Ridge National Laboratory FIN B-0127
ORNL/FTR-1426 82/11/22 SILBERBERG, M Accident Evaluation Branch 12pp 16466 188

B212200021 "Environ Assessments of Fuel Cycle Facilities," monthly progress rept for Oct 1982
KELLY, M J Oak Ridge National Laboratory FIN B-0279
ORNL/ED/EIS-179 82/10/31 GILLEN, P M Uranium Recovery Licensing Branch, 6pp 16529 085.

B212200060 "Measurements of Iodine Partition Coefficients Status of Experimental Program," interim rept
BEAHM, E C , SHOCKLEY, W E Oak Ridge National Laboratory FIN B-0453 82/10/31
Office of Nuclear Regulatory Research, Director 14pp 16527 005

B212200519 "ORNL Projects for NRC Ofc of Nuclear Regulatory Research," monthly highlights rept for Nov 1982
LOTTIS, A L , BAYLOR, V B , HOMAN, F J Oak Ridge National Laboratory 82/12/19
Office of Nuclear Regulatory Research, Director 95pp 16529 157

B212200523 "Chemical Species of Migrating Radionuclides at Commercial Shallow Land Burial Sites," quarterly progress rept for Jul-Sept 1982
KIRBY, L J , TOSTE, A P Battelle Memorial Institute, Pacific Northwest Laboratory PNL-4432-2 82/10/31 NRC - No Detailed Affiliation Given 21pp 16523 001

B212270240 RIL-130
Research Info Ltr 130 re experimental verification of computer simulations of piping response using Heissdampfreaktor seismic tests
MINOUE, R B Office of Nuclear Regulatory Research, Director 82/03/16 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 16553 359

B212270416 "SIMTRAN 1 - Computer Code for Simultaneous Calculation of Oxygen Distributions & Temp Profiles in Zircaloy During Exposure to High Temp Oxidizing Environments "
MALANO, S Oak Ridge National Laboratory ORNL-5083 75/11/30
NRC - No Detailed Affiliation Given 148pp 16570 233

B212270534 "Direct Reactor Auxiliary Cooling Sys Modeling in SSC," interim rept
CHAN, B C , GUPPY, J G , KENNETT, R J Brookhaven National Laboratory FIN A-3015 BNL-NUREG-32170 82/10/31
CURTIS, R T , WOOD, P M Division of Accident Evaluation 38pp 16550 326

B212280031 "Degradation of Steam Generator Tubing & Components by Operation of PHRs "
WEEKS, J R , CZAJKOWSKI, C J Brookhaven National Laboratory FIN A-3011 BNL-NUREG-31864 82/12/21
Office of Nuclear Regulatory Research, Director 13pp 16593 127

B212280040 "Properties of Radwastes & Waste Containers," quarterly progress rept, Jul - Sept 1982
SHULER, K J , DAYAL, R Brookhaven National Laboratory FIN A-3027 BNL-NUREG-32069 82/11/30
KIM, K Office of Nuclear Regulatory Research, Director 13pp 16592 354

B212280051 "Effect of Shape Reactivity on Rod Ejection Accident," to be presented to Topical Meeting on Advances in Reactor Computations in Salt Lake City, UT on 830531
NEAGY, P , CAROW, J F Brookhaven National Laboratory BNL-NUREG-32105 82/09/30 6pp 16591 358

B212280055 "Tests W/Inconel 600 to Obtain Quantitative Stress Corrosion Cracking Data for Evaluating Svc Performance "
BANDY, R , VAN ROOYEN, D Brookhaven National Laboratory BNL-NUREG-31814 82/09/30 TABDADA, A Office of Nuclear Regulatory Research, Director 11pp 16592 121

B212280518 "In-Core Detector Activation-To-Power Correlation for PHN Assembly," informal rept
TODDSON, R , EISENHART, L D Brookhaven National Laboratory FIN A-3212 BNL-NUREG-32106 82/11/20
DUNENFELD, M Division of Systems Integration (post 811005) 36pp 16590 077

B212290512 "ORNL Projects for NRC Ofc of Nuclear Regulatory Research," fourth quarter rpt rept
LOTTIS, A L , BAYLOR, V B , HOMAN, F J Oak Ridge National Laboratory 82/11/30
Office of Nuclear Regulatory Research, Director 18/pp 16593 140

B212300137 "Acoustic Emission/Flaw Relationships for Inservice Monitoring of Nuclear Pressure Vessels," monthly ltr progress rept for Nov 1982
HUTTON, P H , KURTZ, R J Battelle Memorial Institute, Pacific Northwest Laboratory FIN B-2088 82/12/17 MUSCARA, J Materials Engineering Branch 16pp 16624 197

B212300402 "Accident Aerosol Characterization," informal monthly progress rept for Nov 1982
OHCAZARSKI, P C Battelle Memorial Institute, Pacific Northwest Laboratory FIN B-2287 82/12/14 BERNSTEIN, S Division of Risk Analysis 8pp 16613 195

NONDOCKETED ITEMS

411

REVIEW GRP NRC RESEARCH REVIEW GROUPS

8212020072 Summary of CRGR Meeting 25 on 821116 re proposed revision to 10CFR20, "Stds for Protection Against Radiation" Revision would reflect use of health risks as basis for radiation protection stds
STELLO,V Regional Operations & Generic Requirements 82/11/30
DIRCKS,W J Office of the Executive Director for Operations 5pp
16272 006

8212090141 Notification of CRGR 821124 meeting re Unresolved Safety Issue A-43 concerning containment emergency sump performance & proposed Reg Guide 1.97 Agenda summary info & proposed NUREG encl
STELLO,V Committee to Review Generic Requirements 82/11/12
EISENHUT,D O Division of Licensing JORDAN,E L Director's Office, Office of Inspection and Enforcement CUNNINGHAM,R E Office of Nuclear Material Safety & Safeguards, Director 122pp
16361 029

--8211120149 Forwards CRGR package for Unresolved Safety Issue A-43, "Containment Emergency Sump Performance" Issue not as significant as previously postulated CRGR review of proposed actions requested
DENTON,H R Office of Nuclear Reactor Regulation, Director 82/10/27
STELLO,V Regional Operations & Generic Requirements 200pp
16361 191

--8211120212 Forwards proposed Revision 3 to Reg Guide 1.97, "Instrumentation for Light Water Cooled Nuclear Power Plants to Assess Plant & Environ Conditions During & Following Accident," regulatory analysis & CRGR summary
MINGQUE,R B Office of Nuclear Regulatory Research, Director 82/11/04
STELLO,V Committee to Review Generic Requirements 43pp
16361 245

8212100159 Provides rept re peer review of differing prof opinion raised by R Rogers Technical basis for approval of specific licensing action less than adequate & review process for actions should be improved
DEARD,J T Peer Review Group TAC 48232 82/11/24 O'REILLY,J P Region 2, Office of Director 4pp
16399 004

8212170245 Forwards long-range CRGR agenda for Dec 1982 - Nov 1983 Mods for agenda items not reflecting current status should be forwarded to W Schwink by 830204
STELLO,V Regional Operations & Generic Requirements 82/12/16
REHM,T A, MINGQUE,R B, DENTON,H R NRC - No Detailed Affiliation Given 12pp
16459 307

8212202856 Forwards CRGR monthly rept for Nov 1982 & open items from previous meetings Info will be included in Executive Director for Operations rept to Commission for wk ending 821217
SCHWINK,H Committee to Review Generic Requirements 82/12/21
Committee to Review Generic Requirements 6pp
16503 345

8212280408 Notices of CRGR Meeting 29 on 820106 to discuss proposed revision to 10CFR51, "Environ Protection Regulations for Domestic Licensing & Related Regulatory Functions" Proposed revision encl
STELLO,V Regional Operations & Generic Requirements 82/12/23
EISENHUT,D O Division of Licensing JORDAN,E L Director's Office, Office of Inspection and Enforcement CUNNINGHAM,R E Office of Nuclear Material Safety & Safeguards, Director 2pp
16557 249

--8212280415 Forwards draft final rule revising 10CFR51, "Environ Protection Regulations for Domestic Licensing & Related Regulatory Functions" & related conforming amends re implementation of CEG NEPA regulations for review
CUNNINGHAM,O H Office of the Executive Legal Director 82/11/17
STELLO,V Regional Operations & Generic Requirements 464pp
16557 251

8212290062 Summary of CRGR Meeting 26 on 821124 re Unresolved Safety Issue A-43, "Containment Emergency Sump Performance" & revision to Reg Guide 1.97
STELLO,V Regional Operations & Generic Requirements 82/12/10
DIRCKS,W J Office of the Executive Director for Operations 5pp
16607 001

SECY POSITION PAPERS BEFORE THE COMMISSION

8212010029 Responds to FOIA request for documents setting forth policy re issuances of NRC press releases in connection w/ enforcement & licensing activities Forwards documents listed on app Documents also available in PDR
FELTON,J M Division of Rules and Records 82/11/01 HARTMAN,S Debevoise & Liberman 3pp
16287 002

--8212010143 SECY-77-574
Obtains Commission guidance re policy concerning use of cameras during licensing hearings
FOUCHARD,J J Office of Public Affairs 77/11/11 13pp
16287 052

8212010327 SECY-82-462
Recommends approval of NRC integrated human factors program plan Plan represents systematic & comprehensive approach for addressing human factors concerns important to safety in FVBS-85
DIRCKS,W J Office of the Executive Director for Operations 82/11/19 68pp
16522 053

8212060419 SECY-82-465
Requests Commission approval of recommended near-term actions related to protection against pressurized thermal shock events
DIRCKS,W J Office of the Executive Director for Operations 82/11/23 501pp
16371 001

8212070487 SECY-82-465 ERR
Page 14 to SECY-82-465
* NRC - No Detailed Affiliation Given 82/12/02 2pp
16351 361

8212090048 Responds to FOIA request for SECYs Forwards SECY-82-23, SECY-82-42, SECY-82-136, SECY-82-137, SECY-82-286 & SECY-82-315 SECY-81-400A available in PDR Review of SECY-81-622A, SECY-82-197A & SECY-82-197B continuing
FELTON,J M Division of Rules and Records 82/10/20 ORABER,L Affiliation Unknown 1p
16384 295

--8202010383 SECY-82-023
Requests Commission approval of denial of petition that licensee be held responsible for emergency planning & response to transportation on accidents involving radioactive matl Draft FR notices, proposed rule & ltrs encl
DIRCKS,W J Office of the Executive Director for Operations 82/01/18 88pp
16384 301

--8203090677 SECY-82-042
Requests approval of proposed amend to existing Section 274b agreement w/State of TX Proposed agreement, proposed FR notice, staff analysis of comments, proposed press release & proposed ltr to governor encl
DIRCKS,W J Office of the Executive Director for Operations 82/02/01 30pp
16385 029

--8204160270 SECY-82-136
Seeks Commission approval of AD determination re blockage of coolant flow to safety-related sys & components
Draft FR notice encl
DIRCKS,W J Office of the Executive Director for Operations 82/03/30 19pp
16385 060

--8204160262 SECY-82-137
Recommends that Commission approve AD recommendation re major deficiencies in mgt controls at nuclear power plant
Draft FR notice encl
DIRCKS,W J Office of the Executive Director for Operations 82/03/30 9pp
16385 080

--8212090224 SECY-82-286
Recommends that Commission approve publication of proposed rulemaking re staffing at nuclear power plants
DIRCKS,W J Office of the Executive Director for Operations 82/07/02 72pp
16385 093

--8209280513 SECY-82-315
Requests Commission approve publication of for comment NUREG-0906, "Guidance for Implementation of 10CFR50 34(g)" Section requires applicants to evaluate differences from SRP
DIRCKS,W J Office of the Executive Director for Operations 82/07/26 16pp
16385 166

8212100088 SECY-82-447A
Suggests encl revision of Nuclear Licensing Reform Act of 1983 be inserted as replacement for Chapter II of draft rept of Regulatory Reform Task Force Mark-up of former package encl for ref
TOURTELLOTTE,J Regulatory Reform Task Force 82/11/30 133pp
16399 095

8212230166 Responds to FOIA request for SECY-82-322, "Review of Director's Decision 2 206 Petition (PSC of NH)" & S Chilk memo to L Bickwit Forwards requested documents
FELTON,J M Division of Rules and Records 82/11/04 GOLDSMITH,M W Energy Research Group, Inc 1p
16540 314

NONDOCKETED ITEMS

--B209010092 SECY-82-322

Recommends that Commission not review B20706 Director's decision denying Seacoast Anti-Pollution League B20205 request for order to show cause why CP should not be suspended or revoked due to lack of financial qualification
MALSCH, M G Office of the General Counsel 82/07/30 4pp
16540 315

B212290036 Responds to FOIA request for five categories of documents
Forwards documents listed in App A Review of documents re
Item 1 continuing

FELTON, J M Division of Rules and Records 82/12/02 HIATT, S L
Ohio Citizens for Responsible Energy 2pp 16607 133

--B212290039 SECY-82-275

Informs Commission of public comments received on NRC,
JH Hendrie & util group proposed ATMS rules & current status
of rulemaking effort
DIRCKS, W J Office of the Executive Director for Operations
82/06/28 18pp 16607 140

STATE PROG STATE PROGRAMS

B212010496 Agrees to assist in preparation of EIA for application for
low level radwaste disposal site, per B20920 request Meeting
to discuss roles & responsibilities suggested
NUSSBAUMER, D A Assistant Director for State Agreements Programs
82/11/04 HAZLE, A J Colorado, State of 1p 16270 236B212020388 Comments on State of CO proposed policy on financial tests
as surety for mill licenses Policy generally acceptable
Specifics of how parent company assumes responsibility for
subsidiary requested
SCARANO, R A Low Level Waste Licensing Branch 82/11/02
NUSSBAUMER, D A Assistant Director for State Agreements Programs
2pp 16297 358B212090048 Responds to FOIA request for SECYs Forwards SECY-82-23,
SECY-82-42, SECY-82-136, SECY-82-137, SECY-82-286 &
SECY-82-315 SECY-81-600A available in PDR Review of
SECY-81-622A, SECY-82-197A & SECY-82-197B continuing
FELTON, J M Division of Rules and Records 82/10/20 GRABER, L
Affiliation Unknown 1p 16384 295

--B203090677 SECY-82-042

Requests approval of proposed amend to existing Section 274b
agreement w/State of TX Proposed agreement, proposed FR
notice, staff analysis of comments, proposed press release &
proposed ltr to governor encl
DIRCKS, W J Office of the Executive Director for Operations
82/02/01 30pp 16385 029

--B212090065 Advises that Commission has approved proposed amend to
existing Section 274b Agreement w/TX Ofc of State Programs
informed of action by telephone on B20226 Agreement should
be forwarded for signature of Chairman Palladino by B20312
CHILK, S J Office of the Secretary of the Commission 882-042
82/02/26 DIRCKS, W J Office of the Executive Director for
Operations 1p 16385 028B212090157 Responds to B21112 ltr re proper reporting procedures for
emergency exercise before formulation of official findings
Preliminary concerns should be reported to regional state
liaison officer, R Trojanowski
O'REILLY, J P Region 2, Office of Director 82/11/22 MYERS, I L
Alabama, State of 2pp 16387 102B212090235 Forwards "Rept & Staff Evaluation of KY Radiation Control
Program for Period 810501-820423 " Rept contains NRC
findings & State of KY comments on findings
WOODRUFF, R L Region 2, Office of Director 82/11/05 ADAMS, D.
Kentucky, State of 1p 16363 090--B212090240 "Rept & Staff Evaluation of KY Radiation Control Program for
Period 810501-820423, " 21st regulatory program review
* NRC - No Detailed Affiliation Given 82/11/05 138pp
16363 091B212090315 Responds to B20903 request for technical assistance, due to
staff turnover in radiation control section. Special
assistance will be provided on limited basis, in terms of
consultations & onsite training
O'REILLY, J P. Region 2, Office of Director. 82/11/08 ALLEN, D T.
Kentucky, State of 2pp. 16365 044--B212090317 Requests NRC assistance in training personnel, due to recent
staff turnover in radiation control section.
ALLEN, D T Kentucky, State of 82/09/03 O'REILLY, J P Region
2, Office of Director 2pp 16365 046B212090390 Confirms discussion held following review & evaluation of
state radiation control program FL program for regulation of
agreement met adequate & compatible w/NRC program Minor
comments developed during review encl
O'REILLY, J P Region 2, Office of Director 82/11/19 HOWELL, J J
Florida, State of 4pp 16364 245B212090470 Forwards "Rept & Staff Evaluation of State of SC Radiation
Control Program," for period 810521-820618
WOODRUFF, R L Region 2, Office of Director 82/11/05 JACKSON, R G
South Carolina, State of 1p 16364 030--B212090476 "Rept & Staff Evaluation of State of SC Radiation Control
Program," for period 810521-820618
* Region 2, Office of Director 82/06/18 88pp 16364 031--B212090481 Ack receipt of NRC ltr re recent NRC evaluation of Agreement
State program N/A stated encl
JACKSON, R S South Carolina, State of 82/07/27 O'REILLY, J P
Region 2, Office of Director 1p 16364 119B212100111 Responds to FOIA request for seven categories of info re
NFS, Erwin, TN Forwards documents listed in App A Documents
listed in App B withheld (ref FOIA Exemptions 3 & 5)
FELTON, J M Division of Rules and Records 82/11/12 WEISS, E R
Harmon & Weiss 4pp 16388 157--B212100121 Forwards addl comments on proposed license conditions for
NFS-Erwin re emergency preparedness
GRINES, B K Division of Emergency Preparedness 82/03/23
PAGE, R Q Uranium Fuel Licensing Branch 1p 16388 164--B212100128 Ack receipt of B20225 concerns re timeliness of alerting N
notifying nearby residents in event of certain type of
emergency at NFS, Inc Emergency planning license conditions
for NFS discussed
TROJANOWSKI, R Region 2, Office of Director 82/03/12
GRAHAM, J A Tennessee, State of 2pp 16388 165B212200069 PNA-82-010 on B21212, 0 5 C; Cs-137 sealed source in
container lost during shipment between Houma, LA &
Cameron, LA Source not found Media interest anticipated
DODA, R J Region 4, Office of Director 82/12/13 1p 16474 26dB212210161 PNA-82-010A on B21213, lost well logging source recovered
near Houma, LA NRC considering appropriate enforcement
action
* Region 4, Office of Director 82/12/16 1p 16483 361B212220549 Notification of contract execution, Mod 2 to "Environ
Surveillance for Measuring Concentrations of Radioactivity &
Radiation Levels in Environ of Commission Licensed
Activities " Contractor State of GA
SILVIS, R M Research Contracts Branch FIN B-5203 NRC-05-79-25d
82/12/15 COBB, L Training & Administration Staff COHEN, L NRC
No Detailed Affiliation Given 1p 16523 349--B212220553 Mod 2, deobligating funds, to "Environ Surveillance for
Measuring Concentrations of Radioactivity & Radiation Levels
in Environ of Commission Licensed Activities Located Within
State of GA & Selected by Commission "
LEDBETTER, J L Georgia, State of GUSTAVE, R P Division of
Contracts FIN B-5203 NRC-05-79-252 82/12/15 1p 16523 350B212270443 NUREG/BR-0025 V08N11
INFORMATION REPORT ON STATE LEGISLATION
KERR, O W Office of State Programs, Director 82/12/31 NRC - No
Detailed Affiliation Given 19pp 16566 339

TOPREP VENDOR REPORTS AND RELATED CORRESPONDENCE

B210210467 Forwards revisions to nonproprietary WCAP-8587, Suppl 1
"Equipment Qualification Data Packages" & proprietary
WCAP-8687, Suppl 2 "Equipment Qualification Test Repts "
Proprietary repts withheld (ref 10CFR2 790)
RAHE, E P Westinghouse Electric Corp NS-EPR-2668 82/10/13
MILLER, J R Standardization & Special Projects Branch 2pp
15763 090--B210210475 Submits application for withholding proprietary WCAP-8687,
Suppl 2 "Equipment Qualification Test Repts," per
10CFR2 790 Affidavit AW-80-27 encl
WIESEHANN, R A Westinghouse Electric Corp AW-82-60 82/10/13
MILLER, J R Standardization & Special Projects Branch 11pp
15763 092

NONDOCKETED ITEMS

413

--B2102104B4 WCAP-8587S1RO ESE-1B
"Equipment Qualification Data Package," Revision 0 to Suppl 1, EODP-ESE-1B, "Veritak Pressure Transmitters Qualification Group A"
RAHE, E P Westinghouse Electric Corp EODP-ESE-1B 02/09/30
23pp 15763 103

--B2102104B9 WCAP-8587S1RO ESE-3B
"Equipment Qualification Data Package," Revision 0 to Suppl 1, EODP-ESE-3B, "Veritak Differential Pressure Transmitters Qualification Group A"
RAHE, E P Westinghouse Electric Corp EODP-ESE-3B 02/09/30
21pp 15763 126

B212010151 Forwards "Final Reviews of TRAP-2, POWER TRAIN & CADDs Topical Repts"
ABRAMSON, P D Argonne National Laboratory FIN A-2121 02/09/02
JENSEN, W Reactor Systems Branch 59pp 16258 148

B212020200 Forwards Revision 1 to CEN-152, "C-E Emergency Procedure Guidelines Vols 1 & 2," in response to D0 Eisenhower
801031 ltr & NUREG-0737, Item I C I Guidelines intended to supersede & replace guidelines in CEN-128
WELLS, R W C-E Operating Plants Owners Group WELLS, R W Northeast Utilities RW-82-67 02/11/22 EISENHUT, D O Division of Licensing 2pp 16272 066

--B212020208 Informs that author replaces KP Baskin as chairman of C-E owners group Policy re communications between owners group & NRC reaffirmed
WELLS, R W C-E Operating Plants Owners Group WELLS, R W Northeast Utilities RW-82-61 02/10/19 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 16272 068

- B212020212 CEN-152 R01
Revision 1 to CEN-152, "Emergency Procedure Guidelines"
* C-E Operating Plants Owners Group 02/11/30 723pp
16272 070

B212020204 Requests resources & review be made available for licensing issues to be considered in EPRI LWR standardization program
Response by B21119 requested
DENTON, H R Office of Nuclear Reactor Regulation, Director 02/11/15 MATTSOHN, R J Division of Systems Integration (post 811005) HANAVER, B H Division of Safety Technology VOLLMER, R H Division of Engineering 24pp 16302 338

B212020267 Forwards proprietary "Westinghouse Advanced PWR Pretendering Module 2 Secondary Side Safeguards" Rept withheld (ref 10CFR2 790) Application for withholding & affidavit encl
RAHE, E P Westinghouse Electric Corp NS-EPR-2688 02/11/29
MIRAOLIA, F Assistant Director for Safety Assessment 2pp
16290 334

--B212020271 Application for withholding proprietary "Westinghouse Advanced PWR Pretendering Module 2 Secondary Side Safeguards" Affidavit encl
WIESEMANN, R A Westinghouse Electric Corp AW-82-69 02/11/29
MIRAOLIA, F Assistant Director for Safety Assessment 9pp
16290 336

B212030098 Forwards proprietary "Exxon Nuclear Co ECCS Cladding Swelling & Rupture Model," Revision 1 Rept withheld (ref 10CFR2 790)
CHANDLER, J C Exxon Nuclear Co, Inc (subs of Exxon Corp) JCC 113 82 02/12/01 THOMAS, C O Standardization & Special Projects Branch 1p 16304 171

B212030229 Requests comments on requirements of Reg Guide 1.97 for reactor coolant temp indication Requirements not met by Westinghouse design Summary of NRC views encl
EISENHUT, D O Division of Licensing LS05-82-11-072 02/11/18
KINGSLEY, D D Westinghouse Operating Plants Owners Group
KINGSLEY, D D Alabama Power Co 5pp 16316 350

B212080552 Agrees w/JS Charnley 820831 ltr proposing administrative amend to licensing Topical Repts NEDE-24011-P-A-4 & NEDE-24011-P-A-4-UB Exception taken w/fuel design option change re barrier fuel, normally reviewed by NRC
THOMAS, C O Standardization & Special Projects Branch 02/11/29
SHERWOOD, O O General Electric Co 2pp 16368 360

B212080603 Notification of B21221 meeting w/Westinghouse owners group in Bethesda, MD to discuss presentation on proposed methods for using reliability data for revising instrumentation sections of STB
BRINKMAN, D S Standardization & Special Projects Branch 02/11/18
THOMAS, C O Standardization & Special Projects Branch 2pp
16379 348

B212090003 Notification of B21207 meeting w/OE, MIT, BNL & Mark I owners group in Bethesda, MD to discuss suppression pool local to bulk temp difference analysis associated w/Mark I long-term program post-implementation review
SIEGEL, B L Operating Reactors Branch 2 02/11/24 VASSALLO, D B Operating Reactors Branch 2 1p 16379 361

B212090077 Advises that issue of wetwell/drywell vacuum breaker actuation during pool swell not applicable to Mark I plants, in response to B21112 questions
PEPPERLEN, H C General Electric Co MFN-186-82 02/11/28
VASSALLO, D B Operating Reactors Branch 2 3pp 16357 327

B212090148 Forwards "Mark I Containment Program Augmented Class 2/3 Fatigue Evaluation Method & Results for Typical Torus Attached & Safety Relief Valve Piping Sys"
PEPPERLEN, H C General Electric Co MFN-187-82 02/11/30
VASSALLO, D B Operating Reactors Branch 2 2pp 16359 121

--B212090155 MPR-751
"Mark I Containment Program Augmented Class 2/3 Fatigue Evaluation Method & Results for Typical Torus Attached & Safety Relief Valve Piping Sys"
* MPR Associates, Inc 02/11/30 44pp 16359 123

B212100052 Notifies that XN-RF-1A, "QA Program Topical Rept for Nuclear Fuel Design & Fabrication," Revision 5, acceptable
HAASB, W P Quality Assurance Branch 02/12/06 VOLMER, C J Exxon Nuclear Co, Inc (subs of Exxon Corp) 2pp 16399 342

B212100111 Responds to FOIA request for seven categories of info re NRS, Erwin, TN Forwards documents listed in App A Documents listed in App B withheld (ref FOIA Exemptions 3 & 5)
FELTON, J M Division of Rules and Records 02/11/12 WEISS, E R Harman & Weiss 4pp 16388 157

--B212100121 Forwards addl comments on proposed license conditions for NRS-Erwin re emergency preparedness
GRIMES, D K Division of Emergency Preparedness 02/03/23
PAGE, R G Uranium Fuel Licensing Branch 1p 16388 164

B212130097 Advises that "Application of Exxon Nuclear Co PWR Thermal Margin Methodology to Mixed Core Configurations," Revision 1, generically applicable to all open lattice PWRs
COOKE, O C Exxon Nuclear Co, Inc (subs of Exxon Corp) 0CC-047 82 02/12/07 HOLMICH, J J Core Performance Branch 1p 16390 189

B212130217 Forwards "FOAM2 - Computer Program to Calculate Core Swell Level & Mass Flow Rate During Small Break LOCA," in response to NUREG-0565 & NUREG-0737, Item II K 3 30
TAYLOR, J H Babcock & Wilcox Co 02/12/01 BERGOREN, J S Standardization & Special Projects Branch 1p 16398 142

--B212130220 BAW-10155
"FOAM2 - Computer Program to Calculate Core Swell Level & Mass Flow Rate During Small Break LOCA"
* Babcock & Wilcox Co 02/11/30 39pp 16398 143

B212130233 Provides info per B21201 telcon re submittal of App 1 to "B&W Small Break LOCA ECCS Evaluation Model" App 1 will be submitted under NUREG-0737, Item II K 3 31
TAYLOR, J H Babcock & Wilcox Co 02/12/03 SHERON, B Reactor Systems Branch 1p 16397 016

B212130234 Notifies of withdrawal of Topical Rept BAW-10026P (NP), "Reactor Vessel Model Flow Test for 145 FA Core" Withdrawal based on decision to discontinue marketing nuclear steam sys
TAYLOR, J H Babcock & Wilcox Co 02/11/23 BERGOREN, J S Standardization & Special Projects Branch 2pp 16390 143

B212130262 Advises that Topical Rept WCAP-10170, "Emergency Response Facilities Design & V&V Process," submitted separately for NRC review & approval, concomitant w/review of design basis & functional sys requirements.
RAHE, E P Westinghouse Electric Corp NS-EPR-2689 02/12/01
THOMAS, C O Standardization & Special Projects Branch 1p 16396 243

B212130296 Forwards proprietary & nonproprietary responses to NRC B21109 questions on WCAP-9863/9864 re methodology for use on two, three & four loop plants, both first cycle & reloads
Application for withholding proprietary info forwarded
RAHE, E P Westinghouse Electric Corp NS-EPR-2690 02/12/10
THOMAS, C O Standardization & Special Projects Branch 1p 16389 289

NONDOCKETED ITEMS

--B212130302 Requests withholding of proprietary responses to NRC questions on WCAP-9863/9864 per 10CFR2 790 Affidavit 76-B & nonproprietary responses w/info deleted encl
WIESEHANN, R A Westinghouse Electric Corp AW-82-72 82/12/10
THOMAS, C D Standardization & Special Projects Branch 18pp
16389 290

B212130360 Approves encl proposed route for transport of spent reactor fuel
SHERR, T S Material Transfer Safeguards Licensing Branch 82/12/01
EMBILIER, T Battelle Memorial Institute, Columbus Laboratories
12pp 16415 001.

B212140092 Forwards affidavit attesting that Bechtel Specs J-110 & J-104 & Calculations FL-01, Revision 0, PB FC-01, Revision 1, PB FC-01, Revision 2 & FC-13, Revision 0 are proprietary & should be withheld per 10CFR2 790
KOHES, J M Bechtel Corp 82/12/09 ALLISON, D NRC - No Detailed Affiliation Given 5pp 16408 273

B212140190 Responds to NRC consultant conclusions on XN-NF-621(P), Revision 1, "Exxon Nuclear DNS Correlation for PHR Fuel Designs " One population for CHF data base recognized 14 test sections
CHANDLER, J C Exxon Nuclear Co., Inc (subs of Exxon Corp)
JCC-120 82 82/12/09 HOLONICH, J J Core Performance Branch 3pp
16410 217.

B212140501 Forwards CENPD-270, "Dry Storage Cask for ISFSI "
SCHERER, A E Combustion Engineering, Inc LD-82-088 82/11/11
ROUSE, L C Advanced Fuel & Spent Fuel Licensing Branch 1p
16431 158

--B212140510 CENPD-270
"Dry Storage Cask for ISFSI."
* Combustion Engineering, Inc 82/10/31. 41pp 16431 159

B212150003 Forwards Revision 1, Suppl 1 to "Gadolina Fuel Properties for LWR Fuel Safety Evaluation "
CHANDLER, J C Exxon Nuclear Co., Inc (subs of Exxon Corp)
JCC-121 82 82/12/13 THOMAS, C D Standardization & Special Projects Branch 1p 16425 148

--B212150005 XN-NF-79-56(NP)(A)R1
Revision 1, Suppl 1 to "Gadolina Fuel Properties for LWR Fuel Safety Evaluation "
* Exxon Nuclear Co., Inc (subs of Exxon Corp) 82/12/10
32pp. 16425 149

B212150055 Informs of three changes to LOCTA-IV computer code used to calculate fuel rod heatup transient in Westinghouse ECCS evaluation model First change concerns modeling of distribution of energy deposition during LOCA
RAHE, E P Westinghouse Electric Corp NS-EPR-2699 82/11/08
MILLER, J R Standardization & Special Projects Branch 3pp
16431 004

B212160365 WCAP-10170
"Emergency Response Facilities Design & V&V Process "
GALLAGHER, J M, HERRICK, E O, GURCAK, A W Westinghouse Electric Corp 21280 1/102582 82/04/29 33pp 16442 250

B212170396 Advises that Revision 22 to Topical Rept CE-1-A re QA program for nuclear power plants acceptable
HAASS, W P Quality Assurance Branch 82/12/08 SWARTZ, E D
Commonwealth Edison Co 1p 16478 141

B212200040 Forwards proprietary & nonproprietary responses to Revision 1 to WCAP-9179/WCAP-9224, "Properties of Fuel & Component Matis." (BER open item re Zircaloy irradiated properties) Proprietary response withheld
RAHE, E P Westinghouse Electric Corp NS-EPR-2697 82/11/30
THOMAS, C D Standardization & Special Projects Branch 2pp
16478 095

--B212200062 Requests withholding of responses to WCAP-9179/WCAP-9224, "Properties of Fuel & Core Component Matis." Revision 1
WIESEHANN, R A Westinghouse Electric Corp AW-82-70 82/11/30
THOMAS, C D Standardization & Special Projects Branch 7pp
16478:097

B212210935 Forwards requests for addl info to complete review of WCAP-10079 (P), "NOTRUMP A Nodal Transient Small Break & General Network Code." & WCAP-10054 (P) "Westinghouse Small Break ECCS Evaluation Model "
THOMAS, C D Standardization & Special Projects Branch 82/12/03
RAHE, E P Westinghouse Electric Corp 2pp 16502 289

--B212210538 Round 1 questions re Reactor Sys Branch review of WCAP-10054, "Westinghouse Small Break ECCS Evaluation Model Using NOTRUMP Code." & WCAP-10079, "NOTRUMP Nodal Transient Small Break & General Network Code "
* Reactor Systems Branch 82/12/03 23pp 16502 290

B212220182 Forwards addl responses re environ & seismic open items per B21019-20 & 1201 meetings Combination of comprehensive testing & analysis assures structural integrity & operability of motors
RAHE, E P Westinghouse Electric Corp NS-EPR-2695 82/12/16
NOONAN, V Equipment Qualification Branch 28pp 16503 055

B212270473 Responds to B21129 request for review of C-E rept, "Dry Storage Cask for ISFSI " Casks conform w/QA program
CENPD-210-A, Revision 3 Program reviewed in 1977 & accepted
HAASS, W P Quality Assurance Branch 21665 82/12/08 ROUSE, L C
Advanced Fuel & Spent Fuel Licensing Branch 1p 16566 360

B212270553 Notification of rescheduled B21217 meeting w/OE, BNL, MET, Detroit Edison & Mark 1 owners group in Bethesda, MD to discuss suppression pool local to bulk temp difference analysis associated w/Mark 1 long-term program
STIGEL, D L Operating Reactors Branch 2 82/12/02 VASSALLO, D B
Operating Reactors Branch 2 1p 16546 342

B212280168 Forwards Amend 6 to Duke-1-A, QA program
ORIER, G W Duke Power Co 82/12/21 HAASS, W P Quality Assurance Branch 1p 16563 222

--B212280173 DUKE-1-A A06
Amend 6 to Duke-1-A, QA program
ORIER, G W, CAMP, L F Duke Power Co 82/12/21 108pp
16563 224

B212290188 Forwards CEN-227, "Summary Rept on Operability of Pressurized Safety Valves in C-E Designed Plants." in response to NUREG-0737, Item II D 1 W/o encl
WELLS, R W C-E Operating Plants Owners Group HELLS, R W Northrost
Utilities RWW-82-70 82/12/20 BERNARD, H Standardization & Special Projects Branch 2pp 16578 055

B212290466 Summary of B21130 meeting w/Westinghouse re advanced PHW std design program
MEYER, D Standardization & Special Projects Branch 82/12/15
Standardization & Special Projects Branch 2pp 16606 058

B212300034 Forwards prepublication draft of Revision 3 to BWR emergency procedure guidelines Revision adds guidelines re secondary containment control & radioactivity release control
BENTE, T J BWR Owners Group BWR00-8262 82/12/22 ETSENHUT, D O
Division of Licensing 2pp 16598 312

--B212300036 Prepublication draft of Revision 3 to emergency procedure guidelines
* BWR Owners Group 82/12/08 66pp 16598 314

WASTE MGT NUCLEAR WASTE MANAGEMENT

B212010003 Notification of B21110 seminar entitled, "EPA High Level Waste Std - Current Status & NMSS Perspective on Implementation " in Silver Spring, MD
KNAPP, M R High Level Waste Licensing Management Branch 82/11/09
High Level Waste Licensing Management Branch 1p 16271 361

B212010008 Forwards title page & table of contents to Sept 1982 final published version of PNL-3632, "AEGIS Technology Demonstration for Nuclear Waste Repository in Basalt " W/o encl
GORDON, M J High Level Waste Licensing Management Branch 82/11/09
COOK, F R High Level Waste Licensing Management Branch
GREEVES, J T, JUSTUS, P S High Level Waste Technical Development Branch 1p 16290 224

B212010010 Forwards list of individuals requiring copy of Hanford site characterization rept
WRIGHT, R J Office of Nuclear Material Safety & Safeguards, Director
82/11/10 STILL, N, HALL, J Division of Waste Management 3pp
16290 221

B212010013 Summary of B20429 meeting w/Dow Chemical Co in Silver Spring, MD re waste form provisions of 10CFR61
JOHNSON, T C Low Level Waste Licensing Branch 82/11/12
MARTIN, J B Division of Waste Management 4pp 16290 217

B212010025 Forwards draft "Generic Radiological Characterization Protocol for Surveys Conducted for DOE/OS Remedial Action Programs," in response to B21012 ltr w/cover page but w/o text
MOTT, H E Energy, Dept of B2/10/26 SCARAND, R A Low Level Waste Licensing Branch 2pp 16271 359

B212010045 Forwards "Review Plan for Site Characterization Repts," "BWIP Issues Identified by NRC" & "Schedules for Production of BWIP Draft Site Characterization Analysis" Identified BWIP issues encl w/o schedules for analysis
MILLER, H J High Level Waste Licensing Management Branch B2/11/15
MARTIN, J R Division of Waste Management 23pp 16289 152

--B212010069 Revised "Review Plan for Site Characterization Repts" * Division of Waste Management B2/11/30 24pp 16289 175

B212010217 Comments on revised memorandum of understanding re ACRS participation in NRC rulemaking & policy making activities New agreement adds at least 4 months to process New administrative steps will increase paperwork
BUNTING, J D Licensing Process & Integration Branch B2/11/05
ROUSE, L C Advanced Fuel & Spent Fuel Licensing Branch 1p 16290 295

B212010220 Forwards ltr sent to Governor Spellman of WA State forwarding site characterization rept & informing of NRC role in process List of addressees attached
BUNTING, J D Licensing Process & Integration Branch B2/11/15
NRC - No Detailed Affiliation Given 1p 16290 299

--B212010221 Forwards site characterization rept for candidate high level waste repository on Hanford Reservation Procedural portion of 10CFR60 repository licensing rule also encl w/o encls
DAVIS, J O Office of Nuclear Material Safety & Safeguards, Director B2/11/15 SPELLMAN, J Washington, State of 5pp 16290 300

B212010227 Forwards branch fact sheet addressing disposal of wastes containing transuranic nuclides
DRAGONETTE, K Low Level Waste Licensing Branch B2/11/17
SALOMON, S Office of State Programs, Director 1p 16290 305

--B212010228 "Disposal of Low Level Wastes Containing Transuranic Elements" * Low Level Waste Licensing Branch B2/11/17 4pp 16290 306

B212010232 Forwards "Characterization of Class B Stable Radwaste Packages of New England Nuclear Corp." Final rept w/o encl
BROWNING, R E Division of Waste Management B2/11/15 DUMAS, D New England Nuclear Corp 1p 16290 312

B212010240 Submits editorial recommendations for Basalt Waste Isolation Project site characterization analysis products
ULECK, R B High Level Waste Licensing Management Branch B2/11/16
High Level Waste Licensing Management Branch 2pp 16290 313

B212010242 Requests two addl copies of Basalt Waste Isolation Project site characterization rept for hydrogeology review group
WRIGHT, R J High Level Waste Licensing Management Branch B2/11/16
STILL, N NRC - No Detailed Affiliation Given 1p 16290 317

B212010245 Discusses J Kimball limited participation in review of Basalt Waste Isolation Project site characterization rept Attendance at B21115 meeting requested
WRIGHT, R J High Level Waste Licensing Management Branch B2/11/17
JACKSON, R Geosciences Branch 2pp 16290 315

B212010250 Forwards info on process formerly used by Luminous Processes, Inc in mfg aircraft dials made w/tritiated paint Info should be helpful in determining Luminous Processes waste form characteristics w/o encl
PERSON, L S Low Level Waste Licensing Branch B2/11/03
BARLETTA, R Brookhaven National Laboratory 1p 16271 291,

B212010252 Discusses B21013 ltr re test method for determining density changes in actinide-doped waste forms Vote of no will be recorded unless MCC-125 test procedure & Section 3 & Equation 6 revised as indicated
BELL, M J High Level Waste Licensing Management Branch B2/11/17
STEINDLER, M J Argonne National Laboratory 2pp 16271 252

B212010302 Responds to L Olson B20923 ltr re workshops & Hanford Site Characterization rept Lists question & answer made necessary for rept clarification
MILLER, H J High Level Waste Technical Development Branch B2/11/05
ANTTONEN, J H Affiliation Unknown 3pp 16271 279

B212010457 Forwards editorial requirements for use in preparing all contracted products under NRC-02-B2-045 No change in cost or delivery of products expected w/o encl
VERMA, T R High Level Waste Technical Development Branch NRC-02-B2-045 B2/11/19 HOWE, J Golder Associates 1p 16268 167

B212010476 Agrees to assist in preparation of EIA for application for low level radwaste disposal site, per B20920 request Meeting to discuss roles & responsibilities suggested
NUSSBAUMER, D A Assistant Director for State Agreements Programs B2/11/04 HAZLE, A J Colorado, State of 1p 16270 256

B212010500 Comments on B6 Grand Junction, CO vicinity properties, per B20920 request Agrees w/conditional designation of properties & need for engineering assessment phase of remedial action
SCARAND, R A Low Level Waste Licensing Branch B2/10/29 MOTT, W E Energy, Dept of 2pp 16270 257

B212010505 Comments on advanced draft of "Site Recommendation Guidelines" Clarification re specific application of siting factors required Selection of repository site must satisfy 10CFR60 criteria
BELL, M J High Level Waste Licensing Management Branch WHML 3109 3 B2/10/28 BALLARD, W Energy, Dept of 2pp 16270 259

B212010508 Concurs w/revised final remedial action concept paper, per B21001 request
SCARAND, R A Low Level Waste Licensing Branch WHML KJH B2/10/21 CAMPBELL, R H Energy, Dept of 1p 16270 261

B212010514 Forwards "Preliminary Site Stabilization & Closure Plan for Barnwell Low Level Radwaste Disposal Facility" & NUREG/CR-2478, Vol 1, per meeting in Natural Bridge State Park, KY re Maxey Flats low level waste facility w/o encl
PENNINGILL, R A Low Level Waste Licensing Branch WH 409 18 B2/11/04 PAGE, R Kentucky, State of 1p 16270 262

B212020040 Act receipt of B21013 request to place list of Federal agencies generating low level waste on blank tape
JACKSON, K C Low Level Waste Licensing Branch WHML 204 2 3 B2/10/29 JORDAN, E A Energy, Dept of 1p 16317 082

B212020060 Forwards revised remedial action concept paper & comments, per K Hamill B20916 telcon
CAMPBELL, R H Energy, Dept of B2/10/01 SCARAND, R A Uranium Recovery Licensing Branch 2pp 16317 025

--B212020073 UMTRA-DOE/AL-33 Revised "Remedial Action Concept Paper for U Mill Tailings at Vitro Site, Salt Lake City, UT" * Energy, Dept of B2/10/31 23pp 16317 027

B212020114 Notifies of development of draft NRC QA Review Plan for reviewing adequacy of QA programs for geotechnical investigations re site characterization activities for nuclear waste repositories Requests meeting & discussion
MILLER, H J High Level Waste Technical Development Branch WHMT 109 4 B2/11/04 BALLARD, W Energy, Dept of 1p 16317 070

B212020117 Forwards tape for record of latest working SPLASHWATR code Requests any prepared documentation w/o encl
GORDON, M J High Level Waste Licensing Management Branch WHML 3109 9 B2/11/10 MILLY, C D Princeton Univ 1p 16310 362

B212020121 Submits info re shallow land disposal of low level nuclear waste NRC responsible for regulating disposal of radwastes DOE responsible for R&D of different disposal methods
Forwards NUREG-0879 & 0782 w/o encl
BURMEIER, J J Division of Waste Management WHMP1 411 1 B2/10/21 FORBSTER, J H Affiliation Unknown 2pp 16308 300

B212020128 Submits instructions for Basalt Waste Isolation Project site characterization assessment authors
ULECK, R B High Level Waste Technical Development Branch B2/11/05
BELL, M J, MILLER, H J, WRIGHT, R NRC - No Detailed Affiliation Given 1p 16308 298

B212020132 Submits principles to be followed re submittal of documents for word processing for Basalt Waste Isolation Project site characterization assessment
MILLER, H J High Level Waste Technical Development Branch, BELL, M J High Level Waste Licensing Management Branch B2/11/05
NRC - No Detailed Affiliation Given 2pp 16308 296

NONDOCKETED ITEMS

B212020136 Confirms conversation w/P Justus re I Alterman limited participation in review of Basalt Waste Isolation Project site characterization rept Alterman will review Chapters 3 & 13
WRIGHT, R J High Level Waste Technical Development Branch
B2/11/15 JACKSON, R Geosciences Branch 2pp 16308 294

B212020146 Forwards requested update of waste mgt portion of ofc manual chapters & 10CFR61 W/o encl
BUNTING, J O Licensing Process & Integration Branch B2/11/16
BEVERIDGE, G Program Support Branch 1p 16308 290

B212020148 Notifies that review of DOE B21112 site characterization rept for Hanford, WA reservation has commenced Draft analysis for public comment expected by mid-Mar 1983 w/final analysis expected by Sept
DAVIS, J O Office of Nuclear Material Safety & Safeguards, Director
B2/11/17 Office of Nuclear Material Safety & Safeguards, Director
2pp 16308 288

B212020171 Forwards correspondence from WJ Dirck's indicating willingness to fund work re dosimetry of Np-237 on sole-source contract basis Contract for Natl Committee for Radiation Protection will be initiated, accordingly
FENRINGER, D J High Level Waste Licensing Management Branch
B2/11/15 KNAPP, M R High Level Waste Licensing Management Branch
1p 16308 285

B212020177 Discusses DOE designation of two Salt Lake City vicinity Properties SLO37 & SLO68 in conjunction w/Vitro Chemical Co inactive mill site
FLORY, C A Low Level Waste Licensing Branch B2/10/29 Low Level Waste Licensing Branch 3pp 16308 280

B212020183 Requests DOE site characterization rept for facility be kept in library for ref purposes only
WRIGHT, R J High Level Waste Technical Development Branch
B2/11/22 CONYNGHAM, M Library Branch 1p 16308 278

B212020187 Forwards trip rept of B20824-25 visit to Columbia, SC re implementation of 10CFR61 waste form requirements
JOHNSON, T C Low Level Waste Licensing Branch B2/10/29
BROWNING, R E Division of Waste Management 6pp 16308 261

B212020195 Notifies that principle data needs per B21019 ltr & B20614 meeting satisfied by manipulating info of type contained on radioactive shipment records received at disposal sites
Meeting date of B21118 confirmed
JACKSON, K C Low Level Waste Licensing Branch WHLL 204 2 3
B2/11/17 COLEMAN, J A Energy, Dept of 2pp 16308 257

B212020196 Trip rept of B20322-23 visit to Norwood, CO to participate in Pioneer Nuclear hearing
HAMILL, K J Low Level Waste Licensing Branch B2/11/15
SCARANO, R A Low Level Waste Licensing Branch 3pp 16308 254

B212020199 Forwards BNL repts identifying phenomena applicable to assessing long-term performance of high level waste packages constructed of TiCode-12 alloy, including crevice corrosion & hydrogen embrittlement W/o encl
BELL, M J High Level Waste Licensing Management Branch B2/11/08
BALLARD, W Energy, Dept of 2pp 16308 148

B212020201 Forwards Chapter 18 of site characterization rept for Basalt Waste Isolation Project re QA Comments requested by B21130
MILLER, H J High Level Waste Technical Development Branch
B2/11/15 HAASS, W P Quality Assurance Branch 1p 16308 147

B212020203 Comments on draft low level waste mgt survey questionnaire
Draft provides excellent format for program to accumulate consistent low level waste data for input to common data sys
JACKSON, K C Low Level Waste Licensing Branch WHLL 204 2 3
B2/11/03 HARDIN, C M Conference of Radiation Control Program Directors, Inc 1p 16308 146

B212020246 Informs that record of decision re long-term mgt of liquid high level radwaste at Western NV Nuclear Svc Ctr, West Valley, appeared in B20915 FR DOE now able to construct & operate facility
PFLUM, C O High Level Waste Licensing Management Branch B2/10/26
BOYLE, R R High Level Waste Licensing Management Branch 3pp 16308 143

B212020386 Trip rept of B20614-15 meeting w/U Subcommittee of VA Coal & Energy Commission in Lexington, VA to hear expert witnesses from govt & academia discuss issues associated w/U mining & milling
HAMILL, K J Low Level Waste Licensing Branch B2/10/29
SCARANO, R A Low Level Waste Licensing Branch 2pp 16308 130

B212020387 Notification of contract execution, Mod 6 to "Cyprus Mines Corp, Hansen Project Mill Tailings Evaluation"
Contractor FC Hart Assoc, Inc
MCLEAREN, T Technical Assistance Contracts Branch FIN D-6927
NRC-02-79-056 B2/11/24 DAVIS, J O Office of Nuclear Material Safety & Safeguards, Director 1p 16297 360

--B212020390 Mod 6, incorporating indirect rate & adding addl funds, to "Cyprus Mines Corp, Hansen Project Mill Tailings Evaluation"
* Fred C Hart Associates, Inc HA00AN, T F Division of Contracts FIN D-6927 NRC-02-79-056 B2/11/24 2pp 16297 361

B212020388 Comments on State of CO proposed policy on financial tests as surety for mill licenses Policy generally acceptable
Specifics of how parent company assumes responsibility for subsidiary requested
SCARANO, R A Low Level Waste Licensing Branch B2/11/02
NUSSBAUMER, D A Assistant Director for State Agreements Programs 2pp 16297 358

B212020397 Trip rept of B11026-27 visit to CO State Univ to attend U mill tailings symposium
HAMILL, K J Low Level Waste Licensing Branch B2/10/29
SCARANO, R A Low Level Waste Licensing Branch 1p 16297 356

B212020400 Forwards trip rept of B20302-04 meetings w/industry & State of CO officials W/o encl
HAMILL, K J Low Level Waste Licensing Branch B2/10/29
SCARANO, R A Low Level Waste Licensing Branch 1p 16297 353

B212020403 Forwards plans for development of draft site characterization Analysis Plans identify products needed, sequence of parallel activities & describe sequence of daily activities between B21210 & B30121
WRIGHT, R J High Level Waste Technical Development Branch
B2/11/09 BOYLE, R, COOK, F R, KNAPP, M High Level Waste Licensing Management Branch 14pp 16297 327

B212100343 Forwards Rn-222 repts for Aug & Sept 1982 TLD chip probes for passive radon monitors improperly prepared by outside lab
MCCLUSKEY, J P Cotter Corp 20862 B2/11/15 HAZLE, A J Colorado, State of 1p 16389 189

--B212100349 Rn-222 repts for Aug-Sept 1982
* Cotter Corp 20862 B2/11/15 3pp 16389 190

B21220546 Requests complete ref to source of "Geological Aspects of Industrial Waste Disposal," to assist in search Paper unknown to geology staff
JUSTUS, P S High Level Waste Technical Development Branch
B2/11/24 CHU, J Tennessee Valley Authority 1p 16523 029

B212230034 Responds to B21103 ltr re low level radwaste disposal regulations Final version of 10CFR61 "Licensing Requirements for Land Disposal of Radwaste" & related amends encl W/o encl
DAVIS, J O Office of Nuclear Material Safety & Safeguards, Director
B2/11/30 UFFEN, R J Queen's Univ, Kingston, Canada 1p 16544 278

B212230066 Forwards comments on draft "NWTB Program Criteria for Mined Geologic Disposal of Nuclear Wastes Repository Performance & Development Criteria, DOE/NWTS 33(3)" Final document should include criteria from 10CFR60
BELL, M J High Level Waste Licensing Management Branch B2/12/01
BALLARD, W H Energy, Dept of 11pp 16544 349

B212230099 Summary of B21103 meeting w/CSU & DRNL in Region 4 ofr re proposed topical rept on long-term stability of U tailings reclamation covers
FLEMING, T E Region 4, Office of Director B2/11/29 SCARANO, R A Low Level Waste Licensing Branch 13pp 16544 311

B212230105 Summary of B21202 meeting w/EPA in Crystal City, VA re NRC & EPA plans for addressing disposal of low activity waste by less restrictive means (de minimis waste disposal)
ROLES, O W Low Level Waste Licensing Branch B2/12/10 SCARANO, R Low Level Waste Licensing Branch 4pp 16544 307

B212230114 Summary of B21117-19 meeting w/util at McGuire & Oconee plants re implementation of waste classification requirements of 10CFR61
ROLES, O W Low Level Waste Licensing Branch B2/12/09 SCARANO, R Low Level Waste Licensing Branch 3pp 16544 302

NONDOCKETED ITEMS

417

8212230118 Advises of contact w/C Cooley (DOE) re J Nell ltrs on performance assessment & content of NRC draft response Meeting will be held in Jan 1983 to prioritize performance aspects
KNAPP, M R Low Level Waste Licensing Branch 82/12/03
BROWNING, R E Office of Nuclear Material Safety & Safeguards Director 1p 16544 301

8212230126 Forwards comments on Waste Mgt section of long-range research plan Steering committee should be established to coordinate high level waste research planning
BUNTINO, J O Procedures & Certification Branch 82/12/01
BROWNE, R S Program Support Branch 22pp 16544 279

8212230133 Summary of state & tribal participation steering group 821001 meeting re proposed priorities before receipt of DOE first site characterization rept
MACDONALD, R Procedures & Certification Branch 82/12/02
BUNTINO, J O Procedures & Certification Branch MILLER, H J High Level Waste Technical Development Branch 4pp 16544 339

8212230138 Responds to questions re interface w/EPA EPA must meet statutory responsibility of setting radiological stds in areas covered by 10CFR20 302(c), since section already deleted
BUNTINO, J O Procedures & Certification Branch 82/12/03
SMITH, R D Region 4, Office of Director 1p 16544 343

8212230145 Advises that comments incorporated into "Technical Position Paper on Near-Surface Disposal Facility Design & Operation" & FR notice will be published to announce availability
PANGBURN, G C Low Level Waste Licensing Branch 82/11/23
HAWKINS, E F Low Level Waste Licensing Branch 1p 16544 058

8212230153 Forwards compilation of updated rules & petitions for quarterly update of regulatory agenda Ofc of Nuclear Regulatory Research will provide update for 10CFR60 rulemaking
BUNTINO, J O Procedures & Certification Branch 82/12/01
BROWNE, R A Program Support Branch 5pp 16544 051

8212230174 Summary of 821130-1203 meetings w/Dames & Moore in Bethesda, MD re Task D of Contract NRC-02-81-049, third work requirement, to modify EIS calculational methodology
ROLES, G W Low Level Waste Licensing Branch NRC-02-81-049
207 6/GWR/82-12 82/12/13 SCARANO, R A Low Level Waste Licensing Branch 2pp 16540 361

8212230191 Summary of ANS 821117 meeting re high level waste performance assessment
ORNSTEIN, P M Low Level Waste Licensing Branch 3407 26/PHD/82/82/12/02 KNAPP, M R High Level Waste Licensing Management Branch 5pp 16513 273

8212230209 Order directing State of NV, Dept of Human Resources, not to renew Radioactive Mat'l License 13-11-0043-02, issued to Nuclear Engineering Co, Inc
WILKES, D Nevada, State of 82/10/27 Nevada, State of 1p 16544 095

--8212230212 Findings of fact & conclusions of law re proposed renewal of Radioactive Mat'l License 13-11-0043-02, issued to Nuclear Engineering Co, Inc License should not be renewed
WILKES, D Nevada, State of 82/10/27 7pp 16544 096

8212230225 Forwards listing of error messages executed in NWMT/DVM code used in Performance Assessment Section Use of encl 1st should expedite initial debugging procedures
WEBER, M F High Level Waste Licensing Management Branch WMHL 3109 9 82/12/03 High Level Waste Licensing Management Branch 4pp 16540 357

8212230231 Forwards proposed revisions to current list of committees involving Ofc of Waste Mgt personnel W/o encl
BUNTINO, J O Licensing Process & Integration Branch 82/11/10
BROWNE, R S Program Support Branch 1p 16540 356

8212230331 Proposes single document describing generic procedures for designating UMTRAP vicinity properties incorporating screening, preliminary & comprehensive surveys needed Suggested outline encl
SCARANO, R A Low Level Waste Licensing Branch 82/12/06 MOTT, W E Energy, Dept of 16pp 16540 251

8212230382 Responds to 821022 request for comments on second draft of "Potential Health & Environ Hazards of U Mine Wastes" Recommends alternatives where regulatory gaps identified or where present stds considered inadequate
MARTIN, J B Division of Waste Management 82/11/19 SJOBLDM, O L Environmental Protection Agency 1p 16540 250

8212230387 Responds to 821101 request for info on nuclear waste Excerpts from Battelle, "Understanding Radwaste" encl DOE should be contacted for info re R&D W/o encl
STILL, N L Division of Waste Management 82/11/26 PRUNIER, C M Affiliation Unknown 2pp 16540 240

8212230388 Responds to 821026 request for info on low level waste disposal & 10CFR61 NUREG-0782, "DES for 10CFR61," will be forwarded
SCARANO, R A Low Level Waste Licensing Branch WMHL 411 4 82/11/17 FERRARA, W R Massachusetts Institute of Technology 1p 16540 239

8212230390 Responds to 821029 request for info on nuclear waste pollution Annual rept & excerpts from Battelle "Understanding Radwaste," encl W/o encl
SURMEIER, J J Licensing Process & Integration Branch WMPI 411 1 82/11/22 CLARK, G Affiliation Unknown 2pp 16540 232

8212230392 Forwards summary of 821029 meeting w/Chem-Nuclear Sys, Inc re proposed radwaste disposal site in CO Site selection process will delay licensing schedule from 3-9 months
PANGBURN, G C Low Level Waste Licensing Branch 82/11/22
HAWKINS, E F Low Level Waste Licensing Branch 3pp 16540 226

8212230394 Submits review of Sept & Oct 1982 monthly repts for Edgemont Cleanup Action Program Soil sampling map of Cottonwood & status of long-term progeny measurement program should be submitted w/Dec rept
FLORY, C A Low Level Waste Licensing Branch FIN B-2217 WMHL CAI 82/11/30 WAGMAN, N A Battelle Memorial Institute, Pacific Northwest Laboratory 2pp 16544 111

8212270430 Ack receipt of 821028 ltr commenting on draft branch technical positions on waste form & waste classification Positions still be revised to incorporate comments
BROWNING, R E Division of Waste Management 82/11/23 SHEALY, R O South Carolina, State of 1p 16571 363

8212270444 Accepts invitation to participate in 821218 workshop in Las Vegas, NV on opportunities for public involvement in NRC licensing process for high level radwaste repository
MARTIN, J B Division of Waste Management 82/11/24 TUCKER, M N Near Information & Resources Services 1p 16571 362

8212270455 Offers no comments on review of annual compilation of actions taken by NRC on QAO recommendations
BUNTINO, J O Licensing Process & Integration Branch 82/11/23
BROWNE, R S Program Support Branch 1p 16568 362

8212270464 Summary of 821026-28 Maxey Flats program review in Slade, KY Rept summarizing info gathered by NRC contractors & USGS will be compiled
PENNIFILL, R A, SIEFKEN, D L Low Level Waste Licensing Branch 82/11/18 HAWKINS, E F Low Level Waste Licensing Branch 4pp 16568 358

8212280184 Submits evaluation of TX Dept of Health 821029 submittal re TX Anaconda Rhode Ranch Required testing & QA program sufficient to assure adequacy of liner mat'l
SMITH, R D Region 4, Office of Director 82/12/02 NUSSBAUMER, D A Assistant Director for State Agreements Programs 3pp 16590 340

--8212280189 Responds to Bailly request for citation to implement NRC Comment 7 request re TX Anaconda Rhode Ranch No citation can be given as general license has not yet been issued
FOMNER, R L Regulations Division 82/11/15 NUSSBAUMER, D A Assistant Director for State Agreements Programs 1p 16590 343

8212290008 Advises that FES on 10CFR61 sent under separate cover FEH may answer 820724 questions on DES re impacts of waste mgt & disposal
DRAOGNETTE, K S Low Level Waste Licensing Branch 82/12/03
GLOSTETIN, M Massachusetts, State of 1p 16607 233

8212290024 Concurs in final draft 1982 annual status rept to Congress on UMTRAP
SCARANO, R A Low Level Waste Licensing Branch 82/11/29
PAVULITZ, J A Energy, Dept of 1p 16607 180

8212290260 Responds to 821102 request for info on nuclear waste sites Excerpts from Battelle Dec 1981 rept, "Understanding Radwaste" 1 map of waste disposal sites encl NRC vs DOE responsibilities explained W/o encl
STILL, N L Division of Waste Management 82/11/26 STAVITZ, J H South Carolina, Univ of 2pp 16606 264

NONDOCKETED ITEMS

XPORTLIC EXPORT AND IMPORT LICENSES

8212010041 Advises that export license issued w/o normal 15-day waiting period due to NRC oversight of placing license amend application in wrong file
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 82/10/28 Assistant Director for Export/Import & International Safeguards 1p 16289 105

8212010043 Advises that license to export penetration parts to Switzerland will be issued w/o normal 15-day waiting period
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 82/10/25 Assistant Director for Export/Import & International Safeguards 1p 16271 338

8212010044 Ltr of assurance re export of 895 kg U-235, contained in 29,032 kg U, to Japan
SHIRAKAWA, T Japan 82/10/26 GRIFFIN, J A Energy, Dept of 1p 16271 337

8212010048 Ltr of assurance re export of 213 kg U-235, contained in 7,462 kg U, to Japan
SHIRAKAWA, T Japan 82/10/22 GRIFFIN, J A Energy, Dept of 1p 16271 336

8212010054 Ltr of assurance re export of 643 kg U-235, contained in 19,767 kg U, to Japan
SHIRAKAWA, T Japan 82/10/22 GRIFFIN, J A Energy, Dept of 1p 16271 344

8212010057 Forwards application to export 791 kg U-235, contained in 22,000 kg U, to Belgium
KIEL, G R Exxon Nuclear Co., Inc (subs of Exxon Corp) 82/10/20 DEVINE, J B Assistant Director for Export/Import & International Safeguards 1p 16271 342

--8212010063 Application for license to export 791 kg U-235, contained in 22,000 kg U, to Belgium
KIEL, G R Exxon Nuclear Co., Inc (subs of Exxon Corp) 82/10/20 1p 16271 343

8212010072 Application to amend License XT-8552, expanding list of authorized countries & issuing new license to export 100,000 kg natural thorium to selected countries
BARNUM, E C MolyCorp, Inc 82/11/17 HEMBY, E Assistant Director for Export/Import & International Safeguards 2pp 16271 347

8212010076 Forwards application for amend to export license for minor nuclear export Ltr of assurance required w/o encl
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 82/11/22 GRIFFIN, J A Energy, Dept of 1p 16289 280

8212010081 Forwards application for export license for minor nuclear export Ltr of assurance required w/o encl
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 82/10/29 GRIFFIN, J A Energy, Dept of 1p 16271 351

8212010086 Informs that License XSNM-1979 may be issued No matl changed circumstances since issuance of License XSNM-1972
MOORE, R N Assistant Director for Export/Import & International Safeguards 82/10/27 Assistant Director for Export/Import & International Safeguards 1p 16271 350

8212010088 Requests Executive Branch position re Mitsui & Co (USA), Inc application for license to export SNM to Japan
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 82/11/22, STOIBER, C R State, Dept of, Bureau of Oceanic & Internatl Environ & Scientific Affairs 1p 16271 349

8212010093 Amend 2 to MolyCorp, Inc export license, authorizing license condition stating that total amount of natural U & thorium may not exceed 500 kg to any country per yr
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 82/11/23 1p 16289 337

8212010095 License for Sandvik Special Metals Corp to export 60 Zircaloy-4 double thinble tubes to Japan
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards SSN-2937 82/11/23 1p 16289 336

8212010101 License for Westinghouse to export 10 compensated ionization chambers to France
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 2E 40141 82/11/23 1p 16290 112

8212010106 License for MolyCorp, Inc to export 100,000 kg natural thorium, contained in rare earth compounds, to 20 listed countries
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 82/11/23 1p 16290 111

8212010110 Discusses licenses issued to MolyCorp, Inc re export of thorium contained in rare earth compounds Licenses issued authorizing export to all countries save Cuba, Vietnam, North Korea & Kampuchea & authorizing export over 10-yr period
HEMBY, E NRC - No Detailed Affiliation Given 82/11/23 NRC - No Detailed Affiliation Given 1p 16290 113

8212010114 Forwards application for license to export SNM to Japan
HATTORI, H Mitsui & Co (U S A), Inc (Subs of Mitsui & Co, Ltd) 82/11/12 Assistant Director for Export/Import & International Safeguards 1p 16271 352

--8212010120 Application for license to export 3,215 kg U-235, contained in 147,990 kg U dioxide, to Japan
MIKAMI, H Mitsui & Co (U S A), Inc (Subs of Mitsui & Co, Ltd) HSK-K1 82/11/12 1p 16271 353

8212010127 Forwards application for license to export SNM to Japan
HATTORI, H Mitsui & Co (U S A), Inc (Subs of Mitsui & Co, Ltd) 82/11/12 Assistant Director for Export/Import & International Safeguards 1p 16271 354

--8212010133 Application for license to export 1,016 kg U-235, contained in 33,079 kg U dioxide, to Japan
MIKAMI, H Mitsui & Co (U S A), Inc (Subs of Mitsui & Co, Ltd) HSK-2F1-R2 (A) 82/11/12 1p 16271 355

8212010189 Ltr of assurance re Exxon 821020 application to export 791 kg U-235, contained in 22,000 kg U, to Belgium
MARCHAL, J European Communities, Commission of 82/10/26 GRIFFIN, J A Energy, Dept of 1p 16290 298

8212010194 Forwards Marubeni America Corp application for export license for minor nuclear export Ltr of assurance required w/o encl
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 82/10/29 GRIFFIN, J A Energy, Dept of 1p 16290 296

8212010199 Forwards application for export license for minor nuclear export Ltr of assurance required w/o encl
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 82/10/26 GRIFFIN, J A Energy, Dept of 1p 16290 297

8212010461 License for Transnuclear, Inc to import 13,500 kg U, enriched to 0.85% U-235, from France
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 82/11/18 1p 16270 221

8212010468 Application to amend export license, increasing quantity of U-235, U-233, thorium & Pu, to West Germany
MOHR, W R OA Technologies, Inc /General Atomic Co IEL-4024 82/11/10 ZIMMERMAN, J Assistant Director for Export/Import & International Safeguards 1p 16270 220

8212020044 License for GE to export primary coolant pumps, fuel charging & discharging machines, control rods & specially designed or prepared parts & components for nuclear reactors, except pressure vessels, to Spain
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards BDW-82-091 82/10/29 1p 16317 081

8212020169 Requests Executive Branch position re Westinghouse application for license to export specially designed components to Brazil w/o encl
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 82/10/27 STOIBER, C R State, Dept of, Bureau of Oceanic & Internatl Environ & Scientific Affairs 1p 16308 286

8212020174 Revision to 821019 application to amend export license, revising description of components in Block 17
WILSON, B D General Electric Co BDW-092-82 82/10/20 HEMBY, E U Office of International Programs, Director 2pp 16308 283

8212020181 Requests Executive Branch position re Saunders-Roe Development, Inc application to amend license increasing mats for export to United Kingdom
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 82/10/29 STOIBER, C R State, Dept of, Bureau of Oceanic & Internatl Environ & Scientific Affairs 1p 16308 279

NONDOCKETED ITEMS

419

8212020198 License for Transnuclear, Inc to export 8,580 mCi Cf-252, in oxide form, to West Germany
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards TNF-422 82/10/29 2pp 16308 150

8212070417 Marked-up applications to amend export licenses, requesting extension for 2 yrs
MORQENSTERN, A Sigma Chemical Co 82/11/15 HEMBLY, E Assistant Director for Export/Import & International Safeguards 1p 16355 356

8212070469 Forwards Saunders-Roe Developments, Inc 821117 ltr providing addl info re 821021 request to increase amount of matl authorized in export license
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 82/11/29 STOIBER, C R State, Dept of, Bureau of Oceanic & Internatl Environ & Scientific Affairs 1p 16356 295

--8212070476 Submits addl info to 821021 application to amend license to export tritium lighting devices
PAISLEY, E J Saunders-Roe Developments, Ltd 82/11/17 HEMBLY, E Assistant Director for Export/Import & International Safeguards 1p 16356 296

8212070484 Ltr of assurance re transfer of nuclear matl to Canada
ELLYSON, C Canada, Atomic Energy Control Board 82/11/09 GRIFFIN, J A Energy, Dept of 1p 16354 273

8212070489 Forwards application for DMI to import 3,298 g U from Canada
HANNETT, B A Transnuclear, Inc 82/11/29 MOORE, N Office of International Programs, Director 1p 16356 291

--8212070503 Application for license for DMI to import 3,298 g U, containing 2,686 g U-235 & 0.70 g Pu, from Canada
HANNETT, B A Transnuclear, Inc MISC-424, 82/11/29 MOORE, N Office of International Programs, Director 3pp 16356 292

8212070502 Forwards Nissho Iwai American Corp 821116 application to amend export license, decreasing quantity of highly enriched U to 32,996 kg U, containing 30,785 kg U-235 w/o encl
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 82/11/24 STOIBER, C R State, Dept of, Bureau of Oceanic & Internatl Environ & Scientific Affairs 1p 16351 360

8212070506 Forwards Mitsui & Co 821116 application to amend export license, decreasing quantity of U-235 to 19.71 g Japanese Embassy should be notified & ltr of assurance revised accordingly w/o encl
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 82/11/23 GRIFFIN, J A Energy, Dept of 1p 16354 272

8212070513 Application for license to export 2.0 kg thorium oxide powder to Japan
COLTON, E Cerac, Inc 82/11/29 HEMBLY, E NRC -- No Detailed Affiliation Given 1p 16356 290

8212080002 License for Exxon Nuclear Co, Inc to export 791 Kg U-235, contained in 22,000 Kg U, to Belgium
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 10-20-82 82/12/02 2pp 16368 324

8212080003 License for Pacific Intl to export 90 g deuterium to South Korea
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 455 82/11/24 1p 16368 323

8212080004 License for Teledyne Wah Chang Albany to export 100 lbs Zircaloy-2 Trer tubes to West Germany.
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 8100-789 (JFM) 82/11/24 1p 16368 322

8212080016 Forwards Transnuclear, Inc 821130 application for export license for minor nuclear export, Ltr of assurance required
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 82/12/02 GRIFFIN, J A Energy, Dept of 1p 16367 171

--8212080020 Application to amend export license, increasing quantity to 175,991 kg U, containing 1,704 kg U-235
HANNETT, B A Transnuclear, Inc (YNP) 82-174/01 82/11/30 MOORE, N Office of International Programs, Director 1p 16367 172

8212080029 Application for amend to import license to include addl 1,593,607 kg U, containing 46,871 kg U-235, from West Germany
HANNETT, B A Transnuclear, Inc 82-027/02 82/11/24 MOORE, N Office of International Programs, Director 1p 16367 154

8212080035 Application to amend export license, extending expiration date to 840401
HANNETT, B A Transnuclear, Inc NUK-378 82/11/29 MOORE, N Office of International Programs, Director 1p 16367 146

8212080221 Application for license to export 150,527 lbs Zircaloy-2 tube shells to Japan End use statement encl
BUONOCORE, J A Mitsui & Co (USA), Inc (Subs of Mitsui & Co, Ltd) 136280 82/11/18 2pp 16367 136

8212080225 Informs that License XSNM-1992 may be issued No matl changes circumstances since issuance of License XSNM-1929
MOORE, R N Assistant Director for Export/Import & International Safeguards 82/12/02 Assistant Director for Export/Import & International Safeguards 1p 16367 135

8212080232 Amend 2 to Transnuclear, Inc export license, extending expiration date from 830901 to 840301
PETERSON, M R Assistant Director for Export/Import & International Safeguards 82/12/02 1p 16370 201

8212080237 License for Mitsui & Co (USA), Inc to export 3,650 lbs Zircaloy-2 tube shells to Japan
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 136276 82/11/30 1p 16370 200

8212080244 Amend 1 to OA Co export license, changing ref to power level of reactor from 1,000 kw to 3,000 kw & increasing value of items for export to Bangladesh
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 1EL-821 82/11/23 1p 16370 197

8212080529 License for Mitsui & Co (USA), Inc to export 2,910 lbs Zircaloy-2 tube shells to Japan
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 136277 82/11/30 1p 16370 190

8212080534 License for Mitsui & Co (USA), Inc to export 150,920 lbs Zircaloy-2 tube shells to Japan
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 136280 82/11/30 1p 16370 189

8212080538 License for C Itoh & Co (America), Inc to export 600 guide thimble tubes to Japan
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards MOI-144 82/11/30 1p 16370 188

8212100087 Application for Amend 6 to export license increasing quantity to 2 mg Cf-252, adding end use statement & specifying end user
SHAW, A Edlow International Co 82/11/29 HEMBLY, E Assistant Director for Export/Import & International Safeguards 1p 16397 345

8212100119 Amend 1 to Transnuclear, Inc export license, extending expiration date from 830401 to 840401 for exports to Switzerland
PETERSON, M R Assistant Director for Export/Import & International Safeguards 82/12/02 1p 16397 008

8212160791 Application to amend import license, changing transport methods for imports to read "by various transport methods in compliance w/all applicable US regulations"
SHAW, A Edlow International Co 82/12/08 Assistant Director for Export/Import & International Safeguards 1p 16465 353

8212160796 Application to amend export license, changing max element weight to 32,996 kg & max isotope weight to 30,785 kg
YAMANA, K Nissho-Iwai American Corp 82/11/17 MOORE, N NRC -- No Detailed Affiliation Given 1p 16465 352

8212170098 License for Edlow Intl Co to export 12.6 kg U-235, contained in 63 kg U, to Canada
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards AECL-1 (B2) 82/12/07 1p 16480 295

8212170023 License for IRT Corp to export 2.24 mg Cf-252, contained in two sealed sources, to Japan
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 82/12/08 1p 16480 334

8212170029 License for CERAC, Inc to export 1,757 kg thorium, contained in 2 kg thorium oxide, to Japan
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 82/12/09 1p 16480 360

NONDOCKETED ITEMS

8212230402 Forwards Battelle 821130 ltr to Transnuclear, Inc requesting Transnuclear, Inc prepare & process application for import license
HANNETT, B A Transnuclear, Inc 82/12/06 MOORE, N Office of International Programs, Director 2pp 16539 361

8212230406 Forwards application to export 79,000 kg U hexafluoride, enriched to 3.35% U-235 & 0.170 kg U-235, contained in 5 kg U, to The Netherlands Ltr of assurance also encl
HANNETT, B Transnuclear, Inc RBU-425 82/12/06 MOORE, N Office of International Programs, Director 1p 16539 357

--8212230410 Application for license to export 79,000 kg U hexafluoride, enriched to 3.35% U-235 & 0.170 kg U-235, contained in 5 kg U, to The Netherlands
HANNETT, B Transnuclear, Inc (RBU-425) 82/12/06 3pp 16539 358

8212230414 Amend 1 to Sigma Chemical Co export license, extending expiration date to 850401
PETERSON, M R Assistant Director for Export/Import & International Safeguards D-72 82/12/06 1p 16544 110

8212230418 Amend 1 to Sigma Chemical Co export license, extending expiration date to 850701
PETERSON, M R Assistant Director for Export/Import & International Safeguards D-80 82/12/06 1p 16544 109

8212230423 Amend 1 to Sigma Chemical Co export license, extending expiration date to 850601
PETERSON, M R Assistant Director for Export/Import & International Safeguards D-77 82/12/06 1p 16544 108

8212230426 Notifies that Transnuclear, Inc 821129 license request for Battelle Columbus Lab to import 3 kg U & 0.7 g Pu from Canada will be granted w/o normal 30-day period of notice
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 82/12/09 Assistant Director for Export/Import & International Safeguards 2pp 16544 106

8212230427 Discusses Exxon Nuclear Co, Inc 821021 application to import 23,200 kg U from France Import will not be inimical to common defense & security
MOORE, R N Assistant Director for Export/Import & International Safeguards 82/11/03 Assistant Director for Export/Import & International Safeguards 1p 16544 105

8212230428 Discusses staff findings re Transnuclear, Inc 820920 application to import 21,000 kg U from France Import will not be inimical to common defense & security
MOORE, R N Assistant Director for Export/Import & International Safeguards 82/11/04 Assistant Director for Export/Import & International Safeguards 1p 16544 104

8212230431 Discusses staff findings re Edlow Intl Co 820917 application to import 5 million kg U from various countries Import will not be inimical to common defense & security
MOORE, R N Assistant Director for Export/Import & International Safeguards 82/11/05 Assistant Director for Export/Import & International Safeguards 1p 16544 103

8212230432 Executive Branch position re Saunders-Roe Development, Inc application to export add'l 700,000 Ci to United Kingdom License should be granted
DEVINE, J B State, Dept of, Bureau of Oceans & Internatl Environ & Scientific Affairs 82/12/03 SHEA, J R Office of International Programs, Director 1p 16544 102

8212230433 Amend 1 to Sigma Chemical Co export license, extending expiration date to 850701
PETERSON, M R Assistant Director for Export/Import & International Safeguards D-79 82/12/06 1p 16529 360

8212270072 Addendum to application for license to export 24 2mm Zircaloy-4 alloy fuel channels to Japan
* Carpenter Technology Corp 82/12/13 2pp 16593 157

8212270077 Forwards application for license to export neutron calibr source to Taiwan
HERSCH, M H Westinghouse Electric Corp MMH-217 82/12/08 ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 1p 16553 155

--8212270079 Application for license to export 1 neutron calibr source to Taiwan
HERSCH, M H Westinghouse Electric Corp MMH-217 82/12/07 1p 16553 156

8212270082 Forwards application for license to export 732 kg U-235, enriched to 3.40% U hexafluoride, to Japan
SHIMA, S Mitsubishi International Corp (subs of Mitsubishi Corp) HSA-5482-07 82/12/06 Assistant Director for Export/Import & International Safeguards 3pp 16553 149

--8212270086 Application for license to export 732 kg U-235, enriched to 3.40% U hexafluoride, to Japan
SHIMA, S Mitsubishi International Corp (subs of Mitsubishi Corp) HSA-5482-07 82/12/06 3pp 16553 152

8212270087 Ltr of assurance re Tokyo Electric Power Co, Inc license to export 337 kg U-235, contained in 11,279 kg U
SHIRAKAWA, T Japan 82/12/10 GRIFFIN, J A Energy, Dept of 1p 16551 362

8212270090 Ltr of assurance re Japan Nuclear Fuel Conversion Co, Ltd license to export 56 kg U-235, contained in 7,875 kg depleted U hexafluoride
SHIRAKAWA, T Japan 82/12/10 GRIFFIN, J A Energy, Dept of 1p 16551 361

8212270092 Requests Executive Branch position re Amersham Intl, Ltd application for license to re-export 2.0 mg Cf-252 to South Africa
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 82/12/13 STOLBER, C R State, Dept of, Bureau of Oceans & Internatl Environ & Scientific Affairs 1p 16551 360

8212270094 Forwards application for export license for minor nuclear export Ltr of assurance required W/o encl
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 82/12/13 GRIFFIN, J A Energy, Dept of 1p 16551 359

8212270096 Forwards application for export license for minor nuclear export Ltr of assurance required W/o encl
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 82/12/14 GRIFFIN, J A Energy, Dept of 1p 16551 358

8212270098 Advises that export of 5 lb Zircaloy-4 trex to Canada meets requirements of Atomic Energy Act & would not be inimical to common defense & security
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 82/12/15 Assistant Director for Export/Import & International Safeguards 1p 16551 357

8212270102 Requests extension of license to import small quantity of U-235 in in-core detectors until June 1983
ANGELONE, A Mitsubishi International Corp (subs of Mitsubishi Corp) PIT-L-3249 82/12/07 WRIGHT, B NRC - No Detailed Affiliation Given 1p 16551 356

8212270105 Addendum to application for license to export 90 2 5mm Zircaloy-4 alloy fuel channels to Japan
* Carpenter Technology Corp 82/12/13 2pp 16551 354

8212270328 Add'l response to FOIA request for documents re IAEA safeguards Forwards App A Documents 1, 9 & 10 Remaining documents in Apps A & B completely & partially withheld (ref FOIA Exemptions 1 & 5)
FELTON, J M Division of Rules and Records 82/11/15 GREENBERG, E V Galloway & Greenberg App 16555 329

--8212270333 Advises that info supplied by State Dept does not clarify nature or significance of delay incurred in completing facility attachments for Swedish reactors Info partially withheld (ref FOIA Exemptions 1 & 5)
SHERR, T S Material Transfer Safeguards Licensing Branch 82/02/01 DEVINE, J B Assistant Director for Export/Import & International Safeguards 1p 16555 336

8212280149 Application for license to export two WL22792 BF3 filled proportional counters to Japan
POCHAL, W F Westinghouse Electric Corp Z660257 82/12/01 1p 16578 038

8212280155 License for Exxon Nuclear Co, Inc to import 23,200 kg U, enriched to 3.53% U-235, from France
PETERSON, M R Office of International Programs, Director 82/12/03 1p 16590 358

8212280172 Requests amend to export license increasing usage to 990,000 Ci Orders for tritium lighting devices confirmed
PATISLEY, E J Saunders-Roe Developments, Ltd 82/12/06 HEMBY, E NRC - No Detailed Affiliation Given 1p 16590 359

8212280178 License for BMI to import 3 298 kg U, containing up to 2 686 kg U-235 & 0.7 g Pu, contained in spent MTR fuel assemblies from Canada
ZIMMERMAN, J V Office of International Programs, Director
82/12/09 2pp 16590 344

8212280181 Requests withdrawal of 821112 application for import license for U-235 Matl delivered by normal channels
PEVEY, L E Commerce, Dept of, National Bureau of Standards
82/12/03 Assistant Director for Export/Import & International Safeguards 1p 16590 360

8212300140 Forwards list of export licenses to be consolidated on one license for export of enriched U to Sweden Requests new license be valid until Jan 1990
BHAM, A Edlow International Co 82/11/09 Assistant Director for Export/Import & International Safeguards 2pp 16624 195

8212300143 Forwards Transnuclear, Inc 821207 ltr re new checklist for Risso Research Reactor export license application for review W/o encl
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 82/12/14 STUBER, C R State, Dept of, Bureau of Oceans & Internatl Environ & Scientific Affairs 1p 16624 193

8212300148 Amend 5 to Saunders-Roe Developments, Inc export license, increasing quantity from 1 million Ci to 2 million Ci tritium
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 82/12/13 1p 16624 187

8212300150 License for Teledyne Wah Chang Albany to export 5 lb Zircaloy-4 Trex w/pure zirconium liner to Canada
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 82/12/15 1p 16624 186

8212300153 License for Mitsui & Co (USA), Inc to export 337 kg U-235, contained in 11,279 kg U as U hexafluoride, to Japan
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 82/12/15 1p 16624 184

8212300159 Application for license to export 5 kg deuterium, contained in 20 kg deuterium oxide, to India
EDELSTEIN, B Aldrich Chemical Co, Inc (subs of Sigma-Aldrich Corp) 29/82 82/12/08 1p 16624 183

8212300158 Application for license to export 5 kg deuterium, contained in 20 kg deuterium oxide, to Argentina
EDELSTEIN, B Aldrich Chemical Co, Inc (subs of Sigma-Aldrich Corp) 26/82 82/12/08 1p 16624 182

8212300163 Application for license to export 5 kg deuterium, contained in 20 kg deuterium oxide, to Israel
EDELSTEIN, B Aldrich Chemical Co, Inc (subs of Sigma-Aldrich Corp) 24/82 82/12/08 1p 16624 180

8212300164 Application for license to export 5 kg deuterium, contained in 20 kg deuterium oxide, to Jamaica
EDELSTEIN, B Aldrich Chemical Co, Inc (subs of Sigma-Aldrich Corp) 27/82 82/12/08 1p 16624 179

8212300166 Application for license to export 5 kg deuterium, contained in 20 kg deuterium oxide, to Mexico
EDELSTEIN, B Aldrich Chemical Co, Inc (subs of Sigma-Aldrich Corp) 28/82 82/12/08 1p 16624 178

8212300169 Application for license to export 5 kg deuterium, contained in 20 kg deuterium oxide, to Chile
EDELSTEIN, B Aldrich Chemical Co, Inc (subs of Sigma-Aldrich Corp) 29/82 82/12/08 1p 16613 055

8212300172 Informs that License XSNM-1987 may be issued No matl changed circumstances since issuance of License XSNM-1987
MOORE, R N Assistant Director for Export/Import & International Safeguards 82/12/16 Assistant Director for Export/Import & International Safeguards 1p 16613 054

8212300173 Amend 1 to import license extending expiration date to 830630
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 82/12/14 1p 16613 053

8212300175 Application for license to export four heater fuel rods w/o nuclear matl & one annulus test section & fittings to Taiwan
* General Electric Co SDN-111-82 82/12/10 1p 16613 052

8212300178 Application for license to export 5 lb Zircaloy-4 Trex w/pure zirconium liner to Canada
AERNI, B L Teledyne Wah Chang Albany 82/12/13 1p 16613 051

8212300180 Application for license to export 5 kg deuterium, contained in 20 kg deuterium oxide, to India
EDELSTEIN, B Aldrich Chemical Co, Inc (subs of Sigma-Aldrich Corp) 31/82 82/12/08 1p 16613 050

8212300181 Application for license to export 5 kg deuterium, contained in 20 kg deuterium oxide, to Chile
EDELSTEIN, B Aldrich Chemical Co, Inc (subs of Sigma-Aldrich Corp) 30/82 82/12/08 1p 16613 049

PERSONAL AUTHOR INDEX

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents.

An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principal Documents."

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
AAMOUT, H. M.	8212010195	50-289 Q	AMBROSINO, R. A.	8212280154*	50-416 S	AXELRAD, J.	8212170345	50-259 Q
AAMOUT, M. M.	8212020346	50-289 Q	AMBROSINO, R. A.	8212280245*	50-416 S	AXELRAD, J.	8212300327	50-331 S
AAMOUT, M. M.	8212020401*	50-289 Q	AMBROSINO, R. A.	8212280412*	50-416 S	AXELRAD, J. A.	8212270388	50-271 Q
AARON, J. R.	8212020244*	50-296 S	AMBROSINO, R. A.	8212280475*	50-416 S	AXELRAD, J. A.	8212270390	50-269 Q
ABRATT, E. C.	8212230363	50-397 A	AMSTEN, R. L.	8212220558*	COMMISSION	AXELSON, W. L.	8212060017*	50-315 Q
ABRATT, E. C.	8212270466*	50-327 D	AMSTUTZ, S. R.	8212300341*	50-155 R	AXELSON, W. L.	8212060238*	50-295 Q
ABEL, S. L.	8212030013*	50-285 S	ANANDAPPA, A.	8212080381*	50-249 S	AXELSON, W. L.	8212060252*	50-409 Q
ABELSON, H.	8212060393	50-352 A	ANDERSON, C. R.	8212280391*	50-244 P	AXELSON, W. L.	8212150019*	50-409 Q
ABELSON, H.	8212060398	50-352 A	ANDERSON, F.	8212220249	NUREG	AXELSON, W. L.	8212210124*	50-237 Q
ABELSON, H.	8212060510	50-352 A	ANDERSON, J. O. M.	8212160762	NUREG	AXELSON, W. L.	8212210340*	50-282 Q
ABELSON, H.	8212070493	50-352 A	ANDERSON, N. R.	8212270181	NUREG	AXLINE, J. W.	8212210342*	50-263 P
ABELSON, H.	8212080018	50-352 A	ANDERSON, P.	8212270316	50-266 Q	AYRE, J. J.	8212270479	71-6144
ABRAHAM, K.	8212010058*	FOIA	ANDERSON, P.	8212270323	50-266 Q	BACHMANN, R. G.	8212030223	50-170 Q
ABRAHAM, K.	8212010137*	FOIA	ANDERSON, S. L.	8212140420*	50-244 P	BACKUS, R. A.	8212140426	50-443 Q
ABRAHAM, P. B.	8212010151	TOPREP	ANDONINI, G. C.	8212130146	70-2949	BACKUS, R. A.	8212140426	50-443 Q
ACKERMAN, W. C.	8212070456	40-8584	ANDRUS, N. J.	8212070407	40-4492	BACKUS, R. A.	8212230334	50-443 Q
ACKERMAN, W. C.	8212230170	40-4492	ANGLOHE, A.	8212270102	XPORTLIC	BACKUS, R. A.	8212230334	50-443 Q
ADAMS, R. E.	8212130135	NUREG	ANTHONY, R. L.	8212230352	50-352 Q	BAER, M. R.	8212270156	NUREG
ADDABBO, J.	8212230276	50-247 U	ANTHONY, R. L.	8212230352	50-352 Q	BAER, R.	8212210250*	50-313 Q
ADENAM, E. Q.	8212010122*	50-390 A	ANTHONY, R. L.	8212230356	50-352 Q	BAER, R. L.	8212290485	50-461 Q
ADENSAM, E. Q.	8212010286	50-369 P	APPEL, R. R.	8212230356	50-352 Q	BAGBY, L. A.	8212150230	71-9167
ADENSAM, E. Q.	8212010506	50-329 F	ARAND, J.	8212080042	40-8781	BAGCHI, G.	8205260070*	50-244 P
ADENSAM, E. Q.	8212070072	50-390 A	ARIAS, J.	8212080317*	50-373 S	BAILEY, R. J.	8212030338*	50-244 Q
ADENSAM, E. Q.	8212100409	50-329 E	ARBJB, H. A.	8212270420	NUREG	BAILEY, R. J.	8212030147*	50-247 Q
ADENSAM, E. Q.	8212130362	50-413 Q	ARCHITZEL, R. E.	8212060305	50-317 S	BAILEY, R. J.	8212060212*	HISC
ADENSAM, E. Q.	8212220093	50-413 D	ARCHITZEL, R. E.	8212100013*	50-317 Q	BAIN, O. M.	8212270042*	50-289 P
ADENSAM, E. Q.	8212270426*	50-437 A	ARIAS, J.	8212280167*	50-250 S	BAIR, O. O.	8212030017*	50-344 S
ADERHOLD, H. C.	8212140146	50-97 R	ARIAS, J.	8212280175*	50-250 S	BAIR, O. O.	8212140355*	50-344 S
ADERHOLD, H. C.	8212140232	50-97 R	ARNOLD, R.	8212060019*	50-320 P	BAISDEN, L.	8212100167	CONTRACT
ADERHOLD, H. C.	8212140238*	50-97 R	ARNOLD, R.	8212060019*	50-320 P	BAKER, C. E.	8212070509	40-8681
ADERHOLD, H. C.	8212140469	50-97 R	ARNOLD, R.	8212060019*	50-320 P	BAKER, C. E.	8212290012	40-8681
ADLER, R. U.	8212010186	50-289 Q	ARNOLD, R. C.	8212060015	50-320 P	BALLINGER, P.	8212300111*	50-298 S
ADLER, R. U.	8212090502	50-289 Q	ARNOLD, R. C.	8212060005	50-320 P	BALLINGER, P. L.	8212290315*	50-298 R
ADLER, R. U.	8212160271	50-289 Q	ARNOLD, R. C.	8212170119	50-289 P	BANDER, T. J.	8212270487	NUREG
AERNT, B. L.	8212300178	XPORTLIC	ARONAUT, F. J.	8212080013*	FOIA	BANDY, R.	8212280035	REG
AGRAWAL, R.	8209230377*	50-155 P	ABINON, A. H.	8212170402*	CONTRACT	BANKS, W. H.	8212130108	NUREG
AGEE, J. R.	8212300218*	QA999	ATA, H.	8212290333*	50-249 S	BANON, H.	8212030025*	50-155 Q
AGLES, J.	8212090313*	50-280 Q	AVLUCK, R.	8212030260	50-397 A	BARAN, R.	8212290134*	50-219 R
AGRAWAL, A. K.	8212270056*	50-289 P	AVLUCK, R.	8212290505	50-397 F	BARBER, G.	8212010158	50-219 S
AHARNE, J.	8204130511*	FOIA	AUSTIN, Q.	8212140061*	50-295 R	BARBER, G.	8212300327	50-331 S
AHN, I. M.	8212020010	REG	AUTHOR, L.	8212140070*	50-286 R	BARLETT, D. L.	8208290112	70-143
ALBANESE, S.	8212230241	50-247 Q	AUTHOR, L.	8212290160*	50-286 R	BARNES, C.	8212270379	50-148 H
ALBERT, J.	8212020065*	50-416 S	AUTIO, H. A.	8212140184	50-29 S	BARNES, C.	8212280524	50-148 P
ALBERT, J. H.	8212210182*	50-416 S	AUTIO, H. A.	8212150155	50-29 S	BARNES, I.	8212070036*	QA999
ALBERT, J. H.	8212280336*	50-416 S	AUTIO, H. A.	8212210278	50-29 S	BARNES, I.	8212070122*	QA999
ALBERT, W. O.	8212060274*	50-508 Q	AUTIO, H. A.	8212290251	50-29 S	BARNES, I.	8212070169*	QA999
ALBERT, W. O.	8212210195*	50-508 Q	AUTIO, H. A.	8212290310	50-29 S	BARNES, I.	8212070434*	QA999
ALBERT, W. O.	8212280301*	50-508 Q	AVANTI, D.	8212080200*	50-187 R	BARNES, I.	8212210103*	QA999
ALBRICHT, R. H.	8212090204*	50-369 Q	AVERY, R.	8212070077	50-247 Q	BARNES, I.	8212210141*	QA999
ALDEN, N. H.	8212160058*	50-277 R	AVERY, R.	8212070083*	50-247 Q	BARNES, I.	8212210366*	QA999
ALEXICH, M. P.	8212100293	50-315 J	AXELRAD, J.	8212010158	50-219 S	BARNES, I.	8212270213*	QA999
ALGER, D. H.	8212080331	50-186 P	AXELRAD, J.	8212060329	50-382 S	BARNES, I.	8212300032*	QA999
ALGERMISSEN, B.	8212280438*	50-409 P	AXELRAD, J.	8212140519	I&E	BARNES, I.	8212300263*	QA999
ALLEN, D. T.	8212090319*	State Prog	AXELRAD, J.	8212170090	I&E	BARNES, I.	8212300280*	QA999
ALTER, S.	8212230241	50-247 Q	AXELRAD, J.	8212170170	50-247 Q	BARNETT, J. E.	8212270173	70-1621

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
BARNETT, J E	8212280254	70-1621	BAYNARD, P Y	8212060225	50-302	BINGHAM, J	8212230276	50-247 U
BARNUM, E C	8212010072	XPORTLIC	BAYNARD, P Y	8212150046	50-302 S	BIRKEL, R A	8212150170	50-357 P
BARR, K	8212070111*	50-320 Q	BAYNARD, P Y	8212150060	50-302 S	BISBEE, Q D	8212160281	50-447 Q
BARR, K P	8212220471*	50-289 Q	BAYNE, J P	8212220314	50-302 S	BISBEE, Q D	8212230346	50-443 Q
BARR, K P	8212090439*	70-27	BAYNE, J P	8212090205	50-247 P	BISBEE, Q D	8212230340	50-443 Q
BARR, K P	8212090204*	50-369 Q	BAYNE, J P	8212100214	50-286 P	BISHOP, L L	8212200049*	50-443 Q
BARR, K P	8212090332*	50-414 Q	BAYNE, J P	8212100288	50-286 P	BISHOP, L L	8212200049*	50-443 Q
BARR, K P	8212090500*	50-250 Q	BAYNE, J P	8212130232	50-247 P	BISHOP, L L	8212280191	50-350 Q
BARR, K P	8212090505*	50-338 Q	BAYNE, J P	8212130330	50-286 P	BISHOP, L L	8212280191	50-350 Q
BARR, K P	8212090517*	70-143	BAYNE, J P	8212140294	50-333 F	BISHOP, L L	8212280506	FOIA
BARRETT, D J	8209230377*	50-155 P	BAYNE, J P	8212210426	50-286 P	RISHOP, T W	8212060154	50-361 Q
BARRETT, L	8212270233	50-320 S	BAYNE, J P	8212220234	50-286 F	RISHOP, T W	8212060166	50-362 Q
BARRETT, L H	8212010366	50-320 P	BAYNE, J P	8212220452	50-333 F	RISHOP, T W	8212060251	50-275 Q
BARRETT, L H	8212020403	50-320 P	BAYNE, J P	8212270259	50-286 P	RISHOP, T W	8212060353	50-275 Q
BARRETT, L H	8212020407	50-320 P	BAYNE, J P	8212290175	50-333 P	RISHOP, T W	8212130169	50-275 Q
BARRETT, L H	8212020408	50-320 P	BAZIN, J	8212270470	CONTRACT	RISHOP, T W	8212130263	50-362 Q
BARRETT, L H	8212090004	50-320 P	BEACH, Q	8212060456	40-6054	RISHOP, T W	8212130329	50-206 Q
BARRETT, L H	8212100170	50-320 R	BEAHM, E C	8212220060	RES	RISHOP, T W	8212170281	50-361 S
BARRETT, L H	8212100176	50-320 R	BEARD, J T	8212100159	REVIEW GRP	RISHOP, T W	8212170369	50-206 Q
BARRETT, L H	8212130154	50-320 R	BECHHOEFER, C	8212070164	50-329 Q	RISHOP, T W	8212170391	50-361 Q
BARRETT, L H	8212230056	50-320 P	BECK, M	8212230121	40-8771	RISHOP, T W	8212210197	50-361 Q
BARRETT, L H	8212270019	50-320 R	BECKHAM, J T	8212150009	50-321 F	BLACKMAN, H S	8212210108	NUREQ
BARRETT, L H	8212280519	50-320 R	BECKHAM, J T	8212170246	50-321 P	BLACKSHAW, O L	8212030110	50-127 P
BARRETT, L H	8212290040	50-320 P	BECKNER, W D	8201120155*	RES	BLAH, O	8212080251	50-266 Q
BARRETT, L H	8212300101	50-320 R	BEILMAN, J P	8212290358*	50-316 S	BLAKE, E L	8212070134	50-209 Q
BARRETT, P	8212210247	50-263 S	DELANDER, J L	8212090396*	50-155 Q	BLAKE, E L	8212070134	50-209 Q
BARTH, C A	8212090222	50-358 Q	DELL, J T	8212270441	NUREQ	BLAKE, J J	8212090186*	50-400 Q
BARTH, C A	8212160241	50-358 Q	DELL, M J	8212010252	WASTE HOT	BLAKE, J J	8212090324*	50-411 Q
BARTH, C A	8212170073	50-400 Q	DELL, M J	8212010505	WASTE HOT	BLAKE, J J	8212090336*	50-369 Q
BARTH, D E	8212230330	50-329 Q	DELL, M J	8212020132	WASTE HOT	BLAKE, J J	8212090336*	50-410 Q
BARTH, K P	8212140455	50-440 Q	DELL, M J	8212020199	WASTE HOT	BLAKE, J J	8212280453	50-260 S
BARTON, C	8212060433	FOIA	DELL, M J	8212230066	WASTE HOT	BLAKE, J J	8212290138*	FOIA
BASHAM, P W	8212220249	NUREQ	BELL, N	8212140418	50-397 Q	BLAKE, R A	8212010150*	50-272 P
BASKIN, K P	8110190932*	50-206 P	BELL, N	8212160267	50-522 Q	BLANCH, P	8212100217	HTIC
BASKIN, K P	8212020253	50-206 P	DELMORE, C J	8212210044*	50-219 R	BLANCH, P	8212160424*	40-6500
BASKIN, K P	8212020373	50-361 P	BEMIS, P	8212030004	50-261 S	BLAYLOCK, J	8212080113*	70-143
BASKIN, K P	8212060239	50-206 P	BENDER, M	8212270471*	FOIA	BLAYLOCK, J	8212080117*	70-143
BASKIN, K P	8212060269	50-206 P	BENNETT, D E	8212220162	NUREQ	BLAYLOCK, J	8212080154*	70-147
BASKIN, K P	8212070190	50-361 P	BENTING, K W	8212210330*	50-263 P	BLOCH, P B	8212080315	50-155 Q
BASKIN, K P	8212070266	50-206 P	BENTING, K W	8212210337*	50-263 P	BLOCH, P B	8212100108	50-440 Q
BASKIN, K P	8212090103	50-206 P	BENTLEY, N R	8212280297*	50-239 P	BLOCH, P B	8212130191	50-266 Q
BASKIN, K P	8212090176	50-361 P	BERATAN, L L	8212290109*	FOIA	BLOCH, P B	8212130249	50-440 Q
BASKIN, K P	8212090376	50-361 P	BERATAN, L L	8212290138*	FOIA	BLOCH, P B	8212150041	50-140 Q
BASKIN, K P	8212090514	50-361 P	BERG, P	8212280511	FOIA	BLOCH, P B	8212160509	50-159 Q
BASKIN, K P	8212130039	50-362 J	BERGOLD, W E	8212060113	50-537 Q	BLOCH, P B	8212230351	50-440 Q
BASKIN, K P	8212140151	50-206 F	BERGOLD, W E	8212090082	50-537 Q	BLOCH, P B	8212300015	50-155 Q
BASKIN, K P	8212170164	50-206 F	BERLIN, K	8212010202	50-528 Q	BLOCH, P B	8212300018	50-440 Q
BASKIN, K P	8212170208	50-361 F	BERMAN, H E	8212230241	50-247 Q	BLODGETT, T H	8212170243	50-389 R
BASKIN, K P	8212200028	50-206 P	BERNABEI, L	8212020382	50-358 Q	BLODGETT, T H	8212280187	50-389 R
BASKIN, K P	8212210001	50-206 P	BERNABEI, L	8212280128	50-358 Q	BLODGETT, T H	8212280333	50-339 A
BASKIN, K P	8212220198	50-206 P	BERNABEI, L	8212280128	50-358 Q	BLODGETT, T H	8212280405	50-389 A
BASKIN, K P	8212230260	50-361 P	BERNARD, H	8212080598	50-97 P	BLODGETT, T H	8212140476	NUREQ
BASKIN, K P	8212230291	50-361 P	BERNATH, S L	8212200046	PR	BLODGETT, T H	8212140388*	50-537 A
BASKIN, K P	8212230325	50-361 P	BERRY, H E	8212170171*	50-305 S	BLODGETT, T H	8212290137	40-8452
BASKIN, K P	8212230349	50-361 P	BERRY, H E	8212270056*	50-289 P	BLOUGH, A R	8212160491*	50-277 Q
BASSO, L F	8212060306*	50-317 S	BERRY, Z E	8212090371*	50-230 S	BLUBAUGH, R E	8212030281	40-3453
BASSO, L F	8212210048*	50-317 S	BERRY, Z E	8212010220	50-250 S	BLUBAUGH, R E	8212290123	40-3453
BASSO, L F	8212290282*	50-317 S	BERRY, Z E	8212210207*	50-250 S	BLUM, J M	8212060077	50-247 Q
BATES, A	8212270453*	FOIA	BERTOSSA, D C	8212170101*	50-277 P	BLUM, J M	8212060077	50-247 Q
BATES, A	8212270461*	FOIA	BETTENHAUSEN, L	8212030051*	50-336 Q	BLUM, J M	8212060089*	50-247 Q
BATES, J W	8212090278*	70-1151	BETTENHAUSEN, L	8212030200*	50-293 Q	BLUM, J M	8212060098	50-247 Q
BATES, J W	8212090416*	70-143	BETTENHAUSEN, L	8212030207*	50-289 Q	BLUM, J M	8212060098	50-247 Q
BATT, D L	8212270145	NUREQ	BETTENHAUSEN, L	8212030221*	50-289 Q	BLUM, J M	8212060098	50-247 Q
BATTY, D L	8212270047*	50-289 P	BETTENHAUSEN, L	8212060190*	50-423 Q	BLUM, J M	8212090101	50-247 Q
BAUER, E O	8212060106*	50-277 P	BETTENHAUSEN, L	8212060237*	50-247 Q	BLUM, J M	8212140384	50-247 Q
BAUER, E O	8212100079*	50-278 P	BETTENHAUSEN, L	8212060258*	50-322 Q	BLUM, J M	8212140393*	50-247 Q
BAUER, E O	8212150062*	50-277 P	BETTENHAUSEN, L	8212070148*	50-309 Q	BLUM, J M	8212140400*	50-247 Q
BAUNACK, W H	8212030078*	50-333 Q	BETTENHAUSEN, L	8212080357*	50-249 S	BLUM, J M	8212200032	50-247 Q
BAKTER, T A	8212100099	50-400 Q	BEVERLY, K	8212100319*	50-237 S	BLUM, J M	8212210238	50-247 Q
BAKTER, T A	8212100099	50-400 Q	BEVER, B D	8212160107*	50-346 F	DODDE, D L	8212080044*	FOIA
BAKTER, T A	8212200026	50-312 Q	BIALIK, E I	8212230261	50-247 Q	DODDE, D L	8212080070*	FOIA
BAKTER, T A	8212270222	50-400 Q	BIBB, H E	8212090537*	50-335 Q	DODDE, D L	8212080081*	FOIA
BAKTER, T A	8212270222	50-400 Q	BIBB, H E	8212090542*	50-335 Q	DODINE, J C	8212060175*	50-244 S
BAKTER, T A	8212300226	50-483 Q	BIBB, H E	8212090564*	50-335 Q	BOGART, D	8212140051*	50-302 R
BAKTER, T A	8212300226	50-483 Q	BIDINGER, O H	8212020209	70-1151	BOGDEN, Q	8212020154	PR
BAKTER, T A	8212300226	50-483 Q	BIDINGER, O H	8212170011*	70-2928	BOGDEN, Q	8212130105	40-1162
BAKTER, T A	8212010053*	50-389 M	BIDINGER, O H	8212090078	70-36	BOGDEN, Q	8212080684*	50-322 H
BAKTER, T A	8212010290*	50-389 M	BIDINGER, O H	8212080235	50-454 Q	BOLLWERK, P	8212210327*	50-263 P
BAKTER, T A	8212010486	RES	BIDINGER, O H	8212080245*	50-434 Q	BONDRE, J R	8212060156	50-206 Q
BAKTER, T A	8212220519	RES	BIDINGER, O H	8212170128*	50-498 A	BOOK, H E	8212060168*	50-206 Q
BAKTER, T A	8212220519	RES	BIDINGER, O H	8212220354*	50-387 P	BOOK, H E	8212130298*	50-187 Q
BAKTER, T A	8212220519	RES	BIDINGER, O H	8212130227*	50-29 P	BOOK, H E	8212210185*	50-344 Q
BAKTER, T A	8212220519	RES	BIDINGER, O H	8212200051	50-440 H	BOOK, H E	8212300213*	70-734
BAKTER, T A	8212220519	RES	BIDINGER, O H	8212070435	50-250 Q	BOOK, H E	8212300240*	70-25
BAKTER, T A	8212220519	RES	BIDINGER, O H	8212170312*	50-295 S	BOOKER, J E	8212100033	50-458 S

PERSONAL AUTHOR INDEX

426

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
BOOKER, J E	8212100239*	50-458 Q	BOOKMAKER, N J	8212080197	50-317 P	BROTTON, G C	8212270018	71-490
BOOKER, J E	8212210136	50-458 S	BOOKMAKER, N J	8212280208*	50-317 Q	BROTTON, G C	8212270027*	71-490
BOOKER, J E	8212210176	50-458 S	BOYD, D C	8212080129*	50-255 Q	BROWN, C	8212270276	50-263 S
BOOKER, J E	8212220274	50-458 A	BOYD, D C	8212080522*	50-155 Q	BROWN, C G	8212020052*	50-302 S
BOOKER, J E	8212270183	50-458 S	BOYD, D C	8212280251*	50-315 Q	BROWN, C G	8212020087*	50-302 S
BOOKER, J E	8212270236	50-458 S	BOYD, D C	8212290335*	50-315 Q	BROWN, C G	8212160108*	50-302 S
BOOKER, J E	8212280196	50-458 S	BOYD, R	8212070111*	50-320 Q	BROWN, C G	8212220322*	50-302 S
BOOKER, J E	8212280252	50-458 S	BOYD, R	8212140319*	50-320 Q	BROWN, H H	8212220394	50-275 Q
BORCHERT, M L	8212170131*	50-498 A	BOYER, V S	8210040253*	50-352 A	BROWN, H H	8212220394	50-275 Q
BORCHERT, R	8212080415*	50-336 S	BOYER, V S	8212030132*	50-352 A	BROWN, J F	8212130182*	CONTRACT
BORCHERT, R	8212210233*	50-336 S	BOYER, V S	8212210495*	50-352 A	BROWN, J	8212160148*	71-454
BORBENICK, B M	8212210009	50-277 Q	BOYER, V S	8212270141	50-352 A	BROWN, R G	8212060471	50-295 P
BORBENICK, B M	8212220128	50-322 Q	BRACHMAN, J Y	8212210435	50-440 D	BROWN, R L	8212220086*	50-458 Q
BORBENICK, B M	8212220135	50-322 Q	BRADBURY, R B	8212020242	PR	BROWN, R T	8212010150*	50-272 P
BORDINE, T C	8212030019	50-155 Q	BRADBURY, R B	8212200045	PR	BROWN, R T	8212010474	RES
BORDINE, T C	8212100304	50-155 S	BRADFORD, W H	8212090519*	50-348 Q	BROWNING, R E	8212010232	WASTE MOT
BORDINE, T C	8212280131	50-155 Q	BRADLEY, E J	8210040239	50-352 K	BROWNING, R E	8212270430	WASTE MOT
BORES, R	8212220276	50-309 S	BRADLEY, E J	8212030122	50-352 A	BROWNLEE, V	8212280060	50-302 S
BORF-S, R J	8212030037*	50-219 Q	BRADLEY, E J	8212060096	50-277 P	BROWNLEE, V L	8212090245*	50-424 Q
BORGANN, E A	8212010089	50-358 A	BRADLEY, E J	8212060106*	50-277 P	BROWNLEE, V L	8212090545*	50-395 Q
BORGANN, E A	8212020225	50-358 S	BRADLEY, E J	8212070025	50-352 A	BRUNNER, J E	8212010035	50-329 A
BORGANN, E A	8212020257	50-358 S	BRADLEY, E J	8212070138	50-352 F	BRUNNER, J E	8212210314	50-329 Q
BORGANN, E A	8212020320	50-358 S	BRADLEY, E J	8212080446	50-352 A	BRYANT, J C	8212090189*	50-269 Q
BORGANN, E A	8212020367	50-358 S	BRADLEY, E J	8212100075	50-278 P	BRYANT, J C	8212090261*	50-413 Q
BORGANN, E A	8212030111	50-358 S	BRADLEY, E J	8212100079*	50-278 P	BRYANT, J C	8212090380*	50-369 Q
BORGANN, E A	8212060030*	50-358 Q	BRADLEY, E J	8212100274	50-352 C	BRYANT, J C	8212150086	50-413 S
BORGANN, E A	8212060039*	50-358 Q	BRADLEY, E J	8212130341	50-352 K	BUCKHAM, J A	8212090405	50-332 Q
BORGANN, E A	8212080472	50-358 F	BRADLEY, E J	8212150058	50-277 P	BUCKLES, J	8212280205	50-358 J
BORGANN, E A	8212090028*	50-358 F	BRADLEY, E J	8212150062*	50-277 P	BUCKLES, J	8212290213	50-315 J
BORGANN, E A	8212090094	50-358 K	BRADLEY, E J	8212170265	50-277 P	BUCKLEZ, R J	8005071094	50-320 P
BORGANN, E A	8212140340*	50-358 A	BRADLEY, E J	8212210358	50-352 F	BUENITZ, R J	8005270762	RES
BORGANN, E A	8212140342*	50-358 A	BRADLEY, E J	8212210402	50-352 A	BUENITZ, R J	8005270829	RES
BORGANN, E A	8212170080	50-358 K	BRADLEY, E J	8212210491	50-352 K	BUENITZ, R J	8006020271	RES
BORGANN, E A	8212170107	50-358 R	BRADLEY, E J	8212270144	50-352 F	BUNTING, J O	8212010217	WASTE MOT
BORGANN, E A	8212170191	50-358 R	BRADLEY, E J	8212280209	50-352 A	BUNTING, J O	8212010220	WASTE MOT
BORGANN, E A	8212170260	50-358 S	BRADLEY, E J	8212290276	50-352 R	BUNTING, J O	8212020146	WASTE MOT
BORGANN, E A	8212210031*	50-358 Q	BRADLEY, R	8212270431*	50-3 H	BUNTING, J O	8212230126	WASTE MOT
BORGANN, E A	8212210545*	50-358 F	BRADY, N	8212060511*	40-86	BUNTING, J O	8212230138	WASTE MOT
BORGANN, E A	8212270190	50-358 S	BRAINARD, M F	8212100162*	CONTRACT	BUNTING, J O	8212230153	WASTE MOT
BORGANN, E A	8212280171*	50-358 Q	BRAMLETT, L S	8212290236*	50-368 R	BUNTING, J O	8212230231	WASTE MOT
BORGANN, E A	8212290277	50-358 S	BRANDENBURG, B	8212020318	50-247 Q	BUNTING, J O	8212270455	WASTE MOT
BORGANN, E A	8212290285	50-358 S	BRANDENBURG, B	8212060103	50-247 Q	BUONOCORE, J A	8212080221	XPORTLIC
BORGANN, E A	8212290342	50-358 S	BRANDENBURG, B	8212090087	50-247 Q	BURDETTE, J	8212020338*	50-443 A
BORGANN, E A	8212290343*	50-358 Q	BRANDENBURG, B	8212090090	50-247 Q	BURDOIN, J F	8212130171*	50-275 Q
BORGANN, E A	8212290364	50-358 S	BRANDENBURG, B	8212140423	50-247 Q	BURGER, F J	8212150176*	50-271 R
BORGANN, E A	8212290397	50-358 S	BRANDENBURG, B	8212140439	50-247 Q	BURGIN, R E	8212220262	40-8135
BORGANN, E A	8212290425*	50-358 A	BRANDENBURG, B	8212140446*	50-247 Q	BURIAN, R J	8212150212	71-5957
BORGANN, E A	8212290429*	50-358 Q	BRANDENBURG, B	8212160289	50-247 Q	BURIAN, R J	8212210529	71-5957
BORGANN, E A	8212290438	50-358 S	BRANDENBURG, B	8212220271	50-247 Q	BURKE, D J	8212090234*	50-280 Q
BORGANN, E A	8212290454*	50-358 Q	BRANDENBURG, B	8212230187	50-247 Q	BURKE, D J	8212090313*	50-280 Q
BORGANN, E A	8212290467	50-358 S	BRANDENBURG, B	8212280293	50-247 Q	BURSTEIN, S.	8212070099	50-266 F
BORGANN, E A	8212290483	50-358 S	BRANDENBURG, B	82122300230	50-247 Q	BURWELL, S B	8212080106	50-445 A
BORKOWSKI, R J	8212270435	NUREO	BRANNIN, J P	8212090410*	50-335 S	BUSS, R	8212080404*	50-265 S
BORST, F J	8212200043	50-267 F	BRANNIN, J P	8212200085*	50-335 S	BUSS, R	8212130202*	50-254 R
BORST, F J	8212200050	50-267 F	BRANNIN, J P	8212200065*	50-335 S	BUSS, R	8212280543	NUREO
BOSNAK, R J	7912190426*	50-206 P	BRATAD, O W	8212170379*	50-397 A	BUTLER, S B	8212090384*	50-327 Q
BOSNAK, R J	8207280369*	FOIA	BRAUN, O J	8212290199*	50-237 P	BYRD, R	8212020037*	50-416 S
BOUCHEY, O D	8210270013	50-397 A	BRENNER, L	8212070220	50-322 Q	BYRD, R	8212020144*	50-416 S
BOUCHEY, O D	8212030107	50-397 Q	BREWER, B T	8212070378*	COMMISSION	BYRD, R	8212280392*	50-416 S
BOUCHEY, O D	8212070131	50-508 F	BRIDEN, D H	8212160107*	50-346 F	BYRD, R	8212280463*	50-416 S
BOUCHEY, O D	8212100256	50-397 F	BRIGHT, L	8212140084*	50-213 Q	BYRD, R	8212300119*	50-416 S
BOUCHEY, O D	8212130033	50-508 K	BRIGHT, O Q	8212090093	50-483 Q	BYRD, R	8212300200*	50-416 S
BOUCHEY, O D	8212140194	50-508 C	BRIGHT, O Q	8212150026	50-483 Q	BYRON, P M	8212100203*	50-341 Q
BOUCHEY, O D	8212150021	50-508 A	BRIGHT, O Q	8212300018	50-440 Q	BYRON, P M	8212100263*	50-346 Q
BOUCHEY, O D	8212150029	50-508 A	BRIGHTSEN, R A	8212080076*	FOIA	CAGNETTA, J P	8212020299	50-213 F
BOUCHEY, O D	8212170138	50-397 E	BRINKMAN, D	8212140482	50-362 F	CAGNETTA, J P	8212020380	ORR
BOUCHEY, O D	8212170173	50-397 A	BRINKMAN, D B	8212080603	TOPREP	CAGNETTA, J P	8212070289	50-213 P
BOUCHEY, O D	8212170175	50-397 A	BROBST, O E	8212080448*	50-317 S	CAGNETTA, J P	8212080541	50-423 S
BOUCHEY, O D	8212170314	50-397 H	BROCCARD, D N	8212270520	NUREO	CAGNETTA, J P	8212080541	50-423 S
BOUCHEY, O D	8212170374	50-397 A	BROCK, B L	8212210246*	70-25	CAGNETTA, J P	8212100277	50-245 P
BOUCHEY, O D	8212200003	PR	BROCK, B L	8212300213*	70-734	CAGNETTA, J P	8212100277	50-245 P
BOUCHEY, O D	8212200036	PR	BROCKETT, T	8212170090	1&E	CAGNETTA, J P	8212170279	50-245 P
BOUCHEY, O D	8212200047	50-397 A	BROCKETT, T	8212170345	50-259 Q	CAGNETTA, J P	8212170279	50-245 P
BOUCHEY, O D	8212200073	PR	BROCKETT, T W	8212160182*	40-6500	CAGNETTA, J P	8212210355	50-423 F
BOUCHEY, O D	8212200074	50-397 A	BROCKETT, T W	8212160362*	40-6500	CAGNETTA, J P	8212210355	50-423 F
BOUCHEY, O D	8212200083	50-397 E	BROCKETT, T W	8212160370*	40-6500	CAGNETTA, J P	8212230257	50-213 P
BOUCHEY, O D	8212230208	50-508 A	BRODSKY, R L	8212230239	50-247 Q	CAHALAN, J E	8212270250*	50-537 A
BOUCHEY, O D	8212270159	50-397 A	BROEHL, D J	8212140280	50-344 F	CALDWELL, R A	8212150049*	50-112 Q
BOUCHEY, O D	8212280440	50-460 A	BROWN, J C	8212130355*	50-286 F	CALK, J C	8212270506*	CONTRACT
BOUCHEY, O D	8212290180	50-397 K	BROWN, J C	8212130357*	50-286 F	CALLAN, L J	8212210208	50-368 S
BOUCHEY, O D	8212290241	50-397 A	BROWN, J C	8212140064	50-286 R	CALLAN, L J	8212280345	50-313 S
BOURNTA, A	8212060381	50-373 P	BROWN, J C	8212210322	50-286 R	CALLAN, L J	8212290210	50-313 S
BOURNTA, A	8212130151	50-373 P	BROWN, J C	8212290156	50-286 R	CALLAN, L J	8212300182	50-368 S
BOURNIA, A	8212300203*	50-416 P	BROOKS, B O	8212270459	NUREO	CAMP, L F	8212280173*	TOPREP
BOUJE, T B	8212160004	70-1100	BROOKS, E H	8212090277*	50-280 Q	CAMPBELL, R H	8212020060	WASTE MOT

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
CAMPBELL, R. H.	8212170405	40-4900	CARTWRIGHT, W. R.	8212300220*	50-338 S	CHILK, S. J.	8212070174	50-329 C
CANTER, H. L.	8212060171*	50-312 Q	CARTWRIGHT, W. R.	8212300232	50-338 S	CHILK, S. J.	8212070183	50-289 C
CANTRELL, F.	8212090519*	50-348 Q	CARTWRIGHT, W. R.	8212300237	50-339 S	CHILK, S. J.	8212070457*	50-298 F
CANTRELL, F. S.	8212090479*	50-259 Q	CARTWRIGHT, W. R.	8212300238*	50-338 S	CHILK, S. J.	8212070494*	50-298 T
CANTRELL, P. F.	8212140327*	50-275 S	CARTWRIGHT, W. R.	8212300241*	50-339 S	CHILK, S. J.	8212070500*	50-298 P
CARDONE, A. T.	8007180114*	50-206 P	CARTWRIGHT, W. R.	8212300245	50-338 S	CHILK, S. J.	8212090052*	FOIA
CARDONE, A. T.	8007230260*	50-206 P	CARTWRIGHT, W. R.	8212300247*	50-338 S	CHILK, S. J.	8212090065*	FOIA
CAREY, J. J.	8212020078	50-334 P	CARTWRIGHT, W. R.	8212300251	50-339 S	CHILK, S. J.	8212090097	50-275 C
CAREY, J. J.	8212020084*	50-334 P	CARTWRIGHT, W. R.	8212300255*	50-339 S	CHILK, S. J.	8212090209*	FOIA
CAREY, J. J.	8212030142	50-334 P	CARTWRIGHT, W. R.	8212300261	50-338 S	CHILK, S. J.	8212090210*	FOIA
CAREY, J. J.	8212030148	50-334 P	CARTWRIGHT, W. R.	8212300267*	50-338 S	CHILK, S. J.	8212090230*	FOIA
CAREY, J. J.	8212080474	50-334 P	CARTWRIGHT, W. R.	8212300291*	50-339 S	CHILK, S. J.	8212100116	50-322 C
CAREY, J. J.	8212080480*	50-334 P	CARTWRIGHT, W. R.	8212300313	50-338 S	CHILK, S. J.	8212130205	50-337 C
CAREY, J. J.	8212090320	50-334 P	CARTWRIGHT, W. R.	8212300315*	50-338 S	CHILK, S. J.	8212130214	50-413 Q
CAREY, J. J.	8212100041*	50-334 Q	CARUSO, R.	8211080107*	50-29 P	CHILK, S. J.	8212140438	50-277 C
CAREY, J. J.	8212130242	50-334 P	CARUSO, R.	8212020356	50-29 P	CHILK, S. J.	8212150045	50-289 C
CAREY, J. J.	8212130243	50-334 P	CARUSO, R.	8212130228	50-29 P	CHILK, S. J.	8212150051	50-275 C
CAREY, J. J.	8212130248*	50-334 P	CARVER, A. M.	8212030092*	50-327 S	CHILK, S. J.	8212150057	50-275 C
CAREY, J. J.	8212160339	50-334 P	CARVER, A. M.	8212210100*	50-328 S	CHILK, S. J.	8212160375	50-247 C
CAREY, J. J.	8212170200	50-334 F	CASE, E. G.	8212130359*	50-352 Q	CHILK, S. J.	8212210242	50-413 Q
CAREY, J. J.	8212270155	50-334 P	CASE, E. G.	8212130361*	50-352 Q	CHILK, S. J.	8212210319	50-289 T
CAREY, J. J.	8212270161*	50-334 P	CASH, A.	8212160361	71-7006	CHILK, S. J.	8212220003	10CFR
CAREY, J. J.	8212270201	50-334 P	CASHWELL, R. J.	8212140195	50-156 S	CHILK, S. J.	8212220006	50-3 F
CAREY, J. J.	8212270207*	50-334 P	CASSIDY, B. P.	8212190137	50-382 Q	CHILK, S. J.	8212220017	50-275 P
CAREY, J. J.	8212290225	50-334 R	CASSIDY, B. P.	8212190133*	50-382 Q	CHILK, S. J.	8212220266	50-289 Q
CAREY, J. J.	8212290289*	50-334 Q	CATCHPOLE, O. J.	8212070461	40-8745	CHILK, S. J.	8212230174*	FOIA
CAREY, J. J.	8212300107	50-334 F	CATCHPOLE, O. J.	8212070480	40-8745	CHILK, S. J.	8212230211	50-341 Q
CARLISLE, C. S.	8212300318*	50-397 Q	CATCHPOLE, O. J.	8212100083	40-8745	CHILK, S. J.	8212230344	50-143 Q
CARLSON, J. D.	8212060261*	50-275 Q	CATTON, I.	8208290028	ACRS	CHILK, S. J.	8212230358	50-247 Q
CARLSON, J. D.	8212060364*	50-275 Q	CATTON, I.	8208290029	ACRS	CHILK, S. J.	8212230360	50-275 Q
CARNEY, W.	8212080689*	50-322 H	CATTON, I.	8208290029	ACRS	CHILK, S. J.	8212270050	10CFR
CAROW, J. F.	8212280051	RES	CATTON, I.	8212060323	ACRS	CHILK, S. J.	8212270092*	FOIA
CARPENTER, J. H.	8212270220	50-322 Q	CATTON, I.	8212070440	ACRS	CHILK, S. J.	8212270114*	FOIA
CARPENTER, T.	8212290023	50-206 Q	CAYIA, A. J.	8212290306*	50-309 S	CHILK, S. J.	8212270214	50-247 C
CARR, A. V.	8212100096	50-413 Q	CERNE, A. C.	8212210282*	50-443 Q	CHILK, S. J.	8212270217	50-275 C
CARR, A. V.	8212280174	50-413 Q	CHACKES, K. H.	8212280179	50-483 Q	CHILK, S. J.	8212270241	50-358 Q
CARRROLL, J. T.	8001140342	50-219 S	CHACKES, K. H.	8212280179	50-483 Q	CHILK, S. J.	8212270249	50-247 Q
CARTER, R. S.	8212210411	50-184 S	CHAMBERS, D. S.	8212080010*	FOIA	CHILK, S. J.	8212270251	50-413 Q
CARTER, R. S.	8212290402*	50-184 Q	CHAMBERS, D. S.	8212080058*	FOIA	CHILK, S. J.	8212280332*	50-247 C
CARTER, S.	8212020354*	50-259 S	CHAMBLEE, J. A.	8212100049	FOIA	CHILK, S. J.	8212290469	50-261 P
CARTER, S.	8212090369*	50-259 S	CHAN, B. C.	8212270534	RES	CHILK, S. J.	8212300026	50-329 Q
CARTWRIGHT, W.	8212300286	50-339 S	CHANCELLOR, R. A.	8212030306	40-8200	CHILK, S. J.	8212300142	50-289 Q
CARTWRIGHT, W. R.	8212090063	50-338 S	CHANDLER, J. C.	8212030088	TOPREP	CHILK, S. J.	8212300151	10CFR
CARTWRIGHT, W. R.	8212090064*	50-338 S	CHANDLER, J. C.	8212140190	TOPREP	CHILK, S. J.	8212300159	10CFR
CARTWRIGHT, W. R.	8212090067	50-339 S	CHANDLER, J. C.	8212150003	TOPREP	CHILK, S. J.	8212300244	50-358 Q
CARTWRIGHT, W. R.	8212090072*	50-339 S	CHANDLER, J. C.	8212290215*	50-237 P	CHIN, S. L.	8212100206	50-275 P
CARTWRIGHT, W. R.	8212090102	50-339 S	CHANDLER, L. J.	8212070007	50-361 Q	CHIN, S. L.	8212100291	50-275 P
CARTWRIGHT, W. R.	8212090107*	50-339 S	CHANDLER, L. J.	8212090199	50-361 Q	CHO, D. H.	8212070083*	50-247 Q
CARTWRIGHT, W. R.	8212090112	50-338 S	CHANEY, H. D.	8212100233*	50-285 Q	CHRISTOSIMOS, N.	8212030197*	50-254 Q
CARTWRIGHT, W. R.	8212090115*	50-338 S	CHANG, K. C.	8212210005*	50-275 P	CHRISTEL, B.	8212170225*	50-249 S
CARTWRIGHT, W. R.	8212090272	50-339 S	CHAPLIN, S. D.	8212060326*	50-320 S	CHRISTEL, B.	8212280479*	50-237 S
CARTWRIGHT, W. R.	8212090287*	50-339 S	CHAPLIN, S. D.	8212150044*	50-320 S	CHRISTIAN, D. L.	8212100260	50-289 A
CARTWRIGHT, W. R.	8212090527	50-338 S	CHAPLIN, S. D.	8212220434*	50-320 S	CHRISTIAN, J. N.	8208290121	FOIA
CARTWRIGHT, W. R.	8212090538*	50-338 S	CHAPLIN, S. D.	8212290240*	50-320 S	CHRISTOFFER, Q.	8212090396*	50-155 Q
CARTWRIGHT, W. R.	8212150028	50-338 S	CHAPYAK, E. J.	8212130157	50-537 A	CHRISTOFFER, Q.	8212280220*	50-10 Q
CARTWRIGHT, W. R.	8212150034*	50-338 S	CHARNOFF, O.	8212060413*	CONTRACT	CHRISTOPHER, W.	8212140444*	50-259 S
CARTWRIGHT, W. R.	8212150094	50-338 S	CHARNOFF, O.	8212070096*	COMMISSION	CHU, K. K.	8212160762	NUREG
CARTWRIGHT, W. R.	8212150096*	50-338 S	CHASE, J. H.	8212090479*	50-259 Q	CHU, M. S.	8212010469	RES
CARTWRIGHT, W. R.	8212200027	50-338 S	CHAUDHARY, S. K.	8212070269*	50-352 Q	CHU, M. S.	8212010481	RES
CARTWRIGHT, W. R.	8212200037*	50-338 S	CHEN, P. Y.	7909280656*	50-237 P	CHUNG, J. W.	8212070158*	50-387 Q
CARTWRIGHT, W. R.	8212210137	50-338 S	CHENG, T. C.	8212220282	NUREG	CHUNG, J. W.	8212290468*	50-387 Q
CARTWRIGHT, W. R.	8212210147*	50-338 S	CHENG, T. M.	8112290035*	50-244 P	CHURCHILL, B. W.	8212100098	50-382 Q
CARTWRIGHT, W. R.	8212210163	50-338 S	CHITANOI, N. J.	8212220345	50-400 S	CHURCHILL, B. W.	8212100098	50-382 Q
CARTWRIGHT, W. R.	8212210171*	50-338 S	CHILK, S. J.	8103310231*	FOIA	CHURCHILL, B. W.	8212100100	50-382 Q
CARTWRIGHT, W. R.	8212210294	50-339 S	CHILK, S. J.	8104100175*	FOIA	CHURCHILL, B. W.	8212100100	50-382 Q
CARTWRIGHT, W. R.	8212210269*	50-339 S	CHILK, S. J.	8211180416	50-395 Q	CHURCHILL, B. W.	8212230357	50-266 Q
CARTWRIGHT, W. R.	8212220244	50-338 S	CHILK, S. J.	8212010096*	FOIA	CHURCHILL, B. W.	8212230357	50-266 Q
CARTWRIGHT, W. R.	8212220268*	50-338 S	CHILK, S. J.	8212010105*	FOIA	CHURCHILL, B. W.	8212230359*	50-266 Q
CARTWRIGHT, W. R.	8212220364	50-339 S	CHILK, S. J.	8212010319	50-361 P	CHURCHILL, B. W.	8212230359*	50-266 Q
CARTWRIGHT, W. R.	8212220368*	50-339 S	CHILK, S. J.	8212010518	10CFR	CHURCHILL, B. W.	8212280182	50-382 Q
CARTWRIGHT, W. R.	8212220387	50-339 S	CHILK, S. J.	8212010522	10CFR	CHURCHILL, B. W.	8212280182	50-382 Q
CARTWRIGHT, W. R.	8212220391*	50-339 S	CHILK, S. J.	8212010526	50-395 P	CHURCHILL, B. W.	8212270036*	50-337 Q
CARTWRIGHT, W. R.	8212220392	50-339 S	CHILK, S. J.	8212010530	50-388 A	CILIMBERO, R.	8212290336*	50-266 Q
CARTWRIGHT, W. R.	8212220397*	50-339 S	CHILK, S. J.	8212020012*	FOIA	CILLIS, M.	8212130298*	50-187 Q
CARTWRIGHT, W. R.	8212220399	50-338 S	CHILK, S. J.	8212020019*	FOIA	CIPOLLA, A. J.	8212160060	40-3392
CARTWRIGHT, W. R.	8212220408*	50-338 S	CHILK, S. J.	8212020056*	FOIA	CLARK, A. T.	8212130430	50-201 P
CARTWRIGHT, W. R.	8212220410	50-338 S	CHILK, S. J.	8212020067*	FOIA	CLARK, A. T.	8212220311	PROJ
CARTWRIGHT, W. R.	8212220416*	50-338 S	CHILK, S. J.	8212020075*	FOIA	CLARK, L.	8212280406	50-20 P
CARTWRIGHT, W. R.	8212300099	50-339 S	CHILK, S. J.	8212020247	PRN	CLARK, P. R.	8212060247	50-219 P
CARTWRIGHT, W. R.	8212300104*	50-339 S	CHILK, S. J.	8212060092	50-289 Q	CLARK, P. R.	8212140180	50-289 P
CARTWRIGHT, W. R.	8212300126	50-338 S	CHILK, S. J.	8212060104	50-275 Q	CLARK, P. R.	8212150110	50-289 P
CARTWRIGHT, W. R.	8212300130*	50-338 S	CHILK, S. J.	8212060242	50-289 Q	CLARK, R.	8212090033*	50-335 P
CARTWRIGHT, W. R.	8212300171	50-338 S	CHILK, S. J.	8212060243	50-413 Q	CLARK, R.	8212090037*	50-335 P
CARTWRIGHT, W. R.	8212300177*	50-338 S	CHILK, S. J.	8212060427*	FOIA	CLARK, R. A.	8212010236	50-285 F
CARTWRIGHT, W. R.	8212300217	50-338 S	CHILK, S. J.	8212070168	50-437 Q	CLARK, R. A.	8212010334	50-309 P

PERSONAL AUTHOR INDEX

427

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
CLARK, R A	8212010417	50-309 P	COLLINS, J J	8212060455	NUREQ	COONEY, M J	8212150061	50-277 S
CLARK, R A	8212010458	50-285 P	COLLINS, J T	8212070437*	50-298 F	COONEY, M J	8212160055	50-277 R
CLARK, R A	8212020391	50-338 P	COLLINS, J T	8212070473*	50-267 F	COONEY, M J	8212160415	50-277 S
CLARK, R A	8212020409	50-267 P	COLLINS, J T	8212080506	50-298 Q	COOPER, W E	8212010206	50-275 R
CLARK, R A	8212070082	50-317 P	COLLINS, J T	8212100197	50-298 Q	COOPER, W E	8212080479	50-275 P
CLARK, R A	8212070084	50-267 P	COLLINS, J T	8212140403	50-298 Q	COOPER, W E	8212080206	50-275 P
CLARK, R A	8212070105	50-317 P	COLLINS, J T	8212200121	50-382 Q	COOPER, W E	8212100291	50-275 F
CLARK, R A	8212070454	50-309 P	COLLINS, J T	8212210021	50-285 Q	COOPER, W E	8212140278	50-275 P
CLARK, R A	8212080012	50-317 P	COLLINS, J T	8212280423	50-382 Q	COOPER, W E	8212140281	50-275 R
CLARK, R A	8212080031	50-318 Q	COLLINS, J T	8212280430*	50-382 Q	COOPER, W E	8212290146	50-275 R
CLARK, R A	8212080040*	50-318 Q	COLLINS, J T	8212300121	50-445 Q	COOPER, W E	8212290205	50-275 P
CLARK, R A	8212090032	50-317 P	COLLINS, T R	8212090332*	50-414 Q	COPELAND, V Q	8212070327	50-155 Q
CLARK, R A	8212090050	50-318 P	COLMBRO, R	8212140401	50-312 P	COPELAND, V Q	8212070327	50-155 Q
CLARK, R A	8212090053*	50-318 P	COLMBRO, R	8212170235*	50-312 R	COPELAND, V Q	8212070352*	50-155 Q
CLARK, R A	8212130092	50-309 P	COLMBRO, R	8212200048*	50-312 R	COPELAND, V Q	8212070352*	50-155 Q
CLARK, R A	8212130095*	50-309 P	COLMBRO, R	8212270288*	50-312 R	COPELAND, V Q	8212210285	50-155 Q
CLARK, R A	8212130366	50-344 P	COLMBRO, R	8212270291*	50-312 R	COPELAND, V Q	8212210285	50-155 Q
CLARK, R A	8212130357*	50-344 P	COLMBRO, R	8212030095*	50-312 S	CORVELL, O P	8212080139*	FOIA
CLARK, R A	8212130372*	50-344 P	COLMBRO, R	8212030106*	50-312 S	CORVELL, O P	8212090451*	50-332 Q
CLARK, R A	8212150226	50-267 P	COLMBRO, R	8212030116*	50-312 S	COSTELLO, J R	8212210223	QA979
CLARK, R A	8212150229	50-309 P	COLMBRO, R	8212060300*	50-312 S	COTTER, B P	8212230215	50-458 Q
CLARK, R A	8212160542	50-313 F	COLMBRO, R	8212270285	50-312 P	COTTER, B P	8212230315	50-458 Q
CLARK, R A	8212160731	50-309 F	COLSHER, C S	8212140464	NUREQ	COTTER, B P	8212280192	50-440 Q
CLARK, R A	8212170024	50-280 F	COLSHER, C S	8212160773	NUREQ	COTTON, O D	8212030168*	50-361 P
CLARK, R A	8212210013	50-313 P	COLTON, E	8212070313	XPORTRIC	COUNSIL, W Q	8211080257	50-245 P
CLARK, R A	8212220551	50-335 P	CONDON, W A	8212140479	50-239 P	COUNSIL, W Q	8211080257	50-245 P
CLARK, R A	8212270025	50-309 F	CONDON, T E	8212090256*	50-400 Q	COUNSIL, W Q	8212020299	50-213 F
CLARK, R A	8212270483	50-344 F	CONDON, T E	8212090258*	50-424 Q	COUNSIL, W Q	8212060157	50-213 P
CLARK, R A	8212270542	50-318 P	CONDON, T E	8212090275*	50-389 Q	COUNSIL, W Q	8212060157	50-213 P
CLARK, R A	8212270546*	50-318 P	CONDON, T E	8212090308*	50-335 Q	COUNSIL, W Q	8212060376	50-213 Q
CLARK, R A	8212280082	50-264 F	CONDON, T E	8212090321*	50-324 Q	COUNSIL, W Q	8212070124	50-245 F
CLARK, R A	8212280410	50-344 P	CONDON, T E	8212090355*	50-400 Q	COUNSIL, W Q	8212070124	50-245 F
CLARK, R A	8212290022	50-313 P	CONDON, T E	8212090364*	50-417 Q	COUNSIL, W Q	8212070286	50-245 P
CLARK, R A	8212290496	50-335 P	CONDON, T E	8212090407*	50-390 Q	COUNSIL, W Q	8212070286	50-245 P
CLARK, R A	8212290499*	50-335 P	CONDON, T E	8212090465*	50-413 Q	COUNSIL, W Q	8212070289	50-213 P
CLARK, R A	8212290501*	50-335 P	CONNAUGHTON, K	8212100308*	50-454 Q	COUNSIL, W Q	8212080341	50-423 S
CLARK, R A	8212300041	50-317 P	CONNER, E L	8212090036*	50-317 P	COUNSIL, W Q	8212080341	50-423 S
CLAY, E L	8212090413*	70-143 P	CONNER, E L	8212130102*	50-309 P	COUNSIL, W Q	8212090114	50-213 F
CLAYTON, F L	8212020130	50-348 P	CONNER, T B	8212020330	50-352 Q	COUNSIL, W Q	8212090114	50-213 F
CLAYTON, F L	8212020182	PR	CONNER, T B	8212020330	50-352 Q	COUNSIL, W Q	8212100071	50-245 Q
CLAYTON, F L	8212070336	50-364 Q	CONNER, T B	8212020339*	50-352 Q	COUNSIL, W Q	8212100071	50-245 Q
CLAYTON, F L	8212090295	50-364 S	CONNER, T B	8212020339*	50-352 Q	COUNSIL, W Q	8212100277	50-245 P
CLAYTON, F L	8212090362	50-348 Q	CONNER, T B	8212210261	50-458 Q	COUNSIL, W Q	8212100277	50-245 P
CLAYTON, F L	8212090412	50-348 Q	CONNER, T B	8212210261	50-458 Q	COUNSIL, W Q	8212140144	50-336 P
CLAYTON, F L	8212100070	50-348 F	CONNER, T B	8212230327	50-352 Q	COUNSIL, W Q	8212140144	50-336 P
CLAYTON, F L	8212150033	50-364 P	CONNER, T B	8212270216	50-352 Q	COUNSIL, W Q	8212140221*	50-245 Q
CLAYTON, F L	8212170197	50-348 R	CONNER, T B	8212270216	50-352 Q	COUNSIL, W Q	8212150036	50-213 F
CLAYTON, F L	8212170234	50-364 P	CONNER, T B	8212280185	50-352 Q	COUNSIL, W Q	8212150128	50-245 P
CLAYTON, F L	8212170297	50-364 R	CONNER, T B	8212280185	50-352 Q	COUNSIL, W Q	8212150128	50-245 P
CLAYTON, F L	8212210130	50-364 P	CONNER, T B	8212300187	50-352 Q	COUNSIL, W Q	8212160216	PR
CLAYTON, F L	8212280280	50-348 P	CONNER, T B	8212300187	50-352 Q	COUNSIL, W Q	8212160216	PR
CLAYTON, F L	8212300216	50-364 P	CONNER, J E	8212080516	RES	COUNSIL, W Q	8212160216	PR
CLEMONSON, F	8212150333*	NUREQ	CONOR, L	8208290104	FOIA	COUNSIL, W Q	8212160470	50-423 S
CLEMENTS, B R	8212160428	50-445 A	CONSTABLE, Q L	8212070123*	50-382 Q	COUNSIL, W Q	8212160470	50-423 S
CLEMENTS, B R	8212030032*	70-1100	CONSTABLE, Q L	8212280378*	50-382 Q	COUNSIL, W Q	8212170117	50-245 P
CLEVELAND, R S	8212160105*	40-6500	CONTE, R	8212140319*	50-320 Q	COUNSIL, W Q	8212170199	50-245 P
CLINE, H E	8212090351*	50-261 Q	CONTE, R	8212220478*	50-289 Q	COUNSIL, W Q	8212170199	50-245 P
COBB, G H	8212280012*	40-1478	CONVERSANE, E	8212290273	CONTRACT	COUNSIL, W Q	8212170279	50-245 P
COBB, L I	8208190245	50-3 Q	CONWAY, J T	8212210105*	QA979	COUNSIL, W Q	8212170279	50-245 P
COBB, L I	8208190257	50-3 Q	CONWAY, J T	8212210366*	QA979	COUNSIL, W Q	8212170321	50-245 P
COCKRELL, R O	8212070185	50-111 W	COOK, J	8212130084*	50-333 R	COUNSIL, W Q	8212170321	50-245 P
COCK, R	8212230241	50-247 Q	COOK, J W	82122020313	50-329 S	COUNSIL, W Q	8212210059	50-213 P
COHEN, C B	8212160518	PR	COOK, J W	8212070017	50-329 R	COUNSIL, W Q	8212210121	50-213 P
COHEN, E H	8212290023	50-206 Q	COOK, J W	8212080392	50-329 A	COUNSIL, W Q	8212210121	50-213 P
COIFIN, I	8212220388*	50-289 Q	COOK, J W	8212090066	50-329 A	COUNSIL, W Q	8212210121	50-213 P
COHN, B M	8206100047*	50-344 F	COOK, J W	8212100237	50-329 S	COUNSIL, W Q	8212210355	50-423 F
COLARULLI, P F	8212080310	50-247 Q	COOK, J W	8212100273	50-329 S	COUNSIL, W Q	8212230257	50-213 P
COLARULLI, P F	8212080310	50-247 Q	COOK, J W	8212140357*	50-329 A	COUNSIL, W Q	8212270152	50-245 P
COLARULLI, P F	8212090090	50-247 Q	COOK, J W	8212170144	50-329 A	COUNSIL, W Q	8212270152	50-245 P
COLBURN, R P	8212140380*	50-537 A	COOK, J W	8212210156	50-329 B	COUNSIL, W Q	8212280119	50-245 P
COLBURN, R P	8212210156	PR	COOK, J W	8212210309	50-329 A	COUNSIL, W Q	8212290447	50-245 P
COLBURN, R P	8212220107	50-454 Q	COOK, J W	8212230112	70-2964	COUNSIL, W Q	8212290447	50-245 P
COLBURN, R P	8212100104	50-338 Q	COOK, J W	8212270126	50-329 S	COUNSIL, W Q	8212290447	50-245 P
COLEMAN, J H	8212100104	50-338 Q	COOK, J W	8212280207	50-329 S	COUNSIL, W Q	8212210089*	50-219 Q
COLEMAN, J H	8212140245	50-338 Q	COOK, J W	8212280225	50-329 F	COUNSIL, W Q	8212220473*	50-280 F
COLEMAN, J H	8212140245	50-338 Q	COOK, J W	8212280320	50-329 S	COUNSIL, W Q	8212270044*	50-261 S
COLEMAN, J H	8212140245	50-338 Q	COOK, J W	8212290203	50-329 A	COUNSIL, W Q	8212270044*	50-261 S
COLEMAN, J H	8212090186*	50-400 Q	COOK, J W	8212290208	50-329 A	COUNSIL, W Q	8212270044*	50-261 S
COLLIER, A R	8212070187*	50-454 A	COOK, T L	8212020108	50-364 P	COUNSIL, W Q	8212270044*	50-261 S
COLLINS, D J	8212220358*	50-244 Q	COOKE, O C	8212130097	TOPREP	COYLE, L	8212100216*	50-237 S
COLLINS, J J	8212060429	NUREQ	COOKE, O C	8212140411	50-282 P	COYLE, L	8212170102*	50-249 S
COLLINS, J J	8212060441	NUREQ	COOKE, O C	8212290206*	50-237 P	COYLE, L	8212290476*	50-249 S
COLLINS, J J	8212060447	NUREQ	COONEY, M J	8212030205	50-278 S	COYLE, L M	8212210160*	50-237 S
COLLINS, J J	8212060451	NUREQ	COONEY, M J	8212030208*	50-278 S	COZENS, G	8212080200*	90-187 R

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
CRADDICK, W. O.	8212060465	NUREQ	CRUTCHFIELD, D.	8212070102	50-213 P	CUTCHIN, J. M.	8212070155	50-440 G
CRAIG, J.	8212060329	50-382 S	CRUTCHFIELD, D.	8212070192	50-235 P	CUTCHIN, J. M.	8212090223	50-440 G
CRAIL, A. C.	8212220282	NUREQ	CRUTCHFIELD, D.	8212070201*	50-255 P	CUTCHIN, J. M.	8212150118	50-440 G
CRANDALL, W. E.	8212080194	50-187 P	CRUTCHFIELD, D.	8212070210	50-235 P	CUTCHIN, J. M.	8212210318	50-440 G
CRANE, C. J.	8207010124*	50-29 P	CRUTCHFIELD, D.	8212070299	50-155 P	CYBULSKIS, P.	8212140476	NUREQ
CRANE, C. J.	8207010149*	50-244 P	CRUTCHFIELD, D.	8212080169	50-409 P	CZAJKOWSKI, C. J.	8212280031	RES
CRANE, C. J.	8207010394*	50-245 P	CRUTCHFIELD, D.	8212080174*	50-409 P	D'ANGELO, A.	8212210211*	50-328 G
CRANE, C. J.	8207010410*	50-409 P	CRUTCHFIELD, D.	8212080206	50-219 P	DALE, L. F.	8212010176	50-416 P
CRANE, C. J.	8207190169*	50-219 P	CRUTCHFIELD, D.	8212080340	50-255 P	DALE, L. F.	8212070274	50-416 P
CRANE, C. J.	8212230110*	50-213 P	CRUTCHFIELD, D.	8212080376	50-29 P	DALE, L. F.	8212170278	50-416 P
CRANE, C. J.	8212230250*	50-277 P	CRUTCHFIELD, D.	8212080389*	50-29 P	DALE, L. F.	8212230252	50-416 P
CRANE, P. A.	8212010190	50-275 P	CRUTCHFIELD, D.	8212080403*	50-29 P	DALE, L. F.	8212270154	50-416 P
CRANE, P. A.	8212030190	50-275 P	CRUTCHFIELD, D.	8212130203	50-255 F	DALE, L. F.	8212270235	50-416 F
CRANE, P. A.	8212030191	50-275 P	CRUTCHFIELD, D.	8212140259	50-29 P	DALEY, C.	8212170311*	50-331 P
CRANE, P. A.	8212060047	50-275 R	CRUTCHFIELD, D.	8212150030	50-155 P	DALLMAN, R. J.	8201120155*	RES
CRANE, P. A.	8212060078	50-323 S	CRUTCHFIELD, D.	8212150039	50-409 P	DALTROFF, S. L.	8212060106*	50-277 F
CRANE, P. A.	8212070235	50-275 P	CRUTCHFIELD, D.	8212150115	50-409 P	DALTROFF, S. L.	8212080323*	50-277 G
CRANE, P. A.	8212080043*	50-275 F	CRUTCHFIELD, D.	8212150194	50-409 P	DALTROFF, S. L.	8212090119	50-277 F
CRANE, P. A.	8212090084	50-275 G	CRUTCHFIELD, D.	8212170050	50-219 F	DALTROFF, S. L.	8212100036	50-277 F
CRANE, P. A.	8212130070	50-275 F	CRUTCHFIELD, D.	8212200008	50-244 P	DALTROFF, S. L.	8212130211	50-277 F
CRANE, P. A.	8212140473	50-275 P	CRUTCHFIELD, D.	8212200100	50-245 P	DALTROFF, S. L.	8212140385	50-277 P
CRANE, P. A.	8212170217	50-275 R	CRUTCHFIELD, D.	8212210127	50-213 P	DALTROFF, S. L.	8212150187*	50-277 F
CRANE, P. A.	8212210002	50-275 P	CRUTCHFIELD, D.	8212210216	50-409 P	DALTROFF, S. L.	8212170248	50-277 P
CRANE, P. A.	8212210014	50-275 P	CRUTCHFIELD, D.	8212210392	50-244 P	DALTROFF, S. L.	8212170289	50-277 P
CRANE, P. A.	8212210090	50-323 A	CRUTCHFIELD, D.	8212210459	50-255 P	DALTROFF, S. L.	8212210312	50-277 P
CRANE, P. A.	8212220217	50-275 P	CRUTCHFIELD, D.	8212220209	50-155 P	DALTROFF, S. L.	8212230313	50-277 F
CRANE, P. A.	8212230210	50-275 P	CRUTCHFIELD, D.	8212220377	50-213 P	DALTROFF, S. L.	8212270167	50-277 P
CRANE, P. A.	8212230298	50-275 P	CRUTCHFIELD, D.	8212220427	50-155 P	DALTROFF, S. L.	8212270219	50-278 P
CRANE, P. A.	8212270371	50-275 P	CRUTCHFIELD, D.	8212230457	50-213 P	DALTROFF, S. L.	8212280452	50-277 P
CRANE, P. A.	8212280098	50-275 P	CRUTCHFIELD, D.	8212230089	50-213 P	DALTROFF, S. L.	8212290235	50-277 P
CRANE, P. A.	8212290366	50-275 R	CRUTCHFIELD, D.	8212230238	50-29 P	DANCE, H. C.	8212030102	50-302 S
CRAWFORD, V. A.	8212060095	50-528 Q	CRUTCHFIELD, D.	8212230243*	50-29 P	DANCE, H. C.	8212070195	50-338 Q
CRAWFORD, V. A.	8212060095	50-328 Q	CRUTCHFIELD, D.	8212230277	50-237 P	DANCE, H. C.	8212090181	50-369 Q
CREED, J. R.	8212060080*	50-346 Q	CRUTCHFIELD, D.	8212230287	50-245 P	DANCE, H. C.	8212090187	50-369 Q
CREED, J. R.	8212090396*	50-155 Q	CRUTCHFIELD, D.	8212230305	50-245 P	DANCE, H. C.	8212090197*	50-369 Q
CREED, J. R.	8212140414*	50-151 Q	CRUTCHFIELD, D.	8212230310	50-219 P	DANCE, H. C.	8212090211	50-389 Q
CREED, J. R.	8212280220*	50-10 Q	CRUTCHFIELD, D.	8212230322	50-155 P	DANCE, H. C.	8212090215	50-280 Q
CREWS, J. L.	8212280279	50-308 Q	CRUTCHFIELD, D.	8212230354	50-155 P	DANCE, H. C.	8212090223*	50-280 Q
CREWS, J. L.	8212280301*	50-508 Q	CRUTCHFIELD, D.	8212270365	50-29 P	DANCE, H. C.	8212090227	50-424 Q
CROCKER, H. W.	8212160406*	50-289 Q	CRUTCHFIELD, D.	8212290239	50-213 Q	DANCE, H. C.	8212090248	50-424 Q
CROCKER, H. W.	8212220388*	50-289 Q	CRUTCHFIELD, D.	8212290242*	50-213 Q	DANCE, H. C.	8212090262	50-370 Q
CROENBERG, A. W.	8212130113	NUREQ	CRUTCHFIELD, D.	8212290267	50-155 P	DANCE, H. C.	8212090267	50-280 Q
CROSSMAN, H. A.	8212070123*	50-382 Q	CRUTCHFIELD, D.	8212290270*	50-155 P	DANCE, H. C.	8212090268	50-389 Q
CROSSMAN, H. A.	8212070133*	50-112 Q	CRUTCHFIELD, D.	8212290278*	50-155 P	DANCE, H. C.	8212090276	50-280 Q
CROSSMAN, H. A.	8212200086*	50-458 Q	CRUTCHFIELD, D.	8212290320	50-409 P	DANCE, H. C.	8212090300*	50-280 Q
CROSSMAN, H. A.	8212200126*	50-382 Q	CRUTCHFIELD, D.	8212300031	50-255 P	DANCE, H. C.	8212090302	50-335 Q
CROSSMAN, H. A.	8212280378*	50-382 Q	CRUTCHFIELD, D.	8212300038*	50-255 P	DANCE, H. C.	8212090317	50-413 Q
CROUCHER, P. W.	8212130113	NUREQ	CRUTCHFIELD, D.	8212300044*	50-255 P	DANCE, H. C.	8212090331	50-389 Q
CROUSE, R. P.	8212020270	50-346 F	CRUTCHFIELD, D.	8212300330	50-155 P	DANCE, H. C.	8212090353	50-389 Q
CROUSE, R. P.	8212060158	50-346 P	CULP, O. H.	8212140349	50-344 F	DANCE, H. C.	8212090373	50-369 Q
CROUSE, R. P.	8212070292	50-346 P	CUMMINGS, J. J.	8212060177*	50-275 Q	DANCE, H. C.	8212090404	50-389 Q
CROUSE, R. P.	8212100040	50-346 P	CUMMINGS, J. E.	8212030192*	50-368 Q	DANCE, H. C.	8212090459	50-413 Q
CROUSE, R. P.	8212100231	50-346 F	CUMMINGS, J. E.	8212070123*	50-382 Q	DANCE, H. C.	8212090478	50-338 Q
CROUSE, R. P.	8212130088	50-246 P	CUMMINGS, J. E.	8212280378*	50-382 Q	DANCE, H. C.	8212090487	50-250 Q
CROUSE, R. P.	8212130090	50-346 P	CUNNINGHAM, A. L.	8212090288*	50-261 Q	DANCE, H. C.	8212090490	50-250 Q
CROUSE, R. P.	8212210081	50-346 P	CUNNINGHAM, O. H.	8212280415*	REVIEWS ORP	DANCE, H. C.	8212090491*	50-338 Q
CROUSE, R. P.	8212210092	50-346 P	CUNNINGHAM, M.	8212140476	NUREQ	DANCE, H. C.	8212090509	50-395 Q
CROUSE, R. P.	8212210348*	50-346 Q	CURRAN, D.	8212200039	50-443 Q	DANCE, H. C.	8212090510*	50-250 Q
CROUSE, R. P.	8212320273	50-346 P	CURRAN, D.	8212200039	50-443 Q	DANCE, H. C.	8212090515	50-338 Q
CROUSE, R. P.	8212270205	50-346 P	CURRAN, D.	8212200049*	50-443 G	DANCE, H. C.	8212090529	50-250 Q
CROUSE, R. P.	8212270210	50-346 P	CURRAN, D.	8212200049*	50-443 G	DANCE, H. C.	8212090530*	50-395 Q
CROUSE, R. P.	8212290226	50-346 Q	CURRAN, J.	8212280506	FOIA	DANCE, H. C.	8212090531	50-335 Q
CROUSE, R. P.	8212290455*	50-346 Q	CURRAN, J. E.	8212020277	PRM	DANCE, H. C.	8212090533	50-335 Q
CROW, W. T.	8212010338	70-371	CURRAN, J. H.	8212160168*	40-6500	DANCE, H. C.	8212090561*	50-335 Q
CROW, W. T.	8212020081*	70-734	CURRAN, J. H.	8212060012	50-362 S	DANCE, H. C.	8212150085	50-302 S
CROW, W. T.	8212100180*	70-1334	CURRAN, J. H.	8212170386*	50-206 Q	DANCE, H. C.	8212150103	50-338 S
CROW, W. T.	8212130287*	70-2957	CURRAN, J. H.	8212270308*	50-206 Q	DANCE, H. C.	8212150144	50-287 S
CROW, W. T.	8212170011*	70-2928	CURTIS, N. H.	8211090019	50-387 E	DANCE, H. C.	8212150151	50-338 S
CROW, W. T.	8212270029*	70-2941	CURTIS, N. W.	8212060066	50-387 P	DANCE, H. C.	8212290137*	FOIA
CRUTCHFIELD, D.	8002270235*	50-206 P	CURTIS, N. W.	8212060140	50-387 F	DANCE, H. C.	8212290165*	FOIA
CRUTCHFIELD, D.	8005070778*	50-237 P	CURTIS, N. W.	8212090214	50-387 P	DANDINI, V. J.	8212130118	NUREQ
CRUTCHFIELD, D.	8006090164*	50-206 P	CURTIS, N. W.	8212140497*	50-387 P	DANIELSON, D. H.	8212170094*	50-255 Q
CRUTCHFIELD, D.	8009180414*	FOIA	CURTIS, N. W.	8212160317	50-387 P	DANIELSON, D. H.	8212270303*	50-282 Q
CRUTCHFIELD, D.	8105110512*	50-219 P	CURTIS, N. W.	8212160417	50-387 P	DANIELSON, D. H.	8212290336*	50-266 Q
CRUTCHFIELD, D.	8211080101	50-29 P	CURTIS, N. W.	8212170271	50-387 P	DANIELSON, D. H.	8212290400*	50-295 Q
CRUTCHFIELD, D.	8211080105*	50-29 P	CURTIS, N. W.	8212210310	50-388 A	DAVID, L. T.	8207180049	FOIA
CRUTCHFIELD, D.	8211080110*	50-29 P	CURTIS, N. W.	8212210450	50-387 K	DAVIDSON, D. R.	8212020296	50-440 S
CRUTCHFIELD, D.	8211170509	50-237 P	CURTIS, N. W.	8212270272	50-387 P	DAVIDSON, D. R.	8212020395	50-440 S
CRUTCHFIELD, D.	8212020245	50-409 P	CURTIS, N. W.	8212280323	50-388 S	DAVIDSON, D. R.	8212070015	50-440 H
CRUTCHFIELD, D.	8212020255	50-155 P	CURTIS, N. W.	8212280346	50-388 S	DAVIS, A. B.	8212080416	50-329 S
CRUTCHFIELD, D.	8212020266	50-155 P	CURTIS, N. W.	8212280347	50-387 P	DAVIS, C. B.	8212020110	50-249 P
CRUTCHFIELD, D.	8212020328	50-409 P	CURTIS, N. W.	8212280400	50-387 S	DAVIS, D. K.	8212020435*	50-10 P
CRUTCHFIELD, D.	8212020332	50-155 P	CURTIS, N. W.	8212280444	50-387 P	DAVIS, H. M.	8212220339	50-440 Q
CRUTCHFIELD, D.	8212060063	50-219 P	CUSTODIO, D. B.	8212210377*	50-219 S	DAVIS, J. O.	8212010221*	WASTE HOT
CRUTCHFIELD, D.	8212070097	50-219 P	CUTCHIN, J. M.	8212030181	50-440 Q	DAVIS, J. O.	8212020148	WASTE HOT

PERSONAL AUTHOR INDEX

429

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
DAVIS, J. Q.	8212100183	40-17	DEVINCENTIS, J.	8212060151	50-443 A	DIEDERICH, O. J.	8212280483	50-373 S
DAVIS, J. Q.	8212230034	WASTE MGT	DEVINCENTIS, J.	8212070100	50-443 A	DIETCH, R.	82122010171	50-361 P
DAVIS, J. R.	8212020389	PRM	DEVINCENTIS, J.	8212070100	50-443 A	DIETCH, R.	8212030157	50-361 P
DAVIS, M. J.	8212090234*	50-280 Q	DEVINCENTIS, J.	8212080163	50-443 F	DIETZ, C. R.	8212030168*	50-361 P
DAVIS, M. J.	8212090313*	50-280 Q	DEVINCENTIS, J.	8212080163	50-443 F	DIETZ, C. R.	8212130188	50-362 P
DAVISON, A.	8212230092	NUREG	DEVINCENTIS, J.	8212080190	50-443 A	DIETZ, C. R.	8212130193*	50-362 P
DAWSON, D. M.	8212150216	71-9001	DEVINCENTIS, J.	8212080190	50-443 A	DIETZ, C. R.	8212270413	50-361 S
DAYAL, R.	8212280040	RES	DEVINCENTIS, J.	8212080207	50-443 A	DIETZ, C. R.	82122020068	50-324 S
DAYAL, R.	8212280514	50-320 P	DEVINCENTIS, J.	8212080224	50-443 A	DIETZ, C. R.	82122020152	50-324 S
DE MARCO, J. H.	8212230235	50-247 Q	DEVINCENTIS, J.	8212080224	50-443 A	DIETZ, C. R.	82122020293	50-324 S
DEAGAZIO, A. W.	8212130111	50-346 P	DEVINCENTIS, J.	8212080329*	50-443 Q	DIETZ, C. R.	82122020306	50-325 S
DEAGAZIO, A. W.	8212280069	50-346 P	DEVINCENTIS, J.	8212080329*	50-443 Q	DIETZ, C. R.	82122020315	50-324 S
DEAK, A. M.	8212070353*	50-269 P	DEVINCENTIS, J.	8212080498	50-443 A	DIETZ, C. R.	82122020362	50-324 S
DEARIEN, J. A.	8212010487	RES	DEVINCENTIS, J.	8212080498	50-443 A	DIETZ, C. R.	8212070006	50-325 S
DEBS, B. T.	8212090500*	50-250 Q	DEVINCENTIS, J.	8212140235	50-443 A	DIETZ, C. R.	8212070112	50-325 S
DEIRICH, L. W.	8212070083*	50-247 Q	DEVINCENTIS, J.	8212140235	50-443 A	DIETZ, C. R.	8212070208	50-325 S
DELANEY, J. C.	8212160341*	40-3265	DEVINCENTIS, J.	8212210273	50-443 S	DIETZ, C. R.	82122020273	50-324 S
DELANEY, J. C.	8212160505*	40-2116	DEVINCENTIS, J.	8212210273	50-443 S	DIETZ, C. R.	8212090100	50-325 S
DELANEY, J. C.	8212160513*	40-2116	DEVINCENTIS, J.	8212210287	50-443 S	DIETZ, C. R.	8212090135	50-325 S
DELANEY, J. C.	8212160534*	40-1606	DEVINCENTIS, J.	8212210287	50-443 S	DIETZ, C. R.	8212090147	50-325 S
DEL BELLO, A. B.	8212130254*	50-247 Q	DEVINCENTIS, J.	8212210449	50-443 S	DIETZ, C. R.	8212090167	50-325 S
DEL GORGE, L. O.	82122040041	50-373 F	DEVINCENTIS, J.	8212210449	50-443 S	DIETZ, C. R.	8212270428*	50-324 Q
DEL GORGE, L. O.	8212060045*	50-10 Q	DEVINCENTIS, J.	8212270146	50-443 A	DIETZ, C. R.	8212090314	50-324 S
DEL GORGE, L. O.	8212090338*	50-234 Q	DEVINCENTIS, J.	8212270146	50-443 A	DIETZ, C. R.	8212090453	50-325 S
DEL GORGE, L. O.	8212090383	50-237 F	DEVINCENTIS, J.	8212270188	50-443 A	DIETZ, C. R.	8212090535	50-325 S
DEL GORGE, L. O.	8212100330*	50-454 Q	DEVINCENTIS, J.	8212270188	50-443 A	DIETZ, C. R.	8212090543	50-325 S
DEL GORGE, L. O.	8212100231*	50-373 Q	DEVINCENTIS, J.	8212270270	50-443 A	DIETZ, C. R.	8212100241	50-324 R
DEL GORGE, L. O.	8212210108*	50-373 Q	DEVINCENTIS, J.	8212270270	50-443 A	DIETZ, C. R.	8212140153	50-325 S
DEL GORGE, L. O.	8212270223*	50-373 Q	DEVINCENTIS, J.	8212270279	50-443 A	DIETZ, C. R.	8212140196	50-325 S
DEL GORGE, L. O.	8212270303*	50-237 Q	DEVINCENTIS, J.	8212270279	50-443 A	DIETZ, C. R.	8212150112	50-325 S
DEL GORGE, L. O.	8212290247	50-454 F	DEVINE, J. B.	8212230432	XPORTLIC	DIETZ, C. R.	8212170141	50-325 S
DELLA RATTIA, A.	8212100081*	50-219 Q	DEVINE, J. F.	8212020193*	MISC	DIETZ, C. R.	8212170216	50-325 S
DELLA RATTIA, A.	8212290352*	70-820	DEVINE, T.	8212020358	50-373 P	DIETZ, C. R.	8212210030	50-325 S
DELLA RATTIA, A.	8212290383*	50-244 Q	DEVINE, T.	8212020382	50-358 Q	DIETZ, C. R.	8212210152	50-325 S
DEMME, P. N.	8212080516	RES	DEVINE, T. D.	8212280128	50-358 Q	DIETZ, C. R.	8212210399	50-325 S
DENISON, E.	8212140276	50-275 P	DEVINE, T. D.	8212280128	50-358 Q	DIETZ, C. R.	8212220488	50-325 S
DENISON, E.	8212140277*	50-275 P	DEWEY, L. S.	8212010038	50-522 Q	DIETZ, C. R.	8212220496	50-325 S
DENISON, E.	8212150164	50-275 P	DEWEY, L. S.	8212201118	50-528 Q	DIETZ, C. R.	8212280383	50-325 S
DENISON, E.	8212150170*	50-275 P	DEWITT, R. B.	8212200075*	50-255 P	DIETZ, C. R.	8212300067	50-324 S
DENISON, E.	8212200080	50-275 P	DEWITT, R. B.	8212280089*	50-255 P	DIETZ, C. R.	8212300221	50-325 S
DENISON, E.	8212200095*	50-275 P	DEWITT, R. B.	8212280107*	50-155 P	DIETZ, C. R.	8212300229	50-325 S
DENNING, J.	8212140476	NUREG	DEYOUNG, R. C.	8208190240	50-3 Q	DIETZ, C. R.	8212300236	50-325 S
DENNY, I. L.	8212130432	40-2061	DEYOUNG, R. C.	8208190256	50-3 Q	DIETZ, C. R.	8212300257	50-325 S
DENTE, T. J.	8212300034	TOPREP	DEYOUNG, R. C.	8208190259	50-3 Q	DIETZ, C. R.	8212300307	50-325 S
DENTON, H. R.	8009110797*	50-10 P	DEYOUNG, R. C.	8208190267	50-3 Q	DIETZ, C. R.	8212300316	50-325 S
DENTON, H. R.	8211120169*	REVIEW GRP	DEYOUNG, R. C.	8212020080*	FOIA	DIETZ, C. R.	8212300331	50-325 S
DENTON, H. R.	8212130137*	50-275 P	DEYOUNG, R. C.	8212060427*	FOIA	DIETZ, C. R.	8212300360	50-325 S
DENTON, H. R.	8212010436	MISC	DEYOUNG, R. C.	8212070033	50-312 Q	DIETZ, C. R.	8212200093	PR
DENTON, H. R.	8212020204	TOPREP	DEYOUNG, R. C.	8212070073	50-247 Q	DIETZ, C. R.	8212010370	50-338 P
DENTON, H. R.	8212030262	50-13 P	DEYOUNG, R. C.	8212070081*	50-247 Q	DIETZ, C. R.	8212170040	50-266 P
DENTON, H. R.	8212060042	50-309 P	DEYOUNG, R. C.	8212070146*	50-312 Q	DIETZ, C. R.	8212210012	50-247 Q
DENTON, H. R.	8212060046*	50-309 P	DIKAZ, N. J.	8212070004	50-83 R	DIETZ, C. R.	8212220061	50-361 P
DENTON, H. R.	8212060052	MISC	DIKAZ, N. J.	8212070009*	50-83 R	DIETZ, C. R.	8212220545	50-263 P
DENTON, H. R.	8212060058*	MISC	DICK, G. F.	8212150326	NUREG	DIETZ, C. R.	8212300190	50-320 P
DENTON, H. R.	8212060064*	MISC	DICKENSON, R. E.	8212160643*	COMMISSION	DIGNAN, T. O.	8212140212	50-443 Q
DENTON, H. R.	8212060142	50-89 P	DICKERSON, M. W.	8212070260*	50-267 Q	DIGNAN, T. O.	8212140212	50-443 Q
DENTON, H. R.	8212060422	50-295 P	DICKKY, F.	8212220406*	50-311 S	DIGNAN, T. O.	8212140217	50-443 Q
DENTON, H. R.	8212060430*	50-295 P	DICKKY, F.	8212220424*	50-311 S	DIGNAN, T. O.	8212140217	50-443 Q
DENTON, H. R.	8212070170	50-289 Q	DICKHOFF, W. H.	8212270434*	50-358 A	DIGNAN, T. O.	8212140430	50-443 Q
DENTON, H. R.	8212080672	50-322 H	DIEDERICH, O. J.	8212020274	50-373 S	DIGNAN, T. O.	8212140430	50-443 Q
DENTON, H. R.	8212100074	50-219 D	DIEDERICH, O. J.	8212020294	50-373 S	DIGNAN, T. O.	8212140437*	50-443 Q
DENTON, H. R.	8212130358	50-352 Q	DIEDERICH, O. J.	8212020305	50-373 S	DIGNAN, T. O.	8212140441	50-443 Q
DENTON, H. R.	8212130359*	50-352 Q	DIEDERICH, O. J.	8212080308	50-373 S	DIGNAN, T. O.	8212140441	50-443 Q
DENTON, H. R.	8212160634	COMMISSION	DIEDERICH, O. J.	8212080318	50-373 S	DIGNAN, T. O.	8212140441	50-443 Q
DENTON, H. R.	8212220048*	50-282 F	DIEDERICH, O. J.	8212080400	50-373 S	DIGNAN, T. O.	8212210228	50-443 Q
DENTON, H. R.	8212270028	50-320 P	DIEDERICH, O. J.	8212080412	50-373 S	DIGNAN, T. O.	8212210228	50-443 Q
DERKS, P. S.	8212270186*	50-133 R	DIEDERICH, O. J.	8212080508	50-373 S	DIGNAN, T. O.	8212220255	50-443 Q
DESSY, R. P.	8212300004	50-312 Q	DIEDERICH, O. J.	8212100272	50-373 S	DIGNAN, T. O.	8212220255	50-443 Q
DETULLO, D.	8212210363*	50-391 Q	DIEDERICH, O. J.	8212130175	50-373 R	DILLON, P.	821210324*	50-286 P
DEVINCENTIS, J.	8212020029	50-443 A	DIEDERICH, O. J.	8212140067	50-373 S	DIRCKS, W. J.	8208010363*	FOIA
DEVINCENTIS, J.	8212020029	50-443 A	DIEDERICH, O. J.	8212140119	50-373 S	DIRCKS, W. J.	82082180082*	FOIA
DEVINCENTIS, J.	8212020286	50-443 A	DIEDERICH, O. J.	8212170123	50-373 S	DIRCKS, W. J.	8208300677*	FOIA
DEVINCENTIS, J.	8212020286	50-443 A	DIEDERICH, O. J.	8212170159	50-373 S	DIRCKS, W. J.	8204160262*	FOIA
DEVINCENTIS, J.	8212020334	50-443 A	DIEDERICH, O. J.	8212170184	50-373 S	DIRCKS, W. J.	8204160270*	FOIA
DEVINCENTIS, J.	8212020334	50-443 A	DIEDERICH, O. J.	8212170211	50-373 S	DIRCKS, W. J.	8208220059*	FOIA
DEVINCENTIS, J.	8212030194	50-443 A	DIEDERICH, O. J.	8212170214*	50-373 S	DIRCKS, W. J.	8209280513*	FOIA
DEVINCENTIS, J.	8212060056	50-443 A	DIEDERICH, O. J.	8212170233	50-373 S	DIRCKS, W. J.	8211170328	50-395 P
DEVINCENTIS, J.	8212060056	50-443 A	DIEDERICH, O. J.	8212170244	50-373 S	DIRCKS, W. J.	8212010327	SECY
DEVINCENTIS, J.	8212060059	50-443 E	DIEDERICH, O. J.	8212270140	50-373 S	DIRCKS, W. J.	8212020185	MISC
DEVINCENTIS, J.	8212060068	50-443 D	DIEDERICH, O. J.	8212270162	50-373 S	DIRCKS, W. J.	8212060052	MISC
DEVINCENTIS, J.	8212060075	50-443 A	DIEDERICH, O. J.	8212270175	50-373 S	DIRCKS, W. J.	8212060419	SECY
DEVINCENTIS, J.	8212060075	50-443 A	DIEDERICH, O. J.	8212270334	50-373 S	DIRCKS, W. J.	8212060509	40-86
DEVINCENTIS, J.	8212060094	50-443 A	DIEDERICH, O. J.	8212280195	50-373 S	DIRCKS, W. J.	8212070062	50-289 H
DEVINCENTIS, J.	8212060094	50-443 A	DIEDERICH, O. J.	8212280229	50-373 S	DIRCKS, W. J.	8212070378*	COMMISSION
DEVINCENTIS, J.	8212060151	50-443 A	DIEDERICH, O. J.	8212280447	50-373 S	DIRCKS, W. J.	8212070443*	50-298 Q

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
DIRCKS, W J	8212070452*	50-278 Q	DUBINSKI, L	8212160516*	40-6500	EISENHUT, D G	8212010014	50-456 A
DIRCKS, W J	8212080595	50-358 R	DUBINSKI, L	8212160583*	40-6500	EISENHUT, D G	8212010017*	50-456 A
DIRCKS, W J	8212090224*	FOIA	DUBOIS, D E	8212100271*	50-298 Q	EISENHUT, D G	8212010126*	50-390 A
DIRCKS, W J	8212100402	50-329 U	DUBRY, N L	8212280251*	50-315 Q	EISENHUT, D G	8212010169*	50-387 P
DIRCKS, W J	8212100398*	FOIA	DUBRY, N E	8212290335*	50-315 Q	EISENHUT, D G	8212030229*	TOPREP
DIRCKS, W J	8212130339	50-327 E	DUCK, J R	8212020269	50-259 J	EISENHUT, D G	8212030253	50-275 P
DIRCKS, W J	8212160008	PR	DUCK, J R	8212280222	50-321 J	EISENHUT, D G	8212060339*	50-280 F
DIRCKS, W J	8212220555	COMMISSION	DUCK, J R	8212280223	50-348 J	EISENHUT, D G	8212060340	50-275 P
DIRCKS, W J	8212270428	50-3 H	DUCK, J R	8212280261	50-259 J	EISENHUT, D G	8212070027	50-289 H
DIRCKS, W J	8212270432	MISC	DUCK, J R	8212280348	50-348 J	EISENHUT, D G	8212070444*	50-298 Q
DIRCKS, W J	8212270481	50-437 A	DUCK, J R	8212280369	50-321 J	EISENHUT, D G	8212080179	50-528 A
DIRCKS, W J	8212280509	FOIA	DUCK, J R	8212290150	50-327 J	EISENHUT, D G	8212080198*	50-528 A
DIRCKS, W J	8212280513*	FOIA	DUCK, J R	8212290246	50-259 J	EISENHUT, D G	8212080291*	50-204 G
DIRCKS, W J	8212270039*	FOIA	DUCK, J R	8212300109	50-327 J	EISENHUT, D G	8212080643	50-346 F
DISE, D P	8212100207	50-410 A	DUCK, J R	8212300202	50-250 J	EISENHUT, D G	8212080677	50-275 P
DITTO, S J	8212060399	ACRS	DUCK, J R	8212300243	50-250 J	EISENHUT, D G	8212100361	50-373 P
DIVINE, J M	8212130152	NUREG	DUCK, J R	8212300294	50-335 J	EISENHUT, D G	8212130281	50-275 P
DIVINE, J M	8212270145	NUREG	DUCK, J R	8212300300	50-438 J	EISENHUT, D G	8212130395	50-275 H
DIXON, D W	8212160734*	50-262 F	DUDNICK, C L	8212020279	PRM	EISENHUT, D G	8212140103	50-29 P
DIXON, D W	8212020340	50-395 F	DUDNICK, C L	8212020288*	PRM	EISENHUT, D G	8212140161*	FOIA
DIXON, D W	8212030060	50-395 S	DUFFEY, D W	8212280362	PT21	EISENHUT, D G	8212170013	50-373 F
DIXON, D W	8212030089	50-395 S	DUMMER, G H	8212060120*	CONTRACT	EISENHUT, D G	8212170014*	50-373 F
DIXON, D W	8212030108	50-395 S	DUNLAP, J H	8212030038*	50-244 Q	EISENHUT, D G	8212170038	50-275 P
DIXON, D W	8212030133	50-395 S	DUNLAP, J M	8212030090*	50-387 Q	EISENHUT, D G	8212170042	50-341 A
DIXON, D W	8212030164	50-395 S	DUNLAP, J H	8212210134*	50-277 Q	EISENHUT, D G	8212170057*	50-341 A
DIXON, D W	8212030186	50-395 S	DUNN, F E	8212270250*	50-537 A	EISENHUT, D G	8212170373	50-275 H
DIXON, D W	8212030188	50-395 S	DUPUISSEY, J F	8212200060	PRM	EISENHUT, D G	8212210544	50-263 P
DIXON, D W	8212070026*	50-395 Q	DUPONT, S O	8212030197*	50-234 Q	EISENHUT, D G	8212220045	50-282 F
DIXON, D W	8212070128	50-395 F	DURR, J	8212060217*	50-309 Q	EISENHUT, D G	8212220434	50-275 P
DIXON, D W	8212070181	50-395 P	DURR, J P	8212070136*	50-322 Q	EISENHUT, D G	8212220482	50-275 P
DIXON, D W	8212090243	50-395 S	DURR, J P	8212100064*	50-387 Q	EISENHUT, D G	8212230020	50-289 P
DIXON, D W	8212090366	50-395 S	DURR, J P	8212220218*	50-397 Q	EISENHUT, D G	8212230023	50-289 P
DIXON, D W	8212090392	50-395 Q	DUS, R	8212080413*	50-373 S	EISENHUT, D G	8212230030*	50-289 P
DIXON, D W	8212090422	50-395 S	DUS, R	8212170194*	50-373 S	EISENHUT, D G	8212230033*	50-289 P
DIXON, D W	8212090449	50-395 S	DUS, R	8212280215*	50-373 S	EISENHUT, D G	8212230041	50-275 P
DIXON, D W	8212090516*	50-395 Q	DUTTON, D E	8212280356	50-424 A	EISENHUT, D G	8212230045	50-275 P
DIXON, D W	8212100292	50-395 F	DUVAL, P A	8212130129*	71-6495	EISENHUT, D G	8212230047	50-275 P
DIXON, D W	8212150077	50-395 S	EAPEN, P K	8212030051*	50-336 Q	EISENHUT, D G	8212230058*	50-275 P
DIXON, D W	8212150089	50-395 S	EAPEN, P K	8212030200*	50-293 Q	EISENHUT, D G	8212230070	50-289 P
DIXON, D W	8212150097	50-395 S	EARLEY, A F	8208290121	FOIA	EISENHUT, D G	8212230299	50-219 F
DIXON, D W	8212150117	50-395 S	EARLEY, A F	8212020381	50-322 Q	EISENHUT, D G	8212270335	50-269 P
DIXON, D W	8212160322	50-395 F	EARLEY, A F	8212020381	50-322 Q	EISENHUT, D G	8212270338*	50-269 P
DIXON, D W	8212170237	50-395 P	ECKERT, J P	8212130067*	70-27	EISENHUT, D G	8212270363	50-346 P
DIXON, D W	8212170287	50-395 S	ECKHARDT, J	8212170281	50-361 S	EISENHUT, D G	8212270370*	50-346 P
DIXON, D W	8212200110	50-395 S	ECKHARDT, J H	8212130263*	50-362 Q	EISENHUT, D G	8212270396	50-312 P
DIXON, D W	8212220328	50-395 S	ECKHARDT, J H	8212210211*	50-528 Q	EISENHUT, D G	8212270399*	50-312 P
DIXON, D W	8212220374	50-395 S	ECONOMOS, C	82122070471	RES	EISENHUT, D G	8212270409	50-302 P
DIXON, D W	8212220411	50-395 S	ECONOMOS, N	8212090324*	50-413 Q	EISENHUT, D G	8212270411*	50-302 P
DIXON, D W	8212220428	50-395 S	EDDINGS, M	8212290164*	50-327 R	EISENHUT, D G	8212270421	50-313 P
DIXON, D W	8212220498	50-395 S	EDDLERMAN, W	8212020238	PR	EISENHUT, D G	8212270423	50-437 A
DIXON, D W	8212230288	50-395 P	EDDLERMAN, W	8212160209	PRM	EISENHUT, D G	8212270424	50-358 A
DIXON, D W	8212300035	50-395 S	EDELMAN, H R	8212070237	50-440 A	EISENHUT, D G	8212270425*	50-437 A
DOBBS, C A	8212020100	RES	EDELMAN, H R	8212070363*	50-440 Q	EISENHUT, D G	8212270427*	50-313 P
DOBBS, C A	8212020104	RES	EDELMAN, H R	8212070397	50-440 E	EISENHUT, D G	8212270466*	50-344 F
DODA, R J	8212080514	I&E	EDELMAN, H R	8212170153	50-440 S	EISENHUT, D G	8212280495	50-275 P
DODA, R J	8212200069	I&E	EDELMAN, H R	8212170241	50-440 S	EISENHUT, D G	8212280504	50-267 P
DODDS, R T	8212060178*	50-243 Q	EDELMAN, H R	8212210370	50-440 S	EISENHUT, D G	8212300188*	50-416 P
DODDS, R T	8212060208*	50-397 Q	EDELMAN, H R	8212280295	50-440 A	EISENHUT, D G	8212300335	50-289 P
DODDS, R T	8212060264*	50-508 Q	EDELMAN, H R	8212280271	50-440 S	ELDRID, D T	8212100287*	50-346 S
DODDS, R T	8212060274*	50-508 Q	EDELMAN, H R	8212290189	50-440 E	ELDRID, D T	8212170285*	50-346 S
DODDS, R T	8212060391*	50-344 Q	EDELMAN, H R	8212290305	50-440 E	ELDRID, D T	8212280290*	50-346 S
DODDS, R T	8212130270*	50-27 Q	EDELMAN, H R	8212290325	50-440 E	ELLERSHAN, L E	8212210141*	QA999
DODDS, R T	8212170361*	50-508 Q	EDELSTEIN, B	8212300155	XPORTLIC	ELLERSHAN, L E	8212300032*	QA999
DODDS, R T	8212170370*	50-508 Q	EDELSTEIN, B	8212300198	XPORTLIC	ELLITTT, J M	8212080079*	FOIA
DODDS, R T	8212210193*	50-508 Q	EDELSTEIN, B	8212300163	XPORTLIC	ELLITTT, J M	8212080137*	FOIA
DODDS, R T	8212210427*	50-397 Q	EDELSTEIN, B	8212300164	XPORTLIC	ELLIS, J	8212230182	50-445 Q
DODDS, R T	8212280301*	50-508 Q	EDELSTEIN, B	8212300166	XPORTLIC	ELLIS, J	8212230195	50-445 Q
DOERFLER, L T	8212030078*	50-333 Q	EDELSTEIN, B	8212300169	XPORTLIC	ELLIS, J	8212300009	50-445 Q
DOESBRO, J M	8212220238	NUREG	EDELSTEIN, B	8212300180	XPORTLIC	ELLIS, J	8212300045	50-445 Q
DOHERTY, D F	8212020378	PR	EDELSTEIN, B	8212300181	XPORTLIC	ELLIS, J S	8212270196	50-322 Q
DOOLITTLE, E L	8212080121	50-546 A	EDGAR, O L	8212060113	50-537 Q	ELLIS, T S	8212270194	50-322 Q
DORSEY, M	8212270470	CONTRACT	EDGAR, O L	8212090082	50-537 Q	ELLYSON, C	8212070484	XPORTLIC
DOUGHTY, J	8212020366	PR	EDGAR, O L	8212200015	50-537 Q	ELRICK, R M	8212130283	NUREG
DOUGHTY, J	8212160321	50-443 Q	EDGAR, O L	8212300011	50-537 Q	ELROD, S A	8212090337*	50-335 Q
DOHNEY, T	8212230276	50-247 U	EDISON, O E	8212020005	50-482 A	ELROD, S A	8212090562*	50-335 Q
DRAOD, J P	8212270435	NUREG	EDLER, S K	8212270449	NUREG	ELROD, S A	8212090564*	50-335 Q
DRACONETTE, K.	8212010227	WASTE MOT	EDWARDS, D L	8212270401	40-3483	ELSAW, T	8212140337*	50-423 Q
DRACONETTE, K S	8212290008	WASTE MOT	ETCH, E	8212280221*	50-247 R	ELSAW, T C	8212140084*	50-213 Q
DREY, L A	8212140486*	50-259 H	ETDRON, A F	8212220228	NUREG	EMCH, R	8212070117	50-155 P
DRYFOOS, R J	8212230241	50-247 Q	EISENHUT, D G	8212280518	RES	EMPEY, D C	8212280373*	50-410 S
DRYSDALE, J A	8212220249	NUREG	EISENHUT, D G	8010170283*	50-206 P	ENSHWILLER, J R	8212060450	FOIA
DUBINSKI, L	8212160082*	40-6500	EISENHUT, D G	8205270590*	FOIA	ENGBRECHT, L	8212080251	50-266 Q
DUBINSKI, L	8212160123*	40-6500	EISENHUT, D G	8208190263	50-3 P	ENGELBERG, T C	8212090489*	70-824
DUBINSKI, L	8212160284*	40-6500	EISENHUT, D G	8211120486	MISC	ENGELKEN, R H	8212170088	50-397 Q
DUBINSKI, L	8212160388*	40-6500	EISENHUT, D G	8211230066	50-219 P	ENGELKEN, R H	8212170383*	50-206 Q

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
ENGELKEN, R. H.	8212210180	50-344 Q	FEINBERG, J. D.	8212070246	50-247 Q	FELTON, J. H.	8212230152	50-313 F
ENGELKEN, R. H.	8212210189	50-308 Q	FEITHNECHT, C.	8212070204	50-334 R	FELTON, J. H.	8212230166	FOIA
ENGELMANN, J. H.	8212200016	PR	FELICETTI, S. A.	8212010109	RES	FELTON, J. H.	8212230369	50-331 F
ENGELMANN, R.	8212170438	40-8348	FELL, R. A.	8212060308*	50-397 Q	FELTON, J. H.	8212270003	50-395 F
ENGLE, L. B.	8212270407	50-338 P	FELTON, J. H.	8212010012	FOIA	FELTON, J. H.	8212270013	50-382 F
ENGLE, L. B.	8212270490	50-338 P	FELTON, J. H.	8212010029	FOIA	FELTON, J. H.	8212270023	FOIA
EPFLER, E. P.	8212030280	ACRS	FELTON, J. H.	8212010033	50-315 F	FELTON, J. H.	8212270036	FOIA
EPFLER, E. P.	8212030280	ACRS	FELTON, J. H.	8212010042	50-317 F	FELTON, J. H.	8212270039	50-322 A
EPFLER, E. P.	8212060325	ACRS	FELTON, J. H.	8212010061	50-112 F	FELTON, J. H.	8212270048	FOIA
EPFLER, E. P.	8212060325	ACRS	FELTON, J. H.	8212010071	50-150 F	FELTON, J. H.	8212270062	50-244 S
EPSTEIN, E.	8212160493*	FOIA	FELTON, J. H.	8212010092	50-320 F	FELTON, J. H.	8212270078	70-143
EPSTEIN, M.	8212270254*	50-537 A	FELTON, J. H.	8212010348	FOIA	FELTON, J. H.	8212270306	FOIA
ERICKSON, B.	8212080056*	FOIA	FELTON, J. H.	8212010361	50-322 A	FELTON, J. H.	8212270315	50-358 H
ERICKSON, B.	8212080142*	FOIA	FELTON, J. H.	8212010446	FOIA	FELTON, J. H.	8212270328	FOIA
ERICKSON, P. B.	8212020123	50-213 F	FELTON, J. H.	8212020008	FOIA	FELTON, J. H.	8212270366	50-148 H
ERICKSON, P. B.	8212140210	50-213 F	FELTON, J. H.	8212030268	50-254 F	FELTON, J. H.	8212270418	50-327 Q
ETHERINGTON, E.	8212220438*	50-275 P	FELTON, J. H.	8212030283	50-10 F	FELTON, J. H.	8212280009	40-1478
ETHERINGTON, H.	8212020048	ACRS	FELTON, J. H.	8212030291	50-309 F	FELTON, J. H.	8212280032	FOIA
FURY, L. W.	8212060069	50-261 P	FELTON, J. H.	8212060395	50-320 P	FELTON, J. H.	8212280512	FOIA
FURY, L. W.	8212100082	50-324 P	FELTON, J. H.	8212060413	FOIA	FELTON, J. H.	8212280520	FOIA
FURY, L. W.	8212140255	50-324 P	FELTON, J. H.	8212060424	FOIA	FELTON, J. H.	8212280527	50-148 P
FURY, L. W.	8212150004	50-261 P	FELTON, J. H.	8212060440	FOIA	FELTON, J. H.	8212290007	50-361 K
FURY, L. W.	8212170338	50-324 P	FELTON, J. H.	8212060453	FOIA	FELTON, J. H.	8212290009	50-322 A
FURY, L. W.	8212170355	50-324 P	FELTON, J. H.	8212070408	FOIA	FELTON, J. H.	8212290015	50-322 A
FURY, L. W.	8212210004	50-324 P	FELTON, J. H.	8212070414	50-295 P	FELTON, J. H.	8212290019	FOIA
EVANS, C. D.	8212090521*	50-338 Q	FELTON, J. H.	8212070425	50-267 F	FELTON, J. H.	8212290025	50-322 K
EVANS, L. J.	8212080008*	FOIA	FELTON, J. H.	8212080006	70-143	FELTON, J. H.	8212290030	50-206 Q
EVANS, L. J.	8212080061*	FOIA	FELTON, J. H.	8212080057	50-275 F	FELTON, J. H.	8212290036	50-440 A
EVANS, L. J.	8212080066*	FOIA	FELTON, J. H.	8212080074	50-313 F	FELTON, J. H.	8212290060	50-244 S
EVANS, L. J.	8212080101*	FOIA	FELTON, J. H.	8212080089	50-315 F	FELTON, J. H.	8212290083	50-295 F
EVANS, L. J.	8212080116*	FOIA	FELTON, J. H.	8212080100	50-259 F	FELTON, J. H.	8212290098	50-295 F
EVANS, L. J.	8212080133*	FOIA	FELTON, J. H.	8212080630	50-346 F	FELTON, J. H.	8212290295	50-3 F
EVANS, L. J.	8212080161*	FOIA	FELTON, J. H.	8212090027	50-358 F	FELTON, J. H.	8212290509	50-295 F
EVANS, L. J.	8212080167*	FOIA	FELTON, J. H.	8212090048	FOIA	FELTON, J. H.	8212300167	50-10 F
EVANS, L. J.	8212100168*	FOIA	FELTON, J. H.	8212100051	FOIA	FELTON, J. H.	8212300204	50-317 F
EVANS, L. J.	8212100185*	FOIA	FELTON, J. H.	8212100053	FOIA	FELTON, J. H.	8212300400	50-254 F
EVANS, L. J.	8212100189*	FOIA	FELTON, J. H.	8212100084	FOIA	FELTON, J. H.	8212300407	50-387 F
FABRY, J.	8212130185*	50-400 A	FELTON, J. H.	8212100105	50-443 A	FELTON, J. H.	8212300412	50-282 F
FALCONER, D.	8212090189*	50-269 Q	FELTON, J. H.	8212100111	70-143	FERRARRO, R. L.	8212170100*	50-397 Q
FARLEY, E. R.	8212030282*	40-3453	FELTON, J. H.	8212100362	FOIA	FERRARRO, R.	8212230276	50-247 U
FARMER, F. G.	8212020086	50-409 P	FELTON, J. H.	8212100374	FOIA	FICKETT, K.	8212230159	FOIA
FARRELL, R. E.	8212170121*	50-295 Q	FELTON, J. H.	8212100380	50-313 F	FIEDLER, P. B.	8212060148	50-219 S
FARRELL, R. E.	8212290348*	50-254 Q	FELTON, J. H.	8212100381	FOIA	FIEDLER, P. B.	8212060332	50-219 Q
FARRELL, R. E.	8212270365*	50-440 Q	FELTON, J. H.	8212100387	FOIA	FIEDLER, P. B.	8212080240	50-219 S
FASANO, A.	8212070111*	50-320 Q	FELTON, J. H.	8212100395	FOIA	FIEDLER, P. B.	8212080349	50-219 S
FASANO, A.	8212140319*	50-320 Q	FELTON, J. H.	8212100399	50-344 F	FIEDLER, P. B.	8212080354*	50-219 Q
FASANO, A.	8212200471*	50-289 Q	FELTON, J. H.	8212100408	FOIA	FIEDLER, P. B.	8212080388	50-219 S
FASANO, A.	8212270233	50-330 S	FELTON, J. H.	8212100412	FOIA	FIEDLER, P. B.	8212080511	50-219 S
FASANO, A.	8212210195*	50-508 Q	FELTON, J. H.	8212130017	50-10 F	FIEDLER, P. B.	8212080556	50-219 Q
FAULKENBERRY, B.	8212202076	50-266 S	FELTON, J. H.	8212130132	50-346 F	FIEDLER, P. B.	8212130306	50-219 F
FAY, C. W.	8212020281*	50-266 S	FELTON, J. H.	8212130149	50-295 F	FIEDLER, P. B.	8212140169	50-219 S
FAY, C. W.	8212100208	50-301 S	FELTON, J. H.	8212130326	50-298 F	FIEDLER, P. B.	8212150270	71-9151
FAY, C. W.	8212100211*	50-301 S	FELTON, J. H.	8212130352	50-286 F	FIEDLER, P. B.	8212210019	50-219 P
FAY, C. W.	8212100322*	50-266 Q	FELTON, J. H.	8212140001	50-10 P	FIEDLER, P. B.	8212210040	50-219 R
FAY, C. W.	8212100223*	50-266 Q	FELTON, J. H.	8212150181	50-277 F	FIEDLER, P. B.	8212210372	50-219 S
FAY, C. W.	8212100234	50-266 S	FELTON, J. H.	8212150248	50-243 F	FIEDLER, P. B.	8212210468*	50-219 Q
FAY, C. W.	8212100225*	50-266 S	FELTON, J. H.	8212150272	50-313 F	FIEDLER, P. B.	8212210555*	50-219 F
FAY, C. W.	8212170161	50-266 S	FELTON, J. H.	8212150301	50-346 F	FIEDLER, P. B.	8212280010	71-5957
FAY, C. W.	8212170172*	50-266 S	FELTON, J. H.	8212150323	50-315 F	FIEDLER, P. B.	8212280218	50-219 Q
FAY, C. W.	8212170326*	50-266 P	FELTON, J. H.	8212160080	40-6500	FIEDLER, P. B.	8212280313	50-219 P
FAY, C. W.	8212210056	50-266 P	FELTON, J. H.	8212160091	50-346 F	FIEDLER, P. B.	8212290127	50-219 R
FAY, C. W.	8212210297	50-266 R	FELTON, J. H.	8212160731	50-262 F	FIEDLER, P. B.	8212290410*	50-219 Q
FAY, C. W.	8212210299*	50-266 R	FELTON, J. H.	8212160745	50-320 F	FIEDLER, J.	8212020335	50-250 J
FAY, C. W.	8212220422	50-266 P	FELTON, J. H.	8212160772	50-313 F	FIELDS, H. C.	8212030139*	50-395 S
FAY, C. W.	8212270125	50-266 P	FELTON, J. H.	8212170012	50-313 F	FIELDS, H. C.	8212090253*	50-395 S
FAY, C. W.	8212270177	50-266 S	FELTON, J. H.	8212170036	50-280 F	FIELDS, H. C.	8212090438*	50-395 S
FAY, C. W.	8212270202*	50-266 S	FELTON, J. H.	8212170053	50-335 F	FIELDS, H. C.	8212170291*	50-395 S
FAY, C. W.	8212270237	50-266 S	FELTON, J. H.	8212170104	50-259 F	FIELDS, H. C.	8212204624*	50-395 S
FAY, C. W.	8212270246*	50-266 S	FELTON, J. H.	8212170445	50-313 F	FIELDS, J. A.	8212200189	CONTRACT
FAY, C. W.	8212280114	50-301 S	FELTON, J. H.	8212170454	50-280 F	FIELDS, J. A.	8212130155	CONTRACT
FAY, C. W.	8212280115*	50-301 S	FELTON, J. H.	8212210508	50-313 F	FIELDS, J. A.	8212130178	CONTRACT
FAY, C. W.	8212280158	50-266 S	FELTON, J. H.	8212210526	50-313 F	FIELDS, J. A.	8212160593	CONTRACT
FAY, C. W.	8212280162*	50-266 S	FELTON, J. H.	8212210541	50-358 F	FIELDS, J. A.	8212270410	CONTRACT
FAY, C. W.	8212280361	50-266 Q	FELTON, J. H.	8212210550	50-219 F	FIELDS, J. A.	8212270415	CONTRACT
FAY, C. W.	8212290095	50-266 P	FELTON, J. H.	8212210576	50-245 F	FIELDS, J. A.	8212270527	CONTRACT
FAY, C. W.	8212290143	50-266 P	FELTON, J. H.	8212220001	50-313 F	FIELDS, J. A.	8212270539	CONTRACT
FAY, C. W.	8212290253	50-266 R	FELTON, J. H.	8212220037	50-3 F	FIELDS, J. A.	8212270555	CONTRACT
FAY, C. W.	8212290257*	50-266 R	FELTON, J. H.	8212220175	50-10 F	FIELDS, J. A.	8212280445	CONTRACT
FAY, C. W.	8212290262*	50-266 R	FELTON, J. H.	8212220298	50-346 F	FIELDS, J. A.	8212280469	CONTRACT
FAY, C. W.	8212290300	50-266 P	FELTON, J. H.	8212220315	50-409 F	FIELDS, J. A.	8212280486	CONTRACT
FAY, C. W.	8212290322	50-266 S	FELTON, J. H.	8212230019	50-10 F	FIELDS, J. A.	8212280494	50-329 A
FAY, C. W.	8212290327*	50-266 S	FELTON, J. H.	8212230046	50-309 F	FIELDS, J. A.	8212290053	CONTRACT
FE, W. F.	8212280119	50-213 F	FELTON, J. H.	8212230067	50-369 F	FILBURN, T.	8212030204*	50-336 S
FEHRINGER, D. J.	8212020171	WASTE MOT	FELTON, J. H.	8212230093	50-269 F	FINAMORE, B. A.	8212080257	50-537 Q
FEIERABEND, C. D.	8212030150*	50-282 Q	FELTON, J. H.	8212230142	FOIA	FINAMORE, B. A.	8212230200	50-537 Q

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
FINAMORE, B A	8212230200	50-537 Q	FRALEY, R F	8212130273*	50-275 P	GARRITY, J H	8212220396*	50-309 Q
FINCH, G L	8212220046*	50-3 F	FRANTZ, S P	8212220448*	50-275 P	GARRITY, J H	8212270291*	50-309 B
FINDLAY, J A	8212010144	NUREQ	FRANTZ, S P	8212270438*	FOIA	GARY, R J	8212140298	50-445 F
FINK, S	8212230270	50-247 Q	FRANTZ, S P	8212270448*	FOIA	GARY, R J	8212150166	50-445 K
FINKEL, A E	8212030221*	50-289 Q	FRANTZ, S P	8212270457*	FOIA	GARY, R J	8212170337	50-445 K
FIDORELLI, G	8212130215*	50-528 Q	FRANTZ, S P	8212280289	50-522 Q	GARY, R J	8212170342*	50-445 E
FISH, H	8212230276	50-247 U	FRANTZ, S P	8212280289	50-522 Q	GARY, R J	8212210391	50-445 K
FISH, R F	8212210185*	50-344 Q	FREEMAN, M S	8212020061*	50-416 S	GARY, R J	8212280267	50-445 K
FITZSIMMONS, M	8212170101*	50-277 P	FREEMAN, M S	8212090113*	50-416 S	GARY, R J	8212280329	50-445 Q
FLACK, E	8212170170	50-247 Q	FREEMAN, M S	8212090164*	50-416 S	GATCH, F B	8212230081	NUREQ
FLACK, D	8212020268	PRM	FREEMAN, M S	8212090344*	50-416 S	GATES, T E	8212270456	NUREQ
FLEENOR, C	8212270484	50-537 A	FREEMAN, M S	8212170213*	50-416 S	GAUL, A J J	8212150072*	50-231 P
FLEENOR, C M	8212220019	CONTRACT	FREEMAN, M S	8212170339*	50-416 S	GAYNOR, R K	8212010476	27-39
FLEISHER, Z S	8212070209	50-247 Q	FREEMAN, M S	8212290149	40-8768	GEARS, O E	8212160531	50-278 P
FLEISHER, Z S	8212070213	50-247 Q	FREEMAN, S	8212100306*	50-416 S	GENTILE, A B	8212160323*	FOIA
FLEISHER, Z S	8212220293	50-247 Q	FREEMAN, S	8212210192*	50-416 S	GENTILLON, C D	8212020095	50-155 P
FLEISHER, Z S	8212300191	50-247 Q	FREEMAN, S	8212140187*	50-29 S	GEORGE, R L	8212210217	MISC
FLEISHER, Z S	8212300197	50-247 Q	FRENCH, L D	8212150160*	50-29 S	GERDEMAN, F W	8212102241	40-8698
FLEISHER, Z S	8212300201*	50-247 Q	FRIDLANDER, M	8212230241	50-247 Q	GERDEMAN, F W	8212270319	40-8698
FLENNING, T E	8212030252	40-299	FRITZ, E J	8212300051	50-440 Q	GERDEMAN, F W	8212270340	40-8698
FLEMING, T E	8212070045	40-8698	FRYE, J H	8212060236	50-142 Q	GERDEMAN, F W	8212300120	40-8698
FLEMING, T E	8212230079	WASTE HOT	FRYE, J H	8212300022	50-70 Q	GERDES, A G	8212230241	50-231 Q
FLEMING, T E	8212280093	40-8698	FURMAN, G R	8212060149	50-317 B	GERNER, L	8212030273*	50-234 F
FLOCK, E	8212140519	1&E	FURMAN, G R	8212080436	50-317 B	GERSTNER, H C	8212020088	50-461 A
FLORY, C A	8212020177	WASTE HOT	FULLER, C	8212200128*	50-267 S	GERSTNER, H C	8212280125	50-461 A
FLORY, C A	8212230394	WASTE HOT	FULLER, C	8212290303*	50-267 S	GERTMAN, D I	8212130108	NUREQ
FLOYD, J M	8212090075*	50-416 S	FULLER, C	8212290410*	50-267 S	GERTSCH, A J	8212290196*	50-313 R
FLOYD, J M	8212090158*	50-416 S	FURCAL, D T	8212060486	NUREQ	GERUSKY, T M	8212160394	PR
FLOYD, J M	8212090184*	50-416 S	FURR, B J	8212290200	50-261 P	GIBBONS, T D	8212090407*	50-370 Q
FLOYD, J M	8212170146*	50-416 S	GAD, R K	8212140212	50-443 Q	GIBBONS, T D	8212090465*	50-413 Q
FLOYD, J M	8212170227*	50-416 S	GAD, R K	8212140212	50-443 Q	GIBSON, A F	8212090252	70-824
FLOYD, J M	8212280037*	50-416 S	GAD, R K	8212140217	50-443 Q	GIBSON, A F	8212090263	70-1201
FLOYD, J M	8212280198*	50-416 S	GAD, R K	8212140217	50-443 Q	GIBSON, A F	8212090264	70-1113
FLOYD, J M	8212280389*	50-416 S	GAD, R K	8212140430	50-443 Q	GIBSON, A F	8212090266	70-1151
FLYNN, M J	8212060297	CONTRACT	GAD, R K	8212140430	50-443 Q	GIBSON, A F	8212090292	70-824
FLYNN, M J	8212170398	CONTRACT	GAD, R K	8212140441	50-443 Q	GIBSON, A F	8212090333	70-1201
FLYNN, M J	8212220018	CONTRACT	GAD, R K	8212140441	50-443 Q	GIBSON, A F	8212090402	70-143
FLYNN, M J	8212270419	CONTRACT	GAD, R K	8212210228	50-443 Q	GIBSON, A F	8212090408	70-143
FLYNN, S F	8212230366	50-400 Q	GAD, R K	8212210228	50-443 Q	GIBSON, A F	8212090428	70-1151
FOBES, R L	8212060371*	50-255 S	GAD, R K	8212220255	50-443 Q	GIBSON, A F	8212090430	70-27
FOBES, R L	8212060382*	50-255 S	GAD, R K	8212220255	50-443 Q	GIBSON, A F	8212090447	50-332 Q
FOBES, R L	8212060392*	50-255 S	GAD, R K	8212220255	50-443 Q	GIBSON, A F	8212090477	70-824
FOBES, R L	8212060396*	50-255 S	GAD, R K	8212220255	50-443 Q	GIBSON, A F	8212090499*	70-824
FOBES, R L	8212060412*	50-255 S	GAD, R K	8212220255	50-443 Q	GIBSON, A F	8212090507	70-143
FOBES, R L	8212060421*	50-255 S	GAD, R K	8212220255	50-443 Q	GIBSON, A F	8212090533	70-143
FOBES, R L	8212060431*	50-255 S	GAD, R K	8212220255	50-443 Q	GIBSON, A F	8212090547	70-1151
FOBES, R L	8212270454	NUREQ	GAD, R K	8212220255	50-443 Q	GIBSON, A F	8212130062	70-27
FOLEY, M O	8212220238	NUREQ	GAD, R K	8212220255	50-443 Q	GIBSON, A F	8212130071*	70-27
FULEY, T	8212140140*	50-247 Q	GAD, R K	8212220255	50-443 Q	GIBSON, A F	8212150138	70-143
FONNER, R L	8212100011	70-143	GAD, R K	8212220255	50-443 Q	GIBSON, A F	8212270128*	70-143
FONNER, R L	8212280189*	WASTE HOT	GAD, R K	8212220255	50-443 Q	GIBSON, A F	8212290137*	FOIA
FONTANA, L	8212160321*	50-382 Q	GAD, R K	8212220255	50-443 Q	GIBSON, A F	8212290165*	FOIA
FONTANA, L	8212160321*	50-382 Q	GAD, R K	8212220255	50-443 Q	GIBSON, A F	8212290184*	FOIA
FOOTE, H P	8212270312	NUREQ	GAD, R K	8212220255	50-443 Q	GIBSON, J	8212290142*	50-336 R
FORD, E J	8212090384*	50-327 Q	GAD, R K	8212220255	50-443 Q	GIBSON, L S	8212280029	PR
FORD, J T	8212230025	70-1201	GAD, R K	8212220255	50-443 Q	GIESEKE, J A	8212270420	NUREQ
FORNEY, W L	8212100308*	50-454 Q	GAD, R K	8212220255	50-443 Q	GIESLER, C W	8212030076	50-305 J
FOSTER, W E	8212070434*	GA999	GAD, R K	8212220255	50-443 Q	GIESLER, C W	8212060049*	50-305 Q
FOSTER, W E	8212270213*	GA999	GAD, R K	8212220255	50-443 Q	GIESLER, C W	8212060090	50-305 S
FOUCHARD, J J	8008260700*	FOIA	GAD, R K	8212220255	50-443 Q	GIESLER, C W	8212070149	50-305 P
FOUCHARD, J J	8212010091*	FOIA	GAD, R K	8212220255	50-443 Q	GIESLER, C W	8212070333	50-305 P
FOUCHARD, J J	8212010102*	FOIA	GAD, R K	8212220255	50-443 Q	GIESLER, C W	8212090257	50-305 F
FOUCHARD, J J	8212010108*	FOIA	GAD, R K	8212220255	50-443 Q	GIESLER, C W	8212140143	50-305 P
FOUCHARD, J J	8212010123*	FOIA	GAD, R K	8212220255	50-443 Q	GIESLER, C W	8212140407	50-305 P
FOUCHARD, J J	8212010143*	FOIA	GAD, R K	8212220255	50-443 Q	GIESLER, C W	8212160003	50-305 P
FOUCHARD, J J	8212010149*	FOIA	GAD, R K	8212220255	50-443 Q	GIESLER, C W	8212170167	50-305 B
FOUCHARD, J J	8212010230*	FOIA	GAD, R K	8212220255	50-443 Q	GIESLER, C W	8212210181	50-305 P
FRAMM, R	8210210095*	50-311 S	GAD, R K	8212220255	50-443 Q	GIESLER, C W	8212270007*	50-305 F
FRAMM, R	8212060174*	50-311 S	GAD, R K	8212220255	50-443 Q	GIESLER, C W	8212270197	50-305 F
FRAMM, R	8212060214*	50-311 S	GAD, R K	8212220255	50-443 Q	GIESLER, C W	8212280193	50-305 F
FRAMM, R	8212060298*	50-272 S	GAD, R K	8212220255	50-443 Q	GIESLER, C W	8212280230	50-305 F
FRAMM, R	8212060308*	50-272 S	GAD, R K	8212220255	50-443 Q	GIESLER, C W	8212280318	50-305 P
FRAMM, R	8212060316*	50-272 S	GAD, R K	8212220255	50-443 Q	GIESLER, C W	8212280467	50-305 R
FRAMM, R	8212080364*	50-272 S	GAD, R K	8212220255	50-443 Q	GIESLER, C W	8212290211	50-305 R
FRAMM, R	8212080442*	50-311 S	GAD, R K	8212220255	50-443 Q	GIFFORD, L S	8212200041	50-447 A
FRAMM, R	8212140060*	50-272 S	GAD, R K	8212220255	50-443 Q	GILBERT, L D	8212030058*	50-482 Q
FRAMM, R	8212140082*	50-272 S	GAD, R K	8212220255	50-443 Q	GILCHRIST, J E	8212210536	40-8054
FRAMM, R	8212140085*	50-311 S	GAD, R K	8212220255	50-443 Q	GILDENHORN	8212080070	CONTRACT
FRAMM, R	8212140107*	50-311 S	GAD, R K	8212220255	50-443 Q	GILDENHORN, A J	8212220025	CONTRACT
FRAMM, R	8212160054*	50-311 S	GAD, R K	8212220255	50-443 Q	GILDENHORN, A J	8212270510	CONTRACT
FRAMM, R	8212160390*	50-311 S	GAD, R K	8212220255	50-443 Q	GILDNER, H L	8212290417*	50-440 Q
FRAMM, R	8212160414*	50-311 S	GAD, R K	8212220255	50-443 Q	GILINSKY, V	8212020023*	FOIA
FRAMM, R	8212220310*	50-272 S	GAD, R K	8212220255	50-443 Q	GILL, A	8212230248*	50-29 P
FRAMM, R	8212220385*	50-311 S	GAD, R K	8212220255	50-443 Q	GILLEN, D H	8212010295	40-4492
FRAMM, R	8212220435*	50-311 S	GAD, R K	8212220255	50-443 Q	GILLEN, D H	8212020001	40-8681

PERSONAL AUTHOR INDEX

433

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
GILLEN, D H	8212030228	40-8681	GRABER, L	8209150055	FOIA	GRESCH, O L	8212020355	50-382 Q
GILLEN, D H	8212030238	40-8681	GRABER, L	8212010314	FOIA	GRESCH, O L	8212230361	50-382 Q
GILLEN, D H	8212030244	40-8681	GRABER, L	8212100404	FOIA	GRSS, M E	8212100356	FOIA
GILLEN, D H	8212030251	40-8681	GRABER, L	8212280033	FOIA	GRSSMAN, H	8212020344	50-460 Q
GILLESPIE, F F	8212080149*	FOIA	GRABER, L	8212290014	FOIA	GRSSMAN, H	8212020350	50-397 Q
GILLET, H T	8212200063*	50-316 R	GRAESSER, K L	8212020234	50-295 S	GRSSMAN, H	8212020360	50-460 Q
GILLET, H T	8212200122*	50-315 R	GRAESSER, K L	8212020272	50-295 S	GRSSMAN, H	8212080272	50-460 Q
GILLET, H T	8212290228*	50-316 R	GRAESSER, K L	8212140055	50-295 S	GRSSMAN, H	8212200104	50-397 Q
GILLET, H T	8212290424*	50-315 R	GRAESSER, K L	8212140321	50-295 S	GRUTENHUIS, H	8212070492	50-305 P
GILLET, H T	8212290428*	50-315 R	GRAESSER, K L	8212170307	50-295 S	GRUBER, E E	8212270280*	50-537 A
GILLEY, E R	8212070429*	CONTRACT	GRAESSER, K L	8212280244	50-295 S	GUCHA, L T	8212090127	50-321 Q
GILMAN, B	8212230276	50-247 U	GRAESSER, K L	8212280432	50-295 S	GUCHA, L T	8212090492	50-321 Q
GJNEVAN, H E	8212060429	NUREQ	GRAESSER, K L	8212280450	50-295 S	GUCHA, L T	8212290131	50-321 P
GINSBERG, T	8212070400	RES	GRAHN, D	8212060429	NUREQ	GUHN, H A	8212080017*	FOIA
GJRRAD, E H	8212090536*	50-43B Q	GRAHN, R A	8212210282*	50-443 Q	GUILBERT, D E	8212280401*	QA999
GIRI, A H	8212080516	RES	GRANT, W B	8212020314*	50-294 Q	GUILD, R	8212280132	50-413 Q
GLASBROCK, R B	8210270016*	50-397 A	GRANT, W B	8212060252*	50-409 Q	GUILD, R	8212280132	50-413 Q
GLASBROCK, H	8212230339	50-440 Q	GRANT, W B	8212100023*	50-263 Q	GUILD, R	8212280132	50-413 Q
GLEASON, J P	8212020321	50-247 Q	GRANT, W B	8212280062*	50-295 Q	GUILD, R	8212280132	50-413 Q
GLEASON, J P	8212060241	50-247 Q	GRAVES, R H	8212080449	50-213 S	GUILD, R	8212280138	50-413 Q
GLEASON, J P	8212090093	50-483 Q	GRAVES, R H	8212150222	71-6574	GUILD, R	8212280138	50-413 Q
GLEASON, J P	8212100103	50-247 Q	GRAY, E H	8212070267*	50-352 Q	GULDEMOND, W	8212030028*	50-373 Q
GLEASON, J P	8212130177	50-483 Q	GRAY, J R	8212010032	50-289 Q	GULDEMOND, W	8212100261	50-373 S
GLEASON, J P	8212130208	50-247 Q	GRAY, J R	8212030210	50-289 Q	GUPPY, J O	8212030323	50-537 A
GLEASON, J P	8212180026	50-483 Q	GRAY, J R	8212090242	50-289 Q	GUPPY, J O	8212270534	RES
GLEASON, J P	8212200097	50-247 Q	GRAY, J R	8212270008	50-289 Q	GURCAK, A W	8212160365	TOPREP
GLEASON, J P	8212230181	50-247 Q	GREEN, H J	8212020114	50-296 S	GUSTAVE, R P	8212080024*	CONTRACT
GLEASON, J P	8212230188	50-247 Q	GREEN, H J	8212030143	50-260 S	GUSTAVE, R P	8212080022	CONTRACT
GLEASON, J P	8212270204	50-483 T	GREEN, H J	8212020179	50-328 S	GUSTAVE, R P	8212020057*	50-354 Q
GLEASON, J P	8212300012	50-247 Q	GREEN, H J	8212020240	50-296 S	GUSTAVE, R P	8212030243*	CONTRACT
GLEASON, J P	8212300014	50-247 Q	GREEN, H J	8212020261	50-296 S	GUSTAVE, R P	8212030266*	CONTRACT
GOODARD, R J	8212060002	50-814 Q	GREEN, H J	8212020348	50-259 S	GUSTAVE, R P	8212050568*	50-443 A
GOODARD, R J	8212210011	50-155 Q	GREEN, H J	8212030039	50-259 S	GUSTAVE, R P	8212100162*	CONTRACT
GOODARD, R J	8212220119	50-461 Q	GREEN, H J	8212030086	50-327 S	GUSTAVE, R P	8212130160*	CONTRACT
GOODARD, R J	8212300176	50-155 Q	GREEN, H J	8212090109	50-259 S	GUSTAVE, R P	8212220528*	CONTRACT
GOODY, A T	8212030038*	50-244 Q	GREEN, H J	8212090143	50-260 S	GUSTAVE, R P	8212220535*	CONTRACT
GOODY, A T	8212030090*	50-387 Q	GREEN, H J	8212090174	50-328 S	GUSTAVE, R P	8212220542*	CONTRACT
GOODY, A T	8212030147*	50-247 Q	GREEN, H J	8212090280	50-259 S	GUSTAVE, R P	8212220553*	CONTRACT
GOODY, A T	8212030175*	50-213 Q	GREEN, H J	8212090361	50-328 S	GUSTAVE, R P	8212230051*	CONTRACT
GOODY, A T	8212030177*	50-334 Q	GREEN, H J	8212090551	50-328 S	GUSTAVE, R P	8212270422*	CONTRACT
GOODY, A T	8212060212*	HIBC	GREEN, H J	8212140198	50-328 S	GUSTAVE, R P	8212270447*	CONTRACT
GOODY, A T	8212100081*	50-219 Q	GREEN, H J	8212140241*	50-327 S	GUSTAVE, R P	8212270503*	CONTRACT
GOODY, A T	8212210134*	50-277 Q	GREEN, H J	8212140440	50-259 S	GUSTAVE, R P	8212270521*	CONTRACT
GOODY, A T	8212210351*	50-309 Q	GREEN, H J	8212150066	50-259 S	GUSTAVE, R P	8212270560*	CONTRACT
GOODY, A T	8212210390*	70-687	GREEN, H J	8212150071	50-296 S	GUSTAVE, R P	8212280049*	CONTRACT
GOODY, A T	8212220437*	70-135	GREEN, H J	8212150101	50-260 S	GUSTAVE, R P	8212300123*	CONTRACT
GOODY, A T	8212230335*	70-1143	GREEN, H J	82122150107	50-296 S	GUSTAVE, R P	8212300192*	CONTRACT
GOODY, A T	8212290352*	70-820	GREEN, H J	8212210095	50-328 S	GUTHRIE, J H	8212290003	50-498 Q
GOODY, A T	8212290363*	70-1100	GREEN, H J	8212220463	50-260 S	GUTHMAN, P H	8212270560*	CONTRACT
GOODY, A T	8212290383*	50-244 Q	GREEN, H J	8212280099	50-260 S	HAASS, W P	8212100052	TOPREP
GOODY, A T	8212290443*	50-272 Q	GREEN, H J	8212280111	50-327 S	HAASS, W P	8212170396	TOPREP
GOODY, A T	8212290479*	50-219 Q	GREEN, H J	8212280133	50-328 S	HAASS, W P	8212270473	PROJ
ODETT, W	8212270030*	70-33	GREEN, H J	8212280147	50-259 S	HACKETT, D B	8105210384*	50-263 Q
ODOL, E	8212200099	50-373 H	GREEN, K	8212170276*	50-250 P	HAFNER, B	8208290118	50-322 A
ODOLBERG, F F	8212270435	NUREQ	GREEN, P K	8211040090*	50-333 S	HAFNER, B	8209150058	50-322 H
ODOLBERG, J H	8212070262	50-498 K	GREENBERG, E V	8212080257	50-537 Q	HAFNER, B	8209150064	50-322 A
ODOLBERG, J H	8212090377	50-498 K	GREENBERG, E V	8212080257	50-537 Q	HAFNER, B	8212290006	50-322 A
ODOLBERG, J H	8212140381	50-498 C	GREENBERG, E V	8212080257	50-537 Q	HAGAN, T F	8212020194*	CONTRACT
ODOLBERG, J H	8212140383*	50-498 C	GREENBERG, E V	8212230200	50-537 Q	HAGAN, T F	8212020390*	CONTRACT
ODOLBERG, J H	8212170120	50-498 A	GREENBERG, E V	8212230200	50-537 Q	HAGAN, T F	8212020404*	CONTRACT
ODOLBERG, J H	8212170124*	50-498 A	GREENBERG, E V	8212230200	50-537 Q	HAGAN, T F	8212060304*	CONTRACT
ODOLBERG, J R	8212010034	50-289 Q	GREENBERG, E V	8212270245	50-537 Q	HAGAN, T F	8212060506*	CONTRACT
ODOLBERG, S	8212080235	50-454 Q	GREENE, G A	8212070400	RES	HAGAN, T F	8212130182*	CONTRACT
ODOLBERG, S	8212080245*	50-434 Q	GREENE, S R	8212140479	50-259 P	HAGAN, T F	8212160608*	CONTRACT
ODOLBERG, S C	8212060010	50-454 Q	GREENMAN	8212210417	50-286 S	HAGAN, T F	8212170401*	CONTRACT
ODOLBERG, S C	8212070157	50-454 Q	GREENMAN, E	8212030032*	70-1100	HAGAN, T F	8212220024*	CONTRACT
ODOLBERG, S C	8212090231	50-454 Q	GREENMAN, E	8212060079	50-443 S	HAGAN, T F	8212220027*	CONTRACT
ODOLFARB, R A	8212150013*	50-247 T	GREGER, L R	8212020314*	50-254 Q	HAGAN, T F	8212270412*	CONTRACT
ODOLFARB, R A	8212150013*	50-247 T	GREGER, L R	8212030114	50-155 S	HAGAN, T F	8212270417*	CONTRACT
ODOLMAN, L A	8212130058	NUREQ	GREGER, L R	8212060197*	50-254 Q	HAGAN, T F	8212270501*	50-537 A
ODOLMAN, L A	8212270513*	CONTRACT	GREGER, L R	8212080296*	50-295 Q	HAGAN, T F	8212270530*	CONTRACT
ODOLMAN, K	8212270069	71-9015	GREGER, L R	8212100023*	50-263 Q	HAGAN, T F	8212270543*	CONTRACT
ODOLSTEIN, R.	8212230241	50-247 Q	GREGER, L R	8212280062*	50-295 Q	HAGAN, T F	8212270556*	CONTRACT
ODQUE, R W	8212030232*	50-259 Q	GREGER, R J	8212270256*	70-820	HAGAN, T F	8212280455*	CONTRACT
ODOLING, B	8212070068*	50-289 H	GREITZER, C	8212230241	50-247 Q	HAGAN, T F	8212280501*	50-329 A
ODOLMAN, L B	8212280256*	50-409 S	GRIER, O W	8212280168	TOPREP	HAGAN, T F	8212290056*	CONTRACT
ODOLWIN, E F	8212010024	50-397 Q	GRIER, O W	8212280173*	TOPREP	HAGAN, C	8212080263*	50-219 S
ODOLWIN, W L	8212150244*	70-1151	GRIBMEYER, J M	8212270442*	FOIA	HAIFER, J	8212130185*	50-400 A
ODORDAN, B B	8211020246*	40-8698	GRIBMEYER, J M	8212270445*	FOIA	HAIRSTON, W Q	8212290312*	50-364 S
ODORDAN, M J	8212010008	WASTE MGT	GRIFFIN, J H	8212280307	50-313 P	HAIRSTON, W Q	8212170207*	50-348 R
ODORDAN, M J	8212020117	WASTE MGT	GRIFFITHS, S K	8212270156	NUREQ	HAIRSTON, W Q	8212170302*	50-364 R
ODRNEIS, J W	8212230001	71-6717	GRIMES, B K	8212100121*	70-143	HAIRSTON, W Q	8212300223*	50-364 S
ODRNEIS, J W	8212210324*	50-286 P	GRIMES, B K	8212150140*	50-392 Q	HAIRSTON, W Q	8212300227*	50-364 S
ODRBER, L	8208290092	FOIA	ORRIS, J A	8212170189*	50-266 Q	HAIRSTON, W Q	8212300231*	50-364 S
ODRBER, L	8209150034	FOIA	ORRIS, J A	8212290116	50-309 R	HAIRSTON, W Q	8212300236*	50-364 S

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
HAIST, D D	8212170370*	50-508 Q	HASSE, R A	8212100339*	50-461 Q	HIND, J A	8212060172	50-254 F
HAIST, D P	8212210195*	50-508 Q	HASSE, R A	8212170121*	50-295 Q	HIND, J A	8212060232	50-295 Q
HAIST, D P	8212260301*	50-508 Q	HASSE, R A	8212270339*	50-305 Q	HIND, J A	8212150015	50-409 Q
HALE, C J	821210223*	QA999	HASSELL, D F	8212280008	50-247 Q	HIND, J A	8212210118	50-237 Q
HALL, B L	8212030232*	50-239 Q	HATTER, B J	8212080011*	FOIA	HIND, J A	8212210329	50-282 Q
HALL, D Q	8212080520	RES	HATTORI, H	8212010114	XPORTLIC	HINKLE, L S	8212060206*	50-317 S
HALL, D P	8212020324	50-461 S	HATTORI, H	8212010127	XPORTLIC	HINRICHS, O	8212080311*	50-247 S
HALL, D P	8212020333	50-461 S	HAWKINS, F C	8212100339*	50-461 Q	HINRICHS, O	8212150027*	50-247 S
HALL, D P	8212060093	50-461 Q	HAWKINS, F C	8212170121*	50-295 Q	HINRICHS, O	8212210133*	50-247 S
HALL, D P	8212060144	50-461 A	HAWKINS, F C	8212270339*	50-303 Q	HINRICHS, O	8212210140*	50-247 S
HALL, D P	8212140057	50-461 S	HAWKINS, F C	8212290348*	50-254 Q	HIRT, C W	8212070276*	50-416 P
HALL, D P	8212280101	50-461 A	HAWTHORNE, J R	8212270459	NUREG	HOCHEBERG, A Q	8212230235	50-247 Q
HALL, D P	8212280360	50-461 Q	HAYES, D. H	8212080573*	50-461 Q	HOCHEFLDER, E	8212010085	PTAI
HALL, H J	7907100669*	50-237 P	HAYES, D. H	8212090236*	50-454 Q	HODGQDN, A D	8212130227*	50-29 P
HALL, H J	7907240319*	50-237 P	HAYES, D. H	8212100240*	50-461 Q	HODGQDN, A P	8212140036	50-352 Q
HALL, H J	7908080624*	50-237 P	HAYES, D. H	8212100308*	50-454 Q	HODGQDN, A P	8212200114	50-352 Q
HALL, H J	8005070798*	50-237 P	HAYES, D. H	8212280381*	50-461 Q	HODGQDN, A P	8212220097	50-352 Q
HANILL, K J	8212020196	WASTE MGT	HAYMAN, R B	8212202049	NUREG	HODGQDN, A P	8212220126	50-352 Q
HANILL, K J	8212020386	WASTE MGT	HAYNES, R C	8212030040	50-322 Q	HODGE, S A	8212140479	50-259 P
HANILL, K J	8212020397	WASTE MGT	HAYNES, R C	8212030124	50-3 F	HOFFMAN, D P	8212300332	50-155 R
HANILL, K J	8212020400	WASTE MGT	HAYNES, R C	8212060207	50-286 F	HOHMAN, B	8212140177*	50-219 S
HANILL, K J	8212140357*	50-263 S	HAYNES, R C	8212070014	50-219 Q	HOLIAN, P D	8212280213*	50-124 P
HAN, J T	8212270181	NUREG	HAYNES, R C	8212070021*	50-219 Q	HOLIAN, P D	8212280216*	50-124 P
HANAUER, S H	8204070020*	FOIA	HAYNES, R C	8212280084	50-247 F	HOLLAND, P	8212020280*	50-237 S
HANAUER, S H	8204070028*	FOIA	HAYNES, R C	8212280186	50-286 F	HOLLEY, W	8212210250*	50-313 Q
HANAUER, S H	8206220070*	FOIA	HAZLE, A J	8212160422	PR	HOLLINGNORTH, B	8212200079	50-443 Q
HANAUER, S H	8207120252*	FOIA	HAZLETT, T C	8212210005*	50-275 P	HOLT, J	8212080280	50-289 H
HANAUER, S H	8212080689	HTSC	HEATH, D L	821220162	NUREG	HOLT, J	8212150022	50-247 Q
HANDEY, H	8212280538	27-48	HEATHERLY, T L	8212090504	50-390 Q	HOLT, J	8212150022	50-247 Q
HANCHETT, J O	8212010168*	FOIA	HEHL, C W	8212030004	50-261 S	HOLTER, G H	8212270033	NUREG
HANCHETT, J O	8212010209*	FOIA	HEIDEL, C H	8212010156*	50-341 K	HOLTER, G H	8212270232	NUREG
HANCHETT, J O	8212210185*	50-344 Q	HEIDER, L H	8212020300	50-29 P	HOMAN, F J	8212010486	RES
HANCOCK, J A	8212060084	50-302 H	HEIDER, L H	8212140379	50-271 P	HOMAN, F J	8212220319	RES
HANNETT, B	8212230406	XPORTLIC	HEIDER, L H	8212290126	50-27 R	HOMAN, F J	8212290312	RES
HANNETT, B	8212230410*	XPORTLIC	HEIDER, H J	8212160538	PR	HONG, C	8212010015*	50-537 F
HANNETT, B A	8212070489	XPORTLIC	HEISKEL, M H	8212130195	71-4909	HOOD, D	8212020210	50-329 A
HANNETT, B A	8212070503*	XPORTLIC	HELLER, J K	8212030129*	50-255 Q	HOOD, D S	8212060389	50-329 A
HANNETT, B A	8212080020*	XPORTLIC	HEMBY, E	8212010110	XPORTLIC	HOOPER, F	8212210296*	50-153 Q
HANNETT, B A	8212080029	XPORTLIC	HENDRIE, J M	8212010112*	FOIA	HOOPER, F	8212210296*	50-153 Q
HANNETT, B A	8212080035	XPORTLIC	HENDRIX, Q W	8212020118	PR	HOOPER, F	8212090380*	50-369 Q
HANNETT, B A	8212230402	XPORTLIC	HENSLEY, K D	8212160420	70-143	HOPIN, W A	8212140409	50-445 Q
HANNON, J H	8212270108	50-3 P	HERBERT, J P	8212020404*	CONTRACT	HOPIN, W A	8212140409	50-445 Q
HANNON, B	8212020277	PRH	HERDT, A R	8212290109*	50-230 Q	HOPIN, W A	8212280273	50-445 Q
HANSON	8212150170*	50-275 P	HERDT, A R	8212290138*	50-261 Q	HOPIN, W A	8212280273	50-445 Q
HARBOUR, J	8212070167	50-322 Q	HERING, R F	8212280165	50-315 Q	HOROWITZ, F D	8212220533*	CONTRACT
HARDIN, A K	8212280278	50-324 S	HERLEKAR, A S	8212210342*	50-263 P	HOSEY, C M	8212090500*	50-250 Q
HARDIN, A K	8212290078*	50-250 Q	HERMANN, R	8203310670*	50-29 P	HOUS, B	8212300007*	50-312 Q
HARDIN, A K	8212290109*	50-250 Q	HERMAN, R W	8212070356	50-329 D	HOUSTON, R	8212170238*	50-373 S
HARDIN, A K	8212290114*	50-250 Q	HERMAN, R W	8212170074	50-329 E	HOUSTON, R W	8212020301*	50-373 S
HARDIN, A K	8212290137*	50-250 Q	HERMAN, R W	8212220548	50-329 E	HOUSTON, R W	8212080332*	50-373 S
HARDING, M R	8212080191*	50-328 S	HERMAN, R W	8212290513	50-329 E	HOUSTON, R W	8212170270*	50-373 S
HARDING, M R	8212030092*	50-327 S	HERMAN, R W	8212290475	50-329 E	HOUSTON, R W	8212270148*	50-373 S
HARDING, M R	8212090178*	50-328 S	HERMAN, R W	8212290508	50-329 A	HOVIB, J B	8212140333	50-522 Q
HARDING, M R	8212140207*	50-328 S	HERMAN, R W	8212330185	50-329 A	HOVIB, J B	8212140333	50-522 Q
HARDING, M R	8212140247*	50-327 S	HERMANDEZ, Q	8212170376*	50-206 Q	HOVIB, J B	8212140334	50-522 Q
HARDING, M R	8212210100*	50-328 S	HERRICK, E Q	8212160365	TOPREP	HOVIB, J B	8212140345	50-522 Q
HARDING, M R	8212280116*	50-327 S	HERRING, K S	8207200474*	50-155 P	HOVIB, J B	8212140354	50-522 Q
HARDING, M R	8212280136*	50-328 S	HERSCH, M H	8212270077	XPORTLIC	HOVIB, J B	8212140354	50-522 Q
HARDING, V	8212070441*	50-298 F	HERSCH, M H	8212270077*	XPORTLIC	HOVIB, J B	8212140356	50-522 Q
HARDY, B L	8212030274	40-8084	HESSON, O H	8212220265	NUREG	HOVIB, J B	8212140356	50-522 Q
HARDY, B L	8212030278	40-8084	HIATT, S L	8212060108	50-440 Q	HOWARD, B N	8212160394	PR
HARDY, B L	8212270331	40-8084	HIATT, S L	8212070192	50-440 Q	HOWARD, E M	8212080088*	70-143
HARDY, J E	8212130123	NUREG	HIATT, S L	8212070199	50-440 Q	HOWARD, E M	8212080093*	70-143
HARJED, J A	8212270492	NUREG	HIATT, S L	8212070203	50-440 Q	HOWARD, E M	8212080129*	70-143
HAROLDSON, R D	8212020086	50-409 P	HIATT, S L	8212230267	50-440 Q	HOWARD, J E	8212170305	50-293 P
HARRAN, Q	8212290227*	50-245 R	HIATT, S L	8212230319	50-440 Q	HOWE, P W	8212090375	50-324 Q
HARRINGTON, R M	8212140479	50-259 P	HIATT, S L	8212230345	50-440 Q	HOWELL, D E	8212140377	50-341 Q
HARRINGTON, W D	8212150224*	50-293 Q	HIATT, S L	8212230368	50-440 Q	HOYLE, A	8212070424	CONTRACT
HARRINGTON, W D	8212150233*	50-293 Q	HIATT, S L	8212280324*	50-440 Q	HOYLE, J C	8212080009*	COMMISSION
HARRINGTON, W D	8212290433*	50-293 Q	HIATT, S L	8212290031	50-440 A	HOYLE, J C	8212270084*	FOIA
HARRIS, A B	8212090372*	50-395 S	HICKEY, J P	8212070094*	COMMISSION	HOYLE, J C	8212270095*	FOIA
HARRIS, J A	8212010244*	FOIA	HICKEY, J P	8212070095*	50-373 S	HOYT, G W	8212030168*	50-361 P
HARRIS, J A	8212010249*	FOIA	HIEBEL, J J	8212020327*	50-373 S	HOYT, H F	8212270203	50-443 Q
HARRIS, J R	8212090364*	50-417 Q	HIEBEL, J J	8212030083*	50-322 Q	HOYT, H F	8212270208	50-443 Q
HARRIS, R H	8212220218*	50-397 Q	HILDEBRAND, J E	8212130060*	50-320 P	HST, T I	8212210333*	50-263 P
HARRISON, F	8212100250*	50-324 R	HILL, D	8212080583*	CONTRACT	HUBBARD, O T	8212070304*	QA999
HARRISON, F L	8212140459	50-261 P	HILL, K L	8212060224*	50-331 S	HUBBARD, R B	8212270227	50-322 T
HARRISON, F L	8212140485	NUREG	HILL, K L	8212140147*	50-331 S	HUBBARD, R B	8212270227	50-322 T
HARRISON, J J	8212080407*	50-546 Q	HILL, K L	8212140338*	50-331 S	HUBBLE, W H	8212030076	50-385 P
HART, T	8212280250*	50-346 S	HILL, K L	8212210034*	50-331 S	HUBBLE, W H	8212020108	50-364 P
HARTMAN, J E	8212220282	NUREG	HILL, K L	8212210074*	50-331 S	HUETER, L J	8212020314*	50-254 Q
HARTMAN, S L	8209150071	FOIA	HILL, K L	8212210358*	50-331 S	HUETER, L J	8212060197*	50-254 Q
HARTZMAN, R M	8212220246	50-247 Q	HILL, K L	8212280497*	50-331 S	HUFFMAN, O N	8212090540*	50-250 Q
HARTZMAN, R M	8212220246	50-247 Q	HILLMAN, R E	8212210044*	50-219 R	HUFFMAN, O N	8212090555*	70-1151
HARWARD, J E	8212300174	50-219 Q	HIND, J A	8212060009	50-315 Q	HUGHES, P O	8212020071*	50-302 S

PERSONAL AUTHOR INDEX

435

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
HUGHES, P. G.	8212150053*	50-302 S	JACKSON, R. E.	8109210340*	FOIA	JOHNSTON, W. V.	8107140119*	50-322 H
HUGHES, P. G.	8212150064*	50-302 S	JACKSON, R. S.	8212090481*	State Prog	JOHNSTON, W. V.	8204270491*	50-255 P
HUGHES, P. G.	8212150102*	50-302 S	JACKSON, T. J.	8212030037*	50-219 Q	JOHNSTON, W. V.	8211290023*	50-206 Q
HUIZENGA, H. W.	8212290005	27-47	JACOBS, A.	8212220522	CONTRACT	JONES, D. W.	8212090270*	70-1113
HUIZENGA, H. W.	8212290005	27-47	JACOBS, A.	821220524	CONTRACT	JONES, G. T.	8212290281	50-259 R
HUKILL, H. D.	8212060054	50-289 F	JACOBS, A.	8212300117	CONTRACT	JONES, J. N.	8212080103*	CONTRACT
HUKILL, H. D.	8212070251	50-289 F	JACOBS, R. H.	8212060508	50-289 P	JONES, R.	8212130218	50-440 Q
HUKILL, H. D.	8212080519	50-289 F	JACOBS, R. S.	8212230241	50-247 Q	JONES, R. E.	8212230366	50-400 Q
HUKILL, H. D.	8212090284	50-289 P	JACOBSON, J.	8212290023	50-206 Q	JONES, R. J.	8212080104*	FOIA
HUKILL, H. D.	8212090293*	50-289 P	JAKUBAITIS, T. C.	8212020237*	50-295 S	JONES, R. J.	8212080109*	FOIA
HUKILL, H. D.	8212090501	50-289 P	JANG, J. C.	8212030037*	50-219 Q	JONES, R. J.	8212080111*	FOIA
HUKILL, H. D.	8212130060*	50-320 P	JANUSKA, A. O.	8212170079*	50-373 Q	JONES, R. J.	8212080126*	FOIA
HUKILL, H. D.	8212130104	50-289 P	JAPE, F.	8212090213*	50-389 Q	JONES, R. J.	8212080146*	FOIA
HUKILL, H. D.	8212140228	50-289 S	JAPE, F.	8212090271*	50-370 Q	JONES, R. J.	8212100164*	FOIA
HUKILL, H. D.	8212140466	50-289 P	JAPC, F.	8212090277*	50-280 Q	JONES, S. Z.	8212060496	40-8102
HUKILL, H. D.	8212210017	50-289 P	JAPE, F.	8212090360*	50-389 Q	JONES, V.	8212290244*	50-260 R
HUKILL, H. D.	8212210232	50-289 R	JAPE, F.	8212090411*	50-389 Q	JONES, W. B.	8212070123*	50-382 Q
HUKILL, H. D.	8212270134	50-289 P	JAPE, F.	8212090493*	50-327 Q	JONES, W. B.	8212280378*	50-382 Q
HUKILL, H. D.	8212270268	50-289 P	JARRELL, D. B.	8212130152	NUREG	JONES, W. C.	8212020093	50-285 P
HUKILL, H. D.	8212290197	50-289 P	JAUDON, J. P.	8212030112*	50-285 Q	JONES, W. C.	8212020119	50-285 P
HULL, P.	8212070348*	50-269 P	JAUDON, J. P.	8212300182	50-368 S	JONES, W. C.	8212030009	50-285 B
HULMAN, L. Q.	8212080626	NUREG	JENKINS, O. R.	8212090274*	70-1201	JONES, W. C.	8212060032*	50-285 P
HULMAN, L. Q.	8212130050	NUREG	JENKINS, O. R.	8212090274*	70-824	JONES, W. C.	8212060254	50-285 P
HUNNICUTT, D. M.	8212030058*	50-482 Q	JENKINS, O. R.	8212090391*	50-261 Q	JONES, W. C.	8212060266	50-285 Q
HUNNICUTT, D. M.	8212030156*	50-445 Q	JENKINS, O. R.	8212090540*	50-290 Q	JONES, W. C.	8212060438	50-285 P
HUNNICUTT, D. M.	8212030192*	50-368 Q	JENKINS, O. R.	8212090555*	70-1151	JONES, W. C.	8212070150*	50-285 Q
HUNNICUTT, D. M.	8212070133*	50-112 Q	JENKINS, O. R.	8212290137*	FOIA	JONES, W. C.	8212070419*	50-285 P
HUNSTAD, A. A.	8212020317*	50-282 S	JENKINS, O. R.	8212290184*	FOIA	JONES, W. C.	8212080380*	50-285 F
HUNSTAD, A. A.	8212080429*	50-282 S	JENSCH, S. H.	8212010238*	FOIA	JONES, W. C.	8212100244*	50-285 G
HUNT, M. D.	8212090256*	50-400 Q	JENSEN, S. A.	8212080551*	50-443 A	JONES, W. C.	8212130312*	50-285 F
HUNT, M. D.	8212090258*	50-424 Q	JENSEN, S. E.	8212140167	50-316 P	JONES, W. C.	8212140416	50-285 P
HUNTER, R. S.	8212030125	50-315 P	JENSEN, S. E.	8212290199*	50-237 P	JONES, W. C.	8212200059	50-285 R
HUNTER, R. S.	8212030145*	50-315 P	JIN, R.	8212140455	50-522 Q	JONES, W. C.	8212210022*	50-285 Q
HUNTER, R. S.	8212060072	50-315 P	JIO, J. H.	8212030239	RES	JONES, W. C.	8212210199	50-285 P
HUNTER, R. S.	8212090296	50-315 P	JOHNSON, A. D.	8212130270*	50-27 Q	JONES, W. C.	8212230326*	50-285 P
HUNTER, R. S.	8212100290	50-315 P	JOHNSON, A. D.	8212300240*	70-25	JONES, W. C.	8212280197	50-285 P
HUNTER, R. S.	8212160001	50-315 F	JOHNSON, A. E.	8212303306	50-275 P	JORDAN, D. D.	8212170133*	50-498 A
HUNTER, R. S.	8212170179	50-316 P	JOHNSON, B. D.	8212060047	50-255 S	JORDAN, E. L.	8208190291	50-3 Q
HUNTER, R. S.	8212210125	50-315 P	JOHNSON, B. D.	8212060337	50-255 S	JORDAN, E. L.	8208190261	50-3 Q
HUNTER, R. S.	8212270136	50-315 P	JOHNSON, B. D.	8212080261	50-255 S	JORDAN, E. L.	8208190266	50-3 Q
HUNTER, R. S.	8212280310	50-316 Q	JOHNSON, B. D.	8212090409	50-255 F	JORDAN, E. L.	8212220505	50-335 Q
HUSAIN, I.	8212280061*	50-409 P	JOHNSON, B. D.	8212100313	50-255 S	JORDAN, E. L.	8212220508	50-220 Q
HUBERTY, D. E.	8212160270*	50-317 S	JOHNSON, B. D.	8212270215	50-255 S	JORDAN, E. L.	8212280023	50-397 Q
HUTKO, K.	8212080525*	50-219 S	JOHNSON, B. D.	8212280330	50-255 Q	JORDAN, H.	8212270420	NUREG
HUTTON, P. H.	8212010483	RES	JOHNSON, B. D.	8212280460	50-255 S	JORDAN, M.	8212290164*	50-327 R
HUTTON, P. H.	8212300137	RES	JOHNSON, B. H.	8211220096*	50-3 P	JORGENSEN, B. L.	8212030129*	50-255 Q
IEDER, R. L.	8212220527	70-143	JOHNSON, E. B.	8212070160	50-237 Q	JULIAN, C. A.	8212090313*	50-280 Q
IGNATONIS, A.	8212150144	50-287 S	JOHNSON, E. C.	8212080520	RES	JULIAN, C. A.	8212090524*	50-280 Q
INGRAM, F.	8212010177*	FOIA	JOHNSON, O. E.	8212150124	50-413 Q	JULIAN, C. A.	8212090234*	50-280 Q
INGRAM, F.	8212010180*	FOIA	JOHNSON, O. E.	8212150127	50-413 Q	JULIAN, C. A.	8212090537*	50-335 Q
INGRAM, F.	8212010218*	FOIA	JOHNSON, O. E.	8212160235	50-413 Q	JULIAN, C. A.	8212090562*	50-335 Q
INGRAM, F.	8212010226*	FOIA	JOHNSON, O. E.	8212160240*	50-413 Q	JULIAN, C. A.	8212090564*	50-335 Q
INGRAM, F.	8212010235*	FOIA	JOHNSON, O. E.	8212160256*	50-413 Q	JULIAN, C. A.	8212150103	50-338 B
INGRAM, F. L.	8212010067*	FOIA	JOHNSON, O. E.	8212160303	50-413 Q	JULIAN, C. A.	8212150151	50-338 B
INGRAM, F. L.	8212010070*	FOIA	JOHNSON, O. E.	8212170180	50-413 Q	JUNGE, M. A.	8212060306*	50-317 S
INGRAM, F. L.	8212010077*	FOIA	JOHNSON, O. E.	8212170186	50-413 Q	JUNGE, M. A.	8212210048*	50-317 B
INGRAM, F. L.	8212010080*	FOIA	JOHNSON, O. E.	8212210317	50-413 Q	JUNGE, M. A.	8212210080*	50-317 B
INGRAM, F. L.	8212010159*	FOIA	JOHNSON, O. E.	8212290002	50-413 Q	JUNGE, M. A.	8212290282*	50-317 B
INGRAM, F. L.	8212010196*	FOIA	JOHNSON, O. W.	8212080505	RES	JUSTUS, P. S.	8212220546	WASTE MGT
INGRAM, F. L.	8212010201*	FOIA	JOHNSON, J. D.	8212270561	NUREG	KAEPPEL, F.	8212100335*	50-265 S
INMAN, Q. W.	8212270561	NUREG	JOHNSON, L.	8212160337*	40-3265	KAHLE, J. B.	8212090517*	70-143
INTERANTE, J.	8212010174*	FOIA	JOHNSON, L.	8212160352*	40-6500	KALIVIANAKIS, N.	8212080390	50-265 S
IRBY, D. J.	8212150069*	50-259 S	JOHNSON, L.	8212160372*	FOIA	KALIVIANAKIS, N.	8212100328	50-265 S
IRBY, D. J.	8212150076*	50-296 S	JOHNSON, L.	8212160386*	FOIA	KALIVIANAKIS, N.	8212130196	50-254 H
IRBY, D. J.	8212220472*	50-260 S	JOHNSON, P.	8212030091	50-312 S	KALHAN, K. L.	8212010056	40-8064
IRWIN, D. P.	8212140463	50-322 Q	JOHNSON, P.	8212060347	50-312 S	KALHAN, K. L.	8212010059	40-8380
IRWIN, D. P.	8212220011	50-322 Q	JOHNSON, P. H.	8212170397*	50-361 Q	KALHAN, K. L.	8212030264	40-8380
IRWIN, H. R.	8212160043	71-5796	JOHNSON, R. D.	8212020325	50-255 S	KALHAN, K. L.	8212200017	40-8064
ISENBRO, J.	8212130147	NUREG	JOHNSON, T. C.	8212010013	WASTE MGT	KAMMER, D. B.	8212140046	50-390 F
IVER, J. S.	8212290181*	50-361 R	JOHNSON, T. C.	8212020187	WASTE MGT	KAMMER, D. B.	8212140323	50-259 K
JABBOUR, K. H.	8212150232	50-413 A	JOHNSON, T. L.	8212300025	40-1341	KAMMER, D. B.	8212150010	50-327 P
JABBOUR, K. N.	8212170422	50-413 A	JOHNSON, W. D.	8212030098*	50-482 Q	KAMMER, D. B.	8212270287	50-390 A
JABBOUR, K. N.	8212220015	50-413 A	JOHNSON, W. D.	8212030112*	50-285 Q	KANE, M. F.	8212010030	50-387 P
JACKI, I. N.	8212170118*	50-454 Q	JOHNSON, W. D.	8212030115*	50-482 Q	KANGA, B. K.	8212030113	50-320 R
JACKI, I. N.	8212170306*	50-10 Q	JOHNSON, W. D.	8212030126*	50-285 Q	KANGA, B. K.	8212060322	50-320 S
JACKI, I. N.	8212290386*	50-249 Q	JOHNSON, W. D.	8212030192*	50-368 Q	KANGA, B. K.	8212070143	50-320 R
JACKSON, O.	8212160050*	71-5796	JOHNSON, W. D.	8212100247	50-285 S	KANGA, B. K.	8212130059	50-320 P
JACKSON, J. P.	8208290147*	COMMISSION	JOHNSON, W. D.	8212200033*	50-285 Q	KANGA, B. K.	8212130318	50-320 F
JACKSON, K. C.	8212020040	WASTE MGT	JOHNSON, W. D.	8212210208	50-368 S	KANGA, B. K.	8212150038	50-320 S
JACKSON, K. C.	8212020195	WASTE MGT	JOHNSON, W. D.	8212280345	50-313 S	KANGA, B. K.	8212160764*	50-320 F
JACKSON, K. C.	8212020203	WASTE MGT	JOHNSON, W. D.	8212290210	50-313 S	KANGA, B. K.	8212210018	50-320 P
JACKSON, P. D.	8212220193	NUREG	JOHNSON, W. D.	8212290249	50-482 B	KANGA, B. K.	8212230449	50-320 S
JACKSON, R.	8002130081*	50-206 P	JOHNSON, J. H.	8212140186	50-277 Q	KANGA, B. K.	8212230295	50-320 P
JACKSON, R. E.	8001280032*	50-482 A	JOHNSON, J. H.	8212300134	50-277 Q	KANGA, B. K.	8212270149	50-320 F
JACKSON, R. E.	8003310092*	50-206 P	JOHNSTON, O.	8212130215*	50-528 Q	KANGA, B. K.	8212280390*	50-320 Q

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
KANGA, B K	8212290233	50-320 S	KEPPLER, J O	8212290306	50-10 F	KNIGHTON, O W	8212130168*	50-361 F
KANGA, B K	8212290359*	50-320 Q	KEPPLER, J O	8212270429*	50-358 A	KNIGHTON, O W	8212130405	50-328 A
KANGA, B K	8212300113	50-320 P	KEPPLER, J O	8212280070	50-10 Q	KNIGHTON, O W	8212220011	50-308 C
KANGA, B K	8212300240	50-320 P	KEPPLER, J O	8212280375	50-461 Q	KNOP, R C	8212080378	50-346 Q
KAPLAN, C	8212140242	50-247 Q	KEPPLER, J O	8212280381*	50-461 Q	KNOP, R C	8212080402*	50-346 Q
KAPLAN, E A	8212280461*	50-295 S	KEPPLER, J O	8212290415	50-295 F	KNOP, R C	8212080561	50-461 Q
KATZMAN, A J	82122903241	50-247 Q	KERCH, H	8212060217*	50-309 Q	KNOP, R C	8212080567*	50-461 Q
KAUCHER, J E	8209140103	50-255 P	KERCH, H W	8212220218*	50-397 Q	KNOP, R C	8212100195	50-367 Q
KAUFFMAN, J T	8212220405*	50-387 Q	KERR, O W	8212270443	50-260 S	KNOP, R C	8212100198	50-341 Q
KAVANAUGH, P F	8212220542*	CONTRACT	KERR, T	8212020153*	50-260 S	KNOP, R C	8212100224	50-461 Q
KAVANAUGH, P F	8212270412*	CONTRACT	KERR, T	8212090153*	50-260 S	KNOP, R C	8212100230*	50-461 Q
KAY, D L	8212270241	50-373 S	KETZLACH, N	8212020081*	70-734	KNOP, R C	8212280381*	50-461 Q
KAY, D L	8212170174*	50-373 S	KETZLACH, N	8212080049*	70-27	KNOP, R C	8212270406	50-546 Q
KAY, D L	8212270356*	50-373 S	KETZLACH, N	8212080695*	70-698	KNOP, R C	8212290412	50-440 Q
KAY, J A	8212060026	50-29 P	KETZLACH, N	8212290058	70-25	KNOP, R C	8212030127	50-482 A
KAY, J A	8212070040	50-29 P	KEY, W J	8212290336*	50-266 Q	KOESTER, O L	8212030135*	50-482 A
KAY, J A	8212070047	50-29 P	KEYSERLING, W	8208290030	ACR8	KOESTER, O L	8212070222	50-482 F
KAY, J A	8212130223	50-29 P	KIEL, O R	8212010057	XPORTLIC	KOESTER, O L	8212170324	50-482 H
KAY, J A	8212140394	50-29 P	KIEL, O R	8212010063*	XPORTLIC	KOESTER, O L	8212200036	PR
KAY, J A	8212280474	50-29 P	KILLINGER, M H	8212060493	70-2968	KOESTER, O L	8212210115	50-482 S
KAYER, W V	8212290199*	50-237 P	KILLINGER, M H	8212080007	70-2964	KOESTER, O L	8212270187	50-482 C
KEARNEY, J J	8212020359	PR	KIN, J W	8212150072*	50-331 P	KOESTER, O L	8212280338	50-482 S
KEIMIG, R	8212060195	50-272 S	KINCAID, C T	8212270512	NURE0	KOLB, O J	8212060492	50-313 F
KEIMIG, R	8212140168	50-219 S	KINDER, E T	8212100102	50-443 A	KOLTA, P	8212140140*	50-247 Q
KEIMIG, R	8212220478*	50-269 Q	KINDER, E T	8212140227	50-443 Q	KOMES, J H	8212140092	TOPREP
KEIMIG, R R	8212290492*	50-193 Q	KINDER, E T	8212140234	50-443 Q	KONKLIN, J E	8212080407*	50-546 Q
KEIMIG, R R	8212300141	50-269 F	KINDER, E T	8212160281	50-443 Q	KONKLIN, J E	8212100200*	50-367 Q
KEISER, H H	8212030041	50-387 S	KINDER, E T	8212230346	50-443 Q	KONKLIN, J E	8212100203*	50-341 Q
KEISER, H H	8212030173	50-387 S	KINDER, E T	8212230348	50-443 Q	KONKLIN, J E	8212100242*	50-483 Q
KEISER, H H	8212060295	50-387 S	KING, A P	8212270066	50-244 S	KONKLIN, J E	8212290414*	50-546 Q
KEISER, H H	8212080320	50-387 S	KING, L L	8212220265	NURE0	KONKLIN, J E	8212290417*	50-440 Q
KEISER, H H	8212080333	50-387 S	KINNEHAN, J D	8212030016	70-2792	KOON, A R	8212030202*	50-395 S
KEISER, H H	8212080362	50-387 S	KINNEY, W W	8212290492*	50-193 Q	KOON, A R	8212090460*	50-395 S
KEISER, H H	8212080369	50-387 S	KINTNER, L L	8212020004	50-358 A	KOON, A R	8212150091*	50-395 S
KEISER, H H	8212080382	50-387 S	KINTNER, L L	8212270031	50-341 A	KOON, A R	8212150122*	50-395 S
KEISER, H H	8212140135	50-387 S	KINTNER, L L	8212270046	50-341 A	KOON, A R	8212220500*	50-395 S
KEISER, H H	8212140182	50-387 S	KINTNER, L L	8212290510	50-341 A	KOOL, A B	8212140659	40-8027
KEISER, H H	8212140258	50-387 S	KIRBY, L J	8212220523	RES	KOT, C A	8212130147	NURE0
KEISER, H H	8212140268	50-387 S	KIRK, W F	8212150266	70-371	KOVACK, T J	8212030273*	50-254 F
KEISER, H H	8212210052	50-387 S	KIRK, W F	8212270541	70-371	KOWALCZUK, A D	8212290137*	F01A
KEISER, H H	8212210236	50-387 S	KIRKMAN, R W	8212160140*	40-6500	KRAITZKE, R T	8212170020*	70-1143
KEISER, H H	8212210343	50-387 S	KIRKMAN, R W	8212160432*	40-6500	KRAITZKE, R T	8212230141*	70-1143
KEISER, H H	8212280403	50-387 S	KIRKMAN, R W	8212160436*	40-6500	KRAUSE, D F	8212170237*	50-316 S
KEISER, H H	8212280465	50-387 S	KIRKMAN, R W	8212160466*	40-6500	KRAUSE, L L	8212090116*	50-259 S
KEISER, H H	8212290441	50-387 S	KIRKMAN, R W	8212160471*	40-6500	KRECHTING, J E	8212010225*	50-275 R
KEITH, H	8212210274*	50-333 S	KIRSCH, D F	8212060159*	50-361 Q	KRECHTING, J E	8212270276	50-275 F
KEITH, H	8212210423*	50-333 S	KIRSCH, D F	8212060170*	50-362 Q	KRECHTING, J E	8212280160	50-275 F
KELLEY, J L	8212010187*	F01A	KIRSCH, D F	8212060261*	50-275 Q	KRECHTING, J E	8212290231	50-275 P
KELLEY, J L	8212020336	50-400 Q	KIRSCH, D F	8212060364*	50-275 Q	KRECHTING, J E	8212290498	50-275 P
KELLEY, J L	8212060135	50-413 Q	KIRSCH, D F	8212130265*	50-362 Q	KRESS, T S	8212130135	NURE0
KELLEY, R H	8212290204*	50-237 P	KIRSCH, D F	8212170376*	50-206 Q	KRICH, R M	8212100248	50-255 S
KELLY, E	8212060079	50-443 S	KIRSCH, D F	8212170397*	50-206 Q	KRIEGER, R W	8212020250	50-206 P
KELLY, J A	8212150049*	50-112 Q	KIRSCH, D F	8212290035*	50-206 Q	KRIEGER, R W	8212170158	50-206 P
KELLY, J L	8212270226	50-413 Q	KIRSCH, D F	8212270042*	50-206 Q	KRIEGER, R W	8212200063	50-206 P
KELLY, J W	8212160426	71-5086	KISH, J H	8212100339*	50-461 Q	KRIMM, R W	8212280426	50-483 F
KELLY, J W	8212270406	70-27	KISLER	8212210417	50-286 S	KRUG, H	8212090213*	50-389 Q
KELLY, J W	8212270537	70-27	KISTER, H	8212030128*	50-286 Q	KUCZYNSKI, L A	8212080342*	50-387 S
KELLY, M J	8212220021	RES	KISTER, H	8212140140*	50-247 Q	KUCZYNSKI, L A	8212080372*	50-387 S
KELLY, R E	8212060276*	50-206 P	KISTER, H	8212150227	50-410 Q	KUCZYNSKI, L A	8212080378*	50-387 S
KELLY, W J	8212210123*	50-275 S	KISTER, H B	8212030078*	50-333 Q	KUCZYNSKI, L A	8212290117*	50-387 R
KELLY, W J	8212290218*	50-275 R	KISTER, H B	8212140495*	50-410 Q	KUNIHIO, D H	8212080041*	F01A
KEMPER, J S	8212100090	50-352 F	KLEINSORGE, W P	8212090336*	50-389 Q	KUNIHIO, D H	8212080095*	F01A
KEMPER, J S	8212170315	50-277 P	KLINE, C	8212020277	PRH	KURTZ, R J	8212010483	RES
KEMPIAK, A J	8212080662	50-373 P	KLINE, J R	8212090093	50-483 Q	KURTZ, R J	8212300137	RES
KENNEDY, D H	8212130247	50-255 R	KLINE, J R	8212100108	50-440 Q	LACEY, W S	8212080419	50-334 S
KENNEDY, R P	8008070798*	50-237 P	KLINE, J R	8212130191	50-266 Q	LACEY, W S	8212080431	50-334 S
KENNETT, R P	8212270534	RES	KLINE, J R	8212130197	50-483 Q	LACEY, W S	8212080526	50-334 S
KENNY, T J	8212030128*	50-286 Q	KLINE, J R	8212150026	50-483 Q	LACEY, W S	8212140174	50-334 S
KENT, E E	8212290049*	50-206 Q	KLINE, J R	8212150041	50-440 Q	LACEY, W S	8212150020	50-334 S
KENYON, B D.	8212030096*	50-387 Q	KLINE, J R	8212230351	50-440 Q	LACEY, W S	8212150025*	50-334 S
KENYON, B D.	8212290115	50-387 R	KNAPP, M R	8212010003	WASTE MGT	LACEY, W S	8212150075	50-334 S
KENYON, T J	8212101017	50-390 A	KNAPP, M R	8212230118	WASTE MGT	LACEY, W S	8212150078*	50-334 S
KEPPLER, J O	8212020347	50-255 Q	KNICELEY, J R	8212060080*	50-346 Q	LACEY, W S	8212290339	50-334 S
KEPPLER, J O	8212030053	50-254 Q	KNICELEY, J R	8212280220*	50-10 Q	LACEY, W S	8212290404	50-334 S
KEPPLER, J O	8212030178	50-10 Q	KNIGHT, J P	8201180567*	50-255 F	LACEY, W S	8212290439	50-334 S
KEPPLER, J O	8212060050	50-295 Q	KNIGHTON, O W	8212010175	50-382 E	LAFAYETTE, I C	8212230241	50-247 G
KEPPLER, J O	8212060249	50-409 Q	KNIGHTON, O W	8212010411	50-382 F	LAGGART, M H	8212210460*	50-219 Q
KEPPLER, J O	8212060250*	50-409 Q	KNIGHTON, O W	8212080204*	50-528 A	LAGIEWSKI, J S	8212060206*	50-317 S
KEPPLER, J O	8212060320	50-461 A	KNIGHTON, O W	8212080827	50-443 M	LAGIEWSKI, J S	8212160270*	50-317 S
KEPPLER, J O	8212080274	50-331 Q	KNIGHTON, O W	8212080532*	50-443 M	LAINAS, G C	8109230665*	F01A
KEPPLER, J O	8212080494	50-454 Q	KNIGHTON, O W	8212080545	50-443 A	LAINAS, G C	8212010400	50-311 P
KEPPLER, J O	8212100221	50-266 Q	KNIGHTON, O W	8212080558	50-400 E	LAINAS, G C	8212020036	50-278 P
KEPPLER, J O	8212140326	50-373 Q	KNIGHTON, O W	8212080564	50-528 A	LAINAS, G C	8212090006	50-295 P
KEPPLER, J O	8212140335	50-388 A	KNIGHTON, O W	8212130161	50-361 P	LAINAS, G C	8212270041	50-289 P
KEPPLER, J O	8212140359	40-2061	KNIGHTON, O W	8212130162*	50-361 P	LAINAS, G C	8212300138	50-254 P

PERSONAL AUTHOR INDEX

437

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
LAK, J R	8212140459	50-261 P	LEVIN, H A	8212140149*	50-29 P	LINEHAN, J J	8212170459*	40-8728
LANDORAF, L C	8212010147	50-341 K	LEVIN, J J	8212070087	50-247 Q	LINEHAN, J J	8212300017	40-8064
LANDRIEU, P R	8212280067	50-354 R	LEVIN, J J	8212070087	50-247 Q	LINER, R T	8212200976*	50-3 P
LANE, V M	8212160304	50-352 Q	LEVIN, J J	8212140439	50-247 Q	LINK, R E	8212100202	50-266 S
LANKFORD, J B	8212090445*	70-1151	LEVIN, J J	8212140439	50-247 Q	LINVILLE, J C	8212030078*	50-333 Q
LAREY, W S	8212290373	50-334 S	LEVIN, J J	8212140446*	50-247 Q	LIPINSKI, W C	8212070438	ACRS
LARSON, C E	8212090392*	50-263 Q	LEVIN, J J	8212140446*	50-247 Q	LIPINSKI, W C	8212070438	ACRS
LARSON, C E	8212280025	50-282 Q	LEVIN, J J	8212210320	50-247 Q	LIPPOLD, W J	8212230274	50-317 P
LARSON, C E	8212060468	NUREQ	LEVIN, J M	8212100394*	50-313 F	LIPPOLD, W J	8212230312	50-318 P
LASATER, G T	8212070345*	50-155 Q	LEVINE, J M	8212160782*	50-313 F	LIPPOLD, W J	8212290120	50-318 P
LASATER, G T	8212070345*	50-155 Q	LEVINE, J M	8212170453*	50-313 F	LIPPOLD, W J	8212290122	50-318 P
LASATER, G T	8212210292*	50-155 Q	LEVINE, J M	8212210320	50-313 F	LIPSCUTZ, D E	8212230241	50-247 Q
LASATER, G T	8212210292*	50-155 Q	LEVINE, J M	8212210339*	50-313 F	LISBON, J	8212160459*	40-6500
LATORRE, V R	8212130370*	50-344 P	LEVINE, J M	8212270143	50-313 S	LITENO, R	8212230312	50-333 S
LAUFER, R J	8212070188	50-329 T	LEVINE, J M	8212280072	50-368 S	LITERSKI, L A	8212130041*	50-10 F
LAUFER, R J	8212070188	50-329 T	LEVINE, J M	8212290486	50-313 S	LITERSKI, L A	8212220202*	50-10 F
LAUNI, C M	8212280489*	50-461 Q	LEVINE, S	7811070329	RES	LITTEL, E O	8212160315*	40-6500
LAUR, B	8212020371*	50-335 S	LEVINE, S	8002260162	RES	LITTEL, E O	8212160350*	40-3265
LAURENSEN, J A	8212070167	50-322 Q	LEVINE, S	8003280100	RES	LITTEL, E O	8212160380*	FOIA
LAVERTY, J H	8212070495*	50-298 P	LEVINE, S	8005281047	RES	LITTEL, E O	8212160391*	FOIA
LAUTON, M D	8212230404	40-8084	LEWIS, S H	8212030010	50-5 P	LITTEL, E O	8212160438*	40-6500
LAUTON, M D	8212230411*	40-8084	LEWIS, R C	82122030212	50-259 Q	LITTEL, E O	8212160310*	40-2116
LAYFIELD, R L	8212280024*	70-146 S	LEWIS, R C	8212030226*	50-259 Q	LITTEL, E O	8212160329*	40-2116
LAZARUS, W	8212140043	50-412 S	LEWIS, R C	8212070018	50-395 Q	LITTEL, E O	8212160341*	FOIA
LAZARUS, W	8212140160*	50-334 Q	LEWIS, R C	8212070030*	50-395 Q	LITTEL, E O	8212160352*	FOIA
LAZARUS, W	8212140168	50-219 S	LEWIS, R C	8212090080	50-259 Q	LITTLE, B H	8212160203*	50-341 Q
LAZARUS, W	8212210089*	50-217 Q	LEWIS, R C	8212090166	50-280 Q	LITTLE, B H	8212170253*	50-341 Q
LAZO, L	8212170410	50-412 A	LEWIS, R C	8212090180*	50-280 Q	LITTLE, M	8212010381	CONTRACT
LEAK, G E	8009170164*	50-409 P	LEWIS, R C	8212090232	50-413 Q	LITTLE, M	8212010388	CONTRACT
LEASBURG, R H	8212070175*	50-280 Q	LEWIS, R C	8212090246*	50-413 Q	LITTLE, M	8212010395	CONTRACT
LEASBURG, R H	8212090218*	50-280 Q	LEWIS, R C	8212090282	50-416 Q	LITTLE, M	8212010403	CONTRACT
LEASBURG, R H	8212090220*	50-280 Q	LEWIS, R C	8212090298*	50-280 Q	LITTLE, M	8212010419	CONTRACT
LEASE, R S	8212290228*	50-316 R	LEWIS, R C	8212090299*	50-324 Q	LITTLE, M	8212010425	CONTRACT
LEBLANC, I	8212290388	50-267 P	LEWIS, R C	8212090316*	50-416 Q	LITTLE, M	8212010432	CONTRACT
LEBO, C D	8212270055*	FOIA	LEWIS, R C	8212090421*	50-416 Q	LITTLE, M	8212010433	CONTRACT
LEBO, C D	8212270059*	FOIA	LEWIS, R C	8212090423	50-302 Q	LITTLE, M	8212060405	CONTRACT
LEBO, C D	8212270065*	FOIA	LEWIS, R C	8212090432	50-348 Q	LITTLE, M	8212080572	CONTRACT
LEBO, C D	8212270088*	FOIA	LEWIS, R C	8212090444*	50-395 Q	LITTLE, W S	8212170087	50-255 Q
LEBO, C D	8212270091*	FOIA	LEWIS, R C	8212090456	50-259 Q	LITTLE, W S	8212170106	50-455 Q
LEDNETTER, J L	8212220553*	CONTRACT	LEWIS, R C	8212090467*	50-259 Q	LITTLE, W S	8212170148	50-154 Q
LEDDICK, R S	8212280121	50-508 Q	LEWIS, R C	8212290109*	50-250 Q	LITTLE, W S	8212170154*	50-155 Q
LEDDICK, R S	8212300075*	50-508 Q	LEWIS, R C	8212290137*	50-250 Q	LITTLE, W S	8212170205	50-483 Q
LEDDICK, R S	8212300274*	50-508 Q	LEWIS, R C	8212290138*	50-261 Q	LITTLE, W S	8212170244	50-341 Q
LEDDICK, R S	8212300324*	50-508 Q	LEWIS, R C	8212290165*	50-261 Q	LITTLE, W S	8212170247*	50-341 Q
LEE, H S	8212020010	RES	LEWIS, R C	8212290184*	50-280 Q	LITTLE, W S	8212170300	50-10 Q
LEE, J C	8212060514	ACRS	LICHTA, E A	8212010448	50-528 A	LITTLE, W S	8212270292	50-282 Q
LEE, J C	8212060514	ACRS	LICHTA, E A	8212080666	50-528 A	LITTLE, W S	8212270334	50-305 Q
LEE, J Y	8212220066*	50-461 T	LICHTA, E A	8212220063	50-528 A	LITTLE, W S	8212290332	50-266 Q
LEE, K W	8212270420	NUREQ	LICHTA, E A	8212270473	50-528 A	LITTLE, W S	8212290346	50-254 Q
LEE, K Y	8212170276*	50-250 P	LICKUS, R H	8212210340*	50-282 Q	LITTLE, W S	8212290376	50-249 Q
LEE, O R	8212200092	50-267 Q	LIDEN, E A	8212010148	50-272 P	LITTLE, W S	8212290380*	50-249 Q
LEE, O R	8212200101*	50-267 Q	LIDEN, E A	8212010155	50-272 P	LITTLE, W S	8212290389	50-295 Q
LEE, O R	8212290367	50-267 Q	LIDEN, E A	8212130192	50-311 P	LIV, W C	8212090536*	50-438 Q
LEC, T D	8212080149*	FOIA	LIDEN, E A	8212130212	50-272 F	LIVERMORE, H H	8212080573*	50-461 Q
LEC, T D	8212090539*	70-143	LIDEN, E A	8212200020	50-272 Q	LIVERMORE, H H	8212100240*	50-461 Q
LEHN, R J	8212070471	RES	LIDEN, E A	8212300306	50-272 F	LLOYD, L L	8212020251	PR
LEIKEN, L	8212210253	70-143	LIDSTONE, C	8212130128	40-8743	LO, T Y	8205240413*	FOIA
LEIKEN, L	8212270238	70-143	LIDSTONE, C	8212230079	40-6622	LO, T Y	8206290144*	FOIA
LEMPGES, T E	8212140029	50-220 R	LIDSTONE, C	8212300129	40-6622	LO, T Y	8208030426*	FOIA
LEMPGES, T E	8212140406*	50-220 Q	LIEBERMAN, A	8212100120	50-440 Q	LOBNER, P R	8212130058	NUREQ
LEMPGES, T E	8212150213*	50-220 Q	LJETZKE, M H	8212270441	NUREQ	LOBOE, B	8212100378	FOIA
LEMPGES, T E	8212200023	PR	LIMOGES, C	8212060152*	50-247 S	LODY, R A	8212010016*	FOIA
LEMPGES, T E	8212200479*	50-220 Q	LINDER, F	8212150084*	50-247 S	LODY, R A	8212010021*	FOIA
LEMPGES, T E	8212290416	50-220 S	LINDER, F	8212030024	50-409 P	LOIS, L	8212230248*	50-29 P
LEMPGES, T E	8212090308*	50-335 Q	LINDER, F	8212070110	50-409 P	LOMANACQ, L M	8212130357*	50-285 P
LENTINE, F O	8212060086	50-295 P	LINDER, F	8212070152	50-409 F	LONG, B M	8212220260	50-440 Q
LENTINE, F O	8212060219	50-295 P	LINDER, F	8212140417*	50-409 Q	LONG, F J	8212290078*	50-250 Q
LENTINE, F O	8212070065	50-295 F	LINDER, F	8212170204	50-409 P	LONG, F J	8212290092*	50-250 Q
LENTINE, F O	8212130035	50-295 P	LINDER, F	8212220323*	50-409 F	LONG, F J	8212290108*	50-250 Q
LENTINE, F O	8212130183	50-295 Q	LINDER, F	8212280059	50-409 P	LONG, F J	8212290114*	50-250 Q
LENTINE, F O	8212130231	50-295 P	LINDER, F	8212280095*	50-409 Q	LONG, F J	8212290118*	50-250 Q
LENTINE, F O	8212210369	50-295 P	LINDER, F	8212280253	50-409 S	LONG, F J	8212290129*	50-250 Q
LENTINE, F O	8212210454	50-295 F	LINDER, F	8212290220	50-409 R	LONG, F J	8212290148*	50-261 Q
LENTINE, F O	8212220431	50-295 P	LINDSEY, I D	8212100117	50-458 Q	LONG, F J	8212290170*	50-280 Q
LEONARD, J R	8212230083*	50-369 F	LINDSEY, I D	8212230192	50-458 Q	LONG, F J	8212290178*	50-280 Q
LESSIE, W O	8212160524	PR	LINEHAN, J J	8212280045	40-8745	LONG, J	8212100235*	50-346 B
LESSOR, L C	8212130346*	50-298 F	LINEHAN, J J	8212010056	40-8064	LONG, J A	8212100005*	QA999
LESSOR, L C	8212290312	50-298 R	LINEHAN, J J	8212010059	40-8380	LONG, R L	8212100060*	50-320 P
LESSOR, L C	8212300106	50-298 S	LINEHAN, J J	8212020001	40-8681	LONG, T	8212280239*	50-346 B
LESSY, R P	8212020326*	50-443 Q	LINEHAN, J J	8212030228	40-8681	LONGENECKER, J	8212010011	50-537 F
LESSY, R P	8212060020	50-443 Q	LINEHAN, J J	8212030235	40-8745	LONGENECKER, J	8212010146	50-537 A
LESSY, R P	8212220136	50-312 Q	LINEHAN, J J	8212030239	40-8681	LONGENECKER, J	8212010161	50-537 A
LESSY, R P	8212290270	50-443 Q	LINEHAN, J J	8212030244	40-8681	LONGENECKER, J	8212020262	50-537 A
LETSCHKE, K J	8212140463	50-322 Q	LINEHAN, J J	8212030251	40-8681	LONGENECKER, J	8212020303	50-537 A
LEVIN, C	8212100045*	50-329 U	LINEHAN, J J	8212030264	40-8380	LONGENECKER, J	8212070226	50-537 A

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
LONGENECKER, J	8212070243	50-537 A	MCDONALD, C E	8212130098	71-6717	MADSEN, G L	8212290431	50-247 F
LONGENECKER, J	8212070311	50-537 A	MCDONALD, C E	8212130107	71-9111	MADSEN, G L	8212290437*	50-247 F
LONGENECKER, J	8212140374	50-537 A	MCDONALD, C E	8212130116	71-9032	MADSEN, G L	8212290460	50-247 Q
LONGENECKER, J	8212150084	50-537 A	MCDONALD, C E	8212130134	71-9151	MADSEN, S H	8212080568*	50-443 A
LONGENECKER, J	8212150133	50-537 A	MCDONALD, C E	8212130136	71-6601	MAIFR, J E	8212080291	50-244 F
LONGENECKER, J	8212150177	50-537 B	MCDONALD, C E	8212130141	71-9094	MAIFR, J E	8212060169	50-244 B
LONGENECKER, J	8212160200	50-537 A	MCDONALD, C E	8212130142	71-9131	MAIFR, J E	8212070094	50-244 P
LONGENECKER, J	8212170190	50-537 A	MCDONALD, C E	8212140302	71-9150	MAIFR, J E	8212070095*	50-244 P
LONGENECKER, J	8212200077	50-537 A	MCDONALD, C E	8212140505	71-9086	MAIFR, J E	8212070282	50-244 P
LONGENECKER, J	8212210045	50-537 A	MCDONALD, C E	8212140509	71-5907	MAIFR, J E	8212080384	50-244 P
LONGENECKER, J	8212210050	50-537 A	MCDONALD, C E	8212140513	71-4909	MAIFR, J E	8212140240	50-244 F
LONGENECKER, J	8212210055	50-537 A	MCDONALD, C E	8212140517*	71-4909	MAIFR, J E	8212140404	50-244 P
LONGENECKER, J	8212230007	50-537 A	MCDONALD, C E	8212160012	71-9006	MAIFR, J E	8212140408*	50-244 P
LONGENECKER, J	8212230237	50-537 A	MCDONALD, C E	8212160016*	71-9006	MAIFR, J E	8212210436	50-244 P
LONGENECKER, J	8212230253	50-537 A	MCDONALD, C E	8212160020	71-170	MAIFR, J E	8212220243	50-244 P
LONGENECKER, J	8212230262	50-537 A	MCDONALD, C E	8212160023*	71-170	MAIFR, J E	8212280388	50-244 F
LONGENECKER, J	8212230263	50-537 A	MCDONALD, C E	8212160026	71-486	MALANG, S	8212270416	RES
LONGENECKER, J	8212230300	50-537 A	MCDONALD, C E	8212160028*	71-486	MALKANI, R	8212080583*	CONTRACT
LONGENECKER, J	8212230321	50-537 A	MCDONALD, C E	8212160032	71-9099	MALLANDA, J J	8212170379*	50-397 A
LONGENECKER, J	8212270185	50-537 A	MCDONALD, C E	8212160035*	71-9099	MALLORY, C H	8212130095	71-9151
LONGENECKER, J	8212270229	50-537 A	MCDONALD, C E	8212160038	71-6003	MALI DRY, C H	8212150282	71-9151
LONGENECKER, J	8212270231	50-537 A	MCDONALD, C E	8212160041*	71-6003	MALHROS, H H	8212270431*	50-244 Q
LONGENECKER, J	8212270248	50-537 A	MCDONALD, C E	8212160169	71-6717	MALONEY, C	8212230241	50-247 Q
LONGENECKER, J	8212270294	50-537 F	MCDONALD, C E	8212160177	71-489	MALSCH, M O	8003310489*	50-409 P
LONGENECKER, J	8212270302	50-537 A	MCDONALD, C E	8212160185*	71-489	MALSCH, M O	8103120528*	FOIA
LONGENECKER, J	8212300215	50-537 A	MCDONALD, C E	8212160727	71-4909	MALSCH, M O	8209010092*	FOIA
LONGENECKER, J	8212300248	50-537 B	MCDONALD, C E	8212160733	71-4909	MANEATIS, D A	8212202225*	50-275 P
LONGENECKER, J	8212300253	50-537 A	MCDONALD, C E	8212160738	71-4909	MANGAM, C V	8212080102	50-220 P
LONGENECKER, J	8212300299	50-537 A	MCDONALD, C E	8212160743	71-5939	MANGAM, C V	8212080302	50-220 P
LONGENECKER, J	8212300343	50-537 A	MCDONALD, C E	8212160748	71-9079	MANGAM, C V	8212030050*	50-220 Q
LOTTITO, E	8212220210*	50-317 R	MCDONALD, C E	8212160750	71-6574	MANGAM, C V	8212060204	50-220 F
LOTTITO, E M	8212220208	50-317 R	MCDONALD, C E	8212160755	71-5461	MANGAM, C V	8212080137	50-220 P
LOTTIS, A L	8212010484	RES	MCDONALD, C E	8212160760	71-9151	MANGAM, C V	8212090106	50-220 F
LOTTIS, A L	8212220519	RES	MCDONALD, C E	8212170001	71-5086	MANGAM, C V	8212090134	50-220 P
LOTTIS, A L	8212290512	RES	MCDONALD, C E	8212170002	71-9151	MANGAM, C V	8212170266	50-220 P
LOVE, R B	8212170286*	50-483 Q	MCDONALD, C E	8212170005	71-9132	MANGAM, C V	8212270265	50-220 P
LOVENDALE, P C	8212030114	50-155 S	MCDONALD, C E	8212170010*	71-9132	MANGAM, C V	8212270333	50-220 P
LOVENDALE, P C	8212100023*	50-263 Q	MCDONALD, C E	8212220036	71-5469	MANN, S F	8212030166	50-410 S
LOW, L D	8212160243*	40-6900	MCDONALD, C E	8212220041	71-4909	MANN, S F	8212140092	50-410 S
LOWENTHAL, N	8212100371	FOIA	MCDONALD, C E	8212220518	71-488	MANN, S F	8212140372	50-410 S
LOYSEN, P	8212140478	50-259 H	MCDONALD, C E	8212220526*	71-488	MANN, S F	8212280363	50-410 S
LUHMIG, W C	8212280116*	50-327 S	MCDONALD, C E	8212220831	71-487	MANN, W C	8212080028*	FOIA
LUHMIG, W C	8212280136*	50-328 S	MCDONALD, C E	8212220838*	71-487	MANSER, W C	8212080260	70-143
LUENKE, E A	8212060236	50-142 Q	MCDONALD, C E	8212230018	71-9001	MANSER, W C	8212090469	70-143
LUETT, N	8212080524*	50-373 S	MCDONALD, C E	8212230036	71-484	MANSER, W C	8212130189	70-143
LUETT, W R	8212080410*	50-373 S	MCDONALD, C E	8212230039*	71-484	MANSER, W C	8212150293	70-143
LUKERS, L L	8212220291	NUREQ	MCDONALD, C E	8212230132	71-5814	MANSER, W C	8212160072	70-143
LUNA, C R	8212270010*	50-305 F	MCDONALD, C E	8212270483	71-9073	MANSER, W C	8212160429	70-143
LUNDVALL, A E	8212060071	50-317 P	MCDONALD, C E	8212280020	71-9852	MANSER, W C	8212270124*	70-143
LUNDVALL, A E	8212060293*	50-317 Q	MCDONALD, C E	8212280021*	71-9852	MANSER, W C	8212270544	70-143
LUNDVALL, A E	8212070054	50-317 P	MCDONALD, C E	8212290088	71-9151	HANTELL, A N	8212230331	50-247 Q
LUNDVALL, A E	8212130065	50-317 F	MCDONALD, P E	8212130113	NUREQ	HANTELL, A N	8212230336*	50-247 Q
LUNDVALL, A E	8212160384	50-317 Q	MCDONALD, R	8212230133	WASTE MGT	HARCHAL, J	8212010189	XPORTLIC
LUNDVALL, A E	8212170252	50-317 P	MADSEN, W	8212030147*	50-247 Q	MARCHESI, A R	8206220072*	FOIA
LUNDVALL, A E	8212170349	50-318 Q	MADSEN, W	8212210351	50-309 Q	MARGULIES, T	8212140476	NUREQ
LUNDVALL, A E	8212200088	50-318 P	MADSEN, W	8212290479*	50-219 Q	MARTINGAS, N	8212010519*	50-352 A
LUNDVALL, A E	8212210420	50-317 P	MADSEN, W J	8212030090*	50-387 Q	MARKEY, E J	8212230276	50-247 U
LUNDVALL, A E	8212210447	50-317 P	MADSEN, T J	8212140414*	50-151 Q	MARKEY, E J	8209150008*	COMMISSION
LUNDVALL, A E	8212280199	50-318 P	MADISON, A	8212030028*	50-373 Q	MARRACK, D	8212160434	PR
LUNDVALL, A E	8212290338	50-318 Q	MADSEN, G L	8212030151	50-445 Q	MARSHALL, J R	8212030066	50-368 S
LUNDY, R T	8212060429	NUREQ	MADSEN, G L	8212070119	50-382 Q	MARSHALL, J R	8212030097	50-313 S
LUNDY, R T	8212060441	NUREQ	MADSEN, G L	8212070126	50-112 Q	MARSHALL, J R	8212030149	50-313 P
LUNDY, R T	8212060451	NUREQ	MADSEN, G L	8212070137	50-298 Q	MARSHALL, J R	8212060087	50-313 Q
LUNDY, R T	8212060455	NUREQ	MADSEN, G L	8212070223	50-382 Q	MARSHALL, J R	8212060262	50-313 P
LURIA, N O	8212210414*	50-322 E	MADSEN, G L	8212070255	50-267 Q	MARSHALL, J R	8212060333	50-313 P
LUSIS, E	8212230309	50-341 Q	MADSEN, G L	8212100212*	50-298 Q	MARSHALL, J R	8212070284	50-313 F
LYANS, J A	8212220249	NUREQ	MADSEN, G L	8212100213*	50-298 Q	MARSHALL, J R	8212090311	50-313 F
LYNCH, J L	8212060062*	50-409 Q	MADSEN, G L	8212100236	50-458 Q	MARSHALL, J R	8212140334	50-368 Q
MA, B H	7908140789*	50-219 P	MADSEN, G L	8212100265	50-298 Q	MARSHALL, J R	8212140481	50-313 Q
MACCREADY, P B	8212060336*	40-8743	MADSEN, G L	8212140157	50-445 Q	MARSHALL, J R	8212130288*	50-313 F
MCDONALD, C E	8212100037	71-483	MADSEN, G L	8212180040	50-112 Q	MARSHALL, J R	8212170113	50-313 P
MCDONALD, C E	8212100057	71-206	MADSEN, G L	8212200006	50-267 F	MARSHALL, J R	8212170215	50-368 P
MCDONALD, C E	8212100062*	71-206	MADSEN, G L	8212200025	50-267 F	MARSHALL, J R	8212210027	50-368 S
MCDONALD, C E	8212100066	71-370	MADSEN, G L	8212200076	50-458 Q	MARSHALL, J R	8212210039	50-368 P
MCDONALD, C E	8212100069*	71-370	MADSEN, G L	8212200084	50-267 Q	MARSHALL, J R	8212210117	50-368 S
MCDONALD, C E	8212100420	71-6717	MADSEN, G L	8212200096	50-267 F	MARSHALL, J R	8212210166	50-313 S
MCDONALD, C E	8212100425	71-9081	MADSEN, G L	8212200108	50-267 F	MARSHALL, J R	8212210169*	50-313 S
MCDONALD, C E	8212130001	71-5910	MADSEN, G L	8212200109	50-267 F	MARSHALL, J R	8212210173	50-368 S
MCDONALD, C E	8212130004	71-5089	MADSEN, G L	8212200125*	50-382 Q	MARSHALL, J R	8212210257	50-368 S
MCDONALD, C E	8212130010	71-5942	MADSEN, G L	8212200126*	50-382 Q	MARSHALL, J R	8212230165*	50-313 F
MCDONALD, C E	8212130038	71-6347	MADSEN, G L	8212210023	50-267 Q	MARSHALL, J R	8212270189	50-368 S
MCDONALD, C E	8212130068	71-454	MADSEN, G L	8212210167	50-267 Q	MARSHALL, J R	8212280142	50-368 S
MCDONALD, C E	8212130074*	71-454	MADSEN, G L	8212280374	50-382 Q	MARSHALL, J R	8212280224	50-313 F
MCDONALD, C E	8212130082	71-9156	MADSEN, G L	8212280409	50-298 Q	MARSHALL, J R	8212280459	50-368 P
MCDONALD, C E	8212130089	71-9156	MADSEN, G L	8212290427*	50-267 P	MARSHALL, J R	8212290168	50-313 R

PERSONAL AUTHOR INDEX

439

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
MARSHALL, J R	8212290194	50-313 R	MATLOCK, R O	8212060179	50-397 S	MCCANN, J F	8212070158*	50-387 Q
MARSHALL, J R	8212290198*	50-313 Q	MATLOCK, R O	8212060289	50-397 S	MCCANN, J F	8212290468*	50-387 Q
MARSHALL, J R	8212290212	50-368 S	MATLOCK, R O	8212210386	50-397 S	MCCLOSKEY, J P	82122030258	40-8511
MARSHALL, J R	8212290234	50-368 R	MATLOCK, R O	8212280443	50-397 Q	MCCLOSKEY, J P	8212100243	WASTE MGT
MARSHALL, J R	8212290321	50-313 S	MATTHEWS, T P	8212200064*	50-285 R	MCCONNELL, T	8212070353*	50-249 P
MARSHALL, J R	8212300052	50-368 S	MATTIA, J C	8212140337*	50-423 Q	MCCORKLE, O H	8212100147*	FOIA
MARSHALL, J R	8212300057	50-368 S	MATTIA, M J	8212130364	CONTRACT	MCCORMACK, G H	8212280030*	70-146
MARSHALL, J R	8212300088	50-368 S	MATTIA, M J	8212280478*	CONTRACT	MCCOY, R W	8212160316*	50-352 Q
MARSHALL, J S	8212130301	50-445 K	MATTIA, M J	8212280491*	CONTRACT	MCCRACKEN, C	8212270038	50-289 P
MARSHALL, R K	8212220265	NUREG	MATTIMOE, J J	8212030081	50-312 S	MCCREE, W B	8212230083*	50-349 F
MARSHALL, W H	8212220197	50-329 Q	MATTIMOE, J J	8212030084	50-312 S	MCCRORY, S L	8212100271*	50-298 Q
MARSTON, R R	8212090274*	70-1201	MATTIMOE, J J	8212030110	50-312 S	MCDERMOTT, D	8212060114	CONTRACT
MARSTON, R R	8212090294*	70-624	MATTIMOE, J J	8212060294	50-312 S	MCDERMOTT, D	8212100124	CONTRACT
MARTIN, J D	8210150165*	50-341 F	MATTIMOE, J J	8212070220	50-312 Q	MCDONALD, R J	8212020194*	CONTRACT
MARTIN, J D	8212100303*	50-331 Q	MATTIMOE, J J	8212070277	50-312 Q	MCDUFFIE, H A	8212130181	50-400 A
MARTIN, J D	8212220460	50-341 F	MATTIMOE, J J	8212070410	50-312 Q	MCDUFFIE, H A	8212160036	50-400 D
MARTIN, J B	8212220382	WASTE MGT	MATTIMOE, J J	8212130337	50-312 F	MCDUFFIE, H A	8212210422	50-400 C
MARTIN, J B	82122270444	WASTE MGT	MATTIMOE, J J	8212140351	50-312 P	MCGARRY, J M	8207180063	50-298 Q
MARTIN, T J	8212080502	50-354 S	MATTIMOE, J J	8212140391	50-312 P	MCGARRY, J M	8212130230	50-413 Q
MARTIN, T J	8212160024	50-354 Q	MATTIMOE, J J	8212170198	50-312 F	MCGARRY, J M	8212130230	50-413 Q
MARTIN, T J	8212290444*	50-354 Q	MATTIMOE, J J	8212170220	50-312 P	MCGARRY, J M	8212160261	50-413 Q
MARTIN, T T	8212010002	PT21	MATTIMOE, J J	8212170255	50-312 P	MCGARRY, J M	8212160261	50-413 Q
MARTIN, T T	8212030018	50-220 Q	MATTIMOE, J J	8212170301	50-312 Q	MCGARRY, J M	8212220232	50-413 Q
MARTIN, T T	8212030029	70-1100	MATTIMOE, J J	8212170319	50-312 P	MCGARRY, J M	8212220232	50-413 Q
MARTIN, T T	8212030030	50-219 Q	MATTIMOE, J J	8212210439	50-312 V	MCGARRY, J M	8212220239*	50-413 Q
MARTIN, T T	8212030034	50-220 Q	MATTIMOE, J J	8212220241	50-312 F	MCGARRY, J M	8212220239*	50-413 Q
MARTIN, T T	8212030035	50-244 Q	MATTIMOE, J J	8212280233	50-312 P	MCGARRY, J M	8212270244	50-413 Q
MARTIN, T T	8212030045	50-336 Q	MATTIMOE, J J	8212300352*	50-312 Q	MCGARRY, J M	8212270244	50-413 Q
MARTIN, T T	8212030087	50-387 Q	MATTISON, R J	8212090005*	50-289 P	MCGARRY, J M	8212270321	50-413 Q
MARTIN, T T	8212030093	50-387 Q	MATTISON, R J	8212130289*	50-275 P	MCGARRY, J M	8212270321	50-413 Q
MARTIN, T T	8212030141	50-247 Q	MATTISON, R J	8212220475*	50-275 P	MCGAUGHY, J P	8212080033	50-416 S
MARTIN, T T	8212030144	50-272 Q	MAUPIN, M H	8212280122	50-338 Q	MCGAUGHY, J P	8212020050	50-416 S
MARTIN, T T	8212030165	50-213 Q	MAUPIN, M H	8212280135	50-338 Q	MCGAUGHY, J P	8212020058	50-416 S
MARTIN, T T	8212030167	50-336 Q	MAURIN, L V	8212030036	50-382 S	MCGAUGHY, J P	8212020138	50-416 S
MARTIN, T T	8212030193	50-289 Q	MAURIN, L V	8212030048	50-382 S	MCGAUGHY, J P	8212090074	50-416 S
MARTIN, T T	8212030195	50-293 Q	MAURIN, L V	8212030055	50-382 S	MCGAUGHY, J P	8212090078	50-416 S
MARTIN, T T	8212030215	50-289 Q	MAURIN, L V	8212070228*	50-382 Q	MCGAUGHY, J P	8212090110	50-416 S
MARTIN, T T	8212060187	50-423 Q	MAURIN, L V	8212090203	50-382 F	MCGAUGHY, J P	8212090131	50-416 S
MARTIN, T T	8212060209	HISC	MAURIN, L V	8212100002	50-382 A	MCGAUGHY, J P	8212090151	50-416 S
MARTIN, T T	8212060215	50-309 Q	MAURIN, L V	8212140395	50-382 S	MCGAUGHY, J P	8212090159	50-416 S
MARTIN, T T	8212060234	50-322 Q	MAURIN, L V	8212150042	50-382 F	MCGAUGHY, J P	8212090177	50-416 S
MARTIN, T T	8212060235	50-247 Q	MAURIN, L V	8212200127*	50-382 Q	MCGAUGHY, J P	8212090191	50-416 S
MARTIN, T T	8212060270	50-293 F	MAURIN, L V	8212200129*	50-382 Q	MCGAUGHY, J P	8212090290*	50-416 Q
MARTIN, T T	8212070120	50-322 Q	MAURIN, L V	8212210066	50-382 S	MCGAUGHY, J P	8212090303*	50-416 Q
MARTIN, T T	8212070144	50-309 Q	MAURIN, L V	8212210172	50-382 S	MCGAUGHY, J P	8212090310*	50-416 Q
MARTIN, T T	8212100038	50-334 Q	MAURIN, L V	8212210230	50-382 S	MCGAUGHY, J P	8212090326	50-416 S
MARTIN, T T	8212100059	50-387 Q	MAURIN, L V	8212210281	50-382 S	MCGAUGHY, J P	8212100297	50-416 S
MARTIN, T T	8212100073	50-219 Q	MAURIN, L V	8212270015*	50-382 F	MCGAUGHY, J P	8212170137	50-416 S
MARTIN, T T	8212140208	50-245 Q	MAURIN, L V	8212270130	50-382 S	MCGAUGHY, J P	8212170209	50-416 S
MARTIN, T T	8212140225	50-333 Q	MAURIN, L V	8212270138	50-382 S	MCGAUGHY, J P	8212170222	50-416 S
MARTIN, T T	8212140251	70-2895	MAURIN, L V	8212270160	50-382 A	MCGAUGHY, J P	8212170263	50-416 S
MARTIN, T T	8212140303	70-2487	MAURIN, L V	8212270166	50-382 S	MCGAUGHY, J P	8212170313	50-416 S
MARTIN, T T	8212150121	50-333 Q	MAURIN, L V	8212270257	50-382 S	MCGAUGHY, J P	8212170334	50-416 S
MARTIN, T T	8212160397	50-289 Q	MAURIN, L V	8212280143	50-382 S	MCGAUGHY, J P	8212200103	50-416 S
MARTIN, T T	8212210129	50-277 Q	MAURIN, L V	8212280169	50-382 S	MCGAUGHY, J P	8212210155	50-416 S
MARTIN, T T	8212210263	50-309 Q	MAURIN, L V	8212280203	50-382 S	MCGAUGHY, J P	8212210179	50-416 S
MARTIN, T T	8212210349	50-309 Q	MAURIN, L V	8212290245	50-382 Q	MCGAUGHY, J P	8212210191	50-416 S
MARTIN, T T	8212210376	70-687	MAURIN, L V	8212300162	50-382 A	MCGAUGHY, J P	8212210212	50-416 S
MARTIN, T T	8212220350	50-244 Q	MAURIN, L V	8212300198	50-382 S	MCGAUGHY, J P	8212210367	50-416 S
MARTIN, T T	8212220383	50-289 Q	MAURIN, L V	8212300219	50-382 S	MCGAUGHY, J P	8212210375	50-416 S
MARTIN, T T	8212220400	50-387 Q	MAURIN, L V	8212300288	50-382 S	MCGAUGHY, J P	8212270147	50-416 P
MARTIN, T T	8212220436	70-135	MAURIN, L V	8212300310	50-382 S	MCGAUGHY, J P	8212280036	50-416 S
MARTIN, T T	8212230330	70-1143	MAUSSHARDT, D B	8212100174	40-2061	MCGAUGHY, J P	8212280080	50-416 S
MARTIN, T T	8212270252	70-820	MAUSSHARDT, D B	8212100496	40-2061	MCGAUGHY, J P	8212280150	50-416 S
MARTIN, T T	8212280200	50-317 Q	MAY, E L	8212290258*	50-29 S	MCGAUGHY, J P	8212280177	50-416 S
MARTIN, T T	8212280385	50-320 Q	MAY, F L	8212290316*	50-29 S	MCGAUGHY, J P	8212280194	50-416 S
MARTIN, T T	8212290351	70-820	MCALPINE, E J	8212090265*	70-824	MCGAUGHY, J P	8212280241	50-416 S
MARTIN, T T	8212290360	70-1100	MCALPINE, E J	8212090270*	70-1113	MCGAUGHY, J P	8212280308	50-416 S
MARTIN, T T	8212290368	40-8610	MCALPINE, E J	8212090278*	70-1151	MCGAUGHY, J P	8212280312	50-416 S
MARTIN, T T	8212290375	50-244 Q	MCALPINE, E J	8212090340*	70-1201	MCGAUGHY, J P	8212280327	50-416 S
MARTIN, T T	8212290408	50-219 Q	MCALPINE, E J	8212090413*	70-143	MCGAUGHY, J P	8212280344	50-416 S
MARTIN, T T	8212290435	50-272 Q	MCALPINE, E J	8212090416*	70-143	MCGAUGHY, J P	8212280377	50-416 S
MARTIN, T T	8212290477	50-219 Q	MCALPINE, E J	8212090445*	70-1151	MCGAUGHY, J P	8212280384	50-416 S
MASON, C C	8212290159	50-327 R	MCALPINE, E J	8212090451*	50-332 Q	MCGAUGHY, J P	8212280402	50-416 S
MASON, C C	8212290164*	50-327 R	MCALPINE, E J	8212090539*	70-143	MCGAUGHY, J P	8212280458	50-416 S
MASSARO, S A	8212130140	NUREG	MCALPINE, E J	8212150088	70-143	MCGAUGHY, J P	8212280466	50-416 S
MASTERS, B R	8212210327*	50-263 P	MCCABE, E	8212130112*	50-267 R	MCGAUGHY, J P	8212300039	50-416 S
MATHIS, C J	8212130303	50-341 A	MCCABE, E	8212290394*	50-267 R	MCGAUGHY, J P	8212300084	50-416 S
MATHIS, C J	8212060198	50-293 S	MCCABE, E	8212060305	50-317 S	MCGAUGHY, J P	8212300114	50-416 S
MATHIS, C J	8212060210	50-293 S	MCCABE, E	8212020003	50-317 Q	MCGAUGHY, J P	8212300186	50-416 S
MATHIS, C J	8212210067	50-293 S	MCCABE, E C	8212070158*	50-387 Q	MCGAUGHY, J P	8212300222	50-416 S
MATHIS, C J	8212210148	50-293 S	MCCABE, E C	8212070267*	50-352 Q	MCGOVERN, J J	8212160245	70-687
MATHIS, C J	8212210249	50-293 S	MCCABE, E C	8212100013*	50-317 Q	MCGUIRE, D R	8212030232*	50-259 Q
MATLOCK, R O	8210270018*	50-397 A	MCCABE, E C	8212160491*	50-277 Q	MCGUIRE, D R	8212070034*	50-395 Q
MATLOCK, R O	8212060021	50-397 Q	MCCABE, E C	8212270468*	50-387 Q	MCGUIRE, D R	8212070206*	50-338 Q

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
MCQUIRE, D R	8212090124*	50-259 Q	MIKAMI, H	8212010133*	XPORTLIC	MILLS, L M	8212100270	50-370 S
MCQUIRE, D R	8212090185*	50-280 Q	MILHOLLIN, O L	8212070160	50-237 Q	MILLS, L M	8212140047	50-438 S
MCQUIRE, D R	8212150090	50-321 S	MILHOLLIN, O L	8212070234	50-341 Q	MILLS, L M	8212140087	50-370 S
MCQUIRE, D R	8212150143*	70-143	MILLER, B K	8212020126	RES	MILLS, L M	8212140141	50-390 S
MCURREN, H J	8212170174	50-247 Q	MILLER, D E	8212060197*	50-254 Q	MILLS, L M	8212140164	50-390 S
MCURREN, H J	8212280014	50-247 Q	MILLER, D E	8212080296*	50-295 Q	MILLS, L M	8212140371	50-439 S
MCUGH, H	8212230027*	50-247 U	MILLER, D E	8212280062*	50-295 Q	MILLS, L M	8212140376	50-390 S
MCINNES, I D	8212210330*	50-263 P	MILLER, O N	8212130123	NUREG	MILLS, L M	8212140415	50-438 S
MCINNES, I D	8212210333*	50-263 P	MILLER, H J	8212010065	WASTE MGT	MILLS, L M	8212190079	50-438 S
MCINNES, I D	8212210337*	50-263 P	MILLER, H J	8212010302	WASTE MGT	MILLS, L M	8212150136	50-390 S
MCINTEER, H A	8212270042*	50-289 P	MILLER, H J	8212020114	WASTE MGT	MILLS, L M	8212170108*	50-259 F
MCILVY, O A	8212220415	50-289 F	MILLER, H J	8212020132	WASTE MGT	MILLS, L M	8212170136	50-260 P
MCIELVY, O A	8212220421*	50-289 F	MILLER, H J	8212020201	WASTE MGT	MILLS, L M	8212170157	50-438 S
MCKENNA, K J	8212130152	NUREG	MILLER, J J	8212080041*	FOIA	MILLS, L M	8212170160	50-438 S
MCKENNA, K J	8212270145	NUREG	MILLER, J R	8212020310*	50-254 Q	MILLS, L M	8212170221	50-438 S
MCLEOD, L H	8212030175*	50-213 Q	MILLER, J R	8212060191	50-254 Q	MILLS, L M	8212170229	50-259 F
MCLEOD, L H	8212290443*	50-272 Q	MILLER, J R	8212080282	50-295 Q	MILLS, L M	8212170236	50-327 P
MCLEOD, L H	8212080331	50-186 P	MILLER, J R	8212090325	50-254 Q	MILLS, L M	8212170239	50-327 P
MCLEOD, L H	8212030064*	50-395 S	MILLER, J R	8212090343	50-263 Q	MILLS, L M	8212170259	50-327 F
MCLEOD, L H	8212030171*	50-395 S	MILLER, J R	8212090387	50-155 Q	MILLS, L M	8212170318	50-327 Q
MCINNEY, C J	8212030199*	50-395 S	MILLER, J R	8212140396	50-151 Q	MILLS, L M	8212170388	50-327 R
MCINNEY, C J	8212150081*	50-395 S	MILLER, J R	8212140399*	50-151 Q	MILLS, L M	8212200001	50-390 S
MCINNEY, C J	8212150100*	50-395 S	MILLER, J R	8212280058	50-295 Q	MILLS, L M	8212200017	50-390 S
MCINNEY, C J	8212280115*	50-395 S	MILLER, J R	8212280091	50-409 Q	MILLS, L M	8212280052	50-518 S
MCINNEY, C J	8212220337*	50-395 S	MILLER, J R	8212280214	50-10 Q	MILLS, L M	8212210026	50-390 S
MCINNEY, C J	8212220364*	50-395 S	MILLER, L K	8212230271*	50-272 R	MILLS, L M	8212210122	50-438 S
MCINNEY, C J	8212220414*	50-395 S	MILLER, L K	8212270280*	50-311 R	MILLS, L M	8212210217	50-390 S
MCINNEY, S	8212230276	50-247 U	MILLER, L K	8212280066	50-272 R	MILLS, L M	8212210256	50-438 S
MCINNEY, T R	8212290104*	50-266 P	MILLER, L K	8212280068*	50-272 R	MILLS, L M	8212210356	50-390 S
MCLEAREN, T	8212020387	CONTRACT	MILLER, M E	8212090095	50-445 Q	MILLS, L M	8212210360	50-371 Q
MCLEAREN, T	8212020402	CONTRACT	MILLER, M E	8212230353	50-445 Q	MILLS, L M	8212210364	50-438 S
MCLEAREN, T	8212060502	CONTRACT	MILLER, R	8212020308	50-254 Q	MILLS, L M	8212210431	50-390 S
MCLEAREN, T	8212290166*	50-244 R	MILLER, R	8212160009	71-489	MILLS, L M	8212210445	50-390 S
MCNEILL, C A	8212060091	50-333 S	MILLER, R P.	8212160608*	CONTRACT	MILLS, L M	8212210451	50-390 S
MCNEILL, C A	8212060223	50-333 S	MILLER, W H	8212090275*	50-389 Q	MILLS, L M	8212220419	50-438 S
MCNEILL, C A	8212060292	50-333 S	MILLER, W H	8212090321*	50-324 Q	MILLS, L M	8212220426	50-390 S
MCNEILL, C A	8212080374	50-333 Q	MILLER, W O	8212200157	50-206 P	MILLS, L M	8212220485	50-390 S
MCNEILL, C A	8212080394	50-333 S	MILLER, W O	8212070463	50-331 P	MILLS, L M	8212270192	50-259 P
MCNEILL, C A	8212130081	50-333 R	MILLER, W O	8212080026	50-305 P	MILLS, L M	8212270262	50-390 A
MCNEILL, C A	8212140236*	50-333 Q	MILLER, W O	8212150296	50-324 F	MILLS, L M	8212270355	50-390 A
MCNEILL, C A	8212150126*	50-333 Q	MILLER, W O	8212220515	50-313 P	MILLS, L M	8212280064	50-438 S
MCNEILL, C A	8212210268	50-333 S	MILLER, W O	8212220530	50-302 Q	MILLS, L M	8212280095	50-259 P
MCNEILL, C A	8212210415	50-333 S	MILLER, W H	8212070340*	50-155 Q	MILLS, L M	8212280100	50-438 S
MCNEILL, R	8212140277*	50-275 P	MILLIGAN, H H	8212160065	50-322 S	MILLS, L M	8212280210	50-438 S
MCNEILL, W H	8212070122*	QA999	MILLS, L M	8212020107	50-438 S	MILLS, L M	8212280295	50-259 P
MCNEILL, W H	8212300263*	QA999	MILLS, L M	8212020137	50-438 S	MILLS, L M	8212280305	50-438 S
MCNEILL, W H	8212280106*	50-260 S	MILLS, L M	8212020139	50-438 S	MILLS, L M	8212280328	50-438 S
MCNEILL, W H	8212090179	50-361 P	MILLS, L M	8212020149	50-438 S	MILLS, L M	8212280340	50-438 S
MCNEILL, W H	8212270318*	50-454 Q	MILLS, L M	8212020162	50-438 S	MILLS, L M	8212280355	50-390 S
MCNEILL, W H	8212060159*	50-361 Q	MILLS, L M	8212020298	50-390 S	MILLS, L M	8212280358	50-438 S
MENDONCA, M H	8212060261*	50-275 Q	MILLS, L M	8212020368	50-390 S	MILLS, L M	8212280437	50-438 K
MENDONCA, M H	8212090355*	50-400 Q	MILLS, L M	8212030001	50-390 S	MILLS, L M	8212290356	50-327 P
MENDONCA, M H	8212230241*	50-247 Q	MILLS, L M	8212030071	50-259 R	MILLS, L M	8212300006	50-438 S
MENDONCA, M H	8212220282	NUREG	MILLS, L M	8212030072	50-438 S	MILLS, L M	8212300293	50-327 P
MENDONCA, M H	8212290446	YOPREP	MILLS, L M	8212030152	50-438 S	MILLS, L M	8212300351	50-327 P
MEYER, K A	8212230274*	50-331 F	MILLS, L M	8212030220*	50-259 Q	MILLS, L M	8212300357	50-327 P
MEYER, K A	8212230377*	50-331 F	MILLS, L M	8212060023	50-327 P	MILLS, L M	8212170311*	50-331 P
MICHAELS, T S	8101080118*	50-255 P	MILLS, L M	8212060061	50-327 P	MILLS, L M	8212060221	50-331 S
MICHAELS, T S	8212080092*	FOIA	MILLS, L M	8212060070	50-390 E	MINECK, D L	8212140134	50-331 R
MICHAELS, T S	8212230241	50-247 Q	MILLS, L M	8212060076	50-527 P	MINECK, D L	8212140142	50-331 S
MIDURA, H J	8210210078	50-311 S	MILLS, L M	8212060081	50-390 A	MINECK, D L	8212140332	50-331 S
MIDURA, H J	8212030117	50-271 S	MILLS, L M	8212070058	50-390 S	MINECK, D L	8212210033	50-331 S
MIDURA, H J	8212060165	50-311 S	MILLS, L M	8212070142	50-390 S	MINECK, D L	8212210070	50-331 R
MIDURA, H J	8212060202	50-311 S	MILLS, L M	8212070176	50-327 P	MINECK, D L	8212210209	50-331 R
MIDURA, H J	8212060291	50-272 S	MILLS, L M	8212070180	50-327 F	MINECK, D L	8212210352	50-331 S
MIDURA, H J	8212060302	50-272 S	MILLS, L M	8212070186	50-390 A	MINECK, D L	8212280454	50-331 S
MIDURA, H J	8212060309	50-272 S	MILLS, L M	8212070267	50-390 S	MINECK, D L	8212010329	50-302 P
MIDURA, H J	8212080356	50-272 S	MILLS, L M	8212070288	50-259 P	MINECK, D L	8212080110	50-312 P
MIDURA, H J	8212080434	50-311 S	MILLS, L M	8212070291	50-390 A	MINECK, D L	8212170078	50-312 P
MIDURA, H J	8212140053	50-272 S	MILLS, L M	8212080108*	50-259 F	MINECK, D L	8212290283	50-312 P
MIDURA, H J	8212140074	50-272 S	MILLS, L M	8212080373	50-327 P	MINECK, D L	8212220282	NUREG
MIDURA, H J	8212140079	50-311 S	MILLS, L M	8212090054	50-390 S	MINECK, J R	8212010191	50-341 Q
MIDURA, H J	8212140099	50-311 S	MILLS, L M	8212090055	50-518 A	MINECK, J R	8212010191	50-341 Q
MIDURA, H J	8212160048	50-311 S	MILLS, L M	8212090083	50-259 P	MINECK, J R	8212140428	50-341 Q
MIDURA, H J	8212160381	50-311 S	MILLS, L M	8212090092*	50-259 Q	MINECK, J R	8212140428	50-341 Q
MIDURA, H J	8212160399	50-311 S	MILLS, L M	8212090099	50-328 S	MINECK, J R	8103250465	RES
MIDURA, H J	8212220300	50-272 S	MILLS, L M	8212090150	50-390 S	MINECK, J R	8104170658	RES
MIDURA, H J	8212220381	50-311 S	MILLS, L M	8212090160	50-390 S	MINECK, J R	8104170664	RES
MIDURA, H J	8212220395	50-311 S	MILLS, L M	8212090163	50-438 S	MINECK, J R	8109280378	RES
MIDURA, H J	8212220420	50-311 S	MILLS, L M	8212090165	50-390 S	MINECK, J R	8111130045	RES
MIDURA, H J	8212220433	50-311 S	MILLS, L M	8212090170	50-390 S	MINECK, J R	8201150075	RES
MIDURA, H J	8212230268	50-272 R	MILLS, L M	8212090347*	50-390 Q	MINECK, J R	8201180563	RES
MIDURA, H J	8212270274	50-311 R	MILLS, L M	8212090355*	50-327 Q	MINECK, J R	8201220290	RES
MIDURA, H J	8212280122*	50-315 R	MILLS, L M	8212090461*	50-259 Q	MINECK, J R	8202260369	RES
MIDURA, H J	8212010120*	XPORTLIC	MILLS, L M	8212090541	50-390 S	MINECK, J R	8207200458	RES

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
NIX, H C	8212210083	50-321 S	NULSEN, B	8212100142*	FOIA	ONISHI, Y	8212220509	NUREG
NIX, H C	8212210188	50-321 S	NULSEN, C K	8212100155*	FOIA	OPREA, G W	8212030100	50-498 S
NIX, H C	8212210446	50-366 S	NUSSBAUMER, D A	8212010496	WASTE MGT	OPREA, G W	8212270172	50-498 S
NIX, H C	8212280159	50-366 S	NUSSBAUMER, D A	8212160090*	FOIA	OPREA, G W	8212290202*	50-498 S
NIX, H C	8212280180	50-321 S	NUSSBAUMER, D A	8212160097*	40-6500	OPERS, W	8212090189*	50-249 Q
NIX, H C	8212280387	50-321 S	NUSSBAUMER, D A	8212160197*	40-6500	ORDERS, W J	8212090313*	50-280 Q
NIX, H C	8212300058	50-366 S	NUSSBAUMER, D A	8212160214*	40-6500	ORNSTEIN, P M	8212230191	WASTE MGT
NIX, H C	8212300071	50-321 S	NUSSBAUMER, D A	8212160260*	40-6500	OSBORNE, M F	8212160549	RES
NIX, H C	8212300098	50-366 S	NUSSBAUMER, D A	8212160273*	40-6500	OSBORNE, M P	8212270320*	50-445 Q
NIX, H C	8212300265	50-321 S	NUSSBAUMER, D A	8212160307*	40-6500	OSTER, C A	8212270559	NUREG
NIX, H C	8212300271	50-321 S	NUSSBAUMER, D A	8212280016*	70-146	OTTER, W M	8212100398*	FOIA
NIX, H C	8212300277	50-321 S	NUSSBAUTIER, D A	8212280019*	70-146	OWATZARSKI, P C	8212300402	RES
NIX, H C	8212300284	50-366 S	NYKIEL, A	8212020285*	50-295 S	OWEN, T B	8212070348*	50-269 P
NIX, H C	8212300285	50-366 S	O'BRIEN, J P	8212060171*	50-312 Q	OWSLY, G F	8212280401	50-316 P
NIX, H C	8212300287	50-321 S	O'NEILL, B	8212070111*	50-320 Q	OZTUNALI, G I	8212280478*	CONTRACT
NIX, H C	8212300299	50-366 S	O'NEILL, D	8212140319*	50-320 Q	PACF, P	8212290169*	50-290 R
NIX, H C	8212300323	50-366 S	O'NEILL, B	8212220471*	50-289 Q	PAGE, M	8212070450	CONTRACT
NIX, H C	8212300328	50-321 S	O'NEILL, J H	8212210222	50-400 Q	PAGE, M	8212270080*	FOIA
NIX, H C	8212300329	50-321 S	O'NEILL, J H	8212210222	50-400 Q	PAGE, M	8212270599	FOIA
NIX, H C	8212300340	50-366 S	O'NEILL, J P	8212080105*	70-143	PAGE, M	8212270133*	FOIA
NIX, H C	8212300344	50-366 S	O'REILLY, J P	8212090108*	50-299 Q	PAGE, M	8212280043	CONTRACT
NIXON, W A	8212070474	40-2061	O'REILLY, J P	8212090111	50-324 Q	PAGE, R G	8212010369	70-36
NOONAN, V S	8211120491*	HISC	O'REILLY, J P	8212090118	50-299 P	PAGE, R G	8212010372*	70-36
NORDERHAUG, L R	8212060228	50-361 Q	O'REILLY, J P	8212090129	50-324 Q	PAGE, R G	8212010489	40-2061
NORDERHAUG, L R	8212090068	70-1359	O'REILLY, J P	8212090132	50-302 F	PAGE, R G	8212010497	70-371
NORDERHAUG, L R	8212090071*	70-1359	O'REILLY, J P	8212090157	State Prog	PAGE, R G	8212010503	70-734
NORDERHAUG, L R	8212090532	50-206 Q	O'REILLY, J P	8212090161	50-338 Q	PAGE, R G	8212080045	70-27
NORDERHAUG, L R	8212130163	50-312 Q	O'REILLY, J P	8212090208	40-8355	PAGE, R G	8212080654	70-698
NORDERHAUG, L R	8212170304	50-344 Q	O'REILLY, J P	8212090285	50-280 Q	PAGE, R G	8212080671*	70-698
NORDERHAUG, L R	8212210240	70-25	O'REILLY, J P	8212090315	State Prog	PAGE, R G	8212100178	70-1334
NORDERHAUG, L R	8212210246*	50-25 C	O'REILLY, J P	8212090346	50-299 P	PAGE, R G	8212130285	70-2957
NORDERHAUG, L R	8212210362	50-362 Q	O'REILLY, J P	8212090355	70-143	PAGE, R G	8212160171*	40-6500
NORFELIUS, C E	8212060074	50-346 Q	O'REILLY, J P	8212090390	State Prog	PAGE, R G	8212170004	70-2928
NORFELIUS, C E	8212060318	50-331 Q	O'REILLY, J P	8212090398	50-395 Q	PAGE, R G	8212270026	70-2941
NORFELIUS, C E	8212080664*	50-373 P	O'REILLY, J P	8212090406	50-395 Q	PAGI IARD, J A	8212060232*	50-409 Q
NORFELIUS, C E	8212100016	50-263 Q	O'REILLY, J P	8212090414	50-416 Q	PAGI IARD, J A	8212190019*	50-409 Q
NORFELIUS, C E	8212100019*	50-263 Q	O'REILLY, J P	8212090429	50-382 A	PAISLEY, E J	8212070476*	XPORTLIC
NORFELIUS, C E	8212100324	50-454 Q	O'REILLY, J P	8212090435	50-364 Q	PAISLEY, E J	8212280172	XPORTLIC
NORFELIUS, C E	8212100329	50-461 Q	O'REILLY, J P	8212090436	50-416 Q	PAJOWSKI, J	8212130028*	50-10 F
NORFELIUS, C E	8212100333*	50-461 Q	O'REILLY, J P	8212090464	50-261 Q	PAJOWSKI, J E	8212130041*	50-10 F
NORFELIUS, C E	8212170105	50-341 Q	O'REILLY, J P	8212090544	50-335 Q	PAJOWSKI, J E	8212220190*	50-10 F
NORFELIUS, C E	8212170109	50-295 Q	O'REILLY, J P	8212090558*	50-335 Q	PAJOWSKI, J E	8212220202*	50-10 F
NORFELIUS, C E	8212170114*	50-295 Q	O'REILLY, J P	8212270116*	70-143	PALLADINO, N J	8212060195	50-275 Q
NORFELIUS, C E	8212170145	50-155 Q	O'TOOLE, J D	8210190499	50-247 F	PALLADINO, N J	8212060164*	50-275 Q
NORFELIUS, C E	8212170177	50-266 Q	O'TOOLE, J D	8212030248*	50-3 F	PALLADINO, N J	8212060470	COMMISSION
NORFELIUS, C E	8212170181*	50-266 Q	O'TOOLE, J D	8212060146	50-247 S	PALLADINO, N J	8212070090	COMMISSION
NORFELIUS, C E	8212210029	50-358 Q	O'TOOLE, J D	8212070285	50-3 P	PALLADINO, N J	8212070342	COMMISSION
NORFELIUS, C E	8212210104	50-373 Q	O'TOOLE, J D	8212070296	50-247 Q	PALLADINO, N J	8212070351*	COMMISSION
NORFELIUS, C E	8212210413	50-461 Q	O'TOOLE, J D	8212080277	50-247 S	PALLADINO, N J	8212070359*	COMMISSION
NORFELIUS, C E	8212270275	50-456 Q	O'TOOLE, J D	8212090205	50-247 P	PALLADINO, N J	8212070368*	COMMISSION
NORFELIUS, C E	8212270295	50-237 Q	O'TOOLE, J D	8212130232	50-247 P	PALLADINO, N J	8212070372*	COMMISSION
NORFELIUS, C E	8212270308*	50-456 Q	O'TOOLE, J D	8212130288	50-247 P	PALLADINO, N J	8212070385	COMMISSION
NORFELIUS, C E	8212280433	50-454 Q	O'TOOLE, J D	8212140353	50-3 F	PALLADINO, N J	8212080005	COMMISSION
NORFELIUS, C E	8212290324	50-266 F	O'TOOLE, J D	8212150023	50-247 S	PALLADINO, N J	8212080023	COMMISSION
NORFELIUS, C E	8212060287*	50-272 Q	O'TOOLE, J D	8212150080	50-247 S	PALLADINO, N J	8212080025*	COMMISSION
NORRIS, H B	8212060201*	50-261 R	O'TOOLE, J D	8212210119	50-247 S	PALMER, R A	8212270441	NUREG
NORRIS, J F	8212090225*	50-287 S	O'TOOLE, J D	8212210128	50-247 S	PALMER, R A	8212020232*	50-316 S
NORRIS, P	8212080575	PR	O'TOOLE, J D	8212220042*	50-3 F	PALMER, R A	8212020289*	50-315 S
NORRIS, P	8212080578	PR	O'TOOLE, J D	8212270120	50-247 F	PALMER, R A	8212060600*	50-316 S
NORRIS, P	8212080585	PR	O'TOOLE, J D	8212270361*	50-247 Q	PALMER, R A	8212100259*	50-315 S
NORRIS, P O	8211160094	PR	O'TOOLE, J D	8212280219	50-247 R	PALMER, R A	8212140165*	50-316 S
NORRIS, P O	8212080594	PR	O'TOOLE, J D	8212280237	50-247 P	PALMER, R A	8212170228*	50-316 S
NORRIS, P O	8212210497	ORQ	O'TOOLE, J D	8212280243*	50-247 P	PALMER, R A	8212170232*	50-316 S
NORRIS, P O	8212210505	ORQ	O'TOOLE, J D	8212280364	50-247 P	PALMER, R A	8212170292*	50-315 S
NORTH, P	8212080505	RES	O'TOOLE, J D	8212290302*	50-3 F	PANDEY, S	8210070227*	50-250 P
NORTON, B	8212280123	50-275 Q	O'TOOLE, J D	8212300273	50-247 P	PANDEY, S	8210220470*	50-317 P
NORTON, B	8212280123	50-275 Q	O'TOOLE, J D	8212300352	50-247 P	PANDEY, S	8210220483*	50-317 P
NOUBAKHSH, H P	8212010428*	ACR8	O'LEIGH, A	8212280061*	50-409 P	PANDEY, S	8210250187*	50-344 P
NOVAK, T M	8211050027*	50-483 A	DESTHANN, M J	8212170079*	50-373 Q	PANDEY, S	8212290536*	50-250 P
NOVAK, T M	8212010354	50-445 Q	OKRENT, D	8212270442*	FOIA	PANDEY, S	8212300348*	50-289 P
NOVAK, T M	8212030269	50-329 A	OKRENT, D	8212270445*	FOIA	PANDY, J	8212150012	50-346 M
NOVAK, T M	8212030275	50-329 A	OKRENT, D	8212270445*	FOIA	PANBURN, O C	8212230145	WASTE MGT
NOVAK, T M	8212030317	50-413 E	OLACH, V R	8212210289*	50-155 Q	PANBURN, O C	8212230392	WASTE MGT
NOVAK, T M	8212060033	50-327 E	OLACH, V R	8212210289*	50-155 Q	PAPAY, L T	8212130333*	50-206 Q
NOVAK, T M	8212060341	50-460 E	OLLER, R E	8212070036*	QA999	PAPAY, L T	8212170384*	50-206 Q
NOVAK, T M	8212070447*	50-298 Q	OLMAN, M D	8212270165	NUREG	PAPERIELLO, C J	8212060051	50-409 Q
NOVAK, T M	8212080540	50-362 P	OLMEDO, L A	8212230241	50-247 Q	PAPERIELLO, C J	8212060055*	50-409 Q
NOVAK, T M	8212130235	50-382 A	OLSEN, A F	8212160086	71-5814	PAPERIELLO, C J	8212060238*	50-293 Q
NOVAK, T M	8212220440	50-275 P	OLSEN, C S	8212060480	NUREG	PAPERIELLO, C J	8212060252*	50-409 Q
NOVAK, T M	8212220461	50-275 P	OLSHAN, L	8212010020	50-456 A	PAPERIELLO, C J	8212100145	50-254 Q
NOVAK, T M	8212280046	50-329 S	OLSHAN, L	8212080120	50-454 F	PAPERIELLO, C J	8212140410	50-409 Q
NOVAK, T M	8212290481	50-440 E	OLSON, R A	8212020034	40-17	PAPERIELLO, C J	8212150019*	50-409 Q
NOVAK, T M	8212300019	50-454 E	OLSON, R C	8212080491	50-317 F	PAPERIELLO, C J	8212170077	50-373 Q
NUGENT, R S	8212090201*	50-440 Q	OLSON, R C	8212140412	NUREG	PAPERIELLO, C J	8212210124*	50-237 Q
NUGENT, R S	8212090201*	50-440 Q	ONDRASIK, H	8212080280	50-289 H	PAPERIELLO, C J	8212210340*	50-282 Q

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
PARCHEN, L. J.	8212220265	NUREG	PENNIFILL, R. A.	8212270464	WASTE MGT	POSNER, P.	8212150017	50-247 Q
PARKER, Q. H.	8212040236	50-142 Q	PERLIS, R. O.	8212010469	RES	POTAPOV, U.	8212070032	QA999
PARKS, O. H.	8212080315	50-155 Q	PEPPING, R. C.	8212010475	RES	POTAPOV, U.	8212070116	QA999
PARKS, O. H.	8212160509	50-155 Q	PERCH, R. L.	8212010030	50-387 P	POTAPOV, U.	8212070156	QA999
PARKS, O. H.	8212210235	50-247 Q		8212220557	50-387 P	POTAPOV, U.	8212070301	QA999
PARTS, P. C.	8212270135	50-354 A	PERKINS, D. H.	8212280438	50-409 P	POTAPOV, U.	8212070416	QA999
PARKER, Q. H.	8212160558	RES	PERLIS, R. O.	8212010385	50-443 Q	POTAPOV, U.	8212100003	QA999
PARKER, L. B.	8212300280	QA999	PERLIS, R. O.	8212020323	50-443 Q	POTAPOV, U.	8212210097	QA999
PARKER, M. E.	8212080522	50-155 Q	PERLIS, R. O.	8212020326	50-443 Q	POTAPOV, U.	8212210135	QA999
PARKER, R. C.	8212290138	50-261 Q	PERLIS, R. O.	8212030163	50-443 Q	POTAPOV, U.	8212210218	QA999
PARKER, R. C.	8212290165	50-261 Q	PERLIS, R. O.	8212280017	50-443 Q	POTAPOV, U.	8212210353	QA999
PARKYN, J. D.	8212020125	PR	PERLMAN, J.	8212080380	CONTRACT	POTAPOV, U.	8212270199	QA999
PARKYN, J. D.	8212020375	PR	PERRY, J. H.	8212230156	71-474	POTAPOV, U.	8212260396	QA999
PARSONS, R. H.	8212070043	50-400 S	PERSHAG, D.	8104230080	FOIA	POTAPOV, U.	8212300027	QA999
PARSONS, R. H.	8212070305	50-400 S				POTAPOV, U.	8212300212	QA999
PARSONS, R. H.	8212090237	50-400 Q	PERSON, L. S.	8212010250	WASTE MGT	POTAPOV, U.	8212300254	QA999
PARSONS, R. H.	8212170183	50-400 S	PESCHKE, J. M.	8212100339	50-461 Q	POTAPOV, U.	8212300276	QA999
PARSONS, R. H.	8212170328	50-400 S	PESCHEL, J. M.	8212170121	50-295 Q	POTAPOV, U.	8212300301	QA999
PARSONS, R. H.	8212220432	50-400 S	PESCHKE, J. M.	8212290348	50-254 Q	POTAPOV, U.	8212280397	50-325 S
PARSONS, R. H.	8212300326	50-400 S	PETERSEN, J. J.	8212130108	NUREG	POTAPOV, U.	8212230155	40-2259
PASTVA, M. J.	8212020083	50-324 S	PETERSEN, D. A.	8212130250	50-255 R	PRATT, C. M.	8212220271	50-247 Q
PASTVA, M. J.	8212020161	50-324 S	PETERSEN, H. R.	8212080232	XPORTRIC	PRATT, C. M.	8212220271	50-247 Q
PASTVA, M. J.	8212020297	50-324 S	PETERSEN, H. R.	8212100119	XPORTRIC	PRATT, C. M.	8212230187	50-247 Q
PASTVA, M. J.	8212020312	50-324 S	PETERSEN, H. R.	8212230414	XPORTRIC	PRATT, C. M.	8212230187	50-247 Q
PASTVA, M. J.	8212020319	50-324 S	PETERSEN, H. R.	8212230418	XPORTRIC	PREVATTE, R.	8212010335	50-309 P
PASTVA, M. J.	8212020365	50-324 S	PETERSEN, H. R.	8212230423	XPORTRIC	PRICE, E. R.	8212160527	40-6500
PASTVA, M. J.	8212070012	50-325 S	PETERSEN, H. R.	8212230433	XPORTRIC	PRICHARD, R. P.	8212130122	71-6497
PASTVA, M. J.	8212070118	50-325 S	PETERSEN, H. R.	8212270336	FOIA	PRICHARD, R. P.	8212160437	71-9122
PASTVA, M. J.	8212070214	50-325 S	PETERSEN, H. R.	8212280155	XPORTRIC	PULLANI, S. V.	8212070148	50-309 Q
PASTVA, M. J.	8212070275	50-324 S	PETRICK, N. A.	8212170288	50-492 A	PURCELL, L. D.	8212280026	70-144
PASTVA, M. J.	8212090105	50-325 S	PETRICK, N. A.	8212280236	50-482 A	PURZY, A. H.	8212100406	50-344 F
PASTVA, M. J.	8212090139	50-325 S	PETRON, C.	8212030207	50-289 Q	QUICK, D. R.	8212090384	50-327 Q
PASTVA, M. J.	8212090152	50-325 S	PETRON, F. P.	8212280092	50-247 F	QUICK, D. R.	8212090500	50-350 Q
PASTVA, M. J.	8212090173	50-325 S	PETTENOILL, H. J.	8212030235	40-1162	QUICK, D. R.	8212070411	50-295 P
PASTVA, M. J.	8212090318	50-324 S	PETTENOILL, H. J.	8212030272	40-6622	QUIGLEY, T. W.	8212060330	40-8743
PASTVA, M. J.	8212090463	50-325 S	PETTENOILL, H. J.	8212060004	40-8084	QUIGLEY, T. W.	8212290145	40-8743
PASTVA, M. J.	8212090542	50-325 S	PETTENOILL, H. J.	8212070045	40-8698	QUILLIAM, J. F.	8212060471	50-295 P
PASTVA, M. J.	8212090550	50-325 S	PETTENOILL, H. J.	8212230391	40-8602	RAHY, J.	8212290430	50-220 S
PASTVA, M. J.	8212140159	50-325 S	PEVENEY, J. E.	8212220034	CONTRACT	RAHNEY, R. L.	8212060336	40-8743
PASTVA, M. J.	8212140202	50-325 S	PEVEY, L. E.	8212280181	XPORTRIC	RAHE, E. P.	8210210467	TOPREP
PASTVA, M. J.	8212150114	50-325 S	PEVEY, R. E.	8212060465	NUREG	RAHE, E. P.	8210210484	TOPREP
PASTVA, M. J.	8212170156	50-325 S	PEYBER, P.	8212230276	50-247 U	RAHE, E. P.	8210210489	TOPREP
PASTVA, M. J.	8212210032	50-325 S	PFYFF, S. J.	8212270325	40-6657	RAHE, E. P.	8212010134	PT21
PASTVA, M. J.	8212210139	50-325 S	PFYFFERLEN, H. C.	8212090077	TOPREP	RAHE, E. P.	8212020267	TOPREP
PASTVA, M. J.	8212210405	50-325 S	PFYFFERLEN, H. C.	8212090148	TOPREP	RAHE, E. P.	8212130262	TOPREP
PASTVA, M. J.	8212220493	50-325 S	PFLUM, C. O.	8212020246	WASTE MGT	RAHE, E. P.	8212130296	TOPREP
PASTVA, M. J.	8212220504	50-325 S	PHILLIPS, H. S.	8212070304	QA999	RAHE, E. P.	8212130055	TOPREP
PASTVA, M. J.	8212300225	50-325 S	PHILLIPS, H. S.	8212300218	QA999	RAHE, E. P.	8212200040	TOPREP
PASTVA, M. J.	8212300259	50-325 S	PHILLIPS, H. S.	8212300303	QA999	RAHE, E. P.	8212220182	TOPREP
PASTVA, M. J.	8212300262	50-325 S	PHILLIPS, J.	8212300128	50-309 R	RAHMONDI, P. J.	8212020256	50-358 A
PASTVA, M. J.	8212300309	50-325 S	PHILLIPS, J.	8212290130	50-29 R	RAMSEY, B. L.	8212290104	50-266 F
PASTVA, M. J.	8212300317	50-325 S	PHILLIPS, M. P.	8212060238	50-295 Q	RAMSEY, C.	8212170162	50-155 C
PASTVA, M. J.	8212300334	50-325 S	PHILLIPS, M. P.	8212210124	50-237 Q	RAMSEY, C.	8212170187	50-266 C
PATON, W. D.	8211080148	50-329 Q	PICKENS, T. A.	8212150072	50-331 P	RANDAZZA, J. B.	8212210266	50-309 C
PATON, W. D.	8212280145	50-397 Q	PICKL, R. H.	8212060060	50-316 S	RANDEL, C.	8212230276	50-247 L
PATLSON, J. P.	8212210340	50-282 Q	PICKL, R. H.	8212100327	50-315 S	RANLET, J.	8212070471	RES
PATLSON, W. F.	8212220051	50-461 T	PIENCE, J. D.	8212150274	71-5939	RATCHFORD, W.	8212230276	50-247 U
PAUL, R. A.	8212300296	50-295 Q	PIENCE, R. D.	8212300123	CONTRACT	RAUSCH, T. J.	8212030043	50-237 P
PAUL, R. A.	8212090433	50-409 Q	PIKE, D. H.	8212270435	NUREG	RAUSCH, T. J.	8212030056	50-254 Q
PAUL, K. G. L.	8212090479	50-259 Q	PILANT, J. H.	8212070175	50-298 P	RAUSCH, T. J.	8212060029	50-237 Q
PAULSON, W.	8212010023	50-204 P	PILANT, J. H.	8212030159	50-298 P	RAUSCH, T. J.	8212060181	50-254 F
PAULSON, W.	8212020252	50-204 P	PILANT, J. H.	8212070141	50-298 Q	RAUSCH, T. J.	8212060207	50-237 P
PAULSON, W.	8212070002	50-204 F	PILANT, J. H.	8212070402	50-298 F	RAUSCH, T. J.	8212060267	50-237 P
PAULSON, W.	8212130204	50-204 P	PILANT, J. H.	8212100171	50-298 P	RAUSCH, T. J.	8212080337	50-237 Q
PAULSON, W. A.	8212010047	50-204 P	PILANT, J. H.	8212100293	50-298 P	RAUSCH, T. J.	8212090301	50-237 P
PAULSON, W. A.	8212020307	50-204 P	PILANT, J. H.	8212130342	50-298 F	RAUSCH, T. J.	8212140172	50-237 P
PAULSON, W. A.	8212080283	50-204 P	PILANT, J. H.	8212140472	71-9001	RAUSCH, T. J.	8212140179	50-254 F
PAULSON, W. A.	8212100009	50-204 P	PILANT, J. H.	8212160433	71-484	RAUSCH, T. J.	8212160013	50-254 P
PAULSON, W. A.	8212100020	50-204 P	PILANT, J. H.	8212200399	50-298 F	RAUSCH, T. J.	8212160326	50-237 Q
PAULSON, W. A.	8212160018	50-204 P	PILGEM, J. P.	8212220265	NUREG	RAUSCH, T. J.	8212210036	50-237 P
PAULSON, W. A.	8212210293	50-204 P	PINKETT, M.	8212230241	50-247 Q	RAUSCH, T. J.	8212280110	50-237 Q
PAULSON, W. A.	8212220447	50-206 P	PITILE, O. L.	8212060080	50-346 Q	RAUSCH, T. J.	8212280263	50-237 P
PAVIA, G. S.	8212140131	50-317 S	PLAZUTO, C. H.	8212270330	50-382 Q	RAUSCH, T. J.	8212280357	50-234 P
PAVIA, G. S.	8212210303	50-317 S	PLIN, O.	8212130153	50-295 F	RAUSCH, T. J.	8212290111	50-254 P
PAVIA, G. S.	8212130191	50-266 Q	PLINI, O.	8212290086	50-295 F	RAUSCH, T. J.	8212290190	50-237 P
PECK, R. B.	8212090194	50-329 T	PLINI, O.	8212290105	50-295 F	RAUSCH, T. J.	8212290407	50-254 F
PEEBLES, T.	8212270151	50-346 Q	PLINK, O.	8212290311	50-295 F	RAWSON, R. J.	8212070003	50-322 Q
PEEBLES, T. A.	8212100263	40-8786	PLONK, T. J.	8212060017	50-315 Q	RAWSON, R. J.	8212200113	50-454 Q
PELIZZA, M. S.	8212030261	50-367 Q	PLUMLEE, O. L.	8212070260	50-267 Q	RAWSON, R. J.	8212280028	50-259 Q
PELKE, P. R.	8212100200	50-367 Q	POCHAL, W. F.	8212280149	XPORTRIC	RAY, H. B.	8212070225	50-361 S
PELKE, P. R.	8212290414	50-546 Q	POLASCHI, J. P.	8212020095	50-155 P	RAY, H. B.	8212070231	50-361 S
PELLATIER, J. P.	8212290378	50-271 S	POLLOCK, M. B.	8212210338	50-322 A	RAY, H. B.	8212070259	50-361 S
PELLATIER, J. P.	8212290384	50-271 S	POPPE, L. K.	8212150202	71-9081	RAY, H. B.	8212070281	50-361 S
PENDER, R. A.	8212090206	50-440 Q	POPPE, L. K.	8212160407	71-9151	RAY, H. B.	8212070283	50-361 S
PENNIFILL, R. A.	8212010514	WASTE MGT	PORTER, M. R.	8212020124	50-296 S			

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
RAY, H B	8212070287*	50-361 S	REYNOLDS, N S	8212270326	50-397 Q	ROHRER, M V	8212300047*	50-416 S
RAY, H B	8212070290	50-361 S	REYNOLDS, N S	8212270326	50-397 Q	ROHRER, M V	8212300087*	50-416 S
RAY, H B	8212070293*	50-361 S	REYNOLDS, N S	8212270329	50-460 Q	ROHRER, M V	8212300228*	50-416 S
RAY, H B	8212070294*	50-361 S	REYNOLDS, N S	8212270329	50-460 Q	ROLES, G W	8212230105	WASTE P.
RAY, H B	8212070324	50-361 S	REYNOLDS, N S	8212270332	50-443 Q	ROLES, G W	8212230114	WASTE P.
RAY, H B	8212070329*	50-361 S	REYNOLDS, N S	8212270332	50-445 Q	ROLES, G W	8212230174	WASTE P.
RAY, H B	8212070330	50-361 S	REYNOLDS, N S	8212280273	50-445 Q	ROMAN, T H	8212140031*	50-240 S
RAY, H B	8212070340*	50-361 S	REYNOLDS, N S	8212280273	50-445 Q	ROMINE, W D	8212090178*	50-328 S
RAY, H B	8212070369	50-361 S	REYNOLDS, N S	8212280277	50-397 Q	RODD, H	8212010409	50-362 P
RAY, H B	8212070374*	50-361 S	REYNOLDS, N S	8212280277	50-397 Q	RODD, H	8212170381	50-341 P
RAY, H B	8212070379	50-361 S	REYNOLDS, N S	8212280294	50-460 Q	ROONEY, V L	8212260005	50-271 P
RAY, H B	8212070383	50-361 S	REYNOLDS, N S	8212280294	50-460 Q	ROOT, L D	8212060324*	50-331 S
RAY, H B	8212070388*	50-361 S	RIE, S	8212170139*	50-249 S	ROOT, L D	8212070216	50-331 P
RAY, H B	8212070399*	50-361 S	RIE, S J	8212170130*	50-237 S	ROOT, L D	8212070308	50-331 P
RAY, H B	8212070406	50-361 S	RHINELANDER, J	8212140470	40-2061	ROOT, L D	8212090322	50-331 P
RAY, H B	8212070412*	50-361 S	RHODES, H J	8212160419*	50-387 P	ROOT, L D	8212090337	50-331 P
RAY, H B	8212140035	50-361 S	RHODES, G Q	8212070158*	50-387 Q	ROOT, L D	8212060276	50-331 P
RAY, H B	8212140263	50-361 S	RHODES, G Q	8212290468*	50-387 Q	ROOT, L D	8212100295	50-331 P
RAY, H B	8212140270*	50-361 S	RHODES, H	8212160659	40-6027	ROOT, L D	8212150070	50-331 P
RAY, H B	8212140272*	50-361 S	RICCARDELLA, P	8212100303*	50-331 Q	ROOT, L D	8212170193	50-331 P
RAY, H B	8212140360	50-206 S	RICE, D A	8212210283*	50-29 S	ROOT, L D	8212170308	50-331 P
RAY, H B	8212140368*	50-206 S	RICE, W A	8212270512	NUREO	ROOT, L D	8212210315	50-331 P
RAY, H B	8212140398	50-361 S	RICH, P C	8212220341	NUREO	ROOT, L D	8212270166	50-331 P
RAY, H B	8212140409*	50-361 S	RICHARDS, J F	8212280455*	CONTRACT	ROOT, L D	8212270298	50-331 P
RAY, H B	8212290102	50-206 R	RICHARDS, L	8212140293	50-329 A	ROOT, L D	8212280065	50-331 P
RAY, H B	8212290176	50-361 R	RICHARDS, S	8212030207*	50-289 Q	ROOY, R W	8212210251	50-450 S
RAYMOND, H J	8212140113*	50-271 Q	RICHARDS, S	8212060190*	50-423 Q	ROOY, R W	8212280428	50-450 S
RAYNOR, J W	8212210303	50-317 S	RICHARDSON, J D	8212260106*	50-416 R	ROSGAN, R	8212170170	50-247 S
RAZLAFF, H J	8212290104*	50-286 P	RICHTER, L	8212100333	50-346 S	ROSGAN, R	8212270311	FOIA
READ, D F	8212020383	PR	RICHTER, L	8212280250*	50-346 S	ROSENFIELD, C S	8212010150*	50-272 P
REAVIS, J A	8212210065*	50-369 R	RIDOUT, E F	8212160134	71-454	ROSENTHAL, A S	8212010141*	FOIA
REAVIS, J A	8212210428*	50-269 R	RIDOUT, E F	8212160140	71-454	ROSENTHAL, B	8212230276	50-247 P
REBELLO, J E	8212010383*	CONTRACT	RINO, H A	8212170118*	50-454 Q	ROSS, F W	8212170457*	40-8728
REBELLO, J E	8212010391*	CONTRACT	RIZZO, J B	8212300410*	50-387 F	ROSS, M A	8212080301*	50-442 S
REBELLO, J E	8212010398*	CONTRACT	ROBBINS, E B	8212160500*	FOIA	ROSS, M A	8212080301*	50-442 S
REBELLO, J E	8212010406*	CONTRACT	ROBERTS, M J	8212030154*	50-445 Q	ROSS, M A	8212130246*	50-440 S
REBELLO, J E	8212010423*	CONTRACT	ROBERTS, J P	8212130148	70-1308	ROSS, M A	8212130246*	50-440 S
REBELLO, J E	8212010430*	CONTRACT	ROBERTS, J P	8212130435	PROJ	ROSS, W J	8212160623	50-272 S
REBELLO, J E	8212010434*	CONTRACT	ROBERTS, J P	8212130438	PROJ	ROSS, W J	8212290525	50-316 P
REBELLO, J E	8212010438*	CONTRACT	ROBERTS, J P	8212210917	PROJ	ROTELLA, T S	8212150158*	50-325 S
REBELLO, J E	8212060413*	CONTRACT	ROBERTS, T	8212280542	NUREO	ROTELLA, T S	8212210186*	50-335 S
REBELLO, J E	8212060577*	CONTRACT	ROBERTS, T M	8212020016*	FOIA	ROTELLA, T S	8212210396*	50-335 S
REBELLO, J E	8212140064*	50-213 Q	ROBERTS, T M	8212070467*	50-298 P	ROTELLA, T S	8212220442*	50-335 S
REBELLO, J E	8212140140*	50-247 Q	ROBINSON, D L	8212280384*	50-249 Q	ROTELLA, T S	8212280384*	50-335 S
REDANO, R T	8212070133*	50-412 Q	ROCCO, J	8212270171	50-206 J	ROTELLA, T S	8212280425*	50-335 S
REDANO, R T	8212280420*	50-298 Q	ROCKWOLD, H C	8212020076	50-395 P	ROTH, J	8212210370*	70-1487
REDMOND, R F	8212280577*	CONTRACT	ROCKWOLD, H C	8212020108	50-364 P	ROTH, J	8212230335*	70-1443
REED, C	8212280298	50-372 P	ROGERS, P	8212030075*	50-368 S	ROUPE, L C	8212090340*	70-1231
REED, J G	8212210276	50-403 Q	ROGERS, P	8212230276	50-247 U	ROUSE, L C	8212140494	50-387 P
REEDY, R F	8212140447	50-275 R	RODRIGUEZ, P	8212070189	50-247 Q	ROUSE, L C	8212160331	70-1487
REEVES, E A	8212160568	50-364 P	RODRIGUEZ, R J	8212030062	50-312 S	ROUSE, L C	8212170014	70-1443
REHM, T A	8212130334	COMMISSION	RODRIGUEZ, R J	8212170231	50-312 R	ROUSE, L C	8212170017*	70-1443
REHM, T A	8212200512	COMMISSION	RODRIGUEZ, R J	8212200042	50-312 R	ROUSE, L C	8212220005	50-280 S
REHM, T A	8212290521	COMMISSION	RODRIGUEZ, R J	8212270283	50-312 R	ROUSE, L C	8212220007*	50-280 S
REHMANN, F H	8212170306*	50-10 Q	ROEDER, J	8212160160*	FOIA	ROUSE, L C	8212220170	50-280 S
REIS, H F	8212280541	27-47	ROEDER, J R	8212160343*	FOIA	ROUSE, L C	8212230136	70-1443
REIS, H F	8212280541	27-47	ROEDER, J R	8212160477*	FOIA	ROUSE, L C	8212230141*	70-1443
REIS, H F	8212280541	27-47	ROESSET, J H	8212170378*	50-275 H	ROUSE, L C	8212230147	50-280 S
REITER, L	8001180235*	50-206 P	ROGERS, D	8212100299	50-128 S	ROUSE, L C	8212290494	50-369 P
REITER, L	8006090788*	50-206 P	ROGERS, H R	8212020191*	50-328 S	ROWE, J W	8212280491*	CONTRACT
REITLER, E K	8212150236	70-1151	ROGERS, H R	8212090556*	50-328 S	ROY, G W	8212160103*	FOIA
REITLER, E K	8212150244*	70-1151	ROGERS, H R	8212140207*	50-328 S	RUITLER, G H	8212290216*	50-305 S
REKTO, W A	8212060237*	50-247 Q	ROGERS, H R	8212140247*	50-327 S	RUNKLE, G E	8212010109	REG
RELMLEY, M E	8212210110	50-375 W	ROGERS, P	8212210020*	50-368 S	RUSCHER, G E	8212220265	NUREO
REPKA, D A	8212080267	50-322 Q	ROGERS, P	8212290233*	50-368 S	RUSSELL, L B	8212060196	50-317 S
REPKA, D A	8212140463	50-322 Q	ROGERS, P	8212300090*	50-368 S	RUSSELL, L B	8212060301	50-317 S
REPKA, D A	8212200111	50-322 Q	ROGERS, R F	8212290137*	50-250 Q	RUSSELL, L B	8212080441	50-317 S
REPKA, D A	8212220106	50-322 Q	ROGERS, R F	8212290184*	50-280 Q	RUSSELL, L B	8212140125	50-317 S
REPKA, D A	8212230142	50-322 Q	ROGERS, V C	8212010115	NUREO	RUSSELL, L B	8212160299	50-317 S
REPKA, D A	8212220166	50-322 Q	ROGERS, V C	8212220341	NUREO	RUSSELL, L B	8212210043	50-317 S
REGUA, Q	8212220465	50-261 P	ROGERS, W O	8212100263*	50-346 Q	RUSSELL, L B	8212210076	50-317 S
REVELEY, T W	8206090121	FOIA	ROHAC, J F	8212030102	50-302 S	RUSSELL, L B	8212210294	50-317 S
REYBS, L	8212030150*	50-282 Q	ROHAT, U B	8212030239	RES	RUSSELL, L B	8212210378	50-317 S
REYES, L	8212270151	50-346 S	ROHRER, M V	8212090081*	50-416 S	RUSSELL, L B	8212270275	50-317 S
REYES, L A	8212100263*	50-346 Q	ROHRER, M V	8212090136*	50-416 S	RUSSELL, W T	8112110396*	50-206 P
REYES, R A	8212100149*	50-305 Q	ROHRER, M V	8212090195*	50-416 S	RUTI EDGE, B G	8212020251	PR
REYNOLDS, J R	8212280288	50-275 Q	ROHRER, M V	8212170277*	50-416 S	RYAN, A D	8212230337	50-247 S
REYNOLDS, J R	8212280288	50-275 Q	ROHRER, M V	8212170327*	50-416 S	SABADOS, J H	8212090416*	70-1443
REYNOLDS, N S	8212140409	50-445 Q	ROHRER, M V	8212210209*	50-416 S	SAHA, P	8212030239	RES
REYNOLDS, N S	8212140409	50-445 Q	ROHRER, M V	8212210227*	50-416 S	SAHA, P	8212060119	RES
REYNOLDS, N S	8212200010	PR	ROHRER, M V	8212210371*	50-416 S	SAKOWSKI, P	8212300263*	0A999
REYNOLDS, N S	8212230314	50-397 Q	ROHRER, M V	8212260081*	50-416 S	SAHANEEO, F J	8212270227	50-322 T
REYNOLDS, N S	8212230314	50-397 Q	ROHRER, M V	8212280183*	50-416 S	SAHANEEO, F J	8212270227	50-322 T
REYNOLDS, N S	8212270317	50-445 Q	ROHRER, M V	8212280311*	50-416 S	SAHEL SON, A	8212270322	50-441 C
REYNOLDS, N S	8212270317	50-445 Q	ROHRER, M V	8212280314*	50-416 S	SAHUEL, F	8212230241	50-247 S

PERSONAL AUTHOR INDEX

445

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
SANDERS, C F	0212150244*	70-1131	SCHWENCER, A	0212220537	50-387 F	SHACK, W J	0212080670*	50-373 P
SANDERS, D F	0212090245*	50-424 Q	SCHWENCER, A	0212220541	50-352 A	SHACK, W J	0212080673*	50-373 P
SANDRY, W A	0212020134	PR	SCHWENCER, A	0212220552	50-387 P	SCHAFER, P W	0212070440*	50-409 Q
SARSCUR, B	0212290309*	50-346 R	SCHWENCER, A	0212220554*	50-387 P	SHAFFER, W	0212060112	50-329 S
SARSTEN, Q E	0212010224	PT21	SCHWENCER, A	0212270491	50-458 F	SHAFFER, W	0212080416	50-329 S
SARSTEN, Q E	0212070295	50-324 S	SCHWENCER, A	0212300184	50-416 P	SHAFFER, W D	0212100161	50-329 A
SASTRE, C	0212060005	RES	SCHWENCER, A	0212300203*	50-416 P	SHANBAKY, M	0212220358*	50-244 Q
SATTAR, D	0212160419*	50-387 P	SCHWENSIER, R	0212270024	70-33	SHANBAKY, M M	0212030023*	50-220 Q
SAUNDERS, G A	0212170404	40-8745	SCHWINA, W	0212220236	REVIEW ORP	SHANNON, J B	0212030285	40-8102
SAUNDERS, R T	0212170044*	50-280 F	SCOTT, D J	0212020239	50-249 S	SHANNON, W E	0212220249	NUREO
SAVINI, R J	0212060410	FOIA	SCOTT, D J	0212020275	50-237 S	SHANNON, Z	0212010398*	CONTRACT
SAHORSKI, A	0212070349*	50-155 Q	SCOTT, D J	0212020337	50-249 S	SHAO, L	0102200777*	FOIA
SAHORSKI, A	0212070349*	50-155 Q	SCOTT, D J	0212220286*	50-10 F	SHAO, L C	0002200995*	50-219 P
SAYER, J	0212130346*	50-298 F	SCOTT, D J	0212080375	50-249 S	SHAO, L C	0212270253	MISC
SCALETTI, D C	0212150203	50-447 A	SCOTT, D J	0212100215	50-237 S	SHARP, R A	0212270065*	FOIA
SCALETTI, D C	0212150209	50-447 A	SCOTT, D J	0212100312	50-237 S	SHARP, R A	0212270131*	FOIA
SCALETTI, D C	0212280510	50-447 A	SCOTT, D J	0212140112	50-10 R	SHAYER, L	0212160752*	50-320 F
SCARANO, R A	0212010500	WASTE HOT	SCOTT, D J	0212109046	50-249 S	SHAW, A	0212109046	70-2955
SCARANO, R A	0212010508	WASTE HOT	SCOTT, D J	0212170122	50-237 S	SHAW, A	0212100087	XPORLTIC
SCARANO, R A	0212020388	WASTE HOT	SCOTT, D J	0212170134	50-249 S	SHAW, A	0212160791	XPORLTIC
SCARANO, R A	0212230381	WASTE HOT	SCOTT, D J	0212170218	50-249 S	SHAW, A	0212300140	XPORLTIC
SCARANO, R A	0212230383	27-47	SCOTT, D J	0212210157	50-237 S	SHEA, J R	0212100138*	FOIA
SCARANO, R A	0212230388	WASTE HOT	SCOTT, D J	0212230028*	50-10 F	SHELLEY, W J	0212100403	40-8768
SCARANO, R A	0212290024	WASTE HOT	SCOTT, D J	0212280472	50-237 S	SHELLEY, W J	0212130237	40-2061
SCHAEFER, D H	0212130253	50-275 S	SCOTT, D J	0212290329	50-249 S	SHELLEY, W J	0212210312	40-2061
SCHAEFER, K	0212080264	50-440 Q	SCOTT, D J	0212290344	50-237 S	SHELLEY, W J	0212230379	40-8027
SCHAEFER, K	0212020372	PR	SCOTT, D J	0212290369	50-249 S	SHELLEY, W J	0212280013	70-1193
SCHENER, A E	0212140501	PROJ	SCOTT, D J	0212290398	50-237 S	SHELLEY, W J	0212280018*	70-1193
SCHENER, A E	0212170163	NUREO	SCOTT, D J	0212290472	50-249 S	SHEN, P K	0210270018*	50-397 A
SCHERMAN, R L	0212090206*	50-440 Q	SCOTT, D J	0212290010	27-48	SHEPARD, J C	0009050320*	FOIA
SCHERRER, J B	0209290122*	50-409 P	SCOTT, D J	0212210185*	50-344 Q	SHEPHERD, J E.	0212270156	NUREO
SCHIEVER, J	0212230276	50-247 U	SCOTT, D J	0212210204*	50-361 Q	SHERMAN, F L	0212270024	70-33
SCHIERLING, H	0212010414	50-498 A	SCOTT, D J	0212010213	ORO	SHERMAN, F L	0212270030*	70-33
SCHIERLING, H	0212170450	50-498 A	SCOTT, D J	0212010219	ORO	SHERR, T S	0212130360	TOPREP
SCHIERLING, H E	0212150217	50-275 P	SCOTT, D J	0212010241	ORO	SHERR, T S	0212130363	50-295 F
SCHIERLING, H E	0212150223	50-275 P	SCOTT, D J	0212010247	ORO	SHERR, T S	0212220517	50-295 P
SCHLISSEL, D A	0212290055	50-244 S	SCOTT, D J	0212010253	ORO	SHERR, T S	0212220520*	50-295 P
SCHMIDT, C	0212270264	40-8783	SCOTT, D J	0212010256	ORO	SHERR, T S	0212270333*	FOIA
SCHMIDT, H C	0212070403	50-445 F	SCOTT, D J	0212220172	NUREO	SHERWOOD, O O	0212130172	50-447 B
SCHMIDTENDORF, G	0212290318*	50-338 R	SCOTT, D J	0212220513	NUREO	SHERWOOD, O O	0212140348	50-447 B
SCHMOCK, D	0212080251	50-266 Q	SECKMAN, P E	0212150132	50-331 J	SHERWOOD, O O	0212140449	50-447 B
SCHNEIDER, C	0212230276	50-247 U	SEIDLE, W C	0212030046	50-482 Q	SHERWOOD, O O	0212230301	50-447 E
SCHNEL, D F	0212020259	50-483 S	SEIDLE, W C	0212030104	50-285 Q	SHERWOOD, O O	0212230328	50-447 A
SCHNELL, D F	0212080256	50-483 F	SEIDLE, W C	0212030109	50-482 Q	SHERWOOD, O O	0212290119	50-447 A
SCHROEDER, B A	0212140120*	50-10 R	SEIDLE, W C	0212030119	50-285 Q	SHEWMON, P	0211100488	50-397 Q
SCHROEDER, B A	0212290345*	50-237 S	SEIDLE, W C	0212030184	50-368 Q	SHEWMON, P	0212020406	ACRS
SCHROEDER, B A	0212290409*	50-237 S	SEIDLE, W C	0212070145	50-285 Q	SHEWMON, P	0212130305*	50-275 P
SCHROEDER, C W	0212130093	50-373 P	SEIDLE, W C	0212100227	50-285 Q	SHEWMON, P	0212220504*	50-237 P
SCHROEDER, C W	0212140068	50-373 P	SEIDLE, W C	0212100228	50-285 Q	SHEWMON, P	0212220544*	50-245 P
SCHROEDER, C W	0212140289	50-373 Q	SEIDLE, W C	0212100254	50-313 S	SHEWMON, P	0212080633*	50-546 F
SCHROEDER, C W	0212140402	50-373 P	SEIDLE, W C	0212150280*	50-313 F	SHIELDS, B W	0212100181	50-546 S
SCHROEDER, C W	0212210463	50-373 K	SEIDLE, W C	0212200022	50-285 Q	SHIELDS, B W	0212170329	50-546 S
SCHROEDER, C W	0212280341	50-373 K	SEIDLE, W C	0212210245	50-313 Q	SHIELDS, B W	0212280157	50-546 S
SCHROEDER, C W	0212270337	50-374 Q	SEIDLE, W C	0212290078*	FOIA	SHIELDS, B W	0212280272	50-546 S
SCHUELKE, D A	0212300417*	50-282 F	SEIDLE, W C	0212290192	50-313 Q	SHIELDS, B W	0212280304	50-546 Q
SCHULZ, R D	0212140495*	50-410 Q	SEIDLERMAN, V K	0212230323	50-247 H	SHIELDS, B W	0212280321	50-546 Q
SCHUM, W S	0212070133*	50-112 Q	SELAN, J C	0209230424*	50-250 P	SHIELDS, B W	0212280462	50-546 S
SCHUMACHER, H C	0212290349	50-482 S	SELAN, J C	0212090023*	50-263 P	SHIELDS, B W	0212290112	50-546 F
SCHUMACHER, H C	0212060062*	50-409 Q	SELLS, D	0212010443	50-498 A	SHIFFER, J D.	0212210116	50-275 S
SCHUMACHER, H C	0212170079*	50-373 Q	SELLS, D E	0212090017	50-335 F	SHIM, K	0212280249*	50-295 S
SCHUMER, C	0212230276	50-247 U	SEMMEL, H	0212020361	50-155 Q	SHIMA, S	0212270082	XPORLTIC
SCHUSTER, H D	0212130293	50-275 S	SEMMEL, H	0212020361	50-155 Q	SHIMA, S	0212270086*	XPORLTIC
SCHUSTER, H D	0212280421	50-344 S	SEMMEL, H	0212070247	50-155 Q	SHIRAKAWA, T	0212010044	XPORLTIC
SCHUSTER, R M	0212210414*	50-322 E	SEMMEL, H	0212070247	50-155 Q	SHIRAKAWA, T	0212010048	XPORLTIC
SCHWAN, C A	0212280421	50-344 S	SEMMEL, H	0212070303*	50-155 Q	SHIRAKAWA, T	0212010054	XPORLTIC
SCHWIKERT-THUL	0212080453*	50-245 S	SEMMEL, H	0212070303*	50-155 Q	SHIRAKAWA, T	0212270087	XPORLTIC
SCHWIKERT-THUL	0212080453*	50-245 S	SEMMEL, H	0212280292	50-155 Q	SHIRAKAWA, T	0212270090	XPORLTIC
SCHWENCER, A	0212010005	50-322 E	SEMMEL, H	0212280292	50-155 Q	SHOCKLEY, W E	0212220060	RES
SCHWENCER, A	0212010027	50-416 P	SEPAR, S	0212270034	FOIA	SHOENAKER, C J.	0212010207	50-341 Q
SCHWENCER, A	0212010377	50-440 E	SERINI, B L	0212100187	70-2960	SHOENAKER, C J	0212010216	50-341 Q
SCHWENCER, A	0212010470	50-352 A	SERINI, B L	0212130287*	70-2957	SHOENAKER, C J	0212070114	50-155 Q
SCHWENCER, A	0212010513	50-352 A	SERRANO, W	0212140366	50-206 P	SHOENAKER, C J	0212100113	50-416 Q
SCHWENCER, A	0212060007	50-322 A	SESTAK, F	0212130193	50-275 P	SHOENAKER, C J	0212140432	50-289 Q
SCHWENCER, A	0212060097	50-352 A	SESTAK, F	0212130200*	50-275 P	SHOENAKER, C J.	0212150032	50-358 Q
SCHWENCER, A	0212060118	50-352 A	SESTAK, F	0212270299*	50-275 P	SHOENAKER, C J	0212230367	50-358 Q
SCHWENCER, A	0212060379	50-416 P	SESTAK, F	0212270301*	50-275 P	SHOENAKER, C J	0212280156*	50-341 Q
SCHWENCER, A	0212060484	50-440 A	SESTAK, F	0212270310*	50-275 P	SHOENAKER, C J	0212300016	50-445 Q
SCHWENCER, A	0212080014	50-461 F	SESTAK, F	0212270312*	50-275 P	SHOENAKER, R P	0212140420*	50-244 P
SCHWENCER, A	0212080566	50-277 P	SESTAK, F	0212280163*	50-275 P	SHOLLEY, W J	0212270563	40-8027
SCHWENCER, A	0212100372*	50-373 P	SESTAK, F	0212290209*	50-275 P	SHOLLY, S C	0212060077	50-247 Q
SCHWENCER, A	0212160729	50-367 A	SESTAK, F	0212290237*	50-275 P	SHOLLY, S C	0212060098	50-247 Q
SCHWENCER, A	0212160747	50-352 A	SESTAK, F	0212290243*	50-275 P	SHOLLY, S C	0212090101	50-247 Q
SCHWENCER, A	0212170034*	50-373 P	SESTAK, F	0212290250*	50-275 P	SHOLLY, S C	0212270414	FOIA
SCHWENCER, A	0212220049	50-458 A	SESTAK, F	0212290462*	50-275 P	SHON, F J	0212080315	50-155 Q
SCHWENCER, A	0212220355	50-397 A	SHACK, W J.	0212080668*	50-373 P	SHON, F J	0212100108	50-440 Q

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
SHON, F J	8212150041	50-440 Q	SMITH, I W	8212200107	50-454 Q	SPELMAN, H J	8212130167	40-2061
SHON, F J	8212160509	50-155 Q	SMITH, J C	8212290132	40-6622	SPELMAN, H J	8212130167	40-2061
SHON, F J	8212230181	50-247 Q	SMITH, J L	8211080125	50-322 E	SPELMAN, H J	8212270459	40-2061
SHON, F J	8212230351	50-440 Q	SMITH, J L	8212010082	50-322 E	SPELMAN, H J	8212270459	40-2061
SHOPENN, N H	8212210184	40-8006	SMITH, J L	8212010087	50-322 E	SPELMAN, H J	8212270478	40-2061
SHOPENN, N H	8212210412	40-7086	SMITH, J L	8212010165	50-322 E	SPELMAN, H J	8212270478	40-2061
SHOPENN, N H	8212230150*	FOIA	SMITH, J L	8212070129	50-322 E	SPENCER, D W	8212270260*	50-837 A
SHOTWELL, J A	8212070242	50-443 Q	SMITH, J L	8212070219	50-322 A	SPENCER, O S	8212130291	50-187 Q
SHUMATE, D R	8212230051*	CONTRACT	SMITH, J L	8212140339	50-322 A	SPENCER, O S	8212300207	70-734
SICILIAN, J M	8212070276*	50-416 P	SMITH, J L	8212210224	50-322 A	SPENCER, O S	8212300234	70-25
SIEBER, J D	8212220373	50-334 P	SMITH, J L	8212210406	50-322 E	SPENCER, W C	8212090305	50-404 Q
SIEBER, J D	8212220409	50-334 P	SMITH, J L	8212230259	50-322 E	SPESSARD, R L	8212090415	50-237 S
SIEBER, J D	8212220423	50-334 P	SMITH, J L	8212270380	50-322 E	SPESSARD, R L	8212080366	50-461 Q
SIEPKEN, D L	8212270464	WASTE MGT	SMITH, J R	8212220528*	CONTRACT	SPESSARD, R L	8212080509	50-155 Q
SIEGEL, B	8206140162*	50-298 Q	SMITH, L C	8212210005*	50-279 P	SPESSARD, R L	8212080515*	50-155 Q
SIEGEL, B L	8212090003	TOPREP	SMITH, M	8212290308*	50-3 F	SPESSARD, R L	8212090472	50-461 Q
SIEGEL, B L	8212270353	TOPREP	SMITH, M J	8212060017*	50-315 Q	SPESSARD, R L	8212100141	50-305 Q
SIEGEL, M A	8212230241	50-247 Q	SMITH, M L	8212280130*	50-338 Q	SPESSARD, R L	8212100144*	50-305 Q
SIEGEL, M D	8212010481	RES	SMITH, P	8212270447*	CONTRACT	SPESSARD, R L	8212100234	50-483 Q
SIEGEL, S H	8211020166*	50-278 H	SMITH, P	8212270266	CONTRACT	SPESSARD, R L	8212100238*	50-483 Q
SIEGFRIED, K A	8212140460	50-341 Q	SMITH, P A	8212070453*	CONTRACT	SPESSARD, R L	8212100255	50-346 Q
SIEGRIST, W	8212160532	PR	SMITH, P A	8212080103*	CONTRACT	SPESSARD, R L	8212100257*	50-346 Q
SILBERG, J	8212130241	50-440 Q	SMITH, P A	8212080583*	CONTRACT	SPESSARD, R L	8212100276	50-454 Q
SILBERG, J	8212130241	50-440 Q	SMITH, P A	8212220034*	CONTRACT	SPESSARD, R L	8212100302*	50-454 Q
SILBERG, J E	8212010208	50-440 Q	SMITH, P A	8212270107*	FOIA	SPESSARD, R L	8212140224	50-373 Q
SILBERG, J E	8212010208	50-440 Q	SMITH, P A	8212270110*	FOIA	SPESSARD, R L	8212280108	50-461 A
SILBERG, J E	8212010212	50-440 Q	SMITH, P A	8212270123*	FOIA	SPESSARD, R L	8212280242	50-315 Q
SILBERG, J E	8212010212	50-440 Q	SMITH, P A	8212270127*	FOIA	SPESSARD, R L	8212280246*	50-315 Q
SILBERG, J E	8212070358	50-440 Q	SMITH, P A	8212270131*	FOIA	SPESSARD, R L	8212280381*	50-461 Q
SILBERG, J E	8212070358	50-440 Q	SMITH, P A	8212270476	CONTRACT	SPESSARD, R L	8212290330	50-315 Q
SILBERG, J E	8212080293	50-440 Q	SMITH, P A	8212270502*	CONTRACT	SPESSARD, R L	8212290331*	50-315 Q
SILBERG, J E	8212080293	50-440 Q	SMITH, P A	8212270509	CONTRACT	SPIRO, H J	8212080027*	FOIA
SILBERG, J E	8212090176	50-440 Q	SMITH, P A	8212270513*	CONTRACT	SPIRO, H J	8212080030*	FOIA
SILBERG, J E	8212140445	50-440 Q	SMITH, P A	8212270516*	CONTRACT	SPIRO, H J	8212080069*	FOIA
SILBERG, J E	8212140445	50-440 Q	SMITH, P A	8212280044*	CONTRACT	SPRUCE, J K	8212170128*	50-498 A
SILBERG, J E	8212160247	50-440 Q	SMITH, P A	8212270273*	CONTRACT	STADNICK, S	8212030234*	50-326 S
SILBERG, J E	8212160247	50-440 Q	SMITH, P A	8212300132*	CONTRACT	STAHL, D M	8212140387	50-339 Q
SILBERG, J E	8212160251	50-440 Q	SMITH, P D	8203010313*	FOIA	STAHL, D M	8212140387	50-329 Q
SILBERG, J E	8212160251	50-440 Q	SMITH, P D	8205040451*	FOIA	STAHMER, F	8212280442*	50-295 S
SILBERG, J E	8212200061	50-440 Q	SMITH, P D	8205240413*	FOIA	STALLINGS, C M	8212290069*	50-280 S
SILBERG, J E	8212200061	50-440 Q	SMITH, P D	8206290144*	FOIA	STALLINGS, C M	8212290075*	50-280 S
SILBERG, J E	8212200061	50-440 Q	SMITH, P D	8208030436*	FOIA	STALLINGS, C M	8212290080*	50-280 S
SILBERG, J E	8212210321	50-440 Q	SMITH, P D	8212100133*	CONTRACT	STALLINGS, C M	8212290085*	50-281 S
SILBERG, J E	8212210345	50-440 Q	SMITH, R D	8212030254	40-8452	STALLINGS, C M	8212290172*	50-280 Q
SILBERG, J E	8212210345	50-440 Q	SMITH, R D	8212030270	40-6622	STALLINGS, J E	8212210501	71-488
SILVER, R D	7907300565*	50-255 P	SMITH, R D	8212170443	40-8728	STALLINS, C M	8212290075*	50-280 S
SILVERSTROM, L	8212200015	50-537 Q	SMITH, R D	8212230219	40-8745	STALLINS, C M	8212290080*	50-280 S
SILVERSTROM, L	8212300011	50-537 Q	SMITH, R D	8212280184	WASTE MGT	STALLINS, C M	8212290085*	50-281 S
SILVIS, R M	8212030236	CONTRACT	SMITH, W D	8212020229	50-316 S	STALLINS, C M	8212290172*	50-280 Q
SILVIS, R M	8212030246	CONTRACT	SMITH, W D	8212020283	50-315 S	STALLINS, J E	8212210501	71-488
SILVIS, R M	8212080560	50-443 A	SMITH, W D	82120600031	50-315 S	STAMIRIS, B	8212020343	50-329 Q
SILVIS, R M	8212220536	CONTRACT	SMITH, W D	8212060048	50-316 S	STAMIRIS, B	8212020345	50-329 Q
SILVIS, R M	8212220539	CONTRACT	SMITH, W D	8212100177	50-316 S	STAMIRIS, B	8212100095	50-329 Q
SILVIS, R M	8212230044	CONTRACT	SMITH, W D	8212100251	50-315 S	STANSBERRY, E R	8212130238	50-182 P
SILVIS, R M	8212270446	CONTRACT	SMITH, W D	8212100322	50-315 S	STANSBERRY, W W	8212070206*	50-338 Q
SILVIS, R M	8212270518	CONTRACT	SMITH, W D	8212140156	50-316 S	STAR, R M	8212080127	50-537 A
SILVIS, R M	8212270558	CONTRACT	SMITH, W D	8212170224	50-316 S	STAR, R M	8212080143	50-537 A
SILVIS, R M	8212280047	CONTRACT	SMITH, W D	8212170267	50-316 S	STAR, R M	8212080148	50-537 Q
SILVIS, R M	8212300170	CONTRACT	SMITH, W D	8212170283	50-315 S	STAR, R M	821220160	50-537 A
SIMCHUK, J D	8212270377	71-9079	SMITH, W D	8212200056	50-316 R	STARKEY, R B	8212060199	50-261 R
SIMCHUK, J D	8212270408	71-9079	SMITH, W D	8212200119	50-315 R	STARKEY, R B	8212090120	50-261 S
SIMON, W A	8211290142*	50-528 A	SMITH, W D	8212270217	50-316 R	STARKEY, R B	8212300272	50-261 S
SIMON-TOV, M	8212010478	RES	SMITH, W D	8212290395	50-316 B	STAROVICH, V S	8212130157	50-537 A
SINCLAIR, J B	8212090374	50-271 P	SMITH, W D	8212290419	50-315 R	STAROVICH, V S	8212030065	50-333 Q
SINCLAIR, J B	8212100310	50-271 P	SMITH, W D	8212210234*	50-289 R	STAROSTECKI, R	8212030069	50-322 Q
SINCLAIR, J B	8212210138	50-271 P	SNEAD, M H	8212290056*	CONTRACT	STAROSTECKI, R	8212030123	50-286 Q
SINCLAIR, J B	8212270212	50-271 P	SNOW, B A	8212290163	50-244 R	STAROSTECKI, R	8212060189	50-412 Q
SINISI, J M	8212280063	50-245 J	SNYDER, B J	8212230384	50-320 P	STAROSTECKI, R	8212060278	50-272 Q
SINISI, J M	8212280258	50-244 J	SNYDER, S J	8212280029	50-320 P	STAROSTECKI, R	8212060285	50-317 Q
SINISI, J M	8212280441	50-293 J	SNYDER, H L	8212210558	40-8584	STAROSTECKI, R	8212070106	50-320 Q
SINISI, J M	8212300333	50-29 J	SOBON, L J	8212290018*	FOIA	STAROSTECKI, R	8212070151	50-387 Q
SINKIN, L	8212060083	50-498 Q	SOLLENBERGER, D	8212070063	40-2259	STAROSTECKI, R	8212070284	50-392 Q
SINKIN, L	8212100125	50-498 Q	SOLLENBERGER, D	8212230391	40-8602	STAROSTECKI, R	8212080314	50-277 Q
SINKULE, M V	8212290184*	50-280 Q	SOLLENBERGER, D	8212270063	40-299	STAROSTECKI, R	8212080321	50-443 Q
SIZEMORE, H M	8212010099*	FOIA	SOLLENBERGER, D	8212280048	40-8681	STAROSTECKI, R	8212080347	50-219 Q
SKOLDS, J L	8212070034*	50-395 Q	SOLLENBERGER, D	8212280079	40-8452	STAROSTECKI, R	8212100007	50-317 Q
SKOLDS, J L	8212090545*	50-395 Q	SOLLERVILLE, K Q	8212280435	40-8763	STAROSTECKI, R	8212140074	50-213 Q
SHEDIRA, C	8211230037	71-9096	SOO, P	8212020010	RES	STAROSTECKI, R	8212140098	50-271 Q
SMITH, A	8212170359*	50-321 P	SOO, A	8212080695*	70-698	STAROSTECKI, R	8212140124	50-272 Q
SMITH, A L	8212300303*	0A999	SOONG, A L	8212100180*	70-1334	STAROSTECKI, R	8212140137	50-247 Q
SMITH, C N	8212080018*	70-143	SPANENBERG, F	8210190729	50-522 B	STAROSTECKI, R	8212140150	50-334 Q
SMITH, O	8212290479*	50-219 Q	SPER, M J	8212290106*	50-204 R	STAROSTECKI, R	8212140311	50-320 Q
SMITH, O C	8212290443*	50-272 Q	SPEIS, T P	8202180460*	50-255 P	STAROSTECKI, R	8212140322	50-423 Q
SMITH, O H	8212160103*	FOIA	SPEIS, T P	8204010021*	50-185 P	STAROSTECKI, R	8212140397	50-220 Q
SMITH, I W	8212200102	50-454 Q	SPEIS, T P	8209220450*	50-331 P	STAROSTECKI, R	8212140424	50-412 Q

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
STAROSTECKI, R	8212140470	50-410 Q	STERNBERG, D M	8212300268	50-508 Q	STOLZ, J F	8212170110	50-312 P
STAROSTECKI, R	8212150159	50-309 Q	STERNBERG, D M	8212300308	50-397 Q	STOLZ, J F	8212170392	50-346 P
STAROSTECKI, R	8212150207	50-220 Q	STERNBERG, D M	8212300320	50-508 Q	STOLZ, J F	8212210013	50-313 P
STAROSTECKI, R	8212150219	50-293 Q	STERNBERG, D M	8212300350	50-312 Q	STOLZ, J F	8212210013	50-313 P
STAROSTECKI, R	8212160480	50-277 Q	STEVENSON, J D	7906040228*	50-237 P	STOLZ, J F	8212290220	50-277 P
STAROSTECKI, R	8212210015	50-293 F	STEVENSON, J D	8212060458	NUREQ	STOLZ, J F	8212270381	50-302 P
STAROSTECKI, R	8212210025	50-293 Q	STEVENSON, J D	8212270221	NUREQ	STOLZ, J F	8212280071*	50-346 P
STAROSTECKI, R	8212210038	50-272 F	STEVENSON, T D	9004010318*	50-237 P	STOLZ, J F	8212280074*	50-346 P
STAROSTECKI, R	8212210084	50-219 Q	STEWART, A E	8212200057	PRM	STOLZ, J F	8212290022	50-313 P
STAROSTECKI, R	8212210131	50-220 F	STEWART, J P	8212060170*	50-362 Q	STOLZ, J F	8212290268*	50-312 P
STAROSTECKI, R	8212210149	50-29 F	STEWART, R C	8212030156*	50-445 Q	STOLZ, J F	8212290299*	50-312 P
STAROSTECKI, R	8212210174	50-277 F	STEWART, M L	8212060134	50-280 P	STOLZ, J F	8212290450	50-321 P
STAROSTECKI, R	8212210177	50-333 F	STEWART, M L	8212060284	50-280 P	STOLZ, J F	8212300189	50-321 Q
STAROSTECKI, R	8212210213	50-322 F	STEWART, M L	8212060303	50-280 P	STOLZ, J F	8212300193	50-346 F
STAROSTECKI, R	8212210270	50-443 Q	STEWART, M L	8212090169*	50-280 Q	STOLZ, J F	8212300339*	50-289 P
STAROSTECKI, R	8212210295	50-271 F	STEWART, W L	8212090217*	50-280 Q	STOUT, R B	8212290206*	50-237 P
STAROSTECKI, R	8212210305	50-213 F	STEWART, W L	8212090286*	50-280 Q	STOUT, R B	8212290215*	50-237 P
STAROSTECKI, R	8212210334	50-334 F	STEWART, W L	8212090419	50-280 F	STRASINGER, R	8212070184	50-368 Q
STAROSTECKI, R	8212210344	50-309 F	STEWART, W L	8212090485*	50-338 Q	STRATDULY, D	8212270299*	50-275 P
STAROSTECKI, R	8212210409	50-3 F	STEWART, W L	8212130319	50-338 P	STRATDULY, D	8212270301*	50-275 P
STAROSTECKI, R	8212210453	50-219 Q	STEWART, W L	8212130326	50-338 P	STRATDULY, D C	8212270310*	50-275 P
STAROSTECKI, R	8212220361	50-213 Q	STEWART, W L	8212130327	50-281 P	STRATDULY, D C	8212270312*	50-275 P
STAROSTECKI, R	8212220366	50-3 Q	STEWART, W L	8212150048	50-338 P	STRATDULY, D C	8212290237*	50-275 P
STAROSTECKI, R	8212220386	50-309 Q	STEWART, W L	8212150059	50-280 F	STRATDULY, D C	8212290243*	50-275 P
STAROSTECKI, R	8212220402	50-293 Q	STEWART, W L	8212170041*	50-280 F	STRATDULY, D C	8212290250*	50-275 P
STAROSTECKI, R	8212220412	50-277 Q	STEWART, W L	8212170457*	50-280 F	STREETEY, J	8212100261	50-373 S
STAROSTECKI, R	8212220413	50-220 Q	STEWART, W L	8212210187	50-338 P	STREETEY, J	8212210247	50-263 S
STAROSTECKI, R	8212220417	50-333 Q	STEWART, W L	8212270179	50-280 F	STREETEY, J	8212280207	50-237 S
STAROSTECKI, R	8212220418	50-29 Q	STEWART, W L	8212280073	50-281 P	STREETEY, J	8212270151	50-346 S
STAROSTECKI, R	8212220423	50-271 Q	STEWART, W L	8212280201	50-338 P	STREETEY, J	8212270276	50-263 S
STAROSTECKI, R	8212220430	50-309 Q	STEWART, W L	8212280257	50-280 F	STREETEY, J F	8212030021	50-373 Q
STAROSTECKI, R	8212220444	50-272 Q	STEWART, W L	8212280259	50-339 P	STREETEY, J F	8212030121	50-255 Q
STAROSTECKI, R	8212220451	50-244 Q	STEWART, W L	8212280349	50-280 P	STREETEY, J F	8212030134	50-282 Q
STAROSTECKI, R	8212220453	50-322 Q	STEWART, W L	8212290191	50-280 P	STREETEY, J F	8212030187	50-254 Q
STAROSTECKI, R	8212220459	50-289 Q	STEWART, W L	8212290238	50-280 R	STREETEY, J F	8212060036	50-10 Q
STAROSTECKI, R	8212220464	50-289 Q	STEWART, W L	8212290248	50-338 P	STREETEY, J F	8212060044	50-305 Q
STAROSTECKI, R	8212220466	50-219 Q	STEWART, W L	8212290261	50-280 Q	STREETEY, J F	8212170196	50-10 Q
STAROSTECKI, R	8212220476	50-220 Q	STEWART, W L	8212290264*	50-280 Q	STREETEY, J F	821210361	50-346 Q
STAROSTECKI, R	8212220490	50-334 Q	STEWART, W L	8212290317	50-338 R	STREETEY, J F	8212270198	50-373 Q
STAROSTECKI, R	8212270358	50-247 Q	STEWART, W L	8212290459	50-281 Q	STREETEY, J F	8212290449	50-346 Q
STAROSTECKI, R	8212290065*	50-244 S	STICKLEY, T H	8212010519*	50-352 A	STREIT, J E	8212080505	RES
STAROSTECKI, R	8212290280	50-334 Q	STICKLEY, T H	8212080551*	50-443 A	STREIT, J E	8212130110	NUREQ
STAROSTECKI, R	8212290350	50-320 Q	STIEDE, W L	8212280448*	50-454 Q	STRIP, D R	8212220204	NUREQ
STAROSTECKI, R	8212290371	50-289 Q	STIEGELMEYER, W	8212270056*	50-289 P	STRIP, S W	8212130352	50-247 Q
STAROSTECKI, R	8212290393	50-184 Q	STILL, N L	8212230387	WASTE MGT	STUCKY, S W	8212160297	50-289 Q
STAROSTECKI, R	8212290422	50-293 Q	STILL, N L	8212290260	WASTE MGT	STUCKY, S W	8212210326	50-537 Q
STAROSTECKI, R	8212290436	50-354 Q	STILLWELL, T C	8209230258*	50-409 P	STUCKY, S W	8212220224	70-143
STAROSTECKI, R	8212290463	50-387 Q	STOLBER, G J	8212070160	50-237 Q	STUCKY, S W	8212280326	50-247 Q
STAROSTECKI, R	8212290488	50-193 Q	STOLZ, J F	8212290026	50-346 F	STUCKY, S W	8212300010	50-413 Q
STAROSTECKI, R	8212270530*	CONTRACT	STOLZ, J F	8212010160	50-302 P	SULLIVAN, E C	8212230241	50-247 Q
STASEK, S	8212170201*	50-10 Q	STOLZ, J F	8212010164*	50-302 P	SULLIVAN, M D	8212100303*	50-331 Q
STEELE, R L	8212030011	50-344 S	STOLZ, J F	8212010172*	50-302 P	SULLIVAN, W H	8212020095	50-155 P
STEFANO, J J	8212070491	50-440 A	STOLZ, J F	8212010193*	50-269 P	SUMMERS, R	8212060287*	50-272 Q
STEFANO, J J	8212080019	50-440 Q	STOLZ, J F	8212010276*	50-269 P	SUMNER, H L	8212020295*	50-366 S
STEFANO, J J	8212080021	50-440 A	STOLZ, J F	8212010330*	50-302 P	SUMNER, H L	8212030174*	50-321 S
STEFANO, J J	8212080115	50-440 A	STOLZ, J F	8212010332*	50-302 P	SUMNER, H L	8212090145*	50-321 S
STEFANO, J J	8212270002	50-440 E	STOLZ, J F	8212010342	50-289 P	SUMNER, H L	8212090193*	50-366 S
STEFANO, J J	8212300077	50-440 A	STOLZ, J F	8212010368*	50-322 A	SUMNER, H L	8212090219*	50-321 S
STEGER, W A	8212070404	FOIA	STOLZ, J F	8212010418*	50-269 P	SUMNER, H L	8212300102*	50-366 S
STENINGUT, R	8212230241	50-247 Q	STOLZ, J F	8212010488*	50-269 P	SURMEIER, J J	8212020121	WASTE MGT
STELLO, V	8212020072	REVIEW GRP	STOLZ, J F	8212030337	50-346 P	SURMEIER, J J	8212230390	WASTE MGT
STELLI, D, V	8212080099*	70-143	STOLZ, J F	8212060024	50-312 Q	SUTHERLAND, W A	8212200072*	50-440 Q
STELLI, D, V	8212080227	ORO	STOLZ, J F	8212060147	50-289 P	SUTHERLAND, W A	8212000072*	50-440 Q
STELLI, D, V	8212090141	REVIEW GRP	STOLZ, J F	8212060310	50-269 Q	SUTTON, J H	8212070169*	QA999
STELLI, D, V	8212170245	REVIEW GRP	STOLZ, J F	8212060313*	50-269 Q	SVENSSON, B A	8212170268*	50-316 S
STELLO, V	8212280408	REVIEW GRP	STOLZ, J F	8212070459	50-346 P	SVENSSON, B A	8212200122*	50-315 R
STELLO, V	8212290062	REVIEW GRP	STOLZ, J F	8212080552*	50-346 P	SVENSSON, B A	8212290228*	50-316 R
STEPHENSON, C J	8212140239*	50-289 S	STOLZ, J F	8212090040	50-346 P	SWALLOW, J H	8212210363*	50-391 Q
STERN, H J	8212230241	50-247 Q	STOLZ, J F	8212090044	50-269 F	SWANSON, D T	8212150123	50-537 Q
STERNBERG, D	8212060163	50-312 Q	STOLZ, J F	8212100365	50-277 P	SWANSON, E R	8212280231*	50-315 Q
STERNBERG, D M	8212060173	50-243 Q	STOLZ, J F	8212100393	50-321 P	SWANSON, E R	8212290335*	50-315 Q
STERNBERG, D M	8212060205	50-397 Q	STOLZ, J F	8212100414	50-346 P	SWARTZ, E D	8212220212	50-10 P
STERNBERG, D M	8212060260	50-508 Q	STOLZ, J F	8212100453*	50-346 P	SWARTZ, E D	8212280117	50-237 P
STERNBERG, D M	8212060384	50-344 Q	STOLZ, J F	8212100481*	50-346 P	SWARTZ, E D	8212280212	50-237 P
STERNBERG, D M	8212090546	50-528 Q	STOLZ, J F	8212100488	50-313 P	SWARTZ, E D	8212280343	50-237 P
STERNBERG, D M	8212130207	50-528 Q	STOLZ, J F	8212130051	50-346 P	SWETLAND, P	8212150169*	50-309 Q
STERNBERG, D M	8212130269	50-27 Q	STOLZ, J F	8212130117*	50-346 P	SWIGER, M A	82122200105	50-440 Q
STERNBERG, D M	8212170103*	50-397 Q	STOLZ, J F	8212130124*	50-346 P	SWIGER, M A	82122200105	50-440 Q
STERNBERG, D M	8212170354	50-508 Q	STOLZ, J F	8212150235	50-302 P	SWIGER, M A	8212300013	50-440 Q
STERNBERG, D M	8212210195*	50-508 Q	STOLZ, J F	8212160542	50-313 F	SWIGER, M A	8212300013	50-440 Q
STERNBERG, D M	8212210203	50-528 Q	STOLZ, J F	8212160544*	50-278 P	SWYLER, K J	8212280040	RES
STERNBERG, D M	8212210416	50-397 Q	STOLZ, J F	8212160550*	50-278 P	SWYLER, K J	82122800514	50-320 P
STERNBERG, D M	8212220213	50-397 Q	STOLZ, J F	8212170009	50-312 P	SYLVESTER, E D	8212220141*	50-312 Q
STERNBERG, D M	8212280301*	50-508 Q	STOLZ, J F	8212170063	50-277 P	SYRONGE, J H	8212020205	50-346 P
STERNBERG, D M	8212300070	50-508 Q	STOLZ, J F	8212170089*	50-312 P	TALLEY, W T	8212130185*	50-400 A

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
TALNAGI, J. W	8212010074*	50-150 F	TIPPS, S B	8212090149*	50-366 S	TRIPP, L. E	8212300072	50-272 P
TAUBER, H	8212090041	50-341 E	TIPPS, S B	8212090207*	50-321 S	TROFC, T. W	8212270561	NUREQ
TAUBER, H	8212100166	50-341 A	TIPPS, S B	8212090234*	50-366 S	TROJANGWSKI, R	8212100128*	70-143
TAUBER, H	8212100267	50-341 A	TIPPS, S B	8212090335*	50-366 S	TROJANSKY	8212010474	RES
TAUBER, H	8212130424	70-2926	TIPPS, S B	8212090341*	50-321 S	TROSKOSKI, W. M	8212140160*	50-334 Q
TAUBER, H	8212130427*	70-2926	TIPPS, S B	8212090388*	50-366 S	TROUP, Q. L	8212090265*	70-824
TAUBER, H	8212140375	50-341 F	TIPPS, S B	8212090391*	50-366 S	TROUP, Q. L	8212290165*	FOIA
TAUBER, H	8212300311	50-341 A	TIPPS, S B	8212090399*	50-366 S	TROUP, Q. L	8212290184*	FOIA
TAYLOR, J	8212080228	50-409 P	TIPPS, S B	8212090446*	50-366 S	TROWBRIDGE, G. F	8212010192	50-289 Q
TAYLOR, J. H	8212130217	TOPREP	TIPPS, S B	8212100279*	50-366 S	TROWBRIDGE, G. F	8212010192	50-289 Q
TAYLOR, J. H	8212130233	TOPREP	TIPPS, S B	8212100286*	50-366 S	TROWBRIDGE, G. F	8212010200*	50-289 Q
TAYLOR, J. H	8212130234	TOPREP	TIPPS, S B	8212100314*	50-366 S	TROWBRIDGE, G. F	8212010200*	50-289 Q
TAYLOR, J. H	8212150113*	50-289 P	TIPPS, S B	8212140123*	50-366 S	TROWBRIDGE, G. F	8212020364	50-289 Q
TAYLOR, M	8212140476	NUREQ	TIPPS, S B	8212140271*	50-321 S	TROWBRIDGE, G. F	8212020364	50-289 Q
TAYLOR, P	8212090213*	50-389 Q	TIPPS, S B	8212140429*	50-366 S	TROWBRIDGE, G. F	8212020377	50-289 Q
TAYLOR, P. A	8212090360*	50-389 Q	TIPPS, S B	8212140436*	50-366 S	TROWBRIDGE, G. F	8212300246	50-289 Q
TAYLOR, T.	8212020265	PRM	TIPPS, S B	8212150011*	50-321 S	TROWBRIDGE, G. F	8212300250	50-289 Q
TERC, N. M	8212160406*	50-289 Q	TIPPS, S B	8212150018*	50-321 S	TROWBRIDGE, G. F	8212300250	50-289 Q
TERC, N. M	8212220388*	50-289 Q	TIPPS, S B	8212150037*	50-321 S	TSAT, N. C	8212010036*	50-266 P
TERHUNE, J. H	8212210414*	50-322 E	TIPPS, S B	8212170099*	50-321 S	TSAT, T	8005280561*	50-219 P
TERRELL, C. W	8212010066*	50-112 F	TIPPS, S B	8212170165*	50-366 S	TSCHUBI, H. F	8212270307*	50-237 Q
TERRELL, C. W	8212010066*	50-112 F	TIPPS, S B	8212170202*	50-321 S	TUCKER, H. B	8212030002	50-369 P
TESKE, M. E	8212280334*	50-387 P	TIPPS, S B	8212210088*	50-321 S	TUCKER, H. B	8212030049	50-413 A
TEST, R. Z	8212080459*	50-213 S	TIPPS, S B	8212210195*	50-321 S	TUCKER, H. B	8212030080	50-413 A
TETZLAFF, A. L	8212290434*	50-315 R	TIPPS, S B	8212210452*	50-366 S	TUCKER, H. B	8212060244	50-369 P
THADANI, M. C	8212010396*	50-443 Q	TIPPS, S B	8212280161*	50-366 S	TUCKER, H. B	8212070341	50-269 P
THANUS, L.	8212220478*	50-289 Q	TIPPS, S B	8212280392*	50-321 S	TUCKER, H. B	8212070370	50-269 P
THATCHER, T. L	8212070172	50-522 Q	TIPPS, S B	8212300063*	50-366 S	TUCKER, H. B	8212090079	50-414 S
THATCHER, T. L	8212070172	50-522 Q	TIPPS, S B	8212300095*	50-321 S	TUCKER, H. B	8212090192*	50-369 Q
THATCHER, T. L	8212160267	50-522 Q	TIPPS, S B	8212300270*	50-321 S	TUCKER, H. B	8212090221	50-287 S
THAYER, T.	8212080031*	FOIA	TIPPS, S B	8212300275*	50-321 S	TUCKER, H. B	8212090233	50-413 Q
THAYER, T. C	8212080084*	FOIA	TIPPS, S B	8212300281*	50-321 S	TUCKER, H. B	8212090239*	50-413 Q
THEHHAUSE, P. C	8212280438*	50-409 P	TIPPS, S B	8212300289*	50-321 S	TUCKER, H. B	8212090250	50-369 Q
THEOFANOUS, T. G	8208270032	ACRS	TIPPS, S B	8212300290*	50-366 S	TUCKER, H. B	8212090323	50-414 S
THEOFANOUS, T. G	8208270032	ACRS	TIPPS, S B	8212300292*	50-366 S	TUCKER, H. B	8212090339	50-369 Q
THEOFANOUS, T. G	8212010428*	ACRS	TIPPS, S B	8212300298*	50-366 S	TUCKER, H. B	8212090401	50-369 Q
THOM, T.	8212270287*	50-259 R	TIPPS, S B	8212300325*	50-366 S	TUCKER, H. B	8212090420	50-269 Q
THOMAS, C. J	8212030020*	70-2792	TIPPS, S B	8212300337*	50-321 S	TUCKER, H. B	8212090442	50-413 Q
THOMAS, C. D	8212020142	50-461 A	TIPPS, S B	8212300345*	50-366 S	TUCKER, H. B	8212090462	50-413 Q
THOMAS, C. D	8212020211	50-146 P	TIPPS, S B	8212300346*	50-366 S	TUCKER, H. B	8212090522	50-413 Q
THOMAS, C. D	8212080552	TOPREP	TOALSTON, A. L	8212010046	50-389 M	TUCKER, H. B	8212130069	50-269 F
THOMAS, C. D	8212150211	50-20 P	TOALSTON, A. L	8212010208	50-389 M	TUCKER, H. B	8212130190	50-269 F
THOMAS, C. D	8212210535	TOPREP	TOALSTON, A. L	8212010292	50-389 M	TUCKER, H. B	8212130257	50-413 A
THOMAS, C. D	8212300092	50-423 A	TOALSTON, A. L	8212010299	50-389 M	TUCKER, H. B	8212140171	50-369 S
THOMAS, F. A	8212060498	NUREQ	TOBIAS, M. L	8212130133	NUREQ	TUCKER, H. B	8212140263	50-413 A
THOMAS, F. A	8212270221	NUREQ	TOBIN, H. J	8212080139*	FOIA	TUCKER, H. B	8212140390	50-369 P
THOMAS, F. A	8212140168	50-219 S	TODD, O. A	8212090445*	70-1151	TUCKER, H. B	8212140425	50-369 S
THOMAS, J	8212210089*	50-219 Q	TODD, M. T	8212300323*	50-247 Q	TUCKER, H. B	8212150073	50-269 P
THOMAS, J. H	8212280473*	50-219 Q	TODDSON, R.	8212280518	RES	TUCKER, H. B	8212160044	50-413 A
THOMAS, L. H	8212280087*	50-247 F	TOHLINSON, D. P	8212030156*	50-445 Q	TUCKER, H. B	8212160249	50-369 P
THOMAS, L. H	8212290207	50-416 F	TOHLINSON, D. P	8212030192*	50-366 Q	TUCKER, H. B	8212160345	50-413 A
THOMAS, M.	8212090271*	50-370 Q	TOMPKINS, B. A	8212200093	50-440 Q	TUCKER, H. B	8212170256	50-413 S
THOMAS, M.	8212090493*	50-327 Q	TOMPKINS, B. A	8212300147	50-289 Q	TUCKER, H. B	8212170290	50-369 P
THOMAS, M.	8212040132	13E	TOMPKINS, B. A	8212300152	50-312 Q	TUCKER, H. B	8212200005	50-369 S
THOMAS, R. D	8212300210*	70-734	TOMPKINS, B. A	8212300137	50-155 P	TUCKER, H. B	8212210060	50-369 R
THOMAS, R. D	8212300213*	70-734	TOMPKINS, B. A	8212300192*	50-366 Q	TUCKER, H. B	8212210079	50-269 P
THOMAS, R. D	8212300240*	70-25	TOMPKINS, B. A	8212300224	50-255 P	TUCKER, H. B	8212210145	50-369 S
THOMAS, V. M	8212220193	NUREQ	TOMPKINS, B. A	8212300415	50-237 S	TUCKER, H. B	8212210231	50-413 S
THOMPSON, D.	8212160103*	FOIA	TONGUE, T	8212220207	50-237 S	TUCKER, H. B	8212210419	50-370 K
THOMPSON, S. E	8212140464	NUREQ	TONGUE, T. M	8212170201*	50-10 Q	TUCKER, H. B	8212210421	50-269 R
THOMPSON, S. E	8212160773	NUREQ	TOSTE, A. P	8212220523	RES	TUCKER, H. B	8212220227	50-413 A
THOMPSON, T.	8212280077*	50-346 S	TOTH, A. D	8212060208*	50-397 Q	TUCKER, H. B	8212230076*	50-369 F
THOMPSON, F. T	8212070239	50-522 Q	TOTH, A. D	8212130270*	50-27 Q	TUCKER, H. B	8212230108*	50-269 F
THOMPSON, F. T.	8212070239	50-522 Q	TOURTELLOTT, J.	8212100088	RECY	TUCKER, H. B	8212270261	50-413 A
THOMPSON, F. T.	8212270225	50-522 Q	TRAMM, T. R	8211290530	50-454 K	TUCKER, H. B	8212280391	50-269 P
THOMPSON, F. T.	8212270225	50-522 Q	TRAMM, T. R	8212020329	50-454 S	TUCKER, H. B	8212280380	50-369 S
THOMUS, L.	8212070111*	50-320 Q	TRAMM, T. R	8212070177	50-454 A	TUCKER, H. B	8212290232	50-369 P
THOMUS, L.	8212140319*	50-320 Q	TRAMM, T. R	8212070198*	50-454 A	TUCKER, H. B	8212290354	50-413 A
THORNBERY, R. C	8212080077*	50-275 F	TRAMM, T. R	8212070207*	50-454 A	TUCKER, H. B	8212300093	50-369 S
THORNBERY, R. C	8212270214	50-275 R	TRAMM, T. R	8212070249	50-454 E	TUCKER, H. B	8212300287	50-287 S
THORNE, P. D	8212220238	NUREQ	TRAMM, T. R	8212140243	50-10 F	TUCKER, H. B	8212300264	50-287 S
THORNTON, P.	8212210258	50-155 Q	TRAMM, T. R	8212170192	50-454 S	TURK, J.	8212280276	50-70
THORNTON, P.	8212210258	50-155 Q	TRAMM, T. R	8212280306	50-454 K	TURK, S. E	8212060007	50-382 Q
THORPE, D.	8212020264*	50-296 S	TRAUGER, T. C	8212270502*	CONTRACT	TURK, S. E	8212080260	50-382 Q
THORPE, D.	8212150104*	50-260 S	TREBY, S. A	8212010040	50-358 Q	TURK, S. E	8212150131	50-382 Q
THORPE, D.	8212150111*	50-296 S	TREBY, S. A	8212290001	50-338 Q	TURK, S. E	8212150148*	50-382 Q
THORSEN, E. O	8212140451	50-247 S	TRENT, D. S	8212220509	NUREQ	TURLEY, K. L	8212290139	50-528 A
THULL, T. S	8212030189*	50-245 S	TRIMBLE, D. C.	8212100013*	50-317 Q	TWOOD, F. J	8212140319*	50-413 A
THULL, T. S	8212160371*	50-245 S	TRIPP, L. E	8212060192*	50-412 Q	TYLER, J. M	8212070330*	50-155 Q
TJEN, P.	8212010469	RES	TRIPP, L. E	8212020006	50-354 Q	TYLER, J. M	8212070330*	50-155 Q
TILLMAN, A.	8212090124*	50-259 Q	TRIPP, L. E.	8212060195	50-272 S	UDALL, M. K	8212230341	50-247 U
TILLMAN, A.	8212150090	50-321 S	TRIPP, L. E.	8212060287*	50-272 Q	UDERITZ, R. A	8212030153*	50-272 Q
TILLMAN, A.	8212150143*	70-143	TRIPP, L. E.	8212140160*	50-334 Q	UDERITZ, R. A	8212140133*	50-272 Q
TIMMINS, D. C	82120270018*	50-397 A	TRIPP, L. E.	8212210089*	50-219 Q	UHRIG, R. E.	8212010026	NUREQ
TIPPS, S. B	8212090126*	50-366 S	TRIPP, L. E.	8212220473*	50-219 Q	UHRIG, R. E.	8212030216	50-369 S

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
UHRIG, R E	8212070215	50-389 S	VANDEWALLE, D J	8212280382	50-255 F	VERRELLI, D M	8212090244*	50-400 Q
UHRIG, R E	8212090200	50-389 S	VANDQORN, P K	8212090261*	50-413 Q	VERRELLI, D M	8212090273	50-324 Q
UHRIG, R E	8212090503*	50-250 Q	VARGA, S A	8212010462	50-272 F	VERRELLI, D M	8212090281	50-261 Q
UHRIG, R E	8212090549*	50-335 Q	VARGA, S A	8212030257	50-247 P	VERRELLI, D M	8212090334	50-390 Q
UHRIG, R E	8212090554*	50-335 Q	VARGA, S A	8212030267	50-305 P	VERRELLI, D M	8212090345	50-261 Q
UHRIG, R E	8212090559*	50-335 Q	VARGA, S A	8212030342	50-305 P	VERRELLI, D M	8212090348	50-400 Q
UHRIG, R E	8212140373	50-389 A	VARGA, S A	8212060130	50-261 P	VERRELLI, D M	8212090354	50-327 Q
UHRIG, R E	8212150068	50-335 P	VARGA, S A	8212060137*	50-261 P	VERRELLI, D M	8212090357	50-417 Q
UHRIG, R E	8212150074	50-389 S	VARGA, S A	8212060138	50-280 F	VERRELLI, D M	8212090370*	50-327 Q
UHRIG, R E	8212150098	50-389 S	VARGA, S A	8212060338	50-280 F	VERRELLI, D M	8212090400	50-390 Q
UHRIG, R E	8212150129	50-389 A	VARGA, S A	8212070478*	50-295 P	VERRELLI, D M	8212090486	50-327 Q
UHRIG, R E	8212150180	50-250 R	VARGA, S A	8212070482*	50-295 P	VERRELLI, D M	8212090497	50-390 Q
UHRIG, R E	8212150204	70-2757	VARGA, S A	8212070498*	50-305 P	VERRELLI, D M	8212090511	50-348 Q
UHRIG, R E	8212170127	50-335 P	VARGA, S A	8212070504*	50-305 P	VERRELLI, D M	8212090528	50-438 Q
UHRIG, R E	8212170269	50-389 A	VARGA, S A	8212080060	50-364 P	VERRELLI, D M	8212280278	50-324 S
UHRIG, R E	8212170273	50-250 P	VARGA, S A	8212080077*	50-364 P	VERRELLI, D M	8212280453	50-260 S
UHRIG, R E	8212170274	50-335 P	VARGA, S A	8212080083*	50-364 P	VETERE, L A	8212150008	50-247 T
UHRIG, R E	8212210101	50-389 E	VARGA, S A	8212080569	50-247 P	VETERE, L A	8212220220	50-247 Q
UHRIG, R E	8212210190	50-250 P	VARGA, S A	8212100012	50-280 P	VETERE, L A	8212220226*	50-247 Q
UHRIG, R E	8212210348	50-389 S	VARGA, S A	8212130023	50-286 P	VETTER, D L	8212270260*	50-537 A
UHRIG, R E	8212210354	50-389 S	VARGA, S A	8212130030	50-247 P	VICTOR, R A	82121300370*	50-344 P
UHRIG, R E	8212220200	50-389 A	VARGA, S A	8212150141	50-295 P	VIETTI, A	8212130244	50-308 A
UHRIG, R E	8212229068*	50-250 Q	VARGA, S A	8212160578*	50-364 P	VIGIL, J C	8109280383*	RES
UHRIG, R E	8212290094*	50-250 Q	VARGA, S A	8212160586*	50-364 P	VINGENT, R E	8212220226*	PRM
UHRIG, R E	8212290097*	50-250 Q	VARGA, S A	8212170032	50-334 F	VOGLER, B H	8212220075	50-440 M
UHRIG, R E	8212290124*	50-250 Q	VARGA, S A	8212220281	50-280 F	VOGLEWEDE, J	8212230248*	50-29 P
UHRIG, R E	8212290263	50-389 E	VARGA, S A	8212220296	50-281 Q	VOOT-LOWELL, R	8212090524*	50-250 Q
UHRIG, R E	8212290357	50-335 P	VARGA, S A	8212220299*	50-281 Q	VOJOT, H E	8212230355	50-341 Q
UHRIG, R E	8212290359	50-335 P	VARGA, S A	8212220470*	50-261 P	VOLLMER, R H	8009290433*	50-206 P
UHRIG, R E	8212290361*	50-335 P	VARGA, S A	8212220477*	50-261 P	VOLLMER, R H	8010150236*	50-206 P
UHRIG, R E	8212300252	50-389 S	VARGA, S A	8212220481	50-280 F	VOLLMER, R H	8010150242*	50-206 P
UHRIG, R E	8212140461	50-389 A	VARGA, S A	8212220487	50-261 F	VOLLMER, R H	8010150246*	50-206 P
ULECK, R B	8212010240	WASTE HOT	VARGA, S A	8212270111*	50-3 F	VOLLMER, R H	8010170287*	50-206 P
ULECK, R B	8212020128	WASTE HOT	VARGA, S A	8212270117*	50-3 F	VOLLMER, R H	8212030265*	50-275 P
ULIE, J	8212170162*	50-155 Q	VARGA, S A	8212290456*	50-295 P	VONHERRMANN, J	8212060471	50-295 P
ULIE, J	8212170189*	50-266 Q	VARGA, S A	8212290464*	50-295 P	VOITH, M H	8212030158	50-54 P
ULRICH, J	8212130177*	50-373 R	VARGA, S A	8212290528*	50-311 P	VOITH, M H	8212070173	50-54 P
UTLEY, E E	8212010078	50-261 P	VARGA, S A	8212290532*	50-311 P	VRIEBHAN, W B	8212010119*	F01A
UTLEY, E E	8212140250	50-324 P	VARGA, S A	8212290534	50-250 P	WADE, P B	8212270194*	50-368 S
UTLEY, E E	8212170210	50-324 P	VARGA, S A	8212300101	50-250 P	WADE, P B	8212300059*	50-368 S
UTLEY, E E	8212290125*	50-261 Q	VARGA, S A	8212300083	50-261 P	WAGNER, D	8212010349	50-394 C
UTLEY, E E	8212290155*	50-261 Q	VARGA, S A	8212300195	50-380 F	WAGNER, D H	8212090030	50-335 P
VAN BLARCOM, E	8212016087*	40-6500	VASSALLO, D B	8212020007	50-331 P	WAGNER, M E	8212070163	50-289 Q
VAN BRUNT, E E	8212030031	50-528 E	VASSALLO, D B	8212060111	50-324 P	WAGNER, P C	8212010185	50-269 P
VAN BRUNT, E E	8212060082	50-530 S	VASSALLO, D B	8212060160	50-324 P	WAGNER, P C	8212010392	50-269 P
VAN BRUNT, E E	8212060143	50-528 Q	VASSALLO, D B	8212090008	50-263 P	WAGNER, P C	8212100355	50-269 P
VAN BRUNT, E E	8212060229	50-528 S	VASSALLO, D B	8212090009	50-263 P	WAGNER, P C	8212210520	50-267 P
VAN BRUNT, E E	8212060240	50-528 S	VASSALLO, D B	8212090010*	50-263 P	WAGNER, P C	8212290421	50-267 P
VAN BRUNT, E E	8212060273	50-528 S	VASSALLO, D B	8212090026*	50-263 P	WAGNER, W J	8212170376*	50-206 Q
VAN BRUNT, E E	8212060283	50-528 S	VASSALLO, D B	8212100014	50-293 P	WAKILD, C	8212160378	70-1113
VAN BRUNT, E E	8212070109	50-528 A	VASSALLO, D B	8212130158	50-271 P	WALKER, D I	8212280022*	70-146
VAN BRUNT, E E	8212070328	50-528 K	VASSALLO, D B	8212130275	50-254 P	WALKER, R	8212090415	50-237 S
VAN BRUNT, E E	8212080137	50-528 F	VASSALLO, D B	8212130276	50-298 P	WALKER, R	8212100261	50-373 S
VAN BRUNT, E E	8212090532*	50-528 Q	VASSALLO, D B	8212130277	50-333 P	WALKER, R	8212210247	50-263 S
VAN BRUNT, E E	8212130216	50-528 S	VASSALLO, D B	8212130280	50-331 P	WALKER, R	8212220207	50-237 S
VAN BRUNT, E E	8212130259	50-530 S	VASSALLO, D B	8212130284	50-220 P	WALKER, R	8212270276	50-263 S
VAN BRUNT, E E	8212130267	50-528 S	VASSALLO, D B	8212130350	50-331 P	WALKER, R D	8212030028*	50-373 Q
VAN BRUNT, E E	8212130292	50-528 E	VASSALLO, D B	8212130365	50-331 P	WALKER, R D	8212030197*	50-254 Q
VAN BRUNT, E E	8212130309	50-530 S	VASSALLO, D B	8212140127	50-254 F	WALKER, R D	8212170201*	50-10 Q
VAN BRUNT, E E	8212130320	50-528 S	VASSALLO, D B	8212210007	50-263 Q	WALKER, S	8212170094*	50-277 P
VAN BRUNT, E E	8212210075	50-528 K	VASSALLO, D B	8212210547*	50-263 P	WALLACE, E C	8212230241	50-247 Q
VAN BRUNT, E E	8212210077	50-528 S	VASSALLO, D B	8212210552*	50-263 P	WALTON, Q	8212060192*	50-412 Q
VAN BRUNT, E E	8212210086	50-528 S	VASSALLO, D B	8212270474	50-293 P	WALTON, Q	8212140094	50-412 S
VAN BRUNT, E E	8212210097	50-528 S	VASSALLO, D B	8212270525	50-331 P	WAMBACH, T V	8212230264*	50-29 P
VAN BRUNT, E E	8212210107	50-528 E	VASSALLO, D B	8212270532*	50-331 P	WANG, C H	8212150252*	50-243 F
VAN BRUNT, E E	8212210225	50-528 S	VASSALLO, D B	8212270536*	50-331 P	WANDLER, M E	8212220070*	50-461 T
VAN BRUNT, E E	8212210237	50-528 S	VASSALLO, D B	8212280002	50-263 P	WANDLER, M E	8212220073*	50-461 T
VAN BRUNT, E E	8212270129	50-528 A	VASSALLO, D B	8212280003*	50-263 P	WAPATO, S T	8212160267	50-522 Q
VAN BRUNT, E E	8212280148	50-528 S	VASSALLO, D B	8212280006*	50-263 P	WARD, E C	8212300416*	50-282 F
VAN BRUNT, E E	8212280227	50-528 S	VASSALLO, D B	8212280007*	50-271 P	WARD, K D	8212170096*	50-255 Q
VAN BRUNT, E E	8212280407	50-529 S	VASSALLO, D B	8212280027*	50-271 P	WARD, K D	8212270305*	50-282 Q
VAN HORN, W P	8212030266*	CONTRACT	VASSALLO, D B	8212280086	50-298 P	WARD, K D	8212290326*	50-266 Q
VAN ROOYEN, D	8212080262	RES	VASSALLO, D B	8212280492	50-271 P	WAREMBOURG, D	8212290094	50-267 R
VAN ROOYEN, D	8212280055	RES	VASSALLO, D B	8212300143	50-324 P	WAREMBOURG, D	8212200123	50-267 S
VANDEL, T E	8212030115*	50-482 Q	VAUGHAN, C H	8212160423	70-1113	WAREMBOURG, D	8212200102	50-267 R
VANDEWALLE, D J	8212020351*	50-255 Q	VAUGHAN, C H	8212230085	70-1113	WAREMBOURG, D	8212290297	50-267 S
VANDEWALLE, D J	8212070300	50-155 F	VAUGHAN, C H	8212230103*	70-1113	WAREMBOURG, D	8212290319	50-267 P
VANDEWALLE, D J	8212100218	50-155 F	VAUGHAN, D K	8212130147	50-269 F	WAREMBOURG, D	8212290403	50-267 P
VANDEWALLE, D J	8212100285	50-155 F	VAUGHAN, R E	8212230124*	50-269 F	WAREMBOURG, D	8212290426	50-267 S
VANDEWALLE, D J	8212170150*	50-155 Q	VAUGHAN, R E	8212230134*	50-269 F	WAREMBOURG, D W	8212200011*	50-267 F
VANDEWALLE, D J	8212200070	50-255 P	VERMA, T R	8212010457	WASTE HOT	WAREMBOURG, D W	8212200030	50-267 F
VANDEWALLE, D J	8212230275	50-255 Q	VERNETSON, W G	8212070009*	50-83 R	WAREMBOURG, D W	8212200035*	50-267 F
VANDEWALLE, D J	8212230342	50-155 P	VERRELLI, D M	8212070122	50-261 V	WAREMBOURG, D W	8212200090*	50-267 Q
VANDEWALLE, D J	8212280083	50-255 P	VERRELLI, D M	8212090183	50-400 Q	WAREMBOURG, D W	8212200098*	50-267 F
VANDEWALLE, D J	8212280103	50-155 P	VERRELLI, D M	8212090229	50-400 Q	WAREMBOURG, D W	8212200116*	50-267 F

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
WARENBURG, D W	8212200117*	50-267 F	WESTERMAN, T F	8212070260*	50-267 Q	WILLIAMSON, O O	8212280364*	50-387 P
WARENBURG, D W	8212210024*	50-267 Q	WESTERMAN, T F	8212100213*	50-298 Q	WILLIAMSON, H E	8212290215*	50-237 P
WARENBURG, D W	8212210173*	50-267 Q	WESTERMAN, T F	8212100271*	50-298 Q	WILLSEY, W B	8212020349	50-277 R
WARENBURG, D W	8212270328	50-267 F	WESTERMAN, T F	8212280420*	50-298 Q	WILLSEY, W B	8212210158	50-277 R
WARENBURG, D W	8212290374	50-267 P	WESTOVER, A T	8212020353	50-341 Q	WILSON, B D	8212020174	XPORTRIC
WARENBURG, D W	8212290391	50-267 R	WETHY, C M	8212170060*	50-335 F	WILSON, C L	8212220265	NUREG
WARENBURG, D W	8212290423	50-267 P	WETHILLER, R J	8212220249	50-335 F	WILSON, J L	8212200090	50-280 S
WARNICK, R	8212060112	50-329 S	WETTERHAHN, H J	8212080288	50-358 Q	WILSON, J L	8212020096*	50-280 S
WARNICK, R F	8212060025	50-358 Q	WETTERHAHN, H J	8212080288	50-358 Q	WILSON, J L	8212090086	50-280 S
WARNICK, R F	8212080416	50-329 S	WETTERHAHN, H J	8212090073	50-358 Q	WILSON, J L	8212090091*	50-280 S
WARNICK, R F	8212140361	50-329 A	WETTERHAHN, H J	8212090073	50-358 Q	WILSON, J L	8212090098*	50-280 S
WARNICK, R F	8212280030*	50-329 S	WETTERHAHN, H J	8212200089	50-358 Q	WILSON, J L	8212090130	50-281 S
WARNICK, R F	8212280034*	50-329 S	WETTERHAHN, H J	8212200089	50-358 Q	WILSON, J L	8212090134*	50-281 S
WARNICK, R F	8212280166	50-358 Q	WETTERHAHN, H J	8212210261	50-458 Q	WILSON, J L	8212090137*	50-281 S
WARNICK, R F	8212290341	50-358 Q	WETTERHAHN, H J	8212210261	50-458 Q	WILSON, J L	8212090144*	50-281 S
WARNICK, R F	8212290391	50-358 Q	WHALEN, R J	8212020248*	50-249 S	WILSON, J L	8212180067	50-281 S
WARNICK, R F	8212290420	50-358 A	WHEELER, L	8212100375	50-443 E	WILSON, J L	8212180087*	50-281 S
WARREN, D H	8212160394	PR	WHEELER, L L	8211040225*	50-443 E	WILSON, J L	8212210365	50-280 S
WATFORD, P S	8212170126*	50-373 S	WHITE, J	8212220276	50-309 S	WILSON, J L	8212210383*	50-280 S
WATFORD, P S	8212280231*	50-373 S	WHITENER, H L	8212090411*	50-389 Q	WILSON, J L	8212210388*	50-280 S
WATKINS, J C	8212080510	RES	WHITENER, H L	8212290165*	50-261 Q	WILSON, J L	8212210397*	50-280 S
WATSON, M	8212210210*	50-331 R	WHITHAM, D	8212130346*	50-298 F	WILSON, J L	8212280126	50-280 S
WEAVER, L W	8212270230*	50-334 R	WHITNEY, O O	8212060200*	50-293 S	WILSON, J L	8212280140*	50-280 S
WEBB, D J	8212220265	NUREG	WHITNEY, O O	8212060220*	50-293 S	WILSON, J L	8212280152*	50-280 S
WEBB, W A	8212270417*	CONTRACT	WHITNEY, O O	8212210071*	50-293 S	WILSON, J L	8212280206*	50-280 S
WEBER, M F	8212230225	WASTE MGT	WHITNEY, O O	8212210153*	50-293 S	WILY, D D	8212090495	50-440 Q
WEBER, M F	8212290182	50-133 R	WHITNEY, O O	8212210264*	50-293 S	WILY, D D	8212090495	50-440 Q
WEBER, M F	8212280031	RES	WICHNER, R P	8212160554	RES	WILY, D D	8212280319	50-440 Q
WEBER, M F	8212020131	REGCD	WIDMANN, R K	8212230380*	40-8027	WILY, D D	8212280319	50-440 Q
WEINKAM, E J	8212170069	50-322 A	WIEDE, J	8212070111*	50-320 Q	WINGO, M D	8212280153*	50-239 S
WEISS, D	8212160067*	40-3392	WIEDE, J	8212140319*	50-320 Q	WINTERHOFF, D	8212280449*	50-373 S
WEISS, E R	8212200021	70-143	WIEDE, J	8212270233	50-320 S	WISENBURG, M R	8212020234	50-498 A
WEISS, E R	8212200021	70-143	WIEUER, A V	8212090071*	70-1359	WISNER, J A	8212060420	FOIA
WEISS, E R	8212210272	50-289 Q	WIEUER, A V	8212210246*	70-25	WISNER, M C	8212280265	NUREG
WEISS, E R	8212210272	50-289 Q	WIESEMAN, R A	8210210475*	TOPREP	WISNER, C E	8212010162*	FOIA
WEISS, E R	8212210336	50-289 Q	WIESEMAN, R A	8212010440	FOIA	WITHERS, B D	8212030027	50-344 P
WEISS, E R	8212210336	50-289 Q	WIESEMAN, R A	8212020271*	TOPREP	WITHERS, B D	8212070316	50-344 P
WEISS, E R	8212220248*	70-143	WIESEMAN, R A	8212060245*	50-369 P	WITHERS, B D	8212100044	50-344 P
WEISS, E R	8212220248*	70-143	WIESEMAN, R A	8212130302*	TOPREP	WITHERS, B D	8212210201	50-344 F
WEISS, E R	8212280270	70-143	WIESEMAN, R A	8212140267	50-413 A	WITHERS, B D	8212270368	50-344 P
WEISS, E R	8212280270	70-143	WIESEMAN, R A	8212140312*	50-413 A	WITHERS, B D	8212280190	50-344 S
WEISS, E R	8212300002	50-289 Q	WIESEMAN, R A	8212200062*	TOPREP	WITHERS, B D	8212280283	50-344 P
WEISS, E R	8212300002	50-289 Q	WIESEMAN, R A	8212270263*	50-286 P	WITHERS, B D	8212280470	50-344 P
WEISS, E R	8212300008	50-289 Q	WIGGINS, J T	8212010422*	50-309 P	WITTENBURG, K	8212270180*	50-373 S
WEISS, E R	8212300008	50-289 Q	WIGGINTON, D	8212020002	50-315 P	WITTENBURG, K	8212280487*	50-373 S
WEISS, E R	8212300242	50-289 Q	WIGGINTON, D	8212070472	50-295 P	WIZNER, D O	8212060057*	50-316 S
WEISS, E R	8212300242	50-289 Q	WIGGINTON, D L	8212010452	50-295 P	WIZNER, D O	8212140165*	50-316 S
WEISS, E R	8212300362	50-289 Q	WIGGINTON, D L	8212160573	50-316 P	WIZNER, D O	8212170296*	50-315 Q
WEISS, E R	8212300362	50-289 Q	WIGGINTON, D L	8212290453	50-295 P	WOFFORD, A W	8212010371*	50-322 A
WEISS, T	8212230276	50-247 U	WIGHT, L H	7907180391*	50-409 P	WOFFORD, A W	8212010393*	50-322 A
WELLS, D J	8212020173	REGCD	WILDER, H A	8212290078*	50-250 Q	WOFFORD, A W	8212010397*	50-322 A
WELLS, D J	8212210443	50-341 S	WILBOR, L	8212100233*	50-285 Q	WOFFORD, A W	8212010401*	50-322 A
WELLS, D J	8212270359	50-341 S	WILBOR, L	8212210250*	50-313 Q	WOLF, J F	8212020376	50-322 Q
WELLS, D J	8212270352	50-341 S	WILDUNG, N J	8212220265	NUREG	WOLF, J F	8212020379	50-322 Q
WELLS, R W	8212020200	TOPREP	WILHELM, D	8212130157	50-537 A	WOLFE, S J	8212020342	50-382 Q
WELLS, R W	8212020200	TOPREP	WILKES, D	8212230209	WASTE MGT	WOLFE, S J	8212020374	50-382 Q
WELLS, R W	8212020208*	TOPREP	WILKES, D	8212230212*	WASTE MGT	WOLFE, S J	8212060088	50-382 Q
WELLS, R W	8212020208*	TOPREP	WILKES, T C	8212300036*	50-321 S	WOLFE, S J	8212070139	50-338 Q
WELLS, R W	8212290188	TOPREP	WILLET, D J	8212060178*	50-243 Q	WOLFE, S J	8212070147	50-338 Q
WELLS, R W	8212290188	TOPREP	WILLET, D J	8212210427*	50-397 Q	WOLFE, S J	8212070236	50-338 Q
WENDERLICH, R L	8212210384*	50-317 S	WILLIAMS, C C	8212170162*	50-155 Q	WOLFE, S J	8212150035	50-382 Q
WENDER, L O	8212140131*	50-317 S	WILLIAMS, C C	8212170189*	50-266 Q	WOLFE, S J	8212160354	50-382 Q
WENSLAWSKI, F A	8212060168*	50-206 Q	WILLIAMS, C C	8212170253*	50-341 Q	WOLFE, S J	8212160503	50-382 Q
WENSLAWSKI, F A	8212130294*	50-187 Q	WILLIAMS, C C	8212170286*	50-483 Q	WOLFE, S J	8212160515	50-382 Q
WENSLAWSKI, F A	8212130298*	50-187 Q	WILLIAMS, C C	8212270318*	50-436 Q	WOLFE, S J	8212270184	50-382 Q
WENSLAWSKI, F A	8212210185*	50-344 Q	WILLIAMS, D	8212030028*	50-373 Q	WOLFE, S J	8212270247	50-382 Q
WENZEL, J S	8212230228	50-247 Q	WILLIAMS, D	8212280251*	50-315 Q	WOLFE, S J	8212140205	50-358 Q
WERNER, R P	8211080257	50-245 P	WILLIAMS, J H	8212020396	50-461 A	WOLFE, S J	8212140205	50-358 Q
WERNER, R P	8211080257	50-245 P	WILLIAMS, J H	8211040086	50-335 S	WOLLETT, S	8212020051	50-354 Q
WERNER, R P	8212070124	50-245 F	WILLIAMS, J H	8212020369	50-335 S	WOLLETT, S	8212100154	CONTRACT
WERNER, R P	8212070124	50-245 F	WILLIAMS, J W	8212090356	50-280 S	WOLTER, E	8212030177*	50-336 Q
WESLEY, D A	8212270260*	50-337 A	WILLIAMS, J W	8212090403	50-335 S	WOLTER, E	8212220437*	70-135
WESLEY, D A	8210190510*	50-247 F	WILLIAMS, J W	8212100219	50-230 S	WOLTER, E	8212270352*	70-820
WESTAFER, G R	8212030023*	50-153 Q	WILLIAMS, J W	8212150156	50-335 S	WONG, C C	8212020231	PR
WESTAFER, G R	8212100006	50-302 F	WILLIAMS, J W	8212200071	50-335 S	WONG, T	8212060513	40-299
WESTAFER, G R	8212140048	50-302 R	WILLIAMS, J W	8212210175	50-335 S	WONG, T	8212230186	40-299
WESTAFER, G R	8212140089	50-302 F	WILLIAMS, J W	8212210202	50-250 S	WONG, T	8212270074	40-299
WESTAFER, G R	8212150099	50-302 S	WILLIAMS, J W	8212210309	50-335 S	WOOD, E C	8212220456	50-309 S
WESTAFER, G R	8212150105	50-302 S	WILLIAMS, J W	8212220441	50-335 S	WOOD, R S	8212140471	NUREG
WESTAFER, G R	8212220270	50-302 P	WILLIAMS, J W	8212280164	50-250 S	WOODHEAD, C P	8212070013	50-142 Q
WESTAFER, G R	8212220284	50-302 F	WILLIAMS, J W	8212280170	50-250 S	WOODHEAD, C P	8212070228	50-440 Q
WESTAFER, G R	8212290177	50-302 F	WILLIAMS, J W	8212280399	50-335 S	WOODHEAD, C P	8212140456	50-142 Q
WESTBROOK, K B	8212280041	40-8786	WILLIAMS, J W	8212280418	50-335 S	WOODHEAD, C P	8212280139	50-341 Q
WESTERMAN, T F	8212030156*	50-445 Q	WILLIAMS, J W	8212290153	50-250 R	WOODHEAD, C P	8212280151	50-341 Q
WESTERMAN, T F	8212070133*	50-112 Q	WILLIAMS, J W	8212300061	50-335 S	WOODRUFF, R L	8212090235	State Prog

PERSONAL AUTHOR INDEX

451

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
WOODRUFF, R L	8212090470	State Prog	YUNDT, C P	8212290201	50-344 R	ZIMMERMAN, J V	8212010199	XPORTLIC
WOODS, J	8212080200*	50-187 R	ZIBULSKY, H	8212220437*	70-135	ZIMMERMAN, J V	8212010461	XPORTLIC
WOODSIDE, P	8212300054	50-440 Q	ZIBULSKY, H	8212290352*	70-820	ZIMMERMAN, J V	8212020044	XPORTLIC
WOOLEVER, E J	8212140427*	50-412 Q	ZIBULSKY, H	8212290363*	70-1100	ZIMMERMAN, J V	8212020169	XPORTLIC
WOOLEVER, E J	8212220283	50-412 H	ZIMMERMAN, D A	8212220238	NUREG	ZIMMERMAN, J V	8212020181	XPORTLIC
WOOLEVER, E J	8212220403	50-412 A	ZIMMERMAN, J V	8212010041	XPORTLIC	ZIMMERMAN, J V	8212020198	XPORTLIC
WOOLEVER, E J	8212220404*	50-412 A	ZIMMERMAN, J V	8212010043	XPORTLIC	ZIMMERMAN, J V	8212070469	XPORTLIC
WOOLSEY, R T	8212060004	40-8084	ZIMMERMAN, J V	8212010076	XPORTLIC	ZIMMERMAN, J V	8212070502	XPORTLIC
WOOLSEY, R T	8212280076	40-8084	ZIMMERMAN, J V	8212010081	XPORTLIC	ZIMMERMAN, J V	8212070506	XPORTLIC
WRAY, J R	82122090439*	70-27	ZIMMERMAN, J V	8212010088	XPORTLIC	ZIMMERMAN, J V	8212080002	XPORTLIC
WRAY, J R	8212090505*	50-338 Q	ZIMMERMAN, J V	8212010093	XPORTLIC	ZIMMERMAN, J V	8212080003	XPORTLIC
WRIGHT, Q C	8212080822*	50-155 Q	ZIMMERMAN, J V	8212010095	XPORTLIC	ZIMMERMAN, J V	8212080004	XPORTLIC
WRIGHT, Q N	8212280176	50-10 H	ZIMMERMAN, J V	8212010101	XPORTLIC	ZIMMERMAN, J V	8212080016	XPORTLIC
WRIGHT, N A	8212060014	50-329 Q	ZIMMERMAN, J V	8212010106	XPORTLIC	ZIMMERMAN, J V	8212080237	XPORTLIC
WRIGHT, N A	8212270005	50-329 Q	ZIMMERMAN, J V	8212010194	XPORTLIC	ZIMMERMAN, J V	8212080244	XPORTLIC
WRIGHT, R J	8212010010	WASTE MGT	YOUNG, T	8212060347	50-312 S	ZIMMERMAN, J V	8212080329	XPORTLIC
WRIGHT, R J	8212010242	WASTE MGT	YOUNG, T	8212130209*	50-528 Q	ZIMMERMAN, J V	8212080334	XPORTLIC
WRIGHT, R J	8212010245	WASTE MGT	YOUNG, T	8212130215*	50-528 Q	ZIMMERMAN, J V	8212080338	XPORTLIC
WRIGHT, R J	8212020136	WASTE MGT	YOUNG, T	8212170394*	50-361 Q	ZIMMERMAN, J V	8212170008	XPORTLIC
WRIGHT, R J	8212020183	WASTE MGT	YOUNG, T	8212170397*	50-361 Q	ZIMMERMAN, J V	8212170023	XPORTLIC
WRIGHT, R J	8212020403	WASTE MGT	YOUNG, T	8212210211*	50-528 Q	ZIMMERMAN, J V	8212170029	XPORTLIC
WULF, W	8212060128	RES	YOUNG, Y A	8212030235	40-8745	ZIMMERMAN, J V	8212230426	XPORTLIC
WULLER, Q E	8212060105	50-461 A	YOUNGBLOOD, D J	8212010020*	50-456 A	ZIMMERMAN, J V	8212270092	XPORTLIC
WULLER, Q E	8212070125	50-461 E	YOUNGBLOOD, B J	8212010049	50-483 Q	ZIMMERMAN, J V	8212270094	XPORTLIC
WULLER, Q E	8212070200	50-461 E	YOUNGBLOOD, B J	8212070448	50-395 E	ZIMMERMAN, J V	8212270096	XPORTLIC
WULLER, Q E	8212070229	50-461 F	YOUNGBLOOD, B J	8212070458	50-358 A	ZIMMERMAN, J V	8212270098	XPORTLIC
WULLER, Q E	8212170303	50-461 A	YOUNGBLOOD, B J	8212070460	50-440 E	ZIMMERMAN, J V	8212280178	XPORTLIC
WULLER, Q E	8212170330	50-461 E	YOUNGBLOOD, B J	8212070466	50-440 A	ZIMMERMAN, J V	8212300143	XPORTLIC
WULLER, Q E	8212210313	50-461 A	YOUNGBLOOD, B J	8212080001	50-358 F	ZIMMERMAN, J V	8212300148	XPORTLIC
WULLER, Q E	8212220233	50-461 A	YOUNGBLOOD, B J	8212080114	50-546 A	ZIMMERMAN, J V	8212300150	XPORTLIC
WULLER, Q E	8212280235	50-461 A	YOUNGBLOOD, B J	8212100094	50-395 P	ZIMMERMAN, J V	8212300153	XPORTLIC
WULLER, Q E	8212290179	50-461 E	YOUNGBLOOD, B J	8212100101*	50-395 P	ZIMMERMAN, J V	8212300173	XPORTLIC
WYNGARDEN, S	8212230389	40-6940	YOUNGBLOOD, B J	8212100110*	50-395 P	ZIMMERMAN, R L	8212060444*	50-255 S
WYNGARDEN, S D	8212020122	40-6940	YOUNGBLOOD, B J	8212170084*	50-341 A	ZIMMERMAN, S R	8212060013	50-261 P
WYNGARDEN, S D	8212160659	40-8027	YOUNGBLOOD, B J	8212230385	50-440 A	ZIMMERMAN, S R	8212090307	50-324 P
YAMANA, K	8212140796	XPORTLIC	YOUNGBLOOD, B J	8212270022	50-482 F	ZIMMERMAN, S R	8212100015	50-261 F
YANDELL, L A	8212030126*	50-285 Q	YOUNGBLOOD, B J	8212290061	50-423 A	ZIMMERMAN, S R	8212100021	50-261 P
YANDELL, L A	8212100247	50-285 S	YOUNGBLOOD, B J	8212290067	50-395 P	ZIMMERMAN, S R	8212100032	50-324 F
YANICHKO, S E	8212140420*	50-244 P	YOUNGBLOOD, B J	8212290071*	50-395 P	ZIMMERMAN, S R	8212130313	50-261 Q
YARGER, K	8212170187*	50-346 S	YOUNGBLOOD, B J	8212290081*	50-395 P	ZIMMERMAN, S R	8212210068	50-261 P
YARNICK, T P	8212230063	40-8102	YOUNGBLOOD, B J	8212290498	50-546 F	ZIMMERMAN, S R	8212210418	50-261 P
YIN, I T	8212290400*	50-295 Q	YOUNGBLOOD, B J	8212290502	50-546 F	ZIMMERMAN, S R	8212280078	50-400 C
YORF, J R	8212010139*	FOIA	YOUNGBLOOD, B J	8212300023	50-423 C	ZIMMERMAN, S R	8212280112	50-277 P
YOUNG, F	8212220478*	50-289 Q	YOUNGBLOOD, B J	8212300066	50-546 Q	ZSCHALER, W A	8212170101*	70-734
YOUNG, O	8212070184	50-358 Q	YUAN, C Y	8212020126	RES	ZURAKOWSKI, P R	8212300213*	50-275 Q
YOUNG, O O	8212270466*	50-327 Q	YUIHAS, O P	8212060168*	50-206 Q	ZWETZIO, O B	8212210204*	50-361 Q
YOUNG, O S	8212230084	40-6659	YUNDT, C P	8212030011	50-344 S			
YOUNG, J A	8212220193	NUREG	YUNDT, C P	8212070343	50-344 R			
YOUNG, T	8212060167*	50-312 Q	YUNDT, C P	8212100411*	50-344 F			
YOUNG, T	8212060171*	50-312 Q	YUNDT, C P	8212140346	50-344 S			

CORPORATE SOURCE INDEX

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents.

An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principal Documents."

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
AWC, Inc.	8212270479	71-6144
Aamodts, The	8212010195	50-289
	8212020346	50-289
	8212020401*	50-289
Advanced Medical Systems, Inc.	8212160043	71-5796
AeroVironment, Inc	8212060336*	40-8743
Alabama Power Co	8212020130	50-348
	8212020162	PR
	8212070336	50-364
	8212090295	50-364
	8212090312*	50-364
	8212090362	50-348
	8212090412	50-348
	8212100070	50-348
	8212100217	MISC
	8212150033	50-364
	8212170197	50-364
	8212170207*	50-348
	8212170234	50-364
	8212170297	50-364
	8212170302*	50-364
	8212210130	50-364
	8212210132*	50-364
	8212280260	50-348
	8212300216	50-364
	8212300223*	50-364
	8212300227*	50-364
	8212300231*	50-364
	8212300236*	50-364
Alden Research Laboratory	8212270320	NUREG
Alderson Reporting	8212100048	50-329
	8212270065*	FOIA
	8212270131*	FOIA
	8212280044*	CONTRACT
Aldrich Chemical Co , Inc (subs of Sigma-Aldrich Corp.)	8212300155	XPORTLIC
	8212300158	XPORTLIC
	8212300163	XPORTLIC
	8212300164	XPORTLIC
	8212300166	XPORTLIC
	8212300169	XPORTLIC
	8212300180	XPORTLIC
	8212300181	XPORTLIC
Allied Chemical Corp.	8212160060	40-3392
Allied General Nuclear Services	8212090405	50-332
Allied-Crossroads Nuclear Corp	8212160131*	40-6500
	8212160193*	40-6500
American Electric Power Service Corp	50-315	J
American Nuclear Insurers	8212300174	50-219
Amersham Corp.	8212150230	71-9167
Anaheim, CA	8212030168*	50-361
Andrulis Research Corp.	8212220027*	CONTRACT
Anthony, R L	8212230352	50-352
	8212230356	50-352
Antioch School of Law, Washington, DC	8212200361	50-155

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Applied Physical Technology, Inc Argonne National Laboratory	8212070247	50-155 G
	8212070303*	50-155 G
	8212280292	50-155 G
	8212060386*	50-416 P
	8212010151	TOPREP
	8212060429	NUREG
	8212060441	NUREG
	8212060447	NUREG
	8212060451	NUREG
	8212060455	NUREG
Arizona Public Service Co	8212070077	50-247 D
	8212070083*	50-247 Q
	8212070431	ACRS
	8212070438	ACRS
	8212080668*	50-373 P
	8212080670*	50-373 P
	8212080673*	50-373 P
	8212130143	NUREG
	8212130147	NUREG
	8212270250*	50-537 A
	8212270260*	50-537 A
	8212270468	NUREG
	8211290135	50-528 A
	8212030031	50-528 E
	8212030031	50-528 E
	8212030031	50-528 E
	8212060082	50-528 S
	8212060143	50-528 G
	8212060229	50-528 G
	8212060240	50-528 G
	8212060275	50-528 G
	8212060275	50-528 G
	8212060275	50-528 G
	8212060283	50-528 S
	8212070109	50-528 A
	8212070328	50-528 K
	8212070328	50-528 K
	8212070328	50-528 K
	8212070331*	50-528 K
	8212080157	50-528 F
	8212080157	50-528 F
	8212080157	50-528 F
	8212090552*	50-528 Q
	8212090552*	50-528 Q
	8212090552*	50-528 Q
	8212130146	70-2949
	8212130216	50-528 G
	8212130259	50-530 S
	8212130267	50-528 S
	8212130267	50-528 S
	8212130267	50-528 S
	8212130292	50-528 C
	8212130292	50-528 G
	8212130309	50-530 G
	8212130320	50-528 S
	8212130320	50-528 S

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Arkansas Power & Light Co	8212210075	50-328 K	Arkansas Tech Univ Army, Dept of Army, Dept of, Corps of Engineers	8212290223*	50-368 S
	8212210077	50-328 S		8212290234	50-368 R
	8212210077	50-328 S		8212290236*	50-368 R
	8212210077	50-328 S		8212290321	50-313 S
	8212210086	50-328 S		8212290486	50-313 S
	8212210086	50-328 S		8212300052	50-368 S
	8212210086	50-328 S		8212300057	50-368 S
	8212210097	50-328 S		8212300059*	50-368 S
	8212210107	50-328 C		8212300062*	50-368 S
	8212210225	50-328 S		8212300088	50-368 S
	8212210237	50-328 S		8212300090*	50-368 S
	8212270129	50-328 A		8212010423*	CONTRACT
	8212280148	50-328 S		8212280455*	CONTRACT
	8212280227	50-328 S		8212280542*	CONTRACT
	8212280227	50-328 S		8212270412*	CONTRACT
	8212280407	50-329 S	Atlas Minerals	8212030281	40-3453
	8212030066	50-368 S		8212030282*	40-3453
	8212030075*	50-368 S		8212270401	40-3453
	8212030097	50-313 S		8212270405*	40-3453
	8212030169	50-313 P		8212290123	40-3453
	8212060087	50-313 Q	Atomic Industrial Forum	8212020380	ORD
	8212060262	50-313 P		8212160431	PR
	8212060262	50-313 P		8212300034	TOPREP
	8212060333	50-313 P		8212300036*	TOPREP
	8212060333	50-313 P		8212090489*	70-824
	8212070284	50-313 F	Babcock & Wilcox Co.	8212130067*	70-27
	8212070284	50-313 P		8212130217	TOPREP
	8212080082*	50-313 F		8212130220*	TOPREP
	8212080082*	50-313 F		8212130233	TOPREP
	8212080085*	50-313 F		8212130234	TOPREP
	8212090311	50-313 F		8212150113*	50-289 P
	8212090311	50-313 F		8212160086	71-5814
	8212100385*	50-313 F		8212160426	71-5986
	8212100394*	50-313 F		8212230025	70-1201
	8212140334	50-368 Q		8212230031*	70-1201
	8212140481	50-313 Q		8212270042*	50-289 P
	8212150289*	50-313 F		8212270047*	50-289 P
	8212160762*	50-313 F		8212270406	70-27
	8212160767*	50-313 F		8212270537	70-27
	8212170018*	50-313 F		8212280401*	GA999
	8212170025*	50-313 F	Beckus, R A	8212140426	50-443 Q
	8212170113	50-313 P		8212230334	50-443 Q
	8212170215	50-368 P		8212010090*	50-317 F
	8212170448*	50-313 F		8212010055*	50-317 F
	8212170453*	50-313 F		8212060071	50-317 P
	8212210027	50-368 S		8212060071	50-317 P
	8212210028*	50-368 S		8212060149	50-317 S
	8212210037	50-368 P		8212060196	50-317 S
	8212210117	50-368 S		8212060206*	50-317 S
	8212210120*	50-368 S		8212060293*	50-317 S
	8212210166	50-313 S		8212060301	50-317 S
	8212210169*	50-313 S		8212060306*	50-317 S
	8212210193	50-368 S		8212070054	50-317 P
	8212210198*	50-368 S		8212070054	50-317 P
	8212210257	50-368 S		8212080197	50-317 P
	8212210260*	50-368 S		8212080197	50-317 P
	8212210514*	50-313 F		8212080441	50-317 S
	8212210521*	50-313 F		8212080448*	50-317 S
	8212210534*	50-313 F		8212080456	50-317 S
	8212210539*	50-313 F		8212080456	50-317 S
	8212220002*	50-313 F	Baltimore Gas & Electric Co	8212080491	50-317 F
	8212220004*	50-313 F		8212130065	50-317 F
	8212220165*	50-313 F		8212130065	50-317 F
	8212220165*	50-313 F		8212140125	50-317 S
	8212220172*	50-313 F		8212140131*	50-317 S
	8212230172*	50-313 F		8212140412	NUREG
	8212270143	50-313 S		8212160259	50-317 S
	8212270189	50-368 S		8212160270*	50-317 S
	8212270194*	50-368 S		8212160384	50-317 S
	8212280072	50-368 S		8212170292	50-317 P
	8212280142	50-368 S		8212170349	50-318 Q
	8212280146*	50-368 S		8212200088	50-318 P
	8212280224	50-313 F		8212210043	50-317 S
	8212280224	50-313 F		8212210048*	50-317 S
	8212280307	50-313 P		8212210076	50-317 S
	8212280309*	50-313 P		8212210080*	50-317 S
	8212280459	50-368 P		8212210294	50-317 S
	8212290168	50-313 R		8212210303*	50-317 S
	8212290168	50-313 R		8212210378	50-317 S
	8212290171*	50-313 R		8212210384*	50-317 S
	8212290171*	50-313 R		8212210420	50-317 P
	8212290194	50-313 R		8212210420	50-317 P
	8212290196*	50-313 R		8212210447	50-317 P
	8212290198*	50-313 Q		8212210448*	50-317 P
	8212290212	50-368 S		8212220298	50-317 R

CORPORATE SOURCE INDEX

455

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Battelle Memorial Institute, Columbus Laboratories	8212220208	50-317 R	Burns & Roe Co C-E Operating Plants Owners Group	8212030239	RES
	8212220210*	50-317 R		8212030323	50-337 A
	8212220210*	50-317 R		8212040005	RES
	8212230274	50-317 P		8212040119	RES
	8212230274	50-317 P		8212040128	RES
	8212230312	50-318 P		8212070400	RES
	8212280199	50-318 P		8212070471	RES
	8212280202*	50-318 P		8212080262	RES
	8212280208*	50-317 Q		8212270534	RES
	8212290120	50-318 P		8212280031	RES
Battelle Memorial Institute, Pacific Northwest Laboratory	8212290122	50-318 P	C F Braun & Co CONOCO, Inc (Continental Oil Co.)	8212280040	RES
	8212290275	50-317 S		8212280051	RES
	8212290282*	50-317 S		8212280055	RES
	8212290338	50-318 Q		8212280514	50-320 P
	8212300209*	50-317 F		8212280518	RES
	8212300209*	50-317 F		8212010015*	50-337 F
	8212300211*	50-317 F		8212020200	TOPREP
	8212300211*	50-317 F		8212020208*	TOPREP
	8212140476	NUREQ		8212020212*	TOPREP
	8212150212	71-5957		8212290188	TOPREP
Battelle Memorial Institute, Pacific Northwest Laboratory	8212150218*	71-5957	California, State of	8212080662	50-373 P
	8212270056*	50-289 P		8212060330	40-8743
	8212270420	NUREQ		8212290145	40-8743
	8212270321*	CONTRACT		8212020251	PR
	8212270543*	CONTRACT		8212220394	50-275 Q
	8210150165*	50-341 F		8212280542	NUREQ
	8212010115	NUREQ		8212270227	50-322 T
	8212010483	RES		8208290029	ACRS
	8212210529	71-5957		8212020131	REGSD
	8212220193	NUREQ		8212270445*	FOIA
Battelle New England Marine Research Laboratory	8212220238	NUREQ	Canada	8212160134	71-454
	8212220265	NUREQ		8212160148*	71-454
	8212220341	NUREQ		8212070484	XPORTLIC
	8212220460	50-341 F		8212220249	NUREQ
	8212220509	NUREQ		8212280132	50-413 Q
	8212220523	RES		8212280138	50-413 Q
	8212270033	NUREQ		8212280138	50-413 Q
	8212270232	NUREQ		8212020048	50-324 S
	8212270449	NUREQ		8212020083*	50-324 S
	8212270456	NUREQ		8212020152	50-324 S
Bechtel Corp	8212270487	NUREQ	Carolina Power & Light Co	8212020161*	50-324 S
	8212270512	NUREQ		8212020293	50-324 S
	8212270559	NUREQ		8212020297*	50-324 S
	8212300137	RES		8212020306	50-325 Q
	8212300402	RES		8212020312*	50-325 Q
	8212210044*	50-219 R		8212020315	50-324 S
	8212290157	40-8452		8212020319*	50-324 S
	8212290161*	40-8452		8212020362	50-324 S
	8212020173	REGSD		8212020365*	50-324 S
	8212140092	TOPREP		8212060013	50-261 P
Beveridge, Fairbanks & Diamond	8212170276*	50-250 P	Boston College	8212060067	50-261 P
	8212230304*	50-275 P		8212060199	50-261 R
	8212100104	50-338 Q		8212060201*	50-261 R
	8212140245	50-338 Q		8212070008	50-325 S
	8212140245	50-338 Q		8212070012*	50-325 S
	8212140249	50-338 Q		8212070043	50-400 S
	8212140249	50-338 Q		8212070043	50-400 S
	821220528*	CONTRACT		8212070112	50-325 S
	8212060198	50-293 S		8212070118*	50-325 S
	8212060200*	50-293 S		8212070208	50-325 S
Boston Edison Co	8212060210	50-293 S	Boston Edison Co	8212070214*	50-325 S
	8212060220*	50-293 S		8212070273	50-324 S
	8212060272*	50-293 F		8212070275*	50-324 S
	8212100031	50-293 F		8212070305	50-400 S
	8212130037	50-293 F		8212070305	50-400 S
	8212140139	50-293 P		8212090100	50-325 S
	8212150224*	50-293 Q		8212090105*	50-325 S
	8212150233*	50-293 Q		8212090120	50-261 S
	8212170305	50-293 P		8212090128*	50-261 S
	8212170310*	50-293 P		8212090135	50-325 S
Brigham Young Univ	8212210067	50-293 S	Brigham Young Univ	8212090137*	50-325 S
	8212210071*	50-293 S		8212090147	50-325 S
	8212210148	50-293 S		8212090152*	50-325 S
	8212210153*	50-293 S		8212090167	50-325 S
	8212210249	50-293 S		8212090173*	50-325 S
	8212210264*	50-293 S		8212090237*	50-400 Q
	8212210458	50-293 Q		8212090289*	50-324 Q
	8212210462*	50-293 Q		8212090307	50-324 P
	8212290433*	50-293 Q		8212090307	50-324 P
	8212160734*	50-262 F		8212090314	50-324 S
Brookhaven National Laboratory	8212160742*	50-262 F	Brookhaven National Laboratory	8212090318*	50-324 S
	8212020010	RES		8212090375	50-324 Q
				8212090453	50-325 S
				8212090463*	50-325 S

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8212090335	50-323 S		8212290125*	50-261 Q
	8212090342*	50-323 S		8212290155*	50-261 Q
	8212090343	50-323 S		8212290200	50-261 P
	8212090350*	50-323 S		8212300067	50-324 S
	8212100015	50-261 F		8212300221	50-323 S
	8212100021	50-261 P		8212300225*	50-323 S
	8212100032	50-324 F		8212300227	50-323 S
	8212100032	50-324 F		8212300256	50-323 S
	8212100078	50-261 P		8212300257	50-323 S
	8212100082	50-324 P		8212300259*	50-323 S
	8212100085*	50-324 P		8212300262*	50-323 S
	8212100097	50-400 Q		8212300272	50-261 S
	8212100099	50-400 Q		8212300296*	50-261 Q
	8212100241	50-324 R		8212300307	50-323 S
	8212100241	50-324 R		8212300309*	50-323 S
	8212100250*	50-324 R		8212300316	50-323 S
	8212100250*	50-324 R		8212300317*	50-323 S
	8212130181	50-400 A		8212300326	50-400 S
	8212130313	50-261 Q		8212300326	50-400 S
	8212130317*	50-261 Q		8212300331	50-323 S
	8212140153	50-323 S		8212300334*	50-323 S
	8212140159*	50-323 S		8212300360	50-323 S
	8212140196	50-323 S	Carpenter Technology Corp	8212270072	XPORTLIC
	8212140202*	50-323 S		8212270105	XPORTLIC
	8212140250	50-324 P	Catalytic, Inc (subs of Air Products & Chemicals, Inc)	8212200060	PRM
	8212140250	50-324 P			
	8212140255	50-324 P	Center for Law in the Public Interest	8212280288	50-275 Q
	8212140255	50-324 P	Central Power & Light	8212170131*	50-498 A
	8212140257*	50-324 P	Cerac, Inc	8212070513	XPORTLIC
	8212140257*	50-324 P	Charles & Hoare	8212280179	50-483 Q
			Charlevoix, MI	8212010438*	CONTRACT
	8212150004	50-261 P			
	8212150112	50-323 S		8212070337*	50-153 Q
	8212150114*	50-323 S		8212070345*	50-153 Q
	8212160036	50-400 D		8212070349*	50-153 Q
	8212170141	50-323 S		8212210289*	50-153 Q
				8212210292*	50-153 Q
	8212170156*	50-323 S			
	8212170183	50-400 S		8212210296*	50-153 Q
	8212170210	50-324 P	Chernoff, G	8212060413*	CONTRACT
	8212170216	50-323 S	Chem-Nuclear Systems, Inc	8212150202	71-9081
	8212170328	50-400 S		8212150206*	71-9081
				8212160407	71-9151
	8212170338	50-324 P			
	8212170338	50-324 P		8212160418*	71-9151
	8212170343*	50-324 P		8212280541	27-47
	8212170343*	50-324 P		8212290005	27-47
	8212170350*	50-324 P	Chicago Bridge & Iron Co	8212020243	PRM
			Christa-Maria	8212020361	50-153 Q
	8212170350*	50-324 P			
	8212170355	50-324 P		8212070247	50-153 Q
	8212170355	50-324 P		8212070303*	50-153 Q
	8212170356*	50-324 P		8212280292	50-153 Q
	8212170356*	50-324 P	Cincinnati Gas & Electric Co	8212010089	50-358 A
				8212020225	50-358 S
	8212170363*	50-324 P			
	8212170363*	50-324 P		8212020257	50-358 S
	8212210004	50-324 P		8212020320	50-358 S
	8212210004	50-324 P		8212020367	50-358 S
	8212210006*	50-324 P		8212030111	50-358 S
				8212060030*	50-358 Q
	8212210006*	50-324 P			
	8212210030	50-323 S		8212060039*	50-358 Q
	8212210032*	50-323 S		8212080288	50-358 Q
	8212210068	50-261 P		8212080472	50-358 F
	8212210182	50-323 S		8212090028*	50-358 F
				8212090031*	50-358 F
	8212210159*	50-323 S			
	8212210222	50-400 Q		8212090034*	50-358 F
	8212210399	50-323 S		8212090073	50-358 Q
	8212210405*	50-323 S		8212090094	50-358 H
	8212210418	50-261 P		8212090096*	50-358 H
				8212140340*	50-358 A
	8212210422	50-400 C			
	8212210422	50-400 C		8212140342*	50-358 A
	8212210424*	50-400 C		8212170080	50-358 H
	8212210424*	50-400 C		8212170107	50-358 R
	8212220345	50-400 S		8212170191	50-358 R
				8212170260	50-358 S
	8212220345	50-400 S			
	8212220432	50-400 S		8212200089	50-358 Q
	8212220432	50-400 S		8212210031*	50-358 Q
	8212220488	50-323 S		8212210545*	50-358 F
	8212220493*	50-323 S		8212270190	50-358 S
				8212270434*	50-358 A
	8212220496	50-323 S			
	8212220504*	50-323 S		8212280171*	50-358 Q
	8212230366	50-400 Q		8212290277	50-358 S
	8212230366	50-400 Q		8212290285	50-358 S
	8212270222	50-400 Q		8212290342	50-358 S
				8212290343*	50-358 Q
	8212280078	50-261 P			
	8212280112	50-400 C		8212290364	50-358 S
	8212280112	50-400 C		8212290397	50-358 S
	8212280383	50-323 S		8212290425*	50-358 A
	8212280397*	50-323 S		8212290429*	50-358 Q

CORPORATE SOURCE INDEX

457

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8212290438	50-358 G	Colt Industries, Inc	8212210341	50-395 S
	8212290439*	50-358 G	Columbia River Inter-Tribal Fish Commission	8212160267	50-522 G
	8212290467	50-358 S			
Citizens Against Nuclear Power	8212290483	50-358 S	Columbus & Southern Ohio Electric Co	8212090034*	50-358 F
	8212200099	50-373 H	Combustion Engineering, Inc	8212020372	PR
				8212140501	PROJ
Citizens Association for Sound Energy	8212230182	50-445 G		8212140510*	PROJ
	8212230182	50-445 G		8212160004	70-1100
	8212230195	50-445 G		8212170163	NUREG
	8212230195	50-445 G		8212210411	50-184 S
	8212300009	50-445 G	Commerce, Dept of	8212280181	YPORTLIC
			Commerce, Dept of, National Bureau of Standards		
	8212300009	50-445 G		8212290402*	50-184 G
	8212300045	50-445 G		8211290830	50-454 K
Citizens Concerned About Nuclear Power, Inc	8212100125	50-445 G	Commonwealth Edison Co	8211290530	50-454 K
Citizens for Energy & Employment	82121010191	50-341 G		8211290559*	50-454 K
				8211290559*	50-454 K
	8212140377	50-341 G		8212020234	50-295 S
	8212140428	50-341 G		8212020237*	50-295 S
	8212140460	50-341 G		8212020239	50-249 S
Cleveland Electric Illuminating Co	8212010208	50-440 G		8212020248*	50-249 S
	8212010208	50-440 G		8212020272	50-295 S
	8212010212	50-440 G			
	8212010212	50-440 G		8212020274	50-373 S
	8212020098*	50-440 K		8212020275	50-237 S
	8212020098*	50-440 K		8212020280*	50-237 S
	8212020296	50-440 S		8212020282*	50-373 S
				8212020285*	50-295 S
	8212020395	50-440 S		8212020294	50-373 S
	8212070015	50-440 H		8212020301*	50-373 S
	8212070015	50-440 H		8212020305	50-373 S
	8212070237	50-440 A		8212020327*	50-373 S
	8212070237	50-440 A		8212020329	50-454 S
	8212070358	50-440 G			
	8212070358	50-440 G		8212020337	50-249 S
	8212070365*	50-440 G		8212020357*	50-249 S
	8212070397	50-440 E		8212030043	50-237 P
	8212070397	50-440 E		8212030054*	50-254 G
				8212030273*	50-254 F
	8212080293	50-440 G		8212030273*	50-254 F
	8212090196	50-440 G		8212030279*	50-254 F
	8212090201*	50-440 C		8212030279*	50-254 F
	8212090201*	50-440 G		8212030284*	50-10 F
	8212090206*	50-440 G		8212030287*	50-10 F
	8212090206*	50-440 G			
	8212090495	50-440 G		8212060029	50-237 G
	8212090495	50-440 G		8212060029	50-237 G
	8212130241	50-440 G		8212060029	50-237 G
	8212130241	50-440 G		8212060041	50-373 F
				8212060041	50-373 F
	8212130246*	50-440 G		8212060045*	50-10 G
	8212130246*	50-440 G		8212060086	50-295 P
	8212140449	50-440 G		8212060086	50-295 P
	8212140445	50-440 G		8212060181*	50-254 F
	8212160247	50-440 G		8212060207	50-237 P
	8212160247	50-440 G		8212060219	50-295 P
	8212160251	50-440 G		8212060219	50-295 P
	8212160251	50-440 G		8212060267	50-237 P
	8212170153	50-440 S		8212070065	50-295 F
	8212170153	50-440 S		8212070065	50-295 F
	8212170241	50-440 S		8212070177	50-454 A
	8212170241	50-440 S		8212070177	50-454 A
	8212200061	50-440 G		8212070177	50-454 A
	8212200061	50-440 G		8212070177	50-454 A
	8212200072*	50-440 G		8212070177	50-454 A
				8212070177	50-454 A
	8212200072*	50-440 G			
	8212200105	50-440 G		8212070198*	50-454 A
	8212210321	50-440 G		8212070207*	50-454 A
	8212210345	50-440 G		8212070249	50-454 E
	8212210370	50-440 S		8212070249	50-454 E
				8212070249	50-454 E
	8212210370	50-440 S		8212070249	50-454 E
	8212280255	50-440 A		8212080235	50-454 G
	8212280255	50-440 A		8212080235	50-454 G
	8212280291	50-440 S		8212080248*	50-454 G
	8212280291	50-440 S		8212080248*	50-454 G
				8212080248*	50-454 G
	8212290189	50-440 E		8212080308	50-373 S
	8212290189	50-440 F		8212080317*	50-373 S
	8212290305	50-440 C		8212080318	50-373 S
	8212290305	50-440 E		8212080332*	50-373 S
	8212290325	50-440 C		8212080375	50-249 S
	8212290325	50-440 E		8212080381*	50-249 S
	8212300013	50-440 G		8212080390	50-265 S
Cleveland, OH	8212150012	50-344 M		8212080400	50-373 S
Coalition For Safe Power	8212140418	50-397 G		8212080404*	50-265 S
	8212160267	50-522 G		8212080410*	50-373 S
Coastal Chamber of Commerce of New Hampshire	8212200079	50-443 G		8212080412	50-373 S
Colorado State Univ	8212130182*	CONTRACT		8212080413*	50-373 S
Colorado, State of	8212160422	PR		8212080508	50-373 S

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8212080324*	50-373 S		8212140243	50-10 F
	8212080337	50-237 Q		8212140243	50-10 F
	8212080337	50-237 Q		8212140243	50-10 F
	8212080337	50-237 Q		8212140243	50-10 F
	8212090301	50-237 P		8212140289	50-373 Q
	8212090338*	50-254 Q		8212140289	50-373 Q
	8212090338*	50-254 Q		8212140292*	50-373 Q
	8212090383	50-237 F		8212140321	50-295 S
	8212090383	50-237 F		8212140327*	50-295 S
	8212090383	50-237 F		8212140402	50-373 P
	8212090383	50-237 F		8212160013	50-254 P
	8212090383	50-237 F		8212160326	50-237 Q
	8212090383	50-237 F		8212160334*	50-237 Q
	8212090383	50-237 F		8212170087	50-249 S
	8212100215	50-237 S		8212170102*	50-249 S
	8212100216*	50-237 S		8212170122	50-237 Q
	8212100272	50-373 S		8212170123	50-373 S
	8212100275*	50-373 S		8212170126*	50-373 S
	8212100312	50-237 S		8212170130*	50-237 S
	8212100319*	50-237 S		8212170134	50-249 S
	8212100328	50-265 S		8212170139*	50-249 S
	8212100330*	50-454 Q		8212170159	50-373 S
	8212100335*	50-265 S		8212170176*	50-373 S
	8212130028*	50-10 F		8212170184	50-373 S
	8212130028*	50-10 F		8212170192	50-454 S
	8212130028*	50-10 F		8212170192	50-454 S
	8212130028*	50-10 F		8212170194*	50-373 S
	8212130028*	50-10 F		8212170211	50-373 S
	8212130028*	50-10 F		8212170214*	50-373 S
	8212130028*	50-10 F		8212170218	50-249 S
	8212130028*	50-10 F		8212170225*	50-249 S
	8212130028*	50-10 F		8212170233	50-373 S
	8212130028*	50-10 F		8212170239*	50-373 S
	8212130028*	50-10 F		8212170264	50-373 S
	8212130028*	50-10 F		8212170270*	50-373 S
	8212130028*	50-10 F		8212170307	50-295 S
	8212130028*	50-10 F		8212170312*	50-295 S
	8212130035	50-295 P		8212210036	50-237 P
	8212130035	50-295 P		8212210108*	50-373 Q
	8212130041*	50-10 F		8212210108*	50-373 Q
	8212130041*	50-10 F		8212210157	50-237 S
	8212130041*	50-10 F		8212210160*	50-237 S
	8212130041*	50-10 F		8212210369	50-295 P
	8212130041*	50-10 F		8212210369	50-295 P
	8212130041*	50-10 F		8212210454	50-295 P
	8212130041*	50-10 F		8212210454	50-295 P
	8212130041*	50-10 F		8212210463	50-373 K
	8212130041*	50-10 F		8212210463	50-373 K
	8212130041*	50-10 F		8212210466*	50-373 K
	8212130041*	50-10 F		8212220190*	50-10 F
	8212130093	50-373 P		8212220190*	50-10 F
	8212130153*	50-295 F		8212220202*	50-10 F
	8212130156*	50-295 F		8212220212	50-10 P
	8212130175	50-373 R		8212220231*	50-10 P
	8212130177*	50-373 R		8212220231*	50-10 P
	8212130183	50-295 Q		8212220231*	50-10 P
	8212130183	50-295 Q		8212220231*	50-10 P
	8212130196	50-254 R		8212220231*	50-10 P
	8212130196	50-254 R		8212220231*	50-10 P
	8212130202*	50-254 R		8212220231*	50-10 P
	8212130202*	50-254 R		8212220231*	50-10 P
	8212130231	50-295 P		8212220231*	50-10 P
	8212130231	50-295 P		8212220231*	50-10 P
	8212130236*	50-295 P		8212220231*	50-10 P
	8212130236*	50-295 P		8212220231*	50-10 P
	8212140055	50-295 R		8212220231*	50-10 P
	8212140055	50-295 R		8212220231*	50-10 P
	8212140061*	50-295 R		8212220231*	50-10 P
	8212140061*	50-295 R		8212220231*	50-10 P
	8212140067	50-373 S		8212220231*	50-10 P
	8212140068	50-373 P		8212220231*	50-10 P
	8212140072*	50-373 P		8212220231*	50-10 P
	8212140095*	50-373 S		8212220231*	50-10 P
	8212140112	50-10 R		8212220231*	50-10 P
	8212140112	50-10 R		8212220231*	50-10 P
	8212140112	50-10 R		8212220231*	50-10 P
	8212140119	50-373 S		8212220231*	50-10 P
	8212140120*	50-10 R		8212220231*	50-10 P
	8212140120*	50-10 R		8212220231*	50-10 P
	8212140120*	50-10 R		8212220231*	50-10 P
	8212140128*	50-373 S		8212220231*	50-10 P
	8212140172	50-237 P		8212220231*	50-10 P
	8212140179	50-254 F		8212220231*	50-10 P
	8212140231*	50-373 Q		8212220231*	50-10 P
	8212140231*	50-373 Q		8212220231*	50-10 P

459

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8212270303*	50-237 Q		8212300179*	50-10 F
	8212270303*	50-237 Q		8212300179*	50-10 F
	8212270354	50-373 S		8212300179*	50-10 F
	8212270356*	50-373 S		8212300179*	50-10 F
	8212280110	50-237 Q		8212300179*	50-10 F
	8212280110	50-237 Q		8212300199*	50-10 F
	8212280117	50-237 P		8212300199*	50-10 F
	8212280117	50-237 P		8212300199*	50-10 F
	8212280117	50-237 P		8212300199*	50-10 F
	8212280117	50-237 P		8212300199*	50-10 F
	8212280117	50-237 P		8212300199*	50-10 F
	8212280195	50-373 S		8212300405*	50-254 F
	8212280212	50-237 P		8212300405*	50-254 F
	8212280212	50-237 P		8212300409*	50-254 F
	8212280212	50-237 P		8212300409*	50-254 F
	8212280212	50-237 P	Connecticut Yankee Atomic Power Co	8212020299	50-213 F
	8212280212	50-237 P		8212060157	50-213 P
	8212280212	50-237 P		8212060376	50-213 Q
	8212280212	50-237 P		8212072089	50-213 P
	8212280212	50-237 P		8212080449	50-213 S
	8212280212	50-237 P		8212080459*	50-213 S
	8212280212	50-237 P		8212090114	50-213 F
	8212280212	50-237 P		8212190036	50-213 F
	8212280215*	50-373 S		8212190222	71-6574
	8212280329	50-373 S		8212160216	PR
	8212280231*	50-373 S		8212210059	50-213 P
	8212280244	50-295 S		8212210063*	50-213 P
	8212280249*	50-295 S		8212210121	50-213 P
	8212280263	50-237 P		8212210121	50-213 P
	8212280263	50-237 P		8212230257	50-213 P
	8212280263	50-237 P		8212280119	50-213 F
	8212280263	50-237 P	Conner & Wetterhahn	8212020330	50-352 Q
	8212280263	50-237 P		8212020339*	50-352 Q
	8212280298	50-373 P		8212080286	50-358 Q
	8212280298	50-373 P		8212090073	50-358 Q
	8212280306	50-454 K		8212200089	50-358 Q
	8212280306	50-454 K		8212210261	50-458 Q
	8212280341	50-373 K		8212230327	50-352 Q
	8212280343	50-237 P		8212270216	50-352 Q
	8212280343	50-237 P		8212280185	50-352 Q
	8212280343	50-237 P		8212300187	50-352 Q
	8212280343	50-237 P	Conover & Associates, Inc Insurance	8212270173	70-1621
	8212280343	50-237 P		8212280254	70-1621
	8212280397	50-254 F	Consad Research Corp	8212070404	F01A
	8212280432	50-295 S	Consolidated Edison Co of New York, Inc	8210190499	50-247 F
	8212280442*	50-295 S		8212020318	50-247 Q
	8212280447	50-373 S		8212020318	50-247 Q
	8212280448*	50-454 Q		8212030248*	50-3 F
	8212280448*	50-454 Q		8212060103	50-247 Q
	8212280449*	50-373 S		8212060103	50-247 Q
	8212280450	50-295 S		8212060146	50-247 S
	8212280461*	50-295 S		8212060152*	50-247 S
	8212280472	50-237 S		8212070285	50-3 P
	8212280479*	50-237 S		8212070285	50-3 P
	8212280483	50-373 S		8212070296	50-247 Q
	8212280487*	50-373 S		8212080297	50-247 S
	8212290086*	50-295 F		8212080311*	50-247 S
	8212290086*	50-295 F		8212090087	50-247 Q
	8212290089*	50-295 F		8212090090	50-247 Q
	8212290089*	50-295 F		8212090090	50-247 Q
	8212290105*	50-295 F		8212090205	50-247 P
	8212290105*	50-295 F		8212130232	50-247 P
	8212290110*	50-295 F		8212130232	50-247 P
	8212290111	50-254 F		8212130288	50-247 P
	8212290111	50-254 F		8212140353	50-3 F
	8212290190	50-237 P		8212140423	50-247 Q
	8212290193*	50-237 P		8212140439	50-247 Q
	8212290247	50-454 F		8212140439	50-247 Q
	8212290247	50-454 F		8212140446*	50-247 Q
	8212290329	50-249 S		8212140446*	50-247 Q
	8212290333*	50-249 S		8212150023	50-247 S
	8212290337	50-374 Q		8212150027*	50-247 S
	8212290344	50-237 S		8212150080	50-247 S
	8212290345*	50-237 S		8212150084*	50-247 S
	8212290369	50-249 S		8212160289	50-247 Q
	8212290385*	50-249 S		8212160289	50-247 Q
	8212290398	50-237 S		8212210119	50-247 S
	8212290407	50-254 P		8212210128	50-247 S
	8212290409*	50-237 S		8212210133*	50-247 S
	8212290472	50-249 S		8212210140*	50-247 S
	8212290478*	50-249 S		8212220042*	50-3 F
	8212290511*	50-295 F		8212220042*	50-3 F
	8212290511*	50-295 F		8212220046*	50-3 F
	8212290513*	50-295 F		8212220046*	50-3 F
	8212300179*	50-10 F		8212220271	50-247 Q

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Consumers Power Co	8212220271	50-247 Q		8212170144	50-329 A
	8212230187	50-247 Q		8212170144	50-329 A
	8212230187	50-247 Q		8212170150*	50-155 Q
	8212270120	50-247 F		8212200029	PR
	8212270361*	50-247 Q		8212200070	50-255 P
	8212280219	50-247 R		8212200075*	50-255 P
	8212280221*	50-247 R		8212200082*	50-255 P
	8212280237	50-247 P		8212210156	50-329 G
	8212280243*	50-247 P		8212210258	50-155 G
	8212280248*	50-247 P		8212210285	50-155 G
	8212280293	50-247 Q		8212210289*	50-155 G
	8212280364	50-247 P		8212210292*	50-155 G
	8212290302*	50-3 F		8212210296*	50-155 G
	8212290308*	50-3 F		8212210309	50-329 A
	8212290308*	50-3 F		8212210314	50-329 Q
	8212300230	50-247 Q		8212210314	50-329 Q
	8212300273	50-247 P		8212230112	70-2964
	8212300352	50-247 P		8212230275	50-255 Q
	8212010035	50-329 A		8212230342	50-155 P
	8212020313	50-329 S		8212230343*	50-155 P
	8212020325	50-255 S		8212230350	50-329 G
	8212020331*	50-255 S		8212270126	50-329 S
	8212020351*	50-255 Q		8212270126	50-329 S
	8212030019	50-155 Q		8212270215	50-255 S
	8212030137	50-155 P		8212270228*	50-255 S
	8212060067	50-255 S		8212280083	50-255 P
	8212060073*	50-255 S		8212280089*	50-255 P
	8212060357	50-255 S		8212280094*	50-255 P
	8212060371*	50-255 S		8212280103	50-155 P
	8212060382*	50-255 S		8212280107*	50-155 P
	8212060392*	50-255 S		8212280113*	50-155 P
	8212060396*	50-255 S		8212280131	50-155 Q
	8212060412*	50-255 S		8212280207	50-329 D
	8212060421*	50-255 S		8212280225	50-329 F
	8212060431*	50-255 S		8212280225	50-329 F
	8212060444*	50-255 S		8212280320	50-329 S
	8212070017	50-329 R		8212280320	50-329 S
	8212070127	50-155 Q		8212280330	50-255 Q
	8212070300	50-155 F		8212280382	50-255 F
	8212070300	50-155 F		8212280460	50-255 S
	8212070300	50-155 F		8212280464*	50-255 S
	8212070300	50-155 F		8212290203	50-329 A
	8212070327	50-155 Q		8212290203	50-329 A
	8212070330*	50-155 Q		8212290208*	50-329 A
	8212070337*	50-155 Q		8212300149*	50-329 A
	8212070340*	50-155 Q		8212300332	50-155 R
	8212070345*	50-155 Q		8212300341*	50-155 R
	8212070349*	50-155 Q		8212280354*	50-387 P
	8212070352*	50-155 Q		8212140146	50-97 R
	8212080261	50-255 S		8212140232	50-97 R
	8212080271*	50-255 S		8212140232	50-97 R
	8212080392	50-329 A		8212140238*	50-97 R
	8212080392	50-329 A		8212140238*	50-97 R
	8212090066	50-329 A		8212140469	50-97 R
	8212090066	50-329 A		8212140469	50-97 R
	8212090069*	50-329 A		8212030258	40-8511
	8212090188	50-329 T		8212100343	WASTE MGT
	8212090188	50-329 T		8212100349*	WASTE MGT
	8212090194*	50-329 T		8212010406*	CONTRACT
	8212090194*	50-329 T		8212300312*	50-341 A

461

[illegible]

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Duke Univ Duquesne Light Co	8212230051*	CONTRACT	ENSA, Inc	8212140366	50-206 P
	8212020078	50-334 P		8212220282	NUREG
	8212020084*	50-334 P		8212270145	NUREG
	8212020089*	50-334 P		8212270454	NUREG
	8212030142	50-334 P		8212270499	NUREG
	8212030148	50-334 P	East Tennessee Development District Ebasco Services, Inc (subs of Enserch Corp)	8212080201	50-537 D
	8212070204	50-334 R		8212170243	50-389 R
	8212080419	50-334 S		8212210324*	50-286 P
	8212080440*	50-334 S		8212280187	50-389 R
	8212080451	50-334 S		8212280333	50-389 A
	8212080474	50-334 P	Edison Electric Institute Edlow International Co	8212280405	50-389 A
	8212080480*	50-334 P		8212020359	PR
	8212080484*	50-334 P		8211090496	70-2955
	8212080497*	50-334 S		8212100087	XPORTLIC
	8212080526	50-334 S		8212160791	XPORTLIC
	8212080530*	50-334 S	Energy Fuels Nuclear, Inc	8212300140	XPORTLIC
	8212090320	50-334 P		8212070509	40-6681
	8212090326*	50-334 P		8212290012	40-6681
	8212100041*	50-334 Q		8212290013*	40-6681
	8212130242	50-334 P		8209220453*	50-331 P
	8212130243	50-334 P	Energy Incorporated	8212100086*	FDIA
	8212130245*	50-334 P		8212100089*	FDIA
	8212130246*	50-334 P		8212230159	FDIA
	8212130264*	50-334 P		8212010025	WASTE HOT
	8212140174	50-334 S		8212020060	WASTE HOT
	8212140191*	50-334 S	Energy Research Group, Inc Energy, Dept of	8212020073*	WASTE HOT
	8212140427*	50-412 Q		8212020262	50-537 A
	8212150020	50-334 S		8212060113	50-537 Q
	8212150025*	50-334 S		8212070378*	COMMUNISIDN
	8212150075	50-334 S		8212090082	50-537 C
	8212150078*	50-334 S		8212130122	71-6495
	8212160339	50-334 P		8212130129*	71-6495
	8212170200	50-334 F		8212130195	71-4909
	8212220283	50-412 H		8212150133	50-537 A
	8212220373	50-334 P		8212160437	71-9132
	8212220403	50-412 A		8212160438*	71-9132
	8212220404*	50-412 A		8212170405	40-6500
	8212220409	50-334 P		8212170409*	40-6500
	8212220425	50-334 P		8212200015	50-537 C
	8212270155	50-334 P		8212210253	70-143
	8212270161*	50-334 P	Energy, Dept of, Clinch River Breeder Reactor Plant	8212220010	40-6500
	8212270163*	50-334 P		8212270238	70-143
	8212270201	50-334 P		8212300011	50-537 F
	8212270207*	50-334 P		8212010011	50-537 F
	8212270209*	50-334 P		8212010146	50-537 A
	8212290225	50-334 R		8212010161	50-537 A
	8212290230*	50-334 R		8212020303	50-537 A
	8212290289*	50-334 Q		8212070226	50-537 A
	8212290339	50-334 S		8212070243	50-537 A
	8212290340*	50-334 S		8212070311	50-537 A
	8212290373	50-334 S		8212140374	50-537 A
	8212290382*	50-334 S		8212150054	50-537 A
	8212290404	50-334 S		8212150177	50-537 D
	8212290411*	50-334 S		8212160200	50-537 A
	8212290439	50-334 S		8212170190	50-537 A
	8212290448*	50-334 S	EDS Nuclear, Inc	8212200077	50-537 A
	8212300107	50-334 F		8212210045	50-537 A
	8211120491*	MISC		8212210050	50-537 A
	8212130224	50-255 P		8212210055	50-537 A
	8212130229*	50-255 P		8212230007	50-537 A
	8212290104*	50-266 P	EQ&O, Inc	8212230237	50-537 A
	790B140789*	50-219 P		8212230253	50-537 A
	8105210384*	50-263 Q		8212230262	50-537 A
	8201120155*	RES		8212230263	50-537 A
	8212010474	RES		8212230300	50-537 A
	8212010519*	50-352 A		8212230321	50-537 A
	8212020076	50-395 P		8212270185	50-537 A
	8212020086	50-409 P		8212270229	50-537 A
	8212020095	50-155 P		8212270231	50-537 A
	8212020100	RES		8212270248	50-537 A
	8212020104	RES		8212270294	50-537 F
	8212020108	50-364 P		8212270302	50-537 A
	8212020110	50-249 P		8212300215	50-537 A
	8212020126	RES		8212300248	50-537 D
	8212060468	NUREG		8212300249*	50-537 B
	8212060471	50-295 P	Engineering & Economics Research, Inc Environmental Coalition on Nuclear Power	8212300253	50-537 A
	8212060480	NUREG		8212300299	50-537 A
	8212080505	RES		8212300343	50-537 A
	8212080510	RES		8212270501*	50-537 A
	8212080516	RES		8212140186	50-277 Q
	8212080520	RES	Epler, E P	8212300134	50-277 Q
	8212080551*	50-443 A		8212030280	ACRS
	8212130108	NUREG		8212060325	ACRS
	8212130113	NUREG			
	8212130152	NUREG			

CORPORATE SOURCE INDEX

463

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Essex Corp	8212130185*	50-400 A		8212280170	50-250 S
European Communities, Commission of	8212010189	XPORTLIC		8212280175*	50-250 S
Exxon Corp	8212030285	40-8102		8212280359	50-335 S
	8212210534	40-8064		8212280366*	50-335 S
	8212210542*	40-8064		8212280418	50-335 S
	8212230063	40-8102			
Exxon Nuclear Co., Inc. (subs. of Exxon Corp.)	8212010057	XPORTLIC		8212280425*	50-335 S
	8212010063*	XPORTLIC		8212290068*	50-250 Q
	8212030088	TOPREP		8212290094*	50-250 Q
	8212130097	TOPREP		8212290097*	50-250 Q
				8212290124*	50-250 Q
	8212140167	50-316 P		8212290153	50-250 R
	8212140190	TOPREP		8212290153	50-250 R
	8212140411	50-282 P		8212290153	50-250 R
	8212150003	TOPREP		8212290153	50-250 R
	8212150005*	TOPREP		8212290169*	50-250 R
	8212150276	70-1297		8212290169*	50-250 R
	8212280404	50-316 P		8212290169*	50-250 R
	8212290199*	50-237 P		8212290169*	50-250 R
	8212290206*	50-237 P		8212290265	50-389 C
	8212290215*	50-237 P		8212290357	50-335 P
Fauske & Associates, Inc.	8212270254*	50-537 A		8212290359	50-335 P
Federal American Partners	8212070407	40-4492		8212290361*	50-335 P
Federal Emergency Management Agency	8212150137*	50-382 Q		8212300041	50-335 S
	8212150153*	50-382 Q		8212300045*	50-335 S
	8212280087*	50-247 F		8212300252	50-389 S
	8212280092*	50-247 F	Florida Power Corp	8211090043	50-302 P
	8212280426	50-483 F		8212020045	50-302 S
	8212290207	50-416 F		8212020052*	50-302 S
	8212020268	PRM		8212020063	50-302 S
Florida Power & Light Co.	8211040086	50-335 S		8212020071*	50-302 S
	8211040090*	50-335 S		8212020077	50-302 S
	8212010026	NUREG		8212020087*	50-302 S
	8212020369	50-335 S		8212060084	50-302 H
	8212020371*	50-335 S		8212060225	50-302 P
	8212030216	50-389 S		8212100006	50-302 F
	8212070215	50-389 S		8212140048	50-302 R
	8212090200	50-389 S		8212140051*	50-302 R
	8212090356	50-250 S		8212140089	50-302 F
	8212090371*	50-250 S		8212150046	50-302 S
	8212090403	50-335 S		8212150053*	50-302 S
	8212090410*	50-335 S		8212150060	50-302 S
	8212090503*	50-250 Q		8212150079	50-302 S
	8212090549*	50-335 Q		8212150102*	50-302 S
	8212090554*	50-335 Q		8212150105	50-302 S
	8212090559*	50-335 Q		8212150108*	50-302 S
	8212100219	50-250 S		8212220270	50-302 P
	8212100220*	50-250 S		8212220284	50-302 F
	8212100260	50-389 S		8212220314	50-302 S
	8212140373	50-389 A		8212220322*	50-302 S
	8212140461	50-389 A		8212290177	50-302 H
	8212150064*	50-302 S	Florida Univ. of Gainesville	8212070004	50-83 R
	8212150068	50-335 P		8212070009*	50-83 R
	8212150074	50-389 S	Flow Science, Inc	8212070276*	50-416 P
	8212150098	50-389 S	Fontana, L.	8212160521*	50-382 Q
	8212150129	50-389 A	Fracture Proof Design Corp	8212270135	50-354 A
	8212150156	50-335 S			
	8212150158*	50-335 S	Frankhauser, D. D.	8212140205	50-358 Q
	8212150180	50-250 R	Franklin Institute/Franklin Research Center	8206160113*	50-271 P
	8212150180	50-250 R			
	8212150204	70-2957		8207010124*	50-29 P
				8207010149*	50-244 P
				8207010396*	50-245 P
	8212170060*	50-335 F			
	8212170065*	50-335 F		8207010410*	50-409 P
	8212170127	50-335 P		8207150169*	50-219 P
	8212170129*	50-335 P		8207180049	FDIA
	8212170269	50-389 A		8209140103*	50-255 P
				8209230258*	50-409 P
	8212170273	50-250 P		8209230377*	50-155 P
	8212170274	50-335 P		8209290122*	50-409 P
	8212200071	50-335 S		8210070227*	50-250 P
	8212200085*	50-335 S		8210220470*	50-317 P
	8212210101	50-389 E		8210220483*	50-317 P
	8212210175	50-335 S		8210250187*	50-344 P
	8212210186*	50-335 S		8212010451*	FDIA
	8212210190	50-250 P		8212170401*	CONTRACT
	8212210202	50-250 S		8212170402*	CONTRACT
	8212210207*	50-250 S		8212220024*	CONTRACT
	8212210348	50-389 S		8212230110*	50-213 P
	8212210354	50-389 S		8212230250*	50-277 P
	8212210389	50-335 S		8212290536*	50-250 P
	8212210396*	50-335 S		8212290536*	50-250 P
	8212220200	50-389 A		8212300348*	50-289 P
	8212220441	50-335 S			
	8212220442*	50-335 S	Fred C. Hart Associates, Inc.	8212020390*	CONTRACT
	8212280164	50-250 S		8212270530*	CONTRACT
	8212280167*	50-250 S	Friends of the Earth	8212220246	50-247 Q
				8212230352	50-352 Q

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Fugro, Inc QA Technologies, Inc /General Atomic Co Oage-Babcock Associates, Inc Oell, W R	8212230356	50-352 O	General Research Corp Georgia Power Co	8212140764*	50-320 F
	8212080568*	50-443 A		8212170119	50-289 P
	8212010468	XPORTRIC		8212210017	50-289 P
	8206100047*	50-344 F		8212210018	50-320 P
	8208290027	ACRS		8212210019	50-219 P
Galloway & Greenberg	8212080257	50-537 O		8212210020*	50-219 P
	8212230200	50-537 O		8212210040	50-219 A
	8212270245	50-537 O		8212210232	50-289 A
	8212010144	NUREG		8212210234*	50-289 P
	8212020174	XPORTRIC		8212210372	50-219 S
General Electric Co	8212080301*	50-440 O		8212210377*	50-219 B
	8212080301*	50-440 O		8212210460*	50-219 O
	8212090077	TOPREP		8212210468*	50-219 O
	8212090148	TOPREP		8212210555*	50-219 F
	8212100005*	QA999		8212210557*	50-219 F
	8212130172	50-447 B		8212220415	50-289 F
	8212130246*	50-440 O		8212220421*	50-289 F
	8212130246*	50-440 O		8212220449	50-320 S
	8212140348	50-447 B		8212220454*	50-320 S
	8212140449	50-447 B		8212230293	50-320 P
	8212160423	70-1113		8212270134	50-289 P
	8212160762	NUREG		8212270149	50-320 F
	8212170101*	50-277 P		8212270268	50-289 P
	8212200041	50-447 A		8212280010	71-5957
	8212200072*	50-440 O		8212280218	50-219 D
	8212230085	70-1113		8212280313	50-219 P
	8212230103*	70-1113		8212280390*	50-320 A
	8212230301	50-447 E		8212290127	50-219 A
	8212230328	50-447 A		8212290134*	50-219 P
	8212270506*	CONTRACT		8212290197	50-289 P
	8212290018*	FOIA		8212290233	50-320 B
	8212290119	50-447 A		8212290240*	50-320 B
	8212300123*	CONTRACT		8212290353*	50-320 A
	8212300175	XPORTRIC		8212290410*	50-219 A
	8212150216	71-9001		8212300113	50-320 P
General Electric Uranium Management Corp	8212010097*	50-320 F	General Research Corp Georgia Power Co	8212300260	50-320 P
General Public Utilities - GPU Service Corp	8212030113	50-320 R		8212300266*	CONTRACT
	8212030120*	50-320 R		8212020292	50-366 S
	8212060015	50-320 P		8212020295*	50-366 S
	8212060019*	50-320 P		8212030170	50-321 B
	8212060022*	50-320 P		8212030174*	50-321 S
	8212060034	50-289 F		8212070297	50-321 S
	8212060085	50-320 P		8212090121	50-366 S
	8212060148	50-219 S		8212090126*	50-366 S
	8212060247	50-219 P		8212090127	50-321 A
	8212060322	50-320 B		8212090140	50-321 S
	8212060326*	50-320 B		8212090142	50-366 S
	8212060332	50-219 O		8212090145*	50-321 S
	8212070143	50-320 R		8212090149*	50-366 B
	8212070251	50-289 F		8212090190	50-366 S
	8212070253*	50-289 F		8212090193*	50-366 S
	8212080240	50-219 B		8212090202	50-321 S
	8212080263*	50-219 S		8212090207*	50-321 S
	8212080349	50-219 S		8212090216	50-321 S
	8212080354*	50-219 O		8212090219*	50-321 S
	8212080359*	50-219 S		8212090247	50-366 S
	8212080368	50-219 S		8212090254*	50-366 S
	8212080393*	50-219 S		8212090329	50-366 S
	8212080511	50-219 S		8212090330	50-321 B
	8212080519	50-289 F		8212090335*	50-366 S
	8212080323*	50-219 S		8212090341*	50-321 S
	8212080556	50-219 O		8212090379	50-321 A
	8212090284	50-289 P		8212090381	50-366 S
	8212090293*	50-289 P		8212090386	50-366 S
	8212090297*	50-289 P		8212090388*	50-366 S
	8212090501	50-289 P		8212090389	50-366 S
	8212090508*	50-289 P		8212090391*	50-366 S
	8212130059	50-320 P		8212090399*	50-366 S
	8212130060*	50-320 P		8212090437	50-366 S
	8212130104	50-289 P		8212090446*	50-366 S
	8212130306	50-219 F		8212090492	50-321 O
	8212130318	50-320 F		8212100264	50-366 S
	8212140169	50-219 S		8212100279*	50-366 S
	8212140177*	50-219 S		8212100282	50-366 S
	8212140180	50-289 P		8212100286*	50-366 S
	8212140228	50-289 B		8212100311	50-366 S
	8212140239*	50-289 S		8212100314*	50-366 S
	8212140362	50-219 J		8212140119	50-366 S
	8212140466	50-289 P		8212140123*	50-366 S
	8212150038	50-320 S		8212140269	50-321 B
	8212150044*	50-320 S		8212140271*	50-321 S
	8212150110	50-289 P		8212140421	50-366 S
	8212150270	71-9151		8212140429*	50-366 S
	8212160752*	50-320 F		8212140433	50-366 S
				8212140436*	50-366 S

CORPORATE SOURCE INDEX

465

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8212150007	50-321 S		8212220274	50-458 A
	8212150009	50-321 F		8212270183	50-458 S
	8212150011*	50-321 S		8212270236	50-458 S
	8212150014	50-321 S		8212280196	50-458 S
	8212150018*	50-321 S		8212280252	50-458 S
	8212150031	50-321 S		8212270560*	CONTRACT
	8212150037*	50-321 S	Gutmann, P. H.	8212140380*	50-537 A
	8212170092	50-321 S	Hanford Engineering Development Laboratory		
	8212170099*	50-321 S		8212140388*	50-537 A
	8212170155	50-366 S	Harmon & Weiss	8212200021	70-143
	8212170165*	50-366 S		8212200039	50-443 O
	8212170166	50-321 S		8212200039	50-443 O
	8212170202*	50-321 S		8212200049*	50-443 O
	8212170246	50-321 P		8212200049*	50-443 O
	8212170353	50-321 R		8212210272	50-289 O
	8212170353	50-321 R		8212210336	50-289 O
	8212170359*	50-321 R		8212220248*	70-143
	8212210083	50-321 S		8212280191	50-358 O
	8212210088*	50-321 S		8212280270	70-143
	8212210188	50-321 S		8212280506	FOIA
	8212210196*	50-321 S		8212300002	50-289 O
	8212210446	50-366 S		8212300008	50-289 O
	8212210452*	50-366 S		82123000242	50-289 O
	8212280159	50-366 S		8212300362	50-289 O
	8212280161*	50-366 S	Harold J. Spelman & Associates	8212130167	40-2061
	8212280180	50-321 S		8212270469	40-2061
	8212280356	50-424 A		8212270478	40-2061
	8212280387	50-321 S	Hittman Corp	8212130055	71-9151
	8212280392*	50-321 S	Hittman Nuclear & Development Corp (subs. Hittman Corp.)	8212130061*	71-9151
	8212290151	50-321 P	House of Rep	8212150282	71-9151
	8212300058	50-366 S		8212070068*	50-289 H
	8212300063*	50-366 S		8212080699*	50-322 H
	8212300091	50-321 S		8212230276	50-247 U
	8212300095*	50-321 S	House of Rep, Interior & Insular Affairs	8209150008*	COMMISSION
	8212300098	50-366 S		8212230341	50-247 U
	8212300102*	50-366 S	Houston Industries, Inc	8212170133*	50-498 A
	8212300265	50-321 S		8212020254	50-498 A
	8212300270*	50-321 S	Houston Lighting & Power Co.	8212030100	50-498 S
	8212300271	50-321 S		8212070262	50-498 K
	8212300275*	50-321 S		8212070262	50-498 K
	8212300277	50-321 S		8212070263*	50-498 K
	8212300281*	50-321 S		8212090377	50-498 K
	8212300284	50-366 S		8212090377	50-498 K
	8212300285	50-366 S		8212090382*	50-498 K
	8212300287	50-321 S		8212090382*	50-498 K
	8212300289*	50-321 S		8212140381	50-498 C
	8212300290*	50-366 S		8212140381	50-498 C
	8212300292*	50-366 S		8212140383*	50-498 C
	8212300293	50-366 S		8212140383*	50-498 C
	8212300298*	50-366 S		8212170120	50-498 F
	8212300323	50-366 S		8212170120	50-498 F
	8212300325*	50-366 S		8212170124*	50-498 A
	8212300328	50-321 S		8212170124*	50-498 A
	8212300329	50-321 S		8212270172	50-498 S
	8212300336*	50-321 S		8212280279	50-498 O
	8212300337*	50-321 S		8212280279	50-498 O
	8212300340	50-366 S		8212280282	50-498 O
	8212300344	50-366 S		8212280282	50-498 O
	8212300345*	50-366 S		8212290202	50-498 S
Georgia, State of	8212300346*	50-366 S	Hovis, Cockrill, Weaver & Bjur	8212140333	50-522 O
Georgia, State of, Dept of Human Resources	8212220553*	CONTRACT		8212140333	50-522 O
Geotechnical Engineers, Inc	8212020251	PR		8212140345	50-522 O
Getty Oil Co (Petrochemicals)	8212280501*	50-329 A		8212140345	50-522 O
	8212230084	40-6659		8212140354	50-522 O
	8212270325	40-6659		8212140354	50-522 O
Gilbert/Commonwealth Cos	8212210461*	50-244 P		8212140386	50-522 O
Glycine-Sales & Service	8212160532	PR		8212140386	50-522 O
Golder Associates	8212280491*	CONTRACT	Huntton & Williams	8208290121	FOIA
Goldman, M	8212270513*	CONTRACT		8212020381	50-322 O
	8212280128	50-358 O		8212270034	FOIA
Government Accountability Project	8212280132	50-413 O		8212270196	50-322 O
Guild, R	8212280132	50-413 O	Idaho National Engineering Laboratory	8212010407	RES
	8212280138	50-413 O	Illinois Power Co	8212020088	50-461 A
	8212280138	50-413 O		8212020324	50-461 B
	8212020378	PR		8212020333	50-461 B
Gulf Coast Environmental Defense Foundation, Inc	8212280030*	70-146		8212060093	50-461 O
Gulf Oil Corp	8212100033	50-458 S		8212060105	50-461 A
Gulf States Utilities Co	8212100239*	50-458 O		8212060144	50-461 A
	8212210136	50-458 S		8212070125	50-461 E
	8212210176	50-458 S		8212070200	50-461 E
	8212210261	50-458 O		8212070229	50-4
	8212210261	50-458 O		8212140057	50-4
				8212170303	50-4

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8212170330	50-461 E	Interior, Dept of, Fish & Wildlife Service	8212160316*	50-332 Q
	8212210313	50-461 A	Interior, Dept of, Geological Survey	8212020193*	50-331 J
	8212220233	50-461 A		8212280438*	50-409 P
	8212280101	50-461 A	Interior, Dept of, National Park Service	8212160643*	COMMITTEE
	8212280235	50-461 A		8212210037	50-275 P
	8212280360	50-461 Q		8212060221	50-331 S
	8212290179	50-461 E	Iowa Electric Light & Power Co	8212060224*	50-331 J
	8212230092	NUREG		8212060324*	50-331 Q
Illinois, State of	8212280176	50-10 H		8212070216	50-331 P
Illinois, State of, Dept Nuc Safety				8212070308	50-331 P
(formerly Dept Public Health)	8212010037*	50-315 F		8212090322	50-331 P
Indiana & Michigan Electric Co	8212010037*	50-315 F		8212090328*	50-331 P
	8212010039*	50-315 F		8212090337	50-331 P
	8212010039*	50-315 F		8212100278	50-331 P
	8212020229	50-316 S		8212100284*	50-331 P
	8212020232*	50-316 S		8212100295	50-331 Q
	8212020283	50-315 S		8212140134	50-331 Q
	8212020289*	50-315 S		8212140142	50-331 Q
	8212030125	50-315 P		8212140147*	50-331 S
	8212030145*	50-315 P		8212140332	50-331 S
	8212060031	50-315 S		8212140330*	50-331 J
	8212060048	50-316 S		8212150070	50-331 P
	8212060057*	50-316 S		8212150132	50-331 J
	8212060060*	50-316 S		8212170193	50-331 P
	8212060072	50-315 P		8212170308	50-331 P
	8212080091*	50-315 F		8212210033	50-331 S
	8212080091*	50-315 F		8212210034*	50-331 S
	8212080096*	50-315 F		8212210070	50-331 S
	8212080096*	50-315 F		8212210074*	50-331 S
	8212090296	50-315 P		8212210209	50-331 R
	8212090296	50-315 P		8212210210*	50-331 P
	8212100177	50-316 S		8212210319	50-331 P
	8212100251	50-315 S		8212210316*	50-331 P
	8212100259*	50-315 S		8212210352	50-331 S
	8212100290	50-315 P		8212210358*	50-331 S
	8212100300*	50-315 P		8212230374*	50-331 S
	8212100322	50-315 S		8212230377*	50-331 S
	8212100327*	50-315 S		8212270168	50-331 P
	8212140156	50-316 S		8212270176*	50-331 P
	8212140165*	50-316 S		8212270290	50-331 Q
	8212150329*	50-315 F		8212280065	50-331 P
	8212150329*	50-315 F		8212280125	50-461 A
	8212150335*	50-315 F		8212280454	50-331 S
	8212160001	50-315 F		8212280457*	50-331 S
	8212160001	50-315 F	Isham, Lincoln & Beale	8212070127	50-155 Q
	8212160002*	50-315 F		8212070327	50-155 Q
	8212160002*	50-315 F		8212070352*	50-155 Q
	8212170179	50-316 P		8212070168	50-329 F
	8212170188*	50-316 P		8212140387	50-329 Q
	8212170224	50-316 S		8212160223	50-155 Q
	8212170228*	50-316 S		8212210288	50-155 Q
	8212170232*	50-316 S		8212210289	50-155 Q
	8212170237*	50-316 S		8212270045	FOIA
	8212170267	50-316 S	Ishikawajima - Harima Heavy Industries Co., Ltd	8212170111*	50-277 P
	8212170268*	50-316 S	Isomedia, Inc (Subs of Massfield Enterprises, Inc.)	8212200053	PR
	8212170283	50-315 S		8212010044	XPORTL IC
	8212170292*	50-315 S	Japan	8212010048	XPORTL IC
	8212170296*	50-315 S		8212010051	XPORTL IC
	8212200056	50-316 R		8212270087	XPORTL IC
	8212200065*	50-316 R		8212270090	XPORTL IC
	8212200119	50-315 R		8001140342	50-219 S
	8212200122*	50-315 R	Jersey Central Power & Light Co	8212060019*	50-330 P
	8212210125	50-315 P		8212060095	50-320 Q
	8212210125	50-315 P	Joint Applicants-Palo Verde	8212280179	50-483 Q
	8212270136	50-315 P	Joint Intervenor-Callaway	8212280288	50-278 Q
	8212280165	50-315 Q	Joint Intervenor-Diablo Canyon		
	8212280310	50-316 Q		8212020355	50-383 Q
	8212290217	50-316 R	Joint Intervenor-Waterford	8212160521*	50-384 Q
	8212290228*	50-316 R		8212230361	50-382 Q
	8212290355	50-316 S		8212010053*	50-389 M
	8212290358*	50-316 S	Justice, Dept of	8212010290*	50-389 M
	8212290419	50-315 R	Justice, Dept of, Attorney General's Office		
	8212290424*	50-315 R		8212010174*	FOIA
	8212290428*	50-315 R	KFRC Radio, San Francisco, CA	8212030127	50-482 A
	8212290434*	50-315 R	Kansas Gas & Electric Co	8212030135*	50-482 A
Information Systems & Network Corp	8212080583*	CONTRACT		8212070222	50-482 A
Inspection Services Corp	8212270018	71-490		8212170324	50-482 M
	8212270027*	71-490		8212200036	PR
Institute for Policy Studies	8212020358	50-373 P		8212210115	50-482 S
	8212280511	FOIA		8212270187	50-482 C
Institute of Nuclear Power Operations	8212080250*	50-409 P		8212270193*	50-482 C
	8212140077	50-10 R		8212280338	50-482 S
	8212140443	50-254 R			
	8212170149	50-135 P	Kansas, Univ of	8212220535*	CONTRACT
			Kentucky, State of	8212090319*	State Prog

CORPORATE SOURCE INDEX

467

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Kerr-McGee Chemical Corp (subs of Kerr-McGee Corp)	8212130432	40-2061	Louisiana Power & Light Co	8212030036	50-382 S
Kerr-McGee Corp	8212130237	40-2061		8212030048	50-382 S
	8212210312	40-2061		8212030055	50-382 S
	8212210515*	40-2061		8212070228*	50-382 G
	8212230379	40-8027		8212090203	50-382 F
	8212230380*	40-8027		8212100002	50-382 A
	8212270563	40-8027		8212100098	50-382 O
	8212280012*	40-1478		8212100100	50-382 G
	8212280013	70-1193		8212140395	50-382 S
	8212280018*	70-1193		8212150042	50-382 F
Kerr-McGee Nuclear Corp	8212100403	40-8768		8212150047*	50-382 F
	8212100407*	40-8768		8212150050*	50-382 F
	8212100410*	40-8768		8212200127*	50-382 O
	8212290149	40-8768		8212200129*	50-382 O
Markpatrick, Lockhart, Hill, Christopher & Phillips	8212220394	50-275 Q		8212210066	50-382 S
LIXJ, Inc	8212060410	FOIA		8212210172	50-382 G
Labat-Anderson, Inc	8212070453*	CONTRACT		8212210230	50-382 S
Labor, Dept of	8212100398*	FOIA		8212210281	50-382 S
Lake County, OH	8212200037	PRM		8212270015*	50-382 F
Lawrence Livermore Laboratory	7908140421*	50-206 P		8212270017*	50-382 F
	7908140784*	50-219 P		8212270130	50-382 S
	7907180332*	50-244 P		8212270138	50-382 G
	8005070798*	50-237 P		8212270160	50-382 A
	8005280555*	50-219 P		8212270166	50-382 S
	8009050320*	FOIA		8212270237	50-382 S
	8010220355*	50-245 P		8212280143	50-382 S
	8112160327*	50-213 P		8212280169	50-382 S
	8203010313*	FOIA		8212280182	50-382 O
	8205040451*	FOIA		8212280203	50-382 S
	8205240413*	FOIA		8212290245	50-382 Q
	8206290144*	FOIA		8212300162	50-382 A
	8208030436*	FOIA		8212300198	50-382 S
	8209230424*	50-250 P		8212300219	50-382 S
	8210260403*	50-206 P		8212300288	50-382 S
	8211060556*	50-286 P		8212300310	50-382 S
	8211110457*	50-440 A	Louisiana, State of	8212100117	50-458 O
	8212090023*	50-263 P		8212230192	50-458 Q
	8212130370*	50-344 P	Lovelace Biomed & Environmental Research Institute	8212220228	NUREG
	8212140497	50-261 P	Lowell General Hosp Lowell, MA	8212030020*	70-2792
	8212140464	NUREG	Lowenstein, Newman, Reis, Axelrad & Toll	8212280279	50-498 Q
	8212140485	NUREG		8212280279	50-498 Q
	8212160773	NUREG		8212280282	50-498 Q
Leifgeuf, Lamb, Leiby & MacRae	8212010147	50-341 K		8212280282	50-498 Q
	8212060028	50-285 P		8212280289	50-522 G
	8212230317	50-285 P		8212280541	27-47
League of Women Voters of Rockford, IL	8212080235	50-454 Q	M D Anderson Hosp, Houston, TX	8212070429*	CONTRACT
	8212080235	50-454 Q	MHB Technical Associates	8212270227	50-322 T
	8212080245*	50-454 Q	MPR Associates, Inc	8212070159*	TOPREP
	8212080245*	50-454 Q	Maine Yankee Atomic Power Co.	8212030297*	50-309 F
	8212280188	50-454 Q		8212030304*	50-309 F
Lockheed Missiles & Space Co (subs Lockheed Aircraft Corp)	8212290056*	CONTRACT		8212060259	50-309 P
Long Island Lighting Co	8211080125	50-322 E		8212100266	50-309 P
	8212010082	50-322 A		8212103324	50-309 P
	8212010087	50-322 E		8212140204	50-309 P
	8212010165	50-322 E		8212140435	50-309 F
	8212010371*	50-322 A		8212140442*	50-309 F
	8212010393*	50-322 A		8212140453*	50-309 F
	8212010397*	50-322 A		8212210165	50-309 S
	8212010401*	50-322 A		8212210170*	50-309 S
	8212020381	50-322 Q		8212210266*	50-309 Q
	8212070129	50-322 E		8212210308	50-309 F
	8212070219	50-322 A		8212220390*	50-309 Q
	8212140339	50-322 A		8212220396*	50-309 Q
	8212140463	50-322 Q		8212220456	50-309 S
	8212160065	50-322 S		8212230057*	50-309 F
	8212200111	50-322 Q		8212230068*	50-309 F
	8212210224	50-322 A		8212290116	50-309 R
	8212210338	50-322 A		8212290128*	50-309 R
	8212210406	50-322 E		8212290291	50-309 S
	8212210410*	50-322 E		8212290306*	50-309 S
	8212210414*	50-322 E	Malapal Resources Co	8212230121	40-8771
	8212230259	50-322 E	Management Analysis Co	8208290147*	COMMISSION
	8212270196	50-322 Q	Mapleton Intervenor	8212220197	50-327 Q
	8212270324	50-322 Q	Marsh & McLennan, Inc, M & M Nuclear Consultants, Inc Div	8212020269	50-259 J
	8212270380	50-322 E		8212020269	50-259 J
Los Alamos Scientific Laboratory	8109280383*	RES		8212020335	50-250 J
Louisiana County, VA	8212130157	50-537 A		8212280063	50-245 J
	8212100104	50-338 Q		8212280063	50-245 J
	8212140248	50-338 Q		8212280205	50-358 J
	8212140245	50-338 Q		8212280222	50-321 J
	8212140249	50-338 Q		8212280222	50-321 J
	8212140249	50-338 Q		8212280223	50-348 J
				8212280223	50-348 J

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8212280258	50-244 J		8212170278	50-416 P
	8212280261	50-259 J		8212170278	50-416 P
	8212280334	50-483 J		8212170313	50-416 S
	8212280348	50-348 J		8212170327*	50-416 S
	8212280348	50-348 J		8212170334	50-416 S
	8212280369	50-321 J		8212170339*	50-416 S
	8212280369	50-321 J		8212200103	50-416 H
	8212280441	50-293 J		8212200106*	50-416 H
	8212290150	50-327 J		8212210155	50-416 S
	8212290150	50-327 J		8212210179	50-416 S
	8212290213	50-315 J		8212210182*	50-416 S
	8212290246	50-259 J		8212210191	50-416 S
	8212300109	50-327 J		8212210192*	50-416 S
	8212300109	50-327 J		8212210203*	50-416 S
	8212300202	50-250 J		8212210212	50-416 S
	8212300202	50-250 J		8212210227*	50-416 S
	8212300243	50-250 J		8212210367	50-416 S
	8212300243	50-250 J		8212210371*	50-416 S
	8212300294	50-335 J		8212210375	50-416 S
	8212300300	50-438 J		8212230252	50-416 P
	8212300333	50-29 J		8212230252	50-416 P
Maryland, State of	821230081	NUREG		8212270147	50-416 P
Massachusetts Institute of Technology	8212040120*	CONTRACT		8212270153*	50-416 P
	8212280406	50-20 P		8212270154	50-416 P
	8212280411*	50-20 P		8212270154	50-416 P
Massachusetts, State of	8212070242	50-443 Q		8212270235	50-416 F
Norton, KY	8212070184	50-358 Q		8212270235	50-416 F
Metropolitan Edison Co	8212010192	50-289 Q		8212280056	50-416 S
	8212010200*	50-289 Q		8212280057*	50-416 S
	8212020364	50-289 Q		8212280080	50-416 S
	8212020377	50-289 Q		8212280081*	50-416 S
	8212060019*	50-320 P		8212280150	50-416 S
	8212070134	50-289 Q		8212280154*	50-416 S
	8212300246	50-289 Q		8212280177	50-416 S
	8212300250	50-289 Q		8212280183*	50-416 S
Miami Valley Power Project	8212020382	50-358 Q		8212280194	50-416 S
	8212280128	50-358 Q		8212280198*	50-416 S
Michigan, State of	8212070330*	50-155 Q		8212280241	50-416 S
Michigan, Univ of	8212040514	ACRS		8212280245*	50-416 S
Midland County, MI	8212010391*	CONTRACT		8212280308	50-416 S
Miles Laboratories, Inc	8212200016	PR		8212280311*	50-416 S
Minneapolis, MN	8212010398*	CONTRACT		8212280312	50-416 S
Minock, J	8212010191	50-341 Q		8212280314*	50-416 S
Mississippi Power & Light Co	8212140428	50-341 Q		8212280327	50-416 S
	8212010176	50-416 P		8212280336*	50-416 S
	8212020033	50-416 S		8212280344	50-416 S
	8212020037*	50-416 S		8212280352*	50-416 S
	8212020050	50-416 S		8212280377	50-416 S
	8212020058	50-416 S		8212280386	50-416 S
	8212020061*	50-416 S		8212280389*	50-416 S
	8212020065*	50-416 S		8212280402	50-416 S
	8212020138	50-416 S		8212280412*	50-416 S
	8212020144*	50-416 S		8212280458	50-416 S
	8212070274	50-416 P		8212280463*	50-416 S
	8212090074	50-416 S		8212280466	50-416 S
	8212090075*	50-416 S		8212280475*	50-416 S
	8212090078	50-416 S		8212300039	50-416 S
	8212090081*	50-416 S		8212300047*	50-416 S
	8212090110	50-416 S		8212300084	50-416 S
	8212090113*	50-416 S		8212300087*	50-416 S
	8212090131	50-416 S		8212300114	50-416 S
	8212090136*	50-416 S		8212300119*	50-416 S
	8212090151	50-416 S		8212300186	50-416 S
	8212090158*	50-416 S		8212300200*	50-416 S
	8212090159	50-416 S		8212300222	50-416 S
	8212090164*	50-416 S		8212300228*	50-416 S
	8212090177	50-416 S		8212280935	NUREG
	8212090184*	50-416 S	Mississippi, State of	8212080331	50-186 P
	8212090191	50-416 S	Missouri, Univ of, Columbia	8212270082	XPORTLIC
	8212090195*	50-416 S	Mitsubishi International Corp (subs of Mitsubishi Corp)	8212270086*	XPORTLIC
	8212090290*	50-416 Q		8212270102	XPORTLIC
	8212090303*	50-416 Q		8212010114	XPORTLIC
	8212090310*	50-416 Q	Mitsui & Co (U S A), Inc (Subs of Mitsui & Co , Ltd)	8212010120*	XPORTLIC
	8212090326	50-416 S		8212010127	XPORTLIC
	8212090344*	50-416 S		8212010133*	XPORTLIC
	8212100297	50-416 S		8212080221	XPORTLIC
	8212100306*	50-416 S		8212010072	XPORTLIC
	8212170137	50-416 S		8212020353	50-341 Q
	8212170146*	50-416 S		8212020251	PR
	8212170209	50-416 S		8212020318	50-247 Q
	8212170213*	50-416 S	MolyCorp, Inc		
	8212170222	50-416 S	Montrose County, MI		
	8212170227*	50-416 S	Montana, State of		
	8212170263	50-416 S	Morgan Associates		
	8212170277*	50-416 S		8212020318	50-247 Q
				8212060103	50-247 Q
				8212060103	50-247 Q

CORPORATE SOURCE INDEX

469

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8212080310	50-247 G		8212230346	50-443 G
	8212090087	50-247 G		8212230348	50-443 G
	8212140423	50-247 G		8212230348	50-443 G
	8212140439	50-247 G	New Jersey, State of	8212280543	NUREG
	8212140439	50-247 G	New Mexico, Univ of	8212010109	REG
	8212140446*	50-247 G			
	8212140446*	50-247 G	New York City Audubon Society	8212220246	50-247 G
	8212140289	50-247 G	New York Univ	8212040077	50-247 G
	8212140289	50-247 G		8212040077	50-247 G
	8212210320	50-247 G		8212040089*	50-247 G
				8212040089*	50-247 G
	8212210320	50-247 G			
	8212220271	50-247 G		8212040098	50-247 G
	8212220271	50-247 G	New York, State of	8212230261	50-247 G
	8212220398	50-247 G		8212290055	50-244 B
	8212230187	50-247 G	New York, State of, Energy Office	8212070246	50-247 G
			New York, NY	8212140242	50-247 G
	8212230187	50-247 G			
	8212280285	50-247 G		8212230235	50-247 G
	8212280285	50-247 G		8212230241	50-247 G
	8212300230	50-247 G		8212230241	50-247 G
Morris, IL	8212010430*	CONTRACT		8212230270	50-247 G
				8212230270	50-247 G
N H Newark Consulting Engineering Services	7907100669*	50-237 P			
	7907240319*	50-237 P	Niagara Mohawk Power Corp	8212230337	50-247 G
	7908080624*	50-237 P		8212020102	50-220 P
	7911150292*	50-237 P		8212020302	50-220 P
NCI Engineering, Inc	8005280561*	50-219 P		8212030050*	50-220 G
				8212030166	50-410 B
	8212010036*	50-206 P			
MUS Corp	8212090201*	50-440 G		8212040204	50-220 F
MUSAC, Inc	8212220034*	CONTRACT		8212090106	50-220 F
MUTICH (Nuclear Technology, Inc)	8212100303*	50-331 G		8212090194	50-220 P
	8212150072*	50-331 P		8212100207	50-410 A
	8212210327*	50-263 P		8212140029	50-220 R
	8212210330*	50-263 P		8212140031*	50-220 R
	8212210333*	50-263 P		8212140093	50-410 S
	8212210337*	50-263 P		8212140372	50-410 S
	8212210342*	50-263 P		8212140406*	50-220 G
	8212210346*	50-263 P		8212150213*	50-220 G
	8212270307*	50-237 G		8212170266	50-220 P
National Academy of Sciences	8212270313*	50-237 G		8212200023	PR
	8212100133*	CONTRACT		8212220479*	50-220 G
	8212270447*	CONTRACT		8212270265	50-220 P
National Council on Radiation Protection & Measurements	8212020166	PR		8212270353	50-220 P
National Wildlife Federation	8212070172	50-922 G		8212280363	50-410 B
	8212160267	50-922 G		8212290416	50-220 G
Natural Resources Defense Council	8212080257	50-937 G	Nisshe-Iwai American Corp	821290430*	50-220 G
	8212200021	70-143		8212160796	XPORTRIC
	8212220248*	70-143	North Carolina State Univ	8212070185	50-111
	8212230200	50-937 G	North Carolina, State of	8212160378	70-1113
	8212280270	70-143	North Carolina, Univ of	8212020383	PR
Navy, Dept of, Naval Facilities Eng Command	8212020118	PR	North Dakota, State of	8212270561	NUREG
Navy, Dept of				8212020291	PR
	8212230156	71-474			
Nebraska Public Power District	8212030159	50-298 P	Northeast Nuclear Energy Co (subs of Northeast Utilities)	8211080237	50-245
	8212030162*	50-298 P			
	8212070141*	50-298 G		8212030180	50-245 E
	8212070175	50-298 P		8212030189*	50-245 B
	8212070402	50-298 P		8212030201	50-336 S
				8212030204*	50-336 G
	8212070491*	50-298 P		8212030227	50-336 G
	8212100171	50-298 P		8212030234*	50-336 S
	8212100293	50-298 P		8212070124	50-245 F
	8212130342*	50-298 P		8212070286	50-245 P
	8212130346*	50-298 P		8212080414	50-336 G
	8212140472	71-9001		8212080415*	50-336 G
	8212160433	71-484		8212080445	50-245 B
	8212280397	50-298 P		8212080453*	50-245 G
	8212290312	50-298 R		8212080541	50-423 B
	8212290315*	50-298 R		8212090114	50-213 F
	8212300106	50-298 G		8212100071	50-245 G
	8212300111*	50-298 G		8212100277	50-245 P
Newton Products, Inc	8212230037	71-9096		8212140144	50-336 P
Nevada, State of	8212230209	WASTE MGT		8212140221*	50-245 G
	8212230212*	WASTE MGT		8212150128	50-245 P
New England Coalition on Nuclear Pollution	8212200039	50-443 G		8212150128	50-245 P
				8212150142*	50-245 P
	8212200039	50-443 G		8212150142*	50-245 P
	8212200049*	50-443 G		8212160216	PR
	8212200049*	50-443 G		8212160358	50-245 B
	8212100102	50-443 A			
New Hampshire, State of					
	8212140227	50-443 G		8212160371*	50-245 B
	8212140227	50-443 G		8212160470	50-423 B
	8212140234	50-443 G		8212170117	50-245 P
	8212140234	50-443 G		8212170199	50-245 P
	8212160281	50-443 G		8212170199	50-245 P
	8212230346	50-443 G		8212170279	50-245 P
				8212170321	50-245 P
				8212170322*	50-245 P
				8212210121	50-213 P

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Northeast Utilities	8212210121	50-213 P	Nuclear Packaging, Inc	8212150293	70-143
	8212210229	50-336 S		8212150298*	70-143
	8212210233*	50-336 S		8212160072	70-143
	8212210355	50-423 F		8212160420	70-143
	8212210579*	50-245 F		8212160429	70-143
	8212210581*	50-245 F		8212220527	70-143
	8212270152	50-245 P		8212270124*	70-143
	8212290139	50-336 R		8212270544	70-143
	8212290142*	50-336 R		8212270377	71-9079
	8212290224	50-245 R		8212270382*	71-9079
	8212290229*	50-245 R	Nuclear Sources & Services, Inc Oak Ridge National Laboratory	8212270408	71-9073
	8212290447	50-245 P		8212130222	71-394
	8211080257	50-245 P		8212010486	RES
	8212020200	TOPREP		8212060460	MUREQ
	8212020208*	TOPREP		8212060465	MUREQ
	8212030180	50-245 S		8212070435	50-250
	8212030201	50-336 S		8212130123	MUREQ
	8212030227	50-336 S		8212130135	MUREQ
	8212060157	50-213 P		8212140479	50-259
	8212060157	50-213 P		8212160549	RES
	8212070124	50-245 F		8212160558	RES
	8212070286	50-245 P		8212160564	RES
	8212080414	50-336 S		8212220013*	40-6500
	8212080445	50-245 S		8212220021	RES
	8212080453*	50-245 S		8212220060	RES
	8212080541	50-423 S	Oconee County, SC Office of Management & Budget	8212220519	RES
	8212100071	50-245 Q		8212270416	RES
	8212100277	50-245 P		8212270435	MUREQ
	8212140144	50-336 P		8212270441	MUREQ
	8212140221*	50-245 Q		8212270492	MUREQ
	8212150128	50-245 P		8212290512	RES
	8212150128	50-245 P		8212010434*	CONTRACT
	8212160216	PR		8212010212	ORQ
	8212160358	50-245 S		8212010219	ORQ
	8212160470	50-423 S		8212010241	ORQ
Northern California Power Agency, California State of, Northern States Power Co	8212170199	50-245 P	Ogle Petroleum, Inc	8212010247	ORQ
	8212170199	50-245 P		8212010253	ORQ
	8212170279	50-245 P		8212010256	ORQ
	8212170321	50-245 P		8212070461	40-0745
	8212170323*	50-245 P		8212070480	40-0745
	8212210121	50-213 P	Ohio Citizens for Responsible Energy	8212100083	40-0745
	8212210229	50-336 S		8212170404	40-0745
	8212210355	50-423 F		8212170407*	40-0745
	8212270152	50-245 P		8212060108	50-440 Q
	8212290139	50-336 R		8212070196	50-440 Q
	8212290188	TOPREP		8212070199	50-440 Q
	8212290224	50-245 R		8212070199	50-440 Q
	8212290447	50-245 P		8212070203	50-440 Q
	8212270502*	CONTRACT		8212070203	50-440 Q
	8212020311	50-282 S	Ohio State Univ	8212230267	50-440 Q
	8212020317*	50-282 S		8212230267	50-440 Q
	8212070391	50-263 P		8212230319	50-440 Q
	8212080420	50-282 S		8212230319	50-440 Q
	8212080429*	50-282 S		8212230345	50-440 Q
	8212090057	50-282 P		8212230345	50-440 Q
	8212090057	50-282 P		8212230368	50-440 Q
	8212090057*	50-282 P		8212230368	50-440 Q
	8212090057*	50-282 P		8212280324*	50-440 Q
	8212090172	50-282 P		8212280324*	50-440 Q
Northern Telecom Northrop Corp Northwest Energy Services Co Norton, Burke, Berry & French Nuclear Associates International Nuclear Energy Service, Inc Nuclear Fuel Services, Inc (subs of Getty Oil Co)	8212090172	50-282 P	Ohio State Univ	8212290031	50-440 A
	8212090382*	50-263 Q		8212010074*	50-150 F
	8212140244	50-263 F		8212010079*	50-150 F
	8212140279	50-282 F		8212060577*	CONTRACT
	8212140344	50-263 S		8212150252*	50-243 F
	8212140357*	50-263 S	Ohio, State of Oklahoma, Univ of	8212150257*	50-243 F
	8212170262	50-282 P		8212210435	50-440 Q
	8212210290	50-282 P		8212010066*	50-112 F
	8212210325	50-263 P		8212060230*	50-112 V
	8212280325	50-282 Q		8212060233*	50-112 V
	8212300416*	50-282 F	Omaha Public Power District	8212020093	50-285 P
	8212300417*	50-282 F		8212020117	50-285 P
	8212160524	PR		8212030009	50-285 Q
	8212080194	50-187 R		8212030013*	50-285 Q
	8212080200*	50-187 R		8212060028	50-285 P
	8210190729	50-522 S		8212060032*	50-285 P
	8212280123	50-275 Q		8212060035*	50-285 P
	8212080024*	CONTRACT		8212060254	50-285 P
	8212280061*	50-409 P		8212060266	50-285 Q
	8212080028*	FOIA		8212060268*	50-285 Q
	8212080032*	FOIA	Ogle Petroleum, Inc	8212060438	50-285 P
	8212090260	70-143		8212070150*	50-285 Q
	8212090469	70-143		8212070419	50-285 P
	8212130189	70-143		8212080380	50-285 F
				8212100244*	50-285 Q

CORPORATE SOURCE INDEX

471

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Orange County Alliance for Survival Oregon Environmental Council	8212130312	50-285 F		8212140135	50-387 S
	8212140416	50-285 P		8212140138*	50-387 S
	8212200059	50-285 R		8212140182	50-387 S
	8212200064*	50-285 R		8212140189*	50-387 S
	8212210022*	50-285 Q		8212140238	50-387 S
	8212210199	50-285 P		8212140261*	50-387 B
	8212230326*	50-285 P		8212140268	50-387 S
	8212280197	50-285 P		8212140323*	50-387 S
	8212290023	50-206 Q		8212140477*	50-387 P
	8212070172	50-522 Q		8212140497*	50-387 P
Oregon, State of Ossining, NY Pacific Gas & Electric Co	8212230073	NUREG		8212160317	50-387 P
	8212150013*	50-247 T		8212160417	50-387 P
	8212010190	50-275 P		8212160419*	50-387 P
	8212010190	50-275 P		8212170271	50-387 P
	8212030190	50-275 P		8212170272*	50-387 P
	8212030191	50-275 P		8212210052	50-387 S
	8212060047	50-275 R		8212210057*	50-387 S
	8212060053*	50-275 R		8212210236	50-387 S
	8212060078	50-323 S		8212210241*	50-387 S
	8212070235	50-275 P		8212210310	50-388 A
	8212080063*	50-275 F		8212210343	50-387 S
	8212080063*	50-275 F		8212210347*	50-387 S
	8212080071*	50-275 F		8212210450	50-387 S
	8212090004	50-275 Q		8212220403*	50-387 Q
	8212130070	50-275 F		8212270272	50-387 P
	8212140473	50-275 P		8212280323	50-388 S
	8212170217	50-275 R		8212280346	50-388 S
	8212170223*	50-275 R		8212280347	50-387 P
	8212210002	50-275 P		8212280400	50-387 S
	8212210005*	50-275 P		8212280400	50-387 S
	8212210014	50-275 P		8212280403	50-387 S
	8212210090	50-323 A		8212280417*	50-387 S
	8212210116	50-275 S		8212280446	50-387 P
	8212210123*	50-275 S		8212280465	50-387 S
	8212220217	50-275 P		8212280468*	50-387 S
	8212220225*	50-275 P		8212290115	50-387 R
	8212220229*	50-275 P		8212290117*	50-387 R
	8212230210	50-275 P		8212290441	50-387 S
	8212230298	50-275 P		8212290446*	50-387 S
	8212230298	50-275 P		8212300408*	50-387 F
	8212230304*	50-275 P	Pennsylvania State Univ Pennsylvania, State of	8212300410*	50-387 F
	8212230304*	50-275 P		8212030010	50-5 P
	8212270371	50-275 P		8212010186	50-289 Q
	8212280098	50-275 P		8212090502	50-289 Q
	8212280123	50-275 Q		8212160271	50-289 Q
	8212290182	50-133 R		8212160394	PR
	8212290186*	50-133 R		8212160459*	40-6500
	8212290214	50-275 R		8212070239	50-522 Q
	8212290218*	50-275 R		8212270225	50-522 Q
	8212290366	50-275 R		8210040239	50-352 K
Palmitto Alliance	8212290372*	50-275 R	Philadelphia Electric Co	8210040239	50-352 I
	8212280132	50-413 Q		8210040253*	50-352 I
	8212280132	50-413 Q		8210040267*	50-352 I
	8212280138	50-413 Q		8210040267*	50-352 I
	8212280138	50-413 Q		8210040272*	50-352 I
Parameter, Inc	8212010016*	FOIA		8210040272*	50-352 I
Parents Concerned About Indian Point	8212010021*	FOIA		8210040278*	50-352 I
	8212070189	50-247 Q		8210040278*	50-352 C
Pathfinder Mines Corp	8212150017	50-247 Q		8212020330	50-352 Q
	8212230155	40-2259		8212020330	50-352 Q
Pennsylvania Power & Light Co	8212230163*	40-2259		8212020339*	50-352 Q
	8212290132	40-6622		8212020339*	50-352 Q
	8212290136*	40-6622		8212020349	50-277 R
	8211090019	50-387 E		8212020349	50-277 R
	8212030041	50-387 S		8212020352*	50-277 R
	8212030047*	50-387 S		8212020352*	50-277 R
	8212030096*	50-387 Q		8212030122	50-352 A
	8212030173	50-387 S		8212030122	50-352 A
	8212030179*	50-387 S		8212030132*	50-352 A
	8212060066	50-387 P		8212030132*	50-352 A
	8212060066	50-387 P		8212030205	50-278 S
	8212060140	50-387 F		8212030208*	50-278 S
	8212080295	50-387 S		8212060096	50-277 P
	8212080303*	50-387 S		8212060096	50-277 P
	8212080320	50-387 S		8212060106*	50-277 P
	8212080328*	50-387 S		8212060106*	50-277 P
	8212080333	50-387 S		8212060109*	50-277 P
	8212080342*	50-387 S		8212060109*	50-277 P
	8212080362	50-387 S		8212070025	50-352 A
	8212080369	50-387 S		8212070025	50-352 A
	8212080372*	50-387 S		8212070138	50-352 F
	8212080378*	50-387 S		8212070138	50-352 F
	8212080382	50-387 S		8212080323*	50-277 Q
	8212080386*	50-387 S		8212080446	50-352 A
	8212090214	50-387 P		8212080446	50-352 A

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8212090119	50-277 F		8212100411*	50-344 I
	8212100036	50-277 F		8212140280	50-344 F
	8212100075	50-278 P		8212140346	50-344 L
	8212100079*	50-278 P		8212140349	50-344 F
	8212100090	50-352 F		8212140355*	50-344 G
	8212100274	50-352 C		8212210201	50-344 F
	8212130211	50-277 P		8212270368	50-344 P
	8212130341	50-352 K		8212280190	50-344 G
	8212140385	50-277 P		8212280283	50-344 P
	8212150058	50-277 P		8212280470	50-344 P
	8212150058	50-277 P		8212290201	50-344 H
	8212150061	50-277 S		8212290204*	50-344 R
	8212150062*	50-277 P	Power Authority of the State of New York	8212020318	50-247 Q
	8212150062*	50-277 P		8212020318	50-247 Q
	8212150187*	50-277 F		8212060091	50-333 G
	8212150187*	50-277 F		8212060101*	50-333 G
	8212150193*	50-277 F		8212060103	50-247 Q
	8212160055	50-277 R		8212060103	50-247 Q
	8212160055	50-277 R		8212060223	50-333 U
	8212160058*	50-277 R		8212060231*	50-333 G
	8212160058*	50-277 R		8212060292	50-333 G
	8212160415	50-277 G		8212060296*	50-247 Q
	8212170248	50-277 P		8212080310	50-247 Q
	8212170248	50-277 P		8212080310	50-247 Q
	8212170265	50-277 P		8212080374	50-333 G
	8212170265	50-277 P		8212080394	50-333 G
	8212170275*	50-277 P		8212080406*	50-333 G
	8212170275*	50-277 P		8212090087	50-247 Q
	8212170280*	50-277 P		8212090090	50-247 Q
	8212170280*	50-277 P		8212090090	50-247 Q
	8212170289	50-277 P		8212090205	50-247 P
	8212170289	50-277 P		8212100214	50-286 P
	8212170315	50-277 P		8212100288	50-286 P
	8212170315	50-277 P		8212130081	50-333 H
	8212210158	50-277 R		8212130084*	50-333 H
	8212210158	50-277 R		8212130232	50-247 P
	8212210162*	50-277 R		8212130232	50-247 P
	8212210162*	50-277 R		8212130330	50-286 P
	8212210312	50-277 P		8212130353*	50-286 I
	8212210312	50-277 P		8212130357*	50-286 I
	8212210398	50-352 F		8212140064	50-286 R
	8212210398	50-352 F		8212140070*	50-286 P
	8212210402	50-352 A		8212140236*	50-333 G
	8212210491	50-352 K		8212140294	50-333 I
	8212210491	50-352 K		8212140423	50-247 Q
	8212210495*	50-352 A		8212140423	50-247 Q
	8212210498*	50-352 C		8212140439	50-247 Q
	8212210498*	50-352 C		8212140439	50-247 Q
	8212210499*	50-352 K		8212140446*	50-247 Q
	8212210499*	50-352 K		8212140446*	50-247 Q
	8212230313	50-277 F		8212150126*	50-333 G
	8212230327	50-352 G		8212160289	50-247 Q
	8212230327	50-352 G		8212160289	50-247 Q
	8212270141	50-352 A		8212210246	50-333 G
	8212270141	50-352 A		8212210274*	50-333 G
	8212270144	50-352 F		8212210322	50-286 P
	8212270144	50-352 F		8212210323*	50-286 P
	8212270167	50-277 P		8212210415	50-333 G
	8212270216	50-352 Q		8212210428*	50-333 G
	8212270219	50-278 P		8212210426	50-286 I
	8212280185	50-352 G		8212220234	50-286 I
	8212280209	50-352 A		8212220271	50-247 Q
	8212280209	50-352 A		8212220271	50-247 Q
	8212280452	50-277 P		8212220398	50-247 Q
	8212290235	50-277 P		8212220452	50-333 F
	8212290276	50-352 R		8212230187	50-247 Q
	8212300187	50-352 Q		8212230187	50-247 Q
Philadelphia Inquirer	8208290112	70-143		8212270259	50-286 P
Planning Research Corp	8212140015*	FOIA		8212280285	50-247 Q
	8212140022*	FOIA		8212280285	50-247 Q
Plateau Resources, Ltd.	8211020241	40-8698		8212290156	50-286 R
	8211020252*	40-8698		8212290160*	50-286 R
	8212270319	40-8698		8212290175	50-333 P
	8212270340	40-8698		8212300230	50-247 Q
	8212300120	40-8698		8212270322	50-461 Q
Pollution & Environmental Problems, Inc	8212070411	50-295 P	Prairie Alliance	8212080103*	CONTRACT
Portland General Electric Co	8212030011	50-344 S	Press Intelligence, Inc	8212130364	CONTRACT
	8212030017*	50-344 S	Professional Reactor Operator Society	8212020134	PR
	8212030027	50-344 P	Project Associates	8212290273*	CONTRACT
	8212070316	50-344 P	Project Management Corp	8212060113	50-537 G
	8212070319*	50-344 P		8212090082	50-537 C
	8212070343	50-344 R		8212000015	50-537 C
	8212070346*	50-344 R		8212300011	50-537 C
	8212100044	50-344 P	Public Interest Research Group, New York	8212080880	50-289 F
	8212100406*	50-344 F		8212150022	50-247 C

CORPORATE SOURCE INDEX

473

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Public Service Co of Colorado	8212200011*	50-267 F	Public Service Electric & Gas Co of New Jersey	8212140235	50-443 A
	8212200030	50-267 F		8212140430	50-443 O
	8212200035*	50-267 F		8212140430	50-443 O
	8212200043	50-267 F		8212140437*	50-443 O
	8212200050	50-267 F		8212140437*	50-443 O
	8212200090*	50-267 Q		8212140441	50-443 O
	8212200092	50-267 Q		8212140441	50-443 O
	8212200094	50-267 R		8212210228	50-443 O
	8212200098*	50-267 F		8212210273	50-443 O
	8212200101*	50-267 Q		8212210273	50-443 O
	8212200116*	50-267 F		8212210287	50-443 B
	8212200117*	50-267 F		8212210287	50-443 B
	8212200123	50-267 G		8212210449	50-443 B
	8212200128*	50-267 B		8212210449	50-443 B
	8212210024*	50-267 Q		8212220255	50-443 O
	8212210102	50-267 R		8212270146	50-443 A
	8212210112*	50-267 R		8212270146	50-443 A
	8212210173*	50-267 Q		8212270188	50-443 A
	8212290297	50-267 S		8212270270	50-443 A
	8212290303*	50-267 G		8212270270	50-443 A
	8212290319	50-267 P		8212270279	50-443 A
	8212290328	50-267 F		8212270279	50-443 A
	8212290367	50-267 Q		8210210078	50-311 S
	8212290374	50-267 P		8210210095*	50-311 B
	8212290388	50-267 P		8212010148	50-272 P
	8212290391	50-267 R		8212010148	50-272 P
	8212290394*	50-267 R		8212010150*	50-272 P
	8212290403	50-267 P		8212010155	50-272 P
	8212290405*	50-267 P		8212030117	50-271 S
	8212290423	50-267 P		8212030153*	50-272 Q
	8212290426	50-267 G		8212060165	50-311 B
	8212290440*	50-267 G		8212060174*	50-311 B
Public Service Co of Indiana, Inc	8212080633*	50-546 F		8212060202	50-311 S
	8212080637*	50-546 F		8212060214*	50-311 S
	8212100181	50-546 B		8212060291	50-272 G
	8212170329	50-546 S		8212060298*	50-272 S
	8212280157	50-546 S		8212060302	50-272 S
	8212280157	50-546 S		8212060308*	50-272 S
	8212280272	50-546 G		8212060309	50-272 S
	8212280304	50-546 Q		8212060316*	50-272 G
	8212280304	50-546 Q		8212080356	50-272 G
	8212280321	50-546 Q		8212080364*	50-272 S
	8212280321	50-546 Q		8212080434	50-311 G
	8212280462	50-546 S		8212080443*	50-311 G
	8212280462	50-546 S		8212080502	50-354 G
	8212290112	50-546 F		8212130192	50-311 P
	8212020029	50-443 A		8212130212	50-272 F
	8212020029	50-443 A		8212140053	50-272 F
	8212020286	50-443 A		8212140060*	50-272
	8212020286	50-443 A		8212140076	50-272
	8212020316*	50-443 A		8212140079	50-311
	8212020316*	50-443 A		8212140082*	50-272
	8212020334	50-443 A		8212140085*	50-311
	8212020334	50-443 A		8212140099	50-311
	8212030194	50-443 A		8212140107*	50-311
	8212030194	50-443 A		8212140133*	50-272
	8212060056	50-443 A		8212160024	50-354
	8212060056	50-443 A		8212160024	50-354
	8212060059	50-443 E		8212160048	50-311 S
	8212060059	50-443 E		8212160054*	50-311 S
	8212060068	50-443 D		8212160381	50-311 S
	8212060068	50-443 D		8212160390*	50-311 S
	8212060075	50-443 A		8212160397	50-311 S
	8212060075	50-443 A		8212160414*	50-311 S
	8212060094	50-443 A		8212200020	50-272 Q
	8212060094	50-443 A		8212200020	50-272 Q
	8212060151	50-443 A		8212220020	50-272 Q
	8212060151	50-443 A		8212220030	50-272 G
	8212070100	50-443 A		82122200310*	50-272 I
	8212070100	50-443 A		82122200381	50-311 I
	8212080163	50-443 F		82122200385*	50-311 I
	8212080163	50-443 F		82122200395	50-311 S
	8212080190	50-443 A		82122200406*	50-311 S
	8212080190	50-443 A		82122200420	50-311 S
	8212080207	50-443 A		82122200424*	50-311 S
	8212080207	50-443 A		82122200433	50-311 S
	8212080207	50-443 A		82122200435*	50-311 S
	8212080224	50-443 A		82122200466	50-272 R
	8212080224	50-443 A		82122200467	50-272 R
	8212080329*	50-443 Q		82122200468*	50-272 R
	8212090498	50-443 A		82122200444*	50-354 Q
Public Service Co of New Hampshire	8212140212	50-443 Q		82122200466	50-272 R
	8212140212	50-443 Q		82122200467	50-272 R
	8212140217	50-443 Q		82122200468*	50-272 R
	8212140217	50-443 Q		82122200444*	50-354 Q
	8212140235	50-443 A			

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Puget Sound Power & Light Co	8212300306	50-272 F		8212070277	50-312 Q
	8212070239	50-522 G		8212070410	50-312 Q
	8212140419	50-522 A		8212130337	50-312 F
	8212270225	50-522 G		8212140351	50-312 P
	8212280289	50-522 G		8212140356	50-312 P
Purdue Univ	8208290032	ACRS		8212140363	50-312 P
	8212010428	ACRS		8212140391	50-312 P
	8212130238	50-182 P		8212140401	50-312 P
	8212130240	50-182 P		8212160009	71-489
Quadrex Corp	8212070278	50-416 P		8212170198	50-312 F
	8212170335	50-461 E		8212170220	50-312 P
R F Reedy, Inc	8212140447	50-275 R		8212170231	50-312 R
Racal Vikonics, Inc	8212270516	CONTRACT		8212170235	50-312 R
Radio Television News Directors Association	8212010119	FOIA		8212170255	50-312 P
Rado Watch Co, Inc	8212160518	PR		8212170301	50-312 Q
Ramsey Engineering Company	8212210501	71-488		8212170319	50-312 P
	8212210504	71-488		8212170320	50-312 P
Raytheon Corp	8212010109	RES		8212200026	50-312 Q
Reed, J O	8212210276	50-483 G		8212200042	50-312 R
Rio Algom, Ltd	8212030274	40-8084		8212200048	50-312 R
	8212030278	40-8084		8212210439	50-312 V
	8212230404	40-8084		8212220241	50-312 P
	8212230411	40-8084		8212270283	50-312 R
	8212270331	40-8084		8212270285	50-312 P
	8212270337	40-8084		8212270288	50-312 R
Robert Charles Moles & Associates	8212300132	CONTRACT		8212270291	50-312 R
Robert L Cloud Associates, Inc.	8212140276	50-275 P		8212280233	50-312 P
	8212140277	50-275 P		8212300353	50-312 Q
	8212150164	50-275 P	San Antonio City Public Service Board	8212170128	50-498
	8212150170	50-275 P	San Diego Gas & Electric Co	8212030168	50-361 P
	8212200080	50-275 P		8212170168	50-206 F
	8212200095	50-275 P		8212200046	PR
Rochester Gas & Electric Corp	8212020291	50-244 F	Sandia Laboratories	8212010469	RES
	8212040169	50-244 S		8212010475	RES
	8212040173	50-244 G		8212010481	RES
	8212070094	50-244 P		8212060486	NUREG
	8212070095	50-244 P		8212060492	50-313 P
	8212070098	50-244 P		8212100158	FOIA
	8212070282	50-244 P		8212130098	NUREG
	8212080384	50-244 P		8212130110	NUREG
	8212140240	50-244 F		8212130118	NUREG
	8212140404	50-244 P		8212130283	NUREG
	8212140408	50-244 P		8212150274	71-5939
	8212140413	50-244 P		8212220162	NUREG
	8212210456	50-244 P		8212220172	NUREG
	8212220243	50-244 P		8212220204	NUREG
	8212280388	50-244 P		8212220391	NUREG
	8212280391	50-244 P		8212220513	NUREG
	8212290163	50-244 R		8212270156	NUREG
	8212290166	50-244 R		8212270163	NUREG
Rockland County, NY	8212140451	50-247 G	Sargent & Lundy, Inc	8212020256	50-358 A
	8212230323	50-247 H		8212280489	50-461 Q
Rockwell International Corp	8212130138	71-6495	Saul, Ewing, Remick & Saul	8212060420	FOIA
	8212210110	50-375 W	Saunders-Roe Developments, Ltd	8212070476	XPORLIC
	8212280362	PT21		8212280172	XPORLIC
	8212280373	50-410 B			
Rocky Mountain Energy Co.	8212030284	40-8380	Science Applications, Inc	8207080445	50-285 P
	8212030295	40-8380		8208310315	50-331 P
	8212230182	40-8380		8209030322	50-255 P
Rossset, J M	8212170378	50-275 H		8209030343	50-213 P
				8211220096	50-3 P
Rogers Engineering Co, Inc	8212010115	NUREG		8212010427	50-309 P
	8212220341	NUREG		8212010469	RES
Rolf Jensen & Associates, Inc	8212270417	CONTRACT		8212020194	CONTRACT
Ropes & Gray	8212140212	50-443 G		8212060304	CONTRACT
	8212140212	50-443 G		8212070115	50-317 P
	8212140217	50-443 G		8212100162	CONTRACT
	8212140217	50-443 G		8212130058	NUREG
	8212140430	50-443 G		8212140260	50-27 P
	8212140430	50-443 G		8212270422	CONTRACT
	8212140437	50-443 G		8212270556	CONTRACT
	8212140441	50-443 G			
	8212140441	50-443 G	Seacoast Anti-Pollution League	8212020366	PR
	8212210228	50-443 G		8212140426	50-443 G
	8212220255	50-443 G		8212160321	50-443 P
	8212030062	50-312 S		8212230334	50-443 G
Sacramento Municipal Utility District			Seattle Times	8212010099	FOIA
	8212030081	50-312 S			
	8212030084	50-312 S	Senate	8212060511	40-86
	8212030095	50-312 S		8212100045	50-329 U
	8212030104	50-312 S		8212220558	COMMISSION
	8212030110	50-312 S		8212270431	50-3 H
	8212030116	50-312 S	Shannon & Wilson, Inc.	8212160608	CONTRACT
	8212060294	50-312 S			
	8212060300	50-312 S	Shaw, Pittman, Potts & Trowbridge	8212010192	50-289 G
	8212070220	50-312 G		8212010200	50-289 G
				8212010208	50-440 G
				8212010208	50-440 G
				8212010212	50-440 G

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8212010212	50-440 Q		8212170257	50-395 P
	8212020364	50-289 Q		8212170287	50-395 S
	8212070096*	COMMISSION		8212170291*	50-395 S
	8212070134	50-289 Q		8212200110	50-395 S
	8212070358	50-440 Q		8212200115*	50-395 S
	8212070358	50-440 Q		8212220328	50-395 S
	8212080293	50-440 Q		8212220337*	50-395 S
	8212100098	50-382 Q		8212220376	50-395 S
	8212100099	50-400 Q		8212220384*	50-395 S
	8212100100	50-382 Q		8212220411	50-395 S
	8212130241	50-440 Q		8212220414*	50-395 S
	8212130241	50-440 Q		8212220428	50-395 S
	8212140445	50-440 Q		8212220462*	50-395 S
	8212140470	40-2061		8212220498	50-395 S
	8212160247	50-440 Q		8212220500*	50-395 S
	8212160247	50-440 Q		8212230288	50-395 P
	8212160251	50-440 Q		8212230294*	50-395 P
	8212160251	50-440 Q		8212300035	50-395 Q
	8212700026	50-312 Q		8212300042*	50-395 Q
	8212200061	50-440 Q	South Carolina, State of	8212090481*	State Proj
	8212200105	50-440 Q	Southern California Edison Co	8005050726*	50-206 P
	8212210222	50-400 Q		8110190952*	50-206 P
	8212210321	50-440 Q		8212010171	50-361 P
	8212210345	50-440 Q		8212020250	50-206 P
	8212230339	50-440 Q		8212020253	50-206 P
	8212230357	50-266 Q		8212020373	50-361 P
	8212230357	50-266 Q		8212020373	50-361 P
	8212230359*	50-266 Q		8212030157	50-361 P
	8212230359*	50-266 Q		8212030168*	50-361 P
	8212270222	50-400 Q		8212030250*	50-361 P
	8212270330	50-382 Q		8212060012	50-362 S
	8212280182	50-382 Q		8212060239	50-206 P
	8212300013	50-440 Q		8212060269	50-206 P
	8212300226	50-483 Q		8212070190	50-361 P
	8212300250	50-289 Q		8212070193*	50-361 P
Bieria Club	8212080257	50-537 Q		8212070225	50-361 S
	8212100371	FOIA		8212070231*	50-361 S
	8212230200	50-537 Q		8212070252	50-361 S
Bigma Chemical Co	8212070417	EXPORTLIC		8212070259*	50-361 S
Bincclair, M	8212280191	50-358 Q		8212070266	50-206 P
Mississippi Alliance for the Environment (SAFE)	8212080235	50-454 Q		8212070281	50-361 S
	8212080245*	50-454 Q		8212070283	50-361 S
Small Business Administration	8212070453*	CONTRACT		8212070287*	50-361 S
	8212080583*	CONTRACT		8212070290	50-361 S
	8212220027*	CONTRACT		8212070293*	50-361 S
	8212270501*	50-537 A		8212070294*	50-361 S
Enril & Wilmer	8212060095	50-528 Q		8212070324	50-361 S
South Carolina Electric & Gas Co	8212020340	50-395 F		8212070329*	50-361 S
	8212030060	50-395 S		8212070330	50-361 S
	8212030064*	50-395 S		8212070360*	50-361 S
	8212030089	50-395 S		8212070369	50-361 S
	8212030100	50-395 S		8212070374*	50-361 S
	8212030133	50-395 S		8212070379	50-361 S
	8212030139*	50-395 S		8212070383	50-361 S
	8212030164	50-395 S		8212070388*	50-361 S
	8212030171*	50-395 S		8212070399*	50-361 S
	8212030186	50-395 S		8212070406	50-361 S
	8212030188	50-395 S		8212070412*	50-361 S
	8212030199*	50-395 S		8212090103	50-206 P
	8212030202*	50-395 S		8212090176	50-361 P
	8212070026*	50-395 Q		8212090179	50-361 P
	8212070128	50-395 F		8212090376	50-361 P
	8212070181	50-395 P		8212090514	50-361 P
	8212090243	50-395 S		8212090514	50-361 P
	8212090253*	50-395 S		8212130039	50-362 J
	8212090366	50-395 S		8212130188	50-362 P
	8212090372*	50-395 S		8212130193*	50-362 P
	8212090392	50-395 Q		8212130198*	50-362 P
	8212090422	50-395 S		8212130333*	50-206 Q
	8212090438*	50-395 S		8212140035	50-361 S
	8212090449	50-395 S		8212140035	50-361 S
	8212090460*	50-395 S		8212140151	50-206 F
	8212090516*	50-395 Q		8212140265	50-361 S
	8212100292	50-395 F		8212140270*	50-361 S
	8212150077	50-395 S		8212140272*	50-361 S
	8212150081*	50-395 S		8212140360	50-206 S
	8212150089	50-395 S		8212140368*	50-206 S
	8212150091*	50-395 S		8212140398	50-361 S
	8212150097	50-395 S		8212140405*	50-361 S
	8212150100*	50-395 S		8212170158	50-206 P
	8212150117	50-395 S		8212170164	50-206 F
	8212150122*	50-395 S		8212170168*	50-206 F
	8212160322	50-395 F		8212170208	50-361 F
	8212160329*	50-395 F		8212170384*	50-206 Q

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8212170384*	50-206 Q		8212080479	50-275 P
	8212170384*	50-206 Q		8212100206	50-275 P
	8212170384*	50-206 Q		8212100291	50-275 P
	8212200028	50-206 P		8212140278	50-275 P
	8212200063	50-206 P		8212140281	50-275 R
	8212210001	50-206 P		8212140285*	50-275 R
	8212220198	50-206 P		8212230306	50-275 P
	8212230260	50-361 P		8212270218*	50-271 P
	8212230260	50-361 P		8212270299*	50-275 P
	8212230291	50-361 P		8212270301*	50-275 P
	8212230291	50-361 P		8212270310*	50-275 P
	8212230325	50-361 P		8212270312*	50-275 P
	8212230349	50-361 P		8212290146	50-275 R
	8212270171	50-206 J		8212290152*	50-275 R
	8212290038*	50-206 Q		8212290205	50-275 P
	8212290102	50-206 R		8212290237*	50-275 P
	8212290106*	50-206 R		8212290243*	50-275 P
	8212290159	50-327 R		8212290290*	50-275 P
	8212290176	50-361 R		8212290452*	50-245 P
	8212290181*	50-361 R	Teledyne Wah Chang Albany	8212300178	XPORTRIC
Southwest Research Institute	8212290413	50-361 S	Tennessee Valley Authority	8212020107	50-438 S
Spencer Chemical Co	8212150134*	50-389 A		8212020107	50-438 S
Spiegel & McDiarmid	8212170094*	50-277 P		8212020116	50-296 S
	8212280026*	70-146		8212020124*	50-296 S
	8212270502*	CONTRACT		8212020137	50-438 S
Stamiris, B	8212020343	50-329 Q		8212020137	50-438 S
	8212020343	50-329 Q		8212020139	50-438 S
	8212020345	50-329 Q		8212020139	50-438 S
	8212020345	50-329 Q		8212020143	50-260 S
	8212100095	50-329 Q		8212020149	50-438 S
Standardized Nuclear Unit Power Plant System	8212170288	50-482 A		8212020149	50-438 S
	8212170288	50-482 A		8212020153*	50-260 S
	8212170288	50-482 A		8212020162	50-438 S
	8212170293*	50-482 A		8212020162	50-438 S
	8212170293*	50-482 A		8212020179	50-328 S
	8212170293*	50-482 A		8212020191*	50-328 S
	8212280236	50-482 A		8212020240	50-296 S
	8212280236	50-482 A		8212020244*	50-296 S
	8212280236	50-482 A		8212020261	50-296 S
	8212280240*	50-482 A		8212020264*	50-296 S
	8212280240*	50-482 A		8212020298	50-390 S
	8212280240*	50-482 A		8212020298	50-390 S
State Dept. of, Bureau of Oceans & Internatl Environ & Scientific Affairs	8212230432	XPORTRIC		8212020348	50-259 S
Stevenson & Associates	8212060458	NUREQ		8212020354*	50-259 S
	8212270221	NUREQ		8212020368	50-390 S
Stone & Webster Engineering Corp	8212010225*	50-275 R		8212020368	50-390 S
	8212020242	PR		8212030001	50-390 S
	8212150195	50-275 P		8212030001	50-390 S
	8212150200*	50-275 P		8212030001	50-390 S
	8212200045	PR		8212030001	50-390 S
	8212270296	50-275 P		8212030001	50-390 S
	8212270299*	50-275 P		8212030039	50-259 S
	8212270301*	50-275 P		8212030044*	50-259 S
	8212270310*	50-275 P		8212030071	50-259 R
	8212270312*	50-275 P		8212030071	50-259 R
	8212270384*	50-322 E		8212030071	50-259 R
	8212280160	50-275 F		8212030071	50-259 R
	8212280163*	50-275 F		8212030071	50-259 R
	8212290209*	50-275 P		8212030072	50-438 S
	8212290231	50-275 P		8212030072	50-438 S
	8212290237*	50-275 P		8212030086	50-327 S
	8212290243*	50-275 P		8212030092*	50-327 S
	8212290250*	50-275 P		8212030152	50-438 S
Stone & Webster, Inc	8211080129*	50-322 E		8212030152	50-438 S
	8212290458	50-275 P		8212030220*	50-259 S
	8212290462*	50-275 P		8212060023	50-327 P
Structural Mechanics Associates	8210190510*	50-247 F		8212060023	50-327 P
Stafford County, NY	8212030025*	50-155 Q		8212060061	50-327 P
	8212140463	50-322 Q		8212060070	50-390 E
	8212270227	50-322 T		8212060070	50-390 E
Sunflower Alliance	8212090495	50-440 Q		8212060076	50-327 P
TERA Corp	8212280319	50-440 Q		8212060076	50-327 P
TRW, Inc.	7907180391*	50-409 P		8212060081	50-390 A
	8212020404*	CONTRACT		8212060081	50-390 A
	8212080027*	FOIA		8212070058	50-390 S
	8212080030*	FOIA		8212070058	50-390 S
	8212080044*	FOIA		8212070142	50-390 S
	8212080065*	FOIA		8212070142	50-390 S
	8212080070*	FOIA		8212070176	50-327 P
	8212080081*	FOIA		8212070180	50-327 F
Talley Industries, Inc	8212160338	PR		8212070186	50-390 A
Teledyne Engineering Services	8212010206	50-275 R		8212070186	50-390 A
	8212010211*	50-275 R		8212070267	50-390 S

477

[illegible]

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8212220463	50-260 S
	8212220472*	50-260 S
	8212220485	50-390 S
	8212220485	50-390 S
	8212270192	50-259 P
	8212270262	50-390 A
	8212270262	50-390 A
	8212270287	50-390 A
	8212270287	50-390 A
	8212270355	50-390 A
	8212270355	50-390 A
	8212280054	50-438 S
	8212280054	50-438 S
	8212280085	50-259 P
	8212280085	50-259 P
	8212280085	50-259 P
	8212280085*	50-259 P
	8212280085*	50-259 P
	8212280085*	50-259 P
	8212280099	50-260 S
	8212280100	50-438 S
	8212280100	50-438 S
	8212280104*	50-260 S
	8212280111	50-327 S
	8212280114*	50-327 S
	8212280133	50-328 S
	8212280136*	50-328 S
	8212280147	50-259 S
	8212280153*	50-259 S
	8212280210	50-438 S
	8212280210	50-438 S
	8212280295	50-259 P
	8212280295	50-259 P
	8212280295*	50-259 P
	8212280297*	50-259 P
	8212280305	50-438 S
	8212280305	50-438 S
	8212280328	50-438 S
	8212280328	50-438 S
	8212280340	50-438 S
	8212280340	50-438 S
	8212280355	50-390 S
	8212280358	50-438 S
	8212280358	50-438 S
	8212280437	50-438 K
	8212290144*	50-327 R
	8212290281	50-259 R
	8212290287*	50-259 R
	8212290287*	50-259 R
	8212290287*	50-259 R
	8212290356	50-327 P
	8212290356	50-327 P
	8212300006	50-438 S
	8212300293	50-327 P
	8212300351	50-327 P
	8212300351	50-327 P
	8212300355*	50-327 P
	8212300355*	50-327 P
	8212300357	50-327 P
	8212300357	50-327 P
	8212300357*	50-327 P
	8212300359*	50-327 P
	8212300359*	50-327 P
	8212090393*	70-143
	8212020338*	50-443 A
	8212100299	50-128 S
Tennessee, State of	8212270024	70-33
Tennessee Univ. of	8212270030*	70-33
Texas A&M Univ., College Station, TX	8212140298	50-445 F
	8212140409	50-445 Q
	8212140409	50-445 Q
Texas Instruments, Inc.	8212150166	50-445 K
	8212150166	50-445 K
	8212150171*	50-445 K
	8212150171*	50-445 K
	8212150428	50-445 A
Texas Utilities Generating Co	8212170337	50-445 E
	8212170342*	50-445 E
	8212210391	50-445 K
	8212210391*	50-445 K
	8212210394*	50-445 K
	8212270317	50-445 Q
	8212270317	50-445 Q
	8212270320*	50-445 Q
	8212270332	50-445 Q

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8212270332	50-445 S
	8212280267	50-445 S
	8212280273	50-445 S
	8212280329	50-445 S
	8212070403	50-445 F
Texas Utilities Services, Inc	8212130301	50-445 H
	8212020205	50-346 F
	8212020270	50-346 F
	8212060158	50-346 F
	8212070292	50-346 F
Toledo Edison Co	8212100040	50-346 P
	8212100229	50-346 S
	8212100231	50-346 S
	8212100235*	50-346 S
	8212100281	50-346 S
	8212100287*	50-346 S
	8212100325	50-346 S
	8212100332*	50-346 S
	8212130088	50-346 P
	8212130090	50-346 P
	8212130137*	50-346 F
	8212130144*	50-346 F
	8212150310*	50-346 F
	8212160098*	50-346 F
	8212160107*	50-346 F
	8212170178	50-346 S
	8212170187*	50-346 S
	8212170282	50-346 S
	8212170285*	50-346 S
	8212210081	50-346 P
	8212210092	50-346 P
	8212210368*	50-346 Q
	8212220273	50-346 F
	8212220302*	50-346 F
	8212220308*	50-346 F
	8212270205	50-346 P
	8212270210	50-346 A
	8212280075	50-346 S
	8212280077*	50-346 S
	8212280234	50-346 S
	8212280237*	50-346 S
	8212280247	50-346 S
	8212280250*	50-346 S
	8212280281	50-346 S
	8212280290*	50-346 S
	8212290226	50-346 Q
	8212290307	50-346 R
	8212290309*	50-346 R
	8212290455*	50-346 Q
Toledo, Univ. of	8212010363*	CONTRACT
Torrey Pines Technology	8211290142*	50-528 A
	8211290148*	50-528 A
	8211290148*	50-528 A
	8211290148*	50-528 A
	8211290150*	50-528 A
	8211290150*	50-528 A
	8211290150*	50-528 A
	8211290155*	50-528 A
	8211290155*	50-528 A
	8211290155*	50-528 A
	8212270281*	50-443 A
	8212270286*	50-443 A
Transco, Inc	8212070489	XPORLTC
Transnuclear, Inc	8212070503*	XPORLTC
	8212080020*	XPORLTC
	8212080039	XPORLTC
	8212080035	XPORLTC
	8212230402	XPORLTC
	8212230406	XPORLTC
	8212230410*	XPORLTC
	8212270069	71-9015
	8212270071*	71-9015 G
	8212080291	50-268
	8212280134*	50-155
	8212010476	27-39
Two Rivers, WI	8212010477*	27-39
URS Corp	8212290010	27-48
US Ecology, Inc (Formerly Nuclear Engineering)	8212210558	40-8564
	8212010478	RES
	8212020477	PRM
Union 76 Minerals Exploration Co	8212020288*	PRM P
Union Carbide Corp	8212030158	50-54
	8212060513	40-299 P
	8212070173	50-54

CORPORATE SOURCE INDEX

479

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	0212070173	50-54 P		0212090112	50-338 S
	0212070182*	50-54 P		0212090115*	50-338 S
	0212160245	70-687		0212090130	50-281 S
	0212230186	40-299		0212090134*	50-281 S
	0212270074	40-299		0212090137*	50-281 S
	0212270083*	40-299		0212090144*	50-281 S
Union Electric Co	0212020259	50-483 S		0212090169*	50-280 Q
	0212080256	50-483 F		0212090175*	50-280 Q
Union of Concerned Scientists	0212300226	50-483 G		0212090217*	50-280 Q
	0212020363	PR		0212090218*	50-280 Q
	0212060077	50-247 G		0212090220*	50-280 Q
	0212060077	50-247 G		0212090272	50-339 S
	0212060089*	50-247 G		0212090286*	50-280 Q
	0212060089*	50-247 G		0212090287*	50-339 S
	0212060098	50-247 G			
	0212090101	50-247 G		0212090305	50-404 Q
	0212140384	50-247 G		0212090419	50-280 S
	0212140384	50-247 G		0212090485*	50-338 Q
	0212140393*	50-247 G		0212090527	50-338 S
	0212140393*	50-247 G		0212090538*	50-338 S
	0212140400*	50-247 G			
	0212140400*	50-247 G		0212130319	50-338 P
	0212150022	50-247 Q		0212130326	50-338 P
	0212200032	50-247 G		0212130327	50-281 P
	0212210238	50-247 Q		0212150028	50-338 S
				0212150034*	50-338 S
	0212210272	50-289 G		0212150048	50-338 P
	0212210336	50-289 G		0212150048	50-338 P
	0212210339*	50-289 G		0212150052*	50-338 P
	0212270414	FOIA		0212150052*	50-338 P
	0212300002	50-289 G		0212150059	50-280 F
	0212300008	50-289 G		0212150059	50-280 F
	0212300242	50-289 G		0212150059	50-280 F
	0212300362	50-289 G		0212150059	50-280 F
Unitec Co (subs of Ecodyne Corp)	0212160530	PR		0212150067	50-281 S
United Engineers & Constructors, Inc	0212010224	PT21		0212150087*	50-281 S
(subs of Raytheon Co)					
	0212070295	50-324 S		0212150094	50-338 S
United Kingdom	0212270066	50-244 S		0212150096*	50-338 S
United Nuclear Corp	0212080042	40-8781		0212170041*	50-280 F
	0212150266	70-371		0212170041*	50-280 F
	0212270256*	70-820			
				0212170457*	50-280 F
	0212270541	70-371		0212170458*	50-280 F
Uranerz USA, Inc	0212270264	40-8783		0212170458*	50-280 F
	0212280435	40-8783		0212200027	50-338 S
	0212280439*	40-8783			
Uranium Resources, Inc	0212030261	40-8786		0212200037*	50-338 S
				0212210137	50-338 S
	0212030263*	40-8786		0212210147*	50-338 S
Utah, State of	0212160394	PR		0212210163	50-338 S
Vanderbilt Univ	0212300192*	CONTRACT		0212210171*	50-338 S
Vermont Yankee Nuclear Power Corp	0212090374	50-271 P			
	0212100310	50-271 P		0212210187	50-338 P
				0212210187	50-338 P
	0212140379	50-271 P		0212210234	50-339 S
	0212140448*	50-271 P		0212210269*	50-339 S
	0212150174	50-271 R		0212210365	50-280 S
	0212150176*	50-271 R			
	0212210138	50-271 P		0212210365	50-280 S
				0212210383*	50-280 S
	0212270212	50-271 P		0212210388*	50-280 S
	0212270378	50-271 S		0212210397*	50-280 S
	0212270384*	50-271 G		0212220244	50-338 S
Virginia Electric & Power Co	0212020090	50-280 S			
	0212020096*	50-280 S		0212220268*	50-338 S
				0212220364	50-339 S
	0212060124	50-280 P		0212220368*	50-339 S
	0212060124	50-280 P		0212220387	50-339 S
	0212060124	50-280 P		0212220391*	50-339 S
	0212060124	50-280 P			
	0212060284	50-280 P		0212220392	50-339 S
	0212060284	50-280 P		0212220397*	50-339 S
	0212060284	50-280 P		0212220399*	50-338 S
	0212060284	50-280 P		0212220408*	50-338 S
	0212060284	50-280 P		0212220410	50-338 S
	0212060303	50-280 P		0212220416*	50-338 S
	0212060303	50-280 P		0212270179	50-280 F
	0212060315*	50-280 P		0212270179	50-280 F
	0212060315*	50-280 P		0212280073	50-281 P
	0212090063	50-338 S		0212280122	50-338 Q
	0212090064*	50-338 S		0212280122	50-338 S
	0212090067	50-339 S		0212280126	50-280 S
	0212090072*	50-339 S		0212280126	50-280 S
	0212090086	50-280 S		0212280130*	50-338 Q
	0212090086	50-280 S		0212280130*	50-338 Q
	0212090091*	50-280 S		0212280135	50-338 Q
	0212090098*	50-280 S		0212280135	50-338 S
	0212090102	50-339 S		0212280140*	50-280 S
	0212090107*	50-339 S		0212280152*	50-280 S
				0212280201	50-338 P

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8212280201	50-338 P		8212130033	50-508 K
	8212280206*	50-280 S		8212130036*	50-508 K
	8212280257	50-280 P		8212140194	50-508 C
	8212280257	50-280 P		8212140201*	50-508 C
	8212280257	50-280 P		8212150021	50-508 A
	8212280257	50-280 P		8212150029	50-508 A
	8212280259	50-337 P		8212160003	50-395 F
	8212280349	50-280 P		8212170100*	50-397 Q
	8212280349	50-280 P		8212170138	50-397 E
	8212290069*	50-280 S		8212170173	50-397 A
	8212290075*	50-280 S		8212170175	50-397 A
	8212290080*	50-280 S		8212170314	50-397 H
	8212290085*	50-280 S		8212170314	50-397 H
	8212290172*	50-280 Q		8212170374	50-397 A
	8212290191	50-280 P		8212170379*	50-397 A
	8212290191	50-280 P		8212200003	PR
	8212290238	50-280 R		8212200036	PR
	8212290244*	50-280 R		8212200047	50-397 A
	8212290244*	50-280 R		8212200073	PR
	8212290248	50-338 P		8212200074	50-397 A
	8212290248	50-338 P		8212200083	50-397 E
	8212290252*	50-338 P		8212210251	50-460 S
	8212290252*	50-338 P		8212210386	50-397 S
	8212290255*	50-338 P		8212230208	50-508 A
	8212290255*	50-338 P		8212230314	50-397 Q
	8212290256*	50-338 P		8212270159	50-397 A
	8212290256*	50-338 P		8212270326	50-397 Q
	8212290261	50-280 Q		8212270329	50-460 Q
	8212290264*	50-280 Q		8212280121	50-508 Q
	8212290317	50-338 R		8212280277	50-397 Q
	8212290318*	50-338 R		8212280277	50-397 Q
	8212290459	50-280 Q		8212280294	50-460 Q
	8212290474*	50-280 Q		8212280428	50-460 S
	8212300079	50-337 S		8212280440	50-460 A
	8212300104*	50-337 S		8212280443	50-397 Q
	8212300126	50-338 S		8212290180	50-397 K
	8212300130*	50-338 S		8212290185*	50-397 K
	8212300171	50-338 S		8212290241	50-397 A
	8212300177*	50-338 S		8212300073*	50-508 Q
	8212300217	50-338 S		8212300274*	50-508 Q
	8212300220*	50-338 S		8212300274*	50-508 Q
	8212300232	50-338 S		8212300318*	50-397 Q
	8212300237	50-337 S		8212300324*	50-508 Q
	8212300238*	50-338 S		8212230162	27-48
	8212300241*	50-337 S		8212280538	27-48
	8212300245	50-338 S	Washington, State of	8212280541	27-47
	8212300247*	50-338 S	Waste Management, Inc	8212290005	27-47
	8212300291	50-339 S	West Branch Conservation Association	8212070209	50-247 Q
	8212300255*	50-339 S		8212070209	50-247 Q
	8212300261	50-338 S		8212070213	50-247 Q
	8212300267*	50-338 S		8212070213	50-247 Q
	8212300286	50-337 S		8212220293	50-247 Q
	8212300291*	50-339 S		8212300191	50-247 Q
	8212300313	50-338 S		8212300191	50-247 Q
	8212300315*	50-338 S		8212300197	50-247 Q
Virginia Polytechnic Institute	8212280211	50-124 P		8212300197	50-247 Q
	8212280213*	50-124 P		8212300201*	50-247 Q
	8212280216*	50-124 P		8212300201*	50-247 Q
	8212280217*	50-124 P		8212300201*	50-247 Q
Vitro Engineering Co	8212160094*	FOIA	West Chicago, IL	8212130167	40-2061
	8212160168*	40-6500		8212270469	40-2061
	8212160264*	40-6500		8212270478	40-2061
	8212160315*	40-6500	West Virginia Univ	8212030118	50-129 P
	8212160323*	FOIA	Westchester County, NY	8212130254*	50-247 Q
	8212160350*	40-3265		8212150008	50-247 T
	8212160380*	FOIA		8212150008	50-247 T
	8212160391*	FOIA		8212150013*	50-247 T
	8212160435*	40-6500		8212150013*	50-247 T
	8212160500*	FOIA		8212220220	50-247 Q
	8212160510*	40-2116		8212220220	50-247 Q
	8212160525*	40-2116		8212220226*	50-247 Q
	8212160541*	FOIA		8212220226*	50-247 Q
	8212160582*	FOIA	Western Nuclear, Inc (subs of Phelps Dodge Corp)	8212230233	50-247 Q
Wall Street Journal	8212060450	FOIA		8212020154	PR
Washington Management Group, Inc	8212060433	FOIA		8212130105	40-1162
Washington Public Power Supply System	8210270013	50-397 A	Westinghouse Electric Corp	8210210467	TQPREP
	8210270016*	50-397 A		8210210475*	TQPREP
	8210270018*	50-397 A		8210210484*	TQPREP
	8212030107	50-397 Q		8210210489*	TQPREP
	8212060021	50-397 Q		8212010154	PT21
	8212060179	50-397 S		8212010440	FOIA
	8212060289	50-397 S		8212020267	TQPREP
	8212070131	50-508 F		8212020271*	TQPREP
	8212100256	50-397 F		8212060245*	50-347 P
	8212100256	50-397 F		8212060276*	50-206 P

CORPORATE SOURCE INDEX

481

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Williams-Robinette & Associates, Inc Witt, D D Wisconsin Electric Power Co	8212070187*	50-454 A	Wisconsin's Environmental Decade	8212210181	50-305 P
	8212130262	TOPREP		8212270007*	50-305 F
	8212130296	TOPREP		8212270010*	50-305 F
	8212130302*	TOPREP		8212270197	50-305 P
	8212140267	50-413 A		8212270203*	50-305 P
	8212140267	50-413 A		8212280193	50-305 P
	8212140312*	50-413 A		8212280230	50-305 F
	8212140312*	50-413 A		8212280318	50-305 P
	8212140318*	50-413 A		8212280467	50-305 P
	8212140420*	50-244 P		8212280473*	50-305 P
Williams-Robinette & Associates, Inc Witt, D D Wisconsin Electric Power Co	8212150055	TOPREP	Wisconsin, Univ of, Madison Woliver, J D Woodward-Clyde Consultants, Inc	8212290211	50-305 R
	8212150238	70-1151		8212290216*	50-305 R
	8212150244*	70-1151		8212270316	50-266 Q
	8212150262	70-1143		8212270316	50-266 Q
	8212150340	70-1151		8212270323	50-266 Q
	8212160346*	50-334 P		8212270323	50-266 Q
	8212160365	TOPREP		8212140195	50-156 B
	8212200040	TOPREP		8212140205	50-358 Q
	8212200062*	TOPREP		790604028*	50-237 P
	8212220124	70-1143		8004010318*	50-237 P
Williams-Robinette & Associates, Inc Witt, D D Wisconsin Electric Power Co	8212220134*	70-1143	Wyle Laboratories Wyle Co Wyoming, State of	8211020246*	40-8698
	8212220182	TOPREP		8212270290*	50-390 A
	8212270077	XPORTLIC		8212170311*	50-331 P
	8212270079*	XPORTLIC		8212010083	PT21
	8212270263*	50-286 P		8212030306	40-8200
	8212270266*	50-286 P		8212060456	40-8064
	8212280149	XPORTLIC		8212070456	40-8504
	8212130160*	CONTRACT		8212170438	40-8348
	8212280319	50-440 Q		8212230079	40-6622
	8212020276	50-266 B		8212230170	40-4492
Williams-Robinette & Associates, Inc Witt, D D Wisconsin Electric Power Co	8212020281*	50-266 S	Xerox Corp Yakima Indian Nation	8212300129	40-6622
	8212070099	50-266 F		8212100358	FOIA
	8212100202	50-266 S		8212140333	50-522 Q
	8212100208	50-301 S		8212140333	50-522 Q
	8212100211*	50-301 S		8212140345	50-522 Q
	8212100222*	50-266 Q		8212140345	50-522 Q
	8212100223*	50-266 Q		8212140354	50-522 Q
	8212100224	50-266 S		8212140354	50-522 Q
	8212100225*	50-266 S		8212140386	50-522 Q
	8212170161	50-266 S		8212140386	50-522 Q
Williams-Robinette & Associates, Inc Witt, D D Wisconsin Electric Power Co	8212170172*	50-266 S	Yankee Atomic Electric Co	8212140455	50-522 Q
	8212170326	50-266 P		8212140455	50-522 Q
	8212170326	50-266 P		8212020029	50-443 A
	8212210056	50-266 P		8212020029	50-443 A
	8212210056	50-266 P		8212020286	50-443 A
	8212210297	50-266 R		8212020286	50-443 A
	8212210297	50-266 R		8212020300	50-29 P
	8212210297*	50-266 R		8212020304*	50-29 F
	8212220422	50-266 P		8212020316*	50-443 A
	8212220422	50-266 P		8212020316*	50-443 A
Williams-Robinette & Associates, Inc Witt, D D Wisconsin Electric Power Co	8212220427*	50-266 P	Yankee Atomic Electric Co	8212020334	50-443 A
	8212220427*	50-266 P		8212020334	50-443 A
	8212230357	50-266 Q		8212060026	50-29 P
	8212230357	50-266 Q		8212060056	50-443 A
	8212230359*	50-266 Q		8212060075	50-443 A
	8212230359*	50-266 Q		8212060094	50-443 A
	8212230359*	50-266 Q		8212060094	50-443 A
	8212270125	50-266 P		8212060151	50-443 A
	8212270177	50-266 S		8212060151	50-443 A
	8212270202*	50-266 S		8212070040	50-29 P
Williams-Robinette & Associates, Inc Witt, D D Wisconsin Electric Power Co	8212270239	50-266 S	Yankee Atomic Electric Co	8212070047	50-29 P
	8212270246*	50-266 S		8212070100	50-443 A
	8212280114	50-301 S		8212070100	50-443 A
	8212280115*	50-301 S		8212080163	50-443 F
	8212280158	50-266 S		8212080163	50-443 F
	8212280162*	50-266 S		8212080190	50-443 A
	8212280361	50-266 Q		8212080190	50-443 A
	8212290095	50-266 P		8212080224	50-443 A
	8212290143	50-266 P		8212080224	50-443 A
	8212290253	50-266 R		8212080329*	50-443 Q
Williams-Robinette & Associates, Inc Witt, D D Wisconsin Electric Power Co	8212290257*	50-266 R	Yankee Atomic Electric Co	8212090498	50-443 A
	8212290262*	50-266 R		8212100109*	50-443 A
	8212290300	50-266 P		8212130223	50-29 P
	8212290322	50-266 S		8212130227*	50-29 P
	8212290327*	50-266 S		8212140184	50-29 S
	8212030076	50-305 J		8212140187*	50-29 S
	8212040049*	50-305 Q		8212140235	50-443 A
	8212040090	50-305 S		8212140235	50-443 A
	8212070149	50-305 P		8212140394	50-29 F
	8212070333	50-305 P		8212150155	50-29 S
Wisconsin Public Service Corp	8212090257	50-305 F	Wisconsin Public Service Corp	8212150160*	50-29 S
	8212140143	50-305 P		8212210273	50-443 S
	8212140407	50-305 P		8212210273	50-443 S
	8212170167	50-305 S		8212210278	50-29 S
	8212170171*	50-305 S		8212210283*	50-29 S
	8212030076	50-305 J		8212140187*	50-29 S
	8212040049*	50-305 Q		8212140235	50-443 A
	8212040090	50-305 S		8212140235	50-443 A
	8212070149	50-305 P		8212140394	50-29 F
	8212070333	50-305 P		8212150155	50-29 S

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8212210287	50-443 S		8212270279	50-443
	8212210287	50-443 S		8212280476	50-29 A
	8212210449	50-443 S		8212280480*	50-29 P
	8212210449	50-443 S		8212290126	50-29 P
	8212270146	50-443 A		8212290130*	50-29 R
	8212270146	50-443 A		8212290251	50-29
	8212270188	50-443 A		8212290258*	50-29
	8212270270	50-443 A		8212290310	50-29
	8212270270	50-443 A		8212290316*	50-29
	8212270279	50-443 A	Yuba Heat Transfer Corp	8212160361	71-9006 S

REPORT NUMBER INDEX

The subject category column in this Index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents.

An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principal Documents."

REPORT NUMBER	ACCESSION NUMBER	SUBJECT CATEGORY	OTHER REPORT NUMBER
02-0540-1108 R00	0212130229*	50-255 P	20754
0715J	0212210542*	40-8064	
07-0870-001 R00	0212270104*	50-266 P	
24 R00	0212290243*	50-275 P	
25 R00	0212290237*	50-275 P	
26 R00	0212290250*	50-275 P	SAND82-7079
02-1033	0212280438*	30-409 P	
02-A R01	0212280354*	30-387 P	
02-H	0212210162*	30-277 R	
0212010109	0212010109	RES	
0212010469	0212010469	RES	SAND82-0996
0212010474	0212010474	RES	
0212010475	0212010475	RES	
0212010478	0212010478	RES	
0212010481	0212010481	RES	
0212010483	0212010483	RES	BNL-NUREG-32107
0212010486	0212010486	RES	
0212010487	0212010487	RES	
0212020010	0212020010	RES	
0212020076	0212020076	50-395 P	
0212020086	0212020086	50-409 P	EGG-EA-6099
0212020095	0212020095	50-155 P	
0212020100	0212020100	RES	
0212020104	0212020104	RES	
0212020108	0212020108	50-364 P	
0212020110	0212020110	50-249 P	EGG-EA-6099
0212020126	0212020126	RES	
0212030023	0212030023	RES	
0212030023	0212030023	50-537 A	
0212060005	0212060005	RES	
0212060119	0212060119	RES	BNL-NUREG-31940
0212060128	0212060128	RES	
0212070400	0212070400	RES	
0212070471	0212070471	RES	
0212080262	0212080262	RES	
0212080505	0212080505	RES	EGG-SEM1-6062
0212080510	0212080510	RES	
0212080516	0212080516	RES	
0212080520	0212080520	RES	
0212160549	0212160549	RES	
0212160558	0212160558	RES	ORNL/FTR-1428
0212160564	0212160564	RES	
0212220021	0212220021	RES	
0212220060	0212220060	RES	
0212220519	0212220519	RES	
0212220523	0212220523	RES	BNL-NUREG-32170
0212270416	0212270416	RES	
0212270534	0212270534	RES	
0212280031	0212280031	RES	
0212280040	0212280040	RES	
0212280051	0212280051	RES	BNL-NUREG-32105
0212280055	0212280055	RES	
0212280514	0212280514	50-320 P	
0212280518	0212280518	RES	
0212290512	0212290512	RES	

REPORT NUMBER	ACCESSION NUMBER	SUBJECT CATEGORY	OTHER REPORT NUMBER
0212300137	0212300137	RES	20873
0212300402	0212300402	RES	
994-76-018 R01	0212210414*	50-322 E	
AM-58A-2534	0212210005*	50-275 P	
AV-R-9563R	0212060336*	40-8743	
BAW-10155	0212130220*	TOPREP	21654
BQ-TOP-1 R02	0212230304*	50-275 P	
CE-1-A R22	0212220231*	50-10 P	
CEN-152 R01	0212020212*	TOPREP	
CENPD-270	0212140510*	PROJ	
DOE/EIS-0096-D	0212170409*	40-6500	21656
DPSU 71-124-4	0212130138*	71-4495	
DUKE-1-A A06	0212280173*	TOPREP	
E-3508 R00	0212270071*	71-9015	
EGG-1183-4210	0105210384*	50-263 G	
EPRI NP-2527-LD	0212170101*	50-277 P	GL-B1-04
EPRI NP-B1-4-LD	0212170111*	50-277 P	
ES-26NS-10-004 DRF B	0212010015*	50-537 F	
GA-C16924 V01	0212290148*	50-528 A	
GA-C16924 V02	0212290150*	50-528 A	
GA-C16924 V03	0212290155*	50-528 A	30 2874 0101
HNP BNR-12	0212090056*	50-518 A	
IACA-CN-42/253	0212080227	ORG	
MFR-751	0212090155*	TOPREP	
NES B1A0091 R01	0212280061*	50-409 P	
NFG 004 R01	0212010150*	50-272 P	30 2874 0102
NSP-74-101 R01	0212210327*	50-263 P	
NSP-74-102 R01	0212210330*	50-263 P	
NSP-74-103 R01	0212210333*	50-263 P	
NSP-74-104 R01	0212210337*	50-263 P	
NSP-74-105 R01	0212210342*	50-263 P	30 2874 0103
NSP-74-105A R01	0212210346*	50-263 P	
NUREG-0020 V06 N07	0212270505	NUREG	
NUREG-0327 R03	0212140471	NUREG	
NUREG-0485 V04 N10	0212010138	NUREG	
NUREG-0540 V04 N06	0212140475	NUREG	30 2874 0103
NUREG-0540 V04 N07	0212270068	NUREG	
NUREG-0580 V11 N11	0212270174	NUREG	
NUREG-0606 V04 N04	0212270243	NUREG	
NUREG-0713 V03	0212270459	NUREG	
NUREG-0748 V02 N10	0212160780	NUREG	30 2874 0103
NUREG-0773	0212140476	NUREG	
NUREG-0824 DRFT	0212010100	50-245 P	
NUREG-0871 V01 N04	0212220143	NUREG	
NUREG-0918	0212270181	NUREG	
NUREG-0936 V01 N03	0212010052	NUREG	SAND82-1659
NUREG-0952	0212140482	50-362 P	
NUREG/BR-0025 V08N11	0212270443	NUREG	
NUREG/BR-0051 V04 N4	0212130140	NUREG	
NUREG/CP-0033 V01	0212220513	NUREG	
NUREG/CP-0033 V02	0212220172	NUREG	SAND82-1659
NUREG/CR-0891	0005070798*	50-237 P	
NUREG/CR-1522	0212270561	NUREG	
NUREG/CR-1935	0212270165	NUREG	
NUREG/CR-2134	0212160762	NUREG	

REPORT NUMBER INDEX

REPORT NUMBER	ACCESSION NUMBER	SUBJECT CATEGORY	OTHER REPORT NUMBER	REPORT NUMBER	ACCESSION NUMBER	SUBJECT CATEGORY	OTHER REPORT NUMBER
NUREG/CR-2170	8212130113	NUREG	EQO-2191	RIL-087	8006020271	RES	
NUREG/CR-2296	8212130283	NUREG	SANDB1-1788	RIL-106	8103250465	RES	
NUREG/CR-2364 V01	8212060429	NUREG	ANL-81-59	RIL-118	8104170664	RES	
NUREG/CR-2364 V02	8212060441	NUREG	ANL-81-59	RIL-119	8104170658	RES	
NUREG/CR-2364 V03	8212060447	NUREG	ANL-81-59	RIL-124	8111130045	RES	
NUREG/CR-2364 V04	8212060451	NUREG	ANL-81-59	RIL-125	8109280378	RES	
NUREG/CR-2364 V05	8212060455	NUREG	ANL-81-59	RIL-126	8201220290	RES	
NUREG/CR-2423	8212220509	NUREG	PNL-4109	RIL-127	8201150075	RES	
NUREG/CR-2526	8212220265	NUREG	PNL-4164	RIL-128	8201180563	RES	
NUREG/CR-2558	8212220282	NUREG	EQO-2159	RIL-129	8202260369	RES	
NUREG/CR-2566	8212010144	NUREG	EPRI NP-2373	RIL-130	8212270240	RES	
NUREG/CR-2601 V01	8212270033	NUREG	PNL-4247	RIL-131	8207200458	RES	
NUREG/CR-2601 V02	8212270232	NUREG	PNL-4247	SAI-186-029-05	8209030343*	50-213 P	
NUREG/CR-2641	8212270435	NUREG	ORNL/TM-8271	SAI-186-029-14	8212140260*	50-229 P	
NUREG/CR-2643	8212130098	NUREG	SANDB2-7036	SAI-186-029-19	8212070115*	50-317 P	
NUREG/CR-2650	8212220162	NUREG	SANDB2-0774	SAI-186-029-20	8209030322*	50-255 P	
NUREG/CR-2672 V01	8212140479	50-259 P	ORNL/TM-8119/V1	SAI-186-029-23	82012010427*	50-309 P	
NUREG/CR-2697	8212130135	NUREG	ORNL/TM-8325	SAI-186-029-25	8207080445*	50-285 P	
NUREG/CR-2716 V02	8212270449	NUREG	PNL-4275-2	SAI-186-029-35	8208310315*	50-331 P	
NUREG/CR-2720	8212130123	NUREG	ORNL/TM-8336	SECY-77-574	8212010143*	FOIA	
NUREG/CR-2723	8212220204	NUREG	SANDB2-1110	SECY-82-023	8202010383*	FOIA	
NUREG/CR-2753	8212060445	NUREG	ORNL-5886	SECY-82-042	8203090677*	FOIA	
NUREG/CR-2765	8212010115	NUREG	PNL-4301	SECY-82-136	8204160270*	FOIA	
NUREG/CR-2768	8212270487	NUREG	PNL-4302	SECY-82-137	8204160262*	FOIA	
NUREG/CR-2774 V02	8212130143	NUREG	ANL-82-24	SECY-82-275	8212290039*	FOIA	
NUREG/CR-2787 V02	8212060492	50-313 P	SANDB2-0978	SECY-82-286	8212090224*	FOIA	
NUREG/CR-2797	8212270492	NUREG	ORNL/NSIC-207	SECY-82-313	8209280513*	FOIA	
NUREG/CR-2807	8212060480	NUREG	EQO-2207	SECY-82-322	8209010092*	FOIA	
NUREG/CR-2811	8212060460	NUREG	ORNL-5895	SECY-82-447A	8212100088	SECY	
NUREG/CR-2822	8212140459	50-261 P	UCRL-53041	SECY-82-462	8212010327	SECY	
NUREG/CR-2823	8212140485	NUREG	UCRL-53042	SECY-82-465	8212060419	SECY	
NUREG/CR-2832	8212220228	NUREG	LMF-97	SECY-82-465 ERR	8212070487	SECY	
NUREG/CR-2843	8212270512	NUREG	PNL-4345	SMA 12901 03	8210190510*	50-247 F	
NUREG/CR-2844	8212130118	NUREG	SANDB2-1684	SMA 13703 02	8212030025*	50-155 G	IEB-80-11
NUREG/CR-2845	8212270156	NUREG	SANDB2-0917	STD-R-02-004	8212130061*	71-9151	
NUREG/CR-2866	8212130157	50-537 A	LA-9478-H3	TER-C5257-298	8209140103*	50-255 P	TAC 11732
NUREG/CR-2875	82122202341	PNL-4370		TER-C5257-325	8209230258*	50-409 P	
NUREG/CR-2888	8212060471	50-295 P	EQO-2201	TER-C5257-405	8209230377*	50-155 P	TAC 41603
NUREG/CR-2894	8212270486	NUREG	PNL-4402	TER-C5257-427	8209270122*	50-409 P	TAC 41368
NUREG/CR-2899	8212130110	NUREG	SANDB2-1870	TER-C5257-453	8207150169*	50-219 P	
NUREG/CR-2900	8212270441	NUREG	ORNL-5876	TER-C5257-454	8207010149*	50-244 P	TAC 42520
NUREG/CR-2917	8212270559	NUREG	PNL-4427	TER-C5257-459	8207010396*	50-245 P	IEB-79-010
NUREG/CR-2918	8212130147	NUREG	ANL-82-53	TER-C5257-460	8212230110*	50-213 P	
NUREG/CR-2927	8212220271	NUREG	SANDB2-0236	TER-C5257-463	8207010124*	50-29 P	IEB-79-018
NUREG/CR-2930	8212130152	NUREG	EQO-2219	TER-C5257-464	8207010410*	50-409 P	IEB-79-015
NUREG/CR-2932 V01	8212060486	NUREG	SANDB1-2027	TER-C5257-479	8212290836*	50-250 P	TAC 42470
NUREG/CR-2942	8212130108	NUREG	EQO-2220	TER-C5257-480	8210070227*	50-250 P	TAC 42471
NUREG/CR-2948	8212270499	NUREG	MEA-2006	TER-C5257-485	8210250187*	50-344 P	
NUREG/CR-2960	8212060468	NUREG	EQO-2224	TER-C5257-487	8210220483*	50-317 P	TAC 42494
NUREG/CR-2961	8212270454	NUREG	EQO-2225	TER-C5257-488	8210220470*	50-317 P	IEB-79-010
NUREG/CR-2970 V01	8212270468	NUREG	ANL-82-41	TER-C5257-492	82122300348*	50-289 P	TAC 42513
NUREG/CR-2975	8212160773	NUREG	UCID-19463	TER-C5257-493	8212230250*	50-277 P	IEB-79-01
NUREG/CR-2976	8212160464	NUREG	UCID-19464	TER-C5257-493	8206160113*	50-271 P	
NUREG/CR-2978	8212270145	NUREG	EQO-2227	TR-5318-1 R00	8212290452*	50-245 P	
NUREG/CR-2982	8212270520	NUREG	SANDB2-7205	TR-5319-1	8212270218*	50-271 P	
NUREG/CR-2995	8212220249	NUREG		TR-25N	8212270281*	50-443 A	
NUREG/CR-3004	8212220193	NUREG	PNL-4509	UCID-18670	8212130370*	50-344 P	
NUREG/CR-3020	8212270221	NUREG		UCID-19145	8212090023*	50-263 P	
NUREG/CR-3040	8212060459	NUREG		UCID-19148	8209230424*	50-250 P	
NUREG/CR-3055	8212220238	NUREG	PNL-4346	UMTRA-DOE/AL-33	8212020073*	WASTE HOT	
NUREG/CR-3077	8212270420	NUREG	BMI-2030	URS/JAB 8051	8212280134*	50-155 G	IEB-80-21
ORO-4014-12	8212070009*	50-83 R		WCAP-10086	8212140420*	50-244 P	
PGE-1035	8212070319*	50-344 P		WCAP-10146	8212270266*	50-286 P	27190 1
PND-PE-010 R00	8212150047*	50-382 F		WCAP-10170	8212160365	TOPREP	21588 1/102582
QUAD-1-82-244	8212170335*	50-461 E		WCAP-8587S1R0 ESE-18	8210210484*	TOPREP	EQDP-ESE-18
QUAD-1-82-245 REV A	8212070278*	50-416 P		WCAP-8587S1R0 ESE-3B	8210210489*	TOPREP	EQDP-ESE-3B
RDD-83 5489 01	8212270042*	50-289 P		XN-NF-79-56 (NP) (A) R1	8212150005*	TOPREP	
RDD 83 5490/5491 02	8212270047*	50-289 P		XN-NF-82-77 (NP) R01	8212290215*	50-237 P	
RIL-038	7811070329	RES		XN-NF-82-84 (NP) R01	8212290206*	50-237 P	
RIL-071	8005281047	RES		XN-NF-82-88 R01	8212290199*	50-237 P	
RIL-076	8002260162	RES					
RIL-079	8003280100	RES					
RIL-081	8005270829	RES					
RIL-082	8005071094	50-320 P					
RIL-085	8005270762	RES					

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

Items listed as enclosures are those indicated by an asterisk following the accession number in the indexes. The second column gives the accession number of the principal document under which the enclosure is listed. Knowing the accession number of the principal document, the date issued, and the category enables locating the title listing of the enclosure.

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents.

ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
7906040228	8212140001	82/11/03	50-237 P
7907100669	8212140001	82/11/03	50-237 P
7907180391	8212140001	82/11/03	50-409 P
7907240319	8212140001	82/11/03	50-237 P
7907300865	8212140001	82/11/03	50-255 P
7908080624	8212140001	82/11/03	50-237 P
7908090435	8212140001	82/11/03	50-10 P
7908140421	8212140001	82/11/03	50-206 P
7908140784	8212140001	82/11/03	50-219 P
7908140789	8212140001	82/11/03	50-219 P
7909180332	8212140001	82/11/03	50-244 P
7909280656	8212140001	82/11/03	50-237 P
7911150252	8212140001	82/11/03	50-237 P
7912190426	8212140001	82/11/03	50-206 P
8001110507	8212100053	82/11/09	FOIA
8001180235	8212140001	82/11/03	50-206 P
8001230275	8212100053	82/11/09	FOIA
8001280032	8212140001	82/11/03	50-482 A
8002130081	8212140001	82/11/03	50-206 P
8002200995	8212140001	82/11/03	50-219 P
8002270255	8212140001	82/11/03	50-206 P
8003310092	8212140001	82/11/03	50-206 P
8003310489	8212140001	82/11/03	50-409 P
8004010318	8212140001	82/11/03	50-237 P
8005080726	8212140001	82/11/03	50-206 P
8005070778	8212140001	82/11/03	50-237 P
8005070798	8212140001	82/11/03	50-237 P
8005280555	8212140001	82/11/03	50-219 P
8005280561	8212140001	82/11/03	50-219 P
8006090164	8212140001	82/11/03	50-206 P
8006090788	8212140001	82/11/03	50-206 P
8007180114	8212140001	82/11/03	50-206 P
8007230260	8212140001	82/11/03	50-206 P
8008260700	8212010029	82/11/01	FOIA
8009080320	8212140001	82/11/03	FOIA
8009110797	8212140001	82/11/03	50-10 P
8009170164	8212140001	82/11/03	50-409 P
8009180414	8212140001	82/11/03	FOIA
8009290433	8212140001	82/11/03	50-206 P
8010180236	8212140001	82/11/03	50-206 P
8010150242	8212140001	82/11/03	50-206 P
8010150246	8212140001	82/11/03	50-206 P
8010170283	8212140001	82/11/03	50-206 P
8010170287	8212140001	82/11/03	50-206 P
8010220355	8212140001	82/11/03	50-245 P
8010800118	8212140001	82/11/03	50-255 P
8010220077	8212100053	82/11/09	FOIA
8010220078	8212100053	82/11/09	FOIA
80103120528	8212100412	82/11/15	FOIA
80103310251	8212100412	82/11/15	FOIA

ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8104100175	8212100412	82/11/15	FOIA
8104230080	8212140001	82/11/03	FOIA
8105110512	8212140001	82/11/03	50-219 P
8105210384	8212210007	82/12/01	50-263 G
8107140119	8212290025	82/11/24	50-322 H
8109210340	8212140001	82/11/03	FOIA
8109230665	8212140001	82/11/03	FOIA
8109280383	8109280378	81/09/11	RES
8110190952	8212140001	82/11/03	50-206 P
8112110356	8212140001	82/11/03	50-206 P
8112160327	8212140001	82/11/03	50-213 P
8112290035	8212140001	82/11/03	50-244 P
8201120155	8201220290	81/12/04	RES
8201180567	8212140001	82/11/03	50-255 P
8202010383	8212090048	82/10/20	FOIA
8202180082	8212020008	82/11/08	FOIA
8202180460	8212140001	82/11/03	50-255 P
8203010313	8212140001	82/11/03	FOIA
8203090677	8212090048	82/10/20	FOIA
8203310670	8212140001	82/11/03	50-29 P
8204010021	8212140001	82/11/03	50-155 P
8204130511	8212020008	82/11/08	FOIA
8204160262	8212090048	82/10/20	FOIA
8204160270	8212090048	82/10/20	FOIA
8204270491	8212140001	82/11/03	50-255 P
8205040451	8212140001	82/11/03	FOIA
8205240413	8212140001	82/11/03	FOIA
8205260070	8212140001	82/11/03	50-244 P
8205270590	8212140001	82/11/03	FOIA
8206070020	8212100053	82/11/09	FOIA
8206070028	8212100053	82/11/09	FOIA
8206100047	8212270483	82/12/14	50-344 F
8206140162	8212070425	82/11/05	50-298 G
8206160113	8212280005	82/11/29	50-271 P
8206220059	8212020008	82/11/08	FOIA
8206220070	8212100053	82/11/09	FOIA
8206220072	8212100053	82/11/09	FOIA
8206290144	8212140001	82/11/03	FOIA
8207010124	8212270365	82/12/16	50-29 P
8207010149	8212200008	82/12/13	50-244 P
8207010396	8212200100	82/12/13	50-245 P
8207010410	8212290320	82/12/21	50-409 P
8207080445	8212010458	82/11/17	50-285 P
8207120252	8212100053	82/11/09	FOIA
8207150169	8212070097	82/11/30	50-219 P
8207200474	8212140001	82/11/03	50-155 P
8207280369	8212140001	82/11/03	FOIA
8208030436	8212140001	82/11/03	FOIA
8208290147	8212070385	82/11/22	COMMISSION
8208310315	8212020007	82/11/23	50-331 P

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSION NUMBER				ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8209010092	8212230166	82/11/04	FOIA	8212010102	8212010029	82/11/01	FOIA
8209030322	8212080340	82/12/02	50-255 P	8212010105	8212010029	82/11/01	FOIA
8209030343	8212210127	82/12/15	50-213 P	8212010108	8212010029	82/11/01	FOIA
8209140103	8212210459	82/12/16	50-255 P	8212010112	8212010029	82/11/01	FOIA
8209150008	8212060470	82/11/23	COMMISSION	8212010119	8212010029	82/11/01	FOIA
8209220450	8212130350	82/12/07	50-331 P	8212010120	8212010114	82/11/12	XPORTLIC
8209220453	8212130350	82/12/07	50-331 P	8212010122	8212010117	82/11/19	50-390 A
8209230258	8212180115	82/12/09	50-409 P	8212010123	8212010029	82/11/01	FOIA
8209230377	8212230354	82/12/09	50-155 P	8212010126	8212010117	82/11/19	50-390 A
8209230424	8212300068	82/12/17	50-250 P	8212010129	8212010117	82/11/19	50-390 A
8209280513	8212070048	82/10/20	FOIA	8212010133	8212010127	82/11/12	XPORTLIC
8209290122	8212020328	82/11/12	50-409 P	8212010139	8212010029	82/11/01	FOIA
8210040253	8210040239	82/09/30	50-352 A	8212010141	8212010029	82/11/01	FOIA
8210040267	8210040239	82/09/30	50-352 K	8212010143	8212010029	82/11/01	FOIA
8210040272	8210040239	82/09/30	50-352 A	8212010149	8212010029	82/11/01	FOIA
8210040278	8210040239	82/09/30	50-352 C	8212010150	8212010148	82/11/24	50-272 P
8210070227	8212270534	82/12/13	50-250 P	8212010156	8212010147	82/11/30	50-341 K
8210150165	8212220460	82/11/08	50-341 F	8212010157	8212010029	82/11/01	FOIA
8210190510	8210190499	82/10/08	50-247 F	8212010159	8212010029	82/11/01	FOIA
8210210095	8210210078	82/10/06	50-311 S	8212010162	8212010029	82/11/01	FOIA
8210210475	8210210467	82/10/13	TOPREP	8212010163	8212010147	82/11/30	50-341 K
8210210484	8210210467	82/10/13	TOPREP	8212010164	8212010160	82/11/17	50-302 P
8210210489	8210210467	82/10/13	TOPREP	8212010167	8212010160	82/11/17	50-302 P
8210220470	8212300041	82/12/16	50-317 P	8212010168	8212010029	82/11/01	FOIA
8210220483	8212300041	82/12/16	50-317 P	8212010172	8212010160	82/11/17	50-302 P
8210250187	8212280410	82/12/17	50-344 P	8212010174	8212010029	82/11/01	FOIA
8210260403	8212010023	82/11/26	50-206 P	8212010177	8212010029	82/11/01	FOIA
8210270016	8210270013	82/10/22	50-397 A	8212010180	8212010029	82/11/01	FOIA
8210270018	8210270013	82/10/22	50-397 A	8212010187	8212010029	82/11/01	FOIA
8211020166	8212130395	82/11/24	50-275 H	8212010193	8212010185	82/11/15	50-267 P
8211020246	8211020241	82/09/17	40-8698	8212010196	8212010029	82/11/01	FOIA
8211020252	8211020241	82/09/17	40-8698	8212010200	8212010192	82/11/29	50-289 Q
8211040090	8211040086	82/10/25	50-335 S	8212010201	8212010029	82/11/01	FOIA
8211040225	8212010375	82/11/08	50-443 E	8212010205	8212010185	82/11/15	50-269 P
8211050027	8212270418	82/11/26	50-483 A	8212010209	8212010029	82/11/01	FOIA
8211060556	8212130023	82/12/02	50-286 P	8212010211	8212010206	82/11/26	50-275 R
8211080105	8211080101	82/11/02	50-29 P	8212010218	8212010029	82/11/01	FOIA
8211080107	8211080101	82/11/02	50-29 P	8212010221	8212010220	82/11/15	WASTE MGT
8211080110	8211080101	82/11/02	50-29 P	8212010225	8212010206	82/11/26	50-275 R
8211080129	8211080125	82/11/03	50-322 E	8212010226	8212010029	82/11/01	FOIA
8211110457	8212060484	82/11/12	50-440 A	8212010228	8212010227	82/11/17	WASTE MGT
8211110483	8212270041	82/11/22	50-289 P	8212010230	8212010029	82/11/01	FOIA
8211120169	8212090141	82/11/12	REVIEW GRP	8212010235	8212010029	82/11/01	FOIA
8211120212	8212090141	82/11/12	REVIEW GRP	8212010238	8212010029	82/11/01	FOIA
8211120491	8211120486	82/10/21	MISC	8212010244	8212010029	82/11/01	FOIA
8211160015	8211170509	82/10/29	50-237 P	8212010249	8212010029	82/11/01	FOIA
8211220096	8208190263	82/12/09	50-3 P	8212010276	8212010185	82/11/15	50-269 P
8211230137	8212130281	82/12/06	50-275 P	8212010290	8212010288	82/11/16	50-389 M
8211290023	8212170369	82/11/30	50-206 Q	8212010330	8212010329	82/11/23	50-302 P
8211290142	8211290135	82/11/19	50-528 A	8212010331	8212010329	82/11/23	50-302 P
8211290148	8211290135	82/11/19	50-528 A	8212010332	8212010329	82/11/23	50-302 P
8211290150	8211290135	82/11/19	50-528 A	8212010335	8212010334	82/11/12	50-309 P
8211290155	8211290135	82/11/19	50-528 A	8212010347	8212010342	82/11/17	50-289 P
8211290599	8211290530	82/11/19	50-454 K	8212010368	8212010361	82/11/09	50-322 A
8212010015	8212010011	82/11/30	50-537 F	8212010371	8212010361	82/11/09	50-322 A
8212010016	8212010012	82/11/08	FOIA	8212010372	8212010369	82/11/24	70-36
8212010017	8212010014	82/11/15	50-456 A	8212010374	8212010369	82/11/24	70-36
8212010020	8212010014	82/11/15	50-456 A	8212010383	8212010381	82/11/23	CONTRACT
8212010021	8212010012	82/11/08	FOIA	8212010389	8212010385	82/11/23	50-443 Q
8212010036	8212010023	82/11/26	50-206 P	8212010391	8212010388	82/11/23	CONTRACT
8212010037	8212010033	82/11/24	50-315 F	8212010393	8212010361	82/11/09	50-322 A
8212010039	8212010033	82/11/24	50-315 F	8212010396	8212010385	82/11/23	50-443 Q
8212010050	8212010042	82/11/24	50-317 F	8212010397	8212010361	82/11/09	50-322 A
8212010051	8212010029	82/11/01	FOIA	8212010398	8212010395	82/11/23	CONTRACT
8212010053	8212010046	82/11/16	50-389 M	8212010401	8212010361	82/11/09	50-322 A
8212010055	8212010042	82/11/24	50-317 F	8212010406	8212010403	82/11/23	CONTRACT
8212010058	8212010029	82/11/01	FOIA	8212010418	8212010392	82/11/22	50-269 P
8212010063	8212010057	82/10/20	XPORTLIC	8212010421	8212010392	82/11/22	50-269 P
8212010066	8212010061	82/11/24	50-112 F	8212010422	8212010417	82/11/18	50-309 P
8212010067	8212010029	82/11/01	FOIA	8212010423	8212010419	82/11/23	CONTRACT
8212010069	8212010065	82/11/15	WASTE MGT	8212010427	8212010417	82/11/18	50-309 P
8212010070	8212010029	82/11/01	FOIA	8212010428	8208290032	82/10/04	ACRB
8212010074	8212010071	82/11/24	50-150 F	8212010430	8212010425	82/11/23	CONTRACT
8212010077	8212010029	82/11/01	FOIA	8212010434	8212010432	82/11/23	CONTRACT
8212010079	8212010071	82/11/24	50-150 F	8212010438	8212010433	82/11/23	CONTRACT
8212010080	8212010029	82/11/01	FOIA	8212010451	8212010446	82/10/26	FOIA
8212010091	8212010029	82/11/01	FOIA	8212010464	8212010458	82/11/17	50-285 P
8212010096	8212010029	82/11/01	FOIA	8212010479	8212010476	82/11/11	27-39
8212010097	8212010092	82/11/24	50-320 F	8212010488	8212010392	82/11/22	50-269 P
8212010099	8212010029	82/11/01	FOIA	8212010519	8212010513	82/11/24	50-352 A

ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8212010102	8212010029	82/11/01	FOIA
8212010105	8212010029	82/11/01	FOIA
8212010108	8212010029	82/11/01	FOIA
8212010112	8212010029	82/11/01	FOIA
8212010119	8212010029	82/11/01	FOIA
8212010120	8212010114	82/11/12	XPORTLIC
8212010122	8212010117	82/11/19	50-390 A
8212010123	8212010029	82/11/01	FOIA
8212010126	8212010117	82/11/19	50-390 A
8212010129	8212010117	82/11/19	50-390 A
8212010133	8212010127	82/11/12	XPORTLIC
8212010139	8212010029	82/11/01	FOIA
8212010141	8212010029	82/11/01	FOIA
8212010143	8212010029	82/11/01	FOIA
8212010149	8212010029	82/11/01	FOIA
8212010150	8212010148	82/11/24	50-272 P
8212010156	8212010147	82/11/30	50-341 K
8212010157	8212010029	82/11/01	FOIA
8212010159	8212010029	82/11/01	FOIA
8212010162	8212010029	82/11/01	FOIA
8212010163	8212010147	82/11/30	50-341 K
8212010164	8212010160	82/11/17	50-302 P
8212010167	8212010160	82/11/17	50-302 P
8212010168	8212010029	82/11/01	FOIA
8212010172	8212010160	82/11/17	50-302 P
8212010174	8212010029	82/11/01	FOIA
8212010180	8212010029	82/11/01	FOIA
8212010187	8212010029	82/11/01	FOIA
8212010193	8212010185	82/11/15	50-269 P
8212010196	8212010029	82/11/01	FOIA
8212010200	8212010192	82/11/29	50-289 Q
8212010201	8212010029	82/11/01	FOIA
8212010205	8212010185	82/11/15	50-269 P
8212010209	8212010029	82/11/01	FOIA
8212010211	8212010206	82/11/26	50-275 R
8212010218	8212010029	82/11/01	FOIA
8212010221	8212010220	82/11/15	WASTE MGT
8212010225	8212010206	82/11/26	50-275 R
8212010226	8212010029	82/11/01	FOIA
8212010228	8212010227	82/11/17	WASTE MGT
8212010230	8212010029	82/11/01	FOIA
8212010235	8212010029	82/11/01	FOIA
8212010238	8212010029	82/11/01	FOIA
8212010244	8212010029	82/11/01	FOIA
8212010249	8212010029	82/11/01	FOIA
8212010276	8212010185	82/11/15	50-269 P
8212010290	8212010288	82/11/16	50-389 M
8212010330	8212010329	82/11/23	50-302 P
8212010331	8212010329	82/11/23	50-302 P
8212010332	8212010329	82/11/23	50-302 P
8212010335	8212010334	82/11/12	50-309 P
8212010347	8212010342	82/11/17	50-289 P
8212010368	8212010361	82/11/09	50-322 A
8212010371	8212010361	82/11/09	50-322 A
8212010372	8212010369	82/11/24	70-36
8212010374	8212010369	82/11/24	70-36
8212010383	8212010381	82/11/23	CONTRACT
8212010389	8212010385	82/11/23	50-443 Q
8212010391	8212010388	82/11/23	CONTRACT
8212010393	8212010361	82/11/09	50-322 A
8212010396	8212010385	82/11/23	50-443 Q
8212010397	8212010361	82/11/09	50-322 A
8212010398	8212010395	82/11/23	CONTRACT
8212010401	8212010361	82/11/09	50-322 A
8212010406	8212010403	82/11/23	CONTRACT
8212010418	8212010392	82/11/22	50-269 P
8212010421	8212010392	82/11/22	50-269 P
8212010422	8212010417	82/11/18	50-309 P
8212010423	8212010419	82/11/23	CONTRACT
8212010427	8212010417	82/11/18	50-309 P
8212010428	8208290032	82/10/04	ACRB
8212010430	8212010425	82/11/23	CONTRACT
8212010434	8212010432	82/11/23	CONTRACT
8212010438	8212010433	82/11/23	CONTRACT
8212010451	8212010446	82/10/26	FOIA
8212010464	8212010488	82/11/17	50-285 P
8212010479	8212010476	82/11/11	27-39
8212010488	8212010392	82/11/22	50-269 P
8212010519	8212010513	82/11/24	50-352 P

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

487

ACCESSION NUMBER					ACCESSION NUMBER				
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY		ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	
8212020012	8212020008	82/11/08	FOIA		8212030050	8212030034	82/11/08	50-220	Q
8212020014	8212020008	82/11/08	FOIA		8212030051	8212030045	82/11/19	50-336	Q
8212020019	8212020008	82/11/08	FOIA		8212030056	8212030053	82/11/30	50-254	Q
8212020023	8212020008	82/11/08	FOIA		8212030058	8212030046	82/11/03	50-482	Q
8212020037	8212020033	82/11/22	50-416	S	8212030064	8212030060	82/11/29	50-395	S
8212020052	8212020045	82/11/24	50-302	S	8212030070	8212030065	82/11/18	50-333	Q
8212020056	8212020008	82/11/08	FOIA		8212030075	8212030066	82/11/18	50-368	S
8212020057	8212020051	82/11/18	50-354	Q	8212030078	8212030065	82/11/18	50-333	Q
8212020061	8212020050	82/11/24	50-416	S	8212030083	8212030069	82/11/18	50-322	Q
8212020065	8212020058	82/11/24	50-416	S	8212030090	8212030087	82/11/19	50-387	Q
8212020067	8212020008	82/11/08	FOIA		8212030092	8212030086	82/11/29	50-327	S
8212020071	8212020063	82/11/24	50-302	S	8212030093	8212030081	82/11/16	50-312	S
8212020073	8212020060	82/10/01	WASTE MAT		8212030096	8212030093	82/11/30	50-387	Q
8212020075	8212020008	82/11/08	FOIA		8212030106	8212030084	82/11/24	50-312	S
8212020080	8212020008	82/11/08	FOIA		8212030112	8212030104	82/11/16	50-285	Q
8212020081	8212010503	82/11/26	70-734		8212030115	8212030109	82/11/02	50-482	Q
8212020083	8212020068	82/11/24	50-324	S	8212030116	8212030110	82/10/05	50-312	S
8212020084	8212020078	82/11/23	50-334	P	8212030120	8212030113	82/11/19	50-320	R
8212020087	8212020077	82/11/24	50-302	S	8212030126	8212030119	82/11/17	50-295	Q
8212020089	8212020078	82/11/23	50-334	P	8212030128	8212030123	82/11/19	50-286	Q
8212020096	8212020090	82/11/24	50-250	S	8212030129	8212030121	82/11/17	50-255	Q
8212020098	8212020091	82/11/23	50-440	K	8212030132	8212030122	82/11/30	50-352	A
8212020124	8212020116	82/11/23	50-296	S	8212030135	8212030127	82/11/24	50-482	A
8212020144	8212020138	82/11/24	50-416	S	8212030139	8212030133	82/11/24	50-395	S
8212020153	8212020143	82/11/23	50-260	S	8212030145	8212030125	82/11/29	50-315	P
8212020161	8212020152	82/11/24	50-324	S	8212030147	8212030141	82/11/19	50-247	Q
8212020191	8212020179	82/11/23	50-328	S	8212030150	8212030134	82/11/17	50-282	Q
8212020193	8212020185	82/11/19	MISC		8212030153	8212030144	82/11/29	50-272	Q
8212020194	8212020189	82/10/29	CONTRACT		8212030156	8212030131	82/11/10	50-445	Q
8212020208	8212020200	82/11/22	TOPREP		8212030162	8212030159	82/11/24	50-298	P
8212020212	8212020200	82/11/22	TOPREP		8212030168	8212030157	82/12/01	50-361	P
8212020232	8212020229	82/11/23	50-316	S	8212030171	8212030164	82/11/24	50-395	S
8212020237	8212020234	82/11/24	50-295	S	8212030174	8212030170	82/11/18	50-321	S
8212020244	8212020240	82/11/23	50-296	S	8212030175	8212030165	82/11/17	50-213	Q
8212020248	8212020239	82/11/16	50-249	S	8212030177	8212030167	82/11/17	50-336	Q
8212020264	8212020261	82/11/17	50-294	S	8212030179	8212030173	82/11/24	50-387	S
8212020271	8212020267	82/11/29	TOPREP		8212030185	8212030178	82/12/01	50-10	Q
8212020280	8212020275	82/11/24	50-237	S	8212030189	8212030180	82/11/24	50-245	S
8212020281	8212020276	82/11/24	50-266	S	8212030192	8212030184	82/11/12	50-368	Q
8212020282	8212020274	82/11/23	50-373	S	8212030197	8212030187	82/11/19	50-254	Q
8212020285	8212020272	82/11/24	50-295	S	8212030199	8212030188	82/11/23	50-395	S
8212020288	8212020279	82/09/89	PRM		8212030200	8212030195	82/11/19	50-293	Q
8212020289	8212020283	82/11/23	50-315	S	8212030202	8212030186	82/11/24	50-395	S
8212020293	8212020292	82/11/19	50-366	S	8212030204	8212030201	82/11/24	50-336	S
8212020297	8212020293	82/11/23	50-324	S	8212030207	8212030193	82/11/19	50-289	Q
8212020301	8212020294	82/11/23	50-373	S	8212030208	8212030205	82/11/19	50-278	S
8212020304	8212020300	82/11/26	50-29	P	8212030220	8212030212	82/11/30	50-259	Q
8212020310	8212020308	82/11/16	50-254	Q	8212030221	8212030215	82/11/19	50-289	Q
8212020312	8212020306	82/11/23	50-325	S	8212030226	8212030212	82/11/30	50-259	Q
8212020314	8212020308	82/11/16	50-254	Q	8212030232	8212030212	82/11/30	50-259	Q
8212020316	8212020286	82/11/23	50-443	A	8212030234	8212030227	82/11/24	50-336	S
8212020317	8212020311	82/11/24	50-282	S	8212030243	8212030236	82/11/30	50-3	F
8212020319	8212020315	82/11/23	50-324	S	8212030248	8212030124	82/12/01	50-361	P
8212020326	8212020323	82/11/30	50-443	Q	8212030250	8212030157	82/10/14	40-8786	
8212020327	8212020305	82/11/24	50-373	S	8212030263	8212030261			
8212020331	8212020325	82/11/23	50-255	B	8212030265	8212030253	82/11/24	50-275	P
8212020338	8212020334	82/11/26	50-443	A	8212030266	8212030246	82/11/30	CONTRACT	
8212020339	8212020330	82/11/30	50-352	Q	8212030272	8212030270	82/11/19	40-6622	
8212020331	8212020347	82/11/26	50-255	Q	8212030273	8212030268	82/11/30	50-254	F
8212020352	8212020349	82/11/24	50-277	R	8212030279	8212030268	82/11/30	50-254	F
8212020354	8212020348	82/11/23	50-259	S	8212030282	8212030281	82/11/09	40-3453	
8212020357	8212020337	82/11/19	50-249	S	8212030285	8212030283	82/11/30	50-10	F
8212020365	8212020362	82/11/23	50-324	S	8212030287	8212030283	82/11/30	50-10	F
8212020371	8212020369	82/11/23	50-335	S	8212030295	8212030284	82/11/01	40-8380	
8212020390	8212020367	82/11/24	CONTRACT		8212030299	8212030291	82/11/30	50-309	F
8212020401	8212020346	82/11/30	50-289	Q	8212030304	8212030291	82/11/30	50-309	F
8212020404	8212020402	82/11/24	CONTRACT		8212060017	8212060009	82/11/15	50-315	Q
8212030003	8212030002	82/11/18	50-369	P	8212060019	8212060015	82/11/27	50-320	P
8212030013	8212030009	82/11/23	50-285	S	8212060022	8212060015	82/11/29	50-320	P
8212030017	8212030011	82/11/10	50-344	S	8212060027	8212060024	82/11/22	50-312	Q
8212030020	8212030016	82/11/24	70-2792		8212060030	8212060025	82/11/30	50-358	Q
8212030023	8212030018	82/11/17	50-220	Q	8212060032	8212060028	82/11/24	50-285	P
8212030025	8212030019	82/11/24	50-155	Q	8212060035	8212060028	82/11/24	50-285	P
8212030028	8212030021	82/11/18	50-373	Q	8212060039	8212060025	82/11/30	50-358	Q
8212030032	8212030029	82/11/19	70-1100		8212060045	8212060035	82/11/26	50-10	Q
8212030033	8212030030	82/11/18	50-219	Q	8212060046	8212060042	82/11/30	50-309	P
8212030037	8212030030	82/11/18	50-219	Q	8212060049	8212060044	82/11/26	50-305	Q
8212030038	8212030035	82/11/18	50-244	Q	8212060053	8212060047	82/11/24	50-275	R
8212030044	8212030039	82/11/26	50-259	S	8212060055	8212060051	82/11/01	50-409	Q
8212030047	8212030041	82/11/19	50-387	S	8212060057	8212060048	82/11/24	50-316	S

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSION NUMBER				ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8212060058	8212060052	82/11/22	MISC	8212060427	8212060424	82/11/12	FOIA
8212060060	8212060048	82/11/24	50-316 S	8212060430	8212060422	82/11/30	50-295 P
8212060062	8212060051	82/11/01	50-409 G	8212060431	8212060357	82/11/24	50-255 S
8212060064	8212060052	82/11/22	MISC	8212060444	8212060357	82/11/24	50-255 S
8212060073	8212060067	82/11/29	50-285 S	8212060445	8212060440	82/11/10	FOIA
8212060080	8212060074	82/11/29	50-346 Q	8212060506	8212060502	82/09/07	CONTRACT
8212060089	8212060077	82/12/03	50-247 Q	8212060511	8212060509	82/11/26	40-86
8212060101	8212060091	82/11/24	50-333 S	8212070009	8212070004	82/11/30	50-83 R
8212060106	8212060094	82/11/19	50-277 P	8212070012	8212070008	82/11/24	50-325 S
8212060109	8212060094	82/12/01	50-277 P	8212070021	8212070014	82/11/30	50-219 Q
8212060120	8212060114	82/11/30	CONTRACT	8212070024	8212070018	82/12/02	50-395 Q
8212060137	8212060130	82/11/16	50-261 P	8212070030	8212070018	82/12/02	50-395 Q
8212060152	8212060146	82/11/22	50-247 S	8212070034	8212070018	82/12/02	50-395 Q
8212060159	8212060154	82/11/19	50-361 Q	8212070036	8212070032	82/11/08	QA999
8212060161	8212060156	82/11/19	50-206 Q	8212070068	8212070062	82/11/18	50-289 H
8212060164	8212060155	82/11/23	50-275 Q	8212070081	8212070073	82/11/26	50-247 Q
8212060167	8212060163	82/11/16	50-312 Q	8212070083	8212070077	82/10/20	50-247 Q
8212060168	8212060156	82/11/19	50-206 Q	8212070095	8212070094	82/12/01	50-244 P
8212060170	8212060166	82/11/19	50-362 Q	8212070096	8212070090	82/11/23	COMMISSION
8212060171	8212060163	82/11/16	50-312 Q	8212070098	8212070094	82/12/01	50-244 P
8212060174	8212060165	82/11/17	50-311 S	8212070111	8212070106	82/11/23	50-320 Q
8212060175	8212060169	82/11/24	50-244 S	8212070113	8212070105	82/11/24	50-317 P
8212060177	8212060155	82/11/23	50-275 Q	8212070117	8212070116	82/11/16	QA999
8212060178	8212060173	82/11/12	50-243 Q	8212070118	8212070112	82/11/24	50-325 S
8212060181	8212060172	82/12/01	50-254 F	8212070122	8212070116	82/11/16	QA999
8212060190	8212060187	82/11/22	50-423 Q	8212070123	8212070119	82/11/17	50-382 Q
8212060192	8212060189	82/11/22	50-412 Q	8212070130	8212070126	82/11/11	50-112 Q
8212060197	8212060191	82/11/23	50-254 Q	8212070133	8212070126	82/11/11	50-112 Q
8212060200	8212060198	82/11/26	50-293 S	8212070136	8212070120	82/11/23	50-322 Q
8212060201	8212060199	82/12/03	50-261 R	8212070141	8212070137	82/12/01	50-298 Q
8212060206	8212060196	82/11/24	50-317 S	8212070146	8212070033	82/11/24	50-312 Q
8212060208	8212060205	82/11/22	50-397 Q	8212070148	8212070144	82/11/23	50-309 Q
8212060212	8212060209	82/11/22	MISC	8212070150	8212070145	82/11/22	50-285 Q
8212060214	8212060202	82/11/17	50-311 S	8212070154	8212070151	82/11/23	50-387 Q
8212060217	8212060215	82/11/22	50-309 Q	8212070158	8212070151	82/11/23	50-387 Q
8212060220	8212060210	82/11/26	50-293 S	8212070159	8212070156	82/11/15	QA999
8212060224	8212060221	82/11/24	50-331 S	8212070161	8212070157	82/12/06	50-454 Q
8212060230	8212060226	82/12/01	50-112 V	8212070162	8212070156	82/11/15	QA999
8212060231	8212060223	82/11/24	50-333 S	8212070169	8212070156	82/11/15	QA999
8212060233	8212060226	82/12/01	50-112 V	8212070182	8212070173	82/11/22	50-54 P
8212060237	8212060235	82/11/22	50-247 Q	8212070187	8212070177	82/11/29	50-454 A
8212060238	8212060232	82/11/19	50-295 Q	8212070193	8212070190	82/12/03	50-454 P
8212060243	8212060244	82/11/23	50-369 P	8212070198	8212070177	82/11/29	50-454 A
8212060250	8212060249	82/11/16	50-409 Q	8212070201	8212070192	82/12/01	50-235 P
8212060252	8212060249	82/11/16	50-409 Q	8212070206	8212070195	82/12/02	50-338 Q
8212060255	8212060232	82/11/19	50-295 Q	8212070207	8212070177	82/11/29	50-454 A
8212060259	8212060234	82/11/22	50-322 Q	8212070210	8212070192	82/12/01	50-255 P
8212060261	8212060251	82/11/22	50-275 Q	8212070214	8212070208	82/11/24	50-325 S
8212060264	8212060260	82/11/15	50-508 Q	8212070228	8212070223	82/12/03	50-382 Q
8212060268	8212060266	82/12/01	50-285 Q	8212070231	8212070225	82/11/18	50-361 S
8212060272	8212060270	82/11/29	50-293 F	8212070253	8212070251	82/12/02	50-289 F
8212060274	8212060260	82/11/15	50-508 Q	8212070256	8212070255	82/11/17	50-267 Q
8212060276	8212060269	82/12/02	50-206 P	8212070259	8212070252	82/11/18	50-361 S
8212060281	8212060278	82/11/22	50-272 Q	8212070260	8212070255	82/11/17	50-267 Q
8212060287	8212060278	82/11/22	50-272 Q	8212070263	8212070262	82/11/29	50-498 K
8212060293	8212060285	82/12/02	50-317 Q	8212070265	8212070264	82/11/23	50-352 Q
8212060296	8212060292	82/11/23	50-333 S	8212070269	8212070264	82/11/23	50-361 S
8212060298	8212060291	82/11/17	50-272 S	8212070275	8212070273	82/11/24	50-324 S
8212060300	8212060294	82/11/19	50-312 S	8212070276	8212070274	82/12/03	50-416 P
8212060304	8212060297	82/11/12	CONTRACT	8212070278	8212070274	82/12/03	50-416 P
8212060306	8212060301	82/11/24	50-317 S	8212070287	8212070283	82/11/19	50-361 S
8212060308	8212060302	82/11/17	50-272 S	8212070293	8212070280	82/11/19	50-361 S
8212060313	8212060310	82/11/16	50-269 P	8212070294	8212070281	82/11/19	50-361 S
8212060315	8212060303	82/12/01	50-280 Q	8212070303	8212070247	82/12/03	50-155 Q
8212060316	8212060309	82/11/24	50-272 S	8212070304	8212070301	82/11/10	QA999
8212060324	8212060318	82/11/30	50-331 Q	8212070319	8212070316	82/11/30	50-344 P
8212060326	8212060322	82/11/22	50-320 Q	8212070329	8212070324	82/11/24	50-361 S
8212060336	8212060330	82/11/18	40-8743	8212070330	8212070327	82/12/03	50-155 Q
8212060339	8212060338	82/11/24	50-280 F	8212070331	8212070328	82/12/06	50-528 K
8212060364	8212060353	82/11/15	50-275 Q	8212070337	8212070327	82/12/03	50-155 Q
8212060371	8212060357	82/11/24	50-255 S	8212070340	8212070327	82/12/03	50-155 Q
8212060382	8212060357	82/11/24	50-255 S	8212070345	8212070327	82/12/03	50-155 Q
8212060386	8212060379	82/11/16	50-416 P	8212070346	8212070343	82/08/05	50-344 R
8212060391	8212060384	82/11/15	50-344 Q	8212070348	8212070341	82/12/01	50-269 P
8212060392	8212060357	82/11/24	50-255 S	8212070349	8212070327	82/12/03	50-155 Q
8212060396	8212060357	82/11/24	50-255 S	8212070351	8212070342	82/11/22	COMMISSION
8212060403	8212060395	82/11/08	50-320 P	8212070352	8212070327	82/12/03	50-155 Q
8212060412	8212060357	82/11/24	50-255 S	8212070353	8212070341	82/12/01	50-269 P
8212060413	8212060405	82/11/17	CONTRACT	8212070359	8212070342	82/11/22	COMMISSION
8212060421	8212060357	82/11/24	50-255 S	8212070360	8212070350	82/11/24	50-361 S

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

489

ACCESSION NUMBER				ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
0212070365	0212070358	02/12/03	50-440 Q	0212080101	0212080006	02/10/25	FOIA
0212070368	0212070342	02/11/22	COMMISSION	0212080103	0212080090	02/11/10	CONTRACT
0212070372	0212070342	02/11/22	COMMISSION	0212080104	0212080006	02/10/25	FOIA
0212070374	0212070369	02/11/24	50-361 S	0212080105	0212080006	02/10/25	70-143
0212070378	0212070342	02/11/22	COMMISSION	0212080108	0212080100	02/12/02	50-259 F
0212070388	0212070379	02/11/19	50-361 S	0212080109	0212080006	02/10/25	FOIA
0212070392	0212070341	02/12/01	50-269 P	0212080111	0212080006	02/10/25	FOIA
0212070395	0212070341	02/12/01	50-269 P	0212080112	0212080100	02/12/02	50-259 F
0212070399	0212070383	02/11/18	50-361 S	0212080113	0212080006	02/10/25	70-143
0212070412	0212070406	02/11/22	50-361 S	0212080116	0212080006	02/10/25	FOIA
0212070418	0212070414	02/11/12	QA999	0212080117	0212080006	02/10/25	70-143
0212070422	0212070414	02/11/12	QA999	0212080126	0212080006	02/10/25	FOIA
0212070429	0212070424	02/11/17	CONTRACT	0212080129	0212080006	02/10/25	70-143
0212070432	0212070425	02/11/05	50-298 F	0212080133	0212080006	02/10/25	FOIA
0212070434	0212070414	02/11/12	QA999	0212080137	0212080006	02/10/25	FOIA
0212070437	0212070425	02/11/05	50-298 F	0212080137	0212080006	02/10/25	FOIA
0212070441	0212070425	02/11/05	50-298 F	0212080142	0212080006	02/10/25	FOIA
0212070443	0212070425	02/11/05	50-298 Q	0212080146	0212080006	02/10/25	FOIA
0212070444	0212070425	02/11/05	50-298 Q	0212080149	0212080006	02/10/25	FOIA
0212070447	0212070425	02/11/05	50-298 Q	0212080154	0212080006	02/10/25	70-143
0212070452	0212070425	02/11/05	50-298 Q	0212080161	0212080006	02/10/25	FOIA
0212070453	0212070450	02/11/29	CONTRACT	0212080167	0212080006	02/10/25	FOIA
0212070455	0212070425	02/11/05	50-298 P	0212080174	0212080169	02/12/06	50-409 P
0212070457	0212070425	02/11/05	50-298 P	0212080178	0212080169	02/12/06	50-409 P
0212070467	0212070425	02/11/05	50-298 P	0212080188	0212080179	02/12/06	50-528 A
0212070473	0212070425	02/11/05	50-267 F	0212080195	0212080179	02/12/06	50-528 A
0212070476	0212070469	02/11/29	XPORLTIC	0212080200	0212080194	02/10/29	50-187 R
0212070478	0212070472	02/11/30	50-295 P	0212080204	0212080179	02/12/06	50-528 A
0212070482	0212070472	02/11/30	50-295 P	0212080211	0212080206	02/12/03	50-219 P
0212070491	0212070425	02/11/05	50-298 F	0212080245	0212080235	02/12/06	50-454 Q
0212070496	0212070425	02/11/05	50-298 T	0212080250	0212080228	02/11/22	50-409 P
0212070498	0212070492	02/11/29	50-305 P	0212080263	0212080240	02/11/23	50-219 S
0212070500	0212070425	02/11/05	50-298 P	0212080271	0212080261	02/11/30	50-255 S
0212070501	0212070492	02/11/29	50-305 P	0212080291	0212170369	02/11/30	50-266 Q
0212070503	0212070469	02/11/29	XPORLTIC	0212080296	0212080282	02/11/12	50-295 Q
0212070504	0212070492	02/11/29	50-305 P	0212080301	0212080293	02/12/06	50-440 Q
0212080008	0212080006	02/10/25	FOIA	0212080303	0212080293	02/11/29	50-387 S
0212080009	0212080005	02/11/23	COMMISSION	0212080311	0212080297	02/11/28	50-247 S
0212080010	0212080006	02/10/25	FOIA	0212080317	0212080308	02/11/30	50-373 S
0212080011	0212080006	02/10/25	FOIA	0212080323	0212080314	02/12/03	50-277 Q
0212080013	0212080006	02/10/25	FOIA	0212080328	0212080320	02/11/29	50-387 S
0212080017	0212080006	02/10/25	FOIA	0212080329	0212080321	02/12/03	50-443 Q
0212080018	0212080006	02/10/25	70-143	0212080332	0212080318	02/12/01	50-373 S
0212080020	0212080016	02/12/02	XPORLTIC	0212080342	0212080333	02/11/29	50-387 S
0212080024	0212080022	02/11/26	CONTRACT	0212080354	0212080347	02/12/03	50-219 Q
0212080025	0212080023	02/11/19	COMMISSION	0212080359	0212080349	02/11/24	50-219 S
0212080027	0212080006	02/10/25	FOIA	0212080364	0212080356	02/11/24	50-272 S
0212080028	0212080006	02/10/25	FOIA	0212080372	0212080362	02/11/30	50-387 S
0212080030	0212080006	02/10/25	FOIA	0212080378	0212080369	02/11/30	50-387 S
0212080032	0212080006	02/10/25	FOIA	0212080381	0212080375	02/11/04	50-249 S
0212080034	0212080031	02/11/19	50-318 Q	0212080386	0212080382	02/12/01	50-387 S
0212080040	0212080031	02/11/19	50-318 Q	0212080389	0212080376	02/12/03	50-29 P
0212080041	0212080006	02/10/25	FOIA	0212080395	0212080388	02/11/24	50-219 S
0212080044	0212080006	02/10/25	FOIA	0212080399	0212080376	02/12/03	50-29 P
0212080049	0212080045	02/11/26	70-27	0212080402	0212080398	02/11/22	50-546 Q
0212080051	0212080006	02/10/25	FOIA	0212080403	0212080376	02/12/03	50-29 P
0212080056	0212080006	02/10/25	FOIA	0212080404	0212080390	02/11/30	50-265 S
0212080058	0212080006	02/10/25	FOIA	0212080406	0212080394	02/12/01	50-333 Q
0212080061	0212080006	02/10/25	FOIA	0212080407	0212080398	02/11/22	50-546 Q
0212080063	0212080057	02/12/02	50-275 F	0212080410	0212080400	02/11/29	50-373 S
0212080065	0212080006	02/10/25	FOIA	0212080413	0212080412	02/11/30	50-373 S
0212080066	0212080006	02/10/25	FOIA	0212080415	0212080414	02/12/03	50-326 S
0212080070	0212080006	02/10/25	FOIA	0212080429	0212080420	02/11/30	50-282 S
0212080071	0212080057	02/12/02	50-275 F	0212080440	0212080419	02/11/25	50-334 S
0212080076	0212080006	02/10/25	FOIA	0212080443	0212080434	02/11/24	50-311 S
0212080077	0212080060	02/11/24	50-364 P	0212080448	0212080441	02/11/29	50-317 S
0212080079	0212080006	02/10/25	FOIA	0212080453	0212080445	02/12/03	50-245 S
0212080080	0212080060	02/11/24	50-364 P	0212080459	0212080449	02/12/02	50-213 S
0212080081	0212080006	02/10/25	FOIA	0212080460	0212080474	02/11/23	50-334 P
0212080082	0212080074	02/12/01	50-313 F	0212080484	0212080474	02/11/23	50-334 P
0212080083	0212080060	02/11/24	50-364 P	0212080497	0212080431	02/11/26	50-324 S
0212080084	0212080006	02/10/25	FOIA	0212080503	0212080494	02/12/02	50-454 Q
0212080089	0212080074	02/12/01	50-313 F	0212080515	0212080509	02/11/22	50-155 Q
0212080088	0212080006	02/10/25	70-143	0212080522	0212080509	02/11/22	50-155 Q
0212080091	0212080089	02/12/02	50-315 F	0212080524	0212080508	02/11/30	50-373 S
0212080092	0212080006	02/10/25	FOIA	0212080525	0212080511	02/11/22	50-219 S
0212080093	0212080006	02/10/25	70-143	0212080530	0212080526	02/11/26	50-334 S
0212080095	0212080006	02/10/25	FOIA	0212080532	0212080527	02/11/29	50-443 M
0212080096	0212080089	02/12/02	50-315 F	0212080551	0212080545	02/11/23	50-443 A
0212080099	0212080006	02/10/25	70-143	0212080557	0212080561	02/11/22	50-461 Q

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSION NUMBER					ACCESSION NUMBER				
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY		ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	
8212080569	8212080560	82/12/03	50-443 A		8212090194	8212090188	82/12/06	50-329 T	
8212080573	8212080561	82/11/22	50-461 Q		8212090195	8212090191	82/12/02	50-416 S	
8212080577	8212080572	82/12/03	CONTRACT		8212090197	8212090187	82/11/19	50-369 Q	
8212080583	8212080580	82/12/02	CONTRACT		8212090198	8212090187	82/11/19	50-369 Q	
8212080597	8212080595	82/12/03	50-358 R		8212090201	8212090196	82/12/07	50-440 Q	
8212080633	8212080630	82/12/02	50-546 F		8212090204	8212090187	82/11/19	50-369 Q	
8212080637	8212080630	82/12/02	50-546 F		8212090206	8212090196	82/12/07	50-440 Q	
8212080649	8212080643	82/11/23	50-346 F		8212090207	8212090202	82/11/30	50-321 S	
8212080652	8212080643	82/11/23	50-346 F		8212090209	8212090048	82/10/20	FOIA	
8212080664	8212080662	82/11/24	50-373 P		8212090210	8212090048	82/10/20	FOIA	
8212080669	8212080662	82/11/24	50-373 P		8212090213	8212090211	82/11/19	50-389 Q	
8212080670	8212080662	82/11/24	50-373 P		8212090217	8212090215	82/11/19	50-280 Q	
8212080671	8212080654	82/11/30	70-698		8212090218	8212090215	82/11/19	50-280 Q	
8212080673	8212080662	82/11/24	50-373 P		8212090219	8212090216	82/11/23	50-321 S	
8212080684	8212080672	82/12/03	50-322 H		8212090220	8212090215	82/11/19	50-280 Q	
8212080689	8212080672	82/12/03	50-322 H		8212090223	8212090215	82/11/19	50-280 Q	
8212080695	8212080654	82/11/30	70-698		8212090224	8212090049	82/10/20	FOIA	
8212090005	8212090020	82/12/09	50-289 P		8212090225	8212090221	82/12/01	50-287 S	
8212090010	8212090008	82/11/30	50-263 P		8212090226	8212090215	82/11/19	50-280 Q	
8212090011	8212090009	82/12/01	50-263 P		8212090230	8212090048	82/10/20	FOIA	
8212090012	8212090008	82/11/30	50-263 P		8212090234	8212090215	82/11/19	50-280 Q	
8212090023	8212090008	82/11/30	50-263 P		8212090236	8212090231	82/12/08	50-454 Q	
8212090026	8212090008	82/11/30	50-263 P		8212090237	8212090229	82/11/10	50-400 Q	
8212090028	8212090027	82/12/02	50-358 F		8212090239	8212090232	82/11/18	50-413 Q	
8212090031	8212090027	82/12/02	50-358 F		8212090240	8212090235	82/11/05	State Prog	
8212090033	8212090030	82/12/03	50-335 P		8212090244	8212090229	82/11/10	50-400 Q	
8212090034	8212090027	82/12/02	50-358 F		8212090245	8212090227	82/11/03	50-424 Q	
8212090035	8212090030	82/12/03	50-335 P		8212090246	8212090232	82/11/18	50-413 Q	
8212090036	8212090032	82/11/30	50-317 P		8212090249	8212090229	82/11/10	50-400 Q	
8212090037	8212090030	82/12/03	50-335 P		8212090251	8212090232	82/11/18	50-413 Q	
8212090043	8212090040	82/12/03	50-346 P		8212090253	8212090243	82/12/02	50-395 S	
8212090052	8212090048	82/10/20	FOIA		8212090254	8212090247	82/11/23	50-366 S	
8212090053	8212090050	82/11/30	50-318 P		8212090256	8212090229	82/11/10	50-400 Q	
8212090056	8212090055	82/11/30	50-518 A		8212090258	8212090248	82/11/02	50-424 Q	
8212090059	8212090055	82/11/30	50-518 A		8212090261	8212090232	82/11/18	50-413 Q	
8212090059	8212090057	82/12/03	50-282 P		8212090265	8212090252	82/11/02	70-824	
8212090064	8212090063	82/12/01	50-338 S		8212090270	8212090264	82/11/04	70-1113	
8212090065	8212090048	82/10/20	FOIA		8212090271	8212090262	82/11/17	50-370 Q	
8212090069	8212090066	82/12/03	50-329 A		8212090274	8212090263	82/11/16	70-1201	
8212090071	8212090068	82/12/06	70-1359		8212090275	8212090268	82/10/26	50-389 Q	
8212090072	8212090067	82/12/01	50-339 S		8212090277	8212090267	82/10/26	50-280 Q	
8212090075	8212090074	82/12/02	50-416 S		8212090278	8212090269	82/12/01	70-1151	
8212090081	8212090078	82/12/01	50-416 S		8212090286	8212090276	82/11/18	50-280 Q	
8212090089	8212090083	82/12/03	50-259 P		8212090287	8212090272	82/12/01	50-339 S	
8212090091	8212090086	82/11/30	50-280 S		8212090288	8212090281	82/11/16	50-261 Q	
8212090092	8212090080	82/12/06	50-259 Q		8212090289	8212090273	82/11/16	50-324 Q	
8212090096	8212090094	82/12/03	50-358 K		8212090290	8212090282	82/12/01	50-416 Q	
8212090098	8212090086	82/11/30	50-280 S		8212090291	8212090280	82/12/03	50-259 S	
8212090105	8212090100	82/12/01	50-325 S		8212090293	8212090284	82/11/30	50-289 P	
8212090107	8212090102	82/11/29	50-339 S		8212090294	8212090292	82/11/16	70-824	
8212090108	8212090080	82/12/06	50-259 Q		8212090297	8212090284	82/11/30	50-289 P	
8212090113	8212090110	82/12/01	50-416 S		8212090298	8212090285	82/11/03	50-280 Q	
8212090115	8212090112	82/11/30	50-338 S		8212090299	8212090273	82/11/16	50-324 Q	
8212090116	8212090109	82/11/30	50-259 S		8212090300	8212090276	82/11/18	50-280 Q	
8212090124	8212090080	82/12/06	50-259 Q		8212090303	8212090282	82/12/01	50-416 Q	
8212090126	8212090121	82/11/30	50-366 S		8212090304	8212090276	82/11/18	50-280 Q	
8212090129	8212090120	82/11/30	50-261 S		8212090306	8212090285	82/11/03	50-280 Q	
8212090134	8212090130	82/12/03	50-281 S		8212090308	8212090302	82/11/02	50-335 Q	
8212090136	8212090131	82/12/01	50-416 S		8212090309	8212090273	82/11/16	50-324 Q	
8212090137	8212090130	82/12/03	50-281 S		8212090310	8212090282	82/12/01	50-416 Q	
8212090139	8212090135	82/12/03	50-325 S		8212090312	8212090295	82/12/01	50-364 S	
8212090144	8212090130	82/12/03	50-281 S		8212090313	8212090276	82/11/18	50-280 Q	
8212090145	8212090140	82/11/30	50-321 S		8212090316	8212090282	82/12/01	50-416 Q	
8212090149	8212090142	82/11/23	50-366 S		8212090318	8212090314	82/12/03	50-324 S	
8212090152	8212090147	82/12/03	50-325 S		8212090319	8212090315	82/11/08	State Prog	
8212090153	8212090143	82/11/30	50-260 S		8212090320	8212090282	82/12/01	50-416 Q	
8212090155	8212090148	82/11/30	TOPREP		8212090321	8212090273	82/11/16	50-324 Q	
8212090158	8212090151	82/12/02	50-416 S		8212090324	8212090317	82/11/19	50-413 Q	
8212090164	8212090159	82/12/02	50-416 S		8212090328	8212090322	82/12/06	50-331 P	
8212090169	8212090166	82/12/06	50-280 Q		8212090332	8212090282	82/12/01	50-416 Q	
8212090173	8212090167	82/11/29	50-325 S		8212090335	8212090329	82/11/30	50-366 S	
8212090175	8212090166	82/12/06	50-280 Q		8212090336	8212090331	82/11/02	50-389 S	
8212090178	8212090174	82/12/02	50-328 S		8212090338	8212090325	82/12/03	50-254 Q	
8212090180	8212090166	82/12/06	50-280 Q		8212090340	8212090333	82/11/02	70-1201	
8212090184	8212090177	82/12/01	50-416 S		8212090341	8212090330	82/11/23	50-321 S	
8212090185	8212090166	82/12/06	50-280 Q		8212090344	8212090326	82/12/01	50-416 S	
8212090186	8212090183	82/10/26	50-400 Q		8212090347	8212090334	82/11/29	50-390 Q	
8212090189	8212090181	82/10/29	50-269 Q		8212090351	8212090345	82/11/03	50-261 Q	
8212090192	8212090187	82/11/19	50-369 Q		8212090352	8212090343	82/12/03	50-263 Q	
8212090193	8212090190	82/12/02	50-366 S		8212090355	8212090348	82/10/27	50-400 Q	

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

491

ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8212090360	8212090353	82/11/03	50-389 Q
8212090364	8212090357	82/10/28	50-417 Q
8212090365	8212090354	82/11/30	50-327 Q
8212090367	8212090361	82/12/03	50-259 S
8212090370	8212090354	82/11/30	50-327 Q
8212090371	8212090356	82/12/02	50-250 S
8212090372	8212090366	82/12/03	50-395 S
8212090378	8212090354	82/11/30	50-327 Q
8212090380	8212090373	82/11/04	50-369 Q
8212090382	8212090377	82/12/06	50-448 K
8212090384	8212090354	82/11/30	50-327 Q
8212090388	8212090381	82/11/23	50-366 S
8212090391	8212090386	82/11/23	50-366 S
8212090393	8212090385	82/11/17	70-143 Q
8212090396	8212090387	82/12/03	50-155 Q
8212090399	8212090389	82/11/30	50-366 S
8212090407	8212090400	82/11/01	50-390 Q
8212090410	8212090403	82/12/01	50-335 S
8212090411	8212090404	82/11/09	50-389 Q
8212090413	8212090402	82/11/26	70-143 Q
8212090416	8212090408	82/11/30	70-143 Q
8212090421	8212090414	82/11/01	50-416 Q
8212090427	8212090414	82/11/01	50-416 Q
8212090438	8212090422	82/12/01	50-395 S
8212090439	8212090430	82/11/19	70-27 Q
8212090440	8212090433	82/12/03	50-409 Q
8212090444	8212090438	82/11/08	50-395 Q
8212090445	8212090428	82/11/17	70-1151 Q
8212090446	8212090437	82/11/30	50-366 S
8212090451	8212090447	82/11/05	50-332 Q
8212090454	8212090398	82/11/08	50-395 Q
8212090460	8212090449	82/12/02	50-395 S
8212090461	8212090456	82/11/12	50-259 Q
8212090463	8212090453	82/12/03	50-325 S
8212090465	8212090459	82/11/15	50-413 Q
8212090467	8212090456	82/11/12	50-259 Q
8212090471	8212090456	82/11/12	50-259 Q
8212090476	8212090470	82/11/05	State Prog
8212090479	8212090456	82/11/12	50-259 Q
8212090481	8212090470	82/11/05	State Prog
8212090485	8212090478	82/11/12	50-338 Q
8212090489	8212090477	82/11/22	70-824 Q
8212090491	8212090478	82/11/12	50-338 Q
8212090493	8212090486	82/11/02	50-327 Q
8212090496	8212090478	82/11/12	50-338 Q
8212090499	8212090477	82/11/22	70-824 Q
8212090500	8212090490	82/11/12	50-250 Q
8212090503	8212090497	82/11/16	50-250 Q
8212090504	8212090497	82/11/03	50-390 Q
8212090505	8212090478	82/11/12	50-338 Q
8212090508	8212090501	82/12/03	50-289 P
8212090510	8212090487	82/11/16	50-250 Q
8212090516	8212090509	82/11/29	50-395 Q
8212090517	8212090507	82/11/12	70-143 Q
8212090518	8212090487	82/11/16	50-250 Q
8212090519	8212090511	82/11/17	50-348 Q
8212090521	8212090515	82/11/09	50-338 Q
8212090524	8212090487	82/11/16	50-250 Q
8212090526	8212090520	82/12/01	50-334 P
8212090530	8212090509	82/11/29	50-395 Q
8212090534	8212090509	82/11/29	50-395 Q
8212090536	8212090528	82/11/12	50-438 Q
8212090537	8212090531	82/11/02	50-339 Q
8212090538	8212090527	82/12/01	50-338 S
8212090539	8212090533	82/11/12	70-143 Q
8212090540	8212090529	82/10/29	50-250 Q
8212090542	8212090535	82/11/29	50-325 S
8212090545	8212090509	82/11/29	50-395 Q
8212090547	8212090544	82/11/29	50-335 Q
8212090550	8212090543	82/11/29	50-325 S
8212090552	8212090546	82/12/03	50-528 Q
8212090554	8212090544	82/11/29	50-335 Q
8212090555	8212090547	82/11/17	70-1151 Q
8212090556	8212090551	82/12/01	50-328 S
8212090558	8212090544	82/11/29	50-335 Q
8212090559	8212090553	82/11/17	50-335 Q
8212090560	8212090544	82/11/29	50-335 Q
8212090561	8212090553	82/11/17	50-335 Q
8212090562	8212090544	82/11/29	50-335 Q
8212090563	8212090553	82/11/17	50-335 Q

ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8212090564	8212090553	82/11/17	50-335 Q
8212100005	8212100003	82/12/06	0A999 Q
8212100010	8212100007	82/11/24	50-317 Q
8212100013	8212100007	82/11/24	50-317 Q
8212100019	8212100016	82/11/24	50-263 Q
8212100023	8212100016	82/11/24	50-263 Q
8212100041	8212100038	82/12/06	50-334 Q
8212100045	8212100042	82/12/07	50-329 U
8212100055	8212100051	82/11/18	FOIA
8212100056	8212100048	82/12/08	50-329 T
8212100062	8212100057	82/11/30	71-206 Q
8212100064	8212100059	82/11/26	50-387 Q
8212100069	8212100066	82/11/30	71-370 Q
8212100077	8212100048	82/12/08	50-329 T
8212100079	8212100079	82/12/08	50-278 P
8212100081	8212100073	82/11/24	50-219 Q
8212100085	8212100082	82/12/06	50-324 P
8212100086	8212100084	82/11/01	FOIA
8212100089	8212100084	82/11/01	FOIA
8212100101	8212100094	82/11/30	50-395 P
8212100106	8212100094	82/11/30	50-395 P
8212100109	8212100105	82/11/18	50-443 A
8212100110	8212100094	82/11/30	50-395 P
8212100112	8212100105	82/11/18	50-443 A
8212100114	8212100105	82/11/18	50-443 E
8212100121	8212100111	82/11/12	70-143 Q
8212100128	8212100111	82/11/12	70-143 Q
8212100133	8212100124	82/12/03	CONTRACT
8212100139	8212100111	82/11/12	FOIA
8212100142	8212100111	82/11/12	FOIA
8212100144	8212100141	82/11/23	50-305 Q
8212100147	8212100111	82/11/12	FOIA
8212100149	8212100141	82/11/23	50-305 Q
8212100155	8212100111	82/11/12	FOIA
8212100158	8212100111	82/11/12	FOIA
8212100162	8212100154	82/11/29	CONTRACT
8212100164	8212100111	82/11/12	FOIA
8212100168	8212100111	82/11/12	FOIA
8212100172	8212100167	82/11/29	CONTRACT
8212100179	8212100053	82/11/09	FOIA
8212100180	8212100178	82/12/02	70-1334 Q
8212100185	8212100111	82/11/12	FOIA
8212100189	8212100111	82/11/12	FOIA
8212100200	8212100195	82/11/24	50-367 Q
8212100203	8212100198	82/11/24	50-341 Q
8212100211	8212100208	82/12/03	50-301 S
8212100212	8212100197	82/11/24	50-298 Q
8212100213	8212100197	82/11/24	50-298 Q
8212100216	8212100215	82/11/24	50-237 S
8212100220	8212100219	82/12/03	50-250 S
8212100222	8212100221	82/12/07	50-266 Q
8212100223	8212100221	82/12/07	50-266 Q
8212100225	8212100224	82/12/03	50-266 S
8212100230	8212100226	82/11/24	50-461 Q
8212100233	8212100228	82/11/09	50-285 Q
8212100235	8212100229	82/12/02	50-346 S
8212100238	8212100234	82/11/26	50-483 Q
8212100239	8212100236	82/12/02	50-458 Q
8212100240	8212100226	82/11/24	50-461 Q
8212100242	8212100234	82/11/26	50-483 Q
8212100244	8212100227	82/12/07	50-285 Q
8212100249	8212100245	82/12/02	70-2872 Q
8212100250	8212100241	82/12/06	50-324 R
8212100257	8212100255	82/11/26	50-346 Q
8212100259	8212100251	82/12/03	50-315 S
8212100263	8212100255	82/11/26	50-346 Q
8212100271	8212100265	82/11/24	50-298 Q
8212100275	8212100272	82/12/02	50-373 S
8212100279	8212100264	82/11/30	50-366 S
8212100284	8212100278	82/11/24	50-301 P
8212100286	8212100282	82/11/30	50-366 S
8212100287	8212100281	82/12/03	50-346 S
8212100300	8212100290	82/12/06	50-315 P
8212100302	8212100296	82/11/23	50-454 Q
8212100303	8212100295	82/12/01	50-331 Q
8212100306	8212100297	82/12/07	50-416 S
8212100308	8212100296	82/11/23	50-454 Q
8212100309	8212100304	82/12/02	50-155 S
8212100314	8212100311	82/11/30	50-366 S
8212100317	8212100313	82/12/02	50-255 S

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSION NUMBER				ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8212100319	8212100312	82/12/01	50-237 S	8212130355	8212130352	82/12/07	50-286 F
8212100327	8212100322	82/12/03	50-315 S	8212130357	8212130352	82/12/07	50-286 F
8212100330	8212100324	82/12/07	50-454 G	8212130359	8212130358	82/12/07	50-352 Q
8212100332	8212100325	82/12/02	50-346 S	8212130361	8212130358	82/12/07	50-352 Q
8212100333	8212100329	82/11/23	50-461 Q	8212130367	8212130366	82/12/06	50-344 P
8212100335	8212100328	82/12/01	50-265 S	8212130369	8212130366	82/12/06	50-344 P
8212100339	8212100329	82/11/23	50-461 G	8212130370	8212130366	82/12/06	50-344 P
8212100349	8212100343	82/11/15	WASTE MOT	8212130372	8212130366	82/12/06	50-344 P
8212100368	8212100361	82/12/03	50-373 P	8212130427	8212130424	82/11/09	70-2926
8212100369	8212100362	82/11/18	FOIA	8212140015	8212140001	82/11/03	FOIA
8212100372	8212100361	82/12/03	50-373 P	8212140022	8212140001	82/11/03	FOIA
8212100383	8212100381	82/11/16	FOIA	8212140031	8212140029	82/12/07	50-220 R
8212100385	8212100380	82/12/07	50-313 F	8212140051	8212140048	82/12/09	50-302 R
8212100394	8212100380	82/12/07	50-313 F	8212140060	8212140033	82/11/24	50-272 S
8212100398	8212100395	82/11/15	FOIA	8212140061	8212140055	82/12/09	50-295 R
8212100406	8212100399	82/12/07	50-344 F	8212140070	8212140064	82/12/09	50-286 R
8212100407	8212100403	82/11/09	40-8768	8212140072	8212140068	82/12/06	50-373 F
8212100410	8212100403	82/11/09	40-8768	8212140082	8212140076	82/11/24	50-272 S
8212100411	8212100399	82/12/07	50-344 F	8212140084	8212140074	82/11/29	50-213 Q
8212100453	8212100414	82/11/30	50-346 P	8212140085	8212140079	82/11/24	50-311 S
8212100474	8212100414	82/11/30	50-346 P	8212140095	8212140067	82/12/06	50-373 S
8212100481	8212100414	82/11/30	50-346 P	8212140105	8212140098	82/11/30	50-271 Q
8212130028	8212130017	82/12/07	50-10 F	8212140107	8212140099	82/11/24	50-311 S
8212130036	8212130033	82/11/30	50-508 K	8212140113	8212140098	82/11/30	50-271 Q
8212130041	8212130017	82/12/07	50-10 F	8212140120	8212140112	82/12/01	50-10 R
8212130060	8212130059	82/12/06	50-320 P	8212140123	8212140115	82/12/07	50-366 S
8212130061	8212130055	82/11/23	71-9151	8212140128	8212140119	82/12/06	50-373 S
8212130067	8212130062	82/11/05	70-27	8212140131	8212140125	82/12/02	50-317 S
8212130071	8212130062	82/11/05	70-27	8212140133	8212140124	82/12/06	50-272 Q
8212130074	8212130068	82/11/30	71-454	8212140138	8212140135	82/12/03	50-387 S
8212130084	8212130081	82/12/07	50-333 R	8212140140	8212140137	82/11/29	50-247 G
8212130093	8212130092	82/11/29	50-309 P	8212140147	8212140142	82/12/03	50-331 S
8212130099	8212130092	82/11/29	50-309 P	8212140149	8212140001	82/11/03	50-29 F
8212130102	8212130092	82/11/29	50-309 P	8212140154	8212140150	82/11/30	50-334 G
8212130117	8212130111	82/11/23	50-346 P	8212140159	8212140153	82/12/06	50-325 S
8212130121	8212130111	82/11/23	50-346 P	8212140160	8212140150	82/11/30	50-334 G
8212130124	8212130111	82/11/23	50-346 P	8212140161	8212140001	82/11/03	FOIA
8212130129	8212130122	82/11/17	71-6495	8212140165	8212140156	82/12/06	50-316 S
8212130137	8212130132	82/12/03	50-346 F	8212140176	8212140171	82/12/03	50-369 S
8212130138	8212130122	82/11/17	71-6495	8212140177	8212140169	82/12/02	50-219 S
8212130144	8212130132	82/12/03	50-346 F	8212140187	8212140184	82/12/03	50-29 S
8212130153	8212130149	82/12/03	50-295 F	8212140189	8212140182	82/12/01	50-387 S
8212130156	8212130149	82/12/03	50-295 F	8212140191	8212140174	82/11/26	50-334 S
8212130160	8212130155	82/12/01	CONTRACT	8212140201	8212140194	82/12/09	50-508 C
8212130162	8212130161	82/12/07	50-361 P	8212140202	8212140196	82/12/06	50-325 S
8212130164	8212130161	82/12/07	50-361 P	8212140207	8212140198	82/12/08	50-328 S
8212130168	8212130161	82/12/07	50-361 P	8212140221	8212140208	82/12/09	50-245 G
8212130171	8212130169	82/11/26	50-275 Q	8212140231	8212140224	82/12/09	50-373 Q
8212130177	8212130175	82/12/06	50-373 R	8212140236	8212140225	82/12/09	50-333 G
8212130182	8212130178	82/11/03	CONTRACT	8212140238	8212140232	82/12/06	50-77 R
8212130185	8212130181	82/12/07	50-400 A	8212140239	8212140228	82/12/02	50-289 S
8212130193	8212130188	82/12/09	50-362 P	8212140247	8212140241	82/12/07	50-327 S
8212130198	8212130188	82/12/09	50-362 P	8212140248	8212140251	82/11/30	70-2895
8212130202	8212130196	82/12/01	50-254 R	8212140256	8212140253	82/12/09	50-329 A
8212130209	8212130207	82/11/29	50-528 Q	8212140257	8212140255	82/12/06	50-324 P
8212130215	8212130207	82/11/29	50-528 Q	8212140260	8212140259	82/12/09	50-29 P
8212130220	8212130217	82/12/01	TOPREP	8212140261	8212140258	82/12/03	50-387 S
8212130227	8212130223	82/12/06	50-29 P	8212140270	8212140265	82/11/30	50-361 S
8212130229	8212130224	82/12/09	50-255 P	8212140271	8212140269	82/11/30	50-321 S
8212130236	8212130231	82/12/03	50-295 P	8212140272	8212140265	82/11/30	50-361 S
8212130240	8212130238	82/12/06	50-182 P	8212140277	8212140276	82/12/08	50-275 P
8212130245	8212130242	82/12/07	50-334 P	8212140285	8212140281	82/12/10	50-275 R
8212130246	8212130241	82/12/03	50-440 Q	8212140292	8212140289	82/12/07	50-373 Q
8212130248	8212130243	82/12/06	50-334 P	8212140312	8212140263	82/12/08	50-413 A
8212130250	8212130247	82/12/06	50-255 R	8212140315	8212140311	82/11/30	50-320 Q
8212130254	8212130252	82/12/10	50-247 Q	8212140318	8212140263	82/12/08	50-413 A
8212130264	8212130243	82/12/06	50-334 P	8212140319	8212140311	82/11/30	50-320 Q
8212130265	8212130243	82/11/29	50-362 Q	8212140325	8212140268	82/12/03	50-387 S
8212130270	8212130267	82/11/24	50-27 Q	8212140327	8212140321	82/12/08	50-295 S
8212130287	8212130265	82/12/03	70-2957	8212140329	8212140326	82/11/23	50-373 Q
8212130289	8212130281	82/12/06	50-275 P	8212140337	8212140322	82/11/29	50-423 Q
8212130293	8212130281	82/12/06	50-275 P	8212140338	8212140332	82/12/03	50-331 S
8212130294	8212130291	82/11/24	50-187 Q	8212140340	8212140335	82/11/30	50-358 A
8212130298	8212130291	82/11/24	50-187 Q	8212140342	8212140335	82/11/30	50-358 A
8212130302	8212130296	82/12/10	TOPREP	8212140355	8212140346	82/11/30	50-344 S
8212130305	8212130281	82/12/06	50-275 P	8212140356	8212140351	82/12/07	50-312 P
8212130317	8212130313	82/12/09	50-261 G	8212140357	8212140344	82/12/06	50-263 S
8212130333	8212130329	82/12/09	50-206 Q	8212140363	8212140351	82/12/07	50-312 P
8212130342	8212130336	82/12/07	50-298 F	8212140367	8212140361	82/12/09	50-329 A
8212130346	8212130336	82/12/07	50-298 F	8212140368	8212140360	82/12/02	50-206 S

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

493

ACCESSION NUMBER				
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	
8212140380	8212140374	82/12/07	50-337 A	
8212140383	8212140381	82/12/10	50-498 C	
8212140388	8212140374	82/12/07	50-537 A	
8212140393	8212140384	82/12/10	50-247 Q	
8212140399	8212140396	82/12/09	50-151 Q	
8212140400	8212140384	82/12/10	50-247 Q	
8212140405	8212140398	82/12/01	50-361 S	
8212140406	8212140397	82/12/07	50-220 Q	
8212140408	8212140404	82/12/08	50-244 P	
8212140413	8212140404	82/12/08	50-244 P	
8212140414	8212140396	82/12/09	50-151 Q	
8212140417	8212140410	82/12/08	50-409 Q	
8212140420	8212140404	82/12/08	50-244 P	
8212140427	8212140424	82/12/07	50-412 Q	
8212140429	8212140421	82/11/30	50-366 S	
8212140434	8212140425	82/11/30	50-369 S	
8212140436	8212140433	82/11/30	50-366 S	
8212140437	8212140426	82/12/09	50-443 Q	
8212140442	8212140435	82/11/24	50-309 F	
8212140444	8212140440	82/12/08	50-259 S	
8212140446	8212140439	82/12/10	50-247 Q	
8212140448	8212140379	82/12/07	50-271 P	
8212140453	8212140435	82/11/24	50-309 F	
8212140486	8212140478	82/11/23	50-259 H	
8212140492	8212140490	82/11/29	50-410 Q	
8212140495	8212140490	82/11/29	50-410 Q	
8212140497	8212140494	82/11/23	50-387 P	
8212140510	8212140501	82/11/11	PROJ	
8212140517	8212140513	82/11/19	71-4909	
8212150005	8212150003	82/12/13	TOPREP	
8212150011	8212150007	82/12/07	50-321 S	
8212150013	8212150008	82/12/09	50-247 T	
8212150018	8212150014	82/12/07	50-321 S	
8212150019	8212150015	82/11/23	50-409 Q	
8212150025	8212150020	82/12/02	50-334 S	
8212150027	8212150023	82/11/29	50-247 S	
8212150034	8212150028	82/12/08	50-338 S	
8212150037	8212150031	82/12/07	50-321 S	
8212150044	8212150038	82/12/01	50-320 S	
8212150047	8212150042	82/12/09	50-382 F	
8212150049	8212150040	82/12/09	50-112 Q	
8212150050	8212150042	82/12/09	50-382 F	
8212150052	8212150048	82/12/08	50-338 P	
8212150053	8212150046	82/12/10	50-302 S	
8212150062	8212150058	82/12/13	50-277 P	
8212150064	8212150060	82/12/10	50-302 S	
8212150069	8212150066	82/12/10	50-259 S	
8212150072	8212150070	82/12/08	50-331 P	
8212150076	8212150071	82/12/09	50-296 S	
8212150078	8212150075	82/12/02	50-334 S	
8212150081	8212150077	82/12/08	50-395 S	
8212150084	8212150080	82/12/01	50-247 S	
8212150087	8212150067	82/12/09	50-281 S	
8212150091	8212150089	82/12/08	50-395 S	
8212150096	8212150094	82/12/08	50-338 S	
8212150100	8212150097	82/12/08	50-395 S	
8212150102	8212150099	82/12/07	50-302 S	
8212150104	8212150101	82/12/10	50-260 S	
8212150108	8212150105	82/12/07	50-302 S	
8212150111	8212150107	82/12/09	50-296 S	
8212150113	8212150110	82/12/10	50-289 P	
8212150114	8212150112	82/12/08	50-325 S	
8212150122	8212150117	82/12/09	50-395 S	
8212150126	8212150121	82/12/10	50-333 Q	
8212150134	8212150129	82/12/07	50-389 A	
8212150137	8212150131	82/12/14	50-382 Q	
8212150140	8212150131	82/12/14	50-382 Q	
8212150142	8212150128	82/12/08	50-245 P	
8212150143	8212150138	82/12/13	70-143 Q	
8212150148	8212150131	82/12/14	50-382 Q	
8212150153	8212150131	82/12/14	50-382 Q	
8212150158	8212150156	82/12/07	50-335 S	
8212150160	8212150155	82/12/06	50-29 S	
8212150163	8212150159	82/12/02	50-309 Q	
8212150169	8212150159	82/12/02	50-309 Q	
8212150170	8212150164	82/12/13	50-275 P	
8212150171	8212150166	82/12/10	50-445 K	
8212150176	8212150174	82/12/09	50-271 R	
8212150183	8212150180	82/12/03	50-250 R	
8212150187	8212150181	82/12/07	50-277 F	

ACCESSION NUMBER				
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	
8212150193	8212150181	82/12/07	50-277 F	
8212150200	8212150195	82/12/10	50-275 P	
8212150206	8212150202	82/11/15	71-9081	
8212150213	8212150207	82/12/10	50-220 Q	
8212150218	8212150212	82/11/24	71-5957	
8212150224	8212150219	82/12/10	50-293 Q	
8212150233	8212150219	82/12/10	50-293 Q	
8212150240	8212150236	82/12/07	50-302 P	
8212150244	8212150238	82/11/22	70-1151	
8212150252	8212150248	82/12/07	50-243 F	
8212150257	8212150248	82/12/07	50-243 F	
8212150280	8212150272	82/12/08	50-313 F	
8212150288	8212150272	82/12/08	50-313 F	
8212150298	8212150293	82/11/17	70-143	
8212150310	8212150301	82/12/08	50-346 F	
8212150329	8212150323	82/12/07	50-315 F	
8212150333	8212150326	82/11/27	NUREG	
8212150335	8212150323	82/12/07	50-315 F	
8212160002	8212160001	82/12/09	50-315 F	
8212160016	8212160012	82/11/23	71-9006	
8212160023	8212160020	82/11/30	71-170	
8212160028	8212160026	82/11/18	71-486	
8212160035	8212160032	82/11/23	71-9099	
8212160041	8212160038	82/11/19	71-6003	
8212160050	8212160043	82/11/01	71-5796	
8212160054	8212160048	82/12/01	50-311 S	
8212160058	8212160055	82/12/10	50-277 F	
8212160067	8212160060	82/10/29	40-3392	
8212160082	8212160080	82/09/30	40-6500	
8212160090	8212160080	82/09/30	FOIA	
8212160094	8212160080	82/09/30	FOIA	
8212160097	8212160080	82/09/30	40-6500	
8212160098	8212160091	82/12/08	50-346 F	
8212160103	8212160080	82/09/30	FOIA	
8212160105	8212160080	82/09/30	40-6500	
8212160107	8212160091	82/12/08	50-346 F	
8212160123	8212160080	82/09/30	40-6500	
8212160131	8212160080	82/09/30	40-6500	
8212160140	8212160080	82/09/30	40-6500	
8212160144	8212160080	82/09/30	40-6500	
8212160148	8212160134	82/11/12	71-454	
8212160160	8212160080	82/09/30	FOIA	
8212160161	8212160080	82/09/30	40-6500	
8212160168	8212160080	82/09/30	40-6500	
8212160182	8212160080	82/09/30	40-6500	
8212160185	8212160177	82/12/03	71-489	
8212160191	8212160080	82/09/30	40-6500	
8212160193	8212160080	82/09/30	40-6500	
8212160197	8212160080	82/09/30	40-6500	
8212160214	8212160080	82/09/30	40-6500	
8212160227	8212160223	82/12/13	50-155 Q	
8212160240	8212160235	82/12/15	50-413 Q	
8212160243	8212160080	82/09/30	40-6500	
8212160260	8212160080	82/09/30	40-6500	
8212160264	8212160080	82/09/30	40-6500	
8212160270	8212160259	81/06/01	50-317 S	
8212160273	8212160080	82/09/30	40-6500	
8212160284	8212160080	82/09/30	40-6500	
8212160307	8212160080	82/09/30	40-6500	
8212160315	8212160080	82/09/30	40-6500	
8212160316	8212160304	82/12/14	50-352 Q	
8212160323	8212160080	82/09/30	FOIA	
8212160329	8212160322	82/12/13	50-395 F	
8212160334	8212160326	82/12/10	50-237 G	
8212160337	8212160080	82/09/30	40-3265	
8212160341	8212160080	82/09/30	40-3265	
8212160343	8212160080	82/09/30	FOIA	
8212160346	8212160339	82/12/08	50-334 P	
8212160350	8212160080	82/09/30	40-3265	
8212160352	8212160080	82/09/30	40-6500	
8212160362	8212160080	82/09/30	40-6500	
8212160370	8212160080	82/09/30	40-6500	
8212160371	8212160358	82/12/10	50-245 S	
8212160372	8212160080	82/09/30	FOIA	
8212160380	8212160080	82/09/30	FOIA	
8212160386	8212160080	82/09/30	FOIA	
8212160388	8212160080	82/09/30	40-6500	
8212160390	8212160381	82/12/01	50-311 S	
8212160391	8212160080	82/09/30	FOIA	
8212160406	8212160397	82/12/03	50-289 Q	

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8212100319	8212100312	82/12/01	50-237 S
8212100327	8212100322	82/12/03	50-313 S
8212100330	8212100324	82/12/07	50-434 Q
8212100332	8212100325	82/12/02	50-346 S
8212100333	8212100329	82/11/23	50-461 Q
8212100335	8212100328	82/12/01	50-265 S
8212100339	8212100329	82/11/23	50-461 Q
8212100349	8212100343	82/11/15	WASTE MAT
8212100368	8212100361	82/12/03	50-373 P
8212100369	8212100362	82/11/18	FOIA
8212100372	8212100361	82/12/03	50-373 P
8212100383	8212100381	82/11/16	FOIA
8212100385	8212100380	82/12/07	50-313 F
8212100394	8212100380	82/12/07	50-313 F
8212100398	8212100395	82/11/15	FOIA
8212100406	8212100399	82/12/07	50-344 F
8212100407	8212100403	82/11/09	40-8768
8212100410	8212100403	82/11/09	40-8768
8212100411	8212100399	82/12/07	50-344 F
8212100453	8212100414	82/11/30	50-346 P
8212100474	8212100414	82/11/30	50-346 P
8212100481	8212100414	82/11/30	50-346 P
8212100028	8212100017	82/12/07	50-10 F
8212100036	8212100033	82/11/30	50-508 K
8212100041	8212100017	82/12/07	50-10 F
8212100060	8212100059	82/12/06	50-320 P
8212100061	8212100055	82/11/23	71-9151
8212100067	8212100062	82/11/05	70-27
8212100071	8212100062	82/11/05	70-27
8212100074	8212100068	82/11/30	71-454
8212100084	8212100081	82/12/07	50-333 R
8212100095	8212100092	82/11/29	50-309 P
8212100099	8212100092	82/11/29	50-309 P
8212100102	8212100092	82/11/29	50-309 P
8212100117	8212100111	82/11/23	50-346 P
8212100121	8212100111	82/11/23	50-346 P
8212100124	8212100111	82/11/23	50-346 P
8212100129	8212100122	82/11/17	71-6495
8212100137	8212100132	82/12/03	50-346 F
8212100138	8212100122	82/11/17	71-6495
8212100144	8212100132	82/12/03	50-346 F
8212100153	8212100149	82/12/03	50-295 F
8212100156	8212100149	82/12/03	50-295 F
8212100160	8212100155	82/12/01	CONTRACT
8212100162	8212100161	82/12/07	50-361 P
8212100164	8212100161	82/12/07	50-361 P
8212100168	8212100161	82/12/07	50-361 P
8212100171	8212100169	82/11/26	50-275 Q
8212100177	8212100175	82/12/06	50-373 R
8212100182	8212100178	82/11/03	CONTRACT
8212100185	8212100181	82/12/07	50-400 A
8212100193	8212100188	82/12/09	50-362 P
8212100198	8212100188	82/12/09	50-362 P
8212100202	8212100196	82/12/01	50-254 R
8212100209	8212100207	82/11/29	50-528 Q
8212100215	8212100207	82/11/29	50-528 Q
8212100220	8212100217	82/12/01	TOPREP
8212100227	8212100223	82/12/06	50-29 P
8212100229	8212100224	82/12/09	50-255 P
8212100236	8212100231	82/12/03	50-295 P
8212100240	8212100238	82/12/06	50-182 P
8212100245	8212100242	82/12/07	50-334 P
8212100246	8212100241	82/12/03	50-440 Q
8212100248	8212100243	82/12/06	50-334 Q
8212100250	8212100247	82/12/06	50-255 R
8212100254	8212100252	82/12/10	50-247 Q
8212100264	8212100249	82/12/06	50-334 P
8212100265	8212100263	82/11/29	50-362 Q
8212100270	8212100269	82/11/24	50-27 Q
8212100287	8212100285	82/12/03	70-2957
8212100289	8212100281	82/12/06	50-275 P
8212100293	8212100281	82/12/06	50-275 P
8212100294	8212100291	82/11/24	50-187 Q
8212100298	8212100291	82/11/24	50-187 Q
8212100302	8212100296	82/12/10	TOPREP
8212100305	8212100281	82/12/06	50-275 P
8212100317	8212100313	82/12/09	50-261 Q
8212100333	8212100329	82/12/09	50-206 Q
8212100342	8212100336	82/12/07	50-298 F
8212100346	8212100336	82/12/07	50-298 F

ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8212100355	8212100352	82/12/07	50-286 F
8212100357	8212100352	82/12/07	50-286 F
8212100359	8212100358	82/12/07	50-352 O
8212100361	8212100358	82/12/07	50-352 O
8212100367	8212100366	82/12/06	50-344 P
8212100369	8212100366	82/12/06	50-344 P
8212100370	8212100366	82/12/06	50-344 P
8212100372	8212100366	82/12/06	50-344 P
8212100427	8212100424	82/11/09	70-2926
8212100015	8212100001	82/11/03	FOIA
8212100022	8212100001	82/11/03	FOIA
8212100031	8212100029	82/12/07	50-220 R
8212100051	8212100048	82/12/09	50-302 R
8212100060	8212100053	82/11/24	50-272 S
8212100061	8212100053	82/12/09	50-295 R
8212100070	8212100064	82/12/09	50-286 R
8212100072	8212100068	82/12/06	50-373 P
8212100082	8212100076	82/11/24	50-272 S
8212100084	8212100074	82/11/24	50-213 Q
8212100085	8212100079	82/11/24	50-311 S
8212100095	8212100067	82/12/06	50-373 S
8212100105	8212100098	82/11/30	50-271 Q
8212100107	8212100099	82/11/24	50-311 S
8212100113	8212100098	82/11/30	50-271 Q
8212100120	8212100112	82/12/01	50-10 R
8212100123	8212100115	82/12/07	50-366 S
8212100128	8212100119	82/12/06	50-373 S
8212100131	8212100125	82/12/02	50-317 S
8212100133	8212100124	82/12/06	50-272 Q
8212100138	8212100135	82/12/03	50-387 S
8212100140	8212100137	82/11/29	50-247 Q
8212100147	8212100142	82/12/03	50-331 S
8212100149	8212100001	82/11/03	50-29 P
8212100154	8212100150	82/11/30	50-334 Q
8212100159	8212100153	82/12/06	50-325 S
8212100160	8212100150	82/11/30	50-334 Q
8212100161	8212100001	82/11/03	FOIA
8212100165	8212100156	82/12/06	50-316 S
8212100176	8212100171	82/12/03	50-369 S
8212100177	8212100169	82/12/02	50-219 S
8212100187	8212100184	82/12/03	50-29 S
8212100189	8212100182	82/12/01	50-387 S
8212100191	8212100174	82/11/26	50-334 S
8212100201	8212100194	82/12/09	50-508 C
8212100202	8212100196	82/12/06	50-325 S
8212100207	8212100198	82/12/08	50-328 S
8212100221	8212100208	82/12/09	50-245 Q
8212100231	8212100224	82/12/09	50-373 Q
8212100236	8212100225	82/12/09	50-333 Q
8212100238	8212100232	82/12/06	50-97 R
8212100239	8212100228	82/12/02	50-289 S
8212100241	8212100241	82/12/07	50-327 S
8212100248	8212100251	82/11/30	70-2895
8212100256	8212100253	82/12/09	50-329 A
8212100257	8212100255	82/12/06	50-324 P
8212100260	8212100259	82/12/09	50-29 P
8212100261	8212100258	82/12/03	50-387 S
8212100270	8212100265	82/11/30	50-361 S
8212100271	8212100269	82/11/30	50-321 S
8212100272	8212100265	82/11/30	50-361 S
8212100277	8212100276	82/12/08	50-275 P
8212100285	8212100281	82/12/10	50-275 R
8212100292	8212100289	82/12/09	50-373 Q
8212100312	8212100263	82/12/08	50-413 A
8212100315	8212100311	82/11/30	50-320 Q
8212100318	8212100263	82/12/08	50-413 A
8212100319	8212100311	82/11/30	50-320 Q
8212100325	8212100268	82/12/03	50-387 S
8212100327	8212100321	82/12/08	50-295 S
8212100329	8212100326	82/11/23	50-373 Q
8212100332	8212100322	82/11/29	50-423 Q
8212100338	8212100332	82/12/03	50-331 S
8212100340	8212100335	82/11/30	50-358 A
8212100342	8212100335	82/11/30	50-358 A
8212100355	8212100346	82/11/30	50-344 S
8212100356	8212100351	82/12/07	50-312 P
8212100357	8212100344	82/12/06	50-263 S
8212100363	8212100351	82/12/07	50-312 P
8212100367	8212100361	82/12/09	50-329 A
8212100368	8212100360	82/12/02	50-206 S

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

493

ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8212140380	8212140374	82/12/07	50-537 A
8212140383	8212140381	82/12/10	50-498 C
8212140388	8212140374	82/12/07	50-537 A
8212140393	8212140384	82/12/10	50-247 Q
8212140399	8212140396	82/12/09	50-151 Q
8212140400	8212140384	82/12/10	50-247 Q
8212140405	8212140398	82/12/01	50-361 S
8212140406	8212140397	82/12/07	50-220 Q
8212140408	8212140404	82/12/08	50-244 P
8212140413	8212140404	82/12/08	50-244 P
8212140414	8212140396	82/12/09	50-151 Q
8212140417	8212140410	82/12/08	50-409 Q
8212140420	8212140404	82/12/08	50-244 P
8212140427	8212140424	82/12/07	50-412 Q
8212140429	8212140421	82/11/30	50-366 S
8212140434	8212140425	82/11/30	50-369 S
8212140436	8212140433	82/11/30	50-366 S
8212140437	8212140426	82/12/09	50-443 Q
8212140442	8212140435	82/11/24	50-309 F
8212140444	8212140440	82/12/08	50-259 S
8212140446	8212140439	82/12/10	50-247 Q
8212140448	8212140379	82/12/07	50-271 P
8212140453	8212140435	82/11/24	50-309 F
8212140486	8212140478	82/11/23	50-259 H
8212140492	8212140490	82/11/29	50-410 Q
8212140495	8212140490	82/11/29	50-410 Q
8212140497	8212140494	82/11/23	50-387 P
8212140510	8212140501	82/11/11	FRQJ
8212140517	8212140513	82/11/19	71-4909
8212150005	8212150003	82/12/13	TQPREP
8212150011	8212150007	82/12/07	50-321 S
8212150013	8212150008	82/12/09	50-247 T
8212150018	8212150014	82/12/07	50-321 S
8212150019	8212150015	82/11/23	50-409 Q
8212150025	8212150020	82/12/02	50-334 S
8212150027	8212150023	82/11/29	50-247 S
8212150034	8212150028	82/12/08	50-338 S
8212150037	8212150031	82/12/07	50-321 S
8212150044	8212150038	82/12/01	50-320 S
8212150047	8212150042	82/12/09	50-382 F
8212150049	8212150040	82/12/09	50-112 Q
8212150050	8212150042	82/12/09	50-382 F
8212150052	8212150048	82/12/08	50-338 P
8212150053	8212150046	82/12/10	50-302 S
8212150062	8212150058	82/12/13	50-277 P
8212150064	8212150060	82/12/10	50-302 S
8212150069	8212150066	82/12/10	50-259 S
8212150072	8212150070	82/12/08	50-331 P
8212150076	8212150071	82/12/09	50-296 S
8212150078	8212150075	82/12/02	50-334 S
8212150081	8212150077	82/12/08	50-395 S
8212150084	8212150080	82/12/01	50-247 S
8212150087	8212150067	82/12/09	50-281 S
8212150091	8212150089	82/12/08	50-395 S
8212150096	8212150094	82/12/08	50-338 S
8212150100	8212150097	82/12/08	50-395 S
8212150102	8212150099	82/12/07	50-302 S
8212150104	8212150101	82/12/10	50-260 S
8212150108	8212150105	82/12/07	50-302 S
8212150111	8212150107	82/12/09	50-296 S
8212150113	8212150110	82/12/10	50-289 P
8212150114	8212150112	82/12/08	50-325 S
8212150122	8212150117	82/12/09	50-395 S
8212150126	8212150121	82/12/10	50-333 Q
8212150134	8212150129	82/12/07	50-389 A
8212150137	8212150131	82/12/14	50-382 Q
8212150140	8212150131	82/12/14	50-382 Q
8212150142	8212150128	82/12/08	50-245 P
8212150143	8212150138	82/12/13	70-143
8212150148	8212150131	82/12/14	50-382 Q
8212150153	8212150131	82/12/14	50-382 Q
8212150158	8212150156	82/12/09	50-335 S
8212150160	8212150155	82/12/06	50-29 E
8212150163	8212150159	82/12/02	50-309 Q
8212150169	8212150159	82/12/02	50-309 Q
8212150170	8212150164	82/12/13	50-275 P
8212150171	8212150166	82/12/10	50-445 K
8212150176	8212150174	82/12/09	50-271 R
8212150183	8212150180	82/12/03	50-250 R
8212150187	8212150181	82/12/07	50-277 F

ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8212150193	8212150181	82/12/07	50-277 F
8212150200	8212150195	82/12/10	50-275 P
8212150206	8212150202	82/11/15	71-9081
8212150213	8212150207	82/12/10	50-220 Q
8212150218	8212150212	82/11/24	71-5957
8212150224	8212150219	82/12/10	50-293 Q
8212150233	8212150219	82/12/10	50-293 Q
8212150240	8212150236	82/12/07	50-302 P
8212150244	8212150238	82/11/22	70-1151
8212150252	8212150248	82/12/07	50-243 F
8212150257	8212150248	82/12/07	50-243 F
8212150260	8212150272	82/12/08	50-313 F
8212150268	8212150272	82/12/08	50-313 F
8212150298	8212150293	82/11/17	70-143
8212150310	8212150301	82/12/09	50-346 F
8212150329	8212150323	82/12/07	50-315 F
8212150333	8212150326	82/11/29	MUREO
8212150335	8212150323	82/12/07	50-315 F
8212160002	8212160001	82/12/09	50-315 F
8212160016	8212160012	82/11/23	71-9006
8212160023	8212160020	82/11/30	71-170
8212160028	8212160026	82/11/18	71-486
8212160035	8212160032	82/11/23	71-9099
8212160041	8212160038	82/11/19	71-6003
8212160050	8212160043	82/11/01	71-5796
8212160054	8212160048	82/12/01	50-311 S
8212160058	8212160055	82/12/10	50-277 R
8212160067	8212160060	82/10/29	71-3392
8212160082	8212160080	82/09/30	40-6500
8212160090	8212160080	82/09/30	FOIA
8212160094	8212160080	82/09/30	FOIA
8212160097	8212160080	82/09/30	40-6500
8212160098	8212160091	82/12/08	50-346 F
8212160103	8212160080	82/09/30	FOIA
8212160105	8212160080	82/09/30	40-6500
8212160107	8212160091	82/12/08	50-346 F
8212160123	8212160080	82/09/30	40-6500
8212160131	8212160080	82/09/30	40-6500
8212160140	8212160080	82/09/30	40-6500
8212160144	8212160080	82/09/30	40-6500
8212160148	8212160134	82/11/12	71-484
8212160160	8212160080	82/09/30	FOIA
8212160161	8212160080	82/09/30	40-6500
8212160168	8212160080	82/09/30	40-6500
8212160182	8212160080	82/09/30	40-6500
8212160185	8212160177	82/12/03	71-489
8212160191	8212160080	82/09/30	40-6500
8212160193	8212160080	82/09/30	40-6500
8212160197	8212160080	82/09/30	40-6500
8212160214	8212160080	82/09/30	40-6500
8212160227	8212160223	82/12/13	50-155 Q
8212160240	8212160235	82/12/15	50-413 Q
8212160243	8212160080	82/09/30	40-6500
8212160260	8212160080	82/09/30	40-6500
8212160264	8212160080	82/09/30	40-6500
8212160270	8212160259	81/06/01	50-317 S
8212160273	8212160080	82/09/30	40-6500
8212160284	8212160080	82/09/30	40-6500
8212160307	8212160080	82/09/30	40-6500
8212160315	8212160080	82/09/30	40-6500
8212160316	8212160304	82/12/14	50-352 Q
8212160323	8212160080	82/09/30	FOIA
8212160329	8212160322	82/12/13	50-395 F
8212160334	8212160326	82/12/10	50-237 Q
8212160337	8212160080	82/09/30	40-3265
8212160341	8212160080	82/09/30	40-3265
8212160343	8212160080	82/09/30	FOIA
8212160346	8212160339	82/12/08	50-334 P
8212160350	8212160080	82/09/30	40-3265
8212160352	8212160080	82/09/30	40-6500
8212160362	8212160080	82/09/30	40-6500
8212160370	8212160080	82/09/30	40-6500
8212160371	8212160358	82/12/10	50-245 S
8212160372	8212160080	82/09/30	FOIA
8212160380	8212160080	82/09/30	FOIA
8212160386	8212160080	82/09/30	FOIA
8212160388	8212160080	82/09/30	40-6500
8212160390	8212160381	82/12/01	50-311 S
8212160391	8212160080	82/09/30	FOIA
8212160406	8212160397	82/12/03	50-289 Q

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSION NUMBER				ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
B212160414	B212160399	82/12/01	50-311 S	B212170129	B212170127	82/12/10	50-335 P
B212160418	B212160407	82/11/16	71-9151	B212170130	B212170122	82/12/03	50-237 S
B212160419	B212160417	82/12/07	50-387 P	B212170131	B212170120	82/12/15	50-498 A
B212160424	B212160080	82/09/30	40-6500	B212170133	B212170120	82/12/15	50-498 A
B212160432	B212160080	82/09/30	40-6500	B212170139	B212170134	82/11/15	50-249 S
B212160435	B212160080	82/09/30	40-6500	B212170140	B212170136	82/12/10	50-260 P
B212160436	B212160080	82/09/30	40-6500	B212170146	B212170137	82/12/13	50-416 S
B212160438	B212160437	82/11/30	71-9132	B212170150	B212170145	82/12/10	50-155 S
B212160459	B212160080	82/09/30	40-6500	B212170154	B212170148	82/12/03	50-155 S
B212160464	B212160080	82/09/30	40-6500	B212170156	B212170141	82/12/10	50-325 S
B212160466	B212160080	82/09/30	40-6500	B212170162	B212170148	82/12/03	50-155 S
B212160471	B212160080	82/09/30	40-6500	B212170165	B212170155	82/12/03	50-366 S
B212160477	B212160080	82/09/30	FOIA	B212170168	B212170144	82/12/15	50-206 F
B212160485	B212160080	82/09/30	40-6500	B212170171	B212170167	82/12/10	50-305 S
B212160496	B212160480	82/12/03	50-277 Q	B212170172	B212170161	82/12/09	50-266 S
B212160491	B212160480	82/12/03	50-277 Q	B212170176	B212170159	82/12/09	50-373 S
B212160493	B212160080	82/09/30	FOIA	B212170181	B212170177	82/11/30	50-266 Q
B212160500	B212160080	82/09/30	FOIA	B212170187	B212170178	82/12/09	50-346 S
B212160505	B212160080	82/09/30	40-2116	B212170188	B212170179	82/12/09	50-316 P
B212160506	B212160080	82/09/30	40-6500	B212170189	B212170177	82/11/30	50-266 Q
B212160510	B212160080	82/09/30	40-2116	B212170194	B212170184	82/12/09	50-373 S
B212160513	B212160080	82/09/30	40-2116	B212170201	B212170196	82/12/03	50-10 Q
B212160516	B212160080	82/09/30	40-6500	B212170202	B212170166	82/12/07	50-321 S
B212160521	B212160515	82/12/15	50-382 Q	B212170207	B212170197	82/12/13	50-348 R
B212160525	B212160080	82/09/30	40-2116	B212170213	B212170209	82/12/13	50-416 S
B212160527	B212160080	82/09/30	40-6500	B212170214	B212170211	82/12/10	50-373 S
B212160534	B212160080	82/09/30	40-1606	B212170223	B212170217	82/12/10	50-275 R
B212160541	B212160080	82/09/30	FOIA	B212170225	B212170218	82/12/03	50-249 S
B212160544	B212160531	82/12/07	50-278 P	B212170227	B212170222	82/12/13	50-416 S
B212160551	B212160531	82/12/07	50-278 P	B212170228	B212170224	82/12/08	50-316 S
B212160552	B212160080	82/09/30	FOIA	B212170232	B212170224	82/12/08	50-316 S
B212160560	B212160531	82/12/07	50-278 P	B212170235	B212170231	82/12/07	50-312 R
B212160578	B212160568	82/12/02	50-364 P	B212170237	B212170224	82/12/08	50-316 S
B212160581	B212160568	82/12/02	50-364 P	B212170238	B212170233	82/12/09	50-373 S
B212160583	B212160080	82/09/30	40-6500	B212170247	B212170244	82/12/03	50-341 Q
B212160586	B212160568	82/12/02	50-364 P	B212170253	B212170244	82/12/03	50-341 Q
B212160587	B212160080	82/09/30	40-6500	B212170268	B212170267	82/12/10	50-316 S
B212160608	B212160593	82/12/03	CONTRACT	B212170270	B212170264	82/12/10	50-373 S
B212160643	B212160634	82/12/08	COMMISSION	B212170272	B212170271	82/12/10	50-387 P
B212160734	B212160731	82/12/10	50-262 F	B212170275	B212170265	82/12/15	50-277 P
B212160742	B212160731	82/12/10	50-262 F	B212170276	B212170273	82/12/03	50-230 P
B212160752	B212160745	82/12/10	50-320 F	B212170277	B212170263	82/12/13	50-416 S
B212160764	B212160745	82/12/10	50-320 F	B212170280	B212170265	82/12/15	50-277 P
B212160782	B212160772	82/12/10	50-313 F	B212170285	B212170282	82/12/08	50-346 S
B212160787	B212160772	82/12/10	50-313 F	B212170286	B212170205	82/12/03	50-483 Q
B212170010	B212170005	82/12/09	71-9132	B212170291	B212170287	82/12/10	50-395 S
B212170011	B212170004	82/12/08	70-2928	B212170292	B212170283	82/12/08	50-315 S
B212170016	B212170013	82/12/09	50-373 P	B212170293	B212170288	82/12/15	50-482 A
B212170017	B212170014	82/12/07	70-1143	B212170296	B212170283	82/12/08	50-315 S
B212170018	B212170012	82/12/10	50-313 F	B212170302	B212170297	82/12/13	50-364 R
B212170020	B212170014	82/12/07	70-1143	B212170306	B212170300	82/11/29	50-10 Q
B212170025	B212170012	82/12/10	50-313 F	B212170310	B212170305	82/12/15	50-293 P
B212170030	B212170013	82/12/09	50-373 P	B212170311	B212170308	82/12/14	50-331 P
B212170034	B212170013	82/12/09	50-373 P	B212170312	B212170307	82/12/09	50-295 S
B212170041	B212170036	82/12/10	50-280 F	B212170320	B212170319	82/12/07	50-312 P
B212170044	B212170036	82/12/10	50-280 F	B212170322	B212170321	82/11/22	50-245 P
B212170057	B212170042	82/12/01	50-341 A	B212170323	B212170321	82/11/22	50-245 P
B212170060	B212170053	82/12/10	50-335 F	B212170327	B212170313	82/12/13	50-416 S
B212170065	B212170053	82/12/10	50-335 F	B212170335	B212170330	82/12/09	50-461 E
B212170076	B212170042	82/12/01	50-341 A	B212170339	B212170334	82/12/13	50-416 S
B212170079	B212170077	82/12/01	50-373 Q	B212170342	B212170337	82/12/15	50-445 E
B212170084	B212170042	82/12/01	50-341 A	B212170343	B212170338	82/12/13	50-324 P
B212170089	B212170078	82/12/01	50-312 P	B212170350	B212170338	82/12/13	50-324 P
B212170091	B212170088	82/12/10	50-397 Q	B212170356	B212170338	82/12/13	50-324 P
B212170094	B212130211	82/12/03	50-277 P	B212170359	B212170353	82/12/07	50-321 R
B212170096	B212170087	82/11/30	50-255 Q	B212170361	B212170354	82/12/02	50-508 Q
B212170099	B212170092	82/12/07	50-321 S	B212170363	B212170355	82/12/10	50-324 P
B212170100	B212170088	82/12/10	50-397 Q	B212170370	B212170354	82/12/02	50-508 Q
B212170101	B212130211	82/12/03	50-277 P	B212170376	B212170369	82/11/30	50-206 Q
B212170102	B212170097	82/12/06	50-249 S	B212170378	B212170373	82/12/08	50-275 H
B212170103	B212170088	82/12/10	50-397 Q	B212170379	B212170374	82/12/09	50-397 A
B212170108	B212170104	82/12/10	50-259 F	B212170383	B212170369	82/11/30	50-206 Q
B212170111	B212130211	82/12/03	50-277 P	B212170384	B212170367	82/11/30	50-206 Q
B212170112	B212170104	82/12/10	50-259 F	B212170386	B212170369	82/11/30	50-206 Q
B212170114	B212170109	82/12/03	50-295 Q	B212170390	B212170388	82/12/07	50-327 R
B212170118	B212170106	82/12/02	50-454 Q	B212170394	B212170391	82/12/03	50-361 Q
B212170121	B212170109	82/12/03	50-295 Q	B212170397	B212170391	82/12/03	50-361 Q
B212170124	B212170120	82/12/15	50-498 A	B212170401	B212170398	82/11/23	CONTRACT
B212170126	B212170123	82/12/10	50-373 S	B212170402	B212170398	82/11/23	CONTRACT
B212170128	B212170120	82/12/15	50-498 A	B212170407	B212170404	82/11/12	40-8745

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

495

ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8212170409	8212170405	82/12/03	40-6500
8212170448	8212170445	82/12/10	50-313 F
8212170453	8212170445	82/12/10	50-313 F
8212170457	8212170454	82/12/13	50-280 F
8212170458	8212170454	82/12/13	50-280 F
8212170459	8212170443	82/11/26	40-8728
8212200011	8212200006	82/11/02	50-267 F
8212200012	8212200005	82/12/03	50-369 S
8212200013	8212200008	82/12/13	50-244 P
8212200033	8212200022	82/11/08	50-285 Q
8212200035	8212200025	82/11/02	50-267 F
8212200037	8212200027	82/12/09	50-338 S
8212200048	8212200042	82/12/13	50-312 R
8212200049	8212200039	82/12/15	50-443 Q
8212200058	8212200051	82/12/14	50-440 H
8212200062	8212200040	82/11/30	TOPREP
8212200064	8212200059	82/12/13	50-285 R
8212200065	8212200056	82/12/14	50-316 R
8212200072	8212200061	82/12/15	50-440 Q
8212200075	8212200070	82/12/15	50-255 P
8212200082	8212200070	82/12/15	50-255 P
8212200085	8212200071	82/12/08	50-335 S
8212200086	8212200074	82/12/01	50-458 Q
8212200090	8212200084	82/11/02	50-267 Q
8212200095	8212200080	82/12/15	50-275 P
8212200098	8212200096	82/11/02	50-267 F
8212200101	8212200092	82/11/29	50-267 Q
8212200106	8212200103	82/12/15	50-416 R
8212200115	8212200110	82/12/13	50-395 S
8212200116	8212200109	82/11/02	50-267 F
8212200117	8212200108	82/11/02	50-267 F
8212200122	8212200119	82/12/14	50-315 R
8212200125	8212200121	82/12/03	50-382 Q
8212200126	8212200121	82/12/03	50-382 Q
8212200127	8212200121	82/12/03	50-382 Q
8212200128	8212200123	82/11/24	50-267 S
8212200129	8212200121	82/12/03	50-382 Q
8212210005	8212210002	82/12/13	50-275 P
8212210006	8212210004	82/12/13	50-324 P
8212210009	8212210007	82/12/01	50-263 Q
8212210020	8212210019	82/12/10	50-219 P
8212210022	8212210021	82/12/14	50-285 Q
8212210024	8212210023	82/11/02	50-267 Q
8212210028	8212210027	82/12/06	50-368 S
8212210031	8212210029	82/12/15	50-358 Q
8212210032	8212210030	82/12/15	50-325 S
8212210034	8212210033	82/12/10	50-331 B
8212210044	8212210040	82/12/10	50-219 R
8212210048	8212210043	82/12/09	50-317 S
8212210057	8212210052	82/12/10	50-387 S
8212210063	8212210059	82/12/14	50-213 P
8212210065	8212210060	82/12/15	50-369 R
8212210071	8212210067	82/12/10	50-293 S
8212210074	8212210070	82/12/10	50-331 S
8212210080	8212210076	82/12/09	50-317 S
8212210087	8212210084	82/11/29	50-219 Q
8212210088	8212210083	82/12/02	50-321 B
8212210089	8212210084	82/11/29	50-219 Q
8212210096	8212210091	82/12/02	0A999
8212210098	8212210091	82/12/02	0A999
8212210100	8212210095	82/12/14	50-328 S
8212210105	8212210091	82/12/02	0A999
8212210108	8212210104	82/12/13	50-373 Q
8212210112	8212210102	82/11/01	50-267 R
8212210120	8212210117	82/12/07	50-368 S
8212210123	8212210116	82/11/24	50-275 S
8212210124	8212210118	82/12/10	50-237 Q
8212210132	8212210130	82/12/10	50-364 P
8212210133	8212210128	82/12/05	50-247 S
8212210134	8212210129	82/12/06	50-277 Q
8212210140	8212210119	82/12/04	50-247 S
8212210141	8212210135	82/12/02	0A999
8212210147	8212210137	82/12/13	50-338 S
8212210153	8212210148	82/12/10	50-293 S
8212210154	8212210145	82/12/08	50-369 S
8212210159	8212210152	82/12/14	50-325 S
8212210160	8212210157	82/12/06	50-237 S
8212210162	8212210158	82/12/15	50-277 R
8212210169	8212210166	82/12/06	50-313 S
8212210170	8212210165	82/12/07	50-309 S

ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8212210171	8212210163	82/12/13	50-338 S
8212210173	8212210167	82/11/02	50-267 Q
8212210182	8212210159	82/12/14	50-416 S
8212210185	8212210180	82/12/02	50-344 Q
8212210186	8212210175	82/12/14	50-335 S
8212210192	8212210179	82/12/14	50-416 S
8212210195	8212210189	82/12/02	50-508 Q
8212210196	8212210188	82/12/07	50-321 S
8212210198	8212210193	82/12/07	50-368 S
8212210204	8212210197	82/12/02	50-361 Q
8212210205	8212210191	82/12/14	50-416 S
8212210207	8212210202	82/12/15	50-250 S
8212210210	8212210209	82/12/15	50-331 R
8212210211	8212210203	82/11/30	50-528 Q
8212210223	8212210218	82/12/03	0A999
8212210227	8212210212	82/12/15	50-416 S
8212210233	8212210229	82/12/10	50-336 S
8212210234	8212210232	82/12/15	50-289 R
8212210241	8212210236	82/12/07	50-387 S
8212210246	8212210240	82/12/14	70-25
8212210250	8212210245	82/11/05	50-313 Q
8212210260	8212210257	82/12/07	50-368 S
8212210264	8212210249	82/12/10	50-293 S
8212210266	8212210263	82/12/13	50-309 Q
8212210269	8212210264	82/12/13	50-339 S
8212210274	8212210268	82/12/09	50-333 S
8212210275	8212210270	82/12/06	50-443 Q
8212210282	8212210270	82/12/06	50-443 Q
8212210283	8212210278	82/12/10	50-29 S
8212210289	8212210285	82/12/17	50-155 Q
8212210292	8212210285	82/12/17	50-155 Q
8212210296	8212210285	82/12/17	50-155 Q
8212210299	8212210297	82/12/10	50-266 R
8212210303	8212210294	82/12/09	50-317 S
8212210316	8212210315	82/12/13	50-331 P
8212210323	8212210322	82/12/15	50-286 P
8212210324	8212210322	82/12/13	50-286 P
8212210327	8212210325	82/12/15	50-263 P
8212210328	8212210326	82/12/17	50-837 Q
8212210330	8212210325	82/12/13	50-263 P
8212210333	8212210325	82/12/15	50-263 P
8212210337	8212210325	82/12/15	50-263 P
8212210339	8212210336	82/12/17	50-289 Q
8212210340	8212210329	82/12/02	50-282 Q
8212210342	8212210325	82/12/15	50-263 P
8212210346	8212210325	82/12/15	50-263 P
8212210347	8212210343	82/12/07	50-387 S
8212210351	8212210349	82/12/06	50-309 Q
8212210357	8212210353	82/11/18	0A999
8212210358	8212210352	82/12/10	50-331 S
8212210363	8212210360	82/12/16	50-391 Q
8212210365	8212210353	82/11/18	0A999
8212210368	8212210361	82/12/16	50-346 Q
8212210371	8212210367	82/12/14	50-416 S
8212210377	8212210372	82/12/08	50-219 S
8212210379	8212210376	82/12/06	70-687
8212210383	8212210365	82/12/13	50-280 S
8212210384	8212210378	82/12/08	50-317 S
8212210388	8212210365	82/12/13	50-280 S
8212210390	8212210376	82/12/06	70-687
8212210394	8212210391	82/12/17	50-445 K
8212210396	8212210389	82/12/13	50-335 S
8212210397	8212210365	82/12/13	50-280 S
8212210405	8212210399	82/12/13	50-325 S
8212210410	8212210406	82/12/14	50-322 E
8212210414	8212210406	82/12/14	50-322 E
8212210423	8212210419	82/12/15	50-370 K
8212210424	8212210422	82/12/15	50-400 C
8212210425	8212210415	82/12/13	50-333 S
8212210427	8212210416	82/12/08	50-397 Q
8212210428	8212210421	82/12/15	50-267 R
8212210448	8212210447	82/11/30	50-317 P
8212210452	8212210446	82/12/07	50-366 S
8212210460	8212210453	82/12/14	50-219 Q
8212210461	8212210456	82/12/15	50-244 P
8212210462	8212210458	82/12/03	50-293 Q
8212210466	8212210463	82/12/13	50-373 K
8212210468	8212210453	82/12/14	50-219 Q
8212210495	8212210491	82/12/17	50-352 A
8212210498	8212210491	82/12/17	50-352 C

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSION NUMBER				ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8212210499	8212210491	82/12/17	50-352 K	8212220470	8212220465	82/12/10	50-261 P
8212210504	8212210501	82/11/03	71-468	8212220471	8212220464	82/12/09	50-269 Q
8212210514	8212210508	82/12/10	50-313 F	8212220472	8212220463	82/12/17	50-260 S
8212210515	8212210512	82/11/04	40-2061	8212220473	8212220466	82/12/07	50-219 Q
8212210521	8212210508	82/12/10	50-313 F	8212220474	8212220465	82/12/10	50-261 P
8212210534	8212210526	82/12/13	50-313 F	8212220475	8212220461	82/12/14	50-275 P
8212210538	8212210535	82/12/03	76PREP	8212220477	8212220465	82/12/10	50-261 P
8212210539	8212210526	82/12/13	50-313 F	8212220478	8212220459	82/12/09	50-289 Q
8212210542	8212210536	82/09/17	40-8064	8212220479	8212220476	82/12/16	50-220 Q
8212210545	8212210541	82/12/10	50-358 F	8212220493	8212220488	82/12/17	50-325 S
8212210547	8212210544	82/12/10	50-263 P	8212220500	8212220498	82/12/16	50-395 S
8212210548	8212210544	82/12/10	50-263 P	8212220504	8212220494	82/12/17	50-325 S
8212210552	8212210544	82/12/10	50-263 P	8212220520	8212220517	82/12/16	50-295 P
8212210555	8212210550	82/12/13	50-219 F	8212220526	8212220518	82/12/09	71-468
8212210557	8212210550	82/12/13	50-219 F	8212220528	8212220522	82/12/07	CONTRACT
8212210579	8212210576	82/12/10	50-245 F	8212220534	8212230277	82/12/16	50-237 P
8212210581	8212210576	82/12/10	50-245 F	8212220535	8212220524	82/12/14	CONTRACT
8212220002	8212220001	82/12/10	50-313 F	8212220538	8212220531	82/12/09	71-467
8212220004	8212220001	82/12/10	50-313 F	8212220542	8212220536	82/12/09	CONTRACT
8212220007	8212220003	82/12/06	50-280 Y	8212220544	8212230287	82/12/16	50-245 P
8212220013	8212220010	82/10/26	40-6500	8212220553	8212220549	82/12/15	CONTRACT
8212220024	8212220018	82/11/22	CONTRACT	8212220554	8212220552	82/12/15	50-387 P
8212220027	8212220019	82/11/03	CONTRACT	8212220556	8212220552	82/12/16	50-387 P
8212220034	8212220025	82/12/07	CONTRACT	8212220557	8212220552	82/12/16	50-387 P
8212220042	8212220037	82/12/13	50-3 F	8212220558	8212220555	82/12/14	COMMISSION
8212220046	8212220037	82/12/13	50-3 F	8212230028	8212230019	82/12/15	50-10 F
8212220048	8212220045	82/12/08	50-282 F	8212230030	8212230023	82/12/10	50-289 P
8212220046	8212220051	82/12/17	50-461 T	8212230031	8212230025	82/12/06	70-1201
8212220070	8212220051	82/12/17	50-461 T	8212230033	8212230020	82/12/09	50-289 P
8212220073	8212220051	82/12/17	50-461 T	8212230039	8212230036	82/12/10	71-464
8212220134	8212220124	82/11/09	70-1143	8212230042	8212230019	82/12/15	50-10 F
8212220141	8212220136	82/12/01	50-312 Q	8212230051	8212230044	82/12/15	CONTRACT
8212220190	8212220175	82/12/10	50-10 F	8212230057	8212230046	82/12/15	50-309 F
8212220202	8212220175	82/12/10	50-10 F	8212230058	8212230049	82/12/09	50-275 P
8212220210	8212220208	82/12/15	50-317 R	8212230061	8212230056	82/12/08	50-320 P
8212220218	8212220213	82/11/24	50-397 Q	8212230068	8212230046	82/12/15	50-309 F
8212220225	8212220217	82/12/17	50-275 P	8212230076	8212230067	82/12/14	50-369 F
8212220226	8212220220	82/12/16	50-247 Q	8212230083	8212230067	82/12/14	50-369 F
8212220229	8212220217	82/12/17	50-275 P	8212230096	8212230089	82/12/13	50-213 P
8212220231	8212220212	82/12/14	50-10 P	8212230103	8212230085	82/12/07	70-1113
8212220239	8212220232	82/12/20	50-413 Q	8212230108	8212230093	82/12/15	50-269 F
8212220248	8212220224	82/12/21	70-143	8212230110	8212230089	82/12/13	50-213 P
8212220248	8212220244	82/12/15	50-338 S	8212230124	8212230093	82/12/15	50-269 F
8212220299	8212220296	82/12/10	50-281 Q	8212230134	8212230093	82/12/15	50-269 F
8212220302	8212220298	82/12/10	50-346 F	8212230141	8212230136	82/12/13	70-1143
8212220308	8212220298	82/12/10	50-346 F	8212230150	8212230142	82/11/10	FOIA
8212220310	8212220300	82/12/08	50-272 S	8212230163	8212230155	82/11/30	40-2259
8212220322	8212220314	82/12/16	50-302 S	8212230165	8212230152	82/12/15	50-313 F
8212220323	8212220315	82/12/10	50-409 F	8212230172	8212230152	82/12/15	50-313 F
8212220331	8212220315	82/12/10	50-409 F	8212230176	8212230166	82/11/04	FOIA
8212220337	8212220328	82/12/17	50-395 S	8212230212	8212230209	82/10/27	WASTE MGT
8212220354	8212220350	82/12/07	50-244 Q	8212230230	8212230220	82/12/20	50-277 P
8212220358	8212220350	82/12/07	50-244 Q	8212230243	8212230238	82/12/17	50-29 P
8212220368	8212220364	82/12/16	50-339 S	8212230248	8212230238	82/12/17	50-29 P
8212220384	8212220376	82/12/16	50-395 S	8212230250	8212230220	82/12/20	50-277 P
8212220385	8212220381	82/12/08	50-311 S	8212230264	8212230238	82/12/17	50-29 P
8212220388	8212220383	82/12/07	50-289 Q	8212230271	8212230248	82/12/10	50-272 R
8212220390	8212220386	82/12/17	50-309 Q	8212230294	8212230288	82/12/17	50-395 P
8212220391	8212220387	82/12/15	50-339 S	8212230304	8212230298	82/12/21	50-275 P
8212220396	8212220386	82/12/17	50-309 Q	8212230326	8212230317	82/12/22	50-285 P
8212220397	8212220392	82/12/15	50-339 S	8212230333	8212230330	82/12/08	70-1143
8212220404	8212220403	82/12/15	50-412 A	8212230335	8212230330	82/12/08	70-1143
8212220405	8212220400	82/12/16	50-367 Q	8212230336	8212230331	82/12/16	50-247 Q
8212220406	8212220395	82/12/08	50-311 S	8212230343	8212230342	82/12/20	50-155 P
8212220408	8212220399	82/12/15	50-338 S	8212230359	8212230357	82/12/20	50-266 Q
8212220414	8212220411	82/12/16	50-395 S	8212230374	8212230369	82/12/15	50-331 F
8212220416	8212220410	82/12/16	50-338 S	8212230377	8212230369	82/12/15	50-331 F
8212220421	8212220415	82/12/08	50-289 F	8212230380	8212230379	82/12/06	40-8027
8212220424	8212220420	82/12/08	50-311 S	8212230410	8212230406	82/12/06	EXPORTIC
8212220427	8212220422	82/12/15	50-266 P	8212230411	8212230404	82/11/22	40-8084
8212220435	8212220433	82/12/08	50-311 S	8212270007	8212270003	82/12/16	50-305 F
8212220437	8212220436	82/12/17	70-139	8212270010	8212270003	82/12/16	50-305 F
8212220438	8212220434	82/12/14	50-275 P	8212270015	8212270013	82/12/16	50-382 F
8212220442	8212220441	82/12/17	50-335 S	8212270017	8212270013	82/12/16	50-382 F
8212220448	8212220440	82/12/14	50-275 P	8212270027	8212270018	82/12/07	71-490
8212220454	8212220449	82/12/10	50-320 S	8212270029	8212270026	82/12/16	70-2941
8212220462	8212220428	82/12/16	50-395 S	8212270030	8212270024	82/11/02	70-33
8212220467	8212220464	82/12/09	50-289 Q	8212270042	8212270038	82/10/27	50-289 P
8212220468	8212220466	82/12/07	50-219 Q	8212270047	8212270038	82/10/27	50-289 P
8212220469	8212220459	82/12/09	50-289 Q	8212270052	8212270048	82/11/19	FOIA

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

497

ACCESSION NUMBER				ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8212270055	8212270048	82/11/19	FOIA	8212270032	8212270377	82/11/29	71-9079
8212270056	8212270038	82/10/27	50-289 P	8212270034	8212270380	82/12/22	50-322 E
8212270059	8212270048	82/11/19	FOIA	8212270035	8212270381	82/12/10	50-302 P
8212270065	8212270048	82/11/19	FOIA	8212270039	8212270396	82/12/10	50-312 P
8212270071	8212270069	82/12/03	71-9015	8212270405	8212270401	82/11/22	40-3453
8212270079	8212270077	82/12/08	XPORTLIC	8212270411	8212270409	82/12/10	50-302 P
8212270080	8212270048	82/11/19	FOIA	8212270412	8212270410	82/11/16	CONTRACT
8212270083	8212270074	82/11/24	40-299	8212270417	8212270415	82/11/23	CONTRACT
8212270084	8212270048	82/11/19	FOIA	8212270422	8212270419	82/11/30	CONTRACT
8212270086	8212270082	82/12/06	XPORTLIC	8212270425	8212270423	82/12/17	50-437 A
8212270088	8212270048	82/11/19	FOIA	8212270426	8212270423	82/12/17	50-437 A
8212270091	8212270048	82/12/11	FOIA	8212270427	8212270421	82/12/10	50-313 P
8212270095	8212270048	82/11/19	FOIA	8212270429	8212270424	82/12/16	50-358 A
8212270099	8212270048	82/11/19	FOIA	8212270431	8212270428	82/12/20	50-3 H
8212270107	8212270048	82/11/19	FOIA	8212270434	8212270424	82/12/16	50-358 A
8212270110	8212270048	82/11/19	FOIA	8212270438	8212270418	82/11/26	FOIA
8212270111	8212270108	82/12/11	50-3 P	8212270439	8212270432	82/12/13	HTSC
8212270112	8212270078	82/12/03	70-143	8212270442	8212270418	82/11/26	FOIA
8212270113	8212270108	82/12/11	50-3 P	8212270445	8212270418	82/11/26	FOIA
8212270114	8212270048	82/11/19	FOIA	8212270447	8212270446	82/12/20	CONTRACT
8212270116	8212270078	82/12/03	70-143	8212270448	8212270418	82/11/26	FOIA
8212270117	8212270108	82/12/11	50-3 P	8212270453	8212270418	82/11/26	FOIA
8212270123	8212270048	82/11/19	FOIA	8212270457	8212270418	82/11/26	FOIA
8212270124	8212270078	82/12/03	70-143	8212270461	8212270418	82/11/26	FOIA
8212270127	8212270048	82/11/19	FOIA	8212270466	8212270418	82/11/26	50-327 D
8212270128	8212270078	82/12/03	70-143	8212270471	8212270418	82/11/26	FOIA
8212270131	8212270048	82/12/11	FOIA	8212270486	8212270483	82/12/14	50-344 F
8212270133	8212270048	82/11/19	FOIA	8212270488	8212270483	82/12/14	50-344 F
8212270148	8212270140	82/12/13	50-373 S	8212270501	8212270484	82/11/05	50-537 A
8212270153	8212270147	82/12/22	50-416 P	8212270502	8212270496	82/12/17	CONTRACT
8212270161	8212270155	82/12/15	50-334 P	8212270506	8212270503	82/12/16	CONTRACT
8212270163	8212270155	82/12/15	50-334 P	8212270513	8212270509	82/12/17	CONTRACT
8212270170	8212270162	82/12/13	50-373 S	8212270516	8212270510	82/12/07	CONTRACT
8212270176	8212270168	82/12/20	50-331 P	8212270521	8212270518	82/12/17	CONTRACT
8212270180	8212270175	82/12/15	50-373 S	8212270530	8212270527	82/11/03	CONTRACT
8212270193	8212270187	82/12/07	50-482 C	8212270532	8212270525	82/12/06	50-331 P
8212270194	8212270189	82/12/13	50-368 S	8212270536	8212270525	82/12/06	50-331 P
8212270202	8212270177	82/12/09	50-266 S	8212270543	8212270539	82/11/29	CONTRACT
8212270203	8212270197	82/12/20	50-305 P	8212270546	8212270542	82/12/06	50-318 P
8212270206	8212270199	82/12/02	GA999	8212270556	8212270555	82/11/29	CONTRACT
8212270207	8212270201	82/12/16	50-334 P	8212270560	8212270558	82/12/21	CONTRACT
8212270209	8212270201	82/12/16	50-334 P	8212280003	8212280002	82/12/06	50-263 P
8212270213	8212270197	82/12/02	GA999	8212280004	8212280002	82/12/06	50-263 P
8212270218	8212270212	82/11/30	50-271 P	8212280006	8212280002	82/12/06	50-263 P
8212270223	8212270198	82/12/20	50-373 Q	8212280007	8212280005	82/11/29	50-271 P
8212270228	8212270215	82/12/13	50-255 S	8212280012	8212280009	82/11/29	40-147B
8212270246	8212270239	82/12/10	50-264 S	8212280015	8212280005	82/11/29	50-271 P
8212270250	8212270248	82/12/23	50-537 A	8212280016	8212280009	82/11/29	70-146
8212270254	8212270248	82/12/23	50-537 A	8212280018	8212280013	82/10/18	70-1193
8212270256	8212270252	82/12/21	70-820	8212280019	8212280009	82/11/29	70-146
8212270260	8212270248	82/12/23	50-537 A	8212280021	8212280020	82/12/20	71-9852
8212270263	8212270259	82/12/06	50-286 P	8212280022	8212280007	82/11/29	70-146
8212270266	8212270259	82/12/06	50-286 P	8212280024	8212280007	82/11/29	70-146
8212270280	8212270274	82/12/10	50-311 R	8212280026	8212280007	82/11/29	70-146
8212270281	8212270279	82/12/08	50-443 A	8212280027	8212280003	82/11/29	50-271 P
8212270286	8212270279	82/12/08	50-443 A	8212280030	8212280009	82/11/29	70-146
8212270288	8212270283	82/12/15	50-312 R	8212280044	8212280043	82/12/15	CONTRACT
8212270289	8212270279	82/12/08	50-443 A	8212280049	8212280047	82/12/15	CONTRACT
8212270290	8212270287	82/12/09	50-390 A	8212280050	8212280046	82/12/07	50-329 S
8212270291	8212270283	82/12/15	50-312 R	8212280054	8212280046	82/12/07	50-329 S
8212270299	8212270296	82/12/20	50-275 P	8212280057	8212280056	82/12/16	50-416 S
8212270301	8212270296	82/12/20	50-275 P	8212280061	8212280059	82/12/16	50-409 P
8212270303	8212270299	82/12/16	50-237 Q	8212280062	8212280058	82/12/10	50-295 Q
8212270305	8212270292	82/12/10	50-282 Q	8212280068	8212280066	82/12/15	50-272 R
8212270307	8212270295	82/12/16	50-237 Q	8212280071	8212280069	82/12/10	50-346 P
8212270308	8212270275	82/12/10	50-456 Q	8212280074	8212280069	82/12/10	50-346 P
8212270310	8212270296	82/12/20	50-275 P	8212280077	8212280075	82/12/17	50-416 S
8212270312	8212270296	82/12/20	50-275 P	8212280081	8212280080	82/12/15	50-416 S
8212270313	8212270295	82/12/16	50-237 Q	8212280087	8212280084	82/12/17	50-247 F
8212270318	8212270275	82/12/10	50-456 Q	8212280088	8212280085	82/12/17	50-259 P
8212270320	8212270317	82/12/22	50-445 Q	8212280089	8212280083	82/12/20	50-255 P
8212270333	8212270328	82/11/15	FOIA	8212280092	8212280084	82/12/17	50-247 F
8212270336	8212270328	82/11/15	FOIA	8212280094	8212280083	82/12/20	50-255 P
8212270337	8212270331	82/12/02	40-8084	8212280095	8212280091	82/12/20	50-409 Q
8212270338	8212270335	82/12/10	50-269 P	8212280106	8212280099	82/12/20	50-260 Q
8212270339	8212270334	82/12/10	50-305 Q	8212280107	8212280103	82/12/20	50-155 P
8212270356	8212270354	82/12/06	50-373 S	8212280113	8212280103	82/12/20	50-155 P
8212270361	8212270358	82/12/20	50-247 Q	8212280115	8212280114	82/12/15	50-301 S
8212270367	8212270365	82/12/16	50-29 P	8212280116	8212280111	82/12/21	50-327 S
8212270370	8212270363	82/12/10	50-346 P	8212280130	8212280122	82/12/22	50-338 Q

ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8212270032	8212270377	82/11/29	71-9079
8212270034	8212270380	82/12/22	50-322 E
8212270035	8212270381	82/12/10	50-302 P
8212270039	8212270396	82/12/10	50-312 P
8212270405	8212270401	82/11/22	40-3453
8212270411	8212270409	82/12/10	50-302 P
8212270412	8212270410	82/11/16	CONTRACT
8212270417	8212270415	82/11/23	CONTRACT
8212270422	8212270419	82/11/30	CONTRACT
8212270425	8212270423	82/12/17	50-437 A
8212270426	8212270423	82/12/17	50-437 A
8212270427	8212270421	82/12/10	50-313 P
8212270429	8212270424	82/12/16	50-358 A
8212270431	8212270428	82/12/20	50-3 H
8212270434	8212270424	82/12/16	50-358 A
8212270438	8212270418	82/11/26	FOIA
8212270439	8212270432	82/12/13	HTSC
8212270442	8212270418	82/11/26	FOIA
8212270445	8212270418	82/11/26	FOIA
8212270447	8212270446	82/12/20	CONTRACT
8212270448	8212270418	82/11/26	FOIA
8212270453	8212270418	82/11/26	FOIA
8212270457	8212270418	82/11/26	FOIA
8212270461	8212270418	82/11/26	FOIA
8212270466	8212270418	82/11/26	50-327 D
8212270471	8212270418	82/11/26	FOIA
8212270486	8212270483	82/12/14	50-344 F
8212270488	8212270489	82/12/14	50-344 F
8212270501	8212270493	82/11/05	50-937 A
8212270502	8212270496	82/12/17	CONTRACT
8212270506	8212270503	82/12/16	CONTRACT
8212270513	8212270509	82/12/17	CONTRACT
8212270516	8212270510	82/12/07	CONTRACT
8212270521	8212270518	82/12/17	CONTRACT
8212270530	8212270527	82/11/03	CONTRACT
8212270532	8212270525	82/12/06	50-331 P
8212270536	8212270525	82/12/06	50-331 P
8212270543	8212270539	82/11/29	CONTRACT
8212270546	8212270542	82/12/06	50-318 P
8212270556	8212270555	82/11/29	CONTRACT
8212270560	8212270558	82/12/21	CONTRACT
8212280003	8212280002	82/12/06	50-263 P
8212280004	8212280002	82/12/06	50-263 P
8212280006	8212280002	82/12/06	50-263 P
8212280007	8212280005	82/11/29	50-271 P
8212280012	8212280009	82/11/29	40-1478
8212280015	8212280005	82/11/29	50-271 P
8212280016	8212280009	82/11/29	70-146
8212280018	8212280013	82/10/18	70-1193
8212280019	8212280009	82/11/29	70-146
8212280021	8212280020	82/12/20	71-9852
8212280022	8212280009	82/11/29	70-146
8212280024	8212280007	82/11/29	70-146
8212280026	8212280007	82/11/29	70-146
8212280027	8212280003	82/11/29	50-271 P
8212280030	8212280009	82/11/29	70-146
8212280044	8212280043	82/12/15	CONTRACT
8212280049	8212280047	82/12/15	CONTRACT
8212280050	8212280046	82/12/07	50-329 S
8212280054	8212280046	82/12/07	50-329 S
8212280057	8212280056	82/12/16	50-416 S
8212280061	8212280059	82/12/16	50-409 P
8212280062	8212280058	82/12/10	50-295 O
8212280065	8212280066	82/12/15	50-272 R
8212280071	8212280069	82/12/10	50-346 S
8212280074	8212280069	82/12/10	50-346 S
8212280077	8212280075	82/12/17	50-346 S
8212280081	8212280080	82/12/15	50-416 S
8212280087	8212280084	82/12/17	50-247 F
8212280088	8212280085	82/12/17	50-299 F
8212280089	8212280083	82/12/20	50-255 P
8212280092	8212280084	82/12/17	50-247 F
8212280094	8212280083	82/12/20	50-255 P
8212280095	8212280091	82/12/20	50-409 O
8212280106	8212280099	82/12/20	50-260 S
8212280107	8212280103	82/12/20	50-155 P
8212280113	8212280103	82/12/20	50-155 P
8212280115	8212280114	82/12/15	50-301 S
8212280116	8212280111	82/12/21	50-327 S
8212280130	8212280122	82/12/22	50-338 S

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSION NUMBER				ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8212280134	8212280131	82/12/16	50-135 Q	8212280464	8212280460	82/12/15	50-255 S
8212280136	8212280133	82/12/21	50-328 S	8212280468	8212280465	82/12/14	50-387 S
8212280140	8212280126	82/12/17	50-280 S	8212280473	8212280467	82/12/23	50-305 P
8212280146	8212280142	82/12/15	50-348 S	8212280475	8212280466	82/12/16	50-416 S
8212280152	8212280126	82/12/17	50-280 S	8212280478	8212280469	82/11/15	CONTRACT
8212280153	8212280147	82/12/20	50-299 S	8212280479	8212280472	82/12/13	50-237 S
8212280154	8212280150	82/12/16	50-416 S	8212280480	8212280476	82/12/23	50-29 P
8212280156	8212280151	82/12/27	50-341 Q	8212280487	8212280483	82/12/16	50-373 S
8212280161	8212280159	82/12/16	50-366 S	8212280489	8212280485	82/12/01	50-461 Q
8212280162	8212280158	82/12/16	50-266 S	8212280491	8212280486	82/11/15	CONTRACT
8212280163	8212280160	82/12/15	50-275 F	8212280501	8212280494	82/11/29	50-329 A
8212280167	8212280164	82/12/20	50-250 S	8212280515	8212280512	82/12/07	FOIA
8212280171	8212280166	82/12/23	50-358 Q	8212280516	8212280513	82/12/22	50-329 E
8212280173	8212280168	82/12/21	TOPREP	8212290013	8212290012	82/11/24	40-8681
8212280175	8212280170	82/12/20	50-250 S	8212290018	8212290015	82/11/24	FOIA
8212280183	8212280177	82/12/16	50-416 S	8212290035	8212290030	82/12/03	50-206 Q
8212280189	8212280184	82/12/02	WASTE MOT	8212290038	8212290030	82/12/03	50-206 Q
8212280198	8212280194	82/12/20	50-416 S	8212290039	8212290036	82/12/02	FOIA
8212280202	8212280199	82/12/23	50-318 P	8212290042	8212290030	82/12/03	50-206 Q
8212280206	8212280126	82/12/17	50-280 S	8212290049	8212290030	82/12/03	50-206 Q
8212280208	8212280200	82/12/21	50-317 Q	8212290056	8212290053	82/09/21	CONTRACT
8212280213	8212280211	82/12/22	50-124 P	8212290064	8212290060	82/11/30	50-250 Q
8212280215	8212280193	82/12/20	50-373 S	8212290065	8212290060	82/11/30	50-244 S
8212280216	8212280211	82/12/22	50-124 P	8212290068	8212290060	82/11/30	50-250 Q
8212280217	8212280211	82/12/22	50-124 P	8212290069	8212290060	82/11/30	50-280 S
8212280220	8212280214	82/12/20	50-10 Q	8212290071	8212290067	82/12/06	50-395 P
8212280221	8212280219	82/12/15	50-247 R	8212290073	8212290060	82/11/30	50-250 Q
8212280231	8212280229	82/12/20	50-373 S	8212290075	8212290060	82/11/30	50-280 S
8212280239	8212280234	82/12/17	50-346 S	8212290076	8212290067	82/12/06	50-395 P
8212280240	8212280236	82/12/22	50-482 A	8212290078	8212290060	82/11/30	50-250 Q
8212280243	8212280237	82/12/17	50-247 P	8212290080	8212290060	82/11/30	50-280 S
8212280245	8212280241	82/12/16	50-416 S	8212290081	8212290067	82/12/06	50-395 P
8212280246	8212280242	82/12/10	50-313 Q	8212290082	8212290060	82/11/30	50-250 Q
8212280248	8212280237	82/12/17	50-247 P	8212290085	8212290060	82/11/30	50-281 S
8212280249	8212280244	82/12/21	50-295 S	8212290086	8212290083	82/12/20	50-295 F
8212280250	8212280247	82/12/15	50-346 S	8212290087	8212290060	82/11/30	50-250 Q
8212280251	8212280242	82/12/10	50-313 Q	8212290089	8212290083	82/12/20	50-295 F
8212280256	8212280253	82/12/16	50-409 S	8212290090	8212290060	82/11/30	50-250 Q
8212280290	8212280281	82/12/15	50-346 S	8212290092	8212290060	82/11/30	50-250 Q
8212280296	8212280295	82/12/20	50-299 P	8212290094	8212290060	82/11/30	50-250 Q
8212280297	8212280295	82/12/20	50-299 P	8212290097	8212290060	82/11/30	50-250 Q
8212280301	8212280299	82/12/22	50-508 Q	8212290100	8212290060	82/11/30	50-250 Q
8212280309	8212280307	82/12/17	50-313 P	8212290101	8212290060	82/11/30	50-250 Q
8212280311	8212280308	82/12/20	50-416 S	8212290104	8212290095	82/12/23	50-266 P
8212280314	8212280312	82/12/20	50-416 S	8212290105	8212290098	82/12/20	50-295 F
8212280324	8212280319	82/12/20	50-440 Q	8212290106	8212290102	82/11/15	50-206 R
8212280332	8212280326	82/12/27	50-247 Q	8212290108	8212290060	82/11/30	50-250 Q
8212280336	8212280327	82/12/20	50-416 S	8212290109	8212290060	82/11/30	50-250 Q
8212280352	8212280344	82/12/20	50-416 S	8212290110	8212290098	82/12/20	50-295 F
8212280354	8212280347	82/12/23	50-387 P	8212290113	8212290060	82/11/30	50-250 Q
8212280366	8212280359	82/12/17	50-335 S	8212290114	8212290060	82/11/30	50-250 Q
8212280367	8212280351	82/12/21	50-269 P	8212290117	8212290115	82/11/11	50-387 R
8212280373	8212280363	82/12/14	50-410 S	8212290118	8212290060	82/11/30	50-250 Q
8212280378	8212280374	82/12/06	50-382 Q	8212290121	8212290060	82/11/30	50-261 Q
8212280381	8212280375	82/12/10	50-461 Q	8212290124	8212290060	82/11/30	50-250 Q
8212280389	8212280386	82/12/16	50-416 S	8212290125	8212290060	82/11/30	50-261 Q
8212280390	8212280385	82/12/21	50-320 Q	8212290128	8212290116	82/11/05	50-309 R
8212280391	8212280388	82/12/21	50-244 P	8212290129	8212290060	82/11/30	50-250 Q
8212280392	8212280387	82/12/14	50-321 S	8212290130	8212290126	82/11/03	50-29 R
8212280394	8212280380	82/12/13	50-369 S	8212290133	8212290060	82/11/30	50-261 Q
8212280397	8212280383	82/12/18	50-325 S	8212290134	8212290127	82/11/11	50-219 R
8212280401	8212280396	82/12/21	QA999	8212290136	8212290132	82/12/09	40-6622
8212280411	8212280406	82/12/22	50-20 P	8212290137	8212290060	82/11/30	50-250 Q
8212280412	8212280402	82/12/17	50-416 S	8212290138	8212290060	82/11/30	50-261 Q
8212280413	8212280409	82/12/08	50-298 Q	8212290142	8212290139	82/11/12	50-336 R
8212280415	8212280408	82/12/23	REVIEW DRP	8212290144	8212290060	82/11/30	50-261 Q
8212280417	8212280403	82/12/14	50-387 S	8212290148	8212290060	82/11/30	50-261 Q
8212280419	8212280410	82/12/17	50-344 P	8212290152	8212290146	82/12/24	50-275 R
8212280420	8212280409	82/12/08	50-298 Q	8212290155	8212290060	82/11/30	50-261 Q
8212280425	8212280418	82/12/17	50-335 S	8212290158	8212290060	82/11/30	50-261 Q
8212280430	8212280423	82/12/06	50-382 Q	8212290160	8212290156	82/11/10	50-286 R
8212280438	8212280434	82/12/17	50-409 P	8212290161	8212290157	82/12/06	40-8452
8212280439	8212280435	82/10/29	40-8783	8212290164	8212290159	82/11/12	50-327 R
8212280442	8212280432	82/12/17	50-295 S	8212290165	8212290060	82/11/30	50-261 Q
8212280448	8212280433	82/12/21	50-454 Q	8212290166	8212290163	82/11/05	50-244 R
8212280449	8212280447	82/12/16	50-373 S	8212290169	8212290153	82/11/15	50-230 R
8212280455	8212280445	82/11/03	CONTRACT	8212290170	8212290060	82/11/30	50-280 Q
8212280457	8212280454	82/12/17	50-331 S	8212290171	8212290168	82/11/12	50-313 R
8212280461	8212280450	82/12/17	50-295 S	8212290172	8212290060	82/11/30	50-280 Q
8212280463	8212280458	82/12/16	50-416 S	8212290178	8212290060	82/11/30	50-280 Q

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

499

ACCESSION NUMBER				ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8212290181	8212290176	82/11/15	50-361 R	8212290410	8212290408	82/12/27	50-219 Q
8212290184	8212290060	82/11/30	50-280 Q	8212290411	8212290404	82/12/15	50-334 S
8212290185	8212290180	82/11/23	50-397 K	8212290414	8212290406	82/12/14	50-346 Q
8212290186	8212290182	82/11/02	50-133 R	8212290417	8212290412	82/12/15	50-440 Q
8212290193	8212290190	82/12/21	50-237 P	8212290424	8212290419	82/11/12	50-315 R
8212290196	8212290194	82/11/15	50-313 R	8212290425	8212290420	82/12/27	50-358 A
8212290198	8212290192	82/12/23	50-313 Q	8212290427	8212290421	82/12/13	50-267 P
8212290199	8212290190	82/12/21	50-237 P	8212290428	8212290419	82/11/12	50-315 R
8212290204	8212290201	82/11/03	50-344 R	8212290429	8212290381	82/12/27	50-358 Q
8212290206	8212290190	82/12/21	50-237 P	8212290430	8212290416	82/12/16	50-220 S
8212290208	8212290203	82/12/17	50-329 A	8212290432	8212290421	82/12/13	50-267 P
8212290209	8212290205	82/12/23	50-275 P	8212290433	8212290422	82/12/23	50-293 Q
8212290215	8212290190	82/12/21	50-237 P	8212290434	8212290419	82/11/12	50-315 R
8212290216	8212290211	82/11/09	50-305 R	8212290437	8212290421	82/12/13	50-267 P
8212290218	8212290214	82/11/02	50-275 R	8212290440	8212290426	82/12/15	50-267 S
8212290222	8212290220	82/11/10	50-409 R	8212290443	8212290435	82/12/14	50-272 Q
8212290223	8212290212	82/12/13	50-368 S	8212290444	8212290436	82/12/22	50-354 Q
8212290228	8212290217	82/11/12	50-316 R	8212290446	8212290441	82/12/20	50-387 S
8212290229	8212290224	82/11/09	50-245 R	8212290448	8212290439	82/12/15	50-334 S
8212290230	8212290225	82/11/08	50-334 R	8212290452	8212290447	82/12/23	50-245 P
8212290236	8212290234	82/11/15	50-368 R	8212290454	8212290381	82/12/27	50-358 Q
8212290237	8212290231	82/12/23	50-275 P	8212290455	8212290449	82/12/23	50-246 Q
8212290240	8212290233	82/12/15	50-320 S	8212290456	8212290453	82/12/20	50-295 P
8212290242	8212290239	82/12/21	50-213 Q	8212290461	8212290453	82/12/20	50-295 P
8212290243	8212290231	82/12/23	50-275 P	8212290462	8212290458	82/12/22	50-275 P
8212290244	8212290238	82/11/15	50-280 R	8212290464	8212290453	82/12/20	50-295 P
8212290250	8212290231	82/12/23	50-275 P	8212290465	8212290463	82/12/14	50-387 Q
8212290252	8212290248	82/12/17	50-338 P	8212290468	8212290463	82/12/14	50-387 Q
8212290255	8212290248	82/12/17	50-338 P	8212290474	8212290459	82/12/27	50-281 Q
8212290256	8212290248	82/12/17	50-338 P	8212290476	8212290472	82/11/08	50-249 S
8212290257	8212290253	82/11/17	50-266 R	8212290479	8212290477	82/12/15	50-219 Q
8212290258	8212290251	82/12/16	50-29 S	8212290490	8212290488	82/12/15	50-193 Q
8212290262	8212290253	82/11/17	50-266 R	8212290492	8212290488	82/12/15	50-193 Q
8212290264	8212290261	82/12/27	50-280 Q	8212290499	8212290496	82/12/14	50-335 P
8212290270	8212290267	82/12/22	50-155 P	8212290501	8212290496	82/12/14	50-335 P
8212290273	8212290266	82/12/16	CONTRACT	8212290511	8212290509	82/12/20	50-295 F
8212290274	8212290267	82/12/22	50-155 P	8212290513	8212290507	82/12/20	50-295 F
8212290278	8212290267	82/12/22	50-155 P	8212290528	8212290525	82/12/03	50-311 P
8212290282	8212290275	82/12/16	50-317 S	8212290530	8212290525	82/12/03	50-311 P
8212290287	8212290281	82/11/10	50-259 R	8212290532	8212290525	82/12/03	50-311 P
8212290288	8212290283	82/12/20	50-312 P	8212290535	8212290534	82/12/13	50-250 P
8212290289	8212290280	82/12/22	50-334 Q	8212290536	8212290534	82/12/13	50-250 P
8212290293	8212290283	82/12/20	50-312 P	8212300007	8212300004	82/12/23	50-312 Q
8212290299	8212290283	82/12/20	50-312 P	8212300029	8212300027	82/12/08	QA999
8212290302	8212290295	82/12/20	50-3 F	8212300032	8212300027	82/12/08	QA999
8212290303	8212290297	82/12/08	50-267 S	8212300036	8212300034	82/12/22	TDPREP
8212290306	8212290291	82/12/14	50-309 S	8212300038	8212300031	82/12/21	50-255 P
8212290308	8212290295	82/12/20	50-3 F	8212300042	8212300035	82/12/21	50-395 S
8212290309	8212290307	82/11/09	50-346 R	8212300044	8212300031	82/12/21	50-255 P
8212290315	8212290312	82/11/02	50-298 R	8212300047	8212300039	82/12/22	50-416 S
8212290316	8212290310	82/12/17	50-29 R	8212300048	8212300041	82/12/16	50-317 P
8212290318	8212290317	82/11/10	50-338 R	8212300059	8212300052	82/12/21	50-368 S
8212290323	8212290320	82/12/21	50-409 P	8212300062	8212300057	82/12/23	50-368 S
8212290327	8212290322	82/12/20	50-266 S	8212300063	8212300058	82/12/16	50-366 S
8212290331	8212290330	82/12/15	50-315 Q	8212300065	8212300061	82/12/22	50-335 S
8212290333	8212290329	82/12/20	50-249 S	8212300071	8212300068	82/12/17	50-250 P
8212290335	8212290330	82/12/15	50-315 Q	8212300075	8212300070	82/12/23	50-508 Q
8212290336	8212290332	82/12/17	50-266 Q	8212300087	8212300084	82/12/22	50-416 S
8212290340	8212290339	82/12/13	50-334 S	8212300090	8212300088	82/12/21	50-368 S
8212290343	8212290341	82/12/27	50-358 Q	8212300095	8212300091	82/12/16	50-321 S
8212290345	8212290344	82/11/16	50-237 S	8212300096	8212300093	82/12/22	50-369 S
8212290348	8212290346	82/12/16	50-254 Q	8212300102	8212300098	82/12/21	50-366 S
8212290352	8212290351	82/12/15	70-820	8212300104	8212300099	82/12/22	50-337 S
8212290353	8212290350	82/12/22	50-320 Q	8212300111	8212300106	82/12/23	50-299 S
8212290358	8212290355	82/12/15	50-316 S	8212300119	8212300114	82/12/22	50-416 S
8212290361	8212290357	82/12/22	50-335 P	8212300123	8212300117	82/12/21	CONTRACT
8212290363	8212290360	82/12/14	70-1100	8212300130	8212300126	82/12/20	50-338 S
8212290372	8212290366	82/12/23	50-275 R	8212300132	8212300127	82/12/20	CONTRACT
8212290379	8212290375	82/12/13	50-244 Q	8212300149	8212210309	82/12/13	50-329 A
8212290380	8212290376	82/12/17	50-249 Q	8212300177	8212300171	82/12/21	50-338 S
8212290382	8212290373	82/12/15	50-334 S	8212300179	8212300167	82/12/20	50-10 F
8212290383	8212290375	82/12/13	50-244 Q	8212300188	8212300184	82/12/20	50-416 P
8212290384	8212290378	82/12/13	50-271 S	8212300192	8212300170	82/12/17	CONTRACT
8212290385	8212290369	82/12/10	50-249 S	8212300194	8212300184	82/12/20	50-416 P
8212290386	8212290376	82/12/17	50-249 Q	8212300199	8212300167	82/12/20	50-10 F
8212290394	8212290391	82/12/14	50-267 R	8212300200	8212300186	82/12/22	50-416 S
8212290400	8212290389	82/12/17	50-265 Q	8212300201	8212300197	82/12/27	50-247 Q
8212290402	8212290393	82/12/23	50-184 Q	8212300203	8212300184	82/12/20	50-416 P
8212290405	8212290403	82/12/13	50-267 P	8212300209	8212300204	82/12/20	50-317 F
8212290409	8212290398	82/11/22	50-237 S	8212300210	8212300207	82/12/08	70-734

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSION NUMBER				
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	
8212300211	8212300204	82/12/20	50-317	F
8212300213	8212300207	82/12/08	70-734	
8212300214	8212300212	82/12/10	0A999	
8212300218	8212300212	82/12/10	0A999	
8212300220	8212300217	82/12/20	50-338	S
8212300223	8212300216	82/12/23	50-364	S
8212300225	8212300221	82/12/23	50-325	S
8212300227	8212300216	82/12/23	50-364	S
8212300228	8212300222	82/12/23	50-416	S
8212300231	8212300216	82/12/23	50-364	S
8212300236	8212300216	82/12/23	50-364	S
8212300238	8212300232	82/12/22	50-338	S
8212300240	8212300234	82/12/22	70-25	
8212300241	8212300237	82/12/21	50-339	S
8212300247	8212300245	82/12/22	50-338	S
8212300249	8212300248	82/12/30	50-537	S
8212300255	8212300251	82/12/22	50-339	S
8212300258	8212300254	82/12/08	0A999	
8212300259	8212300256	82/12/21	50-325	S
8212300262	8212300257	82/12/23	50-325	S
8212300263	8212300254	82/12/08	0A999	
8212300267	8212300261	82/12/22	50-338	S
8212300270	8212300265	82/12/16	50-321	S
8212300274	8212300268	82/12/23	50-508	Q
8212300275	8212300271	82/12/16	50-321	S
8212300278	8212300276	82/12/08	0A999	
8212300280	8212300276	82/12/08	0A999	
8212300281	8212300277	82/12/16	50-321	S
8212300289	8212300287	82/12/16	50-321	S
8212300290	8212300284	82/12/16	50-366	S

ACCESSION NUMBER				
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	
8212300291	8212300286	82/12/22	50-339	S
8212300292	8212300285	82/12/16	50-366	S
8212300296	8212300272	82/12/23	50-261	S
8212300298	8212300295	82/12/16	50-366	S
8212300302	8212300301	82/12/08	0A999	
8212300303	8212300301	82/12/08	0A999	
8212300309	8212300307	82/12/21	50-325	S
8212300312	8212300311	82/12/14	50-341	A
8212300315	8212300313	82/12/21	50-338	S
8212300317	8212300316	82/12/23	50-325	S
8212300318	8212300308	82/12/23	50-397	Q
8212300324	8212300320	82/12/23	50-508	Q
8212300325	8212300323	82/12/14	50-366	S
8212300334	8212300331	82/12/23	50-325	S
8212300336	8212300328	82/12/21	50-321	S
8212300337	8212300329	82/12/16	50-321	S
8212300339	8212300335	82/12/27	50-289	P
8212300341	8212300332	82/11/03	50-155	R
8212300342	8212300335	82/12/27	50-289	P
8212300345	8212300340	82/12/16	50-366	S
8212300346	8212300344	82/12/16	50-366	S
8212300348	8212300335	82/12/27	50-289	P
8212300353	8212300350	82/12/23	50-312	Q
8212300355	8212300351	82/12/23	50-327	P
8212300359	8212300357	82/12/23	50-327	P
8212300405	8212300400	82/12/22	50-254	F
8212300408	8212300407	82/12/22	50-387	F
8212300409	8212300400	82/12/22	50-254	F
8212300410	8212300407	82/12/22	50-387	F
8212300416	8212300412	82/12/22	50-282	F
8212300417	8212300412	82/12/22	50-282	F

APPENDIX A

DEFINITIONS OF DOCKET 50 CATEGORIES

A. APPLICATION/CONSTRUCTION STAGE DOCUMENTS AND CORRESPONDENCE

This category follows the application from submission to the day preceding the issuance of an operating license. It includes all correspondence and documents with substantive technical content that do not fall into other specific categories. Included are:

1. Application for construction permit.
2. General Information submitted with construction permit application.
3. Amendments and changes to items 1 and 2.
4. NRC questions, requests for additional information, and applicant responses
5. Correspondence and documents relating to unresolved design and construction issues.
6. Meeting announcements and summaries of meeting discussions on issues of item 5.
7. Correspondence regarding the Preliminary Safety Analysis Report (PSAR).
8. Information on laws and changes in regulations or policy that affect the status of the application (NEPA, Water Quality Improvement Act, Water Pollution Control Act, etc.).
9. Construction Permit, amendments, and correspondence relating to the construction permit.
10. Scheduling of license application submission or review.
11. Environmental review information.
12. Application for operating license
13. General Information submitted with operating license application.
14. Amendments and changes to items 12 and 13.
15. Correspondence regarding the Final Safety Analysis Report (FSAR).
16. Correspondence and documentation on generic technical matters highlighted by an event at another facility which may affect the subject facility; not covered by an IE Bulletin.
17. Reports of site visits.
18. Backup technical documents (e.g., topical reports) submitted in support of the application.

B. UTILITY PRELIMINARY SAFETY ANALYSIS REPORT (PSAR) AND AMENDMENTS

This category is strictly limited to the items listed below. All related correspondence is filed in Category A.

1. Preliminary Safety Analysis Report (PSAR) submitted by utility (formerly called Hazards Summary Report or Safety Analysis Report).
2. Amendments and changes to the PSAR.

3. Transmittal and acknowledgement letters
4. Certificates of service to the PSAR.

C. UTILITY ENVIRONMENTAL REPORT (ER), AMENDMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other environmental documents and correspondence are filed in Categories A, D, M, P or R.

1. Environmental Report (ER) submitted by the utility.
2. Amendments and supplements to the ER.
3. Transmittal and acknowledgement letters.
4. Information on scheduling of submittal or review of ER.
5. NRC questions, requests for additional information, and applicant responses.
6. Federal register notices citing the availability of items 1 and 2.
7. Correspondence relating to the review of ER.
8. Meeting announcements or reports of meetings where the primary subject of discussion is the ER.

D. NRC DRAFT AND FINAL ENVIRONMENTAL (IMPACT) STATEMENTS (DES AND FES), SUPPLEMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other environmental documents and correspondence are in categories A, C, M, P or R.

1. Draft and Final Environmental (Impact) Statements (DES and FES) prepared by the NRC.
2. Supplements to the DES and FES.
3. Correspondence relating to the DES and FES.
4. Comments from other federal, state and local government agencies.
5. Transmittal and acknowledgement letters.
6. Documents related to NRC review of environmental issues or of ER obtained for purposes of writing the environmental statements.
7. Backup technical documents submitted in connection with above.
8. Federal register notice citing availability of items 1 and 2.
9. Site visits to obtain information for DES or FES.
10. Meeting announcements or reports of meetings where the primary subject of discussion is the DES or FES.

E. NRC SAFETY EVALUATION REPORT (SER), SUPPLEMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other documents dealing with safety related issues are filed in categories A, P or W, depending on the phase of the licensing process.

1. Safety Evaluation Report (SER) prepared by the NRC (formerly called NRC-AEC Hazard Analysis Report).
2. Supplements to SER.
3. Correspondence relating to SER.
4. Federal register notices citing availability of items 1 and 2.
5. Information on scheduling of SER submittals and review.
6. Requests for additional information for use in preparing SER; responses to such requests.
7. Meeting announcements or reports of meetings where the primary subject of discussion is the SER.
8. Transmittal and acknowledgement letters.

F. SECURITY, MEDICAL, EMERGENCY AND FIRE PROTECTION PLANS

All plans in this category are individual submissions. Information submitted as part of the PSAR or FSAR is excluded

1. Fire Hazard Protection Plan and surveys.
2. Plant evacuation correspondence.
3. Safeguards Contingency Plans.
4. Review of Health Physics Program.
5. Correspondence relating to aforementioned plans.
6. Supplements, changes and revisions to plans.

G. LEGAL AND ADJUDICATORY CORRESPONDENCE

This category contains all non-antitrust legal and adjudicatory documentation, except for transcripts, briefings and testimony, which are filed in category T.

1. Atomic Safety and Licensing Board (ASLB) and Atomic Safety and Licensing Appeal Board (ASLAB) hearing related documents.
2. Federal register notices regarding hearings.
3. Requests to make appearances at hearings.
4. Motions, briefs, arguments, statements and related correspondence filed by participants for hearings.
5. Transmittal of supporting documents (e.g., SER, FES) to the boards.
6. Correspondence to and from intervenors.
7. Board orders and decisions.
8. Petitions for Commission action.
9. Legal filings and Commission orders and decisions resulting from item 8.

H. GENERAL CORRESPONDENCE

This category includes documents with little or no bearing on the status of the application or license. Items that have no substantive technical content or meaning for the status of the license or application are included.

1. Change of address notifications
2. Changes in structure of organization
3. Changes in service lists
4. NRC requests to applicant for additional copies of documents.
5. Correspondence from the public requesting information about the facility and NRC responses.
6. Correspondence on strictly administrative matters.
7. Letters of support, concern or opposition to the facility.
8. Correspondence regarding the Local Public Document Rooms (LPDRs).
9. Professional qualification statements not pertaining to the hearing process.

I. FINANCIAL INFORMATION

This category contains all financial information except that submitted as part of the application or its amendments or relating to the imposition of civil penalties.

1. Company annual reports.
2. Separately submitted financial information and related correspondence.

J. INSURANCE AND INDEMNITY INFORMATION

1. Indemnity agreements and amendments.
2. Endorsements insurance policies.
3. Other correspondence regarding indemnity and insurance matters.

K. UTILITY FINAL SAFETY ANALYSIS REPORT (FSAR) AND AMENDMENTS

This category is strictly limited to the items listed below. All related correspondence falls in category A or P.

1. Final Safety Analysis Report (FSAR) (formerly called Final Hazards Summary Report).
2. Amendments and changes to the FSAR.
3. Federal register notices citing availability of items 1 and 2.
4. Transmittal and acknowledgement letters.
5. Certificates of service to the FSAR.

L. LIMITED WORK AUTHORIZATION (LWA) AND RELATED CORRESPONDENCE

This category is limited to documents pertaining to Limited Work Authorizations (LWA) whereby applicants can carry out limited site preparation and construction prior to the granting of a construction permit.

1. Limited Work Authorizations (LWA) and amendments
2. Correspondence pertaining to work performed under LWA s.

M. ANTITRUST REVIEW AND ANTITRUST CORRESPONDENCE

1. Document submitted as part of the applications for a construction permit and operating license entitled "Information Requested by the Attorney General for Antitrust Review".
2. Correspondence where the primary topic of discussion is antitrust matters
3. All antitrust proceeding related documents except for hearing transcripts, testimony and briefings, which are filed in category N.

N. ANTITRUST HEARING TRANSCRIPTS, TESTIMONY AND BRIEFINGS

This category contains word-for-word transcripts of hearings, testimony and briefings in antitrust matters. Related correspondence falls in category M.

O. ADVISORY COMMITTEE ON REACTOR SAFEGUARDS (ACRS) REPORTS AND CORRESPONDENCE

1. Correspondence and letter reports relating to Advisory Committee on Reactor Safeguards (ACRS) reviews.
2. Correspondence from ACRS.
3. Announcement of ACRS meetings.
4. Transmittal and acknowledgement letters.
5. ACRS reports.
6. Statements and written testimony by ACRS members or presented by individuals at ACRS proceedings.
7. Minutes at ACRS Subcommittee Meetings.

P. OPERATING LICENSE STAGE DOCUMENTS AND CORRESPONDENCE

This file assumes the position of the Application/Construction Stage (category A) file for general technical items dated from the issuance of the operating license to the application for termination of the license.

1. Operating license, amendments, proposed amendments, changes and related correspondence.
2. Technical specifications and changes.

3. Backup technical documents (e.g., topical reports) submitted in support of items 1 and 2.
4. Federal register notices citing availability of items 1 and 2.
5. Correspondence regarding the Final Safety Analysis Report (FSAR).
6. All general technical correspondence, meeting announcements or meeting summaries relating to technical specifications, the operating license or technical issues arising after the issuance of the operating license.
7. Correspondence regarding codes (e.g., ASME), regulations, laws or changes in policy that may affect plant operation or bear on the operating license.
8. Information on the Standard Review Plan (STP).
9. Results of surveys or tests conducted in accordance with the technical specifications (not periodic reports, which fall in category R).
10. Correspondence relating to NRC's Systematic Evaluation Program (SEP).
11. Owner's group meeting announcements and reports.
12. Quality assurance information.
13. Environmental matters (technical).
14. Emergency core cooling system documents.
15. Radioactive waste information.
16. Correspondence regarding expansion of spent fuel storage pool.
17. Start-up test reports.
18. Correspondence and documentation on generic technical matters highlighted by an event at another facility which may affect the subject facility; not covered by an IE Bulletin.
19. Reports of site visits.

Q. INSPECTION REPORTS; IE BULLETINS, CIRCULARS AND INFORMATION NOTICES; CIVIL PENALTIES AND RELATED CORRESPONDENCE

1. Inspection reports.
2. IE Bulletins (formerly called Regulatory Operations (RO) Bulletins), Circulars and Information Notices.
3. Responses by applicant to IE correspondence.
4. Applicant's determination of proprietary nature of inspection reports.
5. Letters concerning areas of noncompliance.
6. Pre-service and in-service inspections and procedures.
7. Correspondence and orders relating to imposition and payment of civil penalties, including Notification of Significant Enforcement Actions (ENs).
8. Any correspondence relating to inspection and enforcements that does not specifically relate to incidents or events as defined in category S.

R. PERIODIC OPERATING REPORTS AND RELATED CORRESPONDENCE

This category includes periodic reports of a routine nature.

1. Monthly, semiannual, or annual operating reports (other than financial).
2. Periodic environmental monitoring, effluent testing, or similar reports.
3. Periodic personnel exposure reports.
4. Operational Logbooks.

Logbooks on Environmental Data

Logbooks on Radiological Data

Operations Log on Plant Systems Core

Plant Status Summary Sheets.

5. Correspondence or other documents relating to the above listed items

S. REPORTABLE OCCURRENCES, PNOs, PNSs AND RELATED CORRESPONDENCE

This category contains all materials relating to abnormal, unusual, reportable or nonroutine occurrences or events. This includes:

1. All 24-hour, 10-day, 30-day, interim and final Licensee Event Reports (LERs) and follow-up correspondence (also called incident reports, abnormal occurrence reports and reportable occurrences).
2. Potential or possible reportable deficiency reports and related correspondence.
3. Personnel exposure reports.
4. Construction deficiency reports submitted under 10 CFR 50.55e
5. Preliminary Notification of Occurrence (PNOs) and Preliminary Notification of Safeguards Events (PNSs).
6. Environmental Technical Specifications violation reports and Environmental Event reports.
7. Part 21 Reports of defects and noncompliance.
8. Correspondence or other documents relating to items 1-7

T. TRANSCRIPTS, TESTIMONY AND BRIEFINGS ON NON-ANTITRUST MATTERS

This category contains all word-for-word transcripts, except for antitrust matters (category N), testimony and briefings, and congressional matters (category U).

1. Atomic Safety and Licensing Board (ASLB) and Atomic Safety and Licensing Appeal Board (ASLAB) transcripts.
2. Testimony and statements submitted to ASLB and ASLAB.
3. Commission meeting transcripts.
4. NRC staff briefings to the Commission.
5. Statements and written testimony submitted at Commission meeting or hearings.
6. Transcripts of utility briefs to NRC staff.
7. Advisory Committee on Reactor Safeguards (ACRS) meeting transcripts.
8. Corrections to above items.

U CONGRESSIONAL/EXECUTIVE CORRESPONDENCE

This category contains correspondence on substantive matters. Routine responses to constituent inquiries are filed in category H.

1. Statements and testimony before Congress or before bodies/committees appointed by the Executive or Legislative Branches
2. Preparatory and backup documents for item 1
3. Correspondence to and from NRC Office of Congressional Affairs, Congress and the Executive Branch on other than constituent response matters

V. LICENSING OPERATORS AND RELATED CORRESPONDENCE

1. Operator licenses or administrative information bearing on licensing of operators
2. NRC examination results.
3. Power plant examination summary sheet

W. DECOMMISSIONING STAGE DOCUMENTS AND CORRESPONDENCE

This file assumes the position of the Operating License Stage (category P) file for general technical items from the application for termination of the operating license onward.

1. Application for authority to voluntarily surrender license
2. Application to dismantle the facility and dispose of component parts
3. Technical documents submitted in support of items 1 and 2, such as: Decommissioning Plan, Dismantling Plan, Environmental Report on Dismantling, Safety Analysis Report on Decommissioning
4. Documents relating to disposal of radioactive material and decontamination of the site
5. Other correspondence relating to above items.
6. All documentation relating to the ongoing operation of the plant, formerly filed in category P

X. ONSITE LOW-LEVEL WASTES STORAGE

This category contains items related to the onsite storage of low-level radioactive wastes generated onsite.

Y. INDEPENDENT SPENT FUEL STORAGE INSTALLATIONS (ISFSI)

This category contains documents with an NMSS license and/or a Docket-72 number. For installations on a reactor site, the associated Docket-50 number will also be identified.

1. License applications, licenses, amendments and proposed amendments to possess power reactor spent fuel and other radioactive materials associated with spent storage in an independent spent fuel storage installation. (Such spent fuel storage installations may be on a reactor site or at a separate site.)
2. All related correspondence and reports to the above.

APPENDIX B

DEFINITIONS OF NONDOCKETED CATEGORIES

10CFR – Commission Meeting Records

This category contains documentation pertaining to open and closed Commission meetings. It includes:

1. Sunshine Act Federal Register notices.
2. Full, written explanation of closed meetings.
3. Certification of General Counsel on closed meetings.
4. Commission Determination Statements regarding the public disclosure of transcripts of Commission meetings.
5. Verbatim unofficial and official transcripts or portions of transcripts of open and closed Commission meetings made publicly available in accordance with provisions of 10CFR Part 9, the Sunshine Act, and Commission policies.
6. Enclosures to released transcripts, including applicable viewgraphs, staff papers, and staff correspondence.
7. Staff requirements memoranda for open meetings; memoranda to record, record of votes of Commissioners on items under consideration at meetings.

ACRS – Advisory Committee on Reactor Safeguards

This category contains documentation pertaining to the responsibilities of the Advisory Committee on Reactor Safeguards. ACRS serves as an independent advisory committee to the Commission in safety-related areas. The committee provides advice with respect to the hazards of new or existing nuclear facilities and the adequacy of related safety standards. The documents in this category are:

1. Verbatim transcripts of ACRS subcommittee and full committee meetings relating to facility license applications and safety-related matters.
2. ACRS meeting announcements; description of meeting agendas.
3. ACRS-generated reports, memoranda and correspondence that are publicly available.
4. ACRS consultant reports, comments and related correspondence.
5. ACRS and NRC technical correspondence pertaining to safety matters under review by the Advisory Committee on Reactor Safeguards.

COMMISSION – NRC Commissioners

This category contains documentation pertaining to the daily conduct of Commission business in the Office of the Commissioners, including:

1. Incoming and outgoing correspondence to and from the Commissioners relating to official NRC business, including reports and other enclosures.

2. Travel vouchers, telephone logs and official appointment calendars of individual Commissioners.
3. Weekly Information Reports (SECY series number) prepared by the Executive Director for Operations (EDO) for the Commissioners, providing a summary of key events and items of interest undertaken by individual staff and program offices.

NOTE: For transcripts of Commission meetings, see 10CFR category. For all other staff papers with a SECY series designation prepared for Commission review, see SECY category.

CONTRACT – NRC Contracts and Modifications

This category contains documentation pertaining to AEC and NRC contracts and Interagency Agreements, including:

1. Notifications of issuance of request for proposal (RFP) and invitations for bid (IFB).
2. Solicitations (RFP or IFB) issued by the NRC.
3. Notifications of contract execution, specifying contract number, project title, contractor name, contract type, funding, and period of performance.
4. Contractual documents and contract modifications, if any.

DISCLOSURE – Financial Disclosure Information

This category contains financial disclosure information in accordance with the Ethics in Government Act of 1978.

FOIA – Freedom of Information Act Requests and Releases

This category contains requests for agency records and records released in accordance with the provisions of the Freedom of Information Act (FOIA). Documents in this category include:

1. Requests made by any member of the public (assigned an identifying number YY-NNN for last two digits of the year-numerical sequence) for NRC records made in accordance with the provisions of the Freedom of Information Act.
2. Correspondence between the NRC and the requester relevant to the processing, appeal, denial or granting of an FOIA request.
3. Records or portions of records released in response to specific requests made under FOIA.

GEN TECH IS – Generic Technical Issues

This category contains records pertaining to unresolved safety issues of a generic nature that are being analyzed by the Division of Nuclear Reactor Regulation.

1. Draft reports of action plans to accomplish generic tasks in the regulatory program.
2. Correspondence with industry and internal correspondence regarding the methodologies, analyses, and programmatic and technical aspects of issues.

3. Meeting notifications and minutes.
4. Interim findings and status reports on generic tasks addressing related aspects of generic technical issues.

I&E – Inspection and Enforcement

This category contains bulletins, circulars and information notices that are issued by the Office of Inspection and Enforcement. These issuances describe particular events that occur at a facility that may require some follow-up action on the part of licensees. Also included in this category are preliminary notifications of events (PNOs).

1. I&E Circulars, which describe an event at a licensed facility and are informational in nature.
2. I&E Information Notices, which are similar to circulars but are preliminary in nature and issued shortly after an event has occurred.
3. I&E Bulletins, which describe an event at a licensed facility and request all recipients to perform certain actions as a result of this event.
4. Preliminary Notifications of Events (PNOs), which provide updated information of an event of safety or public interest significance

NOTE For letters forwarding the above issuances, utility responses to such issuances, and related correspondence, see Category Q of individual docket categories.

MISC – Public Document Room Miscellaneous

This category contains documents that do not fall into the scope of the other nondocketed categories.

NUREG – NUREG Reports and Related Correspondence

These documents are formal reports issued by the U.S. Nuclear Regulatory Commission which carry the NUREG series code and correspondence pertaining to those reports. NUREG reports are accounts of work performed either by the NRC staff or by NRC contractors.

1. These reports are normally final work products and are characterized by the following criteria:
 - a. They are predecisional documents which present information to be considered in Commission licensing and policy decisions.
 - b. They present the results of Commission licensing and policy decisions.
 - c. They present the results of technical research conducted for the Commission.
2. Correspondence from industry, government and interested members of the public commenting on reports or requesting clarification or interpretation.
3. Internal NRC memoranda summarizing meetings or discussions pertaining to the content of the reports.

ORG – Correspondence with Other Organizations

This category contains correspondence with professional organizations and associations, records other than Regulatory Guides that pertain to the activities of NRC's Office of Standards Development, and emergency petitions not assigned Petition for Rulemaking (PRM) numbers that request the Commission to take immediate action on some issue. Included are:

1. Meeting summaries and technical correspondence between NRC and professional associations and international bodies, such as the Atomic Industrial Forum and the International Atomic Energy Agency.
2. Correspondence between NRC's Office of Standards Development and other government agencies in which both parties have joint regulatory responsibility, e.g., EPA has authority to control all radioactive pollutants emitted into the air.
3. Internal memoranda, correspondence between NRC and Congress, and other technical correspondence dealing with the role and activities of the Office of Standards Development.
4. Statements, motions, orders and correspondence dealing with emergency petitions filed by parties on such topics as fire protection and re-analysis of the capacity of operating U.S. plants to withstand earthquakes.

NOTE. For Regulatory Guides and comments to Regulatory Guides issued by the NRC Office of Standards Development, see the REGGD category.

For petitions for rule makings filed by the public to amend, rescind or change an NRC regulation, see the PRM category.

PR – Proposed Rule

This category contains records dealing with NRC staff proposals to adopt, amend or repeal a Commission regulation. Proposed Rules (PRs) are normally the result of a Commission determination that sufficient grounds exist for it to proceed with a petition for change in an NRC regulation (PRM) filed by an outside party or person. The documents in this category are:

1. Federal Register notices stating the terms or substance of the proposed rule or a specification of the subject and issues involved.
2. Text of the Proposed Rule (PR).
3. Comments, statements, information, opinions or arguments on the proposed change to a part of the Code of Federal Regulations, Title 10.
4. Requests from the nuclear industry, organizations and other parties for written interpretations of the PR.

PRM – Petition for Rulemaking

This category contains records dealing with petitions filed with the Commission by an outside party to issue, amend or rescind an NRC regulation. Included are:

1. Petitions filed by any interested person or party to issue, amend or rescind an NRC regulation.
2. Federal Register cause notices of the filing of the petition.

3. Correspondence between NRC and the petitioner regarding the status and substance of the petition.
4. Comments from the nuclear industry, professional associations, public interest groups and others in favor of or in opposition to the PRM.

NOTE: For staff recommendations to the Commissioners on whether the PRM should be denied or issued as a Proposed Rule, see the SECY category.

For Commission review of staff recommendations, see the 10CFR category.

PROJ – Projects–Predocket Licensing

This category contains records pertaining to two classes of projects (1) commercial nuclear power plants for which NRC has full licensing responsibilities; and (2) government-owned reactors for which NRC provides technical expertise and occasional review. Both classes are identified with a "P" prefix, followed by a series of numbers.

1. "Pre-docketed" commercial nuclear power plants

This category contains all documentation up until the time that the NRC considers the application and the Preliminary Safety Analysis Report (PSAR) is submitted by the utility for staff review. The unit is then assigned a docket number, and transferred to the Docket 50 category.

These documents are grouped together in categories, designated by alphabetic characters. These are the same categories as those used for the Docket 50 series.

A. Application/Construction Stage

1. Application submitted by the utility.
2. Meeting notices, summaries and correspondence discussing the completeness and adequacy of the PSAR.
3. Applicant's Quality Assurance Manual.
4. Early site review information.
5. Backup technical documents submitted in support of the application.
6. Early site visits.

B. Utility PSAR and Amendments

1. PSARs submitted by the utility.
2. Amendments and changes to the PSAR.
3. Transmittal letters.
4. Letters acknowledging receipt of the PSAR.

G. Adjudicatory Correspondence

1. Motions, briefs, orders, *et al.* pertaining to pre-hearing conferences, if any.

M. Antitrust Correspondence

1. Submittals and related material pertaining to the antitrust review.

Q. Inspection Reports

1. Inspection reports of the applicant's quality assurance program.
2. Notices of deviations.
3. Follow-up correspondence resolving deviations cited

2. Government-owned reactors

Meeting summaries and technical correspondence between NRC and other government technical personnel related to test reactors, critical experiments, and DOD reactors on navy ships and other sites.

PT21 – Noncompliance Reports and Related Correspondence

Deficiency reports are performed in compliance with Part 21 of Title 10 of the Code of Federal Regulations and include:

1. Reports by firms involved in the nuclear industry concerning noncompliance with NRC regulations or the existence of defects which could create a substantial safety hazard.
2. Correspondence pertaining to the NRC review of reports to assess the possibility of generic defects.
3. NRC inspection reports of defects cited.
4. Correspondence specifying appropriate follow-up actions taken by the Agency.

QA999 – Quality Assurance Inspections

This category contains inspection reports of vendors' quality assurance programs and follow-up correspondence. Each vendor facility is assigned a docket number and is part of the QA999 series.

Vendors are defined here as companies, both U.S. and foreign, that are engaged in the design or the manufacture of nuclear components for plants licensed by NRC. QA comprises all those planned and systematic actions necessary to provide adequate confidence that a structure, system or component being manufactured will perform satisfactorily once it is put in service. The controlling criteria are 10 CFR Part 50, Appendix B, vendor QA topical reports, and the PSAR and FSAR submitted by utilities for specific facilities. Documents in this category include:

1. NRC inspection reports, conducted on a quarterly or semi-annual basis, of vendor sites. Inspections may cover the design, fabrication, construction and testing of structural systems and components.
2. Notices of deviations.
3. Vendor corrective actions and other follow-up correspondence associated with the resolution of inspection findings.

REGGD – Regulatory Guides

This category contains new and revised regulatory guides issued by the Commission and related correspondence. These guides describe for the industry and the public methods acceptable to the NRC

staff for implementing specific parts of the NRC's regulations. They also delineate techniques used by the staff in evaluating specific problems or postulated accidents, or provide guidance to applicants. Included are:

1. Federal Register notices announcing the issuance and availability of a proposed regulatory guide.
2. Revised or newly issued Regulatory Guides.
3. NRC value/impact assessment and industry codes, when applicable, that pertain to the issuance of a specific Regulatory Guide.
4. Comments submitted by the nuclear industry and interested members of the public regarding a proposed Regulatory Guide
5. Summary of meetings held in the NRC to discuss proposed Regulatory Guides.

NOTE For documentation pertaining to other work products and activities of the NRC Office of Standards Development, see the Organization category.

RES – Research and Technical Assistance Reports

This category contains reports, generally of an interim nature, submitted by NRC contractors providing research and technical assistance to the Commission. It also includes documentation pertaining to research activities of the Commission. Included are:

1. Project description documents.
2. Letter reports of accomplishments and data reports; for example,
 - a. model documentation reports
 - b. code documentation reports
 - c. code verification reports
3. Pre-test prediction reports.
4. "Quick look" reports.
5. Informal experimental data reports and post-irradiation examination analyses.
6. Conceptual design descriptions.
7. Letter reports of foreign travel and site visits by contractors.
8. Letter, monthly, quarterly, interim or annual status or progress reports on other research projects contracted for by the NRC.
9. Meeting summaries and correspondence dealing with technical matters relating to research and technical assistance contracts.
10. Staff Research Information Letters (RILs) transmitting the documented results from completed research programs.

NOTE: For final reports of research conducted by contractors, see also NUREG reports.

REVIEW GRP – NRC Research Review Groups

This category contains records pertaining to the activities of NRC Research Review Groups. Such groups provide a broad base of technical expertise to aid management in reviewing research in

defined technical areas. They review and comment on research plans and predicted results of major experiments, the validity and applicability of research results, the possible redirection of research projects, new research projects, and priorities within the technical areas covered by the research review group. Documents in this category are.

1. Agendas for quarterly review group meetings.
2. Summary minutes of review group meetings representing views expressed, including dissenting views.
3. Research plans and predicted results of major experiments; presentations by research contractors.
4. Comments on meetings from attendees, including representatives from contractors, universities, vendors and other agencies.
5. Internal memoranda relating to topics under discussion.

RM – Rulemakings

This category contains records pertaining to public hearings held on proposed changes (PRs) to the Commission's regulations. Hearings are instituted at the discretion of the Commission based on the importance and the magnitude of the subject under consideration. Documents in this category include:

1. Designations of the presiding officer and any special directions for the conduct of the hearing.
2. Notifications of hearing board meetings.
3. Petitions, motions, testimony and statements submitted by parties to the hearings.
4. Hearing board orders and rulings.
5. Technical reports submitted as evidence in the proceeding.
6. Reports, if any, of the special board to the Commission regarding a rulemaking proceeding.

SECY – Position Papers Before the Commission

This category consists of staff papers prepared for the information or approval of the Commissioners which are assigned a SECY report series code. Included are:

1. Commission Action papers, which normally include alternatives and recommendations by the staff on a given issue and require Commission action.
2. Consent Calendar items and Policy Session items.

NOTE: For Weekly Information Reports prepared by EDO to the Commissioners providing a summary of key events and items of interest undertaken by staff and program offices, see the NRC Commissioners category.

STATE PROG – State Programs

the Commission's activities and interaction with State
ate Agreements Program, whereby States may assume
uclear materials; (2) the Agency's role in assisting

State and local governments in planning responses to radiological emergencies; and (3) a wide range of liaison and cooperative activities regarding such functions as licensing and siting. It includes.

1. Correspondence between and among NRC Office of State Programs and State officials, mostly State liaison officers, regarding:
 - a. cooperative programs in such technical areas as radiation control, emergency response planning to radiological incidents, water quality and transportation surveillance.
 - b. technical assistance to Agreement States in reviewing applications, compliance actions, developing regulations, and other areas.
2. Agendas, reports and transcripts of regional workshops and training programs on current matters of policy and regulations, i.e. decommissioning and facility siting.
3. State Legislative Reports.
4. Agreement State Licensing Statistics Reports.

NOTE: For specific uranium milling and mining projects in which the Agency is providing technical assistance to States, see the Projects category.

TOPREP – Vendor Reports and Related Correspondence

This category contains topical reports, generally of a technical generic nature, submitted by vendors, and correspondence pertaining to the NRC review of these reports. General vendor related correspondence that is not docket specific is also included in this category.

1. Topical reports, dealing with such technical matters as specifications, testing and safety submitted by architect, engineers and other vendors.
2. Revisions, modifications and amendments to topical reports.
3. Correspondence between NRC and vendors pertaining to the review of submittals.
4. Meeting agendas, summaries, minutes and correspondence pertinent to vendor activities, programs, methodologies and design criteria.

NOTE. For reports submitted by utilities that are written by vendors on their behalf and that relate to docketed cases, see the categories for the Docket 50 series.

WASTE MGT – Nuclear Waste Management

This category is topical in nature and contains records dealing with the activities of the NRC Division of Waste Management. Each topic has been assigned a number, with the series designated by a WM prefix. These documents deal primarily with NRC's interaction with DOE and its future role in licensing and regulating DOE facilities designed for the disposal of high-level waste in geologic repositories. This category will be enlarged later to include records dealing with low-level waste issues and tasks. The documents in this category are:

1. Meeting agenda and minutes of DOE/NRC meetings in which DOE presents information on their geological exploration program to identify sites for nuclear waste repositories.
2. Briefings by DOE on research being conducted on spent fuel storage and nuclear waste management.

3. Correspondence pertaining to NRC's advisory role in providing DOE with technical assistance in the Waste Isolation Pilot Plan (WIPP) for burial of defense wastes.
4. NRC draft staff guides for developing positions on the content and format of environmental reports for geological repositories

XPORTLIC – Export and Import Licenses

This category contains records relating to the issuance of licenses to export or import nuclear facilities and materials. Included are:

1. License applications and amendments to export or import special nuclear material, source material, byproduct material, reactors, nuclear facility components or reactor materials.
2. Correspondence between NRC and applicant or licensee pertaining to the review or status of a pending application or license amendment.
3. Commission letters requesting Executive Branch views.
4. Review and findings of the Executive Branch on whether issuance of a license would be inimical to U.S. common defense and security.
5. Correspondence from foreign governments, international organizations, and members of the public.
6. Staff position papers (SECY series code) prepared for Commissioners review of import or export licenses.
7. Filings pursuant to hearing requests or intervention petitions, if any.
8. Hearing records and decisions.
9. Memoranda from the Office of the Secretary to the Executive Director for Operations regarding the Commission decision on issuance of a proposed license.
10. Licenses, license amendments and license renewals for types specified in item 1.

NOTE: For transcripts of Commission meetings and papers submitted for Commissioner consideration or information, see 10CFR category.

NRC FORM 335 (11/81)		U.S. NUCLEAR REGULATORY COMMISSION BIBLIOGRAPHIC DATA SHEET		1 REPORT NUMBER (Assigned by DDC) NUREG-0540 Vol. 4, No. 12	
4 TITLE AND SUBTITLE (Add Volume No., if appropriate) Title List of Documents Made Publicly Available December 1-31, 1982				2 (Leave blank)	
7 AUTHOR(S)				3 RECIPIENT'S ACCESSION NO	
9 PERFORMING ORGANIZATION NAME AND MAILING ADDRESS (Include Zip Code) Division of Technical Information and Document Control Office of Administration U.S. Nuclear Regulatory Commission Washington, DC 20555				5 DATE REPORT COMPLETED MONTH YEAR	
12 SPONSORING ORGANIZATION NAME AND MAILING ADDRESS (Include Zip Code) Same as 9, above.				DATE REPORT ISSUED MONTH YEAR March 1983	
13 TYPE OF REPORT Monthly				PERIOD COVERED (Inclusive dates)	
15 SUPPLEMENTARY NOTES				14 (Leave blank)	
16 ABSTRACT (200 words or less) This document is a monthly publication containing descriptions of information received and generated by the U.S. NRC. This information includes (1) docketed material associated with civilian nuclear power plants and other uses of radioactive materials, and (2) nondocketed material received and generated by NRC pertinent to its role as a regulatory agency. The following indexes are included: Personal Author Index, Corporate Source Index, Report Number Index, and Cross Reference to Principal Documents Index.					
17 KEY WORDS AND DOCUMENT ANALYSIS			17a DESCRIPTORS		
17b IDENTIFIERS/OPEN-ENDED TERMS					
18 AVAILABILITY STATEMENT Unlimited			19 SECURITY CLASS (This report) Unclassified		21 NO OF PAGES
			20 SECURITY CLASS (This page) Unclassified		22 PRICE \$